

Test Pit Investigation
Digital Photo Log

(Provided on DVD in Bound Report)



1. Looking southeast in courtyard. Photo taken on Tuesday, September 29, 2015. Removing concrete before beginning excavation for Test Pit 1.



2. Looking northeast in courtyard. Photo taken on Tuesday, September 29, 2015. Backfilling Test Pit 1 with material that was excavated from test pit.



3. Looking east in courtyard. Photo taken on Tuesday, September 29, 2015. Excavating soil from Test Pit 2.



4. Looking east in courtyard. Photo taken on Tuesday, September 29, 2015. Test Pit 2 backfilled to previous grade at the end of day with material that was excavated from test pit.



5. Looking northeast in courtyard. Photo taken on Tuesday, September 29, 2015. Breaking apart concrete at location for Test Pit 3.



6. Looking east in courtyard. Photo taken on Tuesday, September 29, 2015. Excavating soil in Test Pit 3 to final depth of approximately 5 ft bls.



7. Looking west in courtyard. Photo taken on Tuesday, September 29, 2015. Beginning to excavate for Test Pit 4, stockpiling soil onto poly.



8. Looking southwest in courtyard. Photo taken on Tuesday, September 29, 2015. Excavating soil in Test Pit 4 to final depth of approximately 5 ft bls.



9. Looking north inside Paint Factory Building. Photo taken on Wednesday, September 30, 2015. Excavating soil for Test Pit 5 and stockpiling on poly.



10. Photo taken on Wednesday, September 30, 2015. Test Pit 5 excavated to final depth of approximately 5 ft bls.



11. Photo taken on Thursday, October 01, 2015. Test Pit 6 excavated to final depth of approximately 5 ft bls.



12. Looking southwest inside Garage Building Photo taken on Thursday, October 01, 2015. Backfilling Test Pit 6 with soil excavated from test pit.



13. Looking south inside Garage Photo taken on Thursday, October 01, 2015. Excavating at location for Test Pit 7.



14. Photo taken on Thursday, October 01, 2015. Excavated to final depth of approximately 5 ft bls at Test Pit 7.