

Proactive by Design



2017 PERIODIC REVIEW REPORT 129 HOLDEN STREET REDEVELOPMENT BUFFALO, NEW YORK BROWNFIELD CLEANUP PROGRAM Site Number C915261

March 20, 2017 File No. 21.0056642.20



PREPARED FOR:

Highland Park Village LLC Buffalo, New York

GZA GeoEnvironmental of New York

535 Washington Street, 11th Floor | Buffalo, New York 14203 716-685-2300

26 Offices Nationwide www.gza.com

Copyright© 2017 GZA GeoEnvironmental of New York



Proactive by Design

GEOTECHNICAL

ENVIRONMENTAL

ECOLOGICAL

WATER

CONSTRUCTION MANAGEMENT

GZA GeoEnvironmental of NY 535 Washington Street 11th Floor Buffalo, NY 14203 T: 716.685.2300 F: 716.685.3629

www.gza.com



VIA EMAIL

March 20, 2017 File No. 21.0056642.20

Mr. Jaspal Walia New York State Department of Environmental Conservation Division of Environmental Remediation 270 Michigan Avenue Buffalo, New York 14203

Re: 2017 Periodic Review Report 129 Holden Street Redevelopment Buffalo, New York Brownfield Cleanup Program Site (Number C915261)

Dear Mr. Walia:

GZA GeoEnvironmental of New York (GZA) is pleased to submit this Periodic Review Report (PRR) on behalf of Highland Park Village LLC (Highland). Highland is the owner and operator of the 129 Holden Street Redevelopment Brownfield Cleanup Program (BCP) Site (No. 915261). This is the first PRR to be submitted for the Site for which a Certificate of Completion (COC) was issued by the New York State Department of Environmental Conservation (NYSDEC) on November 20, 2015. GZA prepared this PRR in general conformance with the guidelines provided to Highland by the NYSDEC in their reminder notice letter dated January 10, 2017.

If you have any questions or need additional information, please call Jim Richert at (716) 844-7048.

Sincerely,

GZA GEOENVIRONMENTAL OF NEW YORK

James Richert, C.P.G.

Senior Project Manager

Bart A. Klettke, P.E.

Principal

Cc: John Ciminelli (Highland Park Village LLC)
David Szymanski (NYSDEC Region 9)



TABLE OF CONTENTS

			Page
1.0	EXECUT	TVE SUMMARY	1
	1.1	BACKGROUND	1
	1.2	EFFECTIVENESS OF THE REMEDIAL PROGRAM	
	1.3	COMPLIANCE	
	1.4	RECOMMENDATIONS	2
2.0	SITE OV	/ERVIEW	2
	2.1	SITE LOCATION AND FEATURES	2
	2.2	INVESTIGATION AND REMEDIAL HISTORY	2
3.0	EVALUA	ATION OF REMEDY PERFORMANCE, EFFECTIVENESS, AND PROTECTIVENESS	3
4.0	INSTITU	JTIONAL CONTROL/ENGINEERING CONTROL (IC/EC) PLAN COMPLIANCE REPORT	3
	4.1	IC/EC REQUIREMENTS AND COMPLIANCE	3
	4.2	IC/EC CERTIFICATION	
5.0	PRR CO	NCLUSIONS AND RECOMMENDATIONS	4
	5.1	PRR CONCLUSIONS	4
	5.2	PRR RECOMMENDATIONS	4

FIGURES

- FIGURE 1 SITE LOCATION MAP
- FIGURE 2 SITE PLAN WITH PHOTO LOCATIONS
- FIGURE 3 FINAL GRADE ELEVATION CONTOURS AND THICKNESS OF CLEAN COVER SYSTEM

APPENDICES

APPENDIX A PHOTOGRAPH LOG

APPENDIX B SITE MANAGEMENT FORM

APPENDIX C PERMITS

APPENDIX D IC/EC CERTIFICATION FORM



1.0 EXECUTIVE SUMMARY

1.1 BACKGROUND

The 129 Holden Street Redevelopment Site (Site) is located in the City of Buffalo, Erie County, New York (Figure 1). The 27.09-acre Site was used as a rock quarry by Buffalo Cement from the early 1900s until the mid-1950s and was filled and developed into the Central Park Shopping Plaza from 1958 to 2011. A Phase I Environmental Site Assessment (ESA) identified several Recognized Environmental Conditions (RECs) including the mixed soil/fill that was used to backfill the quarry as well as several former site uses including a dry cleaner and an auto repair shop. Phase II ESA and Remedial Investigations confirmed the presence of semi-volatile organic compounds (SVOCs) and metals in the soil/fill at concentrations greater than NYSDEC Part 375 Restricted Residential Soil Cleanup Objectives (RRSCOs). Considering that groundwater was not determined to be impacted and that the site contaminants of concern are not volatile, the focus of the Site remedy was to minimize the exposure risks of direct contact and/or inhalation with site contaminants in the soil/fill. The Remedial Action Objectives (RAOs) for the Site included:

- Addressing soils with contaminants above the RRSCOs in the upper 2 feet;
- Prevention of ingestion or direct contact with soil contaminants exceeding the RRSCOs;
- Implementation and maintenance of engineering and institutional controls as follows.

Institutional Controls Include:

- Property use may include restricted residential, restricted commercial, and restricted industrial uses;
- Groundwater may not be used without prior treatment and approval of the regulator;
- Access to the site must be provided to the State of New York;
- Buildings will be built on slabs only; no basements are allowed.

The Engineering Control is:

 Cover System: hardscape and imported clean soil (minimum of 24 inches) underlain by high visibility orange mesh demarcation layer.

The selected site remedy was straight-forward and included two primary components:

- removal and off-site disposal of "hot spot" soil/fill containing SVOCs and Metals above site-specific action levels;
- placement and maintenance of a site cover system.

The Site remedy was completed in the fall of 2015 and a Certificate of Completion (COC) of the BCP remedy was issued by NYSDEC to Highland on November 20, 2015.

1.2 EFFECTIVENESS OF THE REMEDIAL PROGRAM

The site cover system was confirmed to be in place, appears to be complete and in good condition. Therefore, the Site remedy continues to be effective at meeting the Site's RAOs.



1.3 COMPLIANCE

GZA identified the Site areas to be in compliance of the SMP. The Institutional Controls and Engineering Controls (IC/ECs) remain in place and there are no active remedial systems requiring monitoring or operation and maintenance.

1.4 RECOMMENDATIONS

GZA and Highland Park Village LLC (Highland) recommend no changes to the SMP nor to the frequency of PRR submittals. Implementation of the SMP, including the Excavation Work Plan and maintenance of the Site cover system will continue as the Site is redeveloped for the planned and approved residential use.

2.0 SITE OVERVIEW

2.1 SITE LOCATION AND FEATURES

Highland entered into a Brownfield Cleanup Agreement (BCA) with the NYSDEC in February 2012 to investigate and remediate the 27.09-acre property located at 129 Holden Street, in the City of Buffalo, Erie County, New York (Figure 1). The Site (NYSDEC Site No. C915261) was remediated following Track 4 of the Brownfield Cleanup Program (BCP) for restricted residential use. The Site is being redeveloped into the Highland Village Park Community which will include residential living units/apartments.

The Site was used as a rock quarry by Buffalo Cement from the early 1900s until the mid-1950s. The quarry was later filled with mixed hard fill, levelled, and developed and used as a neighborhood shopping plaza, Central Park Plaza, from 1958 to 2011. As social and economic conditions of the neighborhood changed over time, businesses within the plaza struggled and eventually closed. Once purchased by Highland, and in preparation for site remediation and redevelopment, the site buildings and utilities were removed, leaving a flat, vacant site with formerly used slab-on-grade foundations and deteriorated asphalt parking lots.

Historical Site tenants of potential environmental concern included a photo mart, laundromats, an automatic car wash, a dry cleaner, an auto chop shop, and an automotive service shop. The Site was listed twice on the NY Spills database.

2.2 INVESTIGATION AND REMEDIAL HISTORY

Based on the information obtained as part of the Phase I ESA, historic site usage represented Recognized Environmental Concerns (RECs), and additional investigations were recommended.

GZA completed a Phase II ESA that identified semi-volatile organic compounds (SVOCs) and metals at concentrations above the Soil Cleanup Objectives (SCOs) for residential site use (RRSCOs).

GZA conducted a remedial investigation (RI) in 2012 and 2013 under the NYSDEC Brownfield Cleanup Program to better assess the extent and significance of the chemical impact identified during the Phase II ESA.

The RI confirmed that a significant amount of mixed fill materials had been placed at the Site after the quarry operations ceased in the early 1950s, prior to construction of the Central Park Plaza. Total depth of the



subsurface fills on-site ranged between approximately five feet below ground surface (ft. bgs) to greater than 19 ft. bgs. SVOCs and metals were detected in soil/fill samples at concentrations above the Part 375 SCOs for restricted residential site use (RRSCOs); however, specific sources of the SVOCs and metals contamination were not identified. No contaminants of concern were identified in the groundwater.

The Remedial Action Objectives (RAOs) for the Site, as presented in the RI/Alternatives Analysis Report were:

- Address soils with contaminants above the RRSCOs in the upper 2 feet;
- Prevent ingestion or direct contact with soil contaminants exceeding the RRSCOs;
- Institute and maintain engineering and institutional controls to assure the Site is not used in a manner inconsistent with the future anticipated use (restricted residential).

The selected site remedy included two primary components:

- removal and off-site disposal of "hot spots" of soil/fill containing SVOCs and Metals above site-specific action levels;
- placement of a site cover system, made up of either clean soil at a minimum of 2-feet thickness or hardscapes including paved roads, parking lots, sidewalks, or building slab foundations.

The Site remedy was completed in the fall of 2015 and a Certificate of Completion (COC) was issued by NYSDEC to Highland on November 20, 2015.

As part of the Site remedy, the entire Site was covered with a minimum of 2-feet of clean soil for eventual redevelopment as new residential housing. The site currently is undeveloped with one new street extension, Chalmers Avenue.

3.0 EVALUATION OF REMEDY PERFORMANCE, EFFECTIVENESS, AND PROTECTIVENESS

GZA performed a Site Inspection during the reporting period on February 14, 2017. A photo log is provided in Appendix A and a map showing the location and orientation of the Site photos is provided as Figure 2. The site cover system was observed to be providing complete coverage of the Site and appears to be in good condition. The Site remedy, therefore, continues to be effective at meeting the Site RAOs for protection of site users.

4.0 INSTITUTIONAL CONTROL/ENGINEERING CONTROL (IC/EC) PLAN COMPLIANCE REPORT

4.1 IC/EC REQUIREMENTS AND COMPLIANCE

IC/ECs for the site were determined by the NYSDEC and specified in the Decision Document (DD) issued by the NYSDEC on December 19, 2014. Those same IC/ECs were carried forward in the Environmental Easement (EE), issued by the NYSDEC on September 23, 2015 and later again included in the Site Management Plan (SMP) which was prepared by GZA and approved by the NYSDEC on October 16, 2015. Complete lists of the Site IC and ECs are provided in Sections 3.2 and 3.3 of the SMP. Summary lists of the ICs and ECs are provided as follows.



Summary of Site Institutional Controls:

- Property use may include restricted residential, restricted commercial, and restricted industrial uses;
- Groundwater may not be used without prior treatment and approval of the regulator;
- Access to the site must be provided to the State of New York;
- Buildings will be built on slabs only; no basements are allowed.

Summary of Site Engineering Controls:

 Cover System: hardscape and imported clean soil (minimum of 24 inches) underlain by high visibility orange mesh demarcation layer.

Limited on-Site activity has occurred since completion of the Site remedy in the fall of 2015. The only change of site conditions since issuance of the COC is the construction of the Chalmers Avenue extension and related street scape amenities (e.g. young trees, light poles) and buried utilities.

Based on observations made during the Site inspection, discussions with Highland, and surveyed elevations and thicknesses of the cover system at the new Chalmers Avenue extension (See Figure 3) the Site owner is complying with the IC/ECs. The Site remains undeveloped and inactive. The Site cover system is in place and functioning as intended. No building structures are present on Site and Site groundwater is not being used. Although not a required EC, a perimeter chain-link fence with locked gates restricts access to the Site and no one currently uses the site.

4.2 IC/EC CERTIFICATION

The Site-specific IC/EC Certification Form, for reporting period of November 20, 2015 to February 18, 2017, was provided to Highland as an attachment to the January 10, 2017 Reminder Notice letter sent by the NYSDEC. This form has been completed by Highland as Site owner and Certified by GZA as Qualified Environmental Professional (QEP). The completed IC/EC Certification Form for this reporting period is provided in Appendix D of this PRR.

5.0 PRR CONCLUSIONS AND RECOMMENDATIONS

5.1 PRR CONCLUSIONS


GZA identified the Site areas to be in compliance of the SMP. The IC/ECs remain in place and are performing as intended. There are no active remedial systems requiring operation, monitoring, or maintenance.


5.2 PRR RECOMMENDATIONS


GZA and Highland recommend no changes to the SMP nor to the frequency of PRR submittals at this time. Implementation of the SMP, including the Excavation Work Plan and maintenance of the Site cover system will continue as the Site is redeveloped for the planned and approved residential use.



FIGURES







PREPARED FOR



LP CIMINELLI 2421 MAIN ST. BUFFALO, NY 14214 ERIE COUNTY

BCP SITE # C915261 129 HOLDEN STREET CITY OF BUFFALO COUNTY OF ERIE STATE OF NEW YORK

RECORD DRAWING



Centerpointe Corporate Park 375 Essjay Road, Suite 200 Williamsville, NY 14221 www.wendelcompanies.com p:716.688.0766 f:716.625.6825

Wendel WD Architecture, Engineering, Surveying and Landscape Architecture P.C.

THIS DOCUMENT, AND THE IDEAS AND DESIGNS INCORPORATED HEREIN, AS AN INSTRUMENT OF PROFESSIONAL SERVICE, IS THE PROPERTY OF WENDEL WD ARCHITECTURE, ENGINEERING, SURVEYING AND LANDSCAPE ANY OTHER PROJECT WITHOUT THE WRITTEN AUTHORIZATION OF WENDEL. UNAUTHORIZED ALTERATION OR ADDITION TO ANY SURVEY DRAWING, DESIGN, SPECIFICATION, PLAN OR REPORT IS A VIOLATION OF SECTION 7209, PROVISION 2 OF THE NEW YORK STATE EDUCATION LAW.

REVISIONS DWG. TITLE

FIGURE 3:

FINAL GRADE ELEVATION CONTOURS AND THICKNESS OF CLEAN SOIL COVER SYSTEM

3/17/2017

1"=30" STD

PROJ. No. 324720

SHT 1 OF 1

CHK. CJS



APPENDIX A PHOTOGRAPH LOG





Photo 1 – Northwest portion of Site looking southeast



Photo 3 – Chalmers Avenue Extension on western portion of Site looking east



Photo 2 – Northwest portion of Site looking east



Photo 4 – Southwest portion of Site looking east





Photo 5 – Southwest portion of Site looking east



Photo 7 – Drainage gully on southwest portion of Site along Chalmers Avenue Extension looking west



Photo 6 – Drainage gully on southwest portion of Site south of Chalmers Avenue Extension looking southeast



Photo 8 – Drainage gully on southwest Portion of Site along Chalmers Avenue Extension looking south





Photo 9 – Northwest portion of Site looking west



Photo 11 – Northeast portion of Site looking south



Photo 10 – Recycled asphalt pile on northeast portion of Site looking southeast



Photo 12 – Chalmers Avenue Extension looking west





Photo 13 – Drainage gully on south-central portion of Site along former Hill Street looking south



Photo 15 – Southwest portion of Site looking west



Photo 14 – Northeast portion of Site looking northeast



Photo 16 – Drainage gully on eastern portion of Site looking northwest





Photo 17 – Southwest portion of Site looking northwest



Photo 19 – Southeast portion of Site looking east



Photo 18 – Southwest portion of Site looking west



Photo 20 – Southeast portion of Site looking northwest



APPENDIX B SITE MANAGEMENT LOG

129 Holden Street Redevelopment BCP Site No.: C915261

Site Management Form

SITE D	ETAILS			
Site No.: C915261 Site Name: 129 Holden Street R	edevelopment			
Site Address: 129 Holden Street, Buffalo, New York				
	MING INSPECTION			
Name: Tom Bohlen	Email: Thomas.Bohlen@gza.com			
Company: GZA	Phone Number: (716) 844-7050			
Others Present: None				
	ND SITE CONDITIONS			
Inspection Date: February 14, 2017	Inspection Time: 1300 to 1400 hrs			
Weather Conditions: Sunny ~35 degrees F., light winds				
	TE INSPECTION			
Type of Inspection: ✓ Annual Inspection ☐ Routine Maintena	•			
Inspection after a Severe Condition that could effect Sit	e control ☐ Yes ☐ No			
Describe severe condition triggering inspection:	NA			
VERIFICATION (OF SITE DETAILS			
Current Site Owner:	Highland Park Village LLC			
Current Site Operator:	Highland Park Village LLC			
Describe Current Site Use (check all that apply)				
☐ Industrial ☐ Commercial ✓ Residentia	Other Site in development for residentia			
Briefly describe observed site uses:				
te was inactive on the day of inspection and reportedly	has been inactive since fall of 2016 when the constructio			
the Chalmers Ave extenstion and associated buried util	ities were completed, see inspecition photos. Remainder			
ite retains the soil cover system. Minor surface erosion	noted but no significant damage to cover system observe			
See attached City of Buffalo permi	t # 229004 for Right-of-Way Work.			
Note any additional pertinent information to Verification of Site Details (use additional pages if necessary.				
DESCRIPTION OF ENG	SINEERING CONTROLS			
Are the Engineering Controls still in place:	□ No			
If No, explain:				
Is the Site Management Plan still in place:	□ No			
If No, explain:				
AREAS IN NEED OF REI	PAIR OR MAINTENANCE			
Area discussed in this section must be shown on a figure and hav	e photographic documentation.			
None C	Observed			

129 Holden Street Redevelopment BCP Site No.: C915261 Site Management Form

INTRUSIVE ACTIVITIES PERFORMED AT SITE DURING INSPECTION PERIOD
Location: Construction of Chalmers Ave extension and burried util Date: 2016 construction season.
Description of activities being performed:
see Verification of Site Details section above
Are Site records being properly generated and maintained: ✓ Yes
Provide a summary of recordkeeping review and adeuacy:
ADDITIONAL NOTES & COMMENTS
ADDITIONAL NOTES & COMMENTS
The Site redevelopment plan involves multile phases of re-establishment of streets and utilities along with the
planned residential structures. At this time, no structures are present on site. The first new street, Chalmers Ave.
has been constructed along with associated sewers, water lines, and street lamps.
r
INSPECTION CERTIFICATION
I hereby certify that the information included in this report is complete and accurate to the best of my knowledge
Qt 11
Inspector Signature: Thomas Bohlen Date:February 14, 2017



APPENDIX C PERMITS



Right-of-Way Work Permit

Department of Public Works
Division of Engineering

... Building a Better Buffalo

Byron W. Brown, Mayor

Application/Permit No.: 229004

Location: HOLDEN-CHALMERS TO CENTRAL PARK PLAZA

Applicant:

ANASTASI TRUCKING INC.

Issue Date: 10/13/2015

Issued By: MURPM

Expire Date:

Fees: \$46.00

License No.:

License Type:

Plans: No

Extended to: 03/13/2017

<u>Description of Work:</u> 126 LF OF STORM SEWER, 2 MH'S, 4 CATCH BASINS. 100 LF OF WATERLINE. 430 LF OF SANITARY SEWER, 3 MH'S. 525 LF OF GRANITE CURBING AND WALK(EAST SIDE OF HOLDEN). MILL AND OVERLAY EAST SIDE OF HOLDEN. 4 LIGHT BASES AND MISCELLANEOUS SIGNAGE. TOPSOIL AND TREES.

This Permit Expires by Limitation

3/2015 Work Finish:

Work Begin: 10/13/2015

Remarks:

WORK RELATED TO NEW DEVELOPMENT AT CENTRAL PARK PLAZA SITE (HIGHLAND PARK) WORK ON HOLDEN TO UPGRADE WATER AND SEWER FOR FUTURE NEEDS WORK TO BE INSPECTED BY GENERAL CONTRACTOR, LP CIMINELLI.

Contractor is responsible for contacting Dig Safely (formerly Underground Facilities Protective Organization (UFPO) @ 1-800-962-7962 as per New York State Code 753. City R.O.W. to be restored to original condition or better as per DPW specifications. All restoration work to be inspected by Engineering Inspector.

Subject to all laws, ordinances and requirements governing the same, permission is hereby given for the construction work mentioned. The work must be done expeditiously and within a reasonable time, causing as little inconvenience to the public as possible. Before starting work, contact representatives of the Buffalo Water Authority, Buffalo Sewer Authority, Traffic Signal Division, and Fire Alarm office for location of subterranean utilities. Furthermore, contact representatives of the telephone company, gas, electric, and power companies, cable television, and other private utilities for location of subterranean utilities. The city assumes no responsibility for the location of these underground installations. The issuance of this permit does not obligate the city nor does it constitute approval of any excavation which might interfere with these utilities.

If excavation is in the vicinity of city owned trees, contact the Parks Department, Forestry Division.

This permit furnishes no guarantee by the city as to the location of utility property underground or location of private or public service pipes, mains or services at the place where excavation is permitted.

Sr. Engineer/Clerk

City Engineer: Michael J. Finn, P.E.



APPENDIX D IC/EC CERTIFICATION FORM



Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



Site No. C915261	Site Details	Box 1
Site Name 129 Holden Street Red	ie Ievalonment	w :
	- \$	3
Site Address: 129 Holden Street City/Town: Buffalo County: Erie	Zip Code: 14214	9
Site Acreage: 27.1		
Reporting Period: November 20, 20	015 to February 18, 2017	
		· YES NO
		TES NO
Is the information above correct		
If NO, include handwritten above	e or on a separate sheet.	
Has some or all of the site prope tax map amendment during this	erty been sold, subdivided, merged, or under Reporting Period?	rgone a
Has there been any change of u (see 6NYCRR 375-1.11(d))?	se at the site during this Reporting Period	· /
 Have any federal, state, and/or lefor or at the property during this 	ocal permits (e.g., building, discharge) been Reporting Period?	issued
	ions 2 thru 4, include documentation or e previously submitted with this certification	
	previously submitted with this certification	
that documentation has been	previously submitted with this certification	
that documentation has been	previously submitted with this certification	on form.
that documentation has been	previously submitted with this certification development? t with the use(s) listed below?	Box 2
 that documentation has been 5. Is the site currently undergoing of 6. Is the current site use consistent 	previously submitted with this certification development? It with the use(s) listed below? It cial, and Industrial	Box 2 YES NO
5. Is the site currently undergoing of the site currently undergoing of the site current site use consistent Restricted-Residential, Comment 7. Are all ICs/ECs in place and fund IF THE ANSWER TO EITH	previously submitted with this certification development? It with the use(s) listed below? It cial, and Industrial	Box 2 YES NO
5. Is the site currently undergoing of the site currently undergoing of the site current site use consistent Restricted-Residential, Comment 7. Are all ICs/ECs in place and fund IF THE ANSWER TO EITH DO NOT COMPLETE	previously submitted with this certification development? It with the use(s) listed below? It cial, and Industrial Indus	Box 2 YES NO
5. Is the site currently undergoing of the site currently undergoing of the site current site use consistent Restricted-Residential, Comment 7. Are all ICs/ECs in place and fund IF THE ANSWER TO EITH DO NOT COMPLETE	previously submitted with this certification development? It with the use(s) listed below? It with	Box 2 YES NO
5. Is the site currently undergoing of the site currently undergoing of the site currently undergoing of the site current site use consistent Restricted-Residential, Commendation of the site of the	previously submitted with this certification development? It with the use(s) listed below? It with	Box 2 YES NO Delow and tinue.
5. Is the site currently undergoing of the site currently undergoing of the site current site use consistent Restricted-Residential, Comment 7. Are all ICs/ECs in place and fund IF THE ANSWER TO EITH DO NOT COMPLETE	previously submitted with this certification development? It with the use(s) listed below? It with	Box 2 YES NO

8. Has any new information revealed that assumptions made in the Qualitative Exposure Assessment regarding offsite contamination are no longer valid? If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form. 9. Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years) If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. SITE NO. C915261 Description of Institutional Controls Parcel Owner Institutional Control 90.29-2-43.1 Highland Park Village, LLC Ground Water Use Restriction Sill Management Plan Landuse Restriction Site Management Plan Site Management Plan Institution of groundwater use.	Box 2 YES Box	NO A
Assessment regarding offsite contamination are no longer valid? If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form. 9. Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years) If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. SITE NO. C915261 Description of Institutional Controls Parcel Owner Institutional Control 90.29-2-43.1 Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan	Box	A
Assessment regarding offsite contamination are no longer valid? If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form. 9. Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years) If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. SITE NO. C915261 Description of Institutional Controls Parcel Owner Institutional Control Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan Landuse Restriction Site Management Plan	Box	
If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form. 9. Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years) If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. SITE NO. C915261 Description of Institutional Controls Parcel Owner Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan Landuse Restriction Site Management Plan	Box	
that documentation has been previously submitted with this certification form. 9. Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years) If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. SITE NO. C915261 Description of Institutional Controls Parcel Owner Institutional Control 90.29-2-43.1 Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan Landuse Restriction Site Management Plan i) Prohibition of groundwater use.		
(The Qualitative Exposure Assessment must be certified every five years) If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions. SITE NO. C915261 Description of Institutional Controls Parcel Owner Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan Institutional Control Soil Management Plan Landuse Restriction Site Management Plan		
updated Qualitative Exposure Assessment based on the new assumptions. SITE NO. C915261 Description of Institutional Controls Parcel 90.29-2-43.1 Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan i) Prohibition of groundwater use.		x 3
Description of Institutional Controls Parcel Owner Institutional Control 90.29-2-43.1 Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan i) Prohibition of groundwater use.		x 3
Parcel Owner Institutional Control 90.29-2-43.1 Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan i) Prohibition of groundwater use.	ction	
90.29-2-43.1 Highland Park Village, LLC Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan i) Prohibition of groundwater use.	ction	
Ground Water Use Restrict Soil Management Plan Landuse Restriction Site Management Plan i) Prohibition of groundwater use.	ction	
		¥
ii) Land use restrictions. iii) Implementation of the Site Management Plan		
	Bo	x 4
Description of Engineering Controls		
Parcel Engineering Control		
90.29-2-43.1		%
Cover System .		
) Maintenance of the Cover System.	e.	

Р	OY	5

	Periodic Review Report (PRR) Certification Statements
1.	I certify by checking "YES" below that:
	 a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the certification;
	b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and the information presented is accurate and compete.
	YES NO
2.	If this site has an IC/EC Plan (or equivalent as required in the Decision Document), for each Institutional or Engineering control listed in Boxes 3 and/or 4, I certify by checking "YES" below that all of the following statements are true:
	(a) the Institutional Control and/or Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;
	(b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;
	(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;
	(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and
	(e) if a financial assurance mechanism is required by the oversight document for the site, the mechanism remains valid and sufficient for its intended purpose established in the document.
	YES NO
	IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.
	A Corrective Measures Work Plan must be submitted along with this form to address these issues.
	Signature of Owner, Remedial Party or Designated Representative Date

IC CERTIFICATIONS SITE NO. C915261

Box 6

SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

am certifying as Toly Comme/: VP. Highland Hall (Owner or Remedial Party)

for the Site named in the Site Details Section of this form.

Signature of Owner, Remedial Party, or Designated Representative Rendering Certification

Date

IC/EC CERTIFICATIONS

Box 7

Qualified Environmental Professional Signature

I certify that all information in Boxes 4 and 5 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

am certifying as a Qualified Environmental Professional for the HIGHLAND

Signature of Qualified Environmental Professional, for the Owner or Remedial Party, Rendering Certification (Required for PE)

Date



GZA GeoEnvironmental, Inc.