

**NYSDEC**  
**Region 9**  
**Division of Environmental Remediation**

**Site: Bisonite Paint**  
**Phase: Remediation**  
**Site No.: C915010**

**Contractor PM:**  
**NYSDEC PM: Bradley Demo**  
**Construction Manager:**  
**Project Engineers: Thomas Forbes**  
**Remedial Contractor: Roux Inc**  
**Air Monitoring:**  
**Health & Safety:**

**Weather Conditions**

General Description	Cloudy	am	pm
Temperature	23°F	am	pm
Wind Direction	Light/variable	am	pm

**HEALTH & SAFETY:**

*(\*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report).*

Were there any changes to the Health & Safety Plan?		*Yes ( )	No ( )	NA (x)
Were there any exceedances at the perimeter action level reported on this date?	Air:	*Yes ( )	No ( )	NA (x)
Were there any Noise /Vibration exceedances reported on this date?	Noise:	*Yes ( )	No ( )	NA (x)
	Vibration:	*Yes ( )	No ( )	NA (x)
Were there any breaches to the tent structure or silt fence reported/observed on this date?		*Yes ( )	No ( )	NA (x)
Were there any dust/odor issues reported or observed on this date?		*Yes ( )	No (x)	NA ( )

**WASTE HAULING :**

*(\*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report).*

Were there any vehicles which did not display proper D.O.T numbers and placards?		*Yes ( )	No ( )	NA (x)
Were there any vehicles which were not lined or tarped?		*Yes ( )	No ( )	NA (x)
Were there any vehicles which were not decontaminated prior to exiting the work site?		* Yes ( )	No ( )	NA (x)

Materials Removed From Site: N/A

Disposal Facility:

Total Loads: (on this date)

Total Loads: (to date)

Total Daily Weight: (est.)

Total Weight: (\*approx.)

\*Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.

Summary of Events:

- NYSDEC onsite 10:30 am to 11:00 am.
- Routine site exterior inspection. Site cover in good condition as visible (partial snow cover).
- Monitoring wells HMW-2, HMW-3, HMW-4, and HMW-6 were located and covered properly, appearing to be in good condition. HMW-1 was not found as damage was noted in last Periodic Review Report. Another well was located in the Northern "gymnasium" area outside of covered area. May have been HMW-1 and figure was incorrectly marked. HMW-5 was likely under a dumpster.
- All monitoring wells at adjacent lot, site of former Sunoco spill #11-06834 remain closed, no new activity.

VISITORS TO SITE:

NAME	Representing	Entered Exclusion/CRZ Zone	
		Yes ()	No ()
		Yes ()	No ()
		Yes ()	No ()
		Yes ()	No ()
		Yes ()	No ()

PROJECT SCHEDULE:

- 

ISSUES PENDING:

- 

ITEMS OF CONCERN:

-

**Inspector: Bradley Demo**

**Signature:** *Bradley W. Demo*

**Date: 1/15/2025**



HMW-6 at corner of West Huron St. and Bean Alley.





HMW-4/cover at SE corner of gymnasium area.





HMW-3/Site cover at SW corner of gymnasium area.





Conditions at former Sunoco spill site.





Former Sunoco spill site conditions/probable decommissioned monitoring wells.





HMW-2/site cover in central gymnasium area.