August 29, 2022

Glenn May Project Manager New York State Department of Environmental Conservation 270 Michigan Ave Buffalo, NY 14203-2915.

Re: Site Management Periodic Review Report and IC/EC Certification

Site Name: Tract I 3123 Highland Ave

Site No.: C932157

Parcel Nos: 144.06-2-27 lot 34

Site Address: 3123 Highland Ave, Niagara Falls, NY 14305

Dear Mr. May:

On behalf of Brightfields I Corporation, Inventum Engineering, P.C. (Inventum) is submitting this revised periodic review report (PRR) for the Tract I Highland Ave Site (Site No. C932157). This report documents the implementation of, and compliance with, site-specific site management (SM) requirements for the reporting period of January 16, 2017, to January 16, 2022.

The revised report incorporates comments on the PRR received from the New York State Department of Environmental Conservation (NYSDEC) in an e-mail dated June 14, 2022. The NYSDEC's Comments are reproduced in the bullets below followed by Inventum's responses in *italics*.

- Section 1.1 This site is not in the BCP; it has a regular Registry number.
 The registry number for the Tract II property has been corrected in the revised PRR.
- Section 1.1 Department records indicate that these documents are dated 2014.
 The PRR has been revised to correct the submittal dates of the FER and SMP to December 2014.
- Section 1.2.1 The statement that annual inspections are completed is made several times throughout the PRR. Appendix A, however, only includes 1 inspection report.
 - The PRR has been revised to reflect that inspections were conducted; however, only one inspection report was available to Inventum. Inventum will ensure that future annual inspections are documented as required by the SMP.
- Section 2.2 Was a Change of Use Form submitted prior to the initiation of this work?
 There was no change in approved site use as a result of the construction documented in the PRR.

The forms for the site are enclosed documenting the SM requirements during the reporting period. The Institutional Controls (ICs) portion of the form (Box 6) have been signed by Inventum, the designated representative.

The IC/EC Certification Forms are attached as Enclosure A. The PRR narrative is attached (Enclosure B) following applicable components of the format presented in the notification letter.

Respectfully submitted,

Todd Waldrop, P.E.

Project Director Enclosures



Enclosure A

Institutional and Engineering Controls Certification Form





Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



Sit	e No.	C932157	Site Details		Box 1	
Sit	e Name Tra	act I Highland Avenue				
City Co	e Address: y/Town: Nia unty:Niagar e Acreage:	a	Zip Code: 14305			
Re	porting Peri	od: January 16, 2017 to .	January 16, 2022			
					YES	NO
1.	Is the infor	mation above correct?			x	
	If NO, inclu	ude handwritten above or	on a separate sheet.			
2.		or all of the site property mendment during this Rep	been sold, subdivided, merged, or uporting Period?	ındergone a		x
3.		been any change of use a CRR 375-1.11(d))?	at the site during this Reporting Peri	od		x
4.	•	federal, state, and/or loca e property during this Rep	I permits (e.g., building, discharge) porting Period?	been issued	x	
			s 2 thru 4, include documentation viously submitted with this certifi			
5.	Is the site	currently undergoing deve	elopment?			×
					Box 2	
					YES	NO
6.		ent site use consistent wit al and Industrial	h the use(s) listed below?		ī x	
7.	Are all ICs	in place and functioning	as designed?	X		
	IF T		QUESTION 6 OR 7 IS NO, sign and E REST OF THIS FORM. Otherwise		ınd	
AC	Corrective M	leasures Work Plan must	be submitted along with this form	to address th	nese iss	ues.
Sig	nature of Ov	vner, Remedial Party or De	esignated Representative	Date		

		Box 2	A
		YES	NO
8.	Has any new information revealed that assumptions made in the Qualitative Exposure Assessment regarding offsite contamination are no longer valid?		X
	If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form.		
9.	Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years)	×	
	If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions.		
SITE	E NO. C932157	Box	x 3

Description of Institutional Controls

Institutional Control Parcel Owner

146.06-2-27.1 **Brightfields Corporation**

> Ground Water Use Restriction Landuse Restriction Site Management Plan

IC/EC Plan

An Environmental Easement, filed with the Niagara County Clerk's Office on September 12, 2014, imposes the following controls on the property:

- 1. The property may be used for Commercial and Industrial use and shall not be used for Residential or Resticted Residential purposes as described in 6NYCRR 375-1.8(g)(2).
- 2. The use of groundwater underlying the property is prohibited without necessary water quality treatment as determined by the New York State Department of Health or the Niagara County Department of Health.
- 3. Compliance with the Department approved Site Management plan is required.
- 4. The remedial party or site owner must complete and submit to the Department a periodic certification of institutional and engineering controls in accordance with Part 375-1.8(h)(3).

Box 4

Description of Engineering Controls

None Required

Not Applicable/No EC's

Box	5
-----	---

	Periodic Review Report (PRR) Certification Statements
1.	I certify by checking "YES" below that:
	a) the Periodic Review report and all attachments were prepared under the direction of, and reviewed by, the party making the Engineering Control certification;
	b) to the best of my knowledge and belief, the work and conclusions described in this certification are in accordance with the requirements of the site remedial program, and generally accepted engineering practices; and the information presented is accurate and compete.
	YES NO
	$f{x}$
2.	For each Engineering control listed in Box 4, I certify by checking "YES" below that all of the following statements are true:
	(a) The Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Department;
	(b) nothing has occurred that would impair the ability of such Control, to protect public health and the environment;
	(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;
	(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and
	(e) if a financial assurance mechanism is required by the oversight document for the site, the mechanism remains valid and sufficient for its intended purpose established in the document.
	NOT APPLICABLE/NO EC'S
	IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.
	A Corrective Measures Work Plan must be submitted along with this form to address these issues.
	Signature of Owner, Remedial Party or Designated Representative Date

IC CERTIFICATIONS SITE NO. C932157

Box 6

SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNATURE

I certify that all information and statements in Boxes 1,2, and 3 are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.

print name print business address am certifying as Remedial Party for the Site named in the Site Details Section of this form.	Ste C
am certifying as)
for the Site named in the Site Details Section of this form.	_(Owner or Remedial Party)
Signature of Owner, Remedial Party, or Designated Representative Rendering Certification	8/29/2022 Date

Enclosure B Site Management Periodic Review Report





Tract I Highland Ave Site Management Periodic Review Report

3123 Highland Ave Niagara Falls NY, 14305 NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

Table of Contents

1	E	xecut	ive Summary	4
	1.1	Si	te Summary	4
	1.2	Ef	fectiveness of the Remedial Program	5
	1	.2.1	Progress During the Reporting Period	5
	1	.2.2	Progress to Remedial Objectives for the Site	5
	1.3	Co	ompliance	6
	1	.3.1	Potential Non-compliance	<i>6</i>
	1	.3.2	Proposed Steps	<i>6</i>
	1.4	Re	ecommendations	<i>6</i>
	1	.4.1	Recommended Changes to the SMP	<i>6</i>
	1	.4.2	Recommend Changes to the Frequency for Submittal of PRRs	<i>6</i>
	1	.4.3	Recommend Whether the Requirements for Discontinuing Site Management	<i>6</i>
2	S	ite Ov	erview	<i>6</i>
	2.1	Si	te Location	6
	2.2	Cł	nronology of the Remedial Program	<i>6</i>
3	E	valua	te Remedy Performance, Effectiveness, and Protectiveness	7
4	[(C/EC F	Plan Compliance Report	7
	4.1	IC	/EC Requirements and Compliance	7
	4	.1.1	Controls	7
	4	.1.2	Status	7
	4	.1.3	Corrective Measures	8
	4.2	IC	/EC Certification	8
5	N	∕lonito	oring Plan Compliance Report	8
	5.1	M	lonitoring Plan Compliance Report	8
	5.2	M	lonitoring Completed During Reporting Period	8
	5.3	Co	omponents of the Monitoring Plan	8
	5.4	M	lonitoring Deficiencies	8
	5.5	С	onclusions and Recommendations for Changes	8
6	C)perat	ion & Maintenance (O&M) Plan Compliance Report	8
7	C	Overal	I PRR Conclusions and Recommendations	8

NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

Figures

Figure 1 – Site Layout

Appendices

Appendix A – Institutional Controls – Annual Site Wide Inspection Forms

Appendix B – Construction and Occupancy Permits

NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

1 Executive Summary

Inventum Engineering, P.C. (Inventum) has prepared this Site Management (SM) Periodic Review Report (PRR) on behalf of Brightfields Corporation (Brightfields) for the Tract I Site (Site) located at 3123 Highland Ave in the City of Niagara Falls, Niagara County, New York (NYSDEC Site No. C932157). The PRR covers the period from January 16, 2017 to January 16, 2022. This PRR is a required element of the Site remedial program under the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP). The Site has been remediated in accordance with Brownfield Cleanup Agreement (BCA) Index #C932157-03-12, which was executed on April 5, 2012.

The following parcel is included within the Site Management Plan (SMP) and this PRR (Figure 1):

• Parcel 144.06-2-27 lot 34 – Tract I, 5.844 acres commercial/industrial

Site Institutional Controls (ICs) were in place over the PRR reporting period and continue to be effective in maintaining the remedial objectives. No Engineering Controls (ECs) are required at the Site.

No changes to the established SMP are recommended during the next PRR reporting period.

1.1 Site Summary

The $5.9 \pm$ acre site is bounded by the Tulip Corporation to the north, the Tract II property (Site 932136) to the south and east, and highland Avenue to the west (Figure 1).

The Site was the location of a lead/acid battery manufacturing plant from approximately 1910 through the 1950s. In the early 1950s, the plant was retooled to produce hard rubber battery casings and for the filling and charging of lead/acid batteries. Manufacturing activities ceased in the 1970s and the Site was used as a warehouse and automotive body shop until the 1980s. By the late 1980s, the Site had been abandoned and various portions were in disrepair. At that time, the City of Niagara Falls acquired the property via tax foreclosure. In early 1999, the City of Niagara Falls initiated investigations at the Site under the New York State Environmental Restoration Program (ERP) to redevelop the property (ERP #B00160). Following several stages of Site investigation (Section 2.1) the City of Niagara Falls withdrew the Site from the ERP, and in 2011, Brightfields purchased Tract I and entered the Site into the BCP (Site #C932157).

The investigations conducted prior to, and after, entry into the BCP defined the nature and extent of impacts to soil and debris on the Site, which were found to contain lead and other metals, polycyclic aromatic hydrocarbons (PAHs), and polychlorinated biphenyls (PCBs) at concentrations exceeding Commercial Soil Cleanup Objectives (SCOs). Approximately 42-percent of the lead-impacted soils contained lead at concentrations that also exceeding the Toxicity Characteristic Leaching Procedure (TCLP) standard of 5 milligrams per liter (mg/L).

A remedial action was completed in November 2014 (Section 2.2) and included building demolition and the excavation and off-site disposal of soils exceeding the Commercial SCO. The SMP and Final Engineering Report (FER) were submitted to NYSDEC in December 2014. On December 23, 2014, the NYSDEC issued the Certificate of Completion (COC) for the site.

NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

In March of 2016, notification was sent to the NYSDEC indicating that the redevelopment of the property was commencing. Construction was completed in November 2016. The Site is currently utilized as a manufacturer of proprietary and custom injection molding products serving the industrial lead battery, automotive, and consumer markets. Expansion of the manufacturing facility occurred during the reporting period covered under this PRR.

1.2 Effectiveness of the Remedial Program

A FER for the Site was issued in December 2014. The remedy at the Site was to demolish the building and remove and dispose of all soil that exceeded the Commercial SCOs or the TCLP lead standard. Soil that exceeded the TCLP standard of 5 mg/L was treated prior to off-site disposal. The excavated areas of the Site were backfilled with either crushed construction debris or imported fill that met the Commercial SCO. No demarcation barrier was required for the Site.

A deed restriction was placed on the property limiting its use to commercial or industrial purposes. No Engineering Controls were required for the Site.

The SMP details activities that will be undertaken until the Environmental Easements are extinguished in accordance with ECL Article 71, Title 36 and includes, in summary:

- Site-wide inspections will be performed annually. Modification to the frequency or duration of the inspections will require approval from the NYSDEC.
- Sitewide inspections will be documented through completion of an inspection form.
- Preparation of a PRR on an annual basis or as otherwise determined by the NYSDEC.

The frequency of PRRs was reduced from annually to every five-years beginning in 2017.

1.2.1 Progress During the Reporting Period

Inspections were completed in accordance with the SMP; however, only one inspection form was available to Inventum (Appendix A).

1.2.2 Progress to Remedial Objectives for the Site

The Remedial Action Objectives (RAOs) for the Site were established in the December 2011 Interim Remedial Measure Work Plan (IRM Work Plan) and are summarized below. The RAOs have been met through implementation of the remedial program and continued compliance with the SMP.

- Reduce or control, to the extent practicable, the constituents present in the soil at concentrations exceeding the SCOs applicable to the intended use of the property parcels;
- Control the potential for human exposure to the constituents in soil exceeding the applications SCOs:
- Control the physical hazards associated with the buildings and other appurtenances on the Site; and;
- Excavate and dispose of soils identified to exceed the TCLP Standard.

NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

1.3 Compliance

1.3.1 Potential Non-compliance

There were no potential areas of non-compliance identified during the PRR reporting period. Inventum will ensure completion of future annual inspection forms.

1.3.2 Proposed Steps

Not applicable.

1.4 Recommendations

1.4.1 Recommended Changes to the SMP

There are no recommended changes to the SMP at this time.

1.4.2 Recommend Changes to the Frequency for Submittal of PRRs

There is no recommended change to the frequency of the PRRs at this time.

1.4.3 Recommend Whether the Requirements for Discontinuing Site Management

It is appropriate to continue Site Management.

2 Site Overview

2.1 Site Location

The Site is located in Niagara Falls, Niagara County, New York and is identified on the Niagara County Tax Map as Section 144.06, Block 2, 27.1 Lot 34.

The Site consists of approximately 5.9 acres bounded by Tulip Corporation to the north, Tract II Property to the south and east, and Highland Avenue to the West (Figure 1). Historically, the Site was used as a lead/acid battery manufacturing plant for approximately 40 years, from 1910 to the 1950s. The plant was retooled in the early 1950s to produce rubber battery casings. In addition to the rubber battery casings, the plant began filling and charging lead/acid batteries as well. In the 1970s the site ceased manufacturing operations and was used as warehouse space as well as an automotive body shop. By the late 1980s, the Site had been abandoned. The City of Niagara Falls acquired the property via tax foreclosure in 1999. In May of 2000, a Site Characterization was conducted by Ecology and Environment, inc. (E&E) under the New York State Environmental Restoration Program (ERP). Lead, PAHs, and PCBs were detected above applicable SCOs and E&E's findings were documented in a Site Investigation Report. In 2011, the City of Niagara Falls withdrew from the ERP, after additional investigations found elevated levels of lead, arsenic, mercury, zinc, and PAHs. Shortly after, Brightfields purchased the Tract I property from the City of Niagara Falls. In December of 2011, a BCP application was submitted with a Draft IRM WP for the demolition and decontamination of the on-Site structure.

In November of 2021, the plant was purchased by Stryten Energy, headquartered in Alpharetta, Georgia. Current Site operations remain unchanged. Institutional Controls remain in place and unchanged.

2.2 Chronology of the Remedial Program

The remedial action at the Site consisted of the excavation and off-site disposal of soils exceeding both the Commercial Use SCO and the TCLP lead standard. The remedial action was completed in November

NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

2014. Soil that exceeded the TCLP standard of 5 mg/L was treated prior to off-site disposal. The excavated areas of the Site were backfilled with either crushed construction debris that met the Commercial SCO or imported fill that met the applicable Allowable Constituent Levels for Import Fill for Soil under 6 NYCRR Part 375. No demarcation layer was required as part of the remedy or controls. After completion of the remediation, the soil met the Commercial Use SCOs throughout the soil column.

In May of 2016 construction began on Tract I, for an 80,000sqft, clear span, slab on grade, one story light industrial/ commercial, steel butler building. The southwest corner has some office space used by facility management and office personnel. There is a small mezzanine located above the offices used as a break room and employee locker room. Construction was completed in January 2017. Disposal manifests for soils transported offsite during the 2016-2017 main building construction were provided in the 2017 PRR. In May of 2020, a 20,000sqft addition was built on the north side of the existing structure. The addition is the same design as the main structure referenced above and within the footprint of the excavation/grading that occurred for the main building completed in 2017. There was no change in allowable site use as a result of the new construction. No additional soils were transported offsite. Building occupancy for the addition and other relevant permits issued during the reporting period are included in Appendix B.

3 Evaluate Remedy Performance, Effectiveness, and Protectiveness

The performance, effectiveness, and protectiveness of the remedy are verified through evaluating each of the primary remedial measures.

• Site-wide inspections indicate that the compliance to the Site ICs established by the environmental easements, were maintained during the PRR reporting period. An Inspection Form for the reporting period is provided in Appendix A.

4 IC/EC Plan Compliance Report

4.1 IC/EC Requirements and Compliance

A series of IC have been developed and are being adhered to by the Site environmental easement. These ICs are designed to:

- Limit the Site to commercial and/or industrial uses;
- Prohibit groundwater use;
- Implement a SM reporting system in a frequency and manner defined in the SMP; and
- Provide access to the Site for agents, employees, or other representatives of the State of New York.

4.1.1 Controls

No engineering controls (EC) are required for the site.

4.1.2 Status

The Site ICs are all currently active and in force.

NYSDEC Site Number C932157

Dates Covered by Report: January 16, 2017 to January 16, 2022

4.1.3 Corrective Measures

There are no corrective measures proposed at this time.

4.2 IC/EC Certification

The IC/EC certifications are provided in Enclosure A.

5 Monitoring Plan Compliance Report

5.1 Monitoring Plan Compliance Report

Routine Site Monitoring includes annual Site-wide inspection and periodic certification.

5.2 Monitoring Completed During Reporting Period

Site inspections were conducted as required by the SMP; however, only one inspection form was available to Inventum (Appendix A). Inventum will ensure future documentation of the annual inspection. Appendix A.

5.3 Components of the Monitoring Plan

The Site-wide inspection (Appendix A) documents that:

- ICs continue to perform as designed;
- ICs continue to be protective of human health and the environment;
- Compliance with requirements of the SMP and the Environmental Easement were maintained over the PRR reporting period;
- Remedial performance criteria continue to be achieved; and
- Site records are complete and up to date, reference EPA No. NYD074024456 for additional information.

5.4 Monitoring Deficiencies

There were no monitoring deficiencies during the reporting period.

5.5 Conclusions and Recommendations for Changes

No changes to the monitoring program are recommended.

6 Operation & Maintenance (O&M) Plan Compliance Report


The Site remedy does not rely on any mechanical systems to protect public health and the environment; therefore, an O&M Plan Compliance Report is not applicable to this PRR.

7 Overall PRR Conclusions and Recommendations

Site IC/ECs remain in place and effective in maintaining the remedial objectives. No changes to the established SMP or recommended during the next PRR reporting period.

Tract I Highland Ave Site Management Periodic Review Report 3123 Highland Ave NYSDEC Site Number C932157 Dates Covered by Report: January 16, 2017 to January 16, 2022

Figures



Tract I Highland Ave Site Management Periodic Review Report 3123 Highland Ave NYSDEC Site Number C932157 Dates Covered by Report: January 16, 2017 to January 16, 2022

Appendix A – Engineering Controls –Site-Wide Inspection Form

Site Inspection Form

Site Name:	Brightfields/ T	ract I	Weather: <u>Cool, Cloudy</u>
Project Number: 12008			Assessment By: John Yensan
Date: Nover	mber 1, 2019		
<u>Yes</u>	<u>No</u>	<u>N/A</u>	A Site Line
0 0 0 0		M 0 0	 A. Site Use 1. Evidence for Change in Property Usage? 2. Evidence of Groundwater Use? 3. Evidence of vegetable gardening/farming? 2. Day Care or Other Non-Permitted Use Present? 3. Evidence of Excavation? 4. Proper Notification for Excavation Made? 5. CAMP and/or HASP Revised for Excavation
	X X		B. Security1. Signs of Trespassers/Vandalism?2. Other
			C. General Site Conditions1. Vegetation Stress?2. Mowing Required?3. Access Road Drivable?4. Odors?5. Other
	88888808		 D. Soil Inspection 1. Exposed Waste? 2. Side Slope Stable? 3. Erosion? 4. Leachate Seeps (Discolored Vegetation)? 5. Bare Spots? 6. Presence of Burrowing Animals? 7. Deep Rooted Vegetation? 8. Cracking? 9. Other
			 E. Surface Water 1. Obstruction of Flow Ditches? 2. Erosion of Ditches? 3. Silt & Erosion Control? 4. Culverts in Good Condition? 5. Evidence of Overflow or Uncontrollable Flow? 6. Outfalls in Good Condition? 7. Other

Green Remediation Implementation:	
Energy Usage: N/A	
Solid Waste Generation: Dumpster on site for collection and disposal of refuse blown onto	
property from adjacent public ROW's and residential properties.	
Transportation and Shipping: N/A	
Water Usage: N/A	
Other Comments: None.	

Tract I Highland Ave Site Management Periodic Review Report 3123 Highland Ave NYSDEC Site Number C932157 Dates Covered by Report: January 16, 2017 to January 16, 2022

Appendix B – Construction and Occupancy Permits

BUILDING PERMIT

City of Niagara Falls
Department of Code Enforcement
745 Main Street, Niagara Falls, NY 14302-0069
(716) 286-4450 (716) 286-4454 fax

(716) 286-4450	(716) 286-4454 fax	Website: www.NiagaraFallsUSA.org		
Property Address:		Tax Map Number:		
3123 Highland Ave		144.06-2-27.1		
Property Owner:				
NIAGARA COUNTY IDA	A			
Name: BOB FRIT: Address: 424 WOOI City,St,Zip: N. TONAW Phone: (716) 380-	Applicant	1 GE RP OAK HILL BUILDING COMPANY INC. 3556 LAKESHORE ROAD BUFFALO, NY 14219 (716) 822-4966 Ins Exp:		
AND THE PROPERTY OF THE PARTY O	DDITION TO INDUSTRIAL BUILDING	AS PER DRAWING TO CODE		
	CORPORATION - RK SHALL COMPLY WITH NYS EXECU	ITIVE ODDED 202 6		
Lille 3. ALL WOI	W SHALL COMPLET WITH WTS EXECU	TIVE ONDER 202.0		
Total Cost:	316,600 Total Squar	e Feet: 0		
Mandatory Inspections	Special Instructions to Applicant.			
Required	PECTIONS AT 286-4450 - 24 Hours No	Applicant/Contractor MUST Call Underground Facilities Protective Organization (UFPO) at least two days before startin excavation - (1-800-962-7962)		
FOUNDATION EXCAVA	for Permit: 2020-10343			
FOOTING-FOUNDATION		Applicant/Contractor are responsible to contact the New York State Department of Labor regarding asbestos Regulations -		
BUILDING ROUGH		Industrial Code Rule 56 - (716-847-7126)		
ELECTRICAL ROUGH		The undersigned applicant certifies that the plans and specifications		
INSULATION		as filed are in accordance with the regulations and ordinances of the		
FINAL ELECTRICAL		City of Niagara Falls and the State of New York and agree that all		
FINAL BUILDING		work and materials shall be in strict conformity with the Laws		
PLUMBING ROUGH		governing building in this City, and the State of New York.		
FINAL PLUMBING		BOB FRITSCHI being duly sworn says that he/she is the same		
Processed by:	Robert Stanley	person mentioned and described in and who signed the forgoing application; that he/she has read same, or heard it read, and knows		
Inspector:	Joseph Chick	the contents thereof, and that he/she is the owner of the above mentioned premisses or the person authorized by said owner to		
	xamined the forgoing application pplicable laws of the City of	make the foregoing application. But Andry (RS)		
Building Commissioner	Date	(Applicant / Agent's signature)		

THIS APPROVED PERMIT MUST BE ON PREMISES DURING CONSTRUCTION

Permit No: 2020-10343

Applicant	Inspector	Fire Prevention	File	- Billing & Collections

5/14/2021

Expires:

5/14/2020

Issued:

Printed: 3/17/2021 1:31:14 PM

City of Niagara Falls CERTIFICATE FOR: 2020-10343

Page 1 of 1

Property Owner Name:

Property Address Location:

Tax Map Number(SBL):

NIAGARA COUNTY IDA

3123 Highland Ave

144.06-2-27.1

ERECT ADDITION TO INDUSTRIAL BUILDING AS PER DRAWING TO CODE - TULIP CORPORATION -

> DEPARTMENT OF CODE ENFORCEMENT CITY OF NIAGARA FALLS 745 MAIN STREET NIAGARA FALLS, NY 14302-0069 (716) 286-4450 CERTIFICATE OF OCCUPANCY

This Certificate Dated March 17, 2021 is Hereby Issued To:

<----- Applicant

Name: BOB FRITSCHI

Address: 424 WOODLIN AVE.

City, St, Zip: N. TONAWANDA, NY 14120

Type: 0230 ADD TO INDUSTRIAL

Floors

Lbs Per Sq Ft Occupancy

Construction Type

1ST

COM 100 LBS FACTORY F-1

NON-COMBUSTABLE IIB

Inspected By: JC,ML,EP

This certifies that the above described existing building complies, to the best of my knowledge and belief, with the applicable laws and ordinances in effect at the time of construction and may continue to be used as designated.

This Department is not responsible for any minor deficiences which may exist and does not assume responsibility for those systems or construction which are not clearly visible during inspection and which may have been approved at the time of construction of such building.

Building Commissioner

Certificate Fee: \$0.00