

CATTARAUGUS COUNTY LEGISLATURE OFFICE Gerard J. Fitzpatrick, Chairman

303 Court Street Little Valley, New York 14755

Telephone: 716.938.9111, ext. 2386 Fax: 716.938.9698

November 28, 2005

Chief, Site Control Section New York State Department of Environmental Conservation Division of Environmental Remediation 625 Broadway Albany, NY 12233-7020

Dear Site Control Section Chief:

Enclosed please find Cattaraugus County's application for an Environmental Restoration Program (ERP) grant for the Former Randolph Foundry Site located in Randolph, New York. It is the County's intent to utilize the funds to perform an investigation and possibly an Interim Remedial Measure (IRM) to remove some drums and other materials.

The former foundry and machine shop includes an abandoned cement block office and sheet metal manufacturing/warehouse type building. The abandoned structure, which is severely dilapidated and may be structurally unsound in some portions, contains a large garage/work area, workshop areas, former parts and machining areas, storage rooms and office type areas. Various debris, equipment, foundry sands and materials from former processes are still located at the site including some 55-gallon drums and other small containers of materials.

Historical maps indicate that a foundry and machine shop was located on the property as early as 1902 and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years. The recent Phase I Environmental Site Assessment identified potential recognized environmental conditions in connection with the subject property including the following: its history as a solid waste landfill, potential contamination associated with foundry sands and slag piles as well as other materials and wastes; various 55-gallon drums and other containers which are in poor condition and contain unknown contents; and potential PCBs associated with the elevated transformers. Additionally, since the property is severely dilapidated and may be structurally unsound in some portions, removal of wastes and securing the area is considered essential.

The purpose of the project is to perform a detailed site investigation to determine the likelihood and level of contamination and to determine the remedial measures necessary for re-use. Interim remedial measures, such as drum/container and waste identification/removal may be completed during this Phase as an interim remedial measure to enhance site safety and in advance of building demolition.

Cattaraugus County has identified the restoration and redevelopment of brownfields as a critical component of the County's effort to mitigate the severe industrial decline and accompanying rise in unemployment and poverty that the County and the Southwestern New York region has experienced for many years. With the help of the ERP grant, Cattaraugus County can investigate the property and remediate the property which will result in benefit to the safety of the community, the environment and an economic benefit to the county and state. The exact final re-use plan is unknown at this time, however, a portion of the property is anticipated to be considered for commercial or retail use. If contamination levels are low or easily remediated, it is possible that a future residential use is considered.

Current Village needs/site considerations include use for light industrial, re-location or additional facility for a furniture company currently doing business in the Village; re-location or new building for a metallic

ladder manufacturing facility currently operating in the Village; or for the Village highway/other department building.

Thank you for your consideration. The County has completed a pre-application meeting with NYSDEC Region 9 staff to review the site in terms of ERP applicability. We look forward to working with the NYSDEC to alleviate the current state of this Brownfields property and to improve the economic future of the citizens and industries of Cattaraugus County.

Very truly yours,

Gerard J. Fitzpatrick, Chairman Cattaraugus County Legislature

xc: Mr. Martin L. Doster, P.E. New York State Department of Environmental Conservation Regional ERP Contact – Region 9 270 Michigan Avenue Buffalo, New York 14202-2999



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

ENVIRONMENTAL RESTORATION PROGRAM (ERP) APPLICATION 1996 CLEAN WATER/CLEAN AIR BOND ACT

ECL ARTICLE 56 - 6NYCRR 375-4

8/9/04

Applicant Information					Ser Maria	
NAME OF MUNICIPALITY Cattaraugus Cou	NAME OF MUNICIPALITY Cattaraugus County					
NAME OF INDIVIDUAL AUTHORIZED TO SIGN	APPLICATION Mr. Ger	ard J. Fitzpatrick				
TITLE OF AUTHORIZED INDIVIDUAL Chairm	an of Legislature					
ADDRESS 303 Court Street						
CITY/TOWN Little Valley		ZIP CODE 14755				
PHONE 716-938-9111 Ext. 2310	FAX 716-938-9431		E-MAIL jgkeller(@eatteo.c	org	
NAME OF COMMUNITY BASED ORGANIZATIO	N (IF APPLICABLE) NOT	Applicable				
COMMUNITY BASED ORGANIZATION'S REPRE	SENTATIVE					
ADDRESS				_		
CITY/TOWN		ZIP CODE				
PHONE	FAX		E-MAIL			
Site Information						
SITE NAME Former Randolph Foundry Site						
SITE ADDRESS 2-8 Sheldon Street						
CITY/TOWN Randolph		ZIP CODE 14772				
COUNTY Cattaraugus		SIZE (ACRES) 0.94				
LATITUDE 42 09 31 LONGITUDE 78 58 56						
PLEASE ATTACH A COUNTY TAX MAP WITH IDENTIFIER NUMBERS, ALONG WITH ANY FIGURES NEEDED TO SHOW THE LOCATION AND BOUNDARIES OF THE SITE ALSO INCLUDE A USGS 7.5 MINUTE QUAD MAP IN WHICH THE SITE IS LOCATED						
I DO THE SITE BOUNDARIES CORRESPOND TO TAX MAP METES AND BOUNDS? IF NO, PLEASE ATTACH A METES AND BOUNDS DESCRIPTION OF THE SITE IF NO, PLEASE ATTACH A METES AND BOUNDS DESCRIPTION OF THE SITE					DNO	
2 IS THE SITE PART OF A DESIGNATED BROWNFIELD OPPORTUNITY AREA PURSUANT TO GML970-R ² IF YES, IDENTIFY AREA (NAME)			⊠ _{NO}			
3 IS THE SITE LISTED ON THE NYS REGISTR IF YES, FILL IN CURRENT REGISTRY SITE			SITES?	□YES	V NO	
REGISTRY SITE NUMBERCLASSIFICATION						

A	oplican	t Eligibility Information				
1.	FOR OR	E APPLICANT GENERATED. TRANSPORTED OR DISPOSED OF, OR ARRANGED CAUSED THE GENERATION, TRANSPORTATION OR DISPOSAL OF, DOUS WASTE OR PETROLEUM ON THE SITE?	□yes	⊠ NO		
2	OBLIGA	E APPLICANT UNDERTAKEN, OR INTEND TO UNDERTAKE, ANY INDEMNIFICATION TION RESPECTING A PARTY RESPONSIBLE UNDER LAW FOR THE ATION OF THE SITE?	DYES	Z NO		
3	TRANSF GENER/	E APPLICANT LEASED THE SITE TO ANOTHER PARTY THAT GENERATED, ORTED OR DISPOSED OF, OR THAT ARRANGED FOR OR CAUSED THE ITION, TRANSPORTATION OR DISPOSAL OF HAZARDOUS WASTE OR EUM ON THE SITE? IF YES, CHECK ONE OF THE FOLLOWING	□ _{YES}	⊠NO		
	Δ Α.	THE APPLICANT DID NOT KNOW THAT SUCH OTHER PARTY GENERATED. TRANSPORTED OR DISPOSED OF, OR ARRANGED FOR OR CAUSED THE GENERATION, TRANSPORTATION OR DISPOSAL OF SUCH HAZARDOUS WASTE OR PETROLEUM				
	В	THE APPLICANT KNEW THAT SUCH OTHER PARTY GENERATED. TRANSPORTED OR DISPOSED OF, OR ARRANGED FOR OR CAUSED THE GENERATION, TRANSPORTATION OR DISPOSAL OF SUCH HAZARDOUS WASTE OR PETROLEUM AND DID NOT TAKE ACTION TO REMEDIATE OR CAUSE THE REMEDIATION OF SUCH HAZARDOUS WASTE OR PETROLEUM				
	С	THE APPLICANT KNEW THAT SUCH OTHER PARTY GENERATED. TRANSPORTED OR DISPOSED OF, OR ARRANGED FOR OR CAUSED THE GENERATION, TRANSPORTATION OR DISPOSAL OF SUCH HAZARDOUS WASTE OR PETROLEUM AND TOOK ACTION TO REMEDIATE OR CAUSE THE REMEDIATION OF SUCH HAZARDOUS WASTE OR PETROLEUM				
4		IE APPLICANT CURRENTLY OWN THE SITE OR HAS IT OBTAINED TEMPORARY ITS OF OWNERSHIP FOR AN INVESTIGATION PURSUANT TO ECL 56-0508?	V YES	DNO		
Pr	oject I	Description				
PLI EN	EASE ATT VIRONME	ACH A DESCRIPTION OF THE PROJECT WHICH INCLUDES THE FOLLOWING INFORMATION (REFER T NTAL RESTORATION PROGRAM PROCEDURES HANDBOOK FOR DETAILED INSTRUCTIONS)	O THE			
 PURPOSE AND SCOPE OF THE PROJECT. CURRENT AND PROPOSED FUTURE USE OF THE SITE (RESIDENTIAL, COMMERCIAL, INDUSTRIAL). ESTIMATED PROJECT COST (INCLUDE ANY RESPONSIBLE PARTY COST RECOVERY PAYMENTS RECEIVED OR ANTICIPATED, AS WELL AS ANY OTHER ACTUAL OR POTENTIAL FUNDING SOURCES FOR THE PROJECT). HOW THE PROJECT WOULD SATISFY THE CRITERIA OF ECL 56-0505, AND ESTIMATED PROJECT SCHEDULE (FIELD WORK MUST BEGIN WITHIN 12 MONTHS OF THE APPLICATION APPROVAL DATE) 						
Si	te's En	vironmental History				
то		ENT THAT EXISTING INFORMATION/STUDIES/REPORTS ARE AVAILABLE TO THE APPLICANT. PLEAS	SE ATTACH	I THE		
 ENVIRONMENTAL DATA A PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT PREPARED IN ACCORDANCE WITH ASTM E 1527 (American Society for Testing and Materials Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process). AND ALL ENVIRONMENTAL REPORTS RELATED TO CONTAMINANTS ON OR EMANATING FROM THE SITE. 						
-	2 OWNERS A LIST OF PREVIOUS OWNERS WITH NAMES, LAST KNOWN ADDRESSES AND TELEPHONE NUMBERS (DESCRIBE APPLICANT'S RELATIONSHIP, IF ANY, TO EACH PREVIOUS OWNER LISTED IF NO RELATIONSHIP, PUT "NONE")					
3						

Contaminant Info	ormation	San Alexandre		We de stat	-Start	
NDICATE KNOWN OR S	USPECTED CONTAN	IINANTS AND THE MEDIA	WHICH ARE KNOWN OR	SUSPECTED TO HA	VE BEEN	AFFECTED.
Contaminant Category	Soil	Groundwater	Surface Water	Sediment		Soil Gas
Petroleum	1					
hlorinated Solvents						
Other VOCs	1					
VOCs	1					
fetals	1					
esticides						
CBs						
Aher*	1					
		or Remediation Proj			DYES	
		ATER BODY BEEN CONTA			UYES UYES	
THREATE B A CLASS A CONTAME C GROUNDW	NED OR AA SURFACE W NATED WITHOUT AF	R PRIVATE WATER SUPPI ATER BODY OR A PRIMA FECTING AN EXISTING W NTAMINATED ABOVE ST	RY OR PRINCIPAL AQUIFI Ater Supply	ER HAS BEEN		
HAVE ENDANGEREI	D. THREATENED OR	RARE SPECIES, STATE PRO ED BY RELEASES FROM TI		STATE	□YES	$\square_{\rm NO}$
	TS PRESENT IN SOILS EMEDIATION GUID	SWASTE AT LEVELS THA' ANCE VALUES?	FEXCEED DEC DIVISION	OF	□YES	□ _{NO}
IS THE SITE LOCATE	ED IN A DESIGNATEI	DEMPIRE ZONE?			D YES	DNO
IS THE SITE LOCATE	ED IN A DESIGNATEI	DEN-ZONE PURSUANT TO	TL § 21 (b)(6)'		D YES	DNO
HAS ALL OR PART C	F THE SITE BEEN ID	LE OR ABANDONED FOR !	MORE THAN ONE YEAR?		D YES	DNO
HAS THE APPLICAN ONCE IT IS RESTORI		MENT WITH A PRIVATE P	ARTY TO REUSE THE SIT	Ē	VES	□ _{NO}
HAS THE APPLICAN	T COMMITTED TO A	NEW PUBLIC OR RECREA	TIONAL USE?		D YES	DNO
REGARDING THIS A	CTION ⁹ IF YES, INCL NT) IN THE ATTACH	HE STATE ENVIRONMENT .UDE THE DETERMINATIO ED PROJECT DESCRIPTIO W	N (NEGATIVE DECLARA	TION OR	DYES	□ _{NO}
		JNDING SOURCES FOR RE AR AMOUNT IN THE ATT.		PTION	TYES	□ _{NO}

I VALUE AND ADDRESS OF ADDRESS OF ADDRESS ADDRE	NAMES OF TAXABLE	CALMAN T + C	of the second second second	
Munici	ngunu	WO PTIT	100 TIO DE	
UTILITIE	DAILUNE	Gunn	ICAUUI	

The undersigned on behalf of the applicant does hereby certify that:

- All statements made for the purpose of obtaining State assistance for the proposed project either are set out in full in this application, or are set out in full in exhibits attached to this application and incorporated by this reference; and
- · The individual whose signature appears hereon is authorized to sign this application for the municipality.

A FALSE STATEMENT MADE HEREIN IS PUNISHABLE AS A CLASS "A" MISDEMEANOR PURSUANT TO SECTION 210.45 OF THE PENAL LAW

Signature of Individual Authorized to Sign the Application

128/200

Community Based Organization Certification (if applicable) -

The undersigned on behalf of the Community Based Organization acting in partnership with the municipality does hereby certify that:

- The Community Based Organization is a not-for-profit corporation, exempt from taxation under section 501(c)(3) of the internal revenue code whose stated
 mission is promoting reuse of brownfield sites within a specified geographic area in which the Community Based Organization is located, which has 25%
 or more of its board of directors residing in the community in such area;
- · The Community Based Organization represents a community with a demonstrated financial need,
- Not more than 25% of the members, officers or directors of the Community Based Organization are or were employed by or receiving compensation from any person responsible for a site under title 13 or title 14 of article 27 of the Environmental Conservation Law, article 12 of the navigation law or under applicable principles of statutory or common law liability; and
- . The individual whose signature appears hereon is authorized to sign this application for the Community Based Organization.

A FALSE STATEMENT MADE HEREIN IS PUNISHABLE AS A CLASS "A" MISDEMEANOR PURSUANT TO SECTION 210.45 OF THE PENAL LAW.

Signature of Individual Authorized to Sign for the Community Based Organization

Date

SUBMITTAL INFORMATION:

Four (4) complete copies, one with original signatures, are required.

• Three (3) of the copies, one with original signatures, must be sent to:

Chief, Site Control Section New York State Department of Environmental Conservation Division of Environmental Remediation 625 Broadway Albany, NY 12233-7020

One (1) copy must be sent to the DEC regional contact in the regional office covering the county in which the site is
located. Please check our website for the address of our regional offices: http://www.dec.state.ny.us/website/der/index.html

The Department encourages applicants to submit an electronic copy (CD or diskette) of the application and attachments in addition to what is required above.

Partners of the second s			
FOR DEPARTMENT US	SE ONLY:		
ERP SITE NO:	ERP SITE T&A CODE:	PROJECT MANAGER:	

ATTACHMENT 1

SITE INFORMATION - Tax Map - Quad Map




Figure 1. Project areas location in Village of Randolph, Cattaraugus County, New York (USGS 7.5' Quadrangle, Randolph, NY 1986 [1965]).




Figure 3. Tax map of subject and adjacent properties.

ATTACHMENT 2

Project Description

Environmental Restoration Program (ERP) Application

Project Description

A. Purpose and Scope

The application is for an investigation grant.

The former foundry and machine shop property is approximately179 feet by 229 feet and includes an abandoned cement block office and sheet metal manufacturing/warehouse type building. The abandoned structure, which is severely dilapidated and may be structurally unsound in some portions, contains a large garage/work area, workshop areas, former parts and machining areas, storage rooms and office type areas. Various debris, equipment, foundry sands and materials from former processes are still located at the site including some 55-gallon drums and other small containers of materials. These drums are rusty and in poor condition. Foundry sand covers much of the warehouse/manufacturing area and piles are located in some areas. Parts of the site are heavily vegetated and some vegetation is growing within the more dilapidated sections. A lager hopper is located in the rear of the structure as are two large elevated transformers.

Historical maps indicate that a foundry and machine shop was located on the property as early as 1902 and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years. The recent Phase I Environmental Site Assessment identified potential recognized environmental conditions in connection with the subject property including the following: its history as a solid waste landfill, potential contamination associated with foundry sands and slag piles as well as other materials and wastes: various 55-gallon drums and other containers which are in poor condition and contain unknown contents; and potential PCBs associated with the elevated transformers. The property is in very poor condition, may be structurally un-sound in portions and has wastes and materials strewn throughout the interior.

The purpose of the project is to perform a detailed site investigation to determine the likelihood and level of contamination and to determine the remedial measures necessary for re-use. The investigation will follow the Remedial Investigation/Alternatives Analysis (RI/AA) guidance as provided in the Division of Environmental Remediation's Technical Guide (DER-10 - Technical Guidance for Site Investigation and Remediation). The investigation will result in a Record of Decision (ROD). The recommended remedial actions contained in the ROD will be completed by the County or a private entity who will re-develop the site. Interim remedial measures, such as the completion of building demolition, may be completed during this Phase as an interim remedial measure to enhance site safety.

The goal will be to:

- Identify if contamination exists and to define the nature and extent of contamination, if any
- Identify contamination source areas
- Provide data of sufficient quantity and quality for remedial decision making; and
- Evaluate the a sufficient range of remedial alternatives to enable the preparation of a PRAP and ROD.

The specific objectives are:

- identify existing conditions and to evaluate the nature of the fill material and other features such as the site boundary
- analyze specific media including soil and groundwater
- identify and delineate the contaminants of concern,
- identify specific environmental media, potential pathways and affected receptors, if any
- identify specific impacts to the planned re-development and identify the extent of remediation necessary, to meet the property specific needs.
- develop sufficient information to allow development of remedial alternatives.
- to meet or exceed American Society of Testing and Materials (ASTM) E 1903.97 guidance and NYSDEC Brownfields Cleanup Program guidance for investigations and reports
- Assess the presence and extent of hazardous waste at the site, if any, and determine the consequential amount.

The scope of work and reporting will be performed in accordance with the NYSDEC Brownfield Cleanup Program Guide and other NYSDEC guidance (Procedures Handbook and DER-10).

The proposed scope of work is based on the findings of a Phase I Environmental Assessment completed on the property in 2005. The purpose the site assessment will be to determine the likelihood of contamination at the property especially associated with past use. This information will allow for the screening of various technologies for their capability to meet specific cleanup and redevelopment concept plan objectives.

Specific activities will include:

- Perform a site boundary and topographic survey to identify existing conditions and to create a base map for field activities
- Advance a series of test trenches and/or geoprobe boring points at specific defined locations across the property to verify surface and subsurface conditions and to examine visible C&D debris.
- analyze specific media including surface and subsurface soil and groundwater
- Perform a drum and container inventory/sampling
- Perform sampling of interior areas/foundry sands
- Perform sampling below the cement floors
- Verify Ownership and PCB Content of transformers
- identify the contaminants of concern, if any
- identify specific environmental media, potential pathways and affected receptors, if any
- identify any impacts to a development concept plan
- identify extent of remediation necessary, if any, to meet the property specific development goals of redevelopment.

A phased assessment approach is recommended for this site. The first phase assessment will be limited in scope to determine if the possibility of contamination exists (examine "hot spots"). If based on this assessment, contamination is identified, a more focused investigation will be conducted based on the findings of the initial phase.

Based on the findings of the Phase I ESA, the following RI/AA tasks have been identified:

FIELD INVESTIGATION TASKS

1) Project Scoping and Preparation of Work Plans which describes the activities, QA/QC, and health and safety

2) Site Investigation

A remedial investigation will be performed which will include a surface and subsurface soil assessment program including background and residential samples, assessment of groundwater, sub-slab assessment and drum/waste inventory.

Drum/Container Inventory

A drum/waste material inventory will be performed and will precede any building demolition. Initially, using the information gathered during the Phase I such as site history, description of operations performed at the site, and the types of wastes that were generated in the past will be used to help determine the types of wastes that might be present. The following tasks:

- Identify waste drums/containers present
- Consecutively number each drum/container with a unique Drum ID#
- Prepare an inventory which will include, at a minimum
 - Drum/container ID#
 - Size of waste container
 - Type of waste container
 - Condition of waste container
 - Physical description of drum contents (physical state, pH, color, odor, additional field testing as warranted)
 - Field notes and comments
- Prepare a summary of results with minimum analysis necessary for proper characterization (for example, RCRA characteristics, TCLP).
- Sampling and Analysis
- Packaging, Transportation and Disposal

Additionally, a sampling program of foundry sands/slag within the structure will be completed and a detailed inventory of equipment/debris within the facility will be completed to determine the potential for hazardous materials/reuse/disposal.

Surface and Subsurface Soil Assessment

Surface and subsurface conditions and possible soil contamination on this site will be investigated to assess the environmental condition of the property in general prior to re-development. The soil assessment may involve the use of either borings and/or trenches. Surface soil samples will be obtained using dedicated stainless steel spoons from the upper two inches under the sod layer or from the upper two inches of the slit trench/boring.

Materials in debris piles and soil from each slit-trench (approx. 1 foot wide by 4-8 feet long)/borings will be visually described and screened using an organic vapor detector (i.e., PID). Stratification of material in the trenches/borings and observations of soil staining will be noted on the trench/boring logs. Subsurface soil samples will be collected from each test trench/boring from the intervals which indicate contamination either through visual, odor, or PID readings.

Groundwater Assessment

The initial program will also include a limited groundwater sampling program of three to five wells. Based on the subsurface soil assessment results, the need for additional groundwater sampling will be determined. If soil contamination exceeding guidance levels is detected, or, if other information indicates potential for groundwater contamination, additional sampling will be recommended and planned.

Analytical Program

Samples will be analyzed for RCRA metals, and Target Compound List VOCs, SVOCs, PCBs, and STARS petroleum compounds. The results will be compared to current DEC NYSDEC TAGM 4046 Guidance Values/TOGS and or other DEC Brownfields guidance values. Assessment of subsurface conditions will also use visual/olfactory observations and volatile organic screening and the results of the samples submitted for analysis, as deemed necessary based on field observations.

Sub-Slab Investigation

Additionally, areas under the concrete floor will also be examined using borings. The County is examining demolition costs and it is possible that demolition of the building may precede the site subsurface site investigation. If it is desirable to limit destruction of the cement pad, borings will be conducted in this area using Geoprobe® direct push technology over conventional drilling to reduce costs and increase the speed. Continuous soil sampling will be performed using the Geoprobe® with a two-inch diameter sampler resulting in three to five distinct sample cores (i.e., 0-4', 4-8', 8-12', 12-16', 16-20') at each location.

If the fill material is limited to foundry sands and C&D debris, it is anticipated that only minor remedial/removal activities will be required to allow future industrial/commercial use of the property.

SI/IRM

Interim remedial measures may be undertaken at this property to precipitate and/or in concert with building demolition. These may include drum and container removal and removal of other solid wastes including the foundry sands.

3) Identification of Remedial Goals

Based on the data obtained from the first phase of the site investigation, potentially applicable remedial alternatives will be identified for the site. The data subsequently will be reviewed to determine whether there are any data gaps which need to be addressed so that the remedial alternatives can be more fully developed and evaluated. This task will be implemented concurrently with the site investigations, and will, out of necessity, be iterative in nature. Data from the field will be input into the development of the alternatives and in turn, the potential remedial alternatives will dictate the type of data which needs to be collected. At the completion of the first phase site investigation, should it be determined that there are obvious data gaps which will require supplemental investigations to be performed Supplemental Investigations will be implemented.

4) Qualitative Exposure Assessment

Should it be determined during the Site Investigation that the contaminants at the site pose a potential risk to human health and/or the environment, then a qualitative risk assessment (RA) will be performed. This RA will address the potential risk associated with exposure of humans and/or wildlife to contaminated media. This RA will be based on a no-action scenario (i.e., it will be assumed that the site will not be remediated prior to continued recreational use as a park). This will allow the risk associated with current conditions to be assessed.

The data collected during the field investigation will be utilized in the RA to assess the potential migration pathways, identify potential chemicals of concern, and potentially exposed populations (i.e., future park users, maintenance workers and other park workers) and/or wildlife. The health risks will be assessed for all completed exposure pathways. Under a future park use scenario, employees, patrons, and maintenance workers would possibly be exposed to soil via ingestion, dermal contact and inhalation of fugitive dust, and to inhalation of vapors from contaminated soil via utilities, sumps, etc.

The results of the RA will be utilized to determine whether or not the site is suitable for some other use such as light industrial and/or commercial/retail development without remediation, or will require some type of remediation for continued use. The results will also be used in evaluating various potential remedial alternatives which might be implemented at the site to mitigate the potential health risks and to negotiate cleanup levels with NYSDEC.

5) Alternative Analysis

A list of media-specific (groundwater, soil/fill, air,) remedial action objectives will be developed prior to initiation of the SI, and will be refined throughout the SI based on the site characterization data generated by the site investigation. These objectives will keep in mind the anticipated future use of the site, the nature of contaminants present, and potential risk posed to human health and the environment. A comparison between site contaminants, and contaminant-specific cleanup criteria (TAGM 4046) will aid in the determination of the remedial action objectives.

Following development of potentially applicable remedial alternatives, a detailed evaluation of the alternatives will be performed in accordance with the DEC requirements of Remedy Selection.

Alternatives developed will be subjected to a detailed evaluation in order to select the most appropriate and cost-effective remedy for the site in accordance with the DEC guidance documents.

Based on the comparison made under the Analysis of Alternatives, one alterative or approach will be recommended for remediation of the site. This alternative will provide protection to public health and the environmental and be consistent with State clean-up goals, while attaining SCGs in a cost-effective manner.

Since a focused remedial approach or presumptive remedy will likely be undertaken for the site, the Screening of Alternatives step generally undertaken will, in all likelihood, be eliminated. If however, more evaluation is necessary to select between two similar alternatives, the alternatives will be screened with respect to: protecting human health and the environment; attaining SCGs; cost-effectiveness; utilizing permanent solutions or resource recovery technologies to the maximum extent practicable; and satisfying regulatory preferences for treatment that reduces toxicity, mobility, or volume.

6) RI/AA Report

Following completion of the development and evaluation of alternatives, a RI/AA Report will be prepared. This report will summarize the various technologies which were considered, the evaluation and selection of preferred technologies, assembly of selected technologies into alternatives, detailed evaluation of the alternatives, and selection of the preferred alternative for the site. The report will be prepared under the direction of, and be stamped by an engineer licensed to practice in the State of New York. The report will be combined with the SI to form a single report.

7) Public Participation

Public Participation will be key on this project especially since surface soil samples will be necessary in residential yards. A Citizen Participation (CP) plan as per ECL 56-0505.2 will be a component of the project and will be part of the project work plan. This will be submitted to and approved by the DEC prior to the RI fieldwork. The plan will include the requirements in the DEC Procedures Handbook Section 6.2. and Section 8 of the Brownfield Cleanup Program Guide.

B. Description of Current and Proposed Future Use of the Property

With formal addresses of 2 - 8 Sheldon Street (historic Sanborn maps indicate the properties addresses may have changed) in the Village of Randolph. Cattaraugus County, New York, the property is currently vacant. The property is located on the northwestern corner of the intersection of Washington and Sheldon Streets. Adjacent to the property to the east is railroad lines for the Southern Tier Railway Authority.

The property is located in the Village of Randolph within two miles of the center of the village area. The property is generally flat and generally sloping from northeast to southwest and is located within a mixed commercial/residential/business area of the Village of Randolph. The subject property is located in an area currently zoned within a "Village Residential District" and is surrounded by residential homes (both single and multi-family), small commercial, industrial, and retail businesses including a self storage facility. Residential properties are immediately adjacent to the property along its northern and western sides. Adjacent properties include: the Southern Tier Railway to the north and east of the property, and residential structures located on Sheldon and Green Streets to the west, southwest of the property.

The intended re-use will result in benefit to the safety of the community, the environment and in either an economic benefit to the state or a public recreational use. The exact final re-use plan is unknown at this time, however, a portion of the property is anticipated to be considered for commercial or retail use. If contamination levels are low or easily remediated, it is possible that a future residential use is considered.

Current Village needs/site considerations include use for light industrial:

- Re-location or additional facility for a furniture company currently doing business in the Village
- Re-location or new building for a metallic ladder manufacturing facility currently operating in the Village
- Village highway/other department building

C. Estimated Project Costs

The estimated project costs are estimated to be \$135,000. Most of this cost will be associated with costs subcontracted to laboratories, drillers, and backhoe. The following is a breakdown of the cost by task:

TASK	LABOR & ODC COST	SUBCONTRACTOR COST	TOTAL
1 Scoping Meeting/Workplan	\$1.000	\$4,000	\$5,000
2. Site Investigation	\$10,000	\$68,000	\$78,000
SI/IRM	\$3,000	\$22,000	\$25,000
3-5. Remedial Alternatives	\$2,000	\$8,000	\$10,000
6. Report	\$2,000	\$8.000	\$10,000
7. Public Participation	\$2,000	5,000	\$7,000
TOTALS	20,000	\$115,000	\$135,000

D. Estimated Schedule

The estimated schedule is as follows:

Approval of Application: Selection of Professional Consultant/Contract: Completion of Investigation Completion of RI/AA Report Completion of PRAP and ROD December 2005/January 2006 February/March 2006 July 2006 September 2006 January 2007

E. ECL 56-0505 Criteria

a) Benefit to the environment realized by the expeditious remediation of the property

The property is in very poor condition, may be structurally un-sound in portions and has wastes and materials strewn throughout the interior. The area is not fenced off and is open to the public representing a health and safety threat. The expeditious remediation would allow for this concern to be eliminated.

b) The economic benefit to the state by the expeditious remediation of the property

The County and Village desperately needs to have the property put to reuse and to have developable space made available. This effort will primarily attract new business and industry and will expand the real estate tax base while creating new permanent full-time jobs in the private sector. Reclaiming and reusing the property will encourage investment and development. The site is located adjacent to an active rail line and to the downtown area and represents a potential available commercially zoned properties where business could locate.

c) The potential opportunity of the property proposed to be the subject to such project to be used for public recreational purposes

The property is located adjacent to residential housing and an active railroad. It is possible that the future use involves a public park or some recreational use, if it is not re-used for commercial purposes.

d) Real property in a designated brownfield opportunity area pursuant to section nine hundred seventy of the general municipal law

The property is currently not in a BOA, however, the County and Village may be interested in pursuing a BOA which will link this property to other parcels in the Village.

e) The opportunity for other funding sources

See below

F. Other Funding Sources

The County is developing a list of potential other funding sources such as use of the Appalachian Regional Commission (ARC) Grant Program, Southern Tier West Development Foundation, HUD, DOT and others.

4. County Tax Map and USGS Quad Map

See attached

5. Site's Environmental History and Existing Data

In June-July 2005, A Phase I Environmental Site Assessment (ESA) was completed on the property for the County. As part of the Phase I, a review of NYSDEC Region 9 records was completed and indicated that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. and that approximately 1,500 pounds of foundry sand was disposed per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling occurred from 1976 to about 1981. The company initiated a permit application (permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead

reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property, however, this adjacent property is not owned by the County and not part of the ERP.

The former foundry and machine shop property is approximately179 feet by 229 feet and includes an abandoned cement block office and sheet metal manufacturing/warehouse type building. The abandoned structure, which is severely dilapidated and may be structurally unsound in some portions, contains a large garage/work area, workshop areas, former parts and machining areas, storage rooms and office type areas. Various debris, equipment, foundry sands and materials from former processes are still located at the site including a few 55-gallon drums and other small containers of materials. These drums are rusty and in poor condition. Foundry sand covers much of the warehouse/manufacturing area and piles are located in some areas. Parts of the site are heavily vegetated and some vegetation is growing within the more dilapidated sections. A lager hopper is located in the rear of the structure as are two large elevated transformers.

A review of historic aerial and Sanborn maps as well as building permit records indicate that the current structures and property have been altered over time. The exact date that the existing structure was built is unknown, however, historical maps indicate that a foundry and machine shop (F. H. Pike Foundry and Machine Shop) was located on the property as early as 1902. By 1929, historic maps indicate that the property was identified as the Randolph Foundry and Machine Shop. As late as 1897 however, a dairy was located on the front portion of the property. Individuals with knowledge of the history of the Village indicate the Randolph Foundry was at one time owned by Aeolian (verified also by ownership records) and made piano plates out of recycled metal. The foundry was later sold and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years.

Historically, land use in the property area has been commercial/retail and residential properties. A rail line has historically been located immediately adjacent to the eastern portion of the property. The subject property is located in an area currently zoned within a "Village Residential District" and is surrounded by residential homes (both single and multi-family), small commercial, industrial, and retail businesses. Residential properties are immediately adjacent to the property along its northern and western sides. Adjacent properties include: the Southern Tier Railway to the north and east of the property, and residential structures located on Sheldon and Green Streets to the west, southwest of the property.

Foundries (or metal casting operations) make parts from molten metal according to end user specifications. Since the historic maps indicate that the facility was also a machine shop, it implies that the parts (castings) were used to produce larger products such as machinery, motor vehicles, appliances, plumbing fixtures, etc. In this case, at least for a time, parts for pianos. In general, foundry and machine shops are typically somewhat "dirty" operations and involved with the manufacturing, prefabrication, and repair of articles of steel, iron, and other metals. Environmental contamination associated with these facilities include elevated levels of lead and other metals in near and subsurface soils and wastes associated with slag/foundry sands such as phenols. Other

contaminants, including solvents and petroleum products are typically associated with drummed materials.

Portions of the property contain small debris piles. C&D material including brick, concrete block, and wood is located on the south-southeastern front portions of the property. The material appears to be rubble from the former structures. A large pile of concrete, brick, cement, and wood are located in grassy and weed covered areas along the southern portion of the property. Historical maps indicate that a boarding house/dairy was located in this area of the property during the early 1900's.

The Phase I assessment identified potential recognized environmental conditions in connection with the subject property including the following: its history as a SWF/LF, potential contamination associated with foundry sands and slag piles as well as other materials and wastes; various 55-gallon drums and other containers which are in poor condition and contain unknown contents; and potential PCBs associated with the elevated transformers. The property is in very poor condition, may be structurally un-sound in portions and has wastes and materials strewn throughout the interior. A copy of the Phase I has been submitted to the Regional NYSDEC office under separate cover.

6. Proof of Ownership

See attached

ATTACHMENT 3

Site Environmental Data

- Phase 1 (1 copy separate attachment due to size) - List of Owners - List of Operators

ERP Application Site's Environmental History

1) Environmental Data

Refer to attached Phase I Environmental Site Assessment (note Phase I has not been added to electronic copy due to size and nature of attachments). One hard copy is attached. A hard copy has also been provided to Mr. Marty Doster, Region 9 NYSDEC.

2) Owners

List of Owners as follows:

			2 - 8 Sheldon Street	
Liber	Page	Sale Date	From	<u>Tø</u>
2743	5007	03-09-2005	Donald Cresanti	Cattaraugus County
875	215	10-29-1987	Aeolian Pianos, Inc.	Donald Cresanti
504	524	09-03-1952	Randolph Foundry and Machine	Metallic Ladder Manufacturing Corp

3) Operators

List of previous operators are as follows (refer also to historic Sanborn maps attached to the Phase I and electronically):

The exact date that the existing structure was built is unknown, however, historical maps indicate that a foundry and machine shop (F. H. Pike Foundry and Machine Shop) was located on the property as early as 1902. By 1929, historic maps indicate that the property was identified as the Randolph Foundry and Machine Shop. Individuals with knowledge of the history of the Village indicate the Randolph Foundry was at one time owned by Aeolian (verified also by ownership records) and made piano plates out of recycled metal. The foundry was later sold and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years.

Foundries (or metal casting operations) make parts from molten metal according to end user specifications. Since the historic maps indicate that the facility was also a machine shop, it implies that the parts (castings) were used to produce larger products such as machinery, motor vehicles, appliances, plumbing fixtures, etc. In this case, at least for a time, parts for pianos. In general, foundry and machine shops are typically somewhat "dirty" operations and involved with the manufacturing, prefabrication, and repair of articles of steel, iron, and other metals. Environmental contamination associated with these facilities include elevated levels of lead and other metals in near and subsurface soils and wastes associated with slag/foundry sands such as phenols. Other

contaminants, including solvents and petroleum products are typically associated with drummed materials.

A review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. A review of NYSDEC Region 9 records indicates that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. and that approximately 1,500 pounds of foundry sand was disposed per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling occurred from 1976 to about 1981. The company initiated a permit application (permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property.

A brief summary of pertinent information concerning the property based on a review of historic Sanborn maps is as follows:

1885 Map

This map shows that a dairy was located on the property. The rail road (New York/Pennsylvania/Ohio Railroad) existed along the northern and eastern border. Additionally lumber storage is shown on the property along the rail road tracks. Washington Street (known as Depot Street) was adjacent to the northeast. The Randolph Furniture Company was located on the adjacent corner (southeast) of Sheldon and Depot Street.

1891 Map

The 1891 map shows that the same structures present in the 1885 Map however the lumber storage along the railroad tracks is a much larger area. The furniture company located on the adjacent corner (southeast) of Sheldon and Depot Street was called Pearl Furniture Company.

1897 Map

The lumber storage was no longer shown. The furniture company located on the adjacent corner (southeast) of Sheldon and Depot Street was changed to the Elko Paint Company.

1902 Map

The 1902 map shows the F.H. Pike Foundry and Machine Shop located on the northwestern corner of Sheldon and Depot Street. This map shows a Foundry building and the small building previously on the subject property. The lumber storage was no longer present on the property.

1907 Map

This map shows the F.H. Pike Foundry and Machine Shop facility with multiple combined structures occupying the central portion of the property. The machine shop appears larger and there are approximately two sheds to the rear (northwest) of the main structure. A boarding house was located closer to the corner and appears to be the original dairy building depicted on earlier maps.

1913 Map

There is little change from the 1907 map.

1929 Map

This map indicates that the F.H. Pike building is now called the Randolph Foundry and Machine Shop. The main structure has grown in size and the shed in the rear is considered a coke shed. Depot Street is now known as South Washington Street.

1937 Map

This map is unchanged from the 1929 Sanborn Map.

ATTACHMENT 4

Copy of Deed

	CATTARAUGUS Cattaraugus County C Little Valley (716) 9		
No. of Pages:	2	Delivered By: TA	X PARCEL 279
Receipt No.	27435	Return To:	
DATE:	03/10/2005		
Time:	11:46 AM		
Document Type:	DEED		
Parties To Transa	ction: CRESANTI BY TREAS	TO CATT CO	
Town/City:	RD - Randolph		
Deed Infor	mation	Mortga	ge Information
Consideration:	\$0.00	Mortgage Amo	bunt
Transfer Tax:	\$0.00	Basic Mtge. Ta	ax:
RETT No:	02333	Special Mtge. Additional Mtg	

State of New York Cattaraugus County Clerk

Mortgage Serial No .:

This sheet constitutes the Clerk endorsement required by Section 316-A(5) & Section 319 of the Real Property Law of the State of New York. DO NOT DETACH

Dame K. Griffette

 Cattaraugus County Clerk

 *
 2
 7
 4
 3
 5
 0
 0
 7
 *

THIS INDENTURE

Made the 28th day of February, in the year Two Thousand and Five,

BETWEEN Joseph G. Keller, Treasurer of Cattaraugus County, State of New York, party of the first part, and the County of Cattaraugus, State of New York, party of the second part,

WHEREAS, at a Special Term of the County Court of Cattaraugus County, State of New York, held at Little Valley on the 15th day of February, 2005, it was among other things, Ordered, Adjudged and Decreed by said Court in a certain action then pending in the said Court entitled:

> "In the Matter of the Foreclosure of Tax Liens pursuant to Article 11 of the Real Property Tax Law by the County of Cattaraugus List of Delinquent Taxes for 2002",

with respect to all and singular the premises mentioned in the aforesaid judgment and including the premises hereinafter described,

"ORDERED, that all proceedings in this action were duly and properly taken pursuant to Article 11, Title 3 of the Real Property Tax Law of the State of New York, and there has been full and due compliance with the provisions of Article 11, Title 3 of the Real Property Tax Law, and it is further

ORDERED, ADJUDGED AND DECREED that the County of Cattaraugus is hereby granted and awarded possession of every parcel of property described in the Petition and Notice of Foreclosure not heretofore redeemed or withdrawn from foreclosure, and as to which no Answer has been properly interposed, or withdrawn, the same being the parcels more fully described in the last paragraph of this Order, and the Treasurer of the County of Cattaraugus is hereby directed to prepare, execute and cause to be recorded, deeds conveying full and complete title to such parcels to the County of Cattaraugus, pursuant to Section 1136 of the Real Property Tax Law, and it is further

ORDERED, ADJUDGED AND DECREED that upon the execution and recording of such deeds, the County of Cattaraugus shall be seized of an estate in fee simple absolute in all the parcels described therein, and all persons, including the State of New York, infants, incompetents, absentees and non-residents who may have had any right, title, interest, claim, lien or equity of redemption in or upon such parcel shall be, and hereby are, barred and forever foreclosed of all such right, title, interest, claim, lien or equity of redemption in such parcel and each and every part thereof..."

WHEREAS, the aforesaid order and judgment of the said Court was duly entered in the Office of the Clerk of Cattaraugus County on the 16th day of February, 2005.

NOW THIS INDENTURE WITNESSETH, That the said Treasurer of Cattaraugus County, the party of the first part to these presents, in order to carry into effect the direction to him to execute proper conveyances in pursuance of the order and judgment of said Court, and in conformity to the Statute in such a case made and provided, and also in consideration of the premises and \$1.00 and other good and valid consideration, hath bargained and sold, and by these presents doth grant and convey unto the assigns an estate in fee simple absolute in the following described premises including all the right, title and interest of any person having, or claiming to have, an interest therein and more particularly that which the following said persons and parties,

RO Cresanti, Donald, RD 2, Russell PA 16145 RO Cresanti, Donald, 4065 High Point Rd, Winston Salem NC, 27107-3603 had at the time of the commencement of the said action, in and to the following described premises situated in the Town of Randolph, Cattaraugus County, New York, being Parcel 279 according to the Petition and Notice of Foreclosure filed with the Cattaraugus County Clerk on October 7, 2004, and further described as being:

Part of Lot 23, Town 2, Range 9, about 179.00' X 229.00', Acct. No. 0724, TM #70.071-3-16, SHELDON ST

TO HAVE AND TO HOLD THE same to the party of the second part, the County of Cattaraugus, its successors and assigns forever.

IN WITNESS WHEREOF, the Treasurer of the County of Cattaraugus, for the time being, in pursuance of the authority vested in him by law, hath hereunto set his hand affixed the seal of this office the day and year first above written.

¥.2 sh. E aller

Tax Collecting Officer and Treasurer of the County of Cattaraugus, New York

State of New York

County of Cattaraugus

: 33.

2

On this \underbrace{qh}_{day} day of March, 2005, before me, the undersigned, a Notary Public in and for said State, personally appeared JOSEPH G. KELLER, personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that he executed the same in his capacity, and that by his signature on the instrument, the individual, or the person upon behalf of which the individual acted, executed the instrument.

carv

ROBYN FISHER Notary Public, State of New York No. 01FI6073406 Qualified in Cattaraugus County Commission Expires April 22, 2008

ATTACHMENT 5

County of Cattaraugus Resolution

(The resolution was discussed by county legislative committees on October 19, if it was approved, it will be voted on by the County Legislature on October 26)

CATTARAUGUS COUNTY



John R. Searles, Clerk of the Legislature

November 8, 2005

Mr. Peter J. Gorton, President Panamerican Environmental Inc. 2390 Clinton St. Buffalo, NY 14227

Dear Mr. Gorton:

Enclosed you will find a certified resolution of Act Number 485-05, adopted by the Cattaraugus County Legislature on October 26, 2005.

If you have any questions regarding this resolution, please do not hesitate to contact my office at (716) 938-9111, ext. 2232.

Sincerely,

Lori A. Pangborn, Deputy Clerk Cattaraugus County Legislature

llap

Enclosure

AUTHORIZING THE CHAIR TO APPLY FOR STATE ASSISTANCE FROM NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION FOR FORMER RANDOLPH FOUNDRY CLEANUP

Pursuant to Article 56 of the Environmental Conservation Law and the Clean Water/Clean Air Bond Act of 1996.

I. WHEREAS, the County of Cattaraugus, herein called the "Municipality", after thorough consideration of the various aspects of the problem and study of available data, has hereby determined that certain work, as described in its application and attachments, herein called the "Project", is desirable, is in the public interest, and is required in order to implement the Project, and

II. WHEREAS, Article 56 of the Environmental Conservation Law authorizes State assistance to municipalities for environmental restoration projects by means of a contract and the Municipality deems it to be in the public interest and benefit under this law to enter into a contract herewith, now, therefore, be it

I. RESOLVED, that the Chair of the Legislature be, and hereby is, authorized and directed to make application, execute the State Assistance contract, submit Project documentation, on behalf of Cattaraugus County, in all matters related to the Project and State assistance under Environmental Conservation Law Article 56, Title 5 with New York State, and be it further

II. RESOLVED, that the Municipality agrees that it will fund its portion of the cost of the Project and that funds will be available to initiate the Project's field work within twelve (12) months of written approval of its application by the Department of Environmental Conservation, and be it further

III. RESOLVED, that the Clerk of the Legislature is hereby directed to forward one certified copy of this resolution to the New York State Department of Environmental Conservation together with the Application for State Assistance, and be it further

IV. RESOLVED, that this authorization shall take effect immediately. Fiscal Impact: none

STATE OF NEW YORK) COUNTY OF CATTARAUGUS)

I, the undersigned, Deputy Clerk of the Legislature of the County of Cattaraugus, New York, do hereby certify that I have compared the foregoing copy of Resolution Act No. 485-2005 of the Legislature of Said County of Cattaraugus with the original thereof on file in my office and duly adopted by said Legislature at a meeting of said Legislature on the 26^{th} day of October, 2005, and that the same is a true and correct copy of such resolution and of the whole thereof.

In testimony whereof, I have hereunto set my hand and affixed the seal of said County this 8th day of November, 2005.

Lori A. Pangborn, Deputy Clerk Cattaraugus County Legislature

PHASE I ENVIRONMENTAL SITE ASSESSMENT FORMER FOUNDRY BUILDING AND PROPERTY SHELDON STREET TOWN OF RANDOLPH, CATTARAUGUS COUNTY, NEW YORK

Prepared for:

Cattaraugus County 303 Court Street Little Valley, New York 14755

Attention:

Mr. Joseph Keller Treasurer

Prepared by:

Panamerican Environmental, Inc. 2390 Clinton Street Buffalo, New York 14227 Ph: (716) 821-1650 Fax: (716) 821-1607

June - July 2005

Submitted by:

Peter J. Gorton, MPH, CHCM

A Phase I Environmental Site Assessment (ESA) was completed by Panamerican Environmental, Inc. (PEI) for the one-story cement block and metal framed building and former foundry/machine shop property, located on the northwest corner of Sheldon Street and South Washington Street (2-8 Sheldon Street) in the Village of Randolph, Cattaraugus County, New York. Performed for Cattaraugus County, the ESA was conducted in accordance with ASTM standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Practice E 1527-00 (ASTM Standard). In defining a standard of good commercial and customary practice for conducting an environmental assessment of a parcel of property, the goal of the process established by the ASTM Standard is to identify recognized environmental conditions. This Phase I was conducted to meet this goal. Recognized environmental conditions are defined in the ASTM Standard as the presence or the likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum onto or effecting the property.

Investigative activities included agency interviews, site inspections, and interviews with representatives of the local government and local historians, as well as a review of government and historical Village of Randolph records.

The site is unsecured. The former foundry and machine shop property is approximately179 feet by 229 feet and includes an abandoned cement block office and sheet metal manufacturing/warehouse type building. The abandoned structure, which is severely dilapidated and may be structurally unsound in some portions, contains a large garage/work area, workshop areas, former parts and machining areas, storage rooms and office type areas. Various debris, equipment, foundry sands and materials from former processes are still located at the site including some 55-gallon drums and other small containers of materials. These drums are rusty and in poor condition. Foundry sand covers much of the warehouse/manufacturing area and piles are located in some areas. Parts of the site are heavily vegetated and some vegetation is growing within the more dilapidated sections. A lager hopper is located in the rear of the structure as are two large elevated transformers.

A review of historic aerial and Sanborn maps as well as building permit records indicate that the current structures and property have been altered over time. The exact date that the existing structure was built is unknown, however, historical maps indicate that a foundry and machine shop (F. H. Pike Foundry and Machine Shop) was located on the property as early as 1902. By 1929, historic maps indicate that the property was identified as the Randolph Foundry and Machine Shop. As late as 1897 however, a dairy was located on the property. Individuals with knowledge of the history of the Village indicate the Randolph Foundry was at one time owned by Aeolian (verified also by ownership records) and made piano plates out of recycled metal. The foundry was later sold and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years.

Historically, land use in the property area has been commercial/retail and residential properties. A rail line has historically been located immediately adjacent to the eastern portion of the property. The subject property is located in an area currently zoned within a "Village Residential District" and

Panamerican Environmental, Inc.

is surrounded by residential homes (both single and multi-family), small commercial, industrial, and retail businesses. Residential properties are immediately adjacent to the property along its northern and western sides. Adjacent properties include: the Southern Tier Railway to the north and east of the property, and residential structures located on Sheldon and Green Streets to the west, southwest of the property.

Foundries (or metal casting operations) make parts from molten metal according to end user specifications. Since the historic maps indicate that the facility was also a machine shop, it implies that the parts (castings) were used to produce larger products such as machinery, motor vehicles, appliances, plumbing fixtures, etc. In this case, at least for a time, parts for pianos. In general, foundry and machine shops are typically somewhat "dirty" operations and involved with the manufacturing, prefabrication, and repair of articles of steel, iron, and other metals. Environmental contamination associated with these facilities include elevated levels of lead and other metals in near and subsurface soils and wastes associated with slag/foundry sands such as phenols. Other contaminants, including solvents and petroleum products are typically associated with drummed materials.

Portions of the property contain debris piles. C&D material including brick, concrete block, and wood is located on the south-southeastern front portions of the property. The material appears to be rubble from the former structures. A large pile of concrete, brick, cement, and wood are located in grassy and weed covered areas along the southern portion of the property. Historical maps indicate that a boarding house was located in this area of the property during the early 1900's.

A review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. A review of NYSDEC Region 9 records indicates that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. and that approximately 1,500 pounds of foundry sand was disposed per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling occurred from 1976 to about 1981. The company initiated a permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property.

A total of eight (8) additional database records were found for the adjacent and surrounding properties within the ASTM government records search radius. These include seven Spills Information Database (LTANKS) sites, and one registered Underground Storage Tank facility.

This assessment has identified potential recognized environmental conditions in connection with the subject property including the following: its history as a SWF/LF, potential contamination associated with foundry sands and slag piles as well as other materials and wastes; various 55-gallon drums and other containers which are in poor condition and contain unknown contents; and potential PCBs associated with the elevated transformers. The property is in very poor condition, may be structurally un-sound in portions and has wastes and materials strewn

Panamerican Environmental, Inc.

throughout the interior.

Based on the information reviewed for this Phase I ESA, PEI cannot verify with complete certainty that near-surface or subsurface contamination or other environmental impairment does not exist at this property, especially with regard to the foundry sand/slag observed throughout the structure and rubble piles. These may have migrated to both on-site and offsite soils especially since the property operated as a foundry and machine shop for approximately 84 years. In summary, PEI believes that potential environmental risk may be associated with this property and that follow-up assessment may be necessary to determine if contamination exists.

TABLE OF CONTENTS

Sec	Page			
List	of Append	nmary lices raphs and Illustrations	vi	
1.0	INTROD 1.1 1.2 1.3	UCTION Introduction and Purpose	. 1 . 1 . 1	
2.0 3.0		 3.2 General Property and Area Features		
4.0	SITE 4.1 4.2	HISTORYHistorical Sources ReviewedSite and Area Historical Chain of Use4.2.1Chain of Title Information4.2.2Chain of Use Records4.2.3Aerial Photographs4.2.4Sanborn Maps and Other Historical Maps	. 8	

	4.3 Previous Environmental Studies/Historical Data
5.0	REGULATORY/AGENCY RECORDS REVIEW
6.0	OTHER RECORDS REVIEWED/INTERVIEWS CONDUCTED116.1 City Offices116.2 County Offices126.3 NYSDEC Files126.4 Interviews12
7.0	REVIEW OF SPECIAL RESOURCES127.1 Historic Resources127.2 Farmlands127.3 Recreational Areas127.4 Land Use137.5 Wetlands and Floodplains13
8.0	ENVIRONMENTAL ASSESSMENT SUMMARY, CONCLUSIONS AND RECOMMENDATIONS
9.0	DATA NEEDS
10.0	WARRANT AND LIMITATIONS

LIST OF APPENDICES

Appendix

- Aerial Photographs Α.
- ASTM Detailed Radius Database Report Β.
- Site Photographs C.
- D.
- Ε.
- Area/Property Maps Property Title and Assessment Information NYSDEC FOIL and NYSDEC File Information F.

LIST OF PHOTOGRAPHS AND ILLUSTRATIONS

Aerial Photographs

1.	1956	Aerial Photograph
••	1000	, toniar i notographi

- 2. 1966 Aerial Photograph
- 3.1980Aerial Photograph
- 4. 1995 Aerial Photograph
- 5. 2002 Aerial Photograph

Photograph

- 1. Adjacent property to the west (10 Sheldon) of the subject property, facing north.
- 2. Subject property from across Sheldon Street, facing northeast.
- 3. Western portion of subject property, facing north.
- 4. Subject property from the corner of Sheldon and Washington Streets, facing northwest.
- 5. Two pole mounted transformers in the southern portion of the property.
- 6. Weeds, telephone pole and piping debris on the subject property on Sheldon and Washington corner.
- 7. Concrete, miscellaneous material, and grass and weed covered area in the southern portion of the property.
- 8. Pile of debris in the southern portion of the property.
- 9. Inside the southeastern portion of the structure, facing west.
- 10. Eastern portion of the structure, facing north.
- 11. Southeastern portion of the structure, facing east.
- 12. Former AST used for burning of materials located in the southeastern portion of the structure.
- 13. Possible pile of foundry sand and other miscellaneous debris located in the eastern portion of the structure.
- 14. Junk automobile and other debris in the eastern portion of the structure.
- 15. Foundry sand and northwestern area of the eastern portion of the structure, facing northwest.
- 16. Western area of the eastern portion of the structure, facing south.
- 17. Storage of concrete mix and other materials in the northwestern area of the eastern portion of the structure.
- 18. Two large furnaces or molds and other debris located within a pit in the middle of the eastern area of the structure.
- 19. Portions of ceiling and walls in the eastern area of the structure that are in disrepair.
- 20. Large machine on tractor trailer bed unknown use.
- 21. Small storage/electrical area in the northern portion of the structure.
- 22. Two 55-gallon drums near the pit where the furnaces/molds were located.
- 23. Miscellaneous materials in large room of western area of structure.
- 24. Another view of large room of western area and scattered debris/tires.
- 25. 5-gallon pails and other debris in the southern portion of the large room of the western side of the structure.
- 26. Miscellaneous debris located in the western large room, facing southwest.
- 27. Storage of miscellaneous materials in small storage area to the east of the large western room.

- 28. Electrical boxes near the offices in the western portion of the structure.
- 29. Insulation and overhead garage door opening to the southern portion of the structure.
- 30. Storage shelving and bathroom in the southwestern end of the structure.
- 31. Small office area in the southwestern corner of the structure.
- 32. Miscellaneous storage and piping located in the western area of the structure.
- 33. Storage of miscellaneous materials in western area.
- 34. Water-dispense mechanism tied to water pipes in the western portion of the structure.
- 35. Western portion of the structure.
- 36. Area behind large storage unit in the eastern area of the structure.
- 37. Storage unit in the eastern portion of the structure.
- 38. Subject property and structure from the intersection of railroad tracks and Washington Street, facing southwest.
- 39. 55-gallon drum and other miscellaneous debris in weed covered area to the northwest of the subject building.
- 40. Transformers of poles to the rear (north) of the structure.
- 41. Hopper to the rear (north) of the structure.
- 42. 5-gallon containers located in the western portion of the building.

Property/Area Maps

- 1. Project location
- 2. Historical Sanborn maps
- 3. Tax Map

1.0 INTRODUCTION

1.1 INTRODUCTION AND PURPOSE

Panamerican Environmental, Inc. (PEI) performed a Phase I Environmental Site Assessment (ESA), of the Randolph Foundry property and structure located at 2-8 Sheldon Street (northwestern corner of South Washington and Sheldon Streets) in the Village of Randolph, Cattaraugus County, New York. The Phase I ESA has been conducted as part of a due diligence review for a transfer of ownership.

The purpose of this ESA is to evaluate the potential for environmental impairment at the site based on current conditions, as well as present and past activities at the subject property and adjacent properties.

1.2 SCOPE

The scope of work and services for this ESA were performed in accordance with American Society for Testing and Materials (ASTM) Standards E-1527-00, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process." The scope of work performed for this evaluation includes:

- observation of current land-use within 0.5 mile of the site;
- identification of known environmental problems within 1 mile of the site;
- · review of information regarding past uses of the site and adjacent properties;
- review of historical information;
- walkover reconnaissance of the property; and
- review of records at federal, state, and local agencies.

To conduct tasks related to environmental database searches, PEI identified, obtained and reviewed local records to assess whether the property has, or adjacent properties have, posed any environmental hazard in the past, or currently pose such a threat. An environmental database report is included in Appendix B and is summarized in Section 5.

Phase I property reconnaissance tasks were completed by Mr. Peter J. Gorton and Justin J. Ryszkiewicz of PEI on June 22, 2005 and are summarized in Section 1.3. As part of this process, research was also conducted at Village of Randolph, Cattaraugus County and State of New York offices. Services provided also included:

- acquisition and review of aerial photographs and historic Sanborn maps of the property and adjacent land to assess property uses;
- acquisition and review of available local records and documents regarding the site and adjacent land;

The results of these efforts are summarized throughout the report.

1.3 SITE RECONNAISSANCE

Site reconnaissance was conducted on June 22, 2005 to inspect physical features and make

general observations regarding the subject property and adjacent areas. The following tasks were completed:

- visual inspection of the property and the surrounding property was conducted to identify potential environmental impacts existing on the property or from adjacent areas. All rooms at the facility were entered;
- various property features were photographed;
- visual surface observations were made to identify any evidence of spills, such as stains or spills in facility areas or on soil or vegetative stress;
- a survey of adjacent properties was conducted.

The results of the reconnaissances are summarized below and provide a representation of property conditions at the time of the site visit (current conditions). A photographic record is included in Appendix C.

1.3.1 SUMMARY OF OBSERVATIONS

The site is unsecured and vacant. The former foundry and machine shop property is approximately179 feet by 229 feet and includes an abandoned cement block office and sheet metal manufacturing/warehouse type building. The abandoned structure, which is severely dilapidated and may be structurally unsound in some portions, contains a large garage/work area, workshop areas, former parts and machining areas, storage rooms and office type areas. Various debris, equipment, foundry sands and materials from former processes are still located at the site including some 55-gallon drums and other small containers of materials. These drums are rusty and in poor condition. Foundry sand covers much of the warehouse/manufacturing area and piles are located in some areas. Parts of the site are heavily vegetated and some vegetation is growing within the more dilapidated sections. A lager hopper is located in the rear of the structure as are two large elevated transformers.

The property is located in a moderately residential and industrial/commercial area in the Village of Randolph. The property is relatively flat, sloping from northwest to south-southeast.

The following summarizes specific observations noted during the property reconnaissance.

Sheldon Building and Building Interior

- The building area can be accessed from the eastern portion of the property through one overhead door entrance or two single door and overhead doorway along the south wall.

- The walls in the office and storage areas are concrete block.

- The floors are a combination of wood and concrete in the office area, which also has ceiling tile and flourescent light fixtures.

- An overhead garage door entrance is located near the office.

- There is an unisex restroom and a large stockroom to the north of the office (Photograph 30).

- A large storage area (in close proximity to the offices - refer to Photographs 23 to 27), contains concrete and wooden floors and a metal roof. There are various items scattered throughout the area (including 55-gallon drums, 5-gallon containers, and various other materials). There is a small concrete ramp that leads to the overhead garage door opening.

- The garage/manufacturing area (refer to Photographs 9 through 22) contains concrete and

wooden floors, along with wooden, concrete block and metal walls and ceilings. Many areas (ceilings and walls) were in disrepair and parts of the garage were open to the elements. There is miscellaneous debris scattered throughout the area including: containers of paint and paint thinners, gasoline/oils, other cleaning chemicals, machines, automobiles and various parts, building and construction debris (wood, brick, insulation, etc.). Foundry sand/slag was observed across the floor area and in large piles on the floor in the western part of the garage area. Two large furnaces or molds were located within a pit in the middle of this area.

Sheldon Property Exterior

The observations made on the exterior portion of the property are as follows:

Southern Property Area

The majority of the southern portion (refer to Photographs 6 through 8) of the property is covered by thick vegetation and grass. Three separate piles of construction and demolition debris (concrete, wood, brick, etc) were observed. Two pole mounted transformers were also observed. Observations of the ground debris were difficult to make due to the thick vegetation.

Western Portion

The western portion of the property is mostly manicured grass covered along the streets and adjacent residence.

Northern Portion

The northern area is also heavily covered in vegetation. The area immediately to the north of the structure, to the south of the fence, appears to have been used to discard metal products. Several, apparently empty 55-gallon drums, metal rails and crates were observed throughout this area. A pile of cinder blocks were also observed. The area is difficult to walk through due to the mounds of materials and the thick vegetation. Two old transformers were observed on an elevated platform in this area. A large hopper was located outside the building in this area.

Eastern Portion

The eastern portion of the property is grass and concrete covered. The rail lines are in close proximity of this area.

1.3.2 PRIMARY PROPERTY USES

The primary use of the subject property was as a foundry and machine shop from the early 1900's for about 84 years. The building and properties are currently abandoned.

1.3.3 TREATMENT, STORAGE OR DISPOSAL FACILITY (TSDF)

The property is not a TSDF and no areas were observed.

1.3.4 HAZARDOUS WASTE/SUBSTANCES

A review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. The previous site owner disposed of foundry sand on an adjacent lot (see 1.3.9 below).

There were a number of containers observed on the property of unknown contents. Additionally, a large amount of foundry sand which is potentially hazardous for metals and may contain phenols was observed throughout the general warehouse area. It is unknown if past use of the property included impacts to surface/subsurface soil.

1.3.5 ABOVE GROUND/UNDER GROUND CHEMICAL/PETROLEUM STORAGE TANKS (AST/UST)

There is no visible evidence that USTs ever existed on this property. A spill site (Randy's Garage property) was identified in the radius search and is located within close proximity of the subject property (refer to appendix B).

1.3.6 PCB CONTAINING EQUIPMENT

Fluorescent light fixtures were located throughout the structure. Based on the age of these fixtures, it is possible that they contain PCB contaminated fluid within the ballasts. Two sets of pole-mounted transformers were also observed on the exterior portion of the building. It is unknown if the transformers were located on the subject property or the adjacent eastern property and it is also unknown if the transformers are PCB containing.

1.3.7 ASBESTOS CONTAINING MATERIAL/LEAD-BASED PAINT

Potential asbestos containing materials (ACM) were not observed during the site visit. However, due to the age of the building, ACM and lead-based paint is possibly associated with some of the building materials and interior and exterior surfaces of the structure.

1.3.8 STAINS, SPILLS, STRESSED VEGETATION

No major stains, spills, or stressed vegetation were observed outside the facility, however, the floor area was mostly covered with debris and foundry sand. There were a few areas of small staining within the building including oily stained concrete floors - the various areas of staining observed included a portion of the concrete and wooden floors in the garage and storage portions of the building.

1.3.9 LANDFILLS/DUMPING ACTIVITIES

Portions of the property contain debris piles. C&D material including concrete pieces, brick, concrete block, soil fill and wood is located on the eastern and southern exterior portions of the property. As described, the material appears to rubble from a former structure. Due to their size, configuration and vegetation in the area, visual observations could not be made of the contents of

the entire piles and therefore other materials may exist. As mentioned, a review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. A review of NYSDEC Region 9 records indicates that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. And that approximately 1,500 pounds a day of foundry sand was transported per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling was started in 1976 to about 1981. The company initiated a permit application (permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property.

1.3.10 PITS, SUMPS, WELLS

No pits, wells, or sumps were observed on the property and there is no record of wells associated with this property.

1.3.11 PONDS AND LAGOONS

No ponds or lagoons were observed on the property.

1.3.12 COASTAL AREAS

The property does not fall under any coastal zone erosional management.

1.3.13 POTABLE WATER SUPPLY

The property has access to public water.

1.3.14 SEWAGE DISPOSAL

Assessor records indicate private sewers. There were no records found regarding a septic system on the property.

1.3.15 ROADS AND PARKING LOTS

The property does not contain a formal parking area and is immediately adjacent to Sheldon and South Washington Streets.

1.3.16 ODORS

There were no abnormal odors observed at the property during the site reconnaissance.

1.3.17 HEATING AND COOLING SYSTEM

The is vacant and abandoned.

1.3.18 OTHER NOTEWORTHY OBSERVATIONS/ISSUES

No other noteworthy observations or issues other than those described above were observed.

1.4 FORMER ON-SITE COMMERCIAL USES

The exact date that the existing structure was built is unknown, however, historical maps indicate that a foundry and machine shop (F. H. Pike Foundry and Machine Shop) was located on the property as early as 1902. By 1929, historic maps indicate that the property was identified as the Randolph Foundry and Machine Shop. As late as 1897 however, a dairy was located on the property. Individuals with knowledge of the history of the Town indicate the Randolph Foundry was at one time owned by Aeolian (verified also by ownership records) and made piano plates out of recycled metal. The foundry was later sold and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years.

Foundries (or metal casting operations) make parts from molten metal according to end user specifications. Since the historic maps indicate that the facility was also a machine shop, it implies that the parts (castings) were used to produce larger products such as machinery, motor vehicles, appliances, plumbing fixtures, etc. In this case, at least for a time, parts for pianos. In general, foundry and machine shops are typically somewhat "dirty" operations and involved with the manufacturing, prefabrication, and repair of articles of steel, iron, and other metals. Environmental contamination associated with these facilities include elevated levels of lead and other metals in near and subsurface soils and wastes associated with slag/foundry sands. Other contaminants, including solvents and petroleum products are typically associated with drummed materials.

2.0 ASSET INFORMATION AND DESCRIPTION

Pertinent asset information includes:

Property Name:	Former Randolph Foundry (on northwestern corner of Washington and Sheldon Streets)
Property Address:	2 - 8 Sheldon Street SBL# 70.071-3-16 Town of Randolph, New York 14772
Property Owner:	Cattaraugus County
Property Contact:	Mr. Joseph Keller

The legal description for the property is: All that tract or parcel of land, situate in the Village of Randolph, County of Cattaraugus, State of New York, distinguished as part of lot No. Twenty-three (23), Township Two (2), and Range Nine (9). Refer to Appendix F for additional information on property description. In addition, refer to Section 4.0 for a description of the known history of the

property.

3.0 SITE DESCRIPTION

3.1 LOCATION AND CURRENT USE

With formal addresses of 2 - 8 Sheldon Street (historic Sanborn maps indicate the properties addresses may have changed) in the Village of Randolph, Cattaraugus County, New York, the property is currently vacant. The property is located on the northwestern corner of the intersection of Washington and Sheldon Streets. Adjacent to the property to the east is railroad lines for the Southern Tier Railway Authority.

3.2 GENERAL PROPERTY AND AREA FEATURES

The property is located in the Village of Randolph within two miles of the center of the village area. The property is generally flat and generally sloping from northeast to southwest and is located within a mixed commercial/residential/business area of the Village of Randolph.

3.3 ADJACENT PROPERTIES

The following is a brief description of properties immediately adjacent to the subject sites starting with the property north and moving in a clockwise direction.

- North: To the northeast of the subject property are rail lines (unknown if active) for the Southern Tier Rail Service. Further to the north-northwest are single and multi-family residential homes.
- East: East of the property is the rail road and Washington Street. Further to the east are open fields.
- South: South of the subject properties is Sheldon Street. Further to the south are single and multi-family residential structures and commercial structures .
- West: West of the property are residential structures along Sheldon Street and Green Street.

3.4 PROPERTY SURFACE FEATURES AND DRAINAGE

Property surface features and drainage were determined through a combination of site reconnaissance and a review of both aerial photographs and topographic maps. Property drainage is directed laterally to low areas and storm drains and to Town of Randolph storm sewers along adjacent streets. While the irregularly shaped property is relatively flat, the immediate area in the rear of the building appears to be higher then areas to the east, south, and west and therefore storm water in the general area is most likely directed towards the lower lying areas on the subject property.

3.5 UTILITIES

The subject property is vacant or abandoned, but it has access to all major public and private utilities, including water, electric, gas, and telephone.

3.6 SITE GEOLOGY/HYDROGEOLOGY

The United States Department of Agriculture (USDA) Soil Conservation Service *Soil Survey of Cattaraugus County, New York* (1940) was reviewed to determine soil types. The map of this area identified the predominant soil type pertinent to the property to be Rushford Channery Slit Loam, 8 to 15 percent slopes (58c). Soils classified as this type are a very deep, moderately well drained, low-lime, channery medium-textured soil formed in glacial till, 20 to 40 inches thick, overlying silty lake sediments. There is a fragipan at a depth of 15 to 24 inches. The available water capacity is moderate. Permeability is moderate above the fragipan, slow through extremely slow in the fragipan, and moderately slow in the substratum. This unit is moderately well suited to cultivate crops. Seasonal wetness may delay tillage and harvesting activities in some years. Recommended conservation practices should be followed to reduce erosion and maintain the productivity of this soil.

Due to the commercial use of this property, however, this property could also be classified to be Urban land (Ud). Urban land, 0 to 3 percent slopes, is a nearly level miscellaneous area in which 80 percent or more of the soil is covered by asphalt, concrete, buildings, or other impervious structures including parking lots, shopping and business centers, and industrial parks.

A copy of the soil survey map is presented in Appendix D.

4.0 SITE HISTORY

4.1 HISTORICAL SOURCES REVIEWED

A number of sources were used to develop a historical use profile for the property as discussed in this report, and included:

- Assessment records;
- Historical maps;
- Historical records maintained in town, county and state files; and
- Aerial photographs.

4.2 SITE AND AREA HISTORICAL CHAIN OF USE

4.2.1 Chain of Title Information

Title and tax assessor information located at the Town and County offices was reviewed and the most recent title information is summarized below (Refer to Appendix E - Property Title and Assessment Information).

	2 - 8 Sheldon Street						
Liber Page Sale Date From To		<u>To</u>					
2743	5007	03-09-2005	Donald Cresanti	Cattaraugus County			
875	215	10-29-1987	Aeolian Pianos, Inc.	Donald Cresanti			
504	524	09-03-1952	Randolph Foundry and Machine	Metallic Ladder Manufacturing Corp.			

4.2.2 Chain of Use Records

No historic street directories were found which describe recent historical uses of the subject property and nearby properties.

4.2.3 Aerial Photographs

Aerial photographs for the following years were obtained from the Cattaraugus County Soil Conservation Service offices in Springville, New York or as noted below:

1956 Aerial Photograph
1966 Aerial Photograph
1980 Aerial Photograph
1995 Aerial Photograph
2002 Aerial Photograph

A review of these photographs indicates that the property and surrounding area was primarily used as commercial/retail with residential on adjacent streets. Electronically-scanned copies of these photographs are located in Appendix A.

4.2.4 Sanborn Maps and Other Historic Maps

Historical Sanborn maps located for this property include those for the years 1885, 1891, 1897, 1902, 1907, 1913, 1929, and 1937. Copies of these maps are provided in Appendix D. The Sanborn map collection consists of a uniform series of large-scale maps, dating from 1867 (varies on location) to the present (around 1986 again based on location) and depicting the commercial, industrial, and residential sections of some twelve thousand cities and towns in the United States, Canada, and Mexico. The maps were designed to assist fire insurance agents in determining the degree of hazard associated with a particular property and therefore show the size, shape, and construction of dwellings, commercial buildings, and factories as well as fire walls, locations of windows and doors, sprinkler systems, and types of roofs. The maps also indicate widths and names of streets, property boundaries, building use, and house and block numbers. They show the locations of water mains, giving their dimensions, and of fire alarm boxes and hydrants and also show location of tanks.

A brief summary of pertinent information concerning the property based on this review is as follows:

1885 Map

This map shows that a dairy was located on the property. The rail road (New York/Pennsylvania/Ohio Railroad) existed along the northern and eastern border. Additionally

lumber storage is shown on th property along the rail road tracks. Washington Street was known as Depot Street was adjacent to the northeast. The Randolph Furniture Company is located on the adjacent corner (southeast) of Sheldon and Depot Street.

1891 Map

The 1891 map shows that the same structures present in the 1885 Map however the lumber storage along the railroad tracks is a much larger area. The furniture company located on the adjacent corner (southeast) of Sheldon and Depot Street is called Pearl Furniture Company.

1897 Map

The lumber storage is no longer shown. The furniture company located on the adjacent corner (southeast) of Sheldon and Depot Street is changed to the Elko Paint Company.

1902 Map

The 1902 map shows the F.H. Pike Foundry and Machine Shop located on the northwestern corner of Sheldon and Depot Street. This map shows a Foundry building and the small building previously described building on the subject property. The lumber storage is no longer present on the property.

1907 Map

This map shows the F.H. Pike Foundry and Machine Shop facility with multiple combined structures occupying the central portion of the property. The machine shop appears larger and there are a approximately two sheds to the rear (northwest) of the main structure. A boarding house is located closer to the corner and appears to be the original dairy building.

1913 Map

There is little change from the 1907 map.

1929 Map

This map indicates that the F.H. Pike building is now called the Randolph Foundry and Machine Shop. The main structure has grown in size and the shed in the rear is considered a coke shed. Depot Street is now known as South Washington Street.

1937 Map

This map is unchanged from the 1929 Sanborn Map.

4.3 PREVIOUS ENVIRONMENTAL STUDIES/HISTORICAL DATA

No records of previous environmental studies were found on this property.

5.0 REGULATORY/AGENCY RECORDS REVIEW

A review of readily available government agency records was conducted by PEI using a government records search firm, EDR. EDR provides an ASTM Detailed Radius Report based on information obtained from publicly available data sources and other secondary sources. A table summarizing the EDR database search results is presented on page 4 of the EDR report (refer to Appendix B). Additional details on these sites are also contained in the EDR radius report including

information about sites in the immediate area as well as their relative location to the subject property.

A review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. A review of NYSDEC Region 9 records indicates that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. and that approximately 1,500 pounds of foundry sand was disposed per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling occurred from 1976 to about 1981. The company initiated a permit application (permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property.

A total of eight (8) additional database records were found for the adjacent and surrounding properties within the ASTM government records search radius. These include seven Spills Information Database (LTANKS) sites, and one registered Underground Storage Tank facility.

Additionally, a total of thirty-four (34) "orphan sites" (sites with inadequate or poor database address information), were identified in the EDR report. None of these properties appear to be immediately adjacent to the subject property.

A Freedom of Information Law (FOIL) request was submitted to the NYSDEC Region 9 office requesting information concerning the subject and adjacent properties. This information is contained in Appendix F.

6.0 OTHER RECORDS REVIEWED/INTERVIEWS CONDUCTED

In addition to the federal and state databases searched, PEI reviewed a number of other regional information sources.

6.1 TOWN OF RANDOLPH OFFICES

PEI visited or contacted a number of Town of Randolph offices on June 22, 2005. The offices contacted and information obtained included the following:

Town of Randolph Assessor Office

- Real property and assessment information.

Town of Randolph Building and Permitting Department

- Zoning maps, building permits including UST installation and removal (refer to Appendix I)

Town of Randolph Clerks Office

- Building and general files for this property including UST information.

Information obtained from these sources is contained throughout the report.

6.2 COUNTY OFFICES

Aerial photographs, floodplain information, and wetland maps were obtained from the Cattaraugus County Soil Conservation Service offices in Springville, New York. PEI also contacted the Cattaraugus County Real Property Tax Office and Cattaraugus County Court Building in Little Valley for more information on the subject property.

6.3 NYSDEC FILES

NYSDEC files for the subject property were reviewed by PEI on July 13, 2005 (refer to 5.0 above).

6.4 INTERVIEWS

Information obtained during the interview and discussions with town officials is summarized throughout this report. Additionally, PEI contacted local residents familiar with the history of the area including Dr. Dixon G. Stevens and Mr. Robert Beach. They indicated that a Mr. Abbey was a manager of the foundry and that it was owned by the Aeolian Company which made piano plates out if recycled metal. They indicated that the property was sold to a Peter Perez who had connections to Steinway Piano - a fact not born out by a review of the assessor records. They indicated that the foundry went bankrupt about 1986-1987. Mr. Beach indicated that the foundry was owned by Mr. Francis Dexter prior to the Aeolian Corp. Ownership.

PEI also reviewed the files at NYSDEC noted above concerning the landfill designation.

7.0 REVIEW OF SPECIAL RESOURCES

The property does not appear to have any special resource issues on or adjacent to it.

7.1 HISTORIC RESOURCES

The structure does not appear to possess particularly notable architectural features, however, its history may have some significance locally.

7.2 FARMLANDS

The subject property is not related to any agricultural activity. The property and surrounding area has been commercial/residential since the late 1800's.

7.3 RECREATIONAL AREAS

There are no recreational areas associated with this property.

7.4 LAND USE

Land uses in the vicinity of the subject property includes residential, especially along Sheldon, Green and Washington Streets and mixed commercial/retail in the surrounding areas.

7.5 WETLANDS AND FLOODPLAINS

PEI reviewed both the State and Federal Freshwater Wetland Maps contained at the Cattaraugus County Soil Conservation Service offices in Springville, New York. There were no federal or state areas of wetlands identified on the subject property. A review of the Flood Insurance Rate Map of Cattaraugus County indicates that the subject property is located in Zone X - areas determined outside the 500 year flood plain.

8.0 ENVIRONMENTAL ASSESSMENT SUMMARY, CONCLUSIONS AND RECOMMENDATIONS

Information identified by PEI suggests that some issues of environmental concern may exist at the subject property. Based on the information reviewed for this Phase I ESA, PEI cannot verify with complete certainty that near-surface or subsurface contamination or other environmental impairment does not exist at this property, especially with regard to possible foundry sand/slag and the approximately 84 years of property use as a foundry and machine shop. Based on the information obtained regarding this property, it is unknown if additional foundry sand exists outside or immediately adjacent to the structure or if remnant subsurface contamination exists. It is also unknown, based on the site visit and records review, whether past spills have negatively impacted the subsurface environment. Records indicate that foundry sand was buried on an adjacent property.

Portions of the property contain debris piles. C&D material including brick, concrete block, and wood is located on the southeastern border of the property. As described, the material appears to be rubble from a former structure. Due to their size and configuration, visual observations could not be made of the contents of the entire piles and therefore other materials may exist.

During the site visit, PEI observed various containers (55-gallon drums, 5-gallon containers, paint cans, etc.) of unknown contents. Some of these containers were filled with materials while others were empty.

Based on the information compiled during the ESA, **PEI believes that the potential for** contamination exists at this property primarily due to the former operations. This assessment has identified potential recognized environmental conditions in connection with the subject property including the following:

- its history as a SWF/LF, and land filling of an adjacent property.

- potential contamination associated with foundry sands and slag piles as well as other materials and wastes inside the structure. Contaminants typically associated with foundry and machine shop operations include elevated levels of lead, antimony, arsenic, copper and other metals; It is unknown if this material exists outside the structure on the property.

- various 55-gallon drums and other containers which are in poor condition and contain unknown contents; and

- potential PCBs associated with the elevated transformers.

The property is in very poor condition, may be structurally un-sound in portions and has wastes and materials strewn throughout the interior. It is currently not secured and open to access.

9.0 DATA NEEDS

The purpose of any future initial site assessment should be to verify that materials and debris on the property is restricted to C&D debris and to further determine the likelihood of contamination at the property especially associated with the foundry sand/slag and containers. This information will allow for the determination of hazards associated with the property.

Follow-up assessment is therefore recommended. This may include some or all of the following:

- Determine any association with the adjacent property that was used to landfill foundry sand
- Removal/inventory containers and materials/chemicals
- examine and or sample transformers for PCBs
- sampling of sands and slag within the structure
- Removal/examination of the debris piles

- Limited surface and subsurface investigation to examine the extent/type of rubble and to sample surface and subsurface soils.

- Perform an asbestos survey of the potential materials identified

- Perform a site boundary and topographic survey to identify existing conditions and to create a base map for field activities

- analyze specific media including soil
- identify the contaminants of concern, if any
- identify specific environmental media, potential pathways and affected receptors, if any
- identify any impacts to a development concept plan

- identify extent of remediation necessary, if any, to meet the property specific development goals of redevelopment.

Based on the findings of the Phase I ESA, the following potential recommended Phase II tasks have been identified:

1) Development of a Phase II work plan which describes the activities, QA/QC, and health and safety

2) Perform a drum/container inventory and sampling and analysis as necessary

3) perform a detailed inventory of equipment/debris within the facility to determine the potential for hazardous materials.

4) Perform a sampling program of foundry sands/slag within the structure

5) Perform a surface and subsurface soil assessment including a possible sampling and analysis

program. This may involve the use of either borings or trenches. PEI suggests that the use of a backhoe is most appropriate for two purposes: 1) examine areas underneath debris 2) complete trenches in grass areas to determine the nature of the fill and to examine subsurface conditions. The reason for recommending trenching where possible, is that trenches will afford the following:

- The ability to examine a wider subsurface area and waste/fill profile
- The ability to gain access to areas inaccessible to drill rigs/geoprobes.

If soil contamination is indicated, a limited sampling program may be conducted. This assessment should be limited in scope to determine if the possibility of contamination exists (examine "hot spots"). If based on this assessment, contamination is identified, a more focused investigation can be planned.

Materials in each debris pile and soil from each slit-trench (approx. 1 foot wide by 4-8 feet long) should be visually described and screened using an organic vapor detector (i.e., PID). Stratification of material in the trenches and observations of soil staining should be noted on the trench logs. Soil samples may be collected from each test trench from the intervals which indicate contamination either through visual, smell, or PID readings. The purpose of this initial limited assessment is to verify that the material observed is limited to C&D and to determine if foundry sands/slag exist outside the facility. The purpose is not to conduct an investigation directed at determination of nature and extent of contamination which would require significantly more sampling and analysis. Based on the findings of this assessment, more detailed sampling may be required. If it is determined that the property may contain other then C&D debris, a more detailed focused study would be performed.

PEI does not recommend additional sampling (i.e., groundwater, surface water, soil) until the results of the initial assessment program have been assessed. If soil contamination exceeding compliance levels is detected, or, if other information indicates potential for groundwater or surface water/soil contamination, additional sampling will be recommended.

The number and location of samples, if necessary, will depend on field conditions and observations and may change based on discussions with the Village. It is suggested that if samples are collected, they be analyzed for TAL metals, VOCs, SVOCs, and PCBs. The results would be compared to current NYSDEC soil policy (TAGM 4046 amended) and to the full hazardous waste recommended clean-up values. Assessment of subsurface conditions would be based on visual/olfactory observations and volatile organic screening and the results of the samples submitted for analysis, if deemed necessary based on field observations.

The actual program will be developed with the County and will be subject to accessibility and the location of underground utility lines.

10.0 WARRANTS AND LIMITATIONS

This report is based on information from field reconnaissance and visual observations of the property and vicinity, and interpretation of the available information and documentation reviewed, as described within this report. This report is intended exclusively for the purpose outlined herein at the site location and project indicated. The property and this site assessment is limited to the

footprint of the lot.

This report is intended for the sole use of the County of Cattaraugus Office of the Treasurer. The scope of services performed in this assessment may not be appropriate to satisfy the needs of other users and any use or re-use of this document or the findings, conclusions, or recommendations presented, is at the sole risk of the user.

The conclusions set forth in this report are based upon, and limited by, the government data and other information available to PEI. PEI is not able, within the scope of the project, to verify the accuracy of all data supplied by government entities and third parties. Therefore, PEI is not responsible for any conclusion contained in this report that is based on, in whole or in part, upon inaccurate data obtained from third parties.


It should be noted that all surface environmental assessments are inherently limited in the sense that conclusions are drawn and recommendations developed from information obtained from limited research and site evaluation at a specific time. The passage of time may result in a change in environmental circumstances at this site and surrounding properties, or hazardous materials beneath the surface may be present but undetectable during this Phase I assessment.

PEI does not provide professional legal or title insurance services and makes no guarantee, explicit or implied, that the listing which was reviewed represented a comprehensive delineation of past site ownership or tenancy. The work performed in conjunction with this assessment and the data developed are intended as a description of available information at the dates and locations given.

Opinions and recommendations presented herein apply to the site conditions existing at the time of the assessment and those reasonably foreseeable. They cannot necessarily apply to site changes of which PEI is not aware and has not had the opportunity to evaluate.

APPENDIX A

Aerial Photographs



Photograph 1. 1956 Aerial Photograph.




Photograph 2. 1966 Aerial Photograph.



Photograph 3. 1980 Aerial Photograph.



Photograph 4. 1995 Aerial Photograph.



Photograph 5. 2002 Aerial Photograph.

APPENDIX D

Area / Property Maps








Figure 1. Project areas location in Village of Randolph, Cattaraugus County, New York (USGS 7.5' Quadrangle, Randolph, NY 1986 [1965]).











- -














D

 \geq

Ξ.

tores av Handson Han & Re Car PE

I IN ID ES H

ATRESTS			
80.00T		Wattington	Enal Ward.
Berley Alter and a subscription of the	Letter	William, at East Raustrunt.	
		Weight, to sale haustight.	
	A CONTRACTOR OF A CONTRACTOR O		M. E. Charris
creatory, at East Ranchiph. 101-175		00000000	A SALE SALES
	Contraction and a contraction of the second s	#PEDIALB	
412	1 PALL		Opera House,
Waterweth	and the second se	Berting's Conjected Mills Co	6 ¥
hurst.	1 105-004 4		Park Black, marting and and
at Los Randwigs	100 POR 1	a	Phy. P. B., Finnity & Mathias Shop.
and Spring,	at Last Rant nich	Carponter Bres, Chaster Factors,	Pres Collera at East Resources
D	Will familyara	Commercial Blocas	At East Recorded
Fran	* at East Randniph. 8	Congregational Church. 1	
Nepel,		Cross. 2. N., Fami M.G	Randonak Barrel Ca.
	Size. I		
ait Row, and Park	and the second s	District School	Paralities Ca.
57.8 A HA		and the second s	* Earlash and Machine Co.
rig Lane, E. Bandeigt, are Kingale y	Park Land, and Denn.	an the store in the second second	Bugh School
		Last Randolph Episcopal Cherris,	Publishing Ca.
Auri,		E. R. S. Dept.	 Band Ca
	Ter years	of all of president and other all all all all all all all all all al	Rock's Opens House
all, at East Bandurget	* al East Residents	Service and Provide and	A STATE OF A
		Fire Dept., Main Street Station 8	
	Dattan an Crean	Para Dersen Station.	Sample, A. J., Inw and Photing Mill,
utitule Alternation T	Shert is intra-ry	Plost Reptart Charth,	Summer Reast
1 11 11 11	Suipher Springs Blad, at E. Bandurpk, S. S.	and any set of a set of the set o	Stewart, A., Planing and hav Mill.
Amora 10.00 X		0	Territoria e territoria e en territoria e entre
* ##*.ili #	Natawarth	Grane Chorch	
* ET 1. POP #	BIL 214 8		Unam Charth.
aller and a second seco	" H of Mate 1	Barrison Herrison	
	Washington	Randridge Milling Co.	Wattern H. Y. Son's for the Protection
service at East Randstat	* Hannellinger () and and () with the line of the	at Kast Revendent	of Brokerski, T. See y for the Preter thes

ers given are arb

INCLUDING ST P 1318 EAST RANDOLPH



12.14 3

WADSWORTH

5

-

÷.

-3022-B-

\$

7.4

τ.

for any a

E)

Scale of Feet

100



RANDOLPE PAVING -51 minut filters and GRADED -Lavel. PUBLIC LIGHTS -Earthy

1

A

٠

WATER FAOILITIES

WATCH FACILITIES County your of uses werks, remote not spreak day, so, This maintain Mill. The mean start of the start of the start start of the start heavy fract Koney, were start of the start start of the start terms remote and there T Koney. The start start start is the start fract of the start T Koney and the start is the start of terms remote and the start T Koney and the start of the start start terms of the start start of the start of the start start of the start of the start start of the start of the start of the start start terms in the start back to the start of the start of the start of terms in the start back to the start of the start of the starts in the start back to the start of the start of the terms in the start of the start of the start of the start of the Kaney fract of these of the the start of the start of the Kaney fract of the start of the start of the start of the start of the Kaney fract of these of the the start of the start of the start of the Kaney fract of these of the the start of the start of the terms in the start of the start of the start of the start of the terms in the start of the start of the start of the start of the terms in the start of the start of the start of the start of the terms in the start of the terms in the start of the start of the start of the start of the terms in the start of the start

. A next h mixes of matter, x' to F' descenter. More any fairly comparison 100,000 gallons instituted. They of Matter and Jamontices 204. native it p for an its FIRE DEPARTMENT

. Volume is non-constraint, it is of a second state is of a set to be a second state of the second state

87.6780.00 Hit. 5 - Located III. Mass. 90. (see short.5). 1 Character stree the 34 galaxy chemical lank. 300 p. rulnar haak. 1 vel.0, 1,000 nex. 20 relevant lanks;

Along prior to control some control or real of V large that, a but react is instant at the integration startage can show it, another as from the first startage control of the integration of the startage can be first executive Random Deliminary.

THEFT

EAST RANDOLPH

PAVIDG -- 1.4 miles of receiv GRADES -- Newly Intel PORISE LIGHTS -- Electron

WATER FACILITIES

About \$2 builes of moins, T is F dameter. It builts hydracia A range daily conception orderes. Pressue 118 its of Hard 51, at Per-

FIRE DEPARTMENT

0

A

412 1 Valuetawe, Lawryney & chart, 2 american chart and 20 mer. Law tok, apparents partic measured. Fire Nouse search of Max 30, taxe wheat $10,\,$ house all application

1. Ford points T), paying WE (a) takes one W excession halfs mark (Princk support, convex the digital shores was been (a) ranking (IWE), have, one of read halfs one of a statework (a) areas take and antise trends, calves (WE of basisme). I cand mean or home.

Justen priors by particle derives an en. Substant on parts of Pire Stations, stars servich is constant on pair sense Fire Stations and another in from a Office. NO 2182, 518273. 12

He For resistors Roofing Deliver

Para

Gran

RANDOLPH





1 1/22 MAG

24 41

INDER

STREETS.		
		8 Kast Randolph Episonen Grunth
The Association of the state of	1	
Durter,	2 st E Receipt	In Edward's Mumorial N. E. Charth.
A DA WARK CONTRACTOR OF A DATA DATA DATA DATA DATA DATA DATA D		11 & A. R. Capet.
		IT IS IN IN CAPPER
farmerary at E. Randwijk	i homer have been been been been been been been be	10
et E. Randolph.	Mill (formerin)	8 For Dept., Huar Co. No. 8
Canthan, subbalance () have a construction of a f	at R. Rannerph.	12 Rates I have it.
The second second that I will be a state of the B	4	4 . * at East Randolph
1		Pret Japitet Charth.
	19 New,	T * Congregational County,
		Fird Service Gerage,
Quetters,	1 Parts	Pres Methadial Church
1 m	B Park,	
FD 01		the second s
	7 Royle Ho. 17 mm Main, et E. Randolph.	Gen. The Mintug Parties.
at E. Rambupt.	in the part of the second seco	GIRTHE LAS GOME MAD COMMENTS CONTRACTOR
field Spring		Gram Reamond Church,
allege Are	10 Scheel,	
anewangs Read		. Harttens & Braus Milling Co.
200 10		a Brief Barrach, second and a second
and an		Emtinghes Machine Tuni and Die Works,
	I Start, an Woodmany	I manufas month on the contract
Deput, are S. Washington.	Start, an Woodmanns	and the second se
Coper, ore 5. Washington	Soring, at K. Nandelph	13 1 0 0 F Hall
· · · · · · · · · · · · · · · · · · ·	Sulphar Springs Road, see Spring.	
firs Ate		
N. of Man	I manual in the second s	Wethnilet Spremps Course,
N af Mark	Wadeworld,	
	Valugas,	" Parma's State Bank
	A Contraction of the second se	1 Per 084
leves,	· · · · · · · · · · · · · · · · · · ·	17 * * ut Last Sambigh
		14
fall, at E. Randelut,		
A A A A A AN AN AN AN A		14 Randolph Barral Co. (Eurmanip)
		Property and Machine Store,
		Frendry and Machine Storg.
Alles, at E. Randelan	12 Waster Read	14 Perselare Warks No. L
libber i.	7) William, of Z. Randwith.	13 Carage and Machine Co.
and the second se	Noninant,	Bugst Actual and Annas
astriants Ave	14	Sent Co., Best Faching & Storage.
BUTTER ATTACTOR TO A T		. One for here second a sounder
1	APROLALS.	
amastawn	F SPROVER	15. Partia's K. C. Grant,
	1	School Aston (E) Main B.
4 5	A hart C. Daw Free Liners	Susana Paraltara Ca Susanard Di Ca el M. Y
7 (44.80)	** A hert G. Date Free Literary	I brannard DG Ca. of N. Y.
* #5-118	7 Associated Gas & Doctro Soutes, San etc.,	Brate Bank of Bankolph
Linguist at E. Barristan	11 Sumil, D.J. Louise Co., Paning and Sev. Hill,	12 Town Dark & Differ
Logest, St. Sanning,	17 Risson, D.J. Lowing Co., Planarg and Lev. Will,	af Randarias, Benari Dustrias Inc. 1 (For-
L .	Sarden Continued Milk Co	a marty
AND, DISCOUND STREET, SAN	F same wood on't past and concernance	· · · Fuel Names.
6 manufacture interpretation and . 40-49	1	
	Franklin Farm Manager St.	4 YEage Offices
#	Carpenter, Farm methodas, Br	A LONG DOWN CONTRACTOR CONTRACTOR
17-10	P2 Charlent Ballant	1) Wartart H. T. Bosists for the Protection of
And the state of t	an Frank & C. Frank Liberards	8 Bemuiam & Departient Children, Blid ga.
*	A Plat we are a set and all a set and all	
	· Indianies and; one side of Street sho	








Figure 3. Tax map of subject and adjacent properties.

APPENDIX F

NYSDEC FOIL



Panamerican Environmental, Inc. 2390 Clinton Street Buffalo, New York 14227 Tel: (716) 821-1650 Fax: (716) 821-1607

July 05, 2005

Ms. Meaghan Boice-Green Citizen Participation Specialist II NYS Department of Environmental Conservation 270 Michigan Ave. Buffalo, NY 14203-2999

RE: Records Review Request for even numbered parcels between 2 and 8 Sheldon Street (corner of Washington Street), Village of Randolph, Cattaraugus County, New York

Dear Ms. Boice-Green:

Our firm is performing a Phase I Environmental Assessment of a real property located within the jurisdiction of NYSDEC Region 9 at the above referenced area. Under the Freedom of Information Law (FOIL), I am writing to request that a review be made of NYSDEC Region 9 department records which are relevant to the purpose of the Phase I Assessment. Please forward the FOIL request to the following NYSDEC departments for review of department records, if available with regards to the subject site or facility(s) (referenced below).

1) Law Enforcement/Legal Affairs/Env. Enforcement - complaint/notice of violation files, legal proceedings.

2) Solid and Hazardous Waste - site files for active and inactive sites associated with the subject address.

3) NYSDEC Site Inspection Reports associated with the subject address.

4) Spills Division - record of petroleum/chemical releases.

SUBJECT PROPERTY DATA

PROPERTY NAME:	Randolph Foundry
STREET ADDRESS:	2-8 Sheldon Street (corner of Washington Street)
MUNICIPALITY:	Village of Randolph
COUNTY:	Cattaraugus
CURRENT OWNER:	Cattaraugus County
PRIOR OWNER:	Mr. Donald Cresanti
CURRENT USE:	Vacant Warehouse
PAST USE(S):	Foundry
SBL#:	70.71-3-16

Attached for your reference please find a map indicating the area location. If you have any questions regarding this request for information, please contact our office. The information that you provide is greatly appreciated.

Sincerely,

Justin J. Ryszkiewicz Environmental Geologist Panamerican Environmental, Inc.

APPENDIX E

Property Title and Assessment Information



James K. Griffith

27435-007

1

CATTARAUGUS COUNTY CLERK

Cattaraugus County Center 303 Court Street Little Valley, NY 14755 (716) 938-9111 Fax: (716) 938-6009

No. of Pages:	2	Delivered By:	TAX PARCEL 279
Receipt No.	27435	Return To:	
DATE:	03/10/2005		
Time:	11:46 AM		
Document Type:	DEED		
Parties To Transac	tion: CRESANTI BY TREAS	TO CATT CO	
Town/City:	RD - Randolph		
Deed Infon	mation	M	ortgage Information
Consideration:	\$0.00	Mortgage	Amount
Transfer Tax:	\$0.00	Basic Mt	ge. Tax:
RETT No:	02333		<i>I</i> tge. Tax:
		Additiona	al Mtge. Tax:

State of New York Cattaraugus County Clerk

i

Mortgage Serial No.:

This sheet constitutes the Clerk endorsement required by Section 316-A(5) & Section 319 of the Real Property Law of the State of New York. DO NOT DETACH

Dame K. Griffeth

Cattaraugus County Clerk

Made the 28th day of February, in the year Two Thousand and Five,

- -

BETWEEN Joseph G. Keller, Treasurer of Cattaraugus County, State of New York, party of the first part, and the County of Cattaraugus, State of New York, party of the second part,

ł

WHEREAS, at a Special Term of the County Court of Cattaraugus County, State of New York, held at Little Valley on the 15th day of February, 2005, it was among other things, Ordered, Adjudged and Decreed by said Court in a certain action then pending in the said Court entitled:

> "In the Matter of the Foreclosure of Tax Liens pursuant to Article 11 of the Real Property Tax Law by the County of Cattaraugus List of Delinquent Taxes for 2002",

with respect to all and singular the premises mentioned in the aforesaid judgment and including the premises hereinafter described,

"ORDERED, that all proceedings in this action were duly and properly taken pursuant to Article 11, Title 3 of the Real Property Tax Law of the State of New York, and there has been full and due compliance with the provisions of Article 11, Title 3 of the Real Property Tax Law, and it is further

ORDERED, ADJUDGED AND DECREED that the County of Cattaraugus is hereby granted and awarded possession of every parcel of property described in the Petition and Notice of Foreclosure not heretofore redeemed or withdrawn from foreclosure, and as to which no Answer has been properly interposed, or withdrawn, the same being the parcels more fully described in the last paragraph of this Order, and the Treasurer of the County of Cattaraugus is hereby directed to prepare, execute and cause to be recorded, deeds conveying full and complete title to such parcels to the County of Cattaraugus, pursuant to Section 1136 of the Real Property Tax Law, and it is further

ORDERED, ADJUDGED AND DECREED that upon the execution and recording of such deeds, the County of Cattaraugus shall be seized of an estate in fee simple absolute in all the parcels described therein, and all persons, including the State of New York, infants, incompetents, absentees and non-residents who may have had any right, title, interest, claim, lien or equity of redemption in or upon such parcel shall be, and hereby are, barred and forever foreclosed of all such right, title, interest, claim, lien or equity of redemption in such parcel and each and every part thereof..."

WHEREAS, the aforesaid order and judgment of the said Court was duly entered in the Office of the Clerk of Cattaraugus County on the 16th day of February, 2005.

NOW THIS INDENTURE WITNESSETH, That the said Treasurer of Cattaraugus County, the party of the first part to these presents, in order to carry into effect the direction to him to execute proper conveyances in pursuance of the order and judgment of said Court, and in conformity to the Statute in such a case made and provided, and also in consideration of the premises and \$1.00 and other good and valid consideration, hath bargained and sold, and by these presents doth grant and convey unto the assigns an estate in fee simple absolute in the following described premises including all the right, title and interest of any person having, or claiming to have, an interest therein and more particularly that which the following said persons and parties,

RO Cresanti, Donald, RD 2, Russell PA 16345 RO Cresanti, Donald, 4065 High Point Rd, Winston Salem NC, 27107-3603 had at the time of the commencement of the said action, in and to the following described premises situated in the Town of Randolph, Cattaraugus County, New York, being Parcel 279 according to the Petition and Notice of Foreclosure filed with the Cattaraugus County Clerk on October 7, 2004, and further described as being:

Part of Lot 23, Town 2, Range 9, about 179.00' X 229.00', Acct. No. 0724, TM #70.071-3-16, SHELDON ST

TO HAVE AND TO HOLD THE same to the party of the second part, the County of Cattaraugus, its successors and assigns forever.

IN WITNESS WHEREOF, the Treasurer of the County of Cattaraugus, for the time being, in pursuance of the authority vested in him by law, hath hereunto set his hand affixed the seal of this office the day and year first above written. \bigwedge

Tax Collecting Officer and Treasurer

of the County of Cattaraugus, New York

State of New York

ss.

:

:

:

County of Cattaraugus

On this day of March, 2005, before me, the undersigned, a Notary Public in and for said State, personally appeared JOSEPH G. KELLER, personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that he executed the same in his capacity, and that by his signature on the instrument, the individual, or the person upon behalf of which the individual acted, executed the instrument.

tary Public

ROBYN FISHER Notary Public, State of New York No. 01FI6073406 Qualified in Cattaraugus County Commission Expires April 22, 2006 FORM 554X N.Y. DEED-WARRANTY (FROM & CORPORATION)



Made the 29th day of October Nineteen Hundred and Eighty-Seven Between AEOLIAN PIANOS, INC.

TUTBLANX REGISTERED U. S. PAT. OFFICE

STATE OF NEW YORK SS. COUNTY OF CATTARAUGUS RECORDED <u>Jon 20, 1987</u> AT <u>216 PM</u> IN LIBER <u>875</u> PAGE <u>215</u> OF <u>Stedd</u> AND EXAMINED **Shoria Bilotta** CLERK

a corporation organized under the laws of

party of the first part, and

DONALD CRESANTI R.D. #2, Russell, Pennsylvania

party of the second part, **Witnesseth** that the party of the first part, in consideration of


one

Dollar (\$ 1.00)

lawful money of the United States, in hand paid by the part y of the second part, does hereby grant and release unto the part y of the second part, his heirs and assigns forever, all

ALL THAT TRACT OR PARCEL OF LAND situate in the Village of Randolph, County of Cattaraugus and State of New York and being part of Lot 23, Town 2, and Range 9 of the Holland Land Company's survey being further described as follows:

Beginning at an iron stake located at theintersection of the southwesterly bounds of the Erie-Lackawanna Railroad right-of-way and the northerly bounds of Sheldon Street thence North 38° and 29 minutes and 32 seconds West 243.82 feet along the southwesterly bounds of the Erie-Lackawanna Railroad right-of-way to an iron stake thence South 83° and 44 minutes and 26 seconds West 51.75 feet to an iron stake thence South 7° and 50 minutes and 11 seconds East 70.15 feet to an iron stake thence South 11° and 8 minutes and 32 seconds East 48.01 feet to an iron stake thence South 4° and 6 minutes and 26 seconds East 80.08 feet to an iron stake the northerly bounds of Sheldon Street thence North 86° and 23 minutes and 6 seconds East 179.01 feet along the northerly bounds of Sheldon Street to the point or place of beginning.



Together with the appurtenances and all the estate and rights of the party of the first part in and to said premises,

To have and to hold the premises herein granted unto the party of the his heirs and assigns forever. second part.

And the party of the first part covenants as follows:

First. That the part y of the second part shall quietly enjoy the said premises;

Berond. That the party of the first part will forever Warrant the title to said premises.

In Presence of

In Mitness Mhereof, the

party of the first part has caused its corporate seal to be hereunto affixed, and these presents to be signed by its duly authorized officer day of Dotober this Nineteen Hundred and Eighty Seven esta By Peter M. Perez, Chief Executive Officer the Back a Chairman Exec (I.c. · 29th day of October On this Nineteen Hundred and Eighty Seven

Tennessee State of Neurx Works County of SHELBY before me personally came

Peter M. Perez

ss.

to me personally known, who, being by me duly sworn, did depose and say that he resides in Memphis, Tennessee that he is

the Chief Executive Officer of Aeolian Pianos, Inc. the corporation described in, and which executed, the within Instrument, that he knows the seal of said corporation; that the seal affixed to said Instrument is such corporate seal; that it was so affixed by order of the Board of ? Directors name thereto by like order. of said corporation; and that he signed

1946 **500** meto21

THES INDENTURE

MADE the 3rd day of September, Mineteen Hundred and Fifty two (1952) 2 Sheldon Str., Rendouph, No X-

BETWEEN 3 RANDOLPH FOUNDRY AND MACHINE, INC., /a corporation organized and existing under the laws of the State of Maryland, party of the first part, and METALLIC LADDER MANUFACTURING CORPORATION, a corporation organized and existing under the laws of the State of Maryland and duly autorized to transact business

in the State of New York, party of the second part,

WITNESSETH, that the party of the first part, in considderation of One Dollar (\$1.00), lawful money of the United States, in hand paid by the party of the second part, does hereby grant and release unto the party of the second part, its successors and elease forever;

PARENT, IL

ALL THAT TRACT OR PARCEL OF LAND, situate in the Town of Randolph, County of Cattaraugus and State of New. York, distinguished as being part of lot number 23, town 2, range 9, of the Holland Land Company's land as surveyed by Joseph Ellicott, BOUNDED as follows: Beginning in the west line of the Atlantic and Great Western, now (Erie) Railroad Company's land and on the north line of a highway leading westerly from said Railroad Depot; running thence north on said west line of said Railroad lands north 39°, west 3 chains, 62 links; thence south 86°, west 2 chains, 40 links; thence south 6°, east 2 chains, 95 links; thence north 86°, east on the line of said highway, 4 chains, 35 links to the place of beginning.

EXCEPTING AND RESERVING therefrom a parcel of said land 50 feet in width on the west side thereof, extending the entire length of the lot, from north to south, heretofore sold to Lura O. Hogan.

ALSO EXCEPTING AND RESERVING therefrom and from this conveyance the following part or parcel of said premises to wit: The southeast part of said premises BOUNDED as follows: Beginning at a point in the north bounds of Sheldon Street, 144 feet west on said north bounds from the southeast corner of said premises: thence easterly dend, party of the Einst part, and MPANLUE LADDER MANUFACTURING. (CORFORATION, a corporation organized and estisting under the laws of the State of Maryland and duly autorized to transact business in the State of New York, party of the second part,

WHENESSETH, that the party of the first part, in considenation of One Dollar (\$1.00), lawful money of the United States in hand paid by the party of the second part, does hereby grant and release unto the party of the second part, its successors and release forever,

PAROBE TI

ALL THAT TRACT OF PARCEL OF LAND, situate in the Town of Randolph, County of Cattaraugus and State of New York, distinguished as being part of lot number 23, town 2, range 9, of the Holland Lend Company's land as surveyed by Joseph Ellicott, BOUNDED as follows: Beginning in the west line of the Atlantic and Great Western, now (Erie) Railroad Company's land and on the north line of a highway leading westerly from said Railroad Depot; running thence north on said west line of said Railroad lands north 39°, west 3 chains, 62 links; thence south 86°, west 2 chains, 40 links; thence south 6°, east 2 chains, 95 links; thence north 86°, east on the line of said highway, 4 chains, 35 links to the place of beginning.

EXCEPTING AND RESERVING therefrom a parcel of said land 50 feet in width on the west side thereof, extending the entire length of the lot, from north to south, heretofore sold to Lura O. Hogan.

ALSO EXCEPTING AND RESERVING therefrom and from this conveyance the following part or parcel of said premises to wit: The southeast part of said premises BOUNDED as follows: Beginning at a point in the north bounds of Sheldon Street, 144 feet west on said north bounds from the southeast corner of said premises; thence easterly on said north bounds 144 feet to said southeast corner of said premises; thence northerly on the west line of said railroad lands 112 feet; thence westerly 90 feet, said course is 25 feet distant north from the northeast corner of the house on said premises here by reserved, thence southerly 60 feet to the place of beginning.

E & MCCARTHY DRNEYS AT LAW AN, NEW YORK

AREA 300 REALE

PARCER JOOL

ALL THAT TRACT OR PARCEL OF JAND, Situate in the Town of Randolph, County of Cattaraugus and State of New York, distinguished as being part of Lot No. 23, Town 2, and Range 9, of the Holland Land Company's survey being the southeast part of certain premises conveyed by the Sheriff of Cattaraugus County to Charles A. Woodruff by deed dated August 20th, 1893 and recorded in Gattaraugus County (Certain premises) and recorded in Gattaraugus County (Certain premises) and recorded in Gattaraugus County (Certain premises) and recorded an described as follows: Beginning at a point in the north bounds of Sheldon Street 144 feet west on said north bounds from the southeast corner of said premises; thence easterly on said north bounds, 146 feet to said southeast corner of said premises; thence westerly 90 feet, said corner is 25 feet distant north from the northeast corner of the house on said premises hereby conveyed; thence southerly 60 feet to the place of beginning. Being premises described from the vortheast corner of the house on said premises hereby conveyed; thence southerly 60 feet to the place of beginning. Being premises described from the rooth Said of the J. Parenti, by deed dated the 12th day of September, 1947, and recorded in the office of the Olerk of Cattaraugus County, in Bibers. 427 of Deeds at spage 150.

TOREWHER with the appurtenences and all the estate and rights of the party of the first part in and to said premises. TO HAVE AND TO HOLD the premises herein granted unto the party of the second part, its successors and assigns forever. MND the party of the first part, covenants as follows:

FIRST : That the party of the second part shall quietly en joy the said premises;

SECOND : That the party of the first part will forever. WARRANT the title to said premises.

IN WITNESS WHEREOF, the party of the first part has caused its corporate seal to be hereunto affixed and these presents to be signed by its duly authorized corporate officer the day and year first above written.

IN PRIMARIAN (db. (0)?

RANDOLPH FOUNDRY & MACHINE, INC.

LIBER 504 PASE 525

ALSO EXCEPTING AND RESERVING ALL THAT CERTAIN TRACT AND PARCEL OF LAND, situated in the Village of Randolph, N. Y., being a part of a lot heretofore conveyed to Fred H. Pike, and upon which his foundry and machine shop now stand. Part- lot-23, town 2; range 9. Commencing at an iron monument standing in the north bounds of Sheldon Street at the southeast corner of land now owned by one Hogan. Thence easterly along the north bounds of Sheldon Street 29 feet, 6 inches to an iron monument. Thence on a present magnetic course of north 10, 15 minutes west 80 feet to an iron monument. Thence on a present magnetic course of north 10, 15 minutes west 80 feet to an iron monument passing the dwelling house on said premises now owned by Fred H. Pike and parallel with the foundation wall thereof and 8 feet easterly therefrom. Thence north 60, 15 minutes west 48 feet to an iron monument. Thence north 60 west 70 feet and 3 inches to Milan's south line passing the southwest corner of the garage and 3 feet distant therefrom as measured in line with the south side of said buildingthence along Milan's south line south 88°, 15 minutes west 24 feet, 10 inches to an iron monument being also said Hogan's northeast corner. Thence south 2°, 30 minutes east along Hogan's east line 197 feet 6 inches to the place of beginning, containing more or less.

The above described premises are the same premises conveyed by Fred H. Pike to Andrew A. McGilloch and Amy A. McGilloch, his wife, by deed recorded in the Cattaraugus county Clerk's office in Liber 200 of deeds at page 290, and conveyed to describe 200 of and Alvin L. Parenti, by deed dated the 200h day of November, 1947, and recorded in the Office of the Clerk of Cattaraugus County, New York, in Liber 1927 of Deeds at page 156

P.R. HAR AN

Able THAT: TRACT OR PARCEL OF LAND, Structe in the Town of Remobility, County of Certeneurous, and Starce of Men York, described as part of Bot Nor Grency three in the second township and minute same of the Holland hand to be Survey and bounded as followsteast by lands of the Easte Rathroad Got, South by Lands formerly Orned by demos Vall, Mest by Lends of the highway, called South Depot. Street in the Villere of Randolph; North by Gre center of the highway minute from seld reall, road to Larkin Street, Contraining about the acts, more less.

Di veve los- e intenveve description serie denois das serar

owned by thereof and 8 feet easterly therefrom. tion wall thereof and 8 feet easterly therefrom. Thence north 6°, 15 minutes west 48 feet to an from monument. Thence north 6° west 70 feet and 3 inches nonument. Thence north 6° west 70 feet and 3 inches to Milan's south line passing the southwest corner of the garage and 3 feet distant therefrom as measured in line with the south side of said milding measured in line with the south side of said milding measured in line with the south side of said milding west 24 feet, 10 inches to an iron monument being also said logan's northeast corner. Thence south 2°, 10 minutes east along Hogan's east line 197 ref 6 inches to the place of beginning, containing more on less. more or less

The above described premises are the same premises conveyed by Fred H. Pike to Andrew A. McGilloch and Amy A. McCulloch, his wire, by deed recorded in the Cattaraugus County Clerk's office in Liber 290 of deeds at page 200 and conveyed to Joseph S. Parenti and Alvin L. Parenti, by deed dated the 20th day of November, 1947, and recorded in the office of the Clerk of Cattaraugus County, New York, in Liber 427 of Deeds at page 156

PARCELLE

And THAT TRACT OR PARCEL OF LAND, Stouate in the Town of Randolph, Courty of Cattaraugus, and State of New York, described as part of hot Not twenty of New York, described as part of hot Not twenty of the second township and names range of the Holland Land Coler Survey and bounded as followsr-the Holland Land Coler Survey and bounded as followsr-tade tast by Lands of the Easte Railroad Cole South by Lands formerly Conted by James Veil, West by Lands of the highway, Cabled South Depot Street in the Walkers of Randolph, North by Une Center of the highway reinstage from said rall Ford to Landin Street, Containing about two access more of less.

Excepting and reserving from Gaid Land's the Right of May for a highway three rods in width along the west bounds of said Lived. Being the premises des-cribed in a deed to Moseph S. Farenti and Alven I., Parenti, deced November 20, 1927, recorded in the office of the Clerk of Cettoraugus County, New York, in Liber 427 of Deeds at page 15.

A.R. H.J. A. H.H. KA CELOND: MIX STELLS

70.071-3-16 Cresanti, Donald Sheldon St	047601 Randolph Roll Year: 2005 Curr Yr Land Size: 179.00 x 229.00	Warehouse Lar	hool: Randolph Centra nd AV: 6,100 tal AV: 45,800
Owner Total Name: Donald Cresanti Addl Addr: Street: 4065 High Point Rd PO Box: City: Winston Salem, NC Sale Total:	Zip: 27107-3603	Taxable Value County: 45,800Muni:45,800School:45,800Village:45,800Schl after Star:45,800Site 1 of 1Prpcls:WarehouseNbhd Cd:76010Sewer:PrivateWater:Comm/publicUtilities:Gas & elec	Miscellaneous Book: 2743 Page: 5007 Mortg: Bank: Bank: Acet No: 0724 Land 1 of 1 Type: Primary FF: 179.00 Depth: 229.00 Acres: 0 Sqft: 0
Exemption Total: Code	O Term Own Amount Year Pct	Building: 1 Section: 1 Boeck Model: 1 sty warehous Eff Yr Built: 0 Gross Floor: 10760 Bldg Perim: 417	Total: 2 ▲ ▲ ε Stories: 1 Wall A% 100 Wall B% 0 Wall C% 0
Special District Total Code Units WS760 Watershed .00	같은 집에는 것 같아요. 그는 것이지 이야 한 것이 않는 것이 같은 것이 같이 하는 것이 같이 많이 하는 것이 같이 같이 많이 했다. 것이 같이 많이 많이 많이 했다.	Improvement Total: Type Name Dim1	0 Dim2 SQFT Yr Built

Prints the screen

DIVISION OF EQUALIZATION AND ASSESSMENT				-		*
		$\begin{array}{llllllllllllllllllllllllllllllllllll$	04.1001	70.071-3.	-//~ CARD NO C	OF -
LUUNIY-CATTARAUGUS TOWN OF RAN VITESA	RANDOLPH	M = MEASURED ONLY L = LISTED	ROUTE NUMBER	(ROUTE)		1 1
0-071-3-16		ENTRY (ENTRY) I - INTEDIOD INCOMOND	SITE INFORMATION SECTION	SITE O,	PROP CLASS 4 4 9 (USDAS) 7	Š
	5-1-0-1	2 = INTERIOR REFUSAL 3 = TOTAL DEFINSAL	NEIGHBORHOOD CODE	(NBHD)		
500 11/87 179	X 229	4 = ESTIMATE 5 = NO ENTRY	ZONING CODE	(ZONING) 01 NONE 02 SINGLE 02 MUTTE	I RES 05 COMMERCIAL 08	MIXED GOVT
		SOURCE (INFSCE) 1 = OWNER 3 = TENANT	TT VALUATION DISTRICT	111011		
-		n 5	SEWER	(SEWER) I NONE	2 PRIVATE 3 COMM/PUBLIC	EIC 2
•		NL UK	WATER	(WATER) 1 NONE	2 PRIVATE 3 COMM/PUBLIC	LIC 7
SWIS TAX OWNER PROP	LOC LOC SCH LOT	SALLES LIFE (SALLIF) 1 = LAND ONLY 2 = BLDG. ONLY 3 = LAND & BLDG.	UTILITIES	(UTIL) 1 NONE 4 GAS &	2 GAS 3 ELECTRIC ELECTRIC	1
CORRECTION AREA 1 2 3 4	7 8	$\left(\begin{array}{c} \text{VERLFY} \\ \text{MF} \end{array} \right)_{n=1}^{n}$	OVERALL DESIRABILITY	(OVDESR) 1 POOR 4 GOOD	2 FAIR 3 NORMAL 5 EXCELLENT	фиациі
AUDIT CONTROL SECTION (SITES (NUMSIT) (), (), ()	2 = BUYER $5 = AGENT3 = SELLER$	OVERALL CONDITION	(OVCOND) 1 POOR 4 GOOD	2 FAIR 3 NORMAL 5 EXCELLENT	
QUALITY CONTROL REVIEWER (QCBY)	DATE	F	OVERALL EFFECTIVE	(Otmbr m)	0	
CERTIFIED LETTER (CTFLET) DATE		2 = INVALID SALE	THING YEAR	ŀ		-
JR DA	TIME ACTIVITY	TY (ENTRY) (INFSCE)		(OVRGRD) A EXCEL D ECONOMY	B GOOD C AVERAGE E MINIMUM	<u>)</u>
(VISITS) (LISTOR) (LISTDT)						
SIEKD	1:00P.M. N	J V	SIGNATURE BELOW DOES NOT MEAN	I DOES NOT MEAN	SOIL RATING (RATING)	(5
2 1 1 0 2 1 2 1 0 1 3 1 9 1 9	9:45Am	1 1	COLLECTED IN'		P POOR (05) 1 N NOPMAT (06) 1	10
3 1 1 1 1 1			SIGNATURE		Good	2-4-
		-	DATE			1 1 4 0 5 4 0 5
SALES INFORMATION S	SECTION	OFFICE USE ONLY	IN NOTES: NOTES OF	ALDG. UNSATE	(51)	
DATE PRICE	TYPE SOURCE	VALID CHECK COLLEG	to Enter.	glock secture	WATERFRONT TYPE	(WIRFNT)
YYMM (SALPRC)	(SALTYP) (VERIFY)	(VALID)	Lo L	OWNER ANT	L FOND 4 CAN 2 RIVER 5 OCF	CANAL OCEAN/BAY
			19-50	Bull's - Compared		
			NEXT TO R.			
			I&E SENT//	i	2 LOCATION 6 W	VILEW WEINESS
			I&E RECEIVED //		RESTRICTED USE	THEK
ODE						
PRIMARY 09 SECONDARY 10	EFF. F CODE	HILd		SQUARE FEET SOIL	WATER FRONTAGE WTR TNF	LNFLU - ENCE PERCENT
0 3 UNDEVELOPED 11 ORCHARD (LND 04 RESIDUAL 12 REAR TYP) 05 TILLABLE 13 VINEVARD		(DEPITH) (AC	(ACRES)	(SQFT) (RAT ING)	(WIRFIG) FNI LCD	INFLPC)
PASTURE 14 WOODLAND 15	7114	1-				
MASTELLAND						-
EFFECTIVE CODE (EFFCD)		- - - - - -				- - -
2 DEPTH ONLY 2 DEPTH ONLY						
3 FKWLFT AND DEPTH						-

.

BUILDING & SECTION Image: Construction of the sector o	BUILDING & SECTION NO. IDENTICAL BLOGS. MODEL WITH THE STORY HEIGHT VI STORY HEIGHT WALL & PERCENT WALL & PERCENT WALL & PERCENT CONSTRUCTION WALL & PERCENT WALL & PERCENT WALL & PERCENT WALL & PERCENT COND. PERCENT LI STORY HEIGHT WALL & PERCENT MALL & PERCENT LI STORY HEIGHT MALL & PERCENT MALL
BASEMENT PERIMETER	BASEMENT PERIMETER
BASEMENT SQ. FT.	BASEMENT SQ. FT.
MISCRIIAN	COUS IMPROVEMENTS
STRUCTURE STRUC M MEASUREMENT ID CODE C 1 $O_1 2_1 O_1 O_1 = C_1 I_1 = 127$ $O_1 4_1 O_1 O_1 C_1 C_1 I_1 = 127$ $O_1 4_1 O_1 O_1 C_1 C_1 G_1 G_1 G_1 G_1 G_1 G_1 G_1 G_1 G_1 G$	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
	COMMERCIAL
 MISCELLANEOUS IMPROVEMENT CODES MEASURE CODE CONDITION GRADE 1 QUANTITY 1 POOR A EXCELLENT 2 DIMENSIONS 2 FAIR B GOOD 3 SQUARE FEET 3 NORMAL C AVERAGE 4 DOLLARS 4 GOOD D ECONOMY 5 EXCELLENT E MINIMUM	FLOOR LEVEL UNIT CODES B BASEMENT 02 APARTMENTS 10 BAYS F 1ST FLOOR 03 ROOMS 11 GALLONS U UPPER 04 SEATS 12 PADS T TOTAL 05 BEDS 13 RUNS 06 STALLS 14 HOLES 07 LANES 15 PLOTS 08 COURTS 16 BARRELS 09 SLIPS 17 ACKES

3. F. F.

Cattaraugus County Sales History 047601 - 70.071-3-16

06/22/2005

Page 1

Listed Ow	ners		Owner 1 Mailing Address
	Cattaraugus		303 Court St.
			Little Valley, NY 14755
Date	Book/Page	Lot size	Coordinate Locator
3/10/2005	2743/5007	179x229 IR	
Transfer C	Conditions		Lot/Town/Range
Tax Forec	losure		23/2/9
Notes :			

The EDR Radius Map with GeoCheck[®]

Randolph Foundry 4-8 Sheldon Street Randolph, NY 14772

Inquiry Number: 01459790.1r

July 06, 2005

The Standard in Environmental Risk Management Information

EDRTM Environmental

Data Resources Inc

440 Wheelers Farms Road Milford, Connecticut 06460

Nationwide Customer Service

 Telephone:
 1-800-352-0050

 Fax:
 1-800-231-6802

 Internet:
 www.edrnet.com

TABLE OF CONTENTS

SECTION

PAGE

Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	23
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	A-10

Thank you for your business. Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental St Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2005 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

TARGET PROPERTY INFORMATION

ADDRESS

4-8 SHELDON STREET RANDOLPH, NY 14772

COORDINATES

 Latitude (North):
 42.158600 - 42° 9' 31.0"

 Longitude (West):
 78.982700 - 78° 58' 57.7"

 Universal Tranverse Mercator:
 Zone 17

 UTM X (Meters):
 666660.6

 UTM Y (Meters):
 4669141.5

 Elevation:
 1315 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property:	42078-B8 RANDOLPH, NY
Source:	USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM STANDARD

NPL	National Priority List
Proposed NPL	Proposed National Priority List Sites
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information
	System
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
CORRACTS	. Corrective Action Report
RCRA-TSDF	Resource Conservation and Recovery Act Information
RCRA-LQG	Resource Conservation and Recovery Act Information
RCRA-SQG	Resource Conservation and Recovery Act Information
ERNS	Emergency Response Notification System

STATE ASTM STANDARD

SHWS______ Inactive Hazardous Waste Disposal Sites in New York State

CBS UST	Chemical Bulk Storage Database
	. Major Oil Storage Facilities Database
VCP	Voluntary Cleanup Agreements
SWTIRE	Registered Waste Tire Storage & Facility List
	Registered Recycling Facility List

FEDERAL ASTM SUPPLEMENTAL

CONSENT	Superfund (CERCLA) Consent Decrees Records Of Decision
Delisted NPL	National Priority List Deletions
FINDS	. Facility Index System/Facility Identification Initiative Program Summary Report
HMIRS	Hazardous Materials Information Reporting System
MLTS	Material Licensing Tracking System
MINES	Mines Master Index File
NPL Liens	Federal Superfund Liens
PADS	PCB Activity Database System
INDIAN RESERV	Indian Reservations
FUDS	Formerly Used Defense Sites
UMTRA	Uranium Mill Tailings Sites
US ENG CONTROLS	. Engineering Controls Sites List
ODI	Open Dump Inventory
DOD	Department of Defense Sites
RAATS	RCRA Administrative Action Tracking System
TRIS	Toxic Chemical Release Inventory System
TSCA	Toxic Substances Control Act
SSTS	Section 7 Tracking Systems
FTTS INSP	_ FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, &
	Rodenticide Act)/TSCA (Toxic Substances Control Act)

STATE OR LOCAL ASTM SUPPLEMENTAL

	Hazardous Substance Waste Disposal Site Inventory
AST	5
CB2 421	Chemical Bulk Storage Database
MOSF AST	. Major Oil Storage Facilities Database
NY Spills	. Spills Information Database
DEL SHWS	Delisted Registry Sites
DRYCLEANERS	Registered Drycleaners
ENG CONTROLS	Registry of Engineering Controls
AIRS	Air Emissions Data
SPDES	State Pollutant Discharge Elimination System

EDR PROPRIETARY HISTORICAL DATABASES

Coal Gas...... Former Manufactured Gas (Coal Gas) Sites

BROWNFIELDS DATABASES

US BROWNFIELDS	A Listing of Brownfields Sites
	Sites with Institutional Controls
Brownfields	Brownfields Site List
VCP	Voluntary Cleanup Agreements

INST CONTROL...... Registry of Institutional Controls

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STATE ASTM STANDARD

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
AEOLIN CORP	2 SHELDON STREET	0 - 1/8 SSE	1	6

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 05/02/2005 has revealed that there are 7 LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
RANDY'S GARAGE RANDOLPH HIGHWAY DEPT	229 MAIN STREET 15 WADSWORTH STREET	1/8 - 1/4 WNW 1/8 - 1/4 WNW	_	6 11
RANDOLPH TRUCK STOP TANK AT CAMP HOUSE	MAIN STREET 67 LARKIN STREET	1/4 - 1/2WNW 1/4 - 1/2SSW	-	13 16
Lower Elevation	Address	Dist / Dir	Map ID	Page
BEACOM RESIDENCE/GRIFFITH LAKE COUNTRY DAIRY	48 CENTER STREET	1/4 - 1/2NW	7	17

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database


A review of the UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 UST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
TOWN OF RANDOLPH HWY DEPT	15 WADSWORTH STREET	1/8 - 1/4 WNV	V A3	8

Due to poor or inadequate address information, the following sites were not mapped:

SALAMANCA CONV. STATIONSWF/LFLEVI RABER FARM - EMPIRE SPECIALTY CHEESSWF/LFDAVID CHRISTIAN TIRE PILESWF/LFRANDOLPH QUAKER STATEUSTCAMPBELL OIL CO INC RANDOLPHASTCATTARAUGUS COUNTY DPWRCRA-SQG, FINDSNYSDOT BIN 1012180FINDS, RCRA-LQGNYSDOT BIN 1012160FINDS, RCRA-LQGNYSDOT BIN 1012190FINDS, RCRA-LQGRANDOLPH BRIDGE 21FINDSNYS RANDOLPH FISH HATCHERYFINDSRANDOLPH SUBSTATIONFINDSRANDOLPH SUBSTATIONFINDSRANDOLPH & EAST RANDOLPH S T PFINDSRANDOLPH & EAST RANDOLPH S T PFINDSRANDOLPH (V) STPFINDSRANDOLPH CHILDRENS HOMEFINDSTOWN OF RANDOLPH GRAVEL PITFINDSRANDOLPH WILLAGE PARKFINDSNYSDOT RANDOLPH REST STOPNY SpillsNY SDOT RANDOLPH REST STOPNY Spills
C.R. CLARKNY SpillsDOT REST AREANY SpillsDIESEL ON ROAD SHOULDERNY SpillsWEST VALLEY NUCLEAR SERV.NY SpillsWEST VALLEY NUCLEAR SERV.NY SpillsMANSUR TRUCKINGNY SpillsRANDOLPH CHILDREN'S HOMENY SpillsROUTE 394NY SpillsLCD - NYSDOTNY SpillsRANDOLPH MACHINENY SpillsRANDOLPH CENTRAL SCHOOLNY SpillsDON FRAME TRUCKINGNY SpillsTANK AT TWILITE LANESNY Spills

OVERVIEW MAP - 01459790.1r - Panamerican Environmental, Inc




ADDRESS: CITY/STATE/ZIP: LAT/LONG:

4-8 Sheldon Street Randolph NY 14772 42.1586 / 78.9827

Peter J. Gorton INQUIRY #: 01459790.1r July 06, 2005 12:47 pm

Copyright © 2005 EDR, Inc. © 2004 GDT, Inc. Rel. 07/2004. All Rights Reserved.

DATE:



Copyright © 2005 EDR, Inc. © 2004 GDT, Inc. Rel. 07/2004. All Rights Reserved.

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL ASTM STANDAR	D							
NPL Proposed NPL CERCLIS CERC-NFRAP CORRACTS RCRA TSD RCRA Lg. Quan. Gen. RCRA Sm. Quan. Gen. ERNS		1.000 1.000 0.500 0.250 1.000 0.500 0.250 0.250 TP	0 0 0 0 0 0 0 0 0 NR	0 0 0 0 0 0 0 NR	0 0 NR 0 NR NR NR	0 NR NR 0 NR NR NR NR	NR NR NR NR NR NR NR	0 0 0 0 0 0 0 0 0
STATE ASTM STANDARD								
State Haz. Waste State Landfill LTANKS UST CBS UST MOSF UST VCP SWTIRE SWRCY		$\begin{array}{c} 1.000\\ 0.500\\ 0.500\\ 0.250\\ 0.250\\ 0.500\\ 0.500\\ 0.500\\ 0.500\\ 0.500\end{array}$	0 1 0 0 0 0 0 0 0 0	0 0 2 1 0 0 0 0	0 0 5 NR 0 0 0 0	0 NR NR NR NR NR NR NR	NR NR NR NR NR NR NR NR	0 1 7 1 0 0 0 0 0
FEDERAL ASTM SUPPLEM	ENTAL							
CONSENT ROD Delisted NPL FINDS HMIRS MLTS MINES NPL Liens PADS INDIAN RESERV FUDS UMTRA US ENG CONTROLS ODI DOD RAATS TRIS TSCA SSTS FTTS		1.000 1.000 TP TP TP 0.250 TP TP 1.000 1.000 0.500 0.500 0.500 1.000 TP TP TP TP TP	0 0 NR NR 0 NR 0 0 0 0 0 0 NR R R NR NR NR NR	0 0 0 NR N N N N N N N N N N N N N N N N	0 0 0 R NR NR NR 0 0 0 0 0 0 NR	0 0 NR NR NR NR 0 0 NR NR NR NR NR NR NR NR NR NR NR NR NR	NR NR R NR NR N	
STATE OR LOCAL ASTM S	UPPLEMENTA	L						
HSWDS		0.500	0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
AST		TP	NR	NR	NR	NR	NR	0
CBS AST		0.250	0	0	NR	NR	NR	0
MOSF AST		0.500	0	0	0	NR	NR	0
NY Spills		0.125	0	NR	NR	NR	NR	0
DEL SHWS		1.000	0	0	0	0	NR	0
DRYCLEANERS		0.250	0	0	NR	NR	NR	0
ENG CONTROLS		0.500	0	0	0	NR	NR	0
AIRS		TP	NR	NR	NR	NR	NR	0
SPDES		TP	NR	NR	NR	NR	NR	0
EDR PROPRIETARY HISTO	RICAL DATAB	ASES						
Coal Gas		1.000	0	0	0	0	NR	0
BROWNFIELDS DATABAS	ES							
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
US INST CONTROL		0.500	0	0	0	NR	NR	0
Brownfields		0.500	0	0	0	NR	NR	0
VCP		0.500	0	0	0	NR	NR	0
INST CONTROL		0.500	0	0	0	NR	NR	0

NOTES:

AQUIFLOW - see EDR Physical Setting Source Addendum

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

EDR ID Number Database(s) EPA ID Number

Coal Gas Site Search: No site was found in a search of Real Property Scan's ENVIROHAZ database.

1 SSE < 1/8 87 ft.	AEOLIN CORP 2 SHELDON STREET RANDOLPH, NY 1477	2			SWF/LF	S103593113 N/A
Relative: Equal Actual: 1315 ft.	LF: Secondary Addr : Phone Number : Owner Type : Owner Address :	Not reported Private 2 SHELDON STREET	Region Code : Owner Name :	Not reported S ABBEY PL		AGER
	Owner Email : Contact Name : Contact Address	Not reported RANDOLPH, NY 14772 Not reported Not reported Not reported Not reported Not reported	Owner Phone :	Not reported		
	Contact Email : Activity Desc : Activity Number :	Not reported Not reported Landfill - mixed solid waste 05S14	Contact Phone :	Not reported		
	Active : North Coordinate Regulatory Status Waste Type :	No :Not reported	Accuracy Code : East Coordinate :	Not reported Not reported		
	Waste: Authorization # : Expiration Date : Flag :	Not reported None	Authorization Date	:Not reported		
2 WNW 1/8-1/4 966 ft.	RANDY'S GARAGE 229 MAIN STREET EAST RANDOLPH, N	(LTANKS	S101174757 N/A
Relative: Higher	LTANKS: Spill Number:	9407426	Region of Spill:	9	·2E	
Actual: 1321 ft.	Spill Date: ID: Material Spilled:	09/01/1994 12:30 Not reported Not reported	Reported to Dept: Date Call Received Amount Spilled:			
	Region Close Dt: Water Affected: Resource Affectd Spill Cause:	Not reported	Spill Source:	Gas Station		
	Facility Contact: Investigator: Caller Name: Caller Phone:	Not reported MF Not reported Not reported	Facility Tele: SWIS: Caller Agency: Caller Extension:	(716) 358-90 04 Not reported Not reported		
	Notifier Name: Notifier Phone: PBS:	Not reported Not reported Not reported	Notifier Agency: Notifier Extension:	Not reported Not reported		
	Spiller Contact: Spiller: Spiller Address:	Not reported RANDY ALDRICH 229 MAIN STREET EAST RANDOLPH, NY 14730	Spiller Phone:	Not reported		
	Spill Class:	Known release that creates potential f		Response.		
	Spill Closed Dt:	Willing Responsible Party. Corrective 02/07/95	action taken.			

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

S101174757

RANDY'S GARAGE (Continued)

Spill Notifier: C Cleanup Ceased: C	, Other 12/07/95			PBS Number:	Not reported
	12/28/94				
Cleanup Meets Sta		True			
Recommended Per	nalty:	Penalty Not Rec	ommended		
Spiller Cleanup Dat		11			
Enforcement Date:		//			
Investigation Comp UST Involvement:	piete:	/ / True			
Spill Record Last U	lodate:	07/24/00			
Is Updated:	puuto.	False			
Corrective Action P	lan Submi	tted:	//		
Date Spill Entered			09/02/94		
Date Region Sent S	Summary f	o Central Office:	//		
Tank Test:		Not us a suts al			
PBS Number: Tank Number:		Not reported Not reported			
Test Method:		Not reported			
Capacity of Faile	ed Tank:	Not reported			
Leak Rate Failed		Not reported			
Gross Leak Rate	e:	Not reported			
Material:					
Material Class T	•••	1			
Quantity Spilled: Units:		0 Pounds			
Unknown Qty Sp	villed.	No			
Quantity Recove		0			
Unknown Qty Re		True			
Material:		GASOLINE			
Class Type:		Petroleum			
Chem Abstract S	Service Nu	mber:	GASOLINE		
Last Date:	orial Entry	In File:	09/29/1994		
Num Times Mate DEC Remarks: 0			21329 ISIT/JENKINS	RANDY RP/4 GA	SOLINE UST REMOVED
					ENSOR. TANKS OUT OF SERVICE
>	> 6 YEARS	, POSSIBLY 15	YEARS. 10/05	5/94: MF 1ST SOIL	DISPOSAL EXCAVATION
					MF 2ND SOIL DISPOSAL
					1/94. 11/09/94: MF 11/8/94
					OUBLE/TERRY JENKINS.
					MORROW. 11/25/94:MF 11/25 _TS, PASSED FOR COMPOUNDS
					12/29/94: MF 12/28/94 SI
					EM 364 FOR 1/10/95. 12
/:	29/94: MF	2/7/95 RECEIVE	D SOIL DISP	OSAL RECEIPTS. 8	3020 TEST FOR TANK EX
				ER ACTION NECES	
Spill Cause: 0	CONTAMI	NATED SOIL FR	OM THREE T	ANK REMOVAL AR	EAS
Spill Number: 9	9407426			Region of Spill:	9
	09/01/94			Reported to Dept:	
•	204525			Date Call Received	
Material Spilled: 0	GASOLINE			Amount Spilled:	Unknown lbs.
Region Close Dt: 0					
	Not reporte			Spill Source:	GASOLINE STATION
Resource Affectd: (Spill Cause: 7	Groundwat Fank Failu				
•	Not reporte			Tank Size:	Not reported
	Not reporte			Leak Rate:	Not reported

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

-					Database(s)	EPA ID Number
F	RANDY'S GARAGE (Continued)					S101174757
•	PBS:	•	reported			0.01.11.01
1	TOWN OF RANDOLPH HWY DEPT UST U 15 WADSWORTH STREET RANDOLPH, NY 14772					
S	Site 1 of 2 in cluster A					
	PBS UST:					
	PBS Number: SPDES Numb Operator:		9-021059 Not reported TOWN OF RANDOLPH (716) 358-4555	CBS Number: SWIS ID:	Not reported 0476	
	Emergency C	ontact:	JAY L SMITH HWY SUPT (716) 358-2341			
	Total Tanks:		0			
	Owner:		TOWN OF RANDOLPH 15 WADSWORTH STREET RANDOLPH, NY 14772 (716) 358-4555			
	Owner Type:		Local Government			
	Owner Mark:		First Owner			
	Owner Subtyp	e:	Not reported			
	Mailing Addre	SS:	TOWN OF RANDOLPH			
			ATTN: JAY SMITH			
			15 WADSWORTH STREET			
			RANDOLPH, NY 14772			
	Task Otation		(716) 358-4555			
	Tank Status:		Closed - Removed 1000			
	Capacity (gals Tank Location		UNDERGROUND			
	Tank Location		1	Install Date:	Not reported	
	Tank Type:		Steel/carbon steel	Product Stored:	DIESEL	
	Tank Internal:		NONE	Pipe Internal:	NONE	
	Pipe Location		Underground	Pipe Type:	STEEL/IRON	
	Tank External		PAINTED/ASPHALT COATING			
	Missing Data		No Missing Data			
	Pipe External:		NONE			
	Second Conta	inment:	NONE			
	Leak Detectio	n:	NONE			
	Overfill Prot:		Automatic Shut-Off	Dispenser:	Suction	
	Date Tested:		Not reported	Next Test Date:	Not reported	
	Date Closed:		04/01/1996	Test Method:	Not reported	
	Deleted:		False	Updated:	True	
	Dead Letter:		False	Owner Screen:	Minor data missing	
	FAMT:		Fiscal amount for registration fee is	Renewal Date:	Not reported	
	Total Capacity Tank Screen:	/.	0 0	Federal ID:	Not reported	
	Renew Flag:		Renwal has not been printed	Facility Screen:	No data missing	
	Certification F	lao.	False	Certification Date:	-	
	Old PBS Num	0	Not reported	Expiration Date:		
	Inspected Dat		01/29/1991	Inspector:	JES	
	Inspection Re		Not reported			
	Lat/long:		Not reported			
	Facility Type:		OTHER			
	Town or City:		RANDOLPH			
	Town or City (Code:	76			
	County Code:	-	04			

Database(s) E

EDR ID Number EPA ID Number

TOWN OF RANDOLPH HWY DEPT (Continued)

U003316391

PBS Number:	9-021059	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	0476
Operator:	TOWN OF RANDOLPH		
	(716) 358-4555		
Emergency Contact:	JAY L SMITH HWY SUPT		
Total Tapka	(716) 358-2341		
Total Tanks:			
Owner:	TOWN OF RANDOLPH 15 WADSWORTH STREET		
	RANDOLPH, NY 14772		
	(716) 358-4555		
Owner Type:	Local Government		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	TOWN OF RANDOLPH		
	ATTN: JAY SMITH		
	15 WADSWORTH STREET		
	RANDOLPH, NY 14772		
	(716) 358-4555		
Tank Status:	Closed - Removed		
Capacity (gals): Tank Location:	1000 UNDERGROUND		
Tank Id:	2	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	DIESEL
Tank Internal:	NONE	Pipe Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING		
Missing Data for Tank:	No Missing Data		
Pipe External:	NONE		
Second Containment:	NONE		
Leak Detection:	NONE	D .	o <i>i</i> :
Overfill Prot:	Automatic Shut-Off	Dispenser:	Suction
Date Tested: Date Closed:	Not reported 04/01/1996	Next Test Date: Test Method:	Not reported
Deleted:	False	Updated:	Not reported True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is correct		Million data miloomig
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date	:07/08/1991
Old PBS Number:	Not reported	Expiration Date:	09/02/1996
Inspected Date:	01/29/1991	Inspector:	JES
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	RANDOLPH		
Town or City Code: County Code:	76 04		
Region:	9		
Region.	5		
PBS Number:	9-021059	CBS Number:	Not reported
SPDES Number:	Not reported	SWIS ID:	0476
Operator:	TOWN OF RANDOLPH		
_	(716) 358-4555		
Emergency Contact:	JAY L SMITH HWY SUPT		

Database(s)

EDR ID Number EPA ID Number

TOWN OF RANDOLPH HW	/Y DEPT (Continued)		U003316391
	(716) 358-2341		
Total Tanks: Owner:	0 TOWN OF RANDOLPH 15 WADSWORTH STREET RANDOLPH, NY 14772 (716) 358-4555		
Owner Type: Owner Mark:	Local Government First Owner		
Owner Subtype: Mailing Address:	Not reported TOWN OF RANDOLPH ATTN: JAY SMITH 15 WADSWORTH STREET RANDOLPH, NY 14772 (716) 358-4555		
Tank Status: Capacity (gals):	Closed - Removed 1000		
Tank Location:	UNDERGROUND		
Tank Id: Tank Type: Tank Internal:	3 Steel/carbon steel NONE	Install Date: Product Stored: Pipe Internal:	Not reported UNLEADED GASOLINE NONE
Pipe Location: Tank External: Missing Data for Tank:	Underground PAINTED/ASPHALT COATING No Missing Data	Pipe Type:	STEEL/IRON
Pipe External: Second Containment: Leak Detection:	NONE NONE NONE		
Overfill Prot: Date Tested:	Automatic Shut-Off Not reported	Dispenser: Next Test Date:	Suction Not reported
Date Closed:	04/01/1996	Test Method:	Not reported
Deleted:	False	Updated:	True
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is corre		
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0 Repuel has not been printed	Federal ID:	Not reported No data missing
Renew Flag: Certification Flag:	Renwal has not been printed False	Facility Screen: Certification Date	0
Old PBS Number:	Not reported	Expiration Date:	
Inspected Date:	01/29/1991	Inspector:	JES
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type: Town or City:	OTHER RANDOLPH		
Town or City Code:	76		
County Code:	04		
Region:	9		
PBS Number: SPDES Number:	9-021059 Not reported	CBS Number: SWIS ID:	Not reported 0476
Operator:	TOWN OF RANDOLPH (716) 358-4555	500 D.	UTTU
Emergency Contact:	JAY L SMITH HWY SUPT (716) 358-2341		
Total Tanks:	0		
Owner:	TOWN OF RANDOLPH 15 WADSWORTH STREET RANDOLPH, NY 14772 (716) 358-4555		

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

U003316391

TOWN OF RANDOLPH HWY DEPT (Continued)

Owner Type:	Local Government		
Owner Mark:	First Owner		
Owner Subtype:	Not reported		
Mailing Address:	TOWN OF RANDOLPH		
5	ATTN: JAY SMITH		
	15 WADSWORTH STREET		
	RANDOLPH, NY 14772		
	(716) 358-4555		
Tank Status:	Closed Prior to 04/91 (Either Closed In-F	Place or Removed)	
Capacity (gals):	1000	,	
Tank Location:	UNDERGROUND		
Tank Id:	4	Install Date:	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Tank Internal:	Not reported	Pipe Internal:	Not reported
Pipe Location:	1	Pipe Type:	STEEL/IRON
Tank External:	Not reported	1 - 71 -	
Missing Data for Tank:	Minor Data Missing		
Pipe External:	Not reported		
Second Containment:	NONE		
Leak Detection:	NONE		
Overfill Prot:	2	Dispenser:	Suction
Date Tested:	Not reported	Next Test Date:	Not reported
Date Closed:	Not reported	Test Method:	Not reported
Deleted:	False	Updated:	False
Dead Letter:	False	Owner Screen:	Minor data missing
FAMT:	Fiscal amount for registration fee is corre	ect	_
Total Capacity:	0	Renewal Date:	Not reported
Tank Screen:	0	Federal ID:	Not reported
Renew Flag:	Renwal has not been printed	Facility Screen:	No data missing
Certification Flag:	False	Certification Date	e:07/08/1991
Old PBS Number:	Not reported	Expiration Date:	09/02/1996
Inspected Date:	01/29/1991	Inspector:	JES
Inspection Result:	Not reported		
Lat/long:	Not reported		
Facility Type:	OTHER		
Town or City:	RANDOLPH		
Town or City Code:	76		
County Code:	04		
Region:	9		

A4RANDOLPH HIGHWAY DEPTWNW15 WADSWORTH STREET1/8-1/4RANDOLPH, NY

-			-
1	22	23	ft.

Site 2 of 2 in cluster A Relative:

Relative: Higher	LTANKS:			
	Spill Number:	9600425	Region of Spill:	9
Actual:	Spill Date:	04/09/1996 11:00	Reported to Dept:	04/09/96 16:46
1319 ft.	ID:	Not reported	Date Call Received	I:Not reported
	Material Spilled:	Not reported	Amount Spilled:	Not reported
	Region Close Dt:	Not reported		
	Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
	Resource Affectd	: Groundwater		
	Spill Cause:	Tank Test Failure		
	Facility Contact:	JAY SMITH	Facility Tele:	(716) 358-4555
	Investigator:	MNP	SWIS:	04
	Caller Name:	Not reported	Caller Agency:	Not reported
	Caller Phone:	Not reported	Caller Extension:	Not reported

LTANKS S102232942

N/A

Map ID Direction				MAP FINDING	S			
Distance Distance (ft. Elevation) Site						Database(s)	EDR ID Number EPA ID Number
	RANDOLPH HIGHWA	Y DEPT (C	ontinued)					S102232942
	Notifier Name:	Not reporte	ed		Notifier Agency:	Not repo	orted	
	Notifier Phone:	Not reporte			Notifier Extension:	Not repo	orted	
	PBS:	Not reporte			On illing Disease	N	and a set	
	Spiller Contact: Spiller:	Not reporte	ea PH HIGHWAY		Spiller Phone:	Not repo	опеа	
	Spiller Address:	15 WADS	NORTH STRE PH, NY 14772					
	Spill Class:	Known rele	ease that crea	tes potential for tag. Corrective act	ire or hazard. DEC F	Response	ð.	
	Spill Closed Dt:	09/16/96						
	Spill Notifier:	Other			PBS Number:	9-02105	9	
	Cleanup Ceased							
	Last Inspection:		-					
	Cleanup Meets S		True Departur Net I	Decemberded				
	Recommended F Spiller Cleanup D		/ /	Recommended				
	Enforcement Dat	e:	//					
	Investigation Con		//					
	UST Involvement		True					
	Spill Record Last	t Update:	10/22/96					
	Is Updated: Corrective Action	Plan Subm	False	/ /				
	Date Spill Entere			04/09/96				
	Date Region Sen							
	Tank Test:							
	PBS Number:		Not reported					
	Tank Number:		DIESEL					
	Test Method:	ile d Tenlu	Unknown					
	Capacity of Fa Leak Rate Fail		1000 0.00					
	Gross Leak Ra		Not reported					
	PBS Number:		Not reported					
	Tank Number:		DIESEL					
	Test Method:		Unknown					
	Capacity of Fa		1000					
	Leak Rate Fail		0.00					
	Gross Leak Ra	ate:	Not reported					
	PBS Number: Tank Number:		Not reported GASOLINE					
	Test Method:		Unknown					
	Capacity of Fa	iled Tank:	1000					
	Leak Rate Fail		0.00					
	Gross Leak Ra	ate:	Not reported					
	PBS Number:		Not reported					
	Tank Number: Test Method:		FUEL OIL Unknown					
	Capacity of Fa	iled Tank	1000					
	Leak Rate Fail		0.00					
	Gross Leak Ra		Not reported					
	Material:	_						
	Material Class		1					
	Quantity Spille	ea:	0 Gallons					
	Units: Unknown Qty :	Snilled	Gallons No					
	Quantity Reco		0					
	Unknown Qty							
	Material:		DIESEL					

Map ID Direction		MAP FINDING	S			
Distance Distance (ft Elevation	.) Site			Da	atabase(s)	EDR ID Number EPA ID Number
	RANDOLPH HIGHWA	Y DEPT (Continued)				S102232942
	Class Type:	Petroleum				
		Service Number: DIESEL				
	Last Date: Num Times Ma	07/28/1994 aterial Entry In File: 10625				
	DEC Remarks:	04/10/96: MNP INSP. JAY SMITH NOT (FOR TANK CLOSEST TO BUILDING. P IC COVERED, STAGED BEHIND STOR MNP TELECON W/ JAY SMITH - RAND LING SOIL DISPOSAL REQUIREMENT S ACOPY. ONLY 1-2 TRUCKLOADS OF DISPOSED. WILL SEND LETTER. 04/2, , WORK SCHEDULE DUE 5/9/96. 06/04 VED SAMPLE RESULTS. I ASKED HIM FAX OF SAMPLE RESULTS. 06/05/96: MPLE RESULTS. TANK PIT SIDE BOT , SITE CAN BE CLOSED AFTER SOIL I . 09/04/96: RECEIVED DISPOSAL REC MENT. NO FURTHER CLEANUP NEED JAY SMITH. NO FURTHER ACTION NE tank contractor found diesel contamination ated 6-10 tons of contaminated soil and ide samples collected from pit for 8021 8 already backfilled	ILE OF DIESEL COI AGE BUILDING 150 OLPH HWY DEPT. ' S. THE TANK PIT H F DIESEL CONTAMI 4/96: SOIL CLEANU /96: MNP TELECON TO FAX OR MAIL T MNP REVIEWED GI FOM SAMPLES MEE S DISPOSED WE R EIPTS FROM TOWN DED. 09/16/96: MNP EEDED, COMPLETE on during tank pull - 1 staged on plastic - bo	NTAMINATED C NEAR SANI WE DISCUSS AS BEEN SA NATED SOIL P DISPOSAL I W/ JAY SMI TO ME. 06/05/ ENERAL TES ET STARS 1 ECEIVE DISF N OF RANDO DRAFTED CI they excav ottom and s) SOIL, ON D PILE. 04/2 GED TANK F MPLED, DE WHICH SH LETTER SI TH. HE REC '96: RECEIN TING 4/17/9 GUIDANCE POSAL REC LPH HWY [PLAST 23/96: PIT SAMP COULD BE ENT, CEI /ED 96 SA E VALUES EIPTS DEPTART
	Spill Number:	9600425	Region of Spill:	9		
	Spill Date:	04/09/96	Reported to Dept:			
	ID:	231377	Date Call Receive		- 1	
	Material Spilled: Region Close Dt:		Amount Spilled:	Unknown Ga	al.	
	Water Affected:	Not reported	Spill Source:	OTHER NO	N COMM/IN	ISTITUTIONAL
	Resource Affectd:					
	Spill Cause:	Tank Test Failure	Tarly Cines	4000		
	Tank Number: Test Method:	DIESEL UNKNOWN	Tank Size: Leak Rate:	1000 0.00		
	PBS:	Not reported	Leak Nale.	0.00		
		•			-	
5 WNW 1/4-1/2 1554 ft.	RANDOLPH TRUCK S MAIN STREET RANDOLPH, NY	TOP			LTANKS	S101174071 N/A
Relative:	LTANKS:					
Higher	Spill Number:	9211093	Region of Spill:	9		
Astual	Spill Date:	12/01/1992 12:00	Reported to Dept:			
Actual: 1326 ft.	ID: Material Spilled:	Not reported Not reported	Date Call Received Amount Spilled:	Not reported		
	Region Close Dt:		Amount Opined.	Notropolice	•	
	Water Affected:	Not reported	Spill Source:	Gas Station		
	Resource Affectd:					
	Spill Cause:	Tank Failure	Facility Talas	(716) 500 00	225	
	Facility Contact: Investigator:	Not reported MF	Facility Tele: SWIS:	(716) 592-93 04	000	
	Caller Name:	Not reported	Caller Agency:	Not reported	1	
	Caller Phone:	Not reported	Caller Extension:	Not reported		
	Notifier Name:	Not reported	Notifier Agency:	Not reported		
	Notifier Phone:	Not reported	Notifier Extension:	Not reported	ł	
	PBS:	Not reported	o			
	Spiller Contact:	Not reported	Spiller Phone:	Not reported	1	
	Spiller:	SUGAR CREEK				

Map ID	
Direction	
Distance	
Distance (ft.)	
Elevation Site	

Database(s) **EPA ID Number RANDOLPH TRUCK STOP (Continued)** S101174071 Spiller Address: 760 BROOKS AVENUE ROCHESTER, NY 14619 Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. Spill Closed Dt: 05/03/93 Spill Notifier: Citizen PBS Number: Not reported Cleanup Ceased: 05/03/93 Last Inspection: 12/29/92 Cleanup Meets Standard: True **Recommended Penalty:** Penalty Not Recommended Spiller Cleanup Date: 11 Enforcement Date: 11 Investigation Complete: 11 **UST Involvement:** True Spill Record Last Update: 07/24/00 Is Updated: False Corrective Action Plan Submitted: 11 Date Spill Entered In Computer Data File: 12/28/92 Date Region Sent Summary to Central Office: / / Tank Test: PBS Number: Not reported Tank Number: Not reported Test Method: Not reported Capacity of Failed Tank: Not reported Leak Rate Failed Tank: Not reported Gross Leak Rate: Not reported Material: Material Class Type: 1 Quantity Spilled: 200 Units: Gallons Unknown Qty Spilled: 200 Quantity Recovered: 200 Unknown Qty Recovered: False Material: GASOLINE Class Type: Petroleum Chem Abstract Service Number: GASOLINE 09/29/1994 Last Date: Num Times Material Entry In File: 21329 12/28/92: MF 12/23/92 SITE VISIT/MANAGER. HE CLAIMED TANK OUT OF SERVICE DEC Remarks: . STUCK ALL GASOLINE TANKS FOR WATER. 24 OF WATER IN 4K MID GRADE. 12/3 0/92: MF 12/29/92 SITE VISIT/CONTRACTOR/RP. TANK BEING REMOVED. OVER 30 HOLES IN THE TANK. FREE PRODUCT ON THE GROUNDWATER. CONTAMINATION APPERA S WIDE SPREAD. TOLD RP WHAT MUST BE DONE. LETTER SENT. 02/10/93: MF LETT ER TO RP REQUESTING INVENTORY RECORDS BY 3/15/93. 03/01/93: MF 1ST DISPO SAL LETTER SENT GIVING UNTIL 4/1/93. 03/23/93: MF RECEIVED DISPOSAL RECE IPT. LETTER TO RP REDUCING FINE TO 500. PAYABLE BY 4/15/93. 04/20/93: M F 3/26/93 LETTER FROM RP TO REDUCE FINE. 4/20/93, LETTER TO RP REDUCING FINE TO 400. MUST BE RECEIVED BY 5/7/93. 05/03/93: MF RECEIVED CHEK FOR 400.00 TO SATISFY ORDER. EXCAVATION TESTED CLEAN SEE RESULTS). NO FURTH ER ACTION NECESSARY. Spill Cause: WATER IN GAS TANKS OF AUTOS FUELING. Spill Number: 9404072 Region of Spill: 9 Spill Date: 06/23/1994 01:15 Reported to Dept: 06/23/94 01:34 ID: Not reported Date Call Received:Not reported Material Spilled: Not reported

Amount Spilled:

Region Close Dt: Not reported

Not reported

EDR ID Number

Database(s)

EDR ID Number EPA ID Number

S101174071

RANDOLPH TRUCK STOP (Continued)

٩			linueuj				51
	Water Affected:	Not reporte	ed		Spill Source:	Gas Station	
	Resource Affectd:	On Land					
	Spill Cause:	Tank Over	fill				
	Facility Contact:	Not reporte	ed		Facility Tele:	(716) 372-2171	
	Investigator:	MF			SWIS:	04	
	Caller Name:	Not reporte			Caller Agency:	Not reported	
	Caller Phone:	Not reporte			Caller Extension:	Not reported	
	Notifier Name:	Not reporte			Notifier Agency:	Not reported	
	Notifier Phone:	Not reporte			Notifier Extension:	Not reported	
	PBS:	Not reporte			Chiller Dhanai	Not reported	
	Spiller Contact:	Not report			Spiller Phone:	Not reported	
	Spiller: Spiller Address:	GRIFFITH	OIL DKS AVENUE				
	opilier Address.	ROCHEST					
	Spill Class:			nal notential fo	r fire or hazard or K	nown	
	opin olass.				Willing Responsible		
			action taken.		Thining Reopendible	or any.	
	Spill Closed Dt:	06/23/94					
	Spill Notifier:	Responsib	le Partv		PBS Number:	Not reported	
	Cleanup Ceased:	•					
	Last Inspection:						
	Cleanup Meets St		True				
	Recommended P	enalty:	Penalty Not Rec	commended			
	Spiller Cleanup D	ate:	//				
	Enforcement Date	e:	//				
	Investigation Com	nplete:	//				
	UST Involvement:	:	True				
	Spill Record Last	Update:	07/05/94				
	Is Updated:		False				
	Corrective Action			/ /			
	Date Spill Entered			06/23/94			
	Date Region Sent	Summary	to Central Office:	//			
	Tank Test:						
	PBS Number:		Not reported				
	Tank Number:		Not reported				
	Test Method:		Not reported				
	Capacity of Fai		Not reported				
	Leak Rate Faile		Not reported				
	Gross Leak Ra Material:	te:	Not reported				
	Material Class		1				
	Quantity Spilled	•••	5				
	Units:		Gallons				
	Unknown Qty S	Snilled.	5				
	Quantity Recov		4				
	Unknown Qty F						
	Material:		GASOLINE				
	Class Type:		Petroleum				
	Chem Abstract	Service Nu		GASOLINE			
	Last Date:			09/29/1994			
	Num Times Ma	terial Entrv	In File:	21329			
	DEC Remarks:				ETE, APPX 5 GALL	ONS, SPEEDY DRY APP	PLI
					R ACTION NECES		
	Spill Cause:				PEEDY DRY APPLI		
	Spill Number:	9211093			Region of Spill:	9	
	Spill Date:	12/01/92			Reported to Dept:	//	

Database(s)

Date Call Received:12/23/92

200 Gal.

Not reported

Not reported

9

5 Gal.

Not reported Not reported

GASOLINE STATION

GASOLINE STATION

Amount Spilled:

Spill Source:

Tank Size:

Leak Rate:

Region of Spill:

Amount Spilled:

Spill Source:

Tank Size:

Leak Rate:

Reported to Dept: / /

Date Call Received:06/23/94

EDR ID Number **EPA ID Number**

S101174071

RANDOLPH TRUCK STOP (Continued)

ID: 178098 Material Spilled: GASOLINE Region Close Dt: 05/03/93 Water Affected: Not reported Resource Affectd: Groundwater Spill Cause: Tank Failure Tank Number: Not reported Test Method: Not reported PBS: Not reported Spill Number: 9404072 Spill Date: 06/23/94 ID: 201257 Material Spilled: GASOLINE Region Close Dt: 06/23/94 Water Affected: Not reported Resource Affectd: On Land Spill Cause: Tank Overfill Tank Number: Not reported Test Method: Not reported PBS: Not reported

TANK AT CAMP HOUSE ssw **67 LARKIN STREET** RANDOLPH, NY 1/4-1/2

1811 ft.

6

LTANKS S103478732 N/A

Relative:	LTANKS:					
Higher	Spill Number:	9802007		Region of Spill:	9	
	Spill Date:	05/15/199	8 13:30	Reported to Dept:	05/15/98 15:04	
Actual:	ID:	Not report	ed	Date Call Received	d:Not reported	
1399 ft.	Material Spilled:	Not report	ed	Amount Spilled:	Not reported	
	Region Close Dt:	Not report	ed			
	Water Affected:	Not report	ed	Spill Source:	Private Dwelling	
	Resource Affectd					
	Spill Cause:	Tank Failu				
Facility Contact: DAN			WELL	Facility Tele:	(716) 783-1421	
	Investigator:	JFO		SWIS:	04	
	Caller Name:	Not report		Caller Agency:	Not reported	
	Caller Phone:	Not report		Caller Extension:	Not reported	
	Notifier Name:	Not report		Notifier Agency:	Not reported	
	Notifier Phone:	Not report		Notifier Extension:	Not reported	
	PBS:	Not report			N	
	Spiller Contact:	Not report		Spiller Phone:	Not reported	
	Spiller:	-	I ENERGY			
	Spiller Address:		KEE ROAD			
	Spill Class:	ROCHESTER, NY				
	Spill Class.	Known release with minimal potential for fire or hazard. DEC Response.				
	Spill Closed Dt:	Willing Responsible Party. Corrective action taken. 06/30/98				
	Spill Notifier:	Other		PBS Number:	Not reported	
	Cleanup Ceased:	-		T DO Number.	Not reported	
	Last Inspection: 06/18					
Cleanup Meets Standa			True			
	Recommended Penalty:		Penalty Not Recommended			
	Spiller Cleanup D		//			
	Enforcement Date		//			
	Investigation Com	nplete:	11			
	UST Involvement	•	False			

TC01459790.1r Page 16

Database(s)

EDR ID Number EPA ID Number

TANK AT CAMP HOUS	E (Conti	nued)					S103478732
Spill Record Last U	Jpdate:	08/07/98					
Is Updated:		False					
Corrective Action F			//				
Date Spill Entered	•		05/15/98				
Date Region Sent S	Summary	to Central Office	://				
Tank Test: PBS Number:		Not reported					
Tank Number:		Not reported					
Test Method:		Not reported					
Capacity of Faile	ed Tank:	Not reported					
Leak Rate Failed		Not reported					
Gross Leak Rate	e:	Not reported					
Material:							
Material Class T Quantity Spilled:		1 20					
Units:		Gallons					
Unknown Qty Sp	oilled:	20					
Quantity Recove		10					
Unknown Qty Re	ecovered:	False					
Material:		#2 FUEL OIL					
Class Type:	- · ·	Petroleum					
Chem Abstract S Last Date:	Service Nu	umber:	#2 FUEL OIL	-			
Num Times Mate	orial Entry	In File:	12/07/1994 24464				
			-	HOME, I TALKED	TO THEIR CH	ILDREN. (CA
				NT TO FILTER AIR			
l	LOOR AL	ONG WITH A PC	WDER CITRU	JS TO MASK ODOF	R. DELIVERY	WAS MADE	E TO A TAN
				STOWELL OF GRIF			
				P 5/20. I WILL REI			
				ET WITH MR CAMP			
				ONCRETE STAINE F CONTAMINATED			
		RTHER ACTION I				OLLANOI	
				the new tank was fa	ulty oil comp		
•		ene now and clea			2		
	9802007			Region of Spill:	9		
	05/15/98			Reported to Dept: Date Call Receive			
	260182 #2 FUEL (Amount Spilled:	20 Gal.		
Region Close Dt: (/ mount opiniou.	20 00.		
0	Not report	ed		Spill Source:	PRIVATE DV	VELLING	
Resource Affectd:	On Land						
	Tank Failu						
	Not report			Tank Size:	Not reported		
	Not report			Leak Rate:	Not reported		
FD3. I	Not report	eu					
BEACOM RESIDENCE/	GRIFFITH	4				LTANKS	S104516465
48 CENTER STREET							N/A
RANDOLPH, NY							
LTANKS:							
	9975672	0 14.20		Region of Spill:	9	55	
	02/04/200 Not report			Reported to Dept: Date Call Receive		.00	
	Not report				Not reported		

Relative:	LTANKS:	
Lower	Spill Number:	9975672
	Spill Date:	02/04/2000 14:30
Actual:	ID:	Not reported
1310 ft.	Material Spilled:	Not reported
	Region Close Dt:	Not reported

7

NW 1/4-1/2 1896 ft.

TC01459790.1r Page 17

Amount Spilled: Not reported

Map ID Direction			MAP FINDINGS	5		
Distance Distance (ft. Elevation) Site				Database(s)	EDR ID Number EPA ID Number
	BEACOM RESIDENCI	E/GRIFFITH (Continued)				S104516465
	Water Affected:			Spill Source:	Private Dwelling	
	Resource Affectd			Spill Source.	Filvate Dwelling	
	Spill Cause:	Tank Overfill				
	Facility Contact:	DAN STOLLE		Facility Tele:	(716) 783-1411	
	Investigator:	MF		SWIS:	04	
	Caller Name:	Not reported		Caller Agency: Caller Extension:	Not reported	
	Caller Phone: Notifier Name:	Not reported Not reported		Notifier Agency:	Not reported Not reported	
	Notifier Phone:	Not reported		Notifier Extension:		
	PBS:	Not reported				
	Spiller Contact:	MR. BEACOM		Spiller Phone:	(716) 358-4394	
	Spiller:	GRIFFITH OIL				
	Spiller Address:	275 MCKEE ROAD ROCHESTER, NY 14611				
	Spill Class:	Possible release with min		r fire or hazard or K	nown	
	opin oldool	release with no damage.				
		Corrective action taken.			-	
	Spill Closed Dt:	02/07/00				
	Spill Notifier:	Responsible Party		PBS Number:	Not reported	
	Cleanup Ceased: Last Inspection:					
	Cleanup Meets S					
	Recommended P		ecommended			
	Spiller Cleanup D					
	Enforcement Date					
	Investigation Con UST Involvement	•				
	Spill Record Last					
	Is Updated:	False				
	Corrective Action		/ /			
		d In Computer Data File:	02/04/00 14:	56		
	Tank Test:	nt Summary to Central Offic	ce: / /			
	PBS Number:	Not reported				
	Tank Number:					
	Test Method: Capacity of Fa	Not reported ailed Tank: Not reported				
	Leak Rate Fail					
	Gross Leak Ra					
	Material:	- ,				
	Material Class	••				
	Quantity Spille Units:	Gallons				
	Unknown Qty S					
	Quantity Recov					
	•	Recovered: False				
	Material:	#2 FUEL OIL				
	Class Type: Chem Abstract	Petroleum t Service Number:	#2 FUEL OIL			
	Last Date:		12/07/1994			
	Num Times Ma	aterial Entry In File:	24464			
	DEC Remarks:	02/04/00: MF SITE INSE				
		OF 48 CENTER ST. FUE				
		FITTINGS LOOSE . LOS CRACKS. CREW ON SIT				
		O SIGNS OF OVERFILL				
		AN UP. DEBRIS TO BE T	TAKEN TO SHO	P FOR BULK DISP	OSAL. NO FURTHER AG	CTION N

Man			\$	7		
Map ID Direction		MAP FINDING	5			
Distance Distance (ft Elevation	.) Site			Datab	ase(s)	EDR ID Number EPA ID Number
		E/GRIFFITH (Continued)				S104516465
	BEACOW RESIDENCE					3104310403
	Spill Cause:	ECESSARY. OVERFILL OF 275-GAL. A/G FUEL OIL Y UNKNOWN AT THIS POINT.	TANK IN BASEMEN	IT OF RESIDENC	CE. QUA	NTIT
	Spill Number:	9975672	Region of Spill:	9		
	Spill Date:	02/04/00	Reported to Dept:	//		
	ID:	58111	Date Call Received			
	Material Spilled: Region Close Dt:		Amount Spilled:	3 Gal.		
	Water Affected:	Not reported	Spill Source:	PRIVATE DWE	LING	
	Resource Affectd	•	opin oouroo.			
	Spill Cause:	Tank Overfill				
	Tank Number:	Not reported	Tank Size:	Not reported		
	Test Method:	Not reported	Leak Rate:	Not reported		
	PBS:	Not reported				
8 NE 1/4-1/2 2199 ft.	LAKE COUNTRY DAIF MAIN STREET RANDOLPH, NY	RY		LT	ANKS	S100119898 N/A
Relative:	LTANKS:					
Lower	Spill Number:	8911103	Region of Spill:	9		
	Spill Date:	02/20/1990 08:00	Reported to Dept:			
Actual: 1278 ft.	ID: Material Spilled:	Not reported Not reported	Date Call Received Amount Spilled:	d:Not reported Not reported		
1270 11.	Region Close Dt:	•	Amount Spined.	Not reported		
	Water Affected:	Not reported	Spill Source:	Gas Station		
	Resource Affectd	•				
	Spill Cause:	Tank Failure				
	Facility Contact:	Not reported	Facility Tele:	(716) 736-3015		
	Investigator: Caller Name:	MF Not reported	SWIS: Caller Agency:	04 Not reported		
	Caller Phone:	Not reported	Caller Extension:	Not reported		
	Notifier Name:	Not reported		Not reported		
	Notifier Phone:	Not reported	Notifier Extension:	•		
	PBS:	Not reported				
	Spiller Contact:	Not reported	Spiller Phone:	Not reported		
	Spiller:	YAW OIL COMPANY 2 EAST SECOND STREET				
	Spiller Address:	LAKEWOOD, NY 14750				
	Spill Class:	Not reported				
	Spill Closed Dt:	08/12/91				
	Spill Notifier:	Health Department	PBS Number:	Not reported		
	Cleanup Ceased: Last Inspection:					
	Cleanup Meets St					
	Recommended P					
	Spiller Cleanup D	ate: / /				
	Enforcement Date					
	Investigation Com	•				
	UST Involvement Spill Record Last					
	Is Updated:	False				
	Corrective Action					
		d In Computer Data File: 02/26/90				
	-	t Summary to Central Office: / /				
	Tank Test:					
	PBS Number:	Not reported				

Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

S100119898

LAKE COUNTRY DAIRY (Continued)

	• • • •				
Tank Number:Not reportedTest Method:Not reportedCapacity of Failed Tank:Not reportedLeak Rate Failed Tank:Not reportedGross Leak Rate:Not reportedMaterial:Not reported					
Material Class	Туре:	1			
Quantity Spille	d:	30			
Units:		Gallons			
Unknown Qty S	Spilled:	30			
Quantity Reco	vered:	20			
Unknown Qty I		False			
Material:		GASOLINE			
Class Type:		Petroleum			
Chem Abstract	Service Nu	umber:	GASOLINE		
Last Date:			09/29/1994		
Num Times Ma	aterial Entry	In File:	21329		
DEC Remarks:	R TELCOI ND SPILLI WATER W FOLLOW. GROUND DISPOSA DISPOSA 09/29/95:	N W/ CACHD TO ER REMEDIATIC /ILL BE SAMPLE 10/31/90: MF 10 WATER TO BE F L LETTER SENT L RECEIPT GRC	HANDLE SP DN UNDERW/ D 8/15/90, VE /31/90 SAMPI RESAMPLED GIVING UNT DUNDWATER I information a	ILL SITE. 03/02/90: AY. 08/01/90: MF & ENT FAN STILL IN S LE RESULTS RECE IN THE SPRING. LE IL 7/31/91. 08/12/91	CAVATING. 02/28/90: LQ LQR TELCON W/ CACHD A (1/90 TELECON TIM YAW) SERVICE, A REPORT WILL EIVED. NO BTX DETECTED. ETTER SENT. 06/28/91: MF 2ND I: MF 8/12/91 RECEIVED IO FURTHER ACTION NECESSARY. d from th
Spill Cause:		BUILDING	nie. POWES.		
Spill Number:	8911103			Region of Spill:	9
Spill Date:	02/20/90			Reported to Dept:	
ID:	139107			Date Call Receive	
Material Spilled:	GASOLIN	E		Amount Spilled:	30 Gal.
Region Close Dt:	08/12/91				
Water Affected:	Not report	ed		Spill Source:	GASOLINE STATION
Resource Affectd	: Groundwa	ter			
Spill Cause:	Tank Failu	ire			
Tank Number:	Not report	ed		Tank Size:	Not reported
Test Method:	Not report	ed		Leak Rate:	Not reported
PBS:	9-105279				
Spill Number:	0275144			Region of Spill:	9
Spill Date:	06/01/02			Reported to Dept:	/ /
ID:	33634			Date Call Receive	d:06/11/02
Material Spilled:	GASOLIN	E		Amount Spilled:	0 Gal.
Region Close Dt:	01/27/03				
Water Affected:	Not report	ed		Spill Source:	OTHER NON COMM/INSTITUTIONAL
Resource Affectd					
Spill Cause:	Tank Failu				
Tank Number:	Not report			Tank Size:	Not reported
Test Method:	Not report	ed		Leak Rate:	Not reported
PBS:	Not report				

Database(s)

EDR ID Number EPA ID Number

9 ENE 1/4-1/2 2377 ft.	YAW OIL LAKE COUN 2 JAMESTOWN STREE RANDOLPH, NY					LTANKS	S102619465 N/A
Detection	LTANKS:						
Relative: Lower	-	9702289			Region of Spill:	9	
Lower		05/01/1997	7 12.00		Reported to Dept:		
Actual:		Not reporte			Date Call Received		
1277 ft.		Not reporte			Amount Spilled:	Not reported	
	Region Close Dt:				Allount Opinou.	Notropolica	
	-	Not report			Spill Source:	Gas Station	
	Resource Affectd:	•					
		Tank Failu	re				
		TED BOG			Facility Tele:	(716) 763-3015	
	•	MF			SWIS:	04	
	0	Not reporte	ed		Caller Agency:	Not reported	
		Not reporte			Caller Extension:	Not reported	
		Not reporte			Notifier Agency:	Not reported	
	Notifier Phone:	Not reporte	ed		Notifier Extension:	•	
	PBS:	Not reporte	ed				
	Spiller Contact:	Not reporte	ed		Spiller Phone:	Not reported	
	Spiller:	YAW OIL (COMPANY				
	Spiller Address:	2 EAST SI	ECOND STREE	Т			
			DD, NY 14750				
			ease that creates sponsible Party.		ire or hazard. DEC F ion taken.	Response.	
		09/23/97	, ,				
	•	Other			PBS Number:	Not reported	
	Cleanup Ceased:	09/23/97					
	Last Inspection:	08/22/97					
	Cleanup Meets Sta	andard:	False				
	Recommended Pe	enalty:	Penalty Not Re	commended			
	Spiller Cleanup Da	ate:	//				
	Enforcement Date		/ /				
	Investigation Com	•	/ /				
	UST Involvement:		True				
	Spill Record Last l	Update:	10/05/01				
	Is Updated:		False				
	Corrective Action I			/ / 05/22/97			
	Date Spill Entered Date Region Sent	•					
	Tank Test:	Guinnary					
	PBS Number:		Not reported				
	Tank Number:		Not reported				
	Test Method:		Not reported				
	Capacity of Fail	ed Tank:	Not reported				
	Leak Rate Faile		Not reported				
	Gross Leak Rat	e:	Not reported				
	Material:						
	Material Class 7	Гуре:	1				
	Quantity Spilled	:	0				
	Units:		Gallons				
	Unknown Qty S		No				
	Quantity Recove		0				
	Unknown Qty R	ecovered:					
	Material:		GASOLINE				
	Class Type:	Condes No	Petroleum				
	Chem Abstract	Service INU	imper:	GASOLINE			

EDR ID Number Database(s) EPA ID Number

YAW OIL LAKE COUNTY DAIRY (Continued)

S102619465

Spill Number: 9702289 Region of Spill: 9
Spill Date: 05/01/97 Reported to Dept: / /
ID: 248196 Date Call Received:05/21/97
Material Spilled: GASOLINE Amount Spilled: Unknown Gal.
Region Close Dt: 09/23/97
Water Affected: Not reported Spill Source: GASOLINE STATION
Resource Affectd: On Land
Spill Cause: Tank Failure
Tank Number: Not reported Tank Size: Not reported
Test Method: Not reported Leak Rate: Not reported
PBS: 9-105279

<u>Click this hyperlink</u> while viewing on your computer to access additional LTANKS detail in the EDR Site Report.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
CATTARAUGUS COUNTY	S105841838	SALAMANCA CONV. STATION	UNKNOWN		SWF/LF
COLD SPRING	1004761738	CATTARAUGUS COUNTY DPW	COUNTY RTE 39 OVER	14772	RCRA-SQG, FINDS
CONEWANGO	S106402601	LEVI RABER FARM - EMPIRE SPECIALTY CHEES	POPE ROAD	14772	SWF/LF
RANDOLPH	S102133034	NYSDOT RANDOLPH REST STOP	ROUTE 17 EB	14772	NY Spills
RANDOLPH	S102132679	C.R. CLARK	ROUTE 17	14772	NY Spills
RANDOLPH	S102133761	DOT REST AREA	ROUTE 17 EB - REST AREA	14772	NY Spills
RANDOLPH	S102134284	DIESEL ON ROAD SHOULDER	ROUTE 17	14772	NY Spills
RANDOLPH	S103562416	WEST VALLEY NUCLEAR SERV.	ROUTE 17 NEAR RANDOLPH	14772	NY Spills
RANDOLPH	S103562417	WEST VALLEY NUCLEAR SERV.	ROUTE 17 MP 1751121004	14772	NY Spills
RANDOLPH	S102447824	MANSUR TRUCKING	ROUTE 17-5112-1008 EB	14772	NY Spills
RANDOLPH	U003399863	CAMPBELL OIL CO INC RANDOLPH	RTE 242	14772	AST
RANDOLPH	S103569454	RANDOLPH CHILDREN'S HOME	ROUTE 394	14772	NY Spills
RANDOLPH	1001961518	NYSDOT BIN 1012180	RTE 394 BRG OVER BATTLE CREEK	14772	FINDS, RCRA-LQG
RANDOLPH	1001961544	NYSDOT BIN 1012160	RTE 394 OVER DAVIS BROOK	14772	FINDS, RCRA-LQG
RANDOLPH	1001961545	NYSDOT BIN 1012190	RTE 394 BR OVER LIT CONEWANGO	14772	FINDS, RCRA-LQG
RANDOLPH	S104643024		ROUTE 394	14772	NY Spills
RANDOLPH	S105058889	LCD - NYSDOT	RTE. 394	14772	NY Spills
RANDOLPH	S102132899	RANDOLPH MACHINE	CENTER STREET	14772	NY Spills
RANDOLPH	1007809712	RANDOLPH BRIDGE 21	COUNTY ROAD 8 OVER BATTLE CREEK	14772	FINDS
RANDOLPH	1007820230	NYS RANDOLPH FISH HATCHERY	10943 HATCHERY ROAD	14772	FINDS
RANDOLPH	1007797578	RANDOLPH TERRACE	JAMESTOWN STREET	14772	FINDS
RANDOLPH	1007793813	RANDOLPH LOYAL ORDER OF MOOSE	KINGSLEY STREET	14772	FINDS
RANDOLPH	S105912692	DAVID CHRISTIAN TIRE PILE	3292 KIRK RD.	14772	SWF/LF
RANDOLPH	U003318270	RANDOLPH QUAKER STATE	MAIN STREET	14772	UST
RANDOLPH	S106735961	RANDOLPH CENTRAL SCHOOL	MAIN STREET	14772	NY Spills
RANDOLPH	1007797575	RANDOLPH SUBSTATION	MAIN STREET	14772	FINDS
RANDOLPH	1007797378	RANDOLPH & EAST RANDOLPH S T P	MAIN STREET	14772	FINDS
RANDOLPH	1005499928	RANDOLPH (V) STP	MAIN STREET	14772	FINDS
RANDOLPH	S106468266	DON FRAME TRUCKING	MAIN STREET	14772	NY Spills
RANDOLPH	S102559887	TANK AT TWILITE LANES	MAIN STREET (ROUTE 394)	14772	NY Spills
RANDOLPH	1007797384	RANDOLPH CHILDRENS HOME	N/S RT 394 - NE OF RANDOLPH HIGH SCH	14772	FINDS
RANDOLPH	1007767008	TOWN OF RANDOLPH GRAVEL PIT	SARVER RD	14772	FINDS
RANDOLPH	1007809714	RANDOLPH BRIDGE NO. 5 BIN 3323150	SPRING STREET/ELM CREEK	14772	FINDS
RANDOLPH	1007797588	RANDOLPH VILLAGE PARK	WEEDEN RD	14772	FINDS

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

NPL: National Priority List

Source: EPA Telephone: N/A

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/28/05 Date Made Active at EDR: 05/16/05 Database Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC) Telephone: 202-564-7333

EPA Region 1 Telephone 617-918-1143

EPA Region 3 Telephone 215-814-5418

EPA Region 4 Telephone 404-562-8033

Proposed NPL: Proposed National Priority List Sites

Source: EPA Telephone: N/A

> Date of Government Version: 04/27/05 Date Made Active at EDR: 05/16/05 Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 05/04/05 Elapsed ASTM days: 12 Date of Last EDR Contact: 05/04/05

EPA Region 6 Telephone: 214-655-6659

EPA Region 8 Telephone: 303-312-6774

> Date of Data Arrival at EDR: 05/04/05 Elapsed ASTM days: 12 Date of Last EDR Contact: 05/04/05

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA

Telephone: 703-413-0223

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/15/05 Date Made Active at EDR: 04/06/05 Database Release Frequency: Quarterly Date of Data Arrival at EDR: 03/22/05 Elapsed ASTM days: 15 Date of Last EDR Contact: 03/22/05

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Source: EPA Telephone: 703-413-0223

As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

Date of Government Version: 03/22/05 Date of Data Arrival at EDR: 04/01/05 Date Made Active at EDR: 04/06/05 Elapsed ASTM days: 5 Database Release Frequency: Quarterly Date of Last EDR Contact: 04/01/05 **CORRACTS:** Corrective Action Report Source: EPA Telephone: 800-424-9346 CORRACTS identifies hazardous waste handlers with RCRA corrective action activity. Date of Government Version: 03/29/05 Date of Data Arrival at EDR: 04/11/05 Date Made Active at EDR: 05/16/05 Elapsed ASTM days: 35 Database Release Frequency: Quarterly Date of Last EDR Contact: 03/07/05 RCRA: Resource Conservation and Recovery Act Information Source: EPA Telephone: 800-424-9346 RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month. Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator off-site to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste. Date of Government Version: 05/20/05 Date of Data Arrival at EDR: 05/24/05 Date Made Active at EDR: 06/09/05 Elapsed ASTM days: 16 Database Release Frequency: Quarterly Date of Last EDR Contact: 05/24/05 ERNS: Emergency Response Notification System Source: National Response Center, United States Coast Guard Telephone: 202-260-2342 Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances. Date of Government Version: 12/31/04 Date of Data Arrival at EDR: 01/27/05 Date Made Active at EDR: 03/24/05 Elapsed ASTM days: 56 Database Release Frequency: Annually Date of Last EDR Contact: 04/25/05 FEDERAL ASTM SUPPLEMENTAL RECORDS BRS: Biennial Reporting System Source: EPA/NTIS Telephone: 800-424-9346 The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities. Date of Government Version: 12/01/01 Date of Last EDR Contact: 04/15/05 Database Release Frequency: Biennially Date of Next Scheduled EDR Contact: 06/13/05 CONSENT: Superfund (CERCLA) Consent Decrees Source: Department of Justice, Consent Decree Library **Telephone:** Varies Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released

periodically by United States District Courts after settlement by parties to litigation matters.

TC01459790.1r Page GR-2

Date of Government Version: 12/14/04	Date of Last EDR Contact: 04/26/05
Database Release Frequency: Varies	Date of Next Scheduled EDR Contact: 07/25/05
 ROD: Records Of Decision Source: EPA Telephone: 703-416-0223 Record of Decision. ROD documents mandate a permanent remedy at and health information to aid in the cleanup. 	an NPL (Superfund) site containing technical
Date of Government Version: 03/07/05	Date of Last EDR Contact: 04/04/05
Database Release Frequency: Annually	Date of Next Scheduled EDR Contact: 07/04/05
 DELISTED NPL: National Priority List Deletions Source: EPA Telephone: N/A The National Oil and Hazardous Substances Pollution Contingency Pla EPA uses to delete sites from the NPL. In accordance with 40 CFR 3 NPL where no further response is appropriate. 	
Date of Government Version: 04/28/05	Date of Last EDR Contact: 05/04/05
Database Release Frequency: Quarterly	Date of Next Scheduled EDR Contact: 08/01/05
 FINDS: Facility Index System/Facility Identification Initiative Program Sun Source: EPA Telephone: N/A Facility Index System. FINDS contains both facility information and 'poin detail. EDR includes the following FINDS databases in this report: Poinformation Retrieval System), DOCKET (Enforcement Docket used enforcement cases for all environmental statutes), FURS (Federal U Docket System used to track criminal enforcement actions for all environmental Laws and Statutes) 	nters' to other sources that contain more CS (Permit Compliance System), AIRS (Aerometric to manage and track information on civil judicial nderground Injection Control), C-DOCKET (Criminal <i>v</i> ironmental statutes), FFIS (Federal Facilities
Date of Government Version: 04/11/05	Date of Last EDR Contact: 04/04/05
Database Release Frequency: Quarterly	Date of Next Scheduled EDR Contact: 07/04/05
HMIRS: Hazardous Materials Information Reporting System Source: U.S. Department of Transportation Telephone: 202-366-4555 Hazardous Materials Incident Report System. HMIRS contains hazardo	bus material spill incidents reported to DOT.
Date of Government Version: 12/31/04	Date of Last EDR Contact: 04/19/05
Database Release Frequency: Annually	Date of Next Scheduled EDR Contact: 07/18/05
 MLTS: Material Licensing Tracking System Source: Nuclear Regulatory Commission Telephone: 301-415-7169 MLTS is maintained by the Nuclear Regulatory Commission and contai possess or use radioactive materials and which are subject to NRC I EDR contacts the Agency on a quarterly basis. 	
Date of Government Version: 04/14/05	Date of Last EDR Contact: 04/04/05
Database Release Frequency: Quarterly	Date of Next Scheduled EDR Contact: 07/04/05
 MINES: Mines Master Index File Source: Department of Labor, Mine Safety and Health Administration Telephone: 303-231-5959 Contains all mine identification numbers issued for mines active or oper violation information. 	ned since 1971. The data also includes

Date of Government Version: 02/11/05 Database Release Frequency: Semi-Annually	Date of Last EDR Contact: 03/30/05 Date of Next Scheduled EDR Contact: 06/27/05
 NPL LIENS: Federal Superfund Liens Source: EPA Telephone: 202-564-4267 Federal Superfund Liens. Under the authority granted the USEPA by t and Liability Act (CERCLA) of 1980, the USEPA has the authority to to recover remedial action expenditures or when the property owner USEPA compiles a listing of filed notices of Superfund Liens. 	o file liens against real property in order
Date of Government Version: 10/15/91 Database Release Frequency: No Update Planned	Date of Last EDR Contact: 02/22/05 Date of Next Scheduled EDR Contact: 05/23/05
 PADS: PCB Activity Database System Source: EPA Telephone: 202-564-3887 PCB Activity Database. PADS Identifies generators, transporters, com of PCB's who are required to notify the EPA of such activities. 	nmercial storers and/or brokers and disposers
Date of Government Version: 03/30/05 Database Release Frequency: Annually	Date of Last EDR Contact: 05/10/05 Date of Next Scheduled EDR Contact: 08/08/05
DOD: Department of Defense Sites Source: USGS Telephone: 703-692-8801 This data set consists of federally owned or administered lands, admin have any area equal to or greater than 640 acres of the United Stat Date of Government Version: 10/01/03 Database Release Frequency: Semi-Annually	
 UMTRA: Uranium Mill Tailings Sites Source: Department of Energy Telephone: 505-845-0011 Uranium ore was mined by private companies for federal government shut down, large piles of the sand-like material (mill tailings) remain the ore. Levels of human exposure to radioactive materials from th were used as construction materials before the potential health haz 24 inactive uranium mill tailings sites in Oregon, Idaho, Wyoming, U South Dakota, Pennsylvania, and on Navajo and Hopi tribal lands, Energy. 	use in national defense programs. When the mills nafter uranium has been extracted from he piles are low; however, in some cases tailings zards of the tailings were recognized. In 1978, Jtah, Colorado, New Mexico, Texas, North Dakota,
Date of Government Version: 12/29/04 Database Release Frequency: Varies	Date of Last EDR Contact: 03/22/05 Date of Next Scheduled EDR Contact: 06/20/05
ODI: Open Dump Inventory Source: Environmental Protection Agency Telephone: 800-424-9346 An open dump is defined as a disposal facility that does not comply w Subtitle D Criteria.	ith one or more of the Part 257 or Part 258
Date of Government Version: 06/30/85 Database Release Frequency: No Update Planned	Date of Last EDR Contact: 05/23/95 Date of Next Scheduled EDR Contact: N/A
FUDS: Formerly Used Defense Sites Source: U.S. Army Corps of Engineers Telephone: 202-528-4285 The listing includes locations of Formerly Used Defense Sites properti	

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers

is actively working or will take necessary cleanup actions.

TC01459790.1r Page GR-4

Date of Government Version: 12/31/03 Database Release Frequency: Varies	Date of Last EDR Contact: 04/04/05 Date of Next Scheduled EDR Contact: 07/04/05
INDIAN RESERV: Indian Reservations Source: USGS Telephone: 202-208-3710 This map layer portrays Indian administered lands of the United S than 640 acres.	tates that have any area equal to or greater
Date of Government Version: 10/01/03 Database Release Frequency: Semi-Annually	Date of Last EDR Contact: 02/08/05 Date of Next Scheduled EDR Contact: 05/09/05
 US ENG CONTROLS: Engineering Controls Sites List Source: Environmental Protection Agency Telephone: 703-603-8867 A listing of sites with engineering controls in place. Engineering controlations, liners, and treatment methods to create pathway endia or effect human health. 	
Date of Government Version: 01/10/05 Database Release Frequency: Varies	Date of Last EDR Contact: 04/04/05 Date of Next Scheduled EDR Contact: 07/04/05
 RAATS: RCRA Administrative Action Tracking System Source: EPA Telephone: 202-564-4104 RCRA Administration Action Tracking System. RAATS contains repertaining to major violators and includes administrative and civactions after September 30, 1995, data entry in the RAATS dat the database for historical records. It was necessary to termina made it impossible to continue to update the information contain 	vil actions brought by the EPA. For administration tabase was discontinued. EPA will retain a copy of te RAATS because a decrease in agency resources
Date of Government Version: 04/17/95 Database Release Frequency: No Update Planned	Date of Last EDR Contact: 03/07/05 Date of Next Scheduled EDR Contact: 06/06/05
 TRIS: Toxic Chemical Release Inventory System Source: EPA Telephone: 202-566-0250 Toxic Release Inventory System. TRIS identifies facilities which reland in reportable quantities under SARA Title III Section 313. 	elease toxic chemicals to the air, water and
Date of Government Version: 12/31/02 Database Release Frequency: Annually	Date of Last EDR Contact: 03/22/05 Date of Next Scheduled EDR Contact: 06/20/05
 TSCA: Toxic Substances Control Act Source: EPA Telephone: 202-260-5521 Toxic Substances Control Act. TSCA identifies manufacturers and TSCA Chemical Substance Inventory list. It includes data on th site. 	
Date of Government Version: 12/31/02 Database Release Frequency: Every 4 Years	Date of Last EDR Contact: 04/05/05 Date of Next Scheduled EDR Contact: 06/06/05
FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insec Source: EPA Telephone: 202-566-1667	ticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Contro
Date of Government Version: 04/13/05 Database Release Frequency: Quarterly	Date of Last EDR Contact: 03/21/05 Date of Next Scheduled EDR Contact: 06/20/05

Act)

SSTS: Section 7 Tracking Systems

Source: EPA

Telephone: 202-564-4203

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/03 Database Release Frequency: Annually Date of Last EDR Contact: 04/19/05 Date of Next Scheduled EDR Contact: 07/18/05

Date of Next Scheduled EDR Contact: 06/20/05

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) Source: EPA/Office of Prevention, Pesticides and Toxic Substances Telephone: 202-566-1667

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR cor

TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/13/05 Database Release Frequency: Quarterly

STATE OF NEW YORK ASTM STANDARD RECORDS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Source: Department of Environmental Conservation

Telephone: 518-402-9622

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/16/05 Date Made Active at EDR: 06/09/05 Database Release Frequency: Annually Date of Data Arrival at EDR: 05/19/05 Elapsed ASTM days: 21 Date of Last EDR Contact: 05/13/05

Date of Data Arrival at EDR: 05/04/05

Date of Last EDR Contact: 05/02/05

Elapsed ASTM days: 13

Date of Last EDR Contact: 03/21/05

SWF/LF: Facility Register

Source: Department of Environmental Conservation

Telephone: 518-457-2051

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 05/03/05 Date Made Active at EDR: 05/17/05 Database Release Frequency: Semi-Annually

LTANKS: Spills Information Database

Source: Department of Environmental Conservation

Telephone: 518-402-9549

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/02/05 Date Made Active at EDR: 05/31/05 Database Release Frequency: Varies Date of Data Arrival at EDR: 05/04/05 Elapsed ASTM days: 27 Date of Last EDR Contact: 04/25/05

UST: Petroleum Bulk Storage (PBS) Database

Source: Department of Environmental Conservation Telephone: 518-402-9549 Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 01/01/02 Date Made Active at EDR: 03/22/02 Database Release Frequency: No Update Planned	Date of Data Arrival at EDR: 02/20/02 Elapsed ASTM days: 30 Date of Last EDR Contact: 04/25/05
CBS UST: Chemical Bulk Storage Database Source: NYSDEC Telephone: 518-402-9549 Facilities that store regulated hazardous substances in underground ta	anks of any size
Date of Government Version: 01/01/02 Date Made Active at EDR: 03/22/02 Database Release Frequency: No Update Planned	Date of Data Arrival at EDR: 02/20/02 Elapsed ASTM days: 30 Date of Last EDR Contact: 04/25/05
 MOSF UST: Major Oil Storage Facilities Database Source: NYSDEC Telephone: 518-402-9549 Facilities that may be onshore facilities or vessels, with petroleum stor- greater. 	age capacities of 400,000 gallons or
Date of Government Version: 01/01/02 Date Made Active at EDR: 03/22/02 Database Release Frequency: Varies	Date of Data Arrival at EDR: 02/20/02 Elapsed ASTM days: 30 Date of Last EDR Contact: 04/25/05
 VCP: Voluntary Cleanup Agreements Source: Department of Environmental Conservation Telephone: 518-402-9711 New York established its Voluntary Cleanup Program (VCP) to address that often hinder the redevelopment and reuse of contaminated proto to enhance private sector cleanup of brownfields by enabling parties public funds and to reduce the development pressures on "greenfie" 	perties. The Voluntary Cleanup Program was developed s to remediate sites using private rather than
Date of Government Version: 12/17/04 Date Made Active at EDR: 01/31/05 Database Release Frequency: Semi-Annually	Date of Data Arrival at EDR: 12/17/04 Elapsed ASTM days: 45 Date of Last EDR Contact: 04/04/05
SWRCY: Registered Recycling Facility List Source: Department of Environmental Conservation Telephone: 518-402-8705 A listing of recycling facilities.	
Date of Government Version: 05/16/05 Date Made Active at EDR: 05/31/05 Database Release Frequency: Semi-Annually	Date of Data Arrival at EDR: 05/16/05 Elapsed ASTM days: 15 Date of Last EDR Contact: 05/16/05
SWTIRE: Registered Waste Tire Storage & Facility List Source: Department of Environmental Conservation Telephone: 518-402-8694	
Date of Government Version: 04/01/04 Date Made Active at EDR: 06/25/04 Database Release Frequency: Annually	Date of Data Arrival at EDR: 05/19/04 Elapsed ASTM days: 37 Date of Last EDR Contact: 02/17/05
STATE OF NEW YORK ASTM SUPPLEMENTAL RECORDS	
 HSWDS: Hazardous Substance Waste Disposal Site Inventory Source: Department of Environmental Conservation Telephone: 518-402-9564 The list includes any known or suspected hazardous substance waste from the Registry of Inactive Hazardous Waste Disposal Sites and registry 	•

from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 09/01/02 Database Release Frequency: No Update Planned	Date of Last EDR Contact: 02/28/05 Date of Next Scheduled EDR Contact: 05/30/05
AST: Petroleum Bulk Storage Source: Department of Environmental Conservation Telephone: 518-402-9549 Registered Aboveground Storage Tanks.	
Date of Government Version: 01/01/02 Database Release Frequency: No Update Planned	Date of Last EDR Contact: 04/25/05 Date of Next Scheduled EDR Contact: 07/25/05
 CBS AST: Chemical Bulk Storage Database Source: NYSDEC Telephone: 518-402-9549 Facilities that store regulated hazardous substances in aboveground tanks with and/or in underground tanks of any size. 	th capacities of 185 gallons or greater,
Date of Government Version: 01/01/02 Database Release Frequency: No Update Planned	Date of Last EDR Contact: 04/25/05 Date of Next Scheduled EDR Contact: 07/25/05
 MOSF AST: Major Oil Storage Facilities Database Source: NYSDEC Telephone: 518-402-9549 Facilities that may be onshore facilities or vessels, with petroleum storage cap greater. 	pacities of 400,000 gallons or
Date of Government Version: 01/01/02 Database Release Frequency: No Update Planned	Date of Last EDR Contact: 04/25/05 Date of Next Scheduled EDR Contact: 07/25/05
 SPILLS: Spills Information Database Source: Department of Environmental Conservation Telephone: 518-402-9549 Data collected on spills reported to NYSDEC as required by one or more of th Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 as of April 1, 1986, as well as spills occurring since this date. 	
Date of Government Version: 05/02/05 Database Release Frequency: Varies	Date of Last EDR Contact: 04/25/05 Date of Next Scheduled EDR Contact: 07/25/05
DEL SHWS: Delisted Registry Sites Source: Department of Environmental Conservation Telephone: 518-402-9622 A database listing of sites delisted from the Registry of Inactive Hazardous Wa	aste Disposal Sites.
Date of Government Version: 05/16/05 Database Release Frequency: Annually	Date of Last EDR Contact: 05/13/05 Date of Next Scheduled EDR Contact: 08/22/05
ENG CONTROLS: Registry of Engineering Controls Source: Department of Environmental Conservation Telephone: 518-402-9553 Environmental Remediation sites that have engineering controls in place.	
Date of Government Version: N/A Database Release Frequency: Quarterly	Date of Last EDR Contact: N/A Date of Next Scheduled EDR Contact: N/A
DRYCLEANERS: Registered Drycleaners Source: Department of Environmental Conservation Telephone: 518-402-8403 A listing of all registered drycleaning facilities.	

Date of Government Version: 06/15/04 Database Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System Source: Department of Environmental Conservation

Telephone: 518-402-8233

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 02/23/05 Database Release Frequency: No Update Planned

AIRS: Air Emissions Data

Source: Department of Environmental Conservation Telephone: 518-402-8452

Date of Government Version: 12/31/02 Database Release Frequency: Annually

LOCAL RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

Source: Cortland County Health Department Telephone: 607-753-5035

Date of Government Version: 01/19/05 Database Release Frequency: Quarterly

Cortland County Storage Tank Listing

Source: Cortland County Health Department Telephone: 607-753-5035

Date of Government Version: 01/19/05 Database Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

Source: Nassau County Health Department Telephone: 516-571-3314

Date of Government Version: 05/21/03 Database Release Frequency: No Update Planned

Registered Tank Database

Source: Nassau County Health Department Telephone: 516-571-3314

Date of Government Version: 05/21/03 Database Release Frequency: No Update Planned

Storage Tank Database

Source: Nassau County Office of the Fire Marshal Telephone: 516-572-1000

Date of Last EDR Contact: 05/21/04 Date of Next Scheduled EDR Contact: N/A

Date of Last EDR Contact: 02/07/05 Date of Next Scheduled EDR Contact: 05/09/05

Date of Last EDR Contact: 02/22/05 Date of Next Scheduled EDR Contact: 05/23/05

Date of Last EDR Contact: 02/01/05 Date of Next Scheduled EDR Contact: 05/30/05

Date of Last EDR Contact: 02/01/05 Date of Next Scheduled EDR Contact: 05/30/05

Date of Last EDR Contact: 02/01/05 Date of Next Scheduled EDR Contact: 05/02/05

Date of Last EDR Contact: 02/01/05 Date of Next Scheduled EDR Contact: 05/02/05

Date of Government Version: 05/25/04 Database Release Frequency: Varies

Storage Tank Database

Source: Nassau County Office of the Fire Marshal Telephone: 516-572-1000

Date of Government Version: 05/25/04 Database Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database

Source: Rockland County Health Department Telephone: 914-364-2605

Date of Government Version: 04/18/05 Database Release Frequency: Quarterly

Petroleum Bulk Storage Database

Source: Rockland County Health Department Telephone: 914-364-2605

Date of Government Version: 04/18/05 Database Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database

Source: Suffolk County Department of Health Services Telephone: 631-854-2521

Date of Government Version: 04/16/04 Database Release Frequency: Annually

Storage Tank Database

Source: Suffolk County Department of Health Services Telephone: 631-854-2521

Date of Government Version: 04/16/04 Database Release Frequency: Annually

WESTCHESTER COUNTY:

Listing of Storage Tanks

Source: Westchester County Department of Health Telephone: 914-813-5161 Listing of underground storage tanks in Westchester County.

Date of Government Version: 05/05/05 Database Release Frequency: Varies

Listing of Storage Tanks

Source: Westchester County Department of Health Telephone: 914-813-5161 Listing of aboveground storage tanks in Westchester County. Date of Last EDR Contact: 02/18/05 Date of Next Scheduled EDR Contact: 05/09/05

Date of Last EDR Contact: 02/18/05 Date of Next Scheduled EDR Contact: 05/09/05

Date of Last EDR Contact: 04/04/05 Date of Next Scheduled EDR Contact: 07/04/05

Date of Last EDR Contact: 04/04/05 Date of Next Scheduled EDR Contact: 07/04/05

Date of Last EDR Contact: 03/01/05 Date of Next Scheduled EDR Contact: 05/30/05

Date of Last EDR Contact: 03/01/05 Date of Next Scheduled EDR Contact: 05/30/05

Date of Last EDR Contact: 04/26/05 Date of Next Scheduled EDR Contact: 08/29/05

Date of Government Version: 05/05/05 Database Release Frequency: Varies Date of Last EDR Contact: 04/26/05 Date of Next Scheduled EDR Contact: 08/29/05

EDR PROPRIETARY HISTORICAL DATABASES

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

BROWNFIELDS DATABASES

Brownfields: Brownfields Site List

Source: Department of Environmental Conservation Telephone: 518-402-9764

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 12/17/04 Database Release Frequency: Semi-Annually Date of Last EDR Contact: 04/04/05 Date of Next Scheduled EDR Contact: 06/13/05

VCP: Voluntary Cleanup Agreements Source: Department of Environmental Conservation Telephone: 518-402-9711

The voluntary remedial program uses private monies to get contaminated sites r emediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

Date of Government Version: 12/17/04 Database Release Frequency: Semi-Annually Date of Last EDR Contact: 04/04/05 Date of Next Scheduled EDR Contact: 06/13/05

US BROWNFIELDS: A Listing of Brownfields Sites Source: Environmental Protection Agency Telephone: 202-566-2777

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 01/10/05 Database Release Frequency: Semi-Annually

US INST CONTROL: Sites with Institutional Controls

Source: Environmental Protection Agency Telephone: 703-603-8867

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 01/10/05 Database Release Frequency: Varies

INST CONTROL: Registry of Institutional Controls

Source: Department of Environmental Conservation Telephone: 518-402-9553 Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/16/05 Database Release Frequency: Quarterly Date of Last EDR Contact: 05/13/05 Date of Next Scheduled EDR Contact: 08/22/05

Date of Next Scheduled EDR Contact: 07/04/05

Date of Last EDR Contact: 03/14/05

Date of Last EDR Contact: 04/04/05

Date of Next Scheduled EDR Contact: 06/13/05

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: PennWell Corporation

Telephone: (800) 823-6277

This map includes information copyrighted by PennWell Corporation. This information is provided

on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its

fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc. Telephone: 312-280-5991 The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States. Daycare Centers: Day Care Providers

Source: Department of Health Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

New York State Wetlands

Source: Department of Environmental Conservation Telephone: 518-402-8961 Coverages are based on official New York State Freshwater Wetlands Maps as described in Article 24-0301 of the Environmental Conservation Law.

STREET AND ADDRESS INFORMATION

© 2004 Geographic Data Technology, Inc., Rel. 07/2004. This product contains proprietary and confidential property of Geographic Data Technology, Inc. Unauthorized use, including copying for other than testing and standard backup procedures, of this product is expressly prohibited.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

RANDOLPH FOUNDRY 4-8 SHELDON STREET RANDOLPH, NY 14772

TARGET PROPERTY COORDINATES

Latitude (North):	42.158600 - 42° 9' 31.0''
Longitude (West):	78.982697 - 78° 58' 57.7''
Universal Tranverse Mercator:	Zone 17
UTM X (Meters):	666660.6
UTM Y (Meters):	4669141.5
Elevation:	1315 ft. above sea level

EDR's GeoCheck Physical Setting Source Addendum has been developed to assist the environmental professional with the collection of physical setting source information in accordance with ASTM 1527-00, Section 7.2.3. Section 7.2.3 requires that a current USGS 7.5 Minute Topographic Map (or equivalent, such as the USGS Digital Elevation Model) be reviewed. It also requires that one or more additional physical setting sources be sought when (1) conditions have been identified in which hazardous substances or petroleum products are likely to migrate to or from the property, and (2) more information than is provided in the current USGS 7.5 Minute Topographic Map (or equivalent) is generally obtained, pursuant to local good commercial or customary practice, to assess the impact of migration of recognized environmental conditions in connection with the property. Such additional physical setting sources generally include information about the topographic, hydrologic, hydrogeologic, and geologic characteristics of a site, and wells in the area.

Assessment of the impact of contaminant migration generally has two principle investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata. EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

USGS Topographic Map:	42078-B8 RANDOLPH, NY
General Topographic Gradient:	General NNE
Source:	USGS 7.5 min quad index

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County CATTARAUGUS, NY	FEMA Flood <u>Electronic Data</u> YES - refer to the Overview Map and Detail Map
Flood Plain Panel at Target Property:	3600960001B
Additional Panels in search area:	3600650010B 3600950005A 3600950004A 3600950008A
NATIONAL WETLAND INVENTORY	
NWI Quad at Target Property RANDOLPH	NWI Electronic <u>Data Coverage</u> Not Available

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:		
Search Radius:	1.25 miles	
Status:	Not found	

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID Not Reported LOCATION FROM TP GENERAL DIRECTION GROUNDWATER FLOW

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

GEOLOGIC AGE IDENTIFICATION

Era:		Category:	Stratified Sequence
System:	Devonian		
Series:	Upper Devonian		
Code:	D3 (decoded above as Era, System & Serie	s)	

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	VALOIS	
Soil Surface Texture:	gravelly - silt loam	
Hydrologic Group:	Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.	
Soil Drainage Class:	Well drained. Soils have intermediate water holding capacity. Depth to water table is more than 6 feet.	
Hydric Status: Soil does not meet the requirements for a hydric soil.		

Corrosion Potential - Uncoated Steel: LOW

Depth to Bedrock Min:	> 60 inches

Depth to Bedrock Max: > 60 inches

	Soil Layer Information						
	Bou	Indary		Classi	fication		
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	7 inches	gravelly - silt Ioam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 2.00 Min: 0.60	Max: 6.00 Min: 3.60
2	7 inches	30 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 2.00 Min: 0.60	Max: 6.00 Min: 3.60
3	30 inches	47 inches	gravelly - silt Ioam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 6.00 Min: 0.60	Max: 6.00 Min: 3.60
4	47 inches	60 inches	very gravelly - fine sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 6.00 Min: 0.60	Max: 7.30 Min: 4.50

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures:	gravelly - loam channery - silt loam
Surficial Soil Types:	gravelly - loam channery - silt loam
Shallow Soil Types:	gravelly - loam fine sandy loam channery - silt loam
Deeper Soil Types:	stratified gravelly - fine sandy loam very channery - loam channery - loam unweathered bedrock

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

According to ASTM E 1527-00, Section 7.2.2, "one or more additional state or local sources of environmental records may be checked, in the discretion of the environmental professional, to enhance and supplement federal and state sources... Factors to consider in determining which local or additional state records, if any, should be checked include (1) whether they are reasonably ascertainable, (2) whether they are sufficiently useful, accurate, and complete in light of the objective of the records review (see 7.1.1), and (3) whether they are obtained, pursuant to local, good commercial or customary practice." One of the record sources listed in Section 7.2.2 is water well information. Water well information can be used to assist the environmental professional in assessing sources that may impact groundwater flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

		LOCATION
MAP ID	WELL ID	FROM TP
1	USGS2241974	1/2 - 1 Mile SE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

		LOCATION
MAP ID	WELL ID	FROM TP
No PWS System Found		


Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

		LOCATION
MAP ID	WELL ID	FROM TP

No Wells Found

PHYSICAL SETTING SOURCE MAP - 01459790.1r



Cluster of Multiple Icons

TARGET PROPERTY: ADDRESS: CITY/STATE/ZIP: LAT/LONG: Randolph Foundry 4-8 Sheldon Street Randolph NY 14772 42.1586 / 78.9827 CUSTOMER: Panam CONTACT: Peter J. INQUIRY #: 014597 DATE: July 06,

Panamerican Environmental, Inc Peter J. Gorton 01459790.1r July 06, 2005 12:47 pm

GEOCHECK®- PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
1 SE 1/2 - 1 Mile Lower			FED USGS	USGS2241974
Agency cd: Site name: Latitude:	USGS CT 618 420913	Site no:	420913078583000	
Longitude: Dec lon:	0785830 -78.97476187	Dec lat: Coor meth:	42.15367172 M	
Coor accr: Dec latlong datum:	F NAD83	Latlong datum: District:	NAD27 36	
State: Country:	36 US	County: Land net:	009 Not Reported	
Location map: Altitude:	RANDOLPH M-05-1 Not Reported	Map scale: Altitude method:	Not Reported Not Reported	
Altitude accuracy: Hydrologic: Topographic:	Not Reported Conewango. Pennsylvania, New Not Reported	Altitude datum: York. Area = 888 sq.mi.	Not Reported	
Site type: Date inventoried:	Ground-water other than Spring Not Reported	Date construction: Mean greenwich time offset:	Not Reported EST	
Local standard time flag: Aquifer Type: Aquifer:	N Not Reported Not Reported	Type of ground water site:	Single well, other tha	n collector or Ranney type
Well depth: Source of depth data: Real time data flag:	Not Reported Not Reported 0	Hole depth: Project number: Daily flow data begin date:	Not Reported Not Reported 0000-00-00	
Daily flow data end date: Peak flow data begin date: Peak flow data count:	0000-00-00 0000-00-00 0	Daily flow data begin date. Daily flow data count: Peak flow data end date: Water quality data begin date:	0 0000-00-00	
Water quality data end date:1973-08-29 Ground water data begin date: 0000-00-00 Ground water data count: 0		Water quality data count: Ground water data end date:	1 0000-00-00	

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

Zip	Num Sites	< 4 Pci/L	>= 4 Pci/L	>= 20 Pci/L	Avg > 4 Pci/L	Max Pci/L
14772	48	20 (41.7%)	20 (41.7%)	8 (16.7%)	9.92	51.5

Federal EPA Radon Zone for CATTARAUGUS County: 1

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for CATTARAUGUS COUNTY, NY

Number of sites tested: 65

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	1.780 pCi/L	83%	17%	0%
Basement	2.760 pCi/L	62%	31%	8%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey EDR acquired the USGS 7.5' Digital Elevation Model in 2002. 7.5-Minute DEMs correspond to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

New York State Wetlands

Source: Department of Environmental Conservation Telephone: 518-402-8961 Coverages are based on official New York State Freshwater Wetlands Maps as described in Article 24-0301 of the Environmental Conservation Law.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STATE RECORDS

New York Public Water Wells

Source: New York Department of Health Telephone: 518-458-6731

New York Facility and Manifest Data

Source: NYSDEC Telephone: 518-457-6585 Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

RADON

State Database: NY Radon

Source: Department of Health Telephone: 518-402-7556 Radon Test Results

Area Radon Information

Source: USGS Telephone: 703-356-4020 The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA Telephone: 703-356-4020 Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater Source: Department of Commerce, National Oceanic and Atmospheric Administration

APPENDIX C

Site Photographs



Photograph 1. Adjacent property to the west (10 Sheldon) of the subject property, facing north.



Photograph 2. Subject property from across Sheldon Street, facing northeast.



Photograph 3. Western portion of subject property, facing north.



Photograph 4. Subject property from the corner of Sheldon and Washington Streets, facing northwest.



Photograph 5. Two pole mounted transformers in the southern portion of the property.



Photograph 6. Weeds, telephone pole and piping debris on the subject property on Sheldon and Washington corner.



Photograph 7. Concrete, miscellaneous material, and grass and weed covered area in the southern portion of the property.



Photograph 8. Pile of debris in the southern portion of the property.



Photograph 9. Inside the southeastern portion of the structure, facing west.



Photograph 10. Eastern portion of the structure, facing north.



Photograph 11. Southeastern portion of the structure, facing east.



Photograph 12. Former AST used for burning of materials located in the southeastern portion of the structure.



Photograph 13. Possible pile of foundry sand and other miscellaneous debris located in the eastern portion of the structure.



Photograph 14. Junk automobile and other debris in the eastern portion of the structure.



Photograph 15. Foundry sand and northwestern area of the eastern portion of the structure, facing northwest.



Photograph 16. Western area of the eastern portion of the structure, facing south.



Photograph 17. Storage of concrete mix and other materials in the northwestern area of the eastern portion of the structure.



Photograph 18. Two large furnaces or molds and other debris located within a pit in the middle of the eastern area of the structure.



Photograph 19. Portions of ceiling and walls in the eastern area of the structure that are in disrepair.



Photograph 20. Large machine on tractor trailer bed - unknown use.



Photograph 21. Small storage/electrical area in the northern portion of the structure.



Photograph 22. Two 55-gallon drums near the pit where the furnaces/molds were located.



Photograph 23. Miscellaneous materials in large room of western area of structure.



Photograph 24. Another view of large room of western area and scattered debris/tires.




Photograph 25. 5-gallon pails and other debris in the southern portion of the large room of the western side of the structure.



Photograph 26. Miscellaneous debris located in the western large room, facing southwest.



Photograph 27. Storage of miscellaneous materials in small storage area to the east of the large western room.



Photograph 28. Electrical boxes near the offices in the western portion of the structure.



Photograph 29. Insulation and overhead garage door opening to the southern portion of the structure.



Photograph 30. Storage shelving and bathroom in the southwestern end of the structure.



Photograph 31. Small office area in the southwestern corner of the structure.




Photograph 32. Miscellaneous storage and piping located in the western area of the structure.



Photograph 33. Storage of miscellaneous materials in western area.



Photograph 34. Water-dispense mechanism tied to water pipes in the western portion of the structure.



Photograph 35. Western portion of the structure.



Photograph 36. Area behind large storage unit in the eastern area of the structure.



Photograph 37. Storage unit in the eastern portion of the structure.



Photograph 38. Subject property and structure from the intersection of railroad tracks and Washington Street, facing southwest.



Photograph 39. 55-gallon drum and other miscellaneous debris in weed covered area to the northwest of the subject building.



Photograph 40. Transformers of poles to the rear (north) of the structure.



Photograph 41. Hopper to the rear (north) of the structure.



Photograph 42. 5-gallon containers located in the western portion of the building.

PHASE I ENVIRONMENTAL SITE ASSESSMENT FORMER FOUNDRY BUILDING AND PROPERTY SHELDON STREET TOWN OF RANDOLPH, CATTARAUGUS COUNTY, NEW YORK

Prepared for:

Cattaraugus County 303 Court Street Little Valley, New York 14755

Attention:

Mr. Joseph Keller Treasurer

Prepared by:

Panamerican Environmental, Inc. 2390 Clinton Street Buffalo, New York 14227 Ph: (716) 821-1650 Fax: (716) 821-1607

June - July 2005

Submitted by:

Peter J. Gorton, MPH, CHCM

A Phase I Environmental Site Assessment (ESA) was completed by Panamerican Environmental, Inc. (PEI) for the one-story cement block and metal framed building and former foundry/machine shop property, located on the northwest corner of Sheldon Street and South Washington Street (2-8 Sheldon Street) in the Village of Randolph, Cattaraugus County, New York. Performed for Cattaraugus County, the ESA was conducted in accordance with ASTM standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Practice E 1527-00 (ASTM Standard). In defining a standard of good commercial and customary practice for conducting an environmental assessment of a parcel of property, the goal of the process established by the ASTM Standard is to identify recognized environmental conditions. This Phase I was conducted to meet this goal. Recognized environmental conditions are defined in the ASTM Standard as the presence or the likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum onto or effecting the property.

Investigative activities included agency interviews, site inspections, and interviews with representatives of the local government and local historians, as well as a review of government and historical Village of Randolph records.

The site is unsecured. The former foundry and machine shop property is approximately179 feet by 229 feet and includes an abandoned cement block office and sheet metal manufacturing/warehouse type building. The abandoned structure, which is severely dilapidated and may be structurally unsound in some portions, contains a large garage/work area, workshop areas, former parts and machining areas, storage rooms and office type areas. Various debris, equipment, foundry sands and materials from former processes are still located at the site including some 55-gallon drums and other small containers of materials. These drums are rusty and in poor condition. Foundry sand covers much of the warehouse/manufacturing area and piles are located in some areas. Parts of the site are heavily vegetated and some vegetation is growing within the more dilapidated sections. A lager hopper is located in the rear of the structure as are two large elevated transformers.

A review of historic aerial and Sanborn maps as well as building permit records indicate that the current structures and property have been altered over time. The exact date that the existing structure was built is unknown, however, historical maps indicate that a foundry and machine shop (F. H. Pike Foundry and Machine Shop) was located on the property as early as 1902. By 1929, historic maps indicate that the property was identified as the Randolph Foundry and Machine Shop. As late as 1897 however, a dairy was located on the property. Individuals with knowledge of the history of the Village indicate the Randolph Foundry was at one time owned by Aeolian (verified also by ownership records) and made piano plates out of recycled metal. The foundry was later sold and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years.

Historically, land use in the property area has been commercial/retail and residential properties. A rail line has historically been located immediately adjacent to the eastern portion of the property. The subject property is located in an area currently zoned within a "Village Residential District" and

Panamerican Environmental, Inc.

is surrounded by residential homes (both single and multi-family), small commercial, industrial, and retail businesses. Residential properties are immediately adjacent to the property along its northern and western sides. Adjacent properties include: the Southern Tier Railway to the north and east of the property, and residential structures located on Sheldon and Green Streets to the west, southwest of the property.

Foundries (or metal casting operations) make parts from molten metal according to end user specifications. Since the historic maps indicate that the facility was also a machine shop, it implies that the parts (castings) were used to produce larger products such as machinery, motor vehicles, appliances, plumbing fixtures, etc. In this case, at least for a time, parts for pianos. In general, foundry and machine shops are typically somewhat "dirty" operations and involved with the manufacturing, prefabrication, and repair of articles of steel, iron, and other metals. Environmental contamination associated with these facilities include elevated levels of lead and other metals in near and subsurface soils and wastes associated with slag/foundry sands such as phenols. Other contaminants, including solvents and petroleum products are typically associated with drummed materials.

Portions of the property contain debris piles. C&D material including brick, concrete block, and wood is located on the south-southeastern front portions of the property. The material appears to be rubble from the former structures. A large pile of concrete, brick, cement, and wood are located in grassy and weed covered areas along the southern portion of the property. Historical maps indicate that a boarding house was located in this area of the property during the early 1900's.

A review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. A review of NYSDEC Region 9 records indicates that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. and that approximately 1,500 pounds of foundry sand was disposed per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling occurred from 1976 to about 1981. The company initiated a permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property.

A total of eight (8) additional database records were found for the adjacent and surrounding properties within the ASTM government records search radius. These include seven Spills Information Database (LTANKS) sites, and one registered Underground Storage Tank facility.

This assessment has identified potential recognized environmental conditions in connection with the subject property including the following: its history as a SWF/LF, potential contamination associated with foundry sands and slag piles as well as other materials and wastes; various 55-gallon drums and other containers which are in poor condition and contain unknown contents; and potential PCBs associated with the elevated transformers. The property is in very poor condition, may be structurally un-sound in portions and has wastes and materials strewn

Panamerican Environmental, Inc.

throughout the interior.

Based on the information reviewed for this Phase I ESA, PEI cannot verify with complete certainty that near-surface or subsurface contamination or other environmental impairment does not exist at this property, especially with regard to the foundry sand/slag observed throughout the structure and rubble piles. These may have migrated to both on-site and offsite soils especially since the property operated as a foundry and machine shop for approximately 84 years. In summary, PEI believes that potential environmental risk may be associated with this property and that follow-up assessment may be necessary to determine if contamination exists.

TABLE OF CONTENTS

Sec	tion	Page
List	of Append	mmaryii dices
1.0	INTROD 1.1 1.2 1.3	Introduction and Purpose1Scope1Site Reconnaissance11.3.1Summary of Observations1.3.2Primary Property Uses1.3.3Treatment, Storage or Disposal Facilities (TSDF)1.3.4Hazardous Waste/Substances1.3.5Above Ground/Underground Chemical/Petroleum Storage Tanks (AST/UST)1.3.6PCB Containing Equipment1.3.7Asbestos Containing Material/Lead-Based Paint1.3.8Stains, Spills, Stressed Vegetation1.3.9Landfills/Dumping Activities1.3.10Pits, Sumps, Wells1.3.11Ponds and Lagoons1.3.12Coastal Areas1.3.13Potable Water Supply1.3.14Sewage Disposal1.3.15Roads and Parking Lots1.3.16Odors1.3.17Heating and Cooling System1.3.18Other Noteworthy Observations/Issues
2.0	ASS	ET INFORMATION AND DESCRIPTION
3.0	3.1 3.2	DESCRIPTION 7 Location and Current Use 7 General Property and Area Features 7 Adjacent Properties 7 Property Surface Features and Drainage 7 Utilities 8 Site Geology/Hydrogeology 8
4.0	SITE 4.1 4.2	HISTORY8Historical Sources Reviewed8Site and Area Historical Chain of Use84.2.1Chain of Title Information4.2.2Chain of Use Records4.2.3Aerial Photographs4.2.4Sanborn Maps and Other Historical Maps

	4.3 Previous Environmental Studies/Historical Data
5.0	REGULATORY/AGENCY RECORDS REVIEW
6.0	OTHER RECORDS REVIEWED/INTERVIEWS CONDUCTED116.1 City Offices116.2 County Offices126.3 NYSDEC Files126.4 Interviews12
7.0	REVIEW OF SPECIAL RESOURCES127.1 Historic Resources127.2 Farmlands127.3 Recreational Areas127.4 Land Use137.5 Wetlands and Floodplains13
8.0	ENVIRONMENTAL ASSESSMENT SUMMARY, CONCLUSIONS AND RECOMMENDATIONS
9.0	DATA NEEDS
10.0	WARRANT AND LIMITATIONS

LIST OF APPENDICES

Appendix

- Α.
- Aerial Photographs ASTM Detailed Radius Database Report Β.
- C.
- D.
- Ε.
- Site Photographs Area/Property Maps Property Title and Assessment Information NYSDEC FOIL and NYSDEC File Information F.

LIST OF PHOTOGRAPHS AND ILLUSTRATIONS

Aerial Photographs

I. 1956 Aeriai Photodrabr	1.	1956	Aerial Photograph
---------------------------	----	------	-------------------

- 2. 1966 Aerial Photograph
- 3. 1980 Aerial Photograph
- 4. 1995 Aerial Photograph
- 5. 2002 Aerial Photograph

Photograph

- 1. Adjacent property to the west (10 Sheldon) of the subject property, facing north.
- 2. Subject property from across Sheldon Street, facing northeast.
- 3. Western portion of subject property, facing north.
- 4. Subject property from the corner of Sheldon and Washington Streets, facing northwest.
- 5. Two pole mounted transformers in the southern portion of the property.
- 6. Weeds, telephone pole and piping debris on the subject property on Sheldon and Washington corner.
- 7. Concrete, miscellaneous material, and grass and weed covered area in the southern portion of the property.
- 8. Pile of debris in the southern portion of the property.
- 9. Inside the southeastern portion of the structure, facing west.
- 10. Eastern portion of the structure, facing north.
- 11. Southeastern portion of the structure, facing east.
- 12. Former AST used for burning of materials located in the southeastern portion of the structure.
- 13. Possible pile of foundry sand and other miscellaneous debris located in the eastern portion of the structure.
- 14. Junk automobile and other debris in the eastern portion of the structure.
- 15. Foundry sand and northwestern area of the eastern portion of the structure, facing northwest.
- 16. Western area of the eastern portion of the structure, facing south.
- 17. Storage of concrete mix and other materials in the northwestern area of the eastern portion of the structure.
- 18. Two large furnaces or molds and other debris located within a pit in the middle of the eastern area of the structure.
- 19. Portions of ceiling and walls in the eastern area of the structure that are in disrepair.
- 20. Large machine on tractor trailer bed unknown use.
- 21. Small storage/electrical area in the northern portion of the structure.
- 22. Two 55-gallon drums near the pit where the furnaces/molds were located.
- 23. Miscellaneous materials in large room of western area of structure.
- 24. Another view of large room of western area and scattered debris/tires.
- 25. 5-gallon pails and other debris in the southern portion of the large room of the western side of the structure.
- 26. Miscellaneous debris located in the western large room, facing southwest.
- 27. Storage of miscellaneous materials in small storage area to the east of the large western room.

- 28. Electrical boxes near the offices in the western portion of the structure.
- 29. Insulation and overhead garage door opening to the southern portion of the structure.
- 30. Storage shelving and bathroom in the southwestern end of the structure.
- 31. Small office area in the southwestern corner of the structure.
- 32. Miscellaneous storage and piping located in the western area of the structure.
- 33. Storage of miscellaneous materials in western area.
- 34. Water-dispense mechanism tied to water pipes in the western portion of the structure.
- 35. Western portion of the structure.
- 36. Area behind large storage unit in the eastern area of the structure.
- 37. Storage unit in the eastern portion of the structure.
- 38. Subject property and structure from the intersection of railroad tracks and Washington Street, facing southwest.
- 39. 55-gallon drum and other miscellaneous debris in weed covered area to the northwest of the subject building.
- 40. Transformers of poles to the rear (north) of the structure.
- 41. Hopper to the rear (north) of the structure.
- 42. 5-gallon containers located in the western portion of the building.

Property/Area Maps

- 1. Project location
- 2. Historical Sanborn maps
- 3. Tax Map

1.0 INTRODUCTION

1.1 INTRODUCTION AND PURPOSE

Panamerican Environmental, Inc. (PEI) performed a Phase I Environmental Site Assessment (ESA), of the Randolph Foundry property and structure located at 2-8 Sheldon Street (northwestern corner of South Washington and Sheldon Streets) in the Village of Randolph, Cattaraugus County, New York. The Phase I ESA has been conducted as part of a due diligence review for a transfer of ownership.

The purpose of this ESA is to evaluate the potential for environmental impairment at the site based on current conditions, as well as present and past activities at the subject property and adjacent properties.

1.2 SCOPE

The scope of work and services for this ESA were performed in accordance with American Society for Testing and Materials (ASTM) Standards E-1527-00, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process." The scope of work performed for this evaluation includes:

- observation of current land-use within 0.5 mile of the site;
- identification of known environmental problems within 1 mile of the site;
- review of information regarding past uses of the site and adjacent properties;
- review of historical information;
- walkover reconnaissance of the property; and
- review of records at federal, state, and local agencies.

To conduct tasks related to environmental database searches, PEI identified, obtained and reviewed local records to assess whether the property has, or adjacent properties have, posed any environmental hazard in the past, or currently pose such a threat. An environmental database report is included in Appendix B and is summarized in Section 5.

Phase I property reconnaissance tasks were completed by Mr. Peter J. Gorton and Justin J. Ryszkiewicz of PEI on June 22, 2005 and are summarized in Section 1.3. As part of this process, research was also conducted at Village of Randolph, Cattaraugus County and State of New York offices. Services provided also included:

- acquisition and review of aerial photographs and historic Sanborn maps of the property and adjacent land to assess property uses;
- acquisition and review of available local records and documents regarding the site and adjacent land;

The results of these efforts are summarized throughout the report.

1.3 SITE RECONNAISSANCE

Site reconnaissance was conducted on June 22, 2005 to inspect physical features and make

general observations regarding the subject property and adjacent areas. The following tasks were completed:

- visual inspection of the property and the surrounding property was conducted to identify
 potential environmental impacts existing on the property or from adjacent areas. All
 rooms at the facility were entered;
- various property features were photographed;
- visual surface observations were made to identify any evidence of spills, such as stains or spills in facility areas or on soil or vegetative stress;
- a survey of adjacent properties was conducted.

The results of the reconnaissances are summarized below and provide a representation of property conditions at the time of the site visit (current conditions). A photographic record is included in Appendix C.

1.3.1 SUMMARY OF OBSERVATIONS

The site is unsecured and vacant. The former foundry and machine shop property is approximately179 feet by 229 feet and includes an abandoned cement block office and sheet metal manufacturing/warehouse type building. The abandoned structure, which is severely dilapidated and may be structurally unsound in some portions, contains a large garage/work area, workshop areas, former parts and machining areas, storage rooms and office type areas. Various debris, equipment, foundry sands and materials from former processes are still located at the site including some 55-gallon drums and other small containers of materials. These drums are rusty and in poor condition. Foundry sand covers much of the warehouse/manufacturing area and piles are located in some areas. Parts of the site are heavily vegetated and some vegetation is growing within the more dilapidated sections. A lager hopper is located in the rear of the structure as are two large elevated transformers.

The property is located in a moderately residential and industrial/commercial area in the Village of Randolph. The property is relatively flat, sloping from northwest to south-southeast.

The following summarizes specific observations noted during the property reconnaissance.

Sheldon Building and Building Interior

- The building area can be accessed from the eastern portion of the property through one overhead door entrance or two single door and overhead doorway along the south wall.

- The walls in the office and storage areas are concrete block.

- The floors are a combination of wood and concrete in the office area, which also has ceiling tile and flourescent light fixtures.

- An overhead garage door entrance is located near the office.

- There is an unisex restroom and a large stockroom to the north of the office (Photograph 30).

- A large storage area (in close proximity to the offices - refer to Photographs 23 to 27), contains concrete and wooden floors and a metal roof. There are various items scattered throughout the area (including 55-gallon drums, 5-gallon containers, and various other materials). There is a small concrete ramp that leads to the overhead garage door opening.

- The garage/manufacturing area (refer to Photographs 9 through 22) contains concrete and

wooden floors, along with wooden, concrete block and metal walls and ceilings. Many areas (ceilings and walls) were in disrepair and parts of the garage were open to the elements. There is miscellaneous debris scattered throughout the area including: containers of paint and paint thinners, gasoline/oils, other cleaning chemicals, machines, automobiles and various parts, building and construction debris (wood, brick, insulation, etc.). Foundry sand/slag was observed across the floor area and in large piles on the floor in the western part of the garage area. Two large furnaces or molds were located within a pit in the middle of this area.

Sheldon Property Exterior

The observations made on the exterior portion of the property are as follows:

Southern Property Area

The majority of the southern portion (refer to Photographs 6 through 8) of the property is covered by thick vegetation and grass. Three separate piles of construction and demolition debris (concrete, wood, brick, etc) were observed. Two pole mounted transformers were also observed. Observations of the ground debris were difficult to make due to the thick vegetation.

Western Portion

The western portion of the property is mostly manicured grass covered along the streets and adjacent residence.

Northern Portion

The northern area is also heavily covered in vegetation. The area immediately to the north of the structure, to the south of the fence, appears to have been used to discard metal products. Several, apparently empty 55-gallon drums, metal rails and crates were observed throughout this area. A pile of cinder blocks were also observed. The area is difficult to walk through due to the mounds of materials and the thick vegetation. Two old transformers were observed on an elevated platform in this area. A large hopper was located outside the building in this area.

Eastern Portion

The eastern portion of the property is grass and concrete covered. The rail lines are in close proximity of this area.

1.3.2 PRIMARY PROPERTY USES

The primary use of the subject property was as a foundry and machine shop from the early 1900's for about 84 years. The building and properties are currently abandoned.

1.3.3 TREATMENT, STORAGE OR DISPOSAL FACILITY (TSDF)

The property is not a TSDF and no areas were observed.

Panamerican Environmental, Inc.

1.3.4 HAZARDOUS WASTE/SUBSTANCES

A review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. The previous site owner disposed of foundry sand on an adjacent lot (see 1.3.9 below).

There were a number of containers observed on the property of unknown contents. Additionally, a large amount of foundry sand which is potentially hazardous for metals and may contain phenols was observed throughout the general warehouse area. It is unknown if past use of the property included impacts to surface/subsurface soil.

1.3.5 ABOVE GROUND/UNDER GROUND CHEMICAL/PETROLEUM STORAGE TANKS (AST/UST)

There is no visible evidence that USTs ever existed on this property. A spill site (Randy's Garage property) was identified in the radius search and is located within close proximity of the subject property (refer to appendix B).

1.3.6 PCB CONTAINING EQUIPMENT

Fluorescent light fixtures were located throughout the structure. Based on the age of these fixtures, it is possible that they contain PCB contaminated fluid within the ballasts. Two sets of pole-mounted transformers were also observed on the exterior portion of the building. It is unknown if the transformers were located on the subject property or the adjacent eastern property and it is also unknown if the transformers are PCB containing.

1.3.7 ASBESTOS CONTAINING MATERIAL/LEAD-BASED PAINT

Potential asbestos containing materials (ACM) were not observed during the site visit. However, due to the age of the building, ACM and lead-based paint is possibly associated with some of the building materials and interior and exterior surfaces of the structure.

1.3.8 STAINS, SPILLS, STRESSED VEGETATION

No major stains, spills, or stressed vegetation were observed outside the facility, however, the floor area was mostly covered with debris and foundry sand. There were a few areas of small staining within the building including oily stained concrete floors - the various areas of staining observed included a portion of the concrete and wooden floors in the garage and storage portions of the building.

1.3.9 LANDFILLS/DUMPING ACTIVITIES

Portions of the property contain debris piles. C&D material including concrete pieces, brick, concrete block, soil fill and wood is located on the eastern and southern exterior portions of the property. As described, the material appears to rubble from a former structure. Due to their size, configuration and vegetation in the area, visual observations could not be made of the contents of

the entire piles and therefore other materials may exist. As mentioned, a review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. A review of NYSDEC Region 9 records indicates that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. And that approximately 1,500 pounds a day of foundry sand was transported per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling was started in 1976 to about 1981. The company initiated a permit application (permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property.

1.3.10 PITS, SUMPS, WELLS

No pits, wells, or sumps were observed on the property and there is no record of wells associated with this property.

1.3.11 PONDS AND LAGOONS

No ponds or lagoons were observed on the property.

1.3.12 COASTAL AREAS

The property does not fall under any coastal zone erosional management.

1.3.13 POTABLE WATER SUPPLY

The property has access to public water.

1.3.14 SEWAGE DISPOSAL

Assessor records indicate private sewers. There were no records found regarding a septic system on the property.

1.3.15 ROADS AND PARKING LOTS

The property does not contain a formal parking area and is immediately adjacent to Sheldon and South Washington Streets.

1.3.16 ODORS

There were no abnormal odors observed at the property during the site reconnaissance.

Panamerican Environmental, Inc.

5

1.3.17 HEATING AND COOLING SYSTEM

The is vacant and abandoned.

1.3.18 OTHER NOTEWORTHY OBSERVATIONS/ISSUES

No other noteworthy observations or issues other than those described above were observed.

1.4 FORMER ON-SITE COMMERCIAL USES

The exact date that the existing structure was built is unknown, however, historical maps indicate that a foundry and machine shop (F. H. Pike Foundry and Machine Shop) was located on the property as early as 1902. By 1929, historic maps indicate that the property was identified as the Randolph Foundry and Machine Shop. As late as 1897 however, a dairy was located on the property. Individuals with knowledge of the history of the Town indicate the Randolph Foundry was at one time owned by Aeolian (verified also by ownership records) and made piano plates out of recycled metal. The foundry was later sold and went out-of-business around 1986. This suggests that the property was used in some capacity as a foundry and machine shop since at least 1902 or at least 84 years.

Foundries (or metal casting operations) make parts from molten metal according to end user specifications. Since the historic maps indicate that the facility was also a machine shop, it implies that the parts (castings) were used to produce larger products such as machinery, motor vehicles, appliances, plumbing fixtures, etc. In this case, at least for a time, parts for pianos. In general, foundry and machine shops are typically somewhat "dirty" operations and involved with the manufacturing, prefabrication, and repair of articles of steel, iron, and other metals. Environmental contamination associated with these facilities include elevated levels of lead and other metals in near and subsurface soils and wastes associated with slag/foundry sands. Other contaminants, including solvents and petroleum products are typically associated with drummed materials.

2.0 ASSET INFORMATION AND DESCRIPTION

Pertinent asset information includes:

Property Name:	Former Randolph Foundry (on northwestern corner of Washington and Sheldon Streets)
Property Address:	2 - 8 Sheldon Street SBL# 70.071-3-16 Town of Randolph, New York 14772
Property Owner:	Cattaraugus County

Property Contact: Mr. Joseph Keller The legal description for the property is: All that tract or parcel of land, situate in the Village of Randolph, County of Cattaraugus, State of New York, distinguished as part of lot No. Twenty-three (23), Township Two (2), and Range Nine (9). Refer to Appendix F for additional information on property description. In addition, refer to Section 4.0 for a description of the known history of the

property.

3.0 SITE DESCRIPTION

3.1 LOCATION AND CURRENT USE

With formal addresses of 2 - 8 Sheldon Street (historic Sanborn maps indicate the properties addresses may have changed) in the Village of Randolph, Cattaraugus County, New York, the property is currently vacant. The property is located on the northwestern corner of the intersection of Washington and Sheldon Streets. Adjacent to the property to the east is railroad lines for the Southern Tier Railway Authority.

3.2 GENERAL PROPERTY AND AREA FEATURES

The property is located in the Village of Randolph within two miles of the center of the village area. The property is generally flat and generally sloping from northeast to southwest and is located within a mixed commercial/residential/business area of the Village of Randolph.

3.3 ADJACENT PROPERTIES

The following is a brief description of properties immediately adjacent to the subject sites starting with the property north and moving in a clockwise direction.

- North: To the northeast of the subject property are rail lines (unknown if active) for the Southern Tier Rail Service. Further to the north-northwest are single and multi-family residential homes.
- East: East of the property is the rail road and Washington Street. Further to the east are open fields.
- South: South of the subject properties is Sheldon Street. Further to the south are single and multi-family residential structures and commercial structures .
- West: West of the property are residential structures along Sheldon Street and Green Street.

3.4 PROPERTY SURFACE FEATURES AND DRAINAGE

Property surface features and drainage were determined through a combination of site reconnaissance and a review of both aerial photographs and topographic maps. Property drainage is directed laterally to low areas and storm drains and to Town of Randolph storm sewers along adjacent streets. While the irregularly shaped property is relatively flat, the immediate area in the rear of the building appears to be higher then areas to the east, south, and west and therefore storm water in the general area is most likely directed towards the lower lying areas on the subject property.

3.5 UTILITIES

The subject property is vacant or abandoned, but it has access to all major public and private utilities, including water, electric, gas, and telephone.

3.6 SITE GEOLOGY/HYDROGEOLOGY

The United States Department of Agriculture (USDA) Soil Conservation Service *Soil Survey of Cattaraugus County, New York* (1940) was reviewed to determine soil types. The map of this area identified the predominant soil type pertinent to the property to be Rushford Channery Slit Loam, 8 to 15 percent slopes (58c). Soils classified as this type are a very deep, moderately well drained, low-lime, channery medium-textured soil formed in glacial till, 20 to 40 inches thick, overlying silty lake sediments. There is a fragipan at a depth of 15 to 24 inches. The available water capacity is moderate. Permeability is moderate above the fragipan, slow through extremely slow in the fragipan, and moderately slow in the substratum. This unit is moderately well suited to cultivate crops. Seasonal wetness may delay tillage and harvesting activities in some years. Recommended conservation practices should be followed to reduce erosion and maintain the productivity of this soil.

Due to the commercial use of this property, however, this property could also be classified to be Urban land (Ud). Urban land, 0 to 3 percent slopes, is a nearly level miscellaneous area in which 80 percent or more of the soil is covered by asphalt, concrete, buildings, or other impervious structures including parking lots, shopping and business centers, and industrial parks.

A copy of the soil survey map is presented in Appendix D.

4.0 SITE HISTORY

4.1 HISTORICAL SOURCES REVIEWED

A number of sources were used to develop a historical use profile for the property as discussed in this report, and included:

- Assessment records;
- Historical maps;
- Historical records maintained in town, county and state files; and
- Aerial photographs.

4.2 SITE AND AREA HISTORICAL CHAIN OF USE

4.2.1 Chain of Title Information

Title and tax assessor information located at the Town and County offices was reviewed and the most recent title information is summarized below (Refer to Appendix E - Property Title and Assessment Information).

2 - 8 Sheldon Street				
<u>Liber</u>	<u>Page</u>	Sale Date	From	<u>To</u>
2743	5007	03-09-2005	Donald Cresanti	Cattaraugus County
875	215	10-29-1987	Aeolian Pianos, Inc.	Donald Cresanti
504	524	09-03-1952	Randolph Foundry and Machine	Metallic Ladder Manufacturing Corp.

4.2.2 Chain of Use Records

No historic street directories were found which describe recent historical uses of the subject property and nearby properties.

4.2.3 Aerial Photographs

Aerial photographs for the following years were obtained from the Cattaraugus County Soil Conservation Service offices in Springville, New York or as noted below:

1956 Aerial Photograph
1966 Aerial Photograph
1980 Aerial Photograph
1995 Aerial Photograph
2002 Aerial Photograph

A review of these photographs indicates that the property and surrounding area was primarily used as commercial/retail with residential on adjacent streets. Electronically-scanned copies of these photographs are located in Appendix A.

4.2.4 Sanborn Maps and Other Historic Maps

Historical Sanborn maps located for this property include those for the years 1885, 1891, 1897, 1902, 1907, 1913, 1929, and 1937. Copies of these maps are provided in Appendix D. The Sanborn map collection consists of a uniform series of large-scale maps, dating from 1867 (varies on location) to the present (around 1986 again based on location) and depicting the commercial, industrial, and residential sections of some twelve thousand cities and towns in the United States, Canada, and Mexico. The maps were designed to assist fire insurance agents in determining the degree of hazard associated with a particular property and therefore show the size, shape, and construction of dwellings, commercial buildings, and factories as well as fire walls, locations of windows and doors, sprinkler systems, and types of roofs. The maps also indicate widths and names of streets, property boundaries, building use, and house and block numbers. They show the locations of water mains, giving their dimensions, and of fire alarm boxes and hydrants and also show location of tanks.

A brief summary of pertinent information concerning the property based on this review is as follows:

1885 Map

This map shows that a dairy was located on the property. The rail road (New York/Pennsylvania/Ohio Railroad) existed along the northern and eastern border. Additionally

lumber storage is shown on th property along the rail road tracks. Washington Street was known as Depot Street was adjacent to the northeast. The Randolph Furniture Company is located on the adjacent corner (southeast) of Sheldon and Depot Street.

1891 Map

The 1891 map shows that the same structures present in the 1885 Map however the lumber storage along the railroad tracks is a much larger area. The furniture company located on the adjacent corner (southeast) of Sheldon and Depot Street is called Pearl Furniture Company.

1897 Map

The lumber storage is no longer shown. The furniture company located on the adjacent corner (southeast) of Sheldon and Depot Street is changed to the Elko Paint Company.

1902 Map

The 1902 map shows the F.H. Pike Foundry and Machine Shop located on the northwestern corner of Sheldon and Depot Street. This map shows a Foundry building and the small building previously described building on the subject property. The lumber storage is no longer present on the property.

1907 Map

This map shows the F.H. Pike Foundry and Machine Shop facility with multiple combined structures occupying the central portion of the property. The machine shop appears larger and there are a approximately two sheds to the rear (northwest) of the main structure. A boarding house is located closer to the corner and appears to be the original dairy building.

1913 Map

There is little change from the 1907 map.

1929 Map

This map indicates that the F.H. Pike building is now called the Randolph Foundry and Machine Shop. The main structure has grown in size and the shed in the rear is considered a coke shed. Depot Street is now known as South Washington Street.

1937 Map

This map is unchanged from the 1929 Sanborn Map.

4.3 PREVIOUS ENVIRONMENTAL STUDIES/HISTORICAL DATA

No records of previous environmental studies were found on this property.

5.0 REGULATORY/AGENCY RECORDS REVIEW

A review of readily available government agency records was conducted by PEI using a government records search firm, EDR. EDR provides an ASTM Detailed Radius Report based on information obtained from publicly available data sources and other secondary sources. A table summarizing the EDR database search results is presented on page 4 of the EDR report (refer to Appendix B). Additional details on these sites are also contained in the EDR radius report including

information about sites in the immediate area as well as their relative location to the subject property.

A review of government records indicates that the subject property (Aeolin Corporation - 2 Sheldon Street) was listed as a Solid Waste Facility/Landfill (SWF/LF) site. SWF/LF sites typically contain an inventory of solid waste disposal and inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for disposal. A review of NYSDEC Region 9 records indicates that this property was designation as a SWF/LF because it buried foundry sand on the lot across South Washington Street. It appears that the material was placed on a two acre parcel owned by the Aeolin Corp. and that approximately 1,500 pounds of foundry sand was disposed per day. The foundry sand was generated from the sandblasting process and grinding operation. The land filling occurred from 1976 to about 1981. The company initiated a permit application (permit application number 05S14) for the landfill operation in 1979 but never completed the application and instead reportedly began sending material to the Cattaraugus County Landfill. The NYSDEC approved (Mr. Robert Mitrey) the offsite disposal at the Cattaraugus Landfill in March 1981 based on an analysis of the sand. It appears that and unknown quantity of material may still be located on the adjacent property.

A total of eight (8) additional database records were found for the adjacent and surrounding properties within the ASTM government records search radius. These include seven Spills Information Database (LTANKS) sites, and one registered Underground Storage Tank facility.

Additionally, a total of thirty-four (34) "orphan sites" (sites with inadequate or poor database address information), were identified in the EDR report. None of these properties appear to be immediately adjacent to the subject property.

A Freedom of Information Law (FOIL) request was submitted to the NYSDEC Region 9 office requesting information concerning the subject and adjacent properties. This information is contained in Appendix F.

6.0 OTHER RECORDS REVIEWED/INTERVIEWS CONDUCTED

In addition to the federal and state databases searched, PEI reviewed a number of other regional information sources.

6.1 TOWN OF RANDOLPH OFFICES

PEI visited or contacted a number of Town of Randolph offices on June 22, 2005. The offices contacted and information obtained included the following:

Town of Randolph Assessor Office

- Real property and assessment information.

Town of Randolph Building and Permitting Department

- Zoning maps, building permits including UST installation and removal (refer to Appendix I)

Panamerican Environmental, Inc.

Town of Randolph Clerks Office

- Building and general files for this property including UST information.

Information obtained from these sources is contained throughout the report.

6.2 COUNTY OFFICES

Aerial photographs, floodplain information, and wetland maps were obtained from the Cattaraugus County Soil Conservation Service offices in Springville, New York. PEI also contacted the Cattaraugus County Real Property Tax Office and Cattaraugus County Court Building in Little Valley for more information on the subject property.

6.3 NYSDEC FILES

NYSDEC files for the subject property were reviewed by PEI on July 13, 2005 (refer to 5.0 above).

6.4 INTERVIEWS

Information obtained during the interview and discussions with town officials is summarized throughout this report. Additionally, PEI contacted local residents familiar with the history of the area including Dr. Dixon G. Stevens and Mr. Robert Beach. They indicated that a Mr. Abbey was a manager of the foundry and that it was owned by the Aeolian Company which made piano plates out if recycled metal. They indicated that the property was sold to a Peter Perez who had connections to Steinway Piano - a fact not born out by a review of the assessor records. They indicated that the foundry went bankrupt about 1986-1987. Mr. Beach indicated that the foundry was owned by Mr. Francis Dexter prior to the Aeolian Corp. Ownership.

PEI also reviewed the files at NYSDEC noted above concerning the landfill designation.

7.0 REVIEW OF SPECIAL RESOURCES

The property does not appear to have any special resource issues on or adjacent to it.

7.1 HISTORIC RESOURCES

The structure does not appear to possess particularly notable architectural features, however, its history may have some significance locally.

7.2 FARMLANDS

The subject property is not related to any agricultural activity. The property and surrounding area has been commercial/residential since the late 1800's.

7.3 RECREATIONAL AREAS

There are no recreational areas associated with this property.

7.4 LAND USE

Land uses in the vicinity of the subject property includes residential, especially along Sheldon, Green and Washington Streets and mixed commercial/retail in the surrounding areas.

7.5 WETLANDS AND FLOODPLAINS

PEI reviewed both the State and Federal Freshwater Wetland Maps contained at the Cattaraugus County Soil Conservation Service offices in Springville, New York. There were no federal or state areas of wetlands identified on the subject property. A review of the Flood Insurance Rate Map of Cattaraugus County indicates that the subject property is located in Zone X - areas determined outside the 500 year flood plain.

8.0 ENVIRONMENTAL ASSESSMENT SUMMARY, CONCLUSIONS AND RECOMMENDATIONS

Information identified by PEI suggests that some issues of environmental concern may exist at the subject property. Based on the information reviewed for this Phase I ESA, PEI cannot verify with complete certainty that near-surface or subsurface contamination or other environmental impairment does not exist at this property, especially with regard to possible foundry sand/slag and the approximately 84 years of property use as a foundry and machine shop. Based on the information obtained regarding this property, it is unknown if additional foundry sand exists outside or immediately adjacent to the structure or if remnant subsurface contamination exists. It is also unknown, based on the site visit and records review, whether past spills have negatively impacted the subsurface environment. Records indicate that foundry sand was buried on an adjacent property.

Portions of the property contain debris piles. C&D material including brick, concrete block, and wood is located on the southeastern border of the property. As described, the material appears to be rubble from a former structure. Due to their size and configuration, visual observations could not be made of the contents of the entire piles and therefore other materials may exist.

During the site visit, PEI observed various containers (55-gallon drums, 5-gallon containers, paint cans, etc.) of unknown contents. Some of these containers were filled with materials while others were empty.

Based on the information compiled during the ESA, **PEI believes that the potential for** contamination exists at this property primarily due to the former operations. This assessment has identified potential recognized environmental conditions in connection with the subject property including the following:

- its history as a SWF/LF, and land filling of an adjacent property.

- potential contamination associated with foundry sands and slag piles as well as other materials and wastes inside the structure. Contaminants typically associated with foundry and machine shop operations include elevated levels of lead, antimony, arsenic, copper and other metals; It is unknown if this material exists outside the structure on the property.

- various 55-gallon drums and other containers which are in poor condition and contain unknown contents; and

- potential PCBs associated with the elevated transformers.

The property is in very poor condition, may be structurally un-sound in portions and has wastes and materials strewn throughout the interior. It is currently not secured and open to access.

9.0 DATA NEEDS

The purpose of any future initial site assessment should be to verify that materials and debris on the property is restricted to C&D debris and to further determine the likelihood of contamination at the property especially associated with the foundry sand/slag and containers. This information will allow for the determination of hazards associated with the property.

Follow-up assessment is therefore recommended. This may include some or all of the following:

- Determine any association with the adjacent property that was used to landfill foundry sand
- Removal/inventory containers and materials/chemicals
- examine and or sample transformers for PCBs
- sampling of sands and slag within the structure
- Removal/examination of the debris piles
- Limited surface and subsurface investigation to examine the extent/type of rubble and to sample surface and subsurface soils.
- Perform an asbestos survey of the potential materials identified
- Perform a site boundary and topographic survey to identify existing conditions and to create a base map for field activities
- analyze specific media including soil
- identify the contaminants of concern, if any
- identify specific environmental media, potential pathways and affected receptors, if any
- identify any impacts to a development concept plan

- identify extent of remediation necessary, if any, to meet the property specific development goals of redevelopment.

Based on the findings of the Phase I ESA, the following potential recommended Phase II tasks have been identified:

1) Development of a Phase II work plan which describes the activities, QA/QC, and health and safety

2) Perform a drum/container inventory and sampling and analysis as necessary

3) perform a detailed inventory of equipment/debris within the facility to determine the potential for hazardous materials.

4) Perform a sampling program of foundry sands/slag within the structure

5) Perform a surface and subsurface soil assessment including a possible sampling and analysis

program. This may involve the use of either borings or trenches. PEI suggests that the use of a backhoe is most appropriate for two purposes: 1) examine areas underneath debris 2) complete trenches in grass areas to determine the nature of the fill and to examine subsurface conditions. The reason for recommending trenching where possible, is that trenches will afford the following:

- The ability to examine a wider subsurface area and waste/fill profile
- The ability to gain access to areas inaccessible to drill rigs/geoprobes.

If soil contamination is indicated, a limited sampling program may be conducted. This assessment should be limited in scope to determine if the possibility of contamination exists (examine "hot spots"). If based on this assessment, contamination is identified, a more focused investigation can be planned.

Materials in each debris pile and soil from each slit-trench (approx. 1 foot wide by 4-8 feet long) should be visually described and screened using an organic vapor detector (i.e., PID). Stratification of material in the trenches and observations of soil staining should be noted on the trench logs. Soil samples may be collected from each test trench from the intervals which indicate contamination either through visual, smell, or PID readings. The purpose of this initial limited assessment is to verify that the material observed is limited to C&D and to determine if foundry sands/slag exist outside the facility. The purpose is not to conduct an investigation directed at determination of nature and extent of contamination which would require significantly more sampling and analysis. Based on the findings of this assessment, more detailed sampling may be required. If it is determined that the property may contain other then C&D debris, a more detailed focused study would be performed.

PEI does not recommend additional sampling (i.e., groundwater, surface water, soil) until the results of the initial assessment program have been assessed. If soil contamination exceeding compliance levels is detected, or, if other information indicates potential for groundwater or surface water/soil contamination, additional sampling will be recommended.

The number and location of samples, if necessary, will depend on field conditions and observations and may change based on discussions with the Village. It is suggested that if samples are collected, they be analyzed for TAL metals, VOCs, SVOCs, and PCBs. The results would be compared to current NYSDEC soil policy (TAGM 4046 amended) and to the full hazardous waste recommended clean-up values. Assessment of subsurface conditions would be based on visual/olfactory observations and volatile organic screening and the results of the samples submitted for analysis, if deemed necessary based on field observations.

The actual program will be developed with the County and will be subject to accessibility and the location of underground utility lines.

10.0 WARRANTS AND LIMITATIONS

This report is based on information from field reconnaissance and visual observations of the property and vicinity, and interpretation of the available information and documentation reviewed, as described within this report. This report is intended exclusively for the purpose outlined herein at the site location and project indicated. The property and this site assessment is limited to the

footprint of the lot.

This report is intended for the sole use of the County of Cattaraugus Office of the Treasurer. The scope of services performed in this assessment may not be appropriate to satisfy the needs of other users and any use or re-use of this document or the findings, conclusions, or recommendations presented, is at the sole risk of the user.

The conclusions set forth in this report are based upon, and limited by, the government data and other information available to PEI. PEI is not able, within the scope of the project, to verify the accuracy of all data supplied by government entities and third parties. Therefore, PEI is not responsible for any conclusion contained in this report that is based on, in whole or in part, upon inaccurate data obtained from third parties.

It should be noted that all surface environmental assessments are inherently limited in the sense that conclusions are drawn and recommendations developed from information obtained from limited research and site evaluation at a specific time. The passage of time may result in a change in environmental circumstances at this site and surrounding properties, or hazardous materials beneath the surface may be present but undetectable during this Phase I assessment.

PEI does not provide professional legal or title insurance services and makes no guarantee, explicit or implied, that the listing which was reviewed represented a comprehensive delineation of past site ownership or tenancy. The work performed in conjunction with this assessment and the data developed are intended as a description of available information at the dates and locations given.

Opinions and recommendations presented herein apply to the site conditions existing at the time of the assessment and those reasonably foreseeable. They cannot necessarily apply to site changes of which PEI is not aware and has not had the opportunity to evaluate.