January 21, 2011

REVISED REMEDIAL INVESTIGATION WORK PLAN

900 Old Country Road
Garden City, Town of Hempstead,
Nassau County, New York

Prepared for

EQUITY ONE (NORTHEAST PORTFOLIO) INC.
650 Fifth Avenue, 24th Floor
New York, New York 10019

ROUX ASSOCIATES, INC.

Environmental Consulting & Management

ROUX

209 Shafter Street, Islandia, New York 11749 ♦ 631-232-2600

TABLE OF CONTENTS

1.0 INTRODUCTION 1
1.1 Brownfields Cleanup Program Application and Environmental Work Plans 1
1.2 RI Work Plan Document Organization 1
1.3 Project Team Contact Information 1
1.4 Certification 2

2.0 BACKGROUND 3
2.1 Site Description and Setting 3
2.1.1 Property Operations 4
2.1.2 Utilities 5
2.1.3 Topography/Hydrogeology 5
2.1.4 Wetland Areas and Surface Water Bodies 6
2.1.5 Soils 6
2.1.6 Underlying Formation 6
2.1.7 Groundwater 6
2.1.8 Neighboring Properties 7
2.2 Site History 8
2.2.1 City Directories 8
2.2.2 Aerial Photographs 8
2.2.3 Fire Insurance Maps 10
2.3 Results of Previous Environmental Investigations 11
2.3.1 Bulk Storage Tanks 12
2.3.2 Aboveground Storage Tank Closure 12
2.3.3 Underground Storage Tank Closure and Floor Drain System Closures 13
2.3.4 Hazardous Waste Storage Areas 15
2.3.5 Groundwater 16
2.3.6 Soil 17
2.3.7 Summary of Previous Environmental Sampling 20
2.4 Data Usability 20

3.0 RI WORK PLAN OBJECTIVES, SCOPE AND RATIONALE 22
3.1 Objectives and Relationship to RAWP 22
3.2 RI Scope 23
3.2.1 Site Reconnaissance 23
3.2.2 Gore Sorber Sampling 24
3.2.3 Soil Characterization at Potential Impact Areas 25
3.2.4 Radiological Screening Survey 26
3.2.5 Soil Vapor Sampling 27
3.2.6 Groundwater Investigation 28
3.2.7 Qualitative Exposure Assessment 29

4.0 QUALITY ASSURANCE/ QUALITY CONTROL (QA/QC) PROTOCOLS 30

5.0 HEALTH AND SAFETY 31

6.0 REPORTING AND SCHEDULE 32

TABLE OF CONTENTS

(Continued)

TABLES

1. Summary of Historical Groundwater Sample Results, Former Avis Headquarters 900 Old Country Road, Garden City, New York
2. Summary of Historical Soil Sample Results, Former Avis Headquarters 900 Old Country Road, Garden City, New York
3. Proposed Sampling Locations, Former Avis Headquarters 900 Old Country Road, Garden City, New York

FIGURES

1. Site Location Map
2. Land Use
3. Proposed Sampling Locations (Second Mobilization)

APPENDICES

A. EDR GeoCheck ® Report
B. Historic Aerial Photographs
C. Fire Insurance Maps
D. Field Sampling Plan
E. Quality Assurance Project Plan
F. Site Health and Safety Plan

PLATES

1. Historical Groundwater and Soil Vapor Results
2. Historical Soil Sample Results
3. November 2010 Drywell/Leaching Pool Sample Results

1.0 INTRODUCTION

Roux Associates, Inc. (Roux Associates), on behalf of Equity One (Northeast Portfolio) Inc.(Applicant), has prepared this Remedial Investigation (RI) Work Plan for a site (Site) occupying 900 Old Country Road, Garden City, New York (Figure 1).

1.1 Brownfields Cleanup Program Application and Environmental Work Plans

Due to the presence of contaminated groundwater, soil, and soil vapor at the Site, the Applicant plans to remediate the Site under the New York State Brownfield Cleanup Program (BCP). The RI Work Plan is being submitted as part of the BCP application. The RI has been developed in accordance with the draft BCP Guide (May 2004) and the DER-10 Technical Guidance for Site Investigation and Remediation (May 2010) issued by the New York State Department of Environmental Conservation (NYSDEC). The purpose of the RI is to determine the nature and extent of contamination at the Site, characterize environmental media at the Site, qualitatively assess the potential exposure of receptors to Site contaminants, and develop any other additional data necessary to support the development of a Remedial Action Work Plan (RAWP).

The site was accepted to the BCP, and the Brownfield Cleanup Agreement (BCA) was signed on November 10, 2010. Site Number C130206 has been assigned.

1.2 RI Work Plan Document Organization

This RI Work Plan contains a background section (Section 2) describing the Site, its history, and results of previous environmental investigations; a section defining the objectives and scope of the RI (Section 3); and Sections 4 and 5 that describe various project operations plans (e.g., Quality Assurance/Quality Control, Health and Safety). Reporting requirements and the project schedule are discussed in Section 6. Additionally, tables are provided that summarize all previously collected environmental quality data. Finally, maps are also provided to illustrate site conditions, previous environmental data, and locations of proposed sampling efforts.

1.3 Project Team Contact Information

Roux Associates' Project Manager and Principal-In-Charge for this Site will be Craig Werle, Principal Hydrogeologist. Mr. Werle, who is based in Roux Associates' Islandia, New York headquarters office and can be reached at (631) 232-2600, will be responsible for day-to-day

management of the project, including preparation of work plans, and scoping and directing field activities. Wendy Monterosso, Project Hydrogeologist will act as Field Manager for the duration of the project, and will be responsible for implementing and directing field activities onsite.

The name and contact information for the Applicant are provided as follows.

Mr. Michael Berfield
Equity One (Northeast Portfolio) Inc.
650 5th Avenue, 24th Floor
New York, New York 10019

At this time, the following subcontractors have been selected for this project:

Drilling:	Aquifer Drilling & Testing, New Hyde Park, New York
Analytical:	TestAmerica Laboratories, Shelton, Connecticut
Radiological surveys:	Environmental Dimensions, inc., Oak Ridge, Tennessee
GORE Survey:	W. L. Gore & Associates, Inc., Elkton, Maryland
Geophysical surveys:	NAEVA Geophysics, Inc., Congers, New York

At this time, waste disposal, and other subcontracted services have not yet been selected. This information will be provided to NYSDEC immediately following contractor selection.

1.4 Certification

I, Craig A. Werle, P.G., certify that I am currently a Qualified Environmental Professional as defined in 6 NYCRR Part 375 and that this Remedial Investigation Work Plan was prepared in accordance with all applicable statutes and regulations and in substantial conformance with the DER Technical Guidance for Site Investigation and Remediation (DER-10).



January 21, 2011

2.0 BACKGROUND

This section provides pertinent background information, including a description of the Site and its setting, the known history of the Site, and the results of preliminary environmental investigation work conducted at the Site.

2.1 Site Description and Setting

Property Location	
Property Name:	Office, manufacturing and storage buildings
Property Address:	900 Old Country Road
Property Town, County, State:	Village of Garden City, Town of Hempstead Nassau County, New York 11501
Property Tax Identification:	Section 44, Block 67, Lots 26, 27, and 28
Property Topographic Quadrangle:	Freeport, New York
Nearest Intersection:	Old Country Road and East Gate Boulevard
Area Description:	Commercial and Industrial, with some Residential to the north

A Site location map is included as Figure 1.

Property Information	
Property Acreage:	21.858 acres
Property Shape:	Rectangular
Property Use:	One operating furniture store, one former office building, one former office/garage, one former manufacturing building and former storage building
Number of Buildings:	Five
Number of Stories:	One, One and one-half and Three
Date of Construction:	Main Avis and Cendant Buildings prior to 1953, remaining buildings 1953 to 1966
Building Square Footage:	Approximately 499,000 square feet
Basement/Slab-on-Grade:	Slab-on-grade

Property Information	
Number of Units:	
Ceiling Finishes:	Acoustic ceiling tiles and exposed structural elements
Floor Finishes:	Carpet, bare concrete, and ceramic and vinyl tiles
Wall Finishes:	Painted drywall and exposed structural elements
HVAC:	None in Avis Office, Cendant, Manufacturing and Storage buildings; Thomasville Home Furnishings - Natural Gas
Renovation Date:	
Renovation Description:	Demolition of all structures is planned
Vehicular Access:	Via Old Country Road
Other Improvements:	Paved Parking Area
Property Coverage:	Footprints of the subject buildings, associated parking areas, minimal lawn areas and landscaping

An Environmental Data Resources, Inc. (EDR) GeoCheck® Report is provided in Appendix A, which provides information regarding elevation, groundwater flow, Federal USGS well information, Federal FRDS Public Water Supply system information, and state database well information.

2.1.1 Property Operations

The site property is currently mostly unoccupied, with the exception of the following tenants:

Tenant	Operations
Thomasville Home Furnishings	Warehouse/retail sales of furniture

No industrial or manufacturing operations were observed at the Site at the time of the preliminary visit completed in March of 2010.

2.1.2 Utilities

The following companies and municipalities currently provide utility services to the Site:

Utility	Provider
Electricity:	Long Island Power Authority (LIPA)
Natural Gas:	Keyspan
Sanitary Sewerage:	Nassau County Department of Public Works
Potable Water:	Town of Hempstead, Roosevelt field Water District
Solid Waste Removal:	Thomasville Home Furnishings utilizes private waste removal

There is a manifolded series of storm drains on the western, eastern, and southern sides of the property that collected stormwater runoff from the paved parking lots surrounding the buildings. Previous geophysical investigations showed that these are connected via storm drain piping and are described as discharging to Nassau County Recharge Basin. Stormwater in the northern parking areas of the property is handled by several individual dry wells.

Utility and Site infrastructure and utilities have not influenced contaminant migration at the Site because these features are located approximately 15 feet above the water table that is found approximately 21 to 23 feet below grade. Based on the high permeability of unsaturated zone soils, utility trench backfill would not represent a preferential pathway for contaminant migration.

2.1.3 Topography/Hydrogeology

Review of the United States Geological Survey (USGS) 7.5-minute series topographic quadrangle map of Freeport, New York reveals that the elevation of the Site is approximately 85 feet above mean sea level. The topography of the Site is essentially flat with only a slight grade toward the southwest. According to water level data for Long Island (USGS 1989), the water table at the Site is in the Upper Glacial aquifer and the regional depth to groundwater ranges from 22 to 24 feet below land surface within ½ mile of the Site. The regional groundwater flow direction is South-southwest. Local groundwater is expected to mirror local topography and migrate to the South-southwest.

2.1.4 Wetland Areas and Surface Water Bodies

There are no identified wetlands on or adjacent to the Site. There are two mapped wetlands within ½ mile of the Site. Both wetlands are indentified as excavated stormwater recharge basins and are shown on Figure 2. These areas will not be impacted by the proposed development plans.

There are no surface water bodies on or adjacent to the site, or within ½ mile of the site, with the exception of the above-mentioned stormwater recharge basins.

2.1.5 Soils

Based on a review of the United States Department of Agriculture, Soil Conservation Service's *Soil Survey of Nassau County, New York* (February 1987), soils in the area of the Site are classified as Urban land (Ug).

Urban land consists of areas where at least 80-85 percent of the surface is covered by asphalt, concrete, or other impervious building materials.

2.1.6 Underlying Formation

According to the *Surficial Geologic Map of New York* (1989), fluvial sand and gravel underlie the Site. Fluvial sand and gravel consists of deposits of sand and gravel with occasional laterally continuous lenses of silt. The sands and gravel were deposited by glacial activity.

2.1.7 Groundwater

Based on a review of the Hydrologic Framework of Long Island, New York (1989), the principal aquifer in the vicinity of the Site is the Magothy Aquifer. The Magothy Aquifer is known as an unconsolidated coastal plain aquifer and is one of the major aquifers of Long Island, New York.

Based on the review of the above referenced document and the USGS topographic quadrangle map of Freeport, New York, it is expected that the depth to shallow groundwater is approximately 23 feet below ground surface (bgs). Previous investigations have reported groundwater depths at the site ranging from 20 to 23 feet bgs across the site. Local groundwater is expected to flow toward the south west based on water level information collected during previous investigations.

Although there are multiple United States Geological Survey (USGS) monitoring wells within ½ mile of the site, there are no public water supply wells within ½ mile downgradient of the Site as reported in the EDR Report included in Appendix A.

2.1.8 Neighboring Properties

Review of neighboring properties from the Site and from public thoroughfares, and research of available information regarding the neighboring properties, were performed to identify evidence of environmental concern that could adversely impact the Site. The Site is located in a commercial and industrial area of Garden City, New York.

Direction	Operations
North	Commercial/Residential
South	Industrial/Commercial
East	Commercial
West	Commercial

The property is bordered to the north by Old Country Road. Farther north (across Old Country Road) are retail operations including a cell phone store, retail strip store, restaurant, and diner, and commercial operations including a gasoline filling station, catering hall, and hotel. North of the retail and commercial operations are residential houses. The residential properties are located approximately 300 feet north of the Site and continue to the north.

The property is bordered to the east by Zeckendorf Boulevard. Further east (across Zeckendorf Boulevard) are retail operations such as an office supply store, electronics store, and a retail shopping center. The property is bordered to the west by E. Gate Boulevard. Further west (across E. Gate Boulevard) are retail operations including a restaurant, furniture store, an infant clothing store, the Meadowbrook Parkway, a shopping mall, and commercial operations such as a beverage warehouse, hotel, and medical office buildings. The property is adjoined to the south by a commercial operation (Verizon Operations Center), and an industrial operation known as AAR Components, Inc. (AAR). AAR is involved in the refurbishing and resale of aircraft instruments and equipment. Further south and southwest are retail operations that include

department stores, restaurants, a hotel, a movie theater, the Meadowbrook Parkway, and to the southwest is an adult residential community.

There is no agricultural land use within ½ mile of the site. The nearest park, Carle Place Park, is located approximately 2000 feet north of the Site. The adjacent and nearby property usage is identified in Figure 2.

2.2 Site History

Roux Associates evaluated several information sources to determine historic uses of the property.

2.2.1 City Directories

City Directory for the site is to be determined.

2.2.2 Aerial Photographs

Roux Associates reviewed aerial photographs of the Site and surrounding area for the years 1953, 1957, 1966, 1974, 1976, 1980, 1985, and 1994 from EDR of Milford, Connecticut. The aerial photographs were reviewed for evidence of environmental concerns on or near the Site. The following is a discussion of the aerial photograph review:

1953: Review of the 1953 aerial photograph revealed that the Site was improved with two large connected rectangular shaped buildings occupying the northeastern portion of the site. This building is similar in orientation to the large subject former Avis Office and Cendant buildings currently on the property. The remainder of the Site consisted of mostly of paved parking areas and a small lawn area to the north of the buildings.

The adjacent properties to the north were improved with several small structures, including residential housing. The adjacent properties to the south were improved with several large buildings believed to be the American Bosch Arma Corp building and Reeves Instrument Corp. as described on later Sanborn Fire Insurance Maps and a rail spur leading into the property. The adjacent property to the east is the Roosevelt Raceway and to the west across East Gate Boulevard is the Roosevelt Airfield with three airplane hangars along Old Country Road.

1957: Review of the 1957 aerial photograph revealed no major changes to the subject property in comparison to the 1953 aerial photograph. The Roosevelt Raceway area to the east and southeast appears to be under renovation. To the west the three airplane hangars remain along with an additional building to the southwest. The area to the north remains unchanged from the 1953 photograph.

1966: Review of the 1966 aerial photograph revealed the addition of a small rectangular building in the northwest corner of the site that appears to be the current Thomasville Home Furnishings building, along with two more additional structures in the south east corner of the site that appear to be the current Manufacturing building and Storage building. The remaining areas of the Site consisted of paved parking areas and the small landscaped area to the north of the office buildings.

Review of the 1966 aerial photograph revealed no major changes to the adjacent properties to the north and south in comparison to the 1953 aerial photograph, with the exception of the absence of a commercial building that was across Old Country Road to the north and the absence of the rail spur to the south. The adjacent property to the west, which was the Roosevelt Airfield, is now occupied by the Roosevelt Field Mall and the Meadowbrook Parkway. The three airplane hangars are still present along with several commercial buildings. To the east, the Roosevelt Raceway is still present; however it has been reconfigured and an additional building (Island Inn) is now present on Old Country Road across Zeckendorf Boulevard.

1974: Review of the 1974 aerial photograph revealed no major changes to the Site or adjoining properties to the north and south in comparison to the 1966 aerial photograph. To the north, a new commercial building appears to have replaced the former structure across Old Country Road. The adjacent property to the west no longer shows the three airplane hangar structures; instead, there is a large commercial building and parking areas. The Inn and Raceway to the east remain, with additional commercial buildings along Old Country Road.

1976: Review of the 1976 aerial photograph revealed no apparent changes to the Site or adjoining properties in comparison to the 1974 aerial photograph.

1980: Review of the 1980 aerial photograph revealed no major changes to the Site or adjoining properties to the north and south in comparison to the 1976 aerial photograph. To the east there are some additional commercial buildings along Old Country Road.

1985: Review of the 1985 aerial photograph is of very poor quality. Review of the aerial photograph revealed no apparent major changes to the site or adjoining properties however, the image is difficult to interpret due to the poor resolution.

1994: Review of the 1994 aerial photograph revealed no major changes to the subject or adjoining properties in comparison to the 1980 and 1985 aerial photographs, with the exception of additional commercial/retail structures and parking areas to the east (north of the Roosevelt Raceway) and to the southwest (northeast of the Meadowbrook Parkway).

Review of the aerial photographs revealed that the subject Avis office and Cendant office/warehouse buildings were constructed prior to 1953, with additional buildings (Manufacturing, Storage and Thomasville Home Furnishings) constructed after 1953 and prior to 1966. No evidence of environmental concern on or adjacent to the Site was revealed during a

review of the aerial photographs, with the exception of the former airplane hangars that used to exist along Old Country Road at the corner of East Gate Boulevard.

Copies of the aerial photographs are included in Appendix B.

2.2.3 Fire Insurance Maps

A Sanborn fire insurance map covering the Site for the years 1929, 1941, 1961, 1963, 1968, 1970, and 1980 were obtained from EDR of Milford, Connecticut. The fire insurance maps were reviewed for historical uses and evidence of environmental concern on or near the Site. The following is a discussion of the fire insurance maps.

1929: The 1929 fire insurance map does not show the actual site, however a notation of "Roosevelt Aviation Field" appears in the area adjacent to the site location to the east.

1941: Review of the 1941 fire insurance map reveals that the map shows only a small portion of the northwest corner of the site which is labeled "Roosevelt Field Inc." and appears to have been the northeastern portion of the Roosevelt Airfield. Six airplane hangars are depicted along Old Country Road and labeled as B through G. Hangar A is not shown, but may have existed to the east in the area that is not shown. At least three airplane hangars (those labeled B, C, and D) are depicted in the area which comprises the northwest corner of the present day site.

1961: Two fire insurance maps are provided for this year. The first map does not depict the site, but indentifies the Island Inn Motel and Restaurant to the east of the subject site across Zeckendorf Boulevard on Old Country Road and the Roosevelt Raceway to the southeast including its' main track, training track, stables and additional associated structures.

The second map details the entire property including three buildings as part of the American Bosch Arma Corp. (the current attached Avis and Cendant office buildings in the northeast area of the site and the manufacturing building in the southeast corner of the site). The remainder of the subject property is identified as parking. There is a rail spur shown on the southern border of the site and an additional building to the south as part of the American Bosch Arma complex. A fifth building is also shown to the south and is indicated as the Reeves Instrument Corp. East Gate Boulevard is now shown on the western border of the site. To the west of East Gate Boulevard remain three of the six formerly identified airplane hangars (E, F and G), which are now labeled as "vacant", and several commercial buildings including a small restaurant on Old Country Road and Pepsi Cola Bottling Co., United Parcel Service, and an Industrial Medical Clinic along East Gate Boulevard. Further west and south are additional commercial buildings. The area to the north across Old Country Road is not shown on either of the 1961 fire insurance maps.

1963: Review of the two 1963 fire insurance maps reveal that the subject property remains unchanged except for the addition of a small office building that now appears in the

northwest corner of the site (present day Thomasville Home Furnishings building). The area to the east and southeast remain unchanged except for the addition of a few commercial buildings along Old Country Road. The area to the west and southwest also remain largely unchanged; however, the formerly vacant airplane hangars are now identified as L.I. Studios and an additional commercial structure is shown to the southwest near the intersection of Zeckendorf Boulevard and East Gate Boulevard. The 1963 maps do not depict the area to the north of the site across Old Country Road.

1968: Review of the two 1968 fire insurance maps reveal a stamp stating "This Territory No Longer Corrected See Sheets 801, 802 and 807 Nassau County Volume 4-A" and multiple hand notations. This map is similar to the 1941 map only showing a small portion of the northwestern corner of the property which is identified on the map as American Bosch Arma Corp. East Gate Boulevard is shown to the west, and further west, the former airplane hangars are depicted, but manually crossed out and labeled "Railway Express Depot." On the second map, the area to the north across Old Country Road is shown occupied by various commercial buildings along Old Country Road including a filling station and a used cars sales lot directly across from the subject property. The area further to the north of these structures is residential development.

1970: Review of the 1970 fire insurance map shows the subject property largely unchanged, with the exception of a small additional building now shown in the southeastern corner of the site (present day Storage building). The main office building is labeled as American Machine and Foundry Co., but the smaller building in the southeast corner of the property remains labeled as part of the American Bosch Arma complex. Also depicted is an additional rail spur that runs adjacent to the large office building in the northeast portion of the site. The areas to the west, south, and south west appear unchanged. The areas to the east and north are not depicted in the 1970 map.

1980: Review of the two 1980 fire insurance maps reveal that these two maps appear to be duplications of the 1961 fire insurance maps, as there are no differences between the two sets of maps.

Copies of the fire insurance maps are included in Appendix C.

2.3 Results of Previous Environmental Investigations

The following sections provide an overview of the history of bulk storage tanks and the results of previous environmental investigations at the Site. Previous tank removals, drywell closures, and investigations have been performed by Tyree Brothers Environmental Services, Inc. (Tyree), Oxford Engineering Company (OEC), Soil Mechanics Environmental Services (Soil Mechanics), and Apex Companies, LLC (Apex).

2.3.1 Bulk Storage Tanks

Historically, the Former Avis Headquarters and Cendant Corporation operated seven underground and nine aboveground storage tanks at the Site. The aboveground storage tanks (AST) included:

Size (Gallons)	Contents	Location	Current Status
550	Waste Oil	Unknown	Out of Service
550	Waste Oil	Unknown	Out of Service
550	Motor Oil	Unknown	Out of Service
550	Motor Oil	Unknown	Out of Service
550	Motor Oil	Unknown	Out of Service
550	Motor Oil	Unknown	Out of Service
550	Motor Oil	Unknown	Out of Service
550	Motor Oil	Unknown	Out of Service
275	Transmission Fluid	Unknown	Out of Service

The underground storage tanks (UST) included:

Size (Gallons)	Contents	Location	Current Status
20,000	Unknown	Northeast of Cendant building	Removed 1988
20,000	No. 6 Fuel Oil	Northeast of Cendant building	Removed 1988
4,000	Diesel	Northeast of Cendant building	Removed 1988
1,000	Diesel	Northeast of Cendant building	Removed 1988
20,000	No. 6 Fuel Oil	Northeast of Cendant building	Removed 2005
4,000	Diesel	Northeast of Cendant building	Removed 2005
3,000	No. 2 Fuel Oil	Southeast of Manufacturing building	Removed 2005

2.3.2 Aboveground Storage Tank Closure

A previous Records Review conducted by OEC reported the existence of a Nassau County Department of Health (NCDH) Notice of Renewal of Toxic or Hazardous Materials Storage Facility Permit for the subject property. This renewal pertains to the ASTs listed above and lists the status as "In Service" as of October 1992. A Phase I Environmental Site Assessment by OEC performed in 2005 details the existence of three USTs, but does not indicate the presence of any ASTs as observed during work conducted at the Site. A Phase I Environmental Site Assessment performed by Apex in October 2009 reported that ASTs were historically present, but were not

observed during their site reconnaissance. A careful inspection of the Site by Roux Associates confirmed there are no ASTs currently present at the site.

2.3.3 Underground Storage Tank Closure and Floor Drain System Closures

In May of 2005, OEC conducted a records review of files obtained from the Nassau County Department of Health (NCDH). As part of this records review, OEC included information regarding Underground Injection Control (UIC) files for the Site. In 1993, the Site received a letter from the NCDH explaining that the floor drain systems for the boiler and mechanical rooms at the site were in violation of USEPA and NCDH regulations. In response to this violation, Tyree was contracted to trace, clean, and close the respective floor drain systems. Tyree determined that one of the floor drain systems was found to discharge to a concrete containment structure which had a concrete bottom, another system discharged to the Nassau County Sewer System, and a third discharged to a storm sewer culvert leading into the Nassau County Sump. As part of the closure plan all of the floor drains that lead to the sump and the containment structure were sealed and the drainage for these areas was re-routed so that it would be recycled into cooling tank units. Liquid and sludge samples collected from the containment tank prior to closure showed that the tank sludges contained elevated levels of metals, volatile organic compounds and poly chlorinated biphenyls. Although there is a distribution pool depicted on a figure included with the 1994 closure report, there was no mention of this distribution pool in the text of the report itself. Later geophysical investigations performed at the site by Apex determined the locations of the distribution leach pools (LP-28 and LP-29). The containment tank was evacuated and permanently sealed and the discharge pipe leading to the culvert that fed the sump was abandoned. A NCDH representative was present for these activities and approved the closures.

Based on documentation from the NCDH provided in the records review conducted by OEC, one 20,000 gallon tank, one 4,000 gallon tank and one 1,000 gallon tank were removed from the site by Tyree on April 5, 1988 with DEC oversight. According to this record, one hole was discovered in the 1,000 gallon tank and approximately 50-60 yards of contaminated soil was removed as a result. The report also states that “no other contamination was visible.” Information provided in the EDR Radius Map report and the NYSDEC Spill Incidents Database, shows that spill number 8707057 was opened on November 18, 1987 for a diesel tank failure at

the site, which is most likely the tank described above. The NYSDEC memo on the report stated that the tank was pumped out on the same day. An update to the memo dated August 22, 1988 states that Tyree removed all tanks along with 270 yards of soil, and that groundwater samples were taken and results came back clean. The last line of the memo section states that the record has been destroyed in accordance with state archive and record administrator procedures. The NYSDEC database lists the spill as being closed on August 22, 1988.

Additional documentation provided in OEC's records review details that on April 19, 1988, Tyree removed another 20,000 gallon tank (identified on the report as containing No. 6 Fuel Oil) from the site with no incident. An attached note from May 3, 1988 describes that the two 20,000 gallon tanks were removed and replaced with a single 20,000 gallon tank for heating purposes and the 4,000 gallon and 1,000 gallon tanks were removed and replaced with a single 4,000 gallon tank to service a generator.

According to their September 14, 2005 *Underground Storage Tank Closure Report*, in July 2005 OEC removed one 20,000 gallon No. 6 fuel oil tank and one 4,000 gallon diesel tank from the northeastern corner of the Site with approval of the NCDH. The tanks were evacuated of all contents, cleaned, and removed from the Site. The tank excavations were visually inspected and screened with a photo-ionization detector (PID). No contaminated soil was encountered in either excavation, and on July 14, 2005, the NCDH inspector confirmed these findings. The excavations were backfilled to grade and no further action was required.

According to their April 4, 2006 *Underground Storage Tank Closure Report,* in March 2006, OEC removed one 3,000 gallon No. 2 Fuel Oil tank from the southeastern corner of the Site behind the Manufacturing building. The tank was evacuated of all contents and cleaned. The tank excavation was visually inspected and screened with a PID. No contaminated soil was encountered in the excavation, and on March 14, 2006, the NCDH inspector confirmed these findings and that there were no signs of holes in the removed tank. The excavation was backfilled to grade and no further action was required.

2.3.4 Hazardous Waste Storage Areas

Based on a NCDH Application for a Toxic or Hazardous Materials Storage Facility Permit provided in OEC's 2005 records review, as of June 1999 Avis stored waste oil, Biosperse 255 Microbiocide and Performax 410 Corrosion Inhibitor in 55-gallon drums at the site, and these drums were located in three designated areas of the Cendant building. A letter dated June 21, 1999 from NCDH to Avis details that the Site was in violation due to a needed check on the electronic leak detection system for the fuel oil tank and improper waste oil storage. A follow up inspection report from August 1999 describes that corrections were made and the three prior drum storage areas were apparently combined into one storage location in the northeast corner of the Cendant building.

OEC did not address the presence or absence of the aforementioned drums in their Phase I or Phase II reports regarding the Site; however, there is reference to approximately 17 (55-gallon) drums observed in the Manufacturing building. OEC notes that the drums appeared to be empty and were labeled as containing various products related to concrete finishing. OEC also reported the presence of multiple empty 5-gallon and 1-gallon paint containers within the building. Apex also did not observe the drums or storage area referenced in the NCDH Application described above, but reported the presence of the 17 empty drums in the Manufacturing building in their Phase I report. During a March 2010 preliminary site walk, Roux Associates observed the drums described in the Manufacturing building.

OEC noted that based on their inspections, it appears that no chemical storage or handling took place in the Avis office, Thomasville Home Furnishings or Storage buildings, with the exception of *de minimis* quantities of general cleaning and maintenance chemicals. In the Cendant building, six large batteries were observed in an electrical substation, along with a five gallon container of electrolyte Acid Battery Fluid and a 50-gallon trash bin containing used filters and empty battery fluid boxes. OEC recommended that these items be properly packaged and disposed of prior to building demolition. Roux Associates has not encountered any hazardous material storage areas during detailed inspection of the Site.

2.3.5 Groundwater

Soil Mechanics installed 21 monitoring wells (MW-1 to MW-19, MW-9A, and MW-12A) at the Site during their investigation in July and August 2009. The locations of the observation wells are shown on Figure 2. Groundwater samples were collected in July 2009 and sent to Long Island Analytical Laboratories, Inc. (LIA), Holbrook, New York. These samples were analyzed for Target Compound List (TCL) VOCs (USEPA Method 8260) with methyl tert-butyl ether (MTBE), TCL SVOCs, and TCL Metals. A summary of the results are presented in Table 1 and on Plate 1, and are as follows:

- Groundwater samples from wells MW-1 through MW-8, MW-9A, MW-10, MW-12A, MW-13 through MW-16 and MW-19 had no VOCs detected above the minimum detection limits.
- Groundwater samples from wells MW-9, MW-11, MW-12, MW-17, and MW-18 had detections of chlorinated VOCs above the NYSDEC Ambient Water Quality Standards and Guidance Values (AWQSGVs).
- Groundwater samples from wells MW-1 through MW-4 had no detections of SVOCs above the minimum detection limits.
- Groundwater samples from wells MW-5 through MW-19 had SVOC detections of the compound Bis(2-ethylexl)phthalate ranging from 20 to 50 micrograms per liter (µg/L), which is above the AWQSGV of 5 µg/L for this compound.
- Groundwater samples from all of the wells sampled had detections of various metals, with AWQSGV exceedances of arsenic, barium, chromium, iron, lead, manganese, and nickel.

Apex completed a sampling program between September and October 2009 which included collecting groundwater samples from the 21 existing groundwater observation wells at the Site (MW-1 to MW-19, MW 9A and MW-12A). The sampling program was conducted to evaluate groundwater conditions in the vicinity of the observation wells. The groundwater samples were sent to York Analytical Laboratories, Inc. (York), of Stratford, Connecticut for laboratory analysis. The testing parameters included TCL VOCs (USEPA Method 8260) with MTBE and Freon 113, NYSDEC Spill Technology and Remediation Series (STARS) SVOCs, Priority Pollutant Metals (total and dissolved) total cyanide and PCBs. The results are presented in Table 1 and on Plate 1, and are summarized as follows:

- Groundwater samples from wells MW-1 through MW-5, MW-7, MW-8, MW-9A, MW-10, MW-12A, MW-14, MW-15, MW-18, and MW-19 had no VOCs detected above the minimum detection limits (MDLs).

- Groundwater samples from wells MW-9, MW-11, MW-12, MW-13, MW-16, and MW-17 had detections of chlorinated VOCs, all of which exceeded their respective AWQSGVs, with the exception of Tetrachloroethene (PCE) in MW-16 which was detected at a concentration equal to the standard of 5 µg/L.

- Groundwater samples from well MW-6 had a VOC detection of Isopropylbenzene (Cumene) of 21 µg/L, which exceeds the respective standard of 5 µg/L.

- SVOCs were not detected above the MDLs in any of the groundwater samples collected.

- Groundwater samples from all the wells sampled had detections of various metals, in both filtered (dissolved) and unfiltered (total) samples. Groundwater samples from MW-12A had exceedances of chromium (total) and manganese (total and dissolved), and groundwater samples from MW-19 had exceedances of manganese (total).

- PCBs were not detected above the MDLs in any of the groundwater samples collected.

- Cyanide was not detected above the MDLs in any of the groundwater samples collected.

The results indicate that the site groundwater had levels of chlorinated solvents that exceeded AWQSGVs as of 2009. The groundwater in the southern portion of the site generally contained concentrations of PCE and TCE exceeding the class GA groundwater quality standards. The groundwater in the north and northeastern portion of the site contained arsenic, barium, chromium, lead, manganese, and nickel exceeding the standards. All of the wells contained exceedances of iron.

2.3.6 Soil

OEC's Phase I and Phase II Site Investigations performed in 2005 detailed multiple AOCs at the Site including hydraulic elevators and a hydraulic compactor in the Avis and Cendant buildings, seepage/discharge pits and an oil/water separator in the Cendant and Manufacturing buildings, a large wooden tank in the Storage building, multiple transformers in various locations, and a suspected UST south of the Manufacturing building. OEC performed a sampling program to address these AOCs and the results are summarized as follows:

- Hydraulic fluids present in the elevator and compactor systems did not contain PCBs.

- Sediment samples collected from a seepage/discharge pit and oil/water separator in the Cendant building revealed elevated concentrations of metals, SVOCs, and PCBs. The discharge/seepage pit was constructed of concrete walls, with no apparent bottom. The oil/water separator was constructed of two concrete vaults with concrete bottoms and no apparent cracks or holes were observed.

- Sediment samples collected from the discharge pits in the Manufacturing building revealed elevated concentrations of metals and SVOCs. The pits were constructed of steel and did not appear to have any holes upon evacuation and visual inspection.

- Samples collected from the wooden tank in the Storage building contained SVOCs not exceeding the NYSDEC groundwater standards and low levels of metals.

- Transformers at the site were determined to be either "Dry Type" transformers which do not contain PCBs, or owned by Long Island Power Authority and thus any PCB containing transformers had previously been replaced by non-PCB capacitors prior to 1988.

- There were no apparent releases from the unregistered UST located south of the Manufacturing building based on soil samples and PID screening. Which OEC subsequently registered and removed under NCDH supervision as described in Section 2.3.3.

Soil Mechanics performed a site investigation in August 2009 which included a limited geophysical survey, soil borings, soil vapor sampling, and the installation of monitoring wells. Soil samples were collected from boring locations east of the Cendant building in the area of the former Fuel Oil and Diesel tanks, south of the Manufacturing building in the area of the former UST discovered and removed by OEC in 2005, south of the Storage building, in the vicinity of one of the Site septic systems and from several of the monitoring well locations. Soil samples were also collected from the eight drywells in the north and northeastern parking areas as well as additional locations thought to be drywells near the Storage building and north east of the Cendant building (Follow up investigations by Apex showed these other drywells to be part of the multiple leach pool systems present at the Site). A total of four soil vapor samples were collected from areas on the southern side of the Site, one south of the Manufacturing building, one south of the Storage building and one in the vicinity of each septic system. The soil samples were sent to LIA for analysis of VOCs, SVOCs, TAL Metals, and Total Petroleum Hydrocarbons (TPH). The results are presented on Plates 1 and 2, and are summarized as follows:

- Soil samples collected from the former tank areas had no VOCs detected above the MDLs. SVOCs were detected at concentrations below the Unrestricted Use Soil

Cleanup Objectives (SCOs). NCDH had previously approved the closures of the tanks in these areas.

- Soil samples collected from the drywells/leaching pools at the Site had minor detections of VOCs with no detections exceeding the SCOs; various SVOCs and metals were detected in concentrations that exceeded the respective SCOs.

- Soil vapor samples collected from outdoor areas of the site had elevated levels of chlorinated VOCs exceeding the New York State Department of Health (NYSDOH) Matrix 1 or Matrix 2 levels recommending soil vapor mitigation.

Apex performed Phase I and Phase II Site Investigations in September and October 2009. As part of the Site investigation activities, Apex performed a limited geophysical survey, groundwater sampling of existing monitoring wells, and soil sampling from multiple leach pools and from beneath the floor slabs of the Avis, Cendant, Manufacturing and Storage buildings. Apex discovered a total of 29 leach pools in six distinct clusters during their geophysical survey, it appears that these structures had not been fully identified or delineated during previous investigations by others. A representative set of leach pool structures were selected for sampling and 13 of the structures were ultimately sampled. Soil samples collected during this investigation were sent to York for analysis of TCL VOCs including MTBE and Freon 113, NYSDEC STARS SVOCs, Priority Pollutant Metals and PCBs. The results of Apex's Site investigation activities are presented on Plates 1 and 2, and summarized as follows:

- Soil samples were collected from fourteen of the 29 identified leach pools and a stained soil area identified during field work.

- Soil samples were collected from seven locations within the buildings, one each from the Avis and Cendant buildings, two from the storage building and three from the Manufacturing building.

- VOCs were only detected in samples from one leach pool location (LP-21), two locations in the Manufacturing building (S-4 and S-5) and the location in the in the Avis building. All of the VOC detections were below the respective SCOs.

- SVOCs were detected in four of the 13 leach pools sampled, in one of the samples collected from the stained area and in one of the samples from the Manufacturing building. Concentrations exceeded SCOs in only 2 of these locations including the stained soil area.

- PCBs were detected in all of the leach pools sampled, in the two samples collected from the stained soil area, in the two samples from the Storage building and in two of the three samples from the Manufacturing building. Concentrations of PCBs exceeded the SCOs in 10 of these samples.

- Metals were detected in all of the samples, with concentrations exceeding the SCOs in 10 of the samples.

The results of the above investigations show that further soil sampling is needed at the Site to fully delineate the extent of SVOC, PCB and metal impacts present in all of the leach pool areas, drywells and additional areas within the buildings.

2.3.7 Summary of Previous Environmental Sampling

The evaluation of this property is focused on historical industrial operations, which ceased approximately 30 years ago. As documented in several reports, soil and groundwater sampling has been carried out several times at the property between 2005 and the present. In general, the historical data either demonstrates that the issues have been sufficiently addressed, as is the case with the former tank locations at the property, or that the extent of the contamination observed during previous investigations has not been fully delineated.

Contamination at the site is due to historical industrial operations. Recent soil and groundwater sampling results at the Site have shown the presence of chlorinated VOCs, SVOCs, PCBs, and metals.

2.4 Data Usability

Previous groundwater analytical data developed by Soil Mechanics and Apex were evaluated by Roux Associates for data usability purposes during the RI. The purpose (data use) of the groundwater quality data was to:

1) Provide analytical data of sufficient quality to characterize the groundwater; and
2) Provide “screening level” quality data to guide/support future RI sampling efforts.

Data were reviewed for laboratory precision, accuracy, and completeness in accordance with the Test Methods for Evaluating Solid Waste (SW-846) and the New York State Department of Environmental Conservation (NYSDEC) Analytical Services Protocol (ASP).

The laboratory data package deliverables were not produced in accordance with NYSDEC ASP Category B deliverables. Therefore, the data generated by Soil Mechanics and Apex should be considered qualitative and used only as "screening level" quality data to guide/support future RI sampling efforts.

3.0 RI WORK PLAN OBJECTIVES, SCOPE AND RATIONALE

3.1 Objectives and Relationship to RAWP

Previous investigations have documented the presence of the following areas of contamination:

- TCE and PCE in groundwater on the southern side of the Cendant Building and the Manufacturing Building;
- TCE and PCE in soil vapor on the south of the Manufacturing Building and southwest and west of the Cendant Building;
- Metals and PCBs in soil below dry wells and leaching pools throughout the external portions of the site; and
- PCBs and metals in soil below a leach pit in the Cendant Building.

An additional issue is the lack of a comprehensive inspection of the Cendant Building by previous researchers due to the lack of electrical power, the size of the building, and the difficult logistics of conducting a thorough reconnaissance.

Based on the existing data base for the site and known data gaps, the following objectives have been identified for the RIWP:

- Inspect and identify all historic AOCs in onsite buildings;
- Evaluate soil quality associated with all AOCs;
- Identify the existence and three dimensional extent of soil quality impacts in all exterior dry wells/ leaching pools;
- Complete the installation of a comprehensive groundwater monitoring well network to provide coverage for all potential AOCs;
- Delineate the three dimensional extent of previously documented VOC impacts to groundwater;
- Delineate the extent of VOC impacts to soil vapor on south and west sides of the site;
- Evaluate potential radiological impacts from Bosch ARMA manufacturing operations; and
- Evaluate potential fluorocarbon impacts associated with refrigeration units at the Thomasville Furniture location.

Environmental data collected during the RI will be used to qualitatively assess the potential exposure of receptors to Site contaminants, and develop the information necessary to support the development of a RAWP.

3.2 RI Scope

The scope of the RI will entail the collection of supplemental site characterization data so that, together with the historic data including groundwater and soil sampling, the entire Site will be sufficiently characterized to support the development of the site-wide RAWP. To accomplish this, the RI will focus on the following:

- The collection of site characterization data for potential impacted areas;
- The collection of groundwater data for the entire Site;
- The performance of a soil vapor study for the Site;
- The performance of a radiological screening survey for the entire Site; and
- The performance of a qualitative exposure assessment to identify exposure pathways, and evaluate contaminant fate and transport.

The scope of each component of the RI is discussed in the following subsections. Detailed field sampling procedures are provided in the Field Sampling Plan (FSP), Appendix D. The proposed locations are shown on Figure 3 and details are summarized in Tables 3a, 3b and 3c.

3.2.1 Site Reconnaissance

A carefully planned, systematic inspection of the Cendant Building will be conducted to evaluate and identify all potential areas of environmental concern. Adequate lighting will be necessary to illuminate all areas of the building during the inspection. The location of all ASTs, leach pits, floor drains, dry wells or any structures that may have been used to store, collect or dispose of hazardous materials that were used during manufacturing will be the focus of the reconnaissance. Any features identified during the reconnaissance will be targeted during the installation of GeoProbe® soil borings discussed below.

The Site reconnaissance was performed in November 2010 during the initial round of investigations. As described above, Roux Associates did not observe any ASTs or hazardous

materials to be present at the Site. One pit was observed in the southern area of the Cendant building. Another pit was observed in the northern area of the Manufacturing building. No other additional areas of concern were discovered during the Site reconnaissance.

3.2.2 Gore Sorber Sampling

Gore Modules will be used to screen and characterize soil vapor concentrations beneath the slab of the Cendant Building, the Manufacturing building and the surrounding outdoor portions of the Site. The passive soil vapor sampling technology used by the Gore Modules is ideally suited to identify and locate sources of volatile organic vapors over a broad area that would be otherwise difficult to find. Forty Gore Module locations are planned for installation. These will be placed in approximately 125 foot on-center spacing within the Cendant building and one in each quadrant of the manufacturing building. Additional Gore Module locations will be placed in the surrounding outdoor areas of the buildings, associated former leaching structures, and areas of previous soil investigation (Figure 3).

Gore Modules were installed at the Site on November 11 and 12, 2010 for characterization and screening purposes and the results were submitted to NYSDEC on December 29, 2010. The results will be presented again in the Remedial Investigation Report that will be prepared at the conclusion of the RI. As planned, a total of 40 Gore Modules were installed across the Site including beneath the slab of the Cendant Building, the Manufacturing building and in the surrounding outdoor portions of the Site.

Based on the Gore Module sample results, a total of 14 soil borings and four (4) soil vapor sample locations have been selected for further analysis in the Cendant and Manufacturing buildings, and in the outdoor areas between these buildings. Continuous soil samples will be collected using a Geoprobe® and either a four or five foot macrocore sampler. Soil samples will be collected from the 0-2 foot and 2-4 foot interval at these locations. During the installation of the soil borings, lithology will be recorded and samples will be field screened for VOCs with a PID every two-feet to two and a half feet.

These locations were selected using the following method of analysis and evaluation. The graphic plots prepared by Gore that were submitted in the December 29, 2010 RI Addendum

were used to identify all Gore locations that had parameter-specific concentrations above the average background concentration. The figures use a colorimetric scale where background concentrations are presented in shades of blue, green and yellow. Locations with elevated concentrations are presented in shades of orange, red, magenta and purple. The concentration scale for each plot is shown on the right side of the figure.

3.2.3 Soil Characterization at Potential Impact Areas

Thirty-seven borings will be drilled at locations shown in Figure 3. Soil samples will be collected using a Geoprobe®. Geoprobe® samples will be collected continuously using either a four foot or five foot macro core sampler. Based on recent Site inspections, the leach pool structures are no longer visible at the ground surface, with the exception of some of the structures that were unearthed during Apex's investigation. Previous soil samples were collected at depths ranging from 10 to 13 feet below grade (i.e. 2-3 feet below the bottom of the structure). Additional soil samples will be taken from approximately five feet below the bottom of the structure. The proposed sampling locations can be found on Table 3a. During installation of the soil borings, the lithology will be recorded and soil will be field screened for VOCs using a PID, every two-feet to two and a half feet.

All samples will be analyzed for the following parameters.

- Target Compound List plus 30/ Target Analyte (TCL + 30/TAL) (which includes TCL VOA + ID TICS, TCL BNA, (SVOCs) + 20, TCL Pesticides, TCL PCBs, TAL Metals, and Total Cyanide); and
- Total Petroleum Hydrocarbons (TPH).

Soil samples were collected from a total of 29 leach pools and six dry wells using a GeoProbe direct push unit on November 15, 16, and 17, 2010. At each location, a soil boring was advanced through the earthen floor of the dry well with two soil samples collected at varying intervals based on PID readings. When dry wells had been previously sampled during the Phase II investigations conducted in 2009 and exceedances of Part 375 Soil Criteria were detected, the first sample collected by Roux Associates was below the impacted horizon. A total of 69 soil samples were collected. All samples were analyzed for the following parameters: TCL+30 VOCs; TCL BNAs; TCL+20 SVOCs; TCL pesticides; TCL PCBs; TAL metals; total cyanide;

TPH/GRO; TPH/DRO. Three dry wells remain to be sampled in the Thomasville Furniture parking lot located in the northwestern corner of the Site (DW-19, DW-20, and DW-21).

Monitoring well MW-20 was installed on November 17, 2010 using a hollow stem auger drilling rig and a soil sample was collected from the interval immediately above the water table. Monitoring wells MW-17A and MW-21 remain to be installed in the south/southwestern portion of the Site. No groundwater sampling of the wells has been conducted.

To confirm the quality of the leach pool and dry well sampling that was done in November 2010, Roux Associates will resample 20% of the previously sampled locations, a total of seven (7) locations including DW-2, LP-4, LP-15, LP-22, LP-23, LP-26 and LP-29. To evaluate the reliability of the original sampling data, the two sets of results will be compared and any deviations of greater than one order of magnitude will be flagged and reviewed with NYSDEC. Similarly, any sets of results that are found to straddle an applicable Part 375 soil cleanup standard (either Unrestricted Residential or Restricted Commercial) will also be reviewed with NYSDEC. IT is agreed however that where two sets of results are available, the higher concentration will be used for remedial planning purposes.

To evaluate the results of the Gore Module screening samples, soil borings are proposed for several locations beneath the Cendant building, Manufacturing building and the outdoor area between the Cendant and Manufacturing buildings as described above in Section 3.2.2.

3.2.4 Radiological Screening Survey

There is no indication that luminous aircraft dials were ever manufactured at the site using radium. This includes the lack of permits, shipping records or Department of Energy records which would have been generated in the 1950s and 1960s when Bosch ARMA was operating. To eliminate the possibility that radium was used in the manufacturing conducted at the site, a radiological screening survey will be conducted by EDI Inc., a firm with extensive radiological testing experience. To evaluate the potential presence of radium these surveys will be conducted using an unshielded Ludlum Model 44-10 2”x2” Sodium Iodide Detector coupled to a Ludlum Model 2221 Ratemeter/Scaler (set in the Ratemeter Mode). This instrument allows for the effective measurement of high energy photons such as those emanating from Radium-226 (Radon-222) daughter’s Lead and Bismuth-214.

The detector is a solid crystal of sodium iodide which creates a pulse of light when radiation interacts with it. This pulse of light is converted to an electrical signal by a photomultiplier tube (PMT), which gives a reading on the instrument meter. The pulse of light is proportional to the amount of light and the energy deposited in the crystal. This instrument has upper and lower energy discriminator circuits to provide information on the gamma energy and identify the radioactive material. Radium-226 concentrations can be inferred using a broad array of gamma rays from radon-222 daughter's Lead-214 and Bismuth-214. Readily resolved energies include 295.2 keV (19.2 %), 351.9 keV (37.2%), 609.3 keV (46.3 %), 1120 keV (15.1 %) and 1764 keV (15.8%). The instrument has a speaker and the pulses give an audible click, which the assists the technician in pinpointing areas that show elevated count rates.

All survey instruments will be calibrated and source checked daily prior to field use. Calibration Data Sheets will accompany the instrumentation and Daily Source Checks will be performed and recorded along with data collection survey forms of the findings.

3.2.5 Soil Vapor Sampling

Summa canister soil vapor samples will be collected to delineate the extent of VOC soil vapor impacts previously conducted sampling at the site and to quantitatively document and delineate any significant detections found during the Gore Module sampling. Summa canister samples will also be used to evaluate potential fluorocarbon impacts associated with the historic use of refrigeration units at the current Thomasville Furniture building. Soil vapor samples will be collected from areas outside of the building from borings installed using a Geoprobe or manually driven method, to the target depth of five feet. Once the target depth is achieved the rods will be pulled up 2 feet, exposing a void space. New Teflon lined tubing equipped with a threaded stainless steel fitting will be attached to the expendable soil vapor sampling point, to prevent infiltration of ambient air. The soil vapor samples will be collected using pre-cleaned six liter summa canisters with regulators calibrated to collect samples over a one-hour period. The boreholes will be allowed to collapse after the rods are removed and areas of asphalt/concrete will be properly patched. In addition, one outdoor ambient air sample will be collected using one-hour sample periods.

Based on the results of the Gore Module sampling, sub-slab soil vapor samples will be collected in the Cendant building. Prior to the collection of samples from within the building, a pre-sampling inspection will be performed to identify and minimize conditions that may interfere with the proposed testing. This inspection will seek to evaluate the type of structure, floor layout, air flows, physical conditions, and any other pertinent information. Additional details regarding the pre-sampling inspection are included in the FSP. Sample locations for sub-slab soil vapor samples will be selected based on areas of known or suspected industrial activities and based on the results of the Gore Sorber sampling. Sub-slab vapor samples will be collected directly below the slab, by penetrating the floor slab using a hammer drill to create a 1-inch diameter hole in the concrete down to 6–inches below the slab. The sample tubing will be placed through this hole and will be held in place and sealed with a clay seal. The penetrations through the floor will be sealed immediately after completion using a non-shrink cement/bentonite grout.

All soil vapor samples, sub slab vapor samples, and ambient samples will be analyzed using USEPA Method TO-15 for VOCs. Additional details regarding sampling methods are provided in the FSP (Appendix D).

3.2.6 Groundwater Investigation

To characterize groundwater flow and quality conditions, the existing network of monitoring wells will be sampled. Three new monitoring wells will also be installed in the southeast corner of the site (MW-17A, MW-20 and MW-21) to evaluate groundwater quality in this area. (Note: MW-20 was installed during the November 2010 site work, but no groundwater has been collected). The monitoring well locations are shown on Figure 3 and summarized in Table 3c.

Each well will be developed to ensure good hydraulic connection and to reduce/eliminate turbidity of the water. The wells will be developed using a submersible pump, which will be surged periodically until well yield is consistent and has a turbidity below 50 nephelometric turbidity units (NTUs), if possible. Detailed procedures regarding well development are also found in the FSP (Appendix D). All monitoring wells will be surveyed to obtain horizontal and vertical survey coordinates, and water level elevations will be calculated for each well.

Following well development, one round of groundwater samples will be collected and analyzed for:

- Target Compound List plus 30/ Target Analyte (TCL + 30/TAL) (which includes TCL VOA + ID TICS, TCL BNA, (SVOCs) + 20, TCL Pesticides, TCL PCBs, TAL Metals (both total and dissolved), and Total Cyanide); and
- Total Petroleum Hydrocarbons (TPH).

Field parameters will also be collected during well sampling.

3.2.7 Qualitative Exposure Assessment

A qualitative exposure assessment (EA) will be performed following the collection of all RI data. The EA will be performed in accordance with Section 3.3(c)4 of DER-10 and the New York State Department of Health (NYSDOH) guidance for performing a qualitative EA (NYSDEC DER-10; Technical Guidance for Site Investigation and Remediation; Appendix 3 B). The results of the qualitative EA will be provided in the RI report.

According to Section 3.10 of DER-10, and the Fish and Wildlife Resources Impact Analysis Decision Key in DER-10 Appendix 3C, a Fish and Wildlife exposure assessment is not needed.

4.0 QUALITY ASSURANCE/ QUALITY CONTROL (QA/QC) PROTOCOLS

The goal of the QA/QC aspect of the RI is to ensure that suitable and verifiable data results from sampling and analysis performed. To accomplish this, a Quality Assurance Project Plan (QAPP) has been prepared and is provided as Appendix E.

5.0 HEALTH AND SAFETY

A site-specific Health and Safety (H&S) Plan has been prepared for the Site and is provided in Appendix F.

6.0 REPORTING AND SCHEDULE

The following will be provided to the NYSDEC during the course of the RI work.

Sampling Results Technical Memorandum

As described in Section 3.2.1, following the completion of all the RI sampling work, a technical memorandum summarizing the results of the work and including all data, will be submitted to the NYSDEC for review. If additional contaminated areas are identified as a result of the RI, this memorandum will include any revisions to the scope of the RI to address such areas.

Progress Reports

Progress report submittals to be provided to the NYSDEC include the following.

1) Periodic reports, no less than one per month, will be required during RI activities.
2) Identification of any previously unknown contaminated media identified during RI activities will be promptly communicated to NYSDEC's project manager.
3) A Site map will be provided to identify locations discussed in progress reports provided to NYSDEC.

RI Summary Report

Following the completion of the RI, a RI report and a RAWP will be prepared to address any remaining contamination at the Site.

The RI report will include all data developed during the RI, and will meet the technical requirements of NYSDEC's DER-10; Technical Guidance for Site Investigation and Remediation.

Schedule

Remedial Investigation	January 31, 2011 to February 11, 2011
Submit IRM Work Plan for NYSDEC Review	February 25, 2011
NYSDEC and NYSDOH Review	February 25, 2011 to March 25, 2011
Implement IRM Work Plan	March 28, 2011to April 15, 2011
Submit RI Report/Remedial Action Plan	March 25, 2011

NYSDEC and NYSDOH Review	March 25, 2011 to April 22, 2011
Implement Remedial Action Plan	May 2, 2011
Submit Remedial Action Report	To Be Determined

Respectfully submitted,

ROUX ASSOCIATES, INC.

Wendy Monterosso
Project Hydrogeologist

Craig A. Werle, P.G.
Principal Hydrogeologist

Table 1. Summary of Historical Groundwater Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	NYS Class GA Groundwater Quality Standards (µg/l)	MW-1 Aug 2009	MW-1 Sept 2009	MW-2 Aug 2009	MW-2 Sept 2009	MW-3 Aug 2009	MW-3 Oct 2009	MW-4 Aug 2009	MW-4 Oct 2009	MW-5 Aug 2009	MW-5 Oct 2009	MW-6 Aug 2009	MW-6 Oct 2009	MW-7 Aug 2009	MW-7 Oct 2009	MW-8 Aug 2009
VOCs																
cis-1,2-Dichloroethene	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Tetrachloroethene	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Isopropylbenzene (Cumene)	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	**21**	ND	ND	ND
Methylene Chloride	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Trichloroethene	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
SVOCs																
Bis(2-ethylhexl)phthalate	5	ND	ND	ND	ND	ND	ND	ND	ND	**30**	ND	**30**	ND	**20**	ND	**20**
Metals																
Arsenic	25	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	80	8	53	ND	ND
Barium	1000	ND	132	ND	100	ND	159	ND	ND	ND	67	ND	175	**1020**	64	ND
Chromium	50	ND	9	ND	41	**300**	30	ND	ND	**93**	ND	**99**	ND	**150**	ND	ND
Copper	200	ND	ND	ND	8	ND	ND	ND	ND	99	ND	120	7	160	ND	ND
Lead	25	ND	4	ND	ND	ND	ND	ND	ND	**80**	ND	**100**	ND	**140**	ND	ND
Iron	300	**5800**	NA	**1670**	NA	**1510**	NA	**1670**	NA	**104000**	NA	**218000**	NA	**213000**	NA	**39600**
Manganese	300	100	56	98	160	91	24	200	26	**2830**	45	**590**	61	**2950**	32	**1410**
Mercury	1	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Nickel	100	ND	8	ND	36	ND	ND	ND	ND	110	6	76	ND	**140**	5	ND
Antimony	3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Beryllium	11	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Cadmium	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Selenium	10	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Silver	50	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Thallium	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Zinc	NA	540	8	120	16	47	8	33	10	260	9	270	10	390	12	150
PCBs																
Total PCBs	0.9	NA	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA

Notes:
All results in ug/l (ppb) unless noted.
Bold- Exceeds Guidance Value
VOCs- Volatile Organic Compounds
SVOCs- Semivolatile Organic Compounds
PCBs- Polychlorinated Biphenols
ND- Not Detected
NA- Not Applicable

Table 1. Summary of Historical Groundwater Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	NYS Class GA Groundwater Quality Standards (µg/l)	MW-8 Oct 2009	MW-9 Aug 2009	MW-9 Sept 2009	MW-9A Aug 2009	MW-9A Sept 2009	MW-10 Aug 2009	MW-10 Sept 2009	MW-11 Aug 2009	MW-11 Sept 2009	MW-12 Aug 2009	MW-12 Sept 2009	MW-12A Aug 2009	MW-12A Sept 2009	MW-13 Aug 2009
VOCs															
cis-1,2-Dichloroethene	5	ND	ND	ND	ND	ND	ND	ND	ND	**9**	ND	ND	ND	ND	ND
Tetrachloroethene	5	ND	**26.4**	**23**	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Isopropylbenzene (Cumene)	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Methylene Chloride	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Trichloroethene	5	ND	ND	ND	ND	ND	ND	ND	**12.9**	**35**	**13.7**	**15**	ND	ND	ND
SVOCs															
Bis(2-ethylhexl)phthalate	5	ND	**20**	ND	NA	ND	**20**	ND	**30**	ND	**20**	ND	NA	ND	**30**
Metals															
Arsenic	25	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	10	ND
Barium	1000	42	ND	53	NA	139	ND	50	ND	102	ND	176	NA	178	ND
Chromium	50	ND	ND	ND	NA	16	**130**	ND	ND	16	ND	18	NA	**91**	ND
Copper	200	ND	ND	7	NA	5	130	ND	ND	10	ND	10	NA	22	ND
Lead	25	ND	ND	ND	NA	ND	**85**	ND	ND	6	ND	8	NA	25	ND
Iron	300	NA	**7850**	NA	NA	NA	**124000**	NA	**17200**	NA	**6130**	NA	NA	NA	**26000**
Manganese	300	43	**420**	73	NA	35	**5070**	155	230	57	110	271	NA	**1270**	170
Mercury	1	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	ND	ND
Nickel	100	ND	ND	ND	NA	12	91	ND	ND	13	ND	15	NA	86	ND
Antimony	3	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	ND	ND
Beryllium	11	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	ND	ND
Cadmium	5	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	ND	ND
Selenium	10	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	ND	ND
Silver	50	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	ND	ND
Thallium	NA	ND	ND	ND	NA	ND	ND	ND	ND	ND	ND	ND	NA	ND	ND
Zinc	NA	9	29	10	NA	13	290	8	68	55	49	33	NA	17	130
PCBs															
Total PCBs	0.9	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA

Notes:
All results in ug/l (ppb) unless noted.
Bold- Exceeds Guidance Value
VOCs- Volatile Organic Compounds
SVOCs- Semivolatile Organic Compounds
PCBs- Polychlorinated Biphenols
ND- Not Detected
NA- Not Applicable

Table 1. Summary of Historical Groundwater Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	NYS Class GA Groundwater Quality Standards (µg/l)	MW-13 Sept 2009	MW-14 Aug 2009	MW-14 Sept 2009	MW-15 Aug 2009	MW-15 Sept 2009	MW-16 Aug 2009	MW-16 Sept 2009	MW-17 Aug 2009	MW-17 Sept 2009	MW-18 Aug 2009	MW-18 Sept 2009	MW-19 Aug 2009	MW-19 Sept 2009
VOCs														
cis-1,2-Dichloroethene	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Tetrachloroethene	5	ND	ND	ND	ND	ND	ND	5	**27.5**	**19**	ND	ND	ND	ND
Isopropylbenzene (Cumene)	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Methylene Chloride	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	**7.5**	ND	ND	ND
Trichloroethene	5	**6**	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
SVOCs														
Bis(2-ethylhexl)phthalate	5	ND	**30**	ND	**30**	ND	**30**	ND	**30**	ND	**50**	ND	**20**	ND
Metals														
Arsenic	25	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Barium	1000	34	ND	65	ND	84	ND	120	ND	68	ND	123	ND	102
Chromium	50	ND	ND	11	ND	13	ND	ND	ND	7	ND	14	ND	13
Copper	200	ND	ND	8	ND	7	ND	5	ND	ND	ND	10	ND	10
Lead	25	ND	ND	ND	ND	5	ND	ND	ND	ND	ND	5	ND	7
Iron	300	NA	**1550**	NA	**870**	NA	**3360**	NA	**1330**	NA	**560**	NA	**7570**	NA
Manganese	300	5	ND	29	ND	120	240	148	120	67	80	146	**370**	**320**
Mercury	1	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Nickel	100	6	ND	11	ND	10	ND	5	ND	5	ND	13	ND	11
Antimony	3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Beryllium	11	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Cadmium	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Selenium	10	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Silver	50	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Thallium	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Zinc	NA	6	80	22	ND	23	ND	10	ND	9	ND	15	ND	21
PCBs														
Total PCBs	0.9	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA	ND	NA	ND

Notes:
All results in ug/l (ppb) unless noted.
Bold- Exceeds Guidance Value
VOCs- Volatile Organic Compounds
SVOCs- Semivolatile Organic Compounds
PCBs- Polychlorinated Biphenols
ND- Not Detected
NA- Not Applicable

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	Sed-1 (grab) 7/12/2005	Sed-2 (grab) 7/12/2010	Sed-3 (grab) 7/13/2010	Sed-4 (grab) 7/15/2010	DW-1 (7-8) Sept 2005	DW-2 (8-9) Sept 2005	DW-14 (12-13) Sept 2005	DW-16 (11-12) Sept 2005	DW-19 (10-11) Sept 2005
VOCs										
Tetrachloroethene	1.3	ND	ND	ND	ND	ND	ND	ND	ND	ND
1,2,4-Trichlorobenzene	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
2-Hexanone	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Ethylbenzene	1	ND	ND	ND	ND	ND	ND	ND	ND	ND
Toluene	0.7	ND	ND	ND	**29.8**	ND	ND	ND	ND	ND
Xylenes (total)	0.26	ND	ND	ND	ND	ND	ND	ND	ND	ND
SVOCs										
Acenaphthene	20	ND	ND	ND	ND	1.38	**23**	1.33	ND	3.44
Anthracene	100	ND	ND	ND	ND	6.42	37	3.82	0.07	9.39
Benzo[a]anthracene	1	**5.67**	**14.6**	**54**	**6.03**	**34.68**	**89.78**	**23.58**	**0.51**	**34.87**
Benzo[a]pyrene	1	ND	**7.46**	**20.7**	**10.9**	**48.517**	**126.842**	**41.342**	**1.016**	**51.476**
Benzo[b]fluoranthene	1	**3.38**	**12.4**	**40.8**	**5.08**	**53.922**	**162.2**	**66.805**	**1.367**	**70.997**
Benzo[k]fluoranthene	0.8	**2.45**	**5.93**	**30.8**	**7.12**	**41.20**	**113.42**	**35.34**	**0.93**	**42.56**
Bis(2-ethylhexl)phthalate	NA	53.2	88.3	3.41	41.3	ND	ND	ND	ND	ND
Indeno(1,2,3-C,D)pyrene	0.5	ND	**6.31**	**13.3**	ND	**40**	**98**	**43**	**1.015**	**48**
Dibenzo(a,h)anthracene	0.33	ND	**0.737**	**6.14**	ND	**8.736**	**20.24**	**7.82**	0.18	**9.80**
Chrysene	1	**3.16**	**12**	**31.5**	**4.72**	**48.953**	**167.418**	**54.113**	**1.109**	**68.668**
Fluoranthene	100	15.3	37	80.7	15.6	85.7	**388.1**	91.5	1.8	**132.7**
Fluorene	30	2.98	4.86	5.79	6.14	1.5	**35.7**	1.6	ND	4.2
Pentachlorophenol	0.8	ND	ND	ND	ND	ND	ND	ND	ND	ND
Phenanthrene	100	36.3	27.4	54.8	4.87	31.559	**256.452**	31.304	0.515	73.099
Pyrene	100	9.21	23	39.9	11.1	67.035	**268.7**	66.904	1.396	96.773
Phenols	0.33	ND	ND	**7.4**	**31.2**	ND	ND	ND	ND	ND

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	Sed-1 (grab) 7/12/2005	Sed-2 (grab) 7/12/2010	Sed-3 (grab) 7/13/2010	Sed-4 (grab) 7/15/2010	DW-1 (7-8) Sept 2005	DW-2 (8-9) Sept 2005	DW-14 (12-13) Sept 2005	DW-16 (11-12) Sept 2005	DW-19 (10-11) Sept 2005
Metals										
Arsenic	13	**21.5**	9.87	ND	ND	ND	ND	ND	1.85	ND
Barium	350	NS	NS	NS	NS	32.8	32.6	23.6	5.51	44.1
Chromium	30	**69.1**	**6680**	**194**	**54.5**	27.8	**30.9**	24.2	5.1	**31.8**
Copper	50	**1280**	**8230**	**1480**	**217**	38.7	48.7	40.2	3.55	**204**
Lead	63	**323**	**4510**	**159**	**90.8**	**117.0**	**143.0**	**77.8**	4.62	**355.0**
Manganese	1600	NS	NS	NS	NS	93.7	33.4	36.5	41.3	49.5
Mercury	0.18	**0.552**	**5.15**	0.084	0.121	0.087	0.078	0.075	ND	0.037
Nickel	30	**50.8**	**3310**	**66.5**	**39.6**	12.8	13.2	9.77	2.12	10.6
Antimony	NA	10.7	160	7.56	19	ND	ND	ND	ND	ND
Beryllium	7.2	ND	ND	0.2	ND	ND	ND	ND	ND	ND
Cadmium	2.5	**7.4**	**38.4**	**11.6**	ND	ND	1.74	ND	ND	ND
Selenium	4	ND	ND	ND	ND	ND	ND	ND	ND	ND
Silver	2	**10.7**	**23.5**	ND	**7.56**	ND	ND	ND	ND	ND
Thallium	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Zinc	109	**2010**	**3450**	**443**	**13200**	**361**	**258**	**158.8**	18.4	**766**
PCBs										
Total PCBs	0.1	ND	ND	**48.3**	ND	NA	NA	NA	NA	NA

Notes:

All results in mg/kg unless noted.

Bold- Exceeds Guidance Value

VOCs- Volatile Organic Compounds

SVOCs- Semivolatile Organic Compounds

PCBs- Polychlorinated Biphenols

ND- Not Detected

NA- Not Applicable

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	DW-20 (17-18) Sept 2005	DW-21 (12-13) Sept 2005	DW-22 (8-9) Sept 2005	DW-23 (7-8) Sept 2005	DW-24 (9-10) Sept 2005	DW-25 (9-10) Sept 2005	DW-26 (12-13) Sept 2005	B-1 (20-22) Sept 2005	B-2 (20-22) Sept 2005
VOCs										
Tetrachloroethene	1.3	ND	ND	ND	ND	ND	ND	0.02	ND	ND
1,2,4-Trichlorobenzene	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
2-Hexanone	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Ethylbenzene	1	ND	ND	ND	ND	ND	ND	ND	ND	ND
Toluene	0.7	ND	0.008	ND	ND	ND	ND	ND	ND	ND
Xylenes (total)	0.26	ND	ND	ND	ND	ND	ND	ND	ND	ND
SVOCs										
Acenaphthene	20	ND	ND	3.83	ND	ND	ND	ND	ND	ND
Anthracene	100	8.61	34.77	9.04	0.08	ND	ND	ND	ND	ND
Benzo[a]anthracene	1	**55.66**	**109.44**	**40.00**	0.21	0.07	ND	1.47	ND	ND
Benzo[a]pyrene	1	**85.037**	**136.68**	**64.433**	0.382	0.172	0.0645	**1.124**	ND	ND
Benzo[b]fluoranthene	1	**124.609**	**165.724**	**81.389**	0.361	0.158	0.048	**1.162**	ND	ND
Benzo[k]fluoranthene	0.8	**85.79**	**108.44**	**58.84**	0.34	0.12	ND	0.75	ND	ND
Bis(2-ethylhexl)phthalate	NA	ND	ND	ND	ND	ND	ND	3.2	ND	ND
Indeno(1,2,3-C,D)pyrene	0.5	**87**	**103**	**57**	0.295	0.135	0.06	**0.77**	ND	ND
Dibenzo(a,h)anthracene	0.33	**17.03**	**25.23**	**11.49**	0.08	0.05	ND	ND	ND	ND
Chrysene	1	**119.931**	**169.443**	**83.964**	0.4	0.118	ND	0.991	ND	ND
Fluoranthene	100	**210.4**	**360.4**	154.7	0.594	0.059	ND	1.9	ND	ND
Fluorene	30	ND	15.7	5.7	ND	ND	ND	ND	ND	ND
Pentachlorophenol	0.8	ND	ND	ND	ND	ND	ND	**6.5**	ND	ND
Phenanthrene	100	76.898	**224.517**	68.954	0.399	ND	ND	0.719	ND	ND
Pyrene	100	**153.235**	**265.018**	**117.122**	0.476	0.0588	ND	2.244	ND	ND
Phenols	0.33	ND	ND	ND	ND	ND	ND	ND	ND	ND

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	DW-20 (17-18) Sept 2005	DW-21 (12-13) Sept 2005	DW-22 (8-9) Sept 2005	DW-23 (7-8) Sept 2005	DW-24 (9-10) Sept 2005	DW-25 (9-10) Sept 2005	DW-26 (12-13) Sept 2005	B-1 (20-22) Sept 2005	B-2 (20-22) Sept 2005
Metals										
Arsenic	13	2.09	2.39	6.32	ND	ND	3.88	**204**	ND	ND
Barium	350	29	36.3	81.9	33.1	22.1	44.3	**387**	ND	ND
Chromium	30	27.9	**42.1**	**42.9**	14.4	9.46	29.2	**16232**	4.37	1.76
Copper	50	**61.5**	**77.4**	**170**	18.6	35.8	**687**	**7382**	ND	ND
Lead	63	**113.0**	**232.0**	**377.0**	12.5	5.27	**119.0**	**1841.0**	ND	ND
Manganese	1600	32.9	39.9	135	82.5	26.2	35.9	196	10.9	63.6
Mercury	0.18	0.096	0.168	**0.294**	**0.247**	0.05	**0.481**	**1.69**	ND	ND
Nickel	30	12.8	**32**	29.5	8.07	6.96	14.8	**31.4**	ND	ND
Antimony	NA	ND	ND	ND	ND	ND	ND	5.02	ND	ND
Beryllium	7.2	ND	ND	ND	ND	ND	ND	ND	ND	ND
Cadmium	2.5	ND	2.24	**3.66**	ND	ND	1.97	**8.39**	ND	ND
Selenium	4	ND	ND	ND	ND	ND	ND	ND	ND	ND
Silver	2	ND	ND	ND	ND	ND	**3.44**	**9.58**	ND	ND
Thallium	NA	ND	ND	ND	ND	ND	28	ND	ND	ND
Zinc	109	**283**	**463**	**829**	83.8	83.9	**369**	**3948**	4.16	3.73
PCBs										
Total PCBs	0.1	NA	NA	NA	NA	NA	NA	NA	NA	NA

Notes:

All results in mg/kg unless noted.

Bold- Exceeds Guidance Value

VOCs- Volatile Organic Compounds

SVOCs- Semivolatile Organic Compounds

PCBs- Polychlorinated Biphenols

ND- Not Detected

NA- Not Applicable

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	B-3 (20-22) Sept 2005	B-4 (16-18) Sept 2005	B-5 (10-12) Sept 2005	B-6 (16-18) Sept 2005	B-7 (16-18) Sept 2005	B-8 (18-20) Sept 2005	B-9 (18-20) Sept 2005	B-10 (18-20) Sept 2005	B-11 (18-20) Sept 2005
VOCs										
Tetrachloroethene	1.3	ND	ND	ND	ND	ND	ND	ND	ND	ND
1,2,4-Trichlorobenzene	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
2-Hexanone	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Ethylbenzene	1	ND	ND	ND	ND	ND	ND	ND	ND	ND
Toluene	0.7	ND	ND	ND	ND	ND	ND	ND	ND	ND
Xylenes (total)	0.26	ND	ND	ND	ND	ND	ND	ND	ND	ND
SVOCs										
Acenaphthene	20	ND	ND	ND	ND	ND	ND	ND	ND	ND
Anthracene	100	ND	ND	ND	ND	ND	ND	ND	ND	ND
Benzo[a]anthracene	1	ND	ND	0.08	ND	ND	ND	ND	ND	ND
Benzo[a]pyrene	1	ND	ND	0.13	ND	ND	ND	ND	ND	ND
Benzo[b]fluoranthene	1	ND	ND	0.102	ND	ND	ND	ND	ND	ND
Benzo[k]fluoranthene	0.8	ND	ND	0.10	ND	ND	ND	ND	ND	ND
Bis(2-ethylhexl)phthalate	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Indeno(1,2,3-C,D)pyrene	0.5	ND	ND	0.08	ND	ND	ND	ND	ND	ND
Dibenzo(a,h)anthracene	0.33	ND	ND	ND	ND	ND	ND	ND	ND	ND
Chrysene	1	ND	ND	0.109	ND	ND	ND	ND	0.044	ND
Fluoranthene	100	ND	ND	0.1	ND	ND	ND	ND	0.051	ND
Fluorene	30	ND	ND	ND	ND	ND	ND	ND	ND	ND
Pentachlorophenol	0.8	ND	ND	ND	ND	ND	ND	ND	ND	ND
Phenanthrene	100	ND	ND	0.0553	ND	ND	ND	ND	ND	ND
Pyrene	100	ND	ND	0.124	ND	ND	ND	ND	0.0587	ND
Phenols	0.33	ND	ND	ND	ND	ND	ND	ND	ND	ND

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	B-3 (20-22) Sept 2005	B-4 (16-18) Sept 2005	B-5 (10-12) Sept 2005	B-6 (16-18) Sept 2005	B-7 (16-18) Sept 2005	B-8 (18-20) Sept 2005	B-9 (18-20) Sept 2005	B-10 (18-20) Sept 2005	B-11 (18-20) Sept 2005
Metals										
Arsenic	13	ND	ND	ND	ND	ND	ND	ND	ND	ND
Barium	350	ND	ND	ND	ND	ND	ND	ND	ND	ND
Chromium	30	ND	ND	ND	ND	ND	ND	ND	ND	ND
Copper	50	ND	ND	ND	ND	ND	ND	ND	ND	ND
Lead	63	ND	ND	ND	ND	ND	ND	ND	ND	ND
Manganese	1600	4.32	ND	ND	ND	ND	ND	ND	ND	ND
Mercury	0.18	ND	ND	ND	ND	ND	ND	ND	ND	ND
Nickel	30	ND	ND	ND	ND	ND	ND	ND	ND	ND
Antimony	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Beryllium	7.2	ND	ND	ND	ND	ND	ND	ND	ND	ND
Cadmium	2.5	ND	ND	ND	ND	ND	ND	ND	ND	ND
Selenium	4	ND	ND	ND	ND	ND	ND	ND	ND	ND
Silver	2	ND	ND	ND	ND	ND	ND	ND	ND	ND
Thallium	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Zinc	109	4.03	ND	ND	ND	ND	ND	ND	ND	ND
PCBs										
Total PCBs	0.1	NA	NA	NA	NA	NA	NA	NA	NA	NA

Notes:

All results in mg/kg unless noted.

Bold- Exceeds Guidance Value

VOCs- Volatile Organic Compounds

SVOCs- Semivolatile Organic Compounds

PCBs- Polychlorinated Biphenols

ND- Not Detected

NA- Not Applicable

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	B-12 (0-2) Sept 2005	B-13 (18-20) Sept 2005	B-14 (2-4) Sept 2005	B-15 (3-4) Sept 2005	LP-1 (10'-11') 10/13/2009	LP-4 (10'-11') 10/13/2009	LP-9 (12'-13') 10/13/2009	LP-14 (12'-13') 10/13/2009	LP-15 (12'-13') 10/13/2009
VOCs										
Tetrachloroethene	1.3	ND	ND	ND	ND	ND	ND	ND	ND	ND
1,2,4-Trichlorobenzene	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
2-Hexanone	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Ethylbenzene	1	ND	ND	ND	ND	ND	ND	ND	ND	ND
Toluene	0.7	ND	ND	ND	ND	ND	ND	ND	ND	ND
Xylenes (total)	0.26	ND	ND	ND	ND	ND	ND	ND	ND	ND
SVOCs										
Acenaphthene	20	ND	ND	ND	ND	ND	ND	ND	ND	ND
Anthracene	100	ND	ND	ND	ND	ND	ND	ND	ND	ND
Benzo[a]anthracene	1	0.067	ND	ND	0.079	ND	0.2	ND	ND	ND
Benzo[a]pyrene	1	0.084	ND	ND	0.121	ND	0.23	ND	ND	ND
Benzo[b]fluoranthene	1	0.109	ND	ND	0.0918	ND	0.43	ND	ND	ND
Benzo[k]fluoranthene	0.8	0.092	ND	ND	0.10	ND	0.52	ND	ND	ND
Bis(2-ethylhexl)phthalate	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA
Indeno(1,2,3-C,D)pyrene	0.5	0.094	ND	ND	0.0918	ND	ND	ND	ND	ND
Dibenzo(a,h)anthracene	0.33	ND	ND	ND	ND	ND	ND	ND	ND	ND
Chrysene	1	0.105	ND	ND	0.116	ND	0.24	ND	ND	ND
Fluoranthene	100	0.173	0.047	0.1	0.143	0.25	0.38	ND	ND	ND
Fluorene	30	ND	ND	ND	ND	ND	ND	ND	ND	ND
Pentachlorophenol	0.8	ND	ND	ND	ND	ND	ND	ND	ND	ND
Phenanthrene	100	0.0559	0.0616	0.0548	0.15	ND	ND	ND	ND	ND
Pyrene	100	0.134	ND	0.0664	0.132	0.21	0.29	ND	ND	ND
Phenols	0.33	ND	ND	ND	ND	NA	NA	NA	NA	NA

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	B-12 (0-2) Sept 2005	B-13 (18-20) Sept 2005	B-14 (2-4) Sept 2005	B-15 (3-4) Sept 2005	LP-1 (10'-11') 10/13/2009	LP-4 (10'-11') 10/13/2009	LP-9 (12'-13') 10/13/2009	LP-14 (12'-13') 10/13/2009	LP-15 (12'-13') 10/13/2009
Metals										
Arsenic	13	ND	ND	ND	2.81	1.7	1.91	ND	ND	1.11
Barium	350	ND	ND	13.1	37.7	10.7	14.9	5.97	5.4	14.6
Chromium	30	ND	ND	11.8	11	8.02	7.01	3.13	3.7	5.27
Copper	50	ND	ND	4.03	7.04	26.2	14.4	12	5.58	36.5
Lead	63	ND	ND	4.58	10.1	9.31	6.5	2.75	2.29	7.87
Manganese	1600	ND	ND	32.1	138	37.7	48.6	6	10.3	22.2
Mercury	0.18	ND	ND	0.056	ND	ND	ND	ND	ND	ND
Nickel	30	ND	ND	7.23	6.45	6.74	7.17	2.55	2.98	3.55
Antimony	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Beryllium	7.2	ND	ND	ND	ND	ND	ND	ND	ND	ND
Cadmium	2.5	ND	ND	ND	ND	ND	0.64	ND	ND	0.83
Selenium	4	ND	ND	ND	ND	ND	ND	ND	ND	ND
Silver	2	ND	ND	ND	ND	ND	ND	ND	ND	ND
Thallium	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Zinc	109	ND	ND	14.1	27.1	38	**153**	29.4	31.3	**207**
PCBs										
Total PCBs	0.1	NA	NA	NA	NA	0.03	**0.33**	0.04	**0.17**	**0.37**

Notes:

All results in mg/kg unless noted.

Bold- Exceeds Guidance Value

VOCs- Volatile Organic Compounds

SVOCs- Semivolatile Organic Compounds

PCBs- Polychlorinated Biphenols

ND- Not Detected

NA- Not Applicable

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	LP-21 (12'-13') 10/13/2009	LP-22 (12'-13') 10/13/2009	LP-23 (12'-13') 10/13/2009	LP-24 (12'-13') 10/13/2009	LP-25 (10'-11') 10/13/2009	LP-26 (10'-11') 10/13/2009	LP-27 (12'-13') 10/13/2009	LP-28 (11'-12') 10/13/2009	SS-1 (3'-4') 10/13/2009
VOCs										
Tetrachloroethene	1.3	**75**	ND	ND	ND	ND	ND	ND	ND	ND
1,2,4-Trichlorobenzene	NA	230	ND	ND	ND	ND	ND	ND	ND	ND
2-Hexanone	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Ethylbenzene	1	ND	ND	ND	ND	ND	ND	ND	ND	ND
Toluene	0.7	ND	ND	ND	ND	ND	ND	ND	ND	ND
Xylenes (total)	0.26	ND	ND	ND	ND	ND	ND	ND	ND	ND
SVOCs										
Acenaphthene	20	ND	ND	ND	ND	ND	ND	ND	ND	ND
Anthracene	100	ND	ND	ND	ND	ND	ND	ND	ND	ND
Benzo[a]anthracene	1	ND	ND	0.36	ND	ND	ND	3.3	ND	ND
Benzo[a]pyrene	1	ND	ND	0.36	ND	ND	ND	2.9	ND	ND
Benzo[b]fluoranthene	1	ND	ND	0.27	ND	ND	ND	3.8	ND	ND
Benzo[k]fluoranthene	0.8	ND	ND	0.32	ND	ND	ND	4.5	ND	ND
Bis(2-ethylhexl)phthalate	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Indeno(1,2,3-C,D)pyrene	0.5	ND	ND	ND	ND	ND	ND	ND	ND	ND
Dibenzo(a,h)anthracene	0.33	ND	ND	ND	ND	ND	ND	ND	ND	ND
Chrysene	1	ND	ND	0.35	ND	ND	ND	3.4	ND	ND
Fluoranthene	100	ND	ND	0.63	ND	ND	ND	6.3	ND	ND
Fluorene	30	ND	ND	ND	ND	ND	ND	ND	ND	ND
Pentachlorophenol	0.8	ND	ND	ND	ND	ND	ND	ND	ND	ND
Phenanthrene	100	ND	ND	0.31	ND	ND	ND	1.8	ND	ND
Pyrene	100	ND	ND	0.48	ND	ND	ND	3.8	ND	ND
Phenols	0.33	NA	NA	NA	NA	NA	NA	NA	NA	NA

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	LP-21 (12'-13') 10/13/2009	LP-22 (12'-13') 10/13/2009	LP-23 (12'-13') 10/13/2009	LP-24 (12'-13') 10/13/2009	LP-25 (10'-11') 10/13/2009	LP-26 (10'-11') 10/13/2009	LP-27 (12'-13') 10/13/2009	LP-28 (11'-12') 10/13/2009	SS-1 (3'-4') 10/13/2009
Metals										
Arsenic	13	ND	5.12	1.85	1	3.13	1.38	2	ND	2.46
Barium	350	177	46.6	50.1	111	126	**426**	45.8	11.1	27.9
Chromium	30	**16400**	**394**	**48.2**	26.1	21.2	**185**	6.05	**30.1**	10.6
Copper	50	**2110**	**274**	**138**	11	39.4	34.6	17	42.4	10.9
Lead	63	**502**	29.5	33.9	5.87	12.4	28.7	24.10	10.3	15.6
Manganese	1600	45	28.9	165	13	118	27.7	43	6.57	62
Mercury	0.18	ND	ND	ND	ND	ND	ND	ND	ND	ND
Nickel	30	**572**	18.9	8.29	3.69	11.1	12.1	4.78	2.46	7.17
Antimony	NA	193	4.67	ND	ND	ND	2.3	ND	ND	ND
Beryllium	7.2	ND	ND	ND	ND	ND	ND	ND	ND	ND
Cadmium	2.5	**8**	0.69	0.84	0.51	1.58	1.16	0.76	0.59	0.63
Selenium	4	ND	ND	ND	ND	ND	1	ND	ND	ND
Silver	2	ND	ND	ND	ND	ND	ND	ND	**136**	ND
Thallium	NA	ND	ND	ND	ND	ND	ND	ND	ND	ND
Zinc	109	**3380**	**147**	83.7	57.8	**259**	**137**	91.8	22.6	20.7
PCBs										
Total PCBs	0.1	**0.32**	**4.36**	**1.96**	**4.07**	**1.57**	**6.22**	**0.23**	**0.05**	**0.07**

Notes:

All results in mg/kg unless noted.

Bold- Exceeds Guidance Value

VOCs- Volatile Organic Compounds

SVOCs- Semivolatile Organic Compounds

PCBs- Polychlorinated Biphenols

ND- Not Detected

NA- Not Applicable

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	SS-2 (1'-2') 10/13/2009	S-1 (1'-2') 10/14/2009	S-2 (1'-2') 10/14/2009	S-3 (1'-2') 10/13/2009	S-4 (1'-2') 10/13/2009	S-5 (1'-2') 10/13/2009	S-7 (2'-3') 10/14/2009	S-8 (1'-2') 10/14/2009
VOCs									
Tetrachloroethene	1.3	ND	ND	ND	ND	**11**	**38**	ND	ND
1,2,4-Trichlorobenzene	NA	ND	ND	ND	ND	ND	ND	ND	ND
2-Hexanone	NA	ND	ND	ND	ND	ND	ND	13	ND
Ethylbenzene	1	ND	ND	ND	ND	ND	ND	**39**	ND
Toluene	0.7	ND	ND	ND	ND	ND	ND	ND	ND
Xylenes (total)	0.26	ND	ND	ND	ND	ND	ND	**116**	ND
SVOCs									
Acenaphthene	20	ND	ND	ND	ND	ND	ND	ND	ND
Anthracene	100	ND	ND	ND	ND	ND	ND	ND	ND
Benzo[a]anthracene	1	1.1	ND	ND	ND	ND	0.22	ND	ND
Benzo[a]pyrene	1	ND	ND	ND	ND	ND	0.19	ND	ND
Benzo[b]fluoranthene	1	1.2	ND	ND	ND	ND	0.33	ND	ND
Benzo[k]fluoranthene	0.8	1.4	ND	ND	ND	ND	0.19	ND	ND
Bis(2-ethylhexl)phthalate	NA	NA	NA	NA	NA	NA	NA	NA	NA
Indeno(1,2,3-C,D)pyrene	0.5	ND	ND	ND	ND	ND	ND	ND	ND
Dibenzo(a,h)anthracene	0.33	ND	ND	ND	ND	ND	ND	ND	ND
Chrysene	1	1.6	ND	ND	ND	ND	0.28	ND	ND
Fluoranthene	100	2.9	ND	ND	ND	ND	0.48	ND	ND
Fluorene	30	ND	ND	ND	ND	ND	ND	ND	ND
Pentachlorophenol	0.8	ND	ND	ND	ND	ND	ND	ND	ND
Phenanthrene	100	1.2	ND	ND	ND	ND	0.41	ND	ND
Pyrene	100	2.1	ND	ND	ND	ND	0.42	ND	ND
Phenols	0.33	NA	NA	NA	NA	NA	NA	NA	NA

Table 2. Summary of Historical Soil Sample Results
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Analyte	Unrestricted Use Soil Cleanup Objective (mg/kg)	SS-2 (1'-2') 10/13/2009	S-1 (1'-2') 10/14/2009	S-2 (1'-2') 10/14/2009	S-3 (1'-2') 10/13/2009	S-4 (1'-2') 10/13/2009	S-5 (1'-2') 10/13/2009	S-7 (2'-3') 10/14/2009	S-8 (1'-2') 10/14/2009
Metals									
Arsenic	13	5	4.09	3.37	3	1.91	3.42	1	2.25
Barium	350	28.2	21.1	29.5	20.4	18.5	48	9.73	25.7
Chromium	30	19.9	15.3	19.5	15.4	13.4	17.7	6.89	9.68
Copper	50	19	12	11.6	22	**340**	17.5	5	8.09
Lead	63	**65.80**	12.1	4.79	3.82	13.5	13.1	1.34	8.02
Manganese	1600	154	162	313	140	104	344	84	155
Mercury	0.18	ND	ND	ND	ND	ND	ND	ND	ND
Nickel	30	11.2	12.2	15	15.3	20.5	15.8	5.26	7.99
Antimony	NA	ND	ND	ND	ND	ND	0.82	ND	ND
Beryllium	7.2	ND	ND	ND	ND	ND	ND	ND	ND
Cadmium	2.5	1.45	1.06	0.99	0.99	0.73	0.97	0.49	0.67
Selenium	4	2	ND	ND	ND	ND	ND	ND	ND
Silver	2	ND	ND	ND	ND	ND	ND	ND	ND
Thallium	NA	ND	ND	ND	ND	ND	ND	ND	ND
Zinc	109	44.6	28.3	23.4	13.9	60.1	24.4	74.1	16.2
PCBs									
Total PCBs	0.1	0.06	0.045	0.034	ND	0.019	0.019	ND	ND

Notes:

All results in mg/kg unless noted.

Bold- Exceeds Guidance Value

VOCs- Volatile Organic Compounds

SVOCs- Semivolatile Organic Compounds

PCBs- Polychlorinated Biphenols

ND- Not Detected

NA- Not Applicable

Table 3a. Proposed Soil Sampling Locations
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Area of Concern (AOC)	Location	Matrix	Depth to Bottom of Leach Pool/Dry well*	Sample Depths*	Date of Sample	Location to be Re-Sampled	Depths to be Re-Sampled*	Sample Parameters	Sampling Method**	Rationale
Former Leach Pool Structures										
	LP-1	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-2/DW-23	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and	To delineate the nature and extent of potential contamination
	LP-3	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-4	Soil	10	14-16	11/15/2010	Yes	10-11 and 14-16	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-5	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-6	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-7	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-8	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-9	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-10	Soil	10	10-12 and 14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-11	Soil	13	15-17 and 19-21	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-12	Soil	11	11-13 and 17-19	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-13	Soil	10	10-12 and 15-17	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-14	Soil	10	14-16	11/15/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-15/DW-24	Soil	10	14-16	11/16/2010	Yes	12-13 and 14-16	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-16	Soil	10	10-12 and 14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-17	Soil	10	10-12 and 14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-18	Soil	10	10-12 and 14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-19	Soil	10	10-12 and 14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-20	Soil	10	10-12 and 14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-21/DW-26	Soil	10	10-12 and 14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-22	Soil	10	14-16	11/16/2010	Yes	12-13 and 14-16	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-23	Soil	10	14-16	11/16/2010	Yes	12-13 and 14-16	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-24	Soil	10	14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-25	Soil	10	14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination

Table 3a. Proposed Soil Sampling Locations
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Area of Concern (AOC)	Location	Matrix	Depth to Bottom of Leach Pool/Dry well*	Sample Depths*	Date of Sample	Location to be Re-Sampled	Depths to be Re-Sampled*	Sample Parameters	Sampling Method**	Rationale
	LP-26	Soil	10	14-16	11/16/2010	Yes	10-11 and 14-16	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-27	Soil	10	14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-28/DW-25	Soil	10	14-16	11/16/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
	LP-29	Soil	10	10-12 and 14-16	11/16/2010	Yes	10-12 and 14-16	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination
Drywells										
	DW-1	Soil	8.5	8.5-10.5 and 14.5-16.5	11/17/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-2	Soil	9	9-11 and 15-17	11/17/2010	Yes	9-11, 15-17 and 18-20	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-14	Soil	10	10-12 and 14-16	11/17/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-15	Soil	10	10-12 and 14-16	11/17/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-16	Soil	1.5	6-8 and 12-14	11/17/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-19	Soil	Unknown	Bottom of structure or in Representative point within area, and 5 feet below bottom.	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-20	Soil	Unknown	Bottom of structure or in Representative point within area, and 5 feet below bottom.	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-21	Soil	Unknown	Bottom of structure or in Representative point within area, and 5 feet below bottom.	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
	DW-22	Soil	1.5	6-8 and 12-14	11/17/2010	No	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of potential contamination from parking lot run-off
Cendant Building										
	G-04	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-05	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-07	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-08	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-10	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-30	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-32	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-33	Soil	NA	0-2, 2-4 and 8-10	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey

Table 3a. Proposed Soil Sampling Locations
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Area of Concern (AOC)	Location	Matrix	Depth to Bottom of Leach Pool/Dry well*	Sample Depths*	Date of Sample	Location to be Re-Sampled	Depths to be Re-Sampled*	Sample Parameters	Sampling Method**	Rationale
Manufacturing Building										
	G-12	Soil	NA	0-2, 2-4, 2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-13	Soil	NA	0-2, 2-4, 2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-13A	Soil	NA	0-2, 2-4, 2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
South and Southwestern Portion of Site										
	G-17	Soil	NA	0-2, 2-4, 2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-18	Soil	NA	0-2, 2-4, 2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	G-44	Soil	NA	0-2, 2-4, 2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination indicated by the Gore Module Screening Survey
	MW-17A	Soil	NA	2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination identifed during previous investigations
	MW-20	Soil	NA	18-20	11/17/2010	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination identifed during previous investigations
	MW-21	Soil	NA	2-foot interval above the water table and any interval with elevated PID reading	NA	NA	NA	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (TPH GRO and DRO)	To delineate the nature and extent of contamination identifed during previous investigations

QA/QC samples will be collected as described in the QAPP (Appendix E)
* Depths are in feet from grade; Additional intervals may be added based on field observations
** Laboratory will report to their minimum possible standards for each method as described in the QAPP (Appendix E)
TCL - USEPA Contract Laboratory Program Target Compound List
TAL - USEPA Contract Laboratory Program Target Analyte List
TPH - Total Petroleum Hydrocarbons
VOCs - Volatile Organic Compounds
SVOCs - Semivolatile Organic Compounds
PCBs - Polychlorinated Biphenyls
TCL + 30/TAL - includes TCL VOCs + 10 TICs, TCL BNA (SVOCs) + 20 TICs, TCL Pest/PCB, TAL Metals, Total Cyanide
TICs - Tentatively Identified Compounds
TBD - To Be Determined
NA- Not Applicable

Table 3b. Proposed Soil Vapor Sampling Locations
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Area of Concern (AOC)	Location	Matrix	Sample Depth*	Sample Parameters	Sampling Method**	Rationale
Cendant Building	V-7	Soil Vapor	Sub-Slab	VOCs	TO-15	To evaluate the nature and extent of soil vapor impacts as indicated by the Gore Module Screening Survey
	V-8	Soil Vapor	Sub-Slab	VOCs	TO-15	To evaluate the nature and extent of soil vapor impacts as indicated by the Gore Module Screening Survey
	V-9	Soil Vapor	Sub-Slab	VOCs	TO-15	To evaluate the nature and extent of soil vapor impacts as indicated by the Gore Module Screening Survey
South and Southwestern Portion of Site						
	V-1	Soil Vapor	5	VOCs	TO-15	To evaluate the nature and extent of soil vapor impacts as indicated by the Gore Module Screening Survey
	V-2	Soil Vapor	5	VOCs	TO-15	To evaluate the nature and extent of soil vapor impacts as indicated by the Gore Module Screening Survey
	V-3	Soil Vapor	5	VOCs	TO-15	To evaluate the nature and extent of soil vapor impacts as indicated by the Gore Module Screening Survey
	V-4	Soil Vapor	5	VOCs	TO-15	To evaluate the nature and extent of soil vapor impacts as indicated by the Gore Module Screening Survey
Thomasville Furniture						
	V-5	Soil Vapor	5	VOCs	TO-15	To evaluate the nature and extent of potential soil vapor impacts from former refrigeration facilities
	V-6	Soil Vapor	5	VOCs	TO-15	To evaluate the nature and extent of potential soil vapor impacts from former refrigeration facilities

* Feet below grade
** Laboratory will report to their minimum possible standards for each method as described in the QAPP (Appendix E)
VOCs - Volatile Organic Compounds
QA/QC samples will be collected as described in the QAPP (Appendix E)

Table 3c. Proposed Groundwater Sampling Locations
Former Avis Headquarters, 900 Old Country Road, Garden City, New York

Area of Concern (AOC)	Monitoring Wells	Matrix	Sample Depth*	Sample Parameters	Sampling Method**	Rationale
Site-wide Groundwater	MW-1 through MW-19	Groundwater	± 22-32	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (GRO and DRO)	To evaluate the nature and extent of groundwater impacts as indicated by previous investigations
Southeastern Corner	MW-9A	Groundwater	± 44-51	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (GRO and DRO)	To evaluate the vertical extent of groundwater impacts as indicated by previous investigations
	MW-12A	Groundwater	± 42-50	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (GRO and DRO)	To evaluate the vertical extent of groundwater impacts as indicated by previous investigations
	MW-17A, MW-20	Groundwater	± 40-50	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (GRO and DRO)	To evaluate the vertical extent of groundwater impacts as indicated by previous investigations
	MW-21	Groundwater	TBD	TCL + 30/TAL	SW-846 8260B;SW-846 8270C;SW-846 8081A;SW-846 8082;SW-846 6010/7471;SW-846 8015 (GRO and DRO)	To evaluate the nature and extent of groundwater impacts as indicated by previous investigations

* Feet below grade, screened interval of well
** Laboratory will report to their minimum possible standards for each method as described in the QAPP (Appendix E)
TCL - USEPA Contract Laboratory Program Target Compound List
TAL - USEPA Contract Laboratory Program Target Analyte List
TPH - Total Petroleum Hydrocarbons (EPA Method 418.1)
VOCs - Volatile Organic Compounds
SVOCs - Semivolatile Organic Compounds
PCBs - Polychlorinated Biphenyls
TCL + 30/TAL - includes TCL VOCs + 10 TICs, TCL BNA (SVOCs) + 20 TICs, TCL Pest/PCB, TAL Metals, Total Cyanide
TICs - Tentatively Identified Compounds
TBD - To Be Determined
QA/QC samples will be collected as described in the QAPP (Appendix E)



N

0 1000' 2000'

Title:

SITE LOCATION MAP

FORMER AVIS HEADQUARTERS PROPERTY
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

Prepared for:

EQUITY ONE, INC.

ROUX ASSOCIATES, INC.
Environmental Consulting & Management

Compiled by: B.H.	Date: 19JAN11	FIGURE
Prepared by: B.H.C.	Scale: AS SHOWN	1
Project Mgr.: C.W.	Project No.: 1924.0001Y000	
File: 1924.0001Y106R.01.CDR		

\1924Y\0001Y\106R\1924.0001Y106R.01.CDR



QUADRANGLE LOCATION

SOURCE:
USGS; Freeport, NY (2010)
USGS; Hicksville, NY (2010)
7.5 Minute Topographic Quadrangle

LEGEND

- RESIDENTIAL
- COMMERCIAL
- INDUSTRIAL
- WETLAND
- PARK
- TRANSPORTATION

Title:

LAND USE

FORMER AVIS HEADQUARTERS PROPERTY
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

Prepared for:

EQUITY ONE, INC.

ROUX ASSOCIATES, INC.
Environmental Consulting & Management

Compiled by: W.M.	Date: 19JAN11	FIGURE
Prepared by: B.H.C.	Scale: AS SHOWN	2
Project Mgr.: C.W.	Project No.: 1924.0001Y000	
File: 1924.0001Y106R.01.CDR		

\1924Y\0001Y\106R\1924.0001Y106R.02.CDR



LEGEND

PROPOSED SAMPLE LOCATIONS

- PROPOSED SOIL SAMPLE LOCATION
- MW-21 — PROPOSED MONITORING WELL
- V-1 — PROPOSED SOIL VAPOR SAMPLE

COMPLETED RI SAMPLE LOCATIONS

- MW-20 — MONITORING WELL INSTALLED NOVEMBER 2010
- G-27 — GORE MODULE
- LP-25 — LEACH POOL
- CB-3 — CATCH BASIN
- DW-1 — DRY WELL
- MW-8 — EXISTING MONITORING WELL

PROPOSED SAMPLING LOCATIONS (SECOND MOBILIZATION)

FORMER AVIS HEADQUARTERS PROPERTY
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

Prepared For:
EQUITY ONE, INC.

ROUX ASSOCIATES, INC.
Environmental Consulting and Management

Compiled by: W.M	Date: 19JAN11	FIGURE 3
Prepared by: B.H.C.	Scale: AS SHOWN	
Project Mgr: C.W.	Project: 1924.0001Y	
File: 1924.0001Y106R.01.DWG		

\1924\0001Y\106R\1924.0001Y106R.03.DWG

APPENDIX A

EDR GeoCheck®

900 Old Country Road
900 Old Country Road
Garden City, NY 11530

Inquiry Number: 2735789.4s
April 05, 2010

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	7
Orphan Summary	433
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-10
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	A-160

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

COORDINATES

Latitude (North):	40.744120 - 40° 44' 38.8''
Longitude (West):	73.605520 - 73° 36' 19.9''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	617735.2
UTM Y (Meters):	4511076.5
Elevation:	85 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	40073-F5 FREEPORT, NY
Most Recent Revision:	1994
North Map:	40073-G5 HICKSVILLE, NY
Most Recent Revision:	1979
West Map:	40073-F6 LYNBROOK, NY
Most Recent Revision:	1969
Northwest Map:	40073-G6 SEA CLIFF, NY
Most Recent Revision:	1979

AERIAL PHOTOGRAPHY IN THIS REPORT

Photo Year:	No Photo Available
Source:	USDA

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 7 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
AVIS CAR RENTAL 900 OLD COUNTRY RD GARDEN CITY, NY 11530	RCRA-CESQG FINDS LTANKS Date Closed: 8/22/1988 HIST LTANKS Date Closed: 08/22/88 MANIFEST	NYD001954387
AVIS RENT A CAR SYS. 900 OLD COUNTRY RD. GARDEN CITY, NY	UST	N/A

ANACOMP CORP. 900 OLD COUNTRY ROAD GARDEN CITY, NY 11530	MANIFEST	N/A
AVIS RENT A CAR SYSTEM, INC. 900 OLD COUNTRY RD EAST GARDEN CITY, NY 11530	UST	N/A
ANACOMP MICRO GRAPHICS INC 900 OLD COUNTRY RD GARDEN CITY, NY 11530	RCRA-NonGen FINDS MANIFEST	NYD101195709
ANACOMP CORP 900 OLD COUNTRY ROAD GARDEN CITY, NY 11530	MANIFEST	N/A
AVIS RENTAL 900 OLD COUNTRY RD GARDEN CITY, CT 11530	MANIFEST	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal CERCLIS NFRAP site List

CERC-NFRAP ---------- CERCLIS No Further Remedial Action Planned

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

EXECUTIVE SUMMARY

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-SQG ---------- RCRA - Small Quantity Generators

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

SWF/LF ---------- Facility Register

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

CBS UST ---------- Chemical Bulk Storage Database
MOSF UST ---------- Major Oil Storage Facilities Database
CBS AST ---------- Chemical Bulk Storage Database
MOSF AST ---------- Major Oil Storage Facilities Database
MOSF ---------- Major Oil Storage Facility Site Listing
CBS ---------- Chemical Bulk Storage Site Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land
FEMA UST ---------- Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

ENG CONTROLS ---------- Registry of Engineering Controls
INST CONTROL ---------- Registry of Institutional Controls
RES DECL ---------- Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing
VCP ---------- Voluntary Cleanup Agreements

State and tribal Brownfields sites

ERP ---------- Environmental Restoration Program Listing
BROWNFIELDS ---------- Brownfields Site List

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

ODI ---------- Open Dump Inventory

DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
SWTIRE ---------- Registered Waste Tire Storage & Facility List
SWRCY ---------- Registered Recycling Facility List
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL ---------- Clandestine Drug Labs
DEL SHWS ---------- Delisted Registry Sites
US HIST CDL ---------- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

HIST UST ---------- Historical Petroleum Bulk Storage Database
HIST AST ---------- Historical Petroleum Bulk Storage Database

Local Land Records

LIENS 2 ---------- CERCLA Lien Information
LUCIS ---------- Land Use Control Information System

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System

Other Ascertainable Records

DOT OPS ---------- Incident and Accident Data
DOD ---------- Department of Defense Sites
UMTRA ---------- Uranium Mill Tailings Sites
MINES ---------- Mines Master Index File
TRIS ---------- Toxic Chemical Release Inventory System
TSCA ---------- Toxic Substances Control Act
FTTS ---------- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS ---------- FIFRA/TSCA Tracking System Administrative Case Listing
SSTS ---------- Section 7 Tracking Systems
ICIS ---------- Integrated Compliance Information System
PADS ---------- PCB Activity Database System
MLTS ---------- Material Licensing Tracking System
RADINFO ---------- Radiation Information Database
RAATS ---------- RCRA Administrative Action Tracking System
HSWDS ---------- Hazardous Substance Waste Disposal Site Inventory
DRYCLEANERS ---------- Registered Drycleaners
NPDES ---------- State Pollutant Discharge Elimination System
AIRS ---------- Air Emissions Data
E DESIGNATION ---------- E DESIGNATION SITE LISTING
INDIAN RESERV ---------- Indian Reservations
SCRD DRYCLEANERS ---------- State Coalition for Remediation of Drycleaners Listing
COAL ASH DOE ---------- Sleam-Electric Plan Operation Data
PCB TRANSFORMER ---------- PCB Transformer Registration Database
COAL ASH EPA ---------- Coal Combustion Residues Surface Impoundments List
COAL ASH ---------- Coal Ash Disposal Site Listing
FINANCIAL ASSURANCE ---------- Financial Assurance Information Listing

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

EXECUTIVE SUMMARY

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 12/01/2009 has revealed that there are 2 NPL sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OLD ROOSEVELT FIELD CONTAMINAT	***CLINTON ROAD/OLD COUNTR***	***WSW 1/4 - 1/2 (0.461 mi.)***	***0***	***39***
PASLEY SOLVENTS & CHEMICALS, I	***585 COMMERICAL AVENUE***	***SSW 1/2 - 1 (0.813 mi.)***	***0***	***47***

Federal CERCLIS list

CERCLIS: The Comprehensive Environmental Response, Compensation and Liability Information System contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the CERCLIS list, as provided by EDR, and dated 06/30/2009 has revealed that there is 1 CERCLIS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OLD ROOSEVELT FIELD CONTAMINAT	***CLINTON ROAD/OLD COUNTR***	***WSW 1/4 - 1/2 (0.461 mi.)***	***0***	***39***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity

generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 01/13/2010 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
AAR AIRCRAFT COMPONENT SERVICE	*747 ZECKENDORF BOULEVAR*	*SSE 1/8 - 1/4 (0.131 mi.)*	*L70*	*247*

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 01/13/2010 has revealed that there are 5 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WAL-MART #3420	*1220 OLD COUNTRY RD*	*ENE 0 - 1/8 (0.029 mi.)*	*B31*	*128*
EXXON DIV OF CFI #70230	*285 OLD COUNTRY RD & LI*	*W 0 - 1/8 (0.091 mi.)*	*J48*	*169*
VERIZON	*741 ZECKENDORF BLVD 1ST*	*SSE 1/8 - 1/4 (0.130 mi.)*	*M63*	*225*
TARGET #1139	*999 CORPORATE DR*	*ESE 1/8 - 1/4 (0.182 mi.)*	*N75*	*300*
H & R PARTS	*800 AXINN AVE*	*SW 1/8 - 1/4 (0.203 mi.)*	*P79*	*317*

Federal institutional controls / engineering controls registries

US ENG CONTROLS: A listing of sites with engineering controls in place.

A review of the US ENG CONTROLS list, as provided by EDR, and dated 10/01/2009 has revealed that there is 1 US ENG CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OLD ROOSEVELT FIELD CONTAMINAT	*CLINTON ROAD/OLD COUNTR*	*WSW 1/4 - 1/2 (0.461 mi.)*	*0*	*39*

US INST CONTROL: A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

A review of the US INST CONTROL list, as provided by EDR, and dated 10/01/2009 has revealed that there is 1 US INST CONTROL site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OLD ROOSEVELT FIELD CONTAMINAT	*CLINTON ROAD/OLD COUNTR*	*WSW 1/4 - 1/2 (0.461 mi.)*	*0*	*39*

State- and tribal - equivalent CERCLIS

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the SHWS list, as provided by EDR, and dated 02/23/2010 has revealed that there are 5 SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
A.K. ALLEN CORP	***255 E 2ND ST***	***W 1/2 - 1 (0.958 mi.)***	***100***	***387***
Class Code: Significant threat to the public health or environment - action required.				
123 POST AVENUE	123 POST AVENUE	ENE 1/2 - 1 (0.973 mi.)	102	430
Class Code: Significant threat to the public health or environment - action required.				

Lower Elevation	Address	Direction / Distance	Map ID	Page
AWARD PACKAGING (TENANT)	***625 SOUTH STREET***	***S 1/4 - 1/2 (0.448 mi.)***	***96***	***380***
Class Code: Significant threat to the public health or environment - action required.				
PASLEY SOLVENTS & CHEMICALS IN	***556 COMMERCIAL AVENUE***	***S 1/2 - 1 (0.768 mi.)***	***99***	***385***
Class Code: Significant threat to the public health or environment - action required.				
LI BUS MSBA	***COMMERCIAL AVENUE***	***SSW 1/2 - 1 (0.963 mi.)***	***101***	***425***
Class Code: Site is properly closed - requires continued management.				

VAPOR REOPENED: "Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil.Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

A review of the VAPOR REOPENED list, as provided by EDR, and dated 02/02/2010 has revealed that there are 2 VAPOR REOPENED sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PASLEY SOLVENTS & CHEMICALS IN	***556 COMMERCIAL AVENUE***	***S 1/2 - 1 (0.768 mi.)***	***99***	***385***
LI BUS MSBA	***COMMERCIAL AVENUE***	***SSW 1/2 - 1 (0.963 mi.)***	***101***	***425***

State and tribal leaking storage tank lists

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 02/23/2010 has revealed that there are 27

EXECUTIVE SUMMARY

LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FAMILY COURT BLDG	***1200 OLD COUNTRY ROAD***	***0 - 1/8 (0.000 mi.)***	***B8***	***57***
Date Closed: 11/5/1992				
OFFICE BLDG	***1000 ZECKENDORF BLVD***	***0 - 1/8 (0.000 mi.)***	***C16***	***79***
Date Closed: 9/14/1994				
NORTHVILLE GASOLINE CORP	***345 OLD COUNTRY ROAD***	***NNW 0 - 1/8 (0.008 mi.)***	***D27***	***100***
Date Closed: 1/6/1989				
CANNON USA CORP	***1000 AXIN AVENUE***	***SSW 0 - 1/8 (0.104 mi.)***	***K51***	***194***
Date Closed: 9/15/1988				
NY TELEPHONE	***741 ZECKENDORF***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M56***	***200***
Date Closed: 11/14/1990				
PEPSI COLA	***800 EAST GATE BLVD***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M57***	***203***
Date Closed: 3/4/1988				
BELL ATLANTIC	***741 ZECKENDORF BLVD***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M59***	***206***
Date Closed: 10/20/1999				
NEW YORK TELEPHONE CO	***741 ZECKENDORF BLVD***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M61***	***211***
Date Closed: 10/21/1988				
KATHY LALLY RESIDENCE	***339 CURTIS AVENUE***	***NNW 1/8 - 1/4 (0.148 mi.)***	***72***	***292***
Date Closed: 12/23/1993				
MINEOLA FUEL	***14 GARDEN COURT***	***NNW 1/8 - 1/4 (0.177 mi.)***	***74***	***297***
Date Closed: 2/10/1992				
Not reported	1000 CORPORATE DRIVE	ESE 1/8 - 1/4 (0.184 mi.)	N76	315
Date Closed: 4/9/2004				
SMALL RESIDENCE	248 CURTIS AVENUE	WNW 1/8 - 1/4 (0.214 mi.)	81	325
Date Closed: 11/7/2003				
MOBIL S/S	***640 OLD COUNTRY ROAD***	***WSW 1/4 - 1/2 (0.358 mi.)***	***Q83***	***328***
Date Closed: 5/3/1990				
OUR LADY OF HOPE	***CHERRY LANE / BROADWA***	***NNW 1/4 - 1/2 (0.363 mi.)***	***R84***	***335***
Date Closed: 8/29/1990				
Date Closed: 9/15/1989				
SOUZA RESIDENCE	***8 ROCKAWAY AVENUE***	***ENE 1/4 - 1/2 (0.373 mi.)***	***86***	***341***
Date Closed: 2/18/1992				
EAB BANK	***600 OLD COUNTRY ROAD***	***WSW 1/4 - 1/2 (0.378 mi.)***	***Q87***	***343***
Date Closed: 7/23/1993				
HUNTS POINT OIL	***ROOSEVELT FIELD SHOPPIN***	***WSW 1/4 - 1/2 (0.401 mi.)***	***89***	***349***
Date Closed: 3/26/1991				
BELCHER FUEL OIL CO	***RUSHMORE AVE / WESTBU***	***NNW 1/4 - 1/2 (0.404 mi.)***	***90***	***351***
Date Closed: 7/29/1991				
LILCO	***351 WESTBURY AVENUE***	***NNW 1/4 - 1/2 (0.405 mi.)***	***91***	***354***
Date Closed: 4/19/2007				
HESS STATION 32492	***500 WESTBURY AVE***	***NNW 1/4 - 1/2 (0.411 mi.)***	***R92***	***357***
Not reported	***300 WESTBURY AVENUE***	***NNW 1/4 - 1/2 (0.416 mi.)***	***93***	***372***
Date Closed: 10/28/1997				
AMS STATIONERY	***520 WESTBURY AVENUE***	***N 1/4 - 1/2 (0.416 mi.)***	***94***	***374***
Date Closed: 4/6/1993				
MICHAEL SKURNICK	***1400 OLD COUNTRY ROAD***	***ENE 1/4 - 1/2 (0.430 mi.)***	***95***	***377***
Date Closed: 4/21/1997				

Lower Elevation	Address	Direction / Distance	Map ID	Page
PEPSI COLA CO Date Closed: 2/20/1991	***867 EAST GATE BLVD***	***WSW 0 - 1/8 (0.008 mi.)***	***F23***	***92***
NATIONAL HELICOPTER Date Closed: 11/25/1987	***NORTH AVE & E GATE***	***WSW 0 - 1/8 (0.008 mi.)***	***F28***	***103***
NATIONAL HELICOPTER Date Closed: 11/9/1994	***NORTH AVENUE***	***WSW 0 - 1/8 (0.088 mi.)***	***I39***	***154***
GEORGIAN PRESS INC Date Closed: 7/18/1994	***750 ZEKENDORF BLVD***	***SSE 1/8 - 1/4 (0.131 mi.)***	***L64***	***234***

HIST LTANKS: A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database.

A review of the HIST LTANKS list, as provided by EDR, and dated 01/01/2002 has revealed that there are 26 HIST LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FAMILY COURT BLDG Date Closed: 11/05/92	***1200 OLD COUNTRY ROAD***	***0 - 1/8 (0.000 mi.)***	***B8***	***57***
OFFICE BLDG Date Closed: 09/14/94	***1000 ZECKENDORF BLVD***	***0 - 1/8 (0.000 mi.)***	***C16***	***79***
NORTHVILLE GASOLINE CORP Date Closed: 01/06/89	***345 OLD COUNTRY ROAD***	***NNW 0 - 1/8 (0.008 mi.)***	***D27***	***100***
CANNON USA CORP Date Closed: 09/15/88	***1000 AXIN AVENUE***	***SSW 0 - 1/8 (0.104 mi.)***	***K51***	***194***
NY TELEPHONE Date Closed: 11/14/90	***741 ZECKENDORF***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M56***	***200***
PEPSI COLA Date Closed: 03/04/88	***800 EAST GATE BLVD***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M57***	***203***
BELL ATLANTIC Date Closed: 10/20/99	***741 ZECKENDORF BLVD***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M59***	***206***
NEW YORK TELEPHONE CO Date Closed: 10/21/88	***741 ZECKENDORF BLVD***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M61***	***211***
KATHY LALLY RESIDENCE Date Closed: 12/23/93	***339 CURTIS AVENUE***	***NNW 1/8 - 1/4 (0.148 mi.)***	***72***	***292***
MINEOLA FUEL Date Closed: 02/10/92	***14 GARDEN COURT***	***NNW 1/8 - 1/4 (0.177 mi.)***	***74***	***297***
MOBIL S/S Date Closed: 05/03/90	***640 OLD COUNTRY ROAD***	***WSW 1/4 - 1/2 (0.358 mi.)***	***Q83***	***328***
OUR LADY OF HOPE Date Closed: 09/15/89 Date Closed: 08/29/90	***CHERRY LANE / BROADWA***	***NNW 1/4 - 1/2 (0.363 mi.)***	***R84***	***335***
SOUZA RESIDENCE Date Closed: 02/18/92	***8 ROCKAWAY AVENUE***	***ENE 1/4 - 1/2 (0.373 mi.)***	***86***	***341***
EAB BANK Date Closed: 07/23/93	***600 OLD COUNTRY ROAD***	***WSW 1/4 - 1/2 (0.378 mi.)***	***Q87***	***343***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FANNI RESIDENCE	***84 BROADMOOR LANE***	***NE 1/4 - 1/2 (0.379 mi.)***	***88***	***346***
Date Closed: / /				
HUNTS POINT OIL	***ROOSEVELT FIELD SHOPPIN***	***WSW 1/4 - 1/2 (0.401 mi.)***	***89***	***349***
Date Closed: 03/26/91				
BELCHER FUEL OIL CO	***RUSHMORE AVE / WESTBU***	***NNW 1/4 - 1/2 (0.404 mi.)***	***90***	***351***
Date Closed: 07/29/91				
HESS STATION 32492	***500 WESTBURY AVE***	***NNW 1/4 - 1/2 (0.411 mi.)***	***R92***	***357***
Not reported	***300 WESTBURY AVENUE***	***NNW 1/4 - 1/2 (0.416 mi.)***	***93***	***372***
Date Closed: 10/28/97				
AMS STATIONERY	***520 WESTBURY AVENUE***	***N 1/4 - 1/2 (0.416 mi.)***	***94***	***374***
Date Closed: 04/06/93				
MICHAEL SKURNICK	***1400 OLD COUNTRY ROAD***	***ENE 1/4 - 1/2 (0.430 mi.)***	***95***	***377***
Date Closed: 04/21/97				

Lower Elevation	Address	Direction / Distance	Map ID	Page
PEPSI COLA CO	***867 EAST GATE BLVD***	***WSW 0 - 1/8 (0.008 mi.)***	***F23***	***92***
Date Closed: 02/20/91				
NATIONAL HELICOPTER	***NORTH AVE & E GATE***	***WSW 0 - 1/8 (0.008 mi.)***	***F28***	***103***
Date Closed: 11/25/87				
NATIONAL HELICOPTER	***NORTH AVENUE***	***WSW 0 - 1/8 (0.088 mi.)***	***I39***	***154***
Date Closed: 11/09/94				
GEORGIAN PRESS INC	***750 ZEKENDORF BLVD***	***SSE 1/8 - 1/4 (0.131 mi.)***	***L64***	***234***
Date Closed: 07/18/94				
GEORGIAN WEBB OFFSET CO	***750 ZECKENDORF BLVD***	***SSE 1/8 - 1/4 (0.131 mi.)***	***L67***	***237***
Date Closed: / /				

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the UST list, as provided by EDR, and dated 02/18/2010 has revealed that there are 17 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NC FAMILY COURT	1200 OLD COUNTRY RD	0 - 1/8 (0.000 mi.)	B11	72
N.C. FAMILY COURT COMPLEX	1200 OLD COUNTRY RD.	0 - 1/8 (0.000 mi.)	B14	75
INACTIVE - AVIS RENT A CAR	357 OLD COUNTRY RD	NNW 0 - 1/8 (0.003 mi.)	17	81
AMOCO - CARLE PLACE SERVICE ST	345 OLD COUNTRY ROAD	NNW 0 - 1/8 (0.004 mi.)	D18	82
INACTIVE	360 OLD COUNTRY RD	NNW 0 - 1/8 (0.004 mi.)	B19	89
COUNTRY PLAZA SHPNG. CTR.	373-401 OLD COUNTRY RD.	ENE 0 - 1/8 (0.047 mi.)	G34	146
EXXON #70230 DIVISION OF CFI	285 OLD COUNTRY RD	W 0 - 1/8 (0.091 mi.)	J41	160
EXXON #2634747	285 OLD COUNTRY RD.	W 0 - 1/8 (0.091 mi.)	J45	166
EXXON SERVICE STATION	***285 OLD COUNTRY ROAD***	***W 0 - 1/8 (0.091 mi.)***	***J49***	***175***
VERIZON INC.	741 ZECKENDORF BLVD	SSE 1/8 - 1/4 (0.130 mi.)	M60	211
COTUGNO, VICTOR	***10 BYRD AVE***	***W 1/8 - 1/4 (0.157 mi.)***	***73***	***297***
CARLE PLACE UFSD	CHERRY LA.	NNW 1/8 - 1/4 (0.245 mi.)	82	327

Lower Elevation	Address	Direction / Distance	Map ID	Page
PEPCOM INDUSTRIES	867 EAST GATE BLVD	WSW 0 - 1/8 (0.008 mi.)	F22	92
MEADOWBROOK DIST. CORP.	867 E. GATE BLVD.	WSW 0 - 1/8 (0.008 mi.)	F24	94
NATIONAL HELICOPTER CORP.	435 NORTH AVE	WSW 0 - 1/8 (0.088 mi.)	I40	159
FORTUNOFF CLEARANCE CENTER & P	750 ZECKENDORF BLVD	SSE 1/8 - 1/4 (0.131 mi.)	L65	236
ITT CONTINENTAL BAKING CO.	750 ZECKENDORF BLVD	SSE 1/8 - 1/4 (0.131 mi.)	L66	237

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the AST list, as provided by EDR, and dated 02/18/2010 has revealed that there are 15 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VERIZON GNI	1000 ZECKENDORF BLVD	0 - 1/8 (0.000 mi.)	C12	72
MAGNACARE / ELLIPSE BUILDING	825 EAST GATE BLVD	WSW 0 - 1/8 (0.009 mi.)	29	126
WAL-MART STORE# 3420	1220 OLD COUNTRY RD	ENE 0 - 1/8 (0.029 mi.)	B32	144
COSTCO WHOLESALE - STORE #226	1250 OLD COUNTRY RD	ENE 0 - 1/8 (0.074 mi.)	G36	149
EXXON SERVICE STATION	***285 OLD COUNTRY ROAD***	***W 0 - 1/8 (0.091 mi.)***	***J49***	***175***
FORTUNOFF'S	1000 AXINN AVE	SSW 0 - 1/8 (0.104 mi.)	K52	196
WINTHROP UNIV HOSP AMBULATORY	777 ZECKENDORF BLVD	SSE 0 - 1/8 (0.109 mi.)	53	197
VERIZON INC.	741 ZECKENDORF BLVD	SSE 1/8 - 1/4 (0.130 mi.)	M58	205
COTUGNO, VICTOR	***10 BYRD AVE***	***W 1/8 - 1/4 (0.157 mi.)***	***73***	***297***
FORTUNOFF	1300 OLD COUNTRY RD	ENE 1/8 - 1/4 (0.189 mi.)	O77	316
FORTUNOFF'S	1300 OLD COUNTRY RD	ENE 1/8 - 1/4 (0.189 mi.)	O78	316
PROGRESSIVE CASUALTY INS. CO.	1 AXINN AVE	SW 1/8 - 1/4 (0.204 mi.)	P80	325

Lower Elevation	Address	Direction / Distance	Map ID	Page
CENTURY FORKLIFT	172 F CABOT ST	SSE 1/8 - 1/4 (0.128 mi.)	L55	199
AAR AIRCRAFT COMP. SVCS.	747 ZECKENDORF BLVD.	SSE 1/8 - 1/4 (0.131 mi.)	L69	245
AAR TECHNICAL SERVICE CENTER	747 ZECKENDORF BLVD	SSE 1/8 - 1/4 (0.131 mi.)	L71	291

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/23/2010 has revealed that there are 15 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UNKNOWN Date Closed: 4/3/2006	1000 ZECKENDORF AVENUE	0 - 1/8 (0.000 mi.)	C9	60
LEVITZ FURNITURE Date Closed: 7/7/2003	895 EAST GATE BOULEVARD	WSW 0 - 1/8 (0.006 mi.)	E21	90
NORTHVILLE INDUSTRIES Date Closed: 11/10/1997	***345 OLD COUNTRY ROAD***	***NNW 0 - 1/8 (0.008 mi.)***	***D25***	***95***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CP S/S OPERATING CORP	***345 OLD COUNTRY ROAD***	***NNW 0 - 1/8 (0.008 mi.)***	***D26***	***97***
JOHN GRAYSON RESIDENCE	***14 MITCHEL AVENUE***	***NNW 0 - 1/8 (0.024 mi.)***	***30***	***126***
Date Closed: 5/16/1997				
UNKNOWN	1230 OLD COUNTRY ROAD	ENE 0 - 1/8 (0.045 mi.)	B33	145
Date Closed: 7/27/2005				
CARLE PLACE SCHOOL DISTRI	***16 CHERRY LANE***	***NNW 0 - 1/8 (0.068 mi.)***	***H35***	***147***
Date Closed: 8/7/1989				
COSTCO	***1250 OLD COUNTRY ROAD***	***ENE 0 - 1/8 (0.074 mi.)***	***G38***	***152***
Date Closed: 1/27/2004				
TOSCO REFINING	***285 OLD COUNTRY ROAD***	***W 0 - 1/8 (0.091 mi.)***	***J43***	***161***
Date Closed: 8/23/2005				
UNK	***285 OLD COUNTRY ROAD***	***W 0 - 1/8 (0.091 mi.)***	***J44***	***164***
Date Closed: 3/10/1995				
CUMBERLAND FARMS-EXXON	285 OLD COUNTRY ROAD	W 0 - 1/8 (0.091 mi.)	J47	168
RESIDENCE	***21 CHERRY LANE***	***NNW 0 - 1/8 (0.099 mi.)***	***H50***	***191***
Date Closed: 1/31/1994				
BLUM RESIDENCE	***100 ROOSEVELT PLACE***	***NNW 0 - 1/8 (0.124 mi.)***	***54***	***197***
Date Closed: 3/14/1995				

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL HELICOPTER	***NORTH AVE & E GATE***	***WSW 0 - 1/8 (0.008 mi.)***	***F28***	***103***
Date Closed: 6/1/2005				
NATIONAL HELICOPTER	***NORTH AVENUE***	***WSW 0 - 1/8 (0.088 mi.)***	***I39***	***154***
Date Closed: 9/8/1994				

NY Hist Spills: This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database.

A review of the NY Hist Spills list, as provided by EDR, and dated 01/01/2002 has revealed that there are 11 NY Hist Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NORTHVILLE INDUSTRIES	***345 OLD COUNTRY ROAD***	***NNW 0 - 1/8 (0.008 mi.)***	***D25***	***95***
CP S/S OPERATING CORP	***345 OLD COUNTRY ROAD***	***NNW 0 - 1/8 (0.008 mi.)***	***D26***	***97***
JOHN GRAYSON RESIDENCE	***14 MITCHEL AVENUE***	***NNW 0 - 1/8 (0.024 mi.)***	***30***	***126***
CARLE PLACE SCHOOL DISTRI	***16 CHERRY LANE***	***NNW 0 - 1/8 (0.068 mi.)***	***H35***	***147***
COSTCO	***1250 OLD COUNTRY ROAD***	***ENE 0 - 1/8 (0.074 mi.)***	***G38***	***152***
TOSCO REFINING	***285 OLD COUNTRY ROAD***	***W 0 - 1/8 (0.091 mi.)***	***J43***	***161***
UNK	***285 OLD COUNTRY ROAD***	***W 0 - 1/8 (0.091 mi.)***	***J44***	***164***
RESIDENCE	***21 CHERRY LANE***	***NNW 0 - 1/8 (0.099 mi.)***	***H50***	***191***
BLUM RESIDENCE	***100 ROOSEVELT PLACE***	***NNW 0 - 1/8 (0.124 mi.)***	***54***	***197***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL HELICOPTER	***NORTH AVE & E GATE***	***WSW 0 - 1/8 (0.008 mi.)***	***F28***	***103***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL HELICOPTER	*NORTH AVENUE*	*WSW 0 - 1/8 (0.088 mi.)*	*I39*	*154*

Other Ascertainable Records

RCRA-NonGen: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 01/13/2010 has revealed that there are 8 RCRA-NonGen sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROOSEVELT PARK RACEWAY	*ZECKENDORF BLVD & OLD C*	*0 - 1/8 (0.000 mi.)*	*B10*	*61*
NASSAU COUNTY OF FAMILY COURT	*1200 OLD COUNTRY RD*	*0 - 1/8 (0.000 mi.)*	*B13*	*72*
GREEN PACKAGING CORP	*1000 ZECKENDORF BLVD*	*0 - 1/8 (0.000 mi.)*	*C15*	*76*
PRICE CLUB 226	*1250 OLD COUNTRY RD*	*ENE 0 - 1/8 (0.074 mi.)*	*G37*	*149*
NEW YORK TELEPHONE CO	*741 ZECKENDORF BLVD*	*SSE 1/8 - 1/4 (0.130 mi.)*	*M61*	*211*
AT&T LONG LINES	*741 ZECKENDORF BLVD*	*SSE 1/8 - 1/4 (0.130 mi.)*	*M62*	*223*

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL HELICOPTER	*NORTH AVE & E GATE*	*WSW 0 - 1/8 (0.008 mi.)*	*F28*	*103*
FORTUNOFF	*750 ZECKENDORF BLVD*	*SSE 1/8 - 1/4 (0.131 mi.)*	*L68*	*239*

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 12/31/2008 has revealed that there are 2 FUDS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MITCHEL FIELD		NNE 1/4 - 1/2 (0.369 mi.)	85	340
ROOSEVELT FIELD		E 1/4 - 1/2 (0.452 mi.)	97	384

CONSENT: Major Legal settlements that establish responsibility and standards for cleanup at NPL (superfund) sites. Released periodically by U.S. District Courts after settlement by parties to litigation matters.

A review of the CONSENT list, as provided by EDR, and dated 08/03/2009 has revealed that there is 1 CONSENT site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PASLEY SOLVENTS & CHEMICALS, I	*585 COMMERICAL AVENUE*	*SSW 1/2 - 1 (0.813 mi.)*	*0*	*47*

EXECUTIVE SUMMARY

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 12/01/2009 has revealed that there are 2 ROD sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OLD ROOSEVELT FIELD CONTAMINAT	***CLINTON ROAD/OLD COUNTR***	***WSW 1/4 - 1/2 (0.461 mi.)***	***0***	***39***
PASLEY SOLVENTS & CHEMICALS, I	***585 COMMERICAL AVENUE***	***SSW 1/2 - 1 (0.813 mi.)***	***0***	***47***

MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the MANIFEST list, as provided by EDR, and dated 01/04/2010 has revealed that there are 14 MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROOSEVELT PARK RACEWAY	***ZECKENDORF BLVD & OLD C***	***0 - 1/8 (0.000 mi.)***	***B10***	***61***
NASSAU COUNTY OF FAMILY COURT	***1200 OLD COUNTRY RD***	***0 - 1/8 (0.000 mi.)***	***B13***	***72***
GREEN PACKAGING CORP	***1000 ZECKENDORF BLVD***	***0 - 1/8 (0.000 mi.)***	***C15***	***76***
LEVITZ FURNITURE	895 E GATE BOULEVARD	WSW 0 - 1/8 (0.006 mi.)	E20	89
WAL-MART #3420	***1220 OLD COUNTRY RD***	***ENE 0 - 1/8 (0.029 mi.)***	***B31***	***128***
PRICE CLUB 226	***1250 OLD COUNTRY RD***	***ENE 0 - 1/8 (0.074 mi.)***	***G37***	***149***
EXXON DIV OF CFI #70230	***285 OLD COUNTRY RD & LI***	***W 0 - 1/8 (0.091 mi.)***	***J48***	***169***
NEW YORK TELEPHONE CO	***741 ZECKENDORF BLVD***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M61***	***211***
VERIZON	***741 ZECKENDORF BLVD 1ST***	***SSE 1/8 - 1/4 (0.130 mi.)***	***M63***	***225***
TARGET #1139	***999 CORPORATE DR***	***ESE 1/8 - 1/4 (0.182 mi.)***	***N75***	***300***
H & R PARTS	***800 AXINN AVE***	***SW 1/8 - 1/4 (0.203 mi.)***	***P79***	***317***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL HELICOPTER	***NORTH AVE & E GATE***	***WSW 0 - 1/8 (0.008 mi.)***	***F28***	***103***
FORTUNOFF	***750 ZECKENDORF BLVD***	***SSE 1/8 - 1/4 (0.131 mi.)***	***L68***	***239***
AAR AIRCRAFT COMPONENT SERVICE	***747 ZECKENDORF BOULEVAR***	***SSE 1/8 - 1/4 (0.131 mi.)***	***L70***	***247***

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the Manufactured Gas Plants list, as provided by EDR, has revealed that there is 1 Manufactured Gas Plants site within approximately 1 mile of the target property.

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
GARDEN CITY - STEWART AVENUE H	600 STEWART AVE.	SSW 1/2 - 1 (0.762 mi.)	98	385

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
TISHCON CORPORATION	SHWS, VAPOR REOPENED
89 FROST STREET SITE	SHWS, VAPOR REOPENED
FORMER APPLIED FLUIDICS	SHWS, VAPOR REOPENED
EZ-EM, INC.	SHWS, VAPOR REOPENED
WELL #8, #12 G.C. GOLF CLUB	CBS
COMMUNITY PARK POOL	CBS
WELL 13 & 14 G.C. COUNTRY CLUB	CBS
WESTBURY WATER DISTRICT	CBS UST, AST, CBS
MEADOWBROOK STATE PKY	RCRA-NonGen, FINDS, MANIFEST
AVIS CAR LEASING	MANIFEST
CHERRY VALLEY AVENUE OF 1ST ST	RCRA-NonGen, FINDS, MANIFEST
CHERRY VALLEY AVE	RCRA-NonGen, FINDS, MANIFEST
E GATE BLVD & CORPORATE DR	RCRA-NonGen, FINDS, MANIFEST
1100 ROOSEVELT FIELD MALL	RCRA-NonGen, FINDS, MANIFEST
WOOLWORTH	MANIFEST
CARLE PLACE UFSD - CARLE PLACE HIG	MANIFEST
OLD COUNTY RD E & O WASHINGTON	RCRA-NonGen, MANIFEST
NYSDOT	MANIFEST
NYNEX	MANIFEST
EXXON CO USA 31763	MANIFEST
EXXON DIV OF CFI #70321	MANIFEST
OLD ROOSEVELT AIR FIELD HANGAR SIT	SHWS
K - INTERSECTION ST. - HEMPSTEAD M	SHWS
MOHAWK VALLEY ORGANICS	SWF/LF
MINEOLA C & D	SWF/LF
ROOSEVELT RACEWAY LANDFILL	SWF/LF
US NAVY FACILITY	LTANKS, HIST LTANKS
US NAVY	LTANKS, HIST LTANKS
OLD COUNTRY RD	LTANKS, HIST LTANKS, NY Spills, NY Hist Spills
INACTIVE - NYS DOT	UST
MEADOWBROOK E.S.	UST
GARDEN CITY SERVICE YARD	UST
GC UFSD BUS GARAGE	UST
INACTIVE - GULF	UST
OLD WESTBURY WATER WELL #2	UST, AST
VILLAGE OF OLD WESTBURY - PLANT #4	UST, AST
INACTIVE	UST
INACTIVE - SHELL	UST
FDM CORPORATION	UST
WESTBURY WATER DISTRICT	UST
MACY'S #53	AST
NORDSTROM	AST
MINEOLA INC VILLAGE - EMORY ROAD B	AST
MINEOLA WATER PUMPHOUSE # 4	AST
SCHWALM, JOHN	AST
MIKE'S OF GARDEN CITY	AST
NYSDOT BIN 1523680	RCRA-LQG
NYSDOT BIN 1058101	RCRA-NonGen
VERIZON MANHOLE 21	RCRA-NonGen
50 ROSLYN ROAD	HMIRS
NEW CASSEL INDUSTRIAL AREA	DEL SHWS
UNK "VEHICLE"	NY Spills, NY Hist Spills
LILCO	NY Spills, NY Hist Spills
LILCO	NY Spills, NY Hist Spills
JD PACILICO	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills

ELECTRIC LINE TRUCK	NY Spills
GLEN COVE ROAD 1/4 MI SO	NY Spills, NY Hist Spills
LILCO	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
LILCO	NY Spills
EXXON S/S	NY Spills, NY Hist Spills
GREEN RESIDENCE	NY Spills, NY Hist Spills
SPENO PARK	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
NEWBRIDGE ROAD SUB STAT	NY Spills, NY Hist Spills
UNKNOWN	NY Spills
UNK	NY Spills, NY Hist Spills
CHERRY VALLEY AVE & CROSS	NY Spills, NY Hist Spills
A Z RUBBISH REMOVAL CO	NY Spills, NY Hist Spills
MUNICIPAL SERVICE YARD-VILLAGE OF	NY Spills
PEPSI PLANT	NY Spills, NY Hist Spills
LILCO	NY Spills, NY Hist Spills
GARDEN CITY TRANSPORT CO	NY Spills, NY Hist Spills
STERNS DEPARTMENT STORE	NY Spills, NY Hist Spills
DATER CONSTRUCTION	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
ROOSEVELT FIELD MALL	NY Spills
ROOSEVELT FIELD SHOPPING MALL	NY Spills
UNK	NY Spills, NY Hist Spills
MONTENAY POWER COMPANY	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
KIRCHNER RESIDENCE	NY Spills, NY Hist Spills
ON THE ROAD WAY	NY Spills
FORMER GAS STATION	NY Spills, NY Hist Spills
OLD COUNTRY RD & FRANKLIN A	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
UNK	NY Spills, NY Hist Spills
OLD COUNTRY RD	NY Spills
7 ANGEL PRODUCE COMPANY	NY Spills, NY Hist Spills
OLD COUNTRY RD & GRAYSTONE	NY Spills
STEWART DIAMOND QUICK PHO	NY Spills, NY Hist Spills
449 OLD COUNTRY RD	NY Spills, NY Hist Spills
UNKNOWN	NY Spills
UNK	NY Spills, NY Hist Spills
OLD ROOSEVELT FIELD CONTAMINATED G	ICIS
530 HICKSVILLE ROAD - WINTHROP UNI	ICIS
264 OLD COUNTRY ROAD - WINTHROP UN	ICIS

OVERVIEW MAP - 2735789.4s



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Power transmission lines

Oil & Gas pipelines

100-year flood zone

500-year flood zone

National Wetland Inventory

State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 900 Old Country Road	CLIENT: Roux Associates
ADDRESS: 900 Old Country Road Garden City NY 11530	CONTACT: Wendy Monterosso
LAT/LONG: 40.7441 / 73.6055	INQUIRY #: 2735789.4s DATE: April 05, 2010 2:04 pm

Copyright © 2010 EDR, Inc. © 2010 Tele Atlas Rel. 07/2007.

DETAIL MAP - 2735789.4s



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 900 Old Country Road	CLIENT: Roux Associates
ADDRESS: 900 Old Country Road Garden City NY 11530	CONTACT: Wendy Monterosso INQUIRY #: 2735789.4s
LAT/LONG: 40.7441 / 73.6055	DATE: April 05, 2010 2:04 pm

Copyright © 2010 EDR, Inc. © 2010 Tele Atlas Rel. 07/2007.

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL		1.000	0	0	1	1	NR	2
Proposed NPL		1.000	0	0	0	0	NR	0
NPL LIENS		TP	NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL		1.000	0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS		0.500	0	0	1	NR	NR	1
FEDERAL FACILITY		1.000	0	0	0	0	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP		0.500	0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS		1.000	0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF		0.500	0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG		0.250	0	1	NR	NR	NR	1
RCRA-SQG		0.250	0	0	NR	NR	NR	0
RCRA-CESQG	X	0.250	2	3	NR	NR	NR	5
Federal institutional controls / engineering controls registries								
US ENG CONTROLS		0.500	0	0	1	NR	NR	1
US INST CONTROL		0.500	0	0	1	NR	NR	1
Federal ERNS list								
ERNS		TP	NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
SHWS		1.000	0	0	1	4	NR	5
VAPOR REOPENED		1.000	0	0	0	2	NR	2
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF		0.500	0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
LTANKS	X	0.500	7	9	11	NR	NR	27
HIST LTANKS	X	0.500	7	8	11	NR	NR	26
INDIAN LUST		0.500	0	0	0	NR	NR	0
State and tribal registered storage tank lists								
UST	X	0.250	12	5	NR	NR	NR	17

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CBS UST		0.250	0	0	NR	NR	NR	0
MOSF UST		0.500	0	0	0	NR	NR	0
AST		0.250	7	8	NR	NR	NR	15
CBS AST		0.250	0	0	NR	NR	NR	0
MOSF AST		0.500	0	0	0	NR	NR	0
MOSF		0.500	0	0	0	NR	NR	0
CBS		0.250	0	0	NR	NR	NR	0
INDIAN UST		0.250	0	0	NR	NR	NR	0
FEMA UST		0.250	0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
ENG CONTROLS		0.500	0	0	0	NR	NR	0
INST CONTROL		0.500	0	0	0	NR	NR	0
RES DECL		0.125	0	NR	NR	NR	NR	0
State and tribal voluntary cleanup sites								
INDIAN VCP		0.500	0	0	0	NR	NR	0
VCP		0.500	0	0	0	NR	NR	0
State and tribal Brownfields sites								
ERP		0.500	0	0	0	NR	NR	0
BROWNFIELDS		0.500	0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
ODI		0.500	0	0	0	NR	NR	0
DEBRIS REGION 9		0.500	0	0	0	NR	NR	0
SWTIRE		0.500	0	0	0	NR	NR	0
SWRCY		0.500	0	0	0	NR	NR	0
INDIAN ODI		0.500	0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL		TP	NR	NR	NR	NR	NR	0
DEL SHWS		1.000	0	0	0	0	NR	0
US HIST CDL		TP	NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
HIST UST		0.250	0	0	NR	NR	NR	0
HIST AST		TP	NR	NR	NR	NR	NR	0
Local Land Records								
LIENS 2		TP	NR	NR	NR	NR	NR	0
LUCIS		0.500	0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Records of Emergency Release Reports								
HMIRS		TP	NR	NR	NR	NR	NR	0
NY Spills		0.125	15	NR	NR	NR	NR	15
NY Hist Spills		0.125	11	NR	NR	NR	NR	11
Other Ascertainable Records								
RCRA-NonGen	X	0.250	5	3	NR	NR	NR	8
DOT OPS		TP	NR	NR	NR	NR	NR	0
DOD		1.000	0	0	0	0	NR	0
FUDS		1.000	0	0	2	0	NR	2
CONSENT		1.000	0	0	0	1	NR	1
ROD		1.000	0	0	1	1	NR	2
UMTRA		0.500	0	0	0	NR	NR	0
MINES		0.250	0	0	NR	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
FTTS		TP	NR	NR	NR	NR	NR	0
HIST FTTS		TP	NR	NR	NR	NR	NR	0
SSTS		TP	NR	NR	NR	NR	NR	0
ICIS		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
MLTS		TP	NR	NR	NR	NR	NR	0
RADINFO		TP	NR	NR	NR	NR	NR	0
FINDS	X	TP	NR	NR	NR	NR	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
HSWDS		0.500	0	0	0	NR	NR	0
MANIFEST	X	0.250	10	6	NR	NR	NR	16
DRYCLEANERS		0.250	0	0	NR	NR	NR	0
NPDES		TP	NR	NR	NR	NR	NR	0
AIRS		TP	NR	NR	NR	NR	NR	0
E DESIGNATION		0.125	0	NR	NR	NR	NR	0
INDIAN RESERV		1.000	0	0	0	0	NR	0
SCRD DRYCLEANERS		0.500	0	0	0	NR	NR	0
COAL ASH DOE		TP	NR	NR	NR	NR	NR	0
PCB TRANSFORMER		TP	NR	NR	NR	NR	NR	0
COAL ASH EPA		0.500	0	0	0	NR	NR	0
COAL ASH		0.500	0	0	0	NR	NR	0
FINANCIAL ASSURANCE		TP	NR	NR	NR	NR	NR	0
EDR PROPRIETARY RECORDS								
EDR Proprietary Records								
Manufactured Gas Plants		1.000	0	0	0	1	NR	1

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target
Property

AVIS CAR RENTAL
900 OLD COUNTRY RD
GARDEN CITY, NY 11530

Site 1 of 7 in cluster A

RCRA-CESQG 1000375639
FINDS NYD001954387
LTANKS
HIST LTANKS
MANIFEST

Actual:
85 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	AVIS CAR RENTAL
Facility address:	900 OLD COUNTRY RD GARDEN CITY, NY 11530
EPA ID:	NYD001954387
Mailing address:	OLD COUNTRY RD GARDEN CITY, NY 11530
Contact:	FRED ARDIS
Contact address:	OLD COUNTRY RD GARDEN CITY, NY 11530
Contact country:	US
Contact telephone:	(516) 222-3947
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	AVIS CAR RENTAL
Owner/operator address:	OLD COUNTRY RD GARDEN CITY, NY 11530
Owner/operator country:	US
Owner/operator telephone:	(516) 222-3947
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Owner/operator name:	AVIS CAR RENTAL
Owner/operator address:	OLD COUNTRY RD GARDEN CITY, NY 11530
Owner/operator country:	US
Owner/operator telephone:	(516) 222-3947
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

AVIS CAR RENTAL (Continued) **1000375639**

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: AVIS CAR RENTAL
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/26/2004
Facility name: AVIS CAR RENTAL
Classification: Small Quantity Generator

Date form received by agency: 07/08/1999
Facility name: AVIS CAR RENTAL
Site name: AVIS RENT A CAR
Classification: Not a generator, verified

Date form received by agency: 12/04/1986
Facility name: AVIS CAR RENTAL
Site name: AVIS RENT A CAR
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004336282

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AVIS CAR RENTAL (Continued) **1000375639**

LTANKS:

Site ID:	169953
Spill No:	8707057
Spill Date:	11/18/1987
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Spill Closed Dt:	8/22/1988
Facility Addr2:	Not reported
Cleanup Ceased:	8/22/1988
Cleanup Meets Standard:	True
SWIS:	3020
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	11/18/1987
CID:	04
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	11/24/1987
Spill Record Last Update:	9/20/2006
Spiller Name:	Not reported
Spiller Company:	AVIS RENT A CAR
Spiller Address:	900 OLD COUNTRY ROAD
Spiller City,St,Zip:	GARDEN CITY, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	143001
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GOERTZ FD" / / : FM ORDERED TO HAVE TANK PUMPED OUT. F&N TESTER. TANKS PUMPED OUT 11/18/87. 08/22/88: ALL TANKS WERE REMOVED BY TYREE. 270 YDS REMOVED.WATER SAMPLES WERE TAKEN & CAME BACK CLEAN. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	1-1K 1-4K 4K GROSS LEAK COULDN'T HOLD PRODUCT (TOP LEAK) 1K BOTTOM LEAK

Material:

Site ID:	169953
Operable Unit ID:	910938
Operable Unit:	01
Material ID:	466036
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

AVIS CAR RENTAL (Continued) **1000375639**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:
Region of Spill: 1
Spill Number: 8707057
Spill Date: 11/18/1987
Spill Time: 11:00
Spill Cause: Tank Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 08/22/88
Cleanup Ceased: 08/22/88
Cleanup Meets Standard: True
Investigator: GOERTZ FD
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 11/18/87
Reported to Department Time: 13:26
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: AVIS RENT A CAR
Spiller Address: 900 OLD COUNTRY ROAD
Spiller City,St,Zip: GARDEN CITY, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Fire Department
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /

AVIS CAR RENTAL (Continued) **1000375639**

UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 11/24/87
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 03/08/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: / / : FM ORDERED TO HAVE TANK PUMPED OUT. F N TESTER. TANKS PUMPED OUT 11/18/87. 08/22/88: ALL TANKS WERE REMOVED BY TYREE. 270 YDS REMOVED.WATER SAMPLES WERE TAKEN CAME BACK CLEAN.
Spill Cause: 1-1K 1-4K 4K GROSS LEAK COULDN T HOLD PRODUCT TOP LEAK) 1K BOTTOM LEAK

NY MANIFEST:
EPA ID: NYD001954387
Country: USA
Mailing Name: AVIS RENT A CAR
Mailing Contact: AVIS RENT A CAR
Mailing Address: 900 OLD COUNTRY ROAD
Mailing Address 2: Not reported
Mailing City: GARDEN CITY
Mailing State: NY
Mailing Zip: 11530
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 516-222-4260

Document ID: NYB2286414
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: GE9561
Trans2 State ID: Not reported
Generator Ship Date: 910510
Trans1 Recv Date: 910510
Trans2 Recv Date: Not reported
TSD Site Recv Date: 910510
Part A Recv Date: 910813

AVIS CAR RENTAL (Continued) **1000375639**

Part B Recv Date:	910524
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00025
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB4267494
Manifest Status:	Completed copy
Trans1 State ID:	PD9938
Trans2 State ID:	Not reported
Generator Ship Date:	940408
Trans1 Recv Date:	940408
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940408
Part A Recv Date:	940420
Part B Recv Date:	940419
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	020
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	123
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported

AVIS CAR RENTAL (Continued) **1000375639**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB5665905
Manifest Status:	Completed copy
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	920228
Trans1 Recv Date:	920228
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920228
Part A Recv Date:	Not reported
Part B Recv Date:	920318
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB4267656
Manifest Status:	Completed copy
Trans1 State ID:	PD9938
Trans2 State ID:	Not reported
Generator Ship Date:	940414
Trans1 Recv Date:	940414
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940414
Part A Recv Date:	940505
Part B Recv Date:	940425
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D008 - LEAD 5.0 MG/L TCLP

AVIS CAR RENTAL (Continued) **1000375639**

Quantity:	01045
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	019
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	123
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB6934536
Manifest Status:	Completed copy
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	950323
Trans1 Recv Date:	950323
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950323
Part A Recv Date:	Not reported
Part B Recv Date:	950412
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

AVIS CAR RENTAL (Continued) **1000375639**

Document ID:	NYB5385213
Manifest Status:	Completed copy
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	930604
Trans1 Recv Date:	930604
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	930604
Part A Recv Date:	Not reported
Part B Recv Date:	930621
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	93
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	PAH0037642
Manifest Status:	Not reported
Trans1 State ID:	PAAH0682
Trans2 State ID:	PAAH0176
Generator Ship Date:	12/01/2004
Trans1 Recv Date:	12/01/2004
Trans2 Recv Date:	12/02/2004
TSD Site Recv Date:	12/03/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	PAR000501577
Trans2 EPA ID:	Not reported
TSDF ID:	PAD067098
Waste Code:	U121 - TRICHLOROMONOFLUOROMETHANE
Quantity:	00040
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

AVIS CAR RENTAL (Continued) **1000375639**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00006
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00225
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	04
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	PAH0037642
Manifest Status:	Not reported
Trans1 State ID:	PAAH0682
Trans2 State ID:	PAAH0176
Generator Ship Date:	12/01/2004
Trans1 Recv Date:	12/01/2004
Trans2 Recv Date:	12/02/2004
TSD Site Recv Date:	12/03/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	PAR000501577
Trans2 EPA ID:	Not reported
TSDF ID:	PAD067098
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	01.00

AVIS CAR RENTAL (Continued) **1000375639**

Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00027
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	01.00
Year:	04
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB4267674
Manifest Status:	Completed copy
Trans1 State ID:	PD9938
Trans2 State ID:	Not reported
Generator Ship Date:	940411
Trans1 Recv Date:	940411
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940411
Part A Recv Date:	940420
Part B Recv Date:	940420
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	01100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	020
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	123
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

AVIS CAR RENTAL (Continued) **1000375639**

Document ID:	NYB5595642
Manifest Status:	Completed copy
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	920710
Trans1 Recv Date:	920710
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920710
Part A Recv Date:	Not reported
Part B Recv Date:	920728
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA3212864
Manifest Status:	Completed copy
Trans1 State ID:	V30452NY
Trans2 State ID:	Not reported
Generator Ship Date:	870211
Trans1 Recv Date:	870211
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870213
Part A Recv Date:	870219
Part B Recv Date:	870228
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD049836679
Trans2 EPA ID:	NYD980769947
TSDF ID:	NYD049836679
Waste Code:	B005 - PCB ARTICLES WITH 500 PPM OR > PCB
Quantity:	01385
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

AVIS CAR RENTAL (Continued) **1000375639**

Year:	87
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB5668083
Manifest Status:	Completed copy
Trans1 State ID:	XC2643
Trans2 State ID:	Not reported
Generator Ship Date:	920827
Trans1 Recv Date:	920827
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920827
Part A Recv Date:	Not reported
Part B Recv Date:	920918
Generator EPA ID:	NYD001954387
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00025
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	92
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

A2 **AVIS RENT A CAR SYS.** **UST** **U003376732**
Target **900 OLD COUNTRY RD.** **N/A**
Property **GARDEN CITY, NY**

Site 2 of 7 in cluster A

Actual:
85 ft.

NASSAU CO. UST:

Facility ID:	037024
Owner Name:	SIMON PROPERTY GROUP
Owner Address:	115 WEST WASHINGTON ST.
Owner City,St,Zip:	INDIANAPOLIS, IN 46204
Permitee Name:	SIMON PROPERTY GROUP
Permitee Address:	115 WEST WASHINGTON ST.
Permitee City,St,Zip:	INDIANAPOLIS, IN 46204
Tank ID:	0005
Tank Location:	Indoors, Belowground
Capacity (Gal):	00020000
Tank Status:	In Service
Tank Material:	Fiberglass Reinforced Plastic
Int Protection:	None
Ext Protection:	FIBERGLASS REINFORCED PLASTIC
Piping Type:	Double Walled Fiberglass
Material Type:	Fresh/Product
Description:	OIL, FUEL #6
Leak Detect:	ELECTRONIC
Containment:	DOUBLE WALL TANK
Product Gauge:	Yes
Dispense Method:	Suction
Fill Type:	Pumped
Install Date:	101988

A3 **ANACOMP CORP.** **MANIFEST** **S109783447**
Target **900 OLD COUNTRY ROAD** **N/A**
Property **GARDEN CITY, NY 11530**

Site 3 of 7 in cluster A

Actual:
85 ft.

CT MANIFEST:

Manifest No:	CTF0500771
Waste Occurence:	1
UNNA:	3082
Hazard Class:	9
US Dot Description:	RQ HAZARDOUS WASTE, LIQUID, N.O.S.
No of Containers:	001
Container Type:	DM
Quantity:	508
Weight/Volume:	P
Additional Description:	Not reported
Handling Code:	Not reported
Date Record Was Last Modified:	4/26/2004
DEO Who Last Modified Record:	IG
Manifest No:	CTF0500771
Waste Occurence:	1
EPA Waste Code:	D011
Recycled Waste?:	F
Date Record Was Last Modified:	4/26/2004
DEO Who Last Modified Record:	IG
Year:	1997
Manifest ID:	CTF0500771

ANACOMP CORP. (Continued) **S109783447**

TSDF EPA ID:	CTD001156009
TSDF Name:	SAFETY-KLEEN CORP.
TSDF Address:	39 COMMUNITY AVE EXT.
TSDF City,St,Zip:	PLAINFIELD, CT 06374
TSDF Country:	USA
TSDF Telephone:	Not reported
Transport Date:	3/14/1997
Transporter EPA ID:	ILD984908202
Transporter Name:	SAFETY-KLEEN CORP.
Transporter Country:	USA
Transporter Phone:	Not reported
Trans 2 Date:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
Trans 2 Address:	Not reported
Trans 2 City,St,Zip:	CT
Trans 2 Country:	USA
Trans 2 Phone:	Not reported
EPA ID:	NYD101195709
Gererator Phone:	5162223165
Generator Mailing Addr:	900 OLD COUNTRY RD
Generator Mailing Town:	GARDEN CITY
Generator Mailing State:	NY
Generator Mailing Zip:	11530
Generator Mailing Country:	USA
Special Handling:	Not reported
Discrepancies:	Not reported
Date Shipped:	3/14/1997
Date Received:	3/17/1997
Last modified date:	4/26/2004
Last modified by:	IG
Comments:	Not reported

A4 **AVIS RENT A CAR SYSTEM, INC.** **UST** **U003845170**
Target **900 OLD COUNTRY RD** **N/A**
Property **EAST GARDEN CITY, NY 11530**

Site 4 of 7 in cluster A

Actual:
85 ft.

NCFM UST:

Tank Type:	OUTDOOR UG HOR STEEL
Tank Size:	1000
Tank Contents:	#2 FUEL OIL
Tank Type:	OUTDOOR UG HOR STEEL
Tank Size:	4000
Tank Contents:	#2 FUEL OIL
Tank Type:	OUTDOOR UG HOR D/W F/G
Tank Size:	4000
Tank Contents:	DIESEL
Tank Type:	OUTDOOR UG HOR D/W F/G
Tank Size:	4000
Tank Contents:	DIESEL

A5 Target Property | **ANACOMP MICRO GRAPHICS INC**
900 OLD COUNTRY RD
GARDEN CITY, NY 11530

RCRA-NonGen
FINDS
MANIFEST

1000179585
NYD101195709

Site 5 of 7 in cluster A

Actual: 85 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	ANACOMP MICRO GRAPHICS INC
Facility address:	900 OLD COUNTRY RD GARDEN CITY, NY 115302128
EPA ID:	NYD101195709
Mailing address:	OLD COUNTRY RD GARDEN CITY, NY 11530
Contact:	Not reported
Contact address:	OLD COUNTRY RD GARDEN CITY, NY 11530
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ANACOMP MICRO GRAPHICS INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ANACOMP MICRO GRAPHICS INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Unknown
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ANACOMP MICRO GRAPHICS INC
Classification: Not a generator, verified

Date form received by agency: 06/07/2000
Facility name: ANACOMP MICRO GRAPHICS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ANACOMP MICRO GRAPHICS INC
Classification: Not a generator, verified

Date form received by agency: 03/01/1990
Facility name: ANACOMP MICRO GRAPHICS INC
Site name: ANACOMP MICRO GRAPHICS, INC.
Classification: Large Quantity Generator

Date form received by agency: 06/02/1987
Facility name: ANACOMP MICRO GRAPHICS INC
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/10/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009469404

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD101195709
Country: USA
Mailing Name: ANACOMP MICRO GRAPHICS INC.
Mailing Contact: ANACOMP MICRO GRAPHICS INC.

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Mailing Address:	900 OLD COUNTRY ROAD
Mailing Address 2:	Not reported
Mailing City:	GARDEN CITY
Mailing State:	NY
Mailing Zip:	11530
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	516-222-4158

Document ID:	CTF0499241
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYES9459
Trans2 State ID:	Not reported
Generator Ship Date:	961118
Trans1 Recv Date:	961118
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	961202
Part A Recv Date:	961204
Part B Recv Date:	961219
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	CTD001156009
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	01016
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	96
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7177437
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890508
Trans1 Recv Date:	890508
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890508
Part A Recv Date:	890510
Part B Recv Date:	890517
Generator EPA ID:	NYD101195709

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7128612
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890201
Trans1 Recv Date:	890201
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890201
Part A Recv Date:	890208
Part B Recv Date:	890208
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2042901
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	901217
Trans1 Recv Date:	901217
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	901217
Part A Recv Date:	910114
Part B Recv Date:	910118
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1296756
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900502
Trans1 Recv Date:	900502
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900502
Part A Recv Date:	900619
Part B Recv Date:	900510
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1600956
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900622
Trans1 Recv Date:	900622
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900622
Part A Recv Date:	900816
Part B Recv Date:	900628
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1339695
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900705
Trans1 Recv Date:	900705
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900705
Part A Recv Date:	900808
Part B Recv Date:	900723
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1340172
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900716
Trans1 Recv Date:	900716
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900716
Part A Recv Date:	900815
Part B Recv Date:	900803
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2030031
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900914
Trans1 Recv Date:	900914
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900914
Part A Recv Date:	901005
Part B Recv Date:	900921
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1341405
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900803
Trans1 Recv Date:	900803
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900803

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Part A Recv Date:	900911
Part B Recv Date:	900821
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1246833
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	GE9561
Trans2 State ID:	Not reported
Generator Ship Date:	910117
Trans1 Recv Date:	910117
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910117
Part A Recv Date:	910201
Part B Recv Date:	910215
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA8119917
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890829
Trans1 Recv Date:	890829
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890829
Part A Recv Date:	890831
Part B Recv Date:	890906
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA8177832
Manifest Status:	Completed copy
Trans1 State ID:	NK2731
Trans2 State ID:	Not reported
Generator Ship Date:	891013
Trans1 Recv Date:	891013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891013
Part A Recv Date:	891018
Part B Recv Date:	891025
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00135
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA8117739
Manifest Status:	Completed copy
Trans1 State ID:	NK2731
Trans2 State ID:	Not reported
Generator Ship Date:	891003
Trans1 Recv Date:	891003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891003
Part A Recv Date:	891013
Part B Recv Date:	891013
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Document ID:	NYA8177859
Manifest Status:	Completed copy
Trans1 State ID:	NK2731
Trans2 State ID:	Not reported
Generator Ship Date:	891017
Trans1 Recv Date:	891017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891017
Part A Recv Date:	891025
Part B Recv Date:	891025
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00085
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7069815
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890719
Trans1 Recv Date:	890719
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890719
Part A Recv Date:	890725
Part B Recv Date:	890725
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7055217
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890328
Trans1 Recv Date:	890328
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890328
Part A Recv Date:	890510
Part B Recv Date:	890404
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7069176
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890711
Trans1 Recv Date:	890711

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890711
Part A Recv Date:	890714
Part B Recv Date:	890719
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00090
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7070391
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890726
Trans1 Recv Date:	890726
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890726
Part A Recv Date:	890801
Part B Recv Date:	890802
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported

ANACOMP MICRO GRAPHICS INC (Continued) **1000179585**

Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7178436
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890620
Trans1 Recv Date:	890620
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890622
Part A Recv Date:	890623
Part B Recv Date:	890627
Generator EPA ID:	NYD101195709
Trans1 EPA ID:	NYD981182769
Trans2 EPA ID:	Not reported
TSDF ID:	NYD981182769
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Click this hyperlink while viewing on your computer to access
57 additional NY_MANIFEST: record(s) in the EDR Site Report.

A6 **ANACOMP CORP** **MANIFEST** **S109783446**
Target **900 OLD COUNTRY ROAD** **N/A**
Property **GARDEN CITY, NY 11530**

Site 6 of 7 in cluster A

Actual:
85 ft.

CT MANIFEST:

Manifest No:	CTF0499038
Waste Occurence:	1
UNNA:	3082
Hazard Class:	9

ANACOMP CORP (Continued) **S109783446**

US Dot Description:	RQ HAZARDOUS WASTE, LIQUID, N.O.S.
No of Containers:	002
Container Type:	DF
Quantity:	1016
Weight/Volume:	P
Additional Description:	Not reported
Handling Code:	Not reported
Date Record Was Last Modified:	4/26/2004
DEO Who Last Modified Record:	IG
Manifest No:	CTF0499038
Waste Occurence:	1
EPA Waste Code:	D011
Recycled Waste?:	F
Date Record Was Last Modified:	4/26/2004
DEO Who Last Modified Record:	IG
Year:	1996
Manifest ID:	CTF0499241
TSDF EPA ID:	CTD001156009
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Address:	39 COMMUNITY AVE EXT.
TSDF City,St,Zip:	PLAINFIELD, CT 06374
TSDF Country:	USA
TSDF Telephone:	Not reported
Transport Date:	11/18/1996
Transporter EPA ID:	ILD984908202
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Transporter Country:	USA
Transporter Phone:	Not reported
Trans 2 Date:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
Trans 2 Address:	Not reported
Trans 2 City,St,Zip:	CT
Trans 2 Country:	USA
Trans 2 Phone:	Not reported
EPA ID:	NYD101195709
Gererator Phone:	5162223165
Generator Mailing Addr:	900 OLD COUNTRY RD
Generator Mailing Town:	GARDEN CITY
Generator Mailing State:	NY
Generator Mailing Zip:	11530
Generator Mailing Country:	USA
Special Handling:	Not reported
Discrepancies:	Not reported
Date Shipped:	11/18/1996
Date Received:	12/2/1996
Last modified date:	4/26/2004
Last modified by:	IG
Comments:	Not reported
Year:	1996
Manifest ID:	CTF0499038
TSDF EPA ID:	CTD001156009
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Address:	39 COMMUNITY AVE EXT.
TSDF City,St,Zip:	PLAINFIELD, CT 06374
TSDF Country:	USA
TSDF Telephone:	Not reported

ANACOMP CORP (Continued) **S109783446**

Transport Date:	10/1/1996
Transporter EPA ID:	ILD984908202
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Transporter Country:	USA
Transporter Phone:	Not reported
Trans 2 Date:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
Trans 2 Address:	Not reported
Trans 2 City,St,Zip:	CT
Trans 2 Country:	USA
Trans 2 Phone:	Not reported
EPA ID:	NYD101195709
Gererator Phone:	5162223165
Generator Mailing Addr:	900 OLD COUNTRY RD
Generator Mailing Town:	GARDEN CITY
Generator Mailing State:	NY
Generator Mailing Zip:	11530
Generator Mailing Country:	USA
Special Handling:	Not reported
Discrepancies:	Not reported
Date Shipped:	10/1/1996
Date Received:	10/10/1996
Last modified date:	4/26/2004
Last modified by:	IG
Comments:	Not reported

A7 **AVIS RENTAL** **MANIFEST** **S109736138**
Target **900 OLD COUNTRY RD** **N/A**
Property **GARDEN CITY, CT 11530**

Site 7 of 7 in cluster A

Actual:
85 ft.

CT MANIFEST:

Manifest No:	CTB0060387
Waste Occurence:	1
UNNA:	1993
Hazard Class:	FLAMMABLE
US Dot Description:	WASTE FLAMMABLE LIQUID, NOS
No of Containers:	001
Container Type:	TT
Quantity:	400
Weight/Volume:	G
Additional Description:	Y
Handling Code:	T50
Date Record Was Last Modified:	4/27/2004
DEO Who Last Modified Record:	IG
Manifest No:	CTB0060387
Waste Occurence:	1
EPA Waste Code:	D001
Recycled Waste?:	F
Date Record Was Last Modified:	4/27/2004
DEO Who Last Modified Record:	IG
Year:	1987
Manifest ID:	CTB0060387
TSDF EPA ID:	CTD021816889
TSDF Name:	UNITED WASTE OIL CO INC
TSDF Address:	136 GRACEY AVE

AVIS RENTAL (Continued) **S109736138**

TSDF City,St,Zip:	MERIDEN, CT 06450
TSDF Country:	USA
TSDF Telephone:	Not reported
Transport Date:	3/3/1987
Transporter EPA ID:	CTD981065758
Transporter Name:	EVER CLEAR ENVIRONMENTAL SERVICE INC
Transporter Country:	USA
Transporter Phone:	Not reported
Trans 2 Date:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
Trans 2 Address:	Not reported
Trans 2 City,St,Zip:	CT
Trans 2 Country:	USA
Trans 2 Phone:	Not reported
EPA ID:	CTP000006059
Gererator Phone:	5162223780
Generator Mailing Addr:	900 OLD COUNTRY RD
Generator Mailing Town:	GARDEN CITY
Generator Mailing State:	NY
Generator Mailing Zip:	11530
Generator Mailing Country:	USA
Special Handling:	No
Discrepancies:	No
Date Shipped:	3/3/1987
Date Received:	3/3/1987
Last modified date:	4/27/2004
Last modified by:	IG
Comments:	Not reported

NPL **OLD ROOSEVELT FIELD CONTAMINATED GW AREA** **NPL** **1001814341**
Region **CLINTON ROAD/OLD COUNTRY ROAD** **CERCLIS** **NYSFN0204234**
WSW **GARDEN CITY, NY 11530** **US ENG CONTROLS**
1/4-1/2 **US INST CONTROL**
2433 ft. **ROD**
FINDS

NPL:

EPA ID:	NYSFN0204234
EPA Region:	02
Federal:	N
Final Date:	5/11/2000

Site Details:

Site Name:	OLD ROOSEVELT FIELD CONTAMINATED GW AREA
Site Status:	Final
Site Zip:	11530
Site City:	GARDEN CITY
Site State:	NY
Federal Site:	No
Site County:	NASSAU
EPA Region:	02
Date Proposed:	02/04/00
Date Deleted:	Not reported
Date Finalized:	05/11/00

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

Substance Details:

NPL Status:	Currently on the Final NPL
Substance ID:	Not reported
Substance:	Not reported
CAS #:	Not reported
Pathway:	Not reported
Scoring:	Not reported

NPL Status:	Currently on the Final NPL
Substance ID:	U078
Substance:	DICHLOROETHENE, 1,1-
CAS #:	75-35-4
Pathway:	GROUND WATER PATHWAY
Scoring:	2

NPL Status:	Currently on the Final NPL
Substance ID:	U210
Substance:	TETRACHLOROETHENE
CAS #:	127-18-4
Pathway:	GROUND WATER PATHWAY
Scoring:	2

NPL Status:	Currently on the Final NPL
Substance ID:	U211
Substance:	CARBON TETRACHLORIDE
CAS #:	56-23-5
Pathway:	GROUND WATER PATHWAY
Scoring:	4

NPL Status:	Currently on the Final NPL
Substance ID:	U228
Substance:	TRICHLOROETHYLENE (TCE)
CAS #:	79-01-6
Pathway:	GROUND WATER PATHWAY
Scoring:	2

Summary Details:

Conditions at Proposal February 4, 2000): The Environmental Protection Agency is proposing the Old Roosevelt Field Contaminated Ground Water Area ORCA) site to the National Priorities List in order to ensure the safety of an operating public drinking water supply located in an area of ground water contamination. The ORCA site, located in Garden City, Nassau County, New York is a contaminated ground water plume. Currently, the plume is documented by the presence of concentrations ofcarbon tetrachloride; 1,1-dichloroethene 1,1-DCE); tetrachloroethene PCE); and trichloroethene TCE) above health benchmarks in Garden City public supply wells 10 and 11. Historically, the highest levels of TCE were detected in cooling-water wellN8050, formerly located approximately 2,000 feet north-northeast of the Garden City wells. Garden City wells 10 and 11 and the former cooling-water well N8050 are all located on the property that historically was Roosevelt Field. There are severalpotential sources of the ground water contamination, however, there is not adequate information to attribute it to a specific source or sources.
The ORCA site is located on the eastern side of Clinton Road approximately 0.6 mile south of the intersection with Old Country Road. That intersection was the northwest corner of Roosevelt Field and its predecessors, which were used for aviation activities from 1911 until May 1951. The original airfield, known

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

as the Hempstead Plains Aerodrome, encompassed 900 to 1,000 acres east of Clinton Road and south of Old Country Road. The U.S. military began using the Hempstead Plains field before the U.S. entered World War I. When the U.S. entered the war in April 1917, the airfield was takenover as a training center for military pilots and renamed Ha elhurst Field. On September 24, 1918, the Army changed the name of the airfield to Roosevelt Field. After the war, the U.S. Air Service authori ed some companies to operate from RooseveltField but maintained control until July 1, 1920, at which time the Government sold its buildings and improvements and relinquished control of the field. Subsequently, the property owners sold portions along the southern edge of the field andsplit the remainder of the property into two separate fields, Roosevelt Field on the eastern half, and Curtiss Field. Both fields were bought in 1929 by Roosevelt Field, Inc. and the consolidated property was once again renamed Roosevelt Field. The eastern field was sold in 1936 and became a racetrack, while the western field located at the corner of Clinton and Old Country Roads continued to operate as an aviation center. Roosevelt Field was used by the Navy and Army during World WarII. After the war, Roosevelt Field reverted to a commercial airport until it closed in May 1951. Building construction at the site began in 1956. The Roosevelt Field Shopping Mall and Garden City Pla a currently occupy what was once Roosevelt Field. Besides the aviation activities that occurred at Roosevelt Field, there are several other potential sources of solvent contamination in the site vicinity. There are several industrial sites to the north that were significant users of chlorinated solvents in the past. One of those sites discharged effluent with TCE as high as 10,000 parts per billion ppb) to sewer pipes that were found to be leaking in 1978 and again in 1986. To the southeast, there are sites where two former solvent distributors were located. Based on the presence of so many potential sources in close proximity to the Garden City wells, the well contamination cannot be directly attributed to a specific source or sources at this time. Garden City public supply wells 10 and 11 were installed at what had been the southwestern corner of the airfield in 1952 and put into use in 1953. The wells have shown the presence of PCE and TCE since they were first sampled in the late 1970s and early 1980s, and the concentrations have increased significantly since then. In 1987, an air-stripping treatment system was installed at the site to remove VOCs from the raw water being pumped from wells 10 and 11. Sample results of treated well water from May 1993, September 1995, and June/July 1999 have indicated that breakthrough of the treatment system has occurred on those occasions. The population served by each well is estimated to be 3,428 people. Therefore, a population of approximately 6,857 people are considered to be subject to actual contamination at concentrations above health benchmarks, i.e., Level 1. There are also approximately 80 other public supply wells within 4 miles of the site serving more than 300,000 people. Status May 2000): EPA is considering various alternatives for this site. The description of the site release) is based on information available at the time the site was evaluated with the HRS. The description may change as additional informationis gathered on the sources and extent of contamination. See 56 FR 5600, February 11, 1991, or subsequent FR notices. For more information about the ha ardous substances identified in this narrative summary, including general information regarding the effects of exposure to these substances on human health, please see the Agency for Toxic Substances and Disease Registry ATSDR) ToxFAQs. ATSDR ToxFAQs can be found on the Internet at http://www.atsdr.cdc.gov/toxfaq.html or by telephone at 1-888-42-ATSDR or 1-888-422-8737.

Site Status Details:

NPL Status:	Final
Proposed Date:	02/04/2000
Final Date:	05/11/2000

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

Deleted Date: Not reported

Narratives Details:
NPL Name: OLD ROOSEVELT FIELD CONTAMINATED GW AREA
City: GARDEN CITY
State: NY

CERCLIS:
Site ID: 0204234
Federal Facility: Not a Federal Facility
NPL Status: Currently on the Final NPL
Non NPL Status: Not reported

CERCLIS Site Contact Name(s):
Contact Name: Not reported
Contact Tel: Not reported
Contact Title: 20001

Site Description: The Old Roosevelt Field Contaminated Groundwater Area Superfund Site (Site) is an area of groundwater contamination within the Village of Garden City, Town of Hempstead, in central Nassau County, New York. The Site is located on the eastern side of Clinton Road, south of the intersection with Old Country Road, and includes the area of the former Roosevelt Field airfield. The former Roosevelt Field airfield area is currently developed as a large retail shopping mall with a number of restaurants,and a movie theater. Several office buildings (including Garden City Plaza) are on the western perimeter of the mall and share parking space with the mall. A thin strip of open space along Clinton Road (known as Hazelhurst Park) serves as designatedparkland and a buffer between the residential community and the mall complex. Two recharge basins are directly east and south of the mall area. The eastern basin is known as Pembrook Basin and is on property owned by the mall. The basin situated to the south is Nassau County Recharge Basin number 124.Two municipal supply well fields are located south (downgradient) of the former airfield. The Village of Garden City public supply wells (designated as Wells 10 and 11) are located just south of the airfield boundary, on the eastern side of Clinton Road. The Village of Hempstead Wellfield is located approximately 1 mile south of the Garden City supply wells.The Site was used for aviation activities from 1911 to 1951. The original airfield was known as the Hempstead Plains Aerodrome and encompassed 900 to 1,000 acres east of Clinton Road and south of Old Country Road. By the time the field opened in July 1912, there were 5 cement and 30 wooden hangars along Old Country Road, 4 grandstands along Clinton Road, and several flying schools. At least two aviators built aircraft at the field in 1912, including the first all-metal monoplane in America. During its first three years, activities at the airfield included civilian flight training, equipment testing, and aerial stunt shows.The United States (U. S.) military began using the Hempstead Plains field prior to World War I. The New York National Guard First Aero Company began training at the airfield in 1915, and in 1916 the U.S. Army used the field to train Army and Navy officers. When the U. S. entered World War I in April 1917, the airfield was taken over as a training center for military pilots and renamed Hazelhurst Field. The Army removed the grandstands, built barracks along Clinton Road, and built larger hangars along Old Country Road. In 1918, the Army changed the name of the airfield to Roosevelt Field in honor of Quentin Roosevelt, a son of Theodore Roosevelt who had trained there and was killed during the war. Roosevelt Field was used throughout the war to train aviators.After the war, the U. S. Air

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

Service authorized aviation-related companies to operate from Roosevelt Field, but maintained control until July 1, 1920, at which time the Government sold its improvements on the airfield and relinquished control of the field. Subsequently, the property owners sold portions along the southern edge of the field and split the remainder of the property into two flying fields with an incline between them. The eastern half, with sod runways and only two hangars, continued as Roosevelt Field. The western half, which had many hangars, flying schools, and aviation maintenance shops, became known as Curtiss Field.By 1929, the eastern field (Roosevelt) had served as the starting point or terminus of many notable flights, including Lindbergh's takeoff for his historic trans-Atlantic flight in May 1927. The western field (Curtiss) was used for flying circuses, a flying school, aircraft sales and service, and flight tests. Both fields were bought in 1929 by Roosevelt Field, Inc., and the property was once again called Roosevelt Field. Improvements were quickly made, including the installation of several large steel and concrete buildings for hangars, shops, and office space along Old Country Road. As of November 1929, numerous aviation related businesses operated in the hangars and other buildings surrounding the western field. By 1932, paved runways and 50 buildings made Roosevelt Field the country's largest and busiest civil airfield. While the western field developed into the large aviation center that continued to operate throughout the 1930s, the eastern field remained unpaved, with few buildings, until it was leased in1935 and became a racetrack.Roosevelt Field was used by the Navy and Army during World War II. In July 1939, the Army Air Corps contracted Roosevelt Field, Inc. to provide airplane and engine mechanics training to Army personnel at their school. In early 1941, there were more than 200 Army students and approximately 600 other students at the Roosevelt Aviation School. At the beginning of 1942, after the U.S. had entered the war, civilian flying and private hangar rental had ceased at Roosevelt Field due to a ban on private flying in defense areas.As of March 1942, there were 6 steel/concrete hangars, 14 wooden hangars, and several other buildings at Roosevelt Field. The Army training school was concentrated in buildings located along Clinton Road. In addition to the training activities, the Roosevelt Field facilities were used to receive, refuel, crate, and ship Army aircraft.The Navy also used Roosevelt Field during World War II. In November 1942, the Navy Bureau of Aeronautics established a modification center at Roosevelt Field to install British equipment into U.S. aircraft for the British Royal Navy. The Navy leased five steel/concrete hangars along Old Country Road and built a barracks, mess hall, and sick bay and designated this installation as the U.S. Naval Air Facility (NAF) Roosevelt Field by February 1943. By September 1943, the Navy had built wooden buildings between four of the hangars, and in October 1943 leased six additional hangars. NAF Roosevelt Field was responsible for aircraft repair and maintenance, equipment installation, preparation and flight delivery of lend-lease aircraft, and metal work required for the installation of British modifications. The metal work constituted a substantial portion of the facility's work load. The facility also performed salvage work of crashed Royal Navy planes. The Navy vacated all but six hangars shortly after the war ended, and removed their temporary buildings by the time their lease expired on June 30, 1946. Restoration of buildings and grounds was completed by August 1946, and Roosevelt Field operated as a commercial airport until it closed in May 1951.Soon after the airfield closed, the large Roosevelt Field Shopping Center was constructed at the Site and opened in 1957. The old field is currently the site of the shopping mall and office building complexes, the Meadowbrook Parkway and is surrounded by commercial areas and light industry. Three of the old Navy hangars remained standing until some time after June 1971, with various occupants, including a moving/storage firm, discotheque, amusement center, and bus garage.It is likely that chlorinated solvents were used at Roosevelt Field during and after World War II. Chlorinated solvents

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

such as tetrachloroethene (PCE) and trichloroethene (TCE) have been widely used for aircraft manufacturing, maintenance, and repair operations since about the 1930s. Beginning in the late 1930s, the U.S. military issued protocols for use of solvents such as TCE for cleaning airplane parts and for de-icing. The types of airplanes designated for solvent use were present at Roosevelt Field during World War II. The finish specifications for at least one type of plane that the Navy modified at Roosevelt (eight of which were on Site in April 1943) called for aluminum alloy to be cleaned with TCE. An aircraft engine overhaul manual issued in January 1945 specified TCE as a degreasing agent.Wells 10 and 11 were installed by theVillage of Garden City in 1952 and were put into service in 1953. Well 10 is screened from 377 to 417 feet below the ground surface (bgs) and well 11 is screened from 370 to 410 feet bgs. Both wells have shown the presence of PCE and TCE since they were first sampled in the late 1970s and early 1980s, and concentrations increased significantly until 1987, when an air-stripping treatment system was installed to treat the water from the wells. Sampling results of treated well water from May 1993,September 1995, and June/July 1999 indicated that breakthrough of the treatment system had occurred. The highest levels of volatile organic compound (VOC) contamination were noted during the mid-to late 1990s, and have steadily declined since then, although the levels remain above EPA and New York State (NYS) drinking water standards.In addition to the Village of Garden City supply wells, seven cooling water wells in the mall area pumped contaminated groundwater from the Magothy aquifer for usein the air conditioning systems of the mall building and the office buildings west of the mall. Cooling water wells pumped variable amounts of water, with greater extraction rates during the hot summer months. These wells operated from approximately1960 to 1985. After the contaminated groundwater was used in air conditioning systems, the untreated water was returned to the aquifer system via surface recharge, first to the Pembrook recharge basin and later to a drain field west of 100 Garden City Plaza and 200 Garden City Plaza.The discharge of contaminated water into the recharge basin and drain field continued up to 1985 when the cooling water wells were taken out of service due to the presence of VOCs in the groundwater. Surface discharge of contaminated groundwater spread contamination through the Upper Glacial and Magothy aquifers. The recharge basin and drain field also created localized groundwater mounding, which may have spread contamination at the water table. However, the sandy nature of the recharge basin soils likely did not result in retention of VOCs within the soils. In addition, the zone below the recharge basin has been flushed with stormwater runoff for 20 years; residual contamination from Roosevelt Field is not likely to remain in the area. The Pembrook recharge basin currently only receives surficial stormwater runoff from parking lots surrounding the mall and the office buildings. The drain field/diffusion wells near 100 Garden City Plaza are under the paved parking lot west of 100 Garden City Plaza and 200 Garden City Plaza and are not currently identifiable in the field. Significant groundwater contamination is present at depth at SVP/GWM-4, which is located near the general area of the diffusion wells/drain field.EPA’s search for potentially responsible parties (PRPs) is ongoing. EPA has not yet identified any financially viable parties that would be responsible under CERCLA for the Site. If PRPs are identified, EPA will seek to have them perform or pay the cost of EPA’s investigation and cleanup.The Site includes a large shopping mall, numerous restaurants, a movie theater, and office buildings which ring the shopping mall. Most of the open space at the Site is asphalt parking areas for the shopping mall and office buildings. Other parts of the Site include the two Village of Garden City supply wells, two recharge basins and a small strip of open space known as Hazelhurst Park just east of Clinton Road. The use of the Site in the future is unlikely to change.A Record of Decision (ROD) addressing Operable Unit 1 (OU1) was completed in September 2007.

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

CERCLIS Assessment History:

Action:	DISCOVERY
Date Started:	Not reported
Date Completed:	7/27/1999 0:00:00
Priority Level:	Not reported
Action:	PROPOSAL TO NPL
Date Started:	Not reported
Date Completed:	2/4/2000 0:00:00
Priority Level:	Not reported
Action:	FINAL LISTING ON NPL
Date Started:	Not reported
Date Completed:	5/11/2000 0:00:00
Priority Level:	Not reported
Action:	PPA ASSESSMENT
Date Started:	7/15/2000 0:00:00
Date Completed:	12/17/2000 0:00:00
Priority Level:	PPA Signed
Action:	CONSENT AGREEMENT (ADMINISTRATIVE)
Date Started:	Not reported
Date Completed:	12/21/2000 0:00:00
Priority Level:	Not reported
Action:	COMBINED RI/FS
Date Started:	6/25/2001 0:00:00
Date Completed:	9/28/2007 0:00:00
Priority Level:	Not reported
Action:	RECORD OF DECISION
Date Started:	Not reported
Date Completed:	9/28/2007 0:00:00
Priority Level:	Final Remedy Selected at Site
Action:	REMOVAL ASSESSMENT
Date Started:	10/23/2000 0:00:00
Date Completed:	Not reported
Priority Level:	Not reported
Action:	TECHNICAL ASSISTANCE
Date Started:	4/12/2007 0:00:00
Date Completed:	Not reported
Priority Level:	Not reported
Action:	REMEDIAL DESIGN
Date Started:	12/18/2007 0:00:00
Date Completed:	Not reported
Priority Level:	Not reported

US ENG CONTROLS:

EPA ID:	NYSFN0204234
Site ID:	0204234
Name:	OLD ROOSEVELT FIELD CONTAMINATED GW AREA

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

Address: CLINTON ROAD/OLD COUNTRY ROAD
GARDEN CITY, NY 11530
EPA Region: 02
County: NASSAU
Event Code: Not reported
Actual Date: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 9/28/2007
Planned Complet. date: 9/30/2007
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Air Stripping

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 9/28/2007
Planned Complet. date: 9/30/2007
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Discharge

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 9/28/2007
Planned Complet. date: 9/30/2007
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Extraction

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 9/28/2007
Planned Complet. date: 9/30/2007
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Monitoring

US INST CONTROL:
EPA ID: NYSFN0204234
Site ID: 0204234
Name: OLD ROOSEVELT FIELD CONTAMINATED GW AREA
Action Name: RECORD OF DECISION
Address: CLINTON ROAD/OLD COUNTRY ROAD
GARDEN CITY, NY 11530
EPA Region: 02
County: NASSAU
Event Code: Not reported
Inst. Control: Covenant
Actual Date: Not reported
Complet. Date: 09/28/07
Operable Unit: 01
Contaminated Media : Groundwater

EPA ID: NYSFN0204234

OLD ROOSEVELT FIELD CONTAMINATED GW AREA (Continued) **1001814341**

Site ID: 0204234
Name: OLD ROOSEVELT FIELD CONTAMINATED GW AREA
Action Name: RECORD OF DECISION
Address: CLINTON ROAD/OLD COUNTRY ROAD
GARDEN CITY, NY 11530
EPA Region: 02
County: NASSAU
Event Code: Not reported
Inst. Control: Easement
Actual Date: Not reported
Complet. Date: 09/28/07
Operable Unit: 01
Contaminated Media : Groundwater

ROD:

Full-text of USEPA Record of Decision(s) is available from EDR.

FINDS:

Registry ID: 110009303967

Environmental Interest/Information System

CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

NPL
Region
SSW
1/2-1
4292 ft.

PASLEY SOLVENTS & CHEMICALS, INC.
585 COMMERICAL AVENUE
HEMPSTEAD, NY 11530

NPL
CERCLIS
RCRA-NonGen
US ENG CONTROLS
CONSENT
ROD
FINDS

1000282560
NYD991292004

NPL:
EPA ID: NYD991292004
EPA Region: 02
Federal: N
Final Date: 6/10/1986

Category Details:
NPL Status: Currently on the Final NPL
Category Description: Depth To Aquifer-> 10 And <= 25 Feet
Category Value: 25

NPL Status: Currently on the Final NPL
Category Description: Distance To Nearest Population-> 0 And <= 1/4 Mile
Category Value: 1000

Site Details:
Site Name: PASLEY SOLVENTS & CHEMICALS, INC.
Site Status: Final

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Site Zip: 11530
Site City: HEMPSTEAD
Site State: NY
Federal Site: No
Site County: NASSAU
EPA Region: 02
Date Proposed: 10/15/84
Date Deleted: Not reported
Date Finalized: 06/10/86

Substance Details:

NPL Status: Currently on the Final NPL
Substance ID: U239
Substance: XYLENE
CAS #: 1330-20-7
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: W009
Substance: FUEL OIL, #2
CAS #: 68476-30-2
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: Not reported
Substance: Not reported
CAS #: Not reported
Pathway: Not reported
Scoring: Not reported

NPL Status: Currently on the Final NPL
Substance ID: C049
Substance: ETHYLBENZENE
CAS #: 100-41-4
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: C324
Substance: CIS-1,2-DICHLOROETHYLENE
CAS #: 156-59-2
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: C582
Substance: BROMODICHLOROETHYLENE
CAS #: Not reported
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: U019
Substance: BENZENE
CAS #: 71-43-2

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: U044
Substance: CHLOROFORM
CAS #: 67-66-3
Pathway: GROUND WATER PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: U080
Substance: METHYLENE CHLORIDE
CAS #: 75-09-2
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: U210
Substance: TETRACHLOROETHENE
CAS #: 127-18-4
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U220
Substance: TOLUENE
CAS #: 108-88-3
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: U226
Substance: TRICHLOROETHANE, 1,1,1-
CAS #: 71-55-6
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL
Substance ID: U228
Substance: TRICHLOROETHYLENE (TCE)
CAS #: 79-01-6
Pathway: NO PATHWAY INDICATED
Scoring: 1

Summary Details:

Conditions at proposal October 15, 1984): The Pasley Solvents Chemicals, Inc., Site covers about 0.5 acre in Hempstead, Nassau County, New York. Barlo Equipment Co. leased the property and subsequently subleased it to Pasley Solvents. Pasley operated as a chemical distribution facility from l969 through mid-l982 and reportedly stored various organic chemicals, including aliphatic naphthas, aromatic solvents, and ketones. Prior to l969, the site was occupied by Commander Oil,a distributor of fuel oil and gasoline. The site consists of a large one-story building, a tin shed, a small building, and l2 above-ground tanks. In June l98l, the Nassau County Health Department collected soil samples beneath the tanks at depths of 6 inches to 36 inches. Analyses of the samples indicated that the soil was

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

contaminated with halogenated and nonhalogenated organic compounds. Five monitoring wells were installed at the site in August l98l. Analyses of soil andground water from wells 2, 4, and 5 detected halogenated and nonhalogenated organic compounds, as well as constituents of fuel oil and gasoline. The nearest well is less than 0.5 mile from the site. About 12,000 people draw drinking water fromwells within 3 miles of the site. Nassau County has cited both Commander Oil and Pasley Solvents for various violations but without any resulting follow-up action. Status June 10, 1986): EPA is considering various alternatives for this site.

Site Status Details:
- NPL Status: Final
- Proposed Date: 10/15/1984
- Final Date: 06/10/1986
- Deleted Date: Not reported

Narratives Details:
- NPL Name: PASLEY SOLVENTS & CHEMICALS, INC.
- City: HEMPSTEAD
- State: NY

CERCLIS:
- Site ID: 0202422
- Federal Facility: Not a Federal Facility
- NPL Status: Currently on the Final NPL
- Non NPL Status: Not reported

CERCLIS Site Contact Name(s):
- Contact Name: Not reported
- Contact Tel: Not reported
- Contact Title: 22700

Site Description: SITE COVRS ABOUT 0.5 & OPERTED AS A CHEM DISTRBTIN FACIL FROM 1969-MID 1982 & REPRTDLY STORED ALIPHATIC NAPHTHAS,AROMATIC SLVNTS, & KETONES. CONCRN GRND WTR & SOIL CONTAMIN. WORK PLAN IS FINALZD. PRESNTLY NEGOTIA WITH PRP(COMMANDR OIL)

CERCLIS Assessment History:
- Action: DISCOVERY
- Date Started: Not reported
- Date Completed: 9/1/1984 0:00:00
- Priority Level: Not reported

- Action: PROPOSAL TO NPL
- Date Started: Not reported
- Date Completed: 10/15/1984 0:00:00
- Priority Level: Not reported

- Action: PRELIMINARY ASSESSMENT
- Date Started: Not reported
- Date Completed: 10/31/1984 0:00:00
- Priority Level: Low priority for further assessment

- Action: SITE INSPECTION
- Date Started: 7/1/1985 0:00:00
- Date Completed: 8/31/1985 0:00:00
- Priority Level: Higher priority for further assessment

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Action: FINAL LISTING ON NPL
Date Started: Not reported
Date Completed: 6/10/1986 0:00:00
Priority Level: Not reported

Action: Notice Letters Issued
Date Started: Not reported
Date Completed: 6/12/1987 0:00:00
Priority Level: Not reported

Action: AERIAL SURVEY
Date Started: Not reported
Date Completed: 1/1/1988 0:00:00
Priority Level: Not reported

Action: Special Notice Issued
Date Started: Not reported
Date Completed: 2/12/1988 0:00:00
Priority Level: Not reported

Action: RI/FS NEGOTIATIONS
Date Started: 11/15/1986 0:00:00
Date Completed: 8/19/1988 0:00:00
Priority Level: Not reported

Action: COMBINED RI/FS
Date Started: 7/10/1987 0:00:00
Date Completed: 8/19/1988 0:00:00
Priority Level: Not reported

Action: RI/FS WORKPLAN APPROVAL BY HQ
Date Started: 7/30/1987 0:00:00
Date Completed: 8/19/1988 0:00:00
Priority Level: Not reported

Action: NPL RP SEARCH
Date Started: 9/1/1987 0:00:00
Date Completed: 8/19/1988 0:00:00
Priority Level: Not reported

Action: ADMIN ORDER ON CONSENT
Date Started: Not reported
Date Completed: 8/19/1988 0:00:00
Priority Level: Not reported

Action: ADMIN/VOLUNTARY COST RECOVERY
Date Started: Not reported
Date Completed: 9/19/1988 0:00:00
Priority Level: Not reported

Action: REMOVAL ASSESSMENT
Date Started: 3/23/1990 0:00:00
Date Completed: 9/11/1990 0:00:00
Priority Level: Stabilized

Action: RISK/HEALTH ASSESSMENT
Date Started: 3/1/1991 0:00:00

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Date Completed: 10/25/1991 0:00:00
Priority Level: Not reported

Action: PRP RI/FS
Date Started: 8/19/1988 0:00:00
Date Completed: 4/24/1992 0:00:00
Priority Level: Not reported

Action: RECORD OF DECISION
Date Started: Not reported
Date Completed: 4/24/1992 0:00:00
Priority Level: Not reported

Action: Notice Letters Issued
Date Started: Not reported
Date Completed: 7/30/1992 0:00:00
Priority Level: Not reported

Action: REMOVAL ASSESSMENT
Date Started: 12/1/1992 0:00:00
Date Completed: 12/21/1992 0:00:00
Priority Level: Stabilized

Action: RD/RA NEGOTIATIONS
Date Started: 7/30/1992 0:00:00
Date Completed: 3/31/1993 0:00:00
Priority Level: Not reported

Action: ROD Amendment
Date Started: Not reported
Date Completed: 5/22/1995 0:00:00
Priority Level: Final Remedy Selected at Site

Action: RD/RA NEGOTIATIONS
Date Started: 5/1/1994 0:00:00
Date Completed: 8/23/1995 0:00:00
Priority Level: Not reported

Action: Lodged By DOJ
Date Started: Not reported
Date Completed: 11/2/1995 0:00:00
Priority Level: Not reported

Action: CONSENT DECREE
Date Started: 8/23/1995 0:00:00
Date Completed: 1/26/1996 0:00:00
Priority Level: Not reported

Action: REMEDIAL DESIGN
Date Started: 3/31/1993 0:00:00
Date Completed: 4/17/1997 0:00:00
Priority Level: Not reported

Action: PRP RD
Date Started: 1/25/1996 0:00:00
Date Completed: 4/17/1997 0:00:00
Priority Level: Not reported

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Action: PRP RA
Date Started: 4/17/1997 0:00:00
Date Completed: 8/21/1998 0:00:00
Priority Level: Not reported

Action: PRP LR
Date Started: 11/1/1997 0:00:00
Date Completed: 9/30/1999 0:00:00
Priority Level: Not reported

Action: PRELIM CLOSE-OUT REP PREPARED
Date Started: Not reported
Date Completed: 9/30/1999 0:00:00
Priority Level: Not reported

Action: FIVE-YEAR REVIEW
Date Started: Not reported
Date Completed: 8/5/2004 0:00:00
Priority Level: Not reported

Action: STATE SUPPORT AGENCY COOP AGREEMENT
Date Started: 1/26/1987 0:00:00
Date Completed: 12/31/2006 0:00:00
Priority Level: Not reported

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: PASLEY SALES CORP
Facility address: 556 COMMERCIAL AVE BX1
GARDEN CITY, NY 11530
EPA ID: NYD991292004
Mailing address: COMMERCIAL AVE BX 1
GARDEN CITY, NY 11530
Contact: HCONTFIRST HCONTLAST
Contact address: COMMERCIAL AVE BX 1
GARDEN CITY, NY 11530
Contact country: US
Contact telephone: (212) 555-1212
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PASLEY ROBERT PRES
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PASLEY ROBERT PRES

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: PASLEY SALES CORP
Classification: Not a generator, verified

Date form received by agency: 08/11/1980
Facility name: PASLEY SALES CORP
Classification: Unverified

Violation Status: No violations found

US ENG CONTROLS:
EPA ID: NYD991292004
Site ID: 0202422
Name: PASLEY SOLVENTS & CHEMICALS, INC.
Address: 585 COMMERICAL AVENUE
HEMPSTEAD, NY 11530
EPA Region: 02
County: NASSAU
Event Code: Not reported
Actual Date: Not reported

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Air Stripping

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Carbon Adsorption

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Clarification

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Discharge

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Filtration

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Monitoring

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Precipitation

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Groundwater
Engineering Control: Residuals Disposal

Action ID: 001

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: Disposal

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: Monitoring

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: Residuals Disposal

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: Soil Flushing

Action ID: 001
Action Name: RECORD OF DECISION
Action Completion date: 4/24/1992
Planned Complet. date: 4/30/1992
Operable Unit: 01
Contaminated Media : Soil
Engineering Control: Soil Vapor Extraction (in-situ)

CONSENT:
EPA ID: NYD991292004
Site ID: Not reported
Case Title: U.S. V. COMMANDER OIL CORPORATION, ET AL.
Court Num: 95-4489
District: New York, East
Entered Date: 19960125
Full-text of the consent decree for this site issued by the United States District Court is available from EDR. Contact your EDR Account Executive.

ROD:
Full-text of USEPA Record of Decision(s) is available from EDR.

FINDS:

PASLEY SOLVENTS & CHEMICALS, INC. (Continued) **1000282560**

Registry ID: 110004509265

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110009323794

Environmental Interest/Information System
CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

B8 **FAMILY COURT BLDG** **LTANKS S104514003**
1200 OLD COUNTRY ROAD **HIST LTANKS N/A**
< 1/8 **WESTBURY, NY**
1 ft.

Site 1 of 9 in cluster B

Relative: Higher

Actual: 94 ft.

LTANKS:

Site ID:	274664
Spill No:	9200006
Spill Date:	4/1/1992
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/5/1992
Facility Addr2:	Not reported
Cleanup Ceased:	11/5/1992
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	RDDECAND
Referred To:	Not reported
Reported to Dept:	4/1/1992

FAMILY COURT BLDG (Continued) **S104514003**

CID:	04
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/3/1992
Spill Record Last Update:	10/17/2001
Spiller Name:	Not reported
Spiller Company:	ISLAND TRANSPORTATION
Spiller Address:	299 EDISON AVENUE
Spiller City,St,Zip:	WEST BABYLON, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	223401
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DECANDIA" 11/05/92: SPILLER HIRED MPC,15 YDS REMOVED AND DISPOSED OF AT MT HOPE.
Remarks:	SUSPECT DRIVER SPILLED OIL INTO SOIL AREA, NO ACTION AS OF YET

Material:

Site ID:	274664
Operable Unit ID:	964114
Operable Unit:	01
Material ID:	414855
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	9200006
Spill Date:	04/01/1992

FAMILY COURT BLDG (Continued) **S104514003**

Spill Time:	09:15
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/05/92
Cleanup Ceased:	11/05/92
Cleanup Meets Standard:	True
Investigator:	DECANDIA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	04/01/92
Reported to Department Time:	09:38
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	ISLAND TRANSPORTATION
Spiller Address:	299 EDISON AVENUE
Spiller City,St,Zip:	WEST BABYLON, NY
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(516) 694-4490
Facility Extention:	Not reported
Spill Notifier:	Fire Department
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	04/03/92
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	10/17/01
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	30

FAMILY COURT BLDG (Continued) **S104514003**

Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	#2 FUEL OIL
Class Type:	#2 FUEL OIL
Times Material Entry In File:	24464
CAS Number:	Not reported
Last Date:	19941207
DEC Remarks:	11/05/92: SPILLER HIRED MPC,15 YDS REMOVED AND DISPOSED OF AT MT HOPE.
Spill Cause:	SUSPECT DRIVER SPILLED OIL INTO SOIL AREA, NO ACTION AS OF YET

C9 **UNKNOWN** **NY Spills** **S107658074**
1000 ZECKENDORF AVENUE **N/A**
< 1/8 **WESTBURY, NY**
1 ft.

Site 1 of 4 in cluster C

Relative: Higher

Actual: 98 ft.

NY Spills:

Site ID:	361646
Facility Addr2:	Not reported
Facility ID:	0514832
Spill Number:	0514832
Facility Type:	ER
SWIS:	3022
Investigator:	Unassigned
Referred To:	Not reported
Spill Date:	3/27/2006
Reported to Dept:	3/27/2006
CID:	444
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/3/2006
Remediation Phase:	0
Date Entered In Computer:	3/27/2006
Spill Record Last Update:	2/26/2009
Spiller Name:	BILLY STUBER
Spiller Company:	KEYSPAN
Spiller Address:	1000 ZECKENDORF AVENUE
Spiller City,St,Zip:	WESTBURY, NY
Spiller Company:	001
Contact Name:	BILLY STUBER
Contact Phone:	(917) 578-0160
DEC Region:	1
DER Facility ID:	311865
DEC Memo:	16:33 CALL TO STUBER, SPILL ONTO SOIL, MOST ON THE PAD, SOIL REMOVED AND REPLACED.NON PCB PER NAME PLATE, CLEANUP COMPLETE
Remarks:	OVERHEATED UNIT AND IN PROCESS OF CLEANING UP

UNKNOWN (Continued) **S107658074**

Material:

Site ID:	361646
Operable Unit ID:	1119776
Operable Unit:	01
Material ID:	2109218
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

B10 **ROOSEVELT PARK RACEWAY** **RCRA-NonGen** **1000554365**
ZECKENDORF BLVD & OLD COUNTRY **FINDS** **NYD986968279**
< 1/8 **WESTBURY, NY 11590** **MANIFEST**
1 ft.

Site 2 of 9 in cluster B

Relative: Higher

Actual: 94 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	ROOSEVELT PARK RACEWAY
Facility address:	ZECKENDORF BLVD & OLD COUNTRY WESTBURY, NY 11590
EPA ID:	NYD986968279
Mailing address:	ELLISON AVE WESTBURY, NY 11590
Contact:	Not reported
Contact address:	ELLISON AVE WESTBURY, NY 11590
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	EVANS & HUGHES REALTY
Owner/operator address:	UNKNOWN

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

UNKNOWN, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: EVANS & HUGHES REALTY
Owner/operator address: UNKNOWN
UNKNOWN, NY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: ROOSEVELT PARK RACEWAY
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: ROOSEVELT PARK RACEWAY
Classification: Not a generator, verified

Date form received by agency: 03/01/1996
Facility name: ROOSEVELT PARK RACEWAY
Site name: ROOSEVELT RACEWAY GRANDSTAND
Classification: Large Quantity Generator

Date form received by agency: 08/22/1991
Facility name: ROOSEVELT PARK RACEWAY
Classification: Large Quantity Generator

Violation Status: No violations found

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Evaluation Action Summary:
Evaluation date: 12/07/1995
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110008463581

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986968279
Country: USA
Mailing Name: MCS REALTY PARTNERS
Mailing Contact: GARY DAVIS
Mailing Address: 1325 AVE OF AMER
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10019
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 212-554-0500

Document ID: NYB1719927
Manifest Status: Completed copy
Trans1 State ID: T668KB
Trans2 State ID: Not reported
Generator Ship Date: 930414
Trans1 Recv Date: 930414
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930419
Part A Recv Date: 930422
Part B Recv Date: 930504
Generator EPA ID: NYD986968279
Trans1 EPA ID: OHD009865825
Trans2 EPA ID: Not reported
TSDF ID: OHD981960123
Waste Code: B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity: 01200
Units: K - Kilograms (2.2 pounds)
Number of Containers: 004
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Quantity:	00029
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	93
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB5471055
Manifest Status:	Completed copy
Trans1 State ID:	T774KC
Trans2 State ID:	Not reported
Generator Ship Date:	931206
Trans1 Recv Date:	931206
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	931207
Part A Recv Date:	940118
Part B Recv Date:	931227
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	OHD981093420
Trans2 EPA ID:	Not reported
TSDF ID:	OHD981093420
Waste Code:	B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB
Quantity:	14097
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	008
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	93
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Document ID:	NYA7382394
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	940516
Trans1 Recv Date:	940516
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940525
Part A Recv Date:	Not reported
Part B Recv Date:	940613
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	OHD981100969
Trans2 EPA ID:	Not reported
TSDF ID:	OHD981100969
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Quantity:	00220
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB7434828
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	R39387ME
Trans2 State ID:	R51835ME
Generator Ship Date:	951221
Trans1 Recv Date:	951221
Trans2 Recv Date:	951229
TSD Site Recv Date:	960104
Part A Recv Date:	960108
Part B Recv Date:	960119
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	CTD982191942
TSDF ID:	OHD980681571
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00045
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	009
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1136907
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	910805
Trans1 Recv Date:	910805
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910807
Part A Recv Date:	910904
Part B Recv Date:	910906
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	OHD009865825
Trans2 EPA ID:	Not reported
TSDF ID:	OHD981100969
Waste Code:	B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity:	19386
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	061
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Document ID:	NYB7434819
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	R39387ME
Trans2 State ID:	R51835ME
Generator Ship Date:	951221
Trans1 Recv Date:	951221
Trans2 Recv Date:	951229
TSD Site Recv Date:	960104
Part A Recv Date:	960108
Part B Recv Date:	960119
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	CTD982191942
TSDF ID:	OHD980681571
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00025
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1136988
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	911008
Trans1 Recv Date:	911008
Trans2 Recv Date:	Not reported

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

TSD Site Recv Date:	911009
Part A Recv Date:	Not reported
Part B Recv Date:	911028
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	OHD009865825
Trans2 EPA ID:	Not reported
TSDF ID:	OHD981100969
Waste Code:	B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity:	04350
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	015
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00800
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00300
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB7434954
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	R39387ME
Trans2 State ID:	R51835ME
Generator Ship Date:	951221
Trans1 Recv Date:	951221
Trans2 Recv Date:	951227

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

TSD Site Recv Date:	960104
Part A Recv Date:	960108
Part B Recv Date:	960119
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	CTD982191942
TSDF ID:	OHD980681571
Waste Code:	F001 - UNKNOWN
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB5687199
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	JA334
Trans2 State ID:	Not reported
Generator Ship Date:	951031
Trans1 Recv Date:	951031
Trans2 Recv Date:	951101
TSD Site Recv Date:	951101
Part A Recv Date:	Not reported
Part B Recv Date:	951127
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID:	MDD980554653
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	03181
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	02545
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB7434855
Manifest Status:	Completed copy
Trans1 State ID:	XR4680
Trans2 State ID:	R39387ME
Generator Ship Date:	960220
Trans1 Recv Date:	960220
Trans2 Recv Date:	960222
TSD Site Recv Date:	960305
Part A Recv Date:	Not reported
Part B Recv Date:	960315
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	NY0000936385
Trans2 EPA ID:	CTD982191942
TSDF ID:	OHD980681571
Waste Code:	F003 - UNKNOWN
Quantity:	00440
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	085
Year:	96
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB1136916
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	910805
Trans1 Recv Date:	910805

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910807
Part A Recv Date:	910904
Part B Recv Date:	910906
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	OHD009865825
Trans2 EPA ID:	Not reported
TSDF ID:	OHD981100969
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Quantity:	00375
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB4086234
Manifest Status:	Completed copy
Trans1 State ID:	PB9830NY
Trans2 State ID:	Not reported
Generator Ship Date:	921006
Trans1 Recv Date:	921006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	921009
Part A Recv Date:	921124
Part B Recv Date:	921028
Generator EPA ID:	NYD986968279
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID:	OHD981960123
Waste Code:	B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity:	01200
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	150
Waste Code:	Not reported
Quantity:	00080
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

ROOSEVELT PARK RACEWAY (Continued) **1000554365**

Specific Gravity:	Not reported
Year:	92
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

B11 **NC FAMILY COURT** **UST** **U003847417**
1200 OLD COUNTRY RD **N/A**
< 1/8 **WESTBURY, NY 11590**
1 ft.

Site 3 of 9 in cluster B

Relative: Higher
Actual: 94 ft.

NCFM UST:

Tank Type:	OUTDOOR UG HOR D/W F/G
Tank Size:	1000
Tank Contents:	DIESEL

C12 **VERIZON GNI** **AST** **A100197816**
1000 ZECKENDORF BLVD **N/A**
< 1/8 **GARDEN CITY, NY 11530**
1 ft.

Site 2 of 4 in cluster C

Relative: Higher
Actual: 98 ft.

NCFM AST:

Tank Type:	OUTDOOR AG HOR STEEL
Tank Size:	60
Contents:	DIESEL
Tank Type:	INDOOR AG HOR STEEL
Tank Size:	660
Contents:	DIESEL

B13 **NASSAU COUNTY OF FAMILY COURT** **RCRA-NonGen** **1001203112**
1200 OLD COUNTRY RD **FINDS** **NYR000044636**
< 1/8 **WESTBURY, NY 11590** **MANIFEST**
1 ft.

Site 4 of 9 in cluster B

Relative: Higher
Actual: 94 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NASSAU COUNTY OF FAMILY COURT
Facility address:	1200 OLD COUNTRY RD WESTBURY, NY 11590
EPA ID:	NYR000044636
Mailing address:	OLD COUNTRY RD WESTBURY, NY 11590

NASSAU COUNTY OF FAMILY COURT (Continued) **1001203112**

Contact: WILLIAM SLADE
Contact address: OLD COUNTRY RD
WESTBURY, NY 11590
Contact country: US
Contact telephone: (914) 681-6405
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: COUNTY OF NASSAU
Owner/operator address: 1550 FRANKLIN AVE
MINEOLA, NY 11501
Owner/operator country: US
Owner/operator telephone: (516) 571-4201
Legal status: County
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: COUNTY OF NASSAU
Owner/operator address: 1550 FRANKLIN AVE
MINEOLA, NY 11501
Owner/operator country: US
Owner/operator telephone: (516) 571-4201
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NASSAU COUNTY OF FAMILY COURT
Classification: Not a generator, verified

Date form received by agency: 09/11/1997

NASSAU COUNTY OF FAMILY COURT (Continued) **1001203112**

Facility name: NASSAU COUNTY OF FAMILY COURT
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004537207

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000044636
Country:	USA
Mailing Name:	NASSAU CTY FAMILY COURT
Mailing Contact:	WILLIAM SLADE
Mailing Address:	1200 OLD COUNTRY RD
Mailing Address 2:	Not reported
Mailing City:	WESTBURY
Mailing State:	NY
Mailing Zip:	11590
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	914-681-6405

Document ID:	NYG0194391
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	MA102PTH7
Trans2 State ID:	Not reported
Generator Ship Date:	971203
Trans1 Recv Date:	971203
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	971208
Part A Recv Date:	980106
Part B Recv Date:	980127
Generator EPA ID:	NYR000044636
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported
TSDF ID:	AZ0000337360
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	01340
Units:	P - Pounds
Number of Containers:	012
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	97
Manifest Tracking Num:	Not reported
Import Ind:	Not reported

NASSAU COUNTY OF FAMILY COURT (Continued) **1001203112**

Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYG0195282
Manifest Status:	Not reported
Trans1 State ID:	MA5000002394
Trans2 State ID:	Not reported
Generator Ship Date:	01/20/1998
Trans1 Recv Date:	01/20/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/23/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000044636
Trans1 EPA ID:	AZ0000337360
Trans2 EPA ID:	Not reported
TSDF ID:	MA102PTH7
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00254
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	98
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

B14 **N.C. FAMILY COURT COMPLEX** **UST** **U003869071**
1200 OLD COUNTRY RD. **N/A**
< 1/8 **WESTBURY, NY**
1 ft.

Site 5 of 9 in cluster B

Relative:
Higher

Actual:
94 ft.

NASSAU CO. UST:

Facility ID:	053093
Owner Name:	NASSAU COUNTY D.G.S.
Owner Address:	1 WEST STREET
Owner City,St,Zip:	MINEOLA, NY 11501

N.C. FAMILY COURT COMPLEX (Continued) **U003869071**

Permitee Name: NASSAU COUNTY
Permitee Address: Not reported
Permitee City,St,Zip: Not reported

Tank ID: 0003
Tank Location: Indoors, Belowground
Capacity (Gal): 00010000
Tank Status: In Service
Tank Material: Fiberglass Reinforced Plastic
Int Protection: None
Ext Protection: FIBERGLASS REINFORCED PLASTIC
Piping Type: Fiberglass
Material Type: Fresh/Product
Description: OIL, FUEL #2
Leak Detect: ELECTRONIC
Containment: DOUBLE WALL TANK
Product Gauge: No
Dispense Method: Suction
Fill Type: Gravity
Install Date: 021993

Tank ID: 0010
Tank Location: Indoors, Belowground
Capacity (Gal): 00010000
Tank Status: In Service
Tank Material: Fiberglass Reinforced Plastic
Int Protection: Other
Ext Protection: FIBERGLASS REINFORCED PLASTIC
Piping Type: Fiberglass
Material Type: Fresh/Product
Description: OIL, FUEL #2
Leak Detect: ELECTRONIC
Containment: DOUBLE WALL TANK
Product Gauge: No
Dispense Method: Suction
Fill Type: Gravity
Install Date: 021993

C15 **GREEN PACKAGING CORP** **RCRA-NonGen** **1000206727**
1000 ZECKENDORF BLVD **FINDS** **NYD057383572**
< 1/8 **GARDEN CITY, NY 11530** **MANIFEST**
1 ft.

Site 3 of 4 in cluster C

Relative: Higher

Actual: 98 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: GREEN PACKAGING CORP
Facility address: 1000 ZECKENDORF BLVD
GARDEN CITY, NY 115302112
EPA ID: NYD057383572
Mailing address: ZECKENDORF BLVD
GARDEN CITY, NY 11530
Contact: Not reported
Contact address: ZECKENDORF BLVD
GARDEN CITY, NY 11530
Contact country: US
Contact telephone: Not reported

GREEN PACKAGING CORP (Continued) **1000206727**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: GREEN PACKAGING CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: GREEN PACKAGING CORP
Classification: Not a generator, verified

Date form received by agency: 09/07/1984
Facility name: GREEN PACKAGING CORP

GREEN PACKAGING CORP (Continued) **1000206727**

Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004360833

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD057383572
Country:	USA
Mailing Name:	GREEN PACKAGING
Mailing Contact:	HENRY HARTMAN
Mailing Address:	1000 ZECKENDORF BLVD
Mailing Address 2:	Not reported
Mailing City:	GARDEN CITY
Mailing State:	NY
Mailing Zip:	11530
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	516-746-4446

Document ID:	NYA1287909
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PLATE#577
Trans2 State ID:	Not reported
Generator Ship Date:	850528
Trans1 Recv Date:	850528
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	850528
Part A Recv Date:	851024
Part B Recv Date:	850614
Generator EPA ID:	NYD057383572
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID:	NYD000824334
Waste Code:	F003 - UNKNOWN
Quantity:	01265
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	85
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported

GREEN PACKAGING CORP (Continued) **1000206727**

Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

C16 **OFFICE BLDG** **LTANKS** **S100879312**
1000 ZECKENDORF BLVD **HIST LTANKS** **N/A**
< 1/8 **GARDEN CITY, NY**
1 ft.

Site 4 of 4 in cluster C

Relative: Higher

Actual: 98 ft.

LTANKS:

Site ID:	103763
Spill No:	9313927
Spill Date:	2/22/1994
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	9/14/1994
Facility Addr2:	Not reported
Cleanup Ceased:	9/14/1994
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	KAKISPER
Referred To:	Not reported
Reported to Dept:	2/25/1994
CID:	04
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/28/1994
Spill Record Last Update:	9/15/1994
Spiller Name:	Not reported
Spiller Company:	OFFICE BLDG
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	91725
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "KISPERT" 09/14/94: INVESTIGATION UNDER SLAB DONE & AIR MONITORING PERFORMED, NO OTHER ACTION NEEDED AT THIS TIME.
Remarks:	LEAKING FUEL OIL LINE, MILRO ON SITE

Material:

OFFICE BLDG (Continued) **S100879312**

Site ID:	103763
Operable Unit ID:	992373
Operable Unit:	01
Material ID:	389280
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	9313927
Spill Date:	02/22/1994
Spill Time:	12:00
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	09/14/94
Cleanup Ceased:	09/14/94
Cleanup Meets Standard:	True
Investigator:	KISPERT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	02/25/94
Reported to Department Time:	14:48
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

OFFICE BLDG (Continued) **S100879312**

Spiller Name: OFFICE BLDG
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 02/28/94
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 09/15/94
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 20
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 09/14/94: INVESTIGATION UNDER SLAB DONE AIR MONITORING PERFORMED, NO OTHER ACTION NEEDED AT THIS TIME.
Spill Cause: LEAKING FUEL OIL LINE, MILRO ON SITE

---

17 **INACTIVE - AVIS RENT A CAR** **UST** **U003846428**
NNW **357 OLD COUNTRY RD** **N/A**
< 1/8 **CARLE PLACE, NY 11514**
0.003 mi.
18 ft.

Relative:
Higher

Actual:
90 ft.

NCFM UST:
Tank Type: OUTDOOR UG HOR D/W F/G
Tank Size: 10000
Tank Contents: EMPTY

D18
NNW
< 1/8
0.004 mi.
19 ft.

AMOCO - CARLE PLACE SERVICE STATION
345 OLD COUNTRY ROAD
CARLE PLACE, NY 11514

Site 1 of 4 in cluster D

UST **U003913583**
N/A

Relative:
Higher

Actual:
89 ft.

UST:

Facility Id:	1-000189
Region:	STATE
DEC Region:	1
Site Status:	Unregistered
Program Type:	PBS
Expiration Date:	N/A
UTM X:	617547.99982999999
UTM Y:	4511325.50019
Site ID:	361319

Tank Number:	1
Tank Status:	Unregistered
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	9/1/1974
Capacity Gallons:	6000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank ID:	210597
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	6/12/2001
Register:	True
Modified By:	NJACAMPO
Last Modified:	3/21/2006

Tank Number:	2
Tank Status:	Unregistered
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	9/1/1974
Capacity Gallons:	6000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank ID:	210598
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	6/12/2001
Register:	True
Modified By:	NJACAMPO
Last Modified:	3/21/2006

Tank Number:	3
Tank Status:	Unregistered
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	9/1/1974
Capacity Gallons:	8000

AMOCO - CARLE PLACE SERVICE STATION (Continued) **U003913583**

Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank ID:	210599
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	6/12/2001
Register:	True
Modified By:	NJACAMPO
Last Modified:	3/21/2006

Tank Number:	4
Tank Status:	Unregistered
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	9/1/1974
Capacity Gallons:	8000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank ID:	210600
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	6/12/2001
Register:	True
Modified By:	NJACAMPO
Last Modified:	3/21/2006

UST_PBS_BSAFFIL:

Site Id:	361319
Program Number:	1-000189
Facility Type:	On-Site Operator
Affiliation Type:	04
Affiliation Subtype:	NNN
Company Name:	AMOCO SERVICE STATION
Contact Type:	Not reported
Contact Name:	ALAM PETROLEUM INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361319
Program Number:	1-000189
Facility Type:	Mail Contact
Affiliation Type:	07
Affiliation Subtype:	NNN
Company Name:	LEON PETROLEUM LLC

AMOCO - CARLE PLACE SERVICE STATION (Continued) **U003913583**

Contact Type:	Not reported
Contact Name:	ALLEN LEON
Address1:	532 BROADHOLLOW ROAD
Address2:	Not reported
City:	MELVILLE
State:	NY
Zip Code:	11747
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361319
Program Number:	1-000189
Facility Type:	Owner
Affiliation Type:	01
Affiliation Subtype:	E
Company Name:	LEON PETROLEUM LLC
Contact Type:	Not reported
Contact Name:	ALLEN LEON
Address1:	532 BROADHOLLOW ROAD
Address2:	Not reported
City:	MELVILLE
State:	NY
Zip Code:	11747
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361319
Program Number:	1-000189
Facility Type:	Emergency Contact
Affiliation Type:	11
Affiliation Subtype:	NNN
Company Name:	LEON PETROLEUM LLC
Contact Type:	Not reported
Contact Name:	FAISAL CHOUDHRY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 365-0080
Phone Ext:	CELL
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

AMOCO - CARLE PLACE SERVICE STATION (Continued) **U003913583**

UST_AST_PBS_BSEQUIP:

Site Id:	361319
Tank Id Number:	210597
Tank Number:	1
Equipment:	H05
Code Name:	In-Tank System (ATG)
Type:	Tank Leak Detection

Site Id:	361319
Tank Id Number:	210600
Tank Number:	4
Equipment:	B00
Code Name:	None
Type:	Tank External Protection

Site Id:	361319
Tank Id Number:	210599
Tank Number:	3
Equipment:	B00
Code Name:	None
Type:	Tank External Protection

Site Id:	361319
Tank Id Number:	210598
Tank Number:	2
Equipment:	B00
Code Name:	None
Type:	Tank External Protection

Site Id:	361319
Tank Id Number:	210598
Tank Number:	2
Equipment:	H05
Code Name:	In-Tank System (ATG)
Type:	Tank Leak Detection

Site Id:	361319
Tank Id Number:	210597
Tank Number:	1
Equipment:	K01
Code Name:	Catch Basin
Type:	Spill Prevention

Site Id:	361319
Tank Id Number:	210599
Tank Number:	3
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location

Site Id:	361319
Tank Id Number:	210600
Tank Number:	4
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location

AMOCO - CARLE PLACE SERVICE STATION (Continued) **U003913583**

Site Id: 361319
Tank Id Number: 210598
Tank Number: 2
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361319
Tank Id Number: 210599
Tank Number: 3
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361319
Tank Id Number: 210599
Tank Number: 3
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361319
Tank Id Number: 210600
Tank Number: 4
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361319
Tank Id Number: 210599
Tank Number: 3
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 361319
Tank Id Number: 210599
Tank Number: 3
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361319
Tank Id Number: 210600
Tank Number: 4
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361319
Tank Id Number: 210597
Tank Number: 1
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361319

AMOCO - CARLE PLACE SERVICE STATION (Continued) **U003913583**

Tank Id Number: 210597
Tank Number: 1
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361319
Tank Id Number: 210600
Tank Number: 4
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 361319
Tank Id Number: 210599
Tank Number: 3
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361319
Tank Id Number: 210600
Tank Number: 4
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361319
Tank Id Number: 210597
Tank Number: 1
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 361319
Tank Id Number: 210597
Tank Number: 1
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361319
Tank Id Number: 210600
Tank Number: 4
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361319
Tank Id Number: 210597
Tank Number: 1
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 361319
Tank Id Number: 210598

AMOCO - CARLE PLACE SERVICE STATION (Continued) **U003913583**

Tank Number: 2
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 361319
Tank Id Number: 210598
Tank Number: 2
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361319
Tank Id Number: 210598
Tank Number: 2
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361319
Tank Id Number: 210598
Tank Number: 2
Equipment: J01
Code Name: Submersible
Type: Dispenser

NCFM UST:
Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 6000
Tank Contents: LOW UNLEADED GASOLINE

Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 6000
Tank Contents: LOW UNLEADED GASOLINE

Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 8000
Tank Contents: MIDDLE UNLEADED GASOLINE

Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 8000
Tank Contents: HIGH UNLEADED GASOLINE

Tank Type: OUTDOOR UG HOR ON STILT
Tank Size: 100
Tank Contents: LPG

Tank Type: OUTDOOR UG HOR ON STILT
Tank Size: 100
Tank Contents: LPG

Tank Type: OUTDOOR UG HOR ON STILT
Tank Size: 100
Tank Contents: LPG

Tank Type: OUTDOOR UG HOR ON STILT
Tank Size: 100

AMOCO - CARLE PLACE SERVICE STATION (Continued) **U003913583**

Tank Contents: LPG

B19 **INACTIVE** **UST** **U003846272**
NNW **360 OLD COUNTRY RD** **N/A**
< 1/8 **CARLE PLACE, NY 11514**
0.004 mi.
22 ft. **Site 6 of 9 in cluster B**

Relative:
Higher

Actual:
94 ft.

NCFM UST:
Tank Type: OUTDOOR UG HOR STEEL
Tank Size: 3000
Tank Contents: EMPTY

Tank Type: OUTDOOR UG HOR STEEL
Tank Size: 3000
Tank Contents: EMPTY

Tank Type: OUTDOOR UG HOR STEEL
Tank Size: 4000
Tank Contents: EMPTY

E20 **LEVITZ FURNITURE** **MANIFEST** **1009234867**
WSW **895 E GATE BOULEVARD** **N/A**
< 1/8 **GARDEN CITY, NY 11530**
0.006 mi.
32 ft. **Site 1 of 2 in cluster E**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:

EPA ID:	NYP000947143
Country:	USA
Mailing Name:	LEVITZ FURNITURE
Mailing Contact:	WILLIAM SEERY
Mailing Address:	90 PRICE PKWY
Mailing Address 2:	Not reported
Mailing City:	FARMINGDALE
Mailing State:	NY
Mailing Zip:	11735
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	516-682-4926

Document ID:	NJA2925136
Manifest Status:	Not reported
Trans1 State ID:	NYD980761191
Trans2 State ID:	NYD980761191
Generator Ship Date:	06/14/2000
Trans1 Recv Date:	06/14/2000
Trans2 Recv Date:	06/23/2000
TSD Site Recv Date:	07/03/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP000947143
Trans1 EPA ID:	NJD002200046
Trans2 EPA ID:	Not reported
TSDF ID:	S50060

LEVITZ FURNITURE (Continued) **1009234867**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00495
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	009
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	00
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

E21
WSW
< 1/8
0.006 mi.
32 ft.

LEVITZ FURNITURE **NY Spills** **S106015757**
895 EAST GATE BOULEVARD **N/A**
WESTBURY, NY

Site 2 of 2 in cluster E

Relative:
Higher

Actual:
88 ft.

NY Spills:

Site ID:	176154
Facility Addr2:	Not reported
Facility ID:	0303564
Spill Number:	0303564
Facility Type:	ER
SWIS:	3000
Investigator:	UNASSIGNED
Referred To:	Not reported
Spill Date:	7/4/2003
Reported to Dept:	7/5/2003
CID:	266
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/7/2003

LEVITZ FURNITURE (Continued) **S106015757**

Remediation Phase:	0
Date Entered In Computer:	7/5/2003
Spill Record Last Update:	7/8/2003
Spiller Name:	Not reported
Spiller Company:	TASHIRA JIMENEZ
Spiller Address:	61-41 170TH ST, 3RD FLOOR
Spiller City,St,Zip:	FRESH MEADOWS, NY 11365-
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	148050
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE" UNABLE TO CONTACT CHERNOW DURING AFTER HOUR. SINCE SPILL WAS THE DAY BEFORE, IT DOES NOT APPEAR TO REQUIRE ANY RESPONSE, NO CELL PHONE NUMBER WAS LEFT
Remarks:	SPILLER HIT AN UNKNOWN OBJECT IN THE ROAD, BREAKING THE FUEL LINE. SPILLED ONTO PAVEMENT. LESS THAN A QUART MAY HAVE GONE INTO A STORM DRAIN. SPILL ON PAVEMENT WAS CLEANED UP.

Material:

Site ID:	176154
Operable Unit ID:	871614
Operable Unit:	01
Material ID:	552442
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3
Units:	Gallons
Recovered:	3
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

F22
WSW
< 1/8
0.008 mi.
40 ft.

PEPCOM INDUSTRIES
867 EAST GATE BLVD
EAST GARDEN CITY, NY 11530

Site 1 of 4 in cluster F

Relative: Lower

Actual: 84 ft.

UST **U003847620**
N/A

NCFM UST:

Tank Type:	OUTDOOR UG HOR STEEL
Tank Size:	2000
Tank Contents:	EMPTY
Tank Type:	OUTDOOR UG HOR STEEL
Tank Size:	8000
Tank Contents:	EMPTY

F23
WSW
< 1/8
0.008 mi.
40 ft.

PEPSI COLA CO
867 EAST GATE BLVD
GARDEN CITY, NY

Site 2 of 4 in cluster F

Relative: Lower

Actual: 84 ft.

LTANKS **S102659803**
HIST LTANKS **N/A**

LTANKS:

Site ID:	253524
Spill No:	9008243
Spill Date:	10/29/1990
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	2/20/1991
Facility Addr2:	Not reported
Cleanup Ceased:	2/20/1991
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	KMYAGER
Referred To:	Not reported
Reported to Dept:	10/29/1990
CID:	04
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	10/30/1990
Spill Record Last Update:	2/21/1991
Spiller Name:	Not reported
Spiller Company:	PEPSI COLA CO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	207683
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEROSA" 02/20/91: PASSED RETEST 1/29/91 AT -.027 & ORIGINAL FAILURE DUE TO AIR POCKET,NO FURTHER ACTION.
Remarks:	SUSPECT AIR POCKET, COMPANY TO EXCAVATE AND RETEST. 8K GROSS LEAK. TYREE TESTER

PEPSI COLA CO (Continued) **S102659803**

Material:

Site ID:	253524
Operable Unit ID:	945460
Operable Unit:	01
Material ID:	432077
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	253524
Spill Tank Test:	1537782
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

HIST LTANKS:

Region of Spill:	1
Spill Number:	9008243
Spill Date:	10/29/1990
Spill Time:	13:30
Spill Cause:	Tank Test Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	02/20/91
Cleanup Ceased:	02/20/91
Cleanup Meets Standard:	True
Investigator:	DEROSA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	10/29/90
Reported to Department Time:	14:56
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

PEPSI COLA CO (Continued) **S102659803**

Spiller Name: PEPSI COLA CO
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (516) 228-8790
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/30/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 02/21/91
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 02/20/91: PASSED RETEST 1/29/91 AT -.027 ORIGINAL FAILURE DUE TO AIR POCKET,NO FURTHER ACTION.
Spill Cause: SUSPECT AIR POCKET, COMPANY TO EXCAVATE AND RETEST. 8K GROSS LEAK. TYREE TESTER

F24 **MEADOWBROOK DIST. CORP.** **UST** **U003534243**
WSW **867 E. GATE BLVD.** **N/A**
< 1/8 **GARDEN CITY, NY**
0.008 mi.
40 ft. **Site 3 of 4 in cluster F**

Relative:
Lower

Actual:
84 ft.

NASSAU CO. UST:
Facility ID: 037136
Owner Name: MIDWOOD MANAGEMENT
Owner Address: 60 E. 42ND ST.-STE 1814
Owner City,St,Zip: NEW YORK, NY 10165
Permitee Name: MIDWOOD MANAGEMENT
Permitee Address: 60 E. 42ND ST.

MEADOWBROOK DIST. CORP. (Continued) **U003534243**

Permitee City,St,Zip: NEW YORK, NY 10165

Tank ID:	0003
Tank Location:	Indoors, Belowground
Capacity (Gal):	00006000
Tank Status:	In Service
Tank Material:	Fiberglass Reinforced Plastic
Int Protection:	Internal Lining
Ext Protection:	FIBERGLASS REINFORCED PLASTIC
Piping Type:	Fiberglass
Material Type:	Fresh/Product
Description:	OIL, FUEL #2
Leak Detect:	ELECTRONIC
Containment:	DOUBLE WALL TANK
Product Gauge:	Yes
Dispense Method:	Suction
Fill Type:	Gravity
Install Date:	021991

D25 **NORTHVILLE INDUSTRIES** **NY Spills** **S102091654**
NNW **345 OLD COUNTRY ROAD** **NY Hist Spills** **N/A**
< 1/8 **CARLE PLACE, NY**
0.008 mi.
42 ft. **Site 2 of 4 in cluster D**

Relative:
Higher

Actual:
90 ft.

NY Spills:

Site ID:	125009
Facility Addr2:	Not reported
Facility ID:	9110976
Spill Number:	9110976
Facility Type:	ER
SWIS:	3022
Investigator:	JEHAAS
Referred To:	Not reported
Spill Date:	1/17/1992
Reported to Dept:	1/23/1992
CID:	04
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/10/1997
Remediation Phase:	0
Date Entered In Computer:	1/24/1992
Spill Record Last Update:	10/27/2009
Spiller Name:	Not reported
Spiller Company:	NORTHVILLE INDUSTRIES
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported

NORTHVILLE INDUSTRIES (Continued) **S102091654**

Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	290258
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HAAS WELL"
Remarks:	1/8" OF GASOLINE ON WATER IN WELL #4 TO PASS TEST U/G TANK SYSTEM

Material:

Site ID:	125009
Operable Unit ID:	961092
Operable Unit:	01
Material ID:	416046
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9110976
Investigator:	HAAS WELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	01/17/1992 12:00
Reported to Dept Date/Time:	01/23/92 15:20
SWIS:	28
Spiller Name:	NORTHVILLE INDUSTRIES
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Unknown
Reported to Dept:	Groundwater
Water Affected:	Not reported
Spill Source:	12

NORTHVILLE INDUSTRIES (Continued) **S102091654**

Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/10/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/24/92
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/13/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 11/13/97 INACTIVE
Remark: 1/8 OF GASOLINE ON WATER IN WELL 4 TO PASS TEST U/G TANK SYSTEM

D26 **CP S/S OPERATING CORP** **NY Spills** **S104284588**
NNW **345 OLD COUNTRY ROAD** **NY Hist Spills** **N/A**
< 1/8 **CARLE PLACE, NY**
0.008 mi.
42 ft. **Site 3 of 4 in cluster D**

Relative:
Higher

Actual:
90 ft.

NY Spills:
Site ID: 125010
Facility Addr2: Not reported
Facility ID: 9925412
Spill Number: 9925412
Facility Type: ER
SWIS: 3022
Investigator: KMYAGER
Referred To: Not reported
Spill Date: 5/27/1998

CP S/S OPERATING CORP (Continued) **S104284588**

Reported to Dept:	11/24/1999
CID:	04
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	True
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	Not Closed
Remediation Phase:	5
Date Entered In Computer:	12/7/1999
Spill Record Last Update:	9/13/2007
Spiller Name:	ERNIE ROSSANO
Spiller Company:	CP S/S OPERATING CORP
Spiller Address:	345 OLD COUNTRY ROAD
Spiller City,St,Zip:	CARLE PLACE, NY 11747-
Spiller Company:	001
Contact Name:	ERNIE ROSSANO
Contact Phone:	(516) 921-4300
DEC Region:	1
DER Facility ID:	290258
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "YAGER 99-129"
Remarks:	NORTHVILLE HAD REMEDIATED PETROLEUM SPILL 91-10976 AND RECEIVED A NFA LETTER 11/3/97. WATER QUALITY SAMPLING PERFORMED BY C.P. SERVICE STATION OPERATING CORP. (FORMER TARTAN OIL CORP.) DETECTED HIGH DISSOLVED GASOLINE CONST. NORTHVILLE AND C.P. S/S JOINTLY INVESTIGATED THE SITUATION AND RESTARTED THE OLD REMEDIATION SYSTEM. FURTHER EVALUATION BY NORTHVILLE RESULTED IN NORTHVILLE REQUESTING NYSDEC REQUIRE C.P. TO TAKE SOLE RESPONCE. NYSDEC EVALUATED DATA PRESENTED BY NORTHVILLE AND ISSUED NEW SPILL NUMBER.

Material:

Site ID:	125010
Operable Unit ID:	1089771
Operable Unit:	01
Material ID:	566224
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported

CP S/S OPERATING CORP (Continued) **S104284588**

Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 1
Spill Number: 9925412
Investigator: YAGER 99-129
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/27/1998 12:00
Reported to Dept Date/Time: 11/24/99 12:00
SWIS: 28
Spiller Name: CP S/S OPERATING CORP
Spiller Contact: ERNIE ROSSANO
Spiller Phone: (516) 921-4300
Spiller Contact: ERNIE ROSSANO
Spiller Phone: (516) 921-4300
Spiller Address: 345 OLD COUNTRY ROAD
Spiller City,St,Zip: CARLE PLACE, NY 11747-
Spill Cause: Unknown
Reported to Dept: Groundwater
Water Affected: Not reported
Spill Source: 05
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 12/07/99
Date Spill Entered In Computer Data File: 18:18
Update Date: 10/01/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported

CP S/S OPERATING CORP (Continued) **S104284588**

Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Remark: NORTHVILLE HAD REMEDIATED PETROLEUM SPILL 91-10976 AND RECEIVED A NFA LETTER 11/3/97. WATER QUALITY SAMPLING PERFORMED BY C.P. SERVICE STATION OPERATING CORP. FORMER TARTAN OIL CORP.) DETECTED HIGH DISSOLVED GASOLINE CONST. NORTHVILLE AND C.P. S/SJOINTLY INVESTIGATED THE SITUATION AND RESTARTED THE OLD REMEDIATION SYSTEM. FURTHER EVALUATION BY NORTHVILLE RESULTED IN NORTHVILLE REQUESTING NYSDEC REQUIRE C.P. TO TAKE SOLE RESPONCE. NYSDEC EVALUATED DATA PRESENTED BY NORTHVILLE AND ISSUED NEW SPILL NUMBER.

D27 **NORTHVILLE GASOLINE CORP** **LTANKS** **S104513901**
NNW **345 OLD COUNTRY ROAD** **HIST LTANKS** **N/A**
< 1/8 **CARLE PLACE, NY**
0.008 mi.
42 ft. **Site 4 of 4 in cluster D**

Relative:
Higher

Actual:
90 ft.

LTANKS:
Site ID: 125008
Spill No: 8808020
Spill Date: 12/8/1988
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Not reported
Spill Closed Dt: 1/6/1989
Facility Addr2: Not reported
Cleanup Ceased: 1/6/1989
Cleanup Meets Standard: True
SWIS: 3022
Investigator: KDGOERTZ
Referred To: Not reported
Reported to Dept: 1/6/1989
CID: 04
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1/10/1989
Spill Record Last Update: 5/24/2006
Spiller Name: Not reported
Spiller Company: NORTHVILLE GASOLINE CORP
Spiller Address: 35 PINELAWN ROAD
Spiller City,St,Zip: MELVILLE, NY 11747

NORTHVILLE GASOLINE CORP (Continued) **S104513901**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	290258
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GOERTZ FD" 01/06/89: F&N RETESTED SYSTEM ON 12/19/88 AFTER REMOVING OLD STAGE II LINES & SYSTEM PASSED.DEC NOT PRESENT DURING RETEST.DEC NOT PRESENT DURING RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	WERE NOT NOTIFIED UNTIL DEPARTMENT.

Material:

Site ID:	125008
Operable Unit ID:	924467
Operable Unit:	01
Material ID:	452786
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	125008
Spill Tank Test:	1535059
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

HIST LTANKS:

Region of Spill:	1
Spill Number:	8808020
Spill Date:	12/08/1988
Spill Time:	12:00
Spill Cause:	Tank Test Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Gas Station
Spill Class:	Not reported
Spill Closed Dt:	01/06/89
Cleanup Ceased:	01/06/89
Cleanup Meets Standard:	True
Investigator:	GOERTZ FD
Caller Name:	Not reported

NORTHVILLE GASOLINE CORP (Continued) **S104513901**

Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	01/06/89
Reported to Department Time:	12:00
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NORTHVILLE GASOLINE CORP
Spiller Address:	35 PINELAWN ROAD
Spiller City,St,Zip:	MELVILLE, NY 11747
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	Not reported
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	True
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	01/10/89
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	01/12/00
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	0
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	GASOLINE
Class Type:	GASOLINE
Times Material Entry In File:	21329
CAS Number:	Not reported
Last Date:	19940929
DEC Remarks:	01/06/89: F N RETESTED SYSTEM ON 12/19/88 AFTER REMOVING OLD STAGE II LINES SYSTEM PASSED.DEC NOT PRESENT DURING RETEST.DEC NOT PRESENT DURING RETEST.
Spill Cause:	WERE NOT NOTIFIED UNTIL DEPARTMENT.

F28
WSW
< 1/8
0.008 mi.
42 ft.

Relative:
Lower

Actual:
84 ft.

NATIONAL HELICOPTER
NORTH AVE & E GATE
GARDEN CITY, NY 11530

Site 4 of 4 in cluster F

RCRA-NonGen
FINDS
LTANKS
HIST LTANKS
MANIFEST
NY Spills
NY Hist Spills

1000151601
NYD052789716

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	NATIONAL HELICOPTER
Facility address:	NORTH AVE & E GATE GARDEN CITY, NY 11530
EPA ID:	NYD052789716
Mailing address:	E 47TH ST NEW YORK, NY 10017
Contact:	Not reported
Contact address:	E 47TH ST NEW YORK, NY 10017
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CORPORATE PROPERTY INVESTORS
Owner/operator address:	305 E 47TH ST NEW YORK, NY 10017
Owner/operator country:	US
Owner/operator telephone:	(212) 421-8200
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	CORPORATE PROPERTY INVESTORS
Owner/operator address:	305 E 47TH ST NEW YORK, NY 10017
Owner/operator country:	US
Owner/operator telephone:	(212) 421-8200
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Unknown
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown

NATIONAL HELICOPTER (Continued) **1000151601**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NATIONAL HELICOPTER
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: NATIONAL HELICOPTER
Classification: Not a generator, verified

Date form received by agency: 12/19/1994
Facility name: NATIONAL HELICOPTER
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/10/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110008002856

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LTANKS:
Site ID: 217287
Spill No: 8705037
Spill Date: 9/16/1987
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 11/25/1987
Facility Addr2: Not reported
Cleanup Ceased: 11/25/1987
Cleanup Meets Standard: True
SWIS: 3020

NATIONAL HELICOPTER (Continued) **1000151601**

Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	9/16/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	9/23/1987
Spill Record Last Update:	10/18/2006
Spiller Name:	Not reported
Spiller Company:	ISLAND HELICOPTER
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	293158
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GOERTZ FD" / / : ISLAND PUMP & TANK TO UNCOVER.AFTER GASKETS ON THE MANWAY WERE REPLACED,SYSTEM PASSED RETEST ON 9/22/87. DEC NOT PRESENT DURING RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	1-10K TANK LEAK RATE -.161 GPH

Material:

Site ID:	217287
Operable Unit ID:	911341
Operable Unit:	01
Material ID:	467641
Material Code:	0011
Material Name:	Jet Fuel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	217287
Spill Tank Test:	1531641
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

NATIONAL HELICOPTER (Continued) **1000151601**

HIST LTANKS:

Region of Spill:	1
Spill Number:	8705037
Spill Date:	09/16/1987
Spill Time:	16:15
Spill Cause:	Tank Test Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	11/25/87
Cleanup Ceased:	11/25/87
Cleanup Meets Standard:	True
Investigator:	GOERTZ FD
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	09/16/87
Reported to Department Time:	17:43
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	ISLAND HELICOPTER
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(516) 228-9355
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	True
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	09/23/87
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	03/03/99
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

NATIONAL HELICOPTER (Continued) **1000151601**

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: JET FUEL
Class Type: JET FUEL
Times Material Entry In File: 1264
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: / / : ISLAND PUMP TANK TO UNCOVER. / / : ISLAND PUMP TANK TO UNCOVER.AFTER GASKETS ON THE MANWAY WERE REPLACED,SYSTEM PASSED RETEST ON 9/22/87. DEC NOT PRESENT DURING RETEST.
Spill Cause: 1-10K TANK LEAK RATE -.161 GPH

NY MANIFEST:
EPA ID: NYD052789716
Country: USA
Mailing Name: ISLAND HELICOPTER
Mailing Contact: PATRICK E MALLEN
Mailing Address: NORTH AVENUE HELIPORT
Mailing Address 2: Not reported
Mailing City: GARDEN CITY
Mailing State: NY
Mailing Zip: 11530
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 516-228-9355

Document ID: NYB2071764
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: HL4120
Trans2 State ID: Not reported
Generator Ship Date: 901113
Trans1 Recv Date: 901113
Trans2 Recv Date: Not reported
TSD Site Recv Date: 901114
Part A Recv Date: 910404
Part B Recv Date: 901212
Generator EPA ID: NYD052789716
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429
Waste Code: F003 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 111
Waste Code: Not reported
Quantity: 00400
Units: G - Gallons (liquids only)* (8.3 pounds)

NATIONAL HELICOPTER (Continued) **1000151601**

Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	117
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB5368509
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	T662KBOH
Trans2 State ID:	Not reported
Generator Ship Date:	930603
Trans1 Recv Date:	930603
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	930616
Part A Recv Date:	930709
Part B Recv Date:	930707
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	OHD009865825
Trans2 EPA ID:	Not reported
TSDF ID:	GAD093380814
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)

NATIONAL HELICOPTER (Continued) **1000151601**

Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	93
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA5689503
Manifest Status:	Completed copy
Trans1 State ID:	NY1A8036
Trans2 State ID:	Not reported
Generator Ship Date:	880322
Trans1 Recv Date:	880322
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880323
Part A Recv Date:	880329
Part B Recv Date:	880329
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00032
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	087
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Year:	88
Manifest Tracking Num:	Not reported
Import Ind:	Not reported

NATIONAL HELICOPTER (Continued) **1000151601**

Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	CTF0345516
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	XG2539NY
Trans2 State ID:	Not reported
Generator Ship Date:	950127
Trans1 Recv Date:	950127
Trans2 Recv Date:	950131
TSD Site Recv Date:	950202
Part A Recv Date:	Not reported
Part B Recv Date:	950223
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD173735192
Trans2 EPA ID:	Not reported
TSDF ID:	MAD053452637
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA3025765
Manifest Status:	Completed copy
Trans1 State ID:	21635GT
Trans2 State ID:	Not reported
Generator Ship Date:	861028
Trans1 Recv Date:	861028
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861029
Part A Recv Date:	861103

NATIONAL HELICOPTER (Continued) **1000151601**

Part B Recv Date:	861106
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00035
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086
Waste Code:	Not reported
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	081
Year:	86
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA3025776
Manifest Status:	Completed copy
Trans1 State ID:	21635GT
Trans2 State ID:	Not reported
Generator Ship Date:	861028
Trans1 Recv Date:	861028
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861029
Part A Recv Date:	861106
Part B Recv Date:	861107
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	86
Manifest Tracking Num:	Not reported

NATIONAL HELICOPTER (Continued) **1000151601**

Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA5146479
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	880128
Trans1 Recv Date:	880128
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880129
Part A Recv Date:	880203
Part B Recv Date:	880204
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00180
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Year:	88
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA5348223
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NY1A8036
Trans2 State ID:	Not reported
Generator Ship Date:	880520
Trans1 Recv Date:	880520
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880523

NATIONAL HELICOPTER (Continued) **1000151601**

Part A Recv Date:	880706
Part B Recv Date:	880527
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	099
Waste Code:	Not reported
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	097
Year:	88
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7029333
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890823
Trans1 Recv Date:	890823
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890823
Part A Recv Date:	890830
Part B Recv Date:	890829
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES

NATIONAL HELICOPTER (Continued) **1000151601**

Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Waste Code:	Not reported
Quantity:	00095
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	098
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA3053744
Manifest Status:	Completed copy
Trans1 State ID:	7218R7
Trans2 State ID:	Not reported
Generator Ship Date:	860822
Trans1 Recv Date:	860822
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860822
Part A Recv Date:	860827
Part B Recv Date:	860827
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD981185903
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	02140
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	86

NATIONAL HELICOPTER (Continued) **1000151601**

Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA3025517
Manifest Status:	Completed copy
Trans1 State ID:	21635GT
Trans2 State ID:	Not reported
Generator Ship Date:	861021
Trans1 Recv Date:	861021
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861022
Part A Recv Date:	861103
Part B Recv Date:	861024
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	080
Waste Code:	Not reported
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	105
Waste Code:	Not reported
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	118
Year:	86

NATIONAL HELICOPTER (Continued) **1000151601**

Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA6258834
Manifest Status:	Completed copy
Trans1 State ID:	NY8385-RW
Trans2 State ID:	Not reported
Generator Ship Date:	870508
Trans1 Recv Date:	870508
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870508
Part A Recv Date:	870514
Part B Recv Date:	870514
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	082
Waste Code:	Not reported
Quantity:	00495
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	009
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Year:	87
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported

NATIONAL HELICOPTER (Continued) **1000151601**

Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA6258348
Manifest Status:	Completed copy
Trans1 State ID:	NY8385RW
Trans2 State ID:	Not reported
Generator Ship Date:	870410
Trans1 Recv Date:	870410
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870410
Part A Recv Date:	870417
Part B Recv Date:	870417
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	098
Year:	87
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA3025506
Manifest Status:	Completed copy
Trans1 State ID:	21635GT
Trans2 State ID:	Not reported
Generator Ship Date:	861021
Trans1 Recv Date:	861021
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861022
Part A Recv Date:	861030
Part B Recv Date:	861024
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429

NATIONAL HELICOPTER (Continued) **1000151601**

Waste Code:	D004 - ARSENIC 5.0 MG/L TCLP
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	098
Year:	86
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7029324
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890314
Trans1 Recv Date:	890314
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890314
Part A Recv Date:	890317
Part B Recv Date:	890320
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00550
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Waste Code:	Not reported
Quantity:	00400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	098
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	084

NATIONAL HELICOPTER (Continued) **1000151601**

Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	105
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB4997124
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	940330
Trans1 Recv Date:	940330
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940411
Part A Recv Date:	940418
Part B Recv Date:	940429
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	OHD009865825
Trans2 EPA ID:	Not reported
TSDF ID:	GAD093380814
Waste Code:	F003 - UNKNOWN
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

NATIONAL HELICOPTER (Continued) **1000151601**

Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7098966
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	880930
Trans1 Recv Date:	880930
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880930
Part A Recv Date:	881011
Part B Recv Date:	881006
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Waste Code:	Not reported
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	103
Year:	88
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported

NATIONAL HELICOPTER (Continued) **1000151601**

Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2104272
Manifest Status:	Completed copy
Trans1 State ID:	MV6352
Trans2 State ID:	Not reported
Generator Ship Date:	900319
Trans1 Recv Date:	900319
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900319
Part A Recv Date:	900411
Part B Recv Date:	900409
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	F003 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	111
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	098
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	117
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	110
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported

NATIONAL HELICOPTER (Continued) **1000151601**

Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA5190642
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NY8385-RW
Trans2 State ID:	Not reported
Generator Ship Date:	870709
Trans1 Recv Date:	870709
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870713
Part A Recv Date:	870910
Part B Recv Date:	870715
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Waste Code:	Not reported
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	086
Year:	87
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA7029315
Manifest Status:	Completed copy
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890619
Trans1 Recv Date:	890619

NATIONAL HELICOPTER (Continued) **1000151601**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890620
Part A Recv Date:	890623
Part B Recv Date:	890622
Generator EPA ID:	NYD052789716
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	083
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	103
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional NY_MANIFEST: record(s) in the EDR Site Report.

NY Spills:

Site ID:	217290
Facility Addr2:	Not reported
Facility ID:	9409256
Spill Number:	9409256
Facility Type:	ER
SWIS:	3020
Investigator:	BPAUSTIN
Referred To:	Not reported
Spill Date:	10/11/1994
Reported to Dept:	10/11/1994
CID:	Not reported
Spill Cause:	Abandoned Drums
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

NATIONAL HELICOPTER (Continued) **1000151601**

Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	6/1/2005
Remediation Phase:	0
Date Entered In Computer:	10/12/1994
Spill Record Last Update:	6/2/2005
Spiller Name:	Not reported
Spiller Company:	ISLAND HELICOPTER
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	293158
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN" / / : SAME AS 93-11930. TANKS AND 300 YARDS CONTAMINATED SOIL REMOVED, ENDPOINT SAMPLES IN SOIL AND GROUNDWATER- NFA
Remarks:	AT COMMERCIAL TANK SITE, DURING TANK REMOVAL AT SITE, ENCOUNTERED CONTAMINATION IN SOIL, NCFM & DEC WERE ON SITE,

Material:

Site ID:	217290
Operable Unit ID:	1003219
Operable Unit:	01
Material ID:	378679
Material Code:	0012
Material Name:	Kerosene (#1 Fuel Oil)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9409256
Investigator:	AUSTIN
Caller Name:	Not reported

NATIONAL HELICOPTER (Continued) **1000151601**

Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 10/11/1994 13:00
Reported to Dept Date/Time: 10/11/94 17:20
SWIS: 28
Spiller Name: ISLAND HELICOPTER
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Abandoned Drums
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Citizen
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/12/94
Date Spill Entered In Computer Data File: Not reported
Update Date: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: KEROSENE
Class Type: KEROSENE
Times Material Entry In File: 2052
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: / / : SAME AS 93-11930.

NATIONAL HELICOPTER (Continued) **1000151601**

Remark: AT COMMERCIAL TANK SITE, DURING TANK REMOVAL AT SITE, ENCOUNTERED CONTAMINATION IN SOIL, NCFM DEC WERE ON SITE,

---

29 **MAGNACARE / ELLIPSE BUILDING** **AST** **A100300406**
WSW **825 EAST GATE BLVD** **N/A**
< 1/8 **EAST GARDEN CITY, NY 11530**
0.009 mi.
47 ft.

Relative:
Higher

Actual:
86 ft.

NCFM AST:
Tank Type: OUTDOOR AG HOR STEEL
Tank Size: 750
Contents: DIESEL

---

30 **JOHN GRAYSON RESIDENCE** **NY Spills** **S102661271**
NNW **14 MITCHEL AVENUE** **NY Hist Spills** **N/A**
< 1/8 **CARLE PLACE, NY**
0.024 mi.
126 ft.

Relative:
Higher

Actual:
91 ft.

NY Spills:

Site ID:	128360
Facility Addr2:	Not reported
Facility ID:	9308329
Spill Number:	9308329
Facility Type:	ER
SWIS:	3000
Investigator:	ACLAMANN
Referred To:	Not reported
Spill Date:	10/8/1993
Reported to Dept:	10/8/1993
CID:	04
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/16/1997
Remediation Phase:	0
Date Entered In Computer:	10/12/1993
Spill Record Last Update:	5/19/1997
Spiller Name:	Not reported
Spiller Company:	JOHN GRAYSON RESIDENCE
Spiller Address:	14 MITCHEL AVENUE
Spiller City,St,Zip:	CARLE PLACE, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	110747

JOHN GRAYSON RESIDENCE (Continued) **S102661271**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "LAMANNO" SITE CHECKED GIFFORD OIL CONTACTED TO CLEANUP
Remarks: SPILL ON PAVEMENT & SOIL UNDER FILL

Material:
Site ID: 128360
Operable Unit ID: 986995
Operable Unit: 01
Material ID: 394559
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 1
Spill Number: 9308329
Investigator: LAMANNO
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 10/08/1993 14:09
Reported to Dept Date/Time: 10/08/93 15:57
SWIS: 28
Spiller Name: JOHN GRAYSON RESIDENCE
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: 14 MITCHEL AVENUE
Spiller City,St,Zip: CARLE PLACE
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /

JOHN GRAYSON RESIDENCE (Continued) **S102661271**

Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/16/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/12/93
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/19/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: SITE CHECKED GIFFORD OIL CONTACTED TO CLEANUP
Remark: SPILL ON PAVEMENT SOIL UNDER FILL

B31 **WAL-MART #3420** **RCRA-CESQG 1004762045**
ENE **1220 OLD COUNTRY RD** **FINDS NYR000092981**
< 1/8 **WESTBURY, NY 11590** **MANIFEST**
0.029 mi.
151 ft. **Site 7 of 9 in cluster B**

Relative:
Higher

Actual:
97 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: WAL-MART #3420
Facility address: 1220 OLD COUNTRY RD
WESTBURY, NY 11590
EPA ID: NYR000092981
Mailing address: SW 8TH ST DEPT 8916
BENTONVILLE, AR 727160500
Contact: DIANE GRAY
Contact address: SW 8TH ST DEPT 8916
BENTONVILLE, AR 727160500
Contact country: US
Contact telephone: (479) 204-2224

WAL-MART #3420 (Continued) **1004762045**

Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: WAL-MART STORES EAST LP
Owner/operator address: COUNTRY RD
WESTBURY, NY 11590
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/31/2004
Owner/Op end date: Not reported

Owner/operator name: KMART
Owner/operator address: 3100 W BIG BEAVER
TROY, MI 48084
Owner/operator country: US
Owner/operator telephone: (248) 643-1000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: WAL-MART STORES EAST LP
Owner/operator address: SW 8TH ST
BENTONVILLE, AR 72716
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/31/2004
Owner/Op end date: Not reported

Owner/operator name: KMART
Owner/operator address: 3100 W BIG BEAVER
TROY, MI 48084
Owner/operator country: Not reported
Owner/operator telephone: (248) 643-1000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/0001

WAL-MART #3420 (Continued) **1004762045**

Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: WAL-MART #3420
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/13/2004
Facility name: WAL-MART #3420
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/28/2000
Facility name: WAL-MART #3420
Site name: BIG KMART 7475
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D011
Waste name: SILVER

Waste code: K062
Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Waste code: P022
Waste name: CARBON DISULFIDE

Waste code: U052
Waste name: CRESOL (CRESYLIC ACID)

Waste code: U122
Waste name: FORMALDEHYDE

Waste code: U154
Waste name: METHANOL (I)

Waste code: U165

WAL-MART #3420 (Continued) **1004762045**

Waste name: NAPHTHALENE

Waste code: U201
Waste name: 1,3-BENZENEDIOL

Waste code: U211
Waste name: CARBON TETRACHLORIDE

Waste code: U220
Waste name: BENZENE, METHYL-

Violation Status: No violations found

FINDS:

Registry ID: 110004566345

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYR000092981
Country:	USA
Mailing Name:	WALMART #3420
Mailing Contact:	ANDRE CARTER
Mailing Address:	1220 OLD COUNTRY RD
Mailing Address 2:	ATTN: CLAIMS ASSOCIATE
Mailing City:	WESTBURY
Mailing State:	NY
Mailing Zip:	11590
Mailing Zip4:	5624
Mailing Country:	USA
Mailing Phone:	516-683-8030

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-06-16
Trans1 Recv Date:	2008-06-16
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-06-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	80.0

WAL-MART #3420 (Continued) **1004762045**

Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001501148FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-09-12
Trans1 Recv Date:	2008-09-12
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-09-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	60.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001528442FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported

WAL-MART #3420 (Continued) **1004762045**

Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009865825
Generator Ship Date:	2008-02-12
Trans1 Recv Date:	2008-02-12
Trans2 Recv Date:	2008-02-21
TSD Site Recv Date:	2008-02-25
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NCD000648451
Waste Code:	Not reported
Quantity:	45.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001734772FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-06-16
Trans1 Recv Date:	2008-06-16
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-06-16
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	90.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08

WAL-MART #3420 (Continued) **1004762045**

Manifest Tracking Num:	001501148FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-07-18
Trans1 Recv Date:	2008-07-18
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-07-18
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	8.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001506238FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009865825
Generator Ship Date:	2008-03-05
Trans1 Recv Date:	2008-03-05
Trans2 Recv Date:	2008-03-09

WAL-MART #3420 (Continued) **1004762045**

TSD Site Recv Date:	2008-03-18
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NCD000648451
Waste Code:	Not reported
Quantity:	20.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001734438FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009865825
Generator Ship Date:	2008-04-07
Trans1 Recv Date:	2008-04-07
Trans2 Recv Date:	2008-04-09
TSD Site Recv Date:	2008-04-14
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NCD000648451
Waste Code:	Not reported
Quantity:	35.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001883668FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N

WAL-MART #3420 (Continued) **1004762045**

Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009865825
Generator Ship Date:	2008-05-02
Trans1 Recv Date:	2008-05-02
Trans2 Recv Date:	2008-05-09
TSD Site Recv Date:	2008-05-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NCD000648451
Waste Code:	Not reported
Quantity:	35.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	002099045FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-08-12
Trans1 Recv Date:	2008-08-12
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-08-12
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

WAL-MART #3420 (Continued) **1004762045**

TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	40.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001866269FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	06
Manifest Status:	000600207FLE
Trans1 State ID:	NYR000092981
Trans2 State ID:	Not reported
Generator Ship Date:	NCD000648451
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	MAD039322250
TSD Site Recv Date:	Not reported
Part A Recv Date:	NJD986607386
Part B Recv Date:	2006-12-04
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	30
Handling Method:	P
Specific Gravity:	1
Waste Code:	L
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported

WAL-MART #3420 (Continued) **1004762045**

Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	06
Manifest Status:	000600207FLE
Trans1 State ID:	NYR000092981
Trans2 State ID:	Not reported
Generator Ship Date:	NCD000648451
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	MAD039322250
TSD Site Recv Date:	Not reported
Part A Recv Date:	NJD986607386
Part B Recv Date:	2006-12-04
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	35
Handling Method:	P
Specific Gravity:	1
Waste Code:	L
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0169353
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	08/02/2001

WAL-MART #3420 (Continued) **1004762045**

Trans1 Recv Date:	08/02/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/02/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	12210PA
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00112
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00010
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0199179
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/2001
Trans1 Recv Date:	06/13/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)

WAL-MART #3420 (Continued) **1004762045**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0275265
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	04/02/2003
Trans1 Recv Date:	04/02/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/02/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	23138PA
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00015
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	03
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0179874
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported

WAL-MART #3420 (Continued) **1004762045**

Generator Ship Date:	09/06/2001
Trans1 Recv Date:	09/06/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/06/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0187281
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	09/19/2001
Trans1 Recv Date:	09/19/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/19/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported

WAL-MART #3420 (Continued) **1004762045**

Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0195705
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	08/22/2001
Trans1 Recv Date:	08/22/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/22/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0171207
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	10/03/2001
Trans1 Recv Date:	10/03/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

WAL-MART #3420 (Continued) **1004762045**

Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	6058PB
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0218232
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/2001
Trans1 Recv Date:	02/28/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/28/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported

WAL-MART #3420 (Continued) **1004762045**

Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0183906
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	07/05/2001
Trans1 Recv Date:	07/05/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/05/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000092981
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00030
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	01
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Click this hyperlink while viewing on your computer to access
139 additional NY_MANIFEST: record(s) in the EDR Site Report.

B32 **WAL-MART STORE# 3420** **AST** **A100297743**
ENE **1220 OLD COUNTRY RD** **N/A**
< 1/8 **WESTBURY, NY 11590**
0.029 mi.
151 ft. **Site 8 of 9 in cluster B**

Relative:
Higher

Actual:
97 ft.

NCFM AST:

Tank Type:	INDOOR AG HOR STEEL
Tank Size:	180
Contents:	DIESEL

B33 **UNKNOWN** **NY Spills** **S106011490**
ENE **1230 OLD COUNTRY ROAD** **N/A**
< 1/8 **WESTBURY, NY**
0.045 mi.
238 ft. **Site 9 of 9 in cluster B**

Relative:
Higher

Actual:
99 ft.

NY Spills:

Site ID:	112697
Facility Addr2:	Not reported
Facility ID:	0211374
Spill Number:	0211374
Facility Type:	ER
SWIS:	3022
Investigator:	WJGABIN
Referred To:	Not reported
Spill Date:	2/13/2003
Reported to Dept:	2/14/2003
CID:	04
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt:	7/27/2005
Remediation Phase:	0
Date Entered In Computer:	2/14/2003
Spill Record Last Update:	7/28/2005
Spiller Name:	Not reported
Spiller Company:	JOHN COX
Spiller Address:	322 BARWICK BLVD
Spiller City,St,Zip:	MINEOLA, NY
Spiller Company:	001
Contact Name:	ROBERT DILAVORE
Contact Phone:	(516) 572-1092
DEC Region:	1
DER Facility ID:	98432
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GABIN" 2/19/05 INSPECTED SITE, NO SIGN OF CONT MATERIAL ENCOUNTERED AT THE SITE,
Remarks:	something hit gas tank causing leak fire dept on scene and hazmat unit did clean up

Material:

Site ID:	112697
Operable Unit ID:	864711
Operable Unit:	01
Material ID:	511163
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	10

UNKNOWN (Continued) **S106011490**

Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

G34 **COUNTRY PLAZA SHPNG. CTR.** **UST** **U003377333**
ENE **373-401 OLD COUNTRY RD.** **N/A**
< 1/8 **CARLE PLACE, NY**
0.047 mi.
248 ft. **Site 1 of 4 in cluster G**

Relative:
Higher

Actual:
99 ft.

NASSAU CO. UST:
Facility ID: 055541
Owner Name: COUNTRY PLAZA ASSOCIATES
Owner Address: 393 OLD COUNTRY RD.
Owner City,St,Zip: CARLE PLACE, NY 11514
Permitee Name: SAME
Permitee Address: Not reported
Permitee City,St,Zip: Not reported

Tank ID: 0001
Tank Location: Indoors, Belowground
Capacity (Gal): 00007500
Tank Status: In Service
Tank Material: STEEL
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Material Type: Fresh/Product
Description: OIL, FUEL #2
Leak Detect: NONE
Containment: NONE
Product Gauge: Yes
Dispense Method: Suction
Fill Type: Gravity
Install Date: 051972

H35 **CARLE PLACE SCHOOL DISTRI** **NY Spills** **S103564741**
NNW **16 CHERRY LANE** **NY Hist Spills** **N/A**
< 1/8 **CARLE PLACE, NY**
0.068 mi.
358 ft. **Site 1 of 2 in cluster H**

Relative:
Higher

Actual:
94 ft.

NY Spills:

Site ID:	218899
Facility Addr2:	Not reported
Facility ID:	8904497
Spill Number:	8904497
Facility Type:	ER
SWIS:	3022
Investigator:	CXONEILL
Referred To:	Not reported
Spill Date:	8/5/1989
Reported to Dept:	8/5/1989
CID:	04
Spill Cause:	Other
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	8/7/1989
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	8/7/1989
Remediation Phase:	0
Date Entered In Computer:	8/9/1989
Spill Record Last Update:	3/23/2006
Spiller Name:	Not reported
Spiller Company:	CARLE PLACE SCHOOL DISTRI
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	181063
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "O'NEILL FD" 08/07/89: NO EMERGENCY RESPONSE NEEDED. BRING TO ATTENTION OF DIV OF SOL & HAZ WASTE. 10/10/95: This is additional information about material spilled from the translation of the old spill file: FOAM/FIBERGLASS INSU. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	FOAM & FIBERGLASS INSULATION FOR ROOF REPLACEMENT INVOLVED IN STRUCTURAL FIRE, FIRE FIGHTING RUNOFF ON SCHOOL PROPERTY. RUNOFF SINKING INTO GROUND,NON PETROLUEM, NON HAZARDOUS

Material:

Site ID:	Not reported
Operable Unit ID:	Not reported
Operable Unit:	Not reported
Material ID:	Not reported
Material Code:	Not reported
Material Name:	Not reported
Case No.:	Not reported

CARLE PLACE SCHOOL DISTRI (Continued) **S103564741**

Material FA:	Not reported
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	8904497
Investigator:	O'NEILL FD
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	08/05/1989 16:28
Reported to Dept Date/Time:	08/05/89 18:10
SWIS:	28
Spiller Name:	CARLE PLACE SCHOOL DISTRI
Spiller Contact:	Not reported
Spiller Phone:	(516) 997-6942
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Other
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	02
Spill Notifier:	Fire Department
PBS Number:	Not reported
Cleanup Ceased:	08/07/89
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Not reported
Spill Closed Dt:	08/07/89
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /

CARLE PLACE SCHOOL DISTRI (Continued) **S103564741**

Date Spill Entered In Computer Data File: 08/09/89
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/19/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Not reported
Quantity Spilled: Not reported
Unkonwn Quantity Spilled: Not reported
Units: Not reported
Quantity Recovered: Not reported
Unkonwn Quantity Recovered: Not reported
Material: Not reported
Class Type: Not reported
Times Material Entry In File: Not reported
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: 08/07/89: NO EMERGENCY RESPONSE NEEDED. BRING TO ATTENTION OF DIV OF SOL HAZ WASTE. 10/10/95: This is additional information about material spilled from the translation of the old spill file: FOAM/FIBERGLASS INSU.
Remark: FOAM FIBERGLASS INSULATION FOR ROOF REPLACEMENT INVOLVED IN STRUCTURAL FIRE, FIRE FIGHTING RUNOFF ON SCHOOL PROPERTY. RUNOFF SINKING INTO GROUND,NON PETROLUEM, NON HAZARDOUS

G36 **COSTCO WHOLESALE - STORE #226** **AST** **A100198115**
ENE **1250 OLD COUNTRY RD** **N/A**
< 1/8 **WESTBURY, NY 11590**
0.074 mi.
393 ft. **Site 2 of 4 in cluster G**

Relative:
Higher

Actual:
101 ft.

NCFM AST:
Tank Type: OUTDOOR AG HOR STEEL
Tank Size: 500
Contents: DIESEL

G37 **PRICE CLUB 226** **RCRA-NonGen** **1000990673**
ENE **1250 OLD COUNTRY RD** **FINDS** **NY0001039312**
< 1/8 **WESTBURY, NY 11590** **MANIFEST**
0.074 mi.
393 ft. **Site 3 of 4 in cluster G**

Relative:
Higher

Actual:
101 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: PRICE CLUB 226
Facility address: 1250 OLD COUNTRY RD
WESTBURY, NY 115905624
EPA ID: NY0001039312
Mailing address: OLD COUNTRY RD
WESTBURY, NY 11590

PRICE CLUB 226 (Continued) **1000990673**

Contact: Not reported
Contact address: OLD COUNTRY RD
WESTBURY, NY 11590
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PRICE CO
Owner/operator address: 1001 W 19TH ST
NATIONAL CITY, CA 91950
Owner/operator country: US
Owner/operator telephone: (619) 336-6307
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PRICE CO
Owner/operator address: 1001 W 19TH ST
NATIONAL CITY, CA 91950
Owner/operator country: US
Owner/operator telephone: (619) 336-6307
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: PRICE CLUB 226
Classification: Not a generator, verified

Date form received by agency: 07/08/1999

PRICE CLUB 226 (Continued) **1000990673**

Facility name: PRICE CLUB 226
Classification: Not a generator, verified

Date form received by agency: 02/16/1995
Facility name: PRICE CLUB 226
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004324687

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NY0001039312
Country: USA
Mailing Name: PRICE CLUB #226
Mailing Contact: P KOLACK
Mailing Address: 1250 OLD COUNTRY RD
Mailing Address 2: Not reported
Mailing City: WESTBURY
Mailing State: NY
Mailing Zip: 11590
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 516-603-8300

Document ID: NYB6824808
Manifest Status: Completed copy
Trans1 State ID: XC2643
Trans2 State ID: Not reported
Generator Ship Date: 950302
Trans1 Recv Date: 950302
Trans2 Recv Date: Not reported
TSD Site Recv Date: 950302
Part A Recv Date: 950315
Part B Recv Date: 950322
Generator EPA ID: NY0001039312
Trans1 EPA ID: NYD981182769
Trans2 EPA ID: Not reported
TSDF ID: NYD981182769
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: R Material recovery of more than 75 percent of the total material.

PRICE CLUB 226 (Continued) **1000990673**

Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

G38 **COSTCO** **NY Spills** **S102662433**
ENE **1250 OLD COUNTRY ROAD** **NY Hist Spills** **N/A**
< 1/8 **WESTBURY, NY**
0.074 mi.
393 ft. **Site 4 of 4 in cluster G**

Relative:
Higher

Actual:
101 ft.

NY Spills:

Site ID:	142090
Facility Addr2:	Not reported
Facility ID:	9707318
Spill Number:	9707318
Facility Type:	ER
SWIS:	3000
Investigator:	NJACAMPO
Referred To:	Not reported
Spill Date:	9/20/1997
Reported to Dept:	9/22/1997
CID:	04
Spill Cause:	Human Error
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	1/27/2004
Remediation Phase:	0
Date Entered In Computer:	9/22/1997
Spill Record Last Update:	1/31/2004
Spiller Name:	YORAN RUBANENKO
Spiller Company:	COSTCO
Spiller Address:	1250 OLD COUNTRY ROAD
Spiller City,St,Zip:	WESTBURY, NY
Spiller Company:	001
Contact Name:	YORAN RUBANENKO
Contact Phone:	(516) 683-8000 224
DEC Region:	1
DER Facility ID:	121296
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was

COSTCO (Continued) **S102662433**

Remarks:	"ACAMPORA" SPILL WAS ON STORAGE RACK INSIDE OF BLDG. CLEANUP COMPLETED, NO DRAINAGE IMPACTED, ~1/2 DRUM OF WASTE MATERIAL SOMEONE KNOCKED OVER A FORKLIFT BATTERY - ALL CLEANED UP

Material:

Site ID:	142090
Operable Unit ID:	1053690
Operable Unit:	01
Material ID:	332894
Material Code:	0044A
Material Name:	BATTERY ACID
Case No.:	Not reported
Material FA:	Other
Quantity:	4
Units:	Gallons
Recovered:	4
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9707318
Investigator:	ACAMPORA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	09/20/1997 16:00
Reported to Dept Date/Time:	09/22/97 09:54
SWIS:	28
Spiller Name:	COSTCO
Spiller Contact:	YORAN RUBANENKO
Spiller Phone:	(516) 683-8000 224
Spiller Contact:	YORAN RUBANENKO
Spiller Phone:	(516) 683-8000 224
Spiller Address:	1250 OLD COUNTRY ROAD
Spiller City,St,Zip:	WESTBURY, NY
Spill Cause:	Human Error
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	02
Spill Notifier:	Other

COSTCO (Continued) **S102662433**

PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 09/22/97
Date Spill Entered In Computer Data File: Not reported
Update Date: 09/23/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Hazardous Material
Quantity Spilled: 4
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 4
Unkonwn Quantity Recovered: False
Material: BATTERY ACID
Class Type: BATTERY ACID
Times Material Entry In File: 97
CAS Number: Not reported
Last Date: 19940928
DEC Remarks: SPILL WAS ON STORAGE RACK INSIDE OF BLDG. CLEANUP COMPLETED, NO DRAINAGE IMPACTED, 1/2 DRUM OF WASTE MATERIAL
Remark: SOME ONE KNOCKED OVER A FORKLIFT BATTERY - ALL CLEANED UP

I39 **NATIONAL HELICOPTER** **LTANKS** **S101103126**
WSW **NORTH AVENUE** **HIST LTANKS** **N/A**
< 1/8 **GARDEN CITY, NY** **NY Spills**
0.088 mi. **NY Hist Spills**
467 ft. **Site 1 of 2 in cluster I**

Relative:
Lower

Actual:
84 ft.

LTANKS:
Site ID: 217289
Spill No: 9314802
Spill Date: 3/17/1994
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/9/1994
Facility Addr2: Not reported

NATIONAL HELICOPTER (Continued) **S101103126**

Cleanup Ceased:	11/9/1994
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	3/17/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	3/18/1994
Spill Record Last Update:	11/10/1994
Spiller Name:	Not reported
Spiller Company:	NATIONAL HELICOPTER
Spiller Address:	NORTH AVE
Spiller City,St,Zip:	GARDEN CITY, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	179891
DEC Memo:	Not reported
Remarks:	10K FAILED PETROTITE, ISOLATE, EXCAVATE, FM ON SITE, TYREE TESTER

Material:

Site ID:	217289
Operable Unit ID:	996741
Operable Unit:	01
Material ID:	386584
Material Code:	0011
Material Name:	Jet Fuel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	217289
Spill Tank Test:	1542507
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

NATIONAL HELICOPTER (Continued) **S101103126**

HIST LTANKS:

Region of Spill:	1
Spill Number:	9314802
Spill Date:	03/17/1994
Spill Time:	16:00
Spill Cause:	Tank Test Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/09/94
Cleanup Ceased:	11/09/94
Cleanup Meets Standard:	True
Investigator:	T/T/F
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	03/17/94
Reported to Department Time:	16:19
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	NATIONAL HELICOPTER
Spiller Address:	NORTH AVE
Spiller City,St,Zip:	GARDEN CITY
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(516) 228-9355
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	True
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	03/18/94
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	11/10/94
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00

NATIONAL HELICOPTER (Continued) **S101103126**

Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: JET FUEL
Class Type: JET FUEL
Times Material Entry In File: 1264
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: 11/09/94: SYSTEM PASSED RETEST 3/25/94, TANK REMOVED 10/11/94, CONTAMINATION BEING HANDLED UNDER 94-09256.
Spill Cause: 10K FAILED PETROTITE, ISOLATE, EXCAVATE, FM ON SITE, TYREE TESTER

NY Spills:
Site ID: 217288
Facility Addr2: Not reported
Facility ID: 9312360
Spill Number: 9312360
Facility Type: ER
SWIS: 3020
Investigator: GIBBONS
Referred To: Not reported
Spill Date: 1/21/1994
Reported to Dept: 1/21/1994
CID: Not reported
Spill Cause: Deliberate
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: 9/8/1994
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt: 9/8/1994
Remediation Phase: 0
Date Entered In Computer: 1/24/1994
Spill Record Last Update: 5/29/2007
Spiller Name: Not reported
Spiller Company: NATIONAL HELICOPTER
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 1
DER Facility ID: 293158
DEC Memo: Not reported
Remarks: PUTTING CHEMICALS INTO U/G STORAGE TANKS THAT CALLER SAYS ARE LEAKING, CO LEAVING AREA FEB 1/94

NATIONAL HELICOPTER (Continued) **S101103126**

Material:

Site ID:	217288
Operable Unit ID:	994371
Operable Unit:	01
Material ID:	391341
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9312360
Investigator:	GIBBONS
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	01/21/1994 12:00
Reported to Dept Date/Time:	01/21/94 10:10
SWIS:	28
Spiller Name:	NATIONAL HELICOPTER
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Deliberate
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Citizen
PBS Number:	Not reported
Cleanup Ceased:	09/08/94
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended

NATIONAL HELICOPTER (Continued) **S101103126**

Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)
Spill Closed Dt: 09/08/94
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 01/24/94
Date Spill Entered In Computer Data File: Not reported
Update Date: 09/09/94
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: UNKNOWN PETROLEUM
Class Type: UNKNOWN PETROLEUM
Times Material Entry In File: 16414
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: / / : SAME AS 93-11930 PER PETER PAUL.
Remark: PUTTING CHEMICALS INTO U/G STORAGE TANKS THAT CALLER SAYS ARE LEAKING, CO LEAVING AREA FEB 1/94

I40 **NATIONAL HELICOPTER CORP.** **UST** **U003847376**
WSW **435 NORTH AVE** **N/A**
< 1/8 **EAST GARDEN CITY, NY 11530**
0.088 mi.
467 ft. **Site 2 of 2 in cluster I**

Relative:
Lower

Actual:
84 ft.

NCFM UST:
Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 10000
Tank Contents: FUEL, AVIATION TURBINE ENGINE

Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 10000
Tank Contents: FUEL, AVIATION TURBINE ENGINE

J41 **EXXON #70230 DIVISION OF CFI** **UST** **U003968231**
West **285 OLD COUNTRY RD** **N/A**
< 1/8 **CARLE PLACE, NY 11514**
0.091 mi.
481 ft. **Site 1 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

NCFM UST:
Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 10000
Tank Contents: LOW UNLEADED GASOLINE

Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 6000
Tank Contents: HIGH UNLEADED GASOLINE

Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 4000
Tank Contents: MIDDLE UNLEADED GASOLINE

J42 **TOSCO #34747** **MANIFEST** **S109785401**
West **285 OLD COUNTRY RD** **N/A**
< 1/8 **CARLE PLACE, NY 11514**
0.091 mi.
481 ft. **Site 2 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

CT MANIFEST:
Manifest No: NYG3870999
Waste Occurence: 1
UNNA: 1993
Hazard Class: 3
US Dot Description: FLAMMABLE LIQUIDS, N.O.S.
No of Containers: 1
Container Type: TP
Quantity: 100
Weight/Volume: G
Additional Description: Not reported
Handling Code: Not reported
Date Record Was Last Modified: 10/6/2004
DEO Who Last Modified Record: CYF
Manifest No: NYG3870999
Waste Occurence: 1
EPA Waste Code: D001
Recycled Waste?: F
Date Record Was Last Modified: 10/6/2004
DEO Who Last Modified Record: CYF
Year: 2003
Manifest ID: NYG3870999
TSDF EPA ID: CTD002593887
TSDF Name: BRIDGEPORT UNITED RECYCLING, INC.
TSDF Address: 50 CROSS STREET
TSDF City,St,Zip: BRIDGEPORT, CT 06610
TSDF Country: USA
TSDF Telephone: 2032386745
Transport Date: 8/27/2003
Transporter EPA ID: CAR000118992
Transporter Name: ADVANCED FUEL FILTRATION SYSTEMS, INC.
Transporter Country: USA
Transporter Phone: (800)850-8680
Trans 2 Date: Not reported
Trans 2 EPA ID: Not reported

TOSCO #34747 (Continued) **S109785401**

Trans 2 Name:	Not reported
Trans 2 Address:	Not reported
Trans 2 City,St,Zip:	CT
Trans 2 Country:	USA
Trans 2 Phone:	Not reported
EPA ID:	NYD986955730
Gererator Phone:	6027284180
Generator Mailing Addr:	PO BOX 52085
Generator Mailing Town:	PHOENIX
Generator Mailing State:	AZ
Generator Mailing Zip:	85072
Generator Mailing Country:	USA
Special Handling:	Not reported
Discrepancies:	Not reported
Date Shipped:	8/27/2003
Date Received:	9/2/2003
Last modified date:	10/6/2004
Last modified by:	CYF
Comments:	Not reported

J43 **TOSCO REFINING** **NY Spills** **S104510854**
West **285 OLD COUNTRY ROAD** **NY Hist Spills** **N/A**
< 1/8 **CARLE PLACE, NY**
0.091 mi.
481 ft. **Site 3 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

NY Spills:

Site ID:	65014
Facility Addr2:	Not reported
Facility ID:	9914154
Spill Number:	9914154
Facility Type:	ER
SWIS:	3022
Investigator:	CAENGELH
Referred To:	Not reported
Spill Date:	3/2/2000
Reported to Dept:	3/15/2000
CID:	04
Spill Cause:	Unknown
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	8/23/2005
Remediation Phase:	0
Date Entered In Computer:	3/15/2000
Spill Record Last Update:	8/24/2005
Spiller Name:	STEVE BELIM
Spiller Company:	EXXON
Spiller Address:	85 NORTH CENTRAL AVENUE
Spiller City,St,Zip:	VALLEY STREAM, NY
Spiller Company:	001

TOSCO REFINING (Continued) **S104510854**

Contact Name:	STEVE BELIM
Contact Phone:	(813) 744-5266
DEC Region:	1
DER Facility ID:	298855
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ENGELHARDT" AS PER WINSLOW: SITE ASSESSMENT OF FORMER EXXON, WILL SEND INFO TO JOE HAAS 6/2/00 FILE REASSIGNED 8/21/00 FILE REASSIGNED 3 CLEAN SOIL BORINGS, 1 GW SAMPLING, ONLY CONTAMINANT WAS MTBE
Remarks:	UNDER INVESTIGATION

Material:

Site ID:	65014
Operable Unit ID:	1092378
Operable Unit:	01
Material ID:	292446
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9914154
Investigator:	ENGELHARDT
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	03/02/2000 12:00
Reported to Dept Date/Time:	03/15/00 13:38
SWIS:	28
Spiller Name:	EXXON
Spiller Contact:	STEVE BELIM
Spiller Phone:	(813) 744-5266
Spiller Contact:	STEVE BELIM
Spiller Phone:	(813) 744-5266
Spiller Address:	85 NORTH CENTRAL AVENUE

TOSCO REFINING (Continued) **S104510854**

Spiller City,St,Zip: VALLEY STREAM, NY -
Spill Cause: Unknown
Reported to Dept: Groundwater
Water Affected: Not reported
Spill Source: 05
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: False
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/15/00
Date Spill Entered In Computer Data File: Not reported
Update Date: 08/25/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: AS PER WINSLOW: SITE ASSESSMENT OF FORMER EXXON, WILL SEND INFO TO JOE HAAS 6/2/00 FILE REASSIGNED 8/21/00 FILE REASSIGNED
Remark: UNDER INVESTIGATION

J44 **UNK** **NY Spills** **S104786365**
West **285 OLD COUNTRY ROAD** **NY Hist Spills** **N/A**
< 1/8 **CARLE PLACE, NY**
0.091 mi.
481 ft. **Site 4 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

NY Spills:

Site ID:	65013
Facility Addr2:	Not reported
Facility ID:	9409905
Spill Number:	9409905
Facility Type:	ER
SWIS:	3000
Investigator:	JEHAAS
Referred To:	Not reported
Spill Date:	10/24/1994
Reported to Dept:	10/25/1994
CID:	04
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	3/10/1995
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt:	3/10/1995
Remediation Phase:	0
Date Entered In Computer:	10/26/1994
Spill Record Last Update:	3/14/1995
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller City,St,Zip:	***UPDATE***, ZZ
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	62549
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HAAS"
Remarks:	TRACTOR TRAILER HAD LINE FAIL OIL ON ROADWAY, WEST BOUND LANE CLOSED

Material:

Site ID:	65013
Operable Unit ID:	1007648
Operable Unit:	01
Material ID:	375781
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

UNK (Continued) **S104786365**

Tank Test:
- Site ID: Not reported
- Spill Tank Test: Not reported
- Tank Number: Not reported
- Tank Size: Not reported
- Test Method: Not reported
- Leak Rate: Not reported
- Gross Fail: Not reported
- Modified By: Not reported
- Last Modified: Not reported
- Test Method: Not reported

NY Hist Spills:
- Region of Spill: 1
- Spill Number: 9409905
- Investigator: HAAS
- Caller Name: Not reported
- Caller Agency: Not reported
- Caller Phone: Not reported
- Notifier Name: Not reported
- Notifier Agency: Not reported
- Notifier Phone: Not reported
- Spill Date/Time: 10/24/1994 23:00
- Reported to Dept Date/Time: 10/25/94 00:30
- SWIS: 28
- Spiller Name: UNK
- Spiller Contact: Not reported
- Spiller Phone: Not reported
- Spiller Address: Not reported
- Spiller City,St,Zip: Not reported
- Spill Cause: Equipment Failure
- Reported to Dept: On Land
- Water Affected: Not reported
- Spill Source: 07
- Spill Notifier: Police Department
- PBS Number: Not reported
- Cleanup Ceased: 03/10/95
- Cleanup Meets Std: True
- Last Inspection: / /
- Recommended Penalty: Penalty Not Recommended
- Spiller Cleanup Dt: / /
- Enforcement Date: / /
- Invstgn Complete: / /
- UST Involvement: False
- Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
- Spill Closed Dt: 03/10/95
- Corrective Action Plan Submitted: / /
- Date Region Sent Summary to Central Office: / /
- Date Spill Entered In Computer Data File: 10/26/94
- Date Spill Entered In Computer Data File: Not reported
- Update Date: 03/14/95
- Is Updated: False

Tank:
- PBS Number: Not reported

UNK (Continued) **S104786365**

Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927
DEC Remarks: Not reported
Remark: TRACTOR TRAILER HAD LINE FAIL OIL ON ROADWAY, WEST BOUND LANE CLOSED

J45 **EXXON #2634747** **UST** **U003850535**
West **285 OLD COUNTRY RD.** **N/A**
< 1/8 **CARLE PLACE, NY**
0.091 mi.
481 ft. **Site 5 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

NASSAU CO. UST:
Facility ID: 058181
Owner Name: TOSCO CORPORATION
Owner Address: P.O. BOX 52085
Owner City,St,Zip: PHOENIX, AZ 85072
Permitee Name: SAME
Permitee Address: Not reported
Permitee City,St,Zip: Not reported

Tank ID: 0005
Tank Location: Indoors, Belowground
Capacity (Gal): 00001000
Tank Status: In Service
Tank Material: Fiberglass Reinforced Plastic
Int Protection: None
Ext Protection: FIBERGLASS REINFORCED PLASTIC
Piping Type: Other
Material Type: Waste
Description: WASTE OIL
Leak Detect: OTHER
Containment: NONE
Product Gauge: No
Dispense Method: Suction
Fill Type: Gravity
Install Date: 101980

J46
West
< 1/8
0.091 mi.
481 ft.

EXXEON CO. USA
285 OLD COUNTRY ROAD
CARLE PLACE, NY 11514

Site 6 of 9 in cluster J

MANIFEST **S109785400**
N/A

Relative:
Higher

Actual:
93 ft.

CT MANIFEST:

Manifest No:	CTF0013324
Waste Occurence:	1
UNNA:	9189
Hazard Class:	ORM-E
US Dot Description:	HAZARDOUS WASTE LIQUID, NOS
No of Containers:	001
Container Type:	TT
Quantity:	926
Weight/Volume:	G
Additional Description:	Y
Handling Code:	T46
Date Record Was Last Modified:	4/27/2004
DEO Who Last Modified Record:	IG
Manifest No:	CTF0013324
Waste Occurence:	1
EPA Waste Code:	D018
Recycled Waste?:	F
Date Record Was Last Modified:	4/27/2004
DEO Who Last Modified Record:	IG
Year:	1991
Manifest ID:	CTF0013324
TSDF EPA ID:	CTD021816889
TSDF Name:	UNITED OIL RECOVERY, INC.
TSDF Address:	136 GRACEY AVENUE
TSDF City,St,Zip:	MERIDEN, CT 06450
TSDF Country:	USA
TSDF Telephone:	Not reported
Transport Date:	8/7/1991
Transporter EPA ID:	NYD986908085
Transporter Name:	MARINE POLLUTION CONTROL, INC.
Transporter Country:	USA
Transporter Phone:	Not reported
Trans 2 Date:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
Trans 2 Address:	Not reported
Trans 2 City,St,Zip:	CT
Trans 2 Country:	USA
Trans 2 Phone:	Not reported
EPA ID:	NYD986955730
Gererator Phone:	7136567709
Generator Mailing Addr:	285 OLD COUNTRY RD.
Generator Mailing Town:	CARLE PALCE
Generator Mailing State:	NY
Generator Mailing Zip:	Not reported
Generator Mailing Country:	USA
Special Handling:	Yes
Discrepancies:	No
Date Shipped:	8/7/1991
Date Received:	8/7/1991
Last modified date:	4/27/2004
Last modified by:	IG

EXXEON CO. USA (Continued) **S109785400**

Comments: Not reported

J47 **CUMBERLAND FARMS-EXXON** **NY Spills** **S108296811**
West **285 OLD COUNTRY ROAD** **N/A**
< 1/8 **CARLE PLACE, NY**
0.091 mi.
481 ft. **Site 7 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

NY Spills:

Site ID:	374934
Facility Addr2:	Not reported
Facility ID:	0610480
Spill Number:	0610480
Facility Type:	ER
SWIS:	3022
Investigator:	TJDEMEO
Referred To:	Not reported
Spill Date:	12/15/2006
Reported to Dept:	12/15/2006
CID:	04
Spill Cause:	Other
Water Affected:	Not reported
Spill Source:	Gasoline Station
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	Not Closed
Remediation Phase:	1
Date Entered In Computer:	12/15/2006
Spill Record Last Update:	12/18/2006
Spiller Name:	BILL SIMMONS
Spiller Company:	CUMBERLAND FARMS-EXXON
Spiller Address:	285 OLD COUNTRY ROAD
Spiller City,St,Zip:	CARLE PLACE, NY
Spiller Company:	001
Contact Name:	BILL SIMMONS
Contact Phone:	(413) 789-3530
DEC Region:	1
DER Facility ID:	298855
DEC Memo:	12/15/06 11:00 TIM DEMEO ON THE WAY TO INSPECT
Remarks:	REMOVING TANKS AND FOUND PEA STONE IMPACTED FROM SPILL BUCKET:

Material:

Site ID:	374934
Operable Unit ID:	1132586
Operable Unit:	01
Material ID:	2122361
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons

CUMBERLAND FARMS-EXXON (Continued) **S108296811**

Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

J48 **EXXON DIV OF CFI #70230** **RCRA-CESQG** **1004757832**
West **285 OLD COUNTRY RD & LINDBERGH** **FINDS** **NYD986955730**
< 1/8 **CARLE PLACE, NY 11514** **MANIFEST**
0.091 mi.
481 ft. **Site 8 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: EXXON DIV OF CFI #70230
Facility address: 285 OLD COUNTRY RD & LINDBERGH
CARLE PLACE, NY 11514
EPA ID: NYD986955730
Mailing address: DEDHAM ST
CANTON, MA 02021
Contact: MAUREEN JERNSTEDT
Contact address: DEDHAM ST
CANTON, MA 02021
Contact country: US
Contact telephone: (800) 225-9702
Telephone ext.: 3378
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: NO NAME FOUND

EXXON DIV OF CFI #70230 (Continued) **1004757832**

Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 09/10/2003
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/10/2003
Owner/Op end date: Not reported

Owner/operator name: TOSCO
Owner/operator address: PO BOX 52085
PHOENIX, AZ 08507
Owner/operator country: Not reported
Owner/operator telephone: (602) 728-8000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/0001
Owner/Op end date: Not reported

Owner/operator name: TOSCO
Owner/operator address: PO BOX 52085
PHOENIX, AZ 08507
Owner/operator country: US
Owner/operator telephone: (602) 728-8000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

EXXON DIV OF CFI #70230 (Continued) **1004757832**

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: EXXON DIV OF CFI #70230
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 10/01/2004
Facility name: EXXON DIV OF CFI #70230
Classification: Small Quantity Generator

Date form received by agency: 08/08/2001
Facility name: EXXON DIV OF CFI #70230
Site name: TOSCO #34747
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/25/1992
Facility name: EXXON DIV OF CFI #70230
Site name: EXXON #37117
Classification: Large Quantity Generator

Date form received by agency: 03/13/1991
Facility name: EXXON DIV OF CFI #70230
Site name: TOSCO #34747
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:
Waste code: D000
Waste name: Not Defined

Waste code: D018
Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110004468451

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD986955730
Country: USA
Mailing Name: EXXON COMPANY USA
Mailing Contact: CHRISTINE COLUCCIO
Mailing Address: PO BOX 4415
Mailing Address 2: Not reported
Mailing City: HOUSTON
Mailing State: TX
Mailing Zip: 77210

EXXON DIV OF CFI #70230 (Continued) **1004757832**

Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	800-992-3647

Document ID:	PAC8150063
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	921110
Trans1 Recv Date:	921110
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	921111
Part A Recv Date:	921127
Part B Recv Date:	921120
Generator EPA ID:	NYD986955730
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	PAD987266715
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	92
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYG3870999
Manifest Status:	Not reported
Trans1 State ID:	CAR000118992
Trans2 State ID:	Not reported
Generator Ship Date:	08/27/2003
Trans1 Recv Date:	08/27/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/02/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986955730
Trans1 EPA ID:	CTD002593887
Trans2 EPA ID:	Not reported
TSDF ID:	CA016
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00100

EXXON DIV OF CFI #70230 (Continued) **1004757832**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TP - Tanks, portable
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	03
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2444265
Manifest Status:	Completed copy
Trans1 State ID:	LL5554
Trans2 State ID:	Not reported
Generator Ship Date:	911016
Trans1 Recv Date:	911016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	911016
Part A Recv Date:	Not reported
Part B Recv Date:	911105
Generator EPA ID:	NYD986955730
Trans1 EPA ID:	NYD068011352
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	F005 - UNKNOWN
Quantity:	08000
Units:	P - Pounds
Number of Containers:	016
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00660
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported

EXXON DIV OF CFI #70230 (Continued) **1004757832**

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: PAC6823515
Manifest Status: Completed copy
Trans1 State ID: PAAH0172
Trans2 State ID: Not reported
Generator Ship Date: 920213
Trans1 Recv Date: 920213
Trans2 Recv Date: Not reported
TSD Site Recv Date: 920220
Part A Recv Date: Not reported
Part B Recv Date: 920304
Generator EPA ID: NYD986955730
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID: PAD987266715
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 00090
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 100
Year: 92
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYC2423957
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: P121078
Trans2 State ID: Not reported
Generator Ship Date: 930729
Trans1 Recv Date: 930729
Trans2 Recv Date: Not reported
TSD Site Recv Date: 930823
Part A Recv Date: 930806
Part B Recv Date: 930830
Generator EPA ID: NYD986955730
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: VAD105838874
Waste Code: D008 - LEAD 5.0 MG/L TCLP

EXXON DIV OF CFI #70230 (Continued) **1004757832**

Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	93
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

J49 **EXXON SERVICE STATION** **UST U004125575**
West **285 OLD COUNTRY ROAD** **AST N/A**
< 1/8 **CARLE PLACE, NY 11514**
0.091 mi.
481 ft. **Site 9 of 9 in cluster J**

Relative:
Higher

Actual:
93 ft.

UST:

Facility Id:	1-000190
Region:	STATE
DEC Region:	1
Site Status:	Unregistered
Program Type:	PBS
Expiration Date:	N/A
UTM X:	617431.30819000001
UTM Y:	4511292.3374199998
Site ID:	361321
Tank Number:	1
Tank Status:	Unregistered
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	10/6/1980
Capacity Gallons:	4000
Tightness Test Method:	NN
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Tank ID:	210601
Tank Location:	5
Tank Type:	Equivalent technology
Date Test:	3/11/1998
Register:	True
Modified By:	NJACAMPO
Last Modified:	3/21/2006
Tank Number:	2
Tank Status:	Unregistered
Tank Model:	Not reported

EXXON SERVICE STATION (Continued) **U004125575**

Pipe Model: Not reported
Install Date: 10/6/1980
Capacity Gallons: 6000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: Not reported
Tank ID: 210602
Tank Location: 5
Tank Type: Equivalent technology
Date Test: 3/11/1998
Register: True
Modified By: NJACAMPO
Last Modified: 3/21/2006

Tank Number: 3
Tank Status: Unregistered
Tank Model: Not reported
Pipe Model: Not reported
Install Date: 10/6/1980
Capacity Gallons: 10000
Tightness Test Method: NN
Next Test Date: Not reported
Date Tank Closed: Not reported
Tank ID: 210603
Tank Location: 5
Tank Type: Equivalent technology
Date Test: 3/11/1998
Register: True
Modified By: NJACAMPO
Last Modified: 3/21/2006

UST_PBS_BSAFFIL:
Site Id: 361321
Program Number: 1-000190
Facility Type: Emergency Contact
Affiliation Type: 11
Affiliation Subtype: NNN
Company Name: CUMBERLAND FARMS INC.
Contact Type: Not reported
Contact Name: GUS ANTONIOU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 997-9132
Phone Ext: Not reported
Email: Not reported
Fax Number: Not reported
Modified By: NJACAMPO
Date Last Modified: 3/21/2006

Site Id: 361321
Program Number: 1-000190
Facility Type: Owner

EXXON SERVICE STATION (Continued) **U004125575**

Affiliation Type:	01
Affiliation Subtype:	E
Company Name:	CUMBERLAND FARMS INC.
Contact Type:	FIELD REPRESENTATIVE
Contact Name:	RICHARD ETZOLD
Address1:	777 DEDHAM STREET
Address2:	Not reported
City:	CANTON
State:	MA
Zip Code:	02021
Country Code:	001
Phone:	(781) 828-4900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361321
Program Number:	1-000190
Facility Type:	Mail Contact
Affiliation Type:	07
Affiliation Subtype:	NNN
Company Name:	CUMBERLAND FARMS INC.
Contact Type:	FIELD REPRESENTATIVE
Contact Name:	RICHARD ETZOLD
Address1:	777 DEDHAM STREET
Address2:	Not reported
City:	CANTON
State:	MA
Zip Code:	02021
Country Code:	001
Phone:	(781) 828-4900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361321
Program Number:	1-000190
Facility Type:	On-Site Operator
Affiliation Type:	04
Affiliation Subtype:	NNN
Company Name:	EXXON SERVICE STATION
Contact Type:	Not reported
Contact Name:	G&L SERVICE STATION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported

EXXON SERVICE STATION (Continued) **U004125575**

Modified By: NJACAMPO
Date Last Modified: 3/21/2006

UST_AST_PBS_BSEQUIP:
Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: I02

EXXON SERVICE STATION (Continued) **U004125575**

Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: J00
Code Name: None
Type: Dispenser

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: K01
Code Name: Catch Basin

EXXON SERVICE STATION (Continued) **U004125575**

Type:	Spill Prevention
Site Id:	361321
Tank Id Number:	210601
Tank Number:	1
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Site Id:	361321
Tank Id Number:	210601
Tank Number:	1
Equipment:	J01
Code Name:	Submersible
Type:	Dispenser
Site Id:	361321
Tank Id Number:	210605
Tank Number:	5
Equipment:	H01
Code Name:	Interstitial - Electronic Monitoring
Type:	Tank Leak Detection
Site Id:	361321
Tank Id Number:	210605
Tank Number:	5
Equipment:	C00
Code Name:	No Piping
Type:	Pipe Location
Site Id:	361321
Tank Id Number:	210604
Tank Number:	4
Equipment:	J00
Code Name:	None
Type:	Dispenser
Site Id:	361321
Tank Id Number:	210603
Tank Number:	3
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Site Id:	361321
Tank Id Number:	210603
Tank Number:	3
Equipment:	K01
Code Name:	Catch Basin
Type:	Spill Prevention
Site Id:	361321
Tank Id Number:	210601
Tank Number:	1
Equipment:	K01
Code Name:	Catch Basin
Type:	Spill Prevention

EXXON SERVICE STATION (Continued) **U004125575**

Site Id:	361321
Tank Id Number:	210605
Tank Number:	5
Equipment:	K01
Code Name:	Catch Basin
Type:	Spill Prevention

Site Id:	361321
Tank Id Number:	210605
Tank Number:	5
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection

Site Id:	361321
Tank Id Number:	210605
Tank Number:	5
Equipment:	G01
Code Name:	Diking (Aboveground)
Type:	Tank Secondary Containment

Site Id:	361321
Tank Id Number:	210602
Tank Number:	2
Equipment:	I02
Code Name:	High Level Alarm
Type:	Overfill

Site Id:	361321
Tank Id Number:	210604
Tank Number:	4
Equipment:	D10
Code Name:	Copper
Type:	Pipe Type

Site Id:	361321
Tank Id Number:	210604
Tank Number:	4
Equipment:	L00
Code Name:	None
Type:	Piping Leak Detection

Site Id:	361321
Tank Id Number:	210604
Tank Number:	4
Equipment:	B01
Code Name:	Painted/Asphalt Coating
Type:	Tank External Protection

Site Id:	361321
Tank Id Number:	210605
Tank Number:	5
Equipment:	B01
Code Name:	Painted/Asphalt Coating
Type:	Tank External Protection

Site Id:	361321

EXXON SERVICE STATION (Continued) **U004125575**

Tank Id Number: 210602
Tank Number: 2
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 361321
Tank Id Number: 210604

EXXON SERVICE STATION (Continued) **U004125575**

Tank Number: 4
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

AST:
Region: STATE
DEC Region: 1
Site Status: Unregistered
Facility Id: 1-000190
Program Type: PBS
UTM X: 617431.30819000001
UTM Y: 4511292.3374199998
Expiration Date: N/A

Tank Number: 4
Tank Id: 210604
Tank Location: 2
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Unregistered
Tank Model: Not reported
Pipe Model: Not reported

EXXON SERVICE STATION (Continued) **U004125575**

Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NJACAMPO
Last Modified:	3/21/2006

Tank Number:	5
Tank Id:	210605
Tank Location:	2
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Unregistered
Tank Model:	Not reported
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NJACAMPO
Last Modified:	3/21/2006

UST_PBS_BSAFFIL:

Site Id:	361321
Program Number:	1-000190
Facility Type:	Emergency Contact
Affiliation Type:	11
Affiliation Subtype:	NNN
Company Name:	CUMBERLAND FARMS INC.
Contact Type:	Not reported
Contact Name:	GUS ANTONIOU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 997-9132
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361321
Program Number:	1-000190
Facility Type:	Owner
Affiliation Type:	01
Affiliation Subtype:	E
Company Name:	CUMBERLAND FARMS INC.
Contact Type:	FIELD REPRESENTATIVE

EXXON SERVICE STATION (Continued) **U004125575**

Contact Name:	RICHARD ETZOLD
Address1:	777 DEDHAM STREET
Address2:	Not reported
City:	CANTON
State:	MA
Zip Code:	02021
Country Code:	001
Phone:	(781) 828-4900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361321
Program Number:	1-000190
Facility Type:	Mail Contact
Affiliation Type:	07
Affiliation Subtype:	NNN
Company Name:	CUMBERLAND FARMS INC.
Contact Type:	FIELD REPRESENTATIVE
Contact Name:	RICHARD ETZOLD
Address1:	777 DEDHAM STREET
Address2:	Not reported
City:	CANTON
State:	MA
Zip Code:	02021
Country Code:	001
Phone:	(781) 828-4900
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

Site Id:	361321
Program Number:	1-000190
Facility Type:	On-Site Operator
Affiliation Type:	04
Affiliation Subtype:	NNN
Company Name:	EXXON SERVICE STATION
Contact Type:	Not reported
Contact Name:	G&L SERVICE STATION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
Phone Ext:	Not reported
Email:	Not reported
Fax Number:	Not reported
Modified By:	NJACAMPO
Date Last Modified:	3/21/2006

EXXON SERVICE STATION (Continued) **U004125575**

UST_AST_PBS_BSEQUIP:

Site Id:	361321
Tank Id Number:	210603
Tank Number:	3
Equipment:	B00
Code Name:	None
Type:	Tank External Protection

Site Id:	361321
Tank Id Number:	210603
Tank Number:	3
Equipment:	H05
Code Name:	In-Tank System (ATG)
Type:	Tank Leak Detection

Site Id:	361321
Tank Id Number:	210602
Tank Number:	2
Equipment:	B00
Code Name:	None
Type:	Tank External Protection

Site Id:	361321
Tank Id Number:	210603
Tank Number:	3
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location

Site Id:	361321
Tank Id Number:	210602
Tank Number:	2
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection

Site Id:	361321
Tank Id Number:	210602
Tank Number:	2
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location

Site Id:	361321
Tank Id Number:	210601
Tank Number:	1
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location

Site Id:	361321
Tank Id Number:	210601
Tank Number:	1
Equipment:	I02
Code Name:	High Level Alarm
Type:	Overfill

EXXON SERVICE STATION (Continued) **U004125575**

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: B00
Code Name: None
Type: Tank External Protection

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: J00
Code Name: None
Type: Dispenser

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361321

EXXON SERVICE STATION (Continued) **U004125575**

Tank Id Number: 210601
Tank Number: 1
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: J01
Code Name: Submersible
Type: Dispenser

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: C00
Code Name: No Piping
Type: Pipe Location

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: J00
Code Name: None
Type: Dispenser

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361321
Tank Id Number: 210603
Tank Number: 3
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361321
Tank Id Number: 210601
Tank Number: 1
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361321
Tank Id Number: 210605

EXXON SERVICE STATION (Continued) **U004125575**

Tank Number: 5
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: D10
Code Name: Copper
Type: Pipe Type

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: L00
Code Name: None
Type: Piping Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Site Id: 361321
Tank Id Number: 210602
Tank Number: 2

EXXON SERVICE STATION (Continued) **U004125575**

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: D00
Code Name: No Piping
Type: Pipe Type

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210605
Tank Number: 5
Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: I02

EXXON SERVICE STATION (Continued) **U004125575**

Code Name: High Level Alarm
Type: Overfill

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: F00
Code Name: None
Type: Pipe External Protection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: A00
Code Name: None
Type: Tank Internal Protection

Site Id: 361321
Tank Id Number: 210604
Tank Number: 4
Equipment: E00
Code Name: None
Type: Piping Secondary Containment

H50 **RESIDENCE** **NY Spills** **S102098971**
NNW **21 CHERRY LANE** **NY Hist Spills** **N/A**
< 1/8 **CARLE PLACE, NY**
0.099 mi.
525 ft. **Site 2 of 2 in cluster H**

Relative:
Higher

Actual:
94 ft.

NY Spills:
Site ID: 195990
Facility Addr2: Not reported
Facility ID: 9312769
Spill Number: 9312769
Facility Type: ER
SWIS: 3000
Investigator: UNASSIGNED
Referred To: Not reported
Spill Date: 1/29/1994
Reported to Dept: 1/29/1994
CID: 04
Spill Cause: Equipment Failure
Water Affected: Not reported

RESIDENCE (Continued) **S102098971**

Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	1/31/1994
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	1/31/1994
Remediation Phase:	0
Date Entered In Computer:	1/31/1994
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	RESIDENCE
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	163282
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE"
Remarks:	SEAL ON PUMP LEAKED, GIFFORDS WILL CLEANUP, NO RESPONSE NEEDED

Material:

Site ID:	195990
Operable Unit ID:	991365
Operable Unit:	01
Material ID:	388185
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9312769

RESIDENCE (Continued) **S102098971**

Investigator:	NONE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	01/29/1994 17:00
Reported to Dept Date/Time:	01/29/94 18:08
SWIS:	28
Spiller Name:	RESIDENCE
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	09
Spill Notifier:	Other
PBS Number:	Not reported
Cleanup Ceased:	01/31/94
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	01/31/94
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	01/31/94
Date Spill Entered In Computer Data File:	Not reported
Update Date:	/ /
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	1
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	#2 FUEL OIL
Class Type:	#2 FUEL OIL
Times Material Entry In File:	24464
CAS Number:	Not reported

RESIDENCE (Continued) **S102098971**

Last Date: 19941207
DEC Remarks: Not reported
Remark: SEAL ON PUMP LEAKED, GIFFORDS WILL CLEANUP, NO RESPONSE NEEDED

K51 **CANNON USA CORP** **LTANKS** **1000549172**
SSW **1000 AXIN AVENUE** **HIST LTANKS** **N/A**
< 1/8 **GARDEN CITY, NY**
0.104 mi.
551 ft. **Site 1 of 2 in cluster K**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Site ID:	104946
Spill No:	8709864
Spill Date:	11/12/1987
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	9/15/1988
Facility Addr2:	Not reported
Cleanup Ceased:	9/15/1988
Cleanup Meets Standard:	True
SWIS:	3020
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	2/22/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/23/1988
Spill Record Last Update:	7/6/2006
Spiller Name:	Not reported
Spiller Company:	CANNON USA CORP
Spiller Address:	1000 AXIN AVENUE
Spiller City,St,Zip:	GARDEN CITY, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	92650
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GOERTZ FD" / / : GEN UTILITIES WILL EXCAVATE & RETEST ON 3/4/88. 09/15/88: TANK WAS REMOVED BY GENERAL UTILITIES & NO CONTAMINATION WAS FOUND. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	WOULD NOT HOLD IN STANDPIPE. 2.5K

Material:

Site ID:	104946
Operable Unit ID:	915299
Operable Unit:	01
Material ID:	554810
Material Code:	0001

CANNON USA CORP (Continued) **1000549172**

Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 104946
Spill Tank Test: 1533288
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 1
Spill Number: 8709864
Spill Date: 11/12/1987
Spill Time: 12:00
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 09/15/88
Cleanup Ceased: 09/15/88
Cleanup Meets Standard: True
Investigator: GOERTZ FD
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 02/22/88
Reported to Department Time: 12:00
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: CANNON USA CORP
Spiller Address: 1000 AXIN AVENUE
Spiller City,St,Zip: GARDEN CITY, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (516) 488-6700

CANNON USA CORP (Continued) **1000549172**

Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 02/23/88
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 03/08/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: / / : GEN UTILITIES WILL EXCAVATE RETEST ON 3/4/88. 09/15/88: TANK WAS REMOVED BY GENERAL UTILITIES NO CONTAMINATION WAS FOUND.
Spill Cause: WOULD NOT HOLD IN STANDPIPE. 2.5K

K52 **FORTUNOFF'S** **AST** **A100237397**
SSW **1000 AXINN AVE** **N/A**
< 1/8 **EAST GARDEN CITY, NY 11590**
0.104 mi.
551 ft. **Site 2 of 2 in cluster K**

Relative:
Higher

Actual:
89 ft.

NCFM AST:
Tank Type: OUTDOOR AG HOR ON STILT
Tank Size: 1000
Contents: DIESEL

53
SSE
< 1/8
0.109 mi.
578 ft.

WINTHROP UNIV HOSP AMBULATORY SURGERY
777 ZECKENDORF BLVD
EAST GARDEN CITY, NY 11530

AST **A100266711**
N/A

Relative:
Higher

Actual:
91 ft.

NCFM AST:
Tank Type: OUTDOOR AG HOR D/W STEEL
Tank Size: 200
Contents: DIESEL

54
NNW
< 1/8
0.124 mi.
657 ft.

BLUM RESIDENCE
100 ROOSEVELT PLACE
CARLE PLACE, NY

NY Spills **S102101449**
NY Hist Spills **N/A**

Relative:
Higher

Actual:
94 ft.

NY Spills:

Site ID:	147219
Facility Addr2:	Not reported
Facility ID:	9416171
Spill Number:	9416171
Facility Type:	ER
SWIS:	3000
Investigator:	UNASSIGNED
Referred To:	Not reported
Spill Date:	3/14/1995
Reported to Dept:	3/14/1995
CID:	04
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	3/14/1995
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/14/1995
Remediation Phase:	0
Date Entered In Computer:	3/15/1995
Spill Record Last Update:	2/9/2001
Spiller Name:	Not reported
Spiller Company:	COMMANDER
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	125340
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE" 03/15/95: SPILL ON CONCRETE BASEMENT FLOOR, CLEANUP CONFIRMED WITH CALLER VIA TELEPHONE, NO FURTHER ACTION.
Remarks:	AT CHARLES BLUM RESIDENCE, OIL LINE HAD PINHOLE RAGS & SPEEDI DRI & ODOR KILL USED TO CLEANUP

Material:

BLUM RESIDENCE (Continued) **S102101449**

Site ID: 147219
Operable Unit ID: 1009631
Operable Unit: 01
Material ID: 371333
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 1
Spill Number: 9416171
Investigator: NONE
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 03/14/1995 16:45
Reported to Dept Date/Time: 03/14/95 17:32
SWIS: 28
Spiller Name: COMMANDER
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: 03/14/95
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /

BLUM RESIDENCE (Continued) **S102101449**

Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 03/14/95
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 03/15/95
Date Spill Entered In Computer Data File: Not reported
Update Date: 02/09/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 03/15/95: SPILL ON CONCRETE BASEMENT FLOOR, CLEANUP CONFIRMED WITH CALLER VIA TELEPHONE, NO FURTHER ACTION.
Remark: AT CHARLES BLUM RESIDENCE, OIL LINE HAD PINHOLE RAGS SPEEDI DRI ODOR KILL USED TO CLEANUP

L55 **CENTURY FORKLIFT** **AST** **A100195720**
SSE **172 F CABOT ST** **N/A**
1/8-1/4 **WEST BABYLON, NY 11704**
0.128 mi.
676 ft. **Site 1 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

SUFFOLK CO. AST:
Facility ID: 2303
Region: SUFFOLK
Owner Name: VOGEL FAMILY PARTNERS
Owner Address: 123 ALDER ST
Owner City,St,Zip: WEST BABYLON, NY 11704
Tank ID: 2
Location: ABOVE, IN
Installed: Not reported
Capacity: 0000000275
Content: WASTE OIL
Construction: STEEL
Dispenser: SUCTION
Fill Type: GRAVITY
Date Removed: 070899

CENTURY FORKLIFT (Continued) **A100195720**

Official Use:	Removed Tank. 99
Permit to Operate:	120993
Tank Key:	5560
Facility Reference #:	06193
Tank Count:	2
Township:	BABYLON
Tax Map No:	0100

Facility ID:	2303
Region:	SUFFOLK
Owner Name:	VOGEL FAMILY PARTNERS
Owner Address:	123 ALDER ST
Owner City,St,Zip:	WEST BABYLON, NY 11704
Tank ID:	1
Location:	ABOVE, IN
Installed:	Not reported
Capacity:	0000000275
Content:	WASTE OIL
Construction:	STEEL
Dispenser:	SUCTION
Fill Type:	GRAVITY
Date Removed:	070899
Official Use:	Removed Tank. 99
Permit to Operate:	120993
Tank Key:	5559
Facility Reference #:	06193
Tank Count:	2
Township:	BABYLON
Tax Map No:	0100

M56 **NY TELEPHONE** **LTANKS** **S100149614**
SSE **741 ZECKENDORF** **HIST LTANKS** **N/A**
1/8-1/4 **GARDEN CITY, NY**
0.130 mi.
686 ft. **Site 1 of 8 in cluster M**

Relative:
Higher

Actual:
87 ft.

LTANKS:

Site ID:	68855
Spill No:	8606527
Spill Date:	1/21/1987
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	11/14/1990
Facility Addr2:	Not reported
Cleanup Ceased:	11/14/1990
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	MIRZA
Referred To:	Not reported
Reported to Dept:	1/4/1987
CID:	04
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0

NY TELEPHONE (Continued) **S100149614**

Date Entered In Computer: 1/27/1987
Spill Record Last Update: 7/9/1997
Spiller Name: Not reported
Spiller Company: NY TELEPHONE
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 65517
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MIRZA WELL" / / : NY TELEPHONE TO MONITOR OVERNIGHT FOR ANY LEAKAGE. 3 OPTION LETTER.
Remarks: LEAK RATE AT -.225GPH.

Material:
Site ID: 68855
Operable Unit ID: 904111
Operable Unit: 01
Material ID: 472091
Material Code: 0001
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 68855
Spill Tank Test: 1530525
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 1
Spill Number: 8606527
Spill Date: 01/21/1987
Spill Time: 18:30
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 11/14/90

NY TELEPHONE (Continued) **S100149614**

Cleanup Ceased: 11/14/90
Cleanup Meets Standard: True
Investigator: MIRZA WELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 01/04/87
Reported to Department Time: 19:02
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: NY TELEPHONE
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (747) 384-
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 01/27/87
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 07/09/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported

NY TELEPHONE (Continued) **S100149614**

Last Date: 19941207
DEC Remarks: / / : NY TELEPHONE TO MONITOR OVERNIGHT FOR ANY LEAKAGE. 3 OPTION LETTER.
Spill Cause: LEAK RATE AT -.225GPH.

M57 **PEPSI COLA** **LTANKS** **S100172198**
SSE **800 EAST GATE BLVD** **HIST LTANKS** **N/A**
1/8-1/4 **GARDEN CITY, NY**
0.130 mi.
686 ft. **Site 2 of 8 in cluster M**

Relative:
Higher

Actual:
87 ft.

LTANKS:

Site ID:	80239
Spill No:	8709981
Spill Date:	2/11/1988
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	3/4/1988
Facility Addr2:	Not reported
Cleanup Ceased:	3/4/1988
Cleanup Meets Standard:	True
SWIS:	3020
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	2/26/1988
CID:	04
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/29/1988
Spill Record Last Update:	7/6/2006
Spiller Name:	Not reported
Spiller Company:	PEPSI COLA
Spiller Address:	800 EAST GATE BLVD
Spiller City,St,Zip:	GARDEN CITY, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	74394
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GOERTZ FD" 02/29/88: AFTER PLUMBING REPAIRED THE SUCTION & DISCHARGE LINES,TYREE RETESTED & PASSED. DEC NOT PRESENT DURING RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	5K TANK FAILED AT -.420. TYREE TESTER.

Material:

Site ID:	80239
Operable Unit ID:	914913
Operable Unit:	01
Material ID:	461770
Material Code:	0001

PEPSI COLA (Continued) **S100172198**

Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 80239
Spill Tank Test: 1533326
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 1
Spill Number: 8709981
Spill Date: 02/11/1988
Spill Time: 12:00
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 03/04/88
Cleanup Ceased: 03/04/88
Cleanup Meets Standard: True
Investigator: GOERTZ FD
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 02/26/88
Reported to Department Time: 13:00
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: PEPSI COLA
Spiller Address: 800 EAST GATE BLVD
Spiller City,St,Zip: GARDEN CITY, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (516) 228-8200

PEPSI COLA (Continued) **S100172198**

Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 02/29/88
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 03/11/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 02/29/88: AFTER PLUMBING REPAIRED THE SUCTION DISCHARGE LINES,TYREE RETESTED PASSED. DEC NOT PRESENT DURING RETEST.
Spill Cause: 5K TANK FAILED AT -.420. TYREE TESTER.

M58 **VERIZON INC.** **AST** **U003848285**
SSE **741 ZECKENDORF BLVD** **N/A**
1/8-1/4 **EAST GARDEN CITY, NY 11530**
0.130 mi.
686 ft. **Site 3 of 8 in cluster M**

Relative:
Higher

Actual:
87 ft.

NCFM AST:
Tank Type: INDOOR AG HOR STEEL
Tank Size: 2000
Contents: DIESEL

M59 **BELL ATLANTIC** **LTANKS** **S103574762**
SSE **741 ZECKENDORF BLVD** **HIST LTANKS** **N/A**
1/8-1/4 **GARDEN CITY, NY** **NY Spills**
0.130 mi. **NY Hist Spills**
686 ft. **Site 4 of 8 in cluster M**

Relative:
Higher

Actual:
87 ft.

LTANKS:

Site ID:	151062
Spill No:	9809551
Spill Date:	10/29/1998
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/20/1999
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	10/29/1998
CID:	04
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	10/29/1998
Spill Record Last Update:	10/22/1999
Spiller Name:	ANDY BRADLEY
Spiller Company:	LEXICON ENVIRONMENTAL
Spiller Address:	790 EAST MARKET
Spiller City,St,Zip:	WESTCHESTER, PA 19382-
Spiller County:	001
Spiller Contact:	CHUCK PEDANO
Spiller Phone:	(800) 646-3161
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	128384
DEC Memo:	Not reported
Remarks:	TO BE RETESTED IN AM. NASS CO FIRE MARSHAL WAS ADVISED.

Material:

Site ID:	151062
Operable Unit ID:	1070632
Operable Unit:	01
Material ID:	313458
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

BELL ATLANTIC (Continued) **S103574762**

Tank Test:

Site ID:	151062
Spill Tank Test:	1546468
Tank Number:	01
Tank Size:	20000
Test Method:	01
Leak Rate:	0.6
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Petro-Tite/Petro Comp

HIST LTANKS:

Region of Spill:	1
Spill Number:	9809551
Spill Date:	10/29/1998
Spill Time:	16:16
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/20/99
Cleanup Ceased:	/ /
Cleanup Meets Standard:	True
Investigator:	T/T/F
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	10/29/98
Reported to Department Time:	16:16
SWIS:	28
Spiller Contact:	CHUCK PEDANO
Spiller Phone:	(800) 646-3161
Spiller Extention:	Not reported
Spiller Name:	LEXICON ENVIRONMENTAL
Spiller Address:	790 EAST MARKET
Spiller City,St,Zip:	WESTCHESTER, PA 19382-
Spiller Cleanup Date:	/ /
Facility Contact:	ANDY BRADLEY
Facility Phone:	(610) 344-3380
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	True

BELL ATLANTIC (Continued) **S103574762**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/29/98
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/22/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: 01
Tank Size: 20000
Test Method: Petro-Tite
Leak Rate Failed Tank: 0.60
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: DIESEL
Class Type: DIESEL
Times Material Entry In File: 10625
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Spill Cause: TO BE RETESTED IN AM. NASS CO FIRE MARSHAL WAS ADVISED.

NY Spills:
Site ID: 151063
Facility Addr2: Not reported
Facility ID: 9810777
Spill Number: 9810777
Facility Type: ER
SWIS: 3020
Investigator: HMCIRRIT
Referred To: Not reported
Spill Date: 11/25/1998
Reported to Dept: 11/25/1998
CID: 04
Spill Cause: Unknown
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt: 1/24/2000
Remediation Phase: 0
Date Entered In Computer: 11/25/1998
Spill Record Last Update: 6/19/2007

BELL ATLANTIC (Continued) **S103574762**

Spiller Name:	MARTIN BRUSCELLA
Spiller Company:	LIPA
Spiller Address:	333 EARLE OVINGTON BLVD
Spiller City,St,Zip:	UNIONDALE, NY 11553-
Spiller Company:	001
Contact Name:	MARTIN BRUSCELLA
Contact Phone:	(516) 391-6591
DEC Region:	1
DER Facility ID:	273106
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "CIRRITO" TELECON WITH MARTIN BRUSCELLA FOR UPDATE: SHAWN DAVIS ON SCENE AND HAS CELL PHONE, TRADEWINDS WILL ALSO RESPOND OIL RECOVERED, APPROX 2 CY OF SOIL EXCAVATED. NO FURTHER ACTION
Remarks:	MATERIAL TESTED POSITIVE FOR PCB'S, MATERIAL LEAKED FROM A TRANSFORMER. MATERIAL IN A VAULT BUT NOT SURE IF THERES A BOTTOM TO THE VAULT YET. CLEANUP CREW ON SCENE NOW.

Material:

Site ID:	151063
Operable Unit ID:	1068155
Operable Unit:	01
Material ID:	314642
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9810777
Investigator:	CIRRITO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/25/1998 10:20
Reported to Dept Date/Time:	11/25/98 10:31

BELL ATLANTIC (Continued) **S103574762**

SWIS: 28
Spiller Name: LIPA
Spiller Contact: MARTIN BRUSCELLA
Spiller Phone: (516) 391-6591
Spiller Contact: MARTIN BRUSCELLA
Spiller Phone: (516) 391-6591
Spiller Address: 333 EARLE OVINGTON BLVD
Spiller City,St,Zip: UNIONDALE, NY 11553-
Spill Cause: Unknown
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Spill Closed Dt: 01/24/00
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/25/98
Date Spill Entered In Computer Data File: Not reported
Update Date: 01/24/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 50
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: TRANSFORMER OIL
Class Type: TRANSFORMER OIL
Times Material Entry In File: 533
CAS Number: Not reported
Last Date: 19940926
DEC Remarks: TELECON WITH MARTIN BRUSCELLA FOR UPDATE: SHAWN DAVIS ON SCENE AND HAS CELL PHONE, TRADEWINDS WILL ALSO RESPOND OIL RECOVERED, APPROX 2 CY OF SOIL EXCAVATED. NO FURTHER ACTION
Remark: MATERIAL TESTED POSITIVE FOR PCB S, MATERIAL LEAKED FROM A TRANSFORMER. MATERIAL IN A VAULT BUT NOT SURE IF THERES A BOTTOM TO THE VAULT YET. CLEANUP CREW ON SCENE NOW.

M60 **VERIZON INC.** **UST** **U004053167**
SSE **741 ZECKENDORF BLVD** **N/A**
1/8-1/4 **EAST GARDEN CITY, NY 11530**
0.130 mi.
686 ft. **Site 5 of 8 in cluster M**

Relative:
Higher

Actual:
87 ft.

NCFM UST:
Tank Type: OUTDOOR UG HOR STEEL
Tank Size: 25000
Tank Contents: EMPTY

Tank Type: OUTDOOR UG HOR S/W F/G
Tank Size: 8000
Tank Contents: EMPTY

Tank Type: OUTDOOR UG HOR D/W COAT STL
Tank Size: 20000
Tank Contents: DIESEL

Tank Type: OUTDOOR UG HOR D/W COAT STL
Tank Size: 20000
Tank Contents: DIESEL

M61 **NEW YORK TELEPHONE CO** **RCRA-NonGen** **1000136877**
SSE **741 ZECKENDORF BLVD** **LTANKS** **NYD981491491**
1/8-1/4 **GARDEN CITY, NY 11530** **HIST LTANKS**
0.130 mi. **MANIFEST**
686 ft. **Site 6 of 8 in cluster M** **NY Spills**
NY Hist Spills

Relative:
Higher

Actual:
87 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: NEW YORK TELEPHONE CO
Facility address: 741 ZECKENDORF BLVD
GARDEN CITY, NY 11530
EPA ID: NYD981491491
Mailing address: LIVINGSTON ST
BROOKLYN, NY 11201
Contact: Not reported
Contact address: LIVINGSTON ST
BROOKLYN, NY 11201
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

NEW YORK TELEPHONE CO (Continued) **1000136877**

Owner/operator name: NEW YORK TELEPHONE CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: NEW YORK TELEPHONE CO
Classification: Not a generator, verified

Date form received by agency: 10/06/1994
Facility name: NEW YORK TELEPHONE CO
Classification: Not a generator, verified

Date form received by agency: 07/21/1986
Facility name: NEW YORK TELEPHONE CO
Classification: Unverified

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 07/07/2009
Date achieved compliance: 08/27/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2009
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/04/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

NEW YORK TELEPHONE CO (Continued) **1000136877**

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 07/07/2009
Date achieved compliance: 08/27/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2009
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/04/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 07/07/2009
Date achieved compliance: 08/27/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2009
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/04/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 07/07/2009
Date achieved compliance: 08/27/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2009
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/04/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 07/07/2009
Date achieved compliance: 08/27/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/07/2009
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 09/04/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

NEW YORK TELEPHONE CO (Continued) **1000136877**

Evaluation Action Summary:

Evaluation date:	07/07/2009
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Listing - General
Date achieved compliance:	08/27/2009
Evaluation lead agency:	State

Evaluation date:	07/07/2009
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Generators - Pre-transport
Date achieved compliance:	08/27/2009
Evaluation lead agency:	State

Evaluation date:	07/07/2009
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	State Statute or Regulation
Date achieved compliance:	08/27/2009
Evaluation lead agency:	State

Evaluation date:	07/07/2009
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Universal Waste - Small Quantity Handlers
Date achieved compliance:	08/27/2009
Evaluation lead agency:	State

Evaluation date:	07/07/2009
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	TSD IS-Preparedness and Prevention
Date achieved compliance:	08/27/2009
Evaluation lead agency:	State

LTANKS:

Site ID:	151059
Spill No:	8805116
Spill Date:	9/13/1988
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	10/21/1988
Facility Addr2:	Not reported
Cleanup Ceased:	10/21/1988
Cleanup Meets Standard:	True
SWIS:	3020
Investigator:	NJACAMPO
Referred To:	Not reported
Reported to Dept:	9/13/1988
CID:	04
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/15/1988
Spill Record Last Update:	6/7/2006
Spiller Name:	Not reported
Spiller Company:	OSWEGO OIL

NEW YORK TELEPHONE CO (Continued) **1000136877**

Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	273106
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ACAMPORA FD" 10/21/88: TYREE CLEANED UP SPILL, REMOVED TANK & EXCAVATED & DISPOSED 15O YDS OF SOIL. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	OVERFILL OF TANK. OIL IN TWO DRYWELLS-CONT SOIL. NY TELEPHONE HIRING TYREE TO CLEANUP.

Material:

Site ID:	151059
Operable Unit ID:	922263
Operable Unit:	01
Material ID:	457031
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	8805116
Spill Date:	09/13/1988
Spill Time:	13:00
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	10/21/88
Cleanup Ceased:	10/21/88

NEW YORK TELEPHONE CO (Continued) **1000136877**

Cleanup Meets Standard: True
Investigator: ACAMPORA FD
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 09/13/88
Reported to Department Time: 14:35
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: OSWEGO OIL
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Affected Persons
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 09/15/88
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 04/07/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207

NEW YORK TELEPHONE CO (Continued) **1000136877**

DEC Remarks: 10/21/88: TYREE CLEANED UP SPILL, REMOVED TANK EXCAVATED DISPOSED 15O YDS OF SOIL.
Spill Cause: OVERFILL OF TANK. OIL IN TWO DRYWELLS-CONT. SOIL. NY TELEPHONE HIRING TYREE TO CLEANUP.

NY MANIFEST:

EPA ID:	NYD981491491
Country:	USA
Mailing Name:	KEYSPAN
Mailing Contact:	WAYNE SEBRO
Mailing Address:	221 EAST 37TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-338-6564

Document ID:	MAH7042860
Manifest Status:	Completed copy
Trans1 State ID:	MA13273
Trans2 State ID:	ME619018
Generator Ship Date:	940930
Trans1 Recv Date:	940930
Trans2 Recv Date:	941003
TSD Site Recv Date:	941003
Part A Recv Date:	Not reported
Part B Recv Date:	941019
Generator EPA ID:	NYD981491491
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	MAD039322250
TSDF ID:	MAD980523203
Waste Code:	B001 - PCB OIL (CONC) FROM TRANS, CAP, ETC
Quantity:	00005
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00020
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported

NEW YORK TELEPHONE CO (Continued) **1000136877**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	MAD039322250
Generator Ship Date:	2008-10-31
Trans1 Recv Date:	2008-10-31
Trans2 Recv Date:	2008-11-04
TSD Site Recv Date:	2008-11-05
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981491491
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD000816629
Waste Code:	Not reported
Quantity:	2500.0
Units:	P - Pounds
Number of Containers:	5.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001190969FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	MAD039322250
Generator Ship Date:	2008-10-31
Trans1 Recv Date:	2008-10-31
Trans2 Recv Date:	2008-11-04
TSD Site Recv Date:	2008-11-05
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981491491
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD000816629
Waste Code:	Not reported

NEW YORK TELEPHONE CO (Continued) **1000136877**

Quantity:	600.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001190969FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

NY Spills:

Site ID:	151060
Facility Addr2:	Not reported
Facility ID:	9012383
Spill Number:	9012383
Facility Type:	ER
SWIS:	3000
Investigator:	NJACAMPO
Referred To:	Not reported
Spill Date:	3/2/1991
Reported to Dept:	3/2/1991
CID:	04
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	3/13/1991
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	3/13/1991
Remediation Phase:	0
Date Entered In Computer:	3/4/1991
Spill Record Last Update:	3/18/1991
Spiller Name:	Not reported
Spiller Company:	NEW YORK TELEPONE
Spiller Address:	741 ZECKENDORF BLVD
Spiller City,St,Zip:	GARDEN CITY, NY
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	128384
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ACAMPORA" 10/10/95: This is additional information about material

NEW YORK TELEPHONE CO (Continued) **1000136877**

spilled from the translation of the old spill file: HYDRAULIC FLUID.
Remarks: HYDRAULIC HOSE BROKE ON BOOM TRUCK, SPILLED INTO STREET AND DRAIN.HAZ MAT ON SITE. TYREE HIRED USED SPEEDI DRY & DRAIN VAC'D OUT NO RESPONSE NECESSARY, CLEANUP COMPLETE

Material:
Site ID: 151060
Operable Unit ID: 949559
Operable Unit: 01
Material ID: 428871
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 151058
Facility Addr2: Not reported
Facility ID: 0208193
Spill Number: 0208193
Facility Type: ER
SWIS: 3000
Investigator: UNASSIGNED
Referred To: Not reported
Spill Date: 11/7/2002
Reported to Dept: 11/7/2002
CID: 04
Spill Cause: Traffic Accident
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/7/2003
Remediation Phase: 0

NEW YORK TELEPHONE CO (Continued) **1000136877**

Date Entered In Computer: 11/7/2002
Spill Record Last Update: 10/16/2003
Spiller Name: Not reported
Spiller Company: VERIZON
Spiller Address: Not reported
Spiller City,St,Zip: ZZ -
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 1
DER Facility ID: 128384
DEC Memo: Not reported
Remarks: a small portion went into a catch basin - clean up in progress by milroe associates - cell for caller 917-846-4423

Material:
Site ID: 151058
Operable Unit ID: 859729
Operable Unit: 01
Material ID: 552548
Material Code: 0021
Material Name: Transmission Fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 10
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 151058
Operable Unit ID: 859729
Operable Unit: 01
Material ID: 552549
Material Code: 0043A
Material Name: ANTIFREEZE
Case No.: Not reported
Material FA: Other
Quantity: 5
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NEW YORK TELEPHONE CO (Continued) **1000136877**

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

NY Hist Spills:

Region of Spill:	1
Spill Number:	9012383
Investigator:	ACAMPORA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	03/02/1991 08:20
Reported to Dept Date/Time:	03/02/91 12:00
SWIS:	28
Spiller Name:	NEW YORK TELEPONE
Spiller Contact:	Not reported
Spiller Phone:	(516) 794-9984
Spiller Address:	741 ZECKENDORF BLVD
Spiller City,St,Zip:	GARDEN CITY, NY
Spill Cause:	Equipment Failure
Reported to Dept:	In Sewer
Water Affected:	Not reported
Spill Source:	01
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	03/13/91
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	False
Spill Class:	Not reported
Spill Closed Dt:	03/13/91
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	03/04/91
Date Spill Entered In Computer Data File:	Not reported
Update Date:	03/18/91
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	50
Unkonwn Quantity Spilled:	False
Units:	Gallons

NEW YORK TELEPHONE CO (Continued) **1000136877**

Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: WASTE OIL
Class Type: WASTE OIL
Times Material Entry In File: 9509
CAS Number: Not reported
Last Date: 19940927
DEC Remarks: 10/10/95: This is additional information about material spilled from the translation of the old spill file: HYDRAULIC FLUID.
Remark: HYDRAULIC HOSE BROKE ON BOOM TRUCK, SPILLED INTO STREET AND DRAIN.HAZ MAT ON SITE. TYREE HIRED USED SPEEDI DRY DRAIN VAC D OUT NO RESPONSE NECESSARY, CLEANUP COMPLETE

M62 **AT&T LONG LINES** **RCRA-NonGen** **1000133196**
SSE **741 ZECKENDORF BLVD** **FINDS** **NYD980645758**
1/8-1/4 **GARDEN CITY, NY 11530**
0.130 mi.
686 ft. **Site 7 of 8 in cluster M**

Relative: Higher

Actual: 87 ft.

RCRA-NonGen:
Date form received by agency: 01/01/2007
Facility name: A T & T CORP
Facility address: 741 ZECKENDORF BLVD
GARDEN CITY, NY 115302110
EPA ID: NYD980645758
Mailing address: W MONROE SUITE 2240
CHICAGO, NY 60606
Contact: Not reported
Contact address: W MONROE SUITE 2240
CHICAGO, NY 60606
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: A T & T CORP
Owner/operator address: 295 MAPLE AVE
BASKING RIDGE, IL 07920
Owner/operator country: US
Owner/operator telephone: (201) 645-4113
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: A T & T CORP
Owner/operator address: 295 MAPLE AVE
BASKING RIDGE, IL 07920
Owner/operator country: US
Owner/operator telephone: (201) 645-4113
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

AT&T LONG LINES (Continued) **1000133196**

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:

U.S. importer of hazardous waste:	Unknown
Mixed waste (haz. and radioactive):	Unknown
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Unknown
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	Unknown
Furnace exemption:	Unknown
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No
Off-site waste receiver:	Commercial status unknown

Historical Generators:

Date form received by agency: 01/01/2006
Facility name: A T & T CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Facility name: A T & T CORP
Classification: Not a generator, verified

Date form received by agency: 09/25/1997
Facility name: A T & T CORP
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110013676343

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AT&T LONG LINES (Continued) **1000133196**

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

M63 **VERIZON** **RCRA-CESQG** **1001119692**
SSE **741 ZECKENDORF BLVD 1ST FLOOR** **MANIFEST** **NYR000029827**
1/8-1/4 **GARDEN CITY, NY 11530** **NY Spills**
0.130 mi. **NY Hist Spills**
686 ft. **Site 8 of 8 in cluster M**

Relative:
Higher

Actual:
87 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	VERIZON
Facility address:	741 ZECKENDORF BLVD 1ST FLOOR GARDEN CITY, NY 11530
EPA ID:	NYR000029827
Mailing address:	W 18TH ST NEW YORK, NY 10011
Contact:	VALERIE POWELL
Contact address:	W 18TH ST NEW YORK, NY 10011
Contact country:	US
Contact telephone:	(212) 620-4226
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYNEX
Owner/operator address:	741 ZECKENDORF BLVD GARDEN CITY, NY 11530
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	VERIZON
Owner/operator address:	W 18TH ST NEW YORK, NY 10011
Owner/operator country:	US

VERIZON (Continued) **1001119692**

Owner/operator telephone: (212) 620-4226
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/15/2004
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: VERIZON
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/15/2004
Facility name: VERIZON
Classification: Large Quantity Generator

Date form received by agency: 07/08/1999
Facility name: VERIZON
Site name: NYNEX
Classification: Not a generator, verified

Date form received by agency: 02/27/1998
Facility name: VERIZON
Site name: BELL ATLANTIC-NY
Classification: Large Quantity Generator

Date form received by agency: 09/26/1996
Facility name: VERIZON
Site name: NYNEX
Classification: Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYR000029827
Country: USA
Mailing Name: NYNEX
Mailing Contact: PAUL GARGIULO
Mailing Address: 221 E 37TH ST

VERIZON (Continued) **1001119692**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10016
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	212-338-6453

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009869825
Generator Ship Date:	2007-07-09
Trans1 Recv Date:	2007-07-09
Trans2 Recv Date:	2007-07-09
TSD Site Recv Date:	2007-07-17
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000029827
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD000816629
Waste Code:	Not reported
Quantity:	1600.0
Units:	P - Pounds
Number of Containers:	4.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000932163FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	07
Manifest Status:	000932163FLE
Trans1 State ID:	NYR000029827
Trans2 State ID:	Not reported
Generator Ship Date:	OHD000816629
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	MAD039322250
TSD Site Recv Date:	Not reported
Part A Recv Date:	OHD009869825
Part B Recv Date:	2007-07-09
Generator EPA ID:	N
Trans1 EPA ID:	N

VERIZON (Continued) **1001119692**

Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	4
Number of Containers:	DF
Container Type:	1600
Handling Method:	P
Specific Gravity:	1
Waste Code:	L
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	MAQ0065160
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	03/02/2005
Trans1 Recv Date:	03/02/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/09/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000029827
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	MA5000004713
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2005
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported

VERIZON (Continued) **1001119692**

Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYG1624905
Manifest Status:	Not reported
Trans1 State ID:	NYD064743263
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2000
Trans1 Recv Date:	05/08/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/18/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000029827
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	RK3198
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00017
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	00
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	MAQ0065160
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	03/02/2005
Trans1 Recv Date:	03/02/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/09/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000029827

VERIZON (Continued) **1001119692**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	MA5000004713
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Quantity:	00300
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Trans2 State ID:	OHD009869825
Generator Ship Date:	7/9/2007
Trans1 Recv Date:	7/9/2007
Trans2 Recv Date:	7/9/2007
TSD Site Recv Date:	7/17/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000029827
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD000816629
Waste Code:	Not reported
Quantity:	1600
Units:	P - Pounds
Number of Containers:	4
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000932163FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

VERIZON (Continued) **1001119692**

Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: PAC5629654
Manifest Status: Completed copy
Trans1 State ID: PAAH0331
Trans2 State ID: Not reported
Generator Ship Date: 970501
Trans1 Recv Date: 970501
Trans2 Recv Date: Not reported
TSD Site Recv Date: 970502
Part A Recv Date: 970515
Part B Recv Date: 970515
Generator EPA ID: NYR000029827
Trans1 EPA ID: NYD982792814
Trans2 EPA ID: Not reported
TSDF ID: PAD087561015
Waste Code: D002 - NON-LISTED CORROSIVE WASTES
Quantity: 03140
Units: P - Pounds
Number of Containers: 006
Container Type: CW - Wooden boxes
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 97
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

NY Spills:
Site ID: 151061
Facility Addr2: Not reported
Facility ID: 9704611
Spill Number: 9704611
Facility Type: ER
SWIS: 3000
Investigator: UNASSIGNED
Referred To: Not reported
Spill Date: 7/16/1997
Reported to Dept: 7/17/1997
CID: 04
Spill Cause: Housekeeping
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: True

VERIZON (Continued) **1001119692**

Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/17/1997
Remediation Phase:	0
Date Entered In Computer:	7/17/1997
Spill Record Last Update:	7/18/1997
Spiller Name:	RICHARD MYER
Spiller Company:	NYNEX
Spiller Address:	741 ZECKENDORF BLVD
Spiller City,St,Zip:	GARDEN CITY, NY
Spiller Company:	001
Contact Name:	RICHARD MYER
Contact Phone:	(516) 832-3658
DEC Region:	1
DER Facility ID:	128384
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE" NCFM ON SITE AND SPILL WAS CHILLER WATER NOT ANTIFREEZE, NO FURTHER ACTION NEEDED AT THIS TIME
Remarks:	DOING WORK ON AIR COND. AND SPILLING FUILDS INTO LOT AND GOING INTO SEW

Material:

Site ID:	151061
Operable Unit ID:	1047849
Operable Unit:	01
Material ID:	333868
Material Code:	0043A
Material Name:	ANTIFREEZE
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9704611
Investigator:	NONE
Caller Name:	Not reported

VERIZON (Continued) **1001119692**

Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 07/16/1997 18:00
Reported to Dept Date/Time: 07/17/97 10:19
SWIS: 28
Spiller Name: NYNEX
Spiller Contact: RICHARD MYER
Spiller Phone: (516) 832-3658
Spiller Contact: RICHARD MYER
Spiller Phone: (516) 832-3658
Spiller Address: 741 ZECKENDORF BLVD
Spiller City,St,Zip: GARDEN CITY, NY
Spill Cause: Housekeeping
Reported to Dept: In Sewer
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Affected Persons
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 07/17/97
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/17/97
Date Spill Entered In Computer Data File: Not reported
Update Date: 07/18/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Hazardous Material
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: ANTIFREEZE
Class Type: ANTIFREEZE
Times Material Entry In File: 0
CAS Number: Not reported

VERIZON (Continued) **1001119692**

Last Date: Not reported
DEC Remarks: NCFM ON SITE AND SPILL WAS CHILLER WATER NOT ANTIFREEZE, NO FURTHER ACTION NEEDED AT THIS TIME
Remark: DOING WORK ON AIR COND. AND SPILLING FUILDS INTO LOT AND GOING INTO SEW

L64 **GEORGIAN PRESS INC** **LTANKS S100149517**
SSE **750 ZEKENDORF BLVD** **HIST LTANKS N/A**
1/8-1/4 **EAST GARDEN CITY, NY**
0.131 mi.
692 ft. **Site 2 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

LTANKS:

Site ID:	281907
Spill No:	8600958
Spill Date:	5/9/1986
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	7/18/1994
Facility Addr2:	Not reported
Cleanup Ceased:	7/18/1994
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	5/9/1986
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/5/1986
Spill Record Last Update:	3/26/2004
Spiller Name:	Not reported
Spiller Company:	GEORGIAN PRESS INC
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	228862
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "T/T/F WELL" / / : DEC TO SEND 3 OPT.LETTER&FOLLOW UP-F.D. TO HAVE TANK PUMPED OUT. NASSAU CTY FIRE MARSHALL INVESTIGATE. REFERRED TO 89-07005.
Remarks:	2K U/G STEEL TANK FAILED HYDRO STATIC TEST-1LB. LOST AIR&10" PRODUCT IN 20 MINUTES

Material:

Site ID:	281907
Operable Unit ID:	898606
Operable Unit:	01

GEORGIAN PRESS INC (Continued) **S100149517**

Material ID: 477518
Material Code: 0326A
Material Name: ISOPROPYL ALCOHOL
Case No.: 00067630
Material FA: Other
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 281907
Spill Tank Test: 1529921
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 1
Spill Number: 8600958
Spill Date: 05/09/1986
Spill Time: 11:00
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 07/18/94
Cleanup Ceased: 07/18/94
Cleanup Meets Standard: True
Investigator: T/T/F WELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 05/09/86
Reported to Department Time: 11:10
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: GEORGIAN PRESS INC
Spiller Address: Not reported
Spiller City,St,Zip: Not reported

GEORGIAN PRESS INC (Continued) **S100149517**

Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Fire Department
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 06/05/86
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 07/09/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Hazardous Material
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: ISOPROPYL ALCOHOL
Class Type: ISOPROPYL ALCOHOL
Times Material Entry In File: 27
CAS Number: 00067630
Last Date: 19950815
DEC Remarks: / / : DEC TO SEND 3 OPT.LETTER FOLLOW UP-F.D. TO HAVE TANK PUMPED OUT. / / : DEC TO SEND 3 OPT.LETTER FOLLOW UP-F.D. TO HAVE TANK PUMPED OUT. NASSAU CTY FIRE MARSHALL INVESTIGATE. / / : DEC TO SEND 3 OPT.LETTER FOLLOW UP-F.D. TO HAVE TANK PUMPED OUT. NASSAU CTY FIRE MARSHALL INVESTIGATE. REFERRED TO 89-07005.
Spill Cause: 2K U/G STEEL TANK FAILED HYDRO STATIC TEST-1LB. LOST AIR 10 PRODUCT IN 20 MINUTES

L65 **FORTUNOFF CLEARANCE CENTER & PICKUP** **UST** **U004052746**
SSE **750 ZECKENDORF BLVD** **N/A**
1/8-1/4 **EAST GARDEN CITY, NY 11530**
0.131 mi.
692 ft. **Site 3 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

NCFM UST:
Tank Type: OUTDOOR UG HOR D/W STEEL
Tank Size: 2000
Tank Contents: ISO-PROPYL ALCOHOL

L66 **ITT CONTINENTAL BAKING CO.** **UST** **U003846851**
SSE **750 ZECKENDORF BLVD** **N/A**
1/8-1/4 **EAST GARDEN CITY, NY 11530**
0.131 mi.
692 ft. **Site 4 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

NCFM UST:
Tank Type: OUTDOOR UG HOR STEEL
Tank Size: 10000
Tank Contents: DIESEL

L67 **GEORGIAN WEBB OFFSET CO** **HIST LTANKS** **S100150375**
SSE **750 ZECKENDORF BLVD** **NY Spills** **N/A**
1/8-1/4 **GARDEN CITY, NY**
0.131 mi.
692 ft. **Site 5 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

HIST LTANKS:

Region of Spill:	1
Spill Number:	8907005
Spill Date:	08/23/1989
Spill Time:	11:30
Spill Cause:	Tank Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	/ /
Cleanup Ceased:	/ /
Cleanup Meets Standard:	False
Investigator:	MIRZA WELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	08/23/89
Reported to Department Time:	11:30
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	GEORGIAN WEBB OFFSET CO
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	Not reported
Facility Extention:	Not reported
Spill Notifier:	Other
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False

GEORGIAN WEBB OFFSET CO (Continued) **S100150375**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/19/89
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 07/17/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: KEROSENE
Class Type: KEROSENE
Times Material Entry In File: 2052
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Spill Cause: 2 PETROLUEM UG STORAGE TANKS REMOVED IN MARCH CONTAMINATION OBSERVED. FURTHER INVESTIGATION BEING CONDUCTED BY PRESENT OWNERS CONSULTANT ROUX ASSOC

NY Spills:
Site ID: 118787
Facility Addr2: Not reported
Facility ID: 8907005
Spill Number: 8907005
Facility Type: ER
SWIS: 3020
Investigator: Unassigned
Referred To: Not reported
Spill Date: 8/23/1989
Reported to Dept: 8/23/1989
CID: 04
Spill Cause: Other
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 4/11/2008
Remediation Phase: 0
Date Entered In Computer: 10/19/1989

GEORGIAN WEBB OFFSET CO (Continued) **S100150375**

Spill Record Last Update:	4/14/2008
Spiller Name:	Not reported
Spiller Company:	GEORGIAN WEBB OFFSET CO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	298154
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MIRZA WELL"
Remarks:	2 PETROLUEM UG STORAGE TANKS REMOVED IN MARCH CONTAMINATION OBSERVED. FURTHER INVESTIGATION BEING CONDUCTED BY PRESENT OWNERS CONSULTANT ROUX ASSOC

Material:

Site ID:	118787
Operable Unit ID:	934766
Operable Unit:	01
Material ID:	443812
Material Code:	0012
Material Name:	Kerosene (#1 Fuel Oil)
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

L68 **FORTUNOFF** **RCRA-NonGen** **1000115971**
SSE **750 ZECKENDORF BLVD** **FINDS** **NYD101213056**
1/8-1/4 **GARDEN CITY, NY 11530** **MANIFEST**
0.131 mi.
692 ft. **Site 6 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

RCRA-NonGen:

Date form received by agency:	01/01/2007
Facility name:	FORTUNOFF
Facility address:	750 ZECKENDORF BLVD GARDEN CITY, NY 115302119
EPA ID:	NYD101213056
Mailing address:	OLD COUNTRY RD WESTBURY, NY 11590

FORTUNOFF (Continued) **1000115971**

Contact: Not reported
Contact address: OLD COUNTRY RD
WESTBURY, NY 11590
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: M FORTUNOFF CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: M FORTUNOFF CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: FORTUNOFF
Classification: Not a generator, verified

Date form received by agency: 07/08/1999

FORTUNOFF (Continued) **1000115971**

Facility name: FORTUNOFF
Classification: Not a generator, verified

Date form received by agency: 01/28/1985
Facility name: FORTUNOFF
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004378566

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD101213056
Country: USA
Mailing Name: FORTUNOFFS WAREHOUSE
Mailing Contact: FORTUNOFFS WAREHOUSE
Mailing Address: 750 ZECKENDORF BLVD
Mailing Address 2: Not reported
Mailing City: GARDEN CIITY
Mailing State: NY
Mailing Zip: 11530
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 516-228-8100

Document ID: NJA0036587
Manifest Status: Completed copy
Trans1 State ID: NJSWAS847
Trans2 State ID: Not reported
Generator Ship Date: 850225
Trans1 Recv Date: 850225
Trans2 Recv Date: Not reported
TSD Site Recv Date: 850226
Part A Recv Date: 850306
Part B Recv Date: 850305
Generator EPA ID: NYD101213056
Trans1 EPA ID: NJD065825341
Trans2 EPA ID: Not reported
TSDF ID: NJD002454544
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 01375
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 025
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.

FORTUNOFF (Continued) **1000115971**

Specific Gravity:	100
Year:	85
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYA6369255
Manifest Status:	Completed copy
Trans1 State ID:	JA77NJDEP
Trans2 State ID:	Not reported
Generator Ship Date:	870206
Trans1 Recv Date:	870206
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870206
Part A Recv Date:	870218
Part B Recv Date:	870212
Generator EPA ID:	NYD101213056
Trans1 EPA ID:	NJD065825341
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049178296
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01600
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	87
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2978190
Manifest Status:	Completed copy
Trans1 State ID:	PTC1778
Trans2 State ID:	Not reported
Generator Ship Date:	901012

FORTUNOFF (Continued) **1000115971**

Trans1 Recv Date:	901012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	901018
Part A Recv Date:	901106
Part B Recv Date:	901106
Generator EPA ID:	NYD101213056
Trans1 EPA ID:	MND980791321
Trans2 EPA ID:	Not reported
TSDF ID:	KSD980964993
Waste Code:	B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB
Quantity:	10457
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	003
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	05602
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	018
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA0175158
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPS847
Trans2 State ID:	Not reported
Generator Ship Date:	860304
Trans1 Recv Date:	860304
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860305
Part A Recv Date:	860311
Part B Recv Date:	860311
Generator EPA ID:	NYD101213056
Trans1 EPA ID:	NJD065825341
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002454544
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels

FORTUNOFF (Continued) **1000115971**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	86
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2978181
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	PTC1974MN
Trans2 State ID:	Not reported
Generator Ship Date:	901107
Trans1 Recv Date:	901107
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	901112
Part A Recv Date:	901204
Part B Recv Date:	901231
Generator EPA ID:	NYD101213056
Trans1 EPA ID:	MND980791321
Trans2 EPA ID:	Not reported
TSDF ID:	KSD980964993
Waste Code:	B006 - PCB TRANSFORMERS WITH 500 PPM OR > PCB
Quantity:	03855
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	02646
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

FORTUNOFF (Continued) **1000115971**

Mgmt Method Type Code: Not reported

L69 **AAR AIRCRAFT COMP. SVCS.** **AST** **A100210110**
SSE **747 ZECKENDORF BLVD.** **N/A**
1/8-1/4 **GARDEN CITY, NY**
0.131 mi.
693 ft. **Site 7 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

NASSAU CO. AST:

Facility ID:	001697
Tank ID:	0001
Tank Location:	Indoors, Aboveground
Capacity (Gal):	00000100
Tank Status:	In Service
Tank Material:	STEEL
Int Protection:	None
Ext Protection:	NONE
Piping Type:	Steel/Iron
Material Type:	Fresh/Product
Description:	SKYDROL
Leak Detect:	NONE
Containment:	OTHER
Product Gauge:	No
Dispense Method:	Suction
Fill Type:	Gravity
Install Date:	041970
Owner Name:	AAR AIRCRAFT COMP. SVCS.
Owner Address:	747 ZECKENDORF BLVD.
Owner City,St,Zip:	GARDEN CITY, NY 11530
Permitee Name:	SAME
Permitee Address:	Not reported
Permitee City,St,Zip:	Not reported

Facility ID:	001697
Tank ID:	0002
Tank Location:	Indoors, Aboveground
Capacity (Gal):	00000100
Tank Status:	In Service
Tank Material:	STEEL
Int Protection:	None
Ext Protection:	NONE
Piping Type:	Steel/Iron
Material Type:	Fresh/Product
Description:	SKYDROL
Leak Detect:	NONE
Containment:	OTHER
Product Gauge:	No
Dispense Method:	Suction
Fill Type:	Gravity
Install Date:	041970
Owner Name:	AAR AIRCRAFT COMP. SVCS.
Owner Address:	747 ZECKENDORF BLVD.
Owner City,St,Zip:	GARDEN CITY, NY 11530
Permitee Name:	SAME
Permitee Address:	Not reported
Permitee City,St,Zip:	Not reported

Facility ID: 001697

AAR AIRCRAFT COMP. SVCS. (Continued) **A100210110**

Tank ID: 0003
Tank Location: Indoors, Aboveground
Capacity (Gal): 00000030
Tank Status: In Service
Tank Material: STEEL
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Material Type: Fresh/Product
Description: VARSOLS
Leak Detect: NONE
Containment: OTHER
Product Gauge: No
Dispense Method: Suction
Fill Type: Gravity
Install Date: 041970
Owner Name: AAR AIRCRAFT COMP. SVCS.
Owner Address: 747 ZECKENDORF BLVD.
Owner City,St,Zip: GARDEN CITY, NY 11530
Permitee Name: SAME
Permitee Address: Not reported
Permitee City,St,Zip: Not reported

Facility ID: 001697
Tank ID: 0004
Tank Location: Indoors, Aboveground
Capacity (Gal): 00000050
Tank Status: In Service
Tank Material: STEEL
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Material Type: Fresh/Product
Description: OIL, HYDRAULIC
Leak Detect: NONE
Containment: OTHER
Product Gauge: No
Dispense Method: Suction
Fill Type: Gravity
Install Date: 041970
Owner Name: AAR AIRCRAFT COMP. SVCS.
Owner Address: 747 ZECKENDORF BLVD.
Owner City,St,Zip: GARDEN CITY, NY 11530
Permitee Name: SAME
Permitee Address: Not reported
Permitee City,St,Zip: Not reported

Facility ID: 001697
Tank ID: 0005
Tank Location: Indoors, Aboveground
Capacity (Gal): 00000035
Tank Status: In Service
Tank Material: STEEL
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Material Type: Fresh/Product

AAR AIRCRAFT COMP. SVCS. (Continued) **A100210110**

Description: OIL, HYDRAULIC
Leak Detect: NONE
Containment: OTHER
Product Gauge: No
Dispense Method: Suction
Fill Type: Gravity
Install Date: 041970
Owner Name: AAR AIRCRAFT COMP. SVCS.
Owner Address: 747 ZECKENDORF BLVD.
Owner City,St,Zip: GARDEN CITY, NY 11530
Permitee Name: SAME
Permitee Address: Not reported
Permitee City,St,Zip: Not reported

Click this hyperlink while viewing on your computer to access
29 additional NY_AST_NASSAU: record(s) in the EDR Site Report.

L70 **AAR AIRCRAFT COMPONENT SERVICES** **RCRA-LQG** **1000133376**
SSE **747 ZECKENDORF BOULEVARD** **FINDS** **NYD077508091**
1/8-1/4 **GARDEN CITY, NY 11530** **MANIFEST**
0.131 mi. **MANIFEST**
693 ft. **Site 8 of 9 in cluster L** **MANIFEST**

Relative:
Lower

Actual:
84 ft.

RCRA-LQG:
Date form received by agency: 02/14/2008
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR AIRCRAFT COMPONENT SERVICES - NEW YORK
Facility address: 747 ZECKENDORF BLVD
GARDEN CITY, NY 11530
EPA ID: NYD077508091
Mailing address: ZECKENDORF BLVD
GARDEN CITY, NY 11530
Contact: PETER SANZ
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (516) 357-2743
Contact email: PSANZ@AARCORP.COM
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: AAR AIRCRAFT COMPONENT SERVICES
Owner/operator address: AVENUE OF THE AMERICAS

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1980
Owner/Op end date: Not reported

Owner/operator name: STAR FINANCIAL INC
Owner/operator address: AVENUE OF THE AMERICAS
NEW YORK, NY 10036
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1980
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: No
Generated waste on-site: Not reported

Historical Generators:
Date form received by agency: 01/01/2007
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Site name: AAR AIRCRAFT COMPONET SERVICES- NEW YORK
Classification: Small Quantity Generator

Date form received by agency: 02/09/2006
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR AIRCRAFT COMPONET SERVICES- NEW YORK
Classification: Large Quantity Generator

Date form received by agency: 02/08/2006
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR AIRCRAFT COMPONET SERVICES- NEW YORK
Classification: Small Quantity Generator

Date form received by agency: 02/18/2004
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR AIRCRAFT COMPONENT SERVICE
Classification: Large Quantity Generator

Date form received by agency: 01/10/2002
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR AIRCRAFT COMPONENT SERVICES
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AARAIRCRAFT COMPONENT SERVICES
Classification: Large Quantity Generator

Date form received by agency: 02/06/1998
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR TYECHNICAL SERVICE CENTER
Classification: Large Quantity Generator

Date form received by agency: 03/01/1996
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR TECHNICAL SERVICE CENTER
Classification: Large Quantity Generator

Date form received by agency: 03/09/1994
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR TECHNICAL SERVICE CENTER
Classification: Large Quantity Generator

Date form received by agency: 03/03/1992
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR TECHNICAL SERVICE CENTER
Classification: Large Quantity Generator

Date form received by agency: 12/16/1981
Facility name: AAR AIRCRAFT COMPONENT SERVICES - NEW YO
Site name: AAR TECHNICAL SERVICE CENTER
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D004
Waste name: ARSENIC

Waste code: D006
Waste name: CADMIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D035
Waste name: METHYL ETHYL KETONE

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: LABP
Waste name: LAB PACK

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Waste code: P005
Waste name: ALLYL ALCOHOL

Biennial Reports:

Last Biennial Reporting Year: 2007

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 5596.3

Waste code: D004
Waste name: ARSENIC
Amount (Lbs): 4357.8

Waste code: D006
Waste name: CADMIUM
Amount (Lbs): 10417.9

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 5198.7

Waste code: D008
Waste name: LEAD
Amount (Lbs): 3119.3

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 3619.3

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 1238.5

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 1238.5

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 1238.5

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 1238.5

Waste code: LABP
Waste name: LAB PACK
Amount (Lbs): 1410

Waste code: P005
Waste name: ALLYL ALCOHOL
Amount (Lbs): 1238.5

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: TSD IS-Container Use and Management
Date violation determined: 10/15/2008
Date achieved compliance: 12/09/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/04/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/13/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 10/15/2008
Date achieved compliance: 12/09/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/04/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/13/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 10/15/2008
Date achieved compliance: 12/09/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/04/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/13/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 10/15/2008
Date achieved compliance: 12/16/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/04/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/13/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 10/15/2008
Date achieved compliance: 12/09/2008
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/04/2008
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 02/13/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.4(c)(1)
Area of violation: Generators - General
Date violation determined: 05/13/2005
Date achieved compliance: 08/24/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/16/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.2(h)(1)
Area of violation: Generators - General

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date violation determined: 05/13/2005
Date achieved compliance: 08/24/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/16/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 374-3.2(d)(4)(i)
Area of violation: Generators - General
Date violation determined: 05/13/2005
Date achieved compliance: 08/24/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/16/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.9(d)
Area of violation: Generators - General
Date violation determined: 05/13/2005
Date achieved compliance: 08/24/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/16/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-1.1(d)(1)(iv)
Area of violation: Generators - General
Date violation determined: 05/13/2005
Date achieved compliance: 08/24/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/16/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 374-3.3(e)(5)
Area of violation: Generators - General
Date violation determined: 05/13/2005

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date achieved compliance: 08/24/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/16/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(i)(a)
Area of violation: Generators - General
Date violation determined: 05/13/2005
Date achieved compliance: 08/24/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/16/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/03/1999
Date achieved compliance: 01/31/2000
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/30/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 07/14/1997
Date achieved compliance: 07/29/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/14/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 04/21/1989
Date achieved compliance: 02/27/1990

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 12/04/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 5000
Paid penalty amount: 5000

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 04/21/1989
Date achieved compliance: 02/27/1990
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 06/09/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 5000
Final penalty amount: 5000
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 10/15/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 12/09/2008
Evaluation lead agency: State

Evaluation date: 10/15/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 12/16/2008
Evaluation lead agency: State

Evaluation date: 10/15/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 12/09/2008
Evaluation lead agency: State

Evaluation date: 10/15/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 12/09/2008
Evaluation lead agency: State

Evaluation date: 10/15/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Container Use and Management
Date achieved compliance: 12/09/2008
Evaluation lead agency: State

Evaluation date: 05/13/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Area of violation: Generators - General
Date achieved compliance: 08/24/2005
Evaluation lead agency: State

Evaluation date: 12/03/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 01/31/2000
Evaluation lead agency: EPA

Evaluation date: 06/24/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/29/1997
Evaluation lead agency: State

Evaluation date: 08/12/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 02/02/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 04/21/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/27/1990
Evaluation lead agency: State

Evaluation date: 10/06/1983
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110000838522

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

PA MANIFEST:

Manifest Number:	PAH192634
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	06/09/06
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	3
Waste Number:	D001
Container Number:	1
Container Type:	DF
Waste Quantity:	6
Unit:	P
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Manifest Number:	PAH192634
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	06/09/06
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	4
Waste Number:	D001
Container Number:	2
Container Type:	DF
Waste Quantity:	40
Unit:	P
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Manifest Number:	PAH192634
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	06/09/06

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	DM
Waste Quantity:	250
Unit:	P
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Manifest Number:	PAH192634
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	06/09/06
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	1
Waste Number:	D005
Container Number:	1
Container Type:	DM
Waste Quantity:	250
Unit:	P
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Manifest Number:	PAH192634
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	06/09/06
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	DM
Waste Quantity:	200
Unit:	P
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Manifest Number:	003531377JJK
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	3/27/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	2
Container Type:	CW
Waste Quantity:	400
Unit:	P
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Manifest Number:	003531377JJK
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	3/27/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	3
Waste Number:	D001
Container Number:	1
Container Type:	DM
Waste Quantity:	15
Unit:	G
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Manifest Number:	003531377JJK
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	3/27/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	DF
Waste Quantity:	5
Unit:	G
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Manifest Number:	003531377JJK
Manifest Type:	T
Generator Epa Id:	NYD077508091
Generator Date:	3/27/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD Epa Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	516-222-9000
Page Number:	1
Line Number:	4
Waste Number:	D002
Container Number:	1

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Container Type: DF
Waste Quantity: 5
Unit: G
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

NY MANIFEST:
EPA ID: NYD077508091
Country: USA
Mailing Name: AAR TECHNICAL SERVICE CENTER
Mailing Contact: CHARLES J MILLER
Mailing Address: 747 ZECKENDORF BLVD
Mailing Address 2: Not reported
Mailing City: GARDEN CITY
Mailing State: NY
Mailing Zip: 11530
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 516-222-9000

Document ID: NJA2261509
Manifest Status: Completed copy
Trans1 State ID: S6993
Trans2 State ID: Not reported
Generator Ship Date: 960604
Trans1 Recv Date: 960604
Trans2 Recv Date: Not reported
TSD Site Recv Date: 960604
Part A Recv Date: 960619
Part B Recv Date: 960614
Generator EPA ID: NYD077508091
Trans1 EPA ID: NJD980772768
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: D007 - CHROMIUM 5.0 MG/L TCLP
Quantity: 00275
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 005
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00550
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 010
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 96
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA2922872
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	02/29/2000
Trans1 Recv Date:	02/29/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/29/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	S6993
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F005 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F005 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	00
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CT5000001495
Trans2 State ID:	Not reported
Generator Ship Date:	2009-01-02
Trans1 Recv Date:	2009-01-02
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-01-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	CT5000001495
Waste Code:	Not reported
Quantity:	204.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	100016134CTN
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H010

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-06-04
Trans1 Recv Date:	2009-06-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-06-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	30.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	006015857JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-06-04
Trans1 Recv Date:	2009-06-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-06-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	006015857JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-03-04
Trans1 Recv Date:	2009-03-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-03-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	400.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	005369966JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-03-04
Trans1 Recv Date:	2009-03-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-03-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	55.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Year:	09
Manifest Tracking Num:	005369966JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-06-04
Trans1 Recv Date:	2009-06-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-06-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	006015857JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H111

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-03-04
Trans1 Recv Date:	2009-03-04

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-03-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	005369966JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-06-04
Trans1 Recv Date:	2009-06-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-06-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	55.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	006015857JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-06-04
Trans1 Recv Date:	2009-06-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-06-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	145.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	4.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	006015857JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-03-04
Trans1 Recv Date:	2009-03-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-03-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	30.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	005369966JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD980772768
Trans2 State ID:	Not reported
Generator Ship Date:	2009-03-04
Trans1 Recv Date:	2009-03-04
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-03-04
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	Not reported
Quantity:	55.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	005369966JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 2009-03-04
Trans1 Recv Date: 2009-03-04
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-03-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD077508091
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 90.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 3.0
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1.0
Year: 09
Manifest Tracking Num: 005369966JJK
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H061

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD980772768
Trans2 State ID: Not reported
Generator Ship Date: 2009-06-04
Trans1 Recv Date: 2009-06-04
Trans2 Recv Date: Not reported
TSD Site Recv Date: 2009-06-04
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD077508091
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NJD991291105
Waste Code: Not reported
Quantity: 30.0
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1.0

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	006015857JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NJA1049784
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJSWAS300
Trans2 State ID:	Not reported
Generator Ship Date:	900914
Trans1 Recv Date:	900914
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900914
Part A Recv Date:	900928
Part B Recv Date:	901010
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA1601539
Manifest Status:	Completed copy
Trans1 State ID:	S72775490
Trans2 State ID:	Not reported
Generator Ship Date:	940105
Trans1 Recv Date:	940105
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940105
Part A Recv Date:	940118
Part B Recv Date:	940120
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	NJD986609949
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	F001 - UNKNOWN
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00440
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00500
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA1894945
Manifest Status:	Completed copy
Trans1 State ID:	S6993
Trans2 State ID:	Not reported
Generator Ship Date:	940909
Trans1 Recv Date:	940909
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940909
Part A Recv Date:	940919
Part B Recv Date:	940922
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00440
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA2117261
Manifest Status:	Completed copy
Trans1 State ID:	S6993
Trans2 State ID:	Not reported
Generator Ship Date:	950628
Trans1 Recv Date:	950628
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950628
Part A Recv Date:	950707
Part B Recv Date:	950711
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00605
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	011
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA2023223
Manifest Status:	Completed copy
Trans1 State ID:	S6993
Trans2 State ID:	Not reported
Generator Ship Date:	950103
Trans1 Recv Date:	950103
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950103
Part A Recv Date:	950112
Part B Recv Date:	950113
Generator EPA ID:	NYD077508091
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID:	NJD991291105
Waste Code:	D007 - CHROMIUM 5.0 MG/L TCLP
Quantity:	00825
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	015
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Click this hyperlink while viewing on your computer to access
275 additional NY_MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

Manifest Code:	NJA5318577
EPA ID:	NYD077508091
Date Shipped:	20060602
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060602
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060602
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	07200625
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	005369966JJK
EPA ID:	NYD077508091
Date Shipped:	3/4/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	3/4/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	3/4/09
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H141

Waste Code: F005
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 30
Unit: G
Hand Code: H061

Waste Code: D001
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 90
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 400
Unit: P
Hand Code: H141

Manifest Code: 003873560JJK
EPA ID: NYD077508091
Date Shipped: 5/12/2008
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 5/12/2008
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 5/12/2008
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D005
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 500
Unit: P
Hand Code: H111

Manifest Code: 003122891JJK
EPA ID: NYD077508091
Date Shipped: 11/8/200
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 11/8/2
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 11/8/2
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: 004257097JJK
EPA ID: NYD077508091
Date Shipped: 9/8/2008
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 9/8/2008
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 9/9/2008
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H141

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Waste Code: F005
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 55
Unit: P
Hand Code: H111

Manifest Code: 006015857JJK
EPA ID: NYD077508091
Date Shipped: 6/4/09
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 6/4/09
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 6/4/09
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D001
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H061

Waste Code: D001
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 30
Unit: G
Hand Code: H061

Waste Code: D001

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Manifest Year: 2009 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 500
Unit: P
Hand Code: H111

Waste Code: F005
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 30
Unit: G
Hand Code: H061

Waste Code: D001
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 145
Unit: G
Hand Code: H061

Manifest Code: 003121725JJK
EPA ID: NYD077508091
Date Shipped: 7/20/200
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 7/20/2
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 7/23/2
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D006
Manifest Year: 2007 New Jersey Manifest Data

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Quantity: 800
Unit: P
Hand Code: H11

Waste Code: D001
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H06

Waste Code: D001
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H06

Waste Code: D006
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 165
Unit: G
Hand Code: H14

Waste Code: F001
Manifest Year: 2007 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H06

Manifest Code: 004259686JJK
EPA ID: NYD077508091
Date Shipped: 12/1/2008
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 12/1/2008
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 12/1/2008
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: F005
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H141

Waste Code: D001
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D001
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H141

Waste Code: F001
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H061

Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 500
Unit: P
Hand Code: H111

Manifest Code: NJA5249302
EPA ID: NYD077508091
Date Shipped: 20050504
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 050504
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050504
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 06140525
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5248762
EPA ID: NYD077508091
Date Shipped: 20050606
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 050606
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 050606
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 07080521
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Manifest Code:	NJA5270524
EPA ID:	NYD077508091
Date Shipped:	20051005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	051005
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	051005
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	12090521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	005974946JJK
EPA ID:	NYD077508091
Date Shipped:	9/18/09
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	9/18/09
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 9/18/09
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: Not reported
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D006
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 110
Unit: G
Hand Code: H141

Waste Code: D001
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 55
Unit: G
Hand Code: H061

Waste Code: D001
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 30
Unit: G
Hand Code: H061

Waste Code: F005
Manifest Year: 2009 New Jersey Manifest Data
Quantity: 80
Unit: G
Hand Code: H061

Manifest Code: 001872750JJK
EPA ID: NYD077508091
Date Shipped: 3/9/2007
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 3/9/20
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	3/9/20
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	D001
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	220
Unit:	G
Hand Code:	H14

Waste Code:	D006
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	500
Unit:	P
Hand Code:	H11

Waste Code:	D008
Manifest Year:	2007 New Jersey Manifest Data
Quantity:	55
Unit:	G
Hand Code:	H06

Manifest Code:	001871488JJK
EPA ID:	NYD077508091
Date Shipped:	2/11/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	2/11/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	2/11/2008
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 300
Unit: P
Hand Code: H111

Waste Code: D006
Manifest Year: 2008 New Jersey Manifest Data
Quantity: 165
Unit: G
Hand Code: H061

Manifest Code: NJA5110359
EPA ID: NYD077508091
Date Shipped: 20040929
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD980772768
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040929
Date Trans2 Transported Waste: 000000
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040929
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 10290422
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5013070
EPA ID: NYD077508091

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date Shipped:	20040524
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040524
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040524
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	06070422
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5316300
EPA ID:	NYD077508091
Date Shipped:	20060214
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060214
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

AAR AIRCRAFT COMPONENT SERVICES (Continued) **1000133376**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060214
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04120621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

L71 **AAR TECHNICAL SERVICE CENTER** **AST** **1006303849**
SSE **747 ZECKENDORF BLVD** **N/A**
1/8-1/4 **EAST GARDEN CITY, NY 11530**
0.131 mi.
693 ft. **Site 9 of 9 in cluster L**

Relative:
Lower

Actual:
84 ft.

NCFM AST:

Tank Type:	OUTDOOR AG HOR ON STILT
Tank Size:	100
Contents:	LPG
Tank Type:	OUTDOOR AG HOR ON STILT
Tank Size:	100
Contents:	LPG
Tank Type:	OUTDOOR AG HOR ON STILT
Tank Size:	100
Contents:	LPG
Tank Type:	OUTDOOR AG HOR ON STILT
Tank Size:	100
Contents:	LPG
Tank Type:	OUTDOOR AG HOR ON STILT
Tank Size:	240
Contents:	LPG
Tank Type:	OUTDOOR AG HOR STEEL
Tank Size:	1500
Contents:	DIESEL

72
NNW
1/8-1/4
0.148 mi.
781 ft.

KATHY LALLY RESIDENCE
339 CURTIS AVENUE
CARLE PLACE, NY

LTANKS **S102236125**
HIST LTANKS **N/A**
NY Spills
NY Hist Spills

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	153017
Spill No:	9211105
Spill Date:	12/25/1992
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/23/1993
Facility Addr2:	Not reported
Cleanup Ceased:	12/23/1993
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	CAMPBELL
Referred To:	Not reported
Reported to Dept:	12/25/1992
CID:	04
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/29/1992
Spill Record Last Update:	10/11/2001
Spiller Name:	Not reported
Spiller Company:	COMMANDER/PIETRO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	129875
DEC Memo:	Not reported
Remarks:	TANK OVERFILLED, AFFECTED PERSON CALLED COMMANDER FOR CLEANUP

Material:

Site ID:	153017
Operable Unit ID:	978062
Operable Unit:	01
Material ID:	404529
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

KATHY LALLY RESIDENCE (Continued) **S102236125**

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	9211105
Spill Date:	12/25/1992
Spill Time:	20:00
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	12/23/93
Cleanup Ceased:	12/23/93
Cleanup Meets Standard:	True
Investigator:	CAMPBELL
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	12/25/92
Reported to Department Time:	23:20
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	COMMANDER/PIETRO
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(516) 922-7000
Facility Extention:	Not reported
Spill Notifier:	Affected Persons
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False

KATHY LALLY RESIDENCE (Continued) **S102236125**

Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 12/29/92
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/11/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 12/23/93: NO FURTHER ACTION REQUIRED.
Spill Cause: TANK OVERFILLED, AFFECTED PERSON CALLED COMMANDER FOR CLEANUP

NY Spills:
Site ID: 153018
Facility Addr2: Not reported
Facility ID: 9510311
Spill Number: 9510311
Facility Type: ER
SWIS: 3000
Investigator: UNASSIGNED
Referred To: Not reported
Spill Date: 11/15/1995
Reported to Dept: 11/16/1995
CID: 04
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/16/1995
Remediation Phase: 0
Date Entered In Computer: 11/16/1995

KATHY LALLY RESIDENCE (Continued) **S102236125**

Spill Record Last Update:	8/5/2003
Spiller Name:	KATHY LALLY
Spiller Company:	KATHY LALLY RESIDENCE
Spiller Address:	339 CURTIS AVENUE
Spiller City,St,Zip:	CARLE PLACE, ZZ
Spiller Company:	001
Contact Name:	KATHY LALLY
Contact Phone:	(516) 997-8529
DEC Region:	1
DER Facility ID:	129875
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE" COMMANDER IS ON SITE AND IS FIXING VENT. SPILL ON CONCRETE BELOW VENT, APPROX 1 GAL, NO RESPONSE
Remarks:	CLOGGED VENT CAUSED SPILL. OIL COMPANY WORKING ON PROBLEM NOW.

Material:

Site ID:	153018
Operable Unit ID:	1024793
Operable Unit:	01
Material ID:	361236
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9510311
Investigator:	NONE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	11/15/1995 12:00
Reported to Dept Date/Time:	11/16/95 15:17
SWIS:	28
Spiller Name:	KATHY LALLY RESIDENCE

KATHY LALLY RESIDENCE (Continued) **S102236125**

Spiller Contact: KATHY LALLY
Spiller Phone: (516) 997-8529
Spiller Contact: KATHY LALLY
Spiller Phone: (516) 997-8529
Spiller Address: 339 CURTIS AVENUE
Spiller City,St,Zip: CARLE PLACE
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 09
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/16/95
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 11/16/95
Date Spill Entered In Computer Data File: Not reported
Update Date: 11/20/95
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: COMMANDER IS ON SITE AND IS FIXING VENT. SPILL ON CONCRETE BELOW VENT, APPROX 1 GAL, NO RESPONSE
Remark: CLOGGED VENT CAUSED SPILL. OIL COMPANY WORKING ON PROBLEM NOW.

73
West
1/8-1/4
0.157 mi.
828 ft.

COTUGNO, VICTOR
10 BYRD AVE
CARLE PLACE, NY 11514

UST **U003845485**
AST **N/A**

Relative:
Higher

Actual:
90 ft.

NCFM UST:

Tank Type:	OUTDOOR UG VER STL
Tank Size:	100
Tank Contents:	LPG
Tank Type:	OUTDOOR UG VER STL
Tank Size:	100
Tank Contents:	LPG

NCFM AST:

Tank Type:	OUTDOOR AG HOR ON STILT
Tank Size:	29
Contents:	LPG
Tank Type:	OUTDOOR AG HOR ON STILT
Tank Size:	29
Contents:	LPG

74
NNW
1/8-1/4
0.177 mi.
937 ft.

MINEOLA FUEL
14 GARDEN COURT
CARLE PLACE, NY

LTANKS **S102669378**
HIST LTANKS **N/A**

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	200478
Spill No:	9109750
Spill Date:	12/12/1991
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Spill Closed Dt:	2/10/1992
Facility Addr2:	Not reported
Cleanup Ceased:	2/10/1992
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	KMYAGER
Referred To:	Not reported
Reported to Dept:	12/12/1991
CID:	04
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/13/1991
Spill Record Last Update:	2/10/1992
Spiller Name:	Not reported
Spiller Company:	MINEOLA FUEL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001

MINEOLA FUEL (Continued) **S102669378**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	166833
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DEROSA" 02/10/92: CLEANUP SATISFACTORY NO FURTHER ACTION.
Remarks:	ON DRIVEWAY ONLY, MINEOLA FUEL IN PROCESS OF CLEANING UP

Material:

Site ID:	200478
Operable Unit ID:	959791
Operable Unit:	01
Material ID:	418339
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	42
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	9109750
Spill Date:	12/12/1991
Spill Time:	14:30
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Class:	Not reported
Spill Closed Dt:	02/10/92
Cleanup Ceased:	02/10/92
Cleanup Meets Standard:	True
Investigator:	DEROSA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported

MINEOLA FUEL (Continued) **S102669378**

Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 12/12/91
Reported to Department Time: 15:00
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: MINEOLA FUEL
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 12/13/91
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 02/10/92
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 42
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 02/10/92: CLEANUP SATISFACTORY NO FURTHER ACTION.
Spill Cause: ON DRIVEWAY ONLY, MINEOLA FUEL IN PROCESS OF CLEANING UP

N75
ESE
1/8-1/4
0.182 mi.
960 ft.

TARGET #1139
999 CORPORATE DR
WESTBURY, NY 11590

Site 1 of 2 in cluster N

RCRA-CESQG 1008404415
MANIFEST NYR000134023

Relative:
Higher

Actual:
98 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	TARGET #1139
Facility address:	999 CORPORATE DR WESTBURY, NY 115906614
EPA ID:	NYR000134023
Mailing address:	NICOLLET MALL - TPN-725 MINNEAPOLIS, NY 55403
Contact:	JENNIFER R RYMANOWSKI
Contact address:	NICOLLET MALL - TPN-725 MINNEAPOLIS, NY 55403
Contact country:	US
Contact telephone:	(612) 761-1417
Contact email:	JENNIFER.RYMANOWSKI@TARGET.COM
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/04/1998
Owner/Op end date:	Not reported

Owner/operator name:	TARGET CORPORATION
Owner/operator address:	NICOLLET MALL - TPN-725 MINNEAPOLIS, MN 55403
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/04/1998
Owner/Op end date:	Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

TARGET #1139 (Continued) **1008404415**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: Unknown
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No
- Off-site waste receiver: Commercial status unknown

Historical Generators:
- Date form received by agency: 01/01/2006
- Facility name: TARGET #1139
- Classification: Not a generator, verified

- Date form received by agency: 08/02/2005
- Facility name: TARGET #1139
- Classification: Conditionally Exempt Small Quantity Generator

- Violation Status: No violations found

NY MANIFEST:
- EPA ID: NYR000134023
- Country: USA
- Mailing Name: TARGET 1139
- Mailing Contact: N/S
- Mailing Address: 999 CORPORATE DR
- Mailing Address 2: Not reported
- Mailing City: WESTBURY
- Mailing State: NY
- Mailing Zip: 11590
- Mailing Zip4: Not reported
- Mailing Country: USA
- Mailing Phone: 516-222-1003

- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NYD082785429
- Trans2 State ID: Not reported
- Generator Ship Date: 2008-02-20
- Trans1 Recv Date: 2008-02-20
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 2008-02-20
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYR000134023
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported

TARGET #1139 (Continued) **1008404415**

TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001028062FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-05-22
Trans1 Recv Date:	2008-05-22
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-05-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	50.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001491529FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

TARGET #1139 (Continued) **1008404415**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2008-02-06
Trans1 Recv Date:	2008-02-06
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2008-02-06
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	08
Manifest Tracking Num:	001858113FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	06
Manifest Status:	000691649JJK
Trans1 State ID:	NYR000134023
Trans2 State ID:	Not reported
Generator Ship Date:	KYD053348108
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	TXR000050930
TSD Site Recv Date:	Not reported
Part A Recv Date:	NJD071629976
Part B Recv Date:	2006-10-05
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	60
Handling Method:	P
Specific Gravity:	1

TARGET #1139 (Continued) **1008404415**

Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	06
Manifest Status:	NYC7716194
Trans1 State ID:	NYR000134023
Trans2 State ID:	Not reported
Generator Ship Date:	KYD053348108
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	TXR000050930
TSD Site Recv Date:	Not reported
Part A Recv Date:	NJD986607380
Part B Recv Date:	2006-04-20
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DM
Container Type:	60
Handling Method:	P
Specific Gravity:	1
Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported

TARGET #1139 (Continued) **1008404415**

Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	06
Manifest Status:	NYC7862286
Trans1 State ID:	NYR000134023
Trans2 State ID:	Not reported
Generator Ship Date:	KYD053348108
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	TXR000050930
TSD Site Recv Date:	Not reported
Part A Recv Date:	NJD071629976
Part B Recv Date:	2006-07-07
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	60
Handling Method:	P
Specific Gravity:	1
Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	06
Manifest Status:	NYC7884090
Trans1 State ID:	NYR000134023
Trans2 State ID:	Not reported
Generator Ship Date:	KYD053348108
Trans1 Recv Date:	Not reported

TARGET #1139 (Continued) **1008404415**

Trans2 Recv Date:	TXR000050930
TSD Site Recv Date:	Not reported
Part A Recv Date:	NJD980769947
Part B Recv Date:	2006-08-23
Generator EPA ID:	N
Trans1 EPA ID:	N
Trans2 EPA ID:	N
TSDF ID:	N
Waste Code:	N
Quantity:	Not reported
Units:	1
Number of Containers:	DF
Container Type:	60
Handling Method:	P
Specific Gravity:	1
Waste Code:	B
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-02-08
Trans1 Recv Date:	2007-02-08
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-02-09
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.

TARGET #1139 (Continued) **1008404415**

Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000279756FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-05-17
Trans1 Recv Date:	2007-05-17
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-05-18
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000279977FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-10

TARGET #1139 (Continued) **1008404415**

Trans1 Recv Date:	2007-01-10
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-01-11
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000281478FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-01-25
Trans1 Recv Date:	2007-01-25
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-01-26
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000281860FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N

TARGET #1139 (Continued) **1008404415**

Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-03-01
Trans1 Recv Date:	2007-03-01
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-03-02
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000281999FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-04-19
Trans1 Recv Date:	2007-04-19
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-04-19
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023

TARGET #1139 (Continued) **1008404415**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000282347FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-05-03
Trans1 Recv Date:	2007-05-03
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-05-07
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	1.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	002478608JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported

TARGET #1139 (Continued) **1008404415**

Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-08-01
Trans1 Recv Date:	2007-08-01
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-08-01
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	15.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	003048933JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2007-09-05
Trans1 Recv Date:	2007-09-05
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-09-05
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	2.0
Units:	G - Gallons (liquids only)* (8.3 pounds)

TARGET #1139 (Continued) **1008404415**

Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	003049755JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000068684
Trans2 State ID:	Not reported
Generator Ship Date:	2007-08-21
Trans1 Recv Date:	2007-08-21
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2007-08-28
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	TXD046844700
Waste Code:	Not reported
Quantity:	5.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1.0
Year:	07
Manifest Tracking Num:	000898204FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported

TARGET #1139 (Continued) **1008404415**

Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-05-21
Trans1 Recv Date:	2009-05-21
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-05-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	4.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	002487159FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	IND058484114
Trans2 State ID:	Not reported
Generator Ship Date:	2009-02-03
Trans1 Recv Date:	2009-02-03
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-02-14
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	OHD980613541
Waste Code:	Not reported
Quantity:	20.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	000125750WAS

TARGET #1139 (Continued) **1008404415**

Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H040

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	2009-05-21
Trans1 Recv Date:	2009-05-21
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	2009-05-22
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	Not reported
Quantity:	7.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	09
Manifest Tracking Num:	002487159FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Click this hyperlink while viewing on your computer to access
51 additional NY_MANIFEST: record(s) in the EDR Site Report.

N76
ESE
1/8-1/4
0.184 mi.
974 ft.

1000 CORPORATE DRIVE
WESTBURY, NY

Site 2 of 2 in cluster N

LTANKS **S106385824**
N/A

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	98698
Spill No:	0400290
Spill Date:	4/9/2004
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Spill Closed Dt:	4/9/2004
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	4/9/2004
CID:	04
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/9/2004
Spill Record Last Update:	6/7/2004
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	1000 CORPORATE DRIVE
Spiller City,St,Zip:	WESTBURY, NY 11590-
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	87780
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE" 4/9 1405 CHECK DATABASE - NO OTHER RECORDS FOR THIS ADDRESS, AND ONLY 1 OTHER SPILL FOR "CORPORATE" ANYWHERE IN NASSAU 4/9 1407 CALLED NCHD; SPOKE TO MIKE SECRETA - DOES NOT APPEAR THEY HAVE ANY TANKS REGISTERED FOR THIS ADDRESS - HAVE NO TESTS SCHEDULED ANYWHERE FOR TODAY 4/9 1415 CALLED NCFM - NO ONE IN 4/9 ~1420 CHECKED INTERNET - FOUND "NASSAU COUNTY FEDERAL CREDIT UNION" LISTED FOR THIS ADDRESS 4/9 1430 CALLED NCFCU (STEVE FRESE, ADMINISTRATIVE SERVICES SUPER. 516-561-0030) - HAS NO "OIL" - HAS GAS HEAT/HOT WATER - THEY ARE THE ONLY BUSINESS HERE - DOES HAVE A SMALL DIESEL FOR GENERATOR - HE IS NOT AWARE OF ANY SPILLS, TESTS, ETC BUT HE WILL DOUBLE CHECK - "CORPORATE DRIVE MERGES WITH ZECKENDORF" (I.E., COULD CALLER HAVE CONFUSED ADDRESS?) 4/9 ~1440 CHECK MAP - THIS AREA MAY GO UNDER MULTIPLE NAMES SUCH AS WESTBURY, GARDEN CITY, ETC - FOUND 1 PRIOR SPILL FOR "1000 ZECKENDORF GARDEN CITY": 9313927 - LEAKING LINE - CLOSED IN '94
Remarks:	tank test failed

(Continued) **S106385824**

Material:
- Site ID: 98698
- Operable Unit ID: 882500
- Operable Unit: 01
- Material ID: 495075
- Material Code: 0066A
- Material Name: UNKNOWN PETROLEUM
- Case No.: Not reported
- Material FA: Petroleum
- Quantity: 0
- Units: Gallons
- Recovered: No
- Resource Affected: Not reported
- Oxygenate: False

Tank Test:
- Site ID: Not reported
- Spill Tank Test: Not reported
- Tank Number: Not reported
- Tank Size: Not reported
- Test Method: Not reported
- Leak Rate: Not reported
- Gross Fail: Not reported
- Modified By: Not reported
- Last Modified: Not reported
- Test Method: Not reported

O77 **FORTUNOFF** **AST** **A100212175**
ENE **1300 OLD COUNTRY RD** **N/A**
1/8-1/4 **WESTBURY, NY 11590**
0.189 mi.
996 ft. **Site 1 of 2 in cluster O**

Relative:
Higher

Actual:
105 ft.

NCFM AST:
- Tank Type: OUTDOOR AG HOR ON STILT
- Tank Size: 4000
- Contents: DIESEL

O78 **FORTUNOFF'S** **AST** **A100237398**
ENE **1300 OLD COUNTRY RD** **N/A**
1/8-1/4 **WESTBURY, NY 11590**
0.189 mi.
996 ft. **Site 2 of 2 in cluster O**

Relative:
Higher

Actual:
105 ft.

NCFM AST:
- Tank Type: OUTDOOR AG HOR ON STILT
- Tank Size: 4000
- Contents: DIESEL

P79 **H & R PARTS** **RCRA-CESQG** **1000138641**
SW **800 AXINN AVE** **FINDS** **NYD060318060**
1/8-1/4 **GARDEN CITY, NY 11530** **MANIFEST**
0.203 mi.
1073 ft. **Site 1 of 2 in cluster P**

Relative:
Higher

Actual:
90 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	H & R PARTS
Facility address:	800 AXINN AVE GARDEN CITY, NY 115302139
EPA ID:	NYD060318060
Mailing address:	AXINN AVE GARDEN CITY, NY 11530
Contact:	Not reported
Contact address:	AXINN AVE GARDEN CITY, NY 11530
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MIDWOOD MGMT
Owner/operator address:	60 E 42ND ST SUITE 1814 NEW YORK, NY 10165
Owner/operator country:	US
Owner/operator telephone:	(212) 682-9595
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MIDWOOD MGMT
Owner/operator address:	60 E 42ND ST SUITE 1814 NEW YORK, NY 10165
Owner/operator country:	US
Owner/operator telephone:	(212) 682-9595
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

H & R PARTS (Continued) **1000138641**

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: H & R PARTS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/08/1999
Facility name: H & R PARTS
Classification: Not a generator, verified

Date form received by agency: 04/02/1997
Facility name: H & R PARTS
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004362001

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD060318060
Country: USA
Mailing Name: FIL-COIL
Mailing Contact: FIL-COIL
Mailing Address: 800 AXINN AVENUE
Mailing Address 2: Not reported
Mailing City: GARDEN CITY
Mailing State: NY
Mailing Zip: 11530

H & R PARTS (Continued) **1000138641**

Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	516-228-9445

Document ID:	NYB6651675
Manifest Status:	Completed copy
Trans1 State ID:	13734F
Trans2 State ID:	Not reported
Generator Ship Date:	950404
Trans1 Recv Date:	950404
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950404
Part A Recv Date:	950417
Part B Recv Date:	950419
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00189
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	139
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2857113
Manifest Status:	Completed copy
Trans1 State ID:	ET4521
Trans2 State ID:	Not reported
Generator Ship Date:	911212
Trans1 Recv Date:	911212
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	911216
Part A Recv Date:	920107
Part B Recv Date:	920106
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00160

H & R PARTS (Continued) **1000138641**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	121
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA0715306
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	900409
Trans1 Recv Date:	900409
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900410
Part A Recv Date:	900514
Part B Recv Date:	900418
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00500
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	01000
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	90
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported

H & R PARTS (Continued) **1000138641**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA2707520
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	970404
Trans1 Recv Date:	970404
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970404
Part A Recv Date:	970422
Part B Recv Date:	970418
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00107
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	97
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYG1418571
Manifest Status:	Not reported
Trans1 State ID:	NYD077444263
Trans2 State ID:	Not reported
Generator Ship Date:	09/01/1998
Trans1 Recv Date:	09/01/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/02/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	PD1011NY
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES

H & R PARTS (Continued) **1000138641**

Quantity:	00085
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	98
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB5008536
Manifest Status:	Completed copy
Trans1 State ID:	ET4521
Trans2 State ID:	Not reported
Generator Ship Date:	920918
Trans1 Recv Date:	920918
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920921
Part A Recv Date:	Not reported
Part B Recv Date:	921005
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	121
Year:	92
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported

H & R PARTS (Continued) **1000138641**

Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA0562203
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	000000000
Trans2 State ID:	000000000
Generator Ship Date:	890823
Trans1 Recv Date:	890823
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890824
Part A Recv Date:	890927
Part B Recv Date:	890831
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	F001 - UNKNOWN
Quantity:	00500
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	02500
Units:	P - Pounds
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	01500
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	89
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

H & R PARTS (Continued) **1000138641**

Document ID:	NJA2707534
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	970610
Trans1 Recv Date:	970610
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	970613
Part A Recv Date:	970617
Part B Recv Date:	970710
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00367
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	97
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYG3940947
Manifest Status:	Not reported
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/2003
Trans1 Recv Date:	10/30/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD060318060
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID:	MAH60937
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00350
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

H & R PARTS (Continued) **1000138641**

Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Quantity:	00040
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	03
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

P80 **PROGRESSIVE CASUALTY INS. CO.** **AST** **A100198391**
SW **1 AXINN AVE** **N/A**
1/8-1/4 **GARDEN CITY, NY 11530**
0.204 mi.
1077 ft. **Site 2 of 2 in cluster P**

Relative:
Higher

Actual:
90 ft.

NCFM AST:

Tank Type:	OUTDOOR AG HOR STEEL
Tank Size:	1000
Contents:	DIESEL

---

81 **SMALL RESIDENCE** **LTANKS** **S105999318**
WNW **248 CURTIS AVENUE** **N/A**
1/8-1/4 **CARLE PLACE, NY**
0.214 mi.
1128 ft.

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	214530
Spill No:	0303412
Spill Date:	7/1/2003
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	11/7/2003
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	WJGABIN
Referred To:	Not reported
Reported to Dept:	7/1/2003
CID:	04
Water Affected:	Not reported

SMALL RESIDENCE (Continued) **S105999318**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/1/2003
Spill Record Last Update:	11/10/2003
Spiller Name:	ROBERT SMALL
Spiller Company:	SMALL RESIDENCE
Spiller Address:	248 CURTIS AVENUE
Spiller City,St,Zip:	CARLE PLACE, ZZ
Spiller County:	001
Spiller Contact:	ROBERT SMALL
Spiller Phone:	(516) 333-7278
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	177743
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GABIN" LEFT MESSAGE FOR SPOSIT0-PER SPOSITO, MAGNAPATCH PLACED ON TANK, MILRO ENROUTE FOR TANK CHANGEOUT TELECON ROBER SMALL-ESTIMATES 5-10 GALS SPILLED FROM HOLE IN AN A/G OUTDOOR TANK. SOIL AFFECTED.SLOMINS IS RESPONDING THIS AFTERNOON TO PROVIDE HIM WITH A NEW TANK AND TO EXCAVATE THE OLD. HE HAS CONTACTED HIS INSURANCE COMPANY ALLSTATE CLEANUP WAS COMPLETED BY MILRO, A TOTAL OF 8 CUBIC YARDS OF CONTAMINATED SOIL WAS REMOVED AND PROPERLY DISPOSED OF AT PIONEER CROSSING LANDFILL. AN ENDPOINT SAMPLE ANALYTICAL INDICATED MINIMAL POTENTIAL FOR GW CONTAMINATION. NO FURTHER ACTION
Remarks:	Failure of above ground tank at above location. Tank to be replaced and homeowner contacting insurance company in reference to cleanup.

Material:

Site ID:	214530
Operable Unit ID:	870519
Operable Unit:	01
Material ID:	504280
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

82
NNW
1/8-1/4
0.245 mi.
1294 ft.

CARLE PLACE UFSD
CHERRY LA.
CARLE PLACE, NY

UST **U003377122**
N/A

Relative:
Higher

Actual:
96 ft.

NASSAU CO. UST:

Facility ID:	052279
Owner Name:	CARLE PLACE UFSD
Owner Address:	CHERRY LA.
Owner City,St,Zip:	CARLE PLACE, NY 11514
Permitee Name:	SAME
Permitee Address:	Not reported
Permitee City,St,Zip:	Not reported

Tank ID:	0003
Tank Location:	Indoors, Belowground
Capacity (Gal):	00010000
Tank Status:	In Service
Tank Material:	Fiberglass Reinforced Plastic
Int Protection:	Internal Lining
Ext Protection:	FIBERGLASS REINFORCED PLASTIC
Piping Type:	Double Walled Fiberglass
Material Type:	Fresh/Product
Description:	OIL, FUEL #2
Leak Detect:	IN-TANK SYSTEM
Containment:	DOUBLE WALL TANK
Product Gauge:	Yes
Dispense Method:	Suction
Fill Type:	Pumped
Install Date:	091990

Tank ID:	0004
Tank Location:	Indoors, Belowground
Capacity (Gal):	00010000
Tank Status:	In Service
Tank Material:	Fiberglass Reinforced Plastic
Int Protection:	Internal Lining
Ext Protection:	FIBERGLASS REINFORCED PLASTIC
Piping Type:	Double Walled Fiberglass
Material Type:	Fresh/Product
Description:	OIL, FUEL #2
Leak Detect:	IN-TANK SYSTEM
Containment:	DOUBLE WALL TANK
Product Gauge:	Yes
Dispense Method:	Suction
Fill Type:	Pumped
Install Date:	081990

Q83
WSW
1/4-1/2
0.358 mi.
1890 ft.

MOBIL S/S
640 OLD COUNTRY ROAD
GARDEN CITY, NY

Site 1 of 2 in cluster Q

LTANKS **S104075320**
HIST LTANKS **N/A**
NY Spills
NY Hist Spills

Relative:
Higher

Actual:
94 ft.

LTANKS:

Site ID:	100137
Spill No:	9001174
Spill Date:	5/1/1990
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	5/3/1990
Facility Addr2:	Not reported
Cleanup Ceased:	5/3/1990
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	JEHAAS
Referred To:	Not reported
Reported to Dept:	5/1/1990
CID:	04
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	5/3/1990
Spill Record Last Update:	5/4/1990
Spiller Name:	Not reported
Spiller Company:	MOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller City,St,Zip:	FAIRFAX, VA 22037
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	88949
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HAAS" 05/03/90: DEC WITNESSED THE TANK REMOVAL ALONG WITH LUCE.HAAS HAD APPROX 60 CU YDS OF CONT SOIL STOCKPILED.ALL THE CONT WAS REMOVED AND NO FURTHER ACTION IS REQUIRED.
Remarks:	STOCKPILED AND DISPOSED OF CONT SOIL. TANK REMOVAL

Material:

Site ID:	100137
Operable Unit ID:	939544
Operable Unit:	01
Material ID:	439534
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported

MOBIL S/S (Continued) **S104075320**

Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:
Region of Spill: 1
Spill Number: 9001174
Spill Date: 05/01/1990
Spill Time: 11:20
Spill Cause: Tank Overfill
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 05/03/90
Cleanup Ceased: 05/03/90
Cleanup Meets Standard: True
Investigator: HAAS
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 05/01/90
Reported to Department Time: 11:24
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: MOBIL
Spiller Address: 3225 GALLOWS ROAD
Spiller City,St,Zip: FAIRFAX, VA 22037
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (703) 846-5405
Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /

MOBIL S/S (Continued) **S104075320**

UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 05/03/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 05/04/90
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 05/03/90: DEC WITNESSED THE TANK REMOVAL ALONG WITH LUCE.HAAS HAD APPROX 60 CU YDS OF CONT SOIL STOCKPILED.ALL THE CONT WAS REMOVED AND NO FURTHER ACTION IS REQUIRED.
Spill Cause: STOCKPILED AND DISPOSED OF CONT SOIL. TANK REMOVAL

NY Spills:
Site ID: 100140
Facility Addr2: Not reported
Facility ID: 9307092
Spill Number: 9307092
Facility Type: ER
SWIS: 3020
Investigator: GIBBONS
Referred To: Not reported
Spill Date: 9/10/1993
Reported to Dept: 9/10/1993
CID: 04
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Responsible Party
Cleanup Ceased: 9/26/1994
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: True
Spill Class: No spill occured. (Not Possible)
Spill Closed Dt: 9/26/1994
Remediation Phase: 0

MOBIL S/S (Continued) **S104075320**

Date Entered In Computer: 9/13/1993
Spill Record Last Update: 6/4/2007
Spiller Name: Not reported
Spiller Company: MOBIL
Spiller Address: Not reported
Spiller City,St,Zip: NY
Spiller Company: 999
Contact Name: Not reported
Contact Phone: Not reported
DEC Region: 1
DER Facility ID: 319742
DEC Memo: Not reported
Remarks: GAS DELIV LAST NIGHT, MGR SAYS ELECTRIC POWER SURGES OCCURRED

Material:
Site ID: 100140
Operable Unit ID: 985543
Operable Unit: 01
Material ID: 393366
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

Site ID: 100138
Facility Addr2: Not reported
Facility ID: 9001719
Spill Number: 9001719
Facility Type: ER
SWIS: 3000
Investigator: JEHAAS
Referred To: Not reported
Spill Date: 5/14/1990
Reported to Dept: 5/14/1990
CID: 04
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Source: Gasoline Station
Spill Notifier: Health Department

MOBIL S/S (Continued) **S104075320**

Cleanup Ceased:	4/15/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/15/1992
Remediation Phase:	0
Date Entered In Computer:	5/15/1990
Spill Record Last Update:	7/21/1997
Spiller Name:	Not reported
Spiller Company:	MOBIL S/S
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	88949
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HAAS WELL"
Remarks:	W/O TANK, CONTAMINATION FOUND. 20 YDS OF SOIL REMOVED. NEED WELLS. EXCAVATION CLOSE TO FOUNDATION

Material:

Site ID:	100138
Operable Unit ID:	941580
Operable Unit:	01
Material ID:	564960
Material Code:	0022
Material Name:	Waste Oil/Used Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

MOBIL S/S (Continued) **S104075320**

NY Hist Spills:

Region of Spill:	1
Spill Number:	9307092
Investigator:	GIBBONS
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	09/10/1993 11:02
Reported to Dept Date/Time:	09/10/93 14:29
SWIS:	28
Spiller Name:	MOBIL
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spill Cause:	Equipment Failure
Reported to Dept:	On Land
Water Affected:	Not reported
Spill Source:	05
Spill Notifier:	Responsible Party
PBS Number:	Not reported
Cleanup Ceased:	09/26/94
Cleanup Meets Std:	True
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Spiller Cleanup Dt:	/ /
Enforcement Date:	/ /
Invstgn Complete:	/ /
UST Involvement:	True
Spill Class:	No spill occured. (Not Possible)
Spill Closed Dt:	09/26/94
Corrective Action Plan Submitted:	/ /
Date Region Sent Summary to Central Office:	/ /
Date Spill Entered In Computer Data File:	09/13/93
Date Spill Entered In Computer Data File:	Not reported
Update Date:	09/27/94
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	0
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	GASOLINE
Class Type:	GASOLINE

MOBIL S/S (Continued) **S104075320**

Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: 09/26/94: UNDERROOT TANK MONITORING SYS DAMAGED IN ELECTRICAL STORM, SYS REPAIRED BY F N REPLACING SIX MODULES, NO CONTAMINATION FOUND, NO FURTHER ACTION.
Remark: GAS DELIV LAST NIGHT, MGR SAYS ELECTRIC POWER SURGES OCCURRED

Region of Spill: 1
Spill Number: 9001719
Investigator: HAAS WELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/14/1990 14:30
Reported to Dept Date/Time: 05/14/90 15:55
SWIS: 28
Spiller Name: MOBIL S/S
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: Groundwater
Water Affected: Not reported
Spill Source: 05
Spill Notifier: Health Department
PBS Number: Not reported
Cleanup Ceased: 04/15/92
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 04/15/92
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/15/90
Date Spill Entered In Computer Data File: Not reported
Update Date: 07/21/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:

MOBIL S/S (Continued) **S104075320**

Material Class Type:	Petroleum
Quantity Spilled:	0
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	WASTE OIL
Class Type:	WASTE OIL
Times Material Entry In File:	9509
CAS Number:	Not reported
Last Date:	19940927
DEC Remarks:	Not reported
Remark:	W/O TANK, CONTAMINATION FOUND. 20 YDS OF SOIL REMOVED. NEED WELLS. EXCAVATION CLOSE TO FOUNDATION

R84 **OUR LADY OF HOPE** **LTANKS S100149244**
NNW **CHERRY LANE / BROADWAY** **HIST LTANKS N/A**
1/4-1/2 **CARLE PLACE, NY**
0.363 mi.
1917 ft. **Site 1 of 2 in cluster R**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	302231
Spill No:	9005920
Spill Date:	8/16/1990
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Spill Closed Dt:	8/29/1990
Facility Addr2:	Not reported
Cleanup Ceased:	8/29/1990
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	NCHD
Referred To:	NASSAU CNTY HEALTH DEPT
Reported to Dept:	8/28/1990
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/31/1990
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	CHERRY LANE SCHOOL
Spiller Address:	CHERRY LANE
Spiller City,St,Zip:	CARLE PLACE, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	244187
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NCDH"
Remarks:	15 CU YDS REMOVED, CLEAN UP COMPLETE. TANK REMOVAL. 10K

OUR LADY OF HOPE (Continued) **S100149244**

Material:

Site ID:	302231
Operable Unit ID:	946411
Operable Unit:	01
Material ID:	433399
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	310894
Spill No:	8707626
Spill Date:	12/5/1987
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Spill Closed Dt:	9/15/1989
Facility Addr2:	Not reported
Cleanup Ceased:	9/15/1989
Cleanup Meets Standard:	True
SWIS:	3022
Investigator:	KDGOERTZ
Referred To:	Not reported
Reported to Dept:	12/5/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	12/7/1987
Spill Record Last Update:	8/21/2006
Spiller Name:	Not reported
Spiller Company:	OUR LADY OF HOPE
Spiller Address:	CHERRY LANE & BROADWAY
Spiller City,St,Zip:	CARLE PLACE, NY
Spiller County:	001

OUR LADY OF HOPE (Continued) **S100149244**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	250944
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GOERTZ FD" / / : A.VOLINO & SONS TESTER. WILL REPAIR AND RETEST. 09/15/89: TANK WAS REMOVED BY VOLINO ON 5/4/88 IN THE PRESENCE OF NCDH. NO CONTAMINATION WAS FOUND. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES
Remarks:	3K FAILED AT -.242 GPH

Material:

Site ID:	310894
Operable Unit ID:	913293
Operable Unit:	01
Material ID:	466564
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	310894
Spill Tank Test:	1532546
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

HIST LTANKS:

Region of Spill:	1
Spill Number:	9005920
Spill Date:	08/16/1990
Spill Time:	12:00
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	08/29/90
Cleanup Ceased:	08/29/90
Cleanup Meets Standard:	True
Investigator:	NCDH
Caller Name:	Not reported

OUR LADY OF HOPE (Continued) **S100149244**

Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 08/28/90
Reported to Department Time: 16:18
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: CHERRY LANE SCHOOL
Spiller Address: CHERRY LANE
Spiller City,St,Zip: CARLE PLACE, NY
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Health Department
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 08/31/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: 15 CU YDS REMOVED, CLEAN UP COMPLETE. TANK REMOVAL. 10K

OUR LADY OF HOPE (Continued) **S100149244**

Region of Spill:	1
Spill Number:	8707626
Spill Date:	12/05/1987
Spill Time:	16:30
Spill Cause:	Tank Test Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Other Non Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	09/15/89
Cleanup Ceased:	09/15/89
Cleanup Meets Standard:	True
Investigator:	GOERTZ FD
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	12/05/87
Reported to Department Time:	17:55
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	OUR LADY OF HOPE
Spiller Address:	CHERRY LANE & BROADWAY
Spiller City,St,Zip:	CARLE PLACE, NY
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(516) 334-6288
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	12/07/87
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	03/08/99
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

Material:

OUR LADY OF HOPE (Continued) **S100149244**

Material Class Type:	Petroleum
Quantity Spilled:	0
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	#2 FUEL OIL
Class Type:	#2 FUEL OIL
Times Material Entry In File:	24464
CAS Number:	Not reported
Last Date:	19941207
DEC Remarks:	/ / : A.VOLINO SONS TESTER. WILL REPAIR AND RETEST. 09/15/89: TANK WAS REMOVED BY VOLINO ON 5/4/88 IN THE PRESENCE OF NCDH. NO CONTAMINATION WAS FOUND.
Spill Cause:	3K FAILED AT -.242 GPH

---

85 NNE 1/4-1/2 0.369 mi. 1947 ft. **MITCHEL FIELD** **FUDS** **1007211602 N/A**

HEMPSTEAD, NY

Relative: Higher

Actual: 103 ft.

FUDS:

Federal Facility ID:	NY9799F1178
FUDS #:	C02NY0645
INST ID:	54319
Facility Name:	MITCHEL FIELD
City:	Hempstead
State:	NY
EPA Region:	2
County:	NASSAU
Congressional District:	04
US Army District:	New England District (NAE)
Fiscal Year:	2008
Telephone:	978-318-8238
NPL Status:	Not Listed
RAB:	Not reported
CTC:	17371.0988110133
Current Owner:	COUNTY; PRIVATE

FUDS Description Details:

The former Mitchel Field consisted of about 1,437 acres in Hempstead, New York. Mitchel Field has a history of troop encampments since the Revolutionary War. In 1918, it became an active flying field. During World War II, it was used for training and
d for sending tactical units overseas. Abandoned tanks are present at the site, and hazardous and toxic wastes and ordnance could be present. The site is currently occupied by Hofstra University, Nassau Community College, the Nassau Coliseum, and the
e Mitchel Sports Complex. This property is known or suspected to contain military munitions and explosives of concern (e.g., unexploded ordnance) and therefore may present an explosive hazard.

FUDS History Details:

Acquisition of the site occurred from 1917 until 1959. The installation consisted of 1,168.0 acres in fee, 181.67 acres in easement, and 7.08 acres and 79.07 acres that were licensed and leased, respectively. Mitchel Field was deactivated in April 19
961; 1,076.77 acres fee were reported excess to the General Services

MITCHEL FIELD (Continued) **1007211602**

Administration, and the remaining 92.13 acres fee were transferred to other DoD agencies. The principal owners of the site are now Hofstra University and Nassau Community College. T
This property is known or suspected to contain military munitions and explosives of concern (e.g., unexploded ordnance) and therefore may present an explosive hazard.

FUDS Current Program Details:
None

FUDS Future Program Details:
None planned

---

86 SOUZA RESIDENCE **LTANKS S102669415**
ENE 8 ROCKAWAY AVENUE **HIST LTANKS N/A**
1/4-1/2 WESTBURY, NY
0.373 mi.
1972 ft.

Relative: Higher

Actual: 106 ft.

LTANKS:

Site ID:	225689
Spill No:	9111752
Spill Date:	2/14/1992
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Spill Closed Dt:	2/18/1992
Facility Addr2:	Not reported
Cleanup Ceased:	2/18/1992
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2/14/1992
CID:	04
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2/19/1992
Spill Record Last Update:	10/17/2001
Spiller Name:	Not reported
Spiller Company:	COMMANDER OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	186287
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE"
Remarks:	CONTAINED ON CONCRETE FLOOR, COMMANDER PERSONNEL TO DO CLEANUP, SPILL CAME OUT VENT DURING DELIVERY, NO RESPONSE NEEDED

SOUZA RESIDENCE (Continued) **S102669415**

Material:

Site ID:	225689
Operable Unit ID:	965467
Operable Unit:	01
Material ID:	416770
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	9111752
Spill Date:	02/14/1992
Spill Time:	13:05
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Class:	Not reported
Spill Closed Dt:	02/18/92
Cleanup Ceased:	02/18/92
Cleanup Meets Standard:	True
Investigator:	NONE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	02/14/92
Reported to Department Time:	13:39
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

SOUZA RESIDENCE (Continued) **S102669415**

Spiller Name: COMMANDER OIL
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Other
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 02/19/92
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/17/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: CONTAINED ON CONCRETE FLOOR, COMMANDER PERSONNEL TO DO CLEANUP, SPILL CAME OUT VENT DURING DELIVERY, NO RESPONSE NEEDED

Q87 **EAB BANK** **LTANKS** **S100560042**
WSW **600 OLD COUNTRY ROAD** **HIST LTANKS** **N/A**
1/4-1/2 **GARDEN CITY, NY**
0.378 mi.
1997 ft. **Site 2 of 2 in cluster Q**

Relative:
Higher

Actual:
95 ft.

LTANKS:
Site ID: 167945
Spill No: 9305015
Spill Date: 7/21/1993
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: No spill occured. No DEC Response. No corrective action required.

EAB BANK (Continued) **S100560042**

Spill Closed Dt:	7/23/1993
Facility Addr2:	Not reported
Cleanup Ceased:	7/23/1993
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	T/T/F
Referred To:	Not reported
Reported to Dept:	7/21/1993
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/23/1993
Spill Record Last Update:	7/26/1993
Spiller Name:	Not reported
Spiller Company:	EAB BANK
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	141496
DEC Memo:	Not reported
Remarks:	15K FAILED -.056, AMER ENVIR TESTER

Material:

Site ID:	167945
Operable Unit ID:	986640
Operable Unit:	01
Material ID:	394966
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	167945
Spill Tank Test:	1541791
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

EAB BANK (Continued) **S100560042**

HIST LTANKS:

Region of Spill:	1
Spill Number:	9305015
Spill Date:	07/21/1993
Spill Time:	17:50
Spill Cause:	Tank Test Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	No spill occured. No DEC Response. No corrective action required.
Spill Closed Dt:	07/23/93
Cleanup Ceased:	07/23/93
Cleanup Meets Standard:	True
Investigator:	T/T/F
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	07/21/93
Reported to Department Time:	20:12
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	EAB BANK
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(516) 273-8700
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	07/23/93
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	07/26/93
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

EAB BANK (Continued) **S100560042**

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 07/23/93: UPDATE, PER KEITH NOT A SPILL FAILURE RATE FOR 12,501-17,500 GAL IS -.063, NO FURTHER ACTION.
Spill Cause: 15K FAILED -.056, AMER ENVIR TESTER

88
NE
1/4-1/2
0.379 mi.
2003 ft.

Relative:
Higher

Actual:
104 ft.

FANNI RESIDENCE **HIST LTANKS** **S105135192**
84 BROADMOOR LANE **NY Spills** **N/A**
WESTBURY, NY

HIST LTANKS:
Region of Spill: 1
Spill Number: 0106823
Spill Date: 10/01/2001
Spill Time: 16:45
Spill Cause: Tank Overfill
Resource Affectd: On Land
Water Affected: Not reported
Spill Source: Tank Truck
Spill Class: Known release with minimal potential for fire or hazard. No DEC Response. No corrective action required.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: UNASSIGNED
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 10/01/01
Reported to Department Time: 16:54
SWIS: 28
Spiller Contact: FANNI RES
Spiller Phone: (516) 876-8649
Spiller Extention: Not reported
Spiller Name: PETRO
Spiller Address: WEST JOHN STREET
Spiller City,St,Zip: WESTBURY, NY -
Spiller Cleanup Date: / /
Facility Contact: CALLER
Facility Phone: ( ) -

FANNI RESIDENCE (Continued) **S105135192**

Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/01/01
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/03/01
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 10/2/01 TELECON TO DENISE-OVERFILL OF BASEMENT TANK, 2GALS ON CONCRETE AND TILE
Spill Cause: spill into basement. speedy dry put down..clean up will be taken care of later.

NY Spills:
Site ID: 187467
Facility Addr2: Not reported
Facility ID: 0106823
Spill Number: 0106823
Facility Type: ER
SWIS: 3022
Investigator: UNASSIGNED
Referred To: Not reported
Spill Date: 10/1/2001
Reported to Dept: 10/1/2001
CID: 04
Spill Cause: Other
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported

FANNI RESIDENCE (Continued) **S105135192**

Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	3/5/2003
Remediation Phase:	0
Date Entered In Computer:	10/1/2001
Spill Record Last Update:	5/28/2009
Spiller Name:	CALLER
Spiller Company:	PETRO
Spiller Address:	WEST JOHN STREET
Spiller City,St,Zip:	WESTBURY, NY -
Spiller Company:	001
Contact Name:	FANNI RES
Contact Phone:	(516) 876-8649
DEC Region:	1
DER Facility ID:	156629
DEC Memo:	10/2 1040 SPOKE TO DENISE, OVERFILL OF BASEMENT TANK, ~ 2 GALS ON CONCRETE AND TILE
Remarks:	spill into basement. speedy dry put down..clean up will be taken care of later.

Material:

Site ID:	187467
Operable Unit ID:	845031
Operable Unit:	01
Material ID:	531673
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

89
WSW
1/4-1/2
0.401 mi.
2118 ft.

HUNTS POINT OIL
ROOSEVELT FIELD SHOPPING
GARDEN CITY, NY

LTANKS **S102669156**
HIST LTANKS **N/A**

Relative:
Higher

Actual:
90 ft.

LTANKS:

Site ID:	101468
Spill No:	9013096
Spill Date:	1/5/1991
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	3/26/1991
Facility Addr2:	Not reported
Cleanup Ceased:	3/26/1991
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	3/25/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	3/26/1991
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	HUNTS POINT OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	89911
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE"
Remarks:	INSIDE BLDG HAS BEEN CLEANED UP WITH SPEEDI DRY AS OF 1/20/91. NO RESPONSE NECESSARY

Material:

Site ID:	101468
Operable Unit ID:	953008
Operable Unit:	01
Material ID:	425992
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

HUNTS POINT OIL (Continued) **S102669156**

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	9013096
Spill Date:	01/05/1991
Spill Time:	12:00
Spill Cause:	Tank Overfill
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Not reported
Spill Closed Dt:	03/26/91
Cleanup Ceased:	03/26/91
Cleanup Meets Standard:	True
Investigator:	NONE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	03/25/91
Reported to Department Time:	09:45
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	HUNTS POINT OIL
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(212) 893-3100
Facility Extention:	Not reported
Spill Notifier:	Local Agency
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False

Date Region Sent Summary to Central Office: / /

HUNTS POINT OIL (Continued) **S102669156**

Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 03/26/91
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 5
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: Not reported
Spill Cause: INSIDE BLDG HAS BEEN CLEANED UP WITH SPEEDI DRY AS OF 1/20/91. NO RESPONSE NECESSARY

---

90 NNW 1/4-1/2 0.404 mi. 2133 ft.

BELCHER FUEL OIL CO **LTANKS S102668517**
RUSHMORE AVE / WESTBURY A **HIST LTANKS N/A**
CARLE PLACE, NY

Relative: Higher

Actual: 98 ft.

LTANKS:
Site ID: 278395
Spill No: 8809569
Spill Date: 3/13/1989
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Spill Closed Dt: 7/29/1991
Facility Addr2: Not reported
Cleanup Ceased: 7/29/1991
Cleanup Meets Standard: True
SWIS: 3000
Investigator: NJACAMPO
Referred To: Not reported
Reported to Dept: 3/13/1989
CID: Not reported
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0

BELCHER FUEL OIL CO (Continued) **S102668517**

Date Entered In Computer: 3/15/1989
Spill Record Last Update: 7/30/1991
Spiller Name: Not reported
Spiller Company: BELCHER FUEL OIL CO
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 226049
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "ACAMPORA"
Remarks: NCFM ON SCENE,REQUESTING DEC TO RESPOND.AIR POCKET IN LINE CAUSED OVERFLOW. HAZMAT UNIT ON SITE.BELCHER HIRED CONTRACTOR FOR CLEANUP

Material:
Site ID: 278395
Operable Unit ID: 925823
Operable Unit: 01
Material ID: 454292
Material Code: 0002
Material Name: #4 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 400
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:
Region of Spill: 1
Spill Number: 8809569
Spill Date: 03/13/1989
Spill Time: 12:30
Spill Cause: Tank Overfill
Resource Affectd: In Sewer
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Class: Not reported
Spill Closed Dt: 07/29/91

BELCHER FUEL OIL CO (Continued) **S102668517**

Cleanup Ceased:	07/29/91
Cleanup Meets Standard:	True
Investigator:	ACAMPORA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	03/13/89
Reported to Department Time:	13:00
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	BELCHER FUEL OIL CO
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	(718) 886-4500
Facility Extention:	Not reported
Spill Notifier:	Fire Department
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	03/15/89
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	07/30/91
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported
Gross Leak Rate:	Not reported

Material:

Material Class Type:	Petroleum
Quantity Spilled:	400
Unkonwn Quantity Spilled:	False
Units:	Gallons
Quantity Recovered:	0
Unkonwn Quantity Recovered:	False
Material:	#4 FUEL OIL
Class Type:	#4 FUEL OIL
Times Material Entry In File:	1751
CAS Number:	Not reported

BELCHER FUEL OIL CO (Continued) **S102668517**

Last Date: 19941205
DEC Remarks: Not reported
Spill Cause: NCFM ON SCENE,REQUESTING DEC TO RESPOND.AIR POCKET IN LINE CAUSED OVERFLOW. HAZMAT UNIT ON SITE.BELCHER HIRED CONTRACTOR FOR CLEANUP

91
NNW
1/4-1/2
0.405 mi.
2140 ft.

LILCO **LTANKS** **S102096677**
351 WESTBURY AVENUE **NY Spills** **N/A**
CARLE PLACE, NY **NY Hist Spills**

Relative:
Higher

Actual:
98 ft.

LTANKS:

Site ID:	333513
Spill No:	0408620
Spill Date:	11/4/2004
Spill Cause:	Tank Test Failure
Spill Source:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	4/19/2007
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3022
Investigator:	HMCIRRIT
Referred To:	Not reported
Reported to Dept:	11/4/2004
CID:	04
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/8/2004
Spill Record Last Update:	4/20/2007
Spiller Name:	ROY
Spiller Company:	ROBERT BALEMIAN
Spiller Address:	357 WEST NECK ROAD
Spiller City,St,Zip:	LLOYD HARBOR, NY 11743
Spiller County:	001
Spiller Contact:	KEVIN TAYLOR
Spiller Phone:	(631) 673-0612
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	268745
DEC Memo:	550 GAL F/O HORNER EZY LOCATOR 3. 11:40 - T/C KEVIN TAYLOR - ASSUMED 550 GAL #2 FO. PHASE II BEING DONE. TESTED TANK. LEAK - REMOTE FILL & VENT. - PARAGON IS RENTING PROPERTY - BLDG IS UNOCCUPIED. (TAYLOR TO GET OWNER INFO)
Remarks:	THE LEAK IS WITHIN THE REMOTE FILL AND VENT PIPING.

Material:

Site ID:	333513
Operable Unit ID:	1095667
Operable Unit:	01
Material ID:	575795

LILCO (Continued) **S102096677**

Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	333513
Spill Tank Test:	1548316
Tank Number:	Not reported
Tank Size:	550
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified:	11/8/2004
Test Method:	Unknown

NY Spills:

Site ID:	205331
Facility Addr2:	Not reported
Facility ID:	9001564
Spill Number:	9001564
Facility Type:	ER
SWIS:	3000
Investigator:	UNASSIGNED
Referred To:	Not reported
Spill Date:	5/9/1990
Reported to Dept:	5/9/1990
CID:	04
Spill Cause:	Equipment Failure
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	5/10/1990
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Not reported
Spill Closed Dt:	5/10/1990
Remediation Phase:	0
Date Entered In Computer:	5/11/1990
Spill Record Last Update:	9/30/2004
Spiller Name:	Not reported
Spiller Company:	LILCO
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported

LILCO (Continued) **S102096677**

DEC Region: 1
DER Facility ID: 170494
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE"
Remarks: NCPD ON SCENE.F.D APPLIED SPEEDY DRY.WILL CALL DEC ON LAB RESULTS.NEAR BASE OF POLE.

Material:
Site ID: 205331
Operable Unit ID: 941303
Operable Unit: 01
Material ID: 564959
Material Code: 0017A
Material Name: PCB OIL
Case No.: Not reported
Material FA: Petroleum
Quantity: 1
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 1
Spill Number: 9001564
Investigator: NONE
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 05/09/1990 15:20
Reported to Dept Date/Time: 05/09/90 16:55
SWIS: 28
Spiller Name: LILCO
Spiller Contact: Not reported
Spiller Phone: (516) 521-3751
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Equipment Failure
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 01

LILCO (Continued) **S102096677**

Spill Notifier: Fire Department
PBS Number: Not reported
Cleanup Ceased: 05/10/90
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Not reported
Spill Closed Dt: 05/10/90
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 05/11/90
Date Spill Entered In Computer Data File: Not reported
Update Date: / /
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 1
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: PCB OIL
Class Type: PCB OIL
Times Material Entry In File: 1229
CAS Number: Not reported
Last Date: 19940728
DEC Remarks: Not reported
Remark: NCPD ON SCENE.F.D APPLIED SPEEDY DRY.WILL CALL DEC ON LAB RESULTS.NEAR BASE OF POLE.

R92 **HESS STATION 32492** **RCRA-CESQG 1000375949**
NNW **500 WESTBURY AVE** **FINDS NYD982727570**
1/4-1/2 **CARLE PLACE, NY 11514** **LTANKS**
0.411 mi. **HIST LTANKS**
2170 ft. **Site 2 of 2 in cluster R** **MANIFEST**
MANIFEST

Relative:
Higher

Actual:
99 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: HESS STATION 32492
Facility address: 500 WESTBURY AVE
CARLE PLACE, NY 11514
EPA ID: NYD982727570
Mailing address: HESS PLZ
WOODBRIDGE, NY 07095
Contact: Not reported

HESS STATION 32492 (Continued) **1000375949**

Contact address: HESS PLZ
WOODBRIDGE, NY 07095
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: AMERADA HESS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AMERADA HESS CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler accessibilty indicator: Transferred to the program or state equivalent.

Handler Activities Summary:
U.S. importer of hazardous waste: Unknown
Mixed waste (haz. and radioactive): Unknown
Recycler of hazardous waste: No
Transporter of hazardous waste: Unknown
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: Unknown
Furnace exemption: Unknown
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

HESS STATION 32492 (Continued) **1000375949**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

Historical Generators:
Date form received by agency: 01/01/2006
Facility name: HESS STATION 32492
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Facility name: HESS STATION 32492
Site name: RAD ENERGY CORP IMPLEMENTATION SERVICES
Classification: Large Quantity Generator

Date form received by agency: 01/28/1998
Facility name: HESS STATION 32492
Classification: Not a generator, verified

Date form received by agency: 03/23/1989
Facility name: HESS STATION 32492
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004428682

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LTANKS:
Site ID: 218580
Spill No: 9007566
Spill Date: 10/11/1990
Spill Cause: Tank Overfill
Spill Source: Gasoline Station
Spill Class: Not reported
Spill Closed Dt: 11/14/1990
Facility Addr2: Not reported
Cleanup Ceased: 11/14/1990
Cleanup Meets Standard: True
SWIS: 3000
Investigator: KJGOMEZ
Referred To: Not reported
Reported to Dept: 10/11/1990
CID: 04
Water Affected: Not reported
Spill Notifier: Responsible Party

HESS STATION 32492 (Continued) **1000375949**

Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	10/12/1990
Spill Record Last Update:	11/15/1990
Spiller Name:	Not reported
Spiller Company:	AMERADA HESS
Spiller Address:	1 WOODBRIGE PLAZA
Spiller City,St,Zip:	WOODBRIDGE, NJ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	180828
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "GOMEZ"
Remarks:	PRECONSTRUCTION WORK BEING DONE BY HESS, FOUND CONTAMINATION. HESS IN THE PROCESS OF DOING REPAIRS TO LINES

Material:

Site ID:	218580
Operable Unit ID:	944898
Operable Unit:	01
Material ID:	431418
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

Site ID:	218578
Spill No:	8705526
Spill Date:	9/30/1987
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

HESS STATION 32492 (Continued) **1000375949**

Spill Closed Dt:	9/26/2005
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3022
Investigator:	KJGOMEZ
Referred To:	Not reported
Reported to Dept:	9/30/1987
CID:	04
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	10/6/1987
Spill Record Last Update:	2/17/2006
Spiller Name:	Not reported
Spiller Company:	HESS S/S
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	294301
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "AUSTIN WELL" / / : 10/1 TO UNCOVER & REPAIR 10/2 RETEST. 12/14/00 FILE REASSIGNED 6/20/05 FILE REASSIGNED FILE INACTIVE
Remarks:	3-3K SIPHON SYSTEM LEAK RATE -.533 GPH

Material:

Site ID:	218578
Operable Unit ID:	911691
Operable Unit:	01
Material ID:	468123
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	218578
Operable Unit ID:	911691
Operable Unit:	01
Material ID:	2096464
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

HESS STATION 32492 (Continued) **1000375949**

Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 218578
Spill Tank Test: 1531779
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

Site ID: 218579
Spill No: 8705600
Spill Date: 10/2/1987
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 1/9/1995
Facility Addr2: Not reported
Cleanup Ceased: 1/9/1995
Cleanup Meets Standard: True
SWIS: 3000
Investigator: MIRZA
Referred To: Not reported
Reported to Dept: 10/2/1987
CID: 04
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 10/6/1987
Spill Record Last Update: 1/14/2003
Spiller Name: Not reported
Spiller Company: HESS S/S
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1
DER Facility ID: 180828
DEC Memo: Not reported
Remarks: FAILED PETROTITE SYSTEM TEST AT -.5 GPH

Material:
Site ID: 218579
Operable Unit ID: 911734

HESS STATION 32492 (Continued) **1000375949**

Operable Unit: 01
Material ID: 468188
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 218579
Spill Tank Test: 1531811
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

HIST LTANKS:
Region of Spill: 1
Spill Number: 8705526
Spill Date: 09/30/1987
Spill Time: 18:30
Spill Cause: Tank Test Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Gas Station
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: / /
Cleanup Ceased: / /
Cleanup Meets Standard: False
Investigator: AUSTIN WELL
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 09/30/87
Reported to Department Time: 18:44
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: HESS S/S
Spiller Address: Not reported

HESS STATION 32492 (Continued) **1000375949**

Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Tank Tester
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/06/87
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 12/15/00
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: 0
Test Method: Not reported
Leak Rate Failed Tank: 0.00
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: / / : 10/1 TO UNCOVER REPAIR 10/2 RETEST. 12/14/00 FILE REASSIGNED
Spill Cause: 3-3K SIPHON SYSTEM LEAK RATE -.533 GPH

Region of Spill: 1
Spill Number: 9007566
Spill Date: 10/11/1990
Spill Time: 09:00
Spill Cause: Tank Overfill
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Gas Station
Spill Class: Not reported
Spill Closed Dt: 11/14/90
Cleanup Ceased: 11/14/90
Cleanup Meets Standard: True
Investigator: GOMEZ
Caller Name: Not reported
Caller Agency: Not reported

HESS STATION 32492 (Continued) **1000375949**

Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 10/11/90
Reported to Department Time: 09:49
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: AMERADA HESS
Spiller Address: 1 WOODBRIGE PLAZA
Spiller City,St,Zip: WOODBRIDGE, NJ
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: Responsible Party
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 10/12/90
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 11/15/90
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: Not reported
Spill Cause: PRECONSTRUCTION WORK BEING DONE BY HESS, FOUND CONTAMINATION. HESS IN THE PROCESS OF DOING REPAIRS TO LINES

HESS STATION 32492 (Continued) **1000375949**

Region of Spill:	1
Spill Number:	8705600
Spill Date:	10/02/1987
Spill Time:	16:00
Spill Cause:	Tank Test Failure
Resource Affectd:	Groundwater
Water Affected:	Not reported
Spill Source:	Gas Station
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	01/09/95
Cleanup Ceased:	01/09/95
Cleanup Meets Standard:	True
Investigator:	MIRZA
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	10/02/87
Reported to Department Time:	16:35
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	HESS S/S
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	Not reported
Facility Extention:	Not reported
Spill Notifier:	Tank Tester
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	True
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	10/06/87
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	01/12/95
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	0
Test Method:	Not reported
Leak Rate Failed Tank:	0.00
Gross Leak Rate:	Not reported

HESS STATION 32492 (Continued) **1000375949**

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: / / : G.I. WILL ISOLATE TANKS. 01/09/95: G.I. WILL ISOLATE TANKS TANKS REMOVED 12/90, BEING HANDLED UNDER SPILL 87-05526.
Spill Cause: FAILED PETROTITE SYSTEM TEST AT -.5 GPH

NY MANIFEST:
EPA ID: NYD982727570
Country: USA
Mailing Name: HESS STATION 32492
Mailing Contact: JOHN GEITNER
Mailing Address: 1 HESS PLAZA
Mailing Address 2: Not reported
Mailing City: WOODBRIDGE
Mailing State: NJ
Mailing Zip: 07095
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 732-750-7105

Document ID: 06
Manifest Status: NJA5241081
Trans1 State ID: NYD982727570
Trans2 State ID: Not reported
Generator Ship Date: NJD002200046
Trans1 Recv Date: Not reported
Trans2 Recv Date: NJ0000027193
TSD Site Recv Date: Not reported
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: N
Trans1 EPA ID: N
Trans2 EPA ID: N
TSDF ID: N
Waste Code: N
Quantity: Not reported
Units: 1
Number of Containers: DM
Container Type: 55
Handling Method: G
Specific Gravity: 1
Waste Code: T
Quantity: Not reported
Units: Not reported
Number of Containers: Not reported

HESS STATION 32492 (Continued) **1000375949**

Container Type:	Not reported
Handling Method:	Not reported
Specific Gravity:	Not reported
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB2097027
Manifest Status:	Completed copy
Trans1 State ID:	MK8837
Trans2 State ID:	Not reported
Generator Ship Date:	910114
Trans1 Recv Date:	910114
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	910114
Part A Recv Date:	910205
Part B Recv Date:	910131
Generator EPA ID:	NYD982727570
Trans1 EPA ID:	NYD006801245
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Year:	91
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA5241081
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193

HESS STATION 32492 (Continued) **1000375949**

Trans2 State ID:	Not reported
Generator Ship Date:	02/24/2006
Trans1 Recv Date:	02/24/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982727570
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA4046923
Manifest Status:	Not reported
Trans1 State ID:	PAD014146179
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2002
Trans1 Recv Date:	10/15/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982727570
Trans1 EPA ID:	NJD002200046
Trans2 EPA ID:	Not reported
TSDF ID:	06815
Waste Code:	D018 - BENZENE 0.5 MG/L TCLP
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	02
Manifest Tracking Num:	Not reported
Import Ind:	Not reported

HESS STATION 32492 (Continued) **1000375949**

Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA3016268
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/01/1999
Trans1 Recv Date:	07/01/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/03/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982727570
Trans1 EPA ID:	NJD002200046
Trans2 EPA ID:	Not reported
TSDF ID:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Quantity:	00020
Units:	T - Tons
Number of Containers:	001
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	99
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA5241081
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/24/2006
Trans1 Recv Date:	02/24/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2006
Part A Recv Date:	Not reported

HESS STATION 32492 (Continued) **1000375949**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD982727570
Trans1 EPA ID:	S5811
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	06
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

NJ MANIFEST:

Manifest Code:	NJA5241081
EPA ID:	NYD982727570
Date Shipped:	20060224
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060224
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060224
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	04130621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported

HESS STATION 32492 (Continued) **1000375949**

Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

93
NNW
1/4-1/2
0.416 mi.
2198 ft.

300 WESTBURY AVENUE
CARLE PLACE, NY

LTANKS **S104619428**
HIST LTANKS **N/A**

Relative:
Higher

Actual:
99 ft.

LTANKS:

Site ID:	117377
Spill No:	9707529
Spill Date:	9/25/1997
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	10/28/1997
Facility Addr2:	Not reported
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	3000
Investigator:	RMS HAAS
Referred To:	Not reported
Reported to Dept:	9/25/1997
CID:	04
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	9/25/1997
Spill Record Last Update:	10/29/1997
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller City,St,Zip:	***UPDATE***, ZZ
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	102120
DEC Memo:	Not reported
Remarks:	CONTAMINATED SOIL FOUND DURING TANK REMOVAL

Material:

Site ID:	117377
Operable Unit ID:	1053905
Operable Unit:	01
Material ID:	329541

(Continued) **S104619428**

Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: Not reported
Spill Tank Test: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

HIST LTANKS:
Region of Spill: 1
Spill Number: 9707529
Spill Date: 09/25/1997
Spill Time: 14:30
Spill Cause: Tank Failure
Resource Affectd: Groundwater
Water Affected: Not reported
Spill Source: Other Commercial/Industrial
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/28/97
Cleanup Ceased: / /
Cleanup Meets Standard: True
Investigator: RMS HAAS
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 09/25/97
Reported to Department Time: 14:57
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: ( ) -
Spiller Extention: Not reported
Spiller Name: UNK
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spiller Cleanup Date: / /

(Continued) **S104619428**

Facility Contact: Not reported
Facility Phone: Not reported
Facility Extention: Not reported
Spill Notifier: DEC
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: True
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 09/25/97
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 10/29/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 0
Unkonwn Quantity Spilled: True
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: True
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: NO CONTAMINATION OR IMPACT TO GW,NO FURTHER ACTION REQUIRED
Spill Cause: CONTAMINATED SOIL FOUND DURING TANK REMOVAL

94
North
1/4-1/2
0.416 mi.
2199 ft.

AMS STATIONERY
520 WESTBURY AVENUE
CARLE PLACE, NY

LTANKS **S100492754**
HIST LTANKS **N/A**
DRYCLEANERS

Relative:
Higher

Actual:
100 ft.

LTANKS:
Site ID: 253304
Spill No: 9300225
Spill Date: 4/5/1993
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 4/6/1993
Facility Addr2: Not reported
Cleanup Ceased: 4/6/1993
Cleanup Meets Standard: True

AMS STATIONERY (Continued) **S100492754**

SWIS:	3000
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	4/5/1993
CID:	04
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	4/6/1993
Spill Record Last Update:	11/21/2001
Spiller Name:	Not reported
Spiller Company:	AMS STATIONERY
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	207511
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "NONE" 04/06/93: NO RESPONSE REQ'D.
Remarks:	LINE LEAKED TO CONCRETE FLOOR, LINE REPAIRED, SPEEDI DRI APPLIED, P/U AND DISPOSE

Material:

Site ID:	253304
Operable Unit ID:	982112
Operable Unit:	01
Material ID:	400989
Material Code:	0001
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

AMS STATIONERY (Continued) **S100492754**

HIST LTANKS:

Region of Spill:	1
Spill Number:	9300225
Spill Date:	04/05/1993
Spill Time:	12:01
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Other Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	04/06/93
Cleanup Ceased:	04/06/93
Cleanup Meets Standard:	True
Investigator:	NONE
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Caller Extension:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Notifier Extension:	Not reported
Reported to Department Date:	04/05/93
Reported to Department Time:	14:42
SWIS:	28
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
Spiller Name:	AMS STATIONERY
Spiller Address:	Not reported
Spiller City,St,Zip:	Not reported
Spiller Cleanup Date:	/ /
Facility Contact:	Not reported
Facility Phone:	Not reported
Facility Extention:	Not reported
Spill Notifier:	Other
PBS Number:	Not reported
Last Inspection:	/ /
Recommended Penalty:	Penalty Not Recommended
Enforcement Date:	/ /
Investigation Complete:	/ /
UST Involvement:	False
Date Region Sent Summary to Central Office:	/ /
Corrective Action Plan Submitted:	/ /
Date Spill Entered In Computer Data File:	04/06/93
Time Spill Entered In Computer Data File:	Not reported
Spill Record Last Update:	11/21/01
Is Updated:	False

Tank:

PBS Number:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate Failed Tank:	Not reported

AMS STATIONERY (Continued) **S100492754**

Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 2
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: #2 FUEL OIL
Class Type: #2 FUEL OIL
Times Material Entry In File: 24464
CAS Number: Not reported
Last Date: 19941207
DEC Remarks: 04/06/93: NO RESPONSE REQ D.
Spill Cause: LINE LEAKED TO CONCRETE FLOOR, LINE REPAIRED, SPEEDI DRI APPLIED, P/U AND DISPOSE

DRYCLEANERS:
Facility ID: 1282201389
Region: 1

95
ENE
1/4-1/2
0.430 mi.
2268 ft.

MICHAEL SKURNICK **LTANKS** **S102619214**
1400 OLD COUNTRY ROAD **HIST LTANKS** **N/A**
WESTBURY, NY

Relative: Higher

Actual: 106 ft.

LTANKS:
Site ID: 150028
Spill No: 9314334
Spill Date: 3/8/1994
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 4/21/1997
Facility Addr2: Not reported
Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 3000
Investigator: ACLAMANN
Referred To: Not reported
Reported to Dept: 3/8/1994
CID: 04
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/9/1994
Spill Record Last Update: 4/22/1997
Spiller Name: Not reported
Spiller Company: MICHAEL SKURNICK
Spiller Address: 12 PARKVIEW DRIVE
Spiller City,St,Zip: MUTTONTOWN, ZZ
Spiller County: 001

MICHAEL SKURNICK (Continued) **S102619214**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	1
DER Facility ID:	127584
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "LAMANNO" / / : AT OFFICE BLDG. CLEANUP BY TYREE, NO OTHER ACTION NEEDED
Remarks:	SPILL ON PARKING LOT & INTO VENTILATION SHAFT, SORBANT APPLIED

Material:

Site ID:	150028
Operable Unit ID:	996266
Operable Unit:	01
Material ID:	386132
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

HIST LTANKS:

Region of Spill:	1
Spill Number:	9314334
Spill Date:	03/08/1994
Spill Time:	10:15
Spill Cause:	Tank Failure
Resource Affectd:	On Land
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	04/21/97
Cleanup Ceased:	/ /
Cleanup Meets Standard:	True
Investigator:	LAMANNO
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported

MICHAEL SKURNICK (Continued) **S102619214**

Caller Extension: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Notifier Extension: Not reported
Reported to Department Date: 03/08/94
Reported to Department Time: 11:37
SWIS: 28
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
Spiller Name: MICHAEL SKURNICK
Spiller Address: 12 PARKVIEW DRIVE
Spiller City,St,Zip: MUTTONTOWN
Spiller Cleanup Date: / /
Facility Contact: Not reported
Facility Phone: (516) 931-6934
Facility Extention: Not reported
Spill Notifier: Fire Department
PBS Number: Not reported
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Enforcement Date: / /
Investigation Complete: / /
UST Involvement: False
Date Region Sent Summary to Central Office: / /
Corrective Action Plan Submitted: / /
Date Spill Entered In Computer Data File: 03/09/94
Time Spill Entered In Computer Data File: Not reported
Spill Record Last Update: 04/22/97
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 7
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: GASOLINE
Class Type: GASOLINE
Times Material Entry In File: 21329
CAS Number: Not reported
Last Date: 19940929
DEC Remarks: / / : AT OFFICE BLDG. CLEANUP BY TYREE, NO OTHER ACTION NEEDED
Spill Cause: SPILL ON PARKING LOT INTO VENTILATION SHAFT, SORBANT APPLIED

96
South
1/4-1/2
0.448 mi.
2363 ft.

AWARD PACKAGING (TENANT)
625 SOUTH STREET
GARDEN CITY, NY

SHWS **S102135237**
NY Spills **N/A**
NY Hist Spills

Relative:
Lower

Actual:
84 ft.

SHWS:

Program:	HW
Site Code:	343267
Classification:	SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region:	1
Acres:	1.760
HW Code:	130155
Record Add:	4/7/2005 4:21:00 PM
Record Upd:	9/24/2009 8:55:00 AM
Updated By:	GTBOBERS
Site Description:	The Award Packaging site is a former printing facility located in an industrial area to the east of the Roosevelt Field Mall in Nassau County. The site consists of a 40,000 square foot, one-story brick building on a 1.76 acre parcel. The facility applied solvent-based inks to plastic packaging materials. Printing related wastes containing tetrachloroethene, trichloroethane, toluene and xylenes have historically been released into two dry wells in the outdoor waste storage area and to one small dry well inside the building in the ink storage room. In 2004, soil excavations intended to remediate these three dry wells were not able to remove all the contamination. For the two dry wells by the waste storage area, the contamination extends to the underlying groundwater. A groundwater sample collected on August 20, 2004 from the exposed groundwater at the bottom of the excavation for the northern dry well in the waste storage area (DW-2) detected toluene at 29,000 micrograms per liter and total xylenes at 4,700 micrograms per liter. The GA groundwater standard for both compounds is 5 micrograms per liter. The property owner began conducting a remedial investigation in May 2008 and subsequently sampled the soil and groundwater.
Env Problem:	Tetrachoroethene, trichloroethane, toluene and xylenes that were used as solvents in printing operations were released to three on-site dry wells. Removal actions for all three dry wells were not able to remove all the contamination. For the two dry wells by the outdoor waste storage area, the contamination extends to the underlying groundwater. The groundwater beneath the site exceeds New York State groundwater standards. An active public supply well field is located approximately 3500 foot downgradient of the site.
Health Problem:	Exposures to site-related contaminants in groundwater are not expected since the area is served by public water. There are several Garden City supply wells located within one mile of the site that treat raw water to remove VOC contamination. The water is monitored routinely to verify compliance with New York State (NYS) drinking water standards.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:44’10 / 73:36’20
Dell:	False
Record Add:	5/26/2005 8:51:00 AM

AWARD PACKAGING (TENANT) (Continued) **S102135237**

Record Upd:	6/21/2007 2:12:00 PM
Updated By:	JLDYBER
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	DAVID AND RICHARD COHEN
Owner Company:	AWARD PACKAGING
Owner Address:	22-33 BROAD HOLLOW ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	DAVID AND RICHARD COHEN
Owner Company:	COHEN ASSOC. REAL ESTATE
Owner Address:	22-33 BROAD HOLLOW ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	FARMINGDALE, NY 11735
Owner Country:	United States of America
HW Code:	130155
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130155
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130155
Waste Type:	1,1,1 TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130155
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130155
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130155
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NY Spills:

Site ID:	227087
Facility Addr2:	Not reported
Facility ID:	9103570
Spill Number:	9103570
Facility Type:	ER
SWIS:	3000
Investigator:	WJPARISH

AWARD PACKAGING (TENANT) (Continued) **S102135237**

Referred To:	Not reported
Spill Date:	7/1/1991
Reported to Dept:	7/1/1991
CID:	04
Spill Cause:	Deliberate
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Penalty Not Recommended
UST Trust:	False
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt:	5/12/1998
Remediation Phase:	0
Date Entered In Computer:	7/2/1991
Spill Record Last Update:	5/13/1998
Spiller Name:	Not reported
Spiller Company:	AWARD PACKAGING (TENANT)
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Region:	1
DER Facility ID:	187436
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "PARISH" BEING HANDLED BY USEPA, NCDH FOR UIC PROGRAM
Remarks:	CONSULTANT REPORT SHOWS INJECTION WELL CONTAMINATED "THEY ARE DOING VOLUNTARY CLOSURE OF INJECTION WELL", NCDH AWARE OF PROBLEMS, EPA NOTIFIED. FLOOR DRAIN IN STORAGE BLDG

Material:

Site ID:	227087
Operable Unit ID:	957612
Operable Unit:	01
Material ID:	422710
Material Code:	0776A
Material Name:	CHLORINATED SOLVENTS
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported

AWARD PACKAGING (TENANT) (Continued) **S102135237**

Modified By: Not reported
Last Modified: Not reported
Test Method: Not reported

NY Hist Spills:
Region of Spill: 1
Spill Number: 9103570
Investigator: PARISH
Caller Name: Not reported
Caller Agency: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Agency: Not reported
Notifier Phone: Not reported
Spill Date/Time: 07/01/1991 12:00
Reported to Dept Date/Time: 07/01/91 15:41
SWIS: 28
Spiller Name: AWARD PACKAGING (TENANT)
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Address: Not reported
Spiller City,St,Zip: Not reported
Spill Cause: Deliberate
Reported to Dept: Groundwater
Water Affected: Not reported
Spill Source: 01
Spill Notifier: Other
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/12/98
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 07/02/91
Date Spill Entered In Computer Data File: Not reported
Update Date: 05/13/98
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Hazardous Material
Quantity Spilled: 0

AWARD PACKAGING (TENANT) (Continued) **S102135237**

Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: CHLORINATED SOLVENTS
Class Type: CHLORINATED SOLVENTS
Times Material Entry In File: 2
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: BEING HANDLED BY USEPA, NCDH FOR UIC PROGRAM
Remark: CONSULTANT REPORT SHOWS INJECTION WELL CONTAMINATED THEY ARE DOING VOLUNTARY CLOSURE OF INJECTION WELL , NCDH AWARE OF PROBLEMS, EPA NOTIFIED. FLOOR DRAIN IN STORAGE BLDG

---

97 East 1/4-1/2 0.452 mi. 2385 ft. **ROOSEVELT FIELD** **FUDS** **1010309643**
GARDEN CITY, NY **N/A**

Relative: Higher

Actual: 101 ft.

FUDS:
Federal Facility ID: NY9799F8710
FUDS #: C02NY0997
INST ID: 55079
Facility Name: ROOSEVELT FIELD
City: GARDEN CITY
State: NY
EPA Region: 2
County: NASSAU
Congressional District: 04
US Army District: New England District (NAE)
Fiscal Year: 2008
Telephone: 978-318-8238
NPL Status: Not Listed
RAB: Not reported
CTC: 114.4
Current Owner: PRIVATE

FUDS Description Details:

LIGHT INDUSTRIAL AREA SINCE DOD; SEVERAL TCE USERS/PRPS. VARIOUS HANGARS AND RUNWAYS. THE NAVY PREPAIRED AIRCRAFTS FOR OVERSEAS SHIPMENT.THERE WERE SIX ANTISUBMARINE PATROLES WHICH FLEW DAILY FROM ROO SEVELT FIELD. THIS CONDITION WAS TO REMAIN UNTIL
THE END OF WWII.

FUDS History Details:

ROOSEVELT FIELD BEGAN OPERATING AS AN AVIATION FACILITY IN 1909. IN 1939, DOA ENTERED INTO A SERVICE CONTRACT WITH ROOSEVELT AVIATION SCHOOL. THIS CONTRACT WAS TERMINATED IN 1945. IN 1940, DON L EASE AIRCRAFT HANGARS FROM ROOSEVELT FIELD INC. IN 1943
3 LEASE WAS MODIFIED , TO INCLUDE USE OF THE ENTIRE AIRFIELD. IN 1946, THE LEASE WAS TERMINATED. IN 1950, ROOSEVELT FIELD SOLD SITE TO WEBB & KNAPP CORP. IN 1951, ALL AVIATION ACTIVITIES CEASED. CURRENTLY IS A SHOPPING CENTER.

FUDS Current Program Details:

ROOSEVELT FIELD (Continued) **1010309643**

FUDS Future Program Details:

98
SSW
1/2-1
0.762 mi.
4022 ft.

GARDEN CITY - STEWART AVENUE HOLDER **Manufactured Gas Plants** **1008407922**
600 STEWART AVE. **N/A**
EAST GARDEN CITY, NY 11530

Relative:
Lower

Actual:
78 ft.

99
South
1/2-1
0.768 mi.
4053 ft.

PASLEY SOLVENTS & CHEMICALS INC. **SHWS** **S105586257**
556 COMMERCIAL AVENUE **VAPOR REOPENED** **N/A**
GARDEN CITY, NY 11530

Relative:
Lower

Actual:
82 ft.

SHWS:

Program:	HW
Site Code:	55762
Classification:	SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region:	1
Acres:	.250
HW Code:	130016
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	6/18/2007 1:42:00 PM
Updated By:	JAYAVOND

Site Description: Pasley Solvents operated as a chemical distribution facility from 1969 through mid-1982. The site contains several above ground storage tanks. Contamination of soil and groundwater at this facility is noted to be from fuel oil, gasoline, solvents, and chlorinated hydrocarbons. Prior to 1969, the site was occupied by a fuel oil and gasoline distributor. The contamination on-site is suspected to have been caused by spills during loading and unloading operations at the aboveground tanks. There have also been illegal spills of oils and solvents on the ground. Found in on-site groundwater monitoring wells were methylene chloride, chloroform, trichloroethane, toluene, xylene, ethylbenzene and 1,1,1-trichloroethane; all in excess of the NYS Ambient Water Quality Standards and Guidance Values (Part 703). There is a threat to groundwater quality. The aboveground storage tanks were dismantled and removed starting in September of 1988 and completed by January of 1989. A Potentially Responsible Party (PRP) funded Remedial Investigation/ Feasibility Study (RI/FS) has been completed for this site, and a Record of Decision (ROD) was signed in 1992. An amended ROD was signed in March of 1995. The ROD called for remediation of the groundwater and soils both on site and off site using air sparging combined with soil vapor extraction. Construction of the ROD remedy was completed and became operational in October 1997. The USEPA authorized a six month temporary system shutdown on September 19, 2002. USEPA authorized the RP to demobilize and remove the treatment system in 2004. USEPA has proposed delisting the site from the NPL. NYSDOH and NYSDEC have requested additional conformatory sampling be performed prior to concurring with the deletion proposal. This work was done as part of the Roosevelt Field study.

PASLEY SOLVENTS & CHEMICALS INC. (Continued) **S105586257**

Env Problem:	Hazardous waste disposal has caused groundwater contamination in excess of NYS standards in a sole source drinking water aquifer.
Health Problem:	On-site soils have been remediated and there are no remaining site contaminants above levels that restrict use of the property (need to see confirmation data). All site soils can be used for unrestricted residential purposes. Groundwater has been remediated and meets drinking water standards (verify again with data). A five-year review completed in August 2004 found that the implemented remedies are protective of human health.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1969
Disp Term:	1982
Lat/Long:	40:43:44:0 / 73:36:54:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	6/14/2006 7:43:00 AM
Updated By:	rmdenyse
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	PASLEY SOLVENTS AND CHEMICALS CO.
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	PASLEY SOLVENTS AND CHEMICALS CO.
Owner Address:	4 SOUTH ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	OYSTER BAY, NY 11771
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Lawerence Bennett, Inc.
Owner Address:	4 South Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Oyster Bay, NY 11771
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Pasley Solvents & Chemicals, Inc.
Owner Address:	556 Commercial Avenue / PO Box 118
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	PASLEY SOLVENTS AND CHEMICALS CO.

PASLEY SOLVENTS & CHEMICALS INC. (Continued) **S105586257**

Owner Address: P.O. BOX 118
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
HW Code: 130016
Waste Type: FUEL OIL, GASOLINE, SOLVENTS
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130016
Waste Type: CHLORINATED HYDROCARBONS (FOO1 & FOO2)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 05
Cross Ref Type Code: 15
Cross Ref Type: Congressional District
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: INITIAL
Crossref ID: NYD991292004
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS

VAPOR REOPENED:
Site Code: 130016
Facility Status: Underway

---

100 West 1/2-1 0.958 mi. 5059 ft.

A.K. ALLEN CORP
255 E 2ND ST
MINEOLA, NY 11501

RCRA-NonGen 1000101587
SHWS NYD002038040
MANIFEST
MANIFEST

Relative: Higher

Actual: 109 ft.

RCRA-NonGen:
Date form received by agency: 04/18/2008
Facility name: A.K. ALLEN CORP
Facility address: 255 E 2ND STREET
MINEOLA, NY 11501
EPA ID: NYD002038040
Mailing address: E 2ND ST
MINEOLA, NY 11501
Contact: JOE CARUAHLO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (516) 747-5440
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: A K ALLEN CORP
Owner/operator address: Not reported

A.K. ALLEN CORP (Continued) **1000101587**

MINEOLA, NY 11501
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/31/1979
Owner/Op end date: Not reported

Owner/operator name: A K ALLEN CO INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RON BUTTNER
Owner/operator address: E 2ND ST
MINEOLA, NY 11501
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/31/1979
Owner/Op end date: Not reported

Owner/operator name: AK ALLEN CORP
Owner/operator address: E 2ND ST
MINEOLA, NY 11501
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/31/1979
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No
Off-site waste receiver: Commercial status unknown

A.K. ALLEN CORP (Continued) **1000101587**

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: No
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: No
Generated waste on-site: Not reported

Historical Generators:
Date form received by agency: 01/01/2007
Facility name: A.K. ALLEN CORP
Site name: A K ALLEN CORP
Classification: Small Quantity Generator

Date form received by agency: 04/20/2006
Facility name: A.K. ALLEN CORP
Site name: A K ALLEN CORP
Classification: Large Quantity Generator

Date form received by agency: 04/19/2006
Facility name: A.K. ALLEN CORP
Site name: A K ALLEN CORP
Classification: Small Quantity Generator

Date form received by agency: 01/08/2004
Facility name: A.K. ALLEN CORP
Site name: A K ALLEN COMPANY INC
Classification: Small Quantity Generator

Date form received by agency: 07/14/1999
Facility name: A.K. ALLEN CORP
Site name: A K ALLEN CO INC
Classification: Small Quantity Generator

Date form received by agency: 02/19/1981
Facility name: A.K. ALLEN CORP
Site name: A K ALLEN CO INC
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

A.K. ALLEN CORP (Continued) **1000101587**

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Biennial Reports:

Last Biennial Reporting Year: 2007

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 6400

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 3200

Waste code: D007
Waste name: CHROMIUM

A.K. ALLEN CORP (Continued) **1000101587**

Amount (Lbs): 2600

Waste code: D008
Waste name: LEAD
Amount (Lbs): 288800

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 3

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 288800

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 02/21/2007
Date achieved compliance: 04/20/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2007
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 04/24/2007
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 02/21/2007
Date achieved compliance: 04/20/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2007
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 04/24/2007
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 02/21/2007
Date achieved compliance: 02/21/2007
Violation lead agency: State

A.K. ALLEN CORP (Continued) **1000101587**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2007
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 04/24/2007
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 02/21/2007
Date achieved compliance: 02/21/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2007
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 04/24/2007
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 02/21/2007
Date achieved compliance: 02/21/2007
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2007
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 04/24/2007
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 373-3.3(g)(1)
Area of violation: Generators - General
Date violation determined: 11/26/2002
Date achieved compliance: 07/23/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/11/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(i)(a)
Area of violation: Generators - General
Date violation determined: 11/26/2002
Date achieved compliance: 07/23/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

A.K. ALLEN CORP (Continued) **1000101587**

Enforcement action date: 12/11/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(a)(8)(iii)(d)
Area of violation: Generators - General
Date violation determined: 11/26/2002
Date achieved compliance: 07/23/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/11/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2b3,5; 373-2.9f
Area of violation: Generators - General
Date violation determined: 11/15/2001
Date achieved compliance: 09/16/2002
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 03/04/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2b3,5; 373-2.9f
Area of violation: Generators - General
Date violation determined: 11/15/2001
Date achieved compliance: 09/16/2002
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/10/2002
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 7000
Paid penalty amount: 7000

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 05/10/1999
Date achieved compliance: 11/15/2001
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/02/2001

A.K. ALLEN CORP (Continued) **1000101587**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 7000
Paid penalty amount: 7000

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/10/1999
Date achieved compliance: 11/15/2001
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 01/12/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 12099
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/10/1999
Date achieved compliance: 11/15/2001
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/02/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 7000
Paid penalty amount: 7000

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/10/1999
Date achieved compliance: 11/15/2001
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 01/12/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 12099
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/10/1999
Date achieved compliance: 11/15/2001
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 07/02/2001
Enf. disposition status: Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 7000
Paid penalty amount: 7000

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 05/10/1999
Date achieved compliance: 11/15/2001
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 01/12/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 12099
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 08/04/1998
Date achieved compliance: 09/30/1998
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/30/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 2000
Paid penalty amount: 2000

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 08/04/1998
Date achieved compliance: 09/30/1998
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 08/14/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 2250
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/04/1998
Date achieved compliance: 09/30/1998
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/30/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 2000
Paid penalty amount: 2000

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/04/1998
Date achieved compliance: 09/30/1998
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 08/14/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 2250
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 02/21/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 02/21/2007
Evaluation lead agency: State

Evaluation date: 02/21/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 02/21/2007
Evaluation lead agency: State

Evaluation date: 02/21/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 02/21/2007
Evaluation lead agency: State

Evaluation date: 02/21/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 04/20/2007
Evaluation lead agency: State

Evaluation date: 02/21/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 04/20/2007
Evaluation lead agency: State

Evaluation date: 11/26/2002
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/23/2003
Evaluation lead agency: State

Evaluation date: 09/16/2002

A.K. ALLEN CORP (Continued) **1000101587**

Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/26/2002
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/15/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/16/2002
Evaluation lead agency: State

Evaluation date: 03/30/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/15/2001
Evaluation lead agency: State

Evaluation date: 03/30/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 11/15/2001
Evaluation lead agency: State

Evaluation date: 03/30/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 11/15/2001
Evaluation lead agency: State

Evaluation date: 03/30/1999
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/30/1998
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/12/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 09/30/1998
Evaluation lead agency: State

Evaluation date: 02/12/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/30/1998

A.K. ALLEN CORP (Continued) **1000101587**

Evaluation lead agency: State

Evaluation date: 02/12/1998
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/06/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

SHWS:
Program: HW
Site Code: 56748
Classification: SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region: 1
Acres: 4.500
HW Code: 130100
Record Add: 7/14/2004 10:13:00 AM
Record Upd: 10/11/2007 3:44:00 PM
Updated By: JAYAVOND
Site Description: The site is located in an urban/suburban portion of Nassau County in Mineola. The site is located at 255 East Second Street on approximately 4.5 acres. The main site features include several interconnected one-story buildings and asphalt parking areas. The site is adjacent to the Long Island Railroad and a residential neighborhood to the south. To the north, east, and west are other commercial and industrial properties. The site is currently used as machine shop. It has been in use as a machine shop since 1947. Prior operations that primarily led to the contamination include improper storage of drums of waste metal shavings. A remedial investigation was completed in 1996. Supplemental RI work was completed in 2003. An IRM to remove contaminated soil was also completed in 2003. A feasibility study was completed in June 2005. The Record of Decision was issued in March 2006. The soil removal along and under the LIRR was completed during the track shutdown during the weekend of August 24-26, 2007.
Env Problem: The primary contaminants of concern at the site known at this time include volatile organic compounds (VOCs) including tetrachloroethene (PCE, or perc), 1,1,1-trichloroethane (TCA), trichloroethene (TCE) and their breakdown products, polychlorinated bi-phenyls (PCBs). Investigations determined that several dry wells, an interior floor drain, and shallow soils in two discreet former drum storage areas were contaminated. The most significant contamination was found in shallow soils in the former drum storage areas located along the southern property line. This contamination extended off site to the Long Island Railroad right-of way. The soil contamination exceeded soil cleanup objectives. A 2003 Interim Remedial Measure (IRM) removed most of the soil contamination on site and some of the off-site contamination. The soil contamination presented a significant environmental threat due to the potential for the contamination to leach into a sole source aquifer.
Health Problem: Off-site contamination of PCB's, VOC's and heavy metals, are restricted to the Long Island Railroad (LIRR) behind the property;

A.K. ALLEN CORP (Continued) **1000101587**

accessiblity to this area appears to be limited. Therefore, public exposures to off-site contamination in this area is not likely. A soil vapor extraction system has been proposed to remediate existing on site soil gas contamination. NYSDOH and NYSDEC will evaluate the need to conduct additional investigations to determine the potential for soil vapor intrusion into structures on or near the site.

Dump:	True
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1947
Disp Term:	present
Lat/Long:	40:44:15:0 / 73:38:15:0
Dell:	False
Record Add:	5/10/2000 10:49:00 AM
Record Upd:	11/21/2005 11:03:00 AM
Updated By:	KJCARPEN
Own Op:	Disp. Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	THE A.K. ALLEN CORPORATION
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	A K Allen Corporation
Owner Address:	225 East Second Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Mineola, NY 11501
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	A K Allen Corporation
Owner Address:	225 East Second Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Mineola, NY 11501
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	A K Allen Corporation
Owner Address:	225 East Second Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Mineola, NY 11501
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	A K Allen Corporation
Owner Address:	225 EAST SECOND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	MINEOLA, NY 11501

A.K. ALLEN CORP (Continued) **1000101587**

Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	THE A.K. ALLEN CORPORATION
Owner Address:	225 EAST SECOND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	MINEOLA, NY 11501
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	THE A.K. ALLEN CORPORATION
Owner Address:	225 EAST SECOND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	MINEOLA, NY 11501
Owner Country:	United States of America
HW Code:	130100
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130100
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

HW Code: 130100
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130100
Waste Type: 1,2-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130100
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130100
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130100
Waste Type: PCB-AROCLOR 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130100
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130100
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 130100
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD002038040
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 5/10/2001 4:31:00 PM
Record Updated: 2/24/2005 3:54:00 PM
Updated By: REGTRANS

NJ MANIFEST:
Manifest Code: NJA5086020
EPA ID: NYD002038040
Date Shipped: 20040513
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYR000080549
Transporter 2 EPA ID: NJR000011528
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 040513
Date Trans2 Transported Waste: 040517
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 040517
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 05260425
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

Manifest Code: NJA5287888
EPA ID: NYD002038040
Date Shipped: 20060313
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJD982792384
Transporter 2 EPA ID: NJD982792384
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 060313
Date Trans2 Transported Waste: 060321
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 060321
Tranporter 1 Decal: Not reported
Tranporter 2 Decal: Not reported
Data Entry Number: 05170621
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No
Reason Load Was Rejected: Not reported
Waste Code: Not reported
Manifest Year: Not reported
Quantity: Not reported
Unit: Not reported
Hand Code: Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Manifest Code:	NJA5287892
EPA ID:	NYD002038040
Date Shipped:	20060712
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD982792384
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	060712
Date Trans2 Transported Waste:	060713
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	060713
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	08310622
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5214106
EPA ID:	NYD002038040
Date Shipped:	20050914
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD982792384
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050914
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050927
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	11160521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5214107
EPA ID:	NYD002038040
Date Shipped:	20050823
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD986607380
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050823
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050823
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	09300525
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Manifest Code:	NJA5214124
EPA ID:	NYD002038040
Date Shipped:	20050330
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD982792384
Transporter 2 EPA ID:	NJD982792384
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050330
Date Trans2 Transported Waste:	050425
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050425
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	06150522
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5241407
EPA ID:	NYD002038040
Date Shipped:	20051208
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD982792384
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	051208
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	051222
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	02160622
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5214112
EPA ID:	NYD002038040
Date Shipped:	20050726
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD980525786
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050726
Date Trans2 Transported Waste:	050803
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050803
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	12050521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Manifest Code:	NJA5214118
EPA ID:	NYD002038040
Date Shipped:	20050621
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD986607380
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050621
Date Trans2 Transported Waste:	050624
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050629
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	07280521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5210619
EPA ID:	NYD002038040
Date Shipped:	20050106
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD986607380
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050106
Date Trans2 Transported Waste:	050107
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050107
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	03240521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5214117
EPA ID:	NYD002038040
Date Shipped:	20050518
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD982792384
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050518
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050519
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	06220525
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Manifest Code:	NJA5214115
EPA ID:	NYD002038040
Date Shipped:	20050609
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD982792384
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050609
Date Trans2 Transported Waste:	000000
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050610
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	07080521
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5214123
EPA ID:	NYD002038040
Date Shipped:	20050427
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD982792384
Transporter 2 EPA ID:	NYR000080549
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	050427
Date Trans2 Transported Waste:	050516
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	050516
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	06220525
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

Manifest Code:	NJA5214104
EPA ID:	NYD002038040
Date Shipped:	20051110
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD982792384
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	051110
Date Trans2 Transported Waste:	051118
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	051118
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	02240621
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Manifest Code:	NJA5074792
EPA ID:	NYD002038040
Date Shipped:	20040622
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD000813477
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	040622
Date Trans2 Transported Waste:	040629
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	040629
Tranporter 1 Decal:	Not reported
Tranporter 2 Decal:	Not reported
Data Entry Number:	08030422
Reference Manifest Number:	Not reported
Was Load Rejected (Y/N):	No
Reason Load Was Rejected:	Not reported
Waste Code:	Not reported
Manifest Year:	Not reported
Quantity:	Not reported
Unit:	Not reported
Hand Code:	Not reported

NY MANIFEST:

EPA ID:	NYD002038040
Country:	USA
Mailing Name:	A K ALLEN COMPANY INC
Mailing Contact:	TIM BYRNES
Mailing Address:	255 EAST SECOND STREET
Mailing Address 2:	Not reported
Mailing City:	MINEOLA
Mailing State:	NY
Mailing Zip:	11501
Mailing Zip4:	Not reported
Mailing Country:	USA
Mailing Phone:	516-747-5450

Document ID:	NYB6613362
Manifest Status:	Completed copy
Trans1 State ID:	XB4885
Trans2 State ID:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Generator Ship Date:	950830
Trans1 Recv Date:	950830
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	950830
Part A Recv Date:	950913
Part B Recv Date:	950914
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00095
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	019
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	95
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000080549
Trans2 State ID:	NJD986607380
Generator Ship Date:	1/10/2007
Trans1 Recv Date:	1/10/2007
Trans2 Recv Date:	1/12/2007
TSD Site Recv Date:	1/19/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	PAD085690592
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186420JJK
Import Ind:	N
Export Ind:	N

A.K. ALLEN CORP (Continued) **1000101587**

Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000080549
Trans2 State ID:	NJD986607380
Generator Ship Date:	1/10/2007
Trans1 Recv Date:	1/10/2007
Trans2 Recv Date:	1/12/2007
TSD Site Recv Date:	2/3/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	SCD036275626
Waste Code:	Not reported
Quantity:	220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186419JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	3/12/2007
Trans1 Recv Date:	3/12/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	3/19/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	SCD036275626
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186434JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	5/11/2007
Trans1 Recv Date:	5/11/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	5/23/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	SCD036275626
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186448JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	6/25/2007
Trans1 Recv Date:	6/27/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	7/3/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	SCD036275626
Waste Code:	Not reported
Quantity:	165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186460JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	8/3/2007
Trans1 Recv Date:	8/3/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	8/15/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	SCD036275626
Waste Code:	Not reported
Quantity:	110

A.K. ALLEN CORP (Continued) **1000101587**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186465JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	10/4/2007
Trans1 Recv Date:	10/4/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/25/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	SCD036275626
Waste Code:	Not reported
Quantity:	804
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186484JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H061

Document ID:	NYA1046151

A.K. ALLEN CORP (Continued) **1000101587**

Manifest Status:	Completed copy
Trans1 State ID:	34465-GNN
Trans2 State ID:	Not reported
Generator Ship Date:	841101
Trans1 Recv Date:	841101
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	841102
Part A Recv Date:	841109
Part B Recv Date:	841127
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	NYD057722258
Trans2 EPA ID:	Not reported
TSDF ID:	NYD057722258
Waste Code:	F001 - UNKNOWN
Quantity:	00150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	84
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB5584374
Manifest Status:	Completed copy
Trans1 State ID:	XB4885
Trans2 State ID:	Not reported
Generator Ship Date:	920616
Trans1 Recv Date:	920616
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	920616
Part A Recv Date:	Not reported
Part B Recv Date:	920625
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00035
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	007
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	124
Year:	92

A.K. ALLEN CORP (Continued) **1000101587**

Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYH0075726
Manifest Status:	Not reported
Trans1 State ID:	NYD082785429
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2000
Trans1 Recv Date:	03/29/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/29/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	PX3640
Waste Code:	F003 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	00
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYG1612719
Manifest Status:	Not reported
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/2000
Trans1 Recv Date:	01/06/2000
Trans2 Recv Date:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

TSD Site Recv Date:	01/07/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	NYD049178296
Trans2 EPA ID:	Not reported
TSDF ID:	PC4339
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	01200
Units:	P - Pounds
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00800
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	F001 - UNKNOWN
Quantity:	00400
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	00
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NYB4269321
Manifest Status:	Completed copy
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	940505
Trans1 Recv Date:	940505
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	940506
Part A Recv Date:	940513
Part B Recv Date:	940518
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	NYD082785429
Trans2 EPA ID:	Not reported
TSDF ID:	NYD082785429

A.K. ALLEN CORP (Continued) **1000101587**

Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00125
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	Not reported
Quantity:	00005
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	129
Year:	94
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA5210619
Manifest Status:	Not reported
Trans1 State ID:	NYR000080549
Trans2 State ID:	NJD986607380
Generator Ship Date:	01/06/2005
Trans1 Recv Date:	01/06/2005
Trans2 Recv Date:	01/07/2005
TSD Site Recv Date:	01/07/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	050059
TSDF ID:	NJD002200046
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	NJA5210638
Manifest Status:	Not reported
Trans1 State ID:	NJD982792384
Trans2 State ID:	Not reported
Generator Ship Date:	02/16/2005
Trans1 Recv Date:	02/16/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/23/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	08219
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002200046
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00125
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00005
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	Not reported
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00010
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00005
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	Not reported
Quantity:	Not reported
Units:	Not reported
Number of Containers:	Not reported
Container Type:	Not reported
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Year:	Not reported
Manifest Tracking Num:	Not reported
Import Ind:	Not reported
Export Ind:	Not reported
Discr Quantity Ind:	Not reported
Discr Type Ind:	Not reported
Discr Residue Ind:	Not reported
Discr Partial Reject Ind:	Not reported
Discr Full Reject Ind:	Not reported
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	Not reported

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986969947
Trans2 State ID:	Not reported
Generator Ship Date:	8/25/2007
Trans1 Recv Date:	8/25/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	8/27/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	21138
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186471JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H132

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986969947
Trans2 State ID:	Not reported
Generator Ship Date:	8/25/2007
Trans1 Recv Date:	8/25/2007

A.K. ALLEN CORP (Continued) **1000101587**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	8/27/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	21791
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186472JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H132

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	8/25/2007
Trans1 Recv Date:	8/25/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	9/4/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	11512
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186473JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N

A.K. ALLEN CORP (Continued) **1000101587**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H132

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	8/25/2007
Trans1 Recv Date:	8/25/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	9/4/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	15014
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186474JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H132

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	8/25/2007
Trans1 Recv Date:	8/25/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	9/4/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002038040
Trans1 EPA ID:	Not reported

A.K. ALLEN CORP (Continued) **1000101587**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD049836679
Waste Code:	Not reported
Quantity:	15676
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	L Landfill.
Specific Gravity:	1
Year:	07
Manifest Tracking Num:	000186475JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Click this hyperlink while viewing on your computer to access
228 additional NY_MANIFEST: record(s) in the EDR Site Report.

---

101 SSW 1/2-1 0.963 mi. 5086 ft. **LI BUS MSBA** **SHWS** **S101008270**
COMMERCIAL AVENUE **VAPOR REOPENED** **N/A**
GARDEN CITY, NY **NY Spills**
NY Hist Spills

Relative: Lower

Actual: 75 ft.

SHWS:

Program:	HW
Site Code:	55761
Classification:	SITE IS PROPERLY CLOSED - REQUIRES CONTINUED MANAGEMENT
Region:	1
Acres:	.500
HW Code:	130014
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	10/3/2008 9:26:00 AM
Updated By:	JAYAVOND

Site Description: This site was used by an industrial facility for chemical distribution. It is now a county-owned property on which a MTA / Long Island bus garage is located. Chlorinated solvents from the former chemical distribution facility have formed a contaminant plume in the groundwater within the area of the site. A groundwater treatment system utilizing air stripping was installed in 1989. Contamination removals exceed 130,000 pounds of contaminants. The Nassau County DPW has assumed full operation of this system in 2003. Operation of the remedial system must continue until the clean-up criteria of the 1985 Consent Judgment is achieved. The results of a soil sampling program in 1992 indicated that the soil clean-up objectives had been met and that further soil flushing was discontinued. In May 2000, additional work was agreed to that will further enhance groundwater extraction capability and ultimately decrease the time required to complete the groundwater remediation. Additional work was done in 2002, including installation of deeper monitoring wells and upgrade of the pumping

LI BUS MSBA (Continued) **S101008270**

	capacity.
Env Problem:	The remediation included the installation of a slurry wall, air strippers, recovery wells, and the placement of recirculation piping in the source area.
Health Problem:	Exposures to contaminated groundwater via drinking water are not expected because public water serves the area and there are no known users of well water in the vicinity. On-site soils are remediated, so dermal exposures are not expected. The potential for inhalation exposures to volatile organic compounds via soil vapor intrusion has not been evaluated.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1955
Disp Term:	1977
Lat/Long:	40:43:47:0 / 73:36:26:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	11/18/1999 12:00:00 PM
Updated By:	INITIAL
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	PUREX CORPORATION
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	PUREX CORPORATION
Owner Address:	COUNTY CENTER
Owner Addr2:	Not reported
Owner City,St,Zip:	MINEOLA, NY 11501
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	County of Nassau
Owner Address:	County Center
Owner Addr2:	Not reported
Owner City,St,Zip:	Mineola, NY 11501
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Purex Corporation
Owner Address:	41 Glen Cove Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Greenvale, NY 11548
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	C01
Owner Name:	Not reported

LI BUS MSBA (Continued) **S101008270**

Owner Company: County of Nassau
Owner Address: County Center
Owner Addr2: Not reported
Owner City,St,Zip: Mineola, NY 11501
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: Not reported
Owner Company: Purex Corporation
Owner Address: 41 Glen Cove Road
Owner Addr2: Not reported
Owner City,St,Zip: Greenvale, NY 11548
Owner Country: United States of America
HW Code: 130014
Waste Type: CHLORINATED SOLVENTS (FOO1) (FOO1)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD170009000
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 11/18/1999 12:00:00 PM
Record Updated: 5/10/2001 4:31:00 PM
Updated By: REGTRANS

VAPOR REOPENED:
Site Code: 130014
Facility Status: Underway

NY Spills:
Site ID: 215092
Facility Addr2: Not reported
Facility ID: 9609414
Spill Number: 9609414
Facility Type: ER
SWIS: 3000
Investigator: UNASSIGNED
Referred To: Not reported
Spill Date: 10/25/1996
Reported to Dept: 10/28/1996
CID: 351
Spill Cause: Human Error
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: Penalty Not Recommended
UST Trust: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 3/1/1999
Remediation Phase: 0
Date Entered In Computer: 10/28/1996
Spill Record Last Update: 3/2/1999
Spiller Name: GARY FIELD

LI BUS MSBA (Continued) **S101008270**

Spiller Company:	LI BUS MSBA
Spiller Address:	COMMERCIAL AVENUE
Spiller City,St,Zip:	GARDEN CITY, NY
Spiller Company:	001
Contact Name:	GARY FIELD
Contact Phone:	(516) 542-0100 4521
DEC Region:	1
DER Facility ID:	283062
DEC Memo:	Not reported
Remarks:	WHEN COMPRESSORS FOR NATURAL GAS BUSES TURNED ON AFTER MAINTENANCE, COMPRESSOR OIL (+ POSSIBLY NATURAL GAS) SPRAYED ON GROUND. THE MAINTENANCE CO CLEANED UP. SITE IS PART OF PUREX SUPER FOUND CLEAN UP - SPILL FAXED FROM REGION 1 ON 10/28/96

Material:

Site ID:	215092
Operable Unit ID:	1040899
Operable Unit:	01
Material ID:	345139
Material Code:	0811A
Material Name:	COMPRESSOR OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	Not reported
Spill Tank Test:	Not reported
Tank Number:	Not reported
Tank Size:	Not reported
Test Method:	Not reported
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	Not reported
Last Modified:	Not reported
Test Method:	Not reported

NY Hist Spills:

Region of Spill:	1
Spill Number:	9609414
Investigator:	UNASSIGNED
Caller Name:	Not reported
Caller Agency:	Not reported
Caller Phone:	Not reported
Notifier Name:	Not reported
Notifier Agency:	Not reported
Notifier Phone:	Not reported
Spill Date/Time:	10/25/1996 23:00
Reported to Dept Date/Time:	10/28/96 12:05
SWIS:	28
Spiller Name:	LI BUS MSBA
Spiller Contact:	GARY FIELD

LI BUS MSBA (Continued) **S101008270**

Spiller Phone: (516) 542-0100 4521
Spiller Contact: GARY FIELD
Spiller Phone: (516) 542-0100 4521
Spiller Address: COMMERCIAL AVENUE
Spiller City,St,Zip: GARDEN CITY, NY
Spill Cause: Human Error
Reported to Dept: On Land
Water Affected: Not reported
Spill Source: 02
Spill Notifier: Responsible Party
PBS Number: Not reported
Cleanup Ceased: / /
Cleanup Meets Std: True
Last Inspection: / /
Recommended Penalty: Penalty Not Recommended
Spiller Cleanup Dt: / /
Enforcement Date: / /
Invstgn Complete: / /
UST Involvement: False
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 03/01/99
Corrective Action Plan Submitted: / /
Date Region Sent Summary to Central Office: / /
Date Spill Entered In Computer Data File: 10/28/96
Date Spill Entered In Computer Data File: Not reported
Update Date: 03/02/99
Is Updated: False

Tank:
PBS Number: Not reported
Tank Number: Not reported
Tank Size: Not reported
Test Method: Not reported
Leak Rate Failed Tank: Not reported
Gross Leak Rate: Not reported

Material:
Material Class Type: Petroleum
Quantity Spilled: 25
Unkonwn Quantity Spilled: False
Units: Gallons
Quantity Recovered: 0
Unkonwn Quantity Recovered: False
Material: COMPRESSOR OIL
Class Type: COMPRESSOR OIL
Times Material Entry In File: 19
CAS Number: Not reported
Last Date: Not reported
DEC Remarks: Not reported
Remark: WHEN COMPRESSORS FOR NATURAL GAS BUSES TURNED ON AFTER MAINTENANCE, COMPRESSOR OIL + POSSIBLY NATURAL GAS) SPRAYED ON GROUND. THE MAINTENANCE CO CLEANED UP. SITE IS PART OF PUREX SUPER FOUND CLEAN UP - SPILL FAXED FROM REGION 1 ON 10/28/96

102
ENE
1/2-1
0.973 mi.
5139 ft.

123 POST AVENUE
123 POST AVENUE
WESTBURY, NY 11590

SHWS **S106780907**
N/A

Relative:
Higher

Actual:
99 ft.

SHWS:

Program:	HW
Site Code:	58577
Classification:	SIGNIFICANT THREAT TO THE PUBLIC HEALTH OR ENVIRONMENT - ACTION REQUIRED.
Region:	1
Acres:	.200
HW Code:	130088
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	7/17/2009 8:55:00 AM
Updated By:	GTBOBERS

Site Description: The 123 Post Avenue site, located in the Village of Westbury, Nassau County, consists of a 50' by 189' lot. The site consists of a building currently used for dry cleaning and a parking area surounding the building. Dry Cleaning has been conducted at the site since the 1950s. The surrounding areas are used for commercial and residential purposes. The site was placed on the NYS Registry of Inactive Hazardous Waste Disposal Sites in December of 1998 after the Nassau County Department of Health performed a facility inspection in July 1995. Investigations by the NCDOH and the potential responsible party (PRP), who implemented the on-site Remedial Investigation (RI) and Interim Remedial Measure (IRM) with NYSDEC oversight, showed site-related PCE contamination in soils and groundwater. The source of contamination was on-site drywells that had been inproperly used to disposed of waste PCE. On-site soils were found to be contaminated with PCE, groundwater was contaminated with PCE and its breakdown constituents TCE and DCE. A soil vapor extraction, SVE, system was installed on-site by the PRP. The SVE system will operate until the remedial objectives for this site have been met. Impacts to off-site groundwater are significant and have been investigated under a separate State-funded RI/Feasibility Study. A state funded Remedial Design/Action is underway to address the off-site plume. The operation of the on-site SVE will be taken over by a state funded consultant.

Env Problem: The primary contaminant of concern is tetrachloroethene and its breakdown products, trichlorethene and dichloroethene. These contaminants exceed groundwater standards beneath the site and for at least 1800 feet downgradient from the site. The groundwater is approximately 30 feet below grade and the flow direction is to the south. The site is listed on the registry of inactive hazardous waste disposal sites as a class 2 site, representing a significant threat to human health and the environment, it is located within a USEPA designated sole source aquifer, and is in the vicinity of municipal water supply wells.

Health Problem: Soil vapor from the site caused indoor air contamination at several neighboring homes and businesses. The soil vapor extraction system operating at the site has effectively reduced concentrations of tetrachloroethene in these buildings. NYSDOH and NYSDEC will evaluate the need to conduct additional investigations to determine the potential for soil vapor intrusion into structures near the off-site groundwater plume. Direct exposures to the contaminated groundwater are not expected, because the site and surrounding area are served by a public water supply. There are three active public water supply

123 POST AVENUE (Continued) **S106780907**

wells nearby. Two are treated to remove volatile organic compound contamination (not from this site), and the third does not require treatment to comply with standards.

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1998
Lat/Long:	40:45:00:0 / 73:35:30:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	2/8/2006 9:29:00 AM
Updated By:	NEPUTNAM
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	WESTBURY VALET DRY CLEANERS
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	WESTBURY VALET DRY CLEANERS
Owner Address:	123 POST AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	WESTBURY, NY 115903140
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	WESTBURY VALET DRY CLEANERS
Owner Address:	123 POST AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	WESTBURY, NY 115903140
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Westbury Valet Dry Cleaners
Owner Address:	123 Post Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Cassel, NY 11590
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Won Ho Choe/Westbury Top Cleaners
Owner Address:	123 Post Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	New Cassel, NY 11590
Owner Country:	United States of America
HW Code:	130088
Waste Type:	TETRACHLOROETHYLENE (PCE)

123 POST AVENUE (Continued) **S106780907**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130088
Waste Type:	TETRACHLOROETHYLENE (PCE) F002 WASTE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130088
Waste Type:	1,1,2-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130088
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	130088
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
CARLE PLACE	S102565754	UNK "VEHICLE"	E & B NORTHERN STATE PKY	11514	NY Spills, NY Hist Spills
CARLE PLACE	S102091704	LILCO	GLEN COVE RD & OLD CTRY	11514	NY Spills, NY Hist Spills
CARLE PLACE	1001197428		MEADOWBROOK STATE PKY	11514	RCRA-NonGen, FINDS, MANIFEST
CARLE PLACE	U003846664	INACTIVE - NYS DOT	NORTHERN STATE PKY	11514	UST
CARLE PLACE	S102094394	LILCO	OLD COUNTRY RD	11514	NY Spills, NY Hist Spills
CARLE PLACE	S102096163	JD PACILICO	OLD COUNTRY RD	11514	NY Spills, NY Hist Spills
CARLE PLACE	S104784748	UNK	OLD CTRY RD & MEADOWBROOK	11514	NY Spills, NY Hist Spills
CARLE PLACE	S104785973	UNK	OLD COUNTRY RD	11514	NY Spills, NY Hist Spills
CARLE PLACE	S104786168	UNK	OLD CTRY RD & MIDDLEBROOK	11514	NY Spills, NY Hist Spills
CARLE PLACE	1009231757	AVIS CAR LEASING	357 OLD COUNTRY RD	11514	MANIFEST
CARLE PLACE	S109062854	ELECTRIC LINE TRUCK	OLD COUNTRY RD	11514	NY Spills
CARLE PLACE	S102236378	GLEN COVE ROAD 1/4 MI SO	VOICE RD	11514	NY Spills, NY Hist Spills
EAST MEADOW	S102094042	LILCO	RT 106	11554	NY Spills, NY Hist Spills
EAST MEADOW	S102565462	UNK	RT 106 & 7TH ST	11554	NY Spills, NY Hist Spills
EAST MEADOW	S107407074	LILCO	RT 106	11554	NY Spills
EAST MEADOW	S103564787	EXXON S/S	RT 24 & RT 106	11554	NY Spills, NY Hist Spills
EAST MEADOW	S104950946	US NAVY FACILITY	82ND MITCHELL AVE & FRONT	11554	LTANKS, HIST LTANKS
EAST MEADOW	S102100595	GREEN RESIDENCE	902 CHERRY LN	11554	NY Spills, NY Hist Spills
EAST MEADOW	S104785803	SPENO PARK	E MEADOW AVE & RT 10	11554	NY Spills, NY Hist Spills
EAST MEADOW	S104513934	US NAVY	MITCHELL MNR	11554	LTANKS, HIST LTANKS
EAST MEADOW	U003376944	MEADOWBROOK E.S.	OLD WESTBURY RD	11554	UST
EAST MEADOW	S104784434	UNK	ROOSEVELT ST & PROSPECT S	11554	NY Spills, NY Hist Spills
EAST MEADOW	S103274869	NEWBRIDGE ROAD SUB STAT	WEST SIDE NEWBRIDGE RD	11554	NY Spills, NY Hist Spills
EAST MEADOW	S109062819	UNKNOWN	WANTAGH STATE PKY S	11554	NY Spills
GARDEN CITY	S104784143	UNK	100TH CLINTON & ROOSEVELT		NY Spills, NY Hist Spills
GARDEN CITY	S104643466		CHERRY VALLEY AVE & CROSS		NY Spills, NY Hist Spills
GARDEN CITY	U003845761	GARDEN CITY SERVICE YARD	CHERRY VALLEY AVE	11530	UST
GARDEN CITY	S102961398	A Z RUBBISH REMOVAL CO	CHERRY VALLEY AVE & TERMINA		NY Spills, NY Hist Spills
GARDEN CITY	S108297842	MUNICIPAL SERVICE YARD-VILLAGE OF	CHERRY VALLEY AVE		NY Spills
GARDEN CITY	1000708537		CHERRY VALLEY AVENUE OF 1ST ST	11530	RCRA-NonGen, FINDS, MANIFEST
GARDEN CITY	1000186374		CHERRY VALLEY AVE	11530	RCRA-NonGen, FINDS, MANIFEST
GARDEN CITY	U004109180	GC UFSD BUS GARAGE	CHERRY VALLEY AVE	11530	UST
GARDEN CITY	S108410691	WELL #8, #12 G.C. GOLF CLUB	CHERRY VALLEY AVE	11530	CBS
GARDEN CITY	S108410694	COMMUNITY PARK POOL	CHERRY VALLEY AVE	11530	CBS
GARDEN CITY	S104541565	OLD ROOSEVELT AIR FIELD HANGAR SIT	CLINTON RD	11530	SHWS
GARDEN CITY	S108410692	WELL 13 & 14 G.C. COUNTRY CLUB	EDGEMERE RD	11530	CBS
GARDEN CITY	S104789091	PEPSI PLANT	E GATE BLVD		NY Spills, NY Hist Spills
GARDEN CITY	S102135415	LILCO	E GATE BLVD		NY Spills, NY Hist Spills
GARDEN CITY	1006810264		E GATE BLVD & CORPORATE DR	11530	RCRA-NonGen, FINDS, MANIFEST
GARDEN CITY	S102138025	GARDEN CITY TRANSPORT CO	OLD COUNTRY RD		NY Spills, NY Hist Spills
GARDEN CITY	S103936257	STERNS DEPARTMENT STORE	OLD COUNTRY RD		NY Spills, NY Hist Spills
GARDEN CITY	S102140618	DATER CONSTRUCTION	OLD COUNTRY RD		NY Spills, NY Hist Spills
GARDEN CITY	S104785021	UNK	OLD COUNTRY RD		NY Spills, NY Hist Spills

City	EDR ID	Site Name	Site Address	Zip	Database(s)
GARDEN CITY	S107788777	ROOSEVELT FIELD MALL	OLD COUNTRY RD		NY Spills
GARDEN CITY	S109582290	ROOSEVELT FIELD SHOPPING MALL	OLD COUNTRY RD		NY Spills
GARDEN CITY	1011626915	OLD ROOSEVELT FIELD CONTAMINATED G	300 RING RD S	11530	ICIS
GARDEN CITY	S104785159	UNK	ROOSEVELT FIELD MALL		NY Spills, NY Hist Spills
GARDEN CITY	1004760483		1100 ROOSEVELT FIELD MALL	11530	RCRA-NonGen, FINDS, MANIFEST
GARDEN CITY	A100297643	MACY'S #53	8004 ROOSEVELT FIELD MALL		AST
GARDEN CITY	A100199314	NORDSTROM	ROOSEVELT FIELD MALL		AST
GARDEN CITY	S109787764	WOOLWORTH	1100 ROOSEVELT FIELD MALL	11530	MANIFEST
GARDEN CITY	S102137701	MONTENAY POWER COMPANY	STEWART AVE & ROOSEVELT A	11530	NY Spills, NY Hist Spills
GREAT NECK	S109824928	CARLE PLACE UFSD - CARLE PLACE HIG	168 CHERRY LANE	11514	MANIFEST
HEMPSTEAD	S109209072	K - INTERSECTION ST. - HEMPSTEAD M	INTERSECTION ST.	11530	SHWS
MINDEN	S106076056	MOHAWK VALLEY ORGANICS	RTE 5S	11590	SWF/LF
MINEOLA	S104784141	UNK	RT 25 & SAGAMORE AVE	11501	NY Spills, NY Hist Spills
MINEOLA	A100212225	MINEOLA INC VILLAGE - EMORY ROAD B	EMORY RD	11501	AST
MINEOLA	1011599678	530 HICKSVILLE ROAD - WINTHROP UNI	530 HICKSVILLE RD	11501	ICIS
MINEOLA	S102098241	KIRCHNER RESIDENCE	377 MORTON HWY	11501	NY Spills, NY Hist Spills
MINEOLA	1011598373	264 OLD COUNTRY ROAD - WINTHROP UN	264 OLD COUNTRY RD	11501	ICIS
MINEOLA	S108638086	ON THE ROAD WAY	160 OLD COUNTRY RD	11501	NY Spills
MINEOLA	U003846573	INACTIVE - GULF	OLD COUNTRY RD	11501	UST
MINEOLA	S104284507	FORMER GAS STATION	600 OLD COUNTRY RD	11501	NY Spills, NY Hist Spills
MINEOLA	S104646164		OLD COUNTRY RD & FRANKLIN A	11501	NY Spills, NY Hist Spills
MINEOLA	S104784363	UNK	OLD COUNTRY RD & 10TH ST	11501	NY Spills, NY Hist Spills
MINEOLA	S102565255	UNK	OLD COUNTRY RD	11501	NY Spills, NY Hist Spills
MINEOLA	S100148690		OLD COUNTRY RD	11501	LTANKS, HIST LTANKS, NY Spills, NY Hist Spills
MINEOLA	S107409804		OLD COUNTRY RD	11501	NY Spills
MINEOLA	1007205094		OLD COUNTY RD E & O WASHINGTON	11501	RCRA-NonGen, MANIFEST
MINEOLA	A100266701	MINEOLA WATER PUMPHOUSE # 4	OLD COUNTRY RD	11501	AST
MINEOLA	2007443513	50 ROSLYN ROAD	50 ROSLYN RD	11501	HMIRS
MINEOLA	S105842500	MINEOLA C & D	WESTBURY AVE & E 2ND ST	11501	SWF/LF
NEW CASSEL	S106780928	TISHCON CORPORATION	31ST AVE & NEW YORK AVE	11590	SHWS, VAPOR REOPENED
NEW CASSEL	S105973186	NEW CASSEL INDUSTRIAL AREA	BETWEEN OLD COUNTRY RD	11590	DEL SHWS
NEW CASSEL	S103567017	7 ANGEL PRODUCE COMPANY	OLD COUNTRY RD	11590	NY Spills, NY Hist Spills
NEW CASSEL	S106018889		OLD COUNTRY RD & GRAYSTONE	11590	NY Spills
OLD WESTBURY	1010566265	NYSDOT BIN 1523680	RTE 25 OVER GLEN COVE RD	11590	RCRA-LQG
OLD WESTBURY	U003847564	OLD WESTBURY WATER WELL #2	GLEN COVE RD	11590	UST, AST
OLD WESTBURY	U003848297	VILLAGE OF OLD WESTBURY - PLANT #4	MORGAN DR	11590	UST, AST
ROOSEVELT FIELD	S102140607	STEWART DIAMOND QUICK PHO	ROOSEVELT FIELD SHCTR	11530	NY Spills, NY Hist Spills
WESTBURY	S109533756	NYSDOT	E BOUND NORTHERN STATE	11590	MANIFEST
WESTBURY	S106780933	89 FROST STREET SITE	89 FROST ST	11590	SHWS, VAPOR REOPENED
WESTBURY	A100199716	SCHWALM, JOHN	824 S GATE	11590	AST
WESTBURY	S106780934	FORMER APPLIED FLUIDICS	770 MAIN ST	11590	SHWS, VAPOR REOPENED
WESTBURY	1009399953	NYSDOT BIN 1058101	NORTHERN STATE PKY	11590	RCRA-NonGen
WESTBURY	U003913745	INACTIVE	OLD COUNTRY RD	11590	UST
WESTBURY	U003968320	INACTIVE - SHELL	OLD COUNTRY RD	11590	UST
WESTBURY	S105234885		449 OLD COUNTRY RD	11590	NY Spills, NY Hist Spills
WESTBURY	1009233344	NYNEX	OLD CTY RD & E OF POST AVE	11590	MANIFEST

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
WESTBURY	1009399863	VERIZON MANHOLE 21	OLD COUNTRY RD	11590	RCRA-NonGen
WESTBURY	U004125473	FDM CORPORATION	515 OLD COUNTRY RD	11590	UST
WESTBURY	S109785361	EXXON CO USA 31763	2 OLD COUNTRY RD - ELLISON MAP	11590	MANIFEST
WESTBURY	A100226794	MIKE'S OF GARDEN CITY	981 OLD COUNTRY RD	11590	AST
WESTBURY	S109797598	EXXON DIV OF CFI #70321	2 OLD COUNTRY RD - ELLISON MAP	11590	MANIFEST
WESTBURY	S109827363	UNKNOWN	525 OLD COUNTRY RD	11590	NY Spills
WESTBURY	U004053191	WESTBURY WATER DISTRICT	STATE ST	11590	UST
WESTBURY	S104484434	WESTBURY WATER DISTRICT	STATE ST	11590	CBS UST, AST, CBS
WESTBURY	S105842501	ROOSEVELT RACEWAY LANDFILL	STREET	11590	SWF/LF
WESTBURY	S106780935	EZ-EM, INC.	750 SUMMA AVE	11590	SHWS, VAPOR REOPENED
WESTBURY	S104784671	UNK	URBAN AVE & OLD COUNTRY R	11590	NY Spills, NY Hist Spills

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/01/2009
Date Data Arrived at EDR: 01/14/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 04/02/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/01/2009
Date Data Arrived at EDR: 01/14/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 04/02/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 03/01/2010
Next Scheduled EDR Contact: 05/31/2010
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/01/2009
Date Data Arrived at EDR: 01/14/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 04/02/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/30/2009
Date Data Arrived at EDR: 08/11/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 41

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 03/30/2010
Next Scheduled EDR Contact: 07/12/2010
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of NPL and Base Realighnment & Closure sites found in the CERCLIS database where FERRO is involved in cleanup projects.

Date of Government Version: 06/23/2009
Date Data Arrived at EDR: 01/15/2010
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 26

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 01/15/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 06/23/2009
Date Data Arrived at EDR: 09/02/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 19

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 03/11/2010
Next Scheduled EDR Contact: 06/14/2010
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/11/2009
Date Data Arrived at EDR: 12/29/2009
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 43

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 02/15/2010
Next Scheduled EDR Contact: 05/31/2010
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 01/13/2010
Date Data Arrived at EDR: 01/15/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 01/13/2010
Date Data Arrived at EDR: 01/15/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 01/13/2010
Date Data Arrived at EDR: 01/15/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 01/13/2010
Date Data Arrived at EDR: 01/15/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/01/2009
Date Data Arrived at EDR: 10/09/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 03/15/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/01/2009
Date Data Arrived at EDR: 10/09/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 03/15/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 01/22/2010
Date Made Active in Reports: 02/11/2010
Number of Days to Update: 20

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 01/15/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 03/26/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

"Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil.Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 02/02/2010
Date Data Arrived at EDR: 02/24/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 21

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/24/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 01/19/2010
Date Data Arrived at EDR: 01/20/2010
Date Made Active in Reports: 02/08/2010
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 01/11/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 04/01/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 12/07/2009
Date Data Arrived at EDR: 12/09/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 7

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Semi-Annually

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 11/24/2009
Date Data Arrived at EDR: 11/25/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/02/2010
Date Data Arrived at EDR: 02/03/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 15
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/19/2009
Date Data Arrived at EDR: 02/19/2009
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 25
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 03/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/12/2009
Date Data Arrived at EDR: 11/12/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 34
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/24/2009
Date Data Arrived at EDR: 05/20/2009
Date Made Active in Reports: 06/17/2009
Number of Days to Update: 28
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 12/01/2009
Date Data Arrived at EDR: 12/01/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 15
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Quarterly

State and tribal registered storage tank lists

UST: Petroleum Bulk Storage (PBS) Database
Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 02/18/2010
Date Data Arrived at EDR: 02/19/2010
Date Made Active in Reports: 03/18/2010
Number of Days to Update: 27
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database
Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30
Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: Varies

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 02/18/2010
Date Data Arrived at EDR: 02/19/2010
Date Made Active in Reports: 03/18/2010
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 02/18/2010
Date Data Arrived at EDR: 02/19/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 26

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 02/18/2010
Date Data Arrived at EDR: 02/19/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 26

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Quarterly

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 02/08/2010
Date Data Arrived at EDR: 02/09/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 9

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/05/2009
Date Data Arrived at EDR: 11/05/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 41

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 12/07/2009
Date Data Arrived at EDR: 12/09/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 7

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Semi-Annually

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 11/12/2009
Date Data Arrived at EDR: 11/20/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 26

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 12/01/2009
Date Data Arrived at EDR: 12/01/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 15

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/01/2008
Date Data Arrived at EDR: 12/30/2008
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 76

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/02/2010
Date Data Arrived at EDR: 02/03/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 15

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 02/17/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/19/2009
Date Data Arrived at EDR: 02/19/2009
Date Made Active in Reports: 03/16/2009
Number of Days to Update: 25

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 03/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/01/2009
Date Data Arrived at EDR: 10/29/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 48

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 01/18/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 03/26/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 03/26/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 12/31/1992
Date Data Arrived at EDR: 01/31/2007
Date Made Active in Reports: 04/19/2007
Number of Days to Update: 78

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/29/2010
Next Scheduled EDR Contact: 07/12/2010
Data Release Frequency: No Update Planned

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 03/26/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 04/02/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 04/05/2010
Next Scheduled EDR Contact: 07/19/2010
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 03/26/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 03/26/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 10/01/2009
Date Data Arrived at EDR: 11/04/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/23/2010
Next Scheduled EDR Contact: 07/12/2010
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-972-3336
Last EDR Contact: 03/22/2010
Next Scheduled EDR Contact: 06/21/2010
Data Release Frequency: Varies

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 02/03/2010
Next Scheduled EDR Contact: 05/10/2010
Data Release Frequency: Annually

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 01/19/2010
Date Data Arrived at EDR: 01/20/2010
Date Made Active in Reports: 02/08/2010
Number of Days to Update: 19

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 01/11/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Semi-Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 02/08/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 08/19/2009
Date Data Arrived at EDR: 12/29/2009
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 43
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 12/14/2009
Next Scheduled EDR Contact: 03/22/2010
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites
A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 06/09/2009
Date Data Arrived at EDR: 06/11/2009
Date Made Active in Reports: 07/01/2009
Number of Days to Update: 20
Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 03/26/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 11/03/2009
Date Data Arrived at EDR: 11/05/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 41

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005
Date Data Arrived at EDR: 12/11/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 31

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 03/17/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 01/06/2010
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 35

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 01/06/2010
Next Scheduled EDR Contact: 04/12/2010
Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/23/2010
Date Data Arrived at EDR: 02/23/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 04/01/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA-NonGen: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 01/13/2010
Date Data Arrived at EDR: 01/15/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 02/19/2010
Next Scheduled EDR Contact: 04/19/2010
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 10/13/2009
Date Data Arrived at EDR: 11/10/2009
Date Made Active in Reports: 12/16/2009
Number of Days to Update: 36

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 02/09/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 703-692-8801
Last EDR Contact: 01/19/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 09/30/2009
Date Made Active in Reports: 12/01/2009
Number of Days to Update: 62

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 03/18/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 08/03/2009
Date Data Arrived at EDR: 10/27/2009
Date Made Active in Reports: 11/09/2009
Number of Days to Update: 13

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 04/05/2010
Next Scheduled EDR Contact: 07/19/2010
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/01/2009
Date Data Arrived at EDR: 12/15/2009
Date Made Active in Reports: 01/19/2010
Number of Days to Update: 35

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 04/02/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 01/05/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 05/08/2009
Number of Days to Update: 1

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 01/21/2010
Next Scheduled EDR Contact: 06/14/2010
Data Release Frequency: Varies

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/17/2009
Date Data Arrived at EDR: 12/08/2009
Date Made Active in Reports: 01/19/2010
Number of Days to Update: 42

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 03/10/2010
Next Scheduled EDR Contact: 06/21/2010
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 01/13/2010
Date Made Active in Reports: 02/18/2010
Number of Days to Update: 36

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 03/02/2010
Next Scheduled EDR Contact: 06/14/2010
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2002
Date Data Arrived at EDR: 04/14/2006
Date Made Active in Reports: 05/30/2006
Number of Days to Update: 46

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/30/2010
Next Scheduled EDR Contact: 07/12/2010
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 03/01/2010
Next Scheduled EDR Contact: 06/14/2010
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 03/01/2010
Next Scheduled EDR Contact: 06/14/2010
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems
Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 01/06/2010
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 35
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/10/2009
Date Data Arrived at EDR: 11/18/2009
Date Made Active in Reports: 01/19/2010
Number of Days to Update: 62
Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 03/29/2010
Next Scheduled EDR Contact: 07/12/2010
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/01/2009
Date Data Arrived at EDR: 10/21/2009
Date Made Active in Reports: 12/01/2009
Number of Days to Update: 41

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 02/16/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 12/24/2009
Date Data Arrived at EDR: 12/31/2009
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 41

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 03/15/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/12/2010
Date Data Arrived at EDR: 01/13/2010
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 28

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 01/13/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 10/19/2009
Date Data Arrived at EDR: 10/22/2009
Date Made Active in Reports: 12/01/2009
Number of Days to Update: 40

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 03/15/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2007
Date Data Arrived at EDR: 02/19/2009
Date Made Active in Reports: 05/22/2009
Number of Days to Update: 92

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 02/25/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/04/2010
Date Data Arrived at EDR: 02/11/2010
Date Made Active in Reports: 03/17/2010
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 02/11/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 12/28/2009
Date Data Arrived at EDR: 12/28/2009
Date Made Active in Reports: 01/27/2010
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/22/2010
Next Scheduled EDR Contact: 04/05/2010
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 01/20/2010
Date Data Arrived at EDR: 01/21/2010
Date Made Active in Reports: 02/08/2010
Number of Days to Update: 18

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/18/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: No Update Planned

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 09/05/2007
Date Made Active in Reports: 10/17/2007
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 02/01/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 12/09/2009
Date Data Arrived at EDR: 12/29/2009
Date Made Active in Reports: 01/27/2010
Number of Days to Update: 29

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/30/2010
Next Scheduled EDR Contact: 07/12/2010
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/19/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 11/16/2009
Date Data Arrived at EDR: 11/16/2009
Date Made Active in Reports: 01/19/2010
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/08/2010
Next Scheduled EDR Contact: 05/10/2010
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 11/09/2009
Date Data Arrived at EDR: 12/18/2009
Date Made Active in Reports: 02/10/2010
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 03/16/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/19/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: N/A

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 01/27/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 01/19/2010
Date Data Arrived at EDR: 01/20/2010
Date Made Active in Reports: 02/09/2010
Number of Days to Update: 20

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 01/11/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Varies

FINANCIAL ASSURANCE 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 10/31/2008
Date Data Arrived at EDR: 11/25/2008
Date Made Active in Reports: 12/11/2008
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 01/11/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Varies

FINANCIAL ASSURANCE: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 01/13/2010
Date Data Arrived at EDR: 01/14/2010
Date Made Active in Reports: 01/27/2010
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 01/11/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: Quarterly

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 01/01/2008
Date Data Arrived at EDR: 02/18/2009
Date Made Active in Reports: 05/29/2009
Number of Days to Update: 100

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 02/24/2010
Next Scheduled EDR Contact: 05/17/2010
Data Release Frequency: Varies

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 02/20/2009
Date Data Arrived at EDR: 02/25/2009
Date Made Active in Reports: 03/09/2009
Number of Days to Update: 12

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 03/16/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 02/20/2009
Date Data Arrived at EDR: 02/25/2009
Date Made Active in Reports: 03/09/2009
Number of Days to Update: 12

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 03/16/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 02/02/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 08/20/2007
Date Data Arrived at EDR: 10/10/2007
Date Made Active in Reports: 11/19/2007
Number of Days to Update: 40

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/20/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003
Date Data Arrived at EDR: 05/27/2003
Date Made Active in Reports: 06/09/2003
Number of Days to Update: 13

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 02/02/2010
Next Scheduled EDR Contact: 04/26/2010
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 08/20/2007
Date Data Arrived at EDR: 10/10/2007
Date Made Active in Reports: 11/19/2007
Number of Days to Update: 40

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/20/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 12/18/2009
Date Data Arrived at EDR: 12/18/2009
Date Made Active in Reports: 01/20/2010
Number of Days to Update: 33

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/15/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 12/18/2009
Date Data Arrived at EDR: 12/18/2009
Date Made Active in Reports: 01/20/2010
Number of Days to Update: 33

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/15/2010
Next Scheduled EDR Contact: 06/28/2010
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 02/08/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Annually

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006
Date Data Arrived at EDR: 01/11/2007
Date Made Active in Reports: 02/07/2007
Number of Days to Update: 27

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 02/08/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Annually

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 05/05/2005
Date Data Arrived at EDR: 05/31/2005
Date Made Active in Reports: 06/30/2005
Number of Days to Update: 30

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 02/09/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Varies

Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 05/05/2005
Date Data Arrived at EDR: 05/31/2005
Date Made Active in Reports: 06/30/2005
Number of Days to Update: 30

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 02/09/2010
Next Scheduled EDR Contact: 05/24/2010
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2007
Date Data Arrived at EDR: 08/26/2009
Date Made Active in Reports: 09/11/2009
Number of Days to Update: 16

Source: Department of Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 03/02/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 01/20/2010
Date Made Active in Reports: 02/05/2010
Number of Days to Update: 16

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/20/2010
Next Scheduled EDR Contact: 05/03/2010
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 12/01/2009
Date Made Active in Reports: 12/14/2009
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 02/23/2010
Next Scheduled EDR Contact: 06/07/2010
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 11/03/2009
Date Data Arrived at EDR: 02/12/2010
Date Made Active in Reports: 02/22/2010
Number of Days to Update: 10

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 03/01/2010
Next Scheduled EDR Contact: 06/14/2010
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 02/18/2010
Date Made Active in Reports: 02/25/2010
Number of Days to Update: 7

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/25/2010
Next Scheduled EDR Contact: 05/10/2010
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 07/17/2009
Date Made Active in Reports: 08/10/2009
Number of Days to Update: 24

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/22/2010
Next Scheduled EDR Contact: 07/05/2010
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: PennWell Corporation
Telephone: (800) 823-6277
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2009 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

900 OLD COUNTRY ROAD
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

TARGET PROPERTY COORDINATES

Latitude (North):	40.74412 - 40° 44' 38.8''
Longitude (West):	73.60552 - 73° 36' 19.9''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	617735.2
UTM Y (Meters):	4511076.5
Elevation:	85 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	40073-F5 FREEPORT, NY
Most Recent Revision:	1994
North Map:	40073-G5 HICKSVILLE, NY
Most Recent Revision:	1979
West Map:	40073-F6 LYNBROOK, NY
Most Recent Revision:	1969
Northwest Map:	40073-G6 SEA CLIFF, NY
Most Recent Revision:	1979

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WSW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
NASSAU, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property:	36059C0226F - FEMA Q3 Flood data
Additional Panels in search area:	36059C0139F - FEMA Q3 Flood data 36059C0138F - FEMA Q3 Flood data 36059C0207F - FEMA Q3 Flood data 36059C0227F - FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
FREEPORT	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Cenozoic
System:	Quaternary
Series:	Pleistocene
Code:	Qp *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS2116638	0 - 1/8 Mile NW
A2	USGS2116637	0 - 1/8 Mile NW
B3	USGS2116584	0 - 1/8 Mile ESE
A4	USGS2116423	0 - 1/8 Mile NNW
A5	USGS2116428	0 - 1/8 Mile NNW
B6	USGS2116609	0 - 1/8 Mile East
B7	USGS2116610	0 - 1/8 Mile East
C8	USGS2116626	1/8 - 1/4 Mile East
C9	USGS2116598	1/8 - 1/4 Mile East
D10	USGS2116422	1/8 - 1/4 Mile ENE
D11	USGS2116465	1/8 - 1/4 Mile NE
C12	USGS2116597	1/8 - 1/4 Mile East
C13	USGS2116583	1/8 - 1/4 Mile East
D14	USGS2116636	1/8 - 1/4 Mile ENE
D15	USGS2116421	1/8 - 1/4 Mile ENE
16	USGS2116685	1/4 - 1/2 Mile SSE
E17	USGS2116691	1/4 - 1/2 Mile SW
18	USGS2116837	1/4 - 1/2 Mile South
E19	USGS2116677	1/4 - 1/2 Mile SW
20	USGS2116542	1/4 - 1/2 Mile WSW
F21	USGS2116599	1/4 - 1/2 Mile West
F22	USGS2116611	1/4 - 1/2 Mile West
F23	USGS2116585	1/4 - 1/2 Mile West
F24	USGS2116627	1/4 - 1/2 Mile West
25	USGS2116846	1/4 - 1/2 Mile SW
H27	USGS2116429	1/4 - 1/2 Mile WNW
I28	USGS2116799	1/4 - 1/2 Mile South
I29	USGS2116800	1/4 - 1/2 Mile South
I30	USGS2116798	1/4 - 1/2 Mile SSE
G31	USGS2116386	1/4 - 1/2 Mile NNE
H33	USGS2116640	1/4 - 1/2 Mile West
H34	USGS2116639	1/4 - 1/2 Mile West
H35	USGS2116431	1/4 - 1/2 Mile WNW
H36	USGS2116481	1/4 - 1/2 Mile WNW
H37	USGS2116482	1/4 - 1/2 Mile WNW
H38	USGS2116483	1/4 - 1/2 Mile WNW
H39	USGS2116470	1/4 - 1/2 Mile WNW
H40	USGS2116466	1/4 - 1/2 Mile WNW
H41	USGS2116467	1/4 - 1/2 Mile WNW
H42	USGS2116469	1/4 - 1/2 Mile WNW
H43	USGS2116468	1/4 - 1/2 Mile WNW
J44	USGS2116838	1/4 - 1/2 Mile SW
J46	USGS2116815	1/4 - 1/2 Mile SW
J47	USGS2116825	1/4 - 1/2 Mile SW
J48	USGS2116824	1/4 - 1/2 Mile SW
J49	USGS2116814	1/4 - 1/2 Mile SW
K50	USGS2116612	1/4 - 1/2 Mile West
K51	USGS2116600	1/4 - 1/2 Mile West
L52	USGS2116550	1/2 - 1 Mile West
L53	USGS2116751	1/2 - 1 Mile WSW
L54	USGS2116752	1/2 - 1 Mile WSW
55	USGS2116914	1/2 - 1 Mile SSW

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
K56	USGS2116613	1/2 - 1 Mile West
K57	USGS2116430	1/2 - 1 Mile West
M58	USGS2116889	1/2 - 1 Mile SSE
M59	USGS2116890	1/2 - 1 Mile SSE
N60	USGS2116847	1/2 - 1 Mile WSW
N61	USGS2116848	1/2 - 1 Mile WSW
N62	USGS2116849	1/2 - 1 Mile WSW
N63	USGS2116856	1/2 - 1 Mile WSW
64	USGS2116933	1/2 - 1 Mile SW
O65	USGS2116736	1/2 - 1 Mile WSW
O66	USGS2116737	1/2 - 1 Mile WSW
P67	USGS2116484	1/2 - 1 Mile WNW
Q68	USGS2116772	1/2 - 1 Mile SW
69	USGS2116839	1/2 - 1 Mile WSW
R70	USGS2116371	1/2 - 1 Mile WNW
S71	USGS2116813	1/2 - 1 Mile SE
S72	USGS2116771	1/2 - 1 Mile SE
T73	USGS2116686	1/2 - 1 Mile WSW
T74	USGS2116687	1/2 - 1 Mile WSW
P75	USGS2116512	1/2 - 1 Mile WNW
Q76	USGS2116968	1/2 - 1 Mile SW
Q77	USGS2116970	1/2 - 1 Mile SW
Q78	USGS2116971	1/2 - 1 Mile SW
Q79	USGS2116969	1/2 - 1 Mile SW
R80	USGS2116372	1/2 - 1 Mile WNW
U81	USGS2117015	1/2 - 1 Mile SSW
U82	USGS2116979	1/2 - 1 Mile SSW
V83	USGS2116857	1/2 - 1 Mile WSW
V84	USGS2116801	1/2 - 1 Mile WSW
U85	USGS2117016	1/2 - 1 Mile South
W86	USGS2116831	1/2 - 1 Mile WSW
87	USGS2117167	1/2 - 1 Mile SSW
X88	USGS2116450	1/2 - 1 Mile West
X89	USGS2116449	1/2 - 1 Mile West
Y90	USGS2116753	1/2 - 1 Mile West
Y91	USGS2116754	1/2 - 1 Mile West
X92	USGS2116472	1/2 - 1 Mile West
X93	USGS2116471	1/2 - 1 Mile West
W94	USGS2116805	1/2 - 1 Mile WSW
V95	USGS2116788	1/2 - 1 Mile WSW
V96	USGS2116802	1/2 - 1 Mile WSW
V97	USGS2116803	1/2 - 1 Mile WSW
V98	USGS2116804	1/2 - 1 Mile WSW
Z99	USGS2117107	1/2 - 1 Mile South
Z100	USGS2117106	1/2 - 1 Mile South
Z101	USGS2117109	1/2 - 1 Mile South
Z102	USGS2117108	1/2 - 1 Mile South
AA103	USGS2116480	1/2 - 1 Mile East
AA104	USGS2116479	1/2 - 1 Mile East
AA105	USGS2116478	1/2 - 1 Mile East
AB106	USGS2116624	1/2 - 1 Mile East
AB107	USGS2116625	1/2 - 1 Mile East

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
X108	USGS2116519	1/2 - 1 Mile West
V109	USGS2116773	1/2 - 1 Mile SW
110	USGS2116513	1/2 - 1 Mile WNW
AC111	USGS2116345	1/2 - 1 Mile WNW
AC112	USGS2116344	1/2 - 1 Mile WNW
Z113	USGS2117407	1/2 - 1 Mile South
AD114	USGS2116972	1/2 - 1 Mile SW
AE115	USGS2116787	1/2 - 1 Mile SW
AE116	USGS2116869	1/2 - 1 Mile SW
AE117	USGS2116870	1/2 - 1 Mile SW
AC118	USGS2116346	1/2 - 1 Mile WNW
AC119	USGS2116387	1/2 - 1 Mile WNW
AF120	USGS2117027	1/2 - 1 Mile SW
AF121	USGS2117026	1/2 - 1 Mile SW
AF122	USGS2117042	1/2 - 1 Mile SW
123	USGS2116566	1/2 - 1 Mile West
124	USGS2116823	1/2 - 1 Mile ESE
Z125	USGS2117255	1/2 - 1 Mile South
Z126	USGS2117256	1/2 - 1 Mile South
AD127	USGS2116934	1/2 - 1 Mile SW
AD128	USGS2116935	1/2 - 1 Mile SW
AG129	USGS2116789	1/2 - 1 Mile WSW
AG130	USGS2116790	1/2 - 1 Mile WSW
131	USGS2116314	1/2 - 1 Mile ENE
AF132	USGS2116990	1/2 - 1 Mile SW
AF133	USGS2116991	1/2 - 1 Mile SW
AH134	USGS2116871	1/2 - 1 Mile SW
AH135	USGS2117043	1/2 - 1 Mile SW
136	USGS2117269	1/2 - 1 Mile SSW
AI137	USGS2116048	1/2 - 1 Mile NNW
138	USGS2117021	1/2 - 1 Mile SE
139	USGS2116868	1/2 - 1 Mile SE
AI140	USGS2116069	1/2 - 1 Mile North
141	USGS2117367	1/2 - 1 Mile South
AJ142	USGS2116082	1/2 - 1 Mile North
AK145	USGS2117317	1/2 - 1 Mile South
AH146	USGS2117028	1/2 - 1 Mile SW
AJ147	USGS2116083	1/2 - 1 Mile North
AK148	USGS2117191	1/2 - 1 Mile SSE
AK149	USGS2117366	1/2 - 1 Mile South
150	USGS2116485	1/2 - 1 Mile West
151	USGS2117282	1/2 - 1 Mile SSW
154	USGS2116528	1/2 - 1 Mile ENE
AL155	USGS2116992	1/2 - 1 Mile SW
AM156	USGS2117303	1/2 - 1 Mile South
AM157	USGS2117304	1/2 - 1 Mile South
AM158	USGS2117305	1/2 - 1 Mile South
AN159	USGS2116114	1/2 - 1 Mile NE
AN160	USGS2116115	1/2 - 1 Mile NE
161	USGS2116774	1/2 - 1 Mile WSW
AO162	USGS2117110	1/2 - 1 Mile SW
AO163	USGS2117111	1/2 - 1 Mile SW

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
164	USGS2116477	1/2 - 1 Mile East
AP165	USGS2117482	1/2 - 1 Mile South
AP166	USGS2117483	1/2 - 1 Mile South
AL167	USGS2117168	1/2 - 1 Mile SW
AL168	USGS2116993	1/2 - 1 Mile SW
AQ169	USGS2116769	1/2 - 1 Mile ESE
AQ170	USGS2116770	1/2 - 1 Mile ESE
171	USGS2116347	1/2 - 1 Mile WNW
172	USGS2117345	1/2 - 1 Mile SSW
AP173	USGS2117473	1/2 - 1 Mile South
AP174	USGS2117474	1/2 - 1 Mile South
AP175	USGS2117472	1/2 - 1 Mile South
176	USGS2117316	1/2 - 1 Mile South

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
G32	NY0002818	1/4 - 1/2 Mile NNE

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
G26	NYWS006244	1/4 - 1/2 Mile NNE
45	NYWS006251	1/4 - 1/2 Mile WNW
AI143	NYWS006211	1/2 - 1 Mile NNW
AI144	NYWS006210	1/2 - 1 Mile NNW
AH152	NYWS006277	1/2 - 1 Mile SW
AH153	NYWS006276	1/2 - 1 Mile SW

PHYSICAL SETTING SOURCE MAP - 2735789.4s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

0 1/4 1/2 1 Miles

- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

N

SITE NAME:	900 Old Country Road	CLIENT:	Roux Associates
ADDRESS:	900 Old Country Road Garden City NY 11530	CONTACT:	Wendy Monterosso
LAT/LONG:	40.7441 / 73.6055	INQUIRY #:	2735789.4s
		DATE:	April 05, 2010 2:04 pm

Copyright © 2010 EDR, Inc. © 2010 Tele Atlas Rel. 07/2007.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
NW
0 - 1/8 Mile
Higher | **FED USGS** | **USGS2116638**

Agency cd:	USGS	Site no:	404441073362402
Site name:	N 1159. 2		
Latitude:	404441	EDR Site id:	USGS2116638
Longitude:	0733624	Dec lat:	40.7448231
Dec lon:	-73.60623907	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 946 2 52	Map scale:	Not Reported
Altitude:	86.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	35.	Hole depth:	35.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1958-06-17	Ground water data end date:	1987-05-19
Ground water data count:	86		

Ground-water levels, Number of Measurements: 86

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-19		65.86	1979-03-20		71.36
1979-03-05		70.74	1978-12-27		68.96
1978-12-06		69.01	1978-11-20		69.03
1978-10-23		69.45	1978-09-25		69.68
1978-09-15		71.01	1978-08-23		70.41
1978-07-26		70.96	1978-06-27		71.77
1978-06-06		71.61	1978-05-30		71.36
1978-03-23		71.57	1977-12-16		69.41
1977-09-08		67.14	1977-06-07		68.62
1977-03-29		68.69	1976-12-03		69.35
1976-09-02		70.33	1976-06-02		71.54
1976-03-17		70.71	1975-12-30		68.82
1975-09-09		68.00	1975-06-10		67.14
1975-03-19		66.71	1974-12-19		65.78
1974-09-16		66.15	1974-06-07		67.32

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1974-03-21		67.09	1973-12-07		66.33
1973-09-19		67.51	1973-06-12		67.94
1973-03-21		66.64	1972-12-21		65.01
1972-09-11		64.08	1972-06-06		60.68
1972-03-24		59.54	1971-12-16		58.80
1971-09-29		58.41	1971-07-15		59.11
1971-03-24		59.86	1970-12-14		59.26
1970-09-17		59.90	1970-06-16		62.50
1970-03-11		60.03	1970-01-20		60.95
1969-09-22		59.50	1969-06-27		59.11
1969-03-25		60.15	1969-01-21		58.93
1968-09-25		58.38	1968-06-21		59.21
1968-03-28		59.48	1967-12-20		59.53
1967-10-04		59.61	1967-07-14		59.41
1967-04-17		58.85	1966-12-20		57.89
1966-09-27		58.22	1966-06-02		59.72
1966-03-02		60.27	1965-11-10		61.16
1965-08-18		62.48	1965-06-04		64.10
1965-03-12		64.63	1964-12-01		65.46
1964-06-22		66.43	1964-03-26		66.74
1963-12-19		67.13	1963-09-14		67.75
1963-06-26		67.41	1963-03-08		69.58
1962-11-28		70.32	1962-07-24		70.24
1962-03-14		70.95	1961-12-19		71.37
1961-10-11		71.64	1961-07-13		71.37
1960-11-17		70.03	1960-06-06		69.34
1959-10-14		69.08	1959-05-07		70.95
1958-11-25		71.57	1958-06-17		72.65

A2
NW
0 - 1/8 Mile
Higher

FED USGS **USGS2116637**

Agency cd:	USGS	Site no:	404441073362401
Site name:	N 1159. 1		
Latitude:	404441	EDR Site id:	USGS2116637
Longitude:	0733624	Dec lat:	40.7448231
Dec lon:	-73.60623907	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 946 2 52	Map scale:	Not Reported
Altitude:	86.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	33.	Hole depth:	33.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1937-09-01	Ground water data end date:	1957-07-24
Ground water data count:	45		

Ground-water levels, Number of Measurements: 45

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1957-07-24		69.70	1957-04-25		71.65
1956-11-26		71.42	1956-04-11		74.10
1955-11-30		73.82	1955-08-25		72.62
1955-03-24		73.24	1954-09-21		71.78
1954-04-21		72.85	1953-09-21		74.61
1953-03-27		73.50	1951-11-27		72.41
1951-11-13		71.24	1951-05-16		72.79
1951-01-02		70.87	1950-09-01		72.19
1950-04-21		72.83	1949-11-03		74.17
1949-06-17		75.62	1949-01-07		75.83
1948-07-16		75.87	1948-04-05		74.11
1947-10-28		71.05	1947-04-10		72.98
1946-09-25		73.88	1946-02-07		73.86
1945-07-09		73.14	1945-03-02		73.99
1944-05-12		73.89	1944-01-24		72.35
1943-05-28		72.39	1942-11-05		71.64
1942-08-26		72.19	1942-07-09		70.97
1941-06-27		72.00	1941-03-19		72.39
1940-12-03		71.98	1940-10-09		72.33
1940-05-11		73.48	1940-04-11		73.12
1940-03-13		72.82	1939-08-22		74.88
1938-09-29		74.92	1938-02-16		71.27
1937-09-01		70.92			

B3
ESE **FED USGS** **USGS2116584**
0 - 1/8 Mile
Higher

Agency cd:	USGS	Site no:	404437073361701
Site name:	N 7005. 1		
Latitude:	404437	EDR Site id:	USGS2116584
Longitude:	0733617	Dec lat:	40.74371199
Dec lon:	-73.60429458	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 946 1	Map scale:	Not Reported
Altitude:	88.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	71.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

A4
NNW
0 - 1/8 Mile
Higher

FED USGS **USGS2116423**

Agency cd:	USGS	Site no:	404442073362401
Site name:	N 9941. 1		
Latitude:	404443	EDR Site id:	USGS2116423
Longitude:	0733625	Dec lat:	40.74537865
Dec lon:	-73.60651685	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 935 2 52	Map scale:	Not Reported
Altitude:	87.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820427
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	50.	Hole depth:	75.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-29
Water quality data end date:	1988-06-02	Water quality data count:	6
Ground water data begin date:	1982-07-16	Ground water data end date:	1993-07-01
Ground water data count:	44		

Ground-water levels, Number of Measurements: 44

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1993-07-01		61.37	1993-03-31		61.83
1992-06-30		61.47	1991-10-23		63.75
1991-06-26		65.03	1991-01-10		64.92
1990-10-31		65.29	1990-08-15		64.56
1990-06-18		64.67	1990-03-26		63.40
1990-02-12		63.60	1990-01-16		63.30
1989-12-05		63.81	1989-10-24		63.43
1989-09-20		62.68	1989-08-15		62.96
1989-07-18		62.84	1989-06-17		62.41
1989-05-18		60.67	1989-04-12		59.55

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1989-03-23		59.00	1989-02-13		59.28
1989-01-13		59.36	1988-12-21		59.25
1988-11-21		58.58	1988-10-21		58.16
1988-10-11		58.28	1988-10-03		58.26
1988-09-19		58.53	1987-08-31		61.19
1987-07-28		61.81	1987-05-19		62.57
1985-05-10		64.77	1984-08-08		67.89
1984-05-01		65.54	1984-04-25		65.49
1984-04-06		64.57	1983-08-31		61.79
1983-08-29		61.81	1983-04-01		61.22
1983-03-31		61.18	1982-12-14		59.94
1982-08-19		61.43	1982-07-16		62.21

A5
NNW
0 - 1/8 Mile
Higher

FED USGS **USGS2116428**

Agency cd:	USGS	Site no:	404443073362401
Site name:	N 9647. 1		
Latitude:	404443	EDR Site id:	USGS2116428
Longitude:	0733625	Dec lat:	40.74537865
Dec lon:	-73.60651685	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 946 2 52	Map scale:	Not Reported
Altitude:	88.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19790406
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	63.	Hole depth:	63.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1979-06-05	Ground water data end date:	1984-05-01
Ground water data count:	17		

Ground-water levels, Number of Measurements: 17

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-05-01		66.54	1983-04-12		62.84
1982-12-14		60.69	1982-09-10		61.90
1982-07-09		64.03	1982-03-22		64.01
1982-01-12		63.67	1981-10-16		62.76
1981-06-08		64.36	1981-03-10		65.65
1980-12-18		66.15	1980-09-05		67.29
1980-05-30		69.66	1980-03-20		67.44
1979-12-10		68.24	1979-09-11		68.38
1979-06-05		69.61			

B6
East
0 - 1/8 Mile
Higher

FED USGS **USGS2116609**

Agency cd:	USGS	Site no:	404439073361401
Site name:	N 3908. 1		
Latitude:	404439	EDR Site id:	USGS2116609
Longitude:	0733614	Dec lat:	40.74426753
Dec lon:	-73.60346121	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported
Altitude:	86.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	46.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

B7
East
0 - 1/8 Mile
Higher

FED USGS **USGS2116610**

Agency cd:	USGS	Site no:	404439073361402
Site name:	N 6951. 1		
Latitude:	404439	EDR Site id:	USGS2116610
Longitude:	0733614	Dec lat:	40.74426753
Dec lon:	-73.60346121	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported
Altitude:	86.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19601227
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	337.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-03-16	Ground water data end date:	1984-04-25
Ground water data count:	7		

Ground-water levels, Number of Measurements: 7

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		64.12	1983-08-31		59.33
1983-03-31		60.49			
1982-08-19		58.08			
Note: A nearby site that taps the same aquifer had been pumped recently.					
1982-08-12		59.14	1982-04-14		62.38
1982-03-16		61.82			

C8
East
1/8 - 1/4 Mile
Higher

FED USGS **USGS2116626**

Agency cd:	USGS	Site no:	404440073361001
Site name:	N 6841. 1		
Latitude:	404438	EDR Site id:	USGS2116626
Longitude:	0733610	Dec lat:	40.74398974
Dec lon:	-73.60235007	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported

Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19600622
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	337.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-14	Ground water data end date:	1982-04-14
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1982-04-14		62.46

C9
East
1/8 - 1/4 Mile
Higher

FED USGS **USGS2116598**

Agency cd:	USGS	Site no:	404438073361002
Site name:	N 10076. 1		
Latitude:	404438	EDR Site id:	USGS2116598
Longitude:	0733610	Dec lat:	40.74398974
Dec lon:	-73.60235007	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported
Altitude:	101.9		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	337.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1983-08-22
Water quality data end date:	1984-04-23	Water quality data count:	2
Ground water data begin date:	1983-03-31	Ground water data end date:	1983-04-14
Ground water data count:	2		

Ground-water levels, Number of Measurements: 2

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-04-14		60.38	1983-03-31		59.86

D10
ENE
1/8 - 1/4 Mile
Higher

FED USGS **USGS2116422**

Agency cd:	USGS	Site no:	404442073361001
Site name:	N 6842. 1		
Latitude:	404442	EDR Site id:	USGS2116422
Longitude:	0733610	Dec lat:	40.74510084
Dec lon:	-73.60235006	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported
Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	158.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-22
Water quality data end date:	1984-04-23	Water quality data count:	2
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

D11
NE
1/8 - 1/4 Mile
Higher

FED USGS **USGS2116465**

Agency cd:	USGS	Site no:	404445073361001
Site name:	N 918. 1		
Latitude:	404445	EDR Site id:	USGS2116465
Longitude:	0733610	Dec lat:	40.74593416
Dec lon:	-73.60235006	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 955 1 89	Map scale:	Not Reported
Altitude:	100.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	126.	Hole depth:	126.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

C12
East
1/8 - 1/4 Mile
Higher

FED USGS **USGS2116597**

Agency cd:	USGS	Site no:	404438073360701
Site name:	N 6998. 1		
Latitude:	404438	EDR Site id:	USGS2116597
Longitude:	0733607	Dec lat:	40.74398974
Dec lon:	-73.60151671	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported
Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	60.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-12	Ground water data end date:	1984-04-25
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		65.06	1983-03-31		60.70
1982-04-14		64.66	1982-04-12		64.60

C13
East **FED USGS** **USGS2116583**
1/8 - 1/4 Mile
Higher

Agency cd:	USGS	Site no:	404437073360701
Site name:	N 6999. 1		
Latitude:	404437	EDR Site id:	USGS2116583
Longitude:	0733607	Dec lat:	40.74371196
Dec lon:	-73.60151672	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported
Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	60.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D14
ENE
1/8 - 1/4 Mile
Higher

FED USGS **USGS2116636**

Agency cd:	USGS	Site no:	404441073360701
Site name:	N 6856. 1		
Latitude:	404441	EDR Site id:	USGS2116636
Longitude:	0733607	Dec lat:	40.74482305
Dec lon:	-73.60151671	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported
Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	62.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

D15
ENE
1/8 - 1/4 Mile
Higher

FED USGS **USGS2116421**

Agency cd:	USGS	Site no:	404442073360701
Site name:	N 6857. 1		
Latitude:	404442	EDR Site id:	USGS2116421
Longitude:	0733607	Dec lat:	40.74510083
Dec lon:	-73.60151671	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 956 1	Map scale:	Not Reported

Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	60.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

16
SSE **FED USGS** **USGS2116685**
1/4 - 1/2 Mile
Higher

Agency cd:	USGS	Site no:	404427073361301
Site name:	N 7019. 1		
Latitude:	404427	EDR Site id:	USGS2116685
Longitude:	0733613	Dec lat:	40.74093425
Dec lon:	-73.60318345	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 958 1	Map scale:	Not Reported
Altitude:	84.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	302.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

E17
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116691**

Agency cd:	USGS	Site no:	404428073363601
Site name:	N 6512. 1		
Latitude:	404428	EDR Site id:	USGS2116691
Longitude:	0733636	Dec lat:	40.74121209
Dec lon:	-73.60957253	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 937 1	Map scale:	Not Reported
Altitude:	84.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	71.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-03-29	Ground water data end date:	1984-04-25
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		62.59	1983-08-31		58.22
1983-03-31		60.48	1982-08-19		57.74
1982-04-14		60.06	1982-03-29		59.58

18
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116837**

Agency cd:	USGS	Site no:	404422073361801
Site name:	N 8332. 1		
Latitude:	404422	EDR Site id:	USGS2116837
Longitude:	0733618	Dec lat:	40.7395454
Dec lon:	-73.60457239	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 948 1	Map scale:	Not Reported
Altitude:	87.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	88.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

E19
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116677**

Agency cd:	USGS	Site no:	404426073363501
Site name:	N 6545. 1		
Latitude:	404426	EDR Site id:	USGS2116677
Longitude:	0733636	Dec lat:	40.74065654
Dec lon:	-73.60957253	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 938 1	Map scale:	Not Reported
Altitude:	85.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	41.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-14	Ground water data end date:	1984-04-25
Ground water data count:	5		

Ground-water levels, Number of Measurements: 5

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		62.46	1983-08-31		58.53
1983-03-31		58.32	1982-08-19		58.12
1982-04-14		59.84			

20
WSW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116542**

Agency cd:	USGS	Site no:	404433073364301
Site name:	N 9961. 1		
Latitude:	404433	EDR Site id:	USGS2116542
Longitude:	0733643	Dec lat:	40.74260097
Dec lon:	-73.61151702	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 927 1	Map scale:	Not Reported
Altitude:	84.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820617
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-11
Water quality data end date:	1984-04-09	Water quality data count:	2
Ground water data begin date:	1982-08-19	Ground water data end date:	1990-04-23
Ground water data count:	14		

Ground-water levels, Number of Measurements: 14

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1990-04-23		60.50	1988-06-02		62.64
1987-07-28		59.03	1987-05-19		59.80
1985-05-10		62.12	1984-08-08		65.60
1984-04-25		62.59	1984-04-09		61.92
1983-08-31		58.31	1983-08-11		58.53
1983-04-14		58.96	1983-03-31		58.55
1982-11-17		57.12	1982-08-19		57.71

F21
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116599**

Agency cd:	USGS	Site no:	404438073364601
Site name:	N 4889. 1		
Latitude:	404438	EDR Site id:	USGS2116599
Longitude:	0733646	Dec lat:	40.74398984
Dec lon:	-73.61235037	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 926 2	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	41.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

F22
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116611**

Agency cd:	USGS	Site no:	404439073364601
Site name:	N 4888. 1		
Latitude:	404439	EDR Site id:	USGS2116611
Longitude:	0733646	Dec lat:	40.74426762
Dec lon:	-73.61235037	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 926 2	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	41.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

F23
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116585**

Agency cd:	USGS	Site no:	404437073364601
Site name:	N 3153. 1		
Latitude:	404437	EDR Site id:	USGS2116585
Longitude:	0733646	Dec lat:	40.74371207
Dec lon:	-73.61235037	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 926 2	Map scale:	Not Reported
Altitude:	87.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	62.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

F24
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116627**

Agency cd:	USGS	Site no:	404440073364601
Site name:	N 4887. 1		
Latitude:	404440	EDR Site id:	USGS2116627
Longitude:	0733646	Dec lat:	40.74454539
Dec lon:	-73.61235037	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 926 2	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	42.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

25
SW
1/4 - 1/2 Mile
Higher | **FED USGS** | **USGS2116846**

Agency cd:	USGS	Site no:	404423073363901
Site name:	N 9960. 1		
Latitude:	404423	EDR Site id:	USGS2116846
Longitude:	0733639	Dec lat:	40.73982323
Dec lon:	-73.6104059	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 938 1	Map scale:	Not Reported
Altitude:	86.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820618
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-11
Water quality data end date:	1984-04-09	Water quality data count:	2
Ground water data begin date:	1982-08-19	Ground water data end date:	1990-04-23
Ground water data count:	13		

Ground-water levels, Number of Measurements: 13

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1990-04-23		60.85	1987-07-28		58.75
1987-05-19		58.60	1985-05-10		61.37
1984-08-08		64.27	1984-04-25		61.96
1984-04-09		61.32	1983-08-31		56.75
1983-08-11		58.28	1983-04-14		58.44
1983-03-31		57.82	1982-11-17		56.65
1982-08-19		57.50			

G26
NNE
1/4 - 1/2 Mile
Higher | **NY WELLS** | **NYWS006244**

Well Id:	NY2902818	System name:	CARLE PLACE WD
System Id:	N-08457	Well name:	WELL 5
Type:	Well	Active?:	Active
County:	NASSAU COUNTY	Latitude:	404457 000
Longitude:	733607 000	Slec_type_:	AC
Agency:	HELLER, ROBERT T		
Address:	CARLE PLACE WATER DISTRICT 578 MINEOLA AVENUE		
City/State/Zip:	CARLE PLACE NY 11514		
Phone:	516-333-0540		

H27
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116429**

Agency cd:	USGS	Site no:	404443073364801
Site name:	N 3154. 1		
Latitude:	404443	EDR Site id:	USGS2116429
Longitude:	0733648	Dec lat:	40.74537871
Dec lon:	-73.61290593	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 926 2	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	72.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

I28
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116799**

Agency cd:	USGS	Site no:	404418073361701
Site name:	N 6994. 1		
Latitude:	404418	EDR Site id:	USGS2116799
Longitude:	0733617	Dec lat:	40.7384343
Dec lon:	-73.60429461	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 949 1	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	270.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-08	Ground water data end date:	1982-08-19
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-08-19		57.10	1982-08-12		57.20
1982-04-14		59.24	1982-04-08		58.97

I29
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116800**

Agency cd:	USGS	Site no:	404418073361702
Site name:	N 6994. 2		
Latitude:	404418	EDR Site id:	USGS2116800
Longitude:	0733617	Dec lat:	40.7384343
Dec lon:	-73.60429461	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 949 1	Map scale:	Not Reported

Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	270.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1985-01-11
Water quality data end date:	1985-01-11	Water quality data count:	1
Ground water data begin date:	1982-04-08	Ground water data end date:	1983-08-31
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		55.54	1983-03-31		57.22
1982-08-19		57.10	1982-08-12		57.20
1982-04-14		59.24	1982-04-08		58.97

I30
SSE **FED USGS** **USGS2116798**
1/4 - 1/2 Mile
Higher

Agency cd:	USGS	Site no:	404418073361601
Site name:	N 10043. 1		
Latitude:	404418	EDR Site id:	USGS2116798
Longitude:	0733616	Dec lat:	40.7384343
Dec lon:	-73.60401683	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 959 1	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1983-08-09
Water quality data end date:	1988-02-25	Water quality data count:	3
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

G31
NNE **FED USGS** **USGS2116386**
1/4 - 1/2 Mile
Higher

Agency cd:	USGS	Site no:	404457073360701
Site name:	N 8457. 1		
Latitude:	404457	EDR Site id:	USGS2116386
Longitude:	0733607	Dec lat:	40.74926742
Dec lon:	-73.60151668	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 954 2	Map scale:	Not Reported
Altitude:	106.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19691209
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	440.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1969-12-02
Water quality data end date:	1984-04-11	Water quality data count:	21
Ground water data begin date:	1982-04-14	Ground water data end date:	1982-04-14
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1982-04-14		64.81

G32
NNE **FRDS PWS** **NY0002818**
1/4 - 1/2 Mile
Higher

PWS ID:	NY0002818		
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	CARLE PLACE WATER DISTRICT 578 MINEOLA AVENUE CARLE PLACE, NY 11514		
Addressee / Facility:	System Owner/Responsible Party HELLER ROBERT T CARLE PLACE WATER DISTRICT 578 MINEOLA AVENUE CARLE PLACE, NY 11514		
Addressee / Facility:	System Owner/Responsible Party HELLER ROBERT T CARLE PLACE WATER DISTRICT 578 MINEOLA AVENUE CARLE PLACE, NY 11514		
Facility Latitude:	40 44 46	Facility Longitude:	073 36 50
Facility Latitude:	40 44 57	Facility Longitude:	073 36 07
Facility Latitude:	40 45 25	Facility Longitude:	073 36 32
City Served:	NORTH HEMPSTEAD (T)		
Treatment Class	Not Reported	Population:	Not Reported

Violations information not reported.

H33
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116640**

Agency cd:	USGS	Site no:	404441073365301
Site name:	N 7186. 1		
Latitude:	404441	EDR Site id:	USGS2116640
Longitude:	0733650	Dec lat:	40.74482317
Dec lon:	-73.61346151	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 926 2	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	322.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1968-08-08
Water quality data end date:	1968-08-08	Water quality data count:	1
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

H34
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116639**

Agency cd:	USGS	Site no:	404441073365101
Site name:	N 2422. 1		
Latitude:	404441	EDR Site id:	USGS2116639
Longitude:	0733651	Dec lat:	40.74482318
Dec lon:	-73.61373929	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 916 2	Map scale:	Not Reported
Altitude:	93.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19570430
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	110.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1962-10-10
Water quality data end date:	1962-10-10	Water quality data count:	1
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

H35
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116431**

Agency cd:	USGS	Site no:	404443073365102
Site name:	N 2527. 1		
Latitude:	404443	EDR Site id:	USGS2116431
Longitude:	0733651	Dec lat:	40.74537872
Dec lon:	-73.61373929	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 916 2	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19490411
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	118.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

H36
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116481**

Agency cd:	USGS	Site no:	404446073365001
Site name:	N 2747. 2		
Latitude:	404446	EDR Site id:	USGS2116481
Longitude:	0733650	Dec lat:	40.74621204
Dec lon:	-73.6134615	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 925 2 52	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Confined single aquifer		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	333.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1954-09-01
Water quality data end date:	1976-10-27	Water quality data count:	33
Ground water data begin date:	1959-02-11	Ground water data end date:	1985-05-10
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		62.87	1984-04-25		63.65
1983-03-31		59.71	1982-08-19		58.26
1982-04-14		61.14	1964-12-21		62.10
1959-02-16		74.72	1959-02-11		76.85

H37
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116482**

Agency cd:	USGS	Site no:	404446073365003
Site name:	N 2747. 1		
Latitude:	404446	EDR Site id:	USGS2116482
Longitude:	0733650	Dec lat:	40.74621204
Dec lon:	-73.6134615	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 925 2 52	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	417.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

H38
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116483**

Agency cd:	USGS	Site no:	404446073365004
Site name:	N 9963. 1		
Latitude:	404446	EDR Site id:	USGS2116483
Longitude:	0733650	Dec lat:	40.74621204
Dec lon:	-73.6134615	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 925 2 52	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820622
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-15
Water quality data end date:	1984-04-16	Water quality data count:	2
Ground water data begin date:	1982-08-12	Ground water data end date:	1984-08-08
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		67.22	1984-04-25		65.13
1984-04-16		64.92	1983-08-15		61.18
1983-03-31		61.06	1982-11-17		59.37
1982-08-19		59.89	1982-08-12		59.61

H39
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116470**

Agency cd:	USGS	Site no:	404445073365107
Site name:	N 8663. 2		
Latitude:	404445	EDR Site id:	USGS2116470
Longitude:	0733651	Dec lat:	40.74593427
Dec lon:	-73.61373929	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 915 2	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	486.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

H40
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116466**

Agency cd:	USGS	Site no:	404445073365101
Site name:	N 2748. 3		
Latitude:	404445	EDR Site id:	USGS2116466
Longitude:	0733651	Dec lat:	40.74593427
Dec lon:	-73.61373929	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 915 2 52	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	515.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1971-10-05
Water quality data end date:	1988-02-09	Water quality data count:	20
Ground water data begin date:	1982-04-08	Ground water data end date:	1997-04-23
Ground water data count:	14		

Ground-water levels, Number of Measurements: 14

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1997-04-23		59.69	1995-05-02		57.26
1994-04-14		59.60	1992-03-31		58.70
1991-04-10		57.16	1990-04-12		56.87
1989-02-15		57.11	1988-05-11		54.74
1985-05-10		62.49	1984-04-25		63.13
1983-03-31		59.27	1982-08-19		55.03
1982-04-14		60.80	1982-04-08		60.56

H41
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116467**

Agency cd:	USGS	Site no:	404445073365104
Site name:	N 2748. 1		
Latitude:	404445	EDR Site id:	USGS2116467
Longitude:	0733651	Dec lat:	40.74593427
Dec lon:	-73.61373929	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 915 2 52	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	551.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1948-11-20	Ground water data end date:	1964-12-20
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1964-12-20		62.22	1959-02-11		69.71
1948-12-24		73.00	1948-12-18		73.00
1948-12-11		73.10	1948-12-04		73.20
1948-11-27		73.30	1948-11-20		73.30

H42
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116469**

Agency cd:	USGS	Site no:	404445073365106
Site name:	N 8663. 1		
Latitude:	404445	EDR Site id:	USGS2116469
Longitude:	0733651	Dec lat:	40.74593427
Dec lon:	-73.61373929	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 915 2	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	567.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

H43
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116468**

Agency cd:	USGS	Site no:	404445073365105
Site name:	N 2748. 2		
Latitude:	404445	EDR Site id:	USGS2116468
Longitude:	0733651	Dec lat:	40.74593427
Dec lon:	-73.61373929	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 915 2 52	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	332.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1948-11-20	Ground water data end date:	1964-12-20
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1964-12-20		62.22	1959-02-11		69.71
1948-12-24		73.00	1948-12-18		73.00
1948-12-11		73.10	1948-12-04		73.20
1948-11-27		73.30	1948-11-20		73.30

J44
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116838**

Agency cd:	USGS	Site no:	404422073364401
Site name:	N 8458. 1		
Latitude:	404422	EDR Site id:	USGS2116838
Longitude:	0733644	Dec lat:	40.73954547
Dec lon:	-73.61179483	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 928 1	Map scale:	Not Reported

Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19681202
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	350.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-09
Water quality data end date:	1984-08-07	Water quality data count:	4
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

45
WNW
1/4 - 1/2 Mile
Higher

NY WELLS **NYWS006251**

Well Id:	NY2902818	System name:	CARLE PLACE WD
System Id:	N-02748	Well name:	WELL 2
Type:	Well	Active?:	Active
County:	NASSAU COUNTY	Latitude:	404446 000
Longitude:	733650 000	Slec_type_:	AC
Agency:	HELLER, ROBERT T		
Address:	CARLE PLACE WATER DISTRICT 578 MINEOLA AVENUE		
City/State/Zip:	CARLE PLACE NY 11514		
Phone:	516-333-0540		

J46
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116815**

Agency cd:	USGS	Site no:	404419073364304
Site name:	N 5484. 3		
Latitude:	404420	EDR Site id:	USGS2116815
Longitude:	0733644	Dec lat:	40.73898992
Dec lon:	-73.61179483	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 928 1	Map scale:	Not Reported

Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	575.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1982-11-10
Water quality data end date:	1985-05-01	Water quality data count:	10
Ground water data begin date:	1982-03-15	Ground water data end date:	1985-05-10
Ground water data count:	5		

Ground-water levels, Number of Measurements: 5

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		59.52	1984-04-25		59.03
1983-03-31		56.27	1982-04-14		57.92
1982-03-15		56.47			

J47
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116825**

Agency cd:	USGS	Site no:	404420073364401
Site name:	N 9956. 1		
Latitude:	404420	EDR Site id:	USGS2116825
Longitude:	0733644	Dec lat:	40.73898992
Dec lon:	-73.61179483	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 928 1	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820621
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count: 0
Water quality data begin date: 1983-08-05
Water quality data end date: 1984-04-16
Water quality data count: 2
Ground water data begin date: 1982-06-22
Ground water data end date: 1985-05-10
Ground water data count: 49

Ground-water levels, Number of Measurements: 49

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		60.85	1984-08-08		63.82
1984-04-25		61.18	1984-04-16		60.83
1983-09-12		57.10	1983-08-31		57.48
1983-08-05		58.06	1983-07-14		58.66
1983-06-30		58.97	1983-06-30		58.97
1983-06-22		59.13	1983-06-10		59.44
1983-06-01		59.48	1983-05-25		59.33
1983-05-23		59.37	1983-05-13		59.28
1983-05-04		59.09	1983-04-22		58.25
1983-04-18		57.93	1983-04-07		57.33
1983-03-31		57.06	1983-03-22		56.67
1983-03-15		56.44	1983-03-15		56.44
1983-03-04		56.23	1983-02-18		56.12
1983-02-05		56.00	1983-02-03		56.02
1983-01-26		55.83	1983-01-19		55.87
1983-01-09		55.74	1982-12-20		55.90
1982-12-18		55.85	1982-12-08		55.94
1982-11-22		56.16	1982-11-17		56.22
1982-11-01		56.44	1982-10-27		56.41
1982-10-19		56.41	1982-10-12		56.44
1982-10-09		56.38	1982-10-07		56.45
1982-09-28		56.58	1982-09-06		56.79
1982-09-05		56.73	1982-08-31		56.85
1982-08-19		56.93			
Note: A nearby site that taps the same aquifer was being pumped.					
1982-08-10		57.09	1982-06-22		58.36

J48
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116824**

Agency cd:	USGS	Site no:	404420073364301
Site name:	N 5484. 2		
Latitude:	404419	EDR Site id:	USGS2116824
Longitude:	0733643	Dec lat:	40.73871215
Dec lon:	-73.61151705	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 929 1	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	287.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1965-10-01
Water quality data end date:	1979-04-19	Water quality data count:	24
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

J49
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116814**

Agency cd:	USGS	Site no:	404419073364303
Site name:	N 5484. 1		
Latitude:	404419	EDR Site id:	USGS2116814
Longitude:	0733643	Dec lat:	40.73871215
Dec lon:	-73.61151705	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 929 1	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	323.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K50
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116612**

Agency cd:	USGS	Site no:	404439073365901
Site name:	N 2626. 1		
Latitude:	404438	EDR Site id:	USGS2116612
Longitude:	0733655	Dec lat:	40.74398987
Dec lon:	-73.61485044	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 916 2	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	117.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1962-10-10
Water quality data end date:	1962-10-10	Water quality data count:	1
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

K51
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS2116600**

Agency cd:	USGS	Site no:	404438073365502
Site name:	N 2626. 2		
Latitude:	404438	EDR Site id:	USGS2116600
Longitude:	0733655	Dec lat:	40.74398987
Dec lon:	-73.61485044	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 916 2	Map scale:	Not Reported

Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	150.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

L52
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116550**

Agency cd:	USGS	Site no:	404434073365601
Site name:	N 10299. 1		
Latitude:	404434	EDR Site id:	USGS2116550
Longitude:	0733656	Dec lat:	40.74287878
Dec lon:	-73.61512824	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 917 1	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19850329
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	96.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

L53
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116751**

Agency cd:	USGS	Site no:	404432073365602
Site name:	N 6045. 1		
Latitude:	404432	EDR Site id:	USGS2116751
Longitude:	0733656	Dec lat:	40.74232323
Dec lon:	-73.61512824	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 917 1	Map scale:	Not Reported
Altitude:	97.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19570405
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	328.	Hole depth:	338.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-09
Water quality data end date:	1984-08-07	Water quality data count:	3
Ground water data begin date:	1982-04-10	Ground water data end date:	1983-04-14
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-04-14		56.36	1983-03-31		58.41
1982-04-14		60.06	1982-04-10		59.32

L54
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116752**

Agency cd:	USGS	Site no:	404432073365701
Site name:	N 7406. 1		
Latitude:	404432	EDR Site id:	USGS2116752
Longitude:	0733657	Dec lat:	40.74232324
Dec lon:	-73.61540603	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 917 1	Map scale:	Not Reported
Altitude:	96.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19630307
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	38.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

55
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS2116914**

Agency cd:	USGS	Site no:	404412073363401
Site name:	N 9959. 1		
Latitude:	404412	EDR Site id:	USGS2116914
Longitude:	0733634	Dec lat:	40.73676771
Dec lon:	-73.60901699	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 939 1 44	Map scale:	Not Reported
Altitude:	82.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820617
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-11
Water quality data end date:	1987-10-06	Water quality data count:	4
Ground water data begin date:	1982-08-19	Ground water data end date:	1987-10-06
Ground water data count:	12		

Ground-water levels, Number of Measurements: 12

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-10-06		57.96	1987-07-28		58.94
1987-05-19		58.33	1984-08-08		64.85
1984-04-25		62.39	1984-04-06		61.50
1983-08-31		57.12	1983-08-11		58.04
1983-04-14		59.48	1983-03-31		58.41
1982-11-17		56.77	1982-08-19		57.80

K56
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116613**

Agency cd:	USGS	Site no:	404439073365902
Site name:	N 2627. 2		
Latitude:	404439	EDR Site id:	USGS2116613
Longitude:	0733659	Dec lat:	40.74426765
Dec lon:	-73.61596159	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 916 2	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	179.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

K57
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116430**

Agency cd:	USGS	Site no:	404443073365101
Site name:	N 2627. 1		
Latitude:	404439	EDR Site id:	USGS2116430
Longitude:	0733659	Dec lat:	40.74426765
Dec lon:	-73.61596159	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 916 2	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	58.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

M58
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS2116889**

Agency cd:	USGS	Site no:	404411073361001
Site name:	N 9521. 1		
Latitude:	404411	EDR Site id:	USGS2116889
Longitude:	0733610	Dec lat:	40.73648987
Dec lon:	-73.60235013	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 959 1	Map scale:	Not Reported
Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	636.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

M59
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS2116890**

Agency cd:	USGS	Site no:	404411073361002
Site name:	N 9521. 2		
Latitude:	404411	EDR Site id:	USGS2116890
Longitude:	0733610	Dec lat:	40.73648987
Dec lon:	-73.60235013	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 959 1	Map scale:	Not Reported
Altitude:	80.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	604.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-10
Water quality data end date:	1985-01-10	Water quality data count:	5
Ground water data begin date:	1982-03-15	Ground water data end date:	1985-05-10
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		59.82	1983-03-31		56.71
1982-04-14		58.57	1982-03-15		57.18

N60
WSW **FED USGS** **USGS2116847**
1/2 - 1 Mile
Higher

Agency cd:	USGS	Site no:	404423073365401
Site name:	N 9957. 1		
Latitude:	404423	EDR Site id:	USGS2116847
Longitude:	0733654	Dec lat:	40.73982327
Dec lon:	-73.61457269	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 918 1	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820621
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-05
Water quality data end date:	1984-04-24	Water quality data count:	2
Ground water data begin date:	1982-06-22	Ground water data end date:	1984-09-06
Ground water data count:	133		

Ground-water levels, Number of Measurements: 133

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-09-06		62.66	1984-09-03		62.89
1984-09-01		62.72	1984-08-27		63.04
1984-08-13		63.54	1984-08-11		63.37
1984-08-08		63.50	1984-08-06		63.58
1984-08-02		63.49	1984-07-30		63.49
1984-07-26		63.26	1984-07-21		63.07
1984-07-11		62.74	1984-07-03		62.31
1984-06-29		62.01	1984-06-22		61.76
1984-06-18		61.78	1984-06-13		61.54
1984-06-11		61.64	1984-06-05		61.45
1984-05-29		61.15	1984-05-23		60.90
1984-05-19		61.03	1984-05-08		61.01
1984-05-05		60.82	1984-05-03		60.83
1984-04-25		60.45	1984-04-24		60.40
1984-04-19		60.15	1984-04-18		60.21
1984-04-02		59.54	1984-03-21		59.32
1984-03-01		58.91	1984-03-01		58.91
1984-02-17		58.89	1984-01-30		59.12
1984-01-28		59.04	1984-01-25		59.26
1984-01-14		59.06	1984-01-11		59.21
1984-01-08		58.88	1984-01-05		59.06
1984-01-02		58.93	1983-12-30		58.75
1983-12-24		58.50	1983-12-14		58.20
1983-12-02		57.88	1983-11-25		57.71
1983-11-12		57.43	1983-11-03		57.22
1983-10-23		56.83	1983-10-17		56.88
1983-10-15		56.74	1983-10-12		56.81
1983-10-06		56.59	1983-10-03		56.68
1983-09-27		56.48	1983-09-26		56.63
1983-09-22		56.48	1983-09-18		56.65
1983-09-12		56.66	1983-09-05		56.97
1983-08-31		57.09	1983-08-22		57.34
1983-08-15		57.45	1983-08-12		57.21
1983-08-05		57.39	1983-08-01		57.60
1983-07-25		57.83	1983-07-19		57.81
1983-07-14		58.08	1983-07-08		58.35
1983-07-04		58.45	1983-06-22		58.73
1983-06-20		58.79	1983-06-18		58.64
1983-06-13		59.04	1983-06-06		58.95
1983-05-31		58.84	1983-05-24		58.53
1983-05-23		58.61	1983-05-17		58.54
1983-05-09		58.34	1983-04-29		57.82
1983-04-22		57.41	1983-04-14		56.86
1983-04-08		56.60	1983-03-31		56.29
1983-03-22		55.96	1983-03-15		55.79
1983-03-15		55.77	1983-03-11		55.69
1983-03-03		55.66	1983-02-27		55.66
1983-02-25		55.64	1983-02-20		55.54
1983-02-18		55.60	1983-02-16		55.47
1983-01-25		55.19	1983-01-19		55.26
1983-01-15		55.13	1983-01-07		55.13
1983-01-02		55.25	1982-12-31		55.12
1982-12-26		55.27	1982-12-22		55.19
1982-12-20		55.26	1982-12-18		55.18
1982-12-10		55.08	1982-11-30		55.29

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-11-22		55.37	1982-11-17		55.41
1982-11-13		55.46	1982-11-08		55.73
1982-11-06		55.57	1982-11-01		55.87
1982-10-27		55.80	1982-10-25		55.88
1982-10-22		55.80	1982-10-11		56.09
1982-10-09		55.91	1982-09-28		56.16
1982-09-25		56.13	1982-09-20		56.31
1982-09-15		56.17	1982-09-13		56.17
1982-09-07		56.06	1982-09-01		55.71
1982-08-31		55.85	1982-08-25		55.57
1982-08-19		55.76	1982-08-16		55.85
1982-06-22		57.34			

N61
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116848**

Agency cd:	USGS	Site no:	404423073365502
Site name:	N 5485. 2		
Latitude:	404423	EDR Site id:	USGS2116848
Longitude:	0733655	Dec lat:	40.73982327
Dec lon:	-73.61485047	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 918 1	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	278.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1980-02-27
Water quality data end date:	1983-01-13	Water quality data count:	7
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

N62
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116849**

Agency cd:	USGS	Site no:	404423073365503
Site name:	N 5485. 3		
Latitude:	404423	EDR Site id:	USGS2116849
Longitude:	0733655	Dec lat:	40.73982327
Dec lon:	-73.61485047	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 918 1	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	557.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-09-07
Water quality data end date:	1985-05-01	Water quality data count:	6
Ground water data begin date:	1982-03-15	Ground water data end date:	1985-05-10
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		59.65	1984-04-25		59.39
1983-08-31		48.73	1983-03-31		56.18
1982-04-14		57.85	1982-03-15		56.40

N63
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116856**

Agency cd:	USGS	Site no:	404424073365301
Site name:	N 5485. 1		
Latitude:	404423	EDR Site id:	USGS2116856
Longitude:	0733655	Dec lat:	40.73982327
Dec lon:	-73.61485047	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 918 1	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	323.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1965-10-01
Water quality data end date:	1979-04-19	Water quality data count:	24
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

64
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116933**

Agency cd:	USGS	Site no:	404413073364701
Site name:	N 5507. 1		
Latitude:	404413	EDR Site id:	USGS2116933
Longitude:	0733647	Dec lat:	40.73704552
Dec lon:	-73.6126282	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 929 1	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	330.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-03
Water quality data end date:	1984-08-07	Water quality data count:	3
Ground water data begin date:	1982-03-16	Ground water data end date:	1984-04-25
Ground water data count:	5		

Ground-water levels, Number of Measurements: 5

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		59.73	1983-04-14		54.86
1983-03-31		55.63	1982-04-14		57.34
1982-03-16		56.57			

O65
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116736**

Agency cd:	USGS	Site no:	404431073370301
Site name:	N 9951. 1		
Latitude:	404431	EDR Site id:	USGS2116736
Longitude:	0733703	Dec lat:	40.74204548
Dec lon:	-73.61707274	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 907 1 14	Map scale:	Not Reported
Altitude:	95.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820615
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	55.	Hole depth:	55.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-02
Water quality data end date:	1983-10-18	Water quality data count:	4
Ground water data begin date:	1982-08-19	Ground water data end date:	1983-10-18
Ground water data count:	7		

Ground-water levels, Number of Measurements: 7

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-10-18		57.83	1983-08-31		58.16
1983-08-02		58.66	1983-04-14		57.95
1983-03-31		57.40	1982-11-17		56.49
1982-08-19		57.18			

O66
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116737**

Agency cd:	USGS	Site no:	404431073370302
Site name:	N 9951. 2		
Latitude:	404431	EDR Site id:	USGS2116737
Longitude:	0733703	Dec lat:	40.74204548
Dec lon:	-73.61707274	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 907 1 14	Map scale:	Not Reported
Altitude:	95.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19831221
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	44.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-04-30
Water quality data end date:	1984-04-30	Water quality data count:	1
Ground water data begin date:	1984-04-25	Ground water data end date:	1987-05-20
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-20		59.36	1984-08-08		64.51
1984-04-30		61.97	1984-04-25		61.80

P67
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116484**

Agency cd:	USGS	Site no:	404446073370401
Site name:	N 3649. 1		
Latitude:	404446	EDR Site id:	USGS2116484
Longitude:	0733704	Dec lat:	40.74621208
Dec lon:	-73.6173505	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 905	Map scale:	Not Reported
Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	304.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q68
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116772**

Agency cd:	USGS	Site no:	404416073365401
Site name:	N 9958. 1		
Latitude:	404416	EDR Site id:	USGS2116772
Longitude:	0733654	Dec lat:	40.73787886
Dec lon:	-73.6145727	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 919 1	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820622
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-05
Water quality data end date:	1984-04-12	Water quality data count:	2
Ground water data begin date:	1982-08-02	Ground water data end date:	1984-09-06
Ground water data count:	123		

Ground-water levels, Number of Measurements: 123

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-09-06		61.96	1984-09-03		62.10
1984-09-01		61.91	1984-08-27		62.20
1984-08-12		62.88	1984-08-10		62.81
1984-08-08		62.77	1984-08-06		63.07
1984-08-02		62.92	1984-07-29		62.99
1984-07-17		62.45	1984-07-15		62.51
1984-07-11		62.30	1984-07-09		62.34
1984-07-03		61.95	1984-06-30		61.45
1984-06-21		61.00	1984-06-18		61.13
1984-06-13		60.75	1984-06-10		60.99
1984-06-05		60.85	1984-05-30		60.45
1984-05-23		60.11	1984-05-18		60.39
1984-05-10		60.35	1984-05-05		60.19
1984-05-03		60.30	1984-04-25		59.83
1984-04-12		59.37	1984-04-02		58.88
1984-03-29		58.82	1984-03-15		58.48
1984-03-01		58.22	1984-02-22		58.06
1984-02-05		58.28	1984-02-02		58.08
1984-01-30		58.32	1984-01-23		58.39
1984-01-08		58.48	1983-12-30		58.18
1983-12-20		57.74	1983-12-02		57.34
1983-11-15		56.96	1983-11-03		55.25
1983-10-06		55.86	1983-10-03		56.01
1983-09-28		55.72	1983-09-25		55.95
1983-09-21		55.55	1983-09-18		55.89
1983-09-12		55.69	1983-08-31		56.07
1983-08-28		56.30	1983-08-15		56.73
1983-08-12		56.47	1983-08-09		56.21
1983-08-05		56.40	1983-08-01		56.82
1983-07-25		57.09	1983-07-19		56.90
1983-07-14		57.18	1983-07-10		57.46
1983-06-22		58.00	1983-06-17		57.89
1983-06-12		58.33	1983-06-08		58.20
1983-06-06		58.35	1983-06-03		58.12
1983-05-30		58.33	1983-05-23		58.11
1983-05-18		58.11	1983-05-12		57.97
1983-05-04		57.74	1983-04-28		57.34
1983-04-22		56.94	1983-04-14		56.38
1983-04-12		56.00	1983-04-08		55.97
1983-04-06		55.71	1983-03-31		55.69

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-03-27		55.47	1983-03-22		55.47
1983-02-18		54.81	1983-01-19		54.58
1983-01-17		54.65	1983-01-10		54.51
1983-01-06		54.68	1983-01-05		54.46
1983-01-02		54.67	1982-12-31		54.47
1982-12-26		54.74	1982-12-20		54.76
1982-12-14		54.59	1982-12-07		54.58
1982-12-02		54.71	1982-11-22		54.78
1982-11-17		54.76	1982-11-14		55.00
1982-11-12		54.83	1982-11-08		55.17
1982-11-04		54.90	1982-10-30		55.26
1982-10-27		55.20	1982-10-25		55.27
1982-10-21		55.20	1982-10-17		55.39
1982-10-14		55.30	1982-10-12		55.47
1982-10-08		55.16	1982-09-28		55.51
1982-09-24		55.48	1982-09-20		55.61
1982-09-16		55.42	1982-09-13		55.59
1982-09-09		55.43	1982-09-07		55.54
1982-09-02		55.25	1982-08-31		55.41
1982-08-25		55.05	1982-08-19		55.24
1982-08-15		55.34	1982-08-10		55.18
1982-08-02		55.52			

69
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116839**

Agency cd:	USGS	Site no:	404422073370001
Site name:	N 8050. 1		
Latitude:	404422	EDR Site id:	USGS2116839
Longitude:	0733700	Dec lat:	40.73954551
Dec lon:	-73.6162394	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 918 1 14	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19660503
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	328.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1983-08-04
Water quality data end date:	1984-08-07	Water quality data count:	3
Ground water data begin date:	1982-04-14	Ground water data end date:	1982-04-14
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1982-04-14		57.40

R70
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116371**

Agency cd:	USGS	Site no:	404455073370001
Site name:	N 3890. 1		
Latitude:	404455	EDR Site id:	USGS2116371
Longitude:	0733700	Dec lat:	40.74871202
Dec lon:	-73.61623934	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 914	Map scale:	Not Reported
Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	33.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-12	Ground water data end date:	1984-04-26
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-26		65.47	1983-03-31		64.94
1982-04-14		62.26	1982-04-12		62.23

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S71
SE
1/2 - 1 Mile
Higher

FED USGS **USGS2116813**

Agency cd:	USGS	Site no:	404419073354501
Site name:	N 6046. 2		
Latitude:	404416	EDR Site id:	USGS2116813
Longitude:	0733548	Dec lat:	40.73787868
Dec lon:	-73.59623882	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 979 1	Map scale:	Not Reported
Altitude:	101.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19561210
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	175.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1965-10-01
Water quality data end date:	1976-09-02	Water quality data count:	13
Ground water data begin date:	1982-04-08	Ground water data end date:	1985-05-10
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		61.39	1983-08-31		58.80
1983-03-31		58.36	1982-08-19		59.43
1982-04-14		60.41	1982-04-08		60.27

S72
SE
1/2 - 1 Mile
Higher

FED USGS **USGS2116771**

Agency cd:	USGS	Site no:	404416073354801
Site name:	N 6046. 1		
Latitude:	404416	EDR Site id:	USGS2116771
Longitude:	0733548	Dec lat:	40.73787868
Dec lon:	-73.59623882	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 979 1	Map scale:	Not Reported
Altitude:	101.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19561210
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	356.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

T73
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116686**

Agency cd:	USGS	Site no:	404427073370401
Site name:	N 9952. 1		
Latitude:	404427	EDR Site id:	USGS2116686
Longitude:	0733704	Dec lat:	40.74093439
Dec lon:	-73.61735054	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 908 1 14	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820615
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-04
Water quality data end date:	1983-10-20	Water quality data count:	2
Ground water data begin date:	1982-08-19	Ground water data end date:	1983-10-20
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-10-20		57.05	1983-08-31		57.41
1983-08-04		57.76	1983-08-02		57.99
1983-04-14		57.21	1983-03-31		56.55
1982-11-17		55.55	1982-08-19		55.99

T74
WSW **FED USGS** **USGS2116687**
1/2 - 1 Mile
Higher

Agency cd:	USGS	Site no:	404427073370402
Site name:	N 9952. 2		
Latitude:	404427	EDR Site id:	USGS2116687
Longitude:	0733704	Dec lat:	40.74093439
Dec lon:	-73.61735054	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 908 1 14	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19831221
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	44.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count: 0
Water quality data begin date: 1984-04-23
Water quality data end date: 1984-04-23
Water quality data count: 1
Ground water data begin date: 1984-04-23
Ground water data end date: 1987-05-20
Ground water data count: 4

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-20		58.74	1984-08-08		63.71
1984-04-25		60.84	1984-04-23		60.73

P75
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116512**

Agency cd: USGS
Site no: 404448073370501
Site name: N 3700. 1
Latitude: 404448
EDR Site id: USGS2116512
Longitude: 0733705
Dec lat: 40.74676763
Dec lon: -73.61762829
Coor meth: M
Coor accr: S
Latlong datum: NAD27
Dec latlong datum: NAD83
District: 36
State: 36
County: 059
Country: US
Land net: Not Reported
Location map: NF 905 2
Map scale: Not Reported
Altitude: 106.0
Altitude method: Level or other surveying method
Altitude accuracy: 0.1
Altitude datum: National Geodetic Vertical Datum of 1929
Hydrologic: Southern Long Island. New York. Area = 1660 sq.mi.
Topographic: Not Reported
Site type: Ground-water other than Spring
Date construction: 19511031
Date inventoried: Not Reported
Mean greenwich time offset: EST
Local standard time flag: N
Type of ground water site: Single well, other than collector or Ranney type
Aquifer Type: Not Reported
Aquifer: GLACIAL AQUIFER,UPPER
Well depth: 73.
Hole depth: Not Reported
Source of depth data: Not Reported
Project number: Not Reported
Real time data flag: 0
Daily flow data begin date: 0000-00-00
Daily flow data end date: 0000-00-00
Daily flow data count: 0
Peak flow data begin date: 0000-00-00
Peak flow data end date: 0000-00-00
Peak flow data count: 0
Water quality data begin date: 1983-08-22
Water quality data end date: 1984-04-18
Water quality data count: 2
Ground water data begin date: 0000-00-00
Ground water data end date: 0000-00-00
Ground water data count: 0

Ground-water levels, Number of Measurements: 0

Q76
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116968**

Agency cd:	USGS	Site no:	404415073365301
Site name:	N 5486. 1		
Latitude:	404415	EDR Site id:	USGS2116968
Longitude:	0733655	Dec lat:	40.73760109
Dec lon:	-73.61485049	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 919 1	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	Not Reported	Hole depth:	321.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1970-07-16
Water quality data end date:	1975-05-23	Water quality data count:	8
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

Q77
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116970**

Agency cd:	USGS	Site no:	404415073365503
Site name:	N 5486. 3		
Latitude:	404415	EDR Site id:	USGS2116970
Longitude:	0733655	Dec lat:	40.73760109
Dec lon:	-73.61485049	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 919 1	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	560.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

Q78
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116971**

Agency cd:	USGS	Site no:	404415073365504
Site name:	N 5486. 4		
Latitude:	404415	EDR Site id:	USGS2116971
Longitude:	0733655	Dec lat:	40.73760109
Dec lon:	-73.61485049	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 919 1	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	LLOYD AQUIFER		
Well depth:	Not Reported	Hole depth:	1023.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q79
SW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS2116969**

Agency cd:	USGS	Site no:	404415073365502
Site name:	N 5486. 2		
Latitude:	404415	EDR Site id:	USGS2116969
Longitude:	0733655	Dec lat:	40.73760109
Dec lon:	-73.61485049	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 919 1	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	263.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

R80
WNW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS2116372**

Agency cd:	USGS	Site no:	404455073370201
Site name:	N 3887. 1		
Latitude:	404455	EDR Site id:	USGS2116372
Longitude:	0733702	Dec lat:	40.74871203
Dec lon:	-73.61679491	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 904	Map scale:	Not Reported

Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	62.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

U81
SSW **FED USGS** **USGS2117015**
1/2 - 1 Mile
Lower

Agency cd:	USGS	Site no:	404404073363101
Site name:	N 9967. 1		
Latitude:	404404	EDR Site id:	USGS2117015
Longitude:	0733631	Dec lat:	40.73454552
Dec lon:	-73.60818364	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1030 1	Map scale:	Not Reported
Altitude:	82.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820617
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1983-08-11
Water quality data end date:	1984-04-09	Water quality data count:	2
Ground water data begin date:	1982-08-19	Ground water data end date:	1998-03-24
Ground water data count:	20		

Ground-water levels, Number of Measurements: 20

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1998-03-24		58.39	1997-03-11		55.81
1996-03-13		54.01	1995-03-14		54.80
1994-03-30		57.61	1993-03-23		57.64
1992-03-16		57.88	1991-03-21		60.98
1990-03-26		59.86	1989-03-14		54.68
1985-05-10		60.49	1984-08-08		64.30
1984-04-25		62.51	1984-04-09		63.03
1983-08-31		57.40	1983-08-11		57.73
1983-04-14		60.49	1983-03-31		58.61
1982-11-17		56.67	1982-08-19		57.57

U82
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS2116979**

Agency cd:	USGS	Site no:	404402073363002
Site name:	N 2418. 2		
Latitude:	404403	EDR Site id:	USGS2116979
Longitude:	0733631	Dec lat:	40.73426775
Dec lon:	-73.60818365	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1030 1	Map scale:	Not Reported
Altitude:	81.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19470806
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	59.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-14	Ground water data end date:	1984-04-25
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		62.01	1983-08-31		57.16
1983-03-31		57.84	1982-08-19		57.43
1982-08-12		57.63	1982-04-14		57.26

V83
WSW **FED USGS** **USGS2116857**
1/2 - 1 Mile
Higher

Agency cd:	USGS	Site no:	404424073365602
Site name:	N 8666. 1		
Latitude:	404418	EDR Site id:	USGS2116857
Longitude:	0733702	Dec lat:	40.73843443
Dec lon:	-73.61679498	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	88.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19720318
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	67.	Hole depth:	70.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-08
Water quality data end date:	1984-04-24	Water quality data count:	2
Ground water data begin date:	1982-03-16	Ground water data end date:	1984-08-08
Ground water data count:	14		

Ground-water levels, Number of Measurements: 14

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		64.99	1984-04-25		59.66
1984-04-24		59.63	1983-08-31		58.22
1983-08-08		58.09	1983-04-14		56.06
1983-04-14		56.11	1983-03-31		55.39
1983-03-15		54.80	1982-11-17		54.42
1982-08-19		54.73	1982-08-12		54.86
1982-04-14		57.11	1982-03-16		56.81

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V84
WSW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS2116801**

Agency cd:	USGS	Site no:	404418073370201
Site name:	N 9311. 1		
Latitude:	404418	EDR Site id:	USGS2116801
Longitude:	0733702	Dec lat:	40.73843443
Dec lon:	-73.61679498	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19780912
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	229.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-08
Water quality data end date:	1985-04-30	Water quality data count:	8
Ground water data begin date:	1982-03-16	Ground water data end date:	1984-04-25
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		59.86	1983-04-14		52.89
1983-03-31		55.24			
1982-08-19		13.80			
Note: The site was being pumped.					
1982-04-14		56.91	1982-03-16		55.45

U85
South
1/2 - 1 Mile
Lower | **FED USGS** | **USGS2117016**

Agency cd:	USGS	Site no:	404404073363201
Site name:	N 2418. 1		
Latitude:	404402	EDR Site id:	USGS2117016
Longitude:	0733630	Dec lat:	40.73398997
Dec lon:	-73.60790586	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1030 1	Map scale:	Not Reported
Altitude:	81.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	55.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1962-10-15
Water quality data end date:	1966-07-14	Water quality data count:	2
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

W86
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116831**

Agency cd:	USGS	Site no:	404421073370501
Site name:	N 9953. 1		
Latitude:	404421	EDR Site id:	USGS2116831
Longitude:	0733705	Dec lat:	40.73926776
Dec lon:	-73.61762833	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 908 1 14	Map scale:	Not Reported
Altitude:	94.2		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820614
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-04
Water quality data end date:	1984-04-30	Water quality data count:	2
Ground water data begin date:	1982-08-19	Ground water data end date:	1987-07-28
Ground water data count:	12		

Ground-water levels, Number of Measurements: 12

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-07-28		58.36	1987-05-20		58.64
1984-08-08		64.28	1984-04-30		60.58
1984-04-25		60.10	1983-08-31		57.88
1983-08-04		58.02	1983-04-14		56.44
1983-03-31		55.83	1983-03-15		55.21
1982-11-17		54.84	1982-08-19		55.07

87
SSW **FED USGS** **USGS2117167**
1/2 - 1 Mile
Lower

Agency cd:	USGS	Site no:	404401073363401
Site name:	N 2419. 1		
Latitude:	404402	EDR Site id:	USGS2117167
Longitude:	0733636	Dec lat:	40.73398999
Dec lon:	-73.60957258	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1030 1	Map scale:	Not Reported
Altitude:	81.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19470902
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	58.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count: 0
Water quality data begin date: 0000-00-00
Water quality data end date: 0000-00-00
Water quality data count: 0
Ground water data begin date: 1982-12-02
Ground water data end date: 1983-08-31
Ground water data count: 3

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		56.85	1983-03-31		57.06
1982-12-02		55.18			

X88
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116450**

Agency cd: USGS
Site no: 404444073371202
Site name: N 9025. 1
Latitude: 404444
EDR Site id: USGS2116450
Longitude: 0733712
Dec lat: 40.74565655
Dec lon: -73.6195728
Coor meth: M
Coor accr: S
Latlong datum: NAD27
Dec latlong datum: NAD83
District: 36
State: 36
County: 059
Country: US
Land net: Not Reported
Location map: NF 906 2
Map scale: Not Reported
Altitude: 94.0
Altitude method: Level or other surveying method
Altitude accuracy: 0.1
Altitude datum: National Geodetic Vertical Datum of 1929
Hydrologic: Southern Long Island. New York. Area = 1660 sq.mi.
Topographic: Not Reported
Site type: Ground-water other than Spring
Date construction: Not Reported
Date inventoried: Not Reported
Mean greenwich time offset: EST
Local standard time flag: N
Type of ground water site: Single well, other than collector or Ranney type
Aquifer Type: Not Reported
Aquifer: GLACIAL AQUIFER,UPPER
Well depth: 62.
Hole depth: Not Reported
Source of depth data: Not Reported
Project number: Not Reported
Real time data flag: Not Reported
Daily flow data begin date: Not Reported
Daily flow data end date: Not Reported
Daily flow data count: Not Reported
Peak flow data begin date: Not Reported
Peak flow data end date: Not Reported
Peak flow data count: Not Reported
Water quality data begin date: Not Reported
Water quality data end date: Not Reported
Water quality data count: Not Reported
Ground water data begin date: Not Reported
Ground water data end date: Not Reported
Ground water data count: Not Reported

Ground-water levels, Number of Measurements: 0

X89
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116449**

Agency cd:	USGS	Site no:	404444073371201
Site name:	N 9024. 1		
Latitude:	404444	EDR Site id:	USGS2116449
Longitude:	0733712	Dec lat:	40.74565655
Dec lon:	-73.6195728	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 906 2	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	70.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

Y90
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116753**

Agency cd:	USGS	Site no:	404432073371201
Site name:	N 9968. 1		
Latitude:	404432	EDR Site id:	USGS2116753
Longitude:	0733712	Dec lat:	40.74232328
Dec lon:	-73.61957282	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 907 1 14	Map scale:	Not Reported
Altitude:	109.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820622
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-08-15	Ground water data end date:	1982-08-19
Ground water data count:	3		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-08-19		57.23	1982-08-18		57.24
1982-08-15		58.66			

Y91
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116754**

Agency cd:	USGS	Site no:	404432073371202
Site name:	N 9968. 2		
Latitude:	404432	EDR Site id:	USGS2116754
Longitude:	0733712	Dec lat:	40.74232328
Dec lon:	-73.61957282	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 907 1 14	Map scale:	Not Reported
Altitude:	109.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19821115
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	68.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-15
Water quality data end date:	1985-03-22	Water quality data count:	3
Ground water data begin date:	1982-11-17	Ground water data end date:	1987-07-28
Ground water data count:	9		

Ground-water levels, Number of Measurements: 9

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-07-28		58.78	1987-05-20		59.36
1984-08-08		64.85	1984-04-25		61.92
1984-04-06		60.89	1983-08-31		58.12
1983-04-14		57.88	1983-03-31		57.24
1982-11-17		56.59			

X92
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116472**

Agency cd:	USGS	Site no:	404445073371202
Site name:	N 9027. 1		
Latitude:	404445	EDR Site id:	USGS2116472
Longitude:	0733712	Dec lat:	40.74593433
Dec lon:	-73.61957279	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 905 2	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	60.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

X93
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116471**

Agency cd:	USGS	Site no:	404445073371201
Site name:	N 9026. 1		
Latitude:	404445	EDR Site id:	USGS2116471
Longitude:	0733712	Dec lat:	40.74593433
Dec lon:	-73.61957279	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 905 2	Map scale:	Not Reported
Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	62.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

W94
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116805**

Agency cd:	USGS	Site no:	404418073370604
Site name:	N 7306. 4		
Latitude:	404420	EDR Site id:	USGS2116805
Longitude:	0733707	Dec lat:	40.73898999
Dec lon:	-73.61818391	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 908 1 14	Map scale:	Not Reported
Altitude:	92.4		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	51.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1968-03-25	Ground water data end date:	1987-05-20
Ground water data count:	67		

Ground-water levels, Number of Measurements: 67

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-20		50.62	1987-05-20		50.70
1984-05-07		59.75	1984-04-25		59.04
1983-08-31		59.43	1983-04-14		55.58
1983-04-12		56.47	1983-03-31		55.55
1983-03-15		56.05	1983-03-07		56.59
1983-01-05		55.04	1981-10-19		59.19
1981-06-08		59.45	1981-03-11		59.50
1980-12-18		59.38	1980-09-03		61.89
1980-05-30		63.80	1980-03-21		62.53
1979-12-04		62.20	1979-09-14		62.37
1979-05-23		62.56	1979-04-18		62.40
1979-03-20		61.87	1979-03-09		60.72
1978-12-27		58.37	1978-12-06		57.54
1978-08-23		64.14	1978-07-26		67.42
1978-06-27		63.31	1978-06-08		61.49
1978-05-30		61.38	1978-03-24		61.77
1977-12-19		59.69	1977-09-09		59.07
1977-06-08		58.06	1977-03-25		58.07
1976-12-06		59.39	1976-09-09		60.03
1976-06-09		61.65	1976-03-11		60.89
1975-12-15		60.30	1975-09-03		57.62
1975-06-17		57.08	1975-03-24		56.89
1974-12-27		56.55	1974-09-16		55.88
1974-06-19		57.92	1974-03-29		57.88
1973-12-10		57.31	1973-09-24		58.04
1973-06-20		58.77	1973-03-23		57.73
1972-06-08		54.67	1972-03-22		53.89
1971-12-28		53.68	1971-09-23		52.21
1971-06-03		53.65	1971-03-17		53.89
1970-12-04		53.62	1970-09-10		53.77
1970-06-11		55.05	1970-03-04		55.42
1970-01-16		53.80	1969-09-19		54.05
1969-04-14		54.35	1968-09-24		53.17
1968-03-25		54.32			

V95
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116788**

Agency cd:	USGS	Site no:	404417073370501
Site name:	N 9971. 1		
Latitude:	404417	EDR Site id:	USGS2116788
Longitude:	0733705	Dec lat:	40.73815666
Dec lon:	-73.61762834	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19810807
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	40.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-08
Water quality data end date:	1984-08-08	Water quality data count:	2
Ground water data begin date:	1982-04-14	Ground water data end date:	1984-08-08
Ground water data count:	7		

Ground-water levels, Number of Measurements: 7

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		65.37	1984-08-08		66.00
1984-04-25		59.82	1983-08-31		59.64
1983-03-31		55.36	1982-08-19		54.95
1982-04-14		57.19			

V96
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116802**

Agency cd:	USGS	Site no:	404418073370601
Site name:	N 7306. 1		
Latitude:	404418	EDR Site id:	USGS2116802
Longitude:	0733706	Dec lat:	40.73843444
Dec lon:	-73.61790613	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1	Map scale:	Not Reported

Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	32.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1979-09-14	Ground water data end date:	1981-10-19
Ground water data count:	9		

Ground-water levels, Number of Measurements: 9

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1981-10-19		59.19	1981-06-08		59.45
1981-03-11		59.50	1980-12-18		59.38
1980-09-03		61.89	1980-05-30		63.80
1980-03-21		62.53	1979-12-04		62.18
1979-09-14		62.35			

V97
WSW **FED USGS** **USGS2116803**
1/2 - 1 Mile
Higher

Agency cd:	USGS	Site no:	404418073370602
Site name:	N 7306. 2		
Latitude:	404418	EDR Site id:	USGS2116803
Longitude:	0733706	Dec lat:	40.73843444
Dec lon:	-73.61790613	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	41.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-05-22	Ground water data end date:	1961-01-12
Ground water data count:	21		

Ground-water levels, Number of Measurements: 21

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1961-01-12		63.61	1960-06-09		63.73
1959-05-19		65.27	1959-01-02		66.20
1958-05-13		67.32	1957-08-02		63.40
1957-05-08		66.15	1956-12-07		69.36
1956-04-25		69.54	1955-12-09		68.93
1955-08-01		64.49	1955-04-13		67.75
1955-03-23		67.40	1954-09-28		66.30
1954-04-29		67.39	1953-09-29		68.22
1953-04-03		70.36	1952-10-28		68.14
1952-06-23		71.09	1951-12-04		66.60
1951-05-22		68.08			

V98
WSW **FED USGS** **USGS2116804**
1/2 - 1 Mile
Higher

Agency cd:	USGS	Site no:	404418073370603
Site name:	N 7306. 3		
Latitude:	404418	EDR Site id:	USGS2116804
Longitude:	0733706	Dec lat:	40.73843444
Dec lon:	-73.61790613	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1	Map scale:	Not Reported
Altitude:	92.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	40.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1961-09-07	Ground water data end date:	1963-09-26
Ground water data count:	5		

Ground-water levels, Number of Measurements: 5

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1963-09-26		61.28	1962-03-27		64.58
1962-01-11		64.64	1961-10-25		64.93
1961-09-07		65.53			

Z99
South **FED USGS** **USGS2117107**
1/2 - 1 Mile
Higher

Agency cd:	USGS	Site no:	404359073361602
Site name:	N 1160. 3		
Latitude:	404359	EDR Site id:	USGS2117107
Longitude:	0733616	Dec lat:	40.73315661
Dec lon:	-73.60401687	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1051 1 14	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	52.	Hole depth:	52.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1965-09-15	Ground water data end date:	1973-08-14
Ground water data count:	42		

Ground-water levels, Number of Measurements: 42

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1973-08-14		60.47	1973-08-07		60.69
1973-07-31		60.93	1973-07-24		61.12
1973-07-17		61.21	1973-07-10		61.19
1973-07-03		60.86	1973-06-26		60.44
1973-06-19		60.24	1973-06-12		60.26
1973-05-05		60.34	1973-03-21		59.22
1972-12-21		58.12	1972-09-11		56.30
1972-06-06		56.88	1972-03-24		56.14
1971-12-16		55.56	1971-09-29		55.53

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1971-07-15		55.36	1971-03-24		56.14
1970-12-14		55.76	1970-09-12		56.74
1970-06-16		57.71	1970-03-09		57.20
1970-02-06		56.76	1969-09-22		56.94
1969-06-27		56.36	1969-03-25		55.95
1969-01-21		56.36	1968-09-25		56.47
1968-06-21		56.94	1968-03-28		56.29
1967-12-20		56.11	1967-10-04		56.46
1967-07-14		56.20	1967-04-17		55.66
1966-12-20		54.73	1966-09-27		55.24
1966-06-01		55.98	1966-03-02		56.36
1965-11-10		56.99	1965-09-15		57.49

Z100
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117106**

Agency cd:	USGS	Site no:	404359073361601
Site name:	N 1160. 2		
Latitude:	404359	EDR Site id:	USGS2117106
Longitude:	0733616	Dec lat:	40.73315661
Dec lon:	-73.60401687	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1051 1 14	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	35.	Hole depth:	35.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1953-04-09	Ground water data end date:	1965-06-04
Ground water data count:	31		

Ground-water levels, Number of Measurements: 31

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1965-06-04		59.67	1965-03-12		60.44
1964-12-01		59.64	1964-06-19		61.85
1964-03-26		62.02	1963-12-19		61.49
1963-09-13		61.46	1963-06-26		62.76
1963-03-08		63.64	1962-11-28		63.51
1962-07-24		63.53	1962-03-14		65.37
1961-12-19		64.04	1961-10-11		65.12
1961-07-13		64.88	1960-11-17		64.01
1960-06-06		63.43	1959-10-14		62.52
1958-04-21		65.97	1957-07-24		63.66
1957-04-25		65.01	1956-11-26		64.39
1956-04-11		67.04	1955-11-30		67.16
1955-07-22		64.15	1955-04-05		66.12
1955-03-24		65.91	1954-09-21		65.27
1954-04-21		65.30	1953-09-24		66.12
1953-04-09		67.34			

Z101
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117109**

Agency cd:	USGS	Site no:	404359073361604
Site name:	N 1160. 5		
Latitude:	404359	EDR Site id:	USGS2117109
Longitude:	0733616	Dec lat:	40.73315661
Dec lon:	-73.60401687	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1051 1	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	58.	Hole depth:	58.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1982-12-01
Water quality data end date:	1984-07-03	Water quality data count:	6
Ground water data begin date:	1975-06-03	Ground water data end date:	1990-04-23
Ground water data count:	61		

Ground-water levels, Number of Measurements: 61

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1990-04-23		59.20	1987-07-28		64.99
1987-05-21		64.32	1984-08-08		64.02
1984-05-01		62.00	1984-04-25		60.94
1984-04-19		60.72	1983-08-31		56.71
1983-08-25		56.89	1983-08-24		58.58
1983-07-06		59.33	1983-04-14		57.05
1983-04-12		57.28	1983-03-31		56.12
1982-12-14		54.85	1982-09-10		56.61
1982-08-19		56.83	1982-07-09		58.17
1982-04-14		57.48	1982-03-22		56.48
1982-03-18		57.16	1982-01-12		57.15
1981-10-16		56.22	1981-06-08		57.78
1981-03-10		58.35	1980-12-17		59.51
1980-09-05		61.02	1980-06-03		62.77
1980-03-20		60.25	1979-12-10		61.30
1979-09-11		62.18	1979-06-06		63.22
1979-04-19		62.73	1979-03-21		63.19
1979-03-05		62.29	1978-12-29		60.12
1978-11-20		59.53	1978-10-24		59.97
1978-09-26		60.26	1978-09-15		61.08
1978-08-23		61.29	1978-07-26		61.57
1978-06-28		62.09	1978-06-05		62.90
1978-06-01		62.76	1978-03-23		62.45
1977-12-16		61.18	1977-09-08		58.45
1977-06-07		59.11	1977-03-29		59.31
1976-12-03		59.81	1976-09-02		61.36
1976-06-02		61.93	1976-06-01		62.00
1976-03-12		62.10	1975-12-30		60.98
1975-12-12		60.81	1975-09-22		59.66
1975-09-09		59.35	1975-06-10		59.07
1975-06-03		58.93			

Z102
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117108**

Agency cd:	USGS	Site no:	404359073361603
Site name:	N 1160. 4		
Latitude:	404359	EDR Site id:	USGS2117108
Longitude:	0733616	Dec lat:	40.73315661
Dec lon:	-73.60401687	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1051 1 14	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	63.	Hole depth:	63.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1973-08-21	Ground water data end date:	1975-05-01
Ground water data count:	50		

Ground-water levels, Number of Measurements: 50

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1975-05-01		58.31	1975-04-01		58.13
1975-03-03		57.93	1975-02-04		57.89
1975-01-07		57.45	1974-12-03		57.22
1974-11-04		57.38	1974-10-01		57.80
1974-09-16		57.86	1974-09-03		57.48
1974-08-06		57.51	1974-07-02		58.48
1974-06-07		58.80	1974-06-04		59.09
1974-05-07		59.05	1974-04-02		59.09
1974-03-26		58.96	1974-03-21		58.73
1974-03-19		58.65	1974-03-12		58.59
1974-03-05		58.64	1974-02-26		58.63
1974-02-19		58.70	1974-02-11		58.86
1974-02-05		58.93	1974-01-29		59.02
1974-01-22		59.06	1974-01-15		59.16
1974-01-08		59.12	1973-12-31		59.10
1973-12-24		58.93	1973-12-18		58.58
1973-12-11		58.44	1973-12-06		58.23
1973-12-04		58.25	1973-11-27		58.28
1973-11-20		58.46	1973-11-13		58.65
1973-11-05		58.81	1973-10-30		58.78
1973-10-23		58.85	1973-10-16		59.03
1973-10-09		59.20	1973-10-02		59.38
1973-09-25		59.52	1973-09-18		59.57
1973-09-11		59.58	1973-09-04		59.78
1973-08-28		60.00	1973-08-21		60.24

AA103
East
1/2 - 1 Mile
Higher

FED USGS **USGS2116480**

Agency cd:	USGS	Site no:	404446073353003
Site name:	N 9406. 3		
Latitude:	404446	EDR Site id:	USGS2116480
Longitude:	0733530	Dec lat:	40.74621182
Dec lon:	-73.59123861	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 995 1	Map scale:	Not Reported
Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	58.	Hole depth:	59.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1991-06-13
Water quality data end date:	1993-11-12	Water quality data count:	4
Ground water data begin date:	1989-12-05	Ground water data end date:	1993-07-01
Ground water data count:	29		

Ground-water levels, Number of Measurements: 29

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1993-07-01		62.40	1993-05-18		63.57
1993-03-22		62.95	1993-01-08		62.73
1992-08-04		61.89	1992-06-30		62.42
1992-05-11		63.35	1992-03-17		63.95
1992-02-04		64.19	1992-01-02		64.42
1991-11-21		64.61	1991-10-23		64.86
1991-09-04		64.90	1991-08-27		65.02
1991-08-02		65.00	1991-06-25		65.97
1991-05-21		66.89	1991-04-26		67.04
1991-03-21		66.85	1991-02-22		67.07
1991-01-10		66.43	1990-10-31		66.44
1990-08-15		66.01	1990-06-19		66.15
1990-06-18		66.13	1990-03-27		65.08
1990-02-12		65.23	1990-01-16		65.43
1989-12-05		65.62			

AA104
East
1/2 - 1 Mile
Higher

FED USGS **USGS2116479**

Agency cd:	USGS	Site no:	404446073353002
Site name:	N 9406. 2		
Latitude:	404446	EDR Site id:	USGS2116479
Longitude:	0733530	Dec lat:	40.74621182
Dec lon:	-73.59123861	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 995 1	Map scale:	Not Reported
Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19781208
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	38.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1978-12-28	Ground water data end date:	1988-11-21
Ground water data count:	12		

Ground-water levels, Number of Measurements: 12

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1988-11-21		64.84	1988-10-21		66.66
1988-10-11		66.67	1988-10-03		66.64
1988-09-19		66.67	1985-05-15		68.34
1985-05-15		68.34	1984-10-16		70.26
1979-05-24		71.71	1979-04-19		71.60
1979-03-21		71.19	1978-12-28		68.40

AA105
East
1/2 - 1 Mile
Higher

FED USGS **USGS2116478**

Agency cd:	USGS	Site no:	404446073353001
Site name:	N 9406. 1		
Latitude:	404446	EDR Site id:	USGS2116478
Longitude:	0733530	Dec lat:	40.74621182
Dec lon:	-73.59123861	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 995 1	Map scale:	Not Reported

Altitude:	104.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	35.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1978-08-02	Ground water data end date:	1978-10-25
Ground water data count:	2		

Ground-water levels, Number of Measurements: 2

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1978-10-25		68.66	1978-08-02		69.57

AB106
East
1/2 - 1 Mile
Higher

FED USGS **USGS2116624**

Agency cd:	USGS	Site no:	404440073352901
Site name:	N 8682. 1		
Latitude:	404440	EDR Site id:	USGS2116624
Longitude:	0733529	Dec lat:	40.74454518
Dec lon:	-73.59096084	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 996 1	Map scale:	Not Reported
Altitude:	103.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	95.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count: 0
Water quality data begin date: 1983-08-24
Water quality data end date: 1983-08-24
Water quality data count: 1
Ground water data begin date: 1982-04-12
Ground water data end date: 1983-03-31
Ground water data count: 3

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-03-31		62.78	1982-04-14		64.89
1982-04-12		64.88			

AB107
East
1/2 - 1 Mile
Higher

FED USGS **USGS2116625**

Agency cd: USGS
Site no: 404440073352902
Site name: N 8753. 1
Latitude: 404440
EDR Site id: USGS2116625
Longitude: 0733529
Dec lat: 40.74454518
Dec lon: -73.59096084
Coor meth: M
Coor accr: S
Latlong datum: NAD27
Dec latlong datum: NAD83
District: 36
State: 36
County: 059
Country: US
Land net: Not Reported
Location map: NF 996 1
Map scale: Not Reported
Altitude: 103.0
Altitude method: Level or other surveying method
Altitude accuracy: 0.1
Altitude datum: National Geodetic Vertical Datum of 1929
Hydrologic: Southern Long Island. New York. Area = 1660 sq.mi.
Topographic: Not Reported
Site type: Ground-water other than Spring
Date construction: Not Reported
Date inventoried: Not Reported
Mean greenwich time offset: EST
Local standard time flag: N
Type of ground water site: Single well, other than collector or Ranney type
Aquifer Type: Not Reported
Aquifer: MAGOTHY AQUIFER
Well depth: 110.
Hole depth: Not Reported
Source of depth data: Not Reported
Project number: Not Reported
Real time data flag: 0
Daily flow data begin date: 0000-00-00
Daily flow data end date: 0000-00-00
Daily flow data count: 0
Peak flow data begin date: 0000-00-00
Peak flow data end date: 0000-00-00
Peak flow data count: 0
Water quality data begin date: 1983-08-24
Water quality data end date: 1984-05-10
Water quality data count: 2
Ground water data begin date: 1982-03-25
Ground water data end date: 1983-03-31
Ground water data count: 4

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-03-31		62.81	1982-04-14		64.88
1982-04-12		64.85	1982-03-25		66.21

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

X108
West
1/2 - 1 Mile
Higher | **FED USGS** | **USGS2116519**

Agency cd:	USGS	Site no:	404449073370701
Site name:	N 3699. 1		
Latitude:	404446	EDR Site id:	USGS2116519
Longitude:	0733713	Dec lat:	40.7462121
Dec lon:	-73.61985058	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 995 2 52	Map scale:	Not Reported
Altitude:	107.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19511031
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	89.	Hole depth:	94.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1962-10-10
Water quality data end date:	1988-09-12	Water quality data count:	9
Ground water data begin date:	1982-04-12	Ground water data end date:	1982-04-14
Ground water data count:	2		

Ground-water levels, Number of Measurements: 2

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-04-14		60.74	1982-04-12		60.67

V109
SW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS2116773**

Agency cd:	USGS	Site no:	404416073370501
Site name:	N 9972. 1		
Latitude:	404416	EDR Site id:	USGS2116773
Longitude:	0733705	Dec lat:	40.73787889
Dec lon:	-73.61762834	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19810807
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	40.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-08
Water quality data end date:	1984-08-08	Water quality data count:	2
Ground water data begin date:	1983-03-31	Ground water data end date:	1984-08-08
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		67.87	1984-08-08		68.59
1984-05-08		60.46	1984-04-25		59.49
1983-08-31		61.76			
1983-03-31					

Note: The site was dry (no water level recorded).

110
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116513**

Agency cd:	USGS	Site no:	404448073371201
Site name:	N 8659. 1		
Latitude:	404448	EDR Site id:	USGS2116513
Longitude:	0733713	Dec lat:	40.74676765
Dec lon:	-73.61985057	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 995 2	Map scale:	Not Reported

Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	70.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

AC111
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116345**

Agency cd:	USGS	Site no:	404453073371102
Site name:	N 5666. 1		
Latitude:	404453	EDR Site id:	USGS2116345
Longitude:	0733711	Dec lat:	40.74815651
Dec lon:	-73.61929499	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 905 1	Map scale:	Not Reported
Altitude:	95.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	39.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

AC112
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116344**

Agency cd:	USGS	Site no:	404453073371101
Site name:	N 5665. 1		
Latitude:	404453	EDR Site id:	USGS2116344
Longitude:	0733711	Dec lat:	40.74815651
Dec lon:	-73.61929499	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 905 1	Map scale:	Not Reported
Altitude:	95.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	51.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

Z113
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117407**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency cd:	USGS	Site no:	404342073362601
Site name:	N 1160. 1		
Latitude:	404358	EDR Site id:	USGS2117407
Longitude:	0733619	Dec lat:	40.73287885
Dec lon:	-73.60485023	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1041 1 14	Map scale:	Not Reported
Altitude:	93.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	44.	Hole depth:	44.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1975-07-18
Water quality data end date:	1976-09-01	Water quality data count:	13
Ground water data begin date:	1937-08-31	Ground water data end date:	1951-03-10
Ground water data count:	329		

Ground-water levels, Number of Measurements: 329

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1951-03-10		58.35	1950-09-25		64.32
1950-09-01		65.18	1950-08-29		64.53
1950-08-02		64.55	1950-06-27		64.87
1950-05-23		65.21	1950-04-26		65.35
1950-04-21		65.51	1950-04-03		65.67
1950-02-27		65.61	1950-01-25		64.90
1949-12-28		65.10	1949-11-28		65.31
1949-11-03		65.86	1949-10-28		65.99
1949-09-26		66.38	1949-08-29		66.35
1949-07-26		67.20	1949-06-28		67.80
1949-06-17		68.12	1949-05-31		68.57
1949-04-26		68.47	1949-03-31		68.83
1949-03-02		68.69	1949-01-26		68.31
1949-01-07		67.17	1948-12-28		66.09
1948-12-06		66.29	1948-11-03		66.13
1948-09-29		67.15	1948-08-30		67.59
1948-08-03		68.01	1948-07-16		68.05
1948-07-01		67.62	1948-05-26		67.45
1948-05-07		67.14	1948-04-05		67.15
1948-03-26		66.67	1948-02-25		65.68
1948-02-07		65.09	1947-12-31		64.70
1947-12-06		64.89	1947-11-01		63.97

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1947-10-28		64.16
1947-09-09		64.59
1947-07-02		65.46
1947-04-29		65.57
1947-03-31		64.69
1947-01-31		64.71
1946-11-27		65.37
1946-09-24		66.27
1946-07-29		66.78
1946-07-03		67.21
1946-04-25		66.22
1946-02-26		66.56
1946-02-05		66.85
1945-11-27		65.19
1945-10-02		65.82
1945-08-04		66.35
1945-06-29		66.10
1945-05-04		66.27
1945-03-07		66.70
1945-01-29		66.29
1944-11-27		65.38
1944-09-27		65.79
1944-07-26		65.70
1944-06-01		66.83
1944-04-20		66.64
1944-03-07		65.14
1944-01-24		65.67
1943-11-29		64.93
1943-09-27		64.24
1943-07-31		65.08
1943-05-29		65.75
1943-03-27		66.38
1943-01-02		65.14
1942-12-19		64.91
1942-12-05		65.00
1942-11-21		65.05
1942-11-07		65.14
1942-10-31		65.17
1942-10-17		65.37
1942-10-03		65.52
1942-09-19		65.76
1942-09-05		65.99
1942-08-26		66.08
1942-08-15		65.45
1942-08-01		64.97
1942-07-18		64.46
1942-07-09		64.67
1942-06-27		64.55
1942-06-13		64.66
1942-05-30		64.34
1942-05-16		64.48
1942-05-02		64.64
1942-04-18		64.39
1942-04-04		64.76
1942-03-21		64.31
1947-10-06		64.36
1947-08-05		65.09
1947-05-28		65.75
1947-04-10		65.31
1947-02-28		64.68
1946-12-31		64.91
1946-10-31		65.84
1946-08-29		66.51
1946-07-25		66.27
1946-06-04		66.73
1946-04-03		66.43
1946-02-07		66.71
1945-12-26		65.68
1945-11-02		65.36
1945-09-12		66.06
1945-07-09		66.11
1945-06-01		66.45
1945-03-26		66.63
1945-02-26		66.49
1944-12-26		66.30
1944-10-30		65.42
1944-08-28		65.03
1944-06-26		66.47
1944-05-02		67.25
1944-03-27		65.86
1944-02-07		65.23
1943-12-31		64.50
1943-11-01		64.37
1943-08-30		64.63
1943-06-26		65.61
1943-05-01		66.02
1943-03-01		65.79
1942-12-26		64.87
1942-12-12		63.03
1942-11-28		64.99
1942-11-14		65.11
1942-11-05		65.26
1942-10-24		65.27
1942-10-10		65.55
1942-09-26		65.62
1942-09-12		65.90
1942-08-29		66.00
1942-08-22		65.83
1942-08-08		65.21
1942-07-25		64.45
1942-07-11		64.50
1942-07-06		64.59
1942-06-20		64.68
1942-06-06		64.26
1942-05-23		64.45
1942-05-09		64.57
1942-04-25		64.74
1942-04-11		64.82
1942-03-28		64.59
1942-03-14		64.16

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1942-03-07		64.05
1942-02-21		63.90
1942-02-07		63.56
1942-01-24		63.43
1942-01-10		63.45
1941-12-27		63.74
1941-12-13		63.38
1941-11-29		63.55
1941-11-15		63.71
1941-11-01		63.84
1941-10-18		64.01
1941-10-04		64.21
1941-09-20		64.42
1941-09-06		64.65
1941-08-23		64.66
1941-08-09		64.85
1941-07-26		65.01
1941-07-12		65.14
1941-06-28		65.28
1941-06-21		65.36
1941-06-07		65.16
1941-05-24		65.19
1941-05-10		65.40
1941-04-26		65.54
1941-04-12		65.67
1941-03-29		65.79
1941-03-19		65.87
1941-03-08		65.56
1941-02-22		65.75
1941-02-08		65.23
1941-01-25		65.00
1941-01-11		64.70
1940-12-28		64.77
1940-12-14		64.85
1940-11-30		65.06
1940-11-16		64.98
1940-11-02		64.88
1940-10-19		65.06
1940-10-05		65.24
1940-09-21		65.35
1940-09-07		65.54
1940-08-24		65.63
1940-08-10		65.85
1940-07-27		66.05
1940-07-13		66.22
1940-06-29		66.38
1940-06-15		66.63
1940-06-01		66.56
1940-05-18		66.60
1940-05-04		66.54
1940-04-20		66.08
1940-04-11		65.86
1940-03-30		65.94
1940-03-16		65.77
1940-03-09		65.61
1942-02-28		63.85
1942-02-14		63.76
1942-01-31		63.37
1942-01-17		63.41
1942-01-03		63.61
1941-12-20		63.73
1941-12-06		63.47
1941-11-22		63.60
1941-11-08		63.81
1941-10-25		63.92
1941-10-11		64.13
1941-09-27		64.31
1941-09-13		64.54
1941-08-30		64.78
1941-08-16		64.75
1941-08-02		64.93
1941-07-19		65.08
1941-07-05		65.14
1941-06-27		65.39
1941-06-14		65.11
1941-05-31		65.15
1941-05-17		65.33
1941-05-03		65.46
1941-04-19		65.65
1941-04-05		65.69
1941-03-22		65.82
1941-03-15		65.54
1941-03-01		65.59
1941-02-15		65.71
1941-02-01		64.92
1941-01-18		64.89
1941-01-04		64.76
1940-12-21		64.80
1940-12-07		64.98
1940-11-23		65.11
1940-11-09		64.84
1940-10-26		64.94
1940-10-12		65.17
1940-09-28		65.38
1940-09-14		65.44
1940-08-31		65.65
1940-08-17		65.74
1940-08-03		65.95
1940-07-20		66.14
1940-07-06		66.28
1940-06-22		66.44
1940-06-08		66.67
1940-05-25		66.56
1940-05-11		66.60
1940-04-27		66.28
1940-04-13		65.90
1940-04-06		65.80
1940-03-23		65.94
1940-03-13		65.75
1940-03-02		65.13

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1940-02-24		65.17	1940-02-17		64.88
1940-02-10		65.02	1940-02-03		65.11
1940-01-27		65.25	1940-01-20		65.31
1940-01-13		65.10	1940-01-06		65.23
1939-12-30		65.35	1939-12-23		65.45
1939-12-16		65.58	1939-12-09		65.71
1939-12-02		65.81	1939-11-25		65.89
1939-11-18		66.07	1939-11-11		66.07
1939-11-04		65.79	1939-10-28		65.89
1939-10-21		66.01	1939-10-14		66.13
1939-10-07		66.23	1939-09-30		66.35
1939-09-23		66.50	1939-09-16		66.65
1939-09-09		66.79	1939-09-02		66.91
1939-08-26		67.07	1939-08-22		67.15
1939-08-22		67.15	1939-08-19		66.90
1939-08-12		67.09	1939-08-05		67.29
1939-07-29		67.50	1939-07-22		67.70
1939-07-15		67.99	1939-07-08		68.18
1939-07-01		68.39	1939-06-24		68.61
1939-06-17		68.81	1939-06-10		69.02
1939-06-03		69.26	1939-05-27		69.53
1939-05-20		69.73	1939-05-13		69.98
1939-05-06		70.29	1939-04-29		70.56
1939-04-22		70.74	1939-04-15		70.90
1939-04-08		70.45	1939-03-31		70.08
1939-03-24		70.07	1939-03-17		69.47
1939-03-10		69.24	1939-03-03		68.74
1939-02-24		68.51	1939-02-17		68.46
1939-02-10		68.30	1939-02-03		67.54
1939-01-27		67.25	1939-01-20		67.37
1939-01-13		67.48	1939-01-07		67.52
1938-09-29		69.80	1938-02-16		65.19
1937-08-31		64.60			

AD114
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116972**

Agency cd:	USGS	Site no:	404415073370501
Site name:	N 9973. 1		
Latitude:	404415	EDR Site id:	USGS2116972
Longitude:	0733705	Dec lat:	40.73760112
Dec lon:	-73.61762835	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19810812
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	40.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-08
Water quality data end date:	1984-08-08	Water quality data count:	2
Ground water data begin date:	1982-04-14	Ground water data end date:	1984-08-08
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		64.16	1984-08-08		64.30
1984-05-08		60.06	1984-04-25		59.26
1983-08-31		56.87			
1983-03-31					
Note: The site was dry (no water level recorded).					
1982-08-19					
Note: The site was dry (no water level recorded).					
1982-04-14		55.95			

AE115
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116787**

Agency cd:	USGS	Site no:	404417073370201
Site name:	N 9275. 1		
Latitude:	404410	EDR Site id:	USGS2116787
Longitude:	0733700	Dec lat:	40.73621224
Dec lon:	-73.61623942	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010	Map scale:	Not Reported
Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	239.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

AE116
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116869**

Agency cd:	USGS	Site no:	404410073365901
Site name:	N 9310. 1		
Latitude:	404410	EDR Site id:	USGS2116869
Longitude:	0733700	Dec lat:	40.73621224
Dec lon:	-73.61623942	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010 1 14	Map scale:	Not Reported
Altitude:	86.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19780912
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	230.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-09
Water quality data end date:	1985-04-30	Water quality data count:	4
Ground water data begin date:	1982-04-14	Ground water data end date:	1984-04-25
Ground water data count:	7		

Ground-water levels, Number of Measurements: 7

Date	Feet below Surface	Feet to Sealevel
1984-04-25		58.97
1983-04-14		51.98
1982-08-19		11.88
Note: The site was being pumped.		
1982-08-12		13.99
Note: The site was being pumped.		
1982-04-14		56.10
1983-04-14		51.68
1983-03-31		53.79

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AE117
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116870**

Agency cd:	USGS	Site no:	404410073370101
Site name:	N 9974. 1		
Latitude:	404410	EDR Site id:	USGS2116870
Longitude:	0733701	Dec lat:	40.73621224
Dec lon:	-73.61651721	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010 1 14	Map scale:	Not Reported
Altitude:	88.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19810813
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	35.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-07
Water quality data end date:	1984-08-08	Water quality data count:	2
Ground water data begin date:	1982-04-14	Ground water data end date:	1984-08-08
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		62.62	1984-08-08		62.69
1984-05-07		59.83	1984-04-25		59.31
1983-08-31		55.62			
1983-03-31					
Note: The site was dry (no water level recorded).					
1982-08-19		55.30	1982-04-14		56.25

AC118
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116346**

Agency cd:	USGS	Site no:	404453073371301
Site name:	N 5678. 1		
Latitude:	404453	EDR Site id:	USGS2116346
Longitude:	0733713	Dec lat:	40.74815651
Dec lon:	-73.61985057	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 995 1	Map scale:	Not Reported
Altitude:	95.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	49.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

AC119
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116387**

Agency cd:	USGS	Site no:	404457073371001
Site name:	N 8305. 1		
Latitude:	404453	EDR Site id:	USGS2116387
Longitude:	0733713	Dec lat:	40.74815651
Dec lon:	-73.61985057	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 995 2	Map scale:	Not Reported
Altitude:	105.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19670719
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	60.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1976-08-17
Water quality data end date:	1978-06-29	Water quality data count:	3
Ground water data begin date:	1982-04-08	Ground water data end date:	1984-04-25
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		65.37	1983-03-31		60.62
1982-04-14		61.81	1982-04-08		61.99

AF120
SW
1/2 - 1 Mile
Lower

FED USGS **USGS2117027**

Agency cd:	USGS	Site no:	404406073365703
Site name:	N 10020. 2		
Latitude:	404406	EDR Site id:	USGS2117027
Longitude:	0733657	Dec lat:	40.73510114
Dec lon:	-73.61540607	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010 1 14	Map scale:	Not Reported
Altitude:	83.4		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	200.	Hole depth:	290.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-30
Water quality data end date:	1984-05-09	Water quality data count:	2
Ground water data begin date:	1982-08-03	Ground water data end date:	1984-09-06
Ground water data count:	283		

Ground-water levels, Number of Measurements: 283

Date	Feet below Surface	Feet to Sealevel
1984-09-06		60.10
1984-09-03		59.50
1984-08-28		60.00
1984-08-25		58.60
1984-08-20		60.95
1984-08-17		60.60
1984-08-13		61.25
1984-08-09		61.10
1984-08-08		59.35
1984-08-03		59.20
1984-07-03		59.59
1984-07-01		60.90
1984-06-28		57.77
1984-06-24		58.90
1984-06-18		59.83
1984-06-13		56.30
1984-06-06		60.22
1984-06-03		60.83
1984-05-23		56.40
1984-05-19		58.35
1984-05-08		59.55
1984-05-02		57.50
1984-04-29		58.45
1984-04-26		59.24
1984-04-23		58.45
1984-04-18		56.90
1984-04-15		58.80
1984-04-08		57.66
1984-04-01		57.78
1984-03-24		56.26
1984-03-19		57.73
1984-03-16		56.83
1984-03-05		56.66
1984-03-03		57.17
1984-02-29		56.20
1984-02-27		55.57
1984-02-20		56.57
1984-02-16		55.76
1984-02-13		56.00
1984-02-03		56.75
1984-01-30		56.04
1984-01-26		55.56
1984-01-19		56.86
1984-01-13		56.55
1984-01-09		56.20
1983-12-26		56.20
1983-12-21		55.60
1983-12-06		56.20
1983-12-02		55.31
1983-11-30		55.93
1983-11-08		54.45
1983-11-03		55.33
1983-10-25		55.50
1983-10-14		54.33
1983-10-11		55.09
1984-09-05		58.35
1984-08-30		57.20
1984-08-26		59.95
1984-08-21		58.00
1984-08-19		59.80
1984-08-16		58.00
1984-08-12		60.25
1984-08-09		58.95
1984-08-05		60.70
1984-08-03		61.20
1984-07-02		58.90
1984-06-30		59.92
1984-06-27		60.00
1984-06-21		56.92
1984-06-17		58.45
1984-06-13		59.16
1984-06-03		59.61
1984-05-29		59.92
1984-05-22		59.31
1984-05-09		58.57
1984-05-06		57.15
1984-05-02		59.27
1984-04-26		57.70
1984-04-25		59.16
1984-04-22		58.66
1984-04-16		58.14
1984-04-12		56.83
1984-04-06		56.92
1984-04-01		56.62
1984-03-23		57.20
1984-03-18		56.60
1984-03-13		56.75
1984-03-05		55.87
1984-03-03		56.40
1984-02-29		56.75
1984-02-25		55.92
1984-02-20		55.33
1984-02-15		55.42
1984-02-04		55.75
1984-02-01		55.45
1984-01-27		56.67
1984-01-20		56.52
1984-01-16		55.85
1984-01-12		55.80
1984-01-05		57.15
1983-12-24		56.96
1983-12-14		55.15
1983-12-03		54.94
1983-12-01		54.92
1983-11-23		54.42
1983-11-06		55.25
1983-11-02		54.60
1983-10-17		54.09
1983-10-13		52.70
1983-10-08		53.27

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1983-10-07		54.14
1983-10-05		52.25
1983-09-29		53.31
1983-09-28		53.88
1983-09-23		54.93
1983-09-20		53.51
1983-09-15		52.25
1983-09-12		51.61
1983-09-09		56.15
1983-09-01		55.05
1983-08-30		52.85
1983-08-27		54.06
1983-08-22		55.16
1983-08-18		54.56
1983-08-14		56.08
1983-08-11		52.70
1983-08-10		54.23
1983-08-07		54.66
1983-08-04		54.00
1983-07-22		53.89
1983-07-16		55.50
1983-07-14		55.04
1983-07-12		52.17
1983-07-04		52.60
1983-06-29		54.28
1983-06-28		55.08
1983-06-26		54.70
1983-06-23		54.07
1983-06-20		54.81
1983-06-15		53.12
1983-06-13		56.77
1983-06-09		54.38
1983-06-05		55.95
1983-06-01		57.40
1983-05-25		54.48
1983-05-23		55.71
1983-05-20		54.98
1983-05-17		56.70
1983-05-13		54.54
1983-05-07		56.61
1983-05-01		55.29
1983-04-29		55.55
1983-04-24		55.10
1983-04-19		55.86
1983-04-10		54.55
1983-04-06		54.67
1983-03-28		53.90
1983-03-22		54.00
1983-03-19		53.65
1983-03-15		52.64
1983-03-13		52.95
1983-03-01		53.06
1983-02-19		52.21
1983-02-17		53.04
1983-02-08		53.38
1983-10-06		53.29
1983-10-03		55.33
1983-09-28		51.80
1983-09-25		54.00
1983-09-20		50.78
1983-09-18		54.98
1983-09-12		53.74
1983-09-11		51.90
1983-09-03		52.50
1983-08-31		52.81
1983-08-28		53.08
1983-08-26		51.66
1983-08-19		53.00
1983-08-17		52.02
1983-08-13		54.20
1983-08-10		51.60
1983-08-07		53.26
1983-08-05		51.64
1983-07-24		55.56
1983-07-19		54.45
1983-07-15		52.08
1983-07-14		53.06
1983-07-07		53.85
1983-06-29		54.39
1983-06-29		56.24
1983-06-27		52.95
1983-06-25		56.15
1983-06-23		56.18
1983-06-20		56.80
1983-06-14		55.58
1983-06-12		55.61
1983-06-08		57.40
1983-06-02		54.80
1983-05-28		56.25
1983-05-23		56.82
1983-05-22		55.55
1983-05-19		56.45
1983-05-16		55.48
1983-05-09		55.50
1983-05-03		54.35
1983-04-29		53.95
1983-04-26		56.01
1983-04-22		55.23
1983-04-14		53.91
1983-04-06		53.74
1983-03-31		54.41
1983-03-24		53.17
1983-03-19		52.36
1983-03-17		53.69
1983-03-14		53.68
1983-03-06		52.35
1983-02-21		53.30
1983-02-18		53.04
1983-02-17		52.28
1983-01-29		52.25

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel
1983-01-27		53.15
1983-01-23		51.64
1983-01-19		52.16
1982-12-20		52.45
1982-12-18		53.30
1982-12-09		51.80
1982-12-03		52.00
1982-11-23		51.85
1982-11-18		52.00
1982-11-17		52.12
1982-11-14		53.80
1982-11-09		52.20
1982-11-06		52.99
1982-11-02		53.50
1982-10-30		54.11
1982-10-27		52.86
1982-10-26		52.90
1982-10-19		53.34
1982-10-16		53.67
1982-10-12		52.70
1982-10-10		53.55
1982-10-07		51.21
1982-10-03		54.20
1982-10-01		51.75
1982-09-28		53.75
1982-09-24		54.15
1982-09-18		54.75
1982-09-15		51.50
1982-09-09		52.10
1982-09-08		52.50
1982-09-07		52.27
1982-08-03		56.96
1983-01-24		52.10
1983-01-20		52.89
1982-12-21		53.20
1982-12-18		52.19
1982-12-15		52.95
1982-12-06		51.35
1982-11-23		53.19
1982-11-22		52.86
1982-11-18		53.20
1982-11-15		52.52
1982-11-10		53.40
1982-11-08		52.51
1982-11-06		54.21
1982-11-01		51.88
1982-10-28		53.50
1982-10-26		54.15
1982-10-20		52.52
1982-10-17		54.50
1982-10-14		54.03
1982-10-10		54.35
1982-10-07		53.31
1982-10-07		52.61
1982-10-03		52.87
1982-09-28		52.66
1982-09-27		52.06
1982-09-22		52.77
1982-09-16		54.12
1982-09-10		54.75
1982-09-08		54.55
1982-09-07		53.31
1982-08-19		52.79

AF121
SW
1/2 - 1 Mile
Lower

FED USGS **USGS2117026**

Agency cd:	USGS	Site no:	404406073365702
Site name:	N 9955. 1		
Latitude:	404406	EDR Site id:	USGS2117026
Longitude:	0733657	Dec lat:	40.73510114
Dec lon:	-73.61540607	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010 1 14	Map scale:	Not Reported
Altitude:	83.5		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820611
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-04
Water quality data end date:	1984-04-24	Water quality data count:	2
Ground water data begin date:	1982-07-26	Ground water data end date:	1987-05-19
Ground water data count:	134		

Ground-water levels, Number of Measurements: 134

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-19		56.28	1984-09-06		62.07
1984-08-31		62.17	1984-08-18		62.85
1984-08-08		63.24	1984-08-06		63.46
1984-08-02		63.41	1984-07-30		63.70
1984-07-27		63.15	1984-07-23		63.52
1984-07-17		62.93	1984-07-13		63.24
1984-07-11		63.04	1984-07-08		63.29
1984-07-06		62.80	1984-07-03		62.98
1984-07-02		63.07	1984-06-29		62.79
1984-06-26		62.01	1984-06-23		61.46
1984-06-15		61.68	1984-06-13		61.32
1984-06-09		61.78	1984-06-05		61.76
1984-06-03		61.93	1984-05-29		60.77
1984-05-25		60.89	1984-05-23		60.32
1984-05-11		61.22	1984-05-08		60.38
1984-05-03		60.13	1984-04-25		59.80
1984-04-24		59.76	1984-04-18		59.73
1984-04-02		58.66	1984-03-27		58.29
1984-03-19		58.43	1984-03-12		57.79
1984-03-01		57.88	1984-02-23		57.36
1984-02-07		57.63	1984-02-03		57.43
1984-01-30		57.64	1984-01-23		57.36
1984-01-22		57.49	1984-01-07		57.63
1984-01-03		57.43	1984-01-02		57.84
1983-12-24		57.74	1983-12-19		57.24
1983-12-06		56.98	1983-12-02		57.75
1983-11-30		56.81	1983-11-10		56.27
1983-10-26		56.77	1983-10-23		56.31
1983-10-14		56.58	1983-10-12		56.07
1983-10-06		56.24	1983-10-03		56.37
1983-09-29		55.95	1983-09-24		56.30
1983-09-21		55.74	1983-09-12		56.03
1983-08-31		56.55	1983-08-30		56.56
1983-08-20		56.02	1983-08-18		55.82
1983-08-14		56.17	1983-08-11		56.42
1983-08-04		56.79	1983-07-25		57.47
1983-07-19		57.05	1983-07-14		57.34
1983-07-05		57.75	1983-06-29		58.21
1983-06-28		58.03	1983-06-23		58.49
1983-06-21		58.62	1983-06-16		58.15

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-06-12		58.53	1983-06-06		58.62
1983-05-28		58.37	1983-05-23		58.28
1983-04-22		56.73	1983-04-19		56.74
1983-04-14		56.22	1983-04-11		55.83
1983-04-06		55.48	1983-03-31		55.28
1983-03-26		54.84	1983-03-22		54.96
1983-03-18		54.44	1983-03-15		54.56
1983-03-15		54.61	1983-03-01		53.85
1983-02-23		54.01	1983-02-18		53.86
1983-02-17		53.77	1983-02-07		54.14
1983-01-28		54.02	1983-01-24		53.67
1983-01-19		53.98	1983-01-19		53.97
1983-01-13		54.27	1983-01-06		53.73
1982-12-31		53.85	1982-12-20		54.25
1982-12-18		54.33	1982-12-16		54.04
1982-11-29		54.35	1982-11-22		54.64
1982-11-17		54.92	1982-11-14		55.25
1982-11-13		54.92	1982-11-08		55.32
1982-11-06		55.45	1982-11-02		55.17
1982-10-27		55.41	1982-10-23		55.51
1982-10-21		55.48	1982-10-19		55.59
1982-10-17		55.78	1982-10-08		55.54
1982-10-07		55.64	1982-09-28		55.79
1982-09-28		55.76	1982-09-20		55.87
1982-09-08		56.30	1982-09-07		56.41
1982-09-05		56.51	1982-08-31		56.61
1982-08-19		56.96	1982-07-26		57.20

AF122
SW
1/2 - 1 Mile
Lower

FED USGS **USGS2117042**

Agency cd:	USGS	Site no:	404407073365801
Site name:	N 10020. 1		
Latitude:	404406	EDR Site id:	USGS2117042
Longitude:	0733657	Dec lat:	40.73510114
Dec lon:	-73.61540607	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010 1 14	Map scale:	Not Reported
Altitude:	83.4		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	Not Reported	Hole depth:	290.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

123
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116566**

Agency cd:	USGS	Site no:	404435073371801
Site name:	N 3758. 1		
Latitude:	404435	EDR Site id:	USGS2116566
Longitude:	0733717	Dec lat:	40.74315661
Dec lon:	-73.62096174	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 997 2	Map scale:	Not Reported
Altitude:	110.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	91.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1962-10-10
Water quality data end date:	1970-03-12	Water quality data count:	2
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

124
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS2116823**

Agency cd:	USGS	Site no:	404420073353201
Site name:	N 7957. 1		
Latitude:	404420	EDR Site id:	USGS2116823
Longitude:	0733531	Dec lat:	40.73898972
Dec lon:	-73.59151646	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 998 1	Map scale:	Not Reported
Altitude:	96.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	523.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1966-07-01
Water quality data end date:	1985-02-06	Water quality data count:	36
Ground water data begin date:	1982-04-14	Ground water data end date:	1985-05-10
Ground water data count:	4		

Ground-water levels, Number of Measurements: 4

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		62.21	1983-08-31		58.87
1983-03-31		59.42	1982-04-14		60.69

Z125
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117255**

Agency cd:	USGS	Site no:	404356073361801
Site name:	N 9703. 1		
Latitude:	404356	EDR Site id:	USGS2117255
Longitude:	0733618	Dec lat:	40.7323233
Dec lon:	-73.60457244	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1041 1	Map scale:	Not Reported

Altitude:	87.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	106.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-14
Water quality data end date:	1984-05-14	Water quality data count:	1
Ground water data begin date:	1980-12-17	Ground water data end date:	1984-05-14
Ground water data count:	17		

Ground-water levels, Number of Measurements: 17

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-05-14		59.38	1984-04-25		59.69
1983-08-31		54.63	1983-04-14		55.07
1983-04-12		56.02	1983-03-31		54.99
1982-12-14		53.42	1982-09-10		54.51
1982-08-19		54.84	1982-04-14		56.49
1982-03-22		57.17	1982-03-18		55.94
1982-01-12		55.92	1981-10-16		55.35
1981-06-08		55.64	1981-03-11		57.92
1980-12-17		57.84			

Z126
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117256**

Agency cd:	USGS	Site no:	404356073361802
Site name:	N 9713. 1		
Latitude:	404356	EDR Site id:	USGS2117256
Longitude:	0733618	Dec lat:	40.7323233
Dec lon:	-73.60457244	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1041 1	Map scale:	Not Reported
Altitude:	87.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	218.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-14
Water quality data end date:	1988-09-06	Water quality data count:	3
Ground water data begin date:	1980-12-17	Ground water data end date:	1988-09-06
Ground water data count:	20		

Ground-water levels, Number of Measurements: 20

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1988-09-06		52.15	1987-05-21		55.43
1984-05-14		58.55	1984-04-25		59.01
1983-08-31		53.33	1983-04-14		54.12
1983-04-14		53.68	1983-04-12		55.52
1983-03-31		54.56	1982-12-14		52.73
1982-09-10		53.46	1982-08-19		53.54
1982-04-14		56.27	1982-03-22		55.02
1982-03-18		55.45	1982-01-12		55.15
1981-10-16		55.15	1981-06-08		56.17
1981-03-11		57.71	1980-12-17		57.12

AD127
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116934**

Agency cd:	USGS	Site no:	404413073370701
Site name:	N 9965. 1		
Latitude:	404413	EDR Site id:	USGS2116934
Longitude:	0733707	Dec lat:	40.73704558
Dec lon:	-73.61818392	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820614
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1983-08-04
Water quality data end date:	1983-10-18	Water quality data count:	2
Ground water data begin date:	1983-03-15	Ground water data end date:	1983-12-03
Ground water data count:	37		

Ground-water levels, Number of Measurements: 37

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-12-03		56.34	1983-12-02		56.32
1983-11-19		56.11	1983-11-04		55.86
1983-10-24		55.67	1983-10-18		56.09
1983-10-15		57.21	1983-10-11		56.75
1983-10-08		57.18	1983-10-06		56.83
1983-10-02		56.12	1983-09-30		56.60
1983-09-12		56.38	1983-09-07		57.28
1983-09-03		57.53	1983-08-31		57.36
1983-08-24		57.73	1983-08-18		58.03
1983-08-11		56.84	1983-08-11		56.94
1983-08-08		56.52	1983-08-05		57.05
1983-08-04		57.10	1983-07-28		57.52
1983-07-25		57.18	1983-07-23		57.56
1983-07-18		57.10	1983-07-14		57.62
1983-07-14		57.64	1983-07-11		57.75
1983-07-09		58.36	1983-07-04		57.90
1983-07-03		58.47	1983-06-30		58.34
1983-04-14		55.43	1983-03-31		54.69
1983-03-15		54.09			

AD128
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116935**

Agency cd:	USGS	Site no:	404413073370702
Site name:	N 9965. 2		
Latitude:	404413	EDR Site id:	USGS2116935
Longitude:	0733707	Dec lat:	40.73704558
Dec lon:	-73.61818392	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19831221
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	44.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1984-04-23
Water quality data end date:	1984-04-23	Water quality data count:	1
Ground water data begin date:	1983-12-30	Ground water data end date:	1990-05-03
Ground water data count:	37		

Ground-water levels, Number of Measurements: 37

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1990-05-03		58.60	1984-09-06		63.92
1984-08-30		63.12	1984-08-26		62.67
1984-08-23		64.47	1984-08-20		63.94
1984-08-15		64.78	1984-08-12		64.34
1984-08-09		64.95	1984-08-08		64.95
1984-08-06		64.46	1984-08-03		65.10
1984-08-02		65.17	1984-07-03		63.34
1984-06-29		63.82	1984-06-25		63.09
1984-06-23		63.54	1984-06-19		62.90
1984-06-16		63.34	1984-06-11		62.67
1984-06-09		63.31	1984-06-05		61.77
1984-05-26		62.17	1984-05-05		60.67
1984-05-03		60.14	1984-05-01		60.50
1984-04-25		59.32	1984-04-23		59.21
1984-04-18		59.09	1984-04-02		58.15
1984-03-01		57.47	1984-02-23		57.29
1984-02-16		57.47	1984-01-30		57.69
1984-01-25		57.81	1984-01-09		57.81
1983-12-30		58.40			

AG129
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116789**

Agency cd:	USGS	Site no:	404417073371101
Site name:	N 10095. 1		
Latitude:	404417	EDR Site id:	USGS2116789
Longitude:	0733711	Dec lat:	40.73815668
Dec lon:	-73.61929506	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	99.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19830318
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	66.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1983-09-30
Water quality data end date:	1983-10-19	Water quality data count:	2
Ground water data begin date:	1983-03-31	Ground water data end date:	1983-10-19
Ground water data count:	5		

Ground-water levels, Number of Measurements: 5

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-10-19		55.21	1983-09-30		54.98
1983-08-31		55.27	1983-04-14		54.86
1983-03-31		54.57			

AG130
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116790**

Agency cd:	USGS	Site no:	404417073371102
Site name:	N 10095. 2		
Latitude:	404417	EDR Site id:	USGS2116790
Longitude:	0733711	Dec lat:	40.73815668
Dec lon:	-73.61929506	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 909 1 14	Map scale:	Not Reported
Altitude:	99.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19831221
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	51.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-04-16
Water quality data end date:	1984-04-16	Water quality data count:	1
Ground water data begin date:	1984-04-16	Ground water data end date:	1984-08-08
Ground water data count:	3		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		62.77	1984-04-25		59.41
1984-04-16		59.03			

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

131
ENE
1/2 - 1 Mile
Higher | **FED USGS** | **USGS2116314**

Agency cd:	USGS	Site no:	404451073352601
Site name:	N 5654. 1		
Latitude:	404451	EDR Site id:	USGS2116314
Longitude:	0733526	Dec lat:	40.74760067
Dec lon:	-73.59012746	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 995 2	Map scale:	Not Reported
Altitude:	98.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19560815
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Confined single aquifer		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	340.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1956-05-01
Water quality data end date:	1974-05-31	Water quality data count:	31
Ground water data begin date:	1961-02-14	Ground water data end date:	1984-04-25
Ground water data count:	10		

Ground-water levels, Number of Measurements: 10

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		68.57	1983-08-31		65.05
1983-03-31		64.00	1982-08-19		65.30
1982-08-12		65.43	1982-04-14		66.13
1982-03-15		66.04	1964-12-18		76.36
1964-12-15		50.80	1961-02-14		71.26

AF132
SW
1/2 - 1 Mile
Lower | **FED USGS** | **USGS2116990**

Agency cd:	USGS	Site no:	404403073365801
Site name:	N 10096. 1		
Latitude:	404403	EDR Site id:	USGS2116990
Longitude:	0733658	Dec lat:	40.73426782
Dec lon:	-73.61568387	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010 1 14	Map scale:	Not Reported
Altitude:	82.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19830318
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	56.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-25
Water quality data end date:	1983-08-25	Water quality data count:	1
Ground water data begin date:	1983-03-31	Ground water data end date:	1983-12-02
Ground water data count:	13		

Ground-water levels, Number of Measurements: 13

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-12-02		57.09	1983-11-03		57.02
1983-10-20		57.33	1983-10-06		57.70
1983-09-12		57.30	1983-08-31		57.92
1983-08-25		58.10	1983-08-11		58.04
1983-07-14		58.65	1983-06-29		60.45
1983-05-23		59.54	1983-04-14		56.96
1983-03-31		56.01			

AF133
SW
1/2 - 1 Mile
Lower

FED USGS **USGS2116991**

Agency cd:	USGS	Site no:	404403073366001
Site name:	N 10096. 2		
Latitude:	404403	EDR Site id:	USGS2116991
Longitude:	0733658	Dec lat:	40.73426782
Dec lon:	-73.61568387	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1010 1 14	Map scale:	Not Reported
Altitude:	82.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19831221
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	36.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-01
Water quality data end date:	1984-08-07	Water quality data count:	4
Ground water data begin date:	1984-01-30	Ground water data end date:	1984-08-08
Ground water data count:	14		

Ground-water levels, Number of Measurements: 14

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-08-08		64.43	1984-08-07		64.45
1984-08-02		64.55	1984-07-26		64.33
1984-07-03		64.67	1984-06-05		62.93
1984-05-21		61.29	1984-05-07		61.04
1984-05-03		60.90	1984-05-01		60.50
1984-04-25		60.57	1984-04-02		59.42
1984-03-01		58.90	1984-01-30		58.13

AH134
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116871**

Agency cd:	USGS	Site no:	404410073370401
Site name:	N 10019. 1		
Latitude:	404407	EDR Site id:	USGS2116871
Longitude:	0733704	Dec lat:	40.73537893
Dec lon:	-73.61735057	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1000 1 14	Map scale:	Not Reported
Altitude:	87.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	Not Reported	Hole depth:	300.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

AH135
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2117043**

Agency cd:	USGS	Site no:	404407073370402
Site name:	N 9954. 1		
Latitude:	404407	EDR Site id:	USGS2117043
Longitude:	0733704	Dec lat:	40.73537893
Dec lon:	-73.61735057	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1000 1 14	Map scale:	Not Reported
Altitude:	88.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820611
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-02
Water quality data end date:	1984-07-19	Water quality data count:	12
Ground water data begin date:	1982-07-19	Ground water data end date:	1987-05-19
Ground water data count:	47		

Ground-water levels, Number of Measurements: 47

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-19		56.86	1984-08-08		62.59
1984-08-02		62.71	1984-07-19		62.36
1984-07-03		62.08	1984-06-05		61.03
1984-05-03		59.60	1984-04-25		59.31
1984-04-17		59.06	1984-04-02		58.09
1984-03-01		57.26	1984-01-30		57.21
1983-12-02		56.06	1983-12-01		56.04
1983-11-03		55.63	1983-10-06		55.26
1983-09-12		55.02	1983-08-31		55.61
1983-08-16		55.99	1983-08-16		55.98
1983-08-11		55.33	1983-08-02		55.59
1983-07-14		56.30	1983-06-29		57.04
1983-05-23		57.33	1983-04-22		56.03
1983-04-14		55.40	1983-04-14		55.41
1983-03-31		54.50	1983-03-15		53.79
1983-02-18		53.32	1983-01-19		53.30
1982-12-20		53.56	1982-11-22		53.89
1982-11-17		54.09	1982-11-08		54.48
1982-10-27		54.56	1982-10-19		54.71
1982-10-07		54.68	1982-09-28		54.89
1982-09-08		55.30	1982-09-07		55.41
1982-08-19		55.61	1982-08-03		55.87
1982-07-30		56.02	1982-07-26		55.92
1982-07-19		55.96			

136
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS2117269**

Agency cd:	USGS	Site no:	404357073364101
Site name:	N 8068. 1		
Latitude:	404357	EDR Site id:	USGS2117269
Longitude:	0733646	Dec lat:	40.73260115
Dec lon:	-73.61235045	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1021 1	Map scale:	Not Reported

Altitude:	79.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	291.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-09
Water quality data end date:	1988-06-22	Water quality data count:	3
Ground water data begin date:	1982-04-14	Ground water data end date:	1983-04-14
Ground water data count:	3		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-04-14		51.85	1983-03-31		52.43
1982-04-14		55.64			

AI137
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116048**

Agency cd:	USGS	Site no:	404523073363401
Site name:	N 9940. 1		
Latitude:	404523	EDR Site id:	USGS2116048
Longitude:	0733634	Dec lat:	40.75648962
Dec lon:	-73.60901683	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 931 2 52	Map scale:	Not Reported
Altitude:	107.5		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820408
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	53.	Hole depth:	53.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1984-04-10
Water quality data end date:	1988-05-10	Water quality data count:	5
Ground water data begin date:	1983-04-01	Ground water data end date:	1996-12-11
Ground water data count:	45		

Ground-water levels, Number of Measurements: 45

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1996-12-11		62.37	1996-09-10		61.11
1995-12-05		59.59	1995-06-13		61.33
1994-12-14		62.75	1994-06-07		64.88
1993-12-29		63.41	1993-06-22		65.54
1993-03-31		65.58	1992-12-03		64.85
1992-06-30		65.49	1992-06-03		65.88
1991-10-31		67.78	1991-10-23		67.73
1991-06-26		68.52	1991-01-10		68.31
1990-10-31		68.54	1990-08-15		68.19
1990-06-18		68.66	1990-03-27		67.22
1990-02-12		67.29	1990-01-16		67.31
1989-12-05		67.31	1989-10-24		66.47
1989-09-20		66.11	1989-08-15		66.08
1989-07-18		65.93	1989-06-17		65.23
1989-05-18		63.34	1989-04-12		62.21
1989-03-23		61.88	1989-02-13		62.10
1989-01-13		62.27	1988-12-21		62.44
1988-11-21		61.87	1988-10-21		61.63
1988-10-11		61.71	1988-10-03		61.67
1988-09-15		61.76	1987-08-31		64.63
1985-05-10		68.88	1984-04-25		69.33
1984-04-10		68.34	1983-08-31		65.87
1983-04-01		64.68			

138
SE
1/2 - 1 Mile
Higher

FED USGS **USGS2117021**

Agency cd:	USGS	Site no:	404405073352701
Site name:	N 1696. 1		
Latitude:	404407	EDR Site id:	USGS2117021
Longitude:	0733538	Dec lat:	40.73537869
Dec lon:	-73.59346098	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1080 1	Map scale:	Not Reported
Altitude:	97.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19420104
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	472.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1952-10-28
Water quality data end date:	1971-05-26	Water quality data count:	16
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

139
SE
1/2 - 1 Mile
Higher

FED USGS **USGS2116868**

Agency cd:	USGS	Site no:	404410073353401
Site name:	N 12295. 1		
Latitude:	404410	EDR Site id:	USGS2116868
Longitude:	0733534	Dec lat:	40.736212
Dec lon:	-73.59234983	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1080	Map scale:	Not Reported
Altitude:	95.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Not Reported		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	68.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1993-03-31	Ground water data end date:	1993-07-01
Ground water data count:	3		

Ground-water levels, Number of Measurements: 3

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1993-07-01		56.81	1993-05-18		58.22
1993-03-31		58.00			

AI140
North
1/2 - 1 Mile
Higher

FED USGS **USGS2116069**

Agency cd:	USGS	Site no:	404524073363201
Site name:	N 4206. 1		
Latitude:	404524	EDR Site id:	USGS2116069
Longitude:	0733632	Dec lat:	40.75676739
Dec lon:	-73.60846125	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 931 2	Map scale:	Not Reported
Altitude:	106.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	360.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1954-06-01
Water quality data end date:	1988-02-09	Water quality data count:	39
Ground water data begin date:	1959-02-11	Ground water data end date:	1961-02-16
Ground water data count:	2		

Ground-water levels, Number of Measurements: 2

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1961-02-16		73.04	1959-02-11		75.41

141
South
1/2 - 1 Mile
Lower

FED USGS **USGS2117367**

Agency cd:	USGS	Site no:	404352073362401
Site name:	N 8625. 1		
Latitude:	404352	EDR Site id:	USGS2117367
Longitude:	0733624	Dec lat:	40.73121223
Dec lon:	-73.60623917	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1 44	Map scale:	Not Reported
Altitude:	32.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

AJ142
North
1/2 - 1 Mile
Higher

FED USGS **USGS2116082**

Agency cd:	USGS	Site no:	404525073362600
Site name:	-CARLE PLACE WD WELL-WELL 0187T		
Latitude:	404525	EDR Site id:	USGS2116082
Longitude:	0733626	Dec lat:	40.75704515
Dec lon:	-73.60679453	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	HICKSVILLE R-26-3	Map scale:	24000
Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1974-04-01
Water quality data end date:	1974-04-01	Water quality data count:	1
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
NY WELLS	NYWS006211

AI143
NNW
1/2 - 1 Mile
Higher

Well Id:	NY2902818	System name:	CARLE PLACE WD
System Id:	N-06315	Well name:	WELL 4
Type:	Well	Active?:	Active
County:	NASSAU COUNTY	Latitude:	404525 000
Longitude:	733632 000	Slec_type_:	AC
Agency:	HELLER, ROBERT T		
Address:	CARLE PLACE WATER DISTRICT 578 MINEOLA AVENUE		
City/State/Zip:	CARLE PLACE NY 11514		
Phone:	516-333-0540		

Database	EDR ID Number
NY WELLS	NYWS006210

AI144
NNW
1/2 - 1 Mile
Higher

Well Id:	NY2902818	System name:	CARLE PLACE WD
System Id:	N-04206	Well name:	WELL 3
Type:	Well	Active?:	Active
County:	NASSAU COUNTY	Latitude:	404525 000
Longitude:	733632 000	Slec_type_:	AC
Agency:	HELLER, ROBERT T		
Address:	CARLE PLACE WATER DISTRICT 578 MINEOLA AVENUE		
City/State/Zip:	CARLE PLACE NY 11514		
Phone:	516-333-0540		

Database	EDR ID Number
FED USGS	USGS2117317

AK145
South
1/2 - 1 Mile
Higher

Agency cd:	USGS	Site no:	404350073361201
Site name:	N 3697. 1		
Latitude:	404352	EDR Site id:	USGS2117317
Longitude:	0733611	Dec lat:	40.73121219
Dec lon:	-73.60262795	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1052 1	Map scale:	Not Reported
Altitude:	91.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19340410
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	432.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1952-10-28
Water quality data end date:	1970-09-24	Water quality data count:	13
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

AH146
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2117028**

Agency cd:	USGS	Site no:	404406073370700
Site name:	-GARDEN CITY WTP-WELL 0484T		
Latitude:	404406	EDR Site id:	USGS2117028
Longitude:	0733707	Dec lat:	40.73510117
Dec lon:	-73.61818393	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	FREEPORT S-26-2	Map scale:	24000
Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1974-04-03
Water quality data end date:	1974-05-16	Water quality data count:	2
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AJ147
North
1/2 - 1 Mile
Higher | **FED USGS** | **USGS2116083**

Agency cd:	USGS	Site no:	404525073362602
Site name:	N 6315. 1		
Latitude:	404526	EDR Site id:	USGS2116083
Longitude:	0733626	Dec lat:	40.75732292
Dec lon:	-73.60679453	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 941 2	Map scale:	Not Reported
Altitude:	107.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	353.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1958-04-01
Water quality data end date:	1984-04-19	Water quality data count:	41
Ground water data begin date:	1957-08-30	Ground water data end date:	1973-12-03
Ground water data count:	102		

Ground-water levels, Number of Measurements: 102

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1973-12-03		21.74	1973-09-19		22.66
1972-12-19		20.20	1967-12-27		16.39
1967-11-27		16.52	1967-10-27		16.62
1967-09-28		16.70	1967-09-01		16.66
1967-08-02		16.48	1967-06-26		16.07
1967-05-26		15.54	1967-04-26		14.89
1967-03-29		14.44	1967-02-28		14.16
1967-01-25		14.26	1966-12-23		14.14
1966-11-23		14.16	1966-10-26		14.17
1966-09-26		14.28	1966-08-26		14.39
1966-07-22		14.54	1966-06-27		14.75
1966-05-25		14.90	1966-04-26		14.98
1966-03-25		15.14	1966-02-25		15.27
1966-01-26		15.41	1965-12-28		15.56
1965-12-01		15.72	1965-10-29		15.94

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1965-09-30		16.00	1965-08-30		16.17
1965-07-26		16.49	1965-06-25		16.49
1965-06-01		16.52	1965-04-28		16.47
1965-03-30		16.46	1965-02-26		17.28
1965-01-28		16.66	1964-12-23		16.89
1964-12-12		68.38	1964-11-30		17.01
1964-10-22		17.25	1964-09-28		17.56
1964-08-24		17.72	1964-07-23		17.93
1964-05-26		17.79	1964-04-24		17.22
1964-03-26		17.04	1964-03-02		16.85
1964-01-30		16.79	1964-01-06		16.92
1963-12-04		17.07	1963-11-05		17.27
1963-10-01		17.52	1963-08-26		17.82
1963-07-25		18.04	1963-06-24		18.25
1963-06-04		18.39	1963-04-24		18.64
1963-03-25		18.67	1963-02-27		18.37
1963-01-28		18.45	1962-12-27		18.75
1962-12-04		18.97	1962-10-29		19.26
1962-09-28		19.58	1962-08-28		19.99
1962-07-30		20.29	1962-06-29		20.59
1962-05-31		20.84	1962-04-25		20.66
1962-03-26		20.25	1962-03-05		20.16
1962-02-05		21.21	1961-12-29		20.77
1961-11-29		21.25	1961-11-07		21.61
1961-09-28		22.16	1960-12-01		21.44
1959-04-08		20.88	1959-02-11		75.72
1958-12-02		22.25	1958-09-29		23.53
1958-08-29		23.57	1958-05-28		23.42
1958-04-30		22.09	1958-03-31		20.76
1958-02-28		20.06	1958-01-29		19.61
1957-12-31		19.71	1957-12-02		19.78
1957-10-31		20.21	1957-10-18		20.33
1957-10-02		20.45	1957-09-26		20.49
1957-09-19		20.54	1957-09-11		20.59
1957-09-05		20.67	1957-09-04		20.73
1957-09-03		20.90	1957-08-30		28.30

AK148
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS2117191**

Agency cd:	USGS	Site no:	404353073360701
Site name:	N 3698. 1		
Latitude:	404352	EDR Site id:	USGS2117191
Longitude:	0733607	Dec lat:	40.73121218
Dec lon:	-73.60151681	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1052 1	Map scale:	Not Reported

Altitude:	94.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19340410
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	472.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1953-10-01
Water quality data end date:	1971-04-26	Water quality data count:	12
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

AK149
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117366**

Agency cd:	USGS	Site no:	404352073361301
Site name:	N 3696. 1		
Latitude:	404351	EDR Site id:	USGS2117366
Longitude:	0733613	Dec lat:	40.73093442
Dec lon:	-73.60318352	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1052 1	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	444.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1953-10-01
Water quality data end date:	1960-02-02	Water quality data count:	4
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

150
West
1/2 - 1 Mile
Higher

FED USGS **USGS2116485**

Agency cd:	USGS	Site no:	404446073372401
Site name:	N 9962. 1		
Latitude:	404446	EDR Site id:	USGS2116485
Longitude:	0733724	Dec lat:	40.74621213
Dec lon:	-73.62290622	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 995 2 52	Map scale:	Not Reported
Altitude:	111.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820702
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	65.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-15
Water quality data end date:	1987-10-13	Water quality data count:	5
Ground water data begin date:	1982-08-19	Ground water data end date:	1998-03-24
Ground water data count:	21		

Ground-water levels, Number of Measurements: 21

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1998-03-24		61.85	1997-03-11		60.13
1995-03-14		58.74	1994-03-30		60.82
1993-03-23		61.58	1992-03-16		62.35
1991-03-21		64.96	1990-04-23		63.45
1987-10-13		60.42	1985-08-22		63.37
1985-05-10		64.12	1984-08-10		68.05
1984-08-08		68.03	1984-04-25		64.81
1984-04-06		64.12	1983-08-31		61.44
1983-08-15		62.02	1983-04-14		60.83
1983-03-31		59.73	1982-11-17		59.27

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1982-08-19		61.05			

151
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS2117282**

Agency cd:	USGS	Site no:	404358073365601
Site name:	N 9966. 1		
Latitude:	404358	EDR Site id:	USGS2117282
Longitude:	0733656	Dec lat:	40.73287895
Dec lon:	-73.6151283	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1011 1 14	Map scale:	Not Reported
Altitude:	82.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820616
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-08
Water quality data end date:	1984-08-07	Water quality data count:	3
Ground water data begin date:	1982-08-19	Ground water data end date:	1987-07-28
Ground water data count:	30		

Ground-water levels, Number of Measurements: 30

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-07-28		57.39	1987-05-19		56.71
1984-08-08		64.06	1984-08-07		64.15
1984-08-02		64.24	1984-07-03		64.08
1984-06-05		62.60	1984-05-03		60.25
1984-04-25		59.89	1984-04-16		59.92
1984-04-02		58.70	1984-03-01		57.91
1984-01-30		57.25	1983-12-02		56.45
1983-11-03		56.24	1983-10-06		56.89
1983-09-12		56.56	1983-08-31		57.29
1983-08-11		57.10	1983-08-08		57.30
1983-07-14		58.01	1983-06-29		59.12

Ground-water levels, continued.

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-05-23		58.79	1983-04-14		56.35
1983-03-31		55.12	1983-03-15		54.29
1983-03-09		54.22	1983-02-18		53.37
1982-11-17		55.24	1982-08-19		58.53

AH152
SW
1/2 - 1 Mile
Higher

NY WELLS **NYWS006277**

Well Id:	NY2902824	System name:	GARDEN CITY VILLAGE
System Id:	N-05163	Well name:	WELL 12
Type:	Well	Active?:	Active
County:	NASSAU COUNTY	Latitude:	404406 000
Longitude:	733707 000	Slec_type_:	AC
Agency:	HECKEN JR, HAROLD P		
Address:	GARDEN CITY VILLAGE WATER DIST 351 STEWART AVENUE		
City/State/Zip:	GARDEN CITY NY 11530		
Phone:	516-742-5802		

AH153
SW
1/2 - 1 Mile
Higher

NY WELLS **NYWS006276**

Well Id:	NY2902824	System name:	GARDEN CITY VILLAGE
System Id:	N-03935	Well name:	WELL 11
Type:	Well	Active?:	Active
County:	NASSAU COUNTY	Latitude:	404406 000
Longitude:	733707 000	Slec_type_:	AC
Agency:	HECKEN JR, HAROLD P		
Address:	GARDEN CITY VILLAGE WATER DIST 351 STEWART AVENUE		
City/State/Zip:	GARDEN CITY NY 11530		
Phone:	516-742-5802		

154
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS2116528**

Agency cd:	USGS	Site no:	404450073351901
Site name:	N 9399. 1		
Latitude:	404450	EDR Site id:	USGS2116528
Longitude:	0733519	Dec lat:	40.74732288
Dec lon:	-73.58818296	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NG 905 1	Map scale:	Not Reported

Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19780802
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	24.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1978-10-25	Ground water data end date:	1979-04-19
Ground water data count:	5		

Ground-water levels, Number of Measurements: 5

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1979-04-19		72.88	1979-03-21		72.69
1978-12-28		69.83	1978-11-21		69.77
1978-10-25		70.70			

AL155
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116992**

Agency cd:	USGS	Site no:	404403073370601
Site name:	N 9964. 1		
Latitude:	404403	EDR Site id:	USGS2116992
Longitude:	0733706	Dec lat:	40.73426784
Dec lon:	-73.61790615	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1000 1 14	Map scale:	Not Reported
Altitude:	87.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820616
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	1983-08-08
Water quality data end date:	1984-08-08	Water quality data count:	7
Ground water data begin date:	1982-08-12	Ground water data end date:	1985-05-10
Ground water data count:	13		

Ground-water levels, Number of Measurements: 13

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		59.51	1984-08-08		62.77
1984-04-25		59.39	1984-04-19		59.27
1983-08-31		55.76	1983-08-08		55.80
1983-04-14		55.50	1983-04-14		55.53
1983-04-14		55.47	1983-03-31		54.37
1982-11-17		54.26	1982-08-19		56.74
1982-08-12		56.87			

AM156
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117303**

Agency cd:	USGS	Site no:	404349073361801
Site name:	N 9777. 1		
Latitude:	404349	EDR Site id:	USGS2117303
Longitude:	0733619	Dec lat:	40.73037889
Dec lon:	-73.60485024	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	82.5		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	51.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-14	Ground water data end date:	1987-07-28
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-07-28		55.10	1987-05-20		55.32
1983-08-31		55.09	1983-04-14		54.79
1983-03-31		53.94	1982-08-19		54.99
1982-08-12		55.09	1982-04-14		55.34

AM157
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117304**

Agency cd:	USGS	Site no:	404349073361802
Site name:	N 9778. 1		
Latitude:	404349	EDR Site id:	USGS2117304
Longitude:	0733619	Dec lat:	40.73037889
Dec lon:	-73.60485024	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	82.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	83.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-14	Ground water data end date:	1983-08-31
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		54.79	1983-04-14		54.55
1983-03-31		53.89	1982-08-19		54.73
1982-08-12		54.83	1982-04-14		55.32

AM158
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117305**

Agency cd:	USGS	Site no:	404349073361803
Site name:	N 9779. 1		
Latitude:	404349	EDR Site id:	USGS2117305
Longitude:	0733619	Dec lat:	40.73037889
Dec lon:	-73.60485024	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	83.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	258.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-14	Ground water data end date:	1983-08-31
Ground water data count:	8		

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		52.36	1983-04-14		52.43
1983-04-14		52.87	1983-03-31		53.04
1983-03-31		52.98	1982-08-19		52.78
1982-08-12		53.00	1982-04-14		54.59

AN159
NE
1/2 - 1 Mile
Higher

FED USGS **USGS2116114**

Agency cd:	USGS	Site no:	404513073353401
Site name:	N 9950. 1		
Latitude:	404513	EDR Site id:	USGS2116114
Longitude:	0733534	Dec lat:	40.75371172
Dec lon:	-73.59234969	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 982 2 89	Map scale:	Not Reported

Altitude:	112.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19820330
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	69.	Hole depth:	69.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-02
Water quality data end date:	1988-06-25	Water quality data count:	2
Ground water data begin date:	1983-08-31	Ground water data end date:	1991-08-27
Ground water data count:	10		

Ground-water levels, Number of Measurements: 10

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1991-08-27		69.13	1990-10-31		69.90
1990-08-15		69.69	1990-06-18		71.00
1990-04-25		68.64	1987-07-28		76.37
1987-05-27		74.96			
1984-05-02		72.06			
Note: Well was plugged and not in hydraulic contact with formation..					
1984-04-25		71.78	1983-08-31		68.71

AN160
NE
1/2 - 1 Mile
Higher

FED USGS **USGS2116115**

Agency cd:	USGS	Site no:	404513073353402
Site name:	N 11782. 1		
Latitude:	404513	EDR Site id:	USGS2116115
Longitude:	0733534	Dec lat:	40.75371172
Dec lon:	-73.59234969	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 982	Map scale:	Not Reported
Altitude:	112.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Not Reported		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	54.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1990-10-31	Ground water data end date:	1990-10-31
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1990-10-31		69.97

161
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS2116774**

Agency cd:	USGS	Site no:	404416073372001
Site name:	N 10094. 1		
Latitude:	404416	EDR Site id:	USGS2116774
Longitude:	0733720	Dec lat:	40.73787893
Dec lon:	-73.62179513	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 999 1 14	Map scale:	Not Reported
Altitude:	102.5		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	68.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-09-30
Water quality data end date:	1984-04-03	Water quality data count:	2
Ground water data begin date:	1983-03-15	Ground water data end date:	1987-07-28
Ground water data count:	10		

Ground-water levels, Number of Measurements: 10

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-07-28		56.57	1987-05-20		57.36
1984-08-08		63.07	1984-04-25		60.02
1984-04-03		58.59	1983-09-30		55.34
1983-08-31		55.86	1983-04-14		55.14
1983-03-31		54.49	1983-03-15		53.92

AO162
SW
1/2 - 1 Mile
Lower

FED USGS **USGS2117110**

Agency cd:	USGS	Site no:	404359073370101
Site name:	N 10097. 1		
Latitude:	404359	EDR Site id:	USGS2117110
Longitude:	0733702	Dec lat:	40.73315674
Dec lon:	-73.61679502	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1001 1 14	Map scale:	Not Reported
Altitude:	83.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19830318
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	56.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-17
Water quality data end date:	1983-11-15	Water quality data count:	4
Ground water data begin date:	1983-03-31	Ground water data end date:	1983-12-02
Ground water data count:	14		

Ground-water levels, Number of Measurements: 14

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-12-02		56.49	1983-11-15		56.18
1983-11-03		56.23	1983-10-20		56.54
1983-10-06		57.09	1983-09-12		56.64
1983-08-31		57.31	1983-08-17		59.37
1983-08-11		57.76	1983-07-14		59.27
1983-06-29		59.90	1983-05-23		59.00
1983-04-14		58.37	1983-03-31		55.46

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AO163
SW
1/2 - 1 Mile
Lower

FED USGS **USGS2117111**

Agency cd:	USGS	Site no:	404359073370202
Site name:	N 10097. 2		
Latitude:	404359	EDR Site id:	USGS2117111
Longitude:	0733702	Dec lat:	40.73315674
Dec lon:	-73.61679502	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1001 1 14	Map scale:	Not Reported
Altitude:	83.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19831221
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	36.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1984-05-07
Water quality data end date:	1984-09-19	Water quality data count:	9
Ground water data begin date:	1984-01-30	Ground water data end date:	1984-09-19
Ground water data count:	14		

Ground-water levels, Number of Measurements: 14

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-09-19		62.55	1984-08-08		64.35
1984-08-07		64.37	1984-08-02		64.46
1984-07-03		65.00	1984-07-02		66.01
1984-06-05		63.02	1984-05-07		60.98
1984-05-03		60.78	1984-04-25		60.25
1984-04-17		61.28	1984-04-02		59.37
1984-03-01		59.06	1984-01-30		57.66

164
East
1/2 - 1 Mile
Higher

FED USGS **USGS2116477**

Agency cd:	USGS	Site no:	404446073351601
Site name:	N 8714. 1		
Latitude:	404446	EDR Site id:	USGS2116477
Longitude:	0733516	Dec lat:	40.74621178
Dec lon:	-73.58734961	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NG 905 2 89	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

AP165
South
1/2 - 1 Mile
Lower

FED USGS **USGS2117482**

Agency cd:	USGS	Site no:	404348073362701
Site name:	N 9912. 1		
Latitude:	404348	EDR Site id:	USGS2117482
Longitude:	0733627	Dec lat:	40.73010114
Dec lon:	-73.60707253	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	78.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST

Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	110.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-07-16	Ground water data end date:	1987-05-21
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-21		54.43	1983-08-31		53.50
1983-04-14		53.58	1983-03-31		53.33
1982-08-19		53.75	1982-07-16		53.64

AP166
South
1/2 - 1 Mile
Lower

FED USGS **USGS2117483**

Agency cd:	USGS	Site no:	404348073362801
Site name:	N 9801. 1		
Latitude:	404348	EDR Site id:	USGS2117483
Longitude:	0733628	Dec lat:	40.73010114
Dec lon:	-73.60735032	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	77.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	53.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1982-04-14	Ground water data end date:	1987-05-20
Ground water data count:	7		

Ground-water levels, Number of Measurements: 7

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1987-05-20		55.37	1983-08-31		54.82
1983-04-14		54.66	1983-03-31		53.78
1982-08-19		54.80	1982-07-16		55.36
1982-04-14		55.12			

AL167
SW
1/2 - 1 Mile
Lower

FED USGS **USGS2117168**

Agency cd:	USGS	Site no:	404401073370501
Site name:	N 3935. 1		
Latitude:	404400	EDR Site id:	USGS2117168
Longitude:	0733705	Dec lat:	40.73343452
Dec lon:	-73.61762837	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1001 1 14	Map scale:	Not Reported
Altitude:	84.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Northern Long Island. New York. Area = 915 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	415.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1953-07-01
Water quality data end date:	1985-04-05	Water quality data count:	41
Ground water data begin date:	1982-04-08	Ground water data end date:	1985-05-10
Ground water data count:	10		

Ground-water levels, Number of Measurements: 10

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1985-05-10		56.43	1984-04-25		57.46
1983-08-31		44.08	1983-04-14		47.26
1983-04-14		46.55	1983-04-14		46.38
1983-03-31		52.70			
1982-08-19		43.88			
Note: A nearby site that taps the same aquifer was being pumped.					
1982-04-14		54.45	1982-04-08		54.15

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AL168
SW
1/2 - 1 Mile
Higher

FED USGS **USGS2116993**

Agency cd:	USGS	Site no:	404403073370901
Site name:	N 3934. 1		
Latitude:	404402	EDR Site id:	USGS2116993
Longitude:	0733708	Dec lat:	40.73399008
Dec lon:	-73.61846173	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1001 1 14	Map scale:	Not Reported
Altitude:	86.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	422.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1953-06-01
Water quality data end date:	1985-05-14	Water quality data count:	43
Ground water data begin date:	1982-04-08	Ground water data end date:	1997-04-23
Ground water data count:	9		

Ground-water levels, Number of Measurements: 9

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1997-04-23		50.34	1996-04-09		47.36
1995-04-26		50.16	1985-05-10		56.88
1984-04-25		57.54	1983-03-31		52.66
1982-08-12		45.24			
Note: A nearby site that taps the same aquifer was being pumped.					
1982-04-14		54.46	1982-04-08		54.20

AQ169
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS2116769**

Agency cd:	USGS	Site no:	404416073352101
Site name:	N 9709. 1		
Latitude:	404416	EDR Site id:	USGS2116769
Longitude:	0733521	Dec lat:	40.7378786
Dec lon:	-73.5887386	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 999 1	Map scale:	Not Reported
Altitude:	89.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19810110
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	366.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-30
Water quality data end date:	1984-04-17	Water quality data count:	2
Ground water data begin date:	1982-03-25	Ground water data end date:	1983-08-31
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		60.11	1983-03-31		59.45
1982-08-19		60.27			
Note: A nearby site that taps the same aquifer was being pumped.					
1982-08-19		59.99			
Note: A nearby site that taps the same aquifer was being pumped.					
1982-04-14		61.39	1982-03-25		60.39

AQ170
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS2116770**

Agency cd:	USGS	Site no:	404416073352102
Site name:	N 9751. 1		
Latitude:	404416	EDR Site id:	USGS2116770
Longitude:	0733521	Dec lat:	40.7378786
Dec lon:	-73.5887386	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF 999 1	Map scale:	Not Reported

Altitude:	93.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19810110
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	286.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1983-08-30
Water quality data end date:	1984-05-01	Water quality data count:	2
Ground water data begin date:	1982-03-25	Ground water data end date:	1983-08-31
Ground water data count:	6		

Ground-water levels, Number of Measurements: 6

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		60.71	1983-08-30		60.71
1983-03-31		60.20	1982-08-19		61.06
1982-04-14		61.92	1982-03-25		61.31

171
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS2116347**

Agency cd:	USGS	Site no:	404453073372501
Site name:	N 5596. 1		
Latitude:	404454	EDR Site id:	USGS2116347
Longitude:	0733726	Dec lat:	40.74843432
Dec lon:	-73.62346178	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NE 984 2	Map scale:	Not Reported
Altitude:	106.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	468.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count: 0
Water quality data begin date: 1956-06-01
Water quality data end date: 1985-03-29
Water quality data count: 39
Ground water data begin date: 1957-04-10
Ground water data end date: 1984-04-25
Ground water data count: 8

Ground-water levels, Number of Measurements: 8

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1984-04-25		63.40	1983-03-31		59.23
1982-08-20		58.66	1982-04-14		60.76
1982-04-08		60.55	1964-12-16		60.90
1964-12-08		45.24	1957-04-10		58.65

172
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS2117345**

Agency cd: USGS
Site no: 404351073364801
Site name: N 6949. 1
Latitude: 404351
EDR Site id: USGS2117345
Longitude: 0733648
Dec lat: 40.73093452
Dec lon: -73.61290603
Coor meth: M
Coor accr: S
Latlong datum: NAD27
Dec latlong datum: NAD83
District: 36
State: 36
County: 059
Country: US
Land net: Not Reported
Location map: NF1022 1 14
Map scale: Not Reported
Altitude: 79.0
Altitude method: Level or other surveying method
Altitude accuracy: 0.1
Altitude datum: National Geodetic Vertical Datum of 1929
Hydrologic: Southern Long Island. New York. Area = 1660 sq.mi.
Topographic: Not Reported
Site type: Ground-water other than Spring
Date construction: Not Reported
Date inventoried: Not Reported
Mean greenwich time offset: EST
Local standard time flag: N
Type of ground water site: Single well, other than collector or Ranney type
Aquifer Type: Not Reported
Aquifer: GLACIAL AQUIFER,UPPER
Well depth: 46.
Hole depth: Not Reported
Source of depth data: Not Reported
Project number: Not Reported
Real time data flag: 0
Daily flow data begin date: 0000-00-00
Daily flow data end date: 0000-00-00
Daily flow data count: 0
Peak flow data begin date: 0000-00-00
Peak flow data end date: 0000-00-00
Peak flow data count: 0
Water quality data begin date: 1983-08-03
Water quality data end date: 1984-05-11
Water quality data count: 2
Ground water data begin date: 0000-00-00
Ground water data end date: 0000-00-00
Ground water data count: 0

Ground-water levels, Number of Measurements: 0

AP173
South
1/2 - 1 Mile
Lower

FED USGS **USGS2117473**

Agency cd:	USGS	Site no:	404347073362802
Site name:	N 9766. 1		
Latitude:	404347	EDR Site id:	USGS2117473
Longitude:	0733628	Dec lat:	40.72982337
Dec lon:	-73.60735032	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	77.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	99.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1980-12-18	Ground water data end date:	1983-08-31
Ground water data count:	15		

Ground-water levels, Number of Measurements: 15

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		53.54	1983-04-14		53.56
1983-04-12		54.70	1983-03-31		53.11
1982-12-14		51.66	1982-09-10		53.23
1982-08-19		53.71	1982-07-09		54.57
1982-04-14		54.47	1982-03-22		54.50
1982-01-12		52.63	1981-10-16		53.85
1981-06-08		54.72	1981-03-11		56.40
1980-12-18		56.22			

AP174
South
1/2 - 1 Mile
Lower

FED USGS **USGS2117474**

Agency cd:	USGS	Site no:	404347073362803
Site name:	N 9767. 1		
Latitude:	404347	EDR Site id:	USGS2117474
Longitude:	0733628	Dec lat:	40.72982337
Dec lon:	-73.60735032	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	77.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	156.	Hole depth:	160.
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1980-12-18	Ground water data end date:	1983-08-31
Ground water data count:	16		

Ground-water levels, Number of Measurements: 16

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		52.95	1983-04-14		53.00
1983-04-14		53.29	1983-04-12		54.49
1983-03-31		52.85	1982-12-14		51.28
1982-09-10		52.59	1982-08-19		53.14
1982-07-09		54.32	1982-04-14		54.84
1982-03-22		54.22	1982-01-12		53.94
1981-10-16		54.07	1981-06-08		54.09
1981-03-11		56.04	1980-12-18		55.66

AP175
South
1/2 - 1 Mile
Lower

FED USGS **USGS2117472**

Agency cd:	USGS	Site no:	404347073362801
Site name:	N 9765. 1		
Latitude:	404347	EDR Site id:	USGS2117472
Longitude:	0733628	Dec lat:	40.72982337
Dec lon:	-73.60735032	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1042 1	Map scale:	Not Reported
Altitude:	77.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	GLACIAL AQUIFER,UPPER		
Well depth:	46.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1980-12-18	Ground water data end date:	1983-08-31
Ground water data count:	15		

Ground-water levels, Number of Measurements: 15

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1983-08-31		54.67	1983-04-14		54.45
1983-04-12		54.46	1983-03-31		53.58
1982-12-12		52.47	1982-09-10		54.38
1982-08-19		54.66	1982-07-09		56.16
1982-04-14		54.39	1982-03-22		54.11
1982-01-12		52.61	1981-10-16		54.71
1981-06-08		55.52	1981-03-11		56.68
1980-12-18		56.98			

176
South
1/2 - 1 Mile
Higher

FED USGS **USGS2117316**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency cd:	USGS	Site no:	404350073351201
Site name:	N 3695. 1		
Latitude:	404347	EDR Site id:	USGS2117316
Longitude:	0733612	Dec lat:	40.72982333
Dec lon:	-73.60290575	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	36
State:	36	County:	059
Country:	US	Land net:	Not Reported
Location map:	NF1052 1	Map scale:	Not Reported
Altitude:	90.0		
Altitude method:	Level or other surveying method		
Altitude accuracy:	0.1		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Southern Long Island. New York. Area = 1660 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19340913
Date inventoried:	Not Reported	Mean greenwich time offset:	EST
Local standard time flag:	N		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	MAGOTHY AQUIFER		
Well depth:	500.	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	1952-10-28
Water quality data end date:	1971-04-26	Water quality data count:	14
Ground water data begin date:	0000-00-00	Ground water data end date:	0000-00-00
Ground water data count:	0		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

Zip	Num Sites	< 4 Pci/L	>= 4 Pci/L	>= 20 Pci/L	Avg > 4 Pci/L	Max Pci/L
11530	24	22 (91.7%)	2 (8.3%)	0 (0%)	2.04	8.3

Federal EPA Radon Zone for NASSAU County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for NASSAU COUNTY, NY

Number of sites tested: 226

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.640 pCi/L	98%	2%	0%
Basement	1.100 pCi/L	98%	2%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2009 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8056
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX B

Historic Aerial Photographs

900 Old Country Road
900 Old Country Road
Garden City, NY 11530

Inquiry Number: 2735789.3
April 05, 2010

The EDR Aerial Photo Decade Package

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Date EDR Searched Historical Sources:

Aerial Photography April 05, 2010

Target Property:

900 Old Country Road

Garden City, NY 11530

Year	***Scale***	***Details***	***Source***
1953	Aerial Photograph. Scale: 1"=500'	Panel #: /Flight Date: December 02, 1953	EDR
1957	Aerial Photograph. Scale: 1"=750'	Panel #: /Flight Date: March 24, 1957	EDR
1966	Aerial Photograph. Scale: 1"=750'	Panel #: /Flight Date: February 23, 1966	EDR
1966	Aerial Photograph. Scale: 1"=500'	Panel #: /Flight Date: March 08, 1966	EDR
1974	Aerial Photograph. Scale: 1"=750'	Panel #: /Flight Date: March 14, 1974	EDR
1976	Aerial Photograph. Scale: 1"=750'	Panel #: /Flight Date: March 29, 1976	EDR
1980	Aerial Photograph. Scale: 1"=750'	Panel #: /Flight Date: April 06, 1980	EDR
1985	Aerial Photograph. Scale: 1"=1000'	Panel #: /Flight Date: March 16, 1985	EDR
1994	Aerial Photograph. Scale: 1"=750'	Panel #: /Flight Date: April 04, 1994	EDR

INQUIRY #: 2735789.3
YEAR: 1953
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 2735789.3
YEAR: 1957
= 750'
N
EDR Environmental Data Resources Inc

INQUIRY #: 2735789.3
YEAR: 1966
= 750'
N
EDR Environmental Data Resources Inc

INQUIRY #: 2735789.3
YEAR: 1966
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 2735789.3
YEAR: 1974
= 750'
N
EDR Environmental Data Resources Inc

INQUIRY #: 2735789.3

YEAR: 1976

= 750'

N

EDR Environmental Data Resources Inc

INQUIRY #: 2735789.3

YEAR: 1980

= 750'

N

EDR Environmental Data Resources Inc

INQUIRY #: 2735789.3
YEAR: 1985
= 1000'
N

INQUIRY #: 2735789.3

YEAR: 1994

= 750'

N

EDR Environmental Data Resources Inc

APPENDIX C

Fire Insurance Map

900 Old Country Road
900 Old Country Road
Garden City, NY 11530

Inquiry Number: 2735789.2
April 06, 2010

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

4/06/10

Site Name:
900 Old Country Road
900 Old Country Road
Garden City, NY 11530

EDR Inquiry # 2735789.2

Client Name:
Roux Associates
209 Shafter Street
Islandia, NY 11749

Contact: Wendy Monterosso

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Roux Associates were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, State, Zip: Garden City, NY 11530
Cross Street:
P.O. # NA
Project: NA
Certification # 1429-49DC-9D54

Maps Provided:

1970
1968
1963
1961
1941

Sanborn® Library search results
Certification # 1429-49DC-9D54

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Roux Associates (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2010 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1970 Source Sheets



Volume 4A, Sheet 801

1968 Source Sheets

Volume 1, Sheet 13



Volume 1, Sheet 16

1963 Source Sheets



Volume 4A, Sheet 801

1961 Source Sheets



Volume 4A, Sheet 801



Volume 4A, Sheet 801

1941 Source Sheets



Volume 1, Sheet 13

1941 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1941

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 1, Sheet 13

N

1941 Certified Sanborn Map



Certification # 1429-49DC-9D54

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification #: 1429-49DC-9D54

Copyright: 1941

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 1, Sheet 13

N

1961 Certified Sanborn Map

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1961

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54



This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 801

N

1961 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1961

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 806
Volume 4A, Sheet 801
Volume 4A, Sheet 806

N

1961 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name:	900 Old Country Road
Address:	900 Old Country Road
City, ST, ZIP:	Garden City NY 11530
Client:	Roux Associates
EDR Inquiry:	2735789.2
Order Date:	4/6/2010 4:40:03 PM
Certification #	1429-49DC-9D54

Copyright: 1961

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 806
Volume 4A, Sheet 807
Volume 4A, Sheet 801
Volume 4A, Sheet 806

Volume 4A, Sheet 807

N

1961 Certified Sanborn Map

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1961

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54



This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 801

N

1961 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1961

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 802
Volume 4A, Sheet 804
Volume 4A, Sheet 801
Volume 4A, Sheet 802
Volume 4A, Sheet 804

N

1961 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name:	900 Old Country Road
Address:	900 Old Country Road
City, ST, ZIP:	Garden City NY 11530
Client:	Roux Associates
EDR Inquiry:	2735789.2
Order Date:	4/6/2010 4:40:03 PM
Certification #	1429-49DC-9D54
Copyright:	1961

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).



Volume 4A, Sheet 801
Volume 4A, Sheet 807
Volume 4A, Sheet 807
Volume 4A, Sheet 801

0 Feet 150 300 600

N

1963 Certified Sanborn Map

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1963

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54



This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801

N

1963 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1963

THE SANBORN LIBRARY LLC
Sanborn
SEAL OF AUTHENTICITY

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 806

N

1963 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1963

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 806
Volume 4A, Sheet 807
Volume 4A, Sheet 801

1963 Certified Sanborn Map

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1963

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54



This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801

N

1963 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1963

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 804

N

1963 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name:	900 Old Country Road
Address:	900 Old Country Road
City, ST, ZIP:	Garden City NY 11530
Client:	Roux Associates
EDR Inquiry:	2735789.2
Order Date:	4/6/2010 4:40:03 PM
Certification #	1429-49DC-9D54
Copyright:	1963

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 807

N

1968 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name:	900 Old Country Road
Address:	900 Old Country Road
City, ST, ZIP:	Garden City NY 11530
Client:	Roux Associates
EDR Inquiry:	2735789.2
Order Date:	4/6/2010 4:40:03 PM
Certification #	1429-49DC-9D54
Copyright:	1968

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).



Volume 1, Sheet 13
Volume 1, Sheet 15
Volume 1, Sheet 16

0 Feet 150 300 600

N

1968 Certified Sanborn Map

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1968

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 1, Sheet 13
Volume 1, Sheet 16

N

1970 Certified Sanborn Map

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1970

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54



This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801

N

1970 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1970

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 806

N

1970 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name: 900 Old Country Road
Address: 900 Old Country Road
City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1970

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 806
Volume 4A, Sheet 807

N

1970 Certified Sanborn Map

Site Name: 900 Old Country Road
Address: 900 Old Country Road

City, ST, ZIP: Garden City NY 11530

Client: Roux Associates
EDR Inquiry: 2735789.2
Order Date: 4/6/2010 4:40:03 PM
Certification # 1429-49DC-9D54

Copyright: 1970

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54



This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801

N

1970 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name:	900 Old Country Road
Address:	900 Old Country Road
City, ST, ZIP:	Garden City NY 11530
Client:	Roux Associates
EDR Inquiry:	2735789.2
Order Date:	4/6/2010 4:40:03 PM
Certification #	1429-49DC-9D54

Copyright: 1970

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600



Volume 4A, Sheet 801
Volume 4A, Sheet 802
Volume 4A, Sheet 804

N

1970 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 1429-49DC-9D54

Site Name:	900 Old Country Road
Address:	900 Old Country Road
City, ST, ZIP:	Garden City NY 11530
Client:	Roux Associates
EDR Inquiry:	2735789.2
Order Date:	4/6/2010 4:40:03 PM
Certification #	1429-49DC-9D54
Copyright:	1970

This Certified Sanborn Map combines the following sheets (thumbnails on page 3).

0 Feet 150 300 600





Volume 4A, Sheet 801
Volume 4A, Sheet 807

N

APPENDIX D

Field Sampling Plan

January 21, 2011

FIELD SAMPLING PLAN

900 Old Country Road
Garden City, Town of Hempstead,
Nassau County, New York

Prepared for

EQUITY ONE (NORTHEAST PORTFOLIO) INC.
650 Fifth Avenue, 24th Floor
New York, New York

ROUX ASSOCIATES, INC.

Environmental Consulting & Management

ROUX

209 Shafter Street, Islandia, New York 11749 ♦ 631-232-2600

TABLE OF CONTENTS

1.0 INTRODUCTION 1

2.0 SAMPLING OBJECTIVES 2
- 3.1 Soil Sampling 2
- 3.2 Groundwater Sampling 4
- 3.3 Soil Vapor 4

4.0 FIELD SAMPLING PROCEDURES 6
- 4.1 Soil Sampling and Monitoring Well Installation 6
  - 4.1.1 Soil Sampling 6
  - 4.1.2 Monitoring Well Installation 7
- 4.2 Groundwater Sampling 8
- 4.3 Soil and Sub slab Vapor Sampling 8
  - 4.3.1 Pre-Sampling Inspection 9
  - 4.3.2 Geophysical Survey 10
  - 4.3.3 Gore Module Installation 11
  - 4.3.4 Soil Vapor Samples from Soil Borings 11
  - 4.3.5 Sub-Slab Soil Vapor Samples 12
  - 4.3.6 Outdoor Ambient Air Sample 13

5.0 SAMPLE HANDLING AND ANALYSIS 14
- 5.1 Field Sample Handling 14
- 5.2 Sample Custody Documentation 14
- 5.3 Sample Shipment 15

6.0 SITE CONTROL PROCEDURES 17
- 6.1 Decontamination 17
- 6.2 Waste Handling and Disposal 17

TABLES

1. Remedial Investigation Field and Quality Control Sampling Summary
2. Preservation, Holding Times and Sample Containers

ATTACHMENTS

1. Roux Associates' Standard Operating Procedure for Tasks Described in this Field Sampling Plan
2. Chain of Custody Form

1.0 INTRODUCTION

Roux Associates has developed this Field Sampling Plan (FSP) to describe in detail the field sampling methods to be used during performance of the Remedial Investigation (RI) for the site located at 900 Old Country Road, Garden City, New York (Site). The objective of the RI is to determine the nature and extent of contamination at the Site with regards to previously identified areas of concern (AOCs), to identify and investigate any additional previously unidentified AOCs, characterize environmental media at the Site, qualitatively assess the potential exposure of receptors to Site contaminants, and develop any other additional data necessary to support the development of a Remedial Action Work Plan. The current plan for the Site is development, which includes 330,000 square feet of retail commercial space and a possible hotel.

The FSP was prepared in accordance with directives provided in the DER-10 Technical Guidance for Site Investigation and Remediation (May 2010) issued by the New York State Department of Environmental Conservation (NYSDEC), as well as relevant NYSDEC Technical and Administrative Guidance Memoranda (TAGMs), and provides guidelines and procedures to be followed by field personnel during performance of the RI. Information contained in this FSP relates to sampling objectives, sampling locations, sampling frequencies, sample designations, sampling equipment, sample handling, sample analysis, and decontamination.

2.0 SAMPLING OBJECTIVES

Prior Site characterization work was conducted on the Site over the course of several years by various entities.

The objective of the proposed sampling is to determine the nature and extent of the known contamination on Site, to evaluate any additional AOCs and potential associated contamination and to obtain a current representation of the environmental conditions at the Site. Roux Associates has performed a thorough Site reconnaissance and has not located any additional AOCs. To evaluate historically reported areas of concern that were not directly observed by Roux Associates (i.e., hazardous waste storage area) along with the potential for unknown areas of concern GORE-SORBER® screening modules (Gore Modules) were utilized in the Cendant building, Manufacturing building and several locations outside these buildings and their associated leaching structures. The results of the Gore Module sampling were used to assist in finalizing locations for soil and soil vapor sampling as described in Section 3.2.2 of the RI work plan.

The sampling procedures associated with characterization of soil, groundwater, and soil vapors are discussed in detail in Section 4 of this FSP. A discussion of the data quality objectives (DQOs) is provided in the Quality Assurance Project Plan (QAPP) located in Appendix E of the RI Work Plan.

3.0 SAMPLE MEDIA, LOCATIONS, ANALYTICAL SUITES, AND FREQUENCY

The media to be sampled during the RI include soil, groundwater, and soil vapor. Sampling locations, analytical suites, and frequency vary by medium. A discussion of the sampling schedule for each medium is provided below, while the assumed number of field samples to be collected for each medium, including quality control (QC) samples, is shown in Table 1. Specifics regarding the collection of samples at each location and for each task are provided in Section 4 of this FSP.

3.1 Soil Sampling

Soil samples underlying the Site will be collected at 37 locations as shown in Figure 3 of the RI Work Plan). At each former leach pool structure, two soil samples will be collected: one from the base of the former structures and one from five feet below the base of the former structures. In the 11 leach pools that exhibited exceedances when previously sampled by others (LP-4, LP-14,

LP-15, and LP-21 through LP-28) only one soil sample will be collected from the interval approximately five feet below the depth of the previously collected sample (i.e. approximately five to eight feet below the base of the leach pool structure). From each of the eight previously sampled dry wells on the northern and northeastern section of the property (DW-1, DW-2, DW-14, DW-16, DW-19 through DW-22), one soil sample will be collected from the interval with the highest photo-ionization detector (PID) reading and from the interval five feet below this. During the installation of monitoring wells MW-17A, MW-20 and MW-21, one to two soil samples will be collected based on field observations; one soil sample will be collected at the two-foot interval immediately above the water table and an additional sample will be collected from any interval that exhibits visual or olfactory evidence of impacts. Soil samples will be collected from beneath the floor slabs of the Cendant building and the Manufacturing building. All samples will be analyzed for Target Compound List (TCL) plus 30/ Target Analyte List (TCL + 30/TAL) (which includes TCL Volatile Organic Compounds [VOCs], TCL Base neutral acids [BNA], [SVOCs] + 20, TCL Pesticides, TCL polychlorinated biphenyls [PCBs], TAL Metals, and Total Cyanide), and Total Petroleum Hydrocarbons (TPH).

Soil sampling was conducted at the Site in November 2010, as described above. To confirm the quality of the leach pool and dry well sampling that was done in November 2010, Roux Associates will resample 20% of the previously sampled locations, which will include the following seven locations; DW-2, LP-4, LP-15, LP-22, LP-23, LP-26 and LP-29. At each location, soil samples will be collected from the same interval as was previously collected. The selected locations are shown on Figure 3 and the sample intervals are summarized in Table 3a.

To evaluate the results of the Gore Module screening samples, soil borings are proposed for several locations beneath the Cendant building, Manufacturing building and the outdoor area between the these buildings. The selected locations are shown on Figure 3 and the sample intervals are summarized in Table 3a. A total of 14 soil boring locations have been selected for further analysis in the Cendant and Manufacturing buildings, and in the outdoor areas between these buildings. Continuous soil samples will be collected using the direst-push method via a Geoprobe® with either a four or five-foot macrocore sampler. During soil boring activities, lithology will be recorded and soil will be field screened every two feet to two and a half feet for VOCs using a PID.

As described below in Section 4.3.2, soil borings may be added to the scope of work to investigate any additional areas of concern identified during the geophysical survey.

3.2 Groundwater Sampling

Groundwater samples will be collected from all existing monitoring wells (21) located at the Site and the three additional monitoring wells that will be installed during the investigation. After gauging for potential separate-phase petroleum product, each well will be sampled for Target Compound List (TCL) plus 30/ Target Analyte List (TCL + 30/TAL) (which includes TCL Volatile Organic Compounds [VOCs], TCL Base neutral acids [BNA], [SVOCs] + 20, TCL Pesticides, TCL polychlorinated biphenyls [PCBs], TAL Metals (both total and dissolved), and Total Cyanide), and Total Petroleum Hydrocarbons (TPH). Additional sample volume will be collected if necessary for laboratory filtered metals analysis and placed on hold. Any filtered samples selected for analysis will be analyzed in accordance with DER-10 requirements. Field parameters including pH and conductivity will also be measured prior to sampling.

3.3 Soil Vapor

Gore modules will be installed and analyzed across the site to identify additional areas of concern, where further investigation is necessary. Gore modules are passive diffusion samplers that consist of sealed durable microporous tubes of polytetrafluoroethylene or GORE-TEX® Membrane. The sample tubes contain hydrophobic pores that are small enough to reject soil and water to a depth of over 30 feet. Inside each module is an adsorbent structure engineered by Gore to be hydrophobic and collect a wide variety of volatile inorganic and organic compounds ranging from C2 (ethane) to C20 (phytane). The engineered adsorbents inside the modules are designed to physically fit inside a thermal desorption apparatus for analysis by GC/MS. Since these modules can be deployed over a broad area, they are ideal screening tools for evaluating the Cendant building, Manufacturing building, and previously uninvestigated outdoor areas of the site to determine the need for further investigation. Any Gore samples that show evidence of elevated soil vapor concentrations will be targeted for GeoProbe™ soil borings to identify potential areas of concern. Soil vapor samples collected Summa canisters will be used to quantitatively verify the extent of soil vapor impacts indicated by Gore module sample results.

The Gore module locations are shown on Figure 3 of the RI Work Plan. A total of 40 Gore modules were installed in November 2010, 15 throughout the Cendant building, four within the Manufacturing building, and 21 in areas around the outside of the buildings within the vicinity of former soil vapor sampling locations performed by others, and down gradient of areas of concern.

To evaluate the results of the Gore Module samples, a total of nine soil vapor sampling locations are proposed, four from areas around the outside of the southeast corner of the Cendant building and southwest corner of the Manufacturing building, three from below the Cendant building floor slab and two from outside the southeast corner of the Thomasville Home Furnishings building. Sample locations for sub-slab soil vapor samples have been selected based on areas of known or suspected industrial activities, where previous sampling has indicated contamination and based on the results of the Gore Module screening as described in Section 3.2.2 of the RI work plan. In addition, one outdoor ambient air sample will be collected. All samples will be analyzed for VOCs using USEPA method TO-15.

4.0 FIELD SAMPLING PROCEDURES

This section provides a detailed discussion of the field procedures to be used during sampling of the various media being evaluated as part of the RI (i.e., soil, groundwater, and soil vapor). The locations are shown on Figure 3 of the RI work plan and additional information including intervals to be sampled and sample rationale is provided in Tables 3a, 3b and 3c of the RI work plan.

4.1 Soil Sampling and Monitoring Well Installation

Details for the collection of soil samples and the installation of monitoring wells are provided below.

4.1.1 Soil Sampling

Borings will be advanced using a Geoprobe™ truck or track-mounted direct-push drill rig. Samples of the soil profile will be collected in continuous four or five-foot increments using a 2-inch-diameter macrocore sampler to a maximum depth of approximately 21-23 feet below grade, which is the anticipated depth to the water table.

The soil from each four or five-foot interval will be observed for lithology and evidence of contamination (e.g., staining, odors, and/or visible free product) and placed immediately thereafter into large Zip-loc™ bags for recording headspace. After a minimum of 15 minutes for equilibration with the headspace in the Zip-loc™ bag, each sample will be screened for organic vapors using a PID. Samples for possible VOC analysis will be placed in a laboratory-supplied jar prior to screening, due to the potential for loss of VOCs through volatilization. Soil samples from leach pools, dry wells and soil borings will be collected according to Table 3a. In soil borings (MW-17A, MW-20 and MW-21), soil samples will be collected from the two-foot interval immediately above the water table and any interval that exhibits visual evidence of contamination or an elevated PID reading. These samples will be placed in the laboratory-supplied containers and shipped to the laboratory under chain of custody procedures in accordance with Roux Associates standard operating procedures. Upon completion, each boring will be allowed to collapse. Restoration is not required due to the imminent remediation and redevelopment of the Site.

Soil samples in the Cendant building will be collected from the 0-2 foot and 2-4 foot intervals below the building slab. Soil borings will be terminated at ten feet below grade, and the 8-10 foot

interval will be collected and held at the laboratory. If the laboratory results from any given soil boring show evidence of contamination (i.e., visual or elevated PID readings), the 8-10 sample will be analyzed. If any of these soil borings exhibit evidence of contamination (i.e., visual or elevated PID readings), the boring(s) will be continued to the water table, and a soil sample will be collected from the two-foot interval immediately above the water table. Furthermore, four additional borings will be advanced around any location that exhibits evidence of visible contamination or elevated PID readings. The additional four borings will be evenly spaced around the location(s), within a five-foot radius, and sampled in the same manner as described above.

Soil borings in the southeastern corner of the site, including those in the Manufacturing building, will be advanced to the water table. Soil samples will be collected from the two-foot interval immediately above the water table and any interval that exhibits visual or PID evidence of contamination.

Additional details regarding soil-sampling protocols are described in Roux Associates' Standard Operating Procedure for the Collection of Soil Samples for Laboratory Analysis, which is provided in Attachment 1.

4.1.2 Monitoring Well Installation

Following soil sampling activities, monitoring wells will be installed at soil boring locations MW-17A and MW-20 to a depth of approximately 50 feet bls, and at MW-21 to a depth of approximately 33 feet bls. Monitoring wells will be constructed of 2-inch-inside-diameter, Schedule 40 polyvinyl chloride (PVC) casing and, 0.020-inch slot, machined screen. Well screens will be 10 feet long, and will be installed from approximately 40 to 50 feet bls in MW-17A and MW-20, and from approximately 20 to 30 feet in MW-21. A sand pack will be placed around the well screen, extending two feet above the top of the screened zone. Once the driller confirms the depth of the sand pack, a minimum two-foot-thick bentonite pellet seal will be placed above the sand pack. Once the pellets have been allowed to hydrate, a cement-bentonite grout will be pumped into the remaining annular space from the bottom up using a tremie pipe lowered to just above the bentonite seal. The wells will be completed using locking well plugs, and flush mounted, bolt down, watertight, manhole covers cemented into place.

4.2 Groundwater Sampling

Each well will be developed to remove any fine-grained material in the vicinity of the well screen and to promote hydraulic connection with the aquifer. The wells will be developed using a submersible pump, which will be surged periodically until well yield is consistent and has a turbidity below 50 nephelometric turbidity units (NTUs), if possible.

Groundwater samples will be collected no sooner than one week following development of the wells. Prior to sampling, depth to water will be measured at each well using an electronic water level indicator with an accuracy of +/-0.01 feet. All wells will then be purged and sampled using a peristaltic pump, or an alternative method, depending on the observed depth to groundwater and logistical issues. Samples will be analyzed for TCL + 30/TAL (which includes: TCL VOCs+10, TCL BNA, SVOCs + 20, TCL Pesticides, TCL PCBs, TAL Metals (both total and dissolved) and Total Cyanide), and TPH. Additional details for the collection of groundwater samples are included in the Roux Associates SOPs (Attachment 1).

All groundwater samples will be placed in the laboratory-supplied containers and shipped to the laboratory under chain of custody procedures in accordance with Roux Associates' SOPs.

4.3 Soil and Sub slab Vapor Sampling

Soil vapor samples will be collected from areas around the outside of the buildings near potential impact areas, and from below the floor slab of the Cendant building in areas of known or suspected industrial activity. Gore modules were used to determine the most appropriate locations for soil vapor and sub-slab soil vapor samples. In addition, one ambient air sample will be collected to provide data on the background air quality outside of the building.

Prior to the collection of soil and sub-slab vapor samples, a pre-sampling inspection will be performed to identify and minimize conditions that may interfere with the proposed testing and Gore module screening will be conducted. Gore modules will be analyzed for VOCs and SVOCs using a modified 8260/8270 methodology. All soil vapor samples, sub slab vapor samples, and ambient samples will be analyzed using USEPA Method TO-15 for VOCs. The detection limits for all Matrix 1 compounds will be less than 0.25 $\mu g/m^3$, as required in the New York State Department of Health Guidance.

4.3.1 Pre-Sampling Inspection

This inspection will seek to evaluate the type of structure, floor layout, air flows, physical conditions, and any other pertinent information.

Task 1 – Pre-Sampling Inspection, Location Stakeout and Utility Clearance Activities

A pre-sampling inspection will be performed prior to the proposed sampling event to identify and minimize conditions that may interfere with the proposed testing. The inspection will seek to evaluate the type of structure, floor layout, air flows, and physical conditions of the building(s) being studied. At present, it is known that several areas of the Cendant building are in severe disrepair, and there is no active utility service to the building. This information, along with information on sources of potential indoor air contamination, will be summarized in a description of the building inspection/inventory.

Items to be included in the building inventory include the following:

a. construction characteristics, including foundation cracks and utility penetrations, ceiling construction and firewall separations, or other openings that may serve as preferential pathways for vapor intrusion; and

b. use or storage of petroleum products (e.g., fuel containers, gasoline operated equipment and unvented kerosene heaters) by transient building occupants.

Since the buildings are abandoned and have not been in use since 2001, potential interference from current products or activities releasing volatile chemicals is not considered to be an issue. Once any interfering conditions are corrected (if applicable), ventilation may be needed prior to sampling to eliminate residual contamination in the indoor air. If ventilation is appropriate, it will be completed 24 hours or more prior to the scheduled sampling time. Opening windows and doors, and operating exhaust fans may be needed since the building has no operational HVAC system.

Unnecessary building ventilation will be avoided within 24 hours prior to and during sampling.

To avoid potential interferences and dilution effects, every effort will be made to avoid the following for 24 hours prior to sampling:

a. smoking in the building;

b. painting;

c. using a wood stove, fireplace, or other auxiliary heating equipment (e.g., kerosene heater);

d. operating or storing field equipment or generators in the building;

e. allowing containers of gasoline or oil to remain within the building; and

f. engaging in any activities that use materials containing volatile chemicals.

The primary objective of the product inventory is to identify potential air sampling interference by characterizing the occurrence and use of chemicals and products throughout the building, keeping in mind the goal of the investigation and site-specific contaminants of concern.

Any products found in the buildings will be inventoried prior to testing to provide an accurate assessment of the potential contribution of volatile chemicals. If available, chemical ingredients of interest (e.g., analyte list) will be recorded for each product. If the ingredients are not listed on the label, record the product's exact and full name, and the manufacturer's name, address and telephone number will be recorded, if available.

All proposed sample locations will be field located prior to the commencement of the vapor investigation in order to avoid potential subsurface structures and/or utilities. Attempts will be made to obtain information regarding the location of former utilities in the locations that are to be sampled.

4.3.2 Geophysical Survey

A geophysical survey will be performed at the Site to attempt to locate any additional previously unidentified areas of concern, as well as potential utility interference with the planned scope of work. Previous geophysical surveying was performed in limited areas of the Site including the northwestern corner surrounding the Thomasville Home Furnishings building, the northeastern corner of the Site in the area of the former fuel oil and diesel USTs, and in limited areas surrounding the six leaching pool networks and two septic tanks. Roux Associates will target geophysical survey activities on areas that are previously uninvestigated including the areas east south and southwest of the Cendant building and the area surrounding the Manufacturing building. Soil borings will be added to the scope of work if necessary, to address any additional areas of

concern located during the geophysical survey (i.e. suspected or previously unidentified leach pools, dry wells, USTs, etc.).

Interior portions of the Cendant, Manufacturing and Storage buildings may be selected to undergo geophysical survey as warranted based on the findings of the building inspection, and soil borings will be added to the scope of work if needed to address any pertinent findings.

4.3.3 Gore Module Installation

The Gore modules are proposed to be installed in a grid pattern as shown on Figure 3 of the RI Work Plan. Each Gore module will be installed in a one-inch diameter hole drilled through the building slab or asphalt surface completion and extending to approximately six inches below the slab or asphalt. One dedicated Gore module will be installed within each borehole, capped with a sealing device, and left in place for 10-14 days. Following the required exposure period, the Gore modules will be retrieved, returned to their respective sample jars, and submitted to Gore Technologies for analysis under standard chain of custody procedures. Gore modules will analyzed for VOCs and SVOCs using a modified 8260/8270 methodology.

As described in Section 3.3 above, 40 Gore Modules were installed in November 2010, and the results were used to select locations for additional investigation.

4.3.4 Soil Vapor Samples from Soil Borings

Soil vapor samples will be collected from areas outside of the building from temporary soil vapor points installed using a Geoprobe rig, Geoprobe hand tools, or manually driven method, to the target depth of five feet. Once the target depth is achieved the rods will be pulled up two feet, exposing a void space. New Teflon lined tubing will be attached to the expendable soil vapor sampling point inside the rods, to prevent infiltration of ambient air. Soil vapor sampling will take place approximately one week following installation of the temporary soil vapor points.

The sample tubing will be connected to a ‘T’ connector, with one end leading to a vacuum pump and the other end leading to a pre-evacuated SUMMA canister with a laboratory calibrated regulator set to collect a sample over a one-hour interval (100 milliliters per minute). Prior to sample collection, the Teflon^{TM}-lined tubing will be purged of approximately two volumes of the

tubing using a vacuum pump set at a rate of 0.2 liters per minute. A tracer gas (i.e., laboratory grade helium) will be used to enrich the atmosphere in the immediate vicinity of the sampling location in order to test the borehole seal and verify that ambient air is not being drawn into the sample. Following purging and verification with the tracer gas, the valve leading to the pump will be closed, and the soil vapor sample will be directed to the laboratory supplied six-liter SUMMA canister. In addition to the soil vapor samples, one ambient air sample will also be collected in the vicinity of the soil vapor locations to provide background results. Soil vapor samples and the ambient air sample will be submitted for laboratory analysis under chain of custody procedures for analysis using USEPA Method TO-15 for VOCs.

4.3.5 Sub-Slab Soil Vapor Samples

Sample locations for sub-slab soil vapor samples will be selected based on areas of known or suspected industrial activities and the results of the Gore module screening. Sub-slab vapor samples will be collected directly below the slab, by penetrating the floor slab using a hammer drill to create a 1-inch diameter hole in the concrete down to 6–inches below the slab. The sample tubing will be placed through this hole and will be held in place and sealed with a clay seal.

The sample tubing will be connected to a 'T' connector, with one end leading to a vacuum pump and the other end leading to a pre-evacuated SUMMA canister with a laboratory calibrated regulator set to collect a sample over a one-hour interval (100 milliliters per minute). Prior to sample collection, the Teflon^{TM}-lined tubing will be purged of approximately two volumes of the tubing using a vacuum pump set at a rate of 0.2 liters per minute. A tracer gas (i.e., helium) will be used to enrich the atmosphere in the immediate vicinity of the sampling location in order to test the borehole seal and verify that ambient air is not being drawn into the sample. Following purging and verification with the tracer gas, the valve leading to the pump will be closed, and the soil vapor sample will be directed to the laboratory supplied six-liter SUMMA canister. In addition to the soil vapor samples, two ambient air samples will also be collected in the vicinity of some soil vapor locations to provide background results. Soil vapor samples and will be submitted to for laboratory analysis under chain of custody procedures for analysis using USEPA Method TO-15 for VOCs. The detection limits for all Matrix 1 compounds will be less than 0.25 $\mu g/m^3$, as required in the New York State Department of Health Guidance.

When sub-slab vapor samples are collected, the following actions/conditions will be documented to aid in the interpretation of the sampling results:

a. floor plan sketches that include the floor layout with sample locations, former chemical storage areas, garages, doorways, stairways, location of basement sumps or subsurface drains and utility perforations through building foundations, compass orientation (north), and any other pertinent information should be noted;

b. if possible, photographs will accompany floor plan sketches;

c. weather conditions (e.g., precipitation, indoor and outdoor temperature, and barometric pressure) and ventilation conditions (e.g., windows/doors closed) will be reported; and

d. any pertinent observations, such as spills, floor stains, and odors will be recorded.

4.3.6 Outdoor Ambient Air Sample

One outdoor air sample will be collected concurrently with the soil vapor sampling. The outdoor air sample will serve to better define the background atmospheric conditions within the area. This sample will be collected in a Summa canister over a one-hour interval and analyzed for VOCs using USEPA method TO-15. This canister will be placed in locations chosen to provide representative background results based on Site conditions at the time of sampling.

5.0 SAMPLE HANDLING AND ANALYSIS

To ensure quality data acquisition and collection of representative samples, there are selective procedures to minimize sample degradation or contamination. These include procedures for preservation of the samples as well as sample packaging and shipping procedures.

5.1 Field Sample Handling

A detailed discussion of the number and types of samples to be collected during each task, as well as the analyses to be performed can be found in Section 3.0 of this FSP. The types of containers, volumes needed, and preservation techniques for the aforementioned testing parameters are presented in Table 2.

5.2 Sample Custody Documentation

The purpose of documenting sample custody is to confirm that the integrity and handling of the samples is not subject to question. Sample custody will be maintained from the point of sampling through the analysis. Specific procedures regarding sample tracking from the field to the laboratory are described in Roux Associates' SOP for Sample Handling (Attachment 1).

Each individual collecting samples is personally responsible for the care and custody of the samples. All sample labels should be pre-printed or filled out using waterproof ink. The technical staff will review all field activities with the Field Team Leader to determine whether proper custody procedures were followed during the fieldwork and to decide if additional samples are required.

All samples being shipped off-site for analysis must be accompanied by a properly completed chain of custody form (Attachment 2). The sample numbers will be listed on the chain of custody form. When transferring the possession of samples, individuals relinquishing and receiving will sign, date, and note the time on the record. This record documents transfer of custody of samples from the sampler to another person, to/from a secure storage area, and to the laboratory.

Samples will be packaged for laboratory pick up and/or shipment with a separate signed custody record enclosed in each sample box or cooler. Shipping containers will be locked and/or secured with strapping tape in at least two locations for shipment to the laboratory.

5.3 Sample Shipment

Laboratory courier services will be used for sample transport on this project. However, in the event that samples are shipped to the laboratory the following procedures will apply. Sample packaging and shipping procedures are based upon USEPA specifications, as well as U.S. Department of Transportation (DOT) regulations. The procedures vary according to potential sample analytes, concentration, and matrix, and are designed to provide optimum protection for the samples and the public. Sample packaging and shipment must be performed using the general outline described below. Additional information regarding sample handling is provided in Roux Associates' SOP for Sample Handling (Attachment 1).

All samples will be shipped within 12 hours of collection (when possible) and will be preserved appropriately from the time of sample collection. A description of the sample packing and shipping procedures is presented below:

1. Prepare cooler(s) for shipment.
   - Tape drain(s) of cooler shut;
   - Affix "This Side Up" arrow labels and "Fragile" labels on each cooler; and
   - Place mailing label with laboratory address on top of cooler(s).
2. Arrange sample containers in groups by sample number or analyte.
3. Ensure that all bottle labels are completed correctly. Place clear tape over bottle labels to prevent moisture accumulation from causing the label to peel off.
4. Arrange containers in front of assigned coolers.
5. Place packaging material at the bottom of the cooler to act as a cushion for the sample containers.
6. Arrange containers in the cooler so that they are not in contact with the cooler or other samples.
7. Fill remaining spaces with packaging material.
8. Ensure all containers are firmly packed with packaging material.
9. If ice is required to preserve the samples, ice cubes should be repackaged in double Zip-Lock™ bags, and placed on top of the packaging material.
10. Sign chain of custody form (or obtain signature) and indicate the time and date it was relinquished to Federal Express or other carrier, as appropriate.

11. Separate chain of custody forms. Seal proper copies within a large Zip-Lock™ bag and tape to cooler. Retain copies of all forms.

12. Close lid and latch.

13. Secure each cooler using custody seals.

14. Tape cooler shut on both ends.

15. Relinquish to Federal Express or other courier service as appropriate. Retain airbill receipt for project records. (Note: All samples will be shipped for "NEXT A.M." delivery).

16. Telephone laboratory contact and provide him/her with the following shipment information:

    - sampler's name;
    - project name;
    - number of samples sent according to matrix and concentration; and
    - airbill number.

6.0 SITE CONTROL PROCEDURES

Site control procedures, including decontamination and waste handling and disposal, are discussed below.

6.1 Decontamination

In an attempt to avoid the spread of contamination, all drilling and sampling equipment must be decontaminated at a reasonable frequency in a properly designed and located decontamination area. Detailed procedures for the decontamination of field and sampling equipment are included in Roux Associates' SOPs for the Decontamination of Field Equipment, which is provided in Attachment 1. The location of the decontamination area will be determined prior to the start of field operations. The decontamination area will be constructed to ensure that all wash water generated during decontamination can be collected and containerized for proper disposal.

6.2 Waste Handling and Disposal

All waste materials (drill cuttings, decontamination water, etc.) generated during the RI will be consolidated and stored in appropriate bulk containers (drums, etc.), and temporarily staged at an investigation-derived-waste storage area onsite. Roux Associates will then coordinate waste characterization and disposal by appropriate means.

Table 1. Remedial Investigation Field and Quality Control Sampling Summary

Sample Medium	Target Analytes	Field Samples	Replicates[1]	Trip Blanks[2]	Field Blanks[3]	Matrix Spikes[1]	Spike Duplicates[1]	Total No. of Samples
Soil	TCL VOCs	54	3	10	10	3	3	83
	TCL SVOCs +20	54	3		10	3	3	73
	TCL Pesticides	54	3		10	3	3	73
	TCL PCBs	54	3		10	3	3	73
	TAL Metals	54	3		10	3	3	73
	Total Cyanide	54	3		10	3	3	73
	TPH	54	3		10	3	3	73
Groundwater	TCL VOCs	24	2	2	2	2	2	34
	TAL Metals (total)	24	2		2	2	2	32
	TAL Metals (dissolved)	24	2		2	2	2	32
Gore Sorber Modules	Modified VOC/SVOC	40	0	2	0	0	0	42
Soil Vapor	TO-15 VOCs	10	0	0	0	0	0	10

[1] Based on 1 per 20 samples or 1 per Sample Delivery Group (3 days max)

[2] Based on 1 cooler per day

[3] Based on 1 per day

TCL - USEPA Contract Laboratory Program Target Compound List

VOCs - Volatile Organic Compounds

SVOCs - Semivolatile Organic Compounds

PCBs - Polychlorinated Biphenyls

TAL - USEPA Contract Laboratory Program Target Analyte List

Table 2. Preservation, Holding Times and Sample Containers

Analysis	Bottle Type	Preservation(a)	Holding Time(b)
Total Petroleum Hydrocarbons (TPH) 8015 Gas Range Organics	2 oz wide mouth glass, teflon lined cap	Cool to 4°C	14 days from sample collection
Total Petroleum Hydrocarbons (TPH) 8015 Diesel Range Organics	8 oz wide mouth glass, teflon lined cap	Cool to 4°C	14 days to extract, 40 days to analysis
Target Analyte List (TAL) Metals (total) SW-846 6010/7471	8 oz wide mouth glass, teflon lined cap	Cool to 4°C	180 days, Hg 28 days
Target Analyte List (TAL) Metals (dissolved) SW-846 6010/7471	8 oz wide mouth glass, teflon lined cap	Cool to 4°C	180 days, Hg 28 days
Total Cyanide SW-846 9012B	8 oz wide mouth glass, teflon lined cap	Cool to 4°C	14 days from sample collection
TO-15	6 liter Summa Canister	None	14 days from sample collection
Target Compound List (TCL)			
TCL Volatile Organic Compounds (VOCs) SW-846 8260B	2 oz wide mouth glass, teflon lined cap	Cool to 4°C	14 days from sample collection
TCL Semivolatile Organic Compounds (SVOCs) SW-846 8270C	8 oz wide mouth glass, teflon lined cap	Cool to 4°C	14 days to extract, 40 days to analysis
TCL Pesticides SW-846 8081A	8 oz wide mouth glass, teflon lined cap	Cool to 4°C	14 days to extract, 40 days to analysis
TCL Polychlorinated biphenyls (PCBs) SW-846 8082	8 oz wide mouth glass, teflon lined cap	Cool to 4°C	14 days to extract, 40 days to analysis

(a) All soil and groundwater samples to be preserved in ice during collection and transport

(b) Days from date of sample collection.

Attachment 1

Roux Associates'
Standard Operating Procedure for
Tasks Described in this Field Sampling Plan

Date: May 5, 2000

1.0 PURPOSE

The purpose for this standard operating procedure (SOP) is to establish the guidelines for decontamination of all field equipment potentially exposed to contamination during drilling, and soil and water sampling. The objective of decontamination is to ensure that all drilling, and soil-sampling and water-sampling equipment is decontaminated (free of potential contaminants): 1) prior to being brought onsite to avoid the introduction of potential contaminants to the site; 2) between drilling and sampling events/activities onsite to eliminate the potential for cross-contamination between boreholes and/or wells; and 3) prior to the removal of equipment from the site to prevent the transportation of potentially contaminated equipment offsite.

In considering decontamination procedures, state and federal regulatory agency requirements must be considered because of potential variability between state and federal requirements and because of variability in the requirements of individual states. Decontamination procedures must be in compliance with state and/or federal protocols in order that regulatory agency(ies) scrutiny of the procedures and data collected do not result in non acceptance (invalidation) of the work undertaken and data collected.

2.0 PROCEDURE FOR DRILLING EQUIPMENT

The following is a minimum decontamination procedure for drilling equipment. Drilling equipment decontamination procedures, especially any variation from the method itemized below, will be documented on an appropriate field form or in the field notebook.

2.1 The rig and all associated equipment should be properly decontaminated by the contractor before arriving at the test site.

2.2 The augers, drilling casings, rods, samplers, tools, rig, and any piece of equipment that can come in contact (directly or indirectly) with the soil, will be steam cleaned onsite prior to set up for drilling to ensure proper decontamination.

2.3 The same steam cleaning procedures will be followed between boreholes (at a fixed on-site location[s], if appropriate) and before leaving the site at the end of the study.

2.4 All on-site steam cleaning (decontamination) activities will be monitored and documented by a member(s) of the staff of Roux Associates, Inc.

2.5 If drilling activities are conducted in the presence of thick, sticky oils (e.g., PCBs) which coat drilling equipment, then special decontamination procedures may have to be utilized before steam cleaning (e.g., hexane scrub and wash).

2.6 Containment of decontamination fluids may be necessary (e.g., rinseate from steam cleaning) or will be required (e.g., hexane), and disposal must be in accordance with state and/or federal procedures.

3.0 PROCEDURE FOR SOIL-SAMPLING EQUIPMENT

The following is a minimum decontamination procedure for soil-sampling equipment (e.g., split spoons, stainless-steel spatulas). Soil-sampling equipment decontamination procedures, especially any variation from the method itemized below, will be documented on an appropriate field form or in the field notebook.

3.1 Wear disposable gloves while cleaning equipment to avoid cross-contamination and change gloves as needed.

3.2 Steam clean the sampler or rinse with potable water. If soil-sampling activities are conducted in the presence of thick, sticky oils (e.g., PCBs) which coat sampling equipment, then special decontamination procedures may have to be utilized before steam cleaning and washing in detergent solution (e.g., hexane scrub and wash).

3.3 Prepare a non-phosphate, laboratory-grade detergent solution and distilled or potable water in a clean bucket.

3.4 Disassemble the sampler, as necessary and immerse all parts and other sampling equipment in the solution.

3.5 Scrub all equipment in the bucket with a brush to remove any adhering particles.

3.6 Rinse all equipment with copious amounts of potable water followed by distilled or deionized water.

3.7 Place clean equipment on a clean plastic sheet (e.g., polyethylene)

3.8 Reassemble the cleaned sampler, as necessary.

3.9 Transfer the sampler to the driller (or helper) making sure that this individual is also wearing clean gloves, or wrap the equipment with a suitable material (e.g., plastic bag, aluminum foil.

As part of the decontamination procedure for soil-sampling equipment, state and/or federal protocols must be considered. These may require procedures above those specified as minimum for Roux Associates, Inc., such as the use of nitric acid, acetone, etc. Furthermore, the containment and proper disposal of decontamination fluids must be considered with respect to regulatory agency(ies) requirements.

4.0 PROCEDURE FOR WATER-SAMPLING EQUIPMENT

The following is a decontamination procedure for water-sampling equipment (e.g., bailers, pumps). Water-sampling equipment decontamination procedures, especially any variation from the method itemized below, will be documented on an appropriate field form or in the field notebook.

4.1 Decontamination procedures for bailers follow:

a. Wear disposable gloves while cleaning bailer to avoid cross-contamination and change gloves as needed.

b. Prepare a non-phosphate, laboratory-grade detergent solution and potable water in a bucket.

c. Disassemble bailer (if applicable) and discard cord in an appropriate manner, and scrub each part of the bailer with a brush and solution.

d. Rinse with potable water and reassemble bailer.

e. Rinse with copious amounts of distilled or deionized water.

f. Air dry.

g. Wrap equipment with a suitable material (e.g., clean plastic bag, aluminum foil).

h. Rinse bailer at least three times with distilled or deionized water before use.

4.2 Decontamination procedures for pumps follow:

a. Wear disposable gloves while cleaning pump to avoid cross-contamination and change gloves as needed.

b. Prepare a non-phosphate, laboratory-grade detergent solution and potable water in a clean bucket, clean garbage can, or clean 55-gallon drum.

c. Flush the pump and discharge hose (if not disposable) with the detergent solution, and discard disposable tubing and/or cord in an appropriate manner.

d. Flush the pump and discharge hose (if not disposable) with potable water.

e. Place the pump on clear plastic sheeting.

f. Wipe any pump-related equipment (e.g., electrical lines, cables, discharge hose) that entered the well with a clean cloth and detergent solution, and rinse or wipe with a clean cloth and potable water.

g. Air dry.

h. Wrap equipment with a suitable material (e.g., clean plastic bag).

As part of the decontamination procedure for water-sampling equipment, state and/or federal protocols must be considered. These may require procedures above those specified as minimum for Roux Associates, Inc., such as the use of nitric acid, acetone, etc. Furthermore, the containment and proper disposal of decontamination fluids must be considered with respect to regulatory agency(ies) requirements.

Date: May 5, 2000

1.0 PURPOSE

The purpose of this Standard Operating Procedure (SOP) is to establish guidelines for the collection of soil samples for laboratory analysis. This SOP is applicable to soil samples collected from split-spoon samplers during drilling, hand auger samples, grab samples from stockpiled soils, surface samples, test pit samples, etc.

2.0 CONSIDERATIONS

Soil samples may be collected in either a random or biased manner. Random samples can be based on a grid system or statistical methodology. Biased samples can be collected in areas of visible impact or suspected source areas. Soil samples can be collected at the surface, shallow subsurface, or at depth. When samples are collected at depth the water content should be noted, since generally "soil sampling" is restricted to the unsaturated zone. Equipment selection will be determined by the depth of the sample to be collected. A thorough description of the sampling locations and proposed methods of sample collection should be included in the work plan.

Commonly, surface sampling refers to the collection of samples at a 0 to 6 inch depth interval. Certain regulatory agencies may define the depth interval of a surface sample differently, and this must be defined in the work plan. Collection of surface soil samples is most efficiently accomplished with the use of a stainless steel trowel or scoop. For samples at greater depths a decontaminated bucket auger or power auger may be needed to advance the hole to the point of sample collection. Another clean bucket auger should then be used to collect the sample. To collect samples at depths of greater than approximately six feet the use of a drill rig and split spoon samples will usually be necessary. In some situations, sample locations are accessed with the use of a backhoe.

3.0 MATERIALS/EQUIPMENT

a. A work plan which outlines soil sampling requirements.

b. Field notebook, field form(s), maps, chain-of-custody forms, and custody seals.

c. Decontamination supplies (including: non-phosphate, laboratory grade detergent, buckets, brushes, potable water, distilled water, regulatory-required reagents, aluminum foil, plastic sheeting, etc.).

d. Sampling device (split-spoon sampler, stainless steel hand auger, stainless steel trowel, etc.).

e. Stainless steel spoons or spatulas.

f. Disposable sampling gloves.

g. Laboratory-supplied sample containers with labels.

h. Cooler with blue or wet ice.

i. Plastic sheeting.

j. Black pen and indelible marker.

k. Zip-lock bags and packing material.

l. Tape measure.

m. Paper towels or clean rags.

n. Masking and packing tape.

o. Overnight (express) mail forms.

4.0 DECONTAMINATION

All reusable sampling equipment will be thoroughly cleaned according to the decontamination SOP. Where possible, thoroughly pre-cleaned and wrapped sampling equipment should be used and dedicated to individual sampling locations. Disposable items such as sampling gloves, aluminum foil, and plastic sheeting will be changed after each use and discarded in an appropriate manner.

5.0 PROCEDURE

5.1 Prior to collecting soil samples, ensure that all sampling equipment has been thoroughly cleaned according to the decontamination SOP. If samples are to be collected at depth, then the boring must be advanced with thoroughly cleaned equipment to the desired sampling horizon and a different thoroughly cleaned sampler must be used to collect the sample.

5.2 Using disposable gloves and a pre-cleaned, stainless steel spatula or spoon, extract the soil sample from the sampler, measure the recovery, and separate the wash from the true sample. Where allowed by regulatory agency(ies), disposable plastic spoons may be used.

5.3 Place the sample in a laboratory-supplied, pre-cleaned sample container. This should be done as quickly as possible and this is especially important when sampling for volatile organic compounds (VOCs). Samples to be analyzed for VOCs must be collected prior to other constituents.

5.4 The sample container will be labeled with appropriate information such as, client name, site location, sample identification (location, depth, etc.), date and time of collection, and sampler's initials.

5.5 Using the remaining portion of soil from the sampler, log the sample in detail and record sediment characteristics (color, odor, moisture, texture, density, consistency, organic content, layering, grain size, etc.).

5.6 If soil samples are to be composited in the field, then equal portions from selected locations will be placed on a clean plastic sheet and homogenized. Alternately, several samples may be submitted to the laboratory for compositing by weight. The method used is dependent upon regulatory requirements. Specific compositing procedures shall be approved by the appropriate regulatory agency and described in the work plan. Samples to be analyzed for VOCs will not be composited unless required by a regulatory agency.

5.7 After the sample has been collected, labeled, and logged in detail, it is placed in a zip-lock bag and stored in a cooler at 4°C.

5.8 A chain-of-custody form is completed for all samples collected. One copy is retained and two are sent with the samples in a zip-lock bag to the laboratory. A custody seal is placed on the cooler prior to shipment.

5.9 Samples collected from Monday to Friday are to be delivered to the laboratory within 24 hours of collection. If Saturday delivery is unavailable, samples collected on Friday must be delivered by Monday morning. Check the work plan to determine if any analytes require a shorter delivery time.

5.10 The field notebook and appropriate forms should include, but not be limited to the following: client name, site location, sample location, sample depth, sample identification, date and time collected, sampler's name, method of sample collection, number and type of containers, geologic description of material, description of decontamination procedures, etc. A site map should be prepared with exact measurements to each sample location in case follow-up sampling is necessary.

5.11 All reusable sampling equipment must be thoroughly cleaned in accordance with the decontamination SOP. Following the final decontamination (after all samples are collected) the sampling equipment is wrapped in aluminum foil. Discard any gloves, foil, plastic, etc. in an appropriate manner that is consistent with site conditions.

END OF PROCEDURE

Date: May 5, 2000

1.0 PURPOSE

The purpose of this standard operating procedure (SOP) is to establish guidelines for sample handling which will allow consistent and accurate results. Valid chemistry data are integral to investigations that characterize media-quality conditions. Thus, this SOP is designed to ensure that once samples are collected, they are preserved, packed and delivered in a manner which will maintain sample integrity to as great an extent as possible. The procedures outlined are applicable to most sampling events and any required modifications must be clearly described in the work plan.

2.0 CONSIDERATIONS

Sample containers, sampling equipment decontamination, quality assurance/quality control (QA/QC), sample preservation, and sample handling are all components of this SOP.

2.1 Sample Containers

Prior to collection of a sample, considerations must be given to the type of container that will be used to store and transport the sample. The type and number of containers selected is usually based on factors such as sample matrix, potential contaminants to be encountered, analytical methods requested, and the laboratory's internal quality assurance requirements. In most cases, the overriding considerations will be the analytical methodology, or the state or federal regulatory requirements because these regulations generally encompass the other factors. The sample container selected is usually based on some combination of the following criteria:

a. Reactivity of Container Material with Sample

Choosing the proper composition of sample containers will help to ensure that the chemical and physical integrity of the sample is maintained. For sampling potentially hazardous material, glass is the recommended container type because it is chemically inert to most substances. Plastic containers are not recommended for most hazardous wastes because the potential exists for contaminants to adsorb to the surface of the plastic or for the plasticizer to leach into the sample.

In some instances, however, the sample characteristics or analytes of interest may dictate that plastic containers be used instead of glass. Because some metals species will adhere to the sides of the glass containers in an aqueous matrix, plastic bottles (e.g., nalgene) must be used for samples collected for metals analysis. A separate, plastic

container should accompany glass containers if metals analysis is to be performed along with other analyses. Likewise, other sample characteristics may dictate that glass cannot be used. For example, in the case of a strong alkali waste or hydrofluoric solution, plastic containers may be more suitable because glass containers may be etched by these compounds and create adsorptive sites on the container's surface.

b. Volume of the Container

The volume of sample to be collected will be dictated by the analysis being performed and the sample matrix. The laboratory must supply bottles of sufficient volume to perform the required analysis. In most cases, the methodology dictates the volume of sample material required to complete the analysis. However, individual laboratories may provide larger volume containers for various analytes to ensure sufficient quantities for duplicates or other QC checks.

To facilitate transfer of the sample from the sampler into the container and to minimize spillage and sample disturbance, wide-mouth containers are recommended. Aqueous volatile organic samples must be placed into 40-milliliter (ml) glass vials with polytetrafluoroethylene (PTFE) (e.g., TeflonTM) septums. Non-aqueous volatile organic samples should be collected in the same type of vials or in 4-ounce (oz) wide-mouth jars provided by the laboratory. These jars should have PTFE-lined screw caps.

c. Color of Container

Whenever possible, amber glass containers should be used to prevent photodegradation of the sample, except when samples are being collected for metals analysis. If amber containers are not available, then containers holding samples should be protected from light (i.e., place in cooler with ice immediately after filling).

d. Container Closures

Container closures must screw on and off the containers and form a leak-proof seal. Container caps must not be removed until the container is ready to be filled with the sample, and the container cap must be replaced (securely) immediately after filling it. Closures should be constructed of a material which is inert with respect to the sampled material, such as PTFE (e.g., TeflonTM). Alternately, the closure may be separated from the sample by a closure liner that is inert to the sample material such as PTFE sheeting. If soil or sediment samples are being collected, the threads of the container must be wiped clean with a dedicated paper towel or cloth so the cap can be threaded properly.

e. Decontamination of Sample Containers

Sample containers must be laboratory cleaned by the laboratory performing the analysis. The cleaning procedure is dictated by the specific analysis to be performed on the sample. Sample containers must be carefully examined to ensure that all containers appear clean. Do not mistake the preservative as unwanted residue. The bottles should not be field cleaned. If there is any question regarding the integrity of the bottle, then the laboratory must be contacted immediately and the bottle(s) replaced.

f. Sample Bottle Storage and Transport

No matter where the sample bottles are, whether at the laboratory waiting to be packed for shipment or in the field waiting to be filled with sample, care must be taken to avoid contamination. Sample shuttles or coolers, and sample bottles must be stored and transported in clean environments. Sample bottles and clean sampling equipment must never be stored near solvents, gasoline, or other equipment that is a potential source of cross-contamination. When under chain of custody, sample bottles must be secured in locked vehicles, and custody sealed in shuttles or in the presence of authorized personnel. Information which documents that proper storage and transport procedures have been followed must be included in the field notebook and on appropriate field forms.

2.2 Decontamination of Sampling Equipment

Proper decontamination of all re-usable sampling equipment is critical for all sampling episodes. The SOP for Decontamination of Field Equipment and SOPs for method-specific or instrument-specific tasks must also be referred to for guidance for decontamination of various types of equipment.

2.3 Quality Assurance/Quality Control Samples

QA/QC samples are intended to provide control over the proper collection and tracking of environmental measurements, and subsequent review, interpretation and validation of generated analytical data. The SOPs for Collection of Quality Control Samples, for Evaluation and Validation of Data, and for Field Record Keeping and Quality Assurance/Quality Control must be referred to for detailed guidance regarding these respective procedures. SOPs for method-specific or instrument-specific tasks must also be referred to for guidance for QA/QC procedures.

2.4 Sample Preservation Requirements

Certain analytical methodologies for specific analytes require chemical additives in order to stabilize and maintain sample integrity. Generally, this is accomplished under the following two scenarios:

a. Sample bottles are preserved at the laboratory prior to shipment into the field.

b. Preservatives are added in the field immediately after the samples are collected.

Many laboratories provide pre-preserved bottles as a matter of convenience and to help ensure that samples will be preserved immediately upon collection. A problem associated with this method arises if not enough sample could be collected, resulting in too much preservative in the sample. More commonly encountered problems with this method include the possibility of insufficient preservative provided to achieve the desired pH level or the need for additional preservation due to chemical reactions caused by the addition of sample liquids to pre-preserved bottles. The use of pre-preserved bottles is acceptable; however, field sampling teams must always be prepared to add additional preservatives to samples if the aforementioned situations occur. Furthermore, care must be exercised not to overfill sample bottles containing preservatives to prevent the sample and preservative from spilling and therefore diluting the preservative (i.e., not having enough preservative for the volume of sample).

When samples are preserved after collection, special care must be taken. The transportation and handling of concentrated acids in the field requires additional preparation and adherence to appropriate preservation procedures. All preservation acids used in the field should be trace-metal or higher-grade.

2.5 Sample Handling

After the proper sample bottles have been received under chain-of-custody, properly decontaminated equipment has been used to collect the sample, and appropriate preservatives have been added to maintain sample integrity, the final step for the field personnel is checking the sample bottles prior to proper packing and delivery of the samples to the laboratory.

All samples should be organized and the labels checked for accuracy. The caps should be checked for tightness and any 40-ml volatile organic compound (VOC) bottles must be checked for bubbles. Each sample bottle must be placed in an individual "zip-lock" bag to protect the label, and placed on ice. The bottles must be carefully packed to prevent breakage during transport. When several bottles have been collected for an individual sample, they should not be placed adjacent to each other in the cooler to prevent possible breakage of all bottles for a given sample. If there are any samples which are known or suspected to be highly

contaminated, these should be placed in an individual cooler under separate chain-of-custody to prevent possible cross contamination. Sufficient ice (wet or blue packs) should be placed in the cooler to maintain the temperature at 4 degrees Celsius (°C) until delivery at the laboratory. Consult the work plan to determine if a particular ice is specified as the preservation for transportation (e.g., the United States Environmental Protection Agency does not like the use of blue packs because they claim that the samples will not hold at 4°C). If additional coolers are required, then they should be purchased. The chain-of-custody form should be properly completed, placed in a "zip-lock" bag, and placed in the cooler. One copy must be maintained for the project files. The cooler should be sealed with packing tape and a custody seal. The custody seal number should be noted in the field book. Samples collected from Monday through Friday will be delivered to the laboratory within 24 hours of collection. If Saturday delivery is not available, samples collected on Friday must be delivered by Monday morning. Check the work plan to determine if certain analytes require a shorter delivery time. If overnight mail is utilized, then the shipping bill must be maintained for the files and the laboratory must be called the following day to confirm receipt.

3.0 EQUIPMENT AND MATERIALS

3.1 General equipment and materials may include, but not necessarily be limited to, the following:

a. Sample bottles of proper size and type with labels.

b. Cooler with ice (wet or blue pack).

c. Field notebook, appropriate field form(s), chain-of-custody form(s), custody seals.

d. Black pen and indelible marker.

e. Packing tape, "bubble wrap," and "zip-lock" bags.

f. Overnight (express) mail forms and laboratory address.

g. Health and safety plan (HASP).

h. Work plan/scope of work.

i. Pertinent SOPs for specified tasks and their respective equipment and materials.

3.2 Preservatives for specific samples/analytes as specified by the laboratory. Preservatives must be stored in secure, spillproof glass containers with their content, concentration, and date of preparation and expiration clearly labeled.

3.3 Miscellaneous equipment and materials including, but not necessarily limited to, the following:

a. Graduated pipettes.

b. Pipette bulbs.

c. Litmus paper.

d. Glass stirring rods.

e. Protective goggles.

f. Disposable gloves.

g. Lab apron.

h. First aid kit.

i. Portable eye wash station.

j. Water supply for immediate flushing of spillage, if appropriate.

k. Shovel and container for immediate containerization of spillage-impacted soils, if appropriate.

4.0 PROCEDURE

4.1 Examine all bottles and verify that they are clean and of the proper type, number, and volume for the sampling to be conducted.

4.2 Label bottles carefully and clearly with project name and number, site location, sample identification, date, time, and the sampler's initials using an indelible marker.

4.3 Collect samples in the proper manner (refer to specific sampling SOPs).

4.4 Conduct preservation activities as required after each sample has been collected. Field preservation must be done immediately and must not be done later than 30 minutes after sample collection.

4.5 Conduct QC sampling, as required.

4.6 Seal each container carefully and place in an individual "zip lock" bag.

4.7 Organize and carefully pack all samples in the cooler immediately after collection (e.g., bubble wrap). Insulate samples so that breakage will not occur.

4.8 Complete and place the chain-of-custody form in the cooler after all samples have been collected. Maintain one copy for the project file. If the cooler is to be transferred several times prior to shipment or delivery to the laboratory, it may be easier to tape the chain-of-custody to the exterior of the sealed cooler. When exceptionally hazardous samples are known or suspected to be present, this should be identified on the chain-of-custody as a courtesy to the laboratory personnel.

4.9 Add additional ice as necessary to ensure that it will last until receipt by the laboratory.

4.10 Seal the cooler with packing tape and a custody seal. Record the number of the custody seal in the field notebook and on the field form. If there are any exceptionally hazardous samples, then shipping regulations should be examined to ensure that the sample containers and coolers are in compliance and properly labeled.

4.11 Samples collected from Monday through Friday will be delivered to the laboratory within 24 hours of collection. If Saturday delivery is not available, samples collected on Friday must be delivered by Monday morning. Check the work plan to determine if certain analytes require a shorter delivery time.

4.12 Maintain the shipping bill for the project files if overnight mail is utilized and call the laboratory the following day to confirm receipt.

END OF PROCEDURE

Date: May 5, 2000

1.0 PURPOSE

The purpose of this standard operating procedure (SOP) is to establish guidelines for the sampling of ground-water monitoring wells for dissolved constituents. As part of the SOP for the sampling of ground-water monitoring wells, sample collection equipment and devices must be considered, and equipment decontamination and pre-sampling procedures (e.g., measuring water levels, sounding wells, and purging wells) must be implemented. Sampling objectives must be firmly established in the work plan before considering the above.

Valid water-chemistry data are integral to a hydrogeologic investigation that characterizes ground-water quality conditions. Water-quality data are used to evaluate both current and historic aquifer chemistry conditions, as well as to estimate future conditions (e.g., trends, migration pathways). Water-quality data can be used to construct ground-water quality maps to illustrate chemical conditions within the flow system, to generate water-quality plots to depict conditions with time and trends, and to perform statistical analyses to quantify data variability, trends, and cleanup levels.

2.0 EQUIPMENT AND MATERIALS

2.1 In order to sample ground water from monitoring wells, specific equipment and materials are required. The equipment and materials list may include, but not necessarily be limited to, the following:

a. Bailers (Teflon™ or stainless steel).

b. Pumps (centrifugal, peristaltic, bladder, electric submersible, bilge, hand-operated diaphragm, etc.).

c. Gas-displacement device(s).

d. Air-lift device(s).

e. Teflon™ tape, electrical tape.

f. Appropriate discharge hose.

g. Appropriate discharge tubing (e.g., polypropylene, teflon, etc.) if using a peristaltic pump.

h. Appropriate compressed gas if using bladder-type or gas-displacement device.

i. Portable generator and gasoline or alternate power supply if using an electric submersible pump.

j. Non-absorbent cord (e.g., polypropylene, etc.).

k. Plastic sheeting.

l. Tape measure (stainless steel, steel, fiberglass) with 0.01-foot measurement increments and chalk (blue carpenter's).

m. Electronic water-level indicators (e.g., m-scope, etc.) or electric water-level/product level indicators.

n. Non-phosphate, laboratory-grade detergent.

o. Distilled/Deionized water.

p. Potable water.

q. Paper towels, clean rags.

r. Roux Associates' field forms (e.g., daily log, well inspection checklist, sampling, etc.) and field notebook.

s. Well location and site map.

t. Well keys.

u. Stop watch, digital watch with second increments, or watch with a second hand.

v. Water Well Handbook.

w. Calculator.

x. Black pen and water-proof marker.

y. Tools (e.g., pipe wrenches, screwdrivers, hammer, pliers, flashlight, pen knife, etc.).

z. Appropriate health and safety equipment, as specified in the site health and safety plan (HASP).

aa. pH meter(s) and buffers.

bb. Conductivity meter(s) and standards.

cc. Thermometer(s).

dd. Extra batteries (meters, thermometers, flashlight).

ee. Filtration apparatus, filters, pre-filters.

ff. Plasticware (e.g., premeasured buckets, beakers, flasks, funnels).

gg. Disposable gloves.

hh. Water jugs.

ii. Laboratory-supplied sample containers with labels.

jj. Cooler(s).

kk. Ice (wet, blue packs).

ll. Masking, duct, and packing tape.

mm. Chain-of-custody form(s) and custody seal(s).

nn. Site sampling and analysis plan (SAP).

oo. Site health and safety plan (HASP).

pp. Packing material (e.g., bubble wrap)

qq. "Zip-lock" plastic bags.

rr. Overnight (express) mail forms.

3.0 DECONTAMINATION

3.1 Make sure all equipment is decontaminated and cleaned before use (refer to the SOP for Decontamination of Field Equipment for detailed decontamination methods, summaries for bailers and pumps are provided below). Use new, clean materials when decontamination is not appropriate (e.g., non-absorbent cord, disposable gloves). Document, and initial and date the decontamination procedures on the appropriate field form and in the field notebook.

a. Decontaminate a bailer by: 1) wearing disposable gloves, 2) disassembling (if appropriate) and scrubbing in a non-phosphate, laboratory-grade detergent and distilled/deionized water solution, and 3) rinsing first with potable water and then distilled/deionized water.

b. Decontaminate a pump by: 1) wearing disposable gloves, 2) flushing the pump and discharge hose (if not disposable) first with a non-phosphate, laboratory-grade detergent and potable water solution in an appropriate container (clean bucket, garbage can, or 55-gallon drum) and then with

distilled/deionized water or potable water, and 3) wiping pump-related equipment (e.g., electrical lines, cables, discharge hose) first with a clean cloth and detergent solution and then rinsing or wiping with a clean cloth and distilled/deionized water or potable water.

3.2 Note that the decontamination procedures for bailers and pumps are the minimum that must be performed. Check the work plan to determine if chemicals specified by individual state regulatory agencies must also be used for decontamination procedures (e.g., hexane, nitric acid, acetone, isopropanol, etc.).

4.0 CALIBRATION OF FIELD ANALYSIS EQUIPMENT

Calibrate field analysis equipment before use (e.g., thermometers, pH and conductivity meters, etc.). Refer to the specific SOP for field analysis for each respective piece of equipment. Document, and initial and date the calibration procedures on the appropriate field form, in the field notebook, and in the calibration log book.

5.0 PROCEDURE

5.1 Document, and initial and date well identification, pre-sampling information, and problems encountered on the appropriate field form and in the field notebook as needed.

5.2 Inspect the protective casing of the well and the well casing, and note any items of concern such as a missing lock, or bent or damaged casing(s).

5.3 Place plastic sheeting around the well to protect sampling equipment from potential cross contamination.

5.4 Remove the well cap or plug and, if necessary, clean the top of the well off with a clean rag. Place the cap or plug on the plastic sheeting. If the well is not vented, allow several minutes for the water level in the well to equilibrate. If fumes or gases are present, then diagnose these with the proper safety equipment. Never inhale the vapors.

5.5 Measure the depth to water (DTW) from the measuring point (MP) on the well using a steel tape and chalk or an electronic sounding device (m-scope). Refer to the specific SOPs for details regarding the use of a steel tape or a m-scope for measuring water levels. Calculate the water-level elevation. Document, and initial and date the information on the appropriate field form and in the field notebook.

5.6 Measuring the total depth of the well from the MP with a weighted steel tape. Calculate and record the volume of standing water in the well casing on the appropriate field form and in the field notebook.

5.7 Decontaminate the equipment used to measure the water level and sound the well with a non-phosphate, laboratory-grade detergent solution followed by a distilled/deionized water rinse.

5.8 Purge the well prior to sampling (refer to the SOP for Purging a Well). The well should be pumped or bailed to remove the volume of water specified in the work plan. Usually three to five casing volumes are removed if the recharge rate is adequate to accomplish this within a reasonable amount of time.

If the formation cannot produce enough water to sustain purging, then one of two options must be followed. These include: 1) pumping or bailing the well dry, or 2) pumping or bailing the well to "near-dry" conditions (i.e., leaving some water in the well). The option employed must be specified in the work plan and be in accordance with regulatory requirements.

If the well is purged dry, then all the standing water has been removed and upon recovery the well is ready for sampling. However, depending on the rate of recovery and the time needed to complete the sampling round, one of the following procedures may have to be implemented: 1) the well may have to be sampled over a period of more than one day; 2) the well may not yield enough water to collect a complete suite of samples and only select (most important) samples will be collected; or 3) the well may not recover which will preclude sampling. Regardless of the option that must be followed, the sampling procedure must be fully documented. When preparing to conduct a sampling round, review drilling, development and previous sampling information (if available) to identify low-yielding wells in order to purge them first, and potentially allow time for the well to recover for sampling.

5.9 Record the physical appearance of the water (i.e., color, turbidity, odor, etc.) on the appropriate field form and in the field notebook, as it is purged. Note any changes that occur during purging.

5.10 If a bailer is used to collect the sample, then:

a. Flush the decontaminated bailer three times with distilled/deionized water.

b. Tie the non-absorbent cord (polypropylene) to the bailer with a secure knot and then tie the free end of the bailer cord to the protective casing or, if possible, some nearby structure to prevent losing the bailer and cord down the well.

c. Lower the bailer slowly down the well and into the water column to minimize disturbance of the water surface. If a bottom-filling bailer is used, then do not submerge the top of the bailer; however, if a top-filling bailer is used, then submerge the bailer several feet below the water surface.

d. Remove and properly discard one bailer volume from the well to rinse the bailer with well water before sampling. Again, lower the bailer slowly down the well to the appropriate depth depending on the bailer type (as discussed above in 5.11 c). When removing the bailer from the well, do not allow the bailer cord to rest on the ground but coil it on the protective plastic sheeting placed around the well. Certain regulatory agencies require that the first bailer volume collected be utilized for the samples.

5.11 If a pump is used to collect the sample, then use the same pump used to purge the well and, if need be, reduce the discharge rate to facilitate filling sample containers and to avoid problems that can occur while filling sample containers (as listed in Number 5.14, below). Alternately, the purge pump may be removed and a thoroughly decontaminated bailer can be used to collect the sample.

5.12 Remove each appropriate container's cap only when ready to fill each with the water sample, and then replace and secure the cap immediately.

5.13 Fill each appropriate, pre-labeled sample container carefully and cautiously to prevent: 1) agitating or creating turbulence; 2) breaking the container; 3) entry of, or contact with, any other medium; and 4) spilling/splashing the sample and exposing the sampling team to contaminated water. Immediately place the filled sample container in a ice-filled (wet ice or blue pack) cooler for storage. If wet ice is used it is recommended that it be repackaged in zip-lock bags to help keep the cooler dry and the sample labels secure. Check the work plan as to whether wet ice or blue packs are specified for cooling the samples because certain regulatory agencies may specify the use of one and not the other.

5.14 "Top-off" containers for volatile organic compounds (VOCs) and tightly seal with Teflon™-lined septums held in place by open-top screw caps to prevent volatilization. Ensure that there are no bubbles by turning the container upside down and tapping it gently.

5.15 Filter water samples (Procedure 4.6) collected for dissolved metals analysis prior to preservation to remove the suspended sediment from the sample. If water samples are to be collected for total metals analysis, then collect a second set of samples without field filtering.

In the event that the regulatory agency(ies) want unfiltered samples for metals analysis, a second set of filtered samples should also be collected. Because unfiltered samples are indications of total metals (dissolved and suspended) they are not representative of aquifer conditions because ground water does not transport sediment (except in some rare cases). Thus, the results for dissolved metals in ground water should be based on filtered samples even if both filtered and unfiltered sets are presented in a report.

5.16 Add any necessary preservative(s) to the appropriate container(s) prior to, or after (preferred), the collection of the sample, unless the appropriate preservative(s) have already been added by the laboratory before shipment.

5.17 Collect quality control (QC) samples as required in the work plan to monitor sampling and laboratory performance. Refer to the SOP for Collection of Quality Control Samples.

5.18 Conduct field analyses after sample collection is complete by measuring and recording the temperature, conductivity, pH, etc. (as called for in the work plan). Note and record the "final" physical appearance of the water (after purging and sampling) on an appropriate field form and in the field notebook.

5.19 Wipe the well cap with a clean rag, replace the well cap and protective cover (if present). Lock the protective cover.

5.20 Verify that each sample is placed in an individual "zip-lock" bag, wrapped with "bubble wrap," placed in the cooler, and that the cooler has sufficient ice (wet ice or blue packs) to preserve the samples for transportation to the analytical laboratory.

5.21 Decontaminate bailers, hoses, and pumps as discussed in the decontamination SOP. Wrap decontaminated equipment with a suitable material (e.g., clean plastic bag or aluminum foil). Discard cords, rags, gloves, etc. in a manner consistent with site conditions.

5.22 Complete all necessary field forms, field notebook entries, and the chain-of-custody forms. Retain one copy of each chain-of-custody form. Secure the cooler with sufficient packing tape and a custody seal.

5.23 Samples collected from Monday through Friday will be delivered within 24 hours of collection. If Saturday delivery is not available, samples collected on Friday must be delivered by Monday morning. Consult the work plan to determine if any of the analytes require a shorter delivery time.

END OF PROCUDURE

Attachment 2

Chain of Custody Form

ROUX CHAIN OF CUSTODY

№ 11332 Y

ROUX ASSOCIATES, INC.
Environmental Consulting & Management
209 SHAFTER STREET
ISLANDIA, NEW YORK 11749-5074
(631) 232-2600 FAX: (631) 232-9898

ANALYSES

PAGE OF

PROJECT NAME | PROJECT NUMBER

PROJECT LOCATION

PROJECT MANAGER | SAMPLER(S)

SAMPLE DESIGNATION / LOCATION	DATE COLLECTED	TIME COLLECTED		SAMPLE MATRIX						TOTAL BOTTLES	NOTES

RELINQUISHED BY: (SIGNATURE)	FOR	DATE	TIME	SEAL INTACT Y OR N	RECEIVED BY: (SIGNATURE)	FOR	DATE	TIME	SEAL INTACT Y OR N
RELINQUISHED BY: (SIGNATURE)	FOR	DATE	TIME	SEAL INTACT Y OR N	RECEIVED BY: (SIGNATURE)	FOR	DATE	TIME	SEAL INTACT Y OR N

DELIVERY METHOD

ANALYTICAL LABORATORY

COMMENTS

CHAINOF CDR 12AUG98

APPENDIX E

Quality Assurance Project Plan

January 21, 2011

QUALITY ASSURANCE PROJECT PLAN

900 Old Country Road
Garden City, Town of Hempstead,
Nassau County, New York

Prepared for

EQUITY ONE (NORTHEAST PORTFOLIO) INC.
650 Fifth Avenue, 24th Floor
New York, New York 10019

ROUX ASSOCIATES, INC.

Environmental Consulting & Management

ROUX

209 Shafter Street, Islandia, New York 11749 ♦ 631-232-2600

TABLE OF CONTENTS

1.0 INTRODUCTION E–1

2.0 BACKGROUND, OBJECTIVES, AND SCOPE E–2
- 2.1 Soil E–2
- 2.2 Groundwater E–2
- 2.3 Soil Vapor and Sub Slab Samples E–2

3.0 PROJECT ORGANIZATION E–4

4.0 SAMPLING PROCEDURES E–6

5.0 QUALITY ASSURANCE/QUALITY CONTROL E–7

TABLES

1. Field and Laboratory QC Summary
2. Laboratory Reporting Limits for Soil, Water, and Air Samples

1.0 INTRODUCTION

This Quality Assurance Project Plan (QAPP) has been prepared to describe the measures that will be taken to ensure that the data generated during performance of the Remedial Investigation (RI) at 900 Old Country Road, Garden City, New York (Site) are of quality sufficient to meet project-specific data quality objectives (DQOs). The QAPP was prepared in accordance with the guidance provided in New York State Department of Environmental Conservation (NYSDEC) Technical Guidance DER-10 (Technical Guidance for Site Investigation and Remediation), the Brownfield Cleanup Program Guide and the United States Environmental Protection Agency's (USEPA's) Guidance for the Data Quality Objectives Process (EPA QA/G-4).

2.0 BACKGROUND, OBJECTIVES, AND SCOPE

In order to achieve project objectives, Roux Associates has developed a scope of work that includes sampling of soil, groundwater, and soil vapor. A brief overview of each element of the RI scope of work is provided below. RI sampling locations are shown in Figure 4 of the RI Work Plan.

2.1 Soil

Samples of soil will be collected and analyzed at a minimum of twenty-six (26) locations for the following analytes:

- Target Compound List plus 30/Target Analyte List (TCL + 30/TAL), which includes: TCL volatile organic compounds (VOCs) +10, TCL semivolatile organic compounds (SVOCs) +20, TCL pesticides, TCL polychlorinated biphenyls (PCBs), TAL metals, and total cyanide.
- Total Petroleum Hydrocarbons (TPH).

2.2 Groundwater

Groundwater samples will be collected from twenty-one (21) existing monitoring wells installed around the perimeter of the Site and three new monitoring wells installed by Roux Associates during the investigation. After gauging for potential separate-phase petroleum product, each well will be sampled for:

- Target Compound List plus 30/Target Analyte List (TCL + 30/TAL), which includes: TCL volatile organic compounds (VOCs) +10, TCL semivolatile organic compounds (SVOCs) +20, TCL pesticides, TCL polychlorinated biphenyls (PCBs), TAL metals (total and dissolved), and total cyanide.
- Total Petroleum Hydrocarbons (TPH).

Field parameters, including temperature, pH, conductivity, redox potential, dissolved oxygen, and turbidity will also be measured.

2.3 Soil Vapor and Sub Slab Samples

Soil vapor samples will be collected from nine (9) locations around the subject buildings and locations in the interior of the subject buildings based on the results of the planned Gore Module screening. Sampling depths and analytical methods will be selected in consultation with the

NYSDEC and NYSDOH protocols. In addition, one outdoor ambient air sample will be collected.

3.0 PROJECT ORGANIZATION

The overall management structure and a general summary of the responsibilities of project team members are presented below.

Project Manager

Craig Werle of Roux Associates/Remedial Engineering will serve as Project Manager. The Project Manager is responsible for defining project objectives and bears ultimate responsibility for the successful completion of the investigation. This individual will provide overall management for the implementation of the scope of work and will coordinate all field activities. The Project Manager is also responsible for data review/interpretation and report preparation. Activities of the Project Manager are supported by the Project Quality Assurance Coordinator.

Field Team Leader

Wendy Monterosso of Roux Associates/Remedial Engineering will serve as the Field Team Leader. The Field Team Leader bears the responsibility for the successful execution of the field program, as scoped in the RI Work Plan and the Field Sampling Plan (FSP). The Field Team Leader will direct the activities of all technical staff in the field as well all subcontractors. The Field Team Leader will also assist in the interpretation of data and in report preparation. The Field Team Leader reports to the Project Manager.

Laboratory Project Manager

TestAmerica Laboratories, Inc. (TestAmerica) of Shelton, Connecticut, has been selected to analyze the field samples for this project and will be responsible for sample container preparation, sample custody in the laboratory, and completion of the required analysis through oversight of the laboratory staff. TestAmerica is an Environmental Laboratory Approval Program (ELAP) certified lab as described in Section 5. The Laboratory Project Manager will ensure that quality assurance procedures are followed and that an acceptable laboratory report is prepared and submitted. The Laboratory Project Manager reports to the Field Team Leader.

Quality Assurance Officer

Wai Kwan, PhD. of Roux Associates will serve as the Quality Assurance Officer (QAO) for this project. The QAO is responsible for conducting reviews, inspections, and audits to ensure that the data collection is conducted in accordance with the FSP and QAPP. The QAO's responsibilities range from ensuring effective field equipment decontamination procedures and proper sample collection to the review of all laboratory analytical data for completeness and usefulness. The QAO reports to the Project Manager and makes independent recommendations to the Field Team Leader.

4.0 SAMPLING PROCEDURES

Detailed discussions of sampling, decontamination, and sample handling procedures are provided in the FSP (Appendix D of the RI Work Plan).

5.0 QUALITY ASSURANCE/QUALITY CONTROL

The primary intended use for the RI data is to characterize Site conditions and determine if remediation needs to be undertaken at the Site. The primary DQO of the soil, groundwater, and soil vapor sampling programs, therefore, is that data be accurate and precise, and hence representative of the actual Site conditions. Accuracy refers to the ability of the laboratory to obtain a true value (i.e., compared to a standard) and is assessed through the use of laboratory quality control (QC) samples, including laboratory control samples and matrix spike samples, as well as through the use of surrogates, which are compounds not typically found in the environment that are injected into the samples prior to analysis. Precision refers to the ability to replicate a value, and is assessed through both field and laboratory duplicate samples.

Sensitivity is also a critical issue in generating representative data. Laboratory equipment must be of sufficient sensitivity to detect target compounds and analytes at levels below NYSDEC standards and guidelines whenever possible. Equipment sensitivity can be decreased by field or laboratory contamination of samples, and by sample matrix effects. Assessment of instrument sensitivity is performed through the analysis of reagent blanks, near-detection-limit standards, and response factors. Potential field and/or laboratory contamination is assessed through use of trip blanks, method blanks, and equipment rinse blanks (also called “field blanks”).

Table 1 lists the field and laboratory QC samples that will be analyzed to assess data accuracy and precision, as well as to determine if equipment sensitivity has been compromised. Table 2 shows the reporting limits and minimum detection limits achievable by the laboratory.

All RI “assessment” analyses (i.e., TCL VOCs, SVOCs, pesticides/PCBs; TAL metals; and cyanide) will be performed in accordance with the NYSDEC Analytical Services Protocol (ASP), using USEPA SW-846 methods. TestAmerica, Inc. has been selected to analyze the field samples collected during the RI and shall maintain a New York State Department of Health (NYSDOH) ELAP Contract Laboratory Protocol (CLP) certification (Certification Number 10602) for each of the “assessment” analyses listed in Section 2.0.

All laboratory data are to be reported in NYSDEC ASP Category B deliverables and will be delivered to NYSDEC in electronic data deliverable (EDD) format as described on NYSDEC’s

website (http://www.dec.ny.gov/chemical/62440.html). A Data Usability Report will be prepared by an independent party meeting the requirements in Section 2.2(a)1.ii and Appendix 2B of DER-10 for all data packages generated for the RI.

Table 1. Field and Laboratory QC Summary

QC Check Type	Minimum Frequency	Use
Field QC		
Duplicate	1 per matrix per SDG*	Precision
Trip Blank	1 per VOC cooler	Sensitivity
Equipment Rinse Blank	1 per day	Sensitivity
Laboratory QC		
Laboratory Control Sample	1 per matrix per SDG	Accuracy
Matrix Spike/Matrix Spike Duplicate/Matrix Duplicate**	1 per matrix per SDG	Accuracy/Precision
Surrogate Spike	All organics samples	Accuracy
Laboratory Duplicate	1 per matrix per SDG	Precision
Method Blank	1 per matrix per SDG	Sensitivity

Notes:

* SDG - Sample Delivery Group - Assumes a single extraction or preparation

** Provided to lab by field sampling personnel

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code
Soil Analysis	Volatile Organic Compounds (GC/MS)	8260B

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Dichlorodifluoromethane	75-71-8	5	0.35	ug/Kg
Chloromethane	74-87-3	5	0.78	ug/Kg
Vinyl chloride	75-01-4	5	0.23	ug/Kg
Bromomethane	74-83-9	5	2.08	ug/Kg
Chloroethane	75-00-3	5	0.98	ug/Kg
Trichlorofluoromethane	75-69-4	5	0.15	ug/Kg
1,1-Dichloroethene	75-35-4	5	0.58	ug/Kg
1,1,2-Trichloro-1,2,2-trifluoroethane	76-13-1	5	0.79	ug/Kg
Acetone	67-64-1	20	2.24	ug/Kg
Carbon disulfide	75-15-0	5	0.41	ug/Kg
Methyl acetate	79-20-9	5	0.44	ug/Kg
Methylene Chloride	75-09-2	20	1.09	ug/Kg
trans-1,2-Dichloroethene	156-60-5	5	0.39	ug/Kg
Methyl tert-butyl ether	1634-04-4	5	0.21	ug/Kg
1,1-Dichloroethane	75-34-3	5	0.3	ug/Kg
cis-1,2-Dichloroethene	156-59-2	5	0.37	ug/Kg
Methyl Ethyl Ketone	78-93-3	10	1.59	ug/Kg
Chloroform	67-66-3	5	0.34	ug/Kg
1,1,1-Trichloroethane	71-55-6	5	0.53	ug/Kg
Cyclohexane	110-82-7	5	0.69	ug/Kg
Carbon tetrachloride	56-23-5	5	0.95	ug/Kg
Benzene	71-43-2	5	0.57	ug/Kg
1,2-Dichloroethane	107-06-2	5	0.58	ug/Kg
Trichloroethene	79-01-6	5	0.81	ug/Kg
Methylcyclohexane	108-87-2	5	0.33	ug/Kg
1,2-Dichloropropane	78-87-5	5	0.67	ug/Kg
Bromodichloromethane	75-27-4	5	0.3	ug/Kg
cis-1,3-Dichloropropene	10061-01-5	5	0.56	ug/Kg
methyl isobutyl ketone	108-10-1	5	0.55	ug/Kg
Toluene	108-88-3	5	0.074	ug/Kg
trans-1,3-Dichloropropene	10061-02-6	5	0.27	ug/Kg
1,1,2-Trichloroethane	79-00-5	5	0.37	ug/Kg
Tetrachloroethene	127-18-4	5	0.81	ug/Kg
2-Hexanone	591-78-6	10	1.2	ug/Kg

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code
Soil Analysis	Purge and Trap	5030B
Soil Analysis	Semivolatile Compounds by Gas Chromatography/Mass Spectro	8270C

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Dibromochloromethane	124-48-1	5	0.35	ug/Kg
1,2-Dibromoethane	106-93-4	5	0.76	ug/Kg
Chlorobenzene	108-90-7	5	0.59	ug/Kg
Ethylbenzene	100-41-4	5	0.7	ug/Kg
m&p-Xylene	179601-23-1	5	0.35	ug/Kg
o-Xylene	95-47-6	5	0.19	ug/Kg
Xylenes, Total	1330-20-7	5	0.486	ug/Kg
Styrene	100-42-5	5	0.15	ug/Kg
Bromoform	75-25-2	5	0.61	ug/Kg
Isopropylbenzene	98-82-8	5	0.19	ug/Kg
1,1,2,2-Tetrachloroethane	79-34-5	5	0.52	ug/Kg
1,3-Dichlorobenzene	541-73-1	5	0.21	ug/Kg
1,4-Dichlorobenzene	106-46-7	5	0.67	ug/Kg
1,2-Dichlorobenzene	95-50-1	5	0.24	ug/Kg
1,2-Dibromo-3-Chloropropane	96-12-8	10	4.53	ug/Kg
1,2,4-Trichlorobenzene	120-82-1	5	0.75	ug/Kg
1,2-Dichloroethane-d4 (Surr)	17060-07-0			ug/Kg
4-Bromofluorobenzene	460-00-4			ug/Kg
Dibromofluoromethane	1868-53-7	5		ug/Kg
Toluene-d8 (Surr)	2037-26-5			ug/Kg
Tentatively Identified Compound	STL00231			ug/Kg
1,1'-Biphenyl	92-52-4	270	17.5	ug/Kg
2,4,5-Trichlorophenol	95-95-4	1700	13.6	ug/Kg
2,4,6-Trichlorophenol	88-06-2	270	7.4	ug/Kg
2,4-Dichlorophenol	120-83-2	270	14.4	ug/Kg
2,4-Dimethylphenol	105-67-9	270	13.1	ug/Kg
2,4-Dinitrotoluene	121-14-2	270	21.5	ug/Kg
2,4-Dinitrophenol	51-28-5	1700	81	ug/Kg
2,6-Dinitrotoluene	606-20-2	270	7.9	ug/Kg
2-Chloronaphthalene	91-58-7	270	11.5	ug/Kg
2-Chlorophenol	95-57-8	270	15.7	ug/Kg
2-Methylnaphthalene	91-57-6	270	7.7	ug/Kg

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code			
	2-Methylphenol	95-48-7	270	16.2	ug/Kg
	2-Nitroaniline	88-74-4	670	16.4	ug/Kg
	2-Nitrophenol	88-75-5	270	17	ug/Kg
	3,3'-Dichlorobenzidine	91-94-1	330	55.5	ug/Kg
	3-Nitroaniline	99-09-2	670	8.6	ug/Kg
	4,6-Dinitro-2-methylphenol	534-52-1	1700	116	ug/Kg
	4-Bromophenyl phenyl ether	101-55-3	270	17.4	ug/Kg
	4-Chloro-3-methylphenol	59-50-7	270	11.1	ug/Kg
	4-Chloroaniline	106-47-8	270	43.9	ug/Kg
	4-Chlorophenyl phenyl ether	7005-72-3	270	19.9	ug/Kg
	Methylphenol, 3 & 4	106-44-5	270	17.7	ug/Kg
	4-Nitroaniline	100-01-6	270	20.7	ug/Kg
	4-Nitrophenol	100-02-7	1700	20.4	ug/Kg
	Acenaphthene	83-32-9	270	16	ug/Kg
	Acenaphthylene	208-96-8	270	13.2	ug/Kg
	Acetophenone	98-86-2	270	14	ug/Kg
	Anthracene	120-12-7	270	10.5	ug/Kg
	Atrazine	1912-24-9	330	17.1	ug/Kg
	Benzaldehyde	100-52-7	270	45	ug/Kg
	Benzo[a]anthracene	56-55-3	270	9.6	ug/Kg
	Benzo[a]pyrene	50-32-8	270	7.3	ug/Kg
	Benzo[b]fluoranthene	205-99-2	270	7.2	ug/Kg
	Benzo[g,h,i]perylene	191-24-2	270	17.6	ug/Kg
	Benzo[k]fluoranthene	207-08-9	270	24.2	ug/Kg
	Bis(2-chloroethoxy)methane	111-91-1	270	12.5	ug/Kg
	Bis(2-chloroethyl)ether	111-44-4	270	14	ug/Kg
	Bis(2-ethylhexyl) phthalate	117-81-7	270	26.1	ug/Kg
	Butyl benzyl phthalate	85-68-7	270	15.1	ug/Kg
	Caprolactam	105-60-2	270	21.2	ug/Kg
	Carbazole	86-74-8	270	15	ug/Kg
	Chrysene	218-01-9	270	19.9	ug/Kg
	Di-n-butyl phthalate	84-74-2	270	39.2	ug/Kg
	Di-n-octyl phthalate	117-84-0	270	15.3	ug/Kg
	Dibenz(a,h)anthracene	53-70-3	270	21.2	ug/Kg
	Dibenzofuran	132-64-9	270	19	ug/Kg
	Diethyl phthalate	84-66-2	270	27.2	ug/Kg
	Dimethyl phthalate	131-11-3	270	15.5	ug/Kg

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code			
	Fluoranthene	206-44-0	270	13.4	ug/Kg
	Fluorene	86-73-7	270	16.2	ug/Kg
	Hexachlorobenzene	118-74-1	270	18.7	ug/Kg
	Hexachlorobutadiene	87-68-3	270	20.8	ug/Kg
	Hexachlorocyclopentadiene	77-47-4	670	127	ug/Kg
	Hexachloroethane	67-72-1	270	15.4	ug/Kg
	Indeno[1,2,3-cd]pyrene	193-39-5	270	17.5	ug/Kg
	Isophorone	78-59-1	270	14.9	ug/Kg
	N-Nitrosodi-n-propylamine	621-64-7	270	18.2	ug/Kg
	N-Nitrosodiphenylamine	86-30-6	270	15.2	ug/Kg
	Naphthalene	91-20-3	270	14	ug/Kg
	Nitrobenzene	98-95-3	270	17.2	ug/Kg
	Pentachlorophenol	87-86-5	670	164	ug/Kg
	Phenanthrene	85-01-8	270	13.3	ug/Kg
	Phenol	108-95-2	270	17.9	ug/Kg
	Pyrene	129-00-0	270	12.7	ug/Kg
	2,2'-oxybis[1-chloropropane]	108-60-1	270	14	ug/Kg
	1,2-Dichlorobenzene-d4	2199-69-1			ug/Kg
	2,4,6-Tribromophenol	118-79-6	270		ug/Kg
	2-Chlorophenol-d4	93951-73-6			ug/Kg
	2-Fluorobiphenyl	321-60-8	270		ug/Kg
	2-Fluorophenol	367-12-4	330		ug/Kg
	Nitrobenzene-d5	4165-60-0	270		ug/Kg
	Phenol-d5	4165-62-2	330		ug/Kg
	Terphenyl-d14	1718-51-0	270		ug/Kg
	Tentatively Identified Compound	STL00231	330		ug/Kg

Soil Analysis	Automated Soxhlet Extraction	3541
Soil Analysis	Polychlorinated Biphenyls (PCBs) by Gas Chromatography	8082

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
PCB-1016	12674-11-2	17	1.317	ug/Kg
PCB-1221	11104-28-2	17	1.317	ug/Kg
PCB-1232	11141-16-5	17	1.317	ug/Kg
PCB-1242	53469-21-9	17	1.317	ug/Kg
PCB-1248	12672-29-6	17	1.317	ug/Kg
PCB-1254	11097-69-1	17	1.441	ug/Kg

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code			
	PCB-1260	11096-82-5	17	1.441	ug/Kg
	Tetrachloro-m-xylene	877-09-8			ug/Kg
	DCB Decachlorobiphenyl	2051-24-3			ug/Kg

Soil Analysis	Ultrasonic Extraction	3550B
Soil Analysis	Organochlorine Pesticides (GC)	8081A

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
4,4'-DDD	72-54-8	3.3	0.594	ug/Kg
4,4'-DDE	72-55-9	3.3	0.67	ug/Kg
4,4'-DDT	50-29-3	3.3	0.81	ug/Kg
Aldrin	309-00-2	1.7	0.181	ug/Kg
alpha-BHC	319-84-6	1.7	0.244	ug/Kg
beta-BHC	319-85-7	1.7	0.374	ug/Kg
DCB Decachlorobiphenyl	2051-24-3			ug/Kg
delta-BHC	319-86-8	1.7	0.365	ug/Kg
Dieldrin	60-57-1	3.3	0.571	ug/Kg
Endosulfan I	959-98-8	1.7	0.292	ug/Kg
Endosulfan II	33213-65-9	3.3	0.622	ug/Kg
Endosulfan sulfate	1031-07-8	3.3	0.594	ug/Kg
Endrin	72-20-8	3.3	0.617	ug/Kg
Endrin aldehyde	7421-93-4	3.3	0.407	ug/Kg
Endrin ketone	53494-70-5	3.3	0.607	ug/Kg
gamma-BHC (Lindane)	58-89-9	1.7	0.287	ug/Kg
Heptachlor	76-44-8	1.7	0.319	ug/Kg
Heptachlor epoxide	1024-57-3	1.7	0.301	ug/Kg
Methoxychlor	72-43-5	17	3.658	ug/Kg
Tetrachloro-m-xylene	877-09-8			ug/Kg
Toxaphene	8001-35-2	83	9.15	ug/Kg
alpha-Chlordane	5103-71-9	1.7	0.275	ug/Kg
gamma-Chlordane	5103-74-2	1.7	0.53	ug/Kg

Soil Analysis	Ultrasonic Extraction	3550B
Soil Analysis	Metals (ICP/MS)	6020

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Silver	7440-22-4	0.4	0.08	mg/Kg
Aluminum	7429-90-5	20	4	mg/Kg

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code			
	Arsenic	7440-38-2	0.4	0.08	mg/Kg
	Barium	7440-39-3	0.4	0.12	mg/Kg
	Beryllium	7440-41-7	0.4	0.12	mg/Kg
	Calcium	7440-70-2	40	12	mg/Kg
	Cadmium	7440-43-9	0.4	0.08	mg/Kg
	Cobalt	7440-48-4	0.4	0.08	mg/Kg
	Chromium	7440-47-3	0.8	0.16	mg/Kg
	Copper	7440-50-8	0.8	0.08	mg/Kg
	Iron	7439-89-6	20	6.4	mg/Kg
	Potassium	7440-09-7	40	4	mg/Kg
	Magnesium	7439-95-4	40	4	mg/Kg
	Manganese	7439-96-5	1	0.16	mg/Kg
	Sodium	7440-23-5	40	13.2	mg/Kg
	Nickel	7440-02-0	0.4	0.08	mg/Kg
	Lead	7439-92-1	0.4	0.08	mg/Kg
	Antimony	7440-36-0	0.64	0.16	mg/Kg
	Selenium	7782-49-2	0.8	0.24	mg/Kg
	Thallium	7440-28-0	0.56	0.16	mg/Kg
	Vanadium	7440-62-2	0.4	0.08	mg/Kg
	Zinc	7440-66-6	4	0.4	mg/Kg

Soil Analysis	Preparation, Metals	3050B
Soil Analysis	Mercury (CVAA)	7471A

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Mercury	7439-97-6	0.05	0.004	mg/Kg

Soil Analysis	Preparation, Mercury	7471A_Prep
Soil Analysis	Diesel Range Organics (DRO) (GC)	8015B_DRO

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Diesel Range Organics [C10-C28]	STL00143	17000		
o-Terphenyl	84-15-1			

Soil Analysis	Ultrasonic Extraction	3550B
Soil Analysis	Gasoline Range Organics - (GC)	8015B_GRO

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Gasoline Range Organics (C6-C9)	STL00215	25		

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code			
	a,a,a-Trifluorotoluene	98-08-8			

Soil Analysis	Closed System Purge and Trap	5035A_FP
Soil Analysis	Percent Moisture	Moisture

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Percent Moisture	STL00177	0.1		
Percent Solids	STL00234	0.1		

Soil Analysis	Cyanide, Total andor Amenable	9012B

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Cyanide, Total	57-12-5	500	117	ug/Kg

Soil Analysis	Cyanide, Total and/or Amenable, Distillation	9012B_Prep
Soil Analysis	Gasoline Range Organics - (GC)	8015B_GRO

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Gasoline Range Organics (C6-C9)	STL00215	1250		
a,a,a-Trifluorotoluene	98-08-8			

Soil Analysis	Closed System Purge and Trap	5035A_M
Water Analysis	Volatile Organic Compounds (GC/MS)	8260B

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Dichlorodifluoromethane	75-71-8	5	1.01	ug/L
Chloromethane	74-87-3	5	1.09	ug/L
Vinyl chloride	75-01-4	5	0.99	ug/L
Bromomethane	74-83-9	5	2.12	ug/L
Chloroethane	75-00-3	5	1.06	ug/L
Trichlorofluoromethane	75-69-4	5	1.11	ug/L
1,1-Dichloroethene	75-35-4	5	0.83	ug/L
1,1,2-Trichloro-1,2,2-trifluoroethane	76-13-1	5	0.97	ug/L
Acetone	67-64-1	10	1.03	ug/L
Carbon disulfide	75-15-0	5	0.9	ug/L
Methyl acetate	79-20-9	5	0.48	ug/L
Methylene Chloride	75-09-2	5	0.78	ug/L
trans-1,2-Dichloroethene	156-60-5	5	0.76	ug/L
Methyl tert-butyl ether	1634-04-4	5	0.17	ug/L

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code			
	1,1-Dichloroethane	75-34-3	5	1.03	ug/L
	cis-1,2-Dichloroethene	156-59-2	5	0.99	ug/L
	Methyl Ethyl Ketone	78-93-3	10	1.09	ug/L
	Chloroform	67-66-3	5	0.67	ug/L
	1,1,1-Trichloroethane	71-55-6	5	0.69	ug/L
	Cyclohexane	110-82-7	5	0.7	ug/L
	Carbon tetrachloride	56-23-5	5	1.07	ug/L
	Benzene	71-43-2	5	0.74	ug/L
	1,2-Dichloroethane	107-06-2	5	0.72	ug/L
	Trichloroethene	79-01-6	5	0.62	ug/L
	Methylcyclohexane	108-87-2	5	0.98	ug/L
	1,2-Dichloropropane	78-87-5	5	0.71	ug/L
	Bromodichloromethane	75-27-4	5	0.48	ug/L
	cis-1,3-Dichloropropene	10061-01-5	5	0.28	ug/L
	methyl isobutyl ketone	108-10-1	10	0.38	ug/L
	Toluene	108-88-3	5	0.72	ug/L
	trans-1,3-Dichloropropene	10061-02-6	5	0.57	ug/L
	1,1,2-Trichloroethane	79-00-5	5	0.65	ug/L
	Tetrachloroethene	127-18-4	5	0.81	ug/L
	2-Hexanone	591-78-6	10	1.09	ug/L
	Dibromochloromethane	124-48-1	5	0.55	ug/L
	1,2-Dibromoethane	106-93-4	5	0.52	ug/L
	Chlorobenzene	108-90-7	5	0.72	ug/L
	Ethylbenzene	100-41-4	5	0.87	ug/L
	m&p-Xylene	179601-23-1	5	1.66	ug/L
	o-Xylene	95-47-6	5	0.66	ug/L
	Xylenes, Total	1330-20-7	5	2.27	ug/L
	Styrene	100-42-5	5	0.64	ug/L
	Bromoform	75-25-2	5	0.46	ug/L
	Isopropylbenzene	98-82-8	5	0.85	ug/L
	1,1,2,2-Tetrachloroethane	79-34-5	5	0.81	ug/L
	1,3-Dichlorobenzene	541-73-1	5	0.14	ug/L
	1,4-Dichlorobenzene	106-46-7	5	0.59	ug/L
	1,2-Dichlorobenzene	95-50-1	5	0.22	ug/L
	1,2-Dibromo-3-Chloropropane	96-12-8	5	1.16	ug/L
	1,2,4-Trichlorobenzene	120-82-1	5	0.72	ug/L
	1,2-Dichloroethane-d4 (Surr)	17060-07-0			ug/L

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code			
	4-Bromofluorobenzene	460-00-4	5		ug/L
	Dibromofluoromethane	1868-53-7	5		ug/L
	Toluene-d8 (Surr)	2037-26-5	5		ug/L
	Tentatively Identified Compound	STL00231			ug/L

Water Analysis	Purge and Trap	5030B
Water Analysis	Metals (ICP/MS)	6020

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Silver	7440-22-4	5	1	ug/L
Aluminum	7429-90-5	250	50	ug/L
Arsenic	7440-38-2	5	1	ug/L
Barium	7440-39-3	5	1	ug/L
Beryllium	7440-41-7	5	1	ug/L
Calcium	7440-70-2	500	100	ug/L
Cadmium	7440-43-9	5	1	ug/L
Cobalt	7440-48-4	5	1	ug/L
Chromium	7440-47-3	10	2	ug/L
Copper	7440-50-8	10	1	ug/L
Iron	7439-89-6	250	50	ug/L
Potassium	7440-09-7	500	50	ug/L
Magnesium	7439-95-4	500	50	ug/L
Manganese	7439-96-5	12	2	ug/L
Sodium	7440-23-5	500	100	ug/L
Nickel	7440-02-0	5	1	ug/L
Lead	7439-92-1	5	1	ug/L
Antimony	7440-36-0	8	2	ug/L
Selenium	7782-49-2	10	2	ug/L
Thallium	7440-28-0	7	2	ug/L
Vanadium	7440-62-2	5	1	ug/L
Zinc	7440-66-6	50	5	ug/L

Water Analysis	Preparation, Total Metals	3010A
Water Analysis	Mercury (CVAA)	7470A

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Mercury	7439-97-6	0.2	0.06	ug/L

Table 2. Laboratory Reporting Limits for Soil, Water, and Air Samples

Analysis Group Description	Method Description	Method Code
Water Analysis	Preparation, Mercury	7470A_Prep
Water Analysis	Metals (ICP/MS)	6020

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Silver	7440-22-4	5	1	ug/L
Aluminum	7429-90-5	250	50	ug/L
Arsenic	7440-38-2	5	1	ug/L
Barium	7440-39-3	5	1	ug/L
Beryllium	7440-41-7	5	1	ug/L
Calcium	7440-70-2	500	100	ug/L
Cadmium	7440-43-9	5	1	ug/L
Cobalt	7440-48-4	5	1	ug/L
Chromium	7440-47-3	10	2	ug/L
Copper	7440-50-8	10	1	ug/L
Iron	7439-89-6	250	50	ug/L
Potassium	7440-09-7	500	50	ug/L
Magnesium	7439-95-4	500	50	ug/L
Manganese	7439-96-5	12	2	ug/L
Sodium	7440-23-5	500	100	ug/L
Nickel	7440-02-0	5	1	ug/L
Lead	7439-92-1	5	1	ug/L
Antimony	7440-36-0	8	2	ug/L
Selenium	7782-49-2	10	2	ug/L
Thallium	7440-28-0	7	2	ug/L
Vanadium	7440-62-2	5	1	ug/L
Zinc	7440-66-6	50	5	ug/L

Water Analysis	Preparation, Total Metals	3010A
Water Analysis	Sample Filtration	FILTRATION
Water Analysis	Mercury (CVAA)	7470A

Analyte Description	CAS Number	RL - Limit	MDL - Limit	Units
Mercury	7439-97-6	0.2	0.06	ug/L

Water Analysis	Preparation, Mercury	7470A_Prep
Water Analysis	Sample Filtration	FILTRATION

TestAmerica Burlington NYS VI Compound List

Compound	Molecular Weight	Indoor Air* RL (ppbv)	Soil Gas** RL (ppbv)	Indoor Air* RL (ug/m$^{3)}$	Soil Gas** RL (ug/m$^{3)}$
1,1,1-Trichloroethane	133.42	0.04	0.2	0.22	1.1
1,1,2,2-Tetrachloroethane	167.86	0.04	0.2	0.27	1.4
1,1,2-Trichloroethane	133.42	0.04	0.2	0.22	1.1
1,1-Dichloroethane	98.97	0.04	0.2	0.16	0.81
1,1-Dichloroethene	96.95	0.04	0.2	0.16	0.79
1,2-Dibromoethane	187.88	0.04	0.2	0.31	1.5
1,2-Dichloroethane	98.96	0.08	0.2	0.32	0.81
1,2-Dichloropropane	112.99	0.08	0.2	0.37	0.92
1,3,5-Trimethylbenzene	120.19	0.08	0.2	0.39	1.0
1,3-Butadiene	54.09	0.08	0.5	0.18	1.1
2,2,4-Trimethylpentane	114.23	0.04	0.2	0.19	0.9
3-Chloropropene	76.53	0.08	0.5	0.25	1.6
4-Ethyltoluene	120.2	0.04	0.2	0.20	1.0
Benzene	78.11	0.04	0.2	0.13	0.64
Bromodichloromethane	163.83	0.04	0.2	0.27	1.3
Bromoethene	106.96	0.08	0.2	0.35	0.87
Bromoform	252.75	0.04	0.2	0.41	2.1
Bromomethane	94.95	0.08	0.2	0.31	0.78
Carbon Tetrachloride	153.84	0.04	0.2	0.25	1.3
Chloroethane	64.52	0.08	0.5	0.21	1.3
Chloroform	119.39	0.04	0.2	0.20	1.0
cis-1,2-Dichloroethene	96.95	0.04	0.2	0.16	0.79
cis-1,3-Dichloropropene	110.98	0.04	0.2	0.18	0.91
Cyclohexane	84.16	0.04	0.2	0.14	0.69
Dibromochloromethane	242.74	0.04	0.2	0.40	2.0
Dichlorodifluoromethane	120.92	0.04	0.5	0.20	2.5
Dichlorotetrafluoroethane	170.93	0.04	0.2	0.28	1.4
Ethylbenzene	106.16	0.04	0.2	0.17	0.87
m,p-Xylene	106.16	0.08	0.5	0.35	2.2
Methyl tert-Butyl Ether	88.15	0.04	0.5	0.14	1.8
Methylene Chloride	84.94	0.8	0.5	2.78	1.7
n-Heptane	101.2	0.04	0.2	0.17	0.83
n-Hexane	86.18	0.08	0.5	0.28	1.8
o-Xylene	106.16	0.04	0.2	0.17	0.87
Tetrachloroethene	165.85	0.04	0.2	0.27	1.4
Toluene	92.13	0.04	0.2	0.15	0.75
trans-1,2-Dichloroethene	96.95	0.04	0.2	0.16	0.79
trans-1,3-Dichloropropene	110.98	0.04	0.2	0.18	0.91
Trichloroethene	131.4	0.04	0.2	0.21	1.1
Trichlorofluoromethane	137.38	0.04	0.2	0.22	1.1
Vinyl Chloride	62.5	0.08	0.2	0.20	0.51

* Also includes outdoor ambient air .

** Also includes sub-slab soil vapor.

APPENDIX F

Site Health and Safety Plan

January 21, 2011

HEALTH AND SAFETY PLAN

900 Old Country Road
Garden City, Town of Hempstead,
Nassau County, New York

Prepared for

EQUITY ONE (NORTHEAST PORTFOLIO) INC.
650 5th Avenue, 24th Floor
New York, New York 10019

ROUX ASSOCIATES, INC.

Environmental Consulting & Management

ROUX

209 Shafter Street, Islandia, New York 11749 ♦ 631-232-2600

TABLE OF CONTENTS

APPROVALS iv

1.0 INTRODUCTION 1
1.1 Scope of Work 2
1.2 Emergency Numbers 2
1.2.1 Emergency Phone Numbers 2
1.2.2 Project Management/Health and Safety Personnel 3
1.2.3 Other Important Phone Numbers 3
1.2.4 Directions to Winthrop University Hospital 3

2.0 HEALTH AND SAFETY STAFF 4
2.1 Project Principal (PP) – Craig Werle – Roux Associates 4
2.2 Corporate Health and Safety Manager (CHSM) – Joe Gentile – Roux Associates 4
2.3 Site Safety and Health Officer (SSO) – Subraham Singh – Roux Associates 4
2.4 Field Personnel and Subcontractors 5

3.0 SITE LOCATION, DESCRIPTION, AND HISTORY 6
3.1 Property Location and Description 6

4.0 WASTE DESCRIPTION/CHARACTERIZATION 7
4.1 General 7
4.2 Chemical Data Sheets 7
4.2.1 Contaminants of Concern 7

5.0 HAZARD ASSESSMENT 8
5.1 Chemical Hazards 8
5.1.1 Exposure Pathways 8
5.1.2 Operational Action Levels 9
5.1.3 Additional Precautions 9
5.2 Physical Hazards 9
5.2.1 Noise 10
5.2.2 Heat Stress 10
5.2.3 Cold Stress 12
5.2.4 Asbestos 12
5.2.5 Structural Integrity 13
5.2.6 Lockout/Tagout 13
5.3 Biological Hazards 13
5.3.1 Insect Stings 14
5.3.2 Animals and Animal Wastes 14
5.3.3 Mold 14
5.3.4 Bloodborne Pathogens 15
5.4 Hazard Assessment 17

6.0 TRAINING 18
6.1 General Health and Safety Training 18
6.2 Annual Eight-Hour Refresher Training 18
6.3 Site-Specific Training 18
6.4 Onsite Safety Meetings 19

TABLE OF CONTENTS

(Continued)

6.5 First Aid and CPR 19
6.6 Additional Training 19
6.7 Subcontractor Training 19

7.0 MEDICAL SURVEILLANCE PROCEDURES 20
7.1 General 20

8.0 SITE CONTROL, PERSONAL PROTECTIVE EQUIPMENT, AND COMMUNICATIONS 21
8.1 Site Control 21
8.1.1 Support Zone 21
8.1.2 Contamination Reduction Zone 22
8.1.3 Exclusion Zone 22
8.2 Personal Protective Equipment 22
8.2.1 General 22
8.2.2 Personal Protective Equipment Specifications 23
8.2.3 Initial Levels of Protection 25
8.3 Communications 25

9.0 MONITORING PROCEDURES 26
9.1 General 26
9.2 Exclusion Zone Monitoring 26
9.2.1 Instrumentation 26
9.2.2 Action Levels 27
9.2.3 Monitoring During Field Activities 27

10.0 SAFETY CONSIDERATIONS 28
10.1 General 28
10.2 Traffic Control 29
10.3 Sample Handling 29

11.0 DECONTAMINATION AND DISPOSAL PROCEDURES 30
11.1 Contamination Prevention 30
11.2 Personnel Decontamination 30
11.3 Equipment Decontamination 31
11.4 Decontamination during Medical Emergencies 31
11.5 Disposal Procedures 31

12.0 EMERGENCY PLAN 33
12.1 Evacuation 33
12.2 Personnel Injury 34
12.3 Accident/Incident Reporting 34
12.4 Personnel Exposure 35
12.5 Adverse Weather Conditions 35

13.0 LOGS, REPORTS AND RECORD KEEPING 37
13.1 Medical and Training Records 37

TABLE OF CONTENTS

(Continued)

13.2 Onsite Log....37
13.3 Exposure Records....37
13.4 Accident/Incident Reports....37
13.5 OSHA Form 300....37
13.6 Daily Safety Logs....38
13.7 Weekly Safety Reports....38
13.8 Close-Out Safety Report....38
14.0 FIELD TEAM REVIEW....39

TABLES

1. Toxicological, Physical and Chemical Properties of Compounds Potentially Present at the Site
2. Action Levels for Worker Breathing Zone

FIGURES

1. Site Location Map
2. Hospital Route Map

APPENDICES

A. Activity Hazard Analysis
B. Heat and Cold Stress Guidelines
C. Medical Data Form
D. Community Air Monitoring Plan
E. Health and Safety Briefing/Tailgate Meeting Form
F. Accident Report and Investigation Form
G. Acord Form
H. OSHA 300
I. Weekly Safety Report
J. Job Safety and Health Protection Poster

APPROVALS

By their signature, the undersigned certify that this Health and Safety Plan (HASP) is approved and will be utilized at the project site located at 900 Old Country Road, Garden City, New York.

11/8/2010

Joseph Gentile — Date
Corporate Health and Safety Manager
Roux Associates, Inc.



11/8/2010

Subraham Singh — Date
Site Health and Safety Officer
Roux Associates, Inc.



11/8/2010

Craig Werle — Date
Project Principal
Roux Associates, Inc.

1.0 INTRODUCTION

This Site-specific and Safety Plan (HASP) has been prepared in accordance with 29 CFR 1910.120 Occupational Safety and Health Administration (OSHA) Hazardous Waste Operations and Emergency Response (HAZWOPER) and Roux Associates, Inc. (Roux Associates) Standard Operating Procedures (SOPs). It addresses all activities to be performed during the implementation of Remedial Investigation (RI) activities at 900 Old Country Road, Garden City, New York (Site) (Figure 1). The HASP will be implemented by the designated Site Health and Safety Officer (SSO) during work at the Site. The HASP attempts to identify all potential hazards at the Site; however, Site conditions are dynamic and new hazards may appear constantly. Personnel must remain alert to existing and potential hazards as Site conditions change and protect themselves accordingly.

Compliance with this HASP is required of all persons and subcontractors who perform fieldwork or enter the Site. The contents of this HASP may change or undergo revision based upon additional information made available to health and safety personnel, monitoring results, or changes in the technical scope of work. Any changes proposed must be reviewed and approved by the Corporate Health and Safety Manager (CHSM), with the SSO implementing the changes to the HASP.

Upon entering the Site, all visitors are required to sign in. All visitors entering the Contamination Reduction Zone (CRZ) (defined in Section 8.1.2), the Contamination Reduction Corridor (CRC) (defined in Section 8.1.2), or the Exclusion Zone (EZ) (defined in Section 8.1.3) will be required to read and comply with the provisions of this HASP. Visitors will be required to comply with applicable OSHA requirements such as training, medical monitoring, and respiratory protection.

In the event that a visitor does not adhere to the provisions of this HASP, he or she will be required to leave the Site. Mobilization activities not requiring intrusive activities (e.g., survey, equipment staging, etc.) or exposure to potentially impacted areas may only be performed if supervised by a competent Roux Associates employee.

1.1 Scope of Work

The Scope of Work activities will include the implementation of RI activities.

The Scope of Work activities are as follows:

1. Obtain necessary permits and approvals.
2. Preparation and implementation of an approved Health and Safety Plan (HASP).
3. Implementation of RI activities, consisting of site inspection/reconnaissance, geophysical survey, drilling, soil boring and sampling, groundwater sampling, and soil vapor sampling.
4. Implementation of the approved Field Sampling Plan (FSP).
5. Mobilization and demobilization.
6. Maintain good site housekeeping procedures at all times.
7. Identification, protection, and/or relocation of any utilities within the work area.
8. Construct a decontamination pad with proper containment and collection system, if necessary.

1.2 Emergency Numbers

1.2.1 Emergency Phone Numbers

Emergency Medical Service 911

Police: Nassau County Police Department (NCPD).....911

Fire: 911

Hospital: Winthrop University Hospital 516-663-0333

National Response Center.....800-424-8802

Poison Control Center.....800-222-1222

Chemtrec.....800-262-8200

Fire: Westbury Fire Department 516-334-7968

Center for Disease Control.....800-311-3435

USEPA (Region II).....212-637-5000

NYSDEC Emergency Spill Response 800-457-7362

1.2.2 Project Management/Health and Safety Personnel

Title	Contact	Telephone/Cell
Roux Associates		
Project Director	Craig Werle	631-232-2600 Cell – 631-793-1535
Site Health and Safety Officer	Subraham Singh	631-232-2600
Corporate Health and Safety Manager	Joseph Gentile	856-423-8800 Cell – 610-844-6911

1.2.3 Other Important Phone Numbers

Nassau County Emergency Response Team 911

1.2.4 Directions to Winthrop University Hospital

See Figure 2 for street map.

- Start at 900 Old Country Road, Garden City, New York, take a Left onto Old Country Road
- Turn Right on Mineola Boulevard
- Turn Left on 1st Street
- Arrive at Winthrop University Hospital on your left

2.0 HEALTH AND SAFETY STAFF

This section briefly describes all site personnel and their health and safety responsibilities for the RI work to be implemented at the Site. All personnel are responsible for ensuring compliance with the HASP.

2.1 Project Principal (PP) – Craig Werle – Roux Associates

- Has the overall responsibility for the health and safety of Site personnel.
- Ensures that adequate resources are provided to the field health and safety staff to carry out their responsibilities as outlined below.

2.2 Corporate Health and Safety Manager (CHSM) – Joe Gentile – Roux Associates

- Implements the HASP.
- Performs or oversees site-specific training and approves revised or new safety protocols or field operations.
- Coordinates revisions of this HASP with Project Principal.
- Responsible for the development of new task safety protocols and procedures and resolution of any outstanding safety issues which may arise during the conduction of site work.
- Review and approve all health and safety training and medical surveillance records for personnel and subcontractors.

2.3 Site Safety and Health Officer (SSO) – Subraham Singh – Roux Associates

- Directs and coordinates health and safety monitoring activities.
- Ensures that field teams utilize proper personal protective equipment.
- Conducts initial onsite specific training prior to personnel and/or subcontractors commencing work.
- Conducts and documents periodic safety briefings.
- Ensures that field team members comply with this HASP.
- Completes and maintains Accident Report and Investigation Forms.
- Notifies PP and CHSM of all accident/incidents.

- Notifies PP of daily field operations and work progress, who will then communicate at the end of the day to the designated representative the following:

  1. End of day tasks completed

  2. Next day's planned activities

  3. Third party issues

  4. Change of Plans – approvals

- Change in level of personal protective equipment (PPE).

- Maintains contact with Contractors.

- Determines upgrade or downgrade of personal protective equipment (PPE) based on Site conditions and/or real time monitoring results.

- Ensures that monitoring instruments are calibrated daily or as manufacturer's suggested instructions determine.

- Submits and maintains health and safety field log books, daily safety logs, training logs, air monitoring result reports, weekly safety report.

2.4 Field Personnel and Subcontractors

- Report any unsafe or potentially hazardous conditions to the SSO.

- Maintain knowledge of the information, instructions, and emergency response actions contained in the HASP.

- Comply with rules, regulations, and procedures as set forth in this HASP and any revisions, which are instituted.

- Prevent admittance to work Site by unauthorized personnel.

3.0 SITE LOCATION, DESCRIPTION, AND HISTORY

Descriptions of the Site and surrounding property usage are included in the following sections. The location of the Site is presented in Figure 1.

3.1 Property Location and Description

The Site is located at 900 Old Country Road, Garden City, Town of Hempstead, Nassau County, New York. According to the information provided by Equity One (Northeast Portfolio) Inc., the Site is comprised of a 21.858-acre parcel located on the south side of Old Country Road, between East Gate Boulevard and Zeckendorf Boulevard. Northern and eastern sections of the site contain a one story active retail furniture store/warehouse, a three story former office building, a one and a half story former office/warehouse building, a one story former Manufacturing building and a one story former storage building. The buildings are surrounded by paved areas with a minimally landscaped area to the north of the former office building and surrounding the parking areas on Old Country Road.

The building, erected in the mid-1940's, is constructed with concrete block and brick walls, steel frame and roof on a concrete slab. A former boiler room is located north of the northeast corner of the Cendant building. With the exception of a small landscaped area to the north of the former office building and minimal landscaping around the northern parking area along Old Country Road, the land surrounding the building is paved with parking areas to the north, west, and south. Two loading and unloading bays are located along the Cendant building, one on the east side of the building and one along the south side of the building. There are several points of access/egress available for the former office and Cendant buildings.

The interior space of the buildings is partitioned into office and warehouse areas. Interior finishes in office spaces consist primarily of carpeted and vinyl tiled floors, gypsum wallboard interior partitions, and suspended acoustical ceiling tile. Interior finishes in the manufacturing/warehouse space include concrete floors and painted walls. All four unoccupied buildings are in severe disrepair with leaking roofs and no utility service.

The Site is currently owned by Equity One (Northeast Portfolio) Inc. and only one building is currently occupied by Thomasville Home Furnishings in the northwestern portion of the site.

4.0 WASTE DESCRIPTION/CHARACTERIZATION

4.1 General

The following information is presented in order to identify the types of materials that may be encountered at the Site. The detailed information on these materials was obtained from:

- SAX's Dangerous Properties of Industrial Materials – Lewis Eight Edition
- Chemical Hazards of the Workplace – Proctor/Hughes
- Condensed Chemical Dictionary – Hawley
- Rapid Guide to Hazardous Chemical in the Workplace – Lewis 1990
- NIOSH Pocket Guide to Chemical Hazards – 2005
- ACGIH TLV Values and Biological Exposure Indices
- OSHA 29 CFR 1910.1000

4.2 Chemical Data Sheets

Several chemicals that may potentially be present in soils and groundwater at the Site, based on previous soil, soil vapor and groundwater sampling results and historic operations conducted at the Site that have been identified. The Summary of Toxicological Data is found in Table 1 and is provided for review of chemicals that may be encountered. The Summary of Toxicological Data Sheets provides information such as the chemicals characteristics, health hazards, protection, and exposure limits.

4.2.1 Contaminants of Concern

Soil and groundwater contaminants that may be encountered during drilling and sampling activities include both organic and inorganic compounds. Prior investigations at the site have indicated detection of Volatile Organic Compounds (VOCs), Semi-volatile Organic Compounds (SVOCs), metals, and polychlorinated biphenyls (PCBs).

The toxicological, physical, and chemical properties of potential contaminants are presented in Table 1.

5.0 HAZARD ASSESSMENT

The potential to encounter chemical hazards is dependent upon the work activity performed (intrusive versus non-intrusive), and the duration and location of the work activity. Such hazards could include inhalation and/or skin contact with chemicals/gases that could cause: dermatitis, skin burns, being overcome by vapors or asphyxiation.

Physical hazards that may be encountered during Site work include; heat and cold stress, exposure to excessive noise, loss of limbs, being crushed, head injuries, punctures, cuts, falls, electrocution, and bruises, structural integrity of buildings, asbestos and lead paint exposure, and other physical hazards due to motor vehicle operation, heavy equipment and power tools.

Biological hazards may exist during Site activities. These hazards include exposure to insect bites/stings, animals and animal wastes, mold and bloodborne pathogens.

Prior to the beginning of each new phase of work, an activity hazard analysis will be prepared by the SSO with assistance from the CHSM. The analysis will address the hazards for each activity performed in the phase and will present the procedures and safeguards necessary to eliminate the hazards or reduce the risk. The Activity Hazard Analysis Sheets are located in Appendix A.

5.1 Chemical Hazards

The potential for personnel and subcontractors to come in contact with chemical hazards may occur during the following tasks:

- Drilling Activities
- Decontamination Activities

For chronic and acute toxicity data, refer to Summary of Toxicological Data Sheets in Table 1 for further details on compound characteristics.

5.1.1 Exposure Pathways

Exposure to these compounds during ongoing activities may occur through inhalation of contaminated dust particles, inhalation of VOCs and SVOCs, dermal absorption, and accidental ingestion of the contaminant by either direct or indirect cross-contamination activities.

Inhalation of contaminated dust particles (VOCs, SVOCs, and inorganics) can occur during adverse weather conditions (high or changing wind directions) or during operations that may generate airborne dust such as excavation and loading of contaminated soils. Dust control measures such as applying water to roadways and excavations will be implemented where visible dust is generated. Where dust control measures are not feasible or effective, respiratory protection will be used when necessary (see Section 9.2.2 for monitoring procedures and action levels).

5.1.2 Operational Action Levels

A decision-making protocol for an upgrade in levels of protection and/or withdrawal of personnel from an area based on atmospheric hazards is outlined in Table 2.

5.1.3 Additional Precautions

Dermal absorption or skin contact with chemical compounds is possible during intrusive activities at the Site. The use of PPE in accordance with Section 8.2 and strict adherence to proper decontamination procedures should significantly reduce the risk of skin contact.

The potential for accidental ingestion of potentially hazardous chemicals is expected to be remote, when good hygiene practices are used.

5.2 Physical Hazards

A variety of physical hazards may be present during Site activities. These hazards include typical construction activities: operation of motor vehicles and heavy equipment operation, the use of power and hand tools, roping and rigging of steel sheeting, walking on objects, tripping over objects, working on surfaces which have the potential to promote falling, skin burns, crushing of fingers, toes, limbs, head injuries caused by falling objects, temporary loss of one's hearing and/or eyesight. The referenced hazards are not unique and are generally familiar to most hazardous waste site workers at construction sites. Task specific safety requirements for each phase will be covered during safety briefings. Activity Hazard Analysis summaries are contained in Appendix A.

5.2.1 Noise

Noise is a potential hazard associated with operation of heavy equipment, power tools, pumps, and generators. High noise equipment operators will be evaluated at the discretion of the SSO. Employees with an 8-hour time weighted average exposure exceeding 85 dBA will be included in the hearing conservation program in accordance with 29 CFR 1910.95 and 1926.52.

It is mandated that employees working around heavy equipment or using power tools that produce noise levels exceeding 90 dBA are to wear hearing protection that shall consist of earplugs or protective earmuffs.

5.2.2 Heat Stress

Heat stress is a significant potential hazard, associated with the use of protective equipment in a hot weather environment. The human body is designed to function at a certain internal temperature. When metabolism or external sources (fire or hot summer day) cause the body temperature to rise, the body seeks to protect itself by triggering cooling mechanisms. The SSO will monitor the air temperature (as described later in this section) to determine potential adverse affects the weather can cause onsite personnel. Excess heat is dissipated by two means:

- Changes in blood flow to dissipate heat by convection, which can be seen as "flushing" or reddening of the skin in extreme cases.
- Perspiration is the release of water through skin and sweat glands. While working in hot environments, evaporation of perspiration is the primary cooling mechanism.

Protective clothing worn to guard against chemical contact effectively stops the evaporation of perspiration. Thus the use of protective clothing increases heat stress problems.

The major disorders due to heat stress are heat cramps, heat exhaustion, and heat stroke. Heat cramps are painful spasms, which occur in the skeletal muscles of workers who sweat profusely in the heat and drink large quantities of water, but fail to replace the bodies lost salts or electrolytes. Drinking water while continuing to lose salt tends to dilute the body's extracellular fluids. Soon water seeps by osmosis into active muscles and causes pain. Muscles fatigued from work are usually most susceptible to cramps.

Extreme weakness or fatigue, dizziness, nausea, and headache characterize heat exhaustion. In serious cases, a person may vomit or lose consciousness. The skin is clammy and moist, complexion pale or flushed, and body temperature normal or slightly higher than normal. Treatment is rest in a cool place and replacement of body water lost by perspiration. Mild cases may recover spontaneously with this treatment; severe cases may require care for several days. There are no permanent effects.

Heat stroke is a very serious condition caused by the breakdown of the body's regulating mechanisms. The skin is very dry and hot with red mottled or bluish appearance. Unconsciousness, mental confusion, or convulsions may occur. Without quick and adequate treatment, the result can be death or permanent brain damage. As first aid treatment, the person should be moved to a cool place. Body heat should be reduced artificially, but not too rapidly, by soaking the person's clothes in water and fanning them.

Steps that can be taken to reduce heat stress are:

- Acclimate the body. Allow a period of adjustment to make further heat exposure endurable.
- Drink more liquids to replace the body water lost during sweating.
- Rest is necessary and should be conducted under the direction of the SSO.
- Wear personal cooling devices. These are two basic designs; units with pockets for holding frozen packets and units that circulate fluid from a reservoir through tubes to different parts of the body. Both designs can be in the form of a vest, jacket, or coverall. Some circulating units also have a cap for cooling the head.
- Wear long cotton underwear under chemical protective clothing. The cotton will absorb perspiration and will hold it close to the skin. This will provide the body with the maximum cooling available from the limited evaporation that takes place beneath chemical resistant clothing. It also allows for rapid cooling of the body when the protective clothing is removed.

Heat stress is a significant hazard associated with using protective equipment in hot weather environments. Local weather conditions may produce conditions, which will require restricted work schedules in order to protect employees.

Appendix B contains procedures for heat stress; these will be used as a guideline and to provide additional information.

5.2.3 Cold Stress

Cold temperatures are a significant potential hazard. Examples of cold temperature hazards are frostbite and hypothermia.

Frostbite is the most common injury resulting from exposure to cold. The extremities of the body are most often affected. The signs of frostbite are:

- The skin turns white or grayish-yellow.
- Pain is sometimes felt early but subsides later. Often there is no pain.
- The affected parts feel intensely cold and numb.

Hypothermia is characterized by shivering, numbness, drowsiness, muscular weakness, and a low internal body temperature when the body feels extremely warm. This can lead to unconsciousness and death. With both frostbite and hypothermia, the affected areas need to be warmed quickly. Immersion in warm water is an effective means of warming the affected areas quickly. In such cases, medical assistance will be sought.

To prevent these effects from occurring, persons working in the cold should wear adequate clothing and reduce the time spent in the cold area. The field SSO is responsible for determining appropriate time personnel should spend in adverse weather conditions and will monitor this.

Appendix B, which contains the Heat and Cold Stress Guidelines, provides additional information.

5.2.4 Asbestos

Asbestos is a widely used, mineral-based material that is resistant to heat and corrosive chemicals. Depending on the chemical composition, fibers may range from course to silky. The properties that make asbestos fibers to valuable to industry are its high-tensile strength, flexibility, heat and chemical resistance, and good frictional properties. Asbestos is a common naturally occurring group of fibrous minerals. Asbestos fibers have been used in a variety of building materials; generally, most asbestos is found in pipe insulation, doors, textures paints and plasters, structural

fireproofing, and floor tiles. Friable asbestos (that is, material that contains more than 0.1% asbestos by weight and can be crumbled by hand) is a potential hazard because it can release fibers into the air if damaged. Roux Associates' personnel will not disturb any suspected asbestos material.

5.2.5 Structural Integrity

The structural integrity of a building and the safety of the individuals inside depend on meeting and maintaining national and local building codes. Structural integrity can range from minor defects such as loose floorboards and roof leaks to major defects such as floors and walls sagging and collapsed roofs. Numerous other structural defects can exist with or without consequence to the occupants. If Roux Associates personnel detect a problem, they should notify their supervisor, who in turn, should seek the opinion of a qualified structural engineer to offer and opinion regarding the integrity of the building. If in the opinion of the qualified engineer it is unsafe, no work can proceed until a solution to rectify the situation has been performed.

It is presently known that the majority of the onsite buildings have been unoccupied since approximately 2001 and site work performed by various parties has provided reports of severe disrepair, including roof collapse, to large areas of certain buildings on the property. As such, personnel will take this into consideration during the initial site visits and communicate this potential hazard during the safety tailgate meetings to all workers entering the site.

5.2.6 Lockout/Tagout

Roux Associates and all Site contractors will develop a lockout/tagout plan in the event of the repair of electrical, pneumatic, hydraulic, mechanical systems, per OSHA requirements under 29 CFR 1910.147.

5.3 Biological Hazards

The biological hazards, which have the potential to cause adverse health effects, are from exposure to domestic flies, mosquitoes, insects, animals and animal wastes, mold and bloodborne pathogens. The Activity Hazard Analysis (Appendix A) suggests controls for various hazards to be potentially encountered onsite.

5.3.1 Insect Stings

Stings from insects are often painful, cause swelling and can be fatal if a severe allergic reaction such as anaphylactic shock occurs. If a sting occurs, the stinger should be scraped out of the skin, opposite of the sting direction. The area should be washed with soap and water followed by application of an ice pack.

If the victim has a history of allergic reaction, he should be taken to the nearest medical facility. If the victim has medication to reverse the effects of the sting, it should be taken immediately.

If the victim experiences a severe reaction, a constricting band should be placed between the sting and the heart. The bitten area should be kept below the heart if possible. A physician should be contacted immediately for further instructions.

5.3.2 Animals and Animal Wastes

Due to most of the onsite structures being abandoned for several years, there lies the potential for various wildlife to reside within the structures, including, but not limited to, pigeons, bats, mice, rats, squirrels, raccoons, and feral cats. Certain animals can represent significant sources (vectors) of disease transmission. Precautions to avoid or minimize potential contact with (biting) animals (such as some of the above listed) or animal waste and/or deceased animals should be considered prior to all field activities. Rats, squirrels, raccoons, feral cats, and other wild animals can inflict painful bites which can also cause disease (as in the case of rabid animals). Site personnel should avoid contact with any of the above.

If contact occurs, be sure to clean the area thoroughly with soap and water as soon as possible. If a bite occurs, the area should be cleaned thoroughly immediately with soap and water and medical attention should be sought.

5.3.3 Mold

The various states of disrepair of the majority of the onsite structures have led to leaking roofs and the collection of water which may have led to the growth of mold within the buildings.

Although mold affects individuals differently and to different degrees, the following are some of the most common adverse health effects:

- Respiratory problems – wheezing, difficulty breathing;
- Nasal and sinus congestion;
- Eyes – burning, watery, reddened, blurry vision, light sensitivity;
- Dry, hacking cough;
- Sore throat;
- Nose and throat irritation;
- Shortness of breath and lung disease;
- Chronic fatigue;
- Skin irritation;
- Central nervous system (headaches, loss of memory, and mood changes);
- Aches and pains;
- Fever;
- Headaches;
- Diarrhea; and
- Immune suppression.

Decisions about removing individuals from an affected area must be based on the results of a medical evaluation, and be made on a case-by-case basis.

Workers that discover the visible presence of mold in excess of 10 sq. feet need to notify the SSO for consultation. If a worker smells mold and feels that he/she is experiencing symptoms of exposure, he/she should retreat and report the symptoms to the SSO.

5.3.4 Bloodborne Pathogens

The majority of the occupational tasks onsite will not involve a significant risk of exposure to blood, blood components, or body fluids. The highest risk of acquiring any bloodborne pathogen

for employees onsite will be following an injury. When administering first aid care, there are potential hazards associated with bloodborne pathogens that cause diseases such as Human Immunodeficiency Virus (HIV), Hepatitis B (HBV), Hepatitis A (HAV), Hepatitis C (HCV), or the Herpes Simplex Virus (HSV). An employee who has not received the appropriate certification should never execute first aid and/or CPR.

In order to minimize any potential pathogen exposure, all employees should use the hand washing facilities on a regular basis. Additionally, the following universal precautions should be followed to prevent further potential risk:

- Direct skin or mucous membrane contact with blood should be avoided.
- Open skin cuts or sores should be covered to prevent contamination from infectious agents.
- Body parts should be washed immediately after contact with blood or body fluids that might contain blood, even when gloves or other barriers have been used.
- Gloves and disposable materials used to clean spilled blood shall be properly disposed of in an approved hazardous waste container.
- First aid responders shall wear latex or thin mil nitrile gloves when performing any procedure risking contact with blood or body substances.
- Safety glasses will be worn to protect the eyes from splashing or aerosolization of body fluids.
- A CPR mask will be worn when performing CPR to avoid mouth-to-mouth contact.
- Work gloves will be worn to minimize the risk of injury to the hands and fingers when working on all equipment with sharp or rough edges.
- Never pick up broken glass or possible contaminated material with your unprotected hands.
- Never handle wildlife (living or deceased) encountered onsite.

5.4 Hazard Assessment

Task	Hazards	Risk of Exposure
Decontamination	Inhalation/Skin Contact	Moderate
	Heat Stress/Cold Stress	Moderate
	Physical Injury	Moderate
	Noise	Low
Drilling/Sampling	Inhalation/Skin Contact	Moderate
	Heat Stress/Cold Stress	Moderate
	Noise	Moderate/High
	Physical Injury	Moderate

6.0 TRAINING

6.1 General Health and Safety Training

In accordance with Roux Associates' corporate policies, and pursuant to 29 CFR 1910.120, hazardous waste site workers shall, at the time of the job assignment, have received a minimum of 40 hours of initial health and safety training for hazardous waste site operations. As a minimum, the training shall have consisted of instruction in the topics outlined in the above reference. Personnel who have not met the requirements for initial training will not be allowed to work in any Site activities in which they may be exposed to hazards (chemical or physical).

Completion of a 40-hour Health and Safety Training Course for Hazardous Waste Operations or an approved equivalent will fulfill the requirements of this section.

In addition to the required initial training, each employee shall have received 3 days of directly supervised on-the-job training. This training will address the duties the employees are expected to perform.

Roux Associates' SSO has the responsibility of ensuring that personnel assigned to this project comply with these requirements.

6.2 Annual Eight-Hour Refresher Training

Annual 8-hour refresher training will be required of all hazardous waste site field personnel in order to maintain their qualifications for fieldwork. The following topics will be reviewed; toxicology, respiratory protection, including air purifying devices and self-contained breathing apparatus (SCBA), medical surveillance, decontamination procedures, and personal protective clothing. In addition, topics deemed necessary by Roux Associates' Health and Safety Director may be added to the above list.

6.3 Site-Specific Training

Site personnel will receive training that will specifically address the activities, procedures, monitoring, and equipment for Site operations. It will include Site and facility layout, hazards, first aid equipment locations and emergency services at the Site, and will highlight all provisions contained within this HASP. This training will also allow field workers to clarify anything they do

not understand and to reinforce their responsibilities regarding safety and operations for their particular activity.

6.4 Onsite Safety Meetings

Daily safety meetings will be presented each morning to discuss potential safety concerns for the upcoming activities.

The briefings will also provide a forum to facilitate conformance with safety requirements and to identify performance deficiencies related to safety during daily activities or as a result of safety audits by Roux Associates or other involved parties.

6.5 First Aid and CPR

The SSO will identify those individuals having first aid and CPR training in order to ensure that emergency medical treatment is available during field activities. The training will be consistent with the requirements of the American Red Cross Association. Certification and appropriate training documentation will be kept with the Site personnel records.

6.6 Additional Training

The CHSM may require additional or specialized training throughout the project. Such training shall be in the safe operation of heavy or power tool equipment or hazard communication training or other topic deemed Site appropriate.

6.7 Subcontractor Training

All subcontractor personnel working on the Site shall have completed the 40-hour training requirement and meet the medical surveillance requirements found in Section 7.1. Subcontractor training shall be performed in accordance with 29 CFR 1910.120 and HASP specifications. In certain unique situations (e.g., mechanical failure of equipment), the non-trained individual performing emergency repairs may be allowed, at the discretion of the SSO, to perform repairs when no intrusive activities are being performed, and provisions have been made to mitigate potential exposure.

7.0 MEDICAL SURVEILLANCE PROCEDURES

7.1 General

A Medical Surveillance Program has been established as part of this plan and is included in Appendix C. Roux Associates and subcontractor personnel performing field work at the Site are required to have passed a complete medical surveillance examination in accordance with 29 CFR 1910.120(f). A physician's medical release for work will be confirmed by the SSO before an employee can begin Site activities. Such examinations shall include a statement as to the worker's present health status, the ability to work in a hazardous environment (including any required PPE, which may be used during temperature extremes), and the worker's ability to wear respiratory protection.

Appendix C, "Medical Data Sheet," will be completed by all permanent, onsite personnel and will be kept in Roux Associates offices during the conduct of Site operations. Completion is required in addition to compliance with Roux Associates' Health and Safety Program. This data sheet will be available through the Roux Associates Human Resources Department if medical assistance is needed or if transport to hospital facilities is required.

8.0 SITE CONTROL, PERSONAL PROTECTIVE EQUIPMENT, AND COMMUNICATIONS

A modified Site control approach may be utilized since activities will be limited to site inspection/geophysical survey, drilling and sampling only during this phase of work. If remedial work is necessary, the following four-zone approach will be used.

8.1 Site Control

Based on the Site history and operations, a potential for the presence of hazardous material does exist. During drilling and sampling, work areas will be delineated with high visibility cones and/or caution tape. A dedicated decontamination area will be established to decontaminate all equipment used for sampling.

If remedial activities are necessary, a four-zone approach will be employed in order to prevent the spread of contamination from the disturbed areas onsite. The four zones include: the Exclusion Zone (EZ), the Contamination Reduction Zone (CRZ), Contamination Reduction Corridor (CRC) and the Support Zone (SZ). A stepped remedial approach will be managed, and the zones modified as the work progresses. Each of the areas will be defined through the use of control barricades and/or construction/hazard fencing. A clearly marked delineation between the SZ and the remaining three zones, the CRZ and CRC and the EZ will be maintained. The preferred method will utilize high visibility orange fencing and hand driven metal posts, or orange cones. Signage will be posted to further identify and delineate these areas.

8.1.1 Support Zone

The Support Zone (SZ) is an uncontaminated area that will be the field support area for the Site operations. The SZ will contain the temporary project trailers and provides for field team communications and staging for emergency response. Appropriate sanitary facilities and safety equipment will be located in this zone. Potentially contaminated personnel or materials are not allowed in this zone. The only exception will be appropriately packaged/decontaminated and labeled samples. Meteorological conditions will be observed and noted from this zone, as well as those factors pertinent to heat and cold stress.

8.1.2 Contamination Reduction Zone

A Contamination Reduction Zone (CRZ) is established between the exclusion zone and the support zone. The CRZ contains the Contamination Reduction Corridor (CRC) and provides an area for decontamination of personnel and equipment. The CRZ will be used for general Site entry and egress in addition to access for heavy equipment and emergency support services. Personnel are not allowed in the CRZ without:

- A buddy (co-worker);
- Appropriate PPE;
- Medical authorization;
- Training certification; and
- A need to be in the zone.

8.1.3 Exclusion Zone

The area where contamination exists is considered to be the Exclusion Zone (EZ). All areas where excavation and handling of contaminated materials take place are considered the EZ. This zone will be clearly delineated by orange high visibility fencing. Safety tape may be used as a secondary delineation within the EZ. The zone delineation markings may be opened in areas for varying lengths of time to accommodate equipment operation or specific construction activities. The SSO may establish more than one EZ where different levels of protection may be employed or where different hazards exist. Personnel are not allowed in the EZ without:

- A buddy (co-worker);
- Appropriate PPE;
- Medical authorization;
- Training certification; and
- A need to be in the zone.

8.2 Personal Protective Equipment

8.2.1 General

The level of protection worn by field personnel will be enforced by the SSO. Levels of protection for general operations are provided below and are defined in this section. Levels of protection

may be upgraded at the discretion of the SSO. All decisions on the level of protection will be based upon a conservative interpretation by the SSO of the information provided by air monitoring results, environmental results and other appropriate information. Any changes in the level of protection shall be recorded in the health and safety field logbook.

8.2.2 Personal Protective Equipment Specifications

The initial level of personal protective equipment is Level D. It is not anticipated that either Level B or Level C protection will be necessary.

Although not anticipated, any tasks requiring Level B personal protective equipment (PPE) will utilize the following equipment:

- Positive pressure, full facepiece, self-contained breathing apparatus (SCBA) or positive pressure, supplied air respirator with escape SCBA (NIOSH approved)
- Disposable coveralls (Tyvek, Poly-coated Tyvek, or Saranex)
- Gloves, inner: latex or nitrile
- Gloves, outer: nitrile or neoprene
- Chemical resistant boots over the work boots
- Steel toe work boots
- Hard hat
- Hearing protection (as needed)
- Boot cover (as needed)

For tasks requiring Level C PPE, the following equipment may be used in any combination:

- Full-face, air purifying, canister-equipped respirators (NIOSH approved) utilizing Organic Vapor/Acid Gas and P-100 filters (half-face if approved by SSO)
- Disposable coveralls (Tyvek, Poly-coated Tyvek, or Saranex) as required
- Gloves, inner: latex or nitrile as required
- Gloves, outer: nitrile or neoprene as required
- Chemical resistant boots over the work boots as required

- Steel toe work boots
- Hard hat
- Hearing protection (as needed)
- Safety glasses (if half-mask is utilized)
- Boot covers (as needed)

The Minimum level of PPE for entry onto the Site is Level D PPE. The following equipment shall be used:

- Work uniform (long pants, sleeved shirt)
- Hard hat
- Steel toe work boots
- Safety glasses
- Boot covers (as needed)
- Hearing protection (as needed)
- Reflective safety vest

Modified Level D PPE consists of the following:

- Regular Tyvek coveralls (Poly-coated Tyvek as required)
- Outer gloves: leather, cotton, neoprene or nitrile (as required)
- Inner gloves: latex or nitrile (doubled) as required
- Chemical resistant boots over work boots (as required)
- Steel toe work boots
- Hard hat
- Safety glasses
- Hearing protection as needed
- Reflective safety vest

8.2.3 Initial Levels of Protection

Levels of protection for the proposed scope of work may be upgraded or downgraded depending on direct-reading instruments or personnel monitoring. The following are the initial levels of protection that shall be used for each planned field activity:

Activity	Initial level of PPE
Mobilization/Demobilization	D
Site Inspection/Geophysical Survey	D
Decontamination	D
Drilling	D
Groundwater Sampling	D

8.3 Communications

If working in level C/B respiratory protection is required, personnel may find that communication becomes a more difficult task and process to accomplish. Distance and space further complicate this. In order to address this problem, electronic instruments, mechanical devices, or hand signals will be used as follows:

Telephones – Mobile telephones will be carried by designated personnel for communication with emergency support services/facilities.

Radios – Two-way radios will be utilized onsite for communications between field personnel in areas where visual contact cannot be maintained and where hand signals cannot be employed.

Air Horn – Available as posted in the Site trailer or support zone to alert field personnel to an emergency situation. The emergency signal will be the sharp blasts of the air horn.

Hand Signals – This communication method will be employed by members of the field team along with use of the buddy system. Signals become especially important when in the vicinity of heavy moving equipment and when using Level B respiratory equipment. The signals shall become familiar to the entire field team before Site operations commence, and will be reinforced and reviewed during site-specific training.

Signal	Meaning
Hand gripping throat	Out of air; can't breathe
Grip partner's wrist	Leave area immediately; no debate
Hands on top of head	Need assistance
Thumbs up	OK; I'm all right; I understand
Thumbs down	No; Unable to understand you, I'm not all right

9.0 MONITORING PROCEDURES

9.1 General

Monitoring will be performed to verify the adequacy of respiratory protection, to aid in Site layout, and to document worker exposure. If air monitoring in these areas indicates the presence of potentially hazardous materials, control measures will be implemented. All monitoring instruments shall be operated by qualified personnel only and will be calibrated daily prior to use or, more often, as necessary. General monitoring during intrusive site activities will be performed in accordance with the Community Air Monitoring Plan included as Appendix D.

9.2 Exclusion Zone Monitoring

9.2.1 Instrumentation

The following monitoring instruments will be available for use during field operations as necessary. There will be a minimum of one of each piece of equipment on the Site at all times:

- Photoionization Detector (PID) with 10.6 EV probe or Flame Ionization Detector (FID) or equivalent.
- Dust/Particulate Monitor (DM), MIE Miniram, or equivalent.

A PID will be used to monitor VOCs in active work areas, during intrusive activities. VOCs shall also be measured upwind of the work areas to determine background concentrations.

A particulate monitor shall be used to measure concentrations of dust and particulate matter.

When deemed necessary, a CGI/O_2 meter shall be used to monitor for combustible gases and oxygen content during confined space entry or when the HSO deems necessary.

Calibration records shall be documented and recorded daily and included in the daily air monitoring report. This report will be specific to work area monitoring. All instruments shall be calibrated before and after each daily use in accordance with manufacturer's procedures (Appendix E).

9.2.2 Action Levels

Action levels for the upgrading of PPE requirements in the HASP will apply to all Site work during investigation and remediation activities at the Site. Action levels are for known contaminants using direct reading instruments in the Breathing Zone (BZ) for VOCs and particulates, and at the source for combustible gases. The BZ will be determined by the SSO, but is typically 4 to 5 feet above the work area surface or elevation. The action levels to be utilized for the Site are found in Table 2.

9.2.3 Monitoring During Field Activities

Intrusive Operations – Continuous Personnel Breathing Zone Air Monitoring will be performed by the SSO during drilling activities. Real-time monitoring for all onsite activities will be accomplished as follows:

- Monitoring of VOCs in and around the work zones.
- Monitoring for particulates in and around the work zones, when necessary.

The frequency of monitoring may be modified by the SSO, after consultation with the Project Manager. The rationale for any modification must be documented in the HASP.

10.0 SAFETY CONSIDERATIONS

10.1 General

In addition to the specific requirements of this HASP, common sense should be used at all times.

The following general safety rules and practices will be in effect at the site.

- All open holes, trenches, and obstacles will be properly barricaded in accordance with local Site needs and requirements. Proximity to traffic ways, both pedestrian and vehicular, and location of the open hole, trench, or obstacle will determine these needs.

- All excavation and other Site work will be planned and performed with consideration for underground lines.

- Smoking and ignition sources in the vicinity of potentially flammable or contaminated material are strictly prohibited.

- Drilling, boring, and use of cranes and drilling rigs, erection of towers, movement of vehicles and equipment, and other activities will be planned and performed with consideration for the location, height, and relative position of aboveground utilities and fixtures, including signs; lights; canopies; buildings and other structures and construction; and natural features such as trees, boulders, bodies of water, and terrain.

- When working in areas where flammable vapors may be present, particular care shall be exercised with tools and equipment that may be sources of ignition. All tools and equipment provided must be properly bonded and/or grounded.

- Approved and appropriate safety equipment (as specified in this HASP), such as eye protection, hard hats, hand protection (nitrile, leather and/or cut resistant gloves as necessary), foot protection, and respirators, must be worn in areas where required. In addition, eye protection must be worn when sampling soil or water that may be contaminated.

- All site personnel may be called upon to use respirator protection in some situations. Fit testing will be necessary for all persons using respirators. The criteria for facial hair will be determined by the SSO. In general, the guideline is that facial hair cannot impede the fit of the respirator.

- No smoking, eating, chewing tobacco, gum chewing or drinking will be allowed outside the SZ.

- Contaminated tools and hands must be kept away from the face.

- Personnel must use personal hygiene safe guards (washing up) at the end of the shift.

- Each sample must be treated and handled as though it were contaminated.

- Persons with long hair and/or loose-fitting clothing that could become entangled in power equipment must take adequate precautions.

- Horseplay is prohibited in the work area.
- Work while under the influence of intoxicants, narcotics, or controlled substances is strictly prohibited.

10.2 Traffic Control

Traffic control methods and barricades will be used as needed when working in areas of vehicular traffic. Since the site is fenced off and the areas of investigation are not in current use, outside vehicular and pedestrian traffic is not considered to be an issue.

10.3 Sample Handling

Personnel responsible for handling of samples will wear the prescribed level of protection. Samples are to be identified as to their hazard and packaged as to prevent spillage or breakage. Any unusual sample conditions shall be noted. Laboratory personnel and all field personnel shall be advised of sample hazard levels and the potential contaminants present. This can be accomplished by a phone call to the lab coordinator and/or including a written statement with the samples reviewing lab safety procedures in handling in order to assure that the practices are appropriate for the suspected contaminants in the sample.

11.0 DECONTAMINATION AND DISPOSAL PROCEDURES

11.1 Contamination Prevention

Contamination prevention should minimize worker exposure and help ensure valid sample results by precluding cross-contamination. Procedures for contamination avoidance include:

Personnel

- Do not walk through areas of obvious or known contamination.
- Do not directly handle or touch contaminated materials.
- Make sure that there are no cuts or tears on PPE.
- Fasten all closures in suits; cover with tape, if necessary.
- Particular care should be taken to protect any skin injuries.
- Stay upwind of airborne contaminants.
- Do not carry cigarettes, cosmetics, gum, etc., into contaminated areas.

Sampling/Monitoring

- When required by the SSO, cover instruments with clear plastic, leaving openings for sampling ports.
- Bag sample containers prior to emplacement of sample material.

Heavy Equipment

- Care should be taken to limit the amount of contamination that comes in contact with heavy equipment (tires, contaminated augers).
- If contaminated tools are to be placed on non-contaminated equipment for transport to a decontamination area, plastic should be used to keep the equipment clean.
- Dust control measures including water misting will be used on roads inside the Site boundaries.

11.2 Personnel Decontamination

A field wash for equipment and PPE shall be set up and maintained for all persons exiting the EZ. The system will include a gross wash and rinse for all disposable clothing and boots worn in the EZ. As necessary, equipment and facilities will be available for personnel to wash their hands, arms, neck, and face.

11.3 Equipment Decontamination

All potentially contaminated equipment used at the Site will be decontaminated to prevent contaminants from leaving the Site. The decontamination area will provide for the containment of all wastewater from the decontamination process. Respirators and any other PPE that comes in contact with contaminated materials shall pass through a field wash in the decontamination area, and a thorough decontamination at the end of the day. All decontamination rinse water will be collected and managed in accordance with all applicable regulations.

11.4 Decontamination during Medical Emergencies

If emergency life-saving first aid and/or medical treatment are required, normal decontamination procedures may need to be abbreviated or omitted. The Site SSO or designee will accompany contaminated victims to the medical facility to advise on matters involving decontamination, when necessary. The outer garments can be removed if they do not cause delays, interfere with treatment, or aggravate the problem. Respiratory equipment must always be removed. Protective clothing can be cut away. If the outer contaminated garments cannot be safely removed, a plastic barrier between the individual and clean surfaces should be used to help prevent contaminating the inside of ambulances and/or medical personnel. Outer garments are then removed at the medical facility. No attempt will be made to wash or rinse the victim, unless it is known that the individual has been contaminated with an extremely toxic or corrosive material, which could also cause severe injury or loss of life to emergency response personnel. For minor medical problems (ambulatory) or injuries, the normal decontamination procedures will be followed. Note that heat stroke requires prompt treatment to prevent irreversible damage or death. Protective clothing must be promptly removed. Less serious forms of heat stress also require prompt attention and removal of protective clothing immediately. Unless the victim is obviously contaminated, decontamination should be omitted or minimized, and treatment begun immediately.

11.5 Disposal Procedures

A system of segregating all waste will be developed by the SSO.

All discarded materials, waste materials, or other objects shall be handled in such a way as to preclude the potential for spreading contamination, creating a sanitary hazard, or causing litter to

be left onsite. All potentially contaminated materials (e.g., clothing, gloves, etc.,) will be bagged or drummed as necessary, labeled and segregated for disposal. All non-contaminated materials shall be collected and bagged for appropriate disposal as domestic waste.

12.0 EMERGENCY PLAN

Should an emergency situation occur, the emergency plan, outlined in this section, shall be known by Roux Associates and all Subcontractors prior to the start of work. The emergency plan will be available for use at all times during Site work. The plan provides the phone numbers for the fire, police, ambulance, hospital, poison control centers, and directions to the hospital from the Site. This information is to be found in Section 1.2 of the HASP.

Various individual Site characteristics will determine preliminary actions taken to assure that this emergency plan is successfully implemented in the event of a Site emergency. Careful consideration must be given to the proximity of neighborhood housing or places of employment, and to the relative possibility of Site release of vapors, which could affect the surrounding community.

The emergency coordinator shall implement the contingency plan whenever conditions at the Site warrant such action. The coordinator will be responsible for coordination of the evacuation, emergency treatment and transport of Site personnel as necessary, and notification of emergency response units and the appropriate management staff.

In cases where the project manager is not available, the SSO shall serve as the alternate emergency coordinator.

The SSO during an emergency will perform air monitoring as needed, as well as lend assistance and provide health and safety information to responding emergency personnel.

Site Personnel will endeavor to keep non-essential personnel away from the incident until the appropriate emergency resources arrive. At that time, the responders will take control of the Site. Site personnel may be asked to lend assistance to emergency personnel such as during evacuations, help with the injured, etc.

12.1 Evacuation

Evacuation procedures will be discussed prior to the start of work and periodically during safety meetings. In the event of an emergency situation, such as fire, or explosion, an air horn,

automobile horn, or other appropriate device will be sounded for three (3) sharp blasts indicating the initiation of evacuation procedures. The emergency evacuation route shall be known by all site workers. Under no circumstances will incoming personnel or visitors be allowed to proceed into the area once the emergency signal has been given. The SSO or project manager must ensure that access for emergency equipment is provided and that all combustion apparatuses have been shut down once the alarm has been sounded. All Site personnel will assemble in the designated nearest safe location. Once the safety of all personnel is established, the fire department and other emergency response groups will be notified by telephone of the emergency.

12.2 Personnel Injury

Emergency first aid shall be applied onsite as appropriate. If necessary, the individual shall be decontaminated and transported to the nearest hospital. The SSO will supply medical data sheets to medical personnel and complete the accident/incident reports in accordance with Section 13.4 of the HASP.

The ambulance/rescue squad shall be contacted for transport as necessary in an emergency. However, since some situations may require transport of an injured party by other means, the injured person shall be escorted to the hospital. A map to this facility is shown in Figure 2.

12.3 Accident/Incident Reporting

As soon as first aid and/or emergency response needs have been met, the following parties are to be contacted by telephone: (Direct contact, no phone messages).

		Office:	**Cell:**
1. Project Director:	Craig Werle	631-232-2600	631-793-1535
2. Office Health and Safety Manager:	Joe Gentile	856-423-8800	610-844-6911
3. Site Health and Safety Officer:	TBD	631-232-2600	

4. The employer of any injured worker, if not a Roux Associates employee.

Written confirmation of verbal reports are to be submitted within 24 hours. The report form entitled "Accident Report and Investigation Form" (Appendix F) is to be used for this purpose.

All representatives contacted by telephone are to receive a copy of this report. If the employee involved is not a Roux Associates employee, his employer shall receive a copy of the report. In addition to filling out the Accident Report and Investigation Form, if a Roux employee is involved in a vehicle accident, the employee must also complete the Acord form (Appendix G).

For reporting purposes, the term accident refers to fatalities, lost time injuries, spill or exposure to hazardous materials (radioactive materials, toxic materials, explosive or flammable materials), fire, explosion, property damage, or potential occurrence (i.e., near miss) of the above.

Any information released from the health care provider, which is not deemed confidential patient information, is to be attached to the appropriate form. Any medical information, which is released by patient consent, is to be filed in the individual's medical record and treated as confidential.

12.4 Personnel Exposure

Skin Contact:	Use copious amounts of soap and water. Wash/rinse affected area thoroughly, then provide appropriate medical attention. Eyes should be rinsed for 15 minutes upon chemical contamination.
Inhalation:	Move to fresh air and/or, if necessary, decontaminate/transport to hospital.
Ingestion:	Decontamination and transport to emergency medical facility.
Puncture Wound or Laceration:	Decontamination and transport to emergency medical facility.

12.5 Adverse Weather Conditions

In the event of adverse weather conditions, the SSO or project manager will determine if work can continue without sacrificing the health and safety of all field workers. Some of the items to be considered prior to determining if work should continue are:

- Potential for heat stress and heat-related injuries.
- Potential for cold stress and cold-related injuries.
- Treacherous weather-related conditions.
- Limited visibility.
- Electrical storm potential.

Site activities will be limited to daylight hours and acceptable weather conditions. Inclement working conditions include heavy rain, fog, high winds, and lightning. Observe daily weather reports and evacuate if necessary in case of inclement weather conditions.

13.0 LOGS, REPORTS AND RECORD KEEPING

The following is a summary of required health and safety logs, reports, and record keeping for this project.

13.1 Medical and Training Records

The employer keeps medical and training records. The subcontractor employer must provide verification of training and medical qualifications to the SSO. The SSO will keep a log of personnel meeting appropriate training and medical qualifications for Site work. The log will be kept in the project file. Roux Associates will maintain medical records in accordance with 29 CFR 1910.20.

13.2 Onsite Log

The SSO or project manager will keep a log of onsite personnel daily in the designated field book.

13.3 Exposure Records

Any personal monitoring results, laboratory reports, calculations, and air sampling data sheets are part of an employee exposure record. These records will be kept by Roux Associates in accordance with 29 CFR 1910.20.

13.4 Accident/Incident Reports

An accident/incident report must be completed following procedures given in Appendix F. The originals will be sent to Roux Associates for maintenance. Copies will be distributed as stated. A copy of the forms will be kept in the project file.

13.5 OSHA Form 300

An OSHA Form 300 (Log of Occupational Injuries and Illnesses) (Appendix H) will be kept at the Site. All reportable injuries or illnesses will be recorded on this form. At the end of the project, the original will be sent to Roux Associates for maintenance. Subcontractor employers must also meet the requirements of maintaining an OSHA 300 form.

13.6 Daily Safety Logs

The Daily Safety Log form in Appendix E will be completed daily by the SSO and submitted to the project manager.

13.7 Weekly Safety Reports

The Weekly Safety Reports in Appendix I will be completed by the SSO and submitted to the designated Owner's representative, if requested.

13.8 Close-Out Safety Report

At the completion of the work, Roux Associates will submit a closeout Safety Report that will include all logs and reports generated during the project. The report will be signed and dated by the SSO and submitted to the Safety Manager and/or Owner's representative, if requested.

14.0 FIELD TEAM REVIEW

Each Roux Associates employee or subcontractor shall sign this section after site-specific training is completed and before being permitted to work at the Site.

I have read and reviewed the Site Health and Safety Plan prepared for this Site. I understand and will comply with the provisions contained therein.

Site/Project: Equity One (Northeast Portfolio) Inc.
900 Old Country Road
Garden City, New York

Date	Name	Signature	Company

SSO CERTIFICATION OF HOSPITAL DIRECTIONS

Name of Roux Associates SSO:

Date:_____

This is to certify that on _____, I personally drove the route to Winthrop University Hospital as listed in the HASP. The Map Routing and Directions were/were not as listed in the plan. Listed below were conditions that resulted in different directions.

_____
Roux Associates Site Health and Safety Officer

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
1,1,1-Trichloroethane	71-55-6	TWA 350 ppm STEL 440 ppm C 440 ppm	C 350 ppm (1900 mg/m^3) [15-minute]	TWA 350 ppm (1900 mg/m^3)	700 ppm	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin; headache, lassitude (weakness, exhaustion), central nervous system depression, poor equilibrium; dermatitis; cardiac arrhythmias;	Eyes, skin, central nervous system, cardiovascular system, liver	Colorless liquid with a mild, chloroform-like odor. BP: 165°F UEL: 12.5% LEL: 7.5%
1,1,2-Trichloroethane	79-00-5	TWA 10 ppm	Ca TWA 10 ppm (45 mg/m^3) [skin]	TWA 10 ppm (45 mg/m^3) [skin]	Ca [100 ppm]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, nose; central nervous system depression; liver, kidney damage; dermatitis; [potential occupational carcinogen]	Eyes, respiratory system, central nervous system, liver, kidneys	Colorless liquid with a sweet, chloroform-like odor. BP: 237°F UEL: 15.5% LEL: 6%
1,1-Dichloroethane	75-34-3	TWA 100 ppm	TWA 100 ppm (400 mg/m^3)	TWA 100 ppm (400 mg/m^3)	3000 ppm	inhalation, ingestion, skin and/or eye contact	Irritation skin; central nervous system depression; liver, kidney, lung damage	Skin, liver, kidneys, lungs, central nervous system	Colorless, oily liquid with a chloroform-like odor. BP: 135°F Fl.P: 2°F UEL: 11.4% LEL: 5.4%
1,1-Dichloroethene	75-35-4	TWA 5 ppm	Ca (lowest feasible concentration)	TWA 1ppm	Ca [N.D.]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin, throat; dizziness, headache, nausea, dyspnea (breathing difficulty); liver, kidney disturbance; pneumonitis; [potential occupational carcinogen]	Eyes, skin, respiratory system, central nervous system, liver, kidneys	Colorless liquid or gas (above 89°F) with a mild, sweet, chloroform-like odor. BP: 89°F Fl.P: -2°F UEL: 15.5% LEL: 6.5% Class IA Flammable Liquid
1,2,4-Trimethylbenzene	95-63-6	None established	TWA 25 ppm (125mg/m^3)	None established	N.D.	Inhalation; ingestion; skin and/or eye contact	Eye, skin, nose, and throat, resp syst irritation; bronchitis; hypochromic anemia; headache, drowsiness, weakness, dizziness, nausea, incoordination, vomit, confusion; chemical pneumonitis	Eyes, skin, resp sys, CNS, blood	Clear, colorless liquid with a distinctive, aromatic odor BP: 337°F FL.P: 112°F UEL: 6.4% LEL: 0.9% Class II Flammable liquid
1,2,4-Trimethylbenzene	95-63-6	TWA 25 ppm (125 mg	TWA 25 ppm (125 mg/m^3)	None established	N.D.	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, throat, respiratory system; bronchitis; hypochromic anemia; headache, drowsiness, fatigue, dizziness, nausea, incoordination; vomiting, confusion; chemical pneumonitis (aspiration liquid)	Eyes, skin, respiratory system, central nervous system, blood	Clear, colorless liquid with a distinctive, aromatic odor. BP: 337°F Fl.P: 112°F UEL: 6.4% LEL: 0.9% Class II Flammable Liquid
1,2-Dichlorobenzene	95-50-1	TWA 25 ppm STEL 50 ppm	C 50 ppm (300 mg/m^3)	C 50 ppm (300 mg/m^3)	200 ppm	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, nose; liver, kidney damage; skin blisters	Eyes, skin, respiratory system, liver, kidneys	Colorless to pale-yellow liquid with a pleasant, aromatic odor. [herbicide] BP: 357°F Fl.P: 151°F UEL: 9.2% LEL: 2.2% Class IIIA Combustible Liquid

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
1,2-Dichloroethane	107-06-2	TWA 10 ppm	Ca TWA 1 ppm (4 mg/m^3) STEL 2 ppm (8 mg/m^3)	TWA 50 ppm C 100 ppm 200 ppm [5-minute maximum peak in any 3 hours]	Ca [50 ppm]	inhalation, ingestion, skin absorption, skin and/or eye contact	Irritation eyes, corneal opacity; central nervous system depression; nausea, vomiting; dermatitis; liver, kidney, cardiovascular system damage; [potential occupational carcinogen]	Eyes, skin, kidneys, liver, central nervous system, cardiovascular system	Colorless liquid with a pleasant, chloroform-like odor. [Note: Decomposes slowly, becomes acidic & darkens in color.] BP: 182°F Fl.P: 56°F UEL: 16% LEL: 6.2% Class IB Flammable Liquid
1,2-Dichloroethene (total)	540-59-0	TWA 200 ppm (790 m	TWA 200 ppm (790 mg/m^3)	TWA 200 ppm (790 mg/m^3)	1000 ppm	inhalation, ingestion, skin and/or eye contact	Irritation eyes, respiratory system; central nervous system depression	Eyes, respiratory system, central nervous system	Colorless liquid (usually a mixture of the cis & trans isomers) with a slightly acrid, chloroform-like odor BP: 118-140°F Fl.P: 36-39°F UEL: 12.8% LEL: 5.6% Class IB Flammable Liquid
1,3,5-Trimethylbenzene	108-67-8	None established	TWA 25 ppm (125mg/m^3)	None established	N.D.	Inhalation; ingestion; skin and/or eye contact	Eye, skin, nose, and throat, resp syst irritation; bronchitis; hypochromic anemia; headache, drowsiness, weakness, dizziness, nausea, incoordination, vomit, confusion; chemical pneumonitis	Eyes, skin, resp sys, CNS, blood	Clear, colorless liquid with a distinctive, aromatic odor BP: 329°F FL.P: 122°F Class II Flammable liquid
1,3,5-Trimethylbenzene	108-67-8	TWA 25 ppm (125 mg	TWA 25 ppm (125 mg/m^3)	None established	N.D	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, throat, respiratory system; bronchitis; hypochromic anemia; headache, drowsiness, lassitude (weakness, exhaustion), dizziness, nausea, incoordination; vomiting, confusion; chemical pneumonitis (aspiration liquid)	Eyes, skin, respiratory system, central nervous system, blood	Clear, colorless liquid with a distinctive, aromatic odor. BP: 329°F Fl.P: 122°F Class II Flammable Liquid
1,4-Dichlorobenzene	106-46-7	TWA 10 ppm	Ca	TWA 75 ppm (450 mg/m^3)	Ca [150 ppm]	inhalation, skin absorption, ingestion, skin and/or eye contact	Eye irritation, swelling periorbital (situated around the eye); profuse rhinitis; headache, anorexia, nausea, vomiting; weight loss, jaundice, cirrhosis; in animals: liver, kidney injury; [potential occupational carcinogen]	Liver, respiratory system, eyes, kidneys, skin	Colorless or white crystalline solid with a mothball-like odor. [insecticide] BP: 345°F Fl.P: 150°F LEL: 2.5% Combustible Solid
2,4-Dimethylphenol	105-67-9	None established	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin, respiratory system, mouth, throat, stomach; dizziness, weakness, fatigue, nausea, headache; systemic damage; moderate to severe eye injury.	Skin, CVS, eyes, CNS	Clear, colorless liquid with a faint ether or chloroform-like odor BP: 178°F

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
2-Butanone (MEK)	78-93-3	TWA 200 ppm (590 mg/m^3) STEL 300 ppm (885 mg/m^3)	TWA 200 ppm (590 mg/m^3) STEL 300 ppm (885 mg/m^3)	TWA 200 ppm (590 mg/m^3)	3000 ppm	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose; headache; dizziness; vomiting; dermatitis	Eyes, skin, respiratory system, central nervous system	Colorless liquid with a moderately sharp, fragrant, mint- or acetone-like odor. BP: 175°F Fl.P: 16°F UEL(200°F): 11.4% LEL(200°F): 1.4% Class IB Flammable Liquid
Acenaphthene	83-32-9	None established	None established	None established	None established	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, respiratory system	Eyes, skin, respiratory system	Brown solid
Acetone	67-64-1	TWA 500 ppm STEL 50 ppm	TWA 250 ppm (590 mg/m^3)	TWA 1000 ppm (2400 mg/m^3)	2500 ppm [10%LEL]	inhalation, ingestion, skin and/or eye contact	Irritation eyes, nose, throat; headache, dizziness, central nervous system depression; dermatitis	Eyes, skin, respiratory system, central nervous system	Colorless liquid with a fragrant, mint-like odor BP: 133°F Fl.P: 0°F UEL: 12.8% LEL: 2.5% Class IB Flammable Liquid
Anthracene	65996-93-2	TWA 0.2 mg/m^3	Ca TWA 0.1 mg/m^3 (cyclohexane-extractable fraction)	TWA 0.2 mg/m^3 (benzene-soluble fraction)	Ca [80 mg/m^3]	inhalation, skin and/or eye contact	Dermatitis, bronchitis, [potential occupational carcinogen]	respiratory system, skin, bladder, kidneys	Black or dark-brown amorphous residue. Combustible Solids
Antimony	7440-36-0	TWA 0.5 mg/m^3	TWA 0.5 mg/m^3	TWA 0.5 mg/m^3	50 mg/m^3 (as Sb	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, throat, mouth; cough; dizziness; headache; nausea, vomiting, diarrhea; stomach cramps; insomnia; anorexia; unable to smell properly	Eyes, skin, respiratory system, cardiovascular system	Silver-white, lustrous, hard, brittle solid; scale-like crystals; or a dark-gray, lustrous powder. BP: 2975°F
Arsenic (inorganic)	7440-38-2 (metal)	TWA 0.01 mg/m3	Ca C 0.002 mg/m3 [15-min]	TWA 0.010 mg/m3	Ca [5 mg/m3 (as As)]	Inhalation; ingestion; skin and/or eye contact	Ulceration of nasal septum, dermatitis, GI disturbances, peripheral neuropathy, resp irritation, hyperpigmentation of skin, [potential occupational carcinogen]	Liver, kidneys, skin, lungs, lymphatic sys	Metal: sliver-gray or tin-white, brittle, odorless solid BP: sublimes
Asbestos	1332-21-4	TWA 0.1 f/cc	Ca 100,000 fibers/m3	TWA 0.1 fiber/cm3	Ca [IDLH value has not been determined]	Inhalation; ingestion; skin and/or eye contact	Asbestosis (chronic exposure), dyspnea, interstitial fibrosis, restricted pulmonary function, finger clubbing, irritation eyes, [potential occupational carcinogen]	Respiratory system, eyes,	White or greenish (chrysotile), blue (crocidolite), or gray-green (amosite), fibrous, odorless solids. BP: decomposes
Asphalt fumes	8052-42-4	TWA 0.5 mg/m^3(fumes)	Ca C 5 mg/m3 [15 min]	None established	Ca [IDLH value has not been determined]	Skin absorption; inhalation; skin and/or eye contact	Irritation eyes, resp sys	Eyes, respiratory system	Black or dark brown cement-like substance Combustible solid
Barium	7440-39-3	TWA 0.5 mg/m3	None established	TWA 0.5 mg/m3	None established	Inhalation, ingestion, skin contact	Irritation skin, respiratory system, (	Skin, eyes, respiratory system	Yellow white powder BP: 1640 C
Benzene	71-43-2	TWA 0.5 ppm STEL 2.5 ppm	Ca TWA 0.1 ppm STEL 1 ppm	TWA 1 ppm STEL 5 ppm	Ca [500 ppm]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, respiratory system; dizziness; headache, nausea, staggered gait; anorexia, lassitude (weakness, exhaustion); dermatitis; bone marrow depression; [potential occupational carcinogen]	Eyes, skin, respiratory system, blood, central nervous system, bone marrow	Colorless to light yellow liquid with an aromatic odor [Note: Solid below 42 °F] BP: 176°F Fl.Pt = 12°F LEL: 1.2% UEL: 7.8% Class B Flammable liquid

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
Benzo[a]anthracene	56-55-3	None established	None established	None established	None established	Inhalation; ingestion; skin absorption; skin and/or eye contact	Irritation eyes, skin, respiratory system, CNS	Skin	Pale Yellow crystal, solid BP: 438 C
Benzo[a]pyrene	50-32-8	None established	TWA 0.1 mg/m3	TWA 0.2 mg/m3	None established	Inhalation; ingestion; skin absorption; skin and/or eye contact	POISON. This material is an experimental carcinogen, mutagen, tumorigen, neoplastigen and teratogen. It is a probable carcinogen in humans and a known human mutagen. IARC Group 2A carcinogen. It is believed to cause bladder, skin and lung cancer. Exposure to it may damage the developing foetus. May cause reproductive damage. Skin, respiratory and eye irritant or burns.	Skin, eye, bladder, lung, reproductive	Yellow crystals or powder [found in cigarette smoke, coal tar, fuel exhaust gas and in many other sources] BP: 495 C
Benzo[b]fluoranthene	205-99-2	None established	TWA 0.1 mg/m3	TWA 0.2 mg/m3	None established	Inhalation; ingestion; skin and/or eye contact	No data were identified on the toxicity of benzo[b]fluoranthene to humans. Based on results of studies in animals, IARC concluded that benzo[b]fluoranthene is possibly carcinogenic to humans	Respiratory system, skin, bladder, kidneys	Off-white to tan powder
Benzo[k]fluoranthene	207-08-9	None established	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin, respiratory tract, gastrointestinal; fatal if swallowed, inhaled, absorbed through the skin; vomiting, nausea, diarrhea	Lungs, respiratory system	Yellow crystals BP: 480 C
Beryllium	7440-41-7 (metal)	TWA 0.002 mg/m^3	Ca C 0.0005 mg/m^3	TWA 0.002 mg/m^3 C 0.005 mg/m^3 (30 minutes) with a maximum peak of 0.025 mg/m^3	Ca [4 mg/m^3 (as Be)]	inhalation, skin and/or eye contact	Berylliosis (chronic exposure): anorexia, weight loss, lassitude (weakness, exhaustion), chest pain, cough, clubbing of fingers, cyanosis, pulmonary insufficiency; irritation eyes; dermatitis; [potential occupational carcinogen]	Eyes, skin, respiratory system	Metal: A hard, brittle, gray-white solid. BP: 4532°F
Bis(2-ethylhexyl) phthalate	117-81-7	TWA 5 mg/m^3	TWA 5 mg/m^3 STEL 10 mg/m^3 (do not exceed during andy 15-minute work period)	TWA 5 mg/m^3	None established	inhalation, skin and/or eye contact	Irritation eyes, skin, nose, throat; affect the nervous system and liver; damage to male reproductive glands	Eyes, skin, nose, respiratory system, nervous system, reproductive system, liver	Colorless to light colored, thick liquid with slight odor
Butane	106-97-8	TWA 1000 ppm	TWA 800 ppm (1900 mg/m^3)	None established	None established	inhalation, skin and/or eye contact (liquid)	Drowsiness, narcosis, asphyxia; liquid: frostbite	central nervous system	Colorless gas with a gasoline-like or natural gas odor. BP: 31°F UEL: 8.4% LEL: 1.6% Flammable Gas

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
Cadmium	7440-43-9 (metal)	TWA 0.01 mg/m^3	Ca	TWA 0.005 mg/m^3	Ca [9 mg/m^3 (as Cd)]	inhalation, ingestion	Pulmonary edema, dyspnea (breathing difficulty), cough, chest tightness, substernal (occurring beneath the sternum) pain; headache; chills, muscle aches; nausea, vomiting, diarrhea; anosmia (loss of the sense of smell), emphysema, proteinuria, mild anemia; [potential occupational carcinogen]	respiratory system, kidneys, prostate, blood	Metal: Silver-white, blue-tinged lustrous, odorless solid. BP: 1409°F
Carbon Disulfide	75-15-0	TWA 1 ppm	TWA 1 ppm (3 mg/m^3) STEL 10 ppm (30 mg/m^3) [skin]	TWA 20 ppm C 30 ppm 100 ppm (30-minute maximum peak)	500 ppm	inhalation, skin absorption, ingestion, skin and/or eye contact	Dizziness, headache, poor sleep, lassitude (weakness, exhaustion), anxiety, anorexia, weight loss; psychosis; polyneuropathy; Parkinson-like syndrome; ocular changes; coronary heart disease; gastritis; kidney, liver injury; eye, skin burns; dermatitis; reproductive effects	central nervous system, peripheral nervous system, cardiovascular system, eyes, kidneys, liver, skin, reproductive system	Colorless to faint-yellow liquid with a sweet ether-like odor. BP: 116°F Fl.P: -22°F UEL: 50.0% LEL: 1.3% Class IB Flammable Liquid
Chlorobenzene	108-90-7	TWA 10 ppm	None established	TWA 75 ppm (350 mg/m^3)	1000 ppm	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose; drowsiness, incoordination; central nervous system depression; in animals: liver, lung, kidney injury	Eyes, skin, respiratory system, central nervous system, liver	Colorless liquid with an almond-like odor BP: 270°F Fl.P: 82°F UEL: 9.6% LEL: 1.3%
Chloroethane	75-00-3	TWA 100ppm	Handle with caution in the workplace	TWA 1000 ppm (2600 mg/m^3)	3800 ppm [10%LEL]	inhalation, skin absorption (liquid), ingestion (liquid), skin and/or eye contact	Incoordination, inebriation; abdominal cramps; cardiac arrhythmias, cardiac arrest; liver, kidney damage	Liver, kidneys, respiratory system, cardiovascular system, central nervous system	Colorless gas or liquid (below 54°F) with a pungent, ether-like odor. BP: 54°F Fl.P: NA (Gas) -58°F (Liquid) UEL: 15.4% LEL: 3.8%
Chloroform	67-66-3	TWA 10 ppm	Ca STEL 2 ppm (9.78 mg/m^3) [60-minute]	C 50 ppm (240 mg/m^3)	Ca [500 ppm]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; dizziness, mental dullness, nausea, confusion; headache, lassitude (weakness, exhaustion); anesthesia; enlarged liver; [potential occupational carcinogen]	Liver, kidneys, heart, eyes, skin, central nervous system	Colorless liquid with a pleasant odor BP: 143°F
Chromium	7440-47-3	TWA 0.5 mg/m^3 (metal and Cr III compounds) TWA 0.05 mg/m^3 (water-soluble Cr IV compounds) TWA 0.01 mg/m^3 (insoluble Cr IV compounds)	TWA 0.5 mg/m^3	TWA 1 mg/m^3	250 mg/m^3 (as Cr)	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin; lung fibrosis (histologic)	Eyes, skin, respiratory system	Blue-white to steel-gray, lustrous, brittle, hard, odorless solid. BP: 4788°F
Chrysene; Phenanthrene; Pyrene; Coal tar pitch volatiles	65996-93-2	TWA 0.2 mg/m3	Ca TWA 0.1 mg/m^3 (cyclohexane-extractable fraction)	TWA 0.2 mg/m^3 (benzene-soluble fraction)	Ca [80 mg/m^3]	Inhalation, skin and/or eye contact	Dermatitis, bronchitis, [potential occupational carcinogen]	Respiratory system, skin, bladder, kidneys	Black or dark-brown amorphous residue. Combustible Solids

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
cis-1,2-Dichloroethene	158-59-2	TWA 200 ppm	TWA 200 ppm	TWA 200 ppm	None established	inhalation, skin absorption, ingestion	Harmful if swallowed, inhaled, or absorbed through skin. Irritant. Narcotic. Suspected carcinogen	Skin	Colorless liquid BP: 60 C Fl.P: 4 C UEL: 12.8% LEL: 9.7 %
Copper	7440-50-8	TWA 0.2mg/m^3 (fume) 1 mg/m^3 (dusts and mists)	TWA 1 mg/m^3	TWA 1 mg/m^3	100 mg/m^3 (as Cu)	Inhalation, ingestion, skin and/or eye contact	Irritation eyes, respiratory system; cough, dyspnea (breathing difficulty), wheezing	Eyes, skin, respiratory system, liver, kidneys (increase(d) risk with Wilson's disease)	Noncombustible Solid in bulk form, but powdered form may ignite. BP: 4703°F
Dibenzo[a,h]anthracene	53-70-3	None established	None established	None established	None established	Inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin	Eyes, skin; skin photosensitization.	Colorless crystalline powder BP: 524°C
Diesel Fuel #2	68476-34-6	None established	None established	Designated as an OSHA Select Carcinogen	None established	ingestion, skin and/or eye contact	Kidney damage; potential lung damage; suspected carcinogen; irritation of eyes, skin, respiratory tract; dizziness, headache, nausea; chemical pneumonitis (from aspiration of liquid); dry, red skin; irritant contact dermatitis; eye redness, pain.	Eyes, skin, kidneys	Clear yellow brown combustible liquid; floats on water; distinct diesel petroleum hydrocarbon odor. BP: 356-716°F Fl.P: 154.4-165.2°F LEL: 0.6% UEL: 7.0%
Ethylbenzene	100-41-4	TWA 100 ppm STEL 125 ppm	TWA 100 ppm (435 mg/m^3) STEL 125 ppm (545 mg/m^3)	TWA 100 ppm (435 mg/m^3)	800 ppm [10%LEL]	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, mucous membrane; headache; dermatitis; narcosis, coma	Eyes, skin, respiratory system, central nervous system	Colorless liquid with an aromatic odor. BP: 277°F Fl.P: 55°F UEL: 6.7% LEL: 0.8% Class IB Flammable Liquid
Fluoranthene	206-44-0	None established	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; possible burns; heart and liver injury, pulmonary edema, respiratory arrest, gastrointestinal disturbances.	Heart, liver, lungs.	Yellow needles.
Fluorene	86-73-7	None established	None established	None established	None established	inhalation, ingestion, skin and/or eye contact	Irritation skin, digestive tract	Skin	White crystals BP: 563°F
Fuel Oil #2	68476-30-2	TWA 100mg/m^3 (aerosol and vapor, as total hydrocarbons)	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; CNS effects; nausea, vomiting, headache, cramping, dizziness, weakness, loss of coordination,, drowsiness; kidney, liver damage	Eyes, skin, CNS	Clear or yellow to red oily liquid, kerosene-like odor BP: 347 - 689 °F UEL:5-6% LEL: 0.7-1.0%
Gasoline	8006-61-9	TWA 300 ppm STEL 500 ppm	Carcinogen	None established	Ca [IDLH value has not been determined]	Skin absorption; inhalation; ingestion; skin and/or eye contact	Eyes and skin irritation, mucous membrane; dermatitis; headache; listlessness, blurred vision, dizziness, slurred speech, confusion, convulsions; chemical pneumonitis; possible liver, kidney damage [Potential occupational carcinogen]	Eyes, skin, respiratory system, CNS, Liver, Kidneys	Clear liquid with a characteristic odor, aromatic Fl.Pt = -45°F LEL = 1.4% UEL = 7.6% Classs 1B Flammable Liquid

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
Hexachlorobutadiene	87-68-3	TWA 0.02 ppm	Ca TWA 0.02 ppm (0.24 mg/m^3) [skin]	None established	Ca [N.D.]	inhalation, skin absorption, ingestion, skin and/or eye contact	In animals: irritation eyes, skin, respiratory system; kidney damage; [potential occupational carcinogen]	Eyes, skin, respiratory system, kidneys	Clear, colorless liquid with a mild, turpentine-like odor. BP: 419°F
Hydrogen Sulfide	7783-06-4	TWA (10 ppm) STEL (15 ppm) (adopted values for which changes are proposed in the NIC)	C 10 ppm (15 mg/m^3) [10-minute]	C 20 ppm 50 ppm [10-minute maximum peak]	100 ppm	inhalation, skin and/or eye contact	Irritation eyes, respiratory system; apnea, coma, convulsions; conjunctivitis, eye pain, lacrimation (discharge of tears), photophobia (abnormal visual intolerance to light), corneal vesiculation; dizziness, headache, lassitude (weakness, exhaustion), irritability, insomnia; gastrointestinal disturbance; liquid: frostbite	Eyes, respiratory system, central nervous system	Colorless gas with a strong odor of rotten eggs. BP: -77°F UEL: 44.0% LEL: 4.0% Flammable Gas
Indeno[1,2,3-cd]pyrene	193-39-5	None established	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; possible human carcinogen (skin); weakness; affect liver, lung tissue, renal tissue; impariment of blood forming tissue	Skin	Fluorescent green-yellow crystalline solid BP: 536 C
Indeno[1,2,3-cd]pyrene	193-39-5	None established	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; possible human carcinogen (skin); weakness; affect liver, lung tissue, renal tissue; impariment of blood forming tissue	Skin	Yellowish crystal solid BP: 536 C
Isopropylbenzene	98-82-8	TWA 50 ppm	TWA 50 ppm (245 mg/m^3) [skin]	TWA 50 ppm (245 mg/m^3) [skin]	900 ppm [10%LEL]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin, mucous membrane; dermatitis; headache, narcosis, coma	Eyes, skin, respiratory system, central nervous system	Colorless liquid with a sharp, penetrating, aromatic odor. BP: 306°F Fl.P: 96°F UEL: 6.5% LEL: 0.9%
Kerosene	8008-20-6	TWA 200 mg/m^3	TWA 100 mg/m^3	None established	IDLH value has not been determined	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, throat; burning sensation in chest; headache, nausea, lassitude (weakness, exhaustion), restlessness, incoordination, confusion, drowsiness; vomiting, diarrhea; dermatitis; chemical pneumonitis (aspiration liquid)	Eyes, skin, respiratory system, central nervous system	Colorless to yellowish, oily liquid with a strong, characteristic odor. BP: 347-617°F Fl.P: 100-162°F UEL: 5% LEL: 0.7% Class II Combustible Liquid
Lead	7439-92-1	TWA 0.05 mg/m^3	TWA (8-hour) 0.050 mg/m^3	TWA 0.050 mg/m^3	100 mg/m^3 (as Pb)	inhalation, ingestion, skin and/or eye contact	Lassitude (weakness, exhaustion), insomnia; facial pallor; anorexia, weight loss, malnutrition; constipation, abdominal pain, colic; anemia; gingival lead line; tremor; paralysis wrist, ankles; encephalopathy; kidney disease; irritation eyes; hypertension	Eyes, gastrointestinal tract, central nervous system, kidneys, blood, gingival tissue	A heavy, ductile, soft, gray solid. BP: 3164°F Noncombustible Solid in bulk form

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
Manganese	7439-96-5 (metal)	TWA 0.2 mg/m^3	TWA 1 mg/m^3 STEL 3 mg/m^3	C 5 mg/m^3	500 mg/m^3 (as Mn)	inhalation, ingestion	Manganism; asthenia, insomnia, mental confusion; metal fume fever: dry throat, cough, chest tightness, dyspnea (breathing difficulty), rales, flu-like fever; low-back pain; vomiting; malaise (vague feeling of discomfort); lassitude (weakness, exhaustion); kidney damage	respiratory system, central nervous system, blood, kidneys	A lustrous, brittle, silvery solid. BP: 3564°F
Mercury (organo) alkyl compounds (as Hg)	7439-97-6	TWA 0.01 mg/m^3 STEL 0.03 mg/m^3 [skin]	TWA 0.01 mg/m^3 STEL 0.03 mg/m^3 [skin]	TWA 0.01 mg/m^3 C 0.04 mg/m^3	2 mg/m^3 (as Hg)	inhalation, skin absorption, ingestion, skin and/or eye contact	Paresthesia; ataxia, dysarthria; vision, hearing disturbance; spasticity, jerking limbs; dizziness; salivation; lacrimation (discharge of tears); nausea, vomiting, diarrhea, constipation; skin burns; emotional disturbance; kidney injury; possible teratogenic effects	Eyes, skin, central nervous system, peripheral nervous system, kidneys	Appearance and odor vary depending upon the specific (organo) alkyl mercury compound
Mercury compounds [except (organo) alkyls] (as Hg) Mercury	7439-97-6	TWA 0.025 mg/m^3 (elemental and inorganic forms)	Hg Vapor: TWA 0.05 mg/m^3 [skin] Other: C 0.1 mg/m3 [skin]	TWA 0.1 mg/m^3	10 mg/m^3 (as Hg)	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; cough, chest pain, dyspnea (breathing difficulty), bronchitis, pneumonitis; tremor, insomnia, irritability, indecision, headache, lassitude (weakness, exhaustion); stomatitis, salivation; gastrointestinal disturbance, anorexia, weight loss; proteinuria	Eyes, skin, respiratory system, central nervous system, kidneys	Metal: Silver-white, heavy, odorless liquid. [Note: "Other" Hg compounds include all inorganic & aryl Hg compounds except (organo) alkyls.] BP: 674°F
Methyl tert-butyl ether (MTBE)	1634-04-4	TWA 50 ppm	No established REL	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, mucous membrane, respiratory; dizziness, nausea, headache, intoxication	Eyes, skin, mucous membrane, respiratory system, central nervous system	Colorless liquid BP: 55.2 C
Methylene Chloride	75-09-2	TWA 50 ppm, A3 - suspected human carcinogen	Ca	TWA 25 ppm STEL 125 ppm	Ca [2300 ppm]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; lassitude (weakness, exhaustion), drowsiness, dizziness; numbness, tingle limbs; nausea; [potential occupational carcinogen]	Eyes, skin, cardiovascular system, central nervous system	Colorless liquid with a chloroform-like odor BP: 104°F UEL: 23% LEL: 13%
Naphtha (coal tar)	8030-30-6	None established	TWA 100 ppm (400 mg/m^3)	TWA 100 ppm (400 mg/m^3)	1000 ppm [10%LEL]	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose; dizziness, drowsiness; dermatitis; in animals: liver, kidney damage	Eyes, skin, respiratory system, central nervous system, liver, kidneys	Reddish-brown, mobile liquid with an aromatic odor BP: 320-428°F Fl.P: 100-109°F Class II Combustible Liquid

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
Naphthalene	91-20-3	TWA 10 ppm STEL 15 ppm	TWA 10 ppm (50 mg/m^3) STEL 15 ppm (75 mg/m^3)	TWA 10 ppm (50 mg/m^3)	250 ppm	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes; headache, confusion, excitement, malaise (vague feeling of discomfort); nausea, vomiting, abdominal pain; irritation bladder; profuse sweating; jaundice; hematuria (blood in the urine), renal shutdown; dermatitis, optical neuritis, corneal damage	Eyes, skin, blood, liver, kidneys, central nervous system	Colorless to brown solid with an odor of mothballs. BP: 424°F Fl.P: 174°F UEL: 5.9% LEL: 0.9%
n-Butylbenzene	104-51-8	None established	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; CNS depression, lung damage; nausea, vomiting, headache, dizziness, weakness, loss of coordination, blured vision, drowsiness, confusion, disorientation	Eyes, skin,repiratory system, central nervous system	Colorless liquid with a sweet odor BP: 183 C Fl.P: 59 C UEL: 5.8% LEL: 0.8%
Nickel	7440-02-0 (Metal)	TWA 1.5 mg/m^3 (elemental) TWA 0.1 mg/m^3 (soluble inorganic compounds) TWA 0.2 mg/m^3 (insoluble inorganic compounds) TWA 0.1 mg/m^3 (Nickle subsulfide)	Ca TWA 0.015 mg/m^3	TWA 1 mg/m^3	Ca [10 mg/m^3 (as Ni)]	inhalation, ingestion, skin and/or eye contact	Sensitization dermatitis, allergic asthma, pneumonitis; [potential occupational carcinogen]	Nasal cavities, lungs, skin	Metal: Lustrous, silvery, odorless solid. BP: 5139°F
Nitrobenzene	98-95-3	TWA 1 ppm	TWA 1 ppm (5 mg/m^3) [skin]	TWA 1 ppm (5 mg/m^3) [skin]	200 ppm	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; anoxia; dermatitis; anemia; methemoglobinemia; in animals: liver, kidney damage; testicular effects	Eyes, skin, blood, liver, kidneys, cardiovascular system, reproductive system	Yellow, oily liquid with a pungent odor like paste shoe polish. BP: 411°F Fl.P: 190°F LEL(200°F): 1.8%
n-Propylbenzene	103-65-1	None established	None established	None established	None established	inhalation, ingestion, skin and/or eye contact	Harmful if swallowed, Irritation eyes, skin, digestive tract, respiratory tract, central nervous system	Eyes, skin, central nervous system, respiratory system	colorless or light yellow liquid BP: 159 C Fl.P: 47 C UEL: 6% LEL: 0.8%
Petroleum hydrocarbons(Petroleum distillates)	8002-05-9	None established	TWA 350 mg/m^3 C 1800 mg/m^3 [15 min]	TWA 500 ppm (2000 mg/m^3)	1,100 [10% LEL]	Inhalation; ingestion; skin and/or eye contact	Irritation eyes, skin, nose, throat; dizziness, drowsiness, headache, nausea; dried/cracked skin; chemical pneumonitis	CNS, eyes, respiratory system, skin	Colorless liquid with a gasoline or kerosene-like odor BP: 86-460°F Fl. Pt = -40 to -86°F UEL: 5.9% LEL: 1.1% Flammable liquid

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
Phenol	108-95-2	TWA 5 ppm	TWA 5 ppm (19 mg/m^3) C 15.6 ppm (60 mg/m^3) [15-minute] [skin]	TWA 5 ppm (19 mg/m^3) [skin]	250 ppm	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, nose, throat; anorexia, weight loss; lassitude (weakness, exhaustion), muscle ache, pain; dark urine; cyanosis; liver, kidney damage; skin burns; dermatitis; ochronosis; tremor, convulsions, twitching	Eyes, skin, respiratory system, liver, kidneys	Colorless to light-pink, crystalline solid with a sweet, acrid odor. BP: 359°F UEL: 8.6% LEL: 1.8%
p-Isopropyltoluene	99-87-6	None established	None established	None established	None established	inhalation, skin absorption, eye contact	Irritation skin	CNS, skin	Colorless, clear liquid, sweetish aromatic odor BP: 350.8°F Class III Flammable liquid
sec-Butylbenzene	135-98-8	None established	None established	None established	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin, upper airway; central nervous system, headache, dizziness; gastrointestinal disturbance	Respiratory system, central nervous system, eyes, skin;	Colorless liquid BP: 344°F Fl.P: 126 °F UEL: 6.9% LEL: 0.8% Combustible liquid
Selenium	7782-49-2	TWA 0.2 mg/m^3	TWA 0.2 mg/m^3	TWA 0.2 mg/m^3	1 mg/m^3 (as Se)	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, throat; visual disturbance; headache; chills, fever; dyspnea (breathing difficulty), bronchitis; metallic taste, garlic breath, gastrointestinal disturbance; dermatitis; eye, skin burns; in animals: anemia; liver necrosis, cirrhosis; kidney, spleen damage	Eyes, skin, respiratory system, liver, kidneys, blood, spleen	Amorphous or crystalline, red to gray solid. [Note: Occurs as an impurity in most sulfide ores.] BP: 1265°F
Silver	7440-22-4 (metal)	TWA 0.1 mg/m^3 (metal, dust, fumes) TWA 0.01 mg/m^3 (Soluble compounds, as Ag)	TWA 0.01 mg/m^3	TWA 0.01 mg/m^3	10 mg/m^3 (as Ag)	inhalation, ingestion, skin and/or eye contact	Blue-gray eyes, nasal septum, throat, skin; irritation, ulceration skin; gastrointestinal disturbance	Nasal septum, skin, eyes	Metal: White, lustrous solid BP: 3632°F
Slop Oil	69029-75-0	None established	None established	None established	None established	Inhalation; ingestion	Irritation eyes, skin, gastrointestinal tract	Eyes, skin, gastrointestinal tract	Clear light to dark amber liquid, with mild hydrocarbon odor. BP: >500°F Fl.P : 250°F
Sulfuric Acid	7664-93-9	TWA 0.2 mg/m^3	TWA 1 mg/m^3	TWA 1 mg/m^3	15 mg/m^3	inhalation, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, throat; pulmonary edema, bronchitis; emphysema; conjunctivitis; stomatis; dental erosion; eye, skin burns; dermatitis	Eyes, skin, respiratory system, teeth	Colorless to dark-brown, oily, odorless liquid. BP: 554°F Noncombustible Liquid
tert-Butylbenzene	98-06-6	None established	None established	None established	None established	inhalation, skin absorption, ingestion,	Eye and respiratory irritant; CNS depression; liver or kidney damage	Respiratory system, central nervous system, eyes, liver, kidney	Colorless liquid with an aromatic odor BP: 168 - 169 C Fl.P: 34 C UEL:5.6 % LEL: 0.8 %

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

Compound	CAS #	ACGIH TLV	NIOSH REL	OSHA PEL	IDLH	Routes of Exposure	Toxic Properties	Target Organs	Physical/Chemical Properties
Tetrachloroethene	127-18-4	TWA 25 ppm STEL 100 ppm (STEL) listed as A3, animal carcinogen	Ca Minimize workplace exposure concentrations	TWA 100 ppm C 200 ppm (for 5 minutes in any 3-hour period), with a maximum peak of 300 ppm	Ca [150 ppm]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin, nose, throat, respiratory system; nausea; flush face, neck; dizziness, incoordination; headache, drowsiness; skin erythema (skin redness); liver damage; [potential occupational carcinogen]	Eyes, skin, respiratory system, liver, kidneys, central nervous system	Colorless liquid with a mild, chloroform-like odor. BP: 250°F Noncombustible Liquid
Toluene	108-88-3	TWA 20 ppm	TWA 100 ppm (375 mg/m^3) STEL 150 ppm (560 mg/m^3)	TWA 200 ppm C 300 ppm 500 ppm (10-minute maximum peak)	500 ppm	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, nose; lassitude (weakness, exhaustion), confusion, euphoria, dizziness, headache; dilated pupils, lacrimation (discharge of tears); anxiety, muscle fatigue, insomnia; paresthesia; dermatitis; liver, kidney damage	Eyes, skin, respiratory system, central nervous system, liver, kidneys	Colorless liquid with a sweet, pungent, benzene-like odor. BP: 232°F Fl.P: 40°F UEL: 7.1% LEL: 1.1% Class IB Flammable Liquid
trans-1,2-Dichloroethene	156-60-5	TWA 200 ppm	None established	TWA 200 ppm STEL 250 ppm (skin)	None established	inhalation, skin absorption, ingestion, skin and/or eye contact	Narcotic. Irritation eyes, skin, respiratory tract, mucous membrane; CNS depression.	Respiratory tract, mucous membrane, eyes, skin, CNS	Colorless liquid with a fruity pleasant odor BP: 48°C Fl.P 6C UEL: 12.8% LEL: 9.7%
Trichloroethene	79-01-6	TWA 10 ppm STEL 25 ppm	Ca	TWA 100 ppm C 200 ppm 300 ppm (5-minute maximum peak in any 2 hours)	Ca [1000 ppm]	inhalation, skin absorption, ingestion, skin and/or eye contact	Irritation eyes, skin; headache, visual disturbance, lassitude (weakness, exhaustion), dizziness, tremor, drowsiness, nausea, vomiting; dermatitis; cardiac arrhythmias, paresthesia; liver injury; [potential occupational carcinogen]	Eyes, skin, respiratory system, heart, liver, kidneys, central nervous system	Colorless liquid (unless dyed blue) with a chloroform-like odor. BP: 189°F UEL(77°F): 10.5% LEL(77°F): 8%
Vinyl Chloride	75-01-4	TWA 1 ppm	Carcinogen	TWA 1 ppm C 5 ppm [15-minute]	Ca [IDLH value has not been determined]	inhalation, skin, and/or eye contact (liquid)	Lassitude (weakness, exhaustion); abdominal pain, gastrointestinal bleeding; enlarged liver; pallor or cyanosis of extremities; liquid: frostbite; [potential occupational carcinogen]	Liver, central nervous system, blood, respiratory system, lymphatic system	Colorless gas or liquid (below 7°F) with a pleasant odor at high concentrations. BP: 7°F UEL: 33.0% LEL: 3.6% Flammable Gas
Xylene (m, o & p isomers)	108-38-3, 95-47-6, 106-42-3	TWA 100 ppm (435 mg/m^3) STEL 150 ppm	TWA 100 ppm (435 mg/m^3)	TWA 100 ppm (435 mg/m^3)	900 ppm	Skin absorption, inhalation, ingestion, skin, and/or eye contact	Irritation eyes, skin, nose, throat; dizziness, excitement, drowsiness, incoordination, staggering gait; corneal vacuolization; anorexia, nausea, vomiting, abdominal pain; dermatitis	Eyes, skin, respiratory system, central nervous system, gastrointestinal tract, blood, liver, kidneys	Colorless liquid with an aromatic odor BP: 282°F, 292°F, 281°F Fl. Pt. 82°F, 90°F, 81°F LEL: 1.1%, 0.9%, 1.1% UEL: 7.0%, 6.7%, 7.0% Classs C Flammable Liquid
Zinc	7440-66-6	TWA 10 mg/m3 (Inhalable fraction)	None established	TWA 10 mg/m3 (for zinc oxide fume)	None established	skin and/or eye contact, inhalation, ingestion	Irritation eyes, skin, respiratory tract; gastrointestinal disturbances	Eyes, skin, respiratory system	Bluish gray solid BP: 1664.6°F Flammable

Table 1. Toxicological, Physical, and Chemical Properties of Compounds Potentially Present at 900 Old Country Road, Garden City, New York

References

U.S. Department of Labor. 1990. OSHA Regulated Hazardous Substances, industrial Exposure and Control Technologies Government Institutes, Inc.
Hawley's Condensed Chemical Dictionary, Sax, N. Van Nostrand and Reinhold Company, 11th Edition, 1987.
Proctor, N.H., J.P. Hughes and M.L. Fischman, 1989. Chemical Hazards of the Workplace. Van Nostrand Reinhold. New York.
Sax, N.I. and R.J. Lewis. 1989. Dangerous Properties of Industrial Materials. 7th Edition. Van Nostrand Reinhold. New York.
Guide to Occupational Exposure Values. 2008. American Conference of Governmental Industrial Hygienists (ACGIH).
NIOSH Pocket Guide to Chemical Hazards. 2005. Department of Health and Human Services, Centers for Disease Control and Prevention, National Institute for Occupational Safety and Health

Abbreviations:

ACGIH – American Conference of Governmental Industrial Hygienists.
BP – boiling point at 1 atmosphere, °F
C – Ceiling, is a concentration that should not be exceeded during and part of the working exposure.
Ca - considered by NIOSH to be a potential occupational carcinogen
CAS# Chemical Abstracts Service registry number which is unique for each chemical.
Fl. Pt. – Flash point
IDLH - Immediately Dangerous to Life and Health concentrations represent the maximum concentration from which, in the event of respirator failure, one could escape within 30 minutes without a respirator and without experiencing any escape-impairing or irreversible health effects.
LEL – Lower explosive (flammable) limit in air, % by volume (at room temperature)
mg/m^3 – Milligrams of substance per cubic meter of air
NIOSH -National Institute for Occupational Safety and Health.
OSHA – Occupational Safety and Health Administration
PEL - OSHA Permissible Exposure Limit (usually) a time weighted average concentration that must not be exceeded during any 8 hour work shift of a 40 hr work week.
ppm – parts per million
REL – NIOSH Recommended Limit indicated a time weighted average concentration that must not be exceeded during any 10 hour work shift of a 40 hr work week
STEL – Short-term exposure limit
TLV -ACGIH Threshold Limit Values (usually 8 hour time weighted average concentrations).
TWA – 8-hour, time-weighted average
UEL – Upper explosive (flammable) limit in air, % by volume (at room temperature)

TABLE 2

ACTION LEVELS FOR WORKER BREATHING ZONE

Instrument	Action Level *	Level of Respiratory Protection/Action
PID	0 to <5 ppm (one minute sustained)	Level D *
PID	>5 to <50 ppm (one minute sustained)	Utilize APR (Level C)
PID	>50 to <100 ppm (one minute sustained)	Level B
PID	>100ppm	Stop work** (ventilate, apply foam)
CGI/H_2S Meter	<5%	Level D
CGI/H_2S Meter	>5% to <25%	Level B
CGI/H_2S Meter	>25%	Stop work**
CGI/CO Meter	>25%	Level B
CGI/CO Meter	>50%	Stop work** (ventilate area)
CGI/O_2 Meter	<10% LEL, in excavation	Level D
	19.5% oxygen – 23.5%	Level D
CGI/O_2 Meter	>10% LEL, in excavation	Allow to vent, apply foam**
	>23.5% oxygen	Stop work, Oxygen Enriched ATM**
Dust Monitor	0 – 1.0 mg/m^3, 5-minutes average	Level D
Dust Monitor	>1.0 to 5.0 mg/m^3, 5-minutes average	Level D – Institute dust suppression measures
Dust Monitor	5.0 to >50 mg/m^3, 5-minute average	Level C – Institute dust suppression measures

Note: Action levels are based on above background levels.

* Instrument readings will be taken in the breathing zone (BZ) of the workers, unless otherwise indicated.

** Suspend work in immediate area. Conduct air monitoring periodically to determine when work can continue. Implement mitigative measures.



N

0 1000' 2000'

Title:

SITE LOCATION MAP

900 OLD COUNTRY ROAD
GARDEN CITY, NEW YORK

Prepared for:

EQUITY ONE

ROUX ASSOCIATES, INC.
Environmental Consulting & Management

Compiled by: B.H.	Date: 11MAR10	FIGURE
Prepared by: B.H.C.	Scale: AS SHOWN	1
Project Mgr.: C.W.	Project No.: 1924.0001Y000	
File: EQO0110501.CDR		

\EQO1924Y\EQO01Y105\EQO0110501.CDR

FIGURE 2

Directions to Winthrop University Hospital – 259 First Street, Mineola, New York 11501



APPENDIX A

Activity Hazard Analysis

ACTIVITY HAZARD ANALYSIS

ACTIVITY: Mobilization/Demobilization	**Analyzed by / Date:_____**	
Principal Steps	**Potential Hazards**	**Recommended Controls**
Temporary Facilities Set Up (Support and CRZ zones)	Noise	Ear plugs, ear muffs.
	Eyes	Safety glasses with side shields, safety visor or shield.
	Slips-Trips-Falls	Be sure footing is in a clear area free of loose material.
	Power Tools	Hard hats, work gloves.
	Heat Stress/Cold Stress	Follow heat stress/cold stress guidelines in HASP appendices.
	Cuts and Abrasions	Wear work gloves.
	Punctures	Wear puncture resistant steel toed boots, long sleeve shirts, work shirts or cover alls.
	Electrocution	Ground fault circuit interrupters, inspect power supply cords of equipment prior to use.
	Traffic Hazards	Wear orange safety vests and/or high visibility clothing.
	Insect Bites/Wildlife	Use insect repellent. Avoid contact with all wildlife.
	Sun exposure	Use sunscreen as needed, take breaks in shaded areas.
Equipment to be Used	**Inspection Requirements**	**Training Requirements**
Power Tools (e.g., Drills, Saws) Hand Tools (e.g., Hammer, Shovel, Pry Bars) Trailers, Vehicles, Low Boy, Heavy Equipment	Daily inspections to insure personnel wear appropriate PPE during mobilization and demobilization and survey work. Inspect equipment for wear or damage, test emergency shut-off switches. Ensure all equipment on wheels is chocked per Wheel Chocking Policy.	Tool box safety meetings. Review heavy equipment safety guidelines. Review Wheel Chocking Policy.

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Contaminated Soil Excavation		**Analyzed by / Date:_____**
Principal Steps	**Potential Hazards**	**Recommended Controls**
Work Zone Delineations Decon Area Layout Personal/Perimeter Air Monitoring Removal of Contaminated Soil Verification of Soil Removal Loading Contaminated Soil for Disposal Decon/Demobilization	Noise	Ear plugs, ear muffs.
	Eyes	Safety glasses with side shields or upgrade to Level C full-face respirators.
	Electrocution	Inspect area for overhead and/or subsurface electrical lines. Follow Lock out/Tag out Procedures.
	Puncture	Steel toe/steel shank boots. Avoid direct handling of soil – use shovels, rakes or squeegees.
	Wildlife	Avoid contact with all animals.
	Hose Connections	Make sure all vacuum line connections are clamped and secured.
	Traffic – Vehicle	Cones and flagging to be used for vehicles parked on streets – if a lane is to be taken, flagmen to be used.
	Traffic – Pedestrian	All work zones to be delineated by SSO to be able to control area from curious onlookers.

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Contaminated Soil Excavation	**Analyzed by / Date:_____**	
Equipment to be Used	**Inspection Requirements**	**Training Requirements**
Dump Truck(s) Rubber Tire Backhoe Miscellaneous Hand Tools Level D and Level C PPE Excavator	Prior to start of work daily - area for security - barriers in place - equipment inspection/proper wheel chocking PPE Inspections - before donning - buddy system to continually observe - upon de-suiting During Operations – that area remains secure Atmosphere - prior to entering confined space - continually during operations	40-Hour HAZWOPER 8-Hour Refresher Site Specific Training and Orientation Daily Safety Meetings

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Drilling Activities		**Analyzed by / Date:_____**
Principal Steps	**Potential Hazards**	**Recommended Controls**
Work Zone Delineations Decon Area Layout Personal Air Monitoring Installation of Soil Borings Installation of Monitoring Wells Installation of Soil Vapor Sampling Points Decon/Demobilization	Noise	Ear plugs, ear muffs.
	Eyes	Safety glasses with side shields or upgrade to Level C full-face respirators.
	Electrocution	Inspect area for overhead and/or subsurface electrical lines. Follow Lock out/Tag out Procedures.
	Puncture	Steel toe/steel shank boots. Avoid direct handling of soil – use shovels, rakes or squeegees. Leather and/or cut resistant work gloves as appropriate to protect hands.
	Wildlife/Insect Bites	Avoid contact with all animals, use insect repellent.
	Hose Connections	Make sure all vacuum line connections are clamped and secured.
	Traffic – Vehicle	Cones and flagging to be used for vehicles parked on streets – if a lane is to be taken, flagmen to be used.
	Traffic – Pedestrian	All work zones to be delineated by SSO to be able to control area from curious onlookers.
	Hands	Employ a "Show Hands Policy" between drillers and helpers.

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Drilling Activities	**Analyzed by / Date:_____**	
Equipment to be Used	**Inspection Requirements**	**Training Requirements**
Drill Rig Support Truck Miscellaneous Hand Tools Level D and Level C PPE	Prior to start of work daily - area for security - barriers in place - equipment inspection, including emergency shut-off switch testing PPE Inspections - before donning - buddy system to continually observe - upon de-suiting During Operations - that area remains secure Atmosphere - prior to entering confined space - continually during operations	40-Hour HAZWOPER 8-Hour Refresher Site Specific Training and Orientation Daily Safety Meetings

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Miscellaneous Fill Placement		**Analyzed by / Date:_____**
Principal Steps	**Potential Hazards**	**Recommended Controls**
Grading Placement of Fill	Abrasions; heat stress; cold stress; cuts; slips; trips; falls; insects; rodents and stray animals; hazardous noise; puncture; struck by moving heavy equipment; loading and unloading of heavy equipment; crushed or pinned between machinery; and nuisance dust.	Hard hats; safety glasses/goggles; work gloves; puncture resistant steel toed, steel shank work boots; reflective vest and/or high visibility clothing. Hearing protection (muffs/plugs). Personnel should stand at least 10 feet from moving or swing radius of equipment. Personal protective equipment.
Equipment to be Used	**Inspection Requirements**	**Training Requirements**
Bull dozer Grader Dump Trucks Water Truck Hand Tools (Shovels, etc.)	Periodic inspections to ensure site personnel wear the appropriate PPE. Daily site safety inspection check list. Heavy equipment/machinery must be inspected by SSHO & Operator, test emergency shutoff switches.	Tool box safety meetings. Review working around or near heavy equipment and review heavy equipment safety guidelines.

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Sheeting/Pile Installation		**Analyzed by / Date:_____**
Principal Steps	**Potential Hazards**	**Recommended Controls**
Mobilization Equipment Set Up Unloading of Equipment Installation of Shoring/Sheeting Removal of Shoring Loading of Equipment Demobilization	Buried utilities and underground structures Truck traffic Slip / trip / fall Rigging to unload and handle materials Overhead hazards Workmen in the area Site control Equipment operation Sheeting installation and removal Demobilization of equipment Cold / heat stress Biological hazards Hearing protection / eye protection Hand protection Untrained personnel Electric powered hand tools Cutting torches	All trucks to be equipped with backup alarms – pedestrian traffic to have orange protective vests and/or high visibility clothing for visibility. All personnel are to be aware that the potential for slipping / tripping / falling exists at all times due to uneven terrain. Equipment being laid out and staged. Any person working at a height of greater than 6 feet must have a safety harness and shock absorbing lanyard. Sheeting being delivered to the site will have to be unloaded prior to this activity – all grips, slings, chains, clevises or grab hooks and any other lifting devices shall be inspected. A regular inspection of these items shall be made prior to their use for any lifting. Any equipment with frayed or broken components will be set aside and tagged and shall not be used until the appropriate repairs are made. Prior to the start of any activity, the area shall be checked for overhead hazards. Operators and spotters are to be aware of the potential for personnel and/or equipment to be in the work zone. No lifting and rigging shall go over a person or vehicle. During all phases of operations, the minimum personal protection will consist of hard hat, steel-toed and steel-shanked work boots, safety glasses. When handling wire rope, slings, chains, etc., appropriate hand protection will be used (leather or cut resistant work gloves). When working

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Sheeting/Pile Installation		**Analyzed by / Date:_____**
Principal Steps	**Potential Hazards**	**Recommended Controls**
		around equipment, hearing protection shall be used. Extra care shall be taken to make sure no one's hands or feet are caught under or between metal objects when lifting or setting sheeting. Employ hand signals to give "all clear" approval. All personnel shall be trained and qualified to perform the task assigned them. Equipment operators are responsible to make sure their swing radius and work areas are clear. Operators are to be trained and competent with their equipment. During operations, a zone will be established outside of the swing radius and/or fall radius of the equipment and sheeting where control of persons entering and exiting can be safety maintained. The same type of control for vehicles will be maintained. Equipment will be in good working order, equipped with current protective devices and travel alarms, and chocked when not in use. A competent person shall have designed the sheeting/pile plan to meet the stress loads of the environment. This plan shall include all bracing, cross bracing, installation depths.

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Sheeting/Pile Installation		**Analyzed by / Date:_____**
Principal Steps	**Potential Hazards**	**Recommended Controls**
		Hydraulic and/or airlines used to power the vibratory sheeting drive/extractor shall be checked twice daily. Operators and spotters will have a clear plan of communications. All hand signals will be predetermined. There will only be one person spotting for the operator that gives directions. If two-way communications are to be used, the channel will remain undisturbed during lifting and setting operations by company personnel. Tag lines as appropriate will be used to erect and disassemble the sheeting. When loading shoring up to demobilize, there shall not be any lifts over a person or equipment. Potential exists for cold / heat stress. Follow the guidelines for cold / heat stress in the HASP. Replenish fluids and take breaks, as necessary. If there is a need to utilize electric power tools, all cords will be inspected. Ground Fault Interrupter (GFI) outlets will be used. No guards shall have been removed and no triggers will be wired open. If cutting torches are utilized, all lines, gauges, regulators and torches shall be inspected prior to use. Tanks will have current inspection and be inspected upon receipt at the site prior to their use. A 30-minute fire watch will be maintained after burning activity has stopped for the day.

ACTIVITY HAZARD ANALYSIS

(Continued)

ACTIVITY: Sheeting/Pile Installation		**Analyzed by / Date:_____**
Equipment to be Used	**Inspection Requirements**	**Training Requirements**
Tractor Trailers Hydraulic Excavators and/or Cranes Interlocking Steel Sheeting/Shoring/Bracing Materials Miscellaneous Slings, Grips, chains, hooks, Clevises Miscellaneous Electric Power Tools Oxygen and Acetylene Torches Pile Drivers	Daily inspection of equipment as recommended by manufacturer. Inspection of work area and perimeters prior to start and during works operations. Twice daily inspection of cables, slings, etc., electric equipment, torches, regulators, gauges.	Current CDL license for tractor trailer operators. Competent person to develop shoring plan. Site specific HASP. Trained operations/laborers. Daily safety meetings.

APPENDIX B

Heat and Cold Stress Guidelines

Heat Stress

Heat stress is a significant potential hazard and can be associated with heavy physical activity and/or the use of personal protective equipment (PPE) in hot weather environments.

Heat cramps are brought on by prolonged exposure to heat. As an individual sweats, water and salts are lost by the body resulting in painful muscle cramps. The signs and symptoms of heat cramps are as follows:

- severe muscle cramps, usually in the legs and abdomen;
- exhaustion, often to the point of collapse; and
- dizziness or periods of faintness.

First aid treatment includes moving to a shaded area, rest, and fluid intake. Normally, the individual should recover within one-half hour. If the individual has not recovered within 30 minutes and the temperature has not decreased, the individual should be transported to a hospital for medical attention.

Heat exhaustion may occur in a healthy individual who has been exposed to excessive heat. The circulatory system of the individual fails as blood collects near the skin in an effort to rid the body of excess heat. The signs and symptoms of heat exhaustion are as follows:

- rapid and shallow breathing;
- weak pulse;
- cold and clammy skin with heavy perspiration;
- skin appears pale;
- fatigue and weakness;
- dizziness; and
- elevated body temperature.

First aid treatment includes cooling the victim, elevating the feet, and replacing fluids and electrolytes. If the individual has not recovered within 30 minutes and the temperature has not decreased, the individual should be transported to the hospital for medical attention.

Heat stroke occurs when an individual is exposed to excessive heat and stops sweating. This condition is classified as a **MEDICAL EMERGENCY**, requiring immediate cooling of the victim and transport to a medical facility. The signs and symptoms of heat stroke are as follows:

- dry, hot, red skin;
- body temperature approaching or above 105°F;
- large (dilated) pupils; and
- loss of consciousness - the individual may go into a coma.

First aid treatment requires immediate cooling and transportation to a medical facility.

Heat stress (heat cramps, heat exhaustion, and heat stroke) is a significant hazard if any type of protective equipment (semi-permeable or impermeable) which prevents evaporative cooling is worn in hot weather environments. Local weather conditions may require restricted work schedules in order to adequately protect personnel. The use of work/rest cycles (including working in the cooler periods of the day or evening) and training on the signs and symptoms of heat stress should help prevent heat-related illnesses from occurring. Work/rest cycles will depend on the work load required to perform each task, type of protective equipment, temperature, and humidity. In general, when the temperature exceeds 88°F, a 15 minute rest cycle will be initiated once every two hours. In addition, potable water and fluids containing electrolytes (e.g., Gatorade) will be available to replace lost body fluids.

Cold Stress

Cold stress is a danger at low temperatures and when the wind-chill factor is low. Prevention of cold-related illnesses is a function of whole-body protection. Adequate insulating clothing must be used when the air temperature is below 40°F. In addition, reduced work periods followed by rest in a warm area may be necessary in extreme conditions. Training on the signs and symptoms of cold stress should prevent cold-related illnesses from occurring. The signs and symptoms of cold stress include the following:

- severe shivering;
- abnormal behavior;

- slowing of body movement;
- confusion;
- weakness;
- stumbling or repeated falling;
- inability to walk;
- collapse; and/or
- unconsciousness.

First aid requires removing the victim from the cold environment and seeking medical attention immediately. Also, prevent further body heat loss by covering the victim lightly with blankets. Do not cover the victim's face. If the victim is still conscious, administer hot drinks, and encourage activity, such as walking wrapped in a blanket.

APPENDIX C

Medical Data Form

MEDICAL DATA SHEET

This form must be completed by all onsite personnel prior to the commencement of activities, and shall be kept by the Site Health and Safety Officer during site activities. This form must be delivered to any attending physician when medical assistance is needed.

(This form should be typed or printed legibly.)

Site: _____

Name: _____ Home Telephone: _____
(Area Code/Telephone Number)

Address: _____

Date of Birth: _____ Height: _____ Weight: _____

Emergency Contact: _____ Telephone: _____
(Area Code/Telephone Number)

Drug Allergies or Other Allergies: _____

_____

Previous Illnesses or Exposures to Hazardous Substances: _____

_____

_____

Current Medication (Prescription and Non-Prescription): _____

_____

_____

Medical Restrictions: _____

_____

Name, Address and Telephone Number of Person Physician: _____

_____

APPENDIX D

Community Air Monitoring Plan

January 18, 2011

COMMUNITY AIR MONITORING PLAN

900 Old Country Road
Garden City, Nassau County, New York

Prepared for

EQUITY ONE (NORTHEAST PORTFOLIO) INC.
650 Fifth Avenue, 24th Floor
New York, New York 10019

ROUX ASSOCIATES, INC.

Environmental Consulting & Management

ROUX

209 Shafter Street, Islandia, New York 11749 ♦ 631-232-2600

TABLE OF CONTENTS

1.0 INTRODUCTION 1
1.1 Establishing Background Conditions 2
1.2 VOC Monitoring Approach 2
1.3 Particulate Monitoring Approach 2
1.4 Meteorological Monitoring 3
1.5 Available Suppression Techniques 3
1.6 Reporting 4

TABLES

1. Action Limit Summary for Particulates and VOCs, Former Avis Headquarters 900 Old Country Road, Garden City, New York

ATTACHMENT

1. Action Limit Report

1.0 INTRODUCTION

Roux Associates, Inc. (Roux Associates) has developed a project-specific Community Air Monitoring Plan (CAMP) to implement real time monitoring at the Former Avis Headquarters Site, 900 Old Country Road, Garden City, New York (Site) during the Remedial Investigation (RI) work, Interim Remedial Measure (IRM) planned for the remediation activities (limited excavation and offsite disposal) and the demolition activities at the Site. Remedial activities will be performed following the completion of the RI scheduled for early 2011. Previous investigation results indicate that inorganic compounds (metals), semivolatile organic compounds (SVOCs), and polychlorinated biphenyls (PCBs) are present in soil across the Site. Since the IRM includes excavation, soil stockpiling, and backfill activities, particulates will be monitored. Multiple previous investigations at the site have documented the absence of volatile organic compounds (VOCs) in Site soils, therefore, limited VOC monitoring is included as part of this CAMP.

The monitoring program will monitor for particulates at the downwind perimeter of the work area during ground intrusive activities. The design of the CAMP is intended to provide a measure of protection for the downwind community and onsite workers not directly involved with the subject work activities from potential airborne contaminant releases as a direct result of remedial work and demolition activities. This plan is consistent with the New York State Department of Environmental Conservation's (NYSDEC) Fugitive Dust Suppression and Particulate Monitoring Program and the New York State Department of Health's (NYSDOH's) Generic Community Air Monitoring Plan guidance documents included in DER-10.

Roux Associates will be responsible for the implementation of the CAMP during the RI, IRM and demolition activities and will have direct and constant communication with all components of the remediation team in order to effectively and instantaneously initiate the necessary Site controls to prevent and/or minimize any work stoppages related to CAMP issues.

The specifics of the CAMP are presented in the following six (6) sections:

1.1 Establishing Background Conditions

1.2 VOC Monitoring Approach

1.3 Particulate Monitoring Approach

1.4 Meteorological Monitoring Approach

1.5 Available Suppression Techniques

1.6 Reporting

1.1 Establishing Background Conditions

Background air quality monitoring will be conducted during a maximum of two work days prior to the start of the remedial activities. Background air quality monitoring will be conducted for up to 8 hours per day, with the timing generally coinciding with the hours work will typically be occurring at the Site. Background air quality monitoring will be conducted at two sampling stations. Particulate matter (PM-10) will be monitored continuously at each location with a MIE DataRam 4000. The DataRams will be set to take 15-minute running average measurements, and record one average measurement every 15 minutes, including the time and date of the end of the measurement period. The particulate data stored on the DataRams will be periodically transferred to a laptop computer and analyzed as necessary. All particulate will be measured in units of micrograms per cubic meter ($\mu g/m^3$).

1.2 VOC Monitoring Approach

Due to the fact that VOCs are not present in site soils, as evidenced by multiple historical investigations, VOC monitoring will take place only at the active borehole location or limited excavation itself during all RI and remedial activities.

1.3 Particulate Monitoring Approach

Particulate concentrations will be monitored continuously at the upwind and downwind perimeters of the work area at temporary particulate monitoring stations. The particulate monitoring will be performed using real-time monitoring equipment capable of measuring particulate matter less than 10 micrometers in size (PM-10) and capable of integrating over a period of 15 minutes (or less) for comparison to the airborne particulate action levels

(as summarized in Table 1). Monitoring equipment will be MIE Data Ram 4000 monitors or equivalent. One (1) upwind and one (1) downwind monitor will be deployed each day equipped with an omni-directional sampling inlet and a PM-10 sample head. The data logging averaging period will be set to 15-minutes with time and date stamp recording. Alarm averaging will be set at 90 $\mu g/m^3$ above background per 15-minute period. This setting will allow proactive evaluation of work conditions prior to reaching Action Levels of 100 $\mu g/m^3$ above background. The equipment is equipped with an audible alarm to indicate exceedance of the action level. In addition, fugitive dust migration will be visually assessed during all work activities.

All readings will be recorded and made available for NYSDEC and NYSDOH personnel to review. If an exceedance of the action level occurs, an Action Limit Report will be completed identifying the monitoring device location, the measured particulate level, the activity causing the exceedance, meteorological conditions, and the corrective actions taken, as provided in Attachment 1. Daily monitoring equipment locations and meteorological conditions will also be documented on the daily CAMP Monitoring Location Plan. All documentation will be kept on file at the Site.

1.4 Meteorological Monitoring

Meteorological data consisting of wind speed, wind direction, temperatures, barometric pressure, and relative humidity will be collected. The measurements will be continuous and 15-minute average values will be digitally recorded by the instrument. Wind direction readings will be utilized to position the particulate monitoring equipment in appropriate upwind and downwind locations. A Davis Corporation wireless instrument station or equivalent will be used to collect and download all meteorological monitoring data.

1.5 Available Suppression Techniques

If necessary, water misting via controlled fire hose and/or dedicated water truck will be utilized as a Site control measure to mitigate the potential for particulate/dust release in work areas and roadways. Excavation methods, material staging and loading methods, and vapor/dust suppression methods will be performed in accordance with the IRM Work Plan to

be developed following completion of the RI work, and continually evaluated and modified (as necessary) to alleviate the potential for particulate releases.

1.6 Reporting

All recorded data will be downloaded and field logged daily, including Action Limit Reports (if any) and daily CAMP monitoring location figures. All records will be maintained onsite for NYSDEC/NYSDOH review. A description of all CAMP-related activities will be included in an IRM Completion Summary Report submitted to the NYSDEC and NYSDOH. Additionally, all CAMP monitoring records will be included in the overall Final Engineering Report that will be submitted to the NYSDEC and NYSDOH.

Table 1. Action Limit Summary for VOCs and Particulates, Former Avis Headquarters
900 Old Country Road, Garden City, Nassau County, New York

Contaminant	Downwind Action Levels*	Action/Response
Particulates (Monitoring Via Particulate Meter and Observation)	< 100 µg/m^3	1. If dust is observed leaving the work area, then dust control techniques must be implemented or additional controls used.
	100 µg/m3 < level < 150 µg/m^3	1. Employ dust suppression techniques. 2. Work may continue with dust suppression techniques provided that the downwind PM-10 particulate concentration does not exceed 100 µg/m^3 above the upwind level, and provided that no visible dust is migrating from the work area.
	> 150 µg/m^3	1. STOP work. 2. Re-evaluate activities, modify dust suppression techniques. Work can resume provided that dust suppression measures and other controls are successful in reducing the downwind PM-10 particulate concentration to within 150 µg/m^3 of the upwind level and in preventing visible dust migration.
Volatile Organic Compounds (VOCs) (Monitoring Via Photoionization Detector and Odor Observation at the active borehole or excavation site)	< 5 ppm	1. Resume work with continued monitoring.
	5 ppm < level < 25 ppm	1. Work activities must be temporarily halted, source vapors must be identified, suppression techniques employed to abate emissions, and monitoring continued. 2. After these steps, if VOC levels (200 feet downwind of the exclusion zone or half the distance to the nearest potential receptor or structure, whichever is less) are below 5 ppm over background, resume work.
	> 25 ppm	1. Identified contributing ground intrusive activities must be halted and vapor suppression techniques must be evaluated and modified until monitoring indicates VOC levels below the action level. 2. After these steps, if VOC levels (200 feet downwind of the exclusion zone or half the distance to the nearest potential receptor or structure, whichever is less) are below 5 ppm over background, resume work.

* 15-minute running time-weighted average (twa) above background. Particulate readings are based on the respirable (PM-10) fraction. Background readings are taken at upwind locations relative to Work Areas or Exclusion Zones.

ATTACHMENT 1

Action Limit Report

ACTION LIMIT REPORT

Project Location: Former Avis Headquarters, 900 Old Country Road, Garden City, Nassau, New York

Date: _____ Time: _____

Name: _____

Contaminant: PM-10: _____ VOC: _____

Wind Speed: _____ Wind Direction: _____

Temperature: _____ Barometric Pressure: _____

DOWNWIND DATA

Monitor ID #: _____ Location: _____ Level Reported: _____

Monitor ID#: _____ Location: _____ Level Reported: _____

UPWIND DATA

Monitor ID #: _____ Location: _____ Level Reported: _____

Monitor ID#: _____ Location: _____ Level Reported: _____

BACKGROUND CORRECTED LEVELS

Monitor ID #: _____ Location: _____ Level Reported: _____

Monitor ID#: _____ Location: _____ Level Reported: _____

ACTIVITY DESCRIPTION

CORRECTIVE ACTION TAKEN

APPENDIX E

Health and Safety Briefing/Tailgate Meeting Form

HEALTH & SAFETY BRIEFING / TAILGATE MEETING FORM

Site Name / Location _____

Date: _____ Weather Forecast: _____

Names of Personnel Attending Briefing

_____ _____ _____

_____ _____ _____

_____ _____ _____

Planned Work

_____

_____

_____

Instrument Calibration: Instrument/Time/Cal. Gas/Cal. Concentration/Actual Concentration

_____

_____

_____

Items Discussed

_____

_____

_____

_____

_____

Work Permit Type and Applicable Restrictions

_____

_____

_____

Signatures of Attending Personnel

_____ _____ _____

_____ _____ _____

_____ _____ _____

APPENDIX F

Accident Report and Investigation Form

INCIDENT REPORT

Site _____

Site Location _____

Report Prepared By _____
Name Printed Title

Incident Category (Check all that apply)

_____ Injury	_____ Illness	_____ Property Damage
_____ Near Miss	_____ On-Site Equipment	_____ Chemical Exposure
_____ Motor Vehicle	_____ Fire	_____ Electrical
_____ Mechanical	_____ Other	

Date and Time of Incident _____

Name of Persons Injured (see end of report for details)

_____

_____

_____

Narrative Report of Incident

(Provide sufficient detail so that the reader may fully understand the actions leading to or contributing to the incident, the incident occurrence, and actions following the incident. Append additional sheets of paper, if necessary.)

_____

_____

_____

_____

_____

Witnesses to Incident

1. Name _____
   Company _____
   Address _____
   Telephone No. _____

2. Name _____
   Company _____
   Address _____
   Telephone No. _____

Property Damage

Brief Description of Property Damage _____

Estimate of Damage _____

Incident Location

Incident Analysis
(Causative agent most directly related to accident (object, substance, material, machinery, equipment, conditions.)

Was weather a factor? _____

Unsafe mechanical/physical/environmental condition at time of incident (be specific, must be answered):

_____

Unsafe act by injured and/or others contributing to the incident (be specific, must be answered):

_____

Personal factors (improper attitude, lack of knowledge or skill, slow reaction, fatigue):

_____

On-Site Incidents

Level of personal protection equipment required in Site Safety Plan:

_____

_____

_____

Modifications:

_____

_____

_____

Was injured using required equipment?

_____

_____

Incident Follow-Up

Date of Incident:

Brief Description of Incident:

Outcome of Incident:

Physician's Recommendations:

Date Injured Returned to Work:

APPENDIX G

Acord Form

ACORD™ AUTOMOBILE LOSS NOTICE

DATE

PRODUCER	COMPANY	MISCELLANEOUS INFO (Site & location code)
PHONE (A/C, No, Ext): 516-678-2626 James C. Herrmann & Associates LTD 265 Sunrise Highway, Suite #20 Rockville Centre, NY 11570	NAIC CODE: 19410 Commerce & Industry	
POLICY NUMBER: CA-3777920	REFERENCE NUMBER	CAT #
CODE: / SUB CODE: / AGENCY CUSTOMER ID:	EFFECTIVE DATE: 06/01/10 / EXPIRATION DATE: 06/01/11 / DATE OF ACCIDENT AND TIME / AM / PM	PREVIOUSLY REPORTED: YES / NO

INSURED

NAME AND ADDRESS	SOC SEC # OR FEIN: 11-2579482
Roux Associates, Inc. 209 Shafter Street Islandia, NY 11749	
RESIDENCE PHONE (A/C, No): NA	BUSINESS PHONE (A/C, No, Ext): 631-232-2600

CONTACT

CONTACT INSURED

NAME AND ADDRESS	WHERE TO CONTACT
Susan Sullivan, General Counsel Roux Associates, Inc. 209 Shafter Street Islandia, NY 11749	Fax Notice: 631-232-1525 WHEN TO CONTACT
RESIDENCE PHONE (A/C, No):	BUSINESS PHONE (A/C, No, Ext): 631-232-2600

LOSS

LOCATION OF ACCIDENT (Include city & state)	AUTHORITY CONTACTED: / REPORT #:	VIOLATIONS/CITATIONS
DESCRIPTION OF ACCIDENT (Use separate sheet, if necessary)		

POLICY INFORMATION

BODILY INJURY (Per Person)	BODILY INJURY (Per Accident)	PROPERTY DAMAGE	SINGLE LIMIT	MEDICAL PAYMENT	OTC DEDUCTIBLE	OTHER COVERAGE & DEDUCTIBLES (UM, no-fault, towing, etc)
					COLLISION DED	

LOSS PAYEE	UMBRELLA/EXCESS	UMBRELLA	EXCESS	CARRIER:	LIMITS:	AGGR	PER CLAIM/OCC	SIR/DED

INSURED VEHICLE

VEH #	YEAR	MAKE:	BODY TYPE:	PLATE NUMBER	STATE
		MODEL:	V.I.N.:		

OWNER'S NAME & ADDRESS	RESIDENCE PHONE (A/C, No): / BUSINESS PHONE (A/C, No, Ext):
DRIVER'S NAME & ADDRESS (Check if same as owner)	RESIDENCE PHONE (A/C, No): / BUSINESS PHONE (A/C, No, Ext):

RELATION TO INSURED (Employee, family, etc.)	DATE OF BIRTH	DRIVER'S LICENSE NUMBER	STATE	PURPOSE OF USE	USED WITH PERMISSION? YES / NO
Employee					

DESCRIBE DAMAGE	ESTIMATE AMOUNT	WHERE CAN VEHICLE BE SEEN?	WHEN CAN VEH BE SEEN?	OTHER INSURANCE ON VEHICLE

PROPERTY DAMAGED

DESCRIBE PROPERTY (If auto, year, make, model, plate #)	OTHER VEH/PROP INS? YES / NO	COMPANY OR AGENCY NAME: / POLICY #:
OWNER'S NAME & ADDRESS		RESIDENCE PHONE (A/C, No): / BUSINESS PHONE (A/C, No, Ext):
OTHER DRIVER'S NAME & ADDRESS (Check if same as owner)		RESIDENCE PHONE (A/C, No): / BUSINESS PHONE (A/C, No, Ext):

DESCRIBE DAMAGE	ESTIMATE AMOUNT	WHERE CAN DAMAGE BE SEEN?

INJURED

NAME & ADDRESS	PHONE (A/C, No)	PED	INS VEH	OTH VEH	AGE	EXTENT OF INJURY

WITNESSES OR PASSENGERS

NAME & ADDRESS	PHONE (A/C, No)	INS VEH	OTH VEH	OTHER (Specify)

REMARKS (Include adjuster assigned)

REPORTED BY	REPORTED TO	SIGNATURE OF INSURED	SIGNATURE OF PRODUCER

© ACORD CORPORATION 1988

Applicable in Arizona

For your protection, Arizona law requires the following statement to appear on this form. Any person who knowingly presents a false or fraudulent claim for payment of a loss is subject to criminal and civil penalties.

Applicable in Arkansas, District of Columbia, Kentucky, Louisiana, Maine, Michigan, New Jersey, New Mexico, Pennsylvania and Virginia

Any person who knowingly and with intent to defraud any insurance company or another person, files a statement of claim containing any materially false information, or conceals for the purpose of misleading, information concerning any fact, material thereto, commits a fraudulent insurance act, which is a crime, subject to criminal prosecution and civil penalties. In D.C., LA, ME and VA insurance benefits may also be denied.

Applicable in California

Any person who knowingly files a statement of claim containing any false or misleading information is subject to criminal and civil penalties.

Applicable in Colorado

It is unlawful to knowingly provide false, incomplete, or misleading facts or information to an insurance company for the purpose of defrauding or attempting to defraud the company. Penalties may include imprisonment, fines, denial of insurance, and civil damages. Any insurance company or agent of an insurance company who knowingly provides false, incomplete, or misleading facts or information to a policy holder or claimant for the purpose of defrauding or attempting to defraud the policy holder or claimant with regard to a settlement or award payable from insurance proceeds shall be reported to the Colorado Division of Insurance within the Department of Regulatory Agencies.

Applicable in Florida and Idaho

Any person who knowingly and with the intent to injure, Defraud, or Deceive any Insurance Company Files a Statement of Claim Containing any False, Incomplete or Misleading information is Guilty of a Felony.*

* In Florida - Third Degree Felony

Applicable in Hawaii

For your protection, Hawaii law requires you to be informed that presenting a fraudulanet claim for payment of a loss or benefit is a crime punishable by fines or imprisonment , or both.

Applicable in Indiana

A person who knowingly and with intent to defraud an insurer files a statement of claim containing any false, incomplete, or misleading information commits a felony.

Applicable in Minnesota

A person who files a claim with intent to defraud or helps commit a fraud against an insurer is guilty of a crime.

Applicable in Nevada

Pursuant to NRS 686A.291, any person who knowingly and willfully files a statement of claim that contains any false, incomplete or misleading information concerning a material fact is guilty of a felony.

Applicable in New Hampshire

Any person who, with purpose to injure, defraud or deceive any insurance company, files a statement of claim containing any false, incomplete or misleading information is subject to prosecution and punishment for insurance fraud, as provided in RSA 638:20.

Applicable in New York

Any person who knowingly makes or knowingly assists, abets, solicits or conspires with another to make a false report of the theft, destruction, damage or conversion of any motor vehicle to a law enforcement agency, the Department of Motor Vehicles or an insurance company, commits a fraudulent insurance act, which is a crime, and shall also be subject to a civil penalty not to exceed five thousand dollars and the value of the subject motor vehicle or stated claim for each violation.

Applicable in Ohio

Any person who, with intent to defraud or knowing that he/she is facilitating a fraud against an insurer, submits an application or files a claim containing a false or deceptive statement is guilty of insurance fraud.

Applicable in Oklahoma

WARNING: Any person who knowingly and with intent to injure, defraud or deceive any insurer, makes any claim for the proceeds of an insurance policy containing any false, incomplete or misleading information is guilty of a felony.

APPENDIX H

OSHA 300

OSHA's Form 300 (Rev. 01/2004)

Log of Work-Related Injuries and Illnesses

Attention: This form contains information relating to employee health and must be used in a manner that protects the confidentiality of employees to the extent possible while the information is being used for occupational safety and health purposes.

Year _____

U.S. Department of Labor
Occupational Safety and Health Administration

You must record information about every work-related injury or illness that involves loss of consciousness, restricted work activity or job transfer, days away from work, or medical treatment beyond first aid. You must also record significant work-related injuries and illnesses that are diagnosed by a physician or licensed health care professional. You must also record work-related injuries and illnesses that meet any of the specific recording criteria listed in 29 CFR 1904.8 through 1904.12. Feel free to use two lines for a single case if you need to. You must complete an injury and illness incident report (OSHA Form 301) or equivalent form for each injury or illness recorded on this form. If you're not sure whether a case is recordable, call your local OSHA office for help.

Form approved OMB no. 1218-0176

Establishment name _____

City _____ State _____

Identify the person			Describe the case			Classify the case											
						CHECK ONLY ONE box for each case based on the most serious outcome for that case:				Enter the number of days the injured or ill worker was:		Check the "injury" column or choose one type of illness:					
(A) Case No.	(B) Employee's Name	(C) Job Title (e.g., Welder)	(D) Date of injury or onset of illness (mo./day)	(E) Where the event occurred (e.g. Loading dock north end)	(F) Describe injury or illness, parts of body affected, and object/substance that directly injured or made person ill (e.g. Second degree burns on right forearm from acetylene torch)	Death	Days away from work	Remained at work		Away From Work (days)	On job transfer or restriction (days)	(M) Injury	Skin Disorder	Respiratory Condition	Poisoning	Hearing Loss	All other illnesses
								Job transfer or restriction	Other record-able cases								
						(G)	(H)	(I)	(J)	(K)	(L)	(1)	(2)	(3)	(4)	(5)	(6)
					Page totals	*0*	*0*	*0*	*0*	*0*	*0*	*0*	*0*	*0*	*0*	*0*	*0*

Be sure to transfer these totals to the Summary page (Form 300A) before you post it.

Public reporting burden for this collection of information is estimated to average 14 minutes per response, including time to review the instruction, search and gather the data needed, and complete and review the collection of information. Persons are not required to respond to the collection of information unless it displays a currently valid OMB control number. If you have any comments about these estimates or any aspects of this data collection, contact: US Department of Labor, OSHA Office of Statistics, Room N-3644, 200 Constitution Ave, NW, Washington, DC 20210. Do not send the completed forms to this office.

Injury (1) Skin Disorder (2) Respiratory Condition (3) Poisoning (4) Hearing Loss (5) All other illnesses (6)

APPENDIX I

Weekly Safety Report

APPENDIX I

WEEKLY SAFETY REPORT

Job Name_____ **Job#**_____

Week of: **Days Without Lost Time Injury:**

Describe any recordable incidents or accidents:

What actions were taken to prevent such incidents or accidents from occurring again?

Was training conducted addressing the incident? Y N What date?___

What level of PPE is currently in place?

Has PPE been upgraded or downgraded?

Have Perimeter Air Monitoring action limits been exceeded:

What action was taken to mitigate the exceedance?

Have personal air monitoring limits been exceeded:

What actions were taken?

List any problems with air monitoring equipment:

Write a summary of work completed during the week:

Write a summary of proposed work for the coming week:

Summarize any safety issues that are outstanding:

HSO Name: _____ **HSO Signature:** _____

APPENDIX J

Job Safety and Health Protection Poster

You Have a Right to a Safe and Healthful Workplace.

IT'S THE LAW!

- You have the right to notify your employer or OSHA about workplace hazards. You may ask OSHA to keep your name confidential.
- You have the right to request an OSHA inspection if you believe that there are unsafe and unhealthful conditions in your workplace. You or your representative may participate in the inspection.
- You can file a complaint with OSHA within 30 days of discrimination by your employer for making safety and health complaints or for exercising your rights under the *OSH Act*.
- You have a right to see OSHA citations issued to your employer. Your employer must post the citations at or near the place of the alleged violation.
- Your employer must correct workplace hazards by the date indicated on the citation and must certify that these hazards have been reduced or eliminated.
- You have the right to copies of your medical records or records of your exposure to toxic and harmful substances or conditions.
- Your employer must post this notice in your workplace.

The *Occupational Safety and Health Act of 1970 (OSH Act),* P.L. 91-596, assures safe and healthful working conditions for working men and women throughout the Nation. The Occupational Safety and Health Administration, in the U.S. Department of Labor, has the primary responsibility for administering the *OSH Act.* The rights listed here may vary depending on the particular circumstances. To file a complaint, report an emergency, or seek OSHA advice, assistance, or products, call 1-800-321-OSHA or your nearest OSHA office: • Atlanta (404) 562-2300 • Boston (617) 565-9860 • Chicago (312) 353-2220 • Dallas (214) 767-4731 • Denver (303) 844-1600 • Kansas City (816) 426-5861 • New York (212) 337-2378 • Philadelphia (215) 861-4900 • San Francisco (415) 975-4310 • Seattle (206) 553-5930. Teletypewriter (TTY) number is 1-877-889-5627. To file a complaint online or obtain more information on OSHA federal and state programs, visit OSHA's website at **www.osha.gov**. If your workplace is in a state operating under an OSHA-approved plan, your employer must post the required state equivalent of this poster.

1-800-321-OSHA
www.osha.gov

U.S. Department of Labor • Occupational Safety and Health Administration • OSHA 3165



MW-6

Analyte	Jul-09	Sep-09
Isoproylbenzene	ND	**21**
Bis(2-ethylexyl)pthalate	**30**	NA
Arsenic	**80**	8
Chromium	**99**	ND
Iron	**218000**	NA
Lead	**100**	ND
Manganese	**590**	61

MW-3

Analyte	Jul-09	Sep-09
Chromium	**300**	ND
Iron	**1510**	NA

MW-4

Analyte	Jul-09	Sep-09
Iron	**1670**	NA

MW-5

Analyte	Jul-09	Sep-09
Bis(2-ethylexyl)pthalate	**30**	NA
Barium	NA	67
Chromium	**93**	ND
Iron	**104000**	NA
Lead	**80**	ND
Manganese	**2830**	45
Nickel	**110**	6

MW-7

Analyte	Jul-09	Sep-09
Bis(2-ethylexyl)pthalate	**20**	NA
Arsenic	**53**	ND
Barium	**1020**	64
Chromium	**150**	ND
Iron	**213000**	NA
Lead	**140**	ND
Manganese	**2950**	32
Nickel	**140**	5

MW-15

Analyte	Jul-09	Sep-09
Bis(2-ethylexyl)pthalate	**30**	NA
Iron	**870**	NA

MW-1

Analyte	Jul-09	Sep-09
Iron	**5800**	NA

MW-2

Analyte	Jul-09	Sep-09
Iron	**1670**	NA

MW-19

Analyte	Jul-09	Sep-09
Bis(2-ethylexyl)pthalate	**20**	NA
Iron	**7570**	NA
Manganese	**370**	**320**

SVW-4

Analyte	Aug-09
TCE	ND
PCE	0.69
TCA	ND
VC	0.49

MW-18

Analyte	Jul-09	Sep-09
Methylene Chloride	**8**	ND
Bis(2-ethylexyl)pthalate	**50**	NA
Iron	**560**	NA

MW-14

Analyte	Jul-09	Sep-09
Bis(2-ethylexyl)pthalate	**30**	NA
Iron	**1550**	NA

MW-13

Analyte	Jul-09	Sep-09
TCE	ND	**6**
Bis(2-ethylexyl)pthalate	**30**	NA
Iron	**26000**	NA

MW-11

Analyte	Jul-09	Sep-09
TCE	**12.9**	**35**
cis-1,2-Dichloroethene	ND	**9**
Bis(2-ethylexyl)pthalate	**30**	NA
Iron	**17200**	NA

SVW-3

Analyte	Aug-09
TCE	5.2
PCE	1.2
TCA	0.67

MW-12

Analyte	Jul-09	Sep-09
TCE	**13.7**	**15**
Bis(2-ethylexyl)pthalate	**20**	NA
Iron	**6130**	NA

MW-12A

Analyte	Jul-09	Sep-09
Chromium	NA	**91**
Manganese	NA	**1270**

MW-10

Analyte	Jul-09	Sep-09
Bis(2-ethylexyl)pthalate	**20**	NA
Chromium	**130**	ND
Iron	**124000**	NA
Lead	**85**	ND
Manganese	**5070**	155

MW-9

Analyte	Jul-09	Sep-09
PCE	**26.4**	**23**
Bis(2-ethylexyl)pthalate	**20**	NA
Iron	**7850**	NA

MW-9A

No Exceedances

SVW-1

Analyte	Aug-09
TCE	ND
PCE	6
TCA	5.2
VC	0.23

SVW-2

Analyte	Aug-09
TCE	290
PCE	330
TCA	94

MW-17

Analyte	Jul-09	Sep-09
PCE	**28**	**19**
Bis(2-ethylexyl)pthalate	**30**	NA
Iron	**1330**	NA

MW-8

Analyte	Jul-09	Sep-09
Bis(2-ethylexyl)pthalate	**20**	NA
Iron	**39600**	NA
Manganese	**1410**	43

MW-16

Analyte	Jul-09	Sep-09
PCE	ND	5
Bis(2-ethylexyl)pthalate	**30**	NA
Iron	**3360**	NA

LEGEND

- MW-8 — MONITORING WELL
- SVW-1 — SOIL VAPOR SAMPLE
- LP-25 — LEACH POOL
- CB-3 — CATCH BASIN
- DW-1 — DRY WELL
- SED-4 — SOIL SAMPLE
- S-8 — SOIL SAMPLE

TYPICAL SOIL VAPOR SAMPLE DATA BOX

SAMPLE ID: SVW-3

ANALYTES	Aug-09 (SAMPLE DATE)
TCE	5.2
PCE	1.2
TCA	0.67

CONCENTRATION IN ug/m 3

TYPICAL GROUNDWATER SAMPLE DATA BOX

SAMPLE ID: MW-3

ANALYTES	Jul-09	Sep-09 (SAMPLE DATE)
Chromium	300	ND (NOT DETECTED)
Iron	1510	NA (NOT AVAILABLE)

CONCENTRATION IN ug/L

GROUNDWATER STANDARDS

Analyte	Standard (µg/L)
Arsenic	25
Barium	1000
Bis(2-ethylexyl)pthalate	5
Chromium	50
Iron	300
Isoproylbenzene	5
Lead	25
Manganese	300
Nickel	100
PCE	5
TCE	5

ND - Not Detected
NA - Not Available

Concentrations shown in **bold** exceed the respective guidance value

100' 0 100'

Title:

HISTORICAL GROUNDWATER AND SOIL VAPOR RESULTS

FORMER AVIS HEADQUARTERS PROPERTY
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

Prepared For:

EQUITY ONE, INC.

ROUX ASSOCIATES, INC.
Environmental Consulting and Management

Compiled by: W.M.	Date: 19JAN11	PLATE 1
Prepared by: B.H.C.	Scale: AS SHOWN	
Project Mgr: C.W.	Project: 1924.0001Y	
File: 1924.0001Y106R.04.DWG		

\1924Y\0001Y\106R\1924.0001Y106R.04.DWG



DW-19	Sep-09
Analyte	*10-11*
Benzo-a-anthracene	**35**
Benzo-a-pyrene	**51**
Benzo-b-fluoroanthene	**71**
Benzo-k-fluoroanthene	**42.6**
Chrysene	**69**
Dibenzo-a,h-anthracene	**9.80**
Fluoranthene	**133**
Indeno(1,2,3-C,D)Pyrene	**48.1**

DW-21	Sep-09
Analyte	*12-13*
Benzo-a-anthracene	**109**
Benzo-a-pyrene	**137**
Benzo-b-fluoroanthene	**166**
Benzo-k-fluoroanthene	**108.4**
Chrysene	**169**
Dibenzo-a,h-anthracene	**25.23**
Fluoranthene	**360**
Indeno(1,2,3-C,D)Pyrene	**102.9**
Phenanthrene	**225**
Pyrene	**265**

DW-1	Sep-09
Analyte	7-8
Benzo-a-anthracene	**35**
Benzo-a-pyrene	**49**
Benzo-b-fluoroanthene	**54**
Benzo-k-fluoroanthene	**41.2**
Chrysene	**49**
Dibenzo-a,h-anthracene	**8.74**
Indeno(1,2,3-C,D)Pyrene	**40.2**

DW-2	Sep-09
Analyte	*8-9*
Benzo-a-anthracene	**90**
Benzo-a-pyrene	**127**
Benzo-b-fluoroanthene	**162**
Benzo-k-fluoroanthene	**113.4**
Chrysene	**167**
Dibenzo-a,h-anthracene	**20.24**
Fluoranthene	**388**
Fluorene	**36**
Indeno(1,2,3-C,D)Pyrene	**98.4**
Phenanthrene	**256**
Pyrene	**269**

DW-14	Sep-09
Analyte	*12-13*
Benzo-a-anthracene	**90**
Benzo-a-pyrene	**41**
Benzo-b-fluoroanthene	**67**
Benzo-k-fluoroanthene	**35.3**
Chrysene	**54**
Dibenzo-a,h-anthracene	**7.82**
Indeno(1,2,3-C,D)Pyrene	**43.1**

DW-16	Sep-09
Analyte	*11-12*
Benzo-a-pyrene	1
Benzo-b-fluoroanthene	**1.4**
Benzo-k-fluoroanthene	**0.9**
Chrysene	**1.1**
Indeno(1,2,3-C,D)Pyrene	**1.0**

B-1	Sep-09
No Exceedances	*20-22*

B-2	Sep-09
No Exceedances	*20-22*

B-3	Sep-09
No Exceedances	*20-22*

DW-20	Sep-09
Analyte	*17-18*
Benzo-a-anthracene	**56**
Benzo-a-pyrene	**85**
Benzo-b-fluoroanthene	**125**
Benzo-k-fluoroanthene	**85.8**
Chrysene	**120**
Dibenzo-a,h-anthracene	**17.03**
Fluoranthene	**210**
Indeno(1,2,3-C,D)Pyrene	**87.0**
Pyrene	**153**

DW-22	Sep-09
Analyte	*8-9*
Benzo-a-anthracene	**40**
Benzo-a-pyrene	**64**
Benzo-b-fluoroanthene	**81**
Benzo-k-fluoroanthene	**58.8**
Chrysene	**84**
Dibenzo-a,h-anthracene	**11.49**
Fluoranthene	**155**
Indeno(1,2,3-C,D)Pyrene	**56.8**
Pyrene	**117**

S-7	Oct-09
No Exceedances	*2-3*

S-8	Oct-09
No Exceedances	*1-2*

SEDIMENT-4	Jul-05
Analyte	*grab*
Benzo-a-anthracene	**6**
Chrysene	**5**
Benzo-b-fluoroanthene	**5**
Benzo-k-fluoroanthene	**7.1**
Phenols	**31.20**
Toluene*	**30**

SEDIMENT-3	Jul-05
Analyte	*grab*
Benzo-a-anthracene	**54**
Benzo-a-pyrene	**21**
Benzo-b-fluoroanthene	**41**
Benzo-k-fluoroanthene	**30.8**
Chrysene	**32**
Dibenzo-a,h-anthracene	**6.14**
Indeno(1,2,3-C,D)Pyrene	**3.2**
Phenols	**7.40**

LP-28	Oct-09
No Exceedances	*11-12*

DW-25	Sep-09
No Exceedances	*9-10*

B-4	Sep-09
No Exceedances	*16-18*

B-5	Sep-09
No Exceedances	*10-12*

B-6	Sep-09
No Exceedances	*16-18*

B-7	Sep-09
No Exceedances	*16-18*

DW-23	Sep-09
No Exceedances	*7-8*

B-15	Sep-09
No Exceedances	*3-4*

LP-1	Oct-09
No Exceedances	*10-11*

LP-4	Oct-09
No Exceedances	*10-11*

SS-1	Oct-09
No Exceedances	*3-4*

SS-2	Oct-09
Analyte	*1-2*
Benzo-a-anthracene	**1.1**
Benzo-b-fluoroanthene	**1.2**
Benzo-k-fluoroanthene	**1.4**
Chrysene	**1.6**

LP-9	Oct-09
No Exceedances	*12-13*

LP-15	Oct-09
No Exceedances	*12-13*

DW-24	Sep-09
No Exceedances	*9-10*

S-2	Oct-09
No Exceedances	*1-2*

S-1	Oct-09
No Exceedances	*1-2*

LP-23	Oct-09
No Exceedances	*12-13*

LP-25	Oct-09
No Exceedances	*10-11*

SEDIMENT-1	Jul-05
Analyte	*grab*
Benzo-a-anthracene	**6**
Benzo-b-fluoroanthene	**3**
Benzo-k-fluoroanthene	**2.5**
Chrysene	**3**

SEDIMENT-2	Jul-05
Analyte	*grab*
Benzo-a-anthracene	**15**
Benzo-a-pyrene	**7**
Benzo-b-fluoroanthene	**12**
Benzo-k-fluoroanthene	**5.9**
Chrysene	**12**
Indeno(1,2,3-C,D)Pyrene	**6**
Dibenzo-a,h-anthracene	**0.74**

S-5	Oct-09
No Exceedances	*1-2*

S-3	Oct-09
No Exceedances	*1-2*

S-4	Oct-09
No Exceedances	*1-2*

B-8	Sep-09
No Exceedances	*18-20*

B-9	Sep-09
No Exceedances	*18-20*

LP-14	Oct-09
No Exceedances	*12-13*

B-14	Sep-09
No Exceedances	*2-4*

LP-21	Oct-09
No Exceedances	*12-13*

DW-26	Sep-09
Analyte	*12-13*
Benzo-a-anthracene	**1.5**
Benzo-a-pyrene	**1.1**
Benzo-b-fluoroanthene	**1.2**
Indeno(1,2,3-C,D)Pyrene	**0.8**
Pentachlorophenol	**6.5**

LP-22	Oct-09
No Exceedances	*12-13*

B-11	Sep-09
No Exceedances	*18-20*

B-12	Sep-09
No Exceedances	*0-2*

B-13	Sep-09
No Exceedances	*18-20*

LP-26	Oct-09
No Exceedances	*10-11*

B-10	Sep-09
No Exceedances	*18-20*

LP-27	Oct-09
Analyte	*12-13*
Benzo-a-anthracene	**3**
Benzo-a-pyrene	**3**
Benzo-b-fluoroanthene	**4**
Benzo-k-fluoroanthene	**4.50**
Chrysene	**3**

LP-24	Oct-09
No Exceedances	*12-13*

LEGEND

- MW-8 — MONITORING WELL
- SVW-1 — SOIL VAPOR SAMPLE
- LP-25 — LEACH POOL
- CB-3 — CATCH BASIN
- DW-1 — DRY WELL
- SED-4 — SOIL SAMPLE
- S-8 — SOIL SAMPLE

TYPICAL SOIL SVOCs RESULTS DATA BOX

SAMPLE ID — **SS-2** | *Oct-09* — SAMPLE DATE

ANALYTES — *Analyte* | *1-2* — SAMPLE DEPTH (FEET)

Benzo-a-anthracene	**1.1**
Benzo-b-fluoroanthene	**1.2**
Benzo-k-fluoroanthene	**1.4**
Chrysene	**1.6** — CONCENTRATION IN mg/kg

Analyte	Standard (mg/kg)
Benzo-a-anthracene	1
Benzo-a-pyrene	1
Benzo-b-fluoroanthene	1
Benzo-k-fluoroanthene	0.8
Chrysene	1
Dibenzo-a,h-anthracene	0.33
Fluoranthene	100
Fluorene	30
Indeno(1,2,3-C,D)Pyrene	0.5
Pentachlorophenol	0.8
Phenanthrene	100
Phenols	0.33
Pyrene	100
Toluene*	0.7

* Volatile organic compound

Concentrations shown in **bold** exceed the respective guidance value

100' 0 100'

Title:

HISTORICAL SOIL SAMPLE RESULTS SVOCs

FORMER AVIS HEADQUARTERS PROPERTY
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

Prepared For:

EQUITY ONE, INC.

ROUX ASSOCIATES, INC.
Environmental Consulting and Management

Compiled by: W.M.	Date: 19JAN11	PLATE
Prepared by: B.H.C.	Scale: AS SHOWN	**2A**
Project Mgr: C.W.	Project: 1924.0001Y	
File: 1924.0001Y106R.01.DWG		

\1924\Y\0001Y\106R\1924.0001Y106R.01.DWG

C



LEGEND

- MW-8 — MONITORING WELL
- SVW-1 — SOIL VAPOR SAMPLE
- LP-25 — LEACH POOL
- CB-3 — CATCH BASIN
- DW-1 — DRY WELL
- SED-4 — SOIL SAMPLE
- S-8 — SOIL SAMPLE

TYPICAL SOIL METALS AND PCB RESULTS DATA BOX

SAMPLE ID	
LP-23	Oct-09 (SAMPLE DATE)
Analyte	12-13 (SAMPLE DEPTH (FEET))
Chromium	48.2
Copper	138
PCBs	1.96 (CONCENTRATION IN mg/kg)

ANALYTES

Analyte	Standard (mg/kg)
Arsenic	13
Barium	350
Cadmium	2.5
Chromium	30
Copper	50
Lead	63
Manganese	1600
Mercury	0.18
Nickel	30
Silver	2
Zinc	109
PCBs	0.1

Concentrations shown in **bold** exceed the respective guidance value.

Only exceedances are shown.

Title:

HISTORICAL SOIL SAMPLE RESULTS METALS AND PCBs

FORMER AVIS HEADQUARTERS PROPERTY
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

Prepared For:

EQUITY ONE, INC.

ROUX ASSOCIATES, INC.
Environmental Consulting and Management

Compiled by: W.M.	Date: 19JAN11	PLATE
Prepared by: B.H.C.	Scale: AS SHOWN	2B
Project Mgr: C.W.	Project: 1924.0001Y	
File: 1924.0001Y106.04.DWG		

\1924\Y\0001Y\106R\1924.0001Y106.04.DWG

C



DW-2	11/17/10	11/17/10
Depth	9-11'	15-17'
SVOCs		
Benzo[a]anthracene	NE	36000
Benzo[a]pyrene	1400	48000
Benzo[b]fluoranthene	1900	53000
Benzo[k]fluoranthene	NE	19000
Chrysene	1100	33000
Dibenzo[a,h]anthracene	NE	6300
Indeno[1,2,3-cd]pyrene	860	NE

DW-15	11/17/10	11/17/10
Depth	10-12'	14-16'
SVOCs		
Benzo[a]anthracene	7000	NE
Benzo[a]pyrene	13000	NE
Benzo[b]fluoranthene	19000	NE
Benzo[k]fluoranthene	5900	NE
Chrysene	12000	NE
Dibenzo[a,h]anthracene	3700	ND
Indeno[1,2,3-cd]pyrene	18000	NE

DW-14	11/17/10	11/17/10
Depth	10-12'	14-16'
SVOCs		
Benzo[a]pyrene	1300	NE
Benzo[b]fluoranthene	2100	NE
Chrysene	1200	NE
Indeno[1,2,3-cd]pyrene	1700	ND

DW-1	11/17/10	11/17/10
Depth	8.5-10.5'	14.5-16.5'
No Exceedances		

DW-16	11/17/10	11/17/10
Depth	6-8'	12-14'
No Exceedances		

DW-22	11/17/10	11/17/10
Depth	10-12'	14-16'
No Exceedances		

LP-2	11/15/10	11/15/10
Depth	10-12'	14-16'
PCBs		
Total PCBs	320	NE
Pesticides		
4,4'-DDD	13 p	NE
4,4'-DDE	9.3	NE
4,4'-DDT	30	NE

LP-1	11/15/10	11/15/10
Depth	10-12'	14-16'
No Exceedances		

LP-4	11/15/10
Depth	14-16'
No Exceedances	

LP-3	11/15/10	11/15/10
Depth	10-12'	14-16'
No Exceedances		

LP-5	11/15/10	11/15/10
Depth	10-12'	14-16'
Pesticides		
4,4'-DDT	7.9	5.7 J

LP-6	11/15/10	11/15/10
Depth	10-12'	14-16'
Pesticides		
4,4'-DDD	5.6 J	NE
4,4'-DDT	6.2 J	NE

LP-7	11/15/10	11/15/10	11/15/10
Depth	10-12'	10-12' DUP	14-16'
Pesticides			
4,4'-DDT	NE	NE	3.9 J

LP-8	11/15/10	11/15/10
Depth	10-12'	14-16'
No Exceedances		

LP-28	11/16/10
Depth	14-16'
Metals	
Silver	24.7

LP-29	11/16/10	11/16/10
Depth	10-12'	14-16'
Metals		
Silver	16.9	7.5
Pesticides		
4,4'-DDD	6 J	NE

LP-13	11/15/10	11/15/10
Depth	10-12'	15-17'
Pesticides		
beta-BHC	NE	140 p

LP-17	11/16/10	11/16/10
Depth	10-12'	14-16'
No Exceedances		

LP-15	11/16/10
Depth	14-16'
No Exceedances	

LP-19	11/16/10	11/16/10
Depth	10-12'	14-16'
Metals		
Chromium	NE	72.4

LP-23	11/16/10	11/16/10
Depth	14-16'	14-16' DUP
PCBs		
Total PCBs	110	110
Pesticides		
4,4'-DDD	11	3.6 J p
4,4'-DDT	15	7.2
Dieldrin	6.2 J	NE

LP-25	11/16/10
Depth	14-16'
PCBs	
Total PCBs	110
Pesticides	
4,4'-DDD	9.1
4,4'-DDT	12

LP-26	11/16/10
Depth	14-16'
Pesticides	
4,4'-DDD	5.8 J
4,4'-DDT	7.8

LP-24	11/16/10
Depth	14-16'
PCBs	
Total PCBs	129
Pesticides	
4,4'-DDD	7.4
4,4'-DDT	9

LP-27	11/16/10
Depth	14-16'
Metals	
Chromium	44.5

LP-9	11/15/10	11/15/10
Depth	10-12'	14-16'
Metals		
Chromium	31.8	NE

LP-11	11/15/10	11/15/10
Depth	15-17'	19-21'
No Exceedances		

LP-14	11/15/10
Depth	14-16'
No Exceedances	

LP-22	11/16/10
Depth	14-16'
PCBs	
Total PCBs	310
Pesticides	
4,4'-DDD	22
4,4'-DDE	9.2
4,4'-DDT	30
Dieldrin	8.4 p

MW-20	11/17/10
Depth	18-20'
No Exceedances	

LP-10	11/15/10	11/15/10
Depth	10-12'	14-16'
PCBs		
Total PCBs	320	53
Pesticides		
4,4'-DDD	16	NE
4,4'-DDE	8.6	NE
4,4'-DDT	22	4 J
Dieldrin	6.2 J p	NE

LP-12	11/15/10	11/15/10
Depth	11-13'	17-19'
PCBs		
Total PCBs	220	NE
Pesticides		
4,4'-DDD	14	NE
4,4'-DDT	19	NE

LP-16	11/16/10	11/16/10
Depth	10-12'	14-16'
No Exceedances		

LP-18	11/16/10	11/16/10
Depth	10-12'	14-16'
No Exceedances		

LP-20	11/16/10	11/16/10
Depth	10-12'	14-16'
SVOCs		
Indeno[1,2,3-cd]pyrene	520	NE
Pesticides		
4,4'-DDD	10	5.1 J
4,4'-DDE	5.8 J p	NE
4,4'-DDT	9.7	6 J

LP-21	11/16/10	11/16/10
Depth	14-16'	14-16' DUP
No Exceedances		

LEGEND

- SOIL SAMPLE LOCATION
- MW-21 PROPOSED MONITORING WELL
- LP-25 LEACH POOL
- CB-3 CATCH BASIN
- DW-1 DRY WELL

Parameter	Standards*	Standards**
VOCs (µg/kg)	No Exeedances	
SVOCs (µg/kg)		
Benzo[a]anthracene	1000	5600
Benzo[a]pyrene	1000	1000
Benzo[b]fluoranthene	1000	5600
Benzo[k]fluoranthene	800	56000
Chrysene	1000	56000
Dibenzo[a,h]anthracene	330	560
Indeno[1,2,3-cd]pyrene	500	5600
Metals (mg/kg)		
Chromium	30	1500
Silver	2	1500
PCBs (µg/kg)		
Total PCBs	100	1000
Pesticides (µg/kg)		
4,4'-DDD	3.3	92000
4,4'-DDE	3.3	62000
4,4'-DDT	3.3	47000
beta-BHC	36	3000
Dieldrin	5	1400

µg/kg - Micrograms per kilogram
mg/kg - Milligrams per kilogram
*NYSDEC Part 375 Unrestricted Use Criteria
**NYSDEC Part 375 Restricted Commercial Criteria
NYSDEC - New York State Department of Environmental Conservation
J - Estimated value
p - The %RPD between the primary and confirmation column/detector is >40%. The lower value has been reported
DUP - Duplicate Sample
VOCs - Volatile Organic Compounds
SVOCs - Semivolatile Organic Compounds
PCBs - Polychlorinated Biphenyls
NE - No exceedances

NOTES

1. DW-19, DW-20 AND DW-21 NOT SAMPLED.
2. MW-17A AND MW-21 NOT INSTALLED.

100' 0 100'

Title:

NOVEMBER 2010
DRYWELL / LEACHING POOL SAMPLE RESULTS

FORMER AVIS HEADQUARTERS PROPERTY
900 OLD COUNTRY ROAD
GARDEN CITY, NY 11530

Prepared For:

EQUITY ONE, INC.

ROUX ASSOCIATES, INC.
Environmental Consulting and Management

Compiled by: W.M.	Date: 19JAN11	PLATE
Prepared by: B.H.C.	Scale: AS SHOWN	3
Project Mgr: C.W.	Project: 1924.0001Y	
File: 1924.0001Y106R.03.DWG.DWG		

\1924\Y\0001Y\106R\1924.0001Y106R.03.DWG.DWG