AECOM

DATE May 14 2026


605 3rd Avenue
New York, New York 10158
Telephone: (212)-377-8400

DAY	S	M	T	W	TH	F	S

DAILY ACTIVITIES REPORT

WEATHER	Bright Sun	Clear	Overcast	Rain	Snow
TEMP	To 32	32-50	50-70	70-85	85 and up
WIND	Still	Moder	High	Report No.	
HUMIDITY	Dry	Moder	Humid		

PROJECT: Site No.C224260A Former El Puente
CONTRACTOR:
AECOM JOB No.: 60754071
AECOM PROJECT MANAGER: C. Friedman
EPA SITE ID NO.: NYR000280818
LAB CALL OUT ID NO.: 153290



FIELD PERSONNEL	Time In	Time Out	Remarks
Anthony Gilman	600	1500	
Malli Surana	645	1500	

CONTRACTORS (include names of staff)	Time In	Time Out	**Heavy Equipment Onsite**
Republic Services (IDW)	1435	1450	

VISITORS OF NOTE

Time	NAME	Representing	Remarks

WORK ACTIVITIES PERFORMED (Since Last Report):

Two of three of the remaining wells were sampled. MW-01 was not able to be sampled due to low volume of water present in the well and inability to establish flow. The well appears to have a bend in it. Footage was lost during installation.

Public Complaints or Problems Encountered:

N/A

Note: Any public complaints should be recorded and include the names, contact numbers, and summary of the complaint.

SAMPLES COLLECTED (Since Last Report)

EX-MW-04-20260514, EX-MW-05-20260514

AIR MONITORING (Since Last Report)

N/A

Action Levels Exceeded?? - Indicate Time of Day And Any Mitigation Measures or N/A:

N/A

PLANNED DAILY ACTIVITIES FOR NEXT DAY/WEEK

WELL ID	DATE/TIME	DTP	DTW	DTB
MW-01	5/13/26, 0753	ND	ND	50.32
MW-02	5/13/26, 0748	ND	46.00	54.23
MW-03	5/13/2026, 0825	ND	45.29	52.31
EX-MW-03	5/13/26, 0822	ND	46.11	69.28
EX-MW-04	5/13/26, 0819	ND	47.55	54.54
EX-MW-05	5/13/26, 0815	ND	48.28	54.2

Well Gauging Data collected 5/13/26



Set up for EX-MW-05-20260514