PHASE I
ENVIRONMENTAL SITE ASSESSMENT REPORT

November 5, 2019

59-69 Bartlett Street, 84-100 Throop Avenue and
90-100 Gerry Street, Brooklyn, NY 11206

EBC Project No: SNA1903

Block 2269, Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36



Prepared for:

St. Nick's Alliance
2 Kingsland Avenue
Brooklyn, NY 11211

EBC

ENVIRONMENTAL BUSINESS CONSULTANTS

1808 Middle Country Road. Ridge, New York 11961

Phone: 631.504.6000 Fax: 631.924.2870

TABLE OF CONTENTS

EXECUTIVE SUMMARY ..... **i**

1.0 INTRODUCTION **1**

1.1 Purpose 1

1.2 Detailed Scope of Services 1

1.3 Significant Assumptions 3

1.4 Limitations and Exceptions 3

1.5 User Reliance 4

2.0 SITE DESCRIPTION **5**

2.1 Property and Address Location 5
2.1.1 Tax Map Number 5
2.1.2 Acreage and Building Size 5
2.1.3 Ownership 5
2.1.4 Zoning 5

2.2 Current Occupancy and Property Use 5

3.0 USER PROVIDED INFORMATION **7**

3.1 Title Records 7

3.2 Environmental Liens 7

3.3 Specialized Knowledge 7

3.4 Commonly Known or Reasonably Ascertainable Information 7

3.5 Valuation Reduction for Environmental Issues 7

3.6 Reason for Performing Phase I ESA 7

4.0 SITE GEOLOGY AND HYDROGEOLOGY **8**

4.1 Topography and Site Characteristics 8
4.1.1 Elevation 8
4.1.2 Surface Water Bodies 8
4.1.3 Soils 8

4.2 Groundwater Characteristics 9

4.2.1 Depth to the Water and Groundwater Flow Direction 9

4.3 Geology 9

5.0 SITE HISTORY **10**

5.1 Municipal Records Review 10
5.2 Historical Resources Review 16
5.2.1 Sanborn Fire Insurance Map Review 16
5.2.2 Historic Aerial Photograph Review 18
5.2.3 Historic Topographic Map Review 19
5.2.4 Historical City Directory Search 20
5.2.5 Previous Environmental Site Assessments 22
5.2.6 Environmental Liens or Activity and Use Limitations 22
5.3 Summary of Site History 23

6.0 REGULATORY AGENCY DATABASE SEARCH 25
6.1 Federal Databases 25
6.2 State Databases 27
6.3 Tribal Records and EDR Proprietary Databases 36
6.4 Orphan Site Summary 37

7.0 SITE RECONNAISSANCE 38
7.1 Site Inspection 38
7.2 Methodology and Limiting Conditions 38
7.3 Site Description 38
7.4 Utilities 38
7.5 Surrounding Land Use 39
7.6 Interviews 39
7.7 Summary of Environmental Site Features 40
7.7.1 Chemical Use and Storage 40
7.7.2 Hazardous and Non-Hazardous Waste Storage and Disposal 40
7.7.3 Underground and Aboveground Storage Tanks 40
7.7.4 Sanitary and Stormwater Disposal 40
7.7.5 Polychlorinated Biphenyls 40
7.7.6 Debris, Dumping and Surficial Staining 41
7.7.7 Stressed Vegetation 41
7.7.8 Other Environmental Concerns 41

8.0 NON-SCOPE CONSIDERATIONS 43
8.1 Radon 43
8.2 Lead-Based Paint 43
8.3 Asbestos-Containing Materials 43
8.4 Wetlands 44
8.5 Mold and Water Damage 44
8.6 Vapor Encroachment 45

9.0 CONCLUSIONS AND RECOMMENDATIONS 46

10.0 ENVIRONMENTAL PROFESSIONAL STATEMENT 49

11.0 REFERENCES.....50

FIGURES

No.	Description
1	Site Location Map
2	Lot Diagram
3	Tax Map
4	Site Aerial
5A	Zoning Map
5B	Historic Zoning Map
6	Groundwater Flow Map

APPENDICES

APPENDIX A - Representative Site Photographs
APPENDIX B - Local Government Correspondence
APPENDIX C - Historic Information
APPENDIX D - Regulatory Agency Database Report
APPENDIX E - Prior Reports/Miscellaneous

EXECUTIVE SUMMARY

Environmental Business Consultants (EBC) prepared this Phase I Environmental Site Assessment (ESA) for the undeveloped property located on the west site of Throop Avenue, between Gerry Street to the north, and Bartlett Street to the south, in the Broadway Triangle section of the Borough of Brooklyn, New York City, Kings County, New York (hereinafter the "subject property"). Gerry Street borders portions of the site to the north and Bartlett Street borders portions of the site to the south. The subject property is identified by the street addresses of 59-69 Bartlett Street, 84-100 Throop Avenue, and 90-100 Gerry Street, and as Borough 3 – Block 2269 – Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36 on the New York City (NYC) tax maps.

The purpose of the Phase I ESA was to identify and evaluate the presence of recognized environmental conditions. Recognized environmental conditions are defied as the presence or likely presence of any hazardous substances or petroleum products in, on or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions. The work was conducted in accordance with the American Society for Testing and Materials (ASTM) Standard E 1527-13 (Standard Practices for Environmental Site Assessment: Phase I Environmental Site Assessment Process), 40 CFR Part 312 (Standards and Practices for All Appropriate Inquiry; Final Rule), and EBC's proposal for services.

EBC was able to establish a history for the property dating back to 1887. According to a review of NYC records, Sanborn maps, aerial photographs, historic city directories, and historic topographic maps, as well as personal interviews, the subject property was developed with approximately 16 small low-rise 1- to 3-story retail and residential buildings, as well as several small outbuildings, by at least 1887. By 1904, a larger 2-story stable building is present along Gerry Street and a 5-story multi-tenant retail building, including a tailor and knitting shop was present at the corner of Throop Avenue and Bartlett Street. By 1918, the properties along Throop Avenue were redeveloped with multiple 3-story buildings, including an undertaker, residences and retail stores. In addition, the properties along Bartlett Street at the southwestern portion were developed with two 5-story retail buildings. By 193, the undertakers is identified as a retail store and the stable along Gerry Street and the retail building at the southeastern corner are identified as loft buildings. An undeveloped parcel is present at 65 Bartlett Street by 1947 and the building at the corner of Bartlett Street and Throop Avenue is partially occupied by a club. By 1965, the vacant lot along Bartlett Street has been developed with

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

an auto repair shop and an undeveloped lot is visible along Throop Avenue (92-94 Throop Avenue). Three additional parcels along Throop Avenue (86, 88 and 90 Throop Avenue) are shown as undeveloped by 1980, with the northeastern most parcel shown as undeveloped by 1981. The two southwestern parcels (59 and 63 Bartlett Street) are undeveloped by 1986. Between 1989 and 1991, the building at the southeastern corner was demolished at the auto repair shop identified as a non-specific commercial use. The remaining buildings along Gerry Street were demolished between 1992 and 1993. The remaining commercial building along Bartlett Street was demolished between 2007 and 2008.

The subject property is currently vacant, undeveloped, and densely overgrown with low-lying vegetation and several small trees. A small area of concrete-paving is present at the central portion, with a larger area of asphalt-pavement at the northwestern portion. The site perimeters are enclosed with chain-link fencing, except for portions of the western boundary, which are bordered by adjacent buildings. Access gates are located along Gerry Street (north) and Bartlett Street (south). Sidewalks are north, south and east of the site along Gerry Street, Throop Avenue, and Bartlett Street. Some non-hazardous debris and household trash are strewn across the site.

Based on the results of the site inspection, records review and interviews, it was determined that there was one recognized environmental condition (REC) identified for the subject property. RECs are those conditions, which could adversely affect the environmental integrity of the property. The REC is summarized below:

- Information from various historical sources indicate that the subject property (65 Bartlett Street) was utilized as an auto repair shop from at least 1965 through 1989. Given the long term use of the property as an auto repair shop, there is a potential for historic operations to have impacted soil, groundwater and/or soil vapor quality beneath the subject property.

Based on the above findings and conclusions, EBC recommends the following:

- To evaluate potential impacts related to historic usage of the subject property, a subsurface investigation should be performed. At a minimum, the investigation should include the installation of soil borings with the collection of representative samples for laboratory analysis to document subsurface conditions and determine the nature and extent of contamination (if present).

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

In addition to the aforementioned REC, no controlled recognized environmental conditions (CRECs) were identified for the subject property. However, EBC identified two historic recognized environmental conditions (HRECs) and several environmental concerns (ASTM Non-Scope issues and Business Environmental Risks [BERs]). The HREC, environmental concerns/BERs and EBC's recommendations are summarized as follows:

- The subject property (Throop Avenue and Bartlett Street) was listed on the PBS-UST database as having four 550-gallon steel underground storage tank (UST) containing an unspecified product, removed in 1994. The property was not cross-referenced on the LTANKS or NYSPILLs databases, except for two minor incidents unrelated to the USTs. Although, a copy of the tank closure report was not provided, given their closed status and the lack of a corresponding spill incident, EBC considers the site's listing on the PBS databases and the four removed USTs to be a HREC that does not warrant further investigation. A Freedom of Information Act (FOIA) request was made to the NYSDEC for additional information. A response is pending.

- The subject property was identified on the NYSPILLS database related to two minor spill incidents. The first occurred on February 3, 2005, and is related to the discovery of a buried 20-gallon drum containing an unknown oil on the property during the conduct of a Phase II investigation. The drum was removed along with 35 tons of impacted soils, and a post-excavation soil sample did not exhibit evidence of contamination. The second incident, which occurred on January 31, 1993, is related to the discovery of petroleum impacted soil during the collection of soil samples. No additional information is provided regarding this spill. Both spills were closed by the New York State Department of Environmental Conservation (NYSDEC). Given the nature of these releases and their closed status, EBC considers the closed NYSDEC spill incidents to be a HREC that does not warrant further investigation. A Freedom of Information Act (FOIA) request was made to the NYSDEC for additional information. A response is pending.

- As the majority of the subject property was formerly developed with multiple buildings, there is a potential for fill materials to be present (utilized to backfill the foundations and/or basements of the former structures following their demolition. As no information regarding the nature or source of the fill materials was available for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present on the site.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Experience with similar projects shows that typical urban fill materials (impacted or clean) that are not excavated to support construction/redevelopment activities can remain on-site, as such we do not foresee an issue related to undisturbed urban fill. However, all urban fill material that is disturbed during any construction/redevelopment project may require sampling for proper disposal and handling.

- The subject property (each of the nine parcels) is identified as having E-Air restrictions (E-238), which were determined during the Broadway Triangle Rezoning completed by the City in December 2009 (CEQR 09HPD019K). In addition, Lot No. 25 is also identified as having an E-Hazardous Materials restriction. The Hazardous Materials designation indicates that there is a potential for soil and groundwater beneath the subject property to be impacted by historic operations at the site or adjacent properties. As such, the property requires an environmental assessment and review by the New York City Office of Environmental Remediation (NYCOER) to determine if the current and/or historic use of the property has impacted the subsurface and if additional investigation/remediation is warranted. The Air E-Designation requires that any new residential and/or commercial development on Lot Nos. 27, 28 through 31, 33. 35, and 36 utilize natural gas for the heating, ventilation and air conditioning and that stacks must be 55 feet from the western lot line or utilize No. 2 fuel oil with stacks a minimum 70 feet from the western lot line to avoid any potential significant adverse air quality impacts. The HazMat and Air E-designations require the issuance of a Notice to Proceed by the NYCOER before the property can be redeveloped. The presence of E-HazMat and Air designations is considered a BER.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

1.0 INTRODUCTION

1.1 Purpose

This document is a Phase I Environmental Site Assessment (ESA) prepared to determine recognized environmental conditions (RECs) and/or potential environmental concerns (PECs) in connection with the undeveloped property located on the west site of Throop Avenue, between Gerry Street to the north, and Bartlett Street to the south, in the Broadway Triangle section of the Borough of Brooklyn, New York City, Kings County, New York (hereinafter the "subject property"). Gerry Street borders portions of the site to the north and Bartlett Street borders portions of the site to the south. The subject property is identified by the street addresses of 59-69 Bartlett Street, 84-100 Throop Avenue, and 90-100 Gerry Street, and as Borough 3 – Block 2269 – Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36 on the New York City (NYC) tax maps (**Figures 1 through 4)**. Representative site photographs are included in Appendix A.

1.2 Detailed Scope of Services

This Phase I ESA has been prepared in accordance with procedures established by environmental professionals and in concert with the guidance of regulatory agencies and funding institutions and American Society of Testing and Materials (ASTM) Practice E1527-13, inclusive of the United States Environmental Protection Agency (USEPA) "all appropriate inquiry" requirement published in the Federal Register on November 1, 2005. The USEPA "all appropriate inquiry" requirement establishes specific regulatory requirements for conducting all appropriate inquiries into the previous ownership, uses, and environmental conditions of a property for the purposes of qualifying for certain landowner liability protections under Comprehensive Environmental Response, Compensation and Liability Act (CERCLA).

The purpose of ASTM Practice E1527-13 is to define good commercial and customary practice in the United States of America for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants within the scope of CERCLA and petroleum products. As such, the practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA liability; that is, the practices that constitute "all appropriate inquiry into the previous ownership and uses

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

of the property consistent with good commercial or customary practice" as defined in 42 U.S.C. §9601 (35)(B).

As stated in ASTM Practice E1527-13, the purpose of the Phase I ESA is to identify, to the extent feasible pursuant to the process established by ASTM Practice E1527-13, *"recognized environmental conditions in connection with the subject commercial parcel."*

The term *recognized environmental conditions*, as defined by ASTM Practice E1527-13 means*"...the presence or likely presence of any hazardous substances or petroleum products in, on or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions."*

"The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be subject of an enforcement action if brought to the attention of appropriate government agencies. Conditions determined to be de minimis are not recognized environmental conditions. A material threat is a physically observable or obvious threat which is reasonably likely to lead to a release that is threatening and might result in impact to human health and the environment."

This Phase I Environmental Site Assessment, as required by ASTM Practice E1527-13, specifically consists of the following four components:

1. Records Review;
    a. Physical settings document review;
    b. Regulatory database records search;
    c. Local municipal agency records search; and
    d. Historic use records search.
2. Site Reconnaissance;
3. Interviews with Past and Present Owners and Occupants; and
4. Evaluation and Reporting.

As stated in Practice E1527-13, there may be environmental issues or conditions at the property, which may be requested by the user to be addressed as part of the Phase I ESA, which are not covered within the scope of ASTM Practice E1527-13. The issues are referred to as non-scope considerations. The following

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

is a list of non-scope considerations, which may be addressed, in a limited capacity within this Phase I Environmental Site Assessment:

- Radon;
- Lead-Based Paint;
- Asbestos-Containing Materials;
- Wetlands; and
- Mold and Water Damage.

1.3 Significant Assumptions

In preparation of the Phase I Environmental Site Assessment, it is assumed that information provided within the Environmental Database, regulatory agency records, municipal agency records, as well as information obtained from the user is accurate.

1.4 Limitations and Exceptions

The conclusions presented in this report are professional opinions based on the data described in this report. These opinions have been arrived at in accordance with currently accepted engineering and hydrogeologic standards and practices applicable to this location, and are subject to the following inherent limitations:

1. The data presented in this report are from visual inspections, examination of records in the public domain, and interviews with individuals having information about the subject property. The passage of time, manifestation of latent conditions, or occurrence of future events may require further exploration of the subject property, analysis of data, and re-evaluation of the findings, observations, and conclusions presented in this report;

2. The data reported and the findings, observations, and conclusions expressed are limited by the scope of work and defined in ASTM Practice E1527-13. Any deviations from this scope are defined below. Furthermore, the scope of work was defined and developed pursuant to the request of the Client;

3. No warranty or guarantee, whether expressed or implied, is made with respect to the data reported, findings, observations, or conclusions. These are based solely upon site conditions in existence at the time of the investigation, and other information obtained and reviewed by Environmental Business Consultants (EBC);

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

4. EBC's Phase I ESA report presents professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report will not be construed to offer legal opinion or representations as to the requirements of, or compliance with, environmental laws, rules, or regulations, or policies of federal, state, or local government agencies. EBC does not assume liability for financial or other losses or subsequent damage caused by or related to any use of this document;

5. The conclusions presented in this report are professional opinions based on data described in this report. They are intended only for the purpose, site location, and project indicated. This report is not a definitive study of contamination at the subject property and should not be interpreted as such. An evaluation of subsurface soil and groundwater conditions was not performed as part of this investigation. As at any site, the actual condition of the groundwater and sub-surface soil cannot be determined without further investigation;

6. This report is based, in part, on information supplied to EBC by third-party sources. While efforts have been made to substantiate this third-party information, EBC cannot attest to the completeness or accuracy of information provided by others; and

7. The Phase I ESA practice does not include any testing or sampling of materials (e.g., soil, water, air, building materials).

1.5 User Reliance

This report was prepared in November 2019 by EBC at the request of Mr. Charles Stewart or St. Nick's Alliance, for use by St. Nick's Alliance, their legal and consulting representatives and other agents authorized to act on their behalf, in conjunction with the sale or lease of the subject property. EBC assumes no liability for use of this report by any person or entity other than those, for which it was prepared.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

2.0 SITE DESCRIPTION

2.1 Property and Address Location

The subject property consists of nine contiguous tax parcels located on the west side of Throop Avenue, between Gerry Street to the north, and Bartlett Street to the south, in the Broadway Triangle section of the Borough of Brooklyn, New York City, Kings County, New York. The subject property is identified by the street addresses of 59-69 Bartlett Street, 84-100 Throop Avenue, and 90-100 Gerry Street (**Figures 1 through 4**).

2.1.1 Tax Map Number

The subject property is designated as Borough 3 – Block 2269 – Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36 on the NYC tax maps.

2.1.2 Acreage and Building Size

According to New York City Tax Maps, the subject property consists of nine contiguous rectangular- and irregular-shaped tax parcels, totaling 0.63-acre (27,499 square feet). The subject property is currently undeveloped, and densely overgrown with low-lying vegetation and several small trees. A small area of concrete-paving is present at the central portion, with a larger area of asphalt-pavement at the northwestern portion. The site perimeters are enclosed with chain-link fencing. Sidewalks are north, south and east of the site along Gerry Street, Throop Avenue, and Bartlett Street.

2.1.3 Ownership

According to information maintained by the New York City Department of Finance, the current property owner is identified as NYC Housing Preservation and Development (HPD).

2.1.4 Zoning

According to the City of New York Zoning Maps, the subject property is zoned for residential (R7A) use with a C2-4 commercial overlay.

2.2 Current Occupancy and Property Use

The subject property is currently vacant, undeveloped, and densely overgrown with low-lying vegetation and several small trees. A small area of concrete-paving is present at the central portion, with a larger area of asphalt-pavement at the northwestern portion. The site perimeters are enclosed with chain-link fencing,

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

except for portions of the western boundary, which are bordered by adjacent buildings. Access gates are located along Gerry Street (north) and Bartlett Street (south). Sidewalks are north, south and east of the site along Gerry Street, Throop Avenue, and Bartlett Street.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

3.0 USER PROVIDED INFORMATION

3.1 Title Records

As of the date of this report the Client did not engage EBC to perform a Chain of Title review nor was a Chain of Title provided for review.

3.2 Environmental Liens

An environmental lien is a charge, security or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup or other remediation of hazardous substances or petroleum products upon a property, including, but not limited to, liens imposed pursuant to CERCLA 42 USC § 9607 (1) & 9607(r) and similar state and local laws. The user has not made EBC aware of any environmental liens against the subject property and has not requested that EBC perform an environmental lien search for the subject property.

3.3 Specialized Knowledge

The user has not made EBC aware of any specialized knowledge regarding the chemicals or processes formerly in use at the subject or surrounding properties.

3.4 Commonly Known or Reasonably Ascertainable Information

The user has not made EBC aware of any commonly known or reasonably ascertainable information regarding the past uses of the Subject property, specific chemicals in use at the Subject property or any spills, chemical releases or environmental cleanups at the Subject property.

3.5 Valuation Reduction for Environmental Issues

The user has not made EBC aware of any valuation reduction regarding the sale price of the property.

3.6 Reason for Performing Phase I ESA

The Phase I ESA was performed to identify recognized environmental conditions at the Subject property as part of the due diligence to support the acquisition of the property by St. Nick's Alliance.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

4.0 SITE GEOLOGY AND HYDROGEOLOGY

4.1 Topography and Site Characteristics

4.1.1 Elevation

The topography of the site and surrounding area was reviewed from the United States Geological Survey (USGS) 7.5-minute series topographic map for the Brooklyn, NY Quadrangle (**Figure 4**). The elevation of the subject property is approximately 14 feet above mean sea level (amsl). The subject property is relatively flat with the general topographic gradient sloping downward to the northwest.

4.1.2 Surface Water Bodies

There are no surface water bodies on or adjacent to the subject property. The nearest natural surface water body is English Kills, located approximately 0.9 mile northeast of the subject property, at its closest point.

4.1.3 Soils

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. Soil maps, based on the State Soil Geographic (STATSGO) Database, are compiled by generalizing more detailed Soil Survey Geographic (SSURGO) database maps.

According to the STATSGO data, the soil component in the vicinity of the subject property is identified as Urban Land and is described as having a variable surface texture. The STATSGO database states that additional subordinate soil types may be present in the general vicinity of the subject property. These soil types are described as mainly loamy sand and silt loam. Deeper soil types consist of very gravelly, loamy sand, unweathered bedrock and stratified sandy loam.

Additional information regarding the soil classification is also included in on Page A-4 of the Environmental Data Resources, Inc. (EDR) database report (Appendix D).

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

4.2 Groundwater Characteristics

4.2.1 Depth to the Water and Groundwater Flow Direction

Estimated groundwater levels and flow directions may vary due to seasonal fluctuations in precipitation, local usage demands, geology, underground structures, or de-watering operations. Generally, groundwater flow typically mimics surface topography and will also tend to flow towards nearby bodies of water. Information contained in the EDR database report, the USGS Water-Table and Potentiometric-Surface Altitudes in the Upper Glacial, Magothy and Lloyd Aquifers Beneath Long Island, March-April 2013 (**Figure 6**), the USGS web site and topographic map were used to estimate groundwater depth and flow direction.

Based upon a surface elevation of 14 feet amsl, the depth to groundwater in the vicinity of the subject property is approximately 9 feet below grade surface (bgs). Groundwater is expected to flow to the north-northwest, consistent with the regional trend.

A review of well data available from the USGS indicates that the nearest USGS monitoring well with groundwater measurement data (K1237.1) is located approximately 0.6 mile northeast of the subject property. The well has an unspecified elevation of and is screened in the Upper Glacial aquifer at a depth of 63 feet below grade. A total of 239 groundwater measurements were collected from this well between January 1941 and August 1953 with groundwater elevations ranging from -36.53 to -10.35 feet amsl.

4.3 Geology

According to the USGS Ground Water Atlas of the United States, New York region (1995) and the USGS Hydrogeologic Framework of Long Island, New York, the site is situated within the Coastal Plain physiographic province. The Coastal Plain physiographic province is characterized by layers of Cretaceous age sediments (primarily clay, sand and gravel) overlying igneous and metamorphic rocks that crop out in Connecticut. The surface of these rocks slopes to the southeast, and the overlying Coastal Plain sediments slope and thicken in the same direction. Quaternary glacial deposits (primarily outwash sand and gravel) cover the Coastal Plain sediments on Long Island to depths of as much as 600 feet. In the area of the site, bedrock is present at a depth of approximately 175 feet below grade and is overlain by the Lloyd Aquifer, the Gardiners Clay and the Upper Glacial Aquifer, with the Magothy Aquifer absent from the geologic sequence. In addition, the site is located near the northern extents of the Raritan Confining Unit and Jameco Aquifer, which may also be present beneath the site (between the Lloyd Aquifer and the Gardiners Clay).

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

5.0 SITE HISTORY

5.1 Municipal Records Review

As the subject property is located in the Borough of Brooklyn, New York City, Kings County, on-line records searches were conducted or Freedom of Information Act (FOIA) requests were sent to the following agencies: New York City Department of Finance, New York City Registrar, New York City Department of Buildings, the New York City Fire Department, the New York City Department of Environmental Protection (NYCDEP), the New York City Department of Health (NYCDOH), and the New York State Department of Environmental Conservation (NYSDEC) requesting available regulatory information regarding the subject property. Regulatory agencies usually take six to eight weeks to process FOIA requests. Responses/information received to date are included in Appendix B. Any additional responses will be reviewed and forwarded upon receipt. As of the date of this report, the following information has been received:

New York City Department of Finance

The following is a summary of pertinent information obtained:

Tax Lot:	Borough 3 – Block 2269 – Lot No. 25
Address:	90 Gerry Street
Owner:	NYC HPD
Lot Size:	55 by 100 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

Tax Lot:	Borough 3 – Block 2269 – Lot No. 27
Address:	84 Throop Avenue
Owner:	NYC HPD
Lot Size:	25 by 70 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Tax Lot:	Borough 3 – Block 2269 – Lot No. 28
Address:	86 Throop Avenue
Owner:	NYC HPD
Lot Size:	25 by 70 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

Tax Lot:	Borough 3 – Block 2269 – Lot No. 29
Address:	88 Throop Avenue
Owner:	NYC HPD
Lot Size:	25 by 70 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

Tax Lot:	Borough 3 – Block 2269 – Lot No. 30
Address:	90 Throop Avenue
Owner:	NYC HPD
Lot Size:	25 by 70 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

Tax Lot:	Borough 3 – Block 2269 – Lot No. 31
Address:	92 Throop Avenue
Owner:	NYC HPD
Lot Size:	34.33 by 75 feet – irregular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

Tax Lot:	Borough 3 – Block 2269 – Lot No. 33
Address:	69 Bartlett Street
Owner:	NYC HPD
Lot Size:	50 by 65.67 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Tax Lot:	Borough 3 – Block 2269 – Lot No. 35
Address:	65 Bartlett Street
Owner:	NYC HPD
Lot Size:	25 by 54 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

Tax Lot:	Borough 3 – Block 2269 – Lot No. 36
Address:	63 Bartlett Street
Owner:	NYC HPD
Lot Size:	75 by 100 feet – rectangular
Building Class:	V1 – Vacant land, zoned commercial
Zoning:	Residential (R7A) with a C2-4 commercial overlay

New York City Department Buildings

Computerized Property Profile Overviews (PPOs) available from the New York City Department of Buildings (NYCDOB) Building Information System (BIS) website were reviewed for information regarding the subject property. Pertinent information regarding the subject property is summarized below:

Lot No. 25 – 90 Gerry Street

According to the PPO, five Actions are listed for this parcel: three alteration permits, dated in 1941 (2) and 1942; one Certificate of Occupancy (C/O), dated in 1941; and one plumbing repair slip, dated in 1957. The C/O for this parcel was not available from the BIS website.

No DOB violations and no Environmental Control Board (ECB) violations are listed for this parcel.

Two Complaints are listed for this parcel, both dated in September 1991, and are related to reports of a fire damaged building in danger of collapse. However, both Complaints are listed as closed/resolved.

Two Ten Jobs/Filings and no ARA/LAA jobs are listed for the subject property. Asummary of the Jobs/Filings is provided with the DOB records in Appendix B.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Lot No. 27 – 84 Throop Avenue

According to the PPO, 18 Actions are listed for the subject property: six alteration permits, dated in 1904, 1905, 1951 (2), 1953, and 1970; three Certificates of Occupancy (C/Os), dated in 1906, 1909, and 1910; one demolition permit, dated in 1980; two fire escape permits, dated in 1937 and 1940; one plumbing permit, dated in 1940; one unsafe building notice; dated in 1984; and two unknown/unspecified items, one undated and one dated in 1937. The C/O indicates that the parcel was developed with a 3-story mixed-use building (clothing manufacturer and apartments) with a basement (1968).

Two DOB violations and no ECB violations are listed for this parcel. The DOB violations, both dated in September 2011, are identified as closed/resolved

No Complaints, Jobs/Filings or ARA/LAA jobs are listed for this parcel

Lot No. 28 – 86 Throop Avenue

According to the PPO, six Actions are listed for this parcel: one alteration permit, dated in 1954; one building notice, dated in 1968; one demolition permit, dated in 1979; one fire escape permit, dated in 1940; one plumbing permit, dated in 1960; and one unsafe building notice, dated in 1986.

One DOB violation and no ECB violations are listed for this parcel. The DOB violation, dated in September 2011, is identified as closed/resolved.

No Complaints, Jobs/Filings or ARA/LAA jobs are listed this parcel.

Lot No. 29 – 88 Throop Avenue

According to the PPO, 11 Actions are listed for this parcel: two alteration permits, dated in 1953 and 1955; one construction permit, dated in 1962 one demolition permit, dated in 1979; one fire escape permit, dated in 1937; one oil burner application, dated in 1960; one plumbing repair slip, dated in 1968; one unsafe building notice, dated in 1988; and one unknown/unspecified item, undated.

No DOB violations, ECB violations, Complaints, Jobs/Filings or ARA/LAA jobs are listed for this parcel.

Lot No. 30 – 90 Throop Avenue

According to the PPO, 18 Actions are listed for this parcel: one alteration permit, dated in 1934; one construction permit, dated in 1968 one demolition permit, dated in 1979; one fire escape permit, dated in

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

1936; one oil burner application, dated in 1968; two plumbing repair slips, dated in 1960 and 1969; one unsafe building notice, dated in 1990; and two unknown/unspecified item, one undated and the other dated in 1937.

No DOB violations and one ECB violations are listed for this parcel. The ECB violation, dated in May 2002, is related to an unattended construction site/partially demolished structure, and is closed/resolved.

No Complaints, Jobs/Filings, or ARA/LAA jobs are listed for this parcel.

Lot No. 31 – 92 Throop Avenue

According to the PPO, 15 Actions are listed for this parcel: two alteration permits, dated in 1910 and 1966; one building notice, dated in 1904; one C/O, dated in 1908; one demolition permit, dated in 1904; two docket items, dated in 1912 and 1966; one fire escape permit, dated in 1939; one new building permit, undated; one special report, dated in 1940; two unsafe building notices, both dated in 1923 and 1927; and one unknown/unspecified item, undated. The C/O indicates that this parcel was developed with public parking lot (1969).

Two DOB violations and one ECB violation are listed for this parcel. Each of the violations is identified as closed/resolved.

No Complaints are listed for this parcel.

One Job/Filing and no ARA/LAA jobs are listed for this parcel. Asummary of the Job/Filing is provided with the DOB records in Appendix B.

Lot No. 33 – 69 Bartlett Street

According to the PPO, 34 Actions are listed for this parcel: ten alteration permits, dated in 1915 (2); 1922, 1928, 1934 (4), 1943 and 1965; one demolition permit, dated in 1989; seven elevator permits, dated in 1903, 1920 (2), 1961, 1965, 1968, and 1972; one oil burner application, dated in 1960; two new building permits, both dated in 1902; three plumbing and drainage permits, dated in 1916, 1918, and 1920; two plumbing repair slips, dated in 1901 and 1972; one sprinkler permit, dated in 1961; one special report, dated in 1955; one unsafe building notice, dated in 1980; and three unknown/unspecified items, dated in 1939, 1943, and 1961.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Twenty-four DOB violations and no ECB violations are listed for this parcel. Each of the DOB violations is identified as closed/resolved.

Two Complaints are listed for this parcel, both dated in July 1989, related to bricks falling onto adjacent buildings and yards. However, both Complaints are listed as closed/resolved.

No Jobs/Filings or ARA/LAA jobs are listed for this parcel.

Lot No. 35 – 65 Bartlett Street

According to the PPO, six Actions are listed for this parcel: one C/O, dated in 1912; one demolition permit, dated in 1965; one docket item, dated in 1909; two new building permits, dated in 1905 and 1961; and one plumbing permit, dated in 1912. The C/Os indicate that this parcel was developed with a 1-story auto and auto body repair shop (1963).

Five DOB violations and three ECB violations are listed for this parcel. Each of the violations, dated between 1990 and 2007, is identified as closed/resolved.

Four Complaints are listed for this parcel, dated between December 1989 and March 2007, and are related to failure to maintain a building, a fire damages structure, an open and unguarded building and unpermitted alterations. However, each Complaint is listed as closed/resolved.

Two Jobs/Filings and one ARA/LAA job are listed for the subject property. Asummary of the Jobs/Filings and ARA/LAA jobs are provided with the DOB records in Appendix B.

Lot No. 36 – 63 Bartlett Street

According to the PPO, 16 Actions are listed for the subject property: five alteration permits, dated in 1907, 1910, 1938, 1963, and 1987; two building notices, dated in 1959 and 1963; three demolition permits, dated in 1959 (2) and 1963; one oil burner application, dated in 1907; three new building permits, dated in 1904, 1905, and 1911; and one unsafe building notice, dated in 1959.

Thirteen DOB violations and no ECB violations are listed for this parcel. Each of the DOB violations is identified as closed/resolved.

No Complaints, Jobs/Filings, or no ARA/LAA jobs are listed for this parcel.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Copies of the DOB records are included in Appendix B.

New York City Fire Department

Freedom of Information Law (FOIL) application FOIL applications were forwarded to the New York City Fire Department (FDNY) on November 5, 2019. Responses from the FDNY are pending.

New York City Department of Health

A FOIL application was forwarded to the New York City Department of Health (NYCDOH) on November 5, 2019. A response from this agency is pending.

New York City Department of Environmental Protection

A FOIL application was forwarded to the New York City Department of Environmental Protection (NYCDEP) on November 5, 2019. A response from this agency is pending.

New York State Department of Environmental Conservation

A FOIL application was forwarded to the New York State Department of Environmental Conservation (NYSDEC) on November 5, 2019. A response from this agency is pending.

5.2 Historical Resources Review

5.2.1 Sanborn Fire Insurance Map Review

EDR conducted a search of available Sanborn Fire Insurance Maps for the subject property and immediate surrounding area. Fire Insurance Maps were provided for the years 1887, 1904, 1918, 1935, 1947, 1950, 1965, 1977, 1979, 1980, 1981, 1982, 1984, 1986, 1987, 1989, 1991, 1992, 1993, 1995, 1996, 2001, 2002, 2003, 2004, 2005, 2006 and 2007 (Appendix C). EBC's review of the Sanborn Maps is provided on the following table:

Date	Comments
1887	**Subject Property:** Shown as 12 small tax parcels fronting to the north, south and east, along Gerry Street, Bartlett Street and Throop Avenue, respectively. Each of the parcels is developed with one or more low-rise (1- to 3-story) residences or retail buildings, including a bakery at the south-central portion. Several small out buildings (stables, sheds and carriage houses) were also present. Most lots also have undeveloped rear yard areas. **Surrounding Properties:** Gerry Street is to the north, followed by dense low-rise retail and residential development, as well as a livery stable. Low-rise retail and residential development is to the west, along both Gerry and Bartlett Streets. Bartlett Street is to the south, followed by dense, low-rise retail and residential development. Throop Avenue is to the east, followed by dense, low-rise retail and residential development and a horse shoer.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

1904	**Subject Property:** Northern and eastern portions of the site have been redeveloped, with several larger 2-, 3- and 5-story retail and residential buildings, including a stable along Gerry Street, an undertaker at the northeastern corner and several multi-tenant retail stores (east and southeast), including a tailor and knitting shop. Residences along Bartlett Street, as well as a wagon shop and a tailor. **Surrounding Properties:** Shown as developed generally consistent with their 1887 map depictions, although the uses of several retail buildings have changed. The wagon house to the north is identified as closed and tin smiths are to the east and west.
1918	**Subject Property:** Developed consistent with the 1904 map depictions, except that the southwestern portions have been re-developed with two 5-story buildings, identified as retail stores. **Surrounding Properties:** Gerry Street is to the north, followed by dense low-rise retail development, with residences to the northwest. Low-rise retail and residential development is to the west, along both Gerry and Bartlett Streets. Several wagon and auto houses are further to the west. Bartlett Street is to the south, followed by a 5-story school building and two 5-story retail buildings. Throop Avenue is to the east, followed by dense, low-rise retail and residential development and a horse shoer.
1935-1950	Developed consistent with the 1918 map depictions, except that the stable building (north) has been expanded and is identified as a loft building. The undertaker is now identified as a retail store, and the building at the southeastern corner is identified as a mixed-use (retail/loft) building. The 1947 map also shows an undeveloped parcel along Bartlett Street (former 2-story retail building) and the retail building at the southeastern corner also includes a club. **Surrounding Properties:** Also developed generally consistent with their 1918 map depictions, except that a machine shop and several auto repair shops are further to the west. In addition, a service station is present across Throop Avenue to the east (NE corner of Throop Avenue and Bartlett Street). The 1947 map also shows the machine shop to the west as a plumbing store and a machinery repair warehouse is further to the west, along Gerry Street.
1965	**Subject Property:** Developed consistent with the 1950 map depiction, except that the loft building along Gerry Street (north) is identified as having a junk shop on the first floor. An undeveloped parcel is along Throop Avenue (east-central), and the undeveloped parcel along Bartlett Street has been developed with a 1-story repair shop. **Surrounding Properties:** Also developed generally consistent with their 1950 map depictions, except that an undeveloped parcel is to the west, along Gerry Street. A warehouse, parking lot and waste paper facility are further to the west. The properties across Bartlett Street to the southwest are undeveloped and likely converted to the existing NYC Park. Several warehouses are across the intersection of Throop Avenue and Bartlett Street to the southeast.
1977-1982	**Subject Property:** Developed consistent with the 1965 map depiction. The 1980 map also shows three undeveloped (former residences) lots at the east-central portion along Throop Avenue. **Surrounding Properties:** Also developed generally consistent with their 1965 map depictions, except that several undeveloped parcels and a warehouse are to the northwest. In addition, the western adjacent parcel along Gerry Street has been redeveloped with a warehouse. Several additional warehouses are noted further to the west, along Gerry and Bartlett Streets. An auto repair shop is across the intersection of Throop Avenue and Bartlett Street to the southeast. Multiple undeveloped parcels are visible across Gerry Street to the west-northwest beginning on the 1979 map. Additional undeveloped lots are visible across Gerry Street to the north and Throop Avenue to the east, beginning on the 1980 map.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

1984-1992	**Subject Property:** Developed consistent with the 1982 map depiction, except the two 5-story retail buildings (southwest) have been demolished and the lots shown as undeveloped land. The auto repair shop at the southern portion is identified as a non-specific commercial use beginning on the 1991 map. **Surrounding Properties:** Also developed generally consistent with their 1982 map depictions, except that the retail building to the west, along Bartlett Street is now identified as a non-specific commercial use. The school to the south is identified as the United Talmud Academy and the service station property across Throop Avenue is shown as undeveloped beginning on the 1986 map. The 1987 map shows an auto repair shop and industrial building across Gerry Street to the northwest and an iron works to the west, along Gerry Street. The 1989 map shows a warehouse building across Throop Avenue to the east and a lumber storage yard is across Gerry Street to the north, beginning on the 1992 map.
1993-2007	**Subject Property:** Undeveloped land, with the exception of the 1-story commercial building at the south-central portion. The structures at the northwestern portion have been demolished. **Surrounding Properties:** Developed generally consistent with their 1992 map depictions. The properties across Throop Avenue to the east are shown as having been redeveloped with the existing apartment building, playground, and parking lot beginning on the 2001 map. The lumber storage lot to the north, across Gerry Street is shown as undeveloped land beginning on the 2003 map.

The Sanborn maps did not identify the presence of gasoline or other storage tanks on the subject property. However, the maps from 1965 through 1989 show that the subject property (65 Bartlett Street) was utilized as an auto repair shop. Given the long term use of the property as an auto repair shop, there is a potential for historic operations to have impacted soil, groundwater and/or soil vapor quality beneath the subject property.

Additionally, the maps from 1887 through 2007 show that the subject property was developed with one or more commercial/retail and/or residential buildings. Following demolition, the building basements (if present) and/or foundations were backfilled to grade. Fill material may have included construction and demolition (C&D) debris associated with the building demolition and/or material from an unknown off-site source. As no documentation regarding the nature or source of the fill materials utilized to backfill the basements of the former buildings following their demolition was provided for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present on the site. The potential presence of undocumented fill material is considered a Business Environmental Risk (BER).

5.2.2 Historic Aerial Photograph Review

EDR conducted a search and provided copies of available historical aerial photographs showing the subject and surrounding properties. Aerial photographs were provided for the years 1924, 1951, 1954, 1961, 1966, 1974, 1976, 1980, 1984, 1991, 1994, 2006, 2009, 2013, and 2017 (Appendix C). However, given that the historical use of the site was established through a review of a Sanborn Maps, city directories and topographic maps, EBC determined that the historical use of the site has been properly assessed, and, therefore, the

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

historic aerials were only briefly reviewed for evidence of significant differecnces and to fill in time gaps (if any).

The photographs do not show any evidence of historic water bodies, significant re-grading, mining or historic dumping activities, which would indicate a potential environmental risk to the property. In addition, due to the long term, dense urban use of the subject property and surrounding areas, the aerial photographs did not provide significant details regarding potential environmental concerns at the site or surrounding properties.

5.2.3 Historic Topographic Map Review

EBC reviewed the 2016 Brooklyn, NY USGS topographic quadrangle maps, as well as available historic topographic quadrangle maps provided by EDR. EBC's review of the topographic maps is provided on the following table:

Date	Comments
1897-1900	**Subject Property:** Shaded black, indicating that it is developed with one or more structures, consistent with the dense low-rise retail and residential development depicted on the 1887 and 1904 Sanborn maps (see Section 5.2.1). **Surrounding Properties:** Shaded mostly black indicating they are densely developed with buildings. Narrow unshaded areas are in the center of most blocks to depict open yards. Gerry Street is adjacent to the north, Throop Avenue is adjacent to the west, and Bartlett Street is adjacent to the south. A railroad/ subway line is further to the east along Broadway.
1947	**Subject Property:** Shaded black, indicating that it is completely developed with one or more structures, consistent with the dense retail and residential development depicted on the 1947 Sanborn map. **Surrounding Properties:** Shaded mostly black indicating they are densely developed with buildings. Narrow unshaded areas are in the center of most blocks to depict open yards. A school is visible across Bartlett Street to the south, with a church further to the southeast. Gerry Street is adjacent to the north, Throop Avenue is adjacent to the west, and Bartlett Street is adjacent to the south. A railroad/ subway line is further to the east along Broadway.
1956-1995	**Subject Property:** Shaded pink to indicate dense, urban development with no improvements depicted. **Surrounding Properties:** Shaded pink to indicate dense, urban development with no improvements depicted, except for a school (PS 168) across Bartlett Street to the south. Gerry Street is adjacent to the north, Throop Avenue is adjacent to the west, and Bartlett Street is adjacent to the south. Several additional school and church buildings are further to the southeast and a subway line is along Broadway further to the east.
2013-2016	**Subject and Surrounding Properties:** The 2013 though 2016 maps do not depict any buildings or other structures. Surrounding roads are visible, consistent with their current configuration. Schools are located further to the northwest, southwest and southeast.

EBC's historic topographic map review did not reveal evidence of recognized environmental conditions in connection with the site or adjoining properties.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

5.2.4 Historical City Directory Search

EDR conducted a search and provided copies of available historical city directory listings for the subject and adjacent properties. The historical city directory listings (Appendix D) were reviewed, to identify information regarding past uses of the subject and surrounding properties to determine if historical usage represented a REC to the subject property.

Date	Comments
1928	**Subject Property:** Landesberg Engineering Co. (84); M. Friedfeld Pants, H&L Goodman, I. Heller Cigars, Rothman & Obel Pants, Slwpski Brothers & Green Pants (96); and the names of individuals **Surrounding Properties:** "Address not Listed in Research Source"
1934	**Subject Property:** Landesberg Engineering Co. (84); J. Jacobson Heating Contractor and D. Jackson Co. (92); H&L Goodmans, I. Heller Cigars. Hoffman & Friedfeld Pants, Modern Maid Frock Co., Pollack & Holtz Dress Manufacturers, L. Rothman Pants, and Saft Gutstein & Manco Dresses (96); M. Gurian Stationary (65 Bartlett); Gerry Dress Co. and Rosen Brothers News Agency (92 Gerry); and the names of individuals **Surrounding Properties:** Wellson & Carr (55 Bartlett); Wet Silver Wash Co. (89 Gerry Street); and the names of individuals
1940	**Subject Property:** M. Becker Vests, G&R Pants Corp., HL Goodman, G. Lombardo Coats, Roth Brothers Pants, and Suydam Pants (96); M. Pollinger Stationary (65 Bartlett); and the names of individuals **Surrounding Properties:** Jay Bee Grocery (82); C&K Service Station (87); Ace Plumbing Supply Co. (55 Bartlett); Empire Electric Co. and Empire Electric Motor (80 Gerry); and Eisenberg Plumbing Supply and Stagg Plumbing Supply (102 Gerry)
1945	**Subject Property:** Landesberg Engineering Co., Landesberg Sewing Machine Co., and Marland Lead Seal Co. (84); G&R Pants Corp., H. Goodman Insurance, I. Heller Cigars, Roth Brothers Pants, and Suydam Pants (96); Gerry Manufacturing Corp., Leder & Klahr Junk, and Thermo Craft Press (92 Gerry); and the names of individuals **Surrounding Properties:** C&K Service Station (87); L. Lorenz, Inc. Grinding and J. Smith & Sons Co. (80 Gerry); White Silver West Wash Co. (91 Gerry); names of individuals
1949	**Subject Property:** G. Honig Insurance, Landesberg Engineering Co., Landesberg Sewing Machine Co., and Marland Lead Seal Co. (84); H. Goodman Insurance. I. Heller Cigars, Goodman Travel Agency, and Suydam Pants Co. (96); Sunrise Sportswear (100); Arglass Handbag Co., Helene Modes, Inc., and Leder & Klahr Junk (92 Gerry); and the names of individuals **Surrounding Properties:** Jay Bee Grocery (82); C&K Service Station (87); Fertobac Fertilizer Co. and NY Tobacco Products (55 Bartlett); L. Lorenz, Inc. Grinding and J. Smith & Sons Co. (80 Gerry); and the names of individuals
1960	**Subject Property:** May Rose Garments, Suydam Pants Co., Tyrol Sportswear, and A. Valintin Stationary (96); M&G Expert Clothing Co., M&G Trading and RRR Clouse & Sportswear Co. (92 Gerry); and the names of individuals **Surrounding Properties:** Jay Bee Grocery (82); C&K Service Station (87); R&S Foods (53 Bartlett); L. Lorenz, Inc. Grinding (80 Gerry); Electrical Equipt. Co. (86 Gerry); Gerry Laundry and Prestige Linen Service (89 Gerry); Wolgro Products, Inc. (95); and the names of individuals

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

1965	**Subject Property:** Capri Knitwear (96); M&G Expert Clothing Co., M&G Trading, Libby, Inc. (92 Gerry); and the names of individuals **Surrounding Properties:** C&K Service Station (87); L. Lorenz, Inc. Grinding and J. Smith & Sons Co. (80 Gerry); Electrical Equipt. Co. (86 Gerry); Gerry Laundry and All Star Shirt Laundry, Inc. (89 Gerry); Paree Ice Cream Co. and Cofresi Sales Corp. (95 Gerry); Otero Grocery Store (102 Gerry); and the names of individuals
1970	**Subject Property:** Capri Knitwear and Tyrol Sportswear (96); Corso Brothers Auto Collision (65 Bartlett); Libby, Inc. (92 Gerry); and the names of individuals **Surrounding Properties:** Marreros Grocery (82); Johnson Folding Gates, Inc. (86); C&K Service Station (87); L. Lorenz, Inc. Grinding and J. Smith & Sons Co. (80 Gerry);Gerry Laundry and All Star Shirt Laundry, Inc. (89 Gerry); Paree Ice Cream Co. and Cofresi Sales Corp. (95 Gerry); United Oil Belting Co. (97 Gerry); and the names of individuals
1973	**Subject Property:** Capri Knitwear and Tyrol Sportswear (96); Libby, Inc. (92 Gerry); and the names of individuals **Surrounding Properties:** Marreros Grocery (82); Johnson Folding Gates, Inc. (86); C&K Service Station (87); L. Lorenz, Inc. Grinding and J. Smith & Sons Co. (80 Gerry); Globe Prince Machinery Movers (88 Gerry); C&C Coat Apron, Towel & Linen Supply (91 Gerry), United Oil Belting Co. (97 Gerry); Maurano Rooerto Dram Studio (102 Gerry); and the names of individuals
1976	**Subject Property:** Marrero's Grocery Store (84); Capri Knitwear and Tyrol Sportswear (96); Libby, Inc. (92 Gerry); and the names of individuals **Surrounding Properties:** C&K Service Station (87); L. Lorenz, Inc. Grinding and J. Smith & Sons Co. (80 Gerry); and McKibb Star Economy Development and McKibbs Star Shop (102 Gerry)
1980	**Subject Property:** Nu Creative Tones Co., Inc. (90 Gerry) and the names of individuals **Surrounding Properties:** J. Smith & Sons Co. (80 Gerry)
1985	**Subject Property:** United Talmudical Academy (94); A. Williams Trucking & Trenching (65 Bartlett); and Nu Creative Tones Co., Inc. (90 Gerry) **Surrounding Properties:** L. Lorenz, Inc. Grinding and J. Smith & Sons Co. (80 Gerry); Marine Service Equipment Corp. (88 Gerry); 76 Throop Body & Fender Specialists (97 Gerry); and the names of individuals
1992	**Subject Property:** United Talmudical Academy (94) and A. Williams Trucking & Trenching (65 Bartlett) **Surrounding Properties:** Excellent Bus Service (55 Bartlett); NY Shanghai Stove, Inc. (80 Gerry); Marine Service Equipment Corp. (88 Gerry Street); 76 Throop Body & Fender Specialists (97 Gerry); Magic Sales, Inc. (102 Gerry); and the names of individuals
1997	**Subject Property:** A. Williams Trucking & Trenching (65 Bartlett) **Surrounding Properties:** Excellent Bus Service (55 Bartlett) and the names of individuals
2000	**Subject Property:** A. Williams Trucking & Trenching (65 Bartlett) **Surrounding Properties:** Excellent Bus Service (55 Bartlett) and Garcia Auto Repair (97 Gerry)
2005	**Subject Property:** "Address not Listed in Research Source" **Surrounding Properties:** Excellent Bus Service (55 Bartlett); Garcia Auto Repair (97 Gerry); and the names of individuals
2010	**Subject Property:** "Address not Listed in Research Source" **Surrounding Properties:** Floral Expressions USA, Inc. (51 Bartlett); Excellent Bus Service (55 Bartlett); and M&Z Sheet Metal Corp. (95 Gerry); and Professional Help and GIH Knitwear (97 Gerry)
2014	**Subject Property:** "Address not Listed in Research Source" **Surrounding Properties:** Floral Expressions USA, Inc. (51 Bartlett); Excellent Bus Service (55 Bartlett); Yukimi Song Studio LLC (57 Bartlett); M&Z Sheet Metal Corp. (95 Gerry); and Professional Help and GIH Knitwear (97 Gerry)

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Note: Addresses shown in ( ) are on Throop Avenue unless noted otherwise.

EBC's city directory review did not reveal evidence of recognized environmental conditions in connection with the subject property. EBC notes that the subject and nearby properties were identified as various commercial/retail, industrial and/or residential uses since 1934, including several manufacturing facilities, auto repair shops, and service stations. Given the time of operation for these facilities and their potential prior use, the area cannot be confirmed of having no subsurface impacts; however, no specific operation or activity was noted that warrants additional investigation at this time. EBC notes that several of the adjacent/surrounding properties were listed on various regulatory databases indicating hazardous waste generation, petroleum storage and/or petroleum releases; however, these listings are further discussed in Section 6, and determined unlikely to present a significant environmental concern to the subject property.

5.2.5 Previous Environmental Site Assessments

No previous ESAs or information regarding previous environmental investigations/reports for the subject property were provided to EBC for review by the property owner or their representatives.

5.2.6 Environmental Liens or Activity and Use Limitations

A search was conducted for Activity and Use Limitations (AULs) associated with the subject property, more specifically Institutional Controls (ICs) and/or Engineering Controls (ECs), which have been placed upon the property as a result of environmental issues identified at the property. In the City of New York, information on such AULs is maintained by the City of New York Department of City Planning (NYCDCP) and is commonly depicted on zoning maps with an "E" designation, as well as maintained within Chain of Title Records. For a site to be designated with an "E" restriction, several criteria must be met. First, a property must be included within a designated re-zoning area, then the property must be identified as a "Potential" or "Projected" re-development property, and finally, the site must be listed on one or more environmental regulatory databases as listed in the ASTM standard, be adjacent to such a site, and/or have historical usage associated with hazardous materials with the potential to impact human health and/or the environment should a release have occurred. Sites with an "E" designation require additional investigation and/or remediation be performed in order to determine if the historical use of a property, typically manufacturing or chemical usage, have impacted the site. No change of use or development requiring a building permit will be issued for an "E" designated site without approval from the New York City Office of Environmental Remediation (NYCOER). The subject property was identified with an "E" designation, which is further discussed in Section 6.2 of this report.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

The search for environmental liens and AULs also included a review of information available from the New York City Department of Finance, New York City DOB, the EDR database report, City of New York Environmental Quality Review Requirement Declarations, City of New York Zoning maps, and the NYCDCP and NYCOER websites.

The City of New York Environmental Quality Review (CEQR) Requirement Declarations and City of New York Zoning maps and website, as well as the EDR database report, indicate that the subject property (each of the nine parcels) is identified as having E-Air restrictions (E-238), which were determined during the Broadway Triangle Rezoning completed by the City in December 2009 (CEQR 09HPD019K). In addition, Lot No. 25 is also identified as having an E-Hazardous Materials restriction. The Hazardous Materials designation indicates that there is a potential for soil and groundwater beneath the Site to be impacted by historic operations at the Site or adjacent properties. As such, the property requires an environmental assessment and review by the NYCOER to determine if the current and/or historic use of the property has impacted the subsurface and if additional investigation/remediation is warranted. The Air E-Designation requires that any new residential and/or commercial development on Lot Nos. 27, 28 through 31, 33, 35, and 36 utilize natural gas for the heating, ventilation and air conditioning and that stacks must be 55 feet from the western lot line or utilize No. 2 fuel oil with stacks a minimum 70 feet from the western lot line to avoid any potential significant adverse air quality impacts.

The HazMat and Air E-designations require the issuance of a Notice to Proceed by the NYCOER before the property can be redeveloped. The presence of the E-Designation is considered a Business Environmental Risk (BER).

5.3 Summary of Site History

EBC was able to establish a history for the property dating back to 1887. According to a review of NYC records, Sanborn maps, aerial photographs, historic city directories, and historic topographic maps, as well as personal interviews, the subject property was developed with approximately 16 small low-rise 1- to 3-story retail and residential buildings, as well as several small outbuildings, by at least 1887. By 1904, a larger 2-story stable building is present along Gerry Street and a 5-story multi-tenant retail building, including a tailor and knitting shop was present at the corner of Throop Avenue and Bartlett Street. By 1918, the properties along Throop Avenue were redeveloped with multiple 3-story buildings, including an undertaker, residences and retail stores. In addition, the properties along Bartlett Street at the southwestern portion were developed with two 5-story retail buildings. By 193, the undertakers is identified as a retail store and the stable along Gerry Street and the retail building at the southeastern corner are identified as loft buildings. An undeveloped

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

parcel is present at 65 Bartlett Street by 1947 and the building at the corner of Bartlett Street and Throop Avenue is partially occupied by a club. By 1965, the vacant lot along Bartlett Street has been developed with an auto repair shop and an undeveloped lot is visible along Throop Avenue (92-94 Throop Avenue). Three additional parcels along Throop Avenue (86, 88 and 90 Throop Avenue) are shown as undeveloped by 1980, with the northeastern most parcel shown as undeveloped by 1981. The two southwestern parcels (59 and 63 Bartlett Street) are undeveloped by 1986. Between 1989 and 1991, the building at the southeastern corner was demolished at the auto repair shop identified as a non-specific commercial use. The remaining buildings along Gerry Street were demolished between 1992 and 1993. The remaining commercial building along Bartlett Street was demolished between 2007 and 2008.

The subject property is currently vacant, undeveloped, and densely overgrown with low-lying vegetation and several small trees. A small area of concrete-paving is present at the central portion, with a larger area of asphalt-pavement at the northwestern portion. The site perimeters are enclosed with chain-link fencing, except for portions of the western boundary, which are bordered by adjacent buildings. Access gates are located along Gerry Street (north) and Bartlett Street (south). Sidewalks are north, south and east of the site along Gerry Street, Throop Avenue, and Bartlett Street. Some non-hazardous debris and household trash are strewn across the site.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

6.0 REGULATORY AGENCY DATABASE SEARCH

EDR was retained to provide a computerized database search of the project area within an ASTM-standard radius of the subject property. A list of the databases searched and the search radius is shown on the summary table below. EBC reviewed the database output to determine if the property appears on any of the regulatory agency lists.

6.1 Federal Databases

Listing Name or Database Searched	Abbreviation	Search Distance	Subject property Listed?	No. of Sites within the Search Radius
National Priorities List Sites, including Proposed and Delisted Sites	NPL	1.0 mile	No	0 NPL 0 Proposed 0 Delisted
Superfund Enterprise Management System (SEMS) and SEMS Archive Sites	SEMS and SEMS-ARCHIVE	0.5 mile	No	0 SEMS 3 SEMS-ARCHIVE
Corrective Action Reports	CORRACTS	1.0 mile	No	2
Federal Facility Site Information	FFSI	1.0 mile	No	0
Resource Conservation and Recovery Act - Treatment, Storage and Disposal Facilities	RCRA-TSD	0.5 mile	No	0
Resource Conservation and Recovery Act – Active and Former Hazardous Waste Generators	RCRA SQG/LQG/VSQG/ NonGen	Site & Adjoining	No	0 LQG 0 SQG 0 VSQG 0 NonGen
Land Use Control Information System	LUCIS	0.5 mile	No	0
Engineering Control Sites	USEC	Site	No	NA
Institutional Control Sites	USIC	Site	No	NA
Emergency Response Notification System	ERNS	Site	No	NA
Federal Brownfields Sites	US Brownfields	0.5 mile	No	0

In addition to the federal databases included on the table above, over 30 additional federal databases were searched to determine if the subject and/or surrounding properties were listed. The subject property was not

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

listed on the additional federal databases included in the EDR search report and no adjacent or surrounding listings were identified with the potential to represent an environmental concern to the subject property.

The database search generated information on the following listings for the surrounding properties within ASTM radius guidelines that could potentially impact the subject property:

Superfund Enterprise Management System Archive (SEMS Archive): SEMS Archive (formally known as CERCLIS-NFRAP) listings are for properties removed from the SEMS list following an initial investigation because either no contamination was found or contamination was not serious enough to warrant Superfund Action or NPL consideration. Three SEMS Archive listing was identified within a one-half mile radius of the subject property. These listings are summarized as follows:

- Borden Chemicals & Adhesives, 56 Nostrand Avenue, approximately 2,320 feet southwest and hydraulically crossgradient of the subject property. The USEPA completed a Preliminary Assessment and inspection of this facility in October 1980 and the site was subsequently archived. The Borden site is also listed on the RCRA-NonGen, FINDS, and ECHO databases.

- Brooklyn Scrap Metal, 171 Cook Street, approximately 1,340 feet east and hydraulically crossgradient of the subject property. The USEPA completed a Removal Assessment of this facility in January 2015, and the facility was subsequently archived. Brooklyn Scrap Metal Co. was also identified on the Lead Smelters databases.

  JB Slattery & Brothers, Inc., 171-187 Wallabout Street, approximately 1,900 feet west-southwest and hydraulically downgradient of the subject property. The USEPA completed a removal action at this site in November 1991 and the site was subsequently archived. The Slattery facility also listed on the RCRA-NonGen PRP, ICIS, FINDS, ECHO, and NYMANIFEST databases.

Based on the information in the database report, their distance and the presumed hydraulic gradient, it is unlikely that these facilities represent a significant environmental concern to the subject property.

Federal RCRA CORRACTS: CORRACTS identify hazardous waste handlers with RCRA corrective action activity. Two CORRACTS facilities were identified within a one-mile radius of the subject property. These facilities are summarized below:

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

- Pfizer, 13 Bartlett Street, approximately 490 feet southwest and hydraulically crossgradient of the subject property. The database indicates that a RCRA Facility Assessment for the site was completed in September 1992 and the site was assigned a medium corrective action priority. Six RCRA violations are listed for the site, each of which is listed as closed/resolved. The Pfizer, Inc. site is also listed on the RCRA-LQG, RATTS, FINDS and ECHO databases.

- Toldos Yehuda LLC, 8 Walworth Street, approximately 2,670 feet west-southwest and hydraulically crossgradient of the subject property. The database indicates that a RCRA Facility Assessment for this site was completed in November 1985 and the site was assigned a medium correction action priority. Fourteen RCRA violations are listed for the site, each of which is listed as closed/resolved. The Toldos Yehuda LLC site is also listed on the NY Brownfields, RCRA-LQG, and MANIFEST databases.

6.2 State Databases

Listing Name or Database Searched	Abbreviation	Search Distance	Subject property Listed?	No. of Sites within the Search Radius
Inactive Hazardous Waste Disposal Sites, including De-listed Sites	SHWS	1.0 mile	No	7 SHWS 0 Delisted SHWS
Vapor Intrusion Legacy Site List	VAPOR	1.0 mile	No	0
Hazardous Substance Waste Disposal Site	HSWDS	0.5 mile	No	1
Solid Waste Facilities/Landfill Sites	SWF/LF	0.5 mile	No	2
Registered Recycling Facility List	SWRCY	0.5 mile	No	0
Registered Waste Tire Storage Facility List	SWTIRE	0.5 mile	No	0
Leaking Underground Storage Tanks	LTANKS	0.5 mile	No	33 LTANKS
Petroleum Bulk Storage - Underground and Aboveground Storage Tank Databases	PBS UST/AST	Site & Adjoining	**Yes**	0 UST 0 AST
Chemical Bulk Storage - Underground and Aboveground Storage Tank Databases	CBS UST/AST	0.25 mile	No	1
Major Oil Storage Facility - Underground and Aboveground Storage Tank Databases	MOSF UST/AST	Site & Adjoining	No	0
Registry of Engineering Controls	NYEC	Site	No	NA
Registry of Institutional Controls	NYEC	Site	No	NA
Voluntary Cleanup Agreements	VCP	0.5 mile	No	42
State Brownfields Site List	Brownfields	0.5 mile	No	8
E-Designation Site List	E-Des	0.125 mile	**Yes**	89

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Spills Information Database	NYSPILLS	0.125 mile	**Yes**	37
Registered Drycleaning Facilities	DRYCLEANERS	0.25 mile	No	3

The subject property is listed on the, PBS-UST, E-DES and NYSPILLS databases. These listings summarized as follows:

Petroleum Bulk Storage – Tank Facility Listings (TANKS) and Underground and Aboveground Storage Tank Databases (PBS-UST/AST): The inclusion on the PBS-UST/AST list means that a site has one or more registered underground/aboveground storage tank(s), regulated under regulated under 6 NYCRR Part 612 (NYSDEC Petroleum Bulk Storage) and/or the New York City Fire Department (FDNY). This database does not indicate leaks, spills, or other violations.

- HPD Property (PBS ID No. 2-601810), Throop Avenue and Bartlett Street. This facility is listed as having four 550-gallon steel UST containing an unspecified product, removed in 1994. The property was not cross-referenced on the LTANKS or NYSPILLs databases, except for a spill related to a buried drum, and there is no evidence to suggest that this listing represents a significant environmental concern to the subject property (see Section 7.7.3). Although, a copy of the tank closure report was not provided, the thanks are identified as closed/removed and there is no corresponding spill incident. As such, EBC considers the site's listing on the PBS database and the four removed USTs to be a HREC that does not warrant further investigation. A Freedom of Information Act (FOIA) request was made to the NYSDEC for additional information. A response is pending.

NYCDCP Environmental Designation Sites (E-DES): The subject property (each of the nine parcels) is identified as having E-Air restrictions (E-238), which were determined during the Broadway Triangle Rezoning completed by the City in December 2009 (CEQR 09HPD019K). In addition, Lot No. 25 is also identified as having an E-Hazardous Materials restriction. The Hazardous Materials designation indicates that there is a potential for soil and groundwater beneath the Site to be impacted by historic operations at the Site or adjacent properties. As such, the property requires an environmental assessment and review by the NYCOER to determine if the current and/or historic use of the property has impacted the subsurface and if additional investigation/remediation is warranted. The Air E-Designation requires that any new residential and/or commercial development on Lot Nos. 27, 28 through 31, 33, 35, and 36 utilize natural gas for the heating, ventilation and air conditioning and that stacks must be 55 feet from the western lot line or utilize

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

No. 2 fuel oil with stacks a minimum 70 feet from the western lot line to avoid any potential significant adverse air quality impacts.

The HazMat and Air E-designations require the issuance of a Notice to Proceed by the NYCOER before the property can be redeveloped. The presence of the E-Designation is considered a BER.

New York Spills (NYSPILLS) database: The subject property (90-92 Gerry Street) is listed on the NYSPILLS database related to one closed spill incident, which is summarized as follows:

- Spill No. 04-11773 – On Ground, 90-92 Gerry Street. This spill, which occurred on February 3, 2005, is related to the discovery of a buried 20-gallon drum containing an unknown oil on the property during the conduct of a Phase II investigation. The drum was removed along with 35 tons of impacted soils, and a post-excavation soil sample did not exhibit evidence of contamination. The NYSDEC closed the spill on June 26, 2008. Based upon this information, EBC considers the closed NYSDEC spill incident to be a HREC that does not warrant further investigation. A FOIA request was made to the NYSDEC for additional information. A response is pending.

One additional closed spill listed in the database report, appears to also be attributable to the subject property. This incident is summarized as follows:

- Spill No. 92-12706 – NYCHPD/Broadway Triangle, Corner of Throop Avenue and Bartlett Street, adjacent to the east, and hydraulically cross- to upgradient of the subject property. This spill, which occurred on January 31, 1993, is related to the discovery of petroleum impacted soil during the collection of soil samples. No additional information is provided in the database report; however, the spill was closed by the NYSDEC on June 28, 1999. Given the nature of the release and its closed status, EBC considers the closed NYSDEC spill incidents to be a HREC that does not warrant further investigation. A FOIA request was made to the NYSDEC for additional information. A response is pending.

In addition to the New York State (NYS) databases included on the table above, over, ten additional NYS databases were searched to determine if the subject and/or surrounding properties were listed. The subject property was not listed on the additional State databases included in the EDR search report and no adjacent or surrounding listings were identified with the potential to represent an environmental concern to the subject property.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

The database search generated information on the following listings for the surrounding properties within ASTM radius guidelines that could potentially impact the subject property:

State Inactive Hazardous Waste Sites (SHWS): SHWS records are New York State's equivalent to the CERCLIS. These properties may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. These records come from the New York State Department of Environmental Conservation (NYSDEC).

Two SHWS listings were identified within a one-quarter mile radius of the site, and they are summarized as follows:

- Top Hat Cleaners (ID No. 224208), 152 Graham Avenue, approximately 1,960 feet north-northeast and hydraulically cross- to downgradient of the subject property. This facility is a mixed-use (retail/residential) building occupied by a dry cleaner. An investigation conducted at the site identified the presence of chlorinated solvent impacts to soil, soil vapor and groundwater which appear attributable to the dry cleaner. Investigation of this facility is ongoing. Based on the information in the database report, its distance in a dense urban area, the presumed hydraulic gradient, and that the site and surrounding utilize municipally-supplied potable water, it is unlikely that this facility presents a significant environmental risk to the site.

- Former Techtronic Ecological Corporation Site B (ID No. 224259), 480 Flushing Avenue, approximately 2,630 feet west-southwest and hydraulically crossgradient of the subject property. This facility is a former paint and lacquer manufacturer and an auto body repair shop and cyanides were discovered at the site. Limited investigation conducted at this facility to date has revealed VOC and SVOC impacts to soil, groundwater and soil vapor. Investigation is on-going under the NYS Brownfields Cleanup Program. Based on the information in the database report, its distance in a dense urban area, the presumed hydraulic gradient, and that the site and surrounding utilize municipally-supplied potable water, it is unlikely that this facility presents a significant environmental risk to the site.

Five additional SWHS listings were identified between one-half and one-mile from the subject property; however, based upon their distances in a dense urban area, the presumed hydraulic gradient, and/or that the site and surrounding area is supplied potable water from a municipal source, it is unlikely that these facilities represent a significant environmental concern to the subject property.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Hazardous Substance Waste Disposal Sites (HSWDS): The Hazardous Substance Waste Disposal Sites (HSWDS) list includes any known or suspected hazardous substance waste disposal sites. Also included are sites de-listed from the Registry of Inactive Hazardous Waste Disposal Sites list and non-Registry sites that USEPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared.

One HSWDS site was identified within a one-half mile radius of the subject property. This listing is summarized as follows:

- Borden Chemical, 56 Nostrand Avenue, approximately 2,320 feet southwest and hydraulically crossgradient of the subject property. This facility was detailed previously in the SEMS ARCHIVE section, where it was determined unlikely to represent a significant environmental concern to the subject property.

Solid Waste Facilities/Landfill Sites (SWF/LF): This database is an inventory of soil waste disposal facilities or landfills in New York State. Two SWF/LF listings were identified within a one-quarter mile radius of the subject property. These listings are summarized as follows:

- Cooper Tank & Welding, 222-226 Seigel Avenue, approximately 1,800 feet east-northeast and hydraulically crossgradient of the subject property. This facility is identified as an inactive transfer station with no violations.

- Bedford Auto Sales, 984 Myrtle Avenue, approximately 2,280 feet south-southeast and hydraulically cross- to upgradient of the subject property. This facility is identified as an active vehicle dismantling facility, with no violations.

Based on the information provided in the database report, their distance and/or the presumed hydraulic gradient, these facilities are unlikely to represent a significant environmental concern to the subject property.

Leaking Underground Storage Tanks (LTANKS): Each of the 33 LTANKS sites listed in the database were issued letters of no further action by the NYSDEC, and there is no reported evidence in the database search which suggests that these sites are a significant environmental concern to the subject property. In addition, none of the listed closed LTANKS sites is located adjacent to the subject property.

State Chemical Bulk Storage Sites (CBS): The inclusion of a facility on the CBS list means that a site has one or more registered storage tanks, regulated under 6NYCRR Part 595 - 599 (NYSDEC Chemical Bulk

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Storage) and has a total storage capacity equal to or greater than 185 gallons. This database does not indicate leaks, spills, or other violations. One CBS facility (Pfizer, Inc. - Brooklyn, 630 Flushing Avenue) was identified within a one-quarter mile radius of the subject property. The Pfizer facility was identified as having 23 ASTs that were closed or converted to a non-regulated use. This address was cross referenced on the NYSPILLS databases related to several closed petroleum spill incidents. Based on this information, the closed status of the spills, it distance and the presumed hydraulic gradient, it is unlikely that the listed CBS facility represents a significant environmental concern to the subject property.

Voluntary Cleanup Program (VCP) Sites: VCP sites are those facilities where the property owner has to investigate and remediate the site. New York's VCP is a cooperative program for lenders, developers and prospective purchasers to investigate and/or remediate contaminated sites and return them to productive use. Under the VCP, a volunteer performs remedial activities pursuant to one or more NYSDEC approved work plans and agrees to remediate the site to a level that is protective of public health and the environment for the present or intended use of the property. Investigation and remediation is carried out under oversight of the NYSDEC and the New York State Department of Health (NYSDOH) and the volunteer pays the State's oversight costs. When the volunteer completes work, a release from liability from the Department is provided with standard reservations.

Eighteen VCP sites were identified within a one-eighth mile radius of the subject property. These sites are summarized as follows:

- 11 Whipple Street (ID No. 17CVCP011K), 11 Whipple Street, approximately 3000 feet east-south, and hydraulically cross- to upgradient of the subject property. Information obtained from the NYCOER website indicates that this site was redeveloped with a 7-story residential building. Impacted soil/fill materials were excavated and removed from the site and a vapor barrier was installed below the new building. Remedial activities are complete and the issuance of a Certificate of Completion is pending. Based on this information, its distance and/or the presumed hydraulic gradient, it is unlikely that this facility represents a significant environmental concern to the subject property.

- 687 Flushing Avenue (ID No. 18CVCP024K), 687 Flushing Avenue, approximately 410 feet south-southeast, and hydraulically cross- to upgradient of the subject property. Information obtained from the NYCOER website indicates that this site is developed with a 2-story mixed-use building and parking lot, and it is proposed to be redeveloped with a new 13-story mixed-use building with a

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

basement. Impacted soil/fill materials were identified at the site to depths of 8 feet. Minor groundwater and soil vapor impacts were also identified. The proposed remedial activities include excavation of impacted soil/fill and the installation of a vapor barrier. Based on this information, its distance and/or the presumed hydraulic gradient, it is unlikely that this facility represents a significant environmental concern to the subject property.

The 16 remaining VCP sites (82 Throop Avenue, 390 Wallabout Street, 386-388 Wallabout Street, 59-71 Gerry Street, 78 Throop Avenue, 72 Throop Avenue, 376-382 Wallabout Street, 299-301 Wallabout Street, 311-313 Wallabout Street, 661 Flushing Avenue, 207 Harrison Avenue, 177 Harrison Avenue, 116 Walton Street, 52-56 Throop Avenue, 88 Walton Street, and 630 Flushing Avenue) are each located hydraulically crossgradient or downgradient, and as such, it is unlikely that these facilities represent a significant environmental concern to the subject property.

Twenty-four additional VCP listings were identified between one-quarter and one-half mile from the subject property; however, based upon their distances in a dense urban area, the presumed hydraulic gradient, and/or that the site and surrounding area is supplied potable water from a municipal source, it is unlikely that these facilities represent a significant environmental concern to the subject property.

New York State Brownfields Sites (BROWNFIELDS): In New York State, a Brownfields site is any real property in the State, whose redevelopment or reuse may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant, except those properties which are listed as Class 1 or 2 in the Registry of Inactive Hazardous Waste Disposal Sites (Class 2 sites owned by a Volunteer are eligible until July, 1, 2005); sites on the USEPA NPL; hazardous waste treatment, storage, or disposal facilities (TSDFs) permitted under ECL §27-0901 ("interim status" facilities are eligible); sites subject to a cleanup order or Stipulation under Article 12 of the Navigation Law (oil spill prevention, control, and compensation) or under Title 10 of ECL Article 17 (control of the bulk storage of petroleum); or sites subject to any on-going state or federal enforcement actions regarding solid/hazardous waste or petroleum.

One BROWNFIELDS site was identified within a one-eighth mile radius of the subject property. This listing is summarized as follows:

- Pfizer Site B (ID No. C224101), 59-71 and 73-87 Gerry Street, approximately 300 feet to the northwest, across Gerry Street, and hydraulically downgradient of the subject property. This site was historically occupied by a pharmaceuticals company, and is currently undeveloped. Preliminary

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

investigations identified and delineated petroleum-impacted fill materials on and off-site. Approximately 4,700 tones of impacted soils and 18,000 gallons of groundwater were removed in 2002, along with nine USTs and other subsurface structures. A groundwater contaminant plume extends north from this property. Soil vapor investigation is on-going. Based on the information in the database report, its regulatory status, its distance, and the presumed hydraulic gradient, this facility is unlikely to represent a significant environmental concern to the subject property.

Seven additional BROWNFIELDS listings were identified between one-eighth and one-half mile from the subject property; however, based on the information in the database report, their distance in a dense urban area, the presumed hydraulic gradient, and/or that the subject property and surrounding area utilize municipally-supplied potable water, it is unlikely that this facility presents a significant environmental concern to the subject property.

NYCDCP Environmental Designation Sites (E-DES): Environmental "E" designation sites are those sites identified by the NYC Department of City Planning (DCP), which need to be evaluated to address potential issues related to hazardous materials, air quality and/or noise. This designation is typically associated with areas NYC has designated for re-development and/or re-zoning, and ensure that sampling and remediation (if warranted) or other measures implemented at the property if demolition, excavation and construction are proposed to be conducted.

Three types of E-DES listings (HazMat, Air and Noise) exist, although a property can be assigned multiple designations based on known or potential risks to redevelopment. However, only those with a HazMat designation are considered to present a concern based on their historic use/development (i.e., service station, dry cleaner, manufacturing facility, etc.). The HazMat designation indicates that projected and potential development of these sites requires an environmental assessment and review by the NYC Office of Environmental Remediation (NYCOER) to determine if the current and/or historic use of a property has impacted the subsurface and if additional investigation/remediation is warranted.

Eighty-seven E-DES listings were identified within a one-eighth mile of the subject property, three of which (Block 2269, Lot No. 39, Block 2266, Lot No. 36, and Block 2266, Lot No. 36) are adjacent to the subject property. Two of these three facilities are identified as HazMat, and/or Air and Noise sites and are included in the same designation area (E-238 – Broadway Triangle Rezoning) as the subject property. The Hazardous Materials Designation indicates that projected and potential development of this property requires the completion of an environmental assessment and review by the NYCOER to determine if the current and/or

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

historic use of the property impacted the subsurface and if additional investigation and/or remediation is warranted. This designation does not indicate the presence of contamination, nor does it indicate the presence/potential presence of offsite impacts. Therefore, there is no information in the database report that indicates the E-DES listings represent a significant environmental concern to the site.

Registered Drycleaning Facilities (DRYCLEANERS): Three DRYCLEANERS sites (Lotus Cleaners, 80 Manhattan Avenue; Joyful/A&K Good Neighbor Cleaners, 789 Flushing Avenue; and Harrison/Yorktown/Ace Rapid Cleaners, 209 Harrison Avenue) were listed within a one-quarter mile radius of the subject property. Each of these three facilities was cross-referenced on the RCRA database as current or former hazardous waste generators with no open/active violations. Based on the information listed in the database report, their distance, the absence of open/active violations, and the presumed hydraulic gradient, it is unlikely that the listed DRYCLEANERS sites represent a significant environmental concern to the subject property.

New York Spills Information Database (NYSPILLS): Thirty-four of the 37 NYSPILLS sites listed in the database were issued letters of no further action by the NYSDEC, and there is no reported evidence in the database search which suggests that these sites are a significant environmental concern to the subject property. Two of the listed closed NYSPILLS sites are located adjacent to the subject property, and they are summarized as follows:

- Spill No. 13-11882 – Drum Run, 57 Bartlett Street, adjacent to the west and hydraulically crossgradient of the subject property. This spill, which occurred on March 20, 2014, is related to the discovery of two abandoned 55-gallon drums containing an oil/water/soil mixture soil. The drums were removed by a NYSDEC contractor. No release occurred and the spill was closed by the NYSDEC on May 13, 2014.

- Spill No. 10-00520 – Drum Run, Corner of Throop Avenue and Bartlett Street, adjacent to the east, and hydraulically cross- to upgradient of the subject property. This spill, which occurred on April 13, 2010, is related to the discovery of three abandoned 55-gallon drums containing waste oil. The drums were removed by a NYSDEC contractor. No release occurred and the spill was closed by the NYSDEC on May 5, 2010.

A review of the information provided regarding the three remaining active NYSPILLS listings (58 Gerry Street LLC, 58 Gerry Street; Amoco, 655 Flushing Avenue; and Citgo, 594 Broadway), including the nature

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

of the release, its distance and the presumed hydraulic gradient, indicate that this spill is unlikely to represent an environmental concern to the subject property.

6.3 Tribal Records and EDR Proprietary Databases

Listing Name or Database Searched	Abbreviation	Search Distance	Subject property Listed?	No. of Sites within the Search Radius
Indian Reservations	IRESERVE	1.0 mile	No	0
Indian Reservation - Leaking Underground Storage Tanks	ILTANKS	0.5 mile	No	0
Indian Reservation - Registered Underground Storage Tanks	IUST	0.25 mile	No	0
Indian Reservation – Voluntary Cleanup Program Sites	IVCP	0.5 mile	No	0
Indian Reservation – Open Dump Inventory Sites	IODI	0.25 mile	No	0
Manufactured Gas Plants	MGP	1.0 mile	No	5
Historic Cleaners	HISTCL	Site & Adjoining	No	0
Historic Auto Stations	HISTAS	Site & Adjoining	No	1

The database search generated information on the following listings for the surrounding properties within ASTM radius guidelines that could potentially impact the site:

Manufactured Gas Plants (MGPs)

One Manufactured Gas Plant (MGP) site (Skillman Station, Skillman Street between Flushing and Bedford Avenues; Nassau Gas, Skillman Avenue; Rutledge Station, Rutledge Street between Wythe and Kent Avenues; Scholes Street Station, Scholes and Bogart Streets; and Keap Street Station, Keap Street between Wythe and Kent Avenues) is listed in the database report. MGPs were industrial facilities at which gas was produced from coal, oil and other feedstocks. The gas was stored, and then piped to the surrounding area, where it was used for lighting, cooking, and heating homes and businesses. The first MGPs were constructed in the early 1800s, prior to the Civil War. Most were closed during the early-to-middle 1900s, and the last one ceased operations in 1972. The production of manufactured gas created wastes including coal tar and purifier waste (lime or wood chips treated with iron oxides, and used to remove cyanide and sulfur from the manufactured gas). These materials were often disposed of on the site resulting in soil and groundwater contamination. Given that the listed MGP facility is each over one-half mile and hydraulically cross- to

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

downgradient, it is unlikely that this facility represents a significant environmental concern to the subject property.

Historical Auto Stations Database (HISTAS): The HISTAS database provides information compiled by EDR from multiple sources that identify potential sites historically occupied by gas station/filling station/service station sites. Five HISTCL facilities are listed in the database report, one of which (Russ Louis, 81-87 Throop Avenue) is located adjacent to the subject property. Limited information was provided in the database report for this facility, except that it reportedly operated as a service station from at least 1969 through 1975. This facility was not cross-referenced on the PBS, LTANKS, and NYSPILLS databases related to petroleum storage or documented spills. As such, there is no information in the database report to indicate that this facility is likely to represent a significant environmental concern to the subject property.

6.4 Orphan Site Summary

The database report also includes 11 "orphan" sites, which are those properties where due to poor or inadequate address information the location of the property cannot be determined sufficiently for it to be included on the radius map. However, sites with similar street names or zip codes are summarized in the database report as these sites may present environmental risks to the subject property. EBC reviewed additional information available from EDR regarding this site, as well as available USEPA and NYS data and maps to determine if the orphan site presents a significant environmental risk to the subject property. The listed Orphan sites do not appear to represent an environmental concern to the subject property.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

7.0 SITE RECONNAISSANCE

7.1 Site Inspection

EBC representative Keith Butler inspected the subject property on October 10, 2019. No representatives of NYC HPD, the property owner, were present during the site inspection, however, EBC personnel did contact Mr. Charles Stewart, who arranged permission and for EBC to access the site.

7.2 Methodology and Limiting Conditions

Site reconnaissance included a visual inspection of exterior areas, sidewalk areas immediately adjoining the property, and the exteriors of adjacent properties. Due to the presence of dense overgrown vegetation visibility was limited in some areas of the site.

7.3 Site Description

The subject property consists of nine contiguous tax parcels located on the west side of Throop Avenue, between Gerry Street to the north, and Bartlett Street to the south, in the Broadway Triangle section of the Borough of Brooklyn, New York City, Kings County, New York. The subject property is identified by the street addresses of 59-69 Bartlett Street, 84-100 Throop Avenue, and 90-100 Gerry Street), and as Borough 3 – Block 2269 – Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36 on the NYC tax maps.

The subject property is currently vacant, undeveloped, and densely overgrown with low-lying vegetation and several small trees. A small area of concrete-paving is present at the central portion, with a larger area of asphalt-pavement at the northwestern portion. The site perimeters are enclosed with chain-link fencing, except for portions of the western boundary, which are bordered by adjacent buildings. Access gates are located along Gerry Street (north) and Bartlett Street (south). Sidewalks are north, south and east of the site along Gerry Street, Throop Avenue, and Bartlett Street. Some non-hazardous debris and household trash are strewn across the site.

7.4 Utilities

As the site is currently undeveloped, no utilities are directly provided to the property. The following table provides a list of utilities that are reportedly available in the site vicinity and the names of the suppliers:

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Utility	Provider
Domestic Water	New York City Department of Environmental Protection (NYCDEP)
Sanitary Sewer	NYCDEP
Storm Sewer	NYCDEP
Electricity	Con Edison
Natural Gas	Con Edison

7.5 Surrounding Land Use

The subject property is located in a densely developed, mixed-use urban area of Brooklyn, known as Broadway Triangle. The following surrounding land uses were observed during the Phase I ESA site inspection:

North: A Gerry Street, followed by a 4-story residential apartment building (82 Throop Avenue) and an undeveloped lot (99 Gerry Street), with a additional apartment buildings beyond.

South: Bartlett Street, followed by the Beth Rachel School (102 Bartlett Street) and a NYC Park, with Whipple Street beyond.

East: Throop Avenue, followed by a 6-story residential apartment building and associated parking lots (106 Gerry Street), with a mixed-use building beyond.

West: A 3-story residential building (57 Bartlett Street) and a 1-story industrial building (88 Gerry Street), followed by a 1-story industrial building and several undeveloped parcels, with a stove company, residential and mixed-use buildings and undeveloped land beyond.

7.6 Interviews

Mr. Charles Stewart of St. Nick's Alliance, authorized site access, but was not present during the site inspection. Mr. Stewart also provided a brief site history and general site information. Pertinent statements made by Mr. Stewart are included throughout this report.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

7.7 Summary of Environmental Site Features

7.7.1 Chemical Use and Storage

No hazardous substances or activities involving the use of any chemicals were observed onsite during the survey. In addition, the regulatory records review and interviews did not reveal evidence of operations involving the use of hazardous substances or petroleum products at the subject property.

7.7.2 Hazardous and Non-Hazardous Waste Storage and Disposal

No evidence that regulated hazardous materials and/or hazardous wastes are generated, treated, stored or disposed of at the site was observed on the date of the survey. In addition, the regulatory records review and interviews did not reveal evidence of any activities involving the production of hazardous wastes at the site.

As the property is vacant/undeveloped, no significant quantities of solid wastes are currently generated at the site. No RECs, associated with solid waste generation, storage, and disposal were identified at the subject property during the reconnaissance.

7.7.3 Underground and Aboveground Storage Tanks

No evidence of underground storage tanks (i.e. vent or fill pipes) were observed on the property at the time of the site inspection. The EDR database report did not identify any registered petroleum or chemical ASTs or USTs for the site, and there are no known spills/releases attributed to the property.

Additional information may be available in files maintained by the FDNY, NYCDEP and/or NYCOER, however, no responses to EBC's FOIL requests have been received to date. Any information received from these agencies will be reviewed upon receipt and pertinent information forwarded to the client.

7.7.4 Sanitary and Stormwater Disposal

As there are no on-site buildings, no sanitary wastewater is currently discharged from the property. The area surrounding the property is serviced by the NYC municipal sewer system.

Storm water flows overland to adjacent properties, to curbside drains along Gerry Street, Throop Avenue and Bartlett Street, and infiltrates to the ground in unpaved areas. Curbside drains discharge to the NYC municipal storm sewer system.

7.7.5 Polychlorinated Biphenyls

Polychlorinated biphenyls (PCBs) were used until 1978 and are a group of compounds formed by the chlorination of biphenyl. PCBs have extremely high physical and chemical stabilities which led to their being

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

used in many applications, including heat transfer fluids, hydraulic fluids, and dielectrics. PCBs are often found in transformers, capacitors and hydraulic systems.

Electrical equipment containing PCBs are still in use and can pose a serious health hazard if fluids come in direct contact with humans, soil or groundwater. Fires involving electrical equipment containing PCBs can cause the material to be dispersed over a large area and potentially expose many people to a health risk. Because of the health hazard associated with PCBs, they are regulated under the Toxic Substances Control Act (TSCA).

No electrical transformers, hydraulic automotive lifts, elevators or other equipment suspected to contain PCBs were identified on the property at the time of the site inspection. In addition, because there are no buildings on the property, fluorescent light ballasts are not an environmental concern.

7.7.6 Debris, Dumping and Surficial Staining

No evidence of chemical spills, stains or odors was observed on the property at the time of the site inspection. Based on the review of historical and regulatory records, no evidence of landfills, and/or direct burial activities was observed on or proximate to the site. However, as the property was formerly developed with multiple buildings, there is a potential for fill materials to be present (utilized to backfill the foundation and/or basement of the former structures following their demolition. As no information regarding the nature or source of the fill materials was available for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present on the site. The potential presence of fill materials is considered a BER.

7.7.7 Stressed Vegetation

No stressed vegetation was present at the time of inspection.

7.7.8 Other Environmental Concerns

EBC also inspected the subject property for evidence of the following potential environmental concerns:

OTHER AREAS OF CONCERN		
Area of Concern	**Not Observed**	**Observed**
Chemical/Petroleum Odors	X	
Pools of Liquid	X	
Stains or Corrosion	X	
Unidentified Containers	X	
Pits, Ponds, or Lagoons	X	

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

OTHER AREAS OF CONCERN		
Area of Concern	**Not Observed**	**Observed**
Monitoring or Other Wells		X
Stained Soil or Pavement	X	
Air Quality	X	
Stressed Vegetation	X	

Monitoring or Other Wells

The site inspection identified a groundwater monitoring well in the sidewalk area along Throop Avenue, adjacent to the east of the subject property. No information regarding this well was provided for review; however, its location is generally consistent with USGS monitoring well K3483.1, which is part of the regional groundwater elevation network.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

8.0 NON-SCOPE CONSIDERATIONS

8.1 Radon

Radon is a colorless, radioactive, inert gas formed by the decay of radium and may be present in soils and rocks containing granite, shale, phosphate and pitchblende. The USEPA's Map of Radon Zones for New York State, September 1993, indicates that the Brooklyn area is not a radon risk area. The EDR report provides information from the New York State Department of Health (NYSDOH) radon survey which indicates that 51 radon tests have been conducted in Kings County. Test results indicate average radon concentrations of 0.75 pCi/L (first floor level) and 1.37 pCi/L (basements). Data indicate that approximately two percent of basements tested showed results in excess of the 4.0 pCi/L USEPA action level.

Additional data (October 2018) obtained from the NYSDOH indicates that 474 basement radon tests have been conducted in Kings County, with average radon basement concentration of 2.13 pCi/L. Based on these data, radon is not likely to represent an environmental concern for the site.

8.2 Lead-Based Paint

In 1978, the U.S. Product Safety Commission issued a ban on paints or surface coatings that contain greater than 0.06 percent lead. A visual inspection of painted surfaces was conducted during the site inspection. As no buildings or other structures, except for perimeter fencing, lead-based paint (LBP) is not considered an environmental concern.

8.3 Asbestos-Containing Materials

Asbestos is the name given to a group of fibrous silicate minerals, typically those of the serpentine group. The tensile strength, flexibility, and non-flammability of asbestos have led to many uses including structural materials, brake linings, insulation, and pipe manufacture. Asbestos is of concern as an air pollutant because when inhaled it may cause asbestosis, mesothelioma, and bronchogenic carcinoma. In 1989, the USEPA announced regulations that would phase out most uses of asbestos by 1996.

As part of the site inspection, a visual survey was conducted of accessible areas for the presence of suspect asbestos-containing materials (ACM). No suspected ACM were observed during the site inspection and no sampling for asbestos was conducted in conjunction with this Phase I ESA.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

Thermal insulation, surfacing materials, and vinyl/asphalt floor materials installed before 1981 are presumed to contain asbestos. The Occupational Safety and Health Administration (OSHA) asbestos standards (effective October 1995) require owners of commercial or industrial buildings (constructed before 1981) to identify potential asbestos hazards, keep records about potential asbestos hazards, post signs to warn of asbestos hazards, and communicate information about the hazards.

8.4 Wetlands

A review of the NYSDEC Freshwater Wetland Map, Brooklyn, NY Quadrangle, indicates that there are no NYS freshwater wetlands located within a one mile radius of the subject property. ECB also reviewed NYSDEC Tidal Wetlands Maps available online at https://www.dec.ny.gov/lands/4940.html. The tidal wetlands map indicates that there are no NYS tidal wetlands located within a one-mile radius of the subject properties.

Potential federal wetlands were identified from the U.S. Fish and Wildlife Service (FWS) Wetlands Mapper software, which indicates that that no potential federal wetlands are located within a one mile radius of the subject property. Additional information obtained from the FWS website is included in Appendix E.

Federal Emergency Management Agency (FEMA) Flood Insurance Rate Maps (FIRMs) were reviewed to determine if the subject property is located within the 100-year or 500-year flood zones. The FIRMs showing the property (No. 3604970204F) indicates that entire property is located outside the 100-year and 500-year flood zones. This indicates that there is a minimal risk of flooding at the subject property.

8.5 Mold and Water Damage

Concern about indoor exposure to mold has been increasing as the public becomes aware that exposure to mold can cause a variety of health effects and symptoms, including allergic reactions. Molds can be found almost anywhere; they can grow on virtually any organic substance, as long as moisture and oxygen are present. There are molds that can grow on wood, paper, carpet, foods, sheetrock, plaster and insulation. When excessive moisture accumulates in buildings or on building materials, mold growth will often occur, particularly if the moisture problem remains undiscovered or unaddressed.

As part of this assessment, a visual inspection was conducted for the presence of water damage and odors, indicative of the potential for mold growth. No visual or olfactory evidence of mold was identified at the subject property during the site inspection.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

8.6 Vapor Encroachment

As part of this assessment, EBC evaluated the potential for vapor encroachment into onsite structures following the general methodology outlined in ASTM E-2600-10 utilizing professional judgment. The Tier 1 screening assessment was employed to determine if a potential vapor encroachment condition (VEC) exists at the site. The site, adjoining properties and hydraulically upgradient properties were assessed for known or suspected contaminated facilities within approximate minimum search distances. A Tier 1 screening assessment generally consists of the following: a search distance test to identify if there are any known or suspected contaminated sites within the area of concern (AOC); a chemicals of concern (COC) test to determine if chemicals of concern exist at the known or suspected contaminated facilities and a plume test to determine whether or not COC in the contaminated plume may be within the critical distance (or AOC). The critical distance is defined as the linear distance in any direction from the nearest edge of the plume to the site. If the critical distance from the site to the nearest edge of a petroleum hydrocarbon plume is within 528 feet (1/10-mile) or within 1,760 feet (1/3-mile) for nonpetroleum COC (e.g., trichloroethylene, perchloroethylene, etc.), then it is assumed that COC are within the AOC and a potential VEC exists, and additional screening may be necessary. The critical distance and AOC may be modified using professional judgment based on hydraulic gradient direction and contaminant plume width.

The decision to recommend additional screening, even if a potential VEC is determined by distance, is based on other criteria including existing and planned use of the property, type of structures potentially impacted, physical setting, hydraulic gradient, depth to groundwater, soil characteristics, activities in the surrounding area and the presence of natural or manmade conduits. Based on an evaluation of this collective criteria, the potential for a VEC from current and surrounding land use activities is considered low due to the available documentation which suggests no significant visual or olfactory evidence of petroleum hydrocarbon or VOC contamination that has migrated to the groundwater or which has significantly impacted the soil from current and surrounding activities at the site. A Tier 2 screen is not recommended at this time.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

9.0 CONCLUSIONS AND RECOMMENDATIONS

This Phase I ESA has been prepared in conformance with the scope and limitations of ASTM Practice E1527-13 (inclusive of the USEPA all appropriate inquiry requirements) for the undeveloped property located on the west site of Throop Avenue, between Gerry Street to the north, and Bartlett Street to the south, in the Broadway Triangle section of the Borough of Brooklyn, New York City, Kings County, New York. Gerry Street borders portions of the site to the north and Bartlett Street borders portions of the site to the south. The subject property is identified by the street addresses of 59-69 Bartlett Street, 84-100 Throop Avenue, and 90-100 Gerry Street, and as Borough 3 – Block 2269 – Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36 on the NYC tax maps. Any exceptions to, or deletions from, this practice are described in the section of the report entitled Limitations and Exceptions.

Based on the results of the site inspection, records review and interviews, it was determined that there was one recognized environmental condition (REC) identified for the subject property. RECs are those conditions, which could adversely affect the environmental integrity of the property. The REC is summarized below:

- Information from various historical sources indicate that the subject property (65 Bartlett Street) was utilized as an auto repair shop from at least 1965 through 1989. Given the long term use of the property as an auto repair shop, there is a potential for historic operations to have impacted soil, groundwater and/or soil vapor quality beneath the subject property.

Based on the above findings and conclusions, EBC recommends the following:

- To evaluate potential impacts related to historic usage of the subject property, a subsurface investigation should be performed. At a minimum, the investigation should include the installation of soil borings with the collection of representative samples for laboratory analysis to document subsurface conditions and determine the nature and extent of contamination (if present).

In addition to the aforementioned REC, no controlled recognized environmental conditions (CRECs) were identified for the subject property. However, EBC identified two HRECs and several environmental concerns

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

(ASTM Non-Scope issues and BERs). The HREC, environmental concerns/BERs and EBC's recommendations are summarized as follows:

- The subject property (Throop Avenue and Bartlett Street) was listed on the PBS-UST database as having four 550-gallon steel UST containing an unspecified product, removed in 1994. The property was not cross-referenced on the LTANKS or NYSPILLs databases, except for two minor incidents unrelated to the USTs. Although, a copy of the tank closure report was not provided, given their closed status and the lack of a corresponding spill incident, EBC considers the site's listing on the PBS databases and the four removed USTs to be a HREC that does not warrant further investigation. A FOIA request was made to the NYSDEC for additional information. A response is pending.

- The subject property was identified on the NYSPILLS database related to two minor spill incidents. The first occurred on February 3, 2005, and is related to the discovery of a buried 20-gallon drum containing an unknown oil on the property during the conduct of a Phase II investigation. The drum was removed along with 35 tons of impacted soils, and a post-excavation soil sample did not exhibit evidence of contamination. The second incident, which occurred on January 31, 1993, is related to the discovery of petroleum impacted soil during the collection of soil samples. No additional information is provided regarding this spill. Both spills were closed by the NYSDEC. Given the nature of these releases and their closed status, EBC considers the closed NYSDEC spill incidents to be a HREC that does not warrant further investigation. A FOIA request was made to the NYSDEC for additional information. A response is pending.

- As the majority of the subject property was formerly developed with multiple buildings, there is a potential for fill materials to be present (utilized to backfill the foundations and/or basements of the former structures following their demolition. As no information regarding the nature or source of the fill materials was available for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present on the site.

  Experience with similar projects shows that typical urban fill materials (impacted or clean) that are not excavated to support construction/redevelopment activities can remain on-site, as such we do not foresee an issue related to undisturbed urban fill. However, all urban fill material that is disturbed during any construction/redevelopment project may require sampling for proper disposal and handling.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

- The subject property (each of the nine parcels) is identified as having E-Air restrictions (E-238), which were determined during the Broadway Triangle Rezoning completed by the City in December 2009 (CEQR 09HPD019K). In addition, Lot No. 25 is also identified as having an E-Hazardous Materials restriction. The Hazardous Materials designation indicates that there is a potential for soil and groundwater beneath the subject property to be impacted by historic operations at the site or adjacent properties. As such, the property requires an environmental assessment and review by the NYCOER to determine if the current and/or historic use of the property has impacted the subsurface and if additional investigation/remediation is warranted. The Air E-Designation requires that any new residential and/or commercial development on Lot Nos. 27, 28 through 31, 33. 35, and 36 utilize natural gas for the heating, ventilation and air conditioning and that stacks must be 55 feet from the western lot line or utilize No. 2 fuel oil with stacks a minimum 70 feet from the western lot line to avoid any potential significant adverse air quality impacts. The HazMat and Air E-designations require the issuance of a Notice to Proceed by the NYCOER before the property can be redeveloped. The presence of E-HazMat and Air designations is considered a BER.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

10.0 ENVIRONMENTAL PROFESSIONAL STATEMENT

This Phase I ESA has been prepared in accordance with procedures established by environmental professionals and in concert with the guidance of regulatory agencies and funding institutions, ASTM Practice E1527-13, inclusive of the USEPA "All Appropriate Inquiry" requirement published in the Federal Register on November 1, 2005. The USEPA "All Appropriate Inquiry" requirement establishes specific regulatory requirements for conducting all appropriate inquiries into the previous ownership, uses, and environmental conditions of a property for the purposes of qualifying for certain landowner liability protections under CERCLA.

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in § 312.10 part of 40 CFR 312. I have the specific qualifications based on education, training and experience to assess a property of the nature, history and setting of the site referenced above. EBC has developed and performed the "All Appropriate Inquiries" in conformance with the standards and practices set forth in 40 CFR Part 312.

Section 11.0 contains the data gaps and deficiencies of the research data encountered during EBC's preparation of this report.

Reviewed by: 

Keith Butler
Senior Project Manager

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

11.0 REFERENCES

Environmental Data Resources, Inc. regulatory database report (No. 5823513.9s), October 10, 2019.

Environmental Data Resources, Inc. Aerial Photograph (5823513.22), October 2019.

Environmental Data Resources, Inc. City Directory Search (5823513.12), October 2019.

Environmental Data Resources, Inc. Sanborn Map Report (5823513.10), October 2019.

Environmental Data Resources, Inc. Topographic Map Search (5823513.18), October 2019.

National Priorities List Sites: New York. USEPA, 2018 on-line update.

New York City Tax Assessor, records review – October 2019.

New York City Department of Health, Freedom of Information request forwarded October 2019.

New York City Fire Department, Freedom of Information request forwarded October 2019.

New York City Department of Environmental Protection, Freedom of Information request forwarded October 2019.

New York City Office of Environmental Remediation, Freedom of Information request forwarded October 2019.

New York City Building Department, records on-line review October 2019.

U.S.G.S. Topographic Map, Brooklyn, NY Quadrangle.

U.S. Department of the Interior, Fish and Wildlife Service. National Wetlands Inventory Maps.

United States Department of Agriculture, Web Soil Survey.

Federal Emergency Management Agency (FEMA) Flood Zone Map Panel No. 3604970204F.

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
1808 Middle Country Road
Ridge, NY 11961
Phone 631.504.6000
Fax 631.924.2870

QUALIFICATIONS OF

ENVIRONMENTAL PROFESSIONAL

EBC

ENVIRONMENTAL BUSINESS CONSULTANTS

Keith W. Butler, Senior Project Manager

PROFILE

Mr. Butler has extensive project management experience with respect to environmental due diligence and subsurface investigations. He is responsible for the preparation of project proposals, Phase I and II Environmental Site Assessments, Work Plans, Health and Safety Plans, Quality Assurance Project Plans, and investigation reports. Additionally, Mr. Butler has conducted and managed numerous Phase I and II ESAs. In these roles, Mr. Butler is responsible for applying the various state and local regulations, which govern environmental compliance and determine the need for additional investigation and/or remediation.

SELECTED PROJECTS

Madison National Bank, Various Sites, New York

Mr. Butler served as the Project Manager and principal contact for Madison National Bank. He was responsible for the preparation of Transaction Screen and Phase I/II Environmental Site Assessments (ESAs) at various sites throughout the New York metropolitan area, as required by the bank to satisfy client mortgage or construction loan requests.

Jewish Home & Hospital, Manhattan, NY

Most recently, Mr. Butler completed a Phase I ESA at their Bronx campus to obtain US. Housing and Urban Development (HUD) funding for a future construction project. Mr. Butler was also responsible for implementing a Remedial Action Work (RAW) Plan at the Bronx facility as required by the NYSDEC under a Voluntary Cleanup Agreement. The RAW included the preparation of contract documents, excavation of over 2,000 tons petroleum contaminated soils, installation of a Soil Vapor Extraction (SVE) system remedial oversight, and sampling.

Pulte Homes of New York, Patchogue, NY

Mr. Butler served as the Project Manager for the re-development of this six-acre site and was responsible for field oversight and coordination between remediation contractors and various regulatory agencies. Initial phases of the project included the completion of Phase I and II ESAs. Subsequent remediation consisted of UST removal, excavation of petroleum-impacted soils, closure of three NYSDEC spill numbers, removal of contaminated UIC sediment/sludge, the closure of commercial and residential UIC structures and the excavation of arsenic and metals contaminated soil. The project was conducted under approved Remedial Work and Soil Management Plans with oversight from the State, County and Village agencies.

Town of Islip, Blydenburgh Road Landfill, Hauppauge, NY

Mr. Butler served as the Project Manager for the groundwater and leachate monitoring program at the Blydenburgh Road Landfill - Cleanfills 1 and 2 and Leachate Impoundment Area. Mr. Butler was the principal contact for the Town's Resource Recovery Agency. He prepared the quarterly and annual monitoring reports, oversaw sampling efforts, and coordinated with the Town's analytical laboratory and data validation contractors. Mr. Butler was also responsible for preparing quarterly well condition reports and leachate quality reports for compliance with the Town's Suffolk County Discharge Certification Permit.

Ogden Aviation, Various Sites, JFK International Airport, Jamaica, New York

Mr. Butler served as the project manager for the rehabilitation of the satellite fuel farm recovery well system. Recovery wells at the fuel farm had become clogged with iron deposits and bacteria limiting product recovery efforts. Mr. Butler developed and supervised chemical cleaning and redevelopment of recovery wells under the approval of the NYSDEC. The chemical treatment has resulted in significant increases in product recovery volumes.

Brookhaven National Laboratory, Upton, NY

Mr. Butler has worked on a number of remediation system and monitoring well installation projects at BNL. His duties included oversight of installations, system pump tests, performance evaluations, and well development. He also provided oversight of soil borings, temporary well construction, soil and water sampling, and air monitoring for groundwater screening survey of two operable units in hazardous and radioactive waste storage areas. Mr. Butler also provided oversight for groundwater monitoring, well construction, well abandonment, and methane-monitoring wells for landfill closure.

metroPCS, Various Sites, New York

Mr. Butler served as the Project Manager for metroPCS' Long Island region telecommunications site acquisition and expansion program. Mr. Butler was responsible for the preparation of Phase I ESAs, the conduct of Phase II ESAs, including asbestos, lead paint and soil sampling, and coordination of National Environmental Policy Act (NEPA) reports and planning studies at various locations proposed for construction of new cellular telephone facilities. Reports and associated communications were transmitted electronically through metroPCS' data management system.

Dormitory Authority - State of New York, Harlem Hospital Center Modernization Project - Hazardous and Universal Waste Survey, Harlem Hospital, New York, NY

Mr. Butler served as the field team leader for conducting hazardous and universal waste surveys in multiple buildings affiliated with Harlem Hospital Center. The survey included the identification of hazardous and universal waste materials including chemicals, paints, fluorescent bulbs, high intensity discharge bulbs/fixtures, battery operated equipment, above and underground petroleum storage tank identification, PCB containing light ballasts and electrical equipment.

Keith W. Butler, Senior Project Manager

The hospital is comprised of a number of buildings, many that were abandoned and slated for demolition.

SVE Monitoring at Newark International Airport, Elizabeth, NJ
A routine leak detection test indicated that two 10,000-gallon underground storage tanks, which were used to store unleaded gasoline, had failed tightness tests. Follow-up investigation revealed that the product had impacted the subsurface environment. In response to this, a soil vapor extraction system was installed to reduce the residual concentrations of petroleum constituents in soil and groundwater and to minimize vapor migration into subsurface utility vaults. Mr. Butler was responsible for implementing the Remedial Action Work Plan, developed for the site by Ogden and the State of New Jersey. Activities conducted under the RAW include quarterly groundwater monitoring, air sampling, vacuum pressure monitoring, system maintenance and reporting.

Federal Express Site, Newark International Airport, Elizabeth, NJ
Mr. Butler worked with Ogden Aviation and the State of New Jersey to address outstanding environmental issues at the site related to a spill of jet fuel, which occurred during a construction accident. Mr. Butler performed a site assessment, which included groundwater monitoring, product gauging, and groundwater flow modeling. After reviewing these data, Mr. Butler determined that fill material at the site was contributing to soil and groundwater contamination and has petitioned the State for partial site closure. Mr. Butler is continuing to address the remaining area of concern through product recovery and continued monitoring.

Northrop Grumman, Various Sites
Mr. Butler conducted three Phase I ESAs and a Phase II investigation for the presence of PCBs in soil. He also inspected and supervised the removal of underground storage tanks, asbestos abatement projects, and sanitary system closures related to the facility decommissioning. Mr. Butler also conducted groundwater investigations and provided oversight during soil sampling, drilling and soil remediation activities.

New York City Department of Environmental Protection, Various Sites
Mr. Butler served as an Environmental Scientist for hazard investigation at seven sewage pump stations. Mr. Butler addressed a wide range of environmental concerns including asbestos, lead based paints, PCB oil, light ballasts, and other hazardous building materials. He conducted field investigations, sampling, and prepared Hazardous Materials Survey Reports for use during preparation of plans and specifications for proposed pump station construction projects.

Fresh Kills Landfill, Staten Island, New York
Mr. Butler participated in the field operations during pump and yield tests conducted on Cells 1 and 9. The tests were performed to determine the hydraulic properties of the landfill's refuse. He collected groundwater and leachate measurements in recovery wells and in adjacent observation wells under pumping and non-pumping conditions.

PREVIOUS EXPERIENCE

DECA Real Estate Advisors
Director of Environmental Services, 2011-2017

VHB Engineering, Surveying and Landscape Architecture PC, Hauppague NY
Senior Project Manager, 2005-2011

Parsons Brinkerhoff, Inc. New York NY
Senior Project Manager, 2004-2005

P.W. Grosser Consulting, Bohemia, NY
Senior Project Manager, 1998-2004

Eder Associates, Locust Valley, NY
Field Hydrogeologist, 1992-1998

EDUCATION

BS, Geology, Slippery Rock University of Pennsylvania, 1990

PROFESSIONAL REGISTRATIONS/CERTIFICATIONS

OSHA Certification, 40-hour Health & Safety Training at Hazardous Waste Sites

OSHA Certification, 8-hour Refresher Health & Safety Training at Hazardous Waste Sites

OSHA Confined Space Entry Training

FIGURES



FIGURE 1 – SITE LOCATION MAP

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631.924.2870

SITE NAME: Broadway Triangle Site C
STREET ADDRESS: 59-69 Bartlett Street, 84-100 Throop Avenue and 90-100 Gerry Street
MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11206

Source: USGS



FIGURE 2 – LOT DIAGRAM

N

SITE NAME: Broadway Triangle Site C
STREET ADDRESS: 59-69 Bartlett Street, 84-100 Throop Avenue and 90-100 Gerry Street
MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11206

Source: NYC Oasis Map

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631.924.2870

FIGURE 3 – TAX MAP

N

SITE NAME: Broadway Triangle Site C
STREET ADDRESS: 59-69 Bartlett Street, 84-100 Throop Avenue and 90-100 Gerry Street
MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11206

Source: New York City Department of Finance

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631.924.2870

FIGURE 4 – SITE AERIAL

N

SITE NAME: Broadway Triangle Site C
STREET ADDRESS: 59-69 Bartlett Street, 84-100 Throop Avenue and 90-100 Gerry Street
MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11206

Source: Google Earth

EBC
Environmental Business Consultants
Phone 631.504.6000
Fax 631.924.2870



FIGURE 5A – ZONING MAP

N

SITE NAME: Broadway Triangle Site C
STREET ADDRESS: 59-69 Bartlett Street, 84-100 Throop Avenue and 90-100 Gerry Street
MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11206

Source: New York City Department of City Planning

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631.924.2870



FIGURE 5B – HISTORIC ZONING MAP

N

SITE NAME: Broadway Triangle Site C
STREET ADDRESS: 59-69 Bartlett Street, 84-100 Throop Avenue and 90-100 Gerry Street
MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11206

Source: New York City Department of City Planning - 1961

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631.924.2870



FIGURE 6 – GROUNDWATER FLOW MAP

N

SITE NAME: Broadway Triangle Site C
STREET ADDRESS: 59-69 Bartlett Street, 84-100 Throop Avenue and 90-100 Gerry Street
MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11206

Source: New York City Department of Finance

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS
Phone 631.504.6000
Fax 631.924.2870

APPENDIX A

REPRESENTATIVE SITE PHOTOGRAPHS

View of the subject property, looking west-northwest from Bartlett Street.

View of the subject property, looking north along Throop Avenue.

View of the subject property, looking west along Gerry Street.

View of the northern adjacent property, looking north across Gerry Street.

View of the southern adjacent property, southeast across Bartlett Street.

View of the eastern adjacent property, looking east across Throop Avenue.

View of the western adjacent property, looking south from GerryStreet.

View of the western adjacent property, looking north from Bartlett Street.

View showing the western portions of the subject property, looking north,

View showing the eastern portions of the subject property, looking north.

View of the subject property, looking east toward Throop Avenue.

View of subject property, looking northwest.

View of the concrete paved area at the central portion of the subject property.

View of the asphalt-paved area at the northwestern portion of the subject property.

View of non-hazardous household debris at the southern portion on the property, along Bartlett Street.

View of the monitoring well in the sidewalk area east of the subject property, along Throop Avenue.

APPENDIX B

LOCAL GOVERNMENT CORRESPONDENCE

90 GERRY STREET

Borough: BROOKLYN
Block: 2269 Lot: 25

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	NYC HPD
Property Address	90 GERRY STREET 11206
Billing Name and Address	NYC HPD 100 GOLD ST. LBBY 3 NEW YORK NY 10038-1619
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

NYC HPD

Land Information

Lot Size	
Frontage (feet)	55.00
Depth (feet)	100.00
Land Area (sqft)	5,500
Regular / Irregular	Regular
Corner	
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	273,000	273,000
MARKET AV	122,850	122,850
MARKET EX		122,850
TRANS AV	147,259	147,259
TRANS EX		147,259

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	147,259

Market Value History

Tax Year	Market Value
2019 - 2020	273,000
2018 - 2019	328,000
2017 - 2018	409,536
2016 - 2017	341,280
2015 - 2016	284,400

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

84 THROOP AVENUE

Borough: BROOKLYN
Block: 2269 Lot: 27

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	HOUSING PRESERVATION & DEVELOPMENT
Property Address	84 THROOP AVENUE 11206
Billing Name and Address	OWNER/AGENT
	BAD LOCATION ADDRESS
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

HOUSING PRESERVATION & DEVELOPMENT

Land Information

Lot Size	
Frontage (feet)	25.00
Depth (feet)	70.00
Land Area (sqft)	1,750
Regular / Irregular	Regular
Corner	SW
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	182,000	182,000
MARKET AV	81,900	81,900
MARKET EX		81,900
TRANS AV	60,464	60,464
TRANS EX		60,464

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	60,464

Market Value History

Tax Year	Market Value
2019 - 2020	182,000
2018 - 2019	171,000
2017 - 2018	126,144
2016 - 2017	105,120
2015 - 2016	87,600

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

THROOP AVENUE

Borough: BROOKLYN
Block: 2269 Lot: 28

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	HOUSING PRESERVATION & DEVELOPMENT
Property Address	THROOP AVENUE 11206
Billing Name and Address	OWNER/AGENT
	BAD LOCATION ADDRESS
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

HOUSING PRESERVATION & DEVELOPMENT

Land Information

Lot Size	
Frontage (feet)	25.00
Depth (feet)	70.00
Land Area (sqft)	1,750
Regular / Irregular	Regular
Corner	
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	156,000	156,000
MARKET AV	70,200	70,200
MARKET EX		70,200
TRANS AV	56,754	56,754
TRANS EX		56,754

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	56,754

Market Value History

Tax Year	Market Value
2019 - 2020	156,000
2018 - 2019	147,000
2017 - 2018	129,600
2016 - 2017	108,000
2015 - 2016	90,000

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

88 THROOP AVENUE

Borough: BROOKLYN
Block: 2269 Lot: 29

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	HOUSING PRESERVATION & DEVELOPMENT
Property Address	88 THROOP AVENUE 11206
Billing Name and Address	OWNER/AGENT
	BAD LOCATION ADDRESS
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

HOUSING PRESERVATION & DEVELOPMENT

Land Information

Lot Size	
Frontage (feet)	25.00
Depth (feet)	70.00
Land Area (sqft)	1,750
Regular / Irregular	Regular
Corner	
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	156,000	156,000
MARKET AV	70,200	70,200
MARKET EX		70,200
TRANS AV	56,754	56,754
TRANS EX		56,754

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	56,754

Market Value History

Tax Year	Market Value
2019 - 2020	156,000
2018 - 2019	147,000
2017 - 2018	129,600
2016 - 2017	108,000
2015 - 2016	90,000

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

90 THROOP AVENUE

Borough: BROOKLYN
Block: 2269 Lot: 30

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	NYC HPD
Property Address	90 THROOP AVENUE 11206
Billing Name and Address	NYC HPD 100 GOLD ST. LBBY 3 NEW YORK NY 10038-1619
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

NYC HPD

Land Information

Lot Size	
Frontage (feet)	25.00
Depth (feet)	70.00
Land Area (sqft)	1,750
Regular / Irregular	Regular
Corner	
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	156,000	156,000
MARKET AV	70,200	70,200
MARKET EX		70,200
TRANS AV	56,754	56,754
TRANS EX		56,754

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	56,754

Market Value History

Tax Year	Market Value
2019 - 2020	156,000
2018 - 2019	147,000
2017 - 2018	129,600
2016 - 2017	108,000
2015 - 2016	90,000

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

THROOP AVENUE

Borough: BROOKLYN
Block: 2269 Lot: 31

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	NYC HPD
Property Address	THROOP AVENUE
Billing Name and Address	NYC HPD 100 GOLD ST. LBBY 3 NEW YORK NY 10038-1619
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

NYC HPD

Land Information

Lot Size	
Frontage (feet)	34.33
Depth (feet)	75.00
Land Area (sqft)	2,831
Regular / Irregular	Irregular
Corner	
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	207,000	207,000
MARKET AV	93,150	93,150
MARKET EX		93,150
TRANS AV	84,154	84,154
TRANS EX		84,154

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	84,154

Market Value History

Tax Year	Market Value
2019 - 2020	207,000
2018 - 2019	195,000
2017 - 2018	211,000
2016 - 2017	175,680
2015 - 2016	146,400

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

69 BARTLETT STREET

Borough: BROOKLYN
Block: 2269 Lot: 33

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	HOUSING PRESERVATION & DEVELOPMENT
Property Address	69 BARTLETT STREET 11206
Billing Name and Address	OWNER/AGENT
	BAD LOCATION ADDRESS
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

HOUSING PRESERVATION & DEVELOPMENT

Land Information

Lot Size	
Frontage (feet)	50.00
Depth (feet)	65.67
Land Area (sqft)	3,283
Regular / Irregular	Regular
Corner	NW
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	189,000	189,000
MARKET AV	85,050	85,050
MARKET EX		85,050
TRANS AV	90,472	90,472
TRANS EX		90,472

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	90,472

Market Value History

Tax Year	Market Value
2019 - 2020	189,000
2018 - 2019	196,000
2017 - 2018	245,376
2016 - 2017	204,480
2015 - 2016	170,400

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

65 BARTLETT STREET

Borough: BROOKLYN
Block: 2269 Lot: 35

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	NYC HPD
Property Address	65 BARTLETT STREET 11206
Billing Name and Address	NYC HPD 100 GOLD ST. LBBY 3 NEW YORK NY 10038-1619
Tax Class	4
Building Class	V1 - ZONED COMMERCIAL

Property Owner(s)

NYC HPD

Land Information

Lot Size	
Frontage (feet)	25.00
Depth (feet)	54.00
Land Area (sqft)	1,385
Regular / Irregular	Irregular
Corner	
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	187,000	187,000
MARKET AV	84,150	84,150
MARKET EX		84,150
TRANS AV	54,455	54,455
TRANS EX		54,455

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	54,455

Market Value History

Tax Year	Market Value
2019 - 2020	187,000
2018 - 2019	156,000
2017 - 2018	103,680
2016 - 2017	86,400
2015 - 2016	72,000

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

63 BARTLETT STREET

Borough: BROOKLYN
Block: 2269 Lot: 36

2019 - 2020 Final Assessment

Final Assessment Roll for	2019-2020 | City of New York
Taxable Status Date	January 5, 2019
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	HOUSING PRESERVATION & DEVELOPMENT
Property Address	63 BARTLETT STREET 11206
Billing Name and Address	OWNER/AGENT
	BAD LOCATION ADDRESS
Tax Class	1B
Building Class	V0 - ZONED RESIDENTIAL; NOT MANHATTAN

Property Owner(s)

HOUSING PRESERVATION & DEVELOPMENT

Land Information

Lot Size	
Frontage (feet)	75.00
Depth (feet)	100.00
Land Area (sqft)	7,500
Regular / Irregular	Regular
Corner	
Number of Buildings	
Building Size	
Frontage (feet)	
Depth (feet)	
Stories	
Extension	

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	376,000	376,000
MARKET AV	22,560	22,560
MARKET EX		14,515
TRANS AV	14,515	14,515
TRANS EX		14,515

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2019/20 Taxes Will Be Based On	0

Exemption Information

Code	Description	Exempt Value
13356	PARKS DEPT NYC	14,515

Market Value History

Tax Year	Market Value
2019 - 2020	376,000
2018 - 2019	354,000
2017 - 2018	290,304
2016 - 2017	241,920
2015 - 2016	201,600

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

New York City Department of Finance

Office of the City Register

HELP

[Click help for additional instructions]
Selecting a help option will open new window

Search Results By Parcel Identifier

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 25 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Records 1 - 11 << previous next >> Max Rows 25 [Search Options] [New BBL Search] [Edit Current Search] [View Tax Map] [Print Index]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG		2014000360413	25	ENTIRE LOT	9/8/2014	10/29/2014 12:59:24 PM	COURT ORDER	8	THE CITY OF NEW YORK	THE CITY OF NEW YORK				0
DET IMG	5814/2006		25	ENTIRE LOT	9/6/2002	9/25/2002	DEED	3	HAU, MEI Y	GOLDEN WAN INTERNATIONAL GROUP CORPATION LTD			✓	0
DET IMG	5574/2166		25	ENTIRE LOT	4/17/2002	4/18/2002	DEED	3	90-92 GERRY STREET INC	HAU, MEI Y		✓	✓	0
DET IMG	1079/50		25	ENTIRE LOT	6/14/1979	6/14/1979	DEED	52	COMMISSIONER OF FINANCE OF THE CITY OF NEW YORK	THE CITY OF NEW YORK		✓	✓	0
DET IMG	828/996		25	ENTIRE LOT	2/4/1976	2/4/1976	MORTGAGE	5	NY CREATIVE TONES CO INC	CHASE MANHATTAN BANK NATL ASSN		✓		0
DET IMG	769/1795		25	ENTIRE LOT	3/21/1975	3/21/1975	MORTGAGE	4	NU CREATIVE TONES CO INC	CITY OF NY				0
DET IMG	769/1793		25	ENTIRE LOT	3/21/1975	3/21/1975	DEED	2	CITY OF NY	NU CREATIVE TONES CO INC				0
DET IMG	681/138		25	ENTIRE LOT	12/27/1973	12/27/1973	DEED	10	FINANCE ADMIN OF CITY OF NY	CITY OF NY		✓	✓	0
DET IMG	449/1877		25	ENTIRE LOT	11/30/1970	11/30/1970	MORTGAGE	5	90-92 GERRY ST INC	NATHAN AARON		✓		0
DET IMG	449/1875		25	ENTIRE LOT	11/30/1970	11/30/1970	DEED	2	KLAHR MAX	90-92 GERRY ST INC				0
DET IMG	144/366		25	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

New York City Department of Finance

Office of the City Register

HELP

[Click help for additional instructions]
Selecting a help option will open new window

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 27 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Search Results By Parcel Identifier

Records 1 - 3 << previous next >> Max Rows 10 [Search Options] [New BBL Search] [Edit Current Search] [View Tax Map] [Print Index]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	1818/603		27	ENTIRE LOT	5/28/1986	5/28/1986	DEED	130	COMMISSIONER OF FINANCE	CITY OF NEW YORK			✓	0
DET IMG	786/134		27	ENTIRE LOT	6/19/1975	6/19/1975	DEED	1	FINANCE ADMIN CITY OF NY	CITY OF NY		✓	✓	0
DET IMG	144/366		27	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

New York City Department of Finance

Office of the City Register

HELP

[Click help for additional instructions]
Selecting a help option will open new window

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 28 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Search Results By Parcel Identifier

Records 1 - 6 << previous next >> Max Rows 10 ▼ [Search Options] [New BBL Search] [Edit Current Search]
[View Tax Map] [**Print Index**]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	1333/1670		28	ENTIRE LOT	8/17/1982	8/18/1982	DEED	150	COMMISSIONER FINANCENY	NEW YORK CITY			✓	0
DET IMG	871/1950		28	ENTIRE LOT	9/16/1976	9/16/1976	DEED	8	IVAN E. IRIZARRY	THE CITY OF NEW YORK		✓	✓	0
DET IMG	611/1928		28	ENTIRE LOT	2/2/1973	2/2/1973	DEED	2	DEXTRA REALTY CORP	INSTER REALTY CORP				0
DET IMG	407/1805		28	ENTIRE LOT	4/29/1970	4/29/1970	DEED	2	31 SCHAEFFER ST CORP	DEXTRA REALTY CORP				0
DET IMG	286/344		28	ENTIRE LOT	11/7/1966	11/7/1966	DEED	2	ALI MARIAN	31 SCHAEFFER ST CORP				0
DET IMG	144/366		28	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

New York City Department of Finance

Office of the City Register

HELP

[Click help for additional instructions]
Selecting a help option will open new window

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 29 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Search Results By Parcel Identifier

Records 1 - 6 << previous next >> Max Rows 10 ▼ [Search Options] [New BBL Search] [Edit Current Search]
[View Tax Map] [Print Index]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	1333/1670		29	ENTIRE LOT	8/17/1982	8/18/1982	DEED	150	COMMISSIONER FINANCENY	NEW YORK CITY			✓	0
DET IMG	871/1950		29	ENTIRE LOT	9/16/1976	9/16/1976	DEED	8	IVAN E. IRIZARRY	THE CITY OF NEW YORK		✓	✓	0
DET IMG	611/1926		29	ENTIRE LOT	2/2/1973	2/2/1973	DEED	2	DEXTRA REALTY CORP	INSTER REALTY CORP				0
DET IMG	407/1809		29	ENTIRE LOT	4/29/1970	4/29/1970	DEED	2	31 SCHAEFFER ST CORP	DEXTRA REALTY CORP				0
DET IMG	286/346		29	ENTIRE LOT	11/7/1966	11/7/1966	DEED	2	ALI MARIAN	31 SCHAEFFER ST CORP				0
DET IMG	144/366		29	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

Go To: Finance Home Page | NYC.gov Home Page | Contact Us | Privacy Policy | Terms of Use

New York City Department of Finance
Office of the City Register

HELP
[Click help for additional instructions]
Selecting a help option will open new window

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 30 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Search Results By Parcel Identifier

Records 1 - 11 << previous next >> Max Rows 25 ▼ [Search Options] [New BBL Search] [Edit Current Search] [View Tax Map] [Print Index]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	4224/2063		30	ENTIRE LOT	4/8/1998	6/19/1998	DEED	5	WILLIAMS, ADO	CITY OF NEW YORK		✓		0
DET IMG	1348/1632		30	ENTIRE LOT	7/16/1982	10/28/1982	DEED	2	NEW YORK CITY	WILLIAMS, ADO		✓		0
DET IMG	1079/50		30	ENTIRE LOT	6/14/1979	6/14/1979	DEED	52	COMMISSIONER OF FINANCE OF THE CITY OF NEW YORK	THE CITY OF NEW YORK		✓	✓	0
DET IMG	883/683		30	ENTIRE LOT	11/9/1976	11/9/1976	DEED	2	CITY OF NY	GONZALEZ JUAN				0
DET IMG	681/138		30	ENTIRE LOT	12/27/1973	12/27/1973	DEED	10	FINANCE ADMIN OF CITY OF NY	CITY OF NY		✓	✓	0
DET IMG	388/281		30	ENTIRE LOT	1/14/1970	1/14/1970	ASSIGNMENT, MORTGAGE	2	MANUFACTURERS HANOVER TRUST CO	THE UNITED STATES OF AMERICA				0
DET IMG	579/197		30	ENTIRE LOT	11/14/1967	11/14/1967	ASSIGNMENT, MORTGAGE	2	MAC DAVE OIL BURNER CO INC	MANUFACTURES HANOVER TRUST CO				0
DET IMG	579/193		30	ENTIRE LOT	11/14/1967	11/14/1967	MORTGAGE	3	RIVERA CARMEN	MAC DAVE OIL BURNER CO INC				0
DET IMG	421/45		30	ENTIRE LOT	5/9/1967	5/9/1967	DEED	2	ROSDEN REALTY CO INC	RIVERA CARMEN				0
DET IMG	186/334		30	ENTIRE LOT	7/11/1966	7/11/1966	DEED	2	BAUER ANNA	ROSDEN REALTY CO INC				0
DET IMG	144/366		30	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

Go To: Finance Home Page | NYC.gov Home Page | Contact Us | Privacy Policy | Terms of Use

New York City Department of Finance
Office of the City Register

HELP
[Click help for additional instructions]
Selecting a help option will open new window

Search Results By Parcel Identifier

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 31 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Records 1 - 5 << previous next >> Max Rows 10 ▼ [Search Options] [New BBL Search] [Edit Current Search]
[View Tax Map] [Print Index]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	4224/2063		31	ENTIRE LOT	4/8/1998	6/19/1998	DEED	5	WILLIAMS, ADO	CITY OF NEW YORK		✓		0
DET IMG	1348/1632		31	ENTIRE LOT	7/16/1982	10/28/1982	DEED	2	NEW YORK CITY	WILLIAMS, ADO		✓		0
DET IMG	1079/50		31	ENTIRE LOT	6/14/1979	6/14/1979	DEED	52	COMMISSIONER OF FINANCE OF THE CITY OF NEW YORK	THE CITY OF NEW YORK		✓	✓	0
DET IMG	293/296		31	ENTIRE LOT	11/17/1966	11/17/1966	DEED	2	IZAN REALTY CORP	POLAKOFF LILY H		✓		0
DET IMG	144/366		31	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

New York City Department of Finance
Office of the City Register

HELP
[Click help for additional instructions]
Selecting a help option will open new window

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 33 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Search Results By Parcel Identifier

Records 1 - 6 << previous next >> Max Rows 10 ▼ [Search Options] [New BBL Search] [Edit Current Search]
[View Tax Map] [Print Index]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	1079/50		33	ENTIRE LOT	6/14/1979	6/14/1979	DEED	52	COMMISSIONER OF FINANCE OF THE CITY OF NEW YORK	THE CITY OF NEW YORK		✓	✓	0
DET IMG	675/549		33	ENTIRE LOT	11/29/1973	11/29/1973	MORTGAGE	4	STARR IDA	POLAKOFF ELLA		✓		0
DET IMG	144/366		33	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0
DET IMG	50/239		33	ENTIRE LOT	2/21/1966	2/21/1966	DEED	4	POLLARD NATHAN	STARR IDA		✓		0
DET IMG	50/235		33	ENTIRE LOT	2/21/1966	2/21/1966	MORTGAGE	4	STARR IDA	POLLARD NATHAN		✓		0
DET IMG	50/231		33	ENTIRE LOT	2/21/1966	2/21/1966	DEED	4	POLAKOFF ELLA	POLAKOFF SAMUEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

Go To: Finance Home Page | NYC.gov Home Page | Contact Us | Privacy Policy | Terms of Use

New York City Department of Finance

Office of the City Register

HELP

[Click help for additional instructions]
Selecting a help option will open new window

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 35 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Search Results By Parcel Identifier

Records 1 - 9 << previous next >> Max Rows 25 ▼ [Search Options] [New BBL Search] [Edit Current Search] [View Tax Map] [Print Index]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	4225/855		35	ENTIRE LOT		6/19/1998	SATISFACTION OF MORTGAGE	2	WILLIAMS, ADO	US SMALL BUSINESS ADMINISTRATION		✓		0
DET IMG	4225/853		35	ENTIRE LOT		6/19/1998	SATISFACTION OF MORTGAGE	2	WILLIAMS, ADO	USA SMALL BUSINESS ADMINISTRATION		✓		0
DET IMG	4224/2063		35	ENTIRE LOT	4/8/1998	6/19/1998	DEED	5	WILLIAMS, ADO	CITY OF NEW YORK		✓		0
DET IMG	1602/1804		35	ENTIRE LOT		1/31/1985	MORTGAGE	7	WILLIAMS, ADO	USA SMALL BUSI ADMIN		✓		40,000
DET IMG	1470/714		35	ENTIRE LOT		1/30/1984	MORTGAGE	7	WILLIAMS, ADO	USA SMALL BUSINESS ADM		✓		55,000
DET IMG	1112/1099		35	ENTIRE LOT	10/24/1979	10/24/1979	DEED	2	MARKOWITZ ELISSA	WILLIAMS ADO		✓		0
DET IMG	1112/1095		35	ENTIRE LOT	10/24/1979	10/24/1979	MORTGAGE	4	WILLIAMS ADO	MARKOWITZ ELISSA		✓		0
DET IMG	879/1381		35	ENTIRE LOT	10/22/1976	10/22/1976	DEED	3	HENDEL MARK RLTY CORP	MARKOWITZ ELISSA				0
DET IMG	144/366		35	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

New York City Department of Finance
Office of the City Register

HELP
[Click help for additional instructions]
Selecting a help option will open new window

Current Search Criteria:

Borough: BROOKLYN / KINGS
Block: 2269
Lot: 36 **Unit:** N/A
Date Range:
Document Class: All Document Classes

Search Results By Parcel Identifier

Records 1 - 4 << previous next >> Max Rows 10 [Search Options] [New BBL Search] [Edit Current Search] [View Tax Map] [**Print Index**]

View	Reel/Pg/File	CRFN	Lot	Partial	Doc Date	Recorded / Filed	Document Type	Pages	Party1	Party2	Party 3/ Other	More Party 1/2 Names	Corrected/ Remarks	Doc Amount
DET IMG	1079/50		36	ENTIRE LOT	6/14/1979	6/14/1979	DEED	52	COMMISSIONER OF FINANCE OF THE CITY OF NEW YORK	THE CITY OF NEW YORK		✓	✓	0
DET IMG	585/1930		36	ENTIRE LOT	10/3/1972	10/3/1972	MORTGAGE	4	ZAVELOFF AARON	BEN ARRON ROSE				0
DET IMG	585/1928		36	ENTIRE LOT	10/3/1972	10/3/1972	DEED	2	BEN ARRON ELAZAR DECD	ZAVELOFF AARON				0
DET IMG	144/366		36	ENTIRE LOT	5/27/1966	5/27/1966	MORTGAGE	5	EMELKAY CONSTRUCTION CORP	ZALISKY JOEL		✓		0

Search Options | New Parcel Identifier Search | Edit Current Search | View Tax Map

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 90 GERRY STREET BROOKLYN **BIN: 3850726 Block: 2269 Lot: 25**

NUMBER		TYPE	FILE DATE
ALT 3195/41		ALTERATION	12/03/1941
ALT 4780		ALTERATION	08/28/1941
ALT 1993		ALTERATION	06/29/1942
CERT ISSUED 102358-ALT3195/41	(PDF)	CERTIFICATE OF OCCUPANCY	07/09/1941
PRS 3319-92		PLUMBING REPAIR SLIP	11/26/1957

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Job Overview

The below job records do not include filings submitted in DOB NOW; use the DOB NOW Public Portal to access DOB NOW records.

Premises: 90 GERRY STREET BROOKLYN **BIN: 3850726 Block: 2269 Lot: 25**

To start overview at new date, select Month: ▼ **Day:** **Year:**

Show All BIS Job Types ▼ Show All Filings ▼ APPLY

FILE DATE	JOB #	DOC #	JOB TYPE	JOB STATUS	STATUS DATE	LIC #	APPLICANT	IN AUDIT	ZONING APPROVAL
08/29/2002	301397147	01	A3	R PERMIT-ENTIRE	10/04/2002	0062079 PE	Ferraro		NOT APPLICABLE
	Install 8 ft. chain link fence to enclose vacant lot as shown. No changes Work on Floor(s): 001 thru 001								
11/04/1992	300210732	01	DM	X SIGNED OFF	12/10/1992		SCALA		NOT APPLICABLE
	Work on Floor(s): 002								

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: 90 GERRY STREET BROOKLYN **BIN: 3850726** **Block: 2269** **Lot: 25**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME
	51856	N	01	VOID			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

84 THROOP AVENUE **BROOKLYN 11206** **BIN# 3829102**

THROOP AVENUE 84 - 84

Tax Block : 2269
Tax Lot : 27

Community Board : 301

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

DOB Special Place Name:
DOB Building Remarks:

Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	2	0
Violations-ECB (DOB)	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	18	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 84 THROOP AVENUE BROOKLYN **BIN: 3829102 Block: 2269 Lot: 27**

NUMBER		TYPE	FILE DATE
ALT 7150INT&PL-071433		ALTERATION	00/00/1933
ALT 1443INT-021835		ALTERATION	00/00/1935
ALT 1464-031235		ALTERATION	00/00/1935
ALT 4237-081640		ALTERATION	00/00/1940
ALT 650-76-84-033062		ALTERATION	00/00/1962
ALT 766-84-042767		ALTERATION	00/00/1967
ALTA 766-69			00/00/1969
BOIL ERDIVMAN12-29-77			00/00/1929
CERT 199255-040268	(PDF)	CERTIFICATE OF OCCUPANCY	00/00/1968
DEM 1008-84-090580		DEMOLITION	00/00/1980
ENTE 10-1-75)V2639-84-051975			00/00/0000
FE 1970-052737		FIRE ESCAPE	00/00/1937
FE 7947-103140		FIRE ESCAPE	00/00/1940
FEFE 1970-37			00/00/1937
P &D5163-081640		PLUMBING	00/00/1940
UB 1097-84GELSHION5--101378		UNSAFE BUILDING	00/00/1984
V* 2040NASTASI7-31-5-052155		DOB VIOLATION - CLOSED	00/00/0000
CLOSURE DATE: 09/28/2011			
V* 4565/84KRAMER4-4--072266		DOB VIOLATION - CLOSED	00/00/0000
CLOSURE DATE: 09/28/2011			
WITH 6-080133			00/00/1908
7ORK 16946-060737			00/00/1937

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

DOB Violations

Premises: 84 THROOP AVENUE BROOKLYN **BIN: 3829102** **Block: 2269** **Lot: 27**

NUMBER	TYPE	FILE DATE
V* 2040NASTASI7-31-5-052155	DOB VIOLATION - CLOSED	00/00/0000
CLOSURE DATE: 09/28/2011		
V* 4565/84KRAMER4-4--072266	DOB VIOLATION - CLOSED	00/00/0000
CLOSURE DATE: 09/28/2011		

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

m 54-C (Rev. 7/64)—15M-701340(66) 114

DEPARTMENT OF BUILDINGS

ck BOROUGH OF Brooklyn, THE CITY OF NEW YORK

ate APR 2 1968 No. 199255

CERTIFICATE OF OCCUPANCY

O CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No.

THIS CERTIFIES that the ~~new~~ altered ~~existing~~ building premises located at 84 Throop Av enne southwest cor Gerry St Block 2269 Lot 27

That the zoning lot and premises above referred to are situated, bounded and described as follows:

EGINNING at a point on the ~~east~~ southwest ~~west~~ corner formed by the intersection of Throop Avenue and Gerry Street

nning thence south 25'0" feet; thence west 70'0" feet;

nce north 25'0" feet; thence east 70'0" feet;

nning thence feet; thence feet;

the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of andards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646e of the New York Charter have been complied th as certified by a report of the Fire Commissioner to the Borough Superintendent.

Construction classification— Class 3 nonfireproof

~~New~~ No.— Alt. 766-1967 Height 3 stories, 35 feet.

ccupancy classification— Class "A" multiple dwelling-Old Law, manufactur of apparel Located in M 1 - 2 Zoning District.

ime of occupation (Use Group 17B)

time of issuance of permit. const. 3-15-68 - plumb. 3-12-68

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

d The City Planning Commission:

PERMISSIBLE USE AND OCCUPANCY

-Street Parking Spaces

f-Street Loading Berths

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
llar	on ground	-	storage and boiler room
irst	120	15	manufacturing of apparel (Use Group 17B)
econd	40	-	two (2) apartments
hird	40	-	two (2) apartments

ERFORMANCE STANDARDS FOR M1 - 2 TO BE COMPLIED WITH

TOTAL:- Four (4) families and manufacture of apparel (Use Group 17B)

CLASS "A" MULTIPLE DWELLING - Old Law

e issuance of this Certificate of Occupancy is predicated upon the final eport of inspection made on March 5, 1968

HE DEPARTMENT ACCOUNT #C667847 ISSUED 1967 - (fuel oil)

Sewage Disposal: (DOES) (DOES NOT) Discharge Into Either Sanitary or Combined Sewer

THIS CERTIFICATE SHALL BE CONSIDERED A CERTIFICATE OF COMPLIANCE UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW.

Storm Drainage (DOES) (DOES NOT) Discharge Into Either Storm or Combined Sewer

Samuel Pinsker

Borough Superintendent

FICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

86 THROOP AVENUE **BROOKLYN 11206** **BIN# 3256266**

THROOP AVENUE 86 - 86

Health Area	: 1500	**Tax Block**	: 2269
Census Tract	: 507	**Tax Lot**	: 28
Community Board	: 301	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	GERRY STREET, BARTLETT STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	1	0
Violations-ECB (DOB)	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	6	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

90 GERRY STREET **BROOKLYN 11206** **BIN# 3850726**

GERRY STREET 90 - 90

Tax Block : 2269
Tax Lot : 25

Community Board : 301

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

DOB Special Place Name:
DOB Building Remarks:

Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	HAZMAT/AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	2	0
Violations-DOB	0	0
Violations-ECB (DOB)	0	0
Jobs/Filings	2	
ARA / LAA Jobs	0	
Total Jobs	2	
Actions	5	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 86 THROOP AVENUE BROOKLYN **BIN: 3256266** **Block: 2269** **Lot: 28**

NUMBER	TYPE	FILE DATE
ALT 605-021754	ALTERATION	00/00/1954
BN 2080-86-040868	BUILDING NOTICE	00/00/1968
DEM 859-86-101979	DEMOLITION	00/00/1979
FE 624-081540	FIRE ESCAPE	00/00/1940
P &D5166(FOIN88)-102560	PLUMBING	00/00/1960
UB 32-86GEORGE-012077	UNSAFE BUILDING	00/00/1986
V* 1706/86NEWELL10-3-032768	DOB VIOLATION - CLOSED	00/00/0000

CLOSURE DATE: 09/28/2011

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

88 THROOP AVENUE **BROOKLYN 11206** **BIN# 3256267**

THROOP AVENUE 88 - 88

Health Area	: 1500	**Tax Block**	: 2269
Census Tract	: 507	**Tax Lot**	: 29
Community Board	: 301	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	GERRY STREET, BARTLETT STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-ECB (DOB)	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	11	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 88 THROOP AVENUE BROOKLYN **BIN: 3256267** **Block: 2269** **Lot: 29**

NUMBER	TYPE	FILE DATE
		00/00/0000
ALT 4584-102153	ALTERATION	00/00/1953
ALT 792-030155	ALTERATION	00/00/1955
C -A4165-010562	CONSTRUCTION	00/00/1962
DEM 860-101979	DEMOLITION	00/00/1979
FE 1007-032337	FIRE ESCAPE	00/00/1937
FO 5165-102560	OIL BURNER APPLICATION	00/00/1960
PRS 1706-080768	PLUMBING REPAIR SLIP	00/00/1968
UB 33-88GEORGE-012077	UNSAFE BUILDING	00/00/1988
WITH 6-033055		00/00/1903
WORK 15981-041237		00/00/1937

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

90 THROOP AVENUE **BROOKLYN 11206** **BIN# 3256268**

THROOP AVENUE 90 - 90

Health Area	: 1500	**Tax Block**	: 2269
Census Tract	: 507	**Tax Lot**	: 30
Community Board	: 301	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	GERRY STREET, BARTLETT STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-ECB (DOB)	1	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	10	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 90 THROOP AVENUE BROOKLYN **BIN: 3256268** **Block: 2269** **Lot: 30**

NUMBER	TYPE	FILE DATE
		00/00/0000
ALT 1489-041934	ALTERATION	00/00/1934
C -A12692-041268	CONSTRUCTION	00/00/1968
DEM 861-90-101979	DEMOLITION	00/00/1979
FE 3958-123036	FIRE ESCAPE	00/00/1936
FO 68-90-012468	OIL BURNER APPLICATION	00/00/1968
PRS 4288-90-071160	PLUMBING REPAIR SLIP	00/00/1960
PRS 544-031069	PLUMBING REPAIR SLIP	00/00/1969
UB 100-90COHEN-020177	UNSAFE BUILDING	00/00/1990
WORK 14396-011237		00/00/1937
VEC* 052202C01RS02VW	ECB VIOLATION DISMISSED	05/22/2002

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

92 THROOP AVENUE **BROOKLYN 11206** **BIN# 3829106**

THROOP AVENUE 92 - 92 **Tax Block** : 2269
Tax Lot : 31

Community Board : 301

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

DOB Special Place Name:
DOB Building Remarks:

Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	2	0
Violations-ECB (DOB)	1	0
Jobs/Filings	1	
ARA / LAA Jobs	0	
Total Jobs	1	
Actions	15	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 92 THROOP AVENUE BROOKLYN **BIN: 3829106 Block: 2269 Lot: 31**

NUMBER		TYPE	FILE DATE
ALT 2148-102566		ALTERATION	00/00/1910
ALTA 2148-66			00/00/1966
BN 862-041058		BUILDING NOTICE	00/00/1904
CERT 202161-080869	(PDF)	CERTIFICATE OF OCCUPANCY	00/00/1908
DEM 100COMPLETED58-041858		DEMOLITION	00/00/1904
DOC 26944-120866		DOCKET	00/00/1912
DOC 29555ALT2148-66-072269		DOCKET	00/00/1966
FE 2017-39(92)		FIRE ESCAPE	12/21/1939
NB 878(1-1STYFACTOR-072264		NEW BUILDING	00/00/0000
OFFI CE)1-5-68CBL			00/00/0000
SR 398-40(92)		SPECIAL REPORT	01/11/1940
UB 253CHESNEK10-23-5-082056		UNSAFE BUILDING	00/00/1923
UB 143NASTASI10-27-5-051155		UNSAFE BUILDING	00/00/1927
V* 3884/92NEWELL8-11-082268		DOB VIOLATION - DISMISSED	00/00/0000
DISMISSAL DATE: 08/11/1969			**BADGE NO.:** 0000
VP 158STOKES5-2-62-011554		VIOLATION UNSERVED ECB-ACTIVE	00/00/0000
VUB 295NASTASI5-29-58-101657			00/00/1929
V* 050407IMEGNCY093/07		DOB VIOLATION - DISMISSED	05/04/2007
VEC* 052202C01RS01VW		ECB VIOLATION DISMISSED	05/22/2002

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Job Overview

The below job records do not include filings submitted in DOB NOW; use the DOB NOW Public Portal to access DOB NOW records.

Premises: 92 THROOP AVENUE BROOKLYN **BIN: 3829106 Block: 2269 Lot: 31**

To start overview at new date, select Month: ▼ **Day:** **Year:**

Show All BIS Job Types ▼ Show All Filings ▼ APPLY

FILE DATE	JOB #	DOC #	JOB TYPE	JOB STATUS	STATUS DATE	LIC #	APPLICANT	IN AUDIT	ZONING APPROVAL
06/18/2007	302374589	01	DM	X SIGNED OFF	02/02/2012		SCALA		NOT APPLICABLE
	Work on Floor(s): 001								

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 54-C (Rev. 7/64)-33M-705151(67) 346

DEPARTMENT OF BUILDINGS

clc BOROUGH OF Brooklyn , THE CITY OF NEW YORK

Date AUG - 8 1969 No. 202161

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No.

THIS CERTIFIES that the ~~new~~ altered ~~existing~~ building—premises located at

off 92/94; Disp 92 Throop Avenue Block 2269 Lot 31

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the West side of Throop Avenue

distant 65'8" feet north from the corner formed by the intersection of

Throop Avenue and Bartlett Street

running thence west 53'0" feet; thence south 11'8" feet;

thence west 22'0" feet; thence north 46'0" feet;

running thence east 75'0" feet; thence ..... feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646e of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~Old~~ Alt. No.— Alt. 2148-1966 Construction classification — vacant land

Occupancy classification—Public Parking Lot (Use Group 8) . Height - - - stories, - - - feet.

Date of completion— const. 7-25-69 . Located in Zoning District.

at time of issuance of permit. plumb. 7-25-69

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals:
and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces .....

Off-Street Loading Berths .....

STORY	LIVE LOADS Lbs per Sq Ft	PERSONS ACCOMMODATED	USE
cant land	on ground	-	public parking lot (Use Group 8) capacity ten (10) cars

TOTAL:- AS STATED ABOVE

Sewage Disposal:
Saintary Drainage.....Discharge Into Either
(DOES) (DOES NOT) Sanitary or Combined Sewer

Storm Drainage.....Discharge Into Either
(DOES) (DOES NOT) Storm or Combined Sewer

FFICE COPY—DEPARTMENT OF BUILDINGS

Borough Superintendent

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintende

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

96 THROOP AVENUE **BROOKLYN 11206** **BIN# 3061445**

BARTLETT STREET 67 - 69
THROOP AVENUE 96 - 100

Health Area	: 1500	**Tax Block**	: 2269
Census Tract	: 507	**Tax Lot**	: 33
Community Board	: 301	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	GERRY STREET, BARTLETT STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	2	0
Violations-DOB	24	0
Violations-ECB (DOB)	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	34	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 96 THROOP AVENUE BROOKLYN **BIN: 3061445** **Block: 2269** **Lot: 33**

NUMBER	TYPE	FILE DATE
ALT 7805-15	ALTERATION	11/04/1915
ALT 5503-15	ALTERATION	11/15/1915
ALT 7028-22	ALTERATION	04/24/1922
ALT 4629-28	ALTERATION	05/09/1928
ALT 13340-34	ALTERATION	09/28/1934
ALT 9893-34	ALTERATION	10/11/1934
ALT 13451-34	ALTERATION	10/01/1934
ALT 9751-34	ALTERATION	10/08/1934
ALT 2222-072243	ALTERATION	00/00/1943
ALT 1114-65.(96)	ALTERATION	00/00/1965
C/A 3638-61		10/04/1961
DP 365-89	DEMOLITION PERMIT	10/11/1989
ELEV 52-68(96)	ELEVATOR	09/17/1968
ELV 869MANNINGVIOLAT-030344	ELEVATOR	00/00/1903
ELV 4539-20	ELEVATOR	04/21/1920
ELV 3061-20	ELEVATOR	04/24/1920
ELV 82-070561	ELEVATOR	00/00/1961
ELV 46-65(96)	ELEVATOR	00/00/1965
ELV 2781-HOHENBERGE-1972	ELEVATOR	00/00/1972
FO 3877-60(96)	OIL BURNER APPLICATION	08/01/1960
NB 426-02	NEW BUILDING	03/31/1902
NB 723-02	NEW BUILDING	05/06/1902
P+D 950-18		07/31/1918
P&D 868-16	PLUMBING & DRAINAGE	05/12/1916
P&D 2147-20	PLUMBING & DRAINAGE	11/11/1920

Next

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 96 THROOP AVENUE BROOKLYN **BIN: 3061445** **Block: 2269** **Lot: 33**

NUMBER	TYPE	FILE DATE
PD 1533-072243		00/00/1943
PRS 131-011460	PLUMBING REPAIR SLIP	00/00/1901
PRS 712-72	PLUMBING REPAIR SLIP	04/20/1972
SPR 2552-61(96)	SPRINKLERS	00/00/1961
SR 716ROIG-041255	SPECIAL REPORT	00/00/1955
SRSR 6462-3996WASSERMAN		00/00/1939
UB 358-80(96-100)DISM.02/90	UNSAFE BUILDING	00/00/1980
V* 85/96OHARA-010860	DOB VIOLATION - DISMISSED	00/00/0000
DISMISSAL DATE: 12/02/1960		**BADGE NO.:** 0000
V* 8-18-8310-19-81EIT301522	DOB VIOLATION - DISMISSED	00/00/0000
DISMISSAL DATE: 06/30/1994	**AGENCY LICENSE:** CIAWLA	
V* 2567-39WASSERMANVIOLATI	DOB VIOLATION - CLOSED	00/00/1939
CLOSURE DATE: 09/28/2011		
V* 833/ROIG5-16-57-021556	DOB VIOLATION - CLOSED	00/00/1956
CLOSURE DATE: 09/28/2011		
V* 101981EIT301522	DOB VIOLATION - DISMISSED	10/19/1981
DISMISSAL DATE: 06/30/1994	**AGENCY LICENSE:** CIAWLA	
V* 081685ELL1081SS08189	DOB VIOLATION - CLOSED	00/00/1985
CLOSURE DATE: 09/28/2011		
V* 112685E13600303	DOB VIOLATION - DISMISSED	00/00/1985
V* 469/96ROIG6-9-60-012760	DOB VIOLATION - CLOSED	00/00/1996
CLOSURE DATE: 09/28/2011		
VIOL 6-30-3863563543CANNING		00/00/1938
WRKC 1574-34		12/21/1934
V* 060193LL629122466	DOB VIOLATION - DISMISSED	06/01/1993
V* 060194LL629122467	DOB VIOLATION - DISMISSED	06/01/1994
V* 082995LL629135504	DOB VIOLATION - DISMISSED	08/29/1995
V* 091697LL6291225404	DOB VIOLATION - DISMISSED	09/16/1997
V* 050498LL629126085	DOB VIOLATION - DISMISSED	05/04/1998
V* 101289LL108104652	DOB VIOLATION - DISMISSED	10/12/1989
V* 062990LL108103521	DOB VIOLATION - DISMISSED	06/29/1990
V* 042591LL108102453	DOB VIOLATION - DISMISSED	04/25/1991

Previous Next

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 96 THROOP AVENUE BROOKLYN **BIN: 3061445 Block: 2269 Lot: 33**

NUMBER	TYPE	FILE DATE
V* 040792LL108103915	DOB VIOLATION - DISMISSED	04/07/1992
V* 062893LL108103161	DOB VIOLATION - DISMISSED	06/28/1993
V* 031699LL629117847	DOB VIOLATION - DISMISSED	03/16/1999
V* 020700LL629118123	DOB VIOLATION - DISMISSED	02/07/2000
V* 022701LL629117608	DOB VIOLATION - DISMISSED	02/27/2001
V* 032602LL629118658	DOB VIOLATION - DISMISSED	03/26/2002
V* 031903LL629117376	DOB VIOLATION - DISMISSED	03/19/2003
V* 021304LL629121577	DOB VIOLATION - DISMISSED	02/13/2004

Previous

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Elevator Records

Premises: 96 THROOP AVENUE BROOKLYN **BIN: 3061445 Block: 2269 Lot: 33**

RECORD #	HOUSE NUMBER	STREET NAME	NUM DEVICES	LINKS
77805	96	THROOP AVENUE	1	Inspections 8 | Violations 0

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: 96 THROOP AVENUE BROOKLYN **BIN: 3061445 Block: 2269 Lot: 33**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME
	933252	Y	01	VOID			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

65 BARTLETT STREET **BROOKLYN 11206** **BIN# 3061446**

BARTLETT STREET 65 - 65

Health Area	: 1500	**Tax Block**	: 2269
Census Tract	: 507	**Tax Lot**	: 35
Community Board	: 301	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	HARRISON AVENUE, THROOP AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V1-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	4	0
Violations-DOB	5	0
Violations-ECB (DOB)	3	0
Jobs/Filings	2	
ARA / LAA Jobs	1	
Total Jobs	3	
Actions	6	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 65 BARTLETT STREET BROOKLYN **BIN: 3061446 Block: 2269 Lot: 35**

NUMBER		TYPE	FILE DATE
CERT 186298-121763	(PDF)	CERTIFICATE OF OCCUPANCY	00/00/1912
DEM 341-65-113044		DEMOLITION	00/00/1965
DOC 21867-092563		DOCKET	00/00/1909
NB 1181-052661		NEW BUILDING	00/00/1905
NBNB 1181-611-26-12-ALT365			00/00/1961
P &D2657-123022		PLUMBING	00/00/1912
V* 020190C01G01		DOB VIOLATION - DISMISSED	02/01/1990
V* 072804UB3276/04		DOB VIOLATION - DISMISSED	07/28/2004
V* 050404UB3265/04		DOB VIOLATION - DISMISSED	05/04/2004
V* 030807IMEGNCY036/07		DOB VIOLATION - DISMISSED	03/08/2007
VW* 030707C01AH02		VIOLATION - WORK W/O PERMIT DISMISSED	03/07/2007
VEC* 050404C01BR01		ECB VIOLATION DISMISSED	05/04/2004
VEL* 030707C01AH01		VIOLATION ECB LIEN DISMISSED	03/07/2007
VEL* 030707C01AH02		VIOLATION ECB LIEN DISMISSED	03/07/2007

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Complaints By Address

Click here for information on how to remove a Stop Work Order from your property

Premises: 65 BARTLETT STREET BROOKLYN **BIN: 3061446 Block: 2269 Lot: 35**

4 Total Complaints

View Vacate Order Complaints **View SWO Complaints**

Looking for a list of complaint category codes or disposition codes?
(Adobe Acrobat Reader required)

Complaint Number	Address	Date Entered	Category	Inspection Date	Disposition	Status
3218693	65 BARTLETT STREET	03/14/2007	73	03/07/2007	B1	RES
	FAILURE TO MAINTAIN					
3137234	65 BARTLETT STREET	07/28/2004	73	07/30/2004	I2	RES
	PROPERTY OPPOSITE TO 102-20 BARTLETT STREET NUMEROUS FIRESSTABILITY OF INTERIOR MEZZANINE IN QUESTION					
3113988	65 BARTLETT STREET	06/10/2003	29	05/04/2004	A9	RES
	PREMISES VACANT, OPEN AND UNGUARDED WITH ACCUMULATION OF RUBBISH					
3006740	65 BARTLETT STREET	12/12/1989	05	02/01/1990	B1	RES
	NO BLDG PERMIT FOR ALTERATION ON 1ST FL REAR					

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Job Overview

The below job records do not include filings submitted in DOB NOW; use the DOB NOW Public Portal to access DOB NOW records.

Premises: 65 BARTLETT STREET BROOKLYN **BIN: 3061446 Block: 2269 Lot: 35**

To start overview at new date, select Month: ▼ **Day:** **Year:**

Show All BIS Job Types ▼ Show All Filings ▼ APPLY

FILE DATE	JOB #	DOC #	JOB TYPE	JOB STATUS	STATUS DATE	LIC #	APPLICANT	IN AUDIT	ZONING APPROVAL
06/18/2007	302374446	01	DM	R PERMIT-ENTIRE	06/19/2007		SCALA		NOT APPLICABLE
	Work on Floor(s): 001								
11/23/2004	301866755	01	A2	R PERMIT-ENTIRE	12/08/2004	0062079 PE	Ferraro		NOT APPLICABLE
	Installation of temporary plywood protective fence at perimeter of propert								
	Work on Floor(s): 001								

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Job Overview

The below job records do not include filings submitted in DOB NOW; use the DOB NOW Public Portal to access DOB NOW records.

ARA / LAA Job Overview

Premises: 65 BARTLETT STREET BROOKLYN **BIN: 3061446 Block: 2269 Lot: 35**

To start overview at new date, select Month: ▼ **Day:** **Year:** APPLY

FILE DATE	JOB #	JOB TYPE	JOB STATUS	STATUS DATE	LIC #	APPLICANT
12/13/1989	300016319	PR	I LAA SIGNED OFF	12/19/1989	MP 000891	KHAN

INSTALL TWO MODINE UNIT HEATERS MODEL PA150 150,000 BTU MEA 5-70-E APPROX

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Form 54-C (Rev. 4/62)-80M-601036(62) 114

DEPARTMENT OF BUILDINGS

ck
Date DEC 17 1963 BOROUGH OF Brooklyn , THE CITY OF NEW YORK

No. 1165298

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No.

THIS CERTIFIES that the new ~~altered existing~~ building—premises located at

65 Bartlett Street Block 2269 Lot 35

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the north side of Bartlett Street
distant 50 feet west from the corner formed by the intersection of
Throop Avenue and Bartlett Street
running thence north 65'8" feet; thence west 3 feet;
thence south 11'8" feet; thence west 22 feet;
running thence south 54 feet; thence east 25 feet;
to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER ~~that~~, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

N.B. ~~Application~~ No.— 1181-1961 Construction classification—nonfireproof
Occupancy classification—see occupancy below . Height 1 stories, 12'8" feet.
Date of completion—const. 12-12-63 . Located in M 1 - 2 Zoning District.
at time of issuance of permit. plumb. 12-6-63

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces

Off-Street Loading Berths

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
First	on ground	4	automobile and body repair shop - Use Group #17 Oxygen and acetylene tanks installed.
	Building to comply with all the performance standards of an M - 1 District		
		TOTAL:- AS STATED ABOVE	

OFFICE COPY—DEPARTMENT OF BUILDINGS

Borough Superintendent

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

59 BARTLETT STREET **BROOKLYN 11206** **BIN# 3805391**

BARTLETT STREET 59 - 63

Tax Block : 2269
Tax Lot : 36

Community Board : 301

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

DOB Special Place Name:
DOB Building Remarks:

Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	YES
Additional BINs for Building:	NONE		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: V0-VACANT LAND

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	13	0
Violations-ECB (DOB)	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	16	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 59 BARTLETT STREET BROOKLYN **BIN: 3805391** **Block: 2269** **Lot: 36**

NUMBER	TYPE	FILE DATE
ALT 10469-071838	ALTERATION	00/00/1907
ALT 9853-101038	ALTERATION	00/00/1910
ALT 4037-63-103152	ALTERATION	00/00/1963
ALTA 9853-38		00/00/1938
ALTA 211-8759		00/00/1987
BN 2164-59-081342	BUILDING NOTICE	00/00/1959
BN 1421-63-071863	BUILDING NOTICE	00/00/1963
DEMO 1126-59-100980		00/00/1959
DEMO 414-59-052284		00/00/1959
DEMO 415-63-052284		00/00/1963
FO 2271-070650	OIL BURNER APPLICATION	00/00/1907
NB 22361BARTLETTST-040991	NEW BUILDING	00/00/1904
NB 68761BARTLETTST-111191	NEW BUILDING	00/00/1911
NBNB 1815-0559-63		00/00/1905
UB 190-59-63-050984	UNSAFE BUILDING	00/00/1959
V* 2617/63(BDM)-121576	DOB VIOLATION - DISMISSED	00/00/0000
DISMISSAL DATE: 04/13/1987		**BADGE NO.:** 0000
V* 050984UB190-84	DOB VIOLATION - CLOSED	00/00/1984
CLOSURE DATE: 09/28/2011		
WORK 23017-102738		00/00/1910
V* 060193LL629122464	DOB VIOLATION - DISMISSED	06/01/1993
V* 060194LL629122465	DOB VIOLATION - DISMISSED	06/01/1994
V* 082995LL629135503	DOB VIOLATION - DISMISSED	08/29/1995
V* 091697LL6291225405	DOB VIOLATION - DISMISSED	09/16/1997
V* 050498LL629126084	DOB VIOLATION - DISMISSED	05/04/1998
V* 031699LL629117848	DOB VIOLATION - DISMISSED	03/16/1999
V* 020700LL629118124	DOB VIOLATION - DISMISSED	02/07/2000

Next

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 59 BARTLETT STREET BROOKLYN **BIN: 3805391 Block: 2269 Lot: 36**

NUMBER	TYPE	FILE DATE
V* 022701LL629117609	DOB VIOLATION - DISMISSED	02/27/2001
V* 032602LL629118659	DOB VIOLATION - DISMISSED	03/26/2002
V* 031903LL629117377	DOB VIOLATION - DISMISSED	03/19/2003
V* 021304LL629121576	DOB VIOLATION - DISMISSED	02/13/2004

Previous

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Boiler Query

The below information does not include 2017 Boiler Inspection Cycle compliance filings submitted after August 14, 2017; use the DOB NOW Public Portal to access DOB NOW records.

Premises: 59 BARTLETT STREET BROOKLYN **BIN: 3805391 Block: 2269 Lot: 36**

VIOL	NUM	MD	SER#	STATUS	INSP-DATE	RECV-DATE	NAME
	933251	Y	01	VOID			
	16890	N	01	VOID			

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center

Brooklyn, New York 11201-3857

(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A CUSTOMER INFORMATION

Please print the required information below.

Environmental Business Consultants
Name

1808 Middle Country Road
Address

Ridge, NY | 11961
State | Zip Code

(631 504-6000
Telephone Number

OFFICE USE ONLY

_____
Cashier / Search No.

PRU Staff
Accepted By/Initials:_____

Searched By:_____

Total Amount:_____

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the NYC Fire Department and a stamped self-addressed envelope (with postage). Mail checks or money orders directly to the address and unit listed above. DO NOT MAIL CASH.

SECTION B FUEL TANK REPORT - FEE $10.00 / PER REPORT

69 | Bartlett Street | Brooklyn
House Number | Street Name | Borough

- ☐ **THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS**
- ☒ **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS**
- ☐ **THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS**
- ☒ **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS**
- ☐ **MOST RECENT TANK / PIPING TEST RESULTS**
- ☐ **HISTORY OF BURIED TANKS LEAKS**

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Tanks Section

9 MetroTech Center
Brooklyn, New York 11201-3857
(718) 999-2441 or 2442

Fuel Tank Special Report Request Form

SECTION A CUSTOMER INFORMATION

Please print the required information below.

Environmental Business Consultants
Name

1808 Middle Country Road
Address

Ridge, NY 11961
State Zip Code

(631 504-6000
Telephone Number

OFFICE USE ONLY

_____
Cashier / Search No.

PRU Staff
Accepted By/Initials:_____

Searched By:_____

Total Amount:_____

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the NYC Fire Department and a stamped self-addressed envelope (with postage). Mail checks or money orders directly to the address and unit listed above. DO NOT MAIL CASH.

SECTION B FUEL TANK REPORT - FEE $10.00 / PER REPORT

63	Bartlett Street	Brooklyn
House Number	Street Name	Borough

- ☐ **THE TOTAL AMOUNT AND SIZE OF EXISTING FUEL OIL / HEATING TANKS**
- ☒ **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED FUEL OIL / HEATING TANKS**
- ☐ **THE TOTAL AMOUNT AND SIZE OF EXISTING BURIED MOTOR VEHICLE TANKS**
- ☒ **THE TOTAL AMOUNT AND SIZE OF REMOVED OR SEALED BURIED MOTOR VEHICLE TANKS**
- ☐ **MOST RECENT TANK / PIPING TEST RESULTS**
- ☐ **HISTORY OF BURIED TANKS LEAKS**

Note: Requests will be responded to within 10 business days.

PR3 (July-08)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Fire Records Section

9 MetroTech Center

Brooklyn, New York 11201-3857

(718) 999-2681 or 2682

Violation Special Report Request Form

SECTION A CUSTOMER INFORMATION

Please print the required information below.

OFFICE USE ONLY

_____
Cashier / Search No.

PRU Staff
Accepted By/Initials:_____

Searched By:_____

Total Amount:_____

Nov. 5, 2019
Date

Environmental Business Consultants
Name

1808 Middle Country Road
Address

Ridge, NY 11961
Borough, State Zip Code

(631) 504-6000
Telephone Number

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the NYC Fire Department and a stamped self-addressed envelope (with postage). Mail checks or money orders directly to the address and unit listed above. DO NOT MAIL CASH.

SECTION B REQUEST VIOLATION REPORT FEE $10.00 / PER REPORT

Please print the required information below.

69	Bartlett Street	Brooklyn
House No	Street Name	Borough

☑ **EXISTING- ALL NOTICES OF VIOLATION AND VIOLATION ORDERS ISSUED BY THE FIRE PREVENTION**

☐ **EXISTING- ALL SUMMONSES**

Note: This search is limited to outstanding Summonses, Notices of Violation and Violation Orders (VOs) that are reported to be related to a specific address. With respect to VOs this search is limited to VOs issued on January 1, 2008 or thereafter. This search does not contain information on VOs issued by fire companies, unless they were forwarded to the Bureau of Fire Prevention. A requested report will only list the violation numbers. After you have received the Report, you can obtain a copy of any record available for an additional fee of $0.25 (cents) / per page by filling out the copy of violation request form.

Note: Requests will be responded to within 10 business days.

PR4 (April-09)

FIRE DEPARTMENT – CITY OF NEW YORK

Public Records Unit / Fire Records Section

9 MetroTech Center

Brooklyn, New York 11201-3857

(718) 999-2681 or 2682

Violation Special Report Request Form

SECTION A CUSTOMER INFORMATION

Please print the required information below.

OFFICE USE ONLY

_____
Cashier / Search No.

PRU Staff
Accepted By/Initials:_____

Searched By:_____

Total Amount:_____

Nov. 5, 2019
Date

Environmental Business Consultants
Name

1808 Middle Country Road
Address

Ridge, NY 11961
Borough, State Zip Code

(631) 504-6000
Telephone Number

Note: Please make sure you complete this form and attach all required documents. Enclose a check or money order made payable to the NYC Fire Department and a stamped self-addressed envelope (with postage). Mail checks or money orders directly to the address and unit listed above. DO NOT MAIL CASH.

SECTION B REQUEST VIOLATION REPORT FEE $10.00 / PER REPORT

Please print the required information below.

63	Bartlett Street	Brooklyn
House No	Street Name	Borough

☑ **EXISTING- ALL NOTICES OF VIOLATION AND VIOLATION ORDERS ISSUED BY THE FIRE PREVENTION**

☐ **EXISTING- ALL SUMMONSES**

Note: This search is limited to outstanding Summonses, Notices of Violation and Violation Orders (VOs) that are reported to be related to a specific address. With respect to VOs this search is limited to VOs issued on January 1, 2008 or thereafter. This search does not contain information on VOs issued by fire companies, unless they were forwarded to the Bureau of Fire Prevention. A requested report will only list the violation numbers. After you have received the Report, you can obtain a copy of any record available for an additional fee of $0.25 (cents) / per page by filling out the copy of violation request form.

Note: Requests will be responded to within 10 business days.

PR4 (April-09)

Request a Record

Please make your request specific so you receive the fastest service. After you submit a FOIL request you will receive a confirmation number so you can track the status of the response. The agency will notify you about how much time is required to respond to your request.

Category (optional)

Selecting a category helps clarify which agency will receive the request by listing agencies grouped by categories.

Environment

Agency (required)

Select the agency that will handle your request.

Department of Environmental Protection (DEP)

Request Title (required)

Phase I Environmental Site Assessment

90 characters remaining

Note: The agency, category, and title of your request will be visible to the public. Do not enter personal information here.

Ex: Queens Blvd Roadwork Permit.

Request Description (required)

All documents related to the environmental condition or the historic use of the property at 59-69 Bartlett Street, 84-100 Throop Avenue, and 90-100 Gerry Street, Brooklyn, NY 11206 (Block 2269, Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36). The documents are being requested in conjunction with the preparation of a Phase I Environmental Site Assessment.

4643 characters remaining

Note: The request details you write here will not be visible to the public. However, the agency may post a description of the records provided.

Ex: Roadwork permits for work done in on Queens Blvd. between 40th and 45th streets, Borough of

Queens, in September and October 2017.

Upload File (optional, must be less than 20 Mb)

Choose File

No file uploaded

Personal Information

First and last name fields are required. The Email field is optional but recommended. If you do not provide an email you must enter either a phone number, fax number, or address in the Alternate Contact Information section.

This information will not be publicly viewable on this site. You must provide contact information so that the agency can respond to your request for records.

First Name (required)

Keith

32 characters remaining

Last Name (required)

Butler

64 characters remaining

Email

kbutler@ebcincny.com

Alternate Contact Information

No information entered in this section will be visible to the public.

Fields are included in case alternate contact method is needed.

Title

Sr. Project Manager

64 characters remaining

Organization

Environmental Business Consultants

128 characters remaining

Phone

(631) 504-6000

Fax

(631) 924-2870

Address

Address Line 1

1808 Middle Country Road

Address Line 2

Apartment 3D

City

Ridge

State / U.S. Territory

New York

Zip

11961

Submit Request

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov)

Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

Search

City of New York. 2016 All Rights Reserved,

NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page). Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

Your request has been submitted!

You can expect an acknowledgment from the City of New York within 5 business days. The agency will use the contact information you provided.

All messages from the City of New York and/or the information and documents you requested will be posted to this page.

FOIL-2019-826-05012

Title:

Under Review

Open

Department of Environmental Protection (DEP)

Acknowledgment Due Date:
11/13/2019

Contact the Agency

Responses

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov)

Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

Search

City of New York. 2016 All Rights Reserved,
NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page). Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

EBC
ENVIRONMENTAL BUSINESS CONSULTANTS

1808 Middle Country Road. Ridge, New York 11961
Phone: 631.504.6000 Fax: 631.924.2870

November 5, 2019

Records Access Officer
New York City Department of Health
42-09 28th Street, 14th Floor CN 31
Long Island City, New York 10013

Re: Freedom of Information Request
59-69 Bartlett Street/84-100 Throop Avenue/90-100 Gerry Street
Block 2269, Lot Nos. 25, 27, 28, 29, 30, 31, 33, 35, and 36
Brooklyn, New York 11206

Dear Sir or Madam:

Our firm has been retained to prepare an Environmental Assessment for the above-referenced properties.

We are respectfully requesting information regarding any flammable storage permits, chemical or petroleum storage, spills, registered above or underground storage tanks, air discharge permits, investigations of environmental concern (e.g. asbestos, lead paint), etc. for the facility.

We agree with the department's decision to omit any health or personal identification in records provided.

If you require additional information to respond to this request or if there are costs associated with same, please do not hesitate to contact me. Thank you for your cooperation.

Sincerely,

Environmental Business Consultants

Keith Butler
Senior Project Manager

Contact E-Mail: kdbk@verizon.net

Type of Record(s) Requested:* Other

Description of Record(s) Requested:*

Tank closure reports of other documentation related to PBS No. 2-601810 Four 550-gallon USTs removed in March 1994.

Spill No. 04-11773 - 90-92 Gerry Street, Brooklyn 2/3/2005 and closed 6/26/2008.

NYSDEC Office processing the Request:*

- ○ Central Office (Albany) Covers the entire state
- ○ Region 1: (Long Island) Covers the counties of: Nassau and Suffolk
- ● Region 2: (New York City) Covers the counties of: Brooklyn, Bronx, Manhattan, Queens and Staten Island
- ○ Region 3: (Lower Hudson Valley) Covers the counties of: Dutchess, Orange, Putnam, Rockland, Sullivan, Ulster and Westchester
- ○ Region 4: (Capital Region/Northern Catskills) Covers the counties of: Albany, Columbia, Delaware, Greene, Montgomery, Otsego, Rensselaer, Schenectady and Schoharie
- ○ Region 5: (Eastern Adirondacks/Lake Champlain) Covers the counties of: Clinton, Essex, Franklin, Fulton, Hamilton, Saratoga, Warren and Washington
- ○ Region 6: (Western Adirondacks/Eastern Lake Ontario) Covers the counties of: Herkimer, Jefferson, Lewis, Oneida and St. Lawrence
- ○ Region 7: (Central New York) Covers the counties of: Broome, Cayuga, Chenango, Cortland, Madison, Onondaga, Oswego, Tioga and Tompkins
- ○ Region 8: (Western Finger Lakes) Covers the counties of: Chemung, Genesee, Livingston, Monroe, Ontario, Orleans, Schuyler, Seneca, Steuben, Wayne and Yates
- ○ Region 9: (Western New York) Covers the counties of: Allegany, Chautauqua, Cattaraugus, Erie, Niagara and Wyoming counties

Department of Environmental Conservation

Programs

Outdoor Activities
Animals, Plants, Aquatic Life
Chemical and Pollution Control
Energy and Climate
Lands and Waters

Services

Education
Permit, License, Registration
Public Involvement and News
Regulations and Enforcement
Publications, Forms, Maps

Agency Information

About DEC
Employment
Events Calendar
Commissioner
Freedom of Information Law (FOIL)
Doing Business with DEC

Help

A-Z Subject Index
Contact Us
Report a Problem
Find a Form
Apply for a Grant
Privacy Policy
Website Usage and Policies
Accessibility

Language Assistance

L언어 지원
Èd nan Lang
ইংরেজি
Языковая поддержка
Asistencia de idioma
语言援助

CONNECT WITH US

FACEBOOK TWITTER YOUTUBE FLICKR INSTAGRAM

Reference No: W060696-110519

Contact E-Mail: kdbk@verizon.net

Dear Keith:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 11/5/2019 and given the reference number FOIL #**W060696-110519** for tracking purposes. You may expect the Department's response to your request no later than **12/6/2019**.

Record Requested: **Tank closure reports of other documentation related to PBS No. 2-601810 Four 550-gallon USTs removed in March 1994. Spill No. 04-11773 - 90-92 Gerry Street, Brooklyn 2/3/2005 and closed 6/26/2008.**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

https://mycusthelp.com/NEWYORKDEC/_rs/RequestLogin.aspx (https://mycusthelp.com/NEWYORKDEC/_rs/RequestLogin.aspx)

New York State Department of Environmental Conservation, Record Access Office

Powered by GovQA

Department of Environmental Conservation

Programs

Outdoor Activities
Animals, Plants, Aquatic Life
Chemical and Pollution Control
Energy and Climate
Lands and Waters

Services

Education
Permit, License, Registration
Public Involvement and News
Regulations and Enforcement
Publications, Forms, Maps

Agency Information

About DEC
Employment
Events Calendar
Commissioner
Freedom of Information Law (FOIL)
Doing Business with DEC

Help

A-Z Subject Index
Contact Us
Report a Problem
Find a Form
Apply for a Grant
Privacy Policy
Website Usage and Policies
Accessibility

Language Assistance

L언어 지원
Èd nan Lang
ইংরেজি
Языковая поддержка
Asistencia de idioma
语言援助

CONNECT WITH US

FACEBOOK TWITTER YOUTUBE FLICKR INSTAGRAM

APPENDIX C

HISTORIC INFORMATION

Brooklyn Triangle Site C

90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett S

Brooklyn, NY 11206

Inquiry Number: 5823513.10

October 10, 2019

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

10/10/19

Site Name:

Brooklyn Triangle Site C
90-100 Gerry St,84-100 Throop
Brooklyn, NY 11206
EDR Inquiry # 5823513.10

Client Name:

Env. Business Consultants
1808 Middle Country Road
Ridge, NY 11961
Contact: Keith W Butler

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Env. Business Consultants were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 2E7F-45D5-B6A7

PO # NA

Project SNA1903

Maps Provided:

2007	1995	1982	1935
2006	1993	1981	1918
2005	1992	1980	1904
2004	1991	1979	1887
2003	1989	1977	
2002	1987	1965	
2001	1986	1950	
1996	1984	1947	

Sanborn® Library search results

Certification #: 2E7F-45D5-B6A7

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Env. Business Consultants (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets



Volume 3, Sheet 36

2006 Source Sheets



Volume 3, Sheet 36

2005 Source Sheets



Volume 3, Sheet 36

2004 Source Sheets



Volume 3, Sheet 36

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets



Volume 3, Sheet 36

2002 Source Sheets



Volume 3, Sheet 36

2001 Source Sheets



Volume 3, Sheet 36

1996 Source Sheets

Volume 3, Sheet 36

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1995 Source Sheets



Volume 3, Sheet 36

1993 Source Sheets



Volume 3, Sheet 36

1992 Source Sheets

Volume 3, Sheet 36

1991 Source Sheets

Volume 3, Sheet 36

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1989 Source Sheets



Volume 3, Sheet 36

1987 Source Sheets



Volume 3, Sheet 36

1986 Source Sheets

Volume 3, Sheet 36

1984 Source Sheets

Volume 3, Sheet 36

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1982 Source Sheets

Volume 3, Sheet 36

1981 Source Sheets

Volume 3, Sheet 36

1980 Source Sheets

Volume 3, Sheet 36

1979 Source Sheets

Volume 3, Sheet 36

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1977 Source Sheets

Volume 3, Sheet 36

1965 Source Sheets

Volume 3, Sheet 36

1950 Source Sheets

Volume 3, Sheet 36

1947 Source Sheets

Volume 3, Sheet 36

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1935 Source Sheets

Volume 3, Sheet 36

1918 Source Sheets

Volume 3, Sheet 36

1904 Source Sheets

Volume 3, Sheet 36



Volume 3, Sheet 45

1887 Source Sheets

Volume 3, Sheet 82

Volume 3, Sheet 82

Volume 3, Sheet 83

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 36

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #:	2E7F-45D5-B6A7
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #:	2E7F-45D5-B6A7
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

Volume 3, Sheet 36



N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 36

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

Volume 3, Sheet 36



N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

Volume 3, Sheet 36





N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1984

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

Volume 3, Sheet 36



N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1981

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 36

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1947

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 36

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1935

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 36

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1918

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 36

0 Feet 150 300 600

N

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #	2E7F-45D5-B6A7
Copyright	1904

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 3, Sheet 45
Volume 3, Sheet 36

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #2E7F-45D5-B6A7

Site Name:	Brooklyn Triangle Site C
Address:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett
City, ST, ZIP:	Brooklyn, NY 11206
Client:	Env. Business Consultants
EDR Inquiry:	5823513.10
Order Date:	10/10/2019
Certification #:	2E7F-45D5-B6A7
Copyright	1887

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 3, Sheet 83
Volume 3, Sheet 82
Volume 3, Sheet 82

N

Brooklyn Triangle Site B

31,35-45 Bartlett Street, 68-76 Gerry Street

Brooklyn, NY 11206

Inquiry Number: 5823513.22

October 10, 2019

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

10/10/19

Site Name:	Client Name:
Brooklyn Triangle Site B	Env. Business Consultants
31,35-45 Bartlett Street, 68-76	1808 Middle Country Road
Brooklyn, NY 11206	Ridge, NY 11961
EDR Inquiry # 5823513.22	Contact: Keith W Butler

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2017	1"=500'	Flight Year: 2017	USDA/NAIP
2013	1"=500'	Flight Year: 2013	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 04, 1994	USGS/DOQQ
1991	1"=500'	Flight Date: March 09, 1991	NAPP
1984	1"=500'	Flight Date: March 26, 1984	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1976	1"=500'	Flight Date: October 29, 1976	USGS
1974	1"=500'	Flight Date: October 19, 1974	NOAA
1966	1"=500'	Flight Date: February 23, 1966	USGS
1961	1"=500'	Flight Date: April 12, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: January 04, 1954	USGS
1951	1"=500'	Flight Date: April 21, 1951	EDR Proprietary Aerial Viewpoint
1924	1"=500'	Flight Date: July 01, 1924	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


SITE
INQUIRY #: 5823513.22
YEAR: 2017
= 500'
N
EDR

SITE
INQUIRY #: 5823513.22
YEAR: 2013
= 500'
N
EDR


SITE
INQUIRY #: 5823513.22
YEAR: 2009
= 500'
N
EDR


SITE
INQUIRY #: 5823513.22
YEAR: 2006
= 500'
N
EDR


SITE
INQUIRY #: 5823513.22
YEAR: 1994
= 500'
N
EDR



INQUIRY #: 5823513.22

YEAR: 1991

= 500'

N

EDR

SITE
INQUIRY #: 5823513.22
YEAR: 1984
= 500'
N
EDR

INQUIRY #: 5823513.22

YEAR: 1980

= 500'

N

EDR

INQUIRY #: 5823513.22

YEAR: 1976

= 500'

N

EDR


SITE
INQUIRY #: 5823513.22
YEAR: 1974
= 500'
N
EDR

INQUIRY #: 5823513.22

YEAR: 1966

= 500'

N

EDR

SITE
INQUIRY #: 5823513.22
YEAR: 1961
= 500'
N
EDR

INQUIRY #: 5823513.22

YEAR: 1954

= 500'

N

EDR

INQUIRY #: 5823513.22

YEAR: 1951

= 500'

N

EDR

INQUIRY #: 5823513.22

YEAR: 1924

= 500'

N

EDR

Brooklyn Triangle Site B

31,35-45 Bartlett Street, 68-76 Gerry Street

Brooklyn, NY 11206

Inquiry Number: 5823513.18

October 10, 2019

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

10/10/19

Site Name:

Brooklyn Triangle Site B
31,35-45 Bartlett Street, 68-76
Brooklyn, NY 11206
EDR Inquiry # 5823513.18

Client Name:

Env. Business Consultants
1808 Middle Country Road
Ridge, NY 11961
Contact: Keith W Butler

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Env. Business Consultants were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA
Project: SNA1902

Coordinates:

Latitude:	40.701084 40° 42' 4" North
Longitude:	-73.947024 -73° 56' 49" West
UTM Zone:	Zone 18 North
UTM X Meters:	588956.52
UTM Y Meters:	4506108.49
Elevation:	14.00' above sea level

Maps Provided:

2013	1897
1995	
1979	
1967	
1956	
1947	
1900	
1898	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2013 Source Sheets

Brooklyn

7.5-minute, 24000

1995 Source Sheets

Brooklyn

7.5-minute, 24000
Aerial Photo Revised 1977

1979 Source Sheets

Brooklyn

7.5-minute, 24000
Aerial Photo Revised 1977

1967 Source Sheets

Brooklyn

7.5-minute, 24000
Aerial Photo Revised 1966

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1956 Source Sheets

Brooklyn

7.5-minute, 24000

1947 Source Sheets

Brooklyn

7.5-minute, 24000
Aerial Photo Revised 1940

1900 Source Sheets

Brooklyn

15-minute, 62500

1898 Source Sheets

Brooklyn

15-minute, 62500

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1897 Source Sheets

Brooklyn

15-minute, 62500

Historical Topo Map

2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2013, 7.5-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

N


SITE
Greenpoint
Williamsburg
Port Greene
Bedford
Adelphi
BROOKLYN
Bedford-Stuyvesant
RIVER
Maspeth Cr
English Kills
Newtown Creek
Dutch Kills
Radio Towers (WEVB)
Cooper Park
McCarren Park
Tompkins Park
Fulton Park
McGolrick Park
Bushwick Yards
Dept of Pub Works
Powerplant
Armory
Library
Hospital
Police Sta
Fire Sta
Playground
Park
Sta
PO
Williamsburg Bridge
Wallabout Channel
Navy Yard Basin
NEW YORK SHIPYARD
Brooklyn High Sch of Auto Trades
Holy Family Sch
St Stanislaus
St Cecilias Sch
Greenpoint Hosp
Mt Carmel Hall
St Francis Sch
Eli Whitney Voc High Sch
McCaddin Sch
Hebrew Sch
Beth Jacob Seminary
St Marys Sch
Trinity High Sch
Eastern Dist High Sch
McKibbin Playground
St Nicholas Sch
St Leonards Sch
Bushwick Park
Cook Sch
NYC Community College
St Patricks Academy
Pratt Institute
St Josephs College for Women
St Josephs Hall
St Johns Prep Sch
Manorah Hosp
Jr Academy
Adelphi Academy
Bishop Loughlin High Sch
Boys High Sch
Girls High Sch
Home for Blind
Pharmacy College
Rochel Girls Sch
Holy Rosary Sch
St Benedicts Sch
St Josephs Sch
St Johns Hospital
US Naval Clinic
Cumberland Hospital
Flatbush Ave Terminal
Technical High Sch
Greene Park
Bush Park
JHS 126
JHS 49
JHS 50
JHS 148
JHS 33
JHS 57
JHS 258
JHS 35
JHS 111
JHS 274
PS 110
PS 132
PS 17
PS 18
PS 19
PS 16
PS 122
PS 250
PS 147
PS 123
PS 145
PS 26
PS 196
PS 57
PS 168
PS 297
PS 59
PS 157
PS 23
PS 304
PS 79
PS 25
PS 81
PS 34
PS 117
PS 20
PS 87
PS 44
PS 305
PS 3
PS 93
PS 262
PS 309
PS 5
PS 21
PS 40
PS 28
PS 24
PS 120
Bklyn Navy Yard
Bklyn Community College
Bklyn Technical High Sch
Bklyn Hospital
Bklyn Navy Yard Hospital
Bklyn Navy Yard Sta
Bklyn Navy Yard Armory
Bklyn Navy Yard Powerplant
Bklyn Navy Yard Dept of Pub Works
Bklyn Navy Yard Police Sta
Bklyn Navy Yard Fire Sta
Bklyn Navy Yard Playground
Bklyn Navy Yard Park
Bklyn Navy Yard Sta
Bklyn Navy Yard PO
Bklyn Navy Yard Library
Bklyn Navy Yard Armory

Historical Topo Map

1979



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1979, 7.5-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

N

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1967, 7.5-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

N



This report includes information from the following map sheet(s).





TP, Brooklyn, 1956, 7.5-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

Historical Topo Map

1947

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1947, 7.5-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

N

Historical Topo Map

1900

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1900, 15-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

N

Historical Topo Map

1898

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1898, 15-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1897, 15-minute

SITE NAME: Brooklyn Triangle Site B
ADDRESS: 31,35-45 Bartlett Street, 68-76 Gerry Stre
Brooklyn, NY 11206
CLIENT: Env. Business Consultants

N

Brooklyn Triangle Site C
90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett S
Brooklyn, NY 11206

Inquiry Number: 5823513.12
October 10, 2019

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through 2014. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2014	EDR Digital Archive	-	X	X	-
2010	EDR Digital Archive	-	X	X	-
2005	Hill-Donnelly Corporation	-	X	X	-
2000	Cole Information Services	-	X	X	-
	Cole Information Services	X	X	X	-
1997	NYNEX	-	X	X	-
	NYNEX	X	X	X	-
1992	NYNEX Informantion Resource Co.	-	X	X	-
	NYNEX Informantion Resource Co.	X	X	X	-
1985	NYNEX Information Resources Company	-	X	X	-
	NYNEX Information Resources Company	X	X	X	-
1980	New York Telephone	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1980	New York Telephone	X	X	X	-
1976	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1973	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1970	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1965	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1960	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
	New York Telephone Company	-	X	X	-
	New York Telephone Company	X	X	X	-
1949	New York Telephone Company	-	X	X	-
	New York Telephone Company	X	X	X	-
1945	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1940	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	X	X	X	-
1928	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	***Type***	***Findings***
59 Bartlett Street	Client Entered	X
69 Bartlett Street	Client Entered	
90 Gerry Street	Client Entered	X
100 Gerry Street	Client Entered	
84 Throop Avenue	Client Entered	X
100 Throop Avenue	Client Entered	X

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett S
Brooklyn, NY 11206

FINDINGS DETAIL

Target Property research detail.

BARLET st

59 BARLET st

Year	*Uses*	*Source*
1973	Cid Carmen Mrs	New York Telephone

BARTLETT

59 BARTLETT

Year	*Uses*	*Source*
1976	DIDI TOMASA	New York Telephone
	SANTIAGO J	New York Telephone
1960	ANDRILLON JULIA	New York Telephone
	NAVARRO JOHN	New York Telephone
1934	ALPERT MONROE CLK R	R. L. Polk & Co.
	ALPERT MORRIS CHAUT H	R. L. Polk & Co.
	BECK HARRY CHAUF H	R. L. Polk & Co.
	GELLER DORA FNSHR R	R. L. Polk & Co.
	GLASSER LOUIS DRIVER H	R. L. Polk & Co.
	GOLDBERG HELEN STEN R	R. L. Polk & Co.
	GOLDBERG JOS E BAKER H	R. L. Polk & Co.
	H	R. L. Polk & Co.
	HELLER ABR STUDENT R	R. L. Polk & Co.
	HELLER ISAAC CIGARS	R. L. Polk & Co.
	LISPENER PUDNA H	R. L. Polk & Co.
	LUGO CONSUELO R	R. L. Polk & Co.
	MEVISSON THEO CHAUF H	R. L. Polk & Co.
	ORTEGA HARRY PNTR H	R. L. Polk & Co.
	RACHEVSKY JACK FURRIER R	R. L. Polk & Co.
	RODRIQUEZ LUCANO LAB H	R. L. Polk & Co.
	SCHEPPS ABR CLK R	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	SCHEPPS ISAAC H	R. L. Polk & Co.
	SEGARRA MANUEL FURRIER R	R. L. Polk & Co.
	SEGARRA PAUL BUS BOY R	R. L. Polk & Co.
	SEGARRA RALPH DYOR R	R. L. Polk & Co.
	SHERMAN MORIS WASTE	R. L. Polk & Co.
	TAUB GLADYS FUISHR H	R. L. Polk & Co.
	TAUB GOLDIE DRSMKR R	R. L. Polk & Co.
	TAUB SAUL PLMBR R	R. L. Polk & Co.
	TORRES PETER DYER R	R. L. Polk & Co.
	WEINER CHAUF H	R. L. Polk & Co.

63 BARTLETT

Year	Uses	Source
1980	WALLE JESUS	New York Telephone
1976	CASIANO CARMEN	New York Telephone
	CORTEZ LEONIDA	New York Telephone
1960	MELENDEZ GENARA	New York Telephone
	RIVERA RAYMOND	New York Telephone
1934	BARKAN IKE BLDG MASON H	R. L. Polk & Co.
	BARKAN MAX R	R. L. Polk & Co.
	BART JULIUS ELEC SUPPLIES R	R. L. Polk & Co.
	BART MORRIS H	R. L. Polk & Co.
	BART SAML MGR R	R. L. Polk & Co.
	BART SARAH STEN R	R. L. Polk & Co.
	BARTH SAML H	R. L. Polk & Co.
	BROOKS ABR SHOE	R. L. Polk & Co.
	BROOKS JOS SLSMN R	R. L. Polk & Co.
	BROOKS SAML CLK R	R. L. Polk & Co.
	H	R. L. Polk & Co.
	HAUSER SAML OPR H	R. L. Polk & Co.
	JANOFSKY ISIDORE CLK R	R. L. Polk & Co.
	JANOFSKY JOS SLSMN H	R. L. Polk & Co.
	KUSLANSKY MORRIS H	R. L. Polk & Co.
	NAVARRA ECCLESIASTICO COOK H	R. L. Polk & Co.
	SELFERT ABR CARP H	R. L. Polk & Co.
	SKURNIK	R. L. Polk & Co.
	STONE WM SLSMN H	R. L. Polk & Co.
	WALLACE RUBIN SLSMN H	R. L. Polk & Co.

FINDINGS

65 BARTLETT

Year	Uses	Source
1992	A WILLIAMS TRUCKING & TRENCHING INC	NYNEX Informantion Resource Co.
1985	WILLIAMS A	NYNEX Information Resources Company
1934	GURAIN MORRIS CONFR H DO	R. L. Polk & Co.
	GURIAN MORRIS STATIONERY H DO	R. L. Polk & Co.

67 BARTLETT

Year	Uses	Source
1934	SHAPIRO MAX CLNR	R. L. Polk & Co.
	TAILOR	R. L. Polk & Co.

BARTLETT ST

59 BARTLETT ST

Year	Uses	Source
1973	Nieves Iris	New York Telephone
	Santiago E	New York Telephone
1970	Cid Carmen Mrs	New York Telephone
1965	Cid Carmen Mrs	New York Telephone
	Feliciano Thos P	New York Telephone
1960	Cid Carmen Mrs	New York Telephone Company
	Feliciano Thos P	New York Telephone Company
	Perez Gennaro	New York Telephone Company
1949	Cohen Louis	New York Telephone Company
	Gonchor Phillip	New York Telephone Company
1945	Cohen Esther	New York Telephone
1940	Antin	New York Telephone
	Goldstein Esther Mrs	New York Telephone

63 BARTLETT ST

Year	Uses	Source
1973	Lasscille Domingo	New York Telephone
	Maldonado Ivan	New York Telephone
1970	Melendez Javaer	New York Telephone
	Perez Anibal b	New York Telephone
	Rodriguez Maria	New York Telephone
1965	Feliciano Marie	New York Telephone
	Ketzko Nicholas	New York Telephone
1960	Arguelles Elisa	New York Telephone Company

FINDINGS

Year	Uses	Source
1960	Bugarin Max	New York Telephone Company
	Diaz Carmen	New York Telephone Company
	Feliciano Marie	New York Telephone Company
	Ketzko Nicholas	New York Telephone Company
	Malachowsky John	New York Telephone Company
	Montalvo Raymond	New York Telephone Company
1949	Brooks Aba	New York Telephone Company
	Coloma Henry B	New York Telephone Company
	Feldman Sarah	New York Telephone Company
	Gonzalez Andrea Miss	New York Telephone Company
1945	Brooks Abe	New York Telephone
	Negron Mary Mrs	New York Telephone
1940	Brooks Abe	New York Telephone

65 BARTLETT ST

Year	Uses	Source
2000	A TRCKNG & TRNCHNG	Cole Information Services
1997	A Willarns Trucking & Trecking Inc	NYNEX
1970	Corso Brothers Auto Collision Shop	New York Telephone
1940	Pollinger Minnie Mrs statnry	New York Telephone

Bartlett Street

59 Bartlett Street

Year	Uses	Source
1976	DIDI TOMASA	New York Telephone
	SANTIAGO J	New York Telephone
1973	Nieves Iris	New York Telephone
	Santiago E	New York Telephone
1970	Cid Carmen Mrs	New York Telephone
1965	Cid Carmen Mrs	New York Telephone
	Feliciano Thos P	New York Telephone
1960	ANDRILLON JULIA	New York Telephone
	NAVARRO JOHN	New York Telephone
	Cid Carmen Mrs	New York Telephone Company
	Feliciano Thos P	New York Telephone Company
	Perez Gennaro	New York Telephone Company
1949	Cohen Louis	New York Telephone Company
	Gonchor Phillip	New York Telephone Company

FINDINGS

Year	Uses	Source
1945	Cohen Esther	New York Telephone
1940	Antin	New York Telephone
	Goldstein Esther Mrs	New York Telephone
1934	ALPERT MONROE CLK R	R. L. Polk & Co.
	ALPERT MORRIS CHAUT H	R. L. Polk & Co.
	BECK HARRY CHAUF H	R. L. Polk & Co.
	GELLER DORA FNSHR R	R. L. Polk & Co.
	GLASSER LOUIS DRIVER H	R. L. Polk & Co.
	GOLDBERG HELEN STEN R	R. L. Polk & Co.
	GOLDBERG JOS E BAKER H	R. L. Polk & Co.
	H	R. L. Polk & Co.
	HELLER ABR STUDENT R	R. L. Polk & Co.
	HELLER ISAAC CIGARS	R. L. Polk & Co.
	LISPENER PUDNA H	R. L. Polk & Co.
	LUGO CONSUELO R	R. L. Polk & Co.
	MEVISSON THEO CHAUF H	R. L. Polk & Co.
	ORTEGA HARRY PNTR H	R. L. Polk & Co.
	RACHEVSKY JACK FURRIER R	R. L. Polk & Co.
	RODRIQUEZ LUCANO LAB H	R. L. Polk & Co.
	SCHEPPS ABR CLK R	R. L. Polk & Co.
	SCHEPPS ISAAC H	R. L. Polk & Co.
	SEGARRA MANUEL FURRIER R	R. L. Polk & Co.
	SEGARRA PAUL BUS BOY R	R. L. Polk & Co.
	SEGARRA RALPH DYOR R	R. L. Polk & Co.
	SHERMAN MORIS WASTE	R. L. Polk & Co.
	TAUB GLADYS FUISHR H	R. L. Polk & Co.
	TAUB GOLDIE DRSMKR R	R. L. Polk & Co.
	TAUB SAUL PLMBR R	R. L. Polk & Co.
	TORRES PETER DYER R	R. L. Polk & Co.
	WEINER CHAUF H	R. L. Polk & Co.

69 Bartlett Street

Year	Uses	Source

FINDINGS

BARTLT st

59 BARTLT st

Year	Uses	Source
1973	Didi Temas	New York Telephone
	Mendez Antonio	New York Telephone
1970	Didi Tomasa	New York Telephone
	Mendez Antonio	New York Telephone
	Quitos Albino	New York Telephone

BARTLT St

59 BARTLT St

Year	Uses	Source
1965	Almodovar Adolfo	New York Telephone
	Quitos Albino	New York Telephone

63 BARTLT St

Year	Uses	Source
1965	Melendez Genara	New York Telephone

65 BARTLT St

Year	Uses	Source
1965	Cruz Ralph b	New York Telephone

GERRY

90 GERRY

Year	Uses	Source
1985	NU CREATIVE TONES CO INC	NYNEX Information Resources Company
1980	NU CREATIVE LILEC TONES CO INC	New York Telephone
1976	MARTINEZ MARIA M MRS	New York Telephone
1934	ESTREICH LOUIS BKPR R	R. L. Polk & Co.
	ESTREICH MAX TAILOR H	R. L. Polk & Co.
	MORRELL STELLA H	R. L. Polk & Co.
	RESNICK JACK H	R. L. Polk & Co.

92 GERRY

Year	Uses	Source
1976	LIBBY INC	New York Telephone
1960	M & G EXPRT CLOTHING CO INC	New York Telephone

Year	Uses	Source
1960	M & G TRADG	New York Telephone
	R R R BLOUSE & SPORTSWR CO	New York Telephone
1934	GERRY DRESS CO LADIES DRESSE CONTR	R. L. Polk & Co.
	ROSEN BROS NEWS AGENCY INC SAML ROSEN PRES-TREAS NATHANIEL ROSEN SEC	R. L. Polk & Co.
	ROSEN NATHANIEL SEE ROSEN BROS NEWS AGENCY INC	R. L. Polk & Co.
	ROSEN SAML PRES-TREAS ROSEN BROS NEWS AGENCY INC	R. L. Polk & Co.

GERRY ST

90 GERRY ST

Year	Uses	Source
1973	Martinez Maria M Mrs	New York Telephone
	Saldana Frank	New York Telephone
1970	Martinez Maria M Mrs	New York Telephone
1965	Martinez Maria M Mrs	New York Telephone

92 GERRY ST

Year	Uses	Source
1973	Libby Inc	New York Telephone
1970	Libby Inc	New York Telephone
1965	Libby Inc	New York Telephone
	M & G Exprt Clothing Co Inc	New York Telephone
	M & G Tradg	New York Telephone
1960	M & G Exprt Clothing Co Inc	New York Telephone Company
	M & G Tradg	New York Telephone Company
	R R R Blouse & Sportswr Co	New York Telephone Company
1945	Gerry Mfg Corp ladies spclts	New York Telephone
1940	Gerry Dress Co	New York Telephone

Gerry Street

90 Gerry Street

Year	Uses	Source
1985	NU CREATIVE TONES CO INC	NYNEX Information Resources Company
1980	NU CREATIVE LILEC TONES CO INC	New York Telephone
1976	MARTINEZ MARIA M MRS	New York Telephone
1973	Martinez Maria M Mrs	New York Telephone

FINDINGS

Year	Uses	Source
1973	Saldana Frank	New York Telephone
1970	Martinez Maria M Mrs	New York Telephone
1965	Martinez Maria M Mrs	New York Telephone
1934	ESTREICH LOUIS BKPR R	R. L. Polk & Co.
	ESTREICH MAX TAILOR H	R. L. Polk & Co.
	MORRELL STELLA H	R. L. Polk & Co.
	RESNICK JACK H	R. L. Polk & Co.

100 Gerry Street

Year	Uses	Source

GERY

92 GERY

Year	Uses	Source
1949	Arglass Handbag Co	New York Telephone Company
	Helene Modes Inc	New York Telephone Company
	Kopeloff Geo	New York Telephone Company
	Leder & Klahr junk	New York Telephone Company
1945	Leder & Klahr junk	New York Telephone
	Thermo Craft Press	New York Telephone

THROOP

84 THROOP

Year	Uses	Source
1934	STEPCHUCK SAML PRSMN H	R. L. Polk & Co.

THROOP AAV

92 THROOP AAV

Year	Uses	Source
1934	MELE SOPHINE DRSMKR H	R. L. Polk & Co.

THROOP AVE

84 THROOP AVE

Year	Uses	Source
1976	MARRERO S GROCRY STORE	New York Telephone
	SANTIAGO LEONIDES S	New York Telephone

FINDINGS

Year	Uses	Source
1973	Calderon Raul	New York Telephone
1970	Calderon Raul	New York Telephone
1965	Aponte Ana M Mrs	New York Telephone
1960	SAEZ MICHL E	New York Telephone
	SAEZ WILSON B	New York Telephone
	ZARIN HERBERT	New York Telephone
	Saez Michl E	New York Telephone Company
	Saez Wilson b	New York Telephone Company
	Zarin Herbert	New York Telephone Company
1949	Honig Geo Co ins	New York Telephone Company
	Landesberg Engnrng Co	New York Telephone Company
	Landesberg Sewing Machine Co	New York Telephone Company
	Marland Lead Seal Co	New York Telephone Company
	Simchik Alice B	New York Telephone Company
1945	Landesberg Engnrng Co	New York Telephone
	Landesberg Sewing Machine Co	New York Telephone
	Marland Lead Seal Co	New York Telephone
	Schneider Sol	New York Telephone
1934	ANDREYKO STEVEN BAKER H	R. L. Polk & Co.
	ANDREYKO THEO WALTER R	R. L. Polk & Co.
	LANDESBERG ENGINEERING CO INC SAML LANDESBERG PRESTREAS ELEC CONTR	R. L. Polk & Co.
	LANDESBERG SAML PRES-TREAS LANDESBERG ENGINEERING CO INC	R. L. Polk & Co.
1928	BLACK DAVID R	New York Telephone
	LANDESBERG ENGINEERING CO ELEC CONTG	New York Telephone
	LANDESBERG MARTIN M ELEC CONTR	New York Telephone

86 THROOP AVE

Year	Uses	Source
1976	LOPEZ EUFEMIA	New York Telephone
1973	Diaz Luis	New York Telephone
1970	Belardo Jose E	New York Telephone
1965	Ferran Ernest	New York Telephone
1960	FERRAN ERNEST	New York Telephone
	Ferran Ernest	New York Telephone Company
1934	ASNASS ANNA H	R. L. Polk & Co.
	ASNASS LANARD CLK R	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	BELSKY BEATRICE OPR R	R. L. Polk & Co.
	BELSKY EVA H	R. L. Polk & Co.
	BISCEGLIA GERARDO ICE DLR	R. L. Polk & Co.
	FINKELSTEIN LENA FINSISHER R	R. L. Polk & Co.
	FINKELSTEIN SADIE H	R. L. Polk & Co.
	FINKLESTEIN LENA DRSMKR R	R. L. Polk & Co.
	HAWNELOK PETER H	R. L. Polk & Co.
	MACH OPR R	R. L. Polk & Co.
	ROSEN A NATHAN PHYS & SURG	R. L. Polk & Co.
	ROSEN NATHANIEL A PHYS	R. L. Polk & Co.
1928	ASNASS ANNA MRS R	New York Telephone

88 THROOP AVE

Year	Uses	Source
1976	BELARDO JOSE E	New York Telephone
1973	Belardo Jose E	New York Telephone
	Martinez L	New York Telephone
	Molina Andrea	New York Telephone
1934	JENSEN BAKER H	R. L. Polk & Co.
	LENARD BARNEY MFR H	R. L. Polk & Co.
	SAPARTIO JOS H	R. L. Polk & Co.
	SIMPSON DANL IRONWKR H	R. L. Polk & Co.

90 THROOP AVE

Year	Uses	Source
1973	Castro Noida	New York Telephone
1970	Castro Neida	New York Telephone
1960	WIERSTAK PHILIP	New York Telephone
	Wierstak Philip	New York Telephone Company
1934	ALLORO ANTHONY FURRIER H	R. L. Polk & Co.
	BLOTH ANDREW JR STUDENRT R	R. L. Polk & Co.
	DESANTO FRANK MASON H	R. L. Polk & Co.
	STERLING KATH H	R. L. Polk & Co.
	WENZEL WM LNDRYMN H	R. L. Polk & Co.

92 THROOP AVE

Year	Uses	Source
1934	FINKELSTEIN BESSIE BKPR R	R. L. Polk & Co.
	FINKELSTEIN MAX LAB H	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	JACOBSEN JACOB HEATING CONTR H DO	R. L. Polk & Co.
	KLEIN JULIUS H	R. L. Polk & Co.
	MELE ROSE DRSMKR R	R. L. Polk & Co.
	NOVICK PHILIP OPR H	R. L. Polk & Co.
	PERRY LOUIS J SLSMN D JACKSON CO	R. L. Polk & Co.
	WATZ DENNIS LAB H	R. L. Polk & Co.
1928	JACKSON D CO GENL MDSE	New York Telephone

94 THROOP AVE

Year	Uses	Source
1992	UNITED TALMUDICAL ACADEMY	NYNEX Informantion Resource Co.
	UNITED TALMUDICAL ACADEMY INC	NYNEX Informantion Resource Co.
1985	UNITED TALMUDICAL ACADEMY	NYNEX Information Resources Company
	UNITED TALMUDICAL ACADEMY INC	NYNEX Information Resources Company
	UNITED TALMUDICAL ACADEMY TORAH VYIRAH	NYNEX Information Resources Company

96 THROOP AVE

Year	Uses	Source
1976	CAPRI KNITWEAR INC	New York Telephone
	TYROL SPORTWR INC	New York Telephone
1973	Capri Knitwear Inc	New York Telephone
	Tyrol Sportwr Inc	New York Telephone
1970	Capri Knitwear Inc	New York Telephone
	Tyrol Sportwr Inc	New York Telephone
1965	Capri Knitwear Inc	New York Telephone
	Gallo Rose	New York Telephone
	Tyrol Sportwr Inc	New York Telephone
1960	MAY ROSE GARMNTS	New York Telephone
	SUYDAM PANTS CO	New York Telephone
	TYROL SPORTWEAR	New York Telephone
	VALENTIN AIDA STATNRY	New York Telephone
	May Rose Garmnts	New York Telephone Company
	Suydam Pants Co	New York Telephone Company
	Tyrol Sportwear	New York Telephone Company
	Valentin Aida statnry	New York Telephone Company
1949	Goodman Herman ins	New York Telephone Company
	Goodman Travel Agency	New York Telephone Company
	Heller Isaac cgrs	New York Telephone Company

FINDINGS

Year	Uses	Source
1949	Suydam Pants Co	New York Telephone Company
1945	G&R Pants Corp	New York Telephone
	Goodman Herman ins	New York Telephone
	Heller Isaac cgrs	New York Telephone
	Rabinowitz Nathan cts sts	New York Telephone
	Roth Bros pants mfrs	New York Telephone
	Suydam Pants Co	New York Telephone
1940	Becker Morris vests	New York Telephone
	G & R Pants Corp	New York Telephone
	Goodman H & L forgn exch	New York Telephone
	Heller Isaac cgrs	New York Telephone
	Lombardo G coats	New York Telephone
	Roth Bros pants mfrt	New York Telephone
	Suydam Pants Co	New York Telephone
1934	GOODMAN H & L FOREIGN EXCH	R. L. Polk & Co.
	HELLER ISAAC CIGARS	R. L. Polk & Co.
	HOFFMAN & FRIEDFELD PANTS CONTRS	R. L. Polk & Co.
	MODERN MAID FROCK CO DRESS MFRS	R. L. Polk & Co.
	POLLACK & HOLTZ DRESS MFRS	R. L. Polk & Co.
	POLLACK MAX	R. L. Polk & Co.
	ROTHMAN LOUIS PANTS MFR	R. L. Polk & Co.
	SAFT GUTSTEIN & MANCO DRESS CONTRS	R. L. Polk & Co.
	SAFT SAML PANTS CONTR	R. L. Polk & Co.
	SCHWARTZ CARL	R. L. Polk & Co.
	SCIRICA JOS OPR SUIT GUTSTEIN & MANCO	R. L. Polk & Co.
	SHAPIRO HYMAN CLK AND SUIT CONTR	R. L. Polk & Co.
	WEXLER JACOB OPR	R. L. Polk & Co.
	WOLF TOBIAS OPR SOFT GUTSTEIN & MANEO	R. L. Polk & Co.
1928	FRIEDFELD MAX PANTS	New York Telephone
	GOODMAN H & L FOREIGN EXCH	New York Telephone
	HELLER ISAAC CGRS	New York Telephone
	ROTHMAN & OBEL PANTS MFR	New York Telephone
	SLWPSKY BROS & GREEN PANTS CONTR	New York Telephone

FINDINGS

Throop Avenue

84 Throop Avenue

Year	Uses	Source
1976	MARRERO S GROCRY STORE	New York Telephone
	SANTIAGO LEONIDES S	New York Telephone
1973	Calderon Raul	New York Telephone
1970	Calderon Raul	New York Telephone
1965	Aponte Ana M Mrs	New York Telephone
1960	SAEZ MICHL E	New York Telephone
	SAEZ WILSON B	New York Telephone
	ZARIN HERBERT	New York Telephone
	Saez Michl E	New York Telephone Company
	Saez Wilson b	New York Telephone Company
	Zarin Herbert	New York Telephone Company
1949	Honig Geo Co ins	New York Telephone Company
	Landesberg Engnrng Co	New York Telephone Company
	Landesberg Sewing Machine Co	New York Telephone Company
	Marland Lead Seal Co	New York Telephone Company
	Simchik Alice B	New York Telephone Company
1945	Landesberg Engnrng Co	New York Telephone
	Landesberg Sewing Machine Co	New York Telephone
	Marland Lead Seal Co	New York Telephone
	Schneider Sol	New York Telephone
1934	ANDREYKO STEVEN BAKER H	R. L. Polk & Co.
	ANDREYKO THEO WALTER R	R. L. Polk & Co.
	LANDESBERG ENGINEERING CO INC SAML LANDESBERG PRESTREAS ELEC CONTR	R. L. Polk & Co.
	LANDESBERG SAML PRES-TREAS LANDESBERG ENGINEERING CO INC	R. L. Polk & Co.
	STEPCHUCK SAML PRSMN H	R. L. Polk & Co.
1928	BLACK DAVID R	New York Telephone
	LANDESBERG ENGINEERING CO ELEC CONTG	New York Telephone
	LANDESBERG MARTIN M ELEC CONTR	New York Telephone

100 Throop Avenue

Year	Uses	Source
1949	Sunrise Sportwr Co	New York Telephone Company

FINDINGS

THROP AVE

90 THROP AVE

Year	*Uses*	*Source*
1934	BLOTH ANDREW H	R. L. Polk & Co.

TOROOP AVE

92 TOROOP AVE

Year	*Uses*	*Source*
1934	JACKSON D CO GENL MDSE	R. L. Polk & Co.

TROOP AVE

92 TROOP AVE

Year	*Uses*	*Source*
1934	GOLDSTEIN SOL SLSMN D JACKSON CO	R. L. Polk & Co.

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

BARTLETT

46 BARTLETT

Year	Uses	Source
1934	JOSEPHOWITZ YETTA OPR R REAR	R. L. Polk & Co.
	JOSEPHOWITZ MORRIS PRSMN REAR	R. L. Polk & Co.
	JACOBSEN LOUIS CARP H	R. L. Polk & Co.
	JACOBSEN IRVING CTR R	R. L. Polk & Co.
	FELDMAN BENJ H	R. L. Polk & Co.
	MENDELSOHN OSCAR LAB R	R. L. Polk & Co.

48 BARTLETT

Year	Uses	Source
1934	KOSHEYOWSKY WOLF OPR H	R. L. Polk & Co.
	LANGMAN SAML SHIP CLK R	R. L. Polk & Co.
	YEDVOBNICK ABR OPR H	R. L. Polk & Co.
	LEBOWITZ HARRY OPR H	R. L. Polk & Co.
	PEARLMAN	R. L. Polk & Co.
	RABINOWITZ CLK R	R. L. Polk & Co.
	RAFF JOS H	R. L. Polk & Co.
	SCHWARTZ SOL DRIVER H	R. L. Polk & Co.
	SKOLNIK MAX LAB H	R. L. Polk & Co.
	STEIN BERTHA SLSWN R	R. L. Polk & Co.
	STEVENS DOROTHY CLK R	R. L. Polk & Co.
	WAX ALEX BARBER H	R. L. Polk & Co.
	WEBER JACOB INDRYMN H	R. L. Polk & Co.
	WEBER JACOB INDRYMN H	R. L. Polk & Co.
	WILKINSON BETTY DOM R	R. L. Polk & Co.
	WILKINSON JAS OPR R	R. L. Polk & Co.
	WILKINSON ROBT SUPT H	R. L. Polk & Co.
	KLEIN DAVID FURRIER R	R. L. Polk & Co.
	GROSS HYMAN CARRIER PO H	R. L. Polk & Co.
	DEAR MAX OPR H	R. L. Polk & Co.
	COHEN MOLLY R	R. L. Polk & Co.
	BINOWITZ SARAH H	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	BINOWITZ MAX MECH R	R. L. Polk & Co.
	LANGMAN SARAH H	R. L. Polk & Co.

52 BARTLETT

Year	Uses	Source
1934	HERMAN MAX SUPT H	R. L. Polk & Co.
	LEVINE BARNEY GRO H DO	R. L. Polk & Co.
	LEVINE LILLIAN BKPR R	R. L. Polk & Co.
	LEVINE REBECCA BKPR R	R. L. Polk & Co.
	NAFMAN HARRY CARP H	R. L. Polk & Co.
	NAFMAN JOS CLK R	R. L. Polk & Co.
	NAPARSTEK SAML LAB H	R. L. Polk & Co.
	PERSKY LOUIS WINDOW CLNR H	R. L. Polk & Co.
	SEMEL SADIE H	R. L. Polk & Co.
	SLOMOWITZ BENJ SLSMN R	R. L. Polk & Co.
	SLOMOWITZ MARY H	R. L. Polk & Co.
	HANIG DAVID OPR H	R. L. Polk & Co.
	ZUCKERMAN SAML TAILOR H	R. L. Polk & Co.
	GOLDMAN WM OPR H	R. L. Polk & Co.
	DENULLY EDW LAB H	R. L. Polk & Co.
	COOPER SAML H	R. L. Polk & Co.
	BORISKY SARAH MRS R	R. L. Polk & Co.
	BERMAN HYMAN OPR H	R. L. Polk & Co.
	GORDON MRS OPR H	R. L. Polk & Co.

53 BARTLETT

Year	Uses	Source
1960	R & S FOODS	New York Telephone
1934	BERNSTEIN JOE RESTR	R. L. Polk & Co.
	RUBIN JOS RESTR	R. L. Polk & Co.
	SHORE HYMAN BLKSMITH H	R. L. Polk & Co.
	SHORE MAX CARP R	R. L. Polk & Co.
	WERNER JOS ELECTN H	R. L. Polk & Co.

55 BARTLETT

Year	Uses	Source
1992	EXCELLENT BUS SERVICE	NYNEX Informantion Resource Co.
1934	BLOMQUIST CARL INSPR PRES BORO BKN R	R. L. Polk & Co.
	SMITH HARRY PNTR H	R. L. Polk & Co.

Year	Uses	Source
1934	SMITH NATHAN LAB R	R. L. Polk & Co.
	SMITH SARAH R	R. L. Polk & Co.
	WELLSON & CARR MACHS	R. L. Polk & Co.

57 BARTLETT

Year	Uses	Source
1992	GOMEZ MIROSLAVA	NYNEX Informantion Resource Co.
	GELB J	NYNEX Informantion Resource Co.
1985	MEDINA WILFERDO	NYNEX Information Resources Company
1934	BROMBERGER LOUIS H	R. L. Polk & Co.
	FINKELSTEIN ISADOR H	R. L. Polk & Co.
	MOLLICK LOUIS CLNR H DO	R. L. Polk & Co.
	BROMBERGER ESTHER SLSMN R	R. L. Polk & Co.

68 BARTLETT

Year	Uses	Source
1934	EPSTEIN ISIDORE H	R. L. Polk & Co.

71 BARTLETT

Year	Uses	Source
1934	BROWN HARRY LAB H	R. L. Polk & Co.

Bartlett St

51 Bartlett St

Year	Uses	Source
2014	FLORAL EXPRESSIONS USA INC	EDR Digital Archive
	FLORAL EXPRESSIONS USA INC	EDR Digital Archive
2010	FLORAL EXPRESSIONS USA INC	EDR Digital Archive
	FLORAL EXPRESSIONS USA INC	EDR Digital Archive

BARTLETT ST

51 BARTLETT ST

Year	Uses	Source
2005	Newman Jacob	Hill-Donnelly Corporation
1997	FLORES I	NYNEX
1973	Maldonado Jesus	New York Telephone
	Muniz Candida	New York Telephone
1970	Muniz Candida	New York Telephone

Year	Uses	Source
1965	Levy Herman	New York Telephone
1960	Levy Herman	New York Telephone Company
1949	Levy Herman	New York Telephone Company
1945	Siegel Wm	New York Telephone

52 BARTLETT ST

Year	Uses	Source
1949	Schwartz Harry	New York Telephone Company
	Kuslansky Edith C	New York Telephone Company
	Kreger Jack	New York Telephone Company
	Drexler Philip	New York Telephone Company
	Bernstein Jos G	New York Telephone Company
1945	Juris Louis	New York Telephone
	Farbman Louis Mrs	New York Telephone

53 BARTLETT ST

Year	Uses	Source
1973	Vazquez C	New York Telephone
1970	Gonzalez Pascual	New York Telephone

Bartlett St

55 Bartlett St

Year	Uses	Source
2014	EXCELLENT BUS SERVICE INC	EDR Digital Archive
	EXCELLENT BUS SERVICE INC	EDR Digital Archive
2010	EXCELLENT BUS SERVICE INC	EDR Digital Archive
	EXCELLENT BUS SERVICE INC	EDR Digital Archive

BARTLETT ST

55 BARTLETT ST

Year	Uses	Source
2005	Excellent Bus Svc	Hill-Donnelly Corporation
2000	EXCELLENT BUS SVC	Cole Information Services
1997	Excellent Bus Service	NYNEX
1949	Fertobac Fertilizer Co	New York Telephone Company
	NY Tobacco Prods	New York Telephone Company
1940	Ace Plumbing Supl Co	New York Telephone

FINDINGS

Bartlett St

57 Bartlett St

Year	Uses	Source
2014	YUKIMI SONG STUDIO LLC	EDR Digital Archive
	YUKIMI SONG STUDIO LLC	EDR Digital Archive

BARTLETT ST

57 BARTLETT ST

Year	Uses	Source
2005	Smalyk Vasyl	Hill-Donnelly Corporation
	h Druk Olga	Hill-Donnelly Corporation
	Gelb Jeno	Hill-Donnelly Corporation
	h Mateik Volodymyr	Hill-Donnelly Corporation
	Rodriguez Hilda	Hill-Donnelly Corporation
	Aviles Jeffrey	Hill-Donnelly Corporation
1997	ALAMEDA Angela	NYNEX
	GELB Jeno	NYNEX
	GELB Jeno	NYNEX
1970	Bernardo Arocho	New York Telephone

BARTLT st

57 BARTLT st

Year	Uses	Source
1973	Lastra Rogelia	New York Telephone
1970	Lastra Rogelia	New York Telephone

BARTLT St

57 BARTLT St

Year	Uses	Source
1965	Lopez Laura	New York Telephone
	Lastra Rogelia	New York Telephone

GERRY

80 GERRY

Year	Uses	Source
1992	N Y SHANGHAI STOVE INC	NYNEX Informantion Resource Co.

FINDINGS

Year	Uses	Source
1985	LORENZ LUCAS L INC GRNDG	NYNEX Information Resources Company
	SMITH S JOHN E SONS CO	NYNEX Information Resources Company
1980	SMITH S JOHN E SONS CO	New York Telephone
1976	SMITHS JOHN E SONS CO	New York Telephone
	LORENZ LUCAS L INC GRNDG	New York Telephone
1960	LORENZ LUCAS L INC GRNDG	New York Telephone

81 GERRY

Year	Uses	Source
1934	NORMAN HAYMAN CHAUF H	R. L. Polk & Co.
	HABER HARRY SLSMN H	R. L. Polk & Co.
	SEEGER LOUIS LNDRYMN H	R. L. Polk & Co.
	NORMAN NETTLO BKPR R	R. L. Polk & Co.

83 GERRY

Year	Uses	Source
1934	GREENBERG ADOLPH LAB H	R. L. Polk & Co.
	ISAACSON ROSE CLNR H	R. L. Polk & Co.
	LAENGNO FRED FNSHR H	R. L. Polk & Co.
	SHERMAN MAX MOLDER H	R. L. Polk & Co.
	OSTER BLANCHE CLNR R	R. L. Polk & Co.
	OSTER R	R. L. Polk & Co.
	OSTER OPR R	R. L. Polk & Co.
	OSTER ABR LAB R	R. L. Polk & Co.

85 GERRY

Year	Uses	Source
1934	ELLISON ELIAS BKPR H	R. L. Polk & Co.
	COHEN SAML OPR R	R. L. Polk & Co.
	OSIAS R	R. L. Polk & Co.
	COHEN MORRIS OPR R	R. L. Polk & Co.
	SUN NOVELTY CO	R. L. Polk & Co.
	CHEPCARY OSCAR LAB H	R. L. Polk & Co.
	COHEN JOS TAILOR H	R. L. Polk & Co.
	SOLOMON EDDIE CLOAK AND SUIT MKR H	R. L. Polk & Co.

86 GERRY

Year	Uses	Source
1960	ELECTRICAL EQP CO	New York Telephone

FINDINGS

Year	Uses	Source
1934	THOMAS ALMA DOM H	R. L. Polk & Co.
	STPAULS CHURCH OF CHRIST REV J J GREGORY PASTOR	R. L. Polk & Co.
	JEWELL WM REV	R. L. Polk & Co.
	BROWN FRANK LAB H	R. L. Polk & Co.
	ALLEN ALEX PNTR H	R. L. Polk & Co.
	THOMPSON RICHD H	R. L. Polk & Co.
	THOMPSON RICHD CHAUF H	R. L. Polk & Co.
	CASH ELLJAH H	R. L. Polk & Co.
	CASH IRENE R	R. L. Polk & Co.
	JEWELL FREDK LAB R	R. L. Polk & Co.
	JEWELL LILLIAN MAID R	R. L. Polk & Co.

87 GERRY

Year	Uses	Source
1934	KANTOR MORRIS PNTR H	R. L. Polk & Co.
	GOLDSTEIN SOL SLSMN R	R. L. Polk & Co.
	GOLDSTEIN MORRIS MEAT H DO	R. L. Polk & Co.
	BUCHDRUCKER SAM CLK R	R. L. Polk & Co.
	SCHNEIDER H REAR	R. L. Polk & Co.
	BLASZEK SAML PDLR H	R. L. Polk & Co.
	STRYKER FREDK H	R. L. Polk & Co.
	SNYDER FRED H	R. L. Polk & Co.
	BUCHDRUCKER MAX MKR H	R. L. Polk & Co.

88 GERRY

Year	Uses	Source
1992	MARINE SVCE & EQUIPT CORP	NYNEX Informantion Resource Co.
1985	MARINE SVCE & EQUIPT CORP	NYNEX Information Resources Company
1934	WHITE LEROY SHIP CLK R	R. L. Polk & Co.
	WASHINGTON R	R. L. Polk & Co.
	MILLER COLBERT SHIP CLK H	R. L. Polk & Co.
	HARRIS ISAAC H	R. L. Polk & Co.
	BROWN	R. L. Polk & Co.
	BUNDHICK ELI H	R. L. Polk & Co.
	DANIELS EMMETT LAB H	R. L. Polk & Co.
	JONES ANNA R	R. L. Polk & Co.

FINDINGS

89 GERRY

Year	Uses	Source
1960	GERRY LNDRY	New York Telephone
	PRESTIGE LINEN SVCE INC	New York Telephone
1934	WHITE SILVER WET WASH CO INC FERDINAND RESRVATO PRES JOS MARGIOTTA V-PRES	R. L. Polk & Co.

91 GERRY

Year	Uses	Source
1934	FELDER SAML PNTR H	R. L. Polk & Co.
	HUGGARD WILMER DOM R	R. L. Polk & Co.
	FELDER WILFORD SHIP CLK R	R. L. Polk & Co.
	STEVENS JOHN STMFR R	R. L. Polk & Co.
	MARTIN MAE DOM R	R. L. Polk & Co.
	MARTIN FRANK LAB H	R. L. Polk & Co.

93 GERRY

Year	Uses	Source
1960	TAYLOR HELEN REV STDY	New York Telephone
1934	COBLE LESTER DECK HD R RER	R. L. Polk & Co.
	HOBBS AARON DRIVER H	R. L. Polk & Co.
	JONES WALTER LAB H	R. L. Polk & Co.
	CARROLL CURTIS PLMBR H	R. L. Polk & Co.
	LAWRENCE WM LAB H	R. L. Polk & Co.
	MACDUFF LULU H	R. L. Polk & Co.
	MONDROS ROSE H	R. L. Polk & Co.
	TRABERT WM H	R. L. Polk & Co.
	WARTS H	R. L. Polk & Co.

95 GERRY

Year	Uses	Source
1960	WOLGRO PRODS INC	New York Telephone
1934	LARIMORE DELIA H	R. L. Polk & Co.
	LARIMORE CAROLINE R	R. L. Polk & Co.
	FLETCHER EDW J H	R. L. Polk & Co.
	CARBONE VITO H	R. L. Polk & Co.
	CARBONE VITO ICE H DO	R. L. Polk & Co.
	CARBONE ANGELINA DRSMKR R	R. L. Polk & Co.
	CARBONE NICHOLAS ICEMN R	R. L. Polk & Co.
	LARIMORE VIOLA MTS IMPLRS R	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	MCINTYRE DAVID WALTER H	R. L. Polk & Co.
	NICOLA CARBONE LAB R	R. L. Polk & Co.

97 GERRY

Year	Uses	Source
1992	76 THROOP BODY & FENDER SPECIALISTS	NYNEX Informantion Resource Co.
1985	76 THROOP BODY & FENDER SPECIALISTS	NYNEX Information Resources Company
1960	WALKER MALCOM	New York Telephone
	WALKER JUNIOR	New York Telephone
1934	BROWN AMANDA LNDRS H REAS	R. L. Polk & Co.
	BROWN ANNA REAS	R. L. Polk & Co.
	CARROLL MARION MAID R	R. L. Polk & Co.
	DALTON LUCLLA R	R. L. Polk & Co.
	DAVIS RICHD LAB R	R. L. Polk & Co.
	DORSEY ADDIE R	R. L. Polk & Co.
	FLOYD JUSTINA MRS DOM H	R. L. Polk & Co.
	GREEN LENNOX CHAUF H	R. L. Polk & Co.
	MILLER THEO DRIVER R	R. L. Polk & Co.
	MONTI SHELDON LAB R	R. L. Polk & Co.
	MONTI THOS PORTER H	R. L. Polk & Co.
	SMITH JOHN COOK R	R. L. Polk & Co.
	SMITH SIDNEY DRIVER H	R. L. Polk & Co.
	MILLER JESSE CHAUF H	R. L. Polk & Co.
	BECTRON EDW LAB H	R. L. Polk & Co.

99 GERRY

Year	Uses	Source
1960	KINARD CLENDER	New York Telephone
	FORD RICHD A	New York Telephone
	FARROW MAGGIE B	New York Telephone
1934	UNGER DORA INDRS H	R. L. Polk & Co.
	BLOOM BEATRICE SLSWN R	R. L. Polk & Co.
	BLOOM YETTA H	R. L. Polk & Co.
	GERSHANSKY HYMAN H	R. L. Polk & Co.
	JONES FRED H	R. L. Polk & Co.
	ROSE ROSE RESTR	R. L. Polk & Co.
	ROSS MICHL I SHIP CLK R	R. L. Polk & Co.
	ROSS ROSA H	R. L. Polk & Co.

Year	Uses	Source
1934	RYKIN HUGO ICEMN H	R. L. Polk & Co.
	SOLOMON MOE H	R. L. Polk & Co.

102 GERRY

Year	Uses	Source
1992	MAGIC SALES INC	NYNEX Informantion Resource Co.
1976	FURMAN LYDIA	New York Telephone
	MCKIBB STAR ECONOMY DEVELOPMENT	New York Telephone
	MCKIBBS STARS SHOP	New York Telephone
1934	RAM JOHN F POLICE R	R. L. Polk & Co.
	LISKO JOHN LAB H	R. L. Polk & Co.
	ROM JOHN POLICEMN R	R. L. Polk & Co.
	ROM JOSEPHINE H	R. L. Polk & Co.
	ROM ROSE BKPR JOHN T MATCHETT CO R	R. L. Polk & Co.
	SCHWICK HENRY MECH H	R. L. Polk & Co.

GERRY H

81 GERRY H

Year	Uses	Source
1934	NORMAN LOUIS GRO DO	R. L. Polk & Co.

GERRY ST

80 GERRY ST

Year	Uses	Source
1973	Lorenz Lucas L Inc grndg	New York Telephone
	Smiths John E Sons Co	New York Telephone
1970	Smiths John E Sons Co	New York Telephone
	Lorenz Lucas L Inc qrndg	New York Telephone
1965	Smiths John E Sons Co	New York Telephone
	Lorenz Lucas L Inc grndy	New York Telephone
1960	Lorenz Lucas L Inc grndg	New York Telephone Company

86 GERRY ST

Year	Uses	Source
1973	Johnson Folding Gates Inc	New York Telephone
1970	Johnson Folding Gates Inc	New York Telephone
1965	ELECTRICAL EQP CO INC	New York Telephone

Year	Uses	Source
1960	ELECTRICAL EQP CO	New York Telephone Company

88 GERRY ST

Year	Uses	Source
1973	Globe Prince Machinery Movers	New York Telephone

89 GERRY ST

Year	Uses	Source
1970	All Star Shirt Lndry Inc	New York Telephone
	Beverly Lndry	New York Telephone
1965	All Star Shirt Lndry Inc	New York Telephone
	Beverly Lndry	New York Telephone
1960	Gerry Lndry	New York Telephone Company
	Prestige Linen Svce Inc	New York Telephone Company

91 GERRY ST

Year	Uses	Source
1973	C & C Coat Apron Towel & Linen Supf Co Inc	New York Telephone
	Chivily Nicholas J Mrs	New York Telephone
1945	White Silver Wet Wash Co	New York Telephone

93 GERRY ST

Year	Uses	Source
1960	Taylor Helen Rev stdy	New York Telephone Company

Gerry St

95 Gerry St

Year	Uses	Source
2014	M & Z SHEET METAL CORPORATION	EDR Digital Archive
	M & Z SHEET METAL CORPORATION	EDR Digital Archive
2010	M & Z SHEET METAL CORPORATION	EDR Digital Archive
	M & Z SHEET METAL CORPORATION	EDR Digital Archive

GERRY ST

95 GERRY ST

Year	Uses	Source
2005	h Leiby Mchiael	Hill-Donnelly Corporation
1970	Paree Ice Cream Co Inc	New York Telephone

Year	Uses	Source
1970	Cofresi Sales Corp	New York Telephone
1965	Paree Ice Cream Co Inc	New York Telephone
	Cofresi Sales Corp	New York Telephone
1960	Wolgro Prods Inc	New York Telephone Company

Gerry St

97 Gerry St

Year	Uses	Source
2014	GIH KNITWEAR LLC	EDR Digital Archive
	PROFESSIONAL HELP INC	EDR Digital Archive
	GIH KNITWEAR LLC	EDR Digital Archive
	PROFESSIONAL HELP INC	EDR Digital Archive
2010	PROFESSIONAL HELP	EDR Digital Archive
	GIH KNITWEAR LLC	EDR Digital Archive
	PROFESSIONAL HELP	EDR Digital Archive
	GIH KNITWEAR LLC	EDR Digital Archive

GERRY ST

97 GERRY ST

Year	Uses	Source
2005	Garcia Auto Repairs	Hill-Donnelly Corporation
2000	GARCIA AUTO REPAIR	Cole Information Services
1973	United Oil Belting Co	New York Telephone
1970	United Oil Belting Co	New York Telephone
1960	Walker Malcom	New York Telephone Company
	Walker Junior	New York Telephone Company

99 GERRY ST

Year	Uses	Source
1965	Poole Marie	New York Telephone
	Carter Mildred Mrs	New York Telephone
1960	Farrow Maggie B	New York Telephone Company
	Kinard Clender	New York Telephone Company
	Ford Richd A	New York Telephone Company

102 GERRY ST

Year	Uses	Source
1973	Maurano Rooerto Drama Studio	New York Telephone

FINDINGS

Year	Uses	Source
1965	Castillo Jose A	New York Telephone
	Otero Grocry Store	New York Telephone
1940	Eisenberg J plmbng supls	New York Telephone
	Stagg Plumbing Supl Co Inc	New York Telephone

GERY

80 GERY

Year	Uses	Source
1949	Lorenz Lucas L Inc grindng	New York Telephone Company
	Lorenz D F machy	New York Telephone Company
	Smith John E Sons Co machy	New York Telephone Company
1945	Lorenz Lucas L Inc geindng	New York Telephone
	Smith John E Sons Co machy	New York Telephone
1940	Empire Elec Co Inc elec motrs	New York Telephone
	Empire Elec Motor Co reprs	New York Telephone

93 GERY

Year	Uses	Source
1949	Croom Gladys	New York Telephone Company

97 GERY

Year	Uses	Source
1960	Williams Lester	New York Telephone Company
	EVERETT GUSSIE	New York Telephone
	GRANT JANIE E	New York Telephone
	WILLIAMS LESTER	New York Telephone
	Everett Gussie	New York Telephone Company
	Grant Janie E	New York Telephone Company

99 GERY

Year	Uses	Source
1934	UNGER H	R. L. Polk & Co.

102 GERY

Year	Uses	Source
1949	Gregory Julius	New York Telephone Company

FINDINGS

THROON AVE

82 THROON AVE

Year	Uses	Source
1934	KAHANSKY SARAH SLSWN R	R. L. Polk & Co.

THROOP

82 THROOP

Year	Uses	Source
1934	FRANKEL ISRAEL DRUGGIST H DO	R. L. Polk & Co.

THROOP AVE

82 THROOP AVE

Year	Uses	Source
1973	Marreros Grocry Store	New York Telephone
1970	Gonzalez Benjamin	New York Telephone
	Marreros Grocry Store	New York Telephone
1965	Cruz Anna D	New York Telephone
	Santiago Victor	New York Telephone
1960	Jay Bee Grocry	New York Telephone Company
	Perez Alfred	New York Telephone Company
	Schriftman Maury b	New York Telephone Company
	Tessler Solomon Rabbi	New York Telephone Company
	PEREZ ALFRED	New York Telephone
	SCHRIFTMAN MAURY B	New York Telephone
	JAY BEE GROCRY	New York Telephone
	TESSLER SOLOMON RABBI	New York Telephone
1949	Dubin Pauline Mrs	New York Telephone Company
	Dubinsky Benj	New York Telephone Company
	Erdell Jos	New York Telephone Company
	Jay Bee Grocry	New York Telephone Company
	Nefsky Jeanette	New York Telephone Company
	Schriftman Maury b	New York Telephone Company
1945	Erdell Jos	New York Telephone
	Schriftman Maury	New York Telephone
1934	KAHANSKY LILLIAN BKPR R	R. L. Polk & Co.
	KAHANSKY PAUL PDLR H	R. L. Polk & Co.
	KOHANSKY PAUL FRUIT	R. L. Polk & Co.

Year	Uses	Source
1934	RABINOWITZ CTR H	R. L. Polk & Co.
	TENZER BENJ CLK R	R. L. Polk & Co.
	TENZER HELEN OPR R	R. L. Polk & Co.
	TENZER MAX PRSMN H	R. L. Polk & Co.
	TENZER RUTH STEN R	R. L. Polk & Co.
	ZIMLER MAX BAKER H	R. L. Polk & Co.
1928	FRANKEL I DRUGGIST	New York Telephone

87 THROOP AVE

Year	Uses	Source
1976	C & K SVCE STA	New York Telephone
1973	C & K Svce Sta	New York Telephone
1970	C & K Svce Sta	New York Telephone
1965	C & K Svce Sta	New York Telephone
1960	C & K SVCE STA	New York Telephone
	C & K Svce Sta	New York Telephone Company
1949	C & K Svce Sta	New York Telephone Company
1945	C & K Svce Sta	New York Telephone
1940	C & K Svce Sta	New York Telephone

THROOPE AVE

82 THROOPE AVE

Year	Uses	Source
1934	TENZER JOS CLK R	R. L. Polk & Co.

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
102 GERRY	2014, 2010, 2005, 2000, 1997, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
102 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1970, 1960, 1949, 1945, 1934, 1928
102 GERY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
46 BARTLETT	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
48 BARTLETT	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
51 BARTLETT ST	2014, 2010, 2000, 1992, 1985, 1980, 1976, 1940, 1934, 1928
51 Bartlett St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
51 Bartlett St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
52 BARTLETT	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
52 BARTLETT ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1940, 1934, 1928
53 BARTLETT	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
53 BARTLETT ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928
55 BARTLETT	2014, 2010, 2005, 2000, 1997, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
55 BARTLETT ST	2014, 2010, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1934, 1928
55 Bartlett St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
55 Bartlett St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
57 BARTLETT	2014, 2010, 2005, 2000, 1997, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
57 BARTLETT ST	2014, 2010, 2000, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
57 Bartlett St	2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
57 Bartlett St	2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
57 BARTLT St	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
57 BARTLT st	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928
68 BARTLETT	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
71 BARTLETT	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
80 GERRY	2014, 2010, 2005, 2000, 1997, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
80 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1949, 1945, 1940, 1934, 1928
80 GERY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1934, 1928
81 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
81 GERRY H	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
82 THROON AVE	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
82 THROOP	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
82 THROOP AVE	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1940
82 THROOPE AVE	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
83 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
85 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
86 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
86 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1949, 1945, 1940, 1934, 1928
87 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
87 THROOP AVE	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1934, 1928
88 GERRY	2014, 2010, 2005, 2000, 1997, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
88 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
89 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
89 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1949, 1945, 1940, 1934, 1928
91 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
91 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1940, 1934, 1928
93 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
93 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
93 GERY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
95 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
95 Gerry St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
95 Gerry St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
95 GERRY ST	2014, 2010, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1949, 1945, 1940, 1934, 1928
97 GERRY	2014, 2010, 2005, 2000, 1997, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
97 GERRY ST	2014, 2010, 1997, 1992, 1985, 1980, 1976, 1965, 1949, 1945, 1940, 1934, 1928
97 Gerry St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
97 Gerry St	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
97 GERY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
99 GERRY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
99 GERRY ST	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1949, 1945, 1940, 1934, 1928
99 GERY	2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett S	2014, 2010, 2005

APPENDIX D

REGULATORY AGENCY DATABASE REPORT

Brooklyn Triangle Site C
90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett St
Brooklyn, NY 11206

Inquiry Number: 5823513.9s
October 11, 2019

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1386
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

COORDINATES

Latitude (North):	40.7017400 - 40° 42' 6.26''
Longitude (West):	73.9462410 - 73° 56' 46.46''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589024.2
UTM Y (Meters):	4505971.0
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5940597 BROOKLYN, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	LOT 33,TAXBLOCK 2269	69 BARTLETT STREET	NY E DESIGNATION		TP
A2	LOT 35,TAXBLOCK 2269	65 BARTLETT STREET	NY E DESIGNATION		TP
A3	LOT 23,TAXBLOCK 2269	86 GERRY STREET	NY E DESIGNATION		TP
A4	LOT 36,TAXBLOCK 2269	63 BARTLETT STREET	NY E DESIGNATION		TP
A5	LOT 27,TAXBLOCK 2269	84 THROOP AVENUE	NY E DESIGNATION		TP
A6	LOT 24,TAXBLOCK 2269	88 GERRY STREET	NY E DESIGNATION		TP
A7	ON GROUND	90-92 GERRY STREET	NY Spills		TP
A8	LOT 29,TAXBLOCK 2269	88 THROOP AVENUE	NY E DESIGNATION		TP
A9	LOT 30,TAXBLOCK 2269	90 THROOP AVENUE	NY E DESIGNATION		TP
A10	SCIULARA PROP - BART	61 BARTLETT PL	FINDS		TP
A11	GUDDEMI PROPERTY-59	59 BARTLETT PLACE	FINDS		TP
A12	LOT 25,TAXBLOCK 2269	90 GERRY STREET	NY E DESIGNATION		TP
A13	LOT 31,TAXBLOCK 2269	THROOP AVENUE	NY E DESIGNATION	Higher	1 ft.
A14	LOT 28,TAXBLOCK 2269	THROOP AVENUE	NY E DESIGNATION	Higher	1 ft.
A15	DRUM RUN	57 BARTLETT ST	NY Spills	Higher	9, 0.002, SSW
A16	LOT 39,TAXBLOCK 2269	57 BARTLETT STREET	NY E DESIGNATION	Higher	9, 0.002, SSW
A17	LOT 40,TAXBLOCK 2269	55 BARTLETT STREET	NY E DESIGNATION	Higher	34, 0.006, SSW
A18	DRUM RUN	CORNER THROOP AVE AN	NY Spills	Higher	44, 0.008, ESE
A19	BROADWAY TRIANGLE	THROOP AVE / BARTLET	NY Spills	Higher	46, 0.009, East
A20	LOT 41,TAXBLOCK 2269	53 BARTLETT STREET	NY E DESIGNATION	Higher	58, 0.011, SSW
A21	82 THROOP AVENUE	82 THROOP AVENUE	NY VCP	Higher	78, 0.015, NW
A22	LOT 34,TAXBLOCK 2266	82 THROOP AVENUE	NY E DESIGNATION	Higher	78, 0.015, NW
A23	LOT 42,TAXBLOCK 2269	51 BARTLETT STREET	NY E DESIGNATION	Higher	84, 0.016, SSW
A24	LOT 36,TAXBLOCK 2266	99 GERRY STREET	NY E DESIGNATION	Higher	96, 0.018, NW
A25	LOT 37,TAXBLOCK 2266	97 GERRY STREET	NY E DESIGNATION	Higher	96, 0.018, WNW
A26	LOT 38,TAXBLOCK 2266	95 GERRY STREET	NY E DESIGNATION	Higher	102, 0.019, WNW
A27	CON EDISON SERVICE B	49 BARTLET ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Higher	103, 0.020, SSW
A28	LOT 19,TAXBLOCK 2269	82 GERRY STREET	NY E DESIGNATION	Higher	108, 0.020, WSW
A29	LOT 39,TAXBLOCK 2266	93 GERRY STREET	NY E DESIGNATION	Higher	113, 0.021, WNW
A30	RUSS LOUIS	81-87 THROOP AVE	EDR Hist Auto	Lower	121, 0.023, North
A31	CON EDISON SERVICE B	47 BARTLETT ST	RCRA NonGen / NLR, NY MANIFEST	Higher	122, 0.023, SSW
A32	LOT 43,TAXBLOCK 2269	47 BARTLETT STREET	NY E DESIGNATION	Higher	122, 0.023, SSW
A33	PFIZER INC. BROOKLYN	80 GERRY STREET	NY UST	Higher	125, 0.024, WSW
A34	CON EDISON - MANHOLE	78 THROOP AVE	RCRA-LQG	Lower	128, 0.024, NNW
A35	CON EDISON	78 THROOP AVE	NY MANIFEST	Lower	128, 0.024, NNW
A36	78 THROOP AVE	78 THROOP AVENUE	NY UST	Lower	128, 0.024, NNW
A37	CON EDISON - MANHOLE	78 THROOP AVE	NJ MANIFEST	Lower	128, 0.024, NNW
A38	78 THROOP AVE	78 THROOP AVE	NY VCP	Lower	128, 0.024, NNW
A39	UNDERGROUND	78 THROOP AVE	NY Spills	Lower	128, 0.024, NNW

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A40	LOT 40,TAXBLOCK 2266	91 GERRY STREET	NY E DESIGNATION	Higher	128, 0.024, WNW
A41	LOT 47,TAXBLOCK 2266	83 GERRY STREET	NY E DESIGNATION	Higher	139, 0.026, West
A42	LOT 46,TAXBLOCK 2266	83 GERRY STREET	NY E DESIGNATION	Higher	139, 0.026, West
A43	LOT 48,TAXBLOCK 2266	81 GERRY STREET	NY E DESIGNATION, NY MANIFEST	Higher	144, 0.027, West
A44	GERRY PROJECT	81-85 GERRY ST	RCRA NonGen / NLR	Higher	144, 0.027, West
A45	LOT 18,TAXBLOCK 2269	76 GERRY STREET	NY E DESIGNATION	Higher	151, 0.029, WSW
A46	LOT 31,TAXBLOCK 2266	76 THROOP AVENUE	NY E DESIGNATION	Lower	153, 0.029, NNW
B47	LOT 41,TAXBLOCK 2266	GERRY STREET	NY E DESIGNATION	Higher	159, 0.030, WNW
C48	THROOP AVENUE / BART	THROOP AVENUE / BART	NY UST	Higher	172, 0.033, ESE
A49	LOT 45,TAXBLOCK 2269	43 BARTLETT STREET	NY E DESIGNATION	Higher	172, 0.033, SW
D50	CON EDISON SERVICE B	125 GERRY ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	173, 0.033, North
A51	LOT 17,TAXBLOCK 2269	74 GERRY STREET	NY E DESIGNATION	Higher	173, 0.033, WSW
B52	LOT 45,TAXBLOCK 2266	GERRY STREET	NY E DESIGNATION	Higher	177, 0.034, West
B53	LOT 30,TAXBLOCK 2266	74 THROOP AVENUE	NY E DESIGNATION	Lower	178, 0.034, NNW
B54	PFIZER INC BROOKLYN	73 GERRY ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	179, 0.034, West
B55	EMPTY LOT	73-87 GERRY STREET	NY Spills	Higher	179, 0.034, West
B56	LOT 16,TAXBLOCK 2269	GERRY STREET	NY E DESIGNATION	Higher	197, 0.037, WSW
C57	CON EDISON	76 BARTLETT ST	NY MANIFEST	Higher	201, 0.038, East
C58	CON EDISON	76 BARTLETT ST	NJ MANIFEST	Higher	201, 0.038, East
C59	CON EDISON	76 BARTLETT ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	201, 0.038, East
B60	THROOP BUILDINGS	72 THROOP AVE	NJ MANIFEST	Lower	203, 0.038, NNW
B61	CON EDISON	72-74 THROOP AVE & G	NY MANIFEST	Lower	203, 0.038, NNW
B62	CON EDISON	72 THROOP AV	NY MANIFEST	Lower	203, 0.038, NNW
B63	72 THROOP AVENUE	72 THROOP AVENUE	NY VCP	Lower	203, 0.038, NNW
B64	CON EDISON	72-74 THROOP AVE & G	RCRA NonGen / NLR, FINDS, ECHO	Lower	203, 0.038, NNW
B65	CON EDISON	72-74 THROOP AVE & G	NJ MANIFEST	Lower	203, 0.038, NNW
B66	LOT 29,TAXBLOCK 2266	72 THROOP AVENUE	NY E DESIGNATION	Lower	203, 0.038, NNW
B67	THROOP BUILDINGS	72 THROOP AVE	RCRA-LQG, NY MANIFEST	Lower	203, 0.038, NNW
E68	LOT 47,TAXBLOCK 2269	41 BARTLETT STREET	NY E DESIGNATION	Higher	210, 0.040, SW
E69	LOT 11,TAXBLOCK 2272	36 BARTLETT STREET	NY E DESIGNATION	Higher	220, 0.042, SSW
D70	THROOP TRANSMISSION	55 THROOP AVE	EDR Hist Auto	Lower	222, 0.042, NNW
B71	LOT 14,TAXBLOCK 2269	GERRY STREET	NY E DESIGNATION	Higher	233, 0.044, WSW
B72	MAGIC AUTO REPAIR SH	398 WALLABOUT STREET	NY AST	Lower	234, 0.044, NW
B73	LOT 25,TAXBLOCK 2266	398 WALLABOUT STREET	NY E DESIGNATION	Lower	234, 0.044, NW
B74	398 WALLABOUT STREET	398 WALLABOUT ST	NY Spills	Lower	234, 0.044, NW
B75	LOT 24,TAXBLOCK 2266	396 WALLABOUT STREET	NY E DESIGNATION	Lower	234, 0.044, NW
E76	LOT 48,TAXBLOCK 2269	39 BARTLETT STREET	NY E DESIGNATION	Higher	234, 0.044, SW
C77	CON EDISON	95 THROOP AVE	NJ MANIFEST	Higher	236, 0.045, ESE
C78	CON EDISON	95 THROOP AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	236, 0.045, ESE

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
B79	LOT 23,TAXBLOCK 2266	394 WALLABOUT STREET	NY E DESIGNATION	Higher	236, 0.045, NW
B80	LOT 22,TAXBLOCK 2266	392 WALLABOUT STREET	NY E DESIGNATION	Higher	241, 0.046, WNW
B81	LOT 21,TAXBLOCK 2266	390 WALLABOUT STREET	NY E DESIGNATION	Higher	248, 0.047, WNW
B82	390 WALLABOUT STREET	390 WALLABOUT STREET	NY VCP	Higher	248, 0.047, WNW
B83	VENT PIPE	63 GREY ROAD	NY Spills	Higher	252, 0.048, WSW
E84	LOT 49,TAXBLOCK 2269	37 BARTLETT STREET	NY E DESIGNATION	Higher	258, 0.049, SW
B85	LOT 20,TAXBLOCK 2266	388 WALLABOUT STREET	NY E DESIGNATION	Higher	259, 0.049, WNW
B86	LOT 49,TAXBLOCK 2266	GERRY STREET	NY E DESIGNATION	Higher	264, 0.050, West
E87	J&M AUTO SERVICE COR	30 BARTLETT STREET	NY UST	Higher	266, 0.050, SSW
E88	LOT 9,TAXBLOCK 2272	30 BARTLETT STREET	NY E DESIGNATION	Higher	266, 0.050, SSW
B89	LOT 19,TAXBLOCK 2266	386 WALLABOUT STREET	NY E DESIGNATION	Higher	269, 0.051, WNW
B90	386 AND 388 WALLABOU	386 AND 388 WALLABOU	NY VCP	Higher	269, 0.051, WNW
B91	PFIZER INC/GERRY ST	PFIZER INC/GERRY ST	NY LTANKS	Higher	273, 0.052, West
B92	LOT 18,TAXBLOCK 2266	384 WALLABOUT STREET	NY E DESIGNATION	Higher	282, 0.053, WNW
E93	LOT 50,TAXBLOCK 2269	35 BARTLETT STREET	NY E DESIGNATION	Higher	283, 0.054, SW
B94	LOT 17,TAXBLOCK 2266	382 WALLABOUT STREET	NY E DESIGNATION	Higher	297, 0.056, WNW
F95	LOT 45,TAXBLOCK 2272	11 WHIPPLE STREET	NY E DESIGNATION	Higher	299, 0.057, South
F96	11 WHIPPLE STREET	11 WHIPPLE STREET	NY VCP	Higher	299, 0.057, South
B97	PFIZER SITES B AND D	59-71 GERRY ST. AND	NY ENG CONTROLS, NY INST CONTROL, NY VCP	Higher	300, 0.057, WSW
B98	SITE B PFIZER	59-71 GERRY STREET A	NY BROWNFIELDS	Higher	300, 0.057, WSW
C99	ROADWAY	THROUGHP AVE/WHIPPLE	NY Spills	Higher	302, 0.057, SE
D100	WALLABOUT STREET AND	THROOP AVE	NY Spills	Lower	302, 0.057, NNW
D101	CON EDISON - TRANSFO	WALLABOUT ST C 32W T	RCRA-LQG, NY MANIFEST	Lower	303, 0.057, NNW
G102	COMMERCIAL LOT	650 BROADWAY	NY Spills	Higher	309, 0.059, NE
B103	LOT 16,TAXBLOCK 2266	380 WALLABOUT STREET	NY E DESIGNATION	Higher	313, 0.059, WNW
D104	CON EDISON	622 BROADWAY	NY MANIFEST	Lower	315, 0.060, North
D105	CON EDISON SERVICE B	622 BROADWAY	RCRA NonGen / NLR, FINDS	Lower	315, 0.060, North
D106	CON EDISON	622 BROADWAY	NY MANIFEST	Lower	315, 0.060, North
D107	CON EDISON	FRONT OF 622 BROADWA	NY MANIFEST	Lower	315, 0.060, North
D108	CON EDISON SERVICE B	622 BROADWAY	RCRA NonGen / NLR	Lower	315, 0.060, North
C109	CLOSED-LACKOF RECENT	113 THROOP AVE	NY LTANKS	Higher	315, 0.060, ESE
D110	CON EDISON	648 BROADWAY	NY MANIFEST	Higher	316, 0.060, NE
D111	CON EDISON	648 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO	Higher	316, 0.060, NE
D112	CON EDISON	648 BROADWAY	NJ MANIFEST	Higher	316, 0.060, NE
B113	PFIZER INC. SITE BAN	60-66 GERRY STREET	NY UST	Higher	317, 0.060, WSW
B114	ARLINGTON PRESS-191	191 HARRISON AVE	RCRA-LQG, FINDS, ECHO	Higher	317, 0.060, WSW
F115	LOT 46,TAXBLOCK 2272	9 WHIPPLE STREET	NY E DESIGNATION	Higher	318, 0.060, South
E116	LOT 6,TAXBLOCK 2272	24 BARTLETT STREET	NY E DESIGNATION	Higher	326, 0.062, SSW
C117	ALL SAINTS R C CHURC	115 THROOP AVE	NY UST, NY AST	Higher	328, 0.062, ESE

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
D118	SOSA DIAGNOSTIC REPA	620 BROADWAY	NY AST	Lower	329, 0.062, North
B119	CON EDISON MANHOLE:	378 WALLABOUT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	330, 0.062, West
B120	LOT 15,TAXBLOCK 2266	378 WALLABOUT STREET	NY E DESIGNATION	Lower	330, 0.062, West
E121	LOT 147,TAXBLOCK 227	5 WHIPPLE STREET	NY E DESIGNATION	Higher	332, 0.063, South
G122	CON EDISON - MANHOLE	662 BROADWAY	RCRA-LQG, NJ MANIFEST, NY MANIFEST	Higher	335, 0.063, ENE
E123	58 GERRY ST LLC	58 GERRY ST	NY Spills	Higher	337, 0.064, WSW
D124	CON EDISON	BROADWAY & GERRY ST	NJ MANIFEST	Lower	339, 0.064, NNE
D125	CON EDISON	BROADWAY & GERRY ST	RCRA NonGen / NLR	Lower	339, 0.064, NNE
D126	CON EDISON	BROADWAY & GERRY ST	NY MANIFEST	Lower	339, 0.064, NNE
D127	CON EDISON	BROADWAY & GERRY ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	339, 0.064, NNE
D128	CON EDISON	BROADWAY & GERRY ST	NJ MANIFEST	Lower	339, 0.064, NNE
D129	CON EDISON	BROADWAY & GERRY ST	NY MANIFEST	Lower	339, 0.064, NNE
C130	CON EDISON	34 WHIPPLE ST	NY MANIFEST	Higher	345, 0.065, SE
C131	CON EDISON TRANSFORM	34 WHIPPLE ST	RCRA NonGen / NLR	Higher	345, 0.065, SE
E132	LOT 52,TAXBLOCK 2269	31 BARTLETT STREET	NY E DESIGNATION	Higher	346, 0.066, SW
E133	LOT 108,TAXBLOCK 227	BARTLETT STREET	NY E DESIGNATION	Higher	347, 0.066, SSW
B134	LOT 14,TAXBLOCK 2266	376 WALLABOUT STREET	NY E DESIGNATION	Lower	348, 0.066, West
B135	WALLABOUT BUILDINGS	376-382 WALLABOUT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	348, 0.066, West
B136	376-382 WALLABOUT ST	376-382 WALLABOUT ST	NY VCP	Lower	348, 0.066, West
F137	CON EDISON SERVICE B	18 WHIPPLE ST FRONT	RCRA NonGen / NLR, NY MANIFEST	Higher	350, 0.066, SSE
E138	29 BARTLETT STREET	29 BARTLETT STREET	NY Spills	Higher	357, 0.068, SW
E139	29-31 BARTLETT STREE	29-31 BARTLETT STREE	NY AST	Higher	357, 0.068, SW
H140	LOT 33,TAXBLOCK 2250	66 THROOP AVENUE	NY E DESIGNATION	Lower	359, 0.068, NW
H141	VARTEX INSTRUMENT CO	311 WALLABOUT ST	RCRA NonGen / NLR, FINDS, ECHO, NY E DESIGNATION,...	Lower	364, 0.069, NW
H142	LOT 37,TAXBLOCK 2250	311 WALLABOUT STREET	NY E DESIGNATION	Lower	364, 0.069, NW
H143	311-313 WALLABOUT ST	311-313 WALLABOUT ST	NY VCP	Lower	364, 0.069, NW
B144	LOT 43,TAXBLOCK 2250	301 WALLABOUT STREET	NY E DESIGNATION	Lower	366, 0.069, WNW
B145	LOT 38,TAXBLOCK 2250	307 WALLABOUT STREET	NY AST, NY E DESIGNATION	Lower	368, 0.070, NW
F146	LOT 5,TAXBLOCK 2274	16 WHIPPLE STREET	NY E DESIGNATION	Higher	369, 0.070, SSE
B147	LOT 44,TAXBLOCK 2250	299 WALLABOUT STREET	NY E DESIGNATION	Lower	371, 0.070, WNW
B148	299-301 WALLABOUT ST	299-301 WALLABOUT ST	NY VCP	Lower	371, 0.070, WNW
B149	LOT 40,TAXBLOCK 2250	305 WALLABOUT STREET	NY E DESIGNATION	Lower	374, 0.071, WNW
F150	LOT 6,TAXBLOCK 2274	WHIPPLE STREET	NY E DESIGNATION	Higher	377, 0.071, SSE
F151	LOT 1,TAXBLOCK 2274	2 WHIPPLE STREET	NY E DESIGNATION	Higher	381, 0.072, SSE
B152	CON EDISON SERVICE B	372 WALLABOUT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	388, 0.073, West
F153	LOT 49,TAXBLOCK 2272	WHIPPLE STREET	NY E DESIGNATION	Higher	389, 0.074, South
F154	LOT 51,TAXBLOCK 2272	665 FLUSHING AVENUE	NY E DESIGNATION	Higher	393, 0.074, SSW
F155	LOT 52,TAXBLOCK 2272	665 FLUSHING AVENUE	NY E DESIGNATION	Higher	393, 0.074, SSW
H156	LOT 42,TAXBLOCK 2250	WALLABOUT STREET	NY E DESIGNATION	Lower	397, 0.075, WNW

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
B157	CON EDISON	295 WALLABOUT ST	NY MANIFEST	Lower	397, 0.075, WNW
H158	CON EDISON SERVICE B	45 THROOP AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	400, 0.076, NNW
G159	CON EDISON	BARTLETT ST & BROADW	NJ MANIFEST	Higher	401, 0.076, ENE
G160	CON EDISON	BARTLETT ST & BROADW	NY MANIFEST	Higher	401, 0.076, ENE
G161	CON EDISON	BARTLETT ST & BROADW	RCRA NonGen / NLR	Higher	401, 0.076, ENE
F162	LOT 53,TAXBLOCK 2272	663 FLUSHING AVENUE	NY E DESIGNATION	Lower	405, 0.077, SSW
F163	LOT 24,TAXBLOCK 2274	687 FLUSHING AVENUE	NY E DESIGNATION	Higher	410, 0.078, SSE
F164	687 FLUSHING AVENUE	687 FLUSHING AVENUE	NY VCP	Higher	410, 0.078, SSE
E165	PFIZER INC	191 HARRISON AVE	NY E DESIGNATION, NY MANIFEST	Lower	416, 0.079, SW
E166	ARLINGTON PRESS	191 HARRISON AVENUE	NJ MANIFEST	Lower	416, 0.079, SW
F167	TULIP GROVE HOMES	661 FLUSHING AVE	NJ MANIFEST	Lower	418, 0.079, SSW
F168	TULIP GROVE HOMES	661 FLUSHING AVENUE	RCRA-LQG	Lower	418, 0.079, SSW
F169	LOT 54,TAXBLOCK 2272	661 FLUSHING AVENUE	NY E DESIGNATION, NY MANIFEST	Lower	418, 0.079, SSW
F170	661 FLUSHING AVENUE	661 FLUSHING AVENUE	NY VCP	Lower	418, 0.079, SSW
F171	CON EDISON	WHIPPLE ST & FLUSHIN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	422, 0.080, South
I172	CON EDISON - MANHOLE	676 BROADWAY	RCRA-LQG	Higher	422, 0.080, East
I173	CON EDISON - MANHOLE	676 BROADWAY	NY MANIFEST	Higher	422, 0.080, East
C174	EMS BATT 57 @ WOODHU	131 THROOP AVENUE	NY UST	Higher	425, 0.080, SE
C175	CON EDISON	131 THROOP AVE	NY MANIFEST	Higher	425, 0.080, SE
C176	CON EDISON	131 THROOP AVE	NJ MANIFEST	Higher	425, 0.080, SE
C177	EMS BATT 57 @ WOODHU	131 THROOP AVENUE	NY AST	Higher	425, 0.080, SE
C178	CON EDISON	131 THROOP AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	425, 0.080, SE
J179	LOT 45,TAXBLOCK 2250	WALLABOUT STREET	NY E DESIGNATION	Lower	429, 0.081, WNW
H180	LOT 129,TAXBLOCK 225	THROOP AVENUE	NY E DESIGNATION	Lower	429, 0.081, NW
H181	LOT 32,TAXBLOCK 2250	62 THROOP AVENUE	NY E DESIGNATION	Lower	429, 0.081, NW
K182	LOT 1,TAXBLOCK 2266	HARRISON AVENUE	NY E DESIGNATION	Lower	431, 0.082, West
F183	LOT 55,TAXBLOCK 2272	659 FLUSHING AVENUE	NY E DESIGNATION	Lower	432, 0.082, SSW
E184	ACE RAPID CLEANERS	209 HARRISON AVE	EDR Hist Cleaner	Lower	438, 0.083, SSW
E185	HARRISON/YORKTOWN/AC	209 HARRISON AVENUE	NY DRYCLEANERS	Lower	438, 0.083, SSW
E186	ACE RAPID CLEANERS	209 HARRISON AVE	RCRA NonGen / NLR, ICIS, US AIRS, NY MANIFEST	Lower	438, 0.083, SSW
J187	LOT 46,TAXBLOCK 2250	291 WALLABOUT STREET	NY E DESIGNATION	Lower	439, 0.083, WNW
K188	V4821	48 GERRY STREET	RCRA NonGen / NLR, NY MANIFEST	Lower	439, 0.083, WSW
J189	LOT 9,TAXBLOCK 2266	366 WALLABOUT STREET	NY E DESIGNATION	Lower	444, 0.084, West
J190	CON EDISON SERVICE B	366 WALLABOUT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	444, 0.084, West
L191	LOT 3,TAXBLOCK 2272	207 HARRISON AVENUE	NY E DESIGNATION	Lower	451, 0.085, SSW
L192	207 HARRISON AVENUE	207 HARRISON AVENUE	NY VCP	Lower	451, 0.085, SSW
J193	LOT 48,TAXBLOCK 2250	289 WALLABOUT STREET	NY E DESIGNATION	Lower	461, 0.087, WNW
M194	APARTMENT BUILDING	613 BROADWAY	NY Spills	Lower	466, 0.088, North
H195	LOT 29,TAXBLOCK 2250	56 THROOP AVENUE	NY E DESIGNATION	Lower	467, 0.088, NW

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
J196	SERVICE BOX # 7967	285 WALLABOUT ST	NY Spills	Lower	469, 0.089, West
K197	BAIS RUCHEL HIGH SCH	177 HARRISON AVE	RCRA-LQG, NJ MANIFEST, NY MANIFEST	Lower	476, 0.090, WSW
K198	177 HARRISON AVENUE	177 HARRISON AVENUE	NY VCP	Lower	476, 0.090, WSW
L199	MANHOLE #73645	HARRISON AVE NEAR BA	NY Spills	Lower	482, 0.091, SW
L200	BARTLETT ST & HARRIS	BARTLETT STREET/HARR	NY Spills	Lower	482, 0.091, SW
L201	PFIZER INC	11 BARTLETT ST	CORRACTS, RCRA-LQG, RAATS, FINDS, ECHO	Lower	490, 0.093, SW
M202	VAULT 3871	MOORE AND LEONARD ST	NY Spills	Lower	490, 0.093, North
N203	LOT 16,TAXBLOCK 2274	134 THROOP AVENUE	NY E DESIGNATION	Higher	491, 0.093, SE
N204	CON EDISON	701 FLUSHING AVE	NY MANIFEST	Higher	494, 0.094, SE
N205	CON EDISON - SERVICE	701 FLUSHING AVE	RCRA-LQG	Higher	494, 0.094, SE
K206	CON ED - MH 485	GERRY ST & HARRISON	RCRA NonGen / NLR, NY MANIFEST	Lower	498, 0.094, WSW
K207	UNDER GROUND TRANFOR	HARRISON AVE AND GER	NY Spills	Lower	498, 0.094, WSW
H208	LOT 28,TAXBLOCK 2250	54 THROOP AVENUE	NY E DESIGNATION, NY MANIFEST	Lower	498, 0.094, NW
H209	THROOP UNITS LLC	54 THROOP AVE	RCRA-LQG	Lower	498, 0.094, NW
K210	DRUM RUN	GERRY ST & HARRISON	NY Spills	Lower	499, 0.095, WSW
K211	MANHOLE 1144	GERRY ST/HARRISON AV	NY Spills	Lower	499, 0.095, WSW
H212	LOT 25,TAXBLOCK 2250	116 WALTON STREET	NY E DESIGNATION	Lower	505, 0.096, NW
H213	116 WALTON STREET	116 WALTON STREET	NY VCP	Lower	505, 0.096, NW
L214	MANHOLE #42919	THOMPKINS & FLUSHING	NY Spills	Lower	522, 0.099, SSW
L215	CONED MANHOLE #7420	FLUSHING/THOMPKINS	NY Spills	Lower	522, 0.099, SSW
L216	PFIZER INC	11 BARTLETT STREET	NJ MANIFEST	Lower	523, 0.099, SW
L217	PFIZER INC BROOKLYN	11 BARTLETT ST	NY Spills, NY MANIFEST	Lower	523, 0.099, SW
H218	52-56 THROOP AVENUE	52-56 THROOP AVENUE	NY VCP	Lower	524, 0.099, NW
H219	THROOP UNITS LLC	52 THROOP AVE	PA MANIFEST	Lower	524, 0.099, NW
H220	LOT 27,TAXBLOCK 2250	52 THROOP AVENUE	NY E DESIGNATION	Lower	524, 0.099, NW
L221	VAULT 1336 & 1473	FLUSHING AVE & TOMPK	NY Spills	Lower	537, 0.102, SSW
L222	MANHOLE 20779	HARRISON AVE AND FLU	NY Spills	Lower	537, 0.102, SSW
L223	MANHOLE	HARRISON AVE AND FLU	NY Spills	Lower	537, 0.102, SSW
J224	HOO CORP.	94 WALLTON STREET	NY UST	Lower	542, 0.103, WNW
J225	LOT 14,TAXBLOCK 2250	94 WALTON STREET	NY E DESIGNATION	Lower	542, 0.103, WNW
L226	BP SERVICE STATION #	655 FLUSHING AVENUE	NY UST	Lower	547, 0.104, SSW
L227	BP WEST COAST PRODUC	655 FLUSHING AVE	RCRA-SQG	Lower	547, 0.104, SSW
L228	BP WEST COAST PRODUC	655 FLUSHING AVE	NJ MANIFEST	Lower	547, 0.104, SSW
L229	BP WEST COAST PRODUC	655 FLUSHING AVE	NY MANIFEST	Lower	547, 0.104, SSW
L230	P & C SERVICE STATIO	655 FLUSHING AVE	EDR Hist Auto	Lower	547, 0.104, SSW
L231	AMOCO	655 FLUSHING AVE	NY Spills	Lower	547, 0.104, SSW
I232	VS 2973	WIPPLE ST/BROADWAY	NY Spills	Higher	550, 0.104, East
L233	TRANSFORMER VAULT 14	2 TOMPKINS AVE AT FL	NY Spills	Lower	556, 0.105, SSW
L234	CON EDISON - VAULT 1	2 TOMPKINS AVE	RCRA-LQG	Lower	556, 0.105, SSW

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
L235	CON EDISON	2 TOMPKINS AVE	RCRA NonGen / NLR	Lower	556, 0.105, SSW
L236	CON EDISON	2 TOMPKINS AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	556, 0.105, SSW
L237	CON EDISON	2 TOMPKINS AVE	NJ MANIFEST	Lower	556, 0.105, SSW
L238	CON EDISON	2 TOMPKINS AVE	NY MANIFEST	Lower	556, 0.105, SSW
L239	CON EDISON - VAULT 1	2 TOMPKINS AVE	NY MANIFEST	Lower	556, 0.105, SSW
L240	CON EDISON	2 TOMPKINS AVE	NJ MANIFEST	Lower	556, 0.105, SSW
N241	MANHOLE #1000	THRO0P AVE & FLUSHIN	NY Spills	Higher	562, 0.106, SE
N242	MANHOLE 7898	THORNTON & THROOP AV	NY Spills	Higher	565, 0.107, SE
N243	WOODHULL LAUNDROMAT	698 FLUSHING AVE	EDR Hist Cleaner	Higher	581, 0.110, SE
K244	MANHOLE 468	WALLABOUT ST/HARRISO	NY Spills	Lower	588, 0.111, West
K245	CON EDISON SERVICE B	HARRISON AVE & WALLA	RCRA NonGen / NLR, NY MANIFEST	Lower	588, 0.111, West
K246	CON EDISON	HARRISSON & WALLABOU	NY MANIFEST	Lower	588, 0.111, West
K247	CON EDISON	HARRISSON & WALLABOU	NJ MANIFEST	Lower	588, 0.111, West
K248	CON EDISON	HARRISSON & WALLABOU	RCRA NonGen / NLR, FINDS, ECHO	Lower	588, 0.111, West
N249	CON EDISON	THROOP AVE & FLUSHIN	RCRA NonGen / NLR, FINDS, ECHO	Higher	591, 0.112, SE
N250	CON EDISON	THROOP AVE & FLUSHIN	NJ MANIFEST	Higher	591, 0.112, SE
J251	LOT 12,TAXBLOCK 2250	90 WALTON STREET	NY E DESIGNATION	Lower	592, 0.112, WNW
I252	CON EDISON SERVICE B	12 MANHATTAN AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	594, 0.112, ENE
L253	MEL-BERN NUMBER FOUR	645 FLUSHING AVE	EDR Hist Auto	Lower	596, 0.113, SSW
N254	709-715 FLUSHING AVE	709-715 FLUSHING AVE	NY AST	Higher	601, 0.114, ESE
J255	LOT 10,TAXBLOCK 2250	88 WALTON STREET	NY RES DECL, NY E DESIGNATION	Lower	605, 0.115, WNW
J256	88 WALTON STREET	88 WALTON STREET	NY VCP	Lower	605, 0.115, WNW
K257	LOT 37,TAXBLOCK 2249	174 HARRISON AVENUE	NY E DESIGNATION	Lower	610, 0.116, West
M258	DRUM RUN	BROADWAY & WALTON ST	NY Spills	Lower	612, 0.116, NNW
I259	CON EDISON - SERVICE	685 BROADWAY	RCRA-LQG	Higher	617, 0.117, East
I260	CON EDISON	685 BROADWAY	NY MANIFEST	Higher	617, 0.117, East
O261	CON EDISON	149 HOPKINS ST	RCRA NonGen / NLR, NY MANIFEST	Higher	618, 0.117, South
J262	HARRISON WALTON PROP	86-90 WALTON ST	NY MANIFEST	Lower	620, 0.117, WNW
J263	160-163 HARRISON AVE	86-90 WALTON STREET	NY UST	Lower	620, 0.117, WNW
J264	HARRISON WALTON PROP	86-90 WALTON ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	620, 0.117, WNW
J265	LOT 4,TAXBLOCK 2250	161 HARRISON AVENUE	NY RES DECL, NY E DESIGNATION	Lower	620, 0.117, West
O266	CON EDISON	161 HOPKINS ST	NJ MANIFEST	Higher	625, 0.118, South
O267	CON EDISON	161 HOPKINS ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	625, 0.118, South
L268	ACP BK I, LLC	630 FLUSHING AVENUE	NY UST	Lower	629, 0.119, SSW
L269	ACUMEN PARTNERS LLC	630 FLUSHING AVE	NY LTANKS, NY AST, NY VCP, NY Spills, NY MANIFEST	Lower	629, 0.119, SSW
L270	ACP BK I LLC - 630 F	630 FLUSHING AVE	RCRA-LQG, ICIS, US AIRS, NJ MANIFEST	Lower	629, 0.119, SSW
L271	PFIZER INC. BROOKLYN	630 FLUSHING AVENUE	NY CBS, NY CBS AST	Lower	629, 0.119, SSW
P272	CITGO/ 594 BROADWAY	594 BROADWAY	NY Spills	Lower	632, 0.120, NNW
P273	RICHARDS AUTO REPAIR	594 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO	Lower	632, 0.120, NNW

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P274	SUSION DEVELPORS LLC	594 BROADWAY	NY UST	Lower	632, 0.120, NNW
P275	A G IGNITION	594 BROADWAY	EDR Hist Auto	Lower	632, 0.120, NNW
P276	ELLAYAH DELI GROCERY	590 BROADWAY	NY Spills	Lower	633, 0.120, NNW
L277	MANHOLE #997	FLUSHING AVE & DELMO	NY Spills	Lower	640, 0.121, SSW
P278	CON EDISON SERVICE B	147 WALTON ST	RCRA NonGen / NLR, NY MANIFEST	Lower	642, 0.122, NNW
M279	CON EDISON	22-66 LEONARD ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	642, 0.122, North
M280	CON EDISON	22-66 LEONARD ST	NJ MANIFEST	Lower	642, 0.122, North
N281	CON EDISON	719 FLUSHING AVE	NY MANIFEST	Higher	652, 0.123, ESE
J282	NYC DEPT OF EDUCATIO	101 WALTON ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	665, 0.126, WNW
J283	I.S. 318 - BROOKLYN	101 WALTON STREET	NY AST	Higher	665, 0.126, WNW
N284	CON EDISON	185 HOPKINS ST	NY MANIFEST	Higher	674, 0.128, SSE
N285	CON EDISON - SERVICE	185 HOPKINS ST	NJ MANIFEST	Higher	674, 0.128, SSE
N286	CON EDISON - SERVICE	185 HOPKINS ST	RCRA-LQG	Higher	674, 0.128, SSE
P287	CON EDISON - MANHOLE	584 BROADWAY	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Lower	690, 0.131, NNW
N288	EMS @ WOODHULL HOSPI	720 FLUSHING AVE	NY UST	Higher	703, 0.133, SE
O289	CON EDISON - VS 2314	93 HOPKINS ST	RCRA NonGen / NLR, NY MANIFEST	Higher	709, 0.134, SSW
Q290	CON EDISON SERVICE B	32 VARET ST	RCRA NonGen / NLR, NY MANIFEST	Higher	726, 0.138, ENE
R291	CON EDISON	BROADWAY & DEBEVOISE	RCRA NonGen / NLR	Higher	741, 0.140, East
R292	CON EDISON	BROADWAY & DEBEVOISE	RCRA NonGen / NLR, FINDS, ECHO	Higher	741, 0.140, East
R293	CON EDISON	BROADWAY & DEBEVOISE	NJ MANIFEST	Higher	741, 0.140, East
Q294	CON EDISON	30 MANHATTAN AVE	NY MANIFEST	Higher	762, 0.144, NE
Q295	CON EDISON - VAULT S	30 MANHATTAN AVE	RCRA-LQG	Higher	762, 0.144, NE
S296	CON EDISON MANHOLE:	WALTON ST & HARRISON	RCRA-VSQG, FINDS, ECHO	Higher	763, 0.145, West
S297	CON EDISON MANHOLE:	HARRISON AVE & WALTO	RCRA-VSQG, FINDS, ECHO	Higher	763, 0.145, West
T298	PFIZER INC BROOKLYN	338 WALLABOUT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	787, 0.149, WSW
R299	CON EDISON	720 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO	Higher	813, 0.154, ESE
R300	CON EDISON	720 BROADWAY	NJ MANIFEST	Higher	813, 0.154, ESE
R301	CON EDISON	720 BROADWAY	NY MANIFEST	Higher	813, 0.154, ESE
U302	CON EDISON	46 MANHATTAN AVE	NY MANIFEST	Higher	829, 0.157, NE
U303	CON EDISON SERVICE B	46 MANHATTAN AVE	RCRA NonGen / NLR, FINDS	Higher	829, 0.157, NE
T304	255 WALLABOUT ST/PFI	255 WALLABOUT STREET	NY LTANKS	Lower	831, 0.157, WSW
T305	FORMER PFIZER SITE C	334 WALLABOUT STREET	NY BROWNFIELDS, NY E DESIGNATION	Lower	833, 0.158, WSW
P306	CON EDISON - TM 1358	THROOP AVE & LORIMER	RCRA NonGen / NLR, NY MANIFEST	Lower	841, 0.159, NW
V307	CON EDISON	743 FLUSHING AVE SB7	RCRA NonGen / NLR	Higher	841, 0.159, ESE
V308	CON EDISON	743 FLUSHING AVE SB7	NY MANIFEST	Higher	841, 0.159, ESE
V309	CON EDISON	743 FLUSHING AVE SB7	RCRA NonGen / NLR, FINDS, ECHO	Higher	841, 0.159, ESE
V310	CON EDISON	743 FLUSHING AVE SB7	NY MANIFEST	Higher	841, 0.159, ESE
V311	CON EDISON	743 FLUSHING AVE SB7	NJ MANIFEST	Higher	841, 0.159, ESE
V312	CON EDISON	743 FLUSHING AVE SB7	NJ MANIFEST	Higher	841, 0.159, ESE

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
R313	CON EDISON	FLUSHING & BROADWAY	NY MANIFEST	Higher	844, 0.160, ESE
R314	CON EDISON	722 BROADWAY	NJ MANIFEST	Higher	846, 0.160, ESE
R315	CON ED	722 BROADWAY	NY MANIFEST	Higher	846, 0.160, ESE
R316	CON EDISON	722 BROADWAY	RCRA NonGen / NLR	Higher	846, 0.160, ESE
R317	CON EDISON	745 FLUSHING AVE	NJ MANIFEST	Higher	850, 0.161, ESE
R318	CON EDISON	745 FLUSHING AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	850, 0.161, ESE
R319	CON EDISON	745 FLUSHING AVE	NY MANIFEST	Higher	850, 0.161, ESE
W320	CON EDISON	164 THROOP AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	853, 0.162, SSE
W321	CON EDISON	164 THROOP AVE	NY MANIFEST	Higher	853, 0.162, SSE
W322	CON EDISON	164 THROOP AVE	NJ MANIFEST	Higher	853, 0.162, SSE
Q323	GRAYCO CORP.	29 COOK STREET	NY AST	Higher	853, 0.162, ENE
324	PFIZER (ORGANICS/SUC	CENTRAL PORTION OF P	NY VCP	Lower	855, 0.162, SW
P325	CON EDISON MANHOLE:	LORIMER ST & BROADWA	RCRA NonGen / NLR, NY MANIFEST	Lower	859, 0.163, NNW
P326	MTA NYCT - LORIMER S	LORIMER ST & BROADWA	RCRA NonGen / NLR, NY MANIFEST	Lower	859, 0.163, NNW
P327	CON EDISON	LORIMER ST & BROADWA	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	859, 0.163, NNW
Q328	COOK STREET HOUSING	40 VARET STREET	NY UST	Higher	874, 0.166, ENE
Q329	CON EDISON - MANHOLE	60 MOORE ST	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Higher	884, 0.167, NE
R330	CON EDISON	749 FLUSHING AVE	NY MANIFEST	Higher	888, 0.168, ESE
R331	CON EDISON	749 FLUSHING AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	888, 0.168, ESE
R332	CON EDISON	749 FLUSHING AVE	NJ MANIFEST	Higher	888, 0.168, ESE
R333	CON EDISON	FLUSHING & BROADWAY	NY MANIFEST	Higher	888, 0.168, ESE
334	LINDSAY PARK HOUSING	54 BOERUM ST	NY LTANKS	Lower	896, 0.170, North
W335	CON EDISON	168 THROOP AVE	NY MANIFEST	Higher	898, 0.170, SSE
W336	CON EDISON	168 THROOP AVE	NJ MANIFEST	Higher	898, 0.170, SSE
W337	CON EDISON	168 THROOP AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	898, 0.170, SSE
W338	CON EDISON	168 THROOP AVE	NJ MANIFEST	Higher	898, 0.170, SSE
W339	CON EDISON	168 THROOP AVE	RCRA NonGen / NLR	Higher	898, 0.170, SSE
X340	169 LORIMER STREET	169 LORIMER STREET	NY VCP	Higher	909, 0.172, NW
Y341	NYC DEPT OF EDUCATIO	185 ELLERY ST	RCRA-SQG, NY MANIFEST	Higher	910, 0.172, South
V342	CON EDISON	FLUSHING AVE & BROAD	NY MANIFEST	Higher	910, 0.172, ESE
X343	165-169 LORIMER STRE	165-169 LORIMER STRE	NY UST	Higher	914, 0.173, NW
U344	CON EDISON SERVICE B	50 MANHATTAN AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	914, 0.173, NE
R345	CON EDISON - MANHOLE	13 GRAHAM AVE	RCRA-LQG	Higher	917, 0.174, East
R346	CON EDISON - MANHOLE	13 GRAHAM AVE	NY MANIFEST	Higher	917, 0.174, East
S347	70 UNION AVENUE	70 UNION AVENUE	NY UST	Higher	937, 0.177, West
S348	HYDRO TECH	70 UNION AVENUE	NY Spills, NY MANIFEST	Higher	937, 0.177, West
S349	CAS DEVELOPERS LLC	70 UNION AVE	RCRA-VSQG, NJ MANIFEST	Higher	937, 0.177, West
X350	153 LORIMER STREET	153 LORIMER STREET	NY VCP	Higher	940, 0.178, WNW
Z351	CON EDISON	43 COOK ST	NY MANIFEST	Higher	942, 0.178, ENE

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Z352	CON EDISON	43 COOK ST	NY MANIFEST	Higher	942, 0.178, ENE
X353	151 LORIMER STREET	151 LORIMER STREET	NY VCP	Higher	947, 0.179, WNW
V354	CON EDISON	755 FLUSHING	NY MANIFEST	Higher	950, 0.180, ESE
Z355	35 GRAHM AVE.	35 GRAHM AVE	NY LTANKS	Higher	952, 0.180, ENE
T356	FORMER PFIZER SITE A	243-271 WALLABOUT ST	NY BROWNFIELDS	Lower	955, 0.181, WSW
U357	CON ED - VS 5285	SEIGAL ST & MANHATTA	RCRA NonGen / NLR, NY MANIFEST	Higher	960, 0.182, NNE
U358	CON ED-V5285	SEIGAL ST & MANHATTA	NY MANIFEST	Higher	960, 0.182, NNE
AA359	NYCT - BROADWAY-LORI	143 LORIMER ST	RCRA-SQG, NJ MANIFEST, NY MANIFEST	Higher	961, 0.182, WNW
Q360	CON EDISON	51 VARET ST	NY MANIFEST	Higher	964, 0.183, ENE
361	LINDSAY PARK HOUSING	31 LEONARD STREET	NY UST	Higher	981, 0.186, North
AA362	CON EDISON - MANHOLE	133 HARRISON ST	NY MANIFEST	Higher	982, 0.186, WNW
AA363	CON EDISON - MANHOLE	133 HARRISON ST	RCRA-LQG	Higher	982, 0.186, WNW
Z364	L.J.S.T. REALTY	45 COOK STREET	NY AST	Higher	991, 0.188, ENE
Z365	CON EDISON SERVICE B	45 COOK ST	RCRA NonGen / NLR, FINDS	Higher	991, 0.188, ENE
Z366	CON EDISON	45 COOK ST	NY MANIFEST	Higher	991, 0.188, ENE
V367	CON EDISON	5 GRAHAM AVE	NY MANIFEST	Higher	994, 0.188, ESE
V368	CON EDISON SERVICE B	5 GRAHAM AVE	RCRA NonGen / NLR, FINDS	Higher	994, 0.188, ESE
Z369	CON EDISON	OPP 46 COOK ST	NY MANIFEST	Higher	1000, 0.189, East
V370	CON EDISON	BROADWAY & GRAHAM AV	RCRA NonGen / NLR	Higher	1008, 0.191, ESE
V371	CON EDISON	BROADWAY & GRAHAM AV	NJ MANIFEST	Higher	1008, 0.191, ESE
X372	NYCTA - 22 THROOP AV	22 THROOP AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1010, 0.191, NW
Z373	PS 257K SCHOOL	60 COOK ST	RCRA-LQG, NY MANIFEST	Higher	1013, 0.192, East
Z374	P.S. 257 - BROOKLYN	60 COOK STREET	NY AST	Higher	1013, 0.192, East
Z375	CON EDISON SERVICE B	47 GRAHAM AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1022, 0.194, ENE
AB376	CON EDISON SERVICE B	51 GRAHAM AVE	RCRA NonGen / NLR	Higher	1028, 0.195, ENE
AB377	CON EDISON	51 GRAHAM AVE	NY MANIFEST	Higher	1028, 0.195, ENE
Z378	CON EDISON SERVICE B	44 GRAHAM AVE	RCRA NonGen / NLR, FINDS	Higher	1041, 0.197, East
Z379	CON EDISON	44 GRAHAM AVE	NY MANIFEST	Higher	1041, 0.197, East
Z380	CON EDISON SERVICE B	VARET ST & GRAHAM AV	RCRA NonGen / NLR, NY MANIFEST	Higher	1048, 0.198, ENE
X381	196 MIDDLETON STREET	196 MIDDLETON STREET	NY VCP	Higher	1053, 0.199, NW
W382	179 THROOP AVENUE	179 THROOP AVENUE	NY VCP	Higher	1059, 0.201, SSE
W383	WOODHULL REDEVELOPME	179 THROOP AVENUE	NY UST	Higher	1059, 0.201, SSE
AA384	100 UNION AVENUE RED	100 UNION AVENUE	NY BROWNFIELDS, NY E DESIGNATION	Higher	1060, 0.201, WNW
AA385	100 UNION AVENUE	100 UNION AVENUE	NY VCP	Higher	1060, 0.201, WNW
AC386	CON EDISON - 67 MANH	67 MANHATTAN AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1065, 0.202, NNE
AC387	CON EDISON MANHOLE:	67 MANHATTAN AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1065, 0.202, NNE
AC388	LINDSAY PARK HOUSING	67 MANHATTAN AVENUE	NY UST	Higher	1065, 0.202, NNE
AD389	TM2554	322 WALLABOUT STREET	RCRA NonGen / NLR	Lower	1066, 0.202, WSW
AE390	WALTON APARTMENTS	63 WALTON STREET	NY UST	Higher	1066, 0.202, West

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AA391	CON EDISON - TRANSFO	HARRISON AVE & UNION	NJ MANIFEST	Higher	1070, 0.203, WNW
AA392	CON EDISON - TRANSFO	HARRISON AVE & UNION	RCRA-LQG	Higher	1070, 0.203, WNW
AA393	CON EDISON - MANHOLE	UNION AVE HARRISON A	NJ MANIFEST	Higher	1070, 0.203, WNW
AA394	CON ED	HARRISON AVE & UNION	NY MANIFEST	Higher	1070, 0.203, WNW
AA395	CON EDISON - MANHOLE	UNION AVE HARRISON A	RCRA-LQG, NY MANIFEST	Higher	1070, 0.203, WNW
AF396	CON EDISON SERVICE B	204 ELLERY ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1081, 0.205, SSE
AB397	CON EDISON - MANHOLE	64 GRAHAM AVE	RCRA-LQG, NJ MANIFEST, NY MANIFEST	Higher	1113, 0.211, ENE
AE398	CON EDISON SERVICE B	55 WALTON ST	NJ MANIFEST	Higher	1122, 0.213, West
AE399	CON EDISON SERVICE B	55 WALTON ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1122, 0.213, West
AG400	CON EDISON	FLUSHING AVE & BROAD	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1124, 0.213, ESE
AG401	CON EDISON	FLUSHING AVE AND BRO	NY MANIFEST	Higher	1124, 0.213, ESE
AG402	CONSOLIDATED EDISON	BROADWAY & FLUSHING	NY MANIFEST	Higher	1124, 0.213, ESE
AG403	CON EDISON	BROADWAY & FLUSHING	NY MANIFEST	Higher	1124, 0.213, ESE
AG404	CON EDISON	FLUSHING AVE & BROAD	RCRA NonGen / NLR	Higher	1124, 0.213, ESE
AG405	MTA NYCT - FLUSHING	FLUSHING AVE & BROAD	RCRA NonGen / NLR, NY MANIFEST	Higher	1124, 0.213, ESE
AE406	M.B.M. MFG.	70 LORIMER STREET	NY UST	Higher	1137, 0.215, West
Y407	CON EDISON	747 PARK AVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1146, 0.217, South
Z408	CON ED	56 VARET ST	NY MANIFEST	Higher	1165, 0.221, ENE
AA409	CON EDISON	UNION AVE & MIDDLETO	NJ MANIFEST	Higher	1165, 0.221, WNW
AA410	CON ED	UNION AVE & MIDDLETO	NY MANIFEST	Higher	1165, 0.221, WNW
AA411	CON EDISON	UNION AVE & MIDDLETO	RCRA NonGen / NLR, FINDS, ECHO	Higher	1165, 0.221, WNW
AB412	30 FAMILY APT HOUSE	77 VARET ST	NY AST	Higher	1174, 0.222, ENE
AB413	CON EDISON SERVICE B	77 VARET ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1174, 0.222, ENE
AH414	221 MIDDLETON STREET	221 MIDDLETON STREET	NY VCP	Higher	1178, 0.223, NW
415	LES-LEV CORP	73 GRAHAM AVE	NY AST	Higher	1180, 0.223, NE
AG416	CON EDISON - MANHOLE	10 GRAHAM AVE	NY MANIFEST	Higher	1181, 0.224, East
AE417	45 WALTON STREET	45 WALTON STREET	NY VCP	Lower	1185, 0.224, West
AC418	LOTUS CLEANERS	80 MANHATTAN AVE	RCRA-VSQG, ICIS, US AIRS, FINDS, ECHO, NY...	Higher	1189, 0.225, NNE
AB419	CON EDISON	76 GRAHAM AVE	NJ MANIFEST	Higher	1191, 0.226, ENE
AB420	CON EDISON	76 GRAHAM AVE	RCRA NonGen / NLR	Higher	1191, 0.226, ENE
AB421	CON EDISON	76 GRAHAM AVE	NY MANIFEST	Higher	1191, 0.226, ENE
AI422	V2107	2-48 GERRY	RCRA NonGen / NLR, NY MANIFEST	Lower	1194, 0.226, SW
AI423	V1821	2 GERRY STREET	RCRA NonGen / NLR, NY MANIFEST	Lower	1194, 0.226, SW
AI424	NYCTA	FLUSHING & UNION AVE	NY MANIFEST	Lower	1197, 0.227, SW
AI425	MTA NYCT - FLUSHING	FLUSHING & UNION AVE	RCRA-VSQG, NJ MANIFEST	Lower	1197, 0.227, SW
AI426	CON EDISON MANHOLE:	MARCY AVE & FLUSHING	RCRA NonGen / NLR, NY MANIFEST	Lower	1197, 0.227, SW
AJ427	CON EDISON	39 DEBEVOICE ST	NY MANIFEST	Higher	1203, 0.228, East
AE428	43 WALTON STREET	43 WALTON STREET	NY VCP	Lower	1209, 0.229, West
AG429	WOODHULL MEDICAL CEN	760 BROADWAY	PA MANIFEST	Higher	1215, 0.230, ESE

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AG430	NYC-HH - WOODHULL HO	760 BROADWAY	NY Spills, NY AIRS, NY MANIFEST	Higher	1215, 0.230, ESE
AG431	NYC-HH - WOODHULL HO	760 BROADWAY	RCRA-SQG, NY UST, NY AST, ICIS, US AIRS, NJ...	Higher	1215, 0.230, ESE
AH432	GEORGE ROYH	116 UNION AVENUE	NY UST	Higher	1217, 0.230, NW
AA433	CONSOLIDATED EDISON	MIDDLETON & HARRISON	NY MANIFEST	Higher	1220, 0.231, WNW
AE434	ULTIMATE AUTO REPAIR	45 WALTON STREET	NY AST	Lower	1222, 0.231, West
AJ435	UNITED STATES POSTAL	47 DEBEVOISE STREET	NY AST	Higher	1231, 0.233, East
AF436	CON EDISON SERVICE B	756 PARK AVE	RCRA NonGen / NLR	Higher	1251, 0.237, SSE
AF437	CON EDISON	756 PARK AVE	NY MANIFEST	Higher	1251, 0.237, SSE
AD438	CON EDISON MANHOLE:	MARCY AVE & WALLABOU	RCRA NonGen / NLR, NY MANIFEST	Lower	1251, 0.237, WSW
AH439	KNIGHTS COLLISION RE	120- 150 UNION AVENU	NY UST	Higher	1253, 0.237, NW
AH440	KNIGHTS COLLISION EX	120 UNION AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1253, 0.237, NW
AH441	KNIGHTS COLLISION RE	120- 150 UNION AVENU	NY AST	Higher	1253, 0.237, NW
AK442	ENGINE COMPANY 230	701 PARK AVENUE	NY AST	Higher	1264, 0.239, SSW
AL443	AVALON INDUSTRIES IN	95 LORIMER ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1284, 0.243, West
AG444	5 STORY WAREHOUSE BL	785 FLUSHING AVENUE	NY AST	Higher	1285, 0.243, East
AD445	CON EDISON MANHOLE:	442 MARCY AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1285, 0.243, WSW
446	ANTONIA GONSALIS	118-120 HARRISON AVE	NY UST	Higher	1300, 0.246, WNW
447	CON EDISON	BOERUM & LORIMER ST	NY MANIFEST	Higher	1303, 0.247, NNW
AD448	CON EDISON MANHOLE:	298 WALLABOUT AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1306, 0.247, WSW
AM449	429 MARCY AVENUE	429 MARCY AVENUE	NY UST	Lower	1308, 0.248, West
AN450	CON EDISON	97 VARET ST	NY MANIFEST	Higher	1311, 0.248, ENE
AN451	CON EDISON	97 VARET ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1311, 0.248, ENE
AN452	CON EDISON	97 VARET ST	NJ MANIFEST	Higher	1311, 0.248, ENE
AG453	JOYFUL/A & K/GOOD NE	789 FLUSHING AVENUE	NY DRYCLEANERS	Higher	1312, 0.248, East
AG454	JOYFUL CLEANERS	789 FLUSHING AVE	RCRA-SQG, NY MANIFEST	Higher	1312, 0.248, East
AK455	CON EDISON - MANHOLE	695 PARK AVE	NY MANIFEST	Higher	1318, 0.250, SSW
AK456	CON EDISON - MANHOLE	695 PARK AVE	RCRA-LQG	Higher	1318, 0.250, SSW
AM457	415-419 MARCY AVENUE	415-419 MARCY AVENUE	NY VCP	Lower	1344, 0.255, West
AL458	FORMER CHARLES PFIZE	407 MARCY AVENUE	NY ENG CONTROLS, NY INST CONTROL, NY Spills	Lower	1373, 0.260, West
AL459	FORMER CHARLES PFIZE	407 MARCY AVENUE	NY BROWNFIELDS	Lower	1373, 0.260, West
AM460	CONSTRUCTION SITE	420 MARCY AVE	NY LTANKS, NY Spills	Lower	1389, 0.263, West
461	BUSHWICK -NYCHA	24 HUMBOLDT STREET	NY LTANKS, NY Spills	Higher	1479, 0.280, East
462	150 UNION AVENUE	150 UNION AVENUE	NY VCP	Higher	1482, 0.281, NW
463	CONSTRUCTION SITE	5 WALTON AVE	NY LTANKS	Lower	1601, 0.303, WSW
AO464	ENGINE CO. 216/LADD.	187 UNION AVENUE	NY LTANKS, NY Spills	Higher	1759, 0.333, NW
AP465	COOPER TANK & WELDIN	222-26 SIEGAL AVE	NY SWF/LF	Higher	1801, 0.341, ENE
AP466	BORINQUEN PLAZA	110 HUMBOLDT STREET	NY LTANKS, NY UST	Higher	1843, 0.349, NE
467	159 BOERUM STREET	159 BOERUM STREET	NY BROWNFIELDS	Higher	1848, 0.350, NE
468	CONWAY/EMPTY BUILDIN	815 BROADWAY	NY LTANKS	Higher	1854, 0.351, ESE

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AO469	JOHNSON AVE. & BROAD	JOHNSON AVE AND BROA	NY LTANKS	Higher	1877, 0.355, NW
470	BROOKLYN NORTH 03/03	306 RUTLEDGE STREET	NY LTANKS, NY Spills	Higher	1882, 0.356, NW
471	CON ED	130 MOORE ST	NY LTANKS, NY MANIFEST	Higher	1884, 0.357, ENE
472	UNITED STATES ARMORY	355 MARCY AVENUE	NY LTANKS, NY Spills	Higher	1894, 0.359, WNW
AQ473	SLATTERY STOVE SITE	171 WALLBOUT ST	SEMS-ARCHIVE, RCRA NonGen / NLR, PRP, ICIS, FINDS,...	Lower	1898, 0.359, WSW
AR474	BORINQUEN PLAZA	120 HUMBOLDT STREET	NY LTANKS, NY UST	Higher	1916, 0.363, NE
AQ475	242 - 246 WALLABOUT	242 - 246 WALLABOUT	NY VCP	Lower	1945, 0.368, WSW
AP476	CON EDISON	155 SIEGEL ST	NY LTANKS, NY MANIFEST	Higher	1946, 0.369, NE
477	TOP HAT CLEANERS	152 GRAHAM AVE	RCRA-VSQG, NY SHWS, ICIS, US AIRS, NY MANIFEST	Higher	1960, 0.371, NNE
AR478	CONSOLIDATED EDISON	FRONT OF 130 HUMBOLD	NY LTANKS, NY Spills, NY MANIFEST	Higher	1966, 0.372, NE
479	901 MYRTLE AVENUE	901 MYRTLE AVENUE	NY VCP	Higher	2026, 0.384, South
AS480	NOSTRAND AVE & FLUSH	NOSTRAND AVE & FLUSH	NY LTANKS	Lower	2073, 0.393, WSW
481	MOST HOLY TRINITY RE	157 GRAHAM AVE	NY LTANKS, NY UST	Higher	2108, 0.399, NNE
AS482	535 FLUSHING AVENUE	535 FLUSHING AVENUE	NY VCP	Lower	2110, 0.400, WSW
AT483	209 UNION AVENUE	209 UNION AVE - 90TH	NY LTANKS	Higher	2114, 0.400, NNW
AT484	90 PRECINCT NYPD -DD	209 UNION AVENUE	NY LTANKS, NY Spills	Higher	2114, 0.400, NNW
485	GONZALEZ RESIDENCE	29 BEAVER ST	NY LTANKS	Higher	2119, 0.401, ESE
486	948 MYRTLE AVENUE	948 MYRTLE AVENUE	NY VCP	Higher	2123, 0.402, SSE
AU487	BORINQUEN HOUSES	330 BUSHWICK AVENUE	NY LTANKS, NY UST, NY Spills	Higher	2123, 0.402, NE
488	922 MYRTLE AVENUE	922 MYRTLE AVENUE	NY VCP	Higher	2126, 0.403, South
489	FORMER CASCADE LAUND	553 MARCY AVENUE	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Higher	2143, 0.406, SSW
AQ490	260 LEE AVENUE	260 LEE AVENUE	NY VCP	Lower	2148, 0.407, WSW
AS491	527 FLUSHING AVENUE	527 FLUSHING AVENUE	NY VCP	Lower	2187, 0.414, WSW
AU492	BORINQUEN HOUSES	300 BUSHWICK AVENUE	NY LTANKS, NY UST	Higher	2255, 0.427, NE
493	BEDFORD AUTO SALES	984 MYRTLE AVE	NY SWF/LF	Higher	2281, 0.432, SSE
AV494	BORDEN CHEMICAL	56 NOSTRAND AVE.	NY HSWDS	Higher	2317, 0.439, SW
AV495	BORDEN CHEMICAL ADHE	56 NOSTRAND AVE	SEMS-ARCHIVE, RCRA NonGen / NLR, FINDS, ECHO	Higher	2317, 0.439, SW
496	CLOSED-LACKOF RECENT	204 WALLABOUT ST	NY LTANKS	Lower	2363, 0.448, WSW
497	30 WARSOFF PLACE/BKL	30 WARSOFF PLACE	NY LTANKS	Higher	2388, 0.452, WSW
AV498	MARCY HOUSES -NYCHA	603 PARK AVE	NY LTANKS	Higher	2502, 0.474, SW
AV499	MARCY HOUSES -NYCHA	603 PARK AVE	NY LTANKS	Higher	2502, 0.474, SW
500	COMMERCIAL BUILDING	544 PARK AVE	NY LTANKS	Higher	2548, 0.483, SW
501	802-806 MYRTLE AVENU	802-806 MYRTLE AVENU	NY VCP	Higher	2549, 0.483, SSW
502	74 VERNON AVENUE	74 VERNON AVENUE	NY VCP	Higher	2593, 0.491, SSW
503	SUMNER HOUSES -NYCHA	10 LEWIS AVE	NY LTANKS, NY Spills	Higher	2596, 0.492, ESE
504	BROOKLYN SCRAP METAL	171 COOK ST.	SEMS-ARCHIVE, LEAD SMELTERS	Higher	2597, 0.492, East
AW505	FORMER TECHTRONICS S	480 FLUSHING AVENUE	NY SHWS, NY BROWNFIELDS	Higher	2625, 0.497, WSW
506	1-37 FORREST STREET	1-37 FORREST STREET	NY VCP	Higher	2625, 0.497, East
507	83 BUSHWICK PLACE	83 BUSHWICK PLACE	NY VCP	Higher	2628, 0.498, NE

MAPPED SITES SUMMARY

Target Property Address:
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
508	11-23 MONTIETH STREE	11-23 MONTIETH STREE	NY VCP	Higher	2633, 0.499, East
509	WEST BUSHWICK HOUSIN	86-88 BEAVER ST	NY LTANKS	Higher	2637, 0.499, ESE
AW510	FORMER TECHTRONICS E	8 WALWORTH STREET	NY SHWS	Higher	2666, 0.505, WSW
AW511	TOLDOS YEHUDAH LLC	8 WALWORTH ST	CORRACTS, RCRA-LQG, NY BROWNFIELDS, NY MANIFEST	Higher	2666, 0.505, WSW
AW512	SPENCER STREET GW	INTERSECTION OF SPEN	NY SHWS	Lower	2796, 0.530, WSW
AX513	K - SKILLMAN ST. STA	7 SKILLMAN STREET	NY SHWS, NY BROWNFIELDS	Higher	3309, 0.627, WSW
AX514	SKILLMAN STATION	SKILLMAN ST. FLUSHIN	EDR MGP	Higher	3318, 0.628, WSW
515	NASSAU GAS	SKILLMAN AVE	EDR MGP	Higher	3408, 0.645, WSW
516	KOLLMORGAN OPTICAL		FUDS	Higher	3592, 0.680, WSW
517	2 INGRAHAM STREET	2 INGRAHAM ST	NY SHWS, NY VCP, NY BROWNFIELDS	Higher	3845, 0.728, ENE
518	RUTLEDGE STATION	RUTLEDGE ST. WYTHE A	EDR MGP	Higher	4049, 0.767, WSW
519	SCHOLES ST. STATION	SCHOLES ST 7 BOGART	EDR MGP	Higher	4216, 0.798, NE
520	KEAP ST. STATION	KEAP ST. WYTHE AVE.	EDR MGP	Higher	4492, 0.851, West
521	BQE/ANSBACHER COLOR	MEEKER AVENUE	NY SHWS	Higher	4901, 0.928, NNW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
LOT 33,TAXBLOCK 2269 69 BARTLETT STREET BROOKLYN, NY 11206	NY E DESIGNATION	N/A
LOT 35,TAXBLOCK 2269 65 BARTLETT STREET BROOKLYN, NY 11206	NY E DESIGNATION	N/A
LOT 23,TAXBLOCK 2269 86 GERRY STREET BROOKLYN, NY 11206	NY E DESIGNATION	N/A
LOT 36,TAXBLOCK 2269 63 BARTLETT STREET BROOKLYN, NY 11206	NY E DESIGNATION	N/A
LOT 27,TAXBLOCK 2269 84 THROOP AVENUE BROOKLYN, NY 11206	NY E DESIGNATION	N/A
LOT 24,TAXBLOCK 2269 88 GERRY STREET BROOKLYN, NY 11206	NY E DESIGNATION	N/A
ON GROUND 90-92 GERRY STREET BROOKLYN, NY	NY Spills Spill Number/Closed Date: 0411773 / 2008-06-26 Site ID: 337051 Spill Date: 2005-02-03	N/A
LOT 29,TAXBLOCK 2269 88 THROOP AVENUE BROOKLYN, NY 11206	NY E DESIGNATION	N/A
LOT 30,TAXBLOCK 2269 90 THROOP AVENUE BROOKLYN, NY 11206	NY E DESIGNATION	N/A
SCIULARA PROP - BART 61 BARTLETT PL BROOKLYN, NY 11229	FINDS	N/A

EXECUTIVE SUMMARY

Registry ID:: 110028280072

GUDDEMI PROPERTY-59 59 BARTLETT PLACE BROOKLYN, NY 11229	FINDS Registry ID:: 110019093657	N/A
LOT 25,TAXBLOCK 2269 90 GERRY STREET BROOKLYN, NY 11206	NY E DESIGNATION	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal leaking storage tank lists

INDIAN LUST - Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS - Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST - Underground Storage Tank Listing
NY CBS UST - Chemical Bulk Storage Database
NY MOSF UST - Major Oil Storage Facilities Database
NY MOSF - Major Oil Storage Facility Site Listing
NY MOSF AST - Major Oil Storage Facilities Database
INDIAN UST - Underground Storage Tanks on Indian Land
NY TANKS - Storage Tank Faciliy Listing

State and tribal voluntary cleanup sites

INDIAN VCP - Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP - Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS - A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE - Registered Waste Tire Storage & Facility List
NY SWRCY - Registered Recycling Facility List
INDIAN ODI - Report on the Status of Open Dumps on Indian Lands
ODI - Open Dump Inventory
DEBRIS REGION 9 - Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS - Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL - Delisted National Clandestine Laboratory Register
NY DEL SHWS - Delisted Registry Sites
US CDL - National Clandestine Laboratory Register
NY PFAS - PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

NY HIST UST - Historical Petroleum Bulk Storage Database
NY HIST AST - Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS - Spill Liens Information

LIENS 2 ---------- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System
NY Hist Spills ---------- SPILLS Database
NY SPILLS 90 ---------- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---------- SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOD ---------- Department of Defense Sites
SCRD DRYCLEANERS ---------- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---------- Financial Assurance Information
EPA WATCH LIST ---------- EPA WATCH LIST
2020 COR ACTION ---------- 2020 Corrective Action Program List
TSCA ---------- Toxic Substances Control Act
TRIS ---------- Toxic Chemical Release Inventory System
SSTS ---------- Section 7 Tracking Systems
ROD ---------- Records Of Decision
RMP ---------- Risk Management Plans
PADS ---------- PCB Activity Database System
FTTS ---------- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---------- Material Licensing Tracking System
COAL ASH DOE ---------- Steam-Electric Plant Operation Data
COAL ASH EPA ---------- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---------- PCB Transformer Registration Database
RADINFO ---------- Radiation Information Database
HIST FTTS ---------- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---------- Incident and Accident Data
CONSENT ---------- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---------- Indian Reservations
FUSRAP ---------- Formerly Utilized Sites Remedial Action Program
UMTRA ---------- Uranium Mill Tailings Sites
US MINES ---------- Mines Master Index File
ABANDONED MINES ---------- Abandoned Mines
DOCKET HWC ---------- Hazardous Waste Compliance Docket Listing
UXO ---------- Unexploded Ordnance Sites
FUELS PROGRAM ---------- EPA Fuels Program Registered Listing
NY COAL ASH ---------- Coal Ash Disposal Site Listing
NY Financial Assurance ---------- Financial Assurance Information Listing
NY SPDES ---------- State Pollutant Discharge Elimination System
NY VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List
NY UIC ---------- Underground Injection Control Wells
NY COOLING TOWERS ---------- Registered Cooling Towers

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---------- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---------- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 07/19/2019 has revealed that there are 3 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BORDEN CHEMICAL ADHE Site ID: 0201493 EPA Id: NYD012497335	***56 NOSTRAND AVE***	***SW 1/4 - 1/2 (0.439 mi.)***	***AV495***	***1318***
BROOKLYN SCRAP METAL	***171 COOK ST.***	***E 1/4 - 1/2 (0.492 mi.)***	***504***	***1340***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
SLATTERY STOVE SITE Site ID: 0203594 EPA Id: NYD001288349	***171 WALLBOUT ST***	***WSW 1/4 - 1/2 (0.359 mi.)***	***AQ473***	***1217***

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 03/25/2019 has revealed that there are 2 CORRACTS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TOLDOS YEHUDAH LLC	***8 WALWORTH ST***	***WSW 1/2 - 1 (0.505 mi.)***	***AW511***	***1352***

EPA ID:: NYD000824334

Lower Elevation	Address	Direction / Distance	Map ID	Page
PFIZER INC EPA ID:: NYD001374214	***11 BARTLETT ST***	***SW 0 - 1/8 (0.093 mi.)***	***L201***	***373***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/25/2019 has revealed that there are 25 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ARLINGTON PRESS-191 EPA ID:: NYD001513779	***191 HARRISON AVE***	***WSW 0 - 1/8 (0.060 mi.)***	***B114***	***210***
CON EDISON - MANHOLE EPA ID:: NYP004184289	***662 BROADWAY***	***ENE 0 - 1/8 (0.063 mi.)***	***G122***	***226***
CON EDISON - MANHOLE EPA ID:: NYP005094628	676 BROADWAY	E 0 - 1/8 (0.080 mi.)	I172	314
CON EDISON - SERVICE EPA ID:: NYP005021290	701 FLUSHING AVE	SE 0 - 1/8 (0.094 mi.)	N205	383
CON EDISON - SERVICE EPA ID:: NYP004730065	685 BROADWAY	E 0 - 1/8 (0.117 mi.)	I259	489
CON EDISON - SERVICE EPA ID:: NYP004733754	185 HOPKINS ST	SSE 1/8 - 1/4 (0.128 mi.)	N286	632
CON EDISON - VAULT S EPA ID:: NYP005087006	30 MANHATTAN AVE	NE 1/8 - 1/4 (0.144 mi.)	Q295	649
CON EDISON - MANHOLE EPA ID:: NYP004308326	***60 MOORE ST***	***NE 1/8 - 1/4 (0.167 mi.)***	***Q329***	***705***
CON EDISON - MANHOLE EPA ID:: NYP005093158	13 GRAHAM AVE	E 1/8 - 1/4 (0.174 mi.)	R345	736
CON EDISON - MANHOLE EPA ID:: NYP005064977	133 HARRISON ST	WNW 1/8 - 1/4 (0.186 mi.)	AA363	787
PS 257K SCHOOL EPA ID:: NY0000375469	***60 COOK ST***	***E 1/8 - 1/4 (0.192 mi.)***	***Z373***	***803***
CON EDISON - TRANSFO EPA ID:: NYP004875098	HARRISON AVE & UNION	WNW 1/8 - 1/4 (0.203 mi.)	AA392	844
CON EDISON - MANHOLE EPA ID:: NYP004184263	***UNION AVE HARRISON A***	***WNW 1/8 - 1/4 (0.203 mi.)***	***AA395***	***848***
CON EDISON - MANHOLE	***64 GRAHAM AVE***	***ENE 1/8 - 1/4 (0.211 mi.)***	***AB397***	***853***

EPA ID:: NYP004184297				
CON EDISON - MANHOLE EPA ID:: NYP005079742	695 PARK AVE	SSW 1/8 - 1/4 (0.250 mi.)	AK456	1115

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004720009	78 THROOP AVE	NNW 0 - 1/8 (0.024 mi.)	A34	33
THROOP BUILDINGS EPA ID:: NYR000197897	***72 THROOP AVE***	***NNW 0 - 1/8 (0.038 mi.)***	***B67***	***92***
CON EDISON - TRANSFO EPA ID:: NYP004399176	***WALLABOUT ST C 32W T***	***NNW 0 - 1/8 (0.057 mi.)***	***D101***	***189***
TULIP GROVE HOMES EPA ID:: NYR000203539	661 FLUSHING AVENUE	SSW 0 - 1/8 (0.079 mi.)	F168	305
BAIS RUCHEL HIGH SCH EPA ID:: NYR000183780	***177 HARRISON AVE***	***WSW 0 - 1/8 (0.090 mi.)***	***K197***	***349***
PFIZER INC EPA ID:: NYD001374214	***11 BARTLETT ST***	***SW 0 - 1/8 (0.093 mi.)***	***L201***	***373***
THROOP UNITS LLC EPA ID:: NYR000231548	54 THROOP AVE	NW 0 - 1/8 (0.094 mi.)	H209	390
CON EDISON - VAULT 1 EPA ID:: NYP005131800	2 TOMPKINS AVE	SSW 0 - 1/8 (0.105 mi.)	L234	452
ACP BK I LLC - 630 F EPA ID:: NYD986936904	***630 FLUSHING AVE***	***SSW 0 - 1/8 (0.119 mi.)***	***L270***	***550***
CON EDISON - MANHOLE EPA ID:: NYP004306957	***584 BROADWAY***	***NNW 1/8 - 1/4 (0.131 mi.)***	***P287***	***634***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/25/2019 has revealed that there are 5 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYC DEPT OF EDUCATIO EPA ID:: NYR000011163	***185 ELLERY ST***	***S 1/8 - 1/4 (0.172 mi.)***	***Y341***	***725***
NYCT - BROADWAY-LORI EPA ID:: NYR000156547	***143 LORIMER ST***	***WNW 1/8 - 1/4 (0.182 mi.)***	***AA359***	***778***
NYC-HH - WOODHULL HO EPA ID:: NYD981560972	***760 BROADWAY***	***ESE 1/8 - 1/4 (0.230 mi.)***	***AG431***	***970***
JOYFUL CLEANERS EPA ID:: NYR000148882	***789 FLUSHING AVE***	***E 1/8 - 1/4 (0.248 mi.)***	***AG454***	***1111***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BP WEST COAST PRODUC	655 FLUSHING AVE	SSW 0 - 1/8 (0.104 mi.)	L227	428

EPA ID:: NYR000198119

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 03/25/2019 has revealed that there are 6 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PFIZER INC BROOKLYN EPA ID:: NYR000016048	***73 GERRY ST***	***W 0 - 1/8 (0.034 mi.)***	***B54***	***58***
CON EDISON MANHOLE: EPA ID:: NYP004306924	***WALTON ST & HARRISON***	***W 1/8 - 1/4 (0.145 mi.)***	***S296***	***650***
CON EDISON MANHOLE: EPA ID:: NYP004306916	***HARRISON AVE & WALTO***	***W 1/8 - 1/4 (0.145 mi.)***	***S297***	***652***
CAS DEVELOPERS LLC EPA ID:: NYR000146126	***70 UNION AVE***	***W 1/8 - 1/4 (0.177 mi.)***	***S349***	***750***
LOTUS CLEANERS EPA ID:: NYD987029188	***80 MANHATTAN AVE***	***NNE 1/8 - 1/4 (0.225 mi.)***	***AC418***	***894***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - FLUSHING EPA ID:: NYR000043455	***FLUSHING & UNION AVE***	***SW 1/8 - 1/4 (0.227 mi.)***	***AI425***	***909***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 05/13/2019 has revealed that there are 7 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TOP HAT CLEANERS Site Code: 504341	***152 GRAHAM AVE***	***NNE 1/4 - 1/2 (0.371 mi.)***	***477***	***1232***
FORMER TECHTRONICS S Site Code: 548235	***480 FLUSHING AVENUE***	***WSW 1/4 - 1/2 (0.497 mi.)***	***AW505***	***1341***
FORMER TECHTRONICS E Site Code: 529340	8 WALWORTH STREET	WSW 1/2 - 1 (0.505 mi.)	AW510	1350
K - SKILLMAN ST. STA	***7 SKILLMAN STREET***	***WSW 1/2 - 1 (0.627 mi.)***	***AX513***	***1367***

Site Code: 379003

2 INGRAHAM STREET	***2 INGRAHAM ST***	***ENE 1/2 - 1 (0.728 mi.)***	***517***	***1373***

Site Code: 57074

BQE/ANSBACHER COLOR	MEEKER AVENUE	NNW 1/2 - 1 (0.928 mi.)	521	1382

Site Code: 55913
Class Code: Does not present a significant threat to the public health or the environment - action may be deferred.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SPENCER STREET GW	INTERSECTION OF SPEN	WSW 1/2 - 1 (0.530 mi.)	AW512	1365

Site Code: 537811

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 07/02/2019 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COOPER TANK & WELDIN	222-26 SIEGAL AVE	ENE 1/4 - 1/2 (0.341 mi.)	AP465	1187
BEDFORD AUTO SALES	984 MYRTLE AVE	SSE 1/4 - 1/2 (0.432 mi.)	493	1315

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 08/12/2019 has revealed that there are 33 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PFIZER INC/GERRY ST	PFIZER INC/GERRY ST	W 0 - 1/8 (0.052 mi.)	B91	114

Spill Number/Closed Date: 9203348 / 1992-06-22
Site ID: 204940
Spill Date: 1992-06-19

CLOSED-LACKOF RECENT	113 THROOP AVE	ESE 0 - 1/8 (0.060 mi.)	C109	202

Spill Number/Closed Date: 8707623 / 2003-03-04
Site ID: 102990
Spill Date: 1987-12-05

35 GRAHM AVE.	35 GRAHM AVE	ENE 1/8 - 1/4 (0.180 mi.)	Z355	771

Spill Number/Closed Date: 9302281 / 1993-05-19
Site ID: 68726
Spill Date: 1993-05-19

BUSHWICK -NYCHA	***24 HUMBOLDT STREET***	***E 1/4 - 1/2 (0.280 mi.)***	***461***	***1170***

Spill Number/Closed Date: 9505310 / 2005-11-02
Site ID: 315418
Spill Date: 1995-07-31

ENGINE CO. 216/LADD. ***187 UNION AVENUE*** ***NW 1/4 - 1/2 (0.333 mi.)*** ***AO464*** ***1182***
Spill Number/Closed Date: 8607159 / 2005-01-13
Site ID: 188778
Spill Date: 1987-02-24

BORINQUEN PLAZA ***110 HUMBOLDT STREET*** ***NE 1/4 - 1/2 (0.349 mi.)*** ***AP466*** ***1187***
Spill Number/Closed Date: 9605290 / 2010-11-10
Site ID: 86456
Spill Date: 1996-07-24

CONWAY/EMPTY BUILDIN 815 BROADWAY ESE 1/4 - 1/2 (0.351 mi.) 468 1194
Spill Number/Closed Date: 1215990 / 2015-01-20
Site ID: 479335
Spill Date: 2013-03-01

JOHNSON AVE. & BROAD JOHNSON AVE AND BROA NW 1/4 - 1/2 (0.355 mi.) AO469 1196
Spill Number/Closed Date: 9305896 / 1993-08-13
Site ID: 215550
Spill Date: 1993-08-13

BROOKLYN NORTH 03/03 ***306 RUTLEDGE STREET*** ***NW 1/4 - 1/2 (0.356 mi.)*** ***470*** ***1197***
Spill Number/Closed Date: 0001698 / 2008-06-23
Spill Number/Closed Date: 9601941 / 2005-03-02
Spill Number/Closed Date: 8809462 / 2005-03-02
Site ID: 127996
Site ID: 127997
Site ID: 132862
Spill Date: 2000-04-21
Spill Date: 1996-05-09
Spill Date: 1988-11-02

CON ED ***130 MOORE ST*** ***ENE 1/4 - 1/2 (0.357 mi.)*** ***471*** ***1211***
Spill Number/Closed Date: 0303435 / 2003-07-02
Site ID: 264329
Spill Date: 2003-07-02

UNITED STATES ARMORY ***355 MARCY AVENUE*** ***WNW 1/4 - 1/2 (0.359 mi.)*** ***472*** ***1213***
Spill Number/Closed Date: 8806820 / 1992-10-07
Site ID: 135895
Spill Date: 1988-11-15

BORINQUEN PLAZA ***120 HUMBOLDT STREET*** ***NE 1/4 - 1/2 (0.363 mi.)*** ***AR474*** ***1223***
Spill Number/Closed Date: 9807939 / 2010-10-28
Site ID: 201928
Spill Date: 1998-09-29

CON EDISON ***155 SIEGEL ST*** ***NE 1/4 - 1/2 (0.369 mi.)*** ***AP476*** ***1228***
Spill Number/Closed Date: 9100258 / 1998-01-12
Spill Number/Closed Date: 9711438 / 2010-07-12
Site ID: 327446
Site ID: 327447
Spill Date: 1991-04-05
Spill Date: 1998-01-12

CONSOLIDATED EDISON ***FRONT OF 130 HUMBOLD*** ***NE 1/4 - 1/2 (0.372 mi.)*** ***AR478*** ***1241***
Spill Number/Closed Date: 9905903 / 2004-01-08
Spill Number/Closed Date: 9402292 / 2004-01-08

Site ID: 233389
Site ID: 74795
Spill Date: 1999-08-17
Spill Date: 1994-05-16

MOST HOLY TRINITY RE ***157 GRAHAM AVE*** ***NNE 1/4 - 1/2 (0.399 mi.)*** ***481*** ***1249***
Spill Number/Closed Date: 0306650 / 2006-08-25
Site ID: 131344
Spill Date: 2003-09-23

209 UNION AVENUE 209 UNION AVE - 90TH NNW 1/4 - 1/2 (0.400 mi.) AT483 1254
Spill Number/Closed Date: 9502048 / 1995-05-18
Site ID: 322916
Spill Date: 1995-05-18

90 PRECINCT NYPD -DD ***209 UNION AVENUE*** ***NNW 1/4 - 1/2 (0.400 mi.)*** ***AT484*** ***1255***
Spill Number/Closed Date: 8606252 / 2005-01-10
Site ID: 85755
Spill Date: 1987-01-07

GONZALEZ RESIDENCE 29 BEAVER ST ESE 1/4 - 1/2 (0.401 mi.) 485 1261
Spill Number/Closed Date: 0514546 / 2006-03-21
Site ID: 361288
Spill Date: 2006-03-20

BORINQUEN HOUSES ***330 BUSHWICK AVENUE*** ***NE 1/4 - 1/2 (0.402 mi.)*** ***AU487*** ***1262***
Spill Number/Closed Date: 9601914 / 2005-12-09
Site ID: 63348
Spill Date: 1996-05-08

BORINQUEN HOUSES ***300 BUSHWICK AVENUE*** ***NE 1/4 - 1/2 (0.427 mi.)*** ***AU492*** ***1309***
Spill Number/Closed Date: 9711478 / 1998-02-02
Spill Number/Closed Date: 9010701 / 1998-01-13
Spill Number/Closed Date: 9712046 / 2004-02-06
Site ID: 191464
Site ID: 191530
Site ID: 191531
Spill Date: 1998-01-13
Spill Date: 1991-01-07
Spill Date: 1998-01-28

30 WARSOFF PLACE/BKL 30 WARSOFF PLACE WSW 1/4 - 1/2 (0.452 mi.) 497 1323
Spill Number/Closed Date: 8708592 / 1992-09-30
Site ID: 228023
Spill Date: 1988-01-07

MARCY HOUSES -NYCHA 603 PARK AVE SW 1/4 - 1/2 (0.474 mi.) AV498 1325
Spill Number/Closed Date: 0100526 / 2003-12-09
Site ID: 274620
Spill Date: 2001-04-13

MARCY HOUSES -NYCHA 603 PARK AVE SW 1/4 - 1/2 (0.474 mi.) AV499 1326
Spill Number/Closed Date: 9607616 / 2005-12-09
Spill Number/Closed Date: 9611167 / 2007-12-11
Spill Number/Closed Date: 9614725 / 2007-12-11
Spill Number/Closed Date: 9315457 / 2016-01-20
Site ID: 215887
Site ID: 215888
Site ID: 215889
Site ID: 274622
Spill Date: 1996-09-17

Spill Date: 1996-12-10
Spill Date: 1997-03-21
Spill Date: 1992-07-07

COMMERCIAL BUILDING — 544 PARK AVE — SW 1/4 - 1/2 (0.483 mi.) — 500 — 1331
Spill Number/Closed Date: 0613501 / 2008-07-01
Site ID: 378545
Spill Date: 2007-03-15

SUMNER HOUSES -NYCHA — ***10 LEWIS AVE*** — ***ESE 1/4 - 1/2 (0.492 mi.)*** — ***503*** — ***1335***
Spill Number/Closed Date: 9505160 / 2003-10-30
Spill Number/Closed Date: 9505222 / 2015-12-16
Site ID: 180721
Site ID: 180722
Spill Date: 1995-07-27
Spill Date: 1995-07-28

WEST BUSHWICK HOUSIN — 86-88 BEAVER ST — ESE 1/4 - 1/2 (0.499 mi.) — 509 — 1349
Spill Number/Closed Date: 0008389 / 2004-06-09
Site ID: 143808
Spill Date: 2000-10-18

Lower Elevation	Address	Direction / Distance	Map ID	Page
ACUMEN PARTNERS LLC	***630 FLUSHING AVE***	***SSW 0 - 1/8 (0.119 mi.)***	***L269***	***520***
Spill Number/Closed Date: 9901811 / 2006-03-31 Site ID: 201034 Spill Date: 1999-05-17				
255 WALLABOUT ST/PFI	255 WALLABOUT STREET	WSW 1/8 - 1/4 (0.157 mi.)	T304	663
Spill Number/Closed Date: 9005003 / 2006-11-14 Site ID: 219704 Spill Date: 1990-08-06				
LINDSAY PARK HOUSING	54 BOERUM ST	N 1/8 - 1/4 (0.170 mi.)	334	714
Spill Number/Closed Date: 0906148 / 2010-10-27 Site ID: 418462 Spill Date: 2009-08-26				
CONSTRUCTION SITE	***420 MARCY AVE***	***W 1/4 - 1/2 (0.263 mi.)***	***AM460***	***1167***
Spill Number/Closed Date: 0505009 / 2005-11-04 Site ID: 349949 Spill Date: 2005-07-26				
CONSTRUCTION SITE	5 WALTON AVE	WSW 1/4 - 1/2 (0.303 mi.)	463	1181
Spill Number/Closed Date: 9710662 / 2003-03-07 Site ID: 162103 Spill Date: 1997-12-18				
NOSTRAND AVE & FLUSH	NOSTRAND AVE & FLUSH	WSW 1/4 - 1/2 (0.393 mi.)	AS480	1248
Spill Number/Closed Date: 9309562 / 1993-11-08 Site ID: 170265 Spill Date: 1993-11-08				
CLOSED-LACKOF RECENT	204 WALLABOUT ST	WSW 1/4 - 1/2 (0.448 mi.)	496	1322
Spill Number/Closed Date: 8801005 / 2003-03-05 Site ID: 324576 Spill Date: 1988-05-02				

EXECUTIVE SUMMARY

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 26 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PFIZER INC. BROOKLYN Database: UST, Date of Government Version: 06/24/2019	80 GERRY STREET	WSW 0 - 1/8 (0.024 mi.)	A33	29
THROOP AVENUE / BART Database: UST, Date of Government Version: 06/24/2019	THROOP AVENUE / BART	ESE 0 - 1/8 (0.033 mi.)	C48	50
J&M AUTO SERVICE COR Database: UST, Date of Government Version: 06/24/2019	30 BARTLETT STREET	SSW 0 - 1/8 (0.050 mi.)	E87	111
PFIZER INC. SITE BAN Database: UST, Date of Government Version: 06/24/2019	60-66 GERRY STREET	WSW 0 - 1/8 (0.060 mi.)	B113	208
ALL SAINTS R C CHURC Database: UST, Date of Government Version: 06/24/2019	***115 THROOP AVE***	***ESE 0 - 1/8 (0.062 mi.)***	***C117***	***215***
EMS BATT 57 @ WOODHU Database: UST, Date of Government Version: 06/24/2019	131 THROOP AVENUE	SE 0 - 1/8 (0.080 mi.)	C174	316
EMS @ WOODHULL HOSPI Database: UST, Date of Government Version: 06/24/2019	720 FLUSHING AVE	SE 1/8 - 1/4 (0.133 mi.)	N288	637
COOK STREET HOUSING Database: UST, Date of Government Version: 06/24/2019	40 VARET STREET	ENE 1/8 - 1/4 (0.166 mi.)	Q328	703
165-169 LORIMER STRE Database: UST, Date of Government Version: 06/24/2019	165-169 LORIMER STRE	NW 1/8 - 1/4 (0.173 mi.)	X343	729
70 UNION AVENUE Database: UST, Date of Government Version: 06/24/2019	70 UNION AVENUE	W 1/8 - 1/4 (0.177 mi.)	S347	739
LINDSAY PARK HOUSING Database: UST, Date of Government Version: 06/24/2019	31 LEONARD STREET	N 1/8 - 1/4 (0.186 mi.)	361	783
WOODHULL REDEVELOPME Database: UST, Date of Government Version: 06/24/2019	179 THROOP AVENUE	SSE 1/8 - 1/4 (0.201 mi.)	W383	821
LINDSAY PARK HOUSING Database: UST, Date of Government Version: 06/24/2019	67 MANHATTAN AVENUE	NNE 1/8 - 1/4 (0.202 mi.)	AC388	833
WALTON APARTMENTS Database: UST, Date of Government Version: 06/24/2019	63 WALTON STREET	W 1/8 - 1/4 (0.202 mi.)	AE390	841
M.B.M. MFG. Database: UST, Date of Government Version: 06/24/2019	70 LORIMER STREET	W 1/8 - 1/4 (0.215 mi.)	AE406	874
NYC-HH - WOODHULL HO Database: UST, Date of Government Version: 06/24/2019	***760 BROADWAY***	***ESE 1/8 - 1/4 (0.230 mi.)***	***AG431***	***970***
GEORGE ROYH Database: UST, Date of Government Version: 06/24/2019	116 UNION AVENUE	NW 1/8 - 1/4 (0.230 mi.)	AH432	1055
KNIGHTS COLLISION RE Database: UST, Date of Government Version: 06/24/2019	120- 150 UNION AVENU	NW 1/8 - 1/4 (0.237 mi.)	AH439	1075
ANTONIA GONSALIS Database: UST, Date of Government Version: 06/24/2019	118-120 HARRISON AVE	WNW 1/8 - 1/4 (0.246 mi.)	446	1094

Lower Elevation	Address	Direction / Distance	Map ID	Page
78 THROOP AVE Database: UST, Date of Government Version: 06/24/2019	78 THROOP AVENUE	NNW 0 - 1/8 (0.024 mi.)	A36	36

Lower Elevation	Address	Direction / Distance	Map ID	Page
HOO CORP. Database: UST, Date of Government Version: 06/24/2019	94 WALLTON STREET	WNW 0 - 1/8 (0.103 mi.)	J224	414
BP SERVICE STATION # Database: UST, Date of Government Version: 06/24/2019	655 FLUSHING AVENUE	SSW 0 - 1/8 (0.104 mi.)	L226	417
160-163 HARRISON AVE Database: UST, Date of Government Version: 06/24/2019	86-90 WALTON STREET	WNW 0 - 1/8 (0.117 mi.)	J263	497
ACP BK I, LLC Database: UST, Date of Government Version: 06/24/2019	630 FLUSHING AVENUE	SSW 0 - 1/8 (0.119 mi.)	L268	505
SUSION DEVELPORS LLC Database: UST, Date of Government Version: 06/24/2019	594 BROADWAY	NNW 0 - 1/8 (0.120 mi.)	P274	605
429 MARCY AVENUE Database: UST, Date of Government Version: 06/24/2019	429 MARCY AVENUE	W 1/8 - 1/4 (0.248 mi.)	AM449	1102

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 06/24/2019 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PFIZER INC. BROOKLYN Facility Status: Unregulated/Closed CBS Number: 2-000082	***630 FLUSHING AVENUE***	***SSW 0 - 1/8 (0.119 mi.)***	***L271***	***592***

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 20 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ALL SAINTS R C CHURC Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-364673	***115 THROOP AVE***	***ESE 0 - 1/8 (0.062 mi.)***	***C117***	***215***
29-31 BARTLETT STREE Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-611766	29-31 BARTLETT STREE	SW 0 - 1/8 (0.068 mi.)	E139	250
EMS BATT 57 @ WOODHU Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-609575	131 THROOP AVENUE	SE 0 - 1/8 (0.080 mi.)	C177	321
709-715 FLUSHING AVE Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-610576	709-715 FLUSHING AVE	ESE 0 - 1/8 (0.114 mi.)	N254	481
I.S. 318 - BROOKLYN Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-355682	101 WALTON STREET	WNW 1/8 - 1/4 (0.126 mi.)	J283	626
GRAYCO CORP. Database: AST, Date of Government Version: 06/24/2019	29 COOK STREET	ENE 1/8 - 1/4 (0.162 mi.)	Q323	690

Facility Id: 2-608645

L.J.S.T. REALTY Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-607392	45 COOK STREET	ENE 1/8 - 1/4 (0.188 mi.)	Z364	788
P.S. 257 - BROOKLYN Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-354279	60 COOK STREET	E 1/8 - 1/4 (0.192 mi.)	Z374	806
30 FAMILY APT HOUSE Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-116823	77 VARET ST	ENE 1/8 - 1/4 (0.222 mi.)	AB412	885
LES-LEV CORP Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-246832	73 GRAHAM AVE	NE 1/8 - 1/4 (0.223 mi.)	415	890
NYC-HH - WOODHULL HO Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-406864	***760 BROADWAY***	***ESE 1/8 - 1/4 (0.230 mi.)***	***AG431***	***970***
UNITED STATES POSTAL Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-453137	47 DEBEVOISE STREET	E 1/8 - 1/4 (0.233 mi.)	AJ435	1068
KNIGHTS COLLISION RE Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-608507	120- 150 UNION AVENU	NW 1/8 - 1/4 (0.237 mi.)	AH441	1083
ENGINE COMPANY 230 Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-357383	701 PARK AVENUE	SSW 1/8 - 1/4 (0.239 mi.)	AK442	1085
5 STORY WAREHOUSE BL Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-130397	785 FLUSHING AVENUE	E 1/8 - 1/4 (0.243 mi.)	AG444	1090

Lower Elevation	Address	Direction / Distance	Map ID	Page
MAGIC AUTO REPAIR SH Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-610019	398 WALLABOUT STREET	NW 0 - 1/8 (0.044 mi.)	B72	97
SOSA DIAGNOSTIC REPA Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-610529	620 BROADWAY	N 0 - 1/8 (0.062 mi.)	D118	220
LOT 38,TAXBLOCK 2250 Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-481343	***307 WALLABOUT STREET***	***NW 0 - 1/8 (0.070 mi.)***	***B145***	***259***
ACUMEN PARTNERS LLC Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-017329	***630 FLUSHING AVE***	***SSW 0 - 1/8 (0.119 mi.)***	***L269***	***520***
ULTIMATE AUTO REPAIR Database: AST, Date of Government Version: 06/24/2019 Facility Id: 2-605910	45 WALTON STREET	W 1/8 - 1/4 (0.231 mi.)	AE434	1066

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PFIZER INC. BROOKLYN	***630 FLUSHING AVENUE***	***SSW 0 - 1/8 (0.119 mi.)***	***L271***	***592***
Facility Status: 1 Facility Status: 1 CBS Number: 2-000082				

State and tribal institutional control / engineering control registries

NY RES DECL: A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

A review of the NY RES DECL list, as provided by EDR, has revealed that there are 2 NY RES DECL sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 10,TAXBLOCK 2250	***88 WALTON STREET***	***WNW 0 - 1/8 (0.115 mi.)***	***J255***	***485***
Database: ENV RES DECL, Date of Government Version: 02/13/2019				
LOT 4,TAXBLOCK 2250	***161 HARRISON AVENUE***	***W 0 - 1/8 (0.117 mi.)***	***J265***	***502***
Database: ENV RES DECL, Date of Government Version: 02/13/2019				

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 05/13/2019 has revealed that there are 3 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PFIZER SITES B AND D	***59-71 GERRY ST. AND***	***WSW 0 - 1/8 (0.057 mi.)***	***B97***	***118***
Site Code: 58206				
FORMER CASCADE LAUND	***553 MARCY AVENUE***	***SSW 1/4 - 1/2 (0.406 mi.)***	***489***	***1268***
Site Code: 495614				

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER CHARLES PFIZE	***407 MARCY AVENUE***	***W 1/4 - 1/2 (0.260 mi.)***	***AL458***	***1117***
Site Code: 479327				

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 05/13/2019 has revealed that there are 3 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PFIZER SITES B AND D Site Code: 58206	***59-71 GERRY ST. AND***	***WSW 0 - 1/8 (0.057 mi.)***	***B97***	***118***
FORMER CASCADE LAUND Site Code: 495614	***553 MARCY AVENUE***	***SSW 1/4 - 1/2 (0.406 mi.)***	***489***	***1268***

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER CHARLES PFIZE Site Code: 479327	***407 MARCY AVENUE***	***W 1/4 - 1/2 (0.260 mi.)***	***AL458***	***1117***

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 42 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
82 THROOP AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	82 THROOP AVENUE	NW 0 - 1/8 (0.015 mi.)	A21	20
390 WALLABOUT STREET Database: VCP NYC, Date of Government Version: 12/14/2018	390 WALLABOUT STREET	WNW 0 - 1/8 (0.047 mi.)	B82	107
386 AND 388 WALLABOU Database: VCP NYC, Date of Government Version: 12/14/2018	386 AND 388 WALLABOU	WNW 0 - 1/8 (0.051 mi.)	B90	114
11 WHIPPLE STREET Database: VCP NYC, Date of Government Version: 12/14/2018	11 WHIPPLE STREET	S 0 - 1/8 (0.057 mi.)	F96	118
PFIZER SITES B AND D Database: VCP, Date of Government Version: 05/13/2019 Site Code: 58206	***59-71 GERRY ST. AND***	***WSW 0 - 1/8 (0.057 mi.)***	***B97***	***118***
687 FLUSHING AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	687 FLUSHING AVENUE	SSE 0 - 1/8 (0.078 mi.)	F164	279
169 LORIMER STREET Database: VCP NYC, Date of Government Version: 12/14/2018	169 LORIMER STREET	NW 1/8 - 1/4 (0.172 mi.)	X340	724
153 LORIMER STREET Database: VCP NYC, Date of Government Version: 12/14/2018	153 LORIMER STREET	WNW 1/8 - 1/4 (0.178 mi.)	X350	763
151 LORIMER STREET Database: VCP NYC, Date of Government Version: 12/14/2018	151 LORIMER STREET	WNW 1/8 - 1/4 (0.179 mi.)	X353	768
196 MIDDLETON STREET Database: VCP NYC, Date of Government Version: 12/14/2018	196 MIDDLETON STREET	NW 1/8 - 1/4 (0.199 mi.)	X381	819
179 THROOP AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	179 THROOP AVENUE	SSE 1/8 - 1/4 (0.201 mi.)	W382	820

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
100 UNION AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	100 UNION AVENUE	WNW 1/8 - 1/4 (0.201 mi.)	AA385	826
221 MIDDLETON STREET Database: VCP NYC, Date of Government Version: 12/14/2018	221 MIDDLETON STREET	NW 1/8 - 1/4 (0.223 mi.)	AH414	889
150 UNION AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	150 UNION AVENUE	NW 1/4 - 1/2 (0.281 mi.)	462	1181
901 MYRTLE AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	901 MYRTLE AVENUE	S 1/4 - 1/2 (0.384 mi.)	479	1247
948 MYRTLE AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	948 MYRTLE AVENUE	SSE 1/4 - 1/2 (0.402 mi.)	486	1262
922 MYRTLE AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	922 MYRTLE AVENUE	S 1/4 - 1/2 (0.403 mi.)	488	1267
802-806 MYRTLE AVENU Database: VCP NYC, Date of Government Version: 12/14/2018	802-806 MYRTLE AVENU	SSW 1/4 - 1/2 (0.483 mi.)	501	1333
74 VERNON AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	74 VERNON AVENUE	SSW 1/4 - 1/2 (0.491 mi.)	502	1334
1-37 FORREST STREET Database: VCP NYC, Date of Government Version: 12/14/2018	1-37 FORREST STREET	E 1/4 - 1/2 (0.497 mi.)	506	1346
83 BUSHWICK PLACE Database: VCP NYC, Date of Government Version: 12/14/2018	83 BUSHWICK PLACE	NE 1/4 - 1/2 (0.498 mi.)	507	1347
11-23 MONTIETH STREE Database: VCP NYC, Date of Government Version: 12/14/2018	11-23 MONTIETH STREE	E 1/4 - 1/2 (0.499 mi.)	508	1348

Lower Elevation	Address	Direction / Distance	Map ID	Page
78 THROOP AVE Database: VCP NYC, Date of Government Version: 12/14/2018	78 THROOP AVE	NNW 0 - 1/8 (0.024 mi.)	A38	39
72 THROOP AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	72 THROOP AVENUE	NNW 0 - 1/8 (0.038 mi.)	B63	88
376-382 WALLABOUT ST Database: VCP NYC, Date of Government Version: 12/14/2018	376-382 WALLABOUT ST	W 0 - 1/8 (0.066 mi.)	B136	246
311-313 WALLABOUT ST Database: VCP NYC, Date of Government Version: 12/14/2018	311-313 WALLABOUT ST	NW 0 - 1/8 (0.069 mi.)	H143	258
299-301 WALLABOUT ST Database: VCP NYC, Date of Government Version: 12/14/2018	299-301 WALLABOUT ST	WNW 0 - 1/8 (0.070 mi.)	B148	262
661 FLUSHING AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	661 FLUSHING AVENUE	SSW 0 - 1/8 (0.079 mi.)	F170	310
207 HARRISON AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	207 HARRISON AVENUE	SSW 0 - 1/8 (0.085 mi.)	L192	343
177 HARRISON AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	177 HARRISON AVENUE	WSW 0 - 1/8 (0.090 mi.)	K198	369
116 WALTON STREET Database: VCP NYC, Date of Government Version: 12/14/2018	116 WALTON STREET	NW 0 - 1/8 (0.096 mi.)	H213	396
52-56 THROOP AVENUE Database: VCP NYC, Date of Government Version: 12/14/2018	52-56 THROOP AVENUE	NW 0 - 1/8 (0.099 mi.)	H218	404
88 WALTON STREET Database: VCP NYC, Date of Government Version: 12/14/2018	88 WALTON STREET	WNW 0 - 1/8 (0.115 mi.)	J256	487

Lower Elevation	Address	Direction / Distance	Map ID	Page
ACUMEN PARTNERS LLC	***630 FLUSHING AVE***	***SSW 0 - 1/8 (0.119 mi.)***	***L269***	***520***
Database: VCP, Date of Government Version: 05/13/2019 Site Code: 56802				
PFIZER (ORGANICS/SUC	CENTRAL PORTION OF P	SW 1/8 - 1/4 (0.162 mi.)	324	692
Database: VCP, Date of Government Version: 05/13/2019 Site Code: 58107				
45 WALTON STREET	45 WALTON STREET	W 1/8 - 1/4 (0.224 mi.)	AE417	893
Database: VCP NYC, Date of Government Version: 12/14/2018				
43 WALTON STREET	43 WALTON STREET	W 1/8 - 1/4 (0.229 mi.)	AE428	918
Database: VCP NYC, Date of Government Version: 12/14/2018				
415-419 MARCY AVENUE	415-419 MARCY AVENUE	W 1/4 - 1/2 (0.255 mi.)	AM457	1116
Database: VCP NYC, Date of Government Version: 12/14/2018				
242 - 246 WALLABOUT	242 - 246 WALLABOUT	WSW 1/4 - 1/2 (0.368 mi.)	AQ475	1227
Database: VCP NYC, Date of Government Version: 12/14/2018				
535 FLUSHING AVENUE	535 FLUSHING AVENUE	WSW 1/4 - 1/2 (0.400 mi.)	AS482	1253
Database: VCP NYC, Date of Government Version: 12/14/2018				
260 LEE AVENUE	260 LEE AVENUE	WSW 1/4 - 1/2 (0.407 mi.)	AQ490	1308
Database: VCP NYC, Date of Government Version: 12/14/2018				
527 FLUSHING AVENUE	527 FLUSHING AVENUE	WSW 1/4 - 1/2 (0.414 mi.)	AS491	1308
Database: VCP NYC, Date of Government Version: 12/14/2018				

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 05/13/2019 has revealed that there are 8 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SITE B PFIZER Site Code: 333571	59-71 GERRY STREET A	WSW 0 - 1/8 (0.057 mi.)	B98	185
100 UNION AVENUE RED Site Code: 569083	***100 UNION AVENUE***	***WNW 1/8 - 1/4 (0.201 mi.)***	***AA384***	***824***
159 BOERUM STREET Site Code: 582502	159 BOERUM STREET	NE 1/4 - 1/2 (0.350 mi.)	467	1191
FORMER CASCADE LAUND Site Code: 495614	***553 MARCY AVENUE***	***SSW 1/4 - 1/2 (0.406 mi.)***	***489***	***1268***
FORMER TECHTRONICS S Site Code: 578363	***480 FLUSHING AVENUE***	***WSW 1/4 - 1/2 (0.497 mi.)***	***AW505***	***1341***

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER PFIZER SITE C Site Code: 579698	***334 WALLABOUT STREET***	***WSW 1/8 - 1/4 (0.158 mi.)***	***T305***	***664***
FORMER PFIZER SITE A	243-271 WALLABOUT ST	WSW 1/8 - 1/4 (0.181 mi.)	T356	772

Site Code: 576972				
FORMER CHARLES PFIZE Site Code: 479327	407 MARCY AVENUE	W 1/4 - 1/2 (0.260 mi.)	AL459	1162

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 08/12/2019 has revealed that there are 37 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DRUM RUN Spill Number/Closed Date: 1311882 / 2014-05-13 Site ID: 492812 Spill Date: 2014-03-20	57 BARTLETT ST	SSW 0 - 1/8 (0.002 mi.)	A15	15
DRUM RUN Spill Number/Closed Date: 1000520 / 2010-05-05 Site ID: 431688 Spill Date: 2010-04-13	CORNER THROOP AVE AN	ESE 0 - 1/8 (0.008 mi.)	A18	17
BROADWAY TRIANGLE Spill Number/Closed Date: 9212706 / 1999-06-28 Site ID: 194234 Spill Date: 1993-01-31	THROOP AVE / BARTLET	E 0 - 1/8 (0.009 mi.)	A19	18
EMPTY LOT Spill Number/Closed Date: 9704207 / 2006-11-14 Spill Number/Closed Date: 9516449 / 2000-02-02 Site ID: 218170 Site ID: 137143 Spill Date: 1996-05-14 Spill Date: 1996-03-21	73-87 GERRY STREET	W 0 - 1/8 (0.034 mi.)	B55	62
VENT PIPE Spill Number/Closed Date: 1110386 / 2014-06-09 Site ID: 458220 Spill Date: 2011-11-21	63 GREY ROAD	WSW 0 - 1/8 (0.048 mi.)	B83	107
ROADWAY Spill Number/Closed Date: 0713265 / 2008-03-17 Site ID: 394991 Spill Date: 2008-03-14	THROUGHP AVE/WHIPPLE	SE 0 - 1/8 (0.057 mi.)	C99	187
COMMERCIAL LOT Spill Number/Closed Date: 0000431 / 2002-01-17 Spill Number/Closed Date: 0800660 / 2016-02-19 Site ID: 139733 Site ID: 396451	650 BROADWAY	NE 0 - 1/8 (0.059 mi.)	G102	192

Spill Date: 2000-04-11
Spill Date: 2008-04-15

58 GERRY ST LLC Spill Number/Closed Date: 1707889 / Not Reported Site ID: 564269 Spill Date: 2017-11-17	58 GERRY ST	WSW 0 - 1/8 (0.064 mi.)	E123	230
29 BARTLETT STREET Spill Number/Closed Date: 9506117 / 1995-08-24 Site ID: 134249 Spill Date: 1995-08-17	29 BARTLETT STREET	SW 0 - 1/8 (0.068 mi.)	E138	249
VS 2973 Spill Number/Closed Date: 9808993 / 2002-10-31 Site ID: 195838 Spill Date: 1998-10-19	WIPPLE ST/BROADWAY	E 0 - 1/8 (0.104 mi.)	I232	450
MANHOLE #1000 Spill Number/Closed Date: 0402435 / 2004-09-15 Site ID: 319830 Spill Date: 2004-06-04	THRO0P AVE & FLUSHIN	SE 0 - 1/8 (0.106 mi.)	N241	465
MANHOLE 7898 Spill Number/Closed Date: 0001002 / 2001-12-28 Site ID: 265435 Spill Date: 2000-04-25	THORNTON & THROOP AV	SE 0 - 1/8 (0.107 mi.)	N242	467

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNDERGROUND Spill Number/Closed Date: 1215332 / 2014-01-15 Site ID: 478626 Spill Date: 2013-02-05	78 THROOP AVE	NNW 0 - 1/8 (0.024 mi.)	A39	40
398 WALLABOUT STREET Spill Number/Closed Date: 9912454 / 2005-01-28 Site ID: 152358 Spill Date: 2000-01-31	398 WALLABOUT ST	NW 0 - 1/8 (0.044 mi.)	B74	100
WALLABOUT STREET AND Spill Number/Closed Date: 9900765 / 1999-06-22 Site ID: 260055 Spill Date: 1999-04-20	THROOP AVE	NNW 0 - 1/8 (0.057 mi.)	D100	188
APARTMENT BUILDING Spill Number/Closed Date: 0013601 / 2009-12-14 Site ID: 328889 Spill Date: 2001-03-28	613 BROADWAY	N 0 - 1/8 (0.088 mi.)	M194	345
SERVICE BOX # 7967 Spill Number/Closed Date: 0505280 / 2005-09-28 Site ID: 350231 Spill Date: 2005-07-29	285 WALLABOUT ST	W 0 - 1/8 (0.089 mi.)	J196	347
MANHOLE #73645 Spill Number/Closed Date: 0504634 / 2005-09-23 Site ID: 349511 Spill Date: 2005-07-17	HARRISON AVE NEAR BA	SW 0 - 1/8 (0.091 mi.)	L199	370
BARTLETT ST & HARRIS Spill Number/Closed Date: 0330009 / 2003-05-16	BARTLETT STREET/HARR	SW 0 - 1/8 (0.091 mi.)	L200	371

Site ID: 60814 Spill Date: 2003-05-16				
VAULT 3871 Spill Number/Closed Date: 9901618 / 2002-04-03 Site ID: 202877 Spill Date: 1999-05-11	MOORE AND LEONARD ST	N 0 - 1/8 (0.093 mi.)	M202	381
UNDER GROUND TRANFOR Spill Number/Closed Date: 1508657 / 2016-02-10 Site ID: 517229 Spill Date: 2015-11-20	HARRISON AVE AND GER	WSW 0 - 1/8 (0.094 mi.)	K207	387
DRUM RUN Spill Number/Closed Date: 0900534 / 2009-04-20 Site ID: 412477 Spill Date: 2009-04-15	GERRY ST & HARRISON	WSW 0 - 1/8 (0.095 mi.)	K210	392
MANHOLE 1144 Spill Number/Closed Date: 0300137 / 2003-07-18 Site ID: 226631 Spill Date: 2003-04-04	GERRY ST/HARRISON AV	WSW 0 - 1/8 (0.095 mi.)	K211	393
MANHOLE #42919 Spill Number/Closed Date: 0304585 / 2004-10-13 Site ID: 65498 Spill Date: 2003-07-30	THOMPKINS & FLUSHING	SSW 0 - 1/8 (0.099 mi.)	L214	396
CONED MANHOLE #7420 Spill Number/Closed Date: 0401891 / 2004-09-09 Site ID: 140065 Spill Date: 2004-05-20	FLUSHING/THOMPKINS	SSW 0 - 1/8 (0.099 mi.)	L215	398
PFIZER INC BROOKLYN Spill Number/Closed Date: 9505760 / 1995-08-10 Site ID: 278551 Spill Date: 1995-08-09	***11 BARTLETT ST***	***SW 0 - 1/8 (0.099 mi.)***	***L217***	***402***
VAULT 1336 & 1473 Spill Number/Closed Date: 0211143 / 2003-09-29 Site ID: 330346 Spill Date: 2003-02-05	FLUSHING AVE & TOMPK	SSW 0 - 1/8 (0.102 mi.)	L221	410
MANHOLE 20779 Spill Number/Closed Date: 1300441 / 2013-07-08 Site ID: 480768 Spill Date: 2013-04-13	HARRISON AVE AND FLU	SSW 0 - 1/8 (0.102 mi.)	L222	412
MANHOLE Spill Number/Closed Date: 1300013 / 2013-05-14 Site ID: 480319 Spill Date: 2013-04-01	HARRISON AVE AND FLU	SSW 0 - 1/8 (0.102 mi.)	L223	413
AMOCO Spill Number/Closed Date: 0402082 / 2004-05-26 Spill Number/Closed Date: 0104597 / Not Reported Spill Number/Closed Date: 8401982 / 2003-02-27 Site ID: 264646 Site ID: 196822 Site ID: 196823 Spill Date: 2004-05-25 Spill Date: 2001-07-30	655 FLUSHING AVE	SSW 0 - 1/8 (0.104 mi.)	L231	434

Spill Date: 1984-10-26				
TRANSFORMER VAULT 14 Spill Number/Closed Date: 0607919 / 2007-02-16 Site ID: 371760 Spill Date: 2006-10-11	2 TOMPKINS AVE AT FL	SSW 0 - 1/8 (0.105 mi.)	L233	451
MANHOLE 468 Spill Number/Closed Date: 0005173 / 2001-10-25 Site ID: 285893 Spill Date: 2000-07-31	WALLABOUT ST/HARRISO	W 0 - 1/8 (0.111 mi.)	K244	468
DRUM RUN Spill Number/Closed Date: 0704064 / 2007-08-09 Site ID: 384146 Spill Date: 2007-07-11	BROADWAY & WALTON ST	NNW 0 - 1/8 (0.116 mi.)	M258	488
ACUMEN PARTNERS LLC Spill Number/Closed Date: 1011062 / 2014-01-14 Spill Number/Closed Date: 0203912 / 2003-09-17 Spill Number/Closed Date: 9505769 / 1995-08-10 Spill Number/Closed Date: 0013515 / 2003-06-16 Spill Number/Closed Date: 9303325 / 2006-04-05 Site ID: 444686 Site ID: 302547 Site ID: 302548 Site ID: 201032 Site ID: 201033 Spill Date: 2011-02-01 Spill Date: 2002-07-14 Spill Date: 1995-08-09 Spill Date: 2001-03-27 Spill Date: 1993-06-14	***630 FLUSHING AVE***	***SSW 0 - 1/8 (0.119 mi.)***	***L269***	***520***
CITGO/ 594 BROADWAY Spill Number/Closed Date: 9507227 / Not Reported Site ID: 74922 Spill Date: 1995-08-31	594 BROADWAY	NNW 0 - 1/8 (0.120 mi.)	P272	601
ELLAYAH DELI GROCERY Spill Number/Closed Date: 1400390 / 2014-04-11 Site ID: 493627 Spill Date: 2014-04-11	590 BROADWAY	NNW 0 - 1/8 (0.120 mi.)	P276	613
MANHOLE #997 Spill Number/Closed Date: 9903465 / 1999-10-20 Site ID: 172742 Spill Date: 1999-06-25	FLUSHING AVE & DELMO	SSW 0 - 1/8 (0.121 mi.)	L277	614

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/25/2019 has revealed that

there are 90 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA ID:: NYP004333621	***49 BARTLET ST FRONT***	***SSW 0 - 1/8 (0.020 mi.)***	***A27***	***23***
CON EDISON SERVICE B EPA ID:: NYP004414231	***47 BARTLETT ST***	***SSW 0 - 1/8 (0.023 mi.)***	***A31***	***27***
GERRY PROJECT EPA ID:: NYR000220517	81-85 GERRY ST	W 0 - 1/8 (0.027 mi.)	A44	46
CON EDISON EPA ID:: NYP004829572	***76 BARTLETT ST***	***E 0 - 1/8 (0.038 mi.)***	***C59***	***67***
CON EDISON EPA ID:: NYP004884868	***95 THROOP AVE***	***ESE 0 - 1/8 (0.045 mi.)***	***C78***	***104***
CON EDISON EPA ID:: NYP004738043	***648 BROADWAY***	***NE 0 - 1/8 (0.060 mi.)***	***D111***	***205***
CON EDISON TRANSFORM EPA ID:: NYP004550265	34 WHIPPLE ST	SE 0 - 1/8 (0.065 mi.)	C131	240
CON EDISON SERVICE B EPA ID:: NYP004334918	***18 WHIPPLE ST FRONT***	***SSE 0 - 1/8 (0.066 mi.)***	***F137***	***247***
CON EDISON EPA ID:: NYP004791927	BARTLETT ST & BROADW	ENE 0 - 1/8 (0.076 mi.)	G161	276
CON EDISON EPA ID:: NYP004186920	***WHIPPLE ST & FLUSHIN***	***S 0 - 1/8 (0.080 mi.)***	***F171***	***311***
CON EDISON EPA ID:: NYP004831042	***131 THROOP AVE***	***SE 0 - 1/8 (0.080 mi.)***	***C178***	***323***
CON EDISON EPA ID:: NYP004822066	***THROOP AVE & FLUSHIN***	***SE 0 - 1/8 (0.112 mi.)***	***N249***	***475***
CON EDISON SERVICE B EPA ID:: NYP004313276	***12 MANHATTAN AVE***	***ENE 0 - 1/8 (0.112 mi.)***	***I252***	***478***
CON EDISON EPA ID:: NYP004426862	***149 HOPKINS ST***	***S 0 - 1/8 (0.117 mi.)***	***O261***	***492***
CON EDISON EPA ID:: NYP004884744	***161 HOPKINS ST***	***S 0 - 1/8 (0.118 mi.)***	***O267***	***504***
NYC DEPT OF EDUCATIO EPA ID:: NYD986953461	***101 WALTON ST***	***WNW 1/8 - 1/4 (0.126 mi.)***	***J282***	***622***
CON EDISON - VS 2314 EPA ID:: NYP004106852	***93 HOPKINS ST***	***SSW 1/8 - 1/4 (0.134 mi.)***	***O289***	***639***
CON EDISON SERVICE B EPA ID:: NYP004482386	***32 VARET ST***	***ENE 1/8 - 1/4 (0.138 mi.)***	***Q290***	***642***
CON EDISON EPA ID:: NYP004776399	BROADWAY & DEBEVOISE	E 1/8 - 1/4 (0.140 mi.)	R291	645
CON EDISON EPA ID:: NYP004826572	***BROADWAY & DEBEVOISE***	***E 1/8 - 1/4 (0.140 mi.)***	***R292***	***645***
CON EDISON EPA ID:: NYP004786687	***720 BROADWAY***	***ESE 1/8 - 1/4 (0.154 mi.)***	***R299***	***656***
CON EDISON SERVICE B EPA ID:: NYP004567442	***46 MANHATTAN AVE***	***NE 1/8 - 1/4 (0.157 mi.)***	***U303***	***662***
CON EDISON	743 FLUSHING AVE SB7	ESE 1/8 - 1/4 (0.159 mi.)	V307	670

EPA ID:: NYP004733770				
CON EDISON	***743 FLUSHING AVE SB7***	***ESE 1/8 - 1/4 (0.159 mi.)***	***V309***	***672***
EPA ID:: NYP004733762				
CON EDISON	722 BROADWAY	ESE 1/8 - 1/4 (0.160 mi.)	R316	681
EPA ID:: NYP004819375				
CON EDISON	***745 FLUSHING AVE***	***ESE 1/8 - 1/4 (0.161 mi.)***	***R318***	***683***
EPA ID:: NYP004756904				
CON EDISON	***164 THROOP AVE***	***SSE 1/8 - 1/4 (0.162 mi.)***	***W320***	***686***
EPA ID:: NYP004821365				
CON EDISON	***749 FLUSHING AVE***	***ESE 1/8 - 1/4 (0.168 mi.)***	***R331***	***710***
EPA ID:: NYP004756896				
CON EDISON	***168 THROOP AVE***	***SSE 1/8 - 1/4 (0.170 mi.)***	***W337***	***720***
EPA ID:: NYP004738571				
CON EDISON	168 THROOP AVE	SSE 1/8 - 1/4 (0.170 mi.)	W339	723
EPA ID:: NYP004738357				
CON EDISON SERVICE B	***50 MANHATTAN AVE***	***NE 1/8 - 1/4 (0.173 mi.)***	***U344***	***734***
EPA ID:: NYP004310744				
CON ED - VS 5285	***SEIGAL ST & MANHATTA***	***NNE 1/8 - 1/4 (0.182 mi.)***	***U357***	***774***
EPA ID:: NYP004006680				
CON EDISON SERVICE B	***45 COOK ST***	***ENE 1/8 - 1/4 (0.188 mi.)***	***Z365***	***790***
EPA ID:: NYP004508164				
CON EDISON SERVICE B	***5 GRAHAM AVE***	***ESE 1/8 - 1/4 (0.188 mi.)***	***V368***	***795***
EPA ID:: NYP004515466				
CON EDISON	BROADWAY & GRAHAM AV	ESE 1/8 - 1/4 (0.191 mi.)	V370	797
EPA ID:: NYP004835746				
CON EDISON SERVICE B	***47 GRAHAM AVE***	***ENE 1/8 - 1/4 (0.194 mi.)***	***Z375***	***809***
EPA ID:: NYP004441374				
CON EDISON SERVICE B	51 GRAHAM AVE	ENE 1/8 - 1/4 (0.195 mi.)	AB376	811
EPA ID:: NYP004568747				
CON EDISON SERVICE B	***44 GRAHAM AVE***	***E 1/8 - 1/4 (0.197 mi.)***	***Z378***	***814***
EPA ID:: NYP004513560				
CON EDISON SERVICE B	***VARET ST & GRAHAM AV***	***ENE 1/8 - 1/4 (0.198 mi.)***	***Z380***	***817***
EPA ID:: NYP004471389				
CON EDISON - 67 MANH	***67 MANHATTAN AVE***	***NNE 1/8 - 1/4 (0.202 mi.)***	***AC386***	***827***
EPA ID:: NYR000026468				
CON EDISON MANHOLE:	***67 MANHATTAN AVE***	***NNE 1/8 - 1/4 (0.202 mi.)***	***AC387***	***830***
EPA ID:: NYP004311049				
CON EDISON SERVICE B	***204 ELLERY ST***	***SSE 1/8 - 1/4 (0.205 mi.)***	***AF396***	***851***
EPA ID:: NYP004385704				
CON EDISON SERVICE B	***55 WALTON ST***	***W 1/8 - 1/4 (0.213 mi.)***	***AE399***	***858***
EPA ID:: NYP004288635				
CON EDISON	***FLUSHING AVE & BROAD***	***ESE 1/8 - 1/4 (0.213 mi.)***	***AG400***	***861***
EPA ID:: NYP004186953				
CON EDISON	FLUSHING AVE & BROAD	ESE 1/8 - 1/4 (0.213 mi.)	AG404	870
EPA ID:: NYP004835597				
MTA NYCT - FLUSHING	***FLUSHING AVE & BROAD***	***ESE 1/8 - 1/4 (0.213 mi.)***	***AG405***	***871***

EPA ID:: NYR000082081				
CON EDISON	***747 PARK AVE***	***S 1/8 - 1/4 (0.217 mi.)***	***Y407***	***876***
EPA ID:: NYP004183547				
CON EDISON	***UNION AVE & MIDDLETO***	***WNW 1/8 - 1/4 (0.221 mi.)***	***AA411***	***884***
EPA ID:: NYP004833097				
CON EDISON SERVICE B	***77 VARET ST***	***ENE 1/8 - 1/4 (0.222 mi.)***	***AB413***	***887***
EPA ID:: NYP004471397				
CON EDISON	76 GRAHAM AVE	ENE 1/8 - 1/4 (0.226 mi.)	AB420	901
EPA ID:: NYP004846026				
CON EDISON SERVICE B	756 PARK AVE	SSE 1/8 - 1/4 (0.237 mi.)	AF436	1071
EPA ID:: NYP004567491				
KNIGHTS COLLISION EX	***120 UNION AVE***	***NW 1/8 - 1/4 (0.237 mi.)***	***AH440***	***1079***
EPA ID:: NYD012575643				
AVALON INDUSTRIES IN	***95 LORIMER ST***	***W 1/8 - 1/4 (0.243 mi.)***	***AL443***	***1088***
EPA ID:: NYD001233402				
CON EDISON	***97 VARET ST***	***ENE 1/8 - 1/4 (0.248 mi.)***	***AN451***	***1108***
EPA ID:: NYP004845901				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B	***125 GERRY ST***	***N 0 - 1/8 (0.033 mi.)***	***D50***	***54***
EPA ID:: NYP004307450				
CON EDISON	***72-74 THROOP AVE & G***	***NNW 0 - 1/8 (0.038 mi.)***	***B64***	***89***
EPA ID:: NYP004801981				
CON EDISON SERVICE B	***622 BROADWAY***	***N 0 - 1/8 (0.060 mi.)***	***D105***	***197***
EPA ID:: NYP004512307				
CON EDISON SERVICE B	622 BROADWAY	N 0 - 1/8 (0.060 mi.)	D108	201
EPA ID:: NYP004559654				
CON EDISON MANHOLE:	***378 WALLABOUT ST***	***W 0 - 1/8 (0.062 mi.)***	***B119***	***223***
EPA ID:: NYP004446282				
CON EDISON	BROADWAY & GERRY ST	NNE 0 - 1/8 (0.064 mi.)	D125	233
EPA ID:: NYP004794509				
CON EDISON	***BROADWAY & GERRY ST***	***NNE 0 - 1/8 (0.064 mi.)***	***D127***	***235***
EPA ID:: NYP004794491				
WALLABOUT BUILDINGS	***376-382 WALLABOUT ST***	***W 0 - 1/8 (0.066 mi.)***	***B135***	***243***
EPA ID:: NYR000203521				
VARTEX INSTRUMENT CO	***311 WALLABOUT ST***	***NW 0 - 1/8 (0.069 mi.)***	***H141***	***253***
EPA ID:: NYR000084483				
CON EDISON SERVICE B	***372 WALLABOUT ST***	***W 0 - 1/8 (0.073 mi.)***	***B152***	***265***
EPA ID:: NYP004446217				
CON EDISON SERVICE B	***45 THROOP AVE***	***NNW 0 - 1/8 (0.076 mi.)***	***H158***	***271***
EPA ID:: NYP004409629				
ACE RAPID CLEANERS	***209 HARRISON AVE***	***SSW 0 - 1/8 (0.083 mi.)***	***E186***	***328***
EPA ID:: NYD045446994				
V4821	***48 GERRY STREET***	***WSW 0 - 1/8 (0.083 mi.)***	***K188***	***337***
EPA ID:: NYP004034575				
CON EDISON SERVICE B	***366 WALLABOUT ST***	***W 0 - 1/8 (0.084 mi.)***	***J190***	***340***

EPA ID:: NYP004446225				
CON ED - MH 485 EPA ID:: NYP004006821	***GERRY ST & HARRISON***	***WSW 0 - 1/8 (0.094 mi.)***	***K206***	***385***
CON EDISON EPA ID:: NYP004745261	2 TOMPKINS AVE	SSW 0 - 1/8 (0.105 mi.)	L235	454
CON EDISON EPA ID:: NYP004745469	***2 TOMPKINS AVE***	***SSW 0 - 1/8 (0.105 mi.)***	***L236***	***455***
CON EDISON SERVICE B EPA ID:: NYP004446290	***HARRISON AVE & WALLA***	***W 0 - 1/8 (0.111 mi.)***	***K245***	***469***
CON EDISON EPA ID:: NYP004743332	***HARRISSON & WALLABOU***	***W 0 - 1/8 (0.111 mi.)***	***K248***	***474***
HARRISON WALTON PROP EPA ID:: NYR000226365	***86-90 WALTON ST***	***WNW 0 - 1/8 (0.117 mi.)***	***J264***	***500***
RICHARDS AUTO REPAIR EPA ID:: NYU005001185	***594 BROADWAY***	***NNW 0 - 1/8 (0.120 mi.)***	***P273***	***603***
CON EDISON SERVICE B EPA ID:: NYP004410114	***147 WALTON ST***	***NNW 0 - 1/8 (0.122 mi.)***	***P278***	***615***
CON EDISON EPA ID:: NYP004885196	***22-66 LEONARD ST***	***N 0 - 1/8 (0.122 mi.)***	***M279***	***618***
PFIZER INC BROOKLYN EPA ID:: NY0000055384	***338 WALLABOUT ST***	***WSW 1/8 - 1/4 (0.149 mi.)***	***T298***	***653***
CON EDISON - TM 1358 EPA ID:: NYP004111993	***THROOP AVE & LORIMER***	***NW 1/8 - 1/4 (0.159 mi.)***	***P306***	***667***
CON EDISON MANHOLE: EPA ID:: NYP004436226	***LORIMER ST & BROADWA***	***NNW 1/8 - 1/4 (0.163 mi.)***	***P325***	***694***
MTA NYCT - LORIMER S EPA ID:: NYR000082131	***LORIMER ST & BROADWA***	***NNW 1/8 - 1/4 (0.163 mi.)***	***P326***	***696***
CON EDISON EPA ID:: NYP004183687	***LORIMER ST & BROADWA***	***NNW 1/8 - 1/4 (0.163 mi.)***	***P327***	***699***
NYCTA - 22 THROOP AV EPA ID:: NY0000902171	***22 THROOP AVE***	***NW 1/8 - 1/4 (0.191 mi.)***	***X372***	***799***
TM2554 EPA ID:: NYP004046181	322 WALLABOUT STREET	WSW 1/8 - 1/4 (0.202 mi.)	AD389	840
V2107 EPA ID:: NYP004018420	***2-48 GERRY***	***SW 1/8 - 1/4 (0.226 mi.)***	***AI422***	***903***
V1821 EPA ID:: NYP004018412	***2 GERRY STREET***	***SW 1/8 - 1/4 (0.226 mi.)***	***AI423***	***905***
CON EDISON MANHOLE: EPA ID:: NYP004451571	***MARCY AVE & FLUSHING***	***SW 1/8 - 1/4 (0.227 mi.)***	***AI426***	***915***
CON EDISON MANHOLE: EPA ID:: NYP004451639	***MARCY AVE & WALLABOU***	***WSW 1/8 - 1/4 (0.237 mi.)***	***AD438***	***1073***
CON EDISON MANHOLE: EPA ID:: NYP004473062	***442 MARCY AVE***	***WSW 1/8 - 1/4 (0.243 mi.)***	***AD445***	***1092***
CON EDISON MANHOLE: EPA ID:: NYP004473013	***298 WALLABOUT AVE***	***WSW 1/8 - 1/4 (0.247 mi.)***	***AD448***	***1100***

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 05/15/2019 has revealed that there is 1 FUDS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KOLLMORGAN OPTICAL		WSW 1/2 - 1 (0.680 mi.)	516	1373

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 11/05/2018 has revealed that there are 3 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOTUS CLEANERS Facility Id: 2-6104-01050	***80 MANHATTAN AVE***	***NNE 1/8 - 1/4 (0.225 mi.)***	***AC418***	***894***
JOYFUL/A & K/GOOD NE Facility Id: 2-6104-01170	789 FLUSHING AVENUE	E 1/8 - 1/4 (0.248 mi.)	AG453	1110

Lower Elevation	Address	Direction / Distance	Map ID	Page
HARRISON/YORKTOWN/AC Facility Id: 2-6104-00956	209 HARRISON AVENUE	SSW 0 - 1/8 (0.083 mi.)	E185	328

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 02/28/2019 has revealed that there are 89 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 31,TAXBLOCK 2269	THROOP AVENUE	0 - 1/8 (0.000 mi.)	A13	14
LOT 28,TAXBLOCK 2269	THROOP AVENUE	0 - 1/8 (0.000 mi.)	A14	15
LOT 39,TAXBLOCK 2269	57 BARTLETT STREET	SSW 0 - 1/8 (0.002 mi.)	A16	16
LOT 40,TAXBLOCK 2269	55 BARTLETT STREET	SSW 0 - 1/8 (0.006 mi.)	A17	17
LOT 41,TAXBLOCK 2269	53 BARTLETT STREET	SSW 0 - 1/8 (0.011 mi.)	A20	19
LOT 34,TAXBLOCK 2266	82 THROOP AVENUE	NW 0 - 1/8 (0.015 mi.)	A22	21
LOT 42,TAXBLOCK 2269	51 BARTLETT STREET	SSW 0 - 1/8 (0.016 mi.)	A23	21
LOT 36,TAXBLOCK 2266	99 GERRY STREET	NW 0 - 1/8 (0.018 mi.)	A24	22
LOT 37,TAXBLOCK 2266	97 GERRY STREET	WNW 0 - 1/8 (0.018 mi.)	A25	22
LOT 38,TAXBLOCK 2266	95 GERRY STREET	WNW 0 - 1/8 (0.019 mi.)	A26	23
LOT 19,TAXBLOCK 2269	82 GERRY STREET	WSW 0 - 1/8 (0.020 mi.)	A28	25
LOT 39,TAXBLOCK 2266	93 GERRY STREET	WNW 0 - 1/8 (0.021 mi.)	A29	26
LOT 43,TAXBLOCK 2269	47 BARTLETT STREET	SSW 0 - 1/8 (0.023 mi.)	A32	29
LOT 40,TAXBLOCK 2266	91 GERRY STREET	WNW 0 - 1/8 (0.024 mi.)	A40	43
LOT 47,TAXBLOCK 2266	83 GERRY STREET	W 0 - 1/8 (0.026 mi.)	A41	43
LOT 46,TAXBLOCK 2266	83 GERRY STREET	W 0 - 1/8 (0.026 mi.)	A42	44
LOT 48,TAXBLOCK 2266	***81 GERRY STREET***	***W 0 - 1/8 (0.027 mi.)***	***A43***	***44***
LOT 18,TAXBLOCK 2269	76 GERRY STREET	WSW 0 - 1/8 (0.029 mi.)	A45	48
LOT 41,TAXBLOCK 2266	GERRY STREET	WNW 0 - 1/8 (0.030 mi.)	B47	49
LOT 45,TAXBLOCK 2269	43 BARTLETT STREET	SW 0 - 1/8 (0.033 mi.)	A49	53
LOT 17,TAXBLOCK 2269	74 GERRY STREET	WSW 0 - 1/8 (0.033 mi.)	A51	57

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 45,TAXBLOCK 2266	GERRY STREET	W 0 - 1/8 (0.034 mi.)	B52	57
LOT 16,TAXBLOCK 2269	GERRY STREET	WSW 0 - 1/8 (0.037 mi.)	B56	64
LOT 47,TAXBLOCK 2269	41 BARTLETT STREET	SW 0 - 1/8 (0.040 mi.)	E68	96
LOT 11,TAXBLOCK 2272	36 BARTLETT STREET	SSW 0 - 1/8 (0.042 mi.)	E69	96
LOT 14,TAXBLOCK 2269	GERRY STREET	WSW 0 - 1/8 (0.044 mi.)	B71	97
LOT 48,TAXBLOCK 2269	39 BARTLETT STREET	SW 0 - 1/8 (0.044 mi.)	E76	102
LOT 23,TAXBLOCK 2266	394 WALLABOUT STREET	NW 0 - 1/8 (0.045 mi.)	B79	105
LOT 22,TAXBLOCK 2266	392 WALLABOUT STREET	WNW 0 - 1/8 (0.046 mi.)	B80	105
LOT 21,TAXBLOCK 2266	390 WALLABOUT STREET	WNW 0 - 1/8 (0.047 mi.)	B81	106
LOT 49,TAXBLOCK 2269	37 BARTLETT STREET	SW 0 - 1/8 (0.049 mi.)	E84	109
LOT 20,TAXBLOCK 2266	388 WALLABOUT STREET	WNW 0 - 1/8 (0.049 mi.)	B85	109
LOT 49,TAXBLOCK 2266	GERRY STREET	W 0 - 1/8 (0.050 mi.)	B86	110
LOT 9,TAXBLOCK 2272	30 BARTLETT STREET	SSW 0 - 1/8 (0.050 mi.)	E88	113
LOT 19,TAXBLOCK 2266	386 WALLABOUT STREET	WNW 0 - 1/8 (0.051 mi.)	B89	113
LOT 18,TAXBLOCK 2266	384 WALLABOUT STREET	WNW 0 - 1/8 (0.053 mi.)	B92	115
LOT 50,TAXBLOCK 2269	35 BARTLETT STREET	SW 0 - 1/8 (0.054 mi.)	E93	116
LOT 17,TAXBLOCK 2266	382 WALLABOUT STREET	WNW 0 - 1/8 (0.056 mi.)	B94	116
LOT 45,TAXBLOCK 2272	11 WHIPPLE STREET	S 0 - 1/8 (0.057 mi.)	F95	117
LOT 16,TAXBLOCK 2266	380 WALLABOUT STREET	WNW 0 - 1/8 (0.059 mi.)	B103	195
LOT 46,TAXBLOCK 2272	9 WHIPPLE STREET	S 0 - 1/8 (0.060 mi.)	F115	214
LOT 6,TAXBLOCK 2272	24 BARTLETT STREET	SSW 0 - 1/8 (0.062 mi.)	E116	215
LOT 147,TAXBLOCK 227	5 WHIPPLE STREET	S 0 - 1/8 (0.063 mi.)	E121	225
LOT 52,TAXBLOCK 2269	31 BARTLETT STREET	SW 0 - 1/8 (0.066 mi.)	E132	241
LOT 108,TAXBLOCK 227	BARTLETT STREET	SSW 0 - 1/8 (0.066 mi.)	E133	242
LOT 5,TAXBLOCK 2274	16 WHIPPLE STREET	SSE 0 - 1/8 (0.070 mi.)	F146	261
LOT 6,TAXBLOCK 2274	WHIPPLE STREET	SSE 0 - 1/8 (0.071 mi.)	F150	264
LOT 1,TAXBLOCK 2274	2 WHIPPLE STREET	SSE 0 - 1/8 (0.072 mi.)	F151	265
LOT 49,TAXBLOCK 2272	WHIPPLE STREET	S 0 - 1/8 (0.074 mi.)	F153	267
LOT 51,TAXBLOCK 2272	665 FLUSHING AVENUE	SSW 0 - 1/8 (0.074 mi.)	F154	268
LOT 52,TAXBLOCK 2272	665 FLUSHING AVENUE	SSW 0 - 1/8 (0.074 mi.)	F155	268
LOT 24,TAXBLOCK 2274	687 FLUSHING AVENUE	SSE 0 - 1/8 (0.078 mi.)	F163	278
LOT 16,TAXBLOCK 2274	134 THROOP AVENUE	SE 0 - 1/8 (0.093 mi.)	N203	382

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 31,TAXBLOCK 2266	76 THROOP AVENUE	NNW 0 - 1/8 (0.029 mi.)	A46	48
LOT 30,TAXBLOCK 2266	74 THROOP AVENUE	NNW 0 - 1/8 (0.034 mi.)	B53	58
LOT 29,TAXBLOCK 2266	72 THROOP AVENUE	NNW 0 - 1/8 (0.038 mi.)	B66	91
LOT 25,TAXBLOCK 2266	398 WALLABOUT STREET	NW 0 - 1/8 (0.044 mi.)	B73	99
LOT 24,TAXBLOCK 2266	396 WALLABOUT STREET	NW 0 - 1/8 (0.044 mi.)	B75	101
LOT 15,TAXBLOCK 2266	378 WALLABOUT STREET	W 0 - 1/8 (0.062 mi.)	B120	225
LOT 14,TAXBLOCK 2266	376 WALLABOUT STREET	W 0 - 1/8 (0.066 mi.)	B134	242
LOT 33,TAXBLOCK 2250	66 THROOP AVENUE	NW 0 - 1/8 (0.068 mi.)	H140	253
VARTEX INSTRUMENT CO	***311 WALLABOUT ST***	***NW 0 - 1/8 (0.069 mi.)***	***H141***	***253***
LOT 37,TAXBLOCK 2250	311 WALLABOUT STREET	NW 0 - 1/8 (0.069 mi.)	H142	257
LOT 43,TAXBLOCK 2250	301 WALLABOUT STREET	WNW 0 - 1/8 (0.069 mi.)	B144	258
LOT 38,TAXBLOCK 2250	***307 WALLABOUT STREET***	***NW 0 - 1/8 (0.070 mi.)***	***B145***	***259***
LOT 44,TAXBLOCK 2250	299 WALLABOUT STREET	WNW 0 - 1/8 (0.070 mi.)	B147	262
LOT 40,TAXBLOCK 2250	305 WALLABOUT STREET	WNW 0 - 1/8 (0.071 mi.)	B149	263
LOT 42,TAXBLOCK 2250	WALLABOUT STREET	WNW 0 - 1/8 (0.075 mi.)	H156	269
LOT 53,TAXBLOCK 2272	663 FLUSHING AVENUE	SSW 0 - 1/8 (0.077 mi.)	F162	278
PFIZER INC	***191 HARRISON AVE***	***SW 0 - 1/8 (0.079 mi.)***	***E165***	***279***
LOT 54,TAXBLOCK 2272	***661 FLUSHING AVENUE***	***SSW 0 - 1/8 (0.079 mi.)***	***F169***	***308***
LOT 45,TAXBLOCK 2250	WALLABOUT STREET	WNW 0 - 1/8 (0.081 mi.)	J179	325
LOT 129,TAXBLOCK 225	THROOP AVENUE	NW 0 - 1/8 (0.081 mi.)	H180	325
LOT 32,TAXBLOCK 2250	62 THROOP AVENUE	NW 0 - 1/8 (0.081 mi.)	H181	326

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 1,TAXBLOCK 2266	HARRISON AVENUE	W 0 - 1/8 (0.082 mi.)	K182	326
LOT 55,TAXBLOCK 2272	659 FLUSHING AVENUE	SSW 0 - 1/8 (0.082 mi.)	F183	327
LOT 46,TAXBLOCK 2250	291 WALLABOUT STREET	WNW 0 - 1/8 (0.083 mi.)	J187	337
LOT 9,TAXBLOCK 2266	366 WALLABOUT STREET	W 0 - 1/8 (0.084 mi.)	J189	340
LOT 3,TAXBLOCK 2272	207 HARRISON AVENUE	SSW 0 - 1/8 (0.085 mi.)	L191	342
LOT 48,TAXBLOCK 2250	289 WALLABOUT STREET	WNW 0 - 1/8 (0.087 mi.)	J193	344
LOT 29,TAXBLOCK 2250	56 THROOP AVENUE	NW 0 - 1/8 (0.088 mi.)	H195	347
LOT 28,TAXBLOCK 2250	***54 THROOP AVENUE***	***NW 0 - 1/8 (0.094 mi.)***	***H208***	***388***
LOT 25,TAXBLOCK 2250	116 WALTON STREET	NW 0 - 1/8 (0.096 mi.)	H212	395
LOT 27,TAXBLOCK 2250	52 THROOP AVENUE	NW 0 - 1/8 (0.099 mi.)	H220	410
LOT 14,TAXBLOCK 2250	94 WALTON STREET	WNW 0 - 1/8 (0.103 mi.)	J225	416
LOT 12,TAXBLOCK 2250	90 WALTON STREET	WNW 0 - 1/8 (0.112 mi.)	J251	478
LOT 10,TAXBLOCK 2250	***88 WALTON STREET***	***WNW 0 - 1/8 (0.115 mi.)***	***J255***	***485***
LOT 37,TAXBLOCK 2249	174 HARRISON AVENUE	W 0 - 1/8 (0.116 mi.)	K257	487
LOT 4,TAXBLOCK 2250	***161 HARRISON AVENUE***	***W 0 - 1/8 (0.117 mi.)***	***J265***	***502***

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BORDEN CHEMICAL	56 NOSTRAND AVE.	SW 1/4 - 1/2 (0.439 mi.)	AV494	1316

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 132 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA ID: NYP004333621	***49 BARTLET ST FRONT***	***SSW 0 - 1/8 (0.020 mi.)***	***A27***	***23***
CON EDISON SERVICE B EPA ID: NYP004414231	***47 BARTLETT ST***	***SSW 0 - 1/8 (0.023 mi.)***	***A31***	***27***
LOT 48,TAXBLOCK 2266 EPA ID: NYP004849471	***81 GERRY STREET***	***W 0 - 1/8 (0.027 mi.)***	***A43***	***44***
PFIZER INC BROOKLYN EPA ID: NYR000016048	***73 GERRY ST***	***W 0 - 1/8 (0.034 mi.)***	***B54***	***58***
CON EDISON EPA ID: NYP004829572	76 BARTLETT ST	E 0 - 1/8 (0.038 mi.)	C57	64
CON EDISON	648 BROADWAY	NE 0 - 1/8 (0.060 mi.)	D110	204

EPA ID: NYP004738043				
CON EDISON - MANHOLE EPA ID: NYP004184289	***662 BROADWAY***	***ENE 0 - 1/8 (0.063 mi.)***	***G122***	***226***
CON EDISON EPA ID: NYP004550265	34 WHIPPLE ST	SE 0 - 1/8 (0.065 mi.)	C130	239
CON EDISON SERVICE B EPA ID: NYP004334918	***18 WHIPPLE ST FRONT***	***SSE 0 - 1/8 (0.066 mi.)***	***F137***	***247***
CON EDISON EPA ID: NYP004791927	BARTLETT ST & BROADW	ENE 0 - 1/8 (0.076 mi.)	G160	274
CON EDISON EPA ID: NYP004186920	***WHIPPLE ST & FLUSHIN***	***S 0 - 1/8 (0.080 mi.)***	***F171***	***311***
CON EDISON - MANHOLE EPA ID: NYP005094628	676 BROADWAY	E 0 - 1/8 (0.080 mi.)	I173	316
CON EDISON EPA ID: NYP004831042	131 THROOP AVE	SE 0 - 1/8 (0.080 mi.)	C175	319
CON EDISON EPA ID: NYP005021290	701 FLUSHING AVE	SE 0 - 1/8 (0.094 mi.)	N204	383
CON EDISON SERVICE B EPA ID: NYP004313276	***12 MANHATTAN AVE***	***ENE 0 - 1/8 (0.112 mi.)***	***I252***	***478***
CON EDISON EPA ID: NYP004730065	685 BROADWAY	E 0 - 1/8 (0.117 mi.)	I260	491
CON EDISON EPA ID: NYP004722955 EPA ID: NYP004426862	***149 HOPKINS ST***	***S 0 - 1/8 (0.117 mi.)***	***O261***	***492***
CON EDISON EPA ID: NYP004611646	719 FLUSHING AVE	ESE 0 - 1/8 (0.123 mi.)	N281	620
NYC DEPT OF EDUCATIO EPA ID: NYD986953461	***101 WALTON ST***	***WNW 1/8 - 1/4 (0.126 mi.)***	***J282***	***622***
CON EDISON EPA ID: NYP004733754	185 HOPKINS ST	SSE 1/8 - 1/4 (0.128 mi.)	N284	629
CON EDISON - VS 2314 EPA ID: NYP004106852	***93 HOPKINS ST***	***SSW 1/8 - 1/4 (0.134 mi.)***	***O289***	***639***
CON EDISON SERVICE B EPA ID: NYP004482386	***32 VARET ST***	***ENE 1/8 - 1/4 (0.138 mi.)***	***Q290***	***642***
CON EDISON EPA ID: NYP005087006	30 MANHATTAN AVE	NE 1/8 - 1/4 (0.144 mi.)	Q294	648
CON EDISON EPA ID: NYP004786687	720 BROADWAY	ESE 1/8 - 1/4 (0.154 mi.)	R301	659
CON EDISON EPA ID: NYP004567442	46 MANHATTAN AVE	NE 1/8 - 1/4 (0.157 mi.)	U302	660
CON EDISON EPA ID: NYP004733770	743 FLUSHING AVE SB7	ESE 1/8 - 1/4 (0.159 mi.)	V308	670
CON EDISON EPA ID: NYP004733762	743 FLUSHING AVE SB7	ESE 1/8 - 1/4 (0.159 mi.)	V310	673
CON EDISON EPA ID: NYP004752739	FLUSHING & BROADWAY	ESE 1/8 - 1/4 (0.160 mi.)	R313	677
CON ED	722 BROADWAY	ESE 1/8 - 1/4 (0.160 mi.)	R315	680

EPA ID: NYP004819375				
CON EDISON EPA ID: NYP004756904	745 FLUSHING AVE	ESE 1/8 - 1/4 (0.161 mi.)	R319	685
CON EDISON EPA ID: NYP004821365	164 THROOP AVE	SSE 1/8 - 1/4 (0.162 mi.)	W321	687
CON EDISON - MANHOLE EPA ID: NYP004308326	***60 MOORE ST***	***NE 1/8 - 1/4 (0.167 mi.)***	***Q329***	***705***
CON EDISON EPA ID: NYP004756896	749 FLUSHING AVE	ESE 1/8 - 1/4 (0.168 mi.)	R330	708
CON EDISON EPA ID: NYP004752705	FLUSHING & BROADWAY	ESE 1/8 - 1/4 (0.168 mi.)	R333	712
CON EDISON EPA ID: NYP004738357 EPA ID: NYP004738571	168 THROOP AVE	SSE 1/8 - 1/4 (0.170 mi.)	W335	716
NYC DEPT OF EDUCATIO EPA ID: NYR000011163	***185 ELLERY ST***	***S 1/8 - 1/4 (0.172 mi.)***	***Y341***	***725***
CON EDISON EPA ID: NYP004752689	FLUSHING AVE & BROAD	ESE 1/8 - 1/4 (0.172 mi.)	V342	728
CON EDISON SERVICE B EPA ID: NYP004310744	***50 MANHATTAN AVE***	***NE 1/8 - 1/4 (0.173 mi.)***	***U344***	***734***
CON EDISON - MANHOLE EPA ID: NYP005093158	13 GRAHAM AVE	E 1/8 - 1/4 (0.174 mi.)	R346	738
HYDRO TECH EPA ID: NYR000146126	***70 UNION AVENUE***	***W 1/8 - 1/4 (0.177 mi.)***	***S348***	***744***
CON EDISON EPA ID: NYP004672929	43 COOK ST	ENE 1/8 - 1/4 (0.178 mi.)	Z351	764
CON EDISON EPA ID: NYP004696080 EPA ID: NYP004611026	43 COOK ST	ENE 1/8 - 1/4 (0.178 mi.)	Z352	765
CON EDISON EPA ID: NYP004597811	755 FLUSHING	ESE 1/8 - 1/4 (0.180 mi.)	V354	770
CON ED - VS 5285 EPA ID: NYP004006680	***SEIGAL ST & MANHATTA***	***NNE 1/8 - 1/4 (0.182 mi.)***	***U357***	***774***
CON ED-V5285 EPA ID: NYZ004019618	SEIGAL ST & MANHATTA	NNE 1/8 - 1/4 (0.182 mi.)	U358	777
NYCT - BROADWAY-LORI EPA ID: NYR000156547	***143 LORIMER ST***	***WNW 1/8 - 1/4 (0.182 mi.)***	***AA359***	***778***
CON EDISON EPA ID: NYP004586509	51 VARET ST	ENE 1/8 - 1/4 (0.183 mi.)	Q360	782
CON EDISON - MANHOLE EPA ID: NYP005064977	133 HARRISON ST	WNW 1/8 - 1/4 (0.186 mi.)	AA362	786
CON EDISON EPA ID: NYP004508164	45 COOK ST	ENE 1/8 - 1/4 (0.188 mi.)	Z366	791
CON EDISON EPA ID: NYP004515466	5 GRAHAM AVE	ESE 1/8 - 1/4 (0.188 mi.)	V367	793
CON EDISON EPA ID: NYP004625232	OPP 46 COOK ST	E 1/8 - 1/4 (0.189 mi.)	Z369	796
PS 257K SCHOOL	***60 COOK ST***	***E 1/8 - 1/4 (0.192 mi.)***	***Z373***	***803***

EPA ID: NY0000375469				
CON EDISON SERVICE B EPA ID: NYP004441374	***47 GRAHAM AVE***	***ENE 1/8 - 1/4 (0.194 mi.)***	***Z375***	***809***
CON EDISON EPA ID: NYP004568747	51 GRAHAM AVE	ENE 1/8 - 1/4 (0.195 mi.)	AB377	812
CON EDISON EPA ID: NYP004513560	44 GRAHAM AVE	E 1/8 - 1/4 (0.197 mi.)	Z379	815
CON EDISON SERVICE B EPA ID: NYP004471389	***VARET ST & GRAHAM AV***	***ENE 1/8 - 1/4 (0.198 mi.)***	***Z380***	***817***
CON EDISON - 67 MANH EPA ID: NYR000026468	***67 MANHATTAN AVE***	***NNE 1/8 - 1/4 (0.202 mi.)***	***AC386***	***827***
CON EDISON MANHOLE: EPA ID: NYP004311049	***67 MANHATTAN AVE***	***NNE 1/8 - 1/4 (0.202 mi.)***	***AC387***	***830***
CON ED EPA ID: NYP004875098	HARRISON AVE & UNION	WNW 1/8 - 1/4 (0.203 mi.)	AA394	847
CON EDISON - MANHOLE EPA ID: NYP004184263	***UNION AVE HARRISON A***	***WNW 1/8 - 1/4 (0.203 mi.)***	***AA395***	***848***
CON EDISON SERVICE B EPA ID: NYP004385704	***204 ELLERY ST***	***SSE 1/8 - 1/4 (0.205 mi.)***	***AF396***	***851***
CON EDISON - MANHOLE EPA ID: NYP004184297	***64 GRAHAM AVE***	***ENE 1/8 - 1/4 (0.211 mi.)***	***AB397***	***853***
CON EDISON SERVICE B EPA ID: NYP004288635	***55 WALTON ST***	***W 1/8 - 1/4 (0.213 mi.)***	***AE399***	***858***
CON EDISON EPA ID: NYP004186953	***FLUSHING AVE & BROAD***	***ESE 1/8 - 1/4 (0.213 mi.)***	***AG400***	***861***
CON EDISON EPA ID: NYP004594404	FLUSHING AVE AND BRO	ESE 1/8 - 1/4 (0.213 mi.)	AG401	865
CONSOLIDATED EDISON EPA ID: NYP004157848	BROADWAY & FLUSHING	ESE 1/8 - 1/4 (0.213 mi.)	AG402	867
CON EDISON EPA ID: NYP004598736	BROADWAY & FLUSHING	ESE 1/8 - 1/4 (0.213 mi.)	AG403	868
MTA NYCT - FLUSHING EPA ID: NYR000082081	***FLUSHING AVE & BROAD***	***ESE 1/8 - 1/4 (0.213 mi.)***	***AG405***	***871***
CON EDISON EPA ID: NYP004183547	***747 PARK AVE***	***S 1/8 - 1/4 (0.217 mi.)***	***Y407***	***876***
CON ED EPA ID: NYP004861528	56 VARET ST	ENE 1/8 - 1/4 (0.221 mi.)	Z408	879
CON ED EPA ID: NYP004833097	UNION AVE & MIDDLETO	WNW 1/8 - 1/4 (0.221 mi.)	AA410	882
CON EDISON SERVICE B EPA ID: NYP004471397	***77 VARET ST***	***ENE 1/8 - 1/4 (0.222 mi.)***	***AB413***	***887***
CON EDISON - MANHOLE EPA ID: NYP005186897	10 GRAHAM AVE	E 1/8 - 1/4 (0.224 mi.)	AG416	892
LOTUS CLEANERS EPA ID: NYD987029188	***80 MANHATTAN AVE***	***NNE 1/8 - 1/4 (0.225 mi.)***	***AC418***	***894***
CON EDISON	76 GRAHAM AVE	ENE 1/8 - 1/4 (0.226 mi.)	AB421	902

EPA ID: NYP004846026				
CON EDISON EPA ID: NYP004500856	39 DEBEVOICE ST	E 1/8 - 1/4 (0.228 mi.)	AJ427	917
NYC-HH - WOODHULL HO EPA ID: NYD981560972	***760 BROADWAY***	***ESE 1/8 - 1/4 (0.230 mi.)***	***AG430***	***924***
CONSOLIDATED EDISON EPA ID: NYP004057790	MIDDLETON & HARRISON	WNW 1/8 - 1/4 (0.231 mi.)	AA433	1064
CON EDISON EPA ID: NYP004567491	756 PARK AVE	SSE 1/8 - 1/4 (0.237 mi.)	AF437	1072
KNIGHTS COLLISION EX EPA ID: NYD012575643	***120 UNION AVE***	***NW 1/8 - 1/4 (0.237 mi.)***	***AH440***	***1079***
CON EDISON EPA ID: NYP004698437	BOERUM & LORIMER ST	NNW 1/8 - 1/4 (0.247 mi.)	447	1098
CON EDISON EPA ID: NYP004845901	97 VARET ST	ENE 1/8 - 1/4 (0.248 mi.)	AN450	1106
JOYFUL CLEANERS EPA ID: NYR000148882	***789 FLUSHING AVE***	***E 1/8 - 1/4 (0.248 mi.)***	***AG454***	***1111***
CON EDISON - MANHOLE EPA ID: NYP005079742	695 PARK AVE	SSW 1/8 - 1/4 (0.250 mi.)	AK455	1114

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CON EDISON EPA ID: NYP004720009	78 THROOP AVE	NNW 0 - 1/8 (0.024 mi.)	A35	34
CON EDISON SERVICE B EPA ID: NYP004307450	***125 GERRY ST***	***N 0 - 1/8 (0.033 mi.)***	***D50***	***54***
CON EDISON EPA ID: NYP004801981	72-74 THROOP AVE & G	NNW 0 - 1/8 (0.038 mi.)	B61	85
CON EDISON EPA ID: NYP004720090	72 THROOP AV	NNW 0 - 1/8 (0.038 mi.)	B62	86
THROOP BUILDINGS EPA ID: NYR000197897	***72 THROOP AVE***	***NNW 0 - 1/8 (0.038 mi.)***	***B67***	***92***
CON EDISON - TRANSFO EPA ID: NYP004399176	***WALLABOUT ST C 32W T***	***NNW 0 - 1/8 (0.057 mi.)***	***D101***	***189***
CON EDISON EPA ID: NYP004512307	622 BROADWAY	N 0 - 1/8 (0.060 mi.)	D104	196
CON EDISON EPA ID: NYP004559654	622 BROADWAY	N 0 - 1/8 (0.060 mi.)	D106	198
CON EDISON EPA ID: NYP004689915	FRONT OF 622 BROADWA	N 0 - 1/8 (0.060 mi.)	D107	200
CON EDISON MANHOLE: EPA ID: NYP004446282	***378 WALLABOUT ST***	***W 0 - 1/8 (0.062 mi.)***	***B119***	***223***
CON EDISON EPA ID: NYP004794491	BROADWAY & GERRY ST	NNE 0 - 1/8 (0.064 mi.)	D126	233
CON EDISON EPA ID: NYP004794509	BROADWAY & GERRY ST	NNE 0 - 1/8 (0.064 mi.)	D129	237
WALLABOUT BUILDINGS	***376-382 WALLABOUT ST***	***W 0 - 1/8 (0.066 mi.)***	***B135***	***243***

EPA ID: NYR000203521				
VARTEX INSTRUMENT CO EPA ID: NYR000084483	***311 WALLABOUT ST***	***NW 0 - 1/8 (0.069 mi.)***	***H141***	***253***
CON EDISON SERVICE B EPA ID: NYP004446217	***372 WALLABOUT ST***	***W 0 - 1/8 (0.073 mi.)***	***B152***	***265***
CON EDISON EPA ID: NYP004858587	295 WALLABOUT ST	WNW 0 - 1/8 (0.075 mi.)	B157	269
CON EDISON SERVICE B EPA ID: NYP004409629	***45 THROOP AVE***	***NNW 0 - 1/8 (0.076 mi.)***	***H158***	***271***
PFIZER INC EPA ID: NYD001513779	***191 HARRISON AVE***	***SW 0 - 1/8 (0.079 mi.)***	***E165***	***279***
LOT 54,TAXBLOCK 2272 EPA ID: NYR000203539	***661 FLUSHING AVENUE***	***SSW 0 - 1/8 (0.079 mi.)***	***F169***	***308***
ACE RAPID CLEANERS EPA ID: NYD045446994	***209 HARRISON AVE***	***SSW 0 - 1/8 (0.083 mi.)***	***E186***	***328***
V4821 EPA ID: NYP004034575	***48 GERRY STREET***	***WSW 0 - 1/8 (0.083 mi.)***	***K188***	***337***
CON EDISON SERVICE B EPA ID: NYP004446225	***366 WALLABOUT ST***	***W 0 - 1/8 (0.084 mi.)***	***J190***	***340***
BAIS RUCHEL HIGH SCH EPA ID: NYR000183780	***177 HARRISON AVE***	***WSW 0 - 1/8 (0.090 mi.)***	***K197***	***349***
CON ED - MH 485 EPA ID: NYP004006821	***GERRY ST & HARRISON***	***WSW 0 - 1/8 (0.094 mi.)***	***K206***	***385***
LOT 28,TAXBLOCK 2250 EPA ID: NYR000231548	***54 THROOP AVENUE***	***NW 0 - 1/8 (0.094 mi.)***	***H208***	***388***
PFIZER INC BROOKLYN EPA ID: NYD001374214	***11 BARTLETT ST***	***SW 0 - 1/8 (0.099 mi.)***	***L217***	***402***
BP WEST COAST PRODUC EPA ID: NYR000198119	655 FLUSHING AVE	SSW 0 - 1/8 (0.104 mi.)	L229	432
CON EDISON EPA ID: NYP004745261 EPA ID: NYP004745469	2 TOMPKINS AVE	SSW 0 - 1/8 (0.105 mi.)	L238	458
CON EDISON - VAULT 1 EPA ID: NYP005131800	2 TOMPKINS AVE	SSW 0 - 1/8 (0.105 mi.)	L239	461
CON EDISON SERVICE B EPA ID: NYP004446290	***HARRISON AVE & WALLA***	***W 0 - 1/8 (0.111 mi.)***	***K245***	***469***
CON EDISON EPA ID: NYP004743332	HARRISSON & WALLABOU	W 0 - 1/8 (0.111 mi.)	K246	471
HARRISON WALTON PROP EPA ID: NYR000226365	86-90 WALTON ST	WNW 0 - 1/8 (0.117 mi.)	J262	496
ACUMEN PARTNERS LLC EPA ID: NYD986936904	***630 FLUSHING AVE***	***SSW 0 - 1/8 (0.119 mi.)***	***L269***	***520***
CON EDISON SERVICE B EPA ID: NYP004410114	***147 WALTON ST***	***NNW 0 - 1/8 (0.122 mi.)***	***P278***	***615***
CON EDISON - MANHOLE EPA ID: NYP004306957	***584 BROADWAY***	***NNW 1/8 - 1/4 (0.131 mi.)***	***P287***	***634***
PFIZER INC BROOKLYN	***338 WALLABOUT ST***	***WSW 1/8 - 1/4 (0.149 mi.)***	***T298***	***653***

EPA ID: NY0000055384				
CON EDISON - TM 1358 EPA ID: NYP004111993	***THROOP AVE & LORIMER***	***NW 1/8 - 1/4 (0.159 mi.)***	***P306***	***667***
CON EDISON MANHOLE: EPA ID: NYP004436226	***LORIMER ST & BROADWA***	***NNW 1/8 - 1/4 (0.163 mi.)***	***P325***	***694***
MTA NYCT - LORIMER S EPA ID: NYR000082131	***LORIMER ST & BROADWA***	***NNW 1/8 - 1/4 (0.163 mi.)***	***P326***	***696***
CON EDISON EPA ID: NYP004183687	***LORIMER ST & BROADWA***	***NNW 1/8 - 1/4 (0.163 mi.)***	***P327***	***699***
NYCTA - 22 THROOP AV EPA ID: NY0000902171	***22 THROOP AVE***	***NW 1/8 - 1/4 (0.191 mi.)***	***X372***	***799***
V2107 EPA ID: NYP004018420	***2-48 GERRY***	***SW 1/8 - 1/4 (0.226 mi.)***	***AI422***	***903***
V1821 EPA ID: NYP004018412	***2 GERRY STREET***	***SW 1/8 - 1/4 (0.226 mi.)***	***AI423***	***905***
NYCTA EPA ID: NYR000043455	FLUSHING & UNION AVE	SW 1/8 - 1/4 (0.227 mi.)	AI424	908
CON EDISON MANHOLE: EPA ID: NYP004451571	***MARCY AVE & FLUSHING***	***SW 1/8 - 1/4 (0.227 mi.)***	***AI426***	***915***
CON EDISON MANHOLE: EPA ID: NYP004451639	***MARCY AVE & WALLABOU***	***WSW 1/8 - 1/4 (0.237 mi.)***	***AD438***	***1073***
CON EDISON MANHOLE: EPA ID: NYP004473062	***442 MARCY AVE***	***WSW 1/8 - 1/4 (0.243 mi.)***	***AD445***	***1092***
CON EDISON MANHOLE: EPA ID: NYP004473013	***298 WALLABOUT AVE***	***WSW 1/8 - 1/4 (0.247 mi.)***	***AD448***	***1100***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 2 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WOODHULL MEDICAL CEN Generator EPA Id: NYD981560972	760 BROADWAY	ESE 1/8 - 1/4 (0.230 mi.)	AG429	919

Lower Elevation	Address	Direction / Distance	Map ID	Page
THROOP UNITS LLC Generator EPA Id: NYR000231548	52 THROOP AVE	NW 0 - 1/8 (0.099 mi.)	H219	405

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 50 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	76 BARTLETT ST	E 0 - 1/8 (0.038 mi.)	C58	66

EPA Id: NYP004829572				
CON EDISON EPA Id: NYP004884868	95 THROOP AVE	ESE 0 - 1/8 (0.045 mi.)	C77	102
CON EDISON EPA Id: NYP004738043	648 BROADWAY	NE 0 - 1/8 (0.060 mi.)	D112	207
CON EDISON - MANHOLE EPA Id: NYP004184289	***662 BROADWAY***	***ENE 0 - 1/8 (0.063 mi.)***	***G122***	***226***
CON EDISON EPA Id: NYP004791927	BARTLETT ST & BROADW	ENE 0 - 1/8 (0.076 mi.)	G159	273
CON EDISON EPA Id: NYP004186920	***WHIPPLE ST & FLUSHIN***	***S 0 - 1/8 (0.080 mi.)***	***F171***	***311***
CON EDISON EPA Id: NYP004831042	131 THROOP AVE	SE 0 - 1/8 (0.080 mi.)	C176	320
CON EDISON EPA Id: NYP004822066	THROOP AVE & FLUSHIN	SE 0 - 1/8 (0.112 mi.)	N250	477
CON EDISON EPA Id: NYP004884744	161 HOPKINS ST	S 0 - 1/8 (0.118 mi.)	O266	503
CON EDISON - SERVICE EPA Id: NYP004733754	185 HOPKINS ST	SSE 1/8 - 1/4 (0.128 mi.)	N285	631
CON EDISON EPA Id: NYP004826572	BROADWAY & DEBEVOISE	E 1/8 - 1/4 (0.140 mi.)	R293	647
CON EDISON EPA Id: NYP004786687	720 BROADWAY	ESE 1/8 - 1/4 (0.154 mi.)	R300	658
CON EDISON EPA Id: NYP004733770	743 FLUSHING AVE SB7	ESE 1/8 - 1/4 (0.159 mi.)	V311	675
CON EDISON EPA Id: NYP004733762	743 FLUSHING AVE SB7	ESE 1/8 - 1/4 (0.159 mi.)	V312	676
CON EDISON EPA Id: NYP004819375	722 BROADWAY	ESE 1/8 - 1/4 (0.160 mi.)	R314	679
CON EDISON EPA Id: NYP004756904	745 FLUSHING AVE	ESE 1/8 - 1/4 (0.161 mi.)	R317	682
CON EDISON EPA Id: NYP004821365	164 THROOP AVE	SSE 1/8 - 1/4 (0.162 mi.)	W322	689
CON EDISON EPA Id: NYP004756896	749 FLUSHING AVE	ESE 1/8 - 1/4 (0.168 mi.)	R332	711
CON EDISON EPA Id: NYP004738571	168 THROOP AVE	SSE 1/8 - 1/4 (0.170 mi.)	W336	719
CON EDISON EPA Id: NYP004738357	168 THROOP AVE	SSE 1/8 - 1/4 (0.170 mi.)	W338	722
CAS DEVELOPERS LLC EPA Id: NYR000146126	***70 UNION AVE***	***W 1/8 - 1/4 (0.177 mi.)***	***S349***	***750***
NYCT - BROADWAY-LORI EPA Id: NYR000156547	***143 LORIMER ST***	***WNW 1/8 - 1/4 (0.182 mi.)***	***AA359***	***778***
CON EDISON EPA Id: NYP004835746	BROADWAY & GRAHAM AV	ESE 1/8 - 1/4 (0.191 mi.)	V371	798
CON EDISON - TRANSFO	HARRISON AVE & UNION	WNW 1/8 - 1/4 (0.203 mi.)	AA391	843

EPA Id: NYP004875098				
CON EDISON - MANHOLE EPA Id: NYP004184263	UNION AVE HARRISON A	WNW 1/8 - 1/4 (0.203 mi.)	AA393	846
CON EDISON - MANHOLE EPA Id: NYP004184297	***64 GRAHAM AVE***	***ENE 1/8 - 1/4 (0.211 mi.)***	***AB397***	***853***
CON EDISON SERVICE B EPA Id: NYP004288635	55 WALTON ST	W 1/8 - 1/4 (0.213 mi.)	AE398	857
CON EDISON EPA Id: NYP004835597 EPA Id: NYP004186953	***FLUSHING AVE & BROAD***	***ESE 1/8 - 1/4 (0.213 mi.)***	***AG400***	***861***
CON EDISON EPA Id: NYP004183547	***747 PARK AVE***	***S 1/8 - 1/4 (0.217 mi.)***	***Y407***	***876***
CON EDISON EPA Id: NYP004833097	UNION AVE & MIDDLETO	WNW 1/8 - 1/4 (0.221 mi.)	AA409	881
CON EDISON EPA Id: NYP004846026	76 GRAHAM AVE	ENE 1/8 - 1/4 (0.226 mi.)	AB419	900
NYC-HH - WOODHULL HO EPA Id: NYD981560972	***760 BROADWAY***	***ESE 1/8 - 1/4 (0.230 mi.)***	***AG431***	***970***
CON EDISON EPA Id: NYP004845901	97 VARET ST	ENE 1/8 - 1/4 (0.248 mi.)	AN452	1109

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA Id: NYP004720009	78 THROOP AVE	NNW 0 - 1/8 (0.024 mi.)	A37	38
THROOP BUILDINGS EPA Id: NYR000197897	72 THROOP AVE	NNW 0 - 1/8 (0.038 mi.)	B60	68
CON EDISON EPA Id: NYP004801981	72-74 THROOP AVE & G	NNW 0 - 1/8 (0.038 mi.)	B65	90
CON EDISON EPA Id: NYP004794491	BROADWAY & GERRY ST	NNE 0 - 1/8 (0.064 mi.)	D124	231
CON EDISON EPA Id: NYP004794509	BROADWAY & GERRY ST	NNE 0 - 1/8 (0.064 mi.)	D128	236
ARLINGTON PRESS EPA Id: NYD001513779	191 HARRISON AVENUE	SW 0 - 1/8 (0.079 mi.)	E166	281
TULIP GROVE HOMES EPA Id: NYR000203539	661 FLUSHING AVE	SSW 0 - 1/8 (0.079 mi.)	F167	290
BAIS RUCHEL HIGH SCH EPA Id: NYR000183780	***177 HARRISON AVE***	***WSW 0 - 1/8 (0.090 mi.)***	***K197***	***349***
PFIZER INC EPA Id: NYD001374214	11 BARTLETT STREET	SW 0 - 1/8 (0.099 mi.)	L216	399
BP WEST COAST PRODUC EPA Id: NYR000198119	655 FLUSHING AVE	SSW 0 - 1/8 (0.104 mi.)	L228	430
CON EDISON EPA Id: NYP004745469	2 TOMPKINS AVE	SSW 0 - 1/8 (0.105 mi.)	L237	457
CON EDISON EPA Id: NYP004745261	2 TOMPKINS AVE	SSW 0 - 1/8 (0.105 mi.)	L240	461
CON EDISON	HARRISSON & WALLABOU	W 0 - 1/8 (0.111 mi.)	K247	473

EPA Id: NYP004743332				
ACP BK I LLC - 630 F	***630 FLUSHING AVE***	***SSW 0 - 1/8 (0.119 mi.)***	***L270***	***550***
EPA Id: NYD986936904				
CON EDISON	22-66 LEONARD ST	N 0 - 1/8 (0.122 mi.)	M280	619
EPA Id: NYP004885196				
CON EDISON	***LORIMER ST & BROADWA***	***NNW 1/8 - 1/4 (0.163 mi.)***	***P327***	***699***
EPA Id: NYP004183687				
MTA NYCT - FLUSHING	***FLUSHING & UNION AVE***	***SW 1/8 - 1/4 (0.227 mi.)***	***AI425***	***909***
EPA Id: NYR000043455				

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 5 EDR MGP sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SKILLMAN STATION	SKILLMAN ST. FLUSHIN	WSW 1/2 - 1 (0.628 mi.)	AX514	1372
NASSAU GAS	SKILLMAN AVE	WSW 1/2 - 1 (0.645 mi.)	515	1372
RUTLEDGE STATION	RUTLEDGE ST. WYTHE A	WSW 1/2 - 1 (0.767 mi.)	518	1381
SCHOLES ST. STATION	SCHOLES ST 7 BOGART	NE 1/2 - 1 (0.798 mi.)	519	1381
KEAP ST. STATION	KEAP ST. WYTHE AVE.	W 1/2 - 1 (0.851 mi.)	520	1382

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 5 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RUSS LOUIS	81-87 THROOP AVE	N 0 - 1/8 (0.023 mi.)	A30	26
THROOP TRANSMISSION	55 THROOP AVE	NNW 0 - 1/8 (0.042 mi.)	D70	97
P & C SERVICE STATIO	655 FLUSHING AVE	SSW 0 - 1/8 (0.104 mi.)	L230	433

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
MEL-BERN NUMBER FOUR	645 FLUSHING AVE	SSW 0 - 1/8 (0.113 mi.)	L253	481
A G IGNITION	594 BROADWAY	NNW 0 - 1/8 (0.120 mi.)	P275	613

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 2 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WOODHULL LAUNDROMAT	698 FLUSHING AVE	SE 0 - 1/8 (0.110 mi.)	N243	468

Lower Elevation	Address	Direction / Distance	Map ID	Page
ACE RAPID CLEANERS	209 HARRISON AVE	SSW 0 - 1/8 (0.083 mi.)	E184	327

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 11 records.

Site Name	Database(s)
DAVIDSON PIPE SUPPLY COMPANY	NY SHWS
INGRAHAM STREET SIDEWALK GW	NY SHWS
NORTH OF CORNISH KNIT GOODS	NY SHWS
KENT TERMINAL	NY SHWS, NY VCP
MORGAN OIL TERMINAL	NY SHWS
K - SCHOLES ST. STATION	NY SHWS, NY BROWNFIELDS
MCCARREN COMFORT STSTION	NY LTANKS
BASEMENT	NY LTANKS
RUTLEDGE STATION	NY VCP
SCHOLES ST. STATION	NY VCP
SKILLMAN STATION	NY VCP

OVERVIEW MAP - 5823513.9S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Brooklyn Triangle Site C	CLIENT:	Env. Business Consultants
ADDRESS:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett St Brooklyn NY 11206	CONTACT:	Keith W Butler
LAT/LONG:	40.70174 / 73.946241	INQUIRY #:	5823513.9s
		DATE:	October 11, 2019 9:04 am

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 5823513.9S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Brooklyn Triangle Site C	CLIENT:	Env. Business Consultants
ADDRESS:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett St Brooklyn NY 11206	CONTACT:	Keith W Butler
LAT/LONG:	40.70174 / 73.946241	INQUIRY #:	5823513.9s
		DATE:	October 11, 2019 9:07 am

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	3	NR	NR	3
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		1	0	0	1	NR	2
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		14	11	NR	NR	NR	25
RCRA-SQG	0.250		1	4	NR	NR	NR	5
RCRA-VSQG	0.250		1	5	NR	NR	NR	6
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	2	5	NR	7
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	2	NR	NR	2
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		3	3	27	NR	NR	33
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250		12	14	NR	NR	NR	26
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		1	0	NR	NR	NR	1
NY AST	0.250		8	12	NR	NR	NR	20
NY CBS AST	0.250		1	0	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		2	NR	NR	NR	NR	2
NY ENG CONTROLS	0.500		1	0	2	NR	NR	3
NY INST CONTROL	0.500		1	0	2	NR	NR	3
State and tribal voluntary cleanup sites								
NY VCP	0.500		18	10	14	NR	NR	42
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		1	3	4	NR	NR	8
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125	1	37	NR	NR	NR	NR	38
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		38	52	NR	NR	NR	90
FUDS	1.000		0	0	0	1	NR	1
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	2	NR	NR	NR	NR	NR	2
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		1	2	NR	NR	NR	3
NY E DESIGNATION	0.125	9	89	NR	NR	NR	NR	98

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	1	NR	NR	1
NY MANIFEST	0.250		52	80	NR	NR	NR	132
PA MANIFEST	0.250		1	1	NR	NR	NR	2
NJ MANIFEST	0.250		24	26	NR	NR	NR	50
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	5	NR	5
EDR Hist Auto	0.125		5	NR	NR	NR	NR	5
EDR Hist Cleaner	0.125		2	NR	NR	NR	NR	2
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		12	314	223	57	12	0	618

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **LOT 33,TAXBLOCK 2269** **NY E DESIGNATION** **S110242392**
Target **69 BARTLETT STREET** **N/A**
Property **BROOKLYN, NY 11206**

Site 1 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 33,TAXBLOCK 2269
Address:	69 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	33
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A2 **LOT 35,TAXBLOCK 2269** **NY E DESIGNATION** **S110242395**
Target **65 BARTLETT STREET** **N/A**
Property **BROOKLYN, NY 11206**

Site 2 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 35,TAXBLOCK 2269
Address:	65 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	35
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported

A3 **LOT 23,TAXBLOCK 2269** **NY E DESIGNATION** **S110242368**
Target **86 GERRY STREET** **N/A**
Property **BROOKLYN, NY 11206**

Site 3 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 23,TAXBLOCK 2269
Address:	86 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	23
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A4 **LOT 36,TAXBLOCK 2269** **NY E DESIGNATION** **S110242398**
Target **63 BARTLETT STREET** **N/A**
Property **BROOKLYN, NY 11206**

Site 4 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 36,TAXBLOCK 2269
Address:	63 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	36
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A5 **LOT 27,TAXBLOCK 2269** **NY E DESIGNATION** **S110242377**
Target **84 THROOP AVENUE** **N/A**
Property **BROOKLYN, NY 11206**

Site 5 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 27,TAXBLOCK 2269
Address:	84 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	27
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A6 **LOT 24,TAXBLOCK 2269** **NY E DESIGNATION** **S110242370**
Target **88 GERRY STREET** **N/A**
Property **BROOKLYN, NY 11206**

Site 6 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 24,TAXBLOCK 2269
Address:	88 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	24
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

A7 **ON GROUND** **NY Spills** **S106737228**
Target **90-92 GERRY STREET** **N/A**
Property **BROOKLYN, NY**

Site 7 of 48 in cluster A

Actual: **14 ft.**

SPILLS:

Name:	ON GROUND
Address:	90-92 GERRY STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0411773 / 2008-06-26
Facility ID:	0411773
Facility Type:	ER
DER Facility ID:	272394
Site ID:	337051
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-02-03
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2005-02-03
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-02-03
Spill Record Last Update:	2009-08-27
Spiller Name:	WALTER ROBERTS
Spiller Company:	ON GROUND
Spiller Address:	90-92 GERRY STREET
Spiller Company:	001
Contact Name:	WALTER ROBERTS
DEC Memo:	"Sangesland called Earth Tech Environmental back to ask about this spill Contact said a 20 gal drum of unknown oil was found on the property during soil borings (part of a phase 2 on the site). Sangesland informed Earth Tech that the property owner was responsible for removing the drum from the site, NOT the DEC. Sangesland told Earth Tech to remove the drum, over excavate any contmainated soil, take 1 end point sample, forward a report to DEC with writeup, test results and waste manifest. 04/13/06- Case was transferred from Jake Krimgold to Koon Tang. 08/27/2009 - Copy of Phase 2 report was submitted by Earth Tech. In 2005, during excavation of Test Pit #29 on the site, a drum was discovered at approx 7 ft depth. Drum contained unknown black oil which was leaking. Spill was called in to DEC. Visually contaminated soils were excavated from a depth of 10 ft below grade (approx 35 tons) of soil was removed. Soil sample #TP29-10 was tested and came back No VOCs, or SVOCs therefore no additional excavation work was necessary at this site."
Remarks:	"1-25 GALLON DRUM IN A TEST PIT: DEC CALL TO SEE IF IT CAN BE PICKED UP:"

ON GROUND (Continued) **S106737228**

All Materials:
Site ID: 337051
Operable Unit ID: 1099035
Operable Unit: 01
Material ID: 579358
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

A8 **LOT 29,TAXBLOCK 2269** **NY E DESIGNATION** **S110242382**
Target **88 THROOP AVENUE** **N/A**
Property **BROOKLYN, NY 11206**

Site 8 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:
Name: LOT 29,TAXBLOCK 2269
Address: 88 THROOP AVENUE
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 29
Tax Block: 2269
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

A9 **LOT 30,TAXBLOCK 2269** **NY E DESIGNATION** **S110242386**
Target **90 THROOP AVENUE** **N/A**
Property **BROOKLYN, NY 11206**

Site 9 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:
Name: LOT 30,TAXBLOCK 2269
Address: 90 THROOP AVENUE
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 30
Tax Block: 2269
Borough Code: BK
E-No: E-238

LOT 30,TAXBLOCK 2269 (Continued) **S110242386**

Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

A10 **SCIULARA PROP - BARTLETT PL** **FINDS** **1010012756**
Target **61 BARTLETT PL** **N/A**
Property **BROOKLYN, NY 11229**

Site 10 of 48 in cluster A

Actual: FINDS:
14 ft.

Registry ID: 110028280072

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A11 **GUDDEMI PROPERTY-59 BARTLETT PL** **FINDS** **1007746984**
Target **59 BARTLETT PLACE** **N/A**
Property **BROOKLYN, NY 11229**

Site 11 of 48 in cluster A

Actual: FINDS:
14 ft.

Registry ID: 110019093657

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A12 **LOT 25,TAXBLOCK 2269** **NY E DESIGNATION** **S110242374**
Target **90 GERRY STREET** **N/A**
Property **BROOKLYN, NY 11206**

Site 12 of 48 in cluster A

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 25,TAXBLOCK 2269
Address:	90 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	25
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

A13 **LOT 31,TAXBLOCK 2269** **NY E DESIGNATION** **S110242388**
THROOP AVENUE **N/A**
< 1/8 **BROOKLYN, NY 11206**
1 ft.

Site 13 of 48 in cluster A

Relative: **Higher**

Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 31,TAXBLOCK 2269
Address:	THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	31
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A14 **LOT 28,TAXBLOCK 2269** **NY E DESIGNATION** **S110242379**
THROOP AVENUE **N/A**
< 1/8 **BROOKLYN, NY 11206**
1 ft.

Site 14 of 48 in cluster A

Relative: E DESIGNATION:
Higher

Name:	LOT 28,TAXBLOCK 2269
Address:	THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	28
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

Actual:
14 ft.

A15 **DRUM RUN** **NY Spills** **S116553702**
SSW **57 BARTLETT ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.002 mi.
9 ft.

Site 15 of 48 in cluster A

Relative: SPILLS:
Higher

Name:	DRUM RUN
Address:	57 BARTLETT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1311882 / 2014-05-13
Facility ID:	1311882
Facility Type:	ER
DER Facility ID:	447726
Site ID:	492812
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	D4
SWIS:	2401
Spill Date:	2014-03-20
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2014-03-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

Actual:
15 ft.

DRUM RUN (Continued) **S116553702**

Date Entered In Computer:	2014-03-20
Spill Record Last Update:	2014-05-13
Spiller Name:	Not reported
Spiller Company:	N/A
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NYC DEP HAZ MAT
DEC Memo:	"DEC Piper spoke wiht ABE and added site to drum run 55 gal pumped on 5/12/14"
Remarks:	"two 55 gal red metal drums with oil water mix in one and oil water dirt mix in other"

All Materials:

Site ID:	492812
Operable Unit ID:	1242326
Operable Unit:	01
Material ID:	2242868
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A16 **LOT 39,TAXBLOCK 2269** **NY E DESIGNATION** **S110242403**
SSW **57 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.002 mi.
9 ft. **Site 16 of 48 in cluster A**

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Name:	LOT 39,TAXBLOCK 2269
Address:	57 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	39
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A17
SSW
< 1/8
0.006 mi.
34 ft.

LOT 40,TAXBLOCK 2269
55 BARTLETT STREET
BROOKLYN, NY 11206

Site 17 of 48 in cluster A

NY E DESIGNATION **S110242408**
N/A

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Name:	LOT 40,TAXBLOCK 2269
Address:	55 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	40
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A18
ESE
< 1/8
0.008 mi.
44 ft.

DRUM RUN
CORNER THROOP AVE AND BARTLETT ST
BROOKLYN, NY

Site 18 of 48 in cluster A

NY Spills **S110308002**
N/A

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	DRUM RUN
Address:	CORNER THROOP AVE AND BARTLETT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1000520 / 2010-05-05
Facility ID:	1000520
Facility Type:	ER
DER Facility ID:	380674
Site ID:	431688
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-04-13
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2010-04-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other

DRUM RUN (Continued) **S110308002**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-13
Spill Record Last Update:	2010-05-05
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	YUSEPH SLEEM
DEC Memo:	"DEP tested - determined to be waste oil. Add to next drum run 05/05/10-HRAHMED-No drum was found during DRUM RUN on 4/23/10. DEP and Sanitation was notified. This case is closed. "
Remarks:	"3 55 gallon drums left on sidewalk; containers are not full"

All Materials:

Site ID:	431688
Operable Unit ID:	1183159
Operable Unit:	01
Material ID:	2177356
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A19 **BROADWAY TRIANGLE** **NY Spills** **S102143753**
East **THROOP AVE / BARTLETT ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.009 mi.
46 ft. **Site 19 of 48 in cluster A**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	BROADWAY TRIANGLE
Address:	THROOP AVE / BARTLETT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9212706 / 1999-06-28
Facility ID:	9212706
Facility Type:	ER
DER Facility ID:	161869
Site ID:	194234
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1993-01-31
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1993-02-10
CID:	Not reported
Water Affected:	Not reported

BROADWAY TRIANGLE (Continued) **S102143753**

Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-11
Spill Record Last Update:	1999-06-28
Spiller Name:	BEVERLY REITH
Spiller Company:	NYC HPD
Spiller Address:	100 GOLD STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SEE FILE."
Remarks:	"SITE SOIL SAMPLER SHOW B-T-X"

All Materials:

Site ID:	194234
Operable Unit ID:	979704
Operable Unit:	01
Material ID:	402542
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

A20 **LOT 41,TAXBLOCK 2269** **NY E DESIGNATION** **S110242412**
SSW **53 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.011 mi.
58 ft. **Site 20 of 48 in cluster A**

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Name:	LOT 41,TAXBLOCK 2269
Address:	53 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	41
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and

LOT 41,TAXBLOCK 2269 (Continued) **S110242412**

air conditioning systems
Lot Remediation Date: Not reported

A21 **82 THROOP AVENUE** **NY VCP** **S118943284**
NW **82 THROOP AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.015 mi.
78 ft. **Site 21 of 48 in cluster A**

Relative:
Higher

Actual:
14 ft.

VCP NYC:
Project ID: 13CVCP147K
Project Name: 82 THROOP AVENUE
Project Address: 82 THROOP AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 13CVCP147K
File Name: 2013-06-13.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2013-06-13.13CVCP147K.RIR.pdf

Project ID: 13CVCP147K
File Name: 2013-06-13.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2013-06-13.13CVCP147K.RAWP_DRAFT.pdf

Project ID: 13CVCP147K
File Name: 2013-06-14.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2013-06-14.13CVCP147K.FactSheet1.pdf

Project ID: 13CVCP147K
File Name: 2013-06-14.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2013-06-13.13CVCP147K.Translated_FactSheet1.pdf

Project ID: 13CVCP147K
File Name: 2013-06-17.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2013-06-17.13CVCP147K.82_Throop_Avenue.Translated_CPS.pdf

Project ID: 13CVCP147K
File Name: 2013-08-01.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2013-08-01.13CVCP147K.82-Throop.FactSheet-2.pdf

Project ID: 13CVCP147K
File Name: 2013-08-02.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2013-08-02.13CVCP147K.Translated_FactSheet-2.pdf

Project ID: 13CVCP147K
File Name: 2015-07-09.RAR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP147K/2015-07-09.13CVCP147K.82_Throop_Avenue.Report.RAR_final.EBC.pdf

A22
NW
< 1/8
0.015 mi.
78 ft.

LOT 34,TAXBLOCK 2266
82 THROOP AVENUE
BROOKLYN, NY

Site 22 of 48 in cluster A

NY E DESIGNATION **S110242393**
N/A

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 34,TAXBLOCK 2266
Address:	82 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	34
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A23
SSW
< 1/8
0.016 mi.
84 ft.

LOT 42,TAXBLOCK 2269
51 BARTLETT STREET
BROOKLYN, NY 11206

Site 23 of 48 in cluster A

NY E DESIGNATION **S110242414**
N/A

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Name:	LOT 42,TAXBLOCK 2269
Address:	51 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	42
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems

LOT 42,TAXBLOCK 2269 (Continued) **S110242414**

Lot Remediation Date: Not reported

A24 **LOT 36,TAXBLOCK 2266** **NY E DESIGNATION** **S110242397**
NW **99 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.018 mi.
96 ft. **Site 24 of 48 in cluster A**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 36,TAXBLOCK 2266
Address:	99 GERRY STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	36
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

A25 **LOT 37,TAXBLOCK 2266** **NY E DESIGNATION** **S116624673**
WNW **97 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.018 mi.
96 ft. **Site 25 of 48 in cluster A**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 37,TAXBLOCK 2266
Address:	97 GERRY STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	37
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

A26
WNW
< 1/8
0.019 mi.
102 ft.

LOT 38,TAXBLOCK 2266
95 GERRY STREET
BROOKLYN, NY 11206

Site 26 of 48 in cluster A

NY E DESIGNATION **S116624674**
N/A

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 38,TAXBLOCK 2266
Address:	95 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	38
Tax Block:	2266
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported

A27
SSW
< 1/8
0.020 mi.
103 ft.

CON EDISON SERVICE BOX: 7015
49 BARTLET ST FRONT OF
BROOKLYN, NY 11206

Site 27 of 48 in cluster A

RCRA NonGen / NLR **1016960976**
NY MANIFEST **NYP004333621**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/23/2013
Facility name:	CON EDISON SERVICE BOX: 7015
Facility address:	49 BARTLET ST FRONT OF BROOKLYN, NY 11206
EPA ID:	NYP004333621
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	ANTHONY SIGNORE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	718-666-4714
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

CON EDISON SERVICE BOX: 7015 (Continued) **1016960976**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/23/2013
Site name: CON EDISON SERVICE BOX: 7015
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 49 BARTLET ST FRONT OF
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004333621
Facility Status: Not reported
Location Address 1: OPP 49 BARTLETT ST
Code: BP
Location Address 2: SB #7015
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004333621
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/23/2013
Trans1 Recv Date: 07/23/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/24/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported

CON EDISON SERVICE BOX: 7015 (Continued) **1016960976**

Generator EPA ID:	NYP004333621
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002085906GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A28 **LOT 19,TAXBLOCK 2269** **NY E DESIGNATION** **S117675956**
WSW **82 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.020 mi.
108 ft. **Site 28 of 48 in cluster A**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 19,TAXBLOCK 2269
Address:	82 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	19
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK

LOT 19,TAXBLOCK 2269 (Continued) **S117675956**

Zoning Map No: 13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

A29 **LOT 39,TAXBLOCK 2266** **NY E DESIGNATION** **S110242402**
WNW **93 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.021 mi.
113 ft. **Site 29 of 48 in cluster A**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 39,TAXBLOCK 2266
Address: 93 GERRY STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 39
Tax Block: 2266
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

A30 **RUSS LOUIS** **EDR Hist Auto** **1020410489**
North **81-87 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11216**
0.023 mi.
121 ft. **Site 30 of 48 in cluster A**

Relative: **Lower**
Actual: **13 ft.**

EDR Hist Auto

Year:	Name:	Type:
1969	RUSS LOUIS	Gasoline Service Stations
1970	RUSS LOUIS	Gasoline Service Stations
1971	RUSS LOUIS	Gasoline Service Stations
1972	RUSS LOUIS	Gasoline Service Stations
1973	RUSS LOUIS	Gasoline Service Stations
1974	RUSS LOUIS	Gasoline Service Stations
1975	RUSS LOUIS	Gasoline Service Stations

A31 **CON EDISON SERVICE BOX: 7013** **RCRA NonGen / NLR** **1016967825**
SSW **47 BARTLETT ST** **NY MANIFEST** **NYP004414231**
< 1/8 **BROOKLYN, NY 11206**
0.023 mi.
122 ft. **Site 31 of 48 in cluster A**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/08/2014
Facility name:	CON EDISON SERVICE BOX: 7013
Facility address:	47 BARTLETT ST BROOKLYN, NY 11206
EPA ID:	NYP004414231
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/08/2014
Site name:	CON EDISON SERVICE BOX: 7013
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	47 BARTLETT ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004414231
Facility Status:	Not reported
Location Address 1:	47 BARTLETT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 7013 (Continued) **1016967825**

Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004414231
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/2014
Trans1 Recv Date:	01/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004414231
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300519GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1

CON EDISON SERVICE BOX: 7013 (Continued) **1016967825**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A32 **LOT 43,TAXBLOCK 2269** **NY E DESIGNATION** **S110242416**
SSW **47 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.023 mi.
122 ft. **Site 32 of 48 in cluster A**

Relative: E DESIGNATION:
Higher

Name:	LOT 43,TAXBLOCK 2269
Address:	47 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	43
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported

Actual:
15 ft.

A33 **PFIZER INC. BROOKLYN PLANT** **NY UST** **U003418592**
WSW **80 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.024 mi.
125 ft. **Site 33 of 48 in cluster A**

Relative: UST:
Higher

Name:	PFIZER INC. BROOKLYN PLANT
Address:	80 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-603703 / Unregulated/Closed
Program Type:	PBS

Actual:
14 ft.

PFIZER INC. BROOKLYN PLANT (Continued) **U003418592**

Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588991.78779
UTM Y:	4506144.25018
Site Type:	Unknown

Affiliation Records:

Site Id:	25607
Affiliation Type:	Facility Owner
Company Name:	PFIZER INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	630 FLUSHING AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 780-8686
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25607
Affiliation Type:	Mail Contact
Company Name:	PFIZER INC.
Contact Type:	Not reported
Contact Name:	THOMAS J. SNEE
Address1:	630 FLUSHING AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 780-8686
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25607
Affiliation Type:	Facility Operator
Company Name:	PFIZER INC. BROOKLYN PLANT
Contact Type:	Not reported
Contact Name:	PFIZER INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 780-8686
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

PFIZER INC. BROOKLYN PLANT (Continued) **U003418592**

Site Id:	25607
Affiliation Type:	Emergency Contact
Company Name:	PFIZER INC.
Contact Type:	Not reported
Contact Name:	PFIZER INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 780-8880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	B001
Tank ID:	55259
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D00 - Pipe Type - No Piping
J02 - Dispenser - Suction Dispenser

Tank Number:	B002
Tank ID:	55260
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	275
Install Date:	Not reported

PFIZER INC. BROOKLYN PLANT (Continued) **U003418592**

Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
J02 - Dispenser - Suction Dispenser

Tank Number: B003
Tank ID: 55261
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 400
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

A34
NNW
< 1/8
0.024 mi.
128 ft.

CON EDISON - MANHOLE 493
78 THROOP AVE
BROOKLYN, NY 11206

Site 34 of 48 in cluster A

RCRA-LQG | **1019324741** / **NYP004720009**

Relative:
Lower

Actual:
13 ft.

RCRA-LQG:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON - MANHOLE 493
Facility address:	78 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004720009
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/28/2015
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

CON EDISON - MANHOLE 493 (Continued) **1019324741**

Owner/Op start date: 01/28/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 3320

Violation Status: No violations found

A35 **CON EDISON** **NY MANIFEST** **S117738919**
NNW **78 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.024 mi.
128 ft. **Site 35 of 48 in cluster A**

Relative: NY MANIFEST:
Lower
Name: CON EDISON
Actual: Address: 78 THROOP AVE
13 ft. City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004720009
Facility Status: Not reported
Location Address 1: 78 THROOP AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

CON EDISON (Continued) **S117738919**

NY MANIFEST:

EPAID:	NYP004720009
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/28/2015
Trans1 Recv Date:	01/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004720009
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620360GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117738919**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A36 **78 THROOP AVE** **NY UST** **U004216876**
NNW **78 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.024 mi.
128 ft. **Site 36 of 48 in cluster A**

Relative:
Lower

Actual:
13 ft.

UST:

Name:	78 THROOP AVE
Address:	78 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-612152 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588997.46146
UTM Y:	4506249.85134
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	490007
Affiliation Type:	Facility Owner
Company Name:	78-80 THROOP REALTY LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	505 FLUSHING AVE, 1D
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11205
Country Code:	001
Phone:	(609) 454-2319
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-01-28

Site Id:	490007
Affiliation Type:	Mail Contact
Company Name:	78-80 THROOP REALTY LLC
Contact Type:	Not reported
Contact Name:	BOB MORO
Address1:	505 FLUSHING AVENUE
Address2:	1D
City:	BROOKLYN
State:	NY
Zip Code:	11205
Country Code:	001

78 THROOP AVE (Continued) **U004216876**

Phone:	(609) 464-2319
EMail:	BMORO3@YAHOO.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-01-28

Site Id:	490007
Affiliation Type:	Facility Operator
Company Name:	78 THROOP AVE
Contact Type:	Not reported
Contact Name:	BOB MORO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(609) 464-2319
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-12-17

Site Id:	490007
Affiliation Type:	Emergency Contact
Company Name:	78-80 THROOP REALTY LLC
Contact Type:	Not reported
Contact Name:	BOB MORO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(609) 464-2319
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-12-17

Tank Info:

Tank Number:	001
Tank ID:	250624
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	02/05/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR

78 THROOP AVE (Continued) **U004216876**

Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None

A37 **CON EDISON - MANHOLE 493** **NJ MANIFEST** **S120666431**
NNW **78 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.024 mi.
128 ft. **Site 37 of 48 in cluster A**

Relative: **Lower**
Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYP004720009
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002620360GBF
EPA ID:	NYP004720009
Date Shipped:	1/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON - MANHOLE 493 (Continued) **S120666431**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

A38 **78 THROOP AVE** **NY VCP** **S118943233**
NNW **78 THROOP AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.024 mi.
128 ft. **Site 38 of 48 in cluster A**

Relative: **Lower**

Actual: **13 ft.**

VCP NYC:

Project ID:	13CVCP095K
Project Name:	78 THROOP AVE
Project Address:	78 THROOP AVE
Borough:	BROOKLYN

VCP NYC:

Project ID:	13CVCP095K
File Name:	2012-11-15.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2012-11-15.13CVCP095K.RIR.pdf

Project ID:	13CVCP095K
File Name:	2012-12-14.RAWP
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2012-12-14.13CVCP095K.RAWP_Final.pdf

Project ID:	13CVCP095K
File Name:	2012-11-15.FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2012-11-15.13CVCP095K.FactSheet1.pdf

Project ID:	13CVCP095K
File Name:	2012-11-15.Translated_FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2012-11-15.13CVCP095K.Translated_FactSheet1.pdf

78 THROOP AVE (Continued) **S118943233**

Project ID: 13CVCP095K
File Name: 2012-11-15.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2012-11-15.13CVCP095K.Translated_CPS.pdf

Project ID: 13CVCP095K
File Name: 2012-12-14.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2012-12-17.13CVCP095K.Decision_Document.pdf

Project ID: 13CVCP095K
File Name: 2013-01-29.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2013-01-29.13CVCP095K.FactSheet-2.pdf

Project ID: 13CVCP095K
File Name: 2012-01-30.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2012-01-30.13CVCP095K.Translated_FactSheet2.pdf

Project ID: 13CVCP095K
File Name: 2015-05-18.Factsheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2015-05-18.13CVCP095K.doc.78-80_Throop_Avenue.FactSheet-3.OER.pdf

Project ID: 13CVCP095K
File Name: 2015-07-09.RAR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP095K/2015-07-09.13CVCP095K.Report.RAR_final.EBC.pdf

---

A39 **UNDERGROUND** **NY Spills** **S112809841**
NNW **78 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.024 mi.
128 ft. **Site 39 of 48 in cluster A**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:

Name:	UNDERGROUND
Address:	78 THROOP AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1215332 / 2014-01-15
Facility ID:	1215332
Facility Type:	ER
DER Facility ID:	433902
Site ID:	478626
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2013-02-05
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2013-02-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling

UNDERGROUND (Continued) **S112809841**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-02-05
Spill Record Last Update:	2014-01-27
Spiller Name:	KEVEN BRUSSEE
Spiller Company:	UNKNOWN
Spiller Address:	78 THROOP AVE
Spiller Company:	999
Contact Name:	KEVEN BRUSSEE
DEC Memo:	"02/12/13-Hiralkumar Patel. 1:17 PM:- spoke with Kevin. he mentioned that the subject site is e designated and they are working with NYC OER for remediation. during previous investigations, they collected groundwater samples from three on-site wells and found chlorinated solvents. they prepared RAP and got approved by OER. recently, during excavation, they found 1,000 gal UST. today, they found another 550 gal tank. currently, the excavation is about 7 ft bg. its 50 ft by 100 ft site and it will be developed as 4 story condo with celler with new foundation at 8 ft bg. Kevin mentioned that groundwater was found around 8.5 ft bg during previous investigations. passive SSDS and vapor barrier designs have been approved by NYC OER. Hannah Moore NYC OER Ph. (212) 442-6372 78-80 Throop LLC. **property owner** c/o Rabsky Group 505 Flushing Ave, # 1D Brooklyn, NY 11205 Attn.: Ph. (718) 237-2261 alternate address: none no PBS or other spills found. as per ACRIS record, 78-80 Throop LLC. owns properties 78 Throop Ave and 80 Throop Ave and as per NYC DOB record, both properties are being developed. also, as per NYC DOB record, site 78 Throop Ave has little e designation for hazmat/noise/air. ---------- 1:51 PM:- left message at Rabsky Group. 02/15/13-Hiralkumar Patel. 9:33 AM:- received email from Kevin including Remedial Investigation Report. report forwarded to DEC Sharif for review. after discussing with DEC Sharif, case assigned to him. 01/15/14-Hiralkumar Patel. DEC Nick Lombardo came to discuss PBS application form he received for registation of a 100 gal tank. informed him that contractor found one 1,000 gal and one 550 gal tank at the site. he will talk to contractor to discuss this. case reassigned to DEC Patel. 10:24 AM:- spoke with Kevin. inquired him about remediation work. he mentioned that three lots (78/80/82 Throop Ave) being redeveloped with three separate buildings. all three lots were excavated to about 8-9 ft bg, little into groundwater, for entire footprint. EBC collected endpoint samples. foundation for all three buidings have been poured. asked Kevin to submit report for review. 11:07 AM:- received email from Kevin including report. he mentioned that some soil and liquid manifests are missing which will be submitted soon, once available. reviewed available documents. 1) Remedial Investigation Report dated Oct. 2012: - site located at 78-80 Throop Ave; block 2266; lots # 32 and 33 - proposed future use of the site will consist of two identical 4-story apartment buildings - both buildings will have a full cellar beneath the footprint of each building - concrete slab of the cellar will be approx. 6 ft 4 inches below sidewalk level - excavation for each new building and rear cellar-level court yard will likely extend to a depth of approx. 8 ft bg - prior to 1887, the property was developed with a bakery, livery and wagon house. the

UNDERGROUND (Continued) **S112809841**

operation was closed by 1904. sometime between 1904 and 1905 the site was redeveloped with a 5-story mixed use commerical/residential building. the first floor was divided into two commercial spaces and the upper floors were residential. the 5-story mixed use building remained until the entire lot was demolished in 1980. the site has remained undeveloped since, but the land was used for lumber storage until 2003. since 2003, the site has remained vacant - elevation of the property is approx. 14 ft - depth to bedrock is greater than 100 ft - installed four (4) borings (SB-1 through SB-4) to a depth of 10 ft bg - subsurface soil at the site consisted of historic fill, which was primarily comprised of brick, concrete, wood and other debris in a borwn silty-sand mix - layer of historic fill extended to a depth of 7 ft bg - native soil consisting of a brown sand is present below the historic fill layer - no PID readings were obtained from any of the soil borings with the exception of slightly elevated readings noted for soil recovered from approx. 8 to 10 ft bg from SB1 (50 ppm) and SB3 (100 ppm) - soil at 8-10 ft bg exhibited a petroleum odor, and was stained slightly grey - collected two soil samples from each boring: one from 0-2 ft bg and another from 8-10 ft bg - collected one duplicate soil sample from boring SB-4 from 0-2 ft bg - found some VOC contamination in deeper soil from 8-10 ft bg - found some SVOC contamination in shallow soil from 0-2 ft bg - installed three (3) 1-inch diameter temporary monitoring wells (in borings SB-1, SB-2 and SB-3) - wells were installed to a depth of 15 ft bg, with 10 ft of screen - collected 3 groundwater samples and 1 duplicate groundwater sample - no free product was observed within the three monitoring wells - depth to groundwater is approx. 10 ft bg ---------- - groundwater flow direction based on prior investigations performed on adjacent properties is from south to north ---------- - three groundwater samples and one duplicate groundwater sample (from boring SB-1) were collected for analysis - found only chlorinated compounds in groundwater samples - installed three (3) soil vapor probes (VP-1 through VP-3) to a depth of 6 ft bg and collected 3 samples - found petroleum and chlorinated compounds in soil-vapor samples 2) Remedial Action Work Plan dated Oct. 2012: - excavation of soil/fill to a depth of approx. 8 ft bg for development purposes and excavation of the area with VOC contamination to an anticipated depth of approx. 10 ft bg - collection and analysis of endpoint samples - installation of vapor barrier below the concrete slab and behind the foundation walls of the two proposed buildings - installation and operation of a passive SSDS below the vapor barrier 3) tank removal report dated 09/17/13: - two (2) 1,000 gal USTs removed: one from near the front of 80 Throop Ave (lot 33) and another from near the front of 82 Throop Ave (lot 34) - both lots were excavated to a depth of approx. 7 ft bg (depth of groundwater table) for redevelopment purposes, but additional excavation was performed below the groundwater interface to remove 2 ft smear zone of petroleum impacted soil from across teh front of 60 ft of site - pool of water accumulated within the excavation - total of approx. 784 gal of groundwater and a thin film of oil that accumulated on the groundwater surface was removed - endpoint samples were collected from entire site - no contamination noted in endpoint samples based on available information, case closed. ** e designation**"

Remarks: "found while removal of tank - clean up pending"

All Materials:

Site ID: 478626

Operable Unit ID: 1228394

UNDERGROUND (Continued) **S112809841**

Operable Unit:	01
Material ID:	2225994
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A40 **LOT 40,TAXBLOCK 2266** **NY E DESIGNATION** **S110242407**
WNW **91 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.024 mi.
128 ft. **Site 40 of 48 in cluster A**

Relative: E DESIGNATION:
Higher

Name:	LOT 40,TAXBLOCK 2266
Address:	91 GERRY STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	40
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

Actual:
14 ft.

A41 **LOT 47,TAXBLOCK 2266** **NY E DESIGNATION** **S122872751**
West **83 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.026 mi.
139 ft. **Site 41 of 48 in cluster A**

Relative: E DESIGNATION:
Higher

Name:	LOT 47,TAXBLOCK 2266
Address:	83 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	47
Tax Block:	2266
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009

Actual:
14 ft.

LOT 47,TAXBLOCK 2266 (Continued) **S122872751**

Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

A42 **LOT 46,TAXBLOCK 2266** **NY E DESIGNATION** **S122872749**
West **83 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.026 mi.
139 ft. **Site 42 of 48 in cluster A**

Relative: E DESIGNATION:
Higher
Name: LOT 46,TAXBLOCK 2266
Actual: Address: 83 GERRY STREET
14 ft. City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 46
Tax Block: 2266
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

A43 **LOT 48,TAXBLOCK 2266** **NY E DESIGNATION** **S118463292**
West **81 GERRY STREET** **NY MANIFEST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.027 mi.
144 ft. **Site 43 of 48 in cluster A**

Relative: E DESIGNATION:
Higher
Name: LOT 48,TAXBLOCK 2266
Actual: Address: 81 GERRY STREET
14 ft. City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 48
Tax Block: 2266
Borough Code: BK

LOT 48,TAXBLOCK 2266 (Continued) **S118463292**

E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

NY MANIFEST:
Name: CON EDISON
Address: 81 GERRY ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004849471
Facility Status: Not reported
Location Address 1: 81 GERRY ST
Code: BP
Location Address 2: SB 8505
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004849471
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 10/07/2015
Trans1 Recv Date: 10/07/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/08/2015
Part A Recv Date: Not reported

LOT 48,TAXBLOCK 2266 (Continued) **S118463292**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004849471
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002622008GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A44 **GERRY PROJECT** **RCRA NonGen / NLR** **1018158976**
West **81-85 GERRY ST** **NYR000220517**
< 1/8 **BROOKLYN, NY 11206**
0.027 mi.
144 ft. **Site 44 of 48 in cluster A**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/18/2017
Facility name:	GERRY PROJECT
Facility address:	81-85 GERRY ST BROOKLYN, NY 11206
EPA ID:	NYR000220517
Mailing address:	SPENCER ST BROOKLYN, NY 11205
Contact:	JOEL BRAVER
Contact address:	SPENCER ST BROOKLYN, NY 11205

GERRY PROJECT (Continued) **1018158976**

Contact country: US
Contact telephone: 718-676-1087
Contact email: JOEL@EXPRESSBUILDERS.COM
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: JOEL BRAVER
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/10/2015
Owner/Op end date: Not reported

Owner/operator name: EXPRESS BUILDERS JB
Owner/operator address: SPENCER ST
BROOKLYN, NY 11205
Owner/operator country: US
Owner/operator telephone: 718-676-1087
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/22/2013
Owner/Op end date: Not reported

Owner/operator name: JOEL BRAVER
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/10/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No

GERRY PROJECT (Continued) **1018158976**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/14/2015
Site name: GERRY PROJECT
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

A45 **LOT 18,TAXBLOCK 2269** **NY E DESIGNATION** **S110242359**
WSW **76 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.029 mi.
151 ft. **Site 45 of 48 in cluster A**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 18,TAXBLOCK 2269
Address: 76 GERRY STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 18
Tax Block: 2269
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

A46 **LOT 31,TAXBLOCK 2266** **NY E DESIGNATION** **S110242387**
NNW **76 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.029 mi.
153 ft. **Site 46 of 48 in cluster A**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:
Name: LOT 31,TAXBLOCK 2266
Address: 76 THROOP AVENUE
City,State,Zip: BROOKLYN, NY 11206

LOT 31,TAXBLOCK 2266 (Continued) **S110242387**

Tax Lot(s):	31
Tax Block:	2266
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported

B47 **LOT 41,TAXBLOCK 2266** **NY E DESIGNATION** **S110242411**
WNW **GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.030 mi.
159 ft. **Site 1 of 48 in cluster B**

Relative: Higher
Actual: 14 ft.

E DESIGNATION:

Name:	LOT 41,TAXBLOCK 2266
Address:	GERRY STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	41
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

C48
ESE
< 1/8
0.033 mi.
172 ft.

THROOP AVENUE / BARTLETT STREET — **NY UST** — **U002034160**
THROOP AVENUE / BARTLETT STREET — **N/A**
BROOKLYN, NY 11000

Site 1 of 16 in cluster C

Relative:
Higher

Actual:
15 ft.

UST:

Name:	THROOP AVENUE / BARTLETT STREET
Address:	THROOP AVENUE / BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11000
Id/Status:	2-601810 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589095.76956
UTM Y:	4506136.58719
Site Type:	Other

Affiliation Records:

Site Id:	23772
Affiliation Type:	Facility Owner
Company Name:	NYC DEPART. OF HOUSING PRESERVATION AND DEVELOPMEN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	75 MAIDEN LANE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 978-6540
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23772
Affiliation Type:	Mail Contact
Company Name:	ECOSYSTEMS STRATEGIES, INC.
Contact Type:	Not reported
Contact Name:	PAUL H. CIMIELLO
Address1:	60 WORRAL AVENUE
Address2:	Not reported
City:	POUGHKEEPSIE
State:	NY
Zip Code:	12603
Country Code:	001
Phone:	(914) 452-1658
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23772
Affiliation Type:	Facility Operator
Company Name:	THROOP AVENUE / BARTLETT STREET
Contact Type:	Not reported
Contact Name:	NYC DEPT. OF HOUSING PRESERVAT
Address1:	Not reported

THROOP AVENUE / BARTLETT STREET (Continued) **U002034160**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23772
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPART. OF HOUSING PRESERVATION AND DEVELOPMEN
Contact Type:	Not reported
Contact Name:	NYC DEPT. OF HOUSING PRESERVAT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47899
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping

THROOP AVENUE / BARTLETT STREET (Continued) **U002034160**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None

Tank Number: 002
Tank ID: 47900
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 47901
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

THROOP AVENUE / BARTLETT STREET (Continued) **U002034160**

H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	004
Tank ID:	47902
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None

A49 **LOT 45,TAXBLOCK 2269** **NY E DESIGNATION** **S110242419**
SW **43 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.033 mi.
172 ft. **Site 47 of 48 in cluster A**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 45,TAXBLOCK 2269
Address:	43 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	45
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported

LOT 45,TAXBLOCK 2269 (Continued) **S110242419**

Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date: Not reported

D50 **CON EDISON SERVICE BOX: 8514** **RCRA NonGen / NLR** **1016677182**
North **125 GERRY ST** **FINDS** **NYP004307450**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.033 mi. **NY MANIFEST**
173 ft. **Site 1 of 19 in cluster D**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:
Date form received by agency: 06/06/2013
Facility name: CON EDISON SERVICE BOX: 8514
Facility address: 125 GERRY ST
BROOKLYN, NY 11206
EPA ID: NYP004307450
Mailing address: VING PL, RM 828
NEW YORK, NY 10003
Contact: ANTHONY SIGNORE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/06/2013
Site name: CON EDISON SERVICE BOX: 8514
Classification: Conditionally Exempt Small Quantity Generator

CON EDISON SERVICE BOX: 8514 (Continued) **1016677182**

Violation Status: No violations found

FINDS:

Registry ID: 110058877504

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677182
Registry ID:	110058877504
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058877504

NY MANIFEST:

Name:	CON EDISON
Address:	125 GERRY ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004307450
Facility Status:	Not reported
Location Address 1:	125 GERRY
Code:	BP
Location Address 2:	SERV BOX 8514
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004307450
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013

CON EDISON SERVICE BOX: 8514 (Continued) **1016677182**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2013
Trans1 Recv Date:	05/06/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307450
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002017386GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A51
WSW
< 1/8
0.033 mi.
173 ft.

LOT 17,TAXBLOCK 2269
74 GERRY STREET
BROOKLYN, NY 11206

Site 48 of 48 in cluster A

NY E DESIGNATION

S110242357
N/A

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 17,TAXBLOCK 2269
Address:	74 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	17
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

B52
West
< 1/8
0.034 mi.
177 ft.

LOT 45,TAXBLOCK 2266
GERRY STREET
BROOKLYN, NY 11206

Site 2 of 48 in cluster B

NY E DESIGNATION

S120838979
N/A

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 45,TAXBLOCK 2266
Address:	GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	45
Tax Block:	2266
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

B53
NNW
< 1/8
0.034 mi.
178 ft.

LOT 30,TAXBLOCK 2266
74 THROOP AVENUE
BROOKLYN, NY 11206

Site 3 of 48 in cluster B

NY E DESIGNATION

S110242385
N/A

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 30,TAXBLOCK 2266
Address:	74 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	30
Tax Block:	2266
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

B54
West
< 1/8
0.034 mi.
179 ft.

PFIZER INC BROOKLYN PLANT
73 GERRY ST
BROOKLYN, NY 11206

Site 4 of 48 in cluster B

RCRA-VSQG
FINDS
ECHO
NY MANIFEST

1001079897
NYR000016048

Relative:
Higher

Actual:
14 ft.

RCRA-VSQG:

Date form received by agency:	01/01/2007
Facility name:	PFIZER INC BROOKLYN PLANT
Facility address:	73 GERRY ST BROOKLYN, NY 11206-4308
EPA ID:	NYR000016048
Mailing address:	FLUSHING AVE BROOKLYN, NY 11206-5092
Contact:	Not reported
Contact address:	FLUSHING AVE BROOKLYN, NY 11206-5092
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

PFIZER INC BROOKLYN PLANT (Continued) **1001079897**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	PFIZER INC
Owner/operator address:	630 FLUSHING AVE BROOKLYN, NY 11206
Owner/operator country:	US
Owner/operator telephone:	718-780-8472
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	PFIZER INC
Owner/operator address:	630 FLUSHING AVE BROOKLYN, NY 11206
Owner/operator country:	US
Owner/operator telephone:	718-780-8472
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006

PFIZER INC BROOKLYN PLANT (Continued) **1001079897**

Site name: PFIZER INC BROOKLYN PLANT
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/08/1999
Site name: PFIZER INC BROOKLYN PLANT
Classification: Not a generator, verified

Date form received by agency: 11/07/1995
Site name: PFIZER INC BROOKLYN PLANT
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110004520091

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001079897
Registry ID: 110004520091
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004520091

NY MANIFEST:
Name: PFIZER INC
Address: 73 GERRY ST
City,State,Zip: BROOKLYN, NY 11206-4308
Country: USA
EPA ID: NYR000016048
Facility Status: Not reported
Location Address 1: 73 GERRY ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206

PFIZER INC BROOKLYN PLANT (Continued) **1001079897**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000016048
Mailing Name: PFIZER INC
Mailing Contact: THOMAS SNEE
Mailing Address 1: 630 FLUSHING AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11206
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187808686

NY MANIFEST:
Document ID: NYG4254804
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: NJD986607380
Trans2 State ID: Not reported
Generator Ship Date: 05/10/2005
Trans1 Recv Date: 05/10/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/19/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000016048
Trans1 EPA ID: AC314ANJ
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F003 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00

PFIZER INC BROOKLYN PLANT (Continued) **1001079897**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B55 **EMPTY LOT** **NY Spills** **S104501441**
West **73-87 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.034 mi.
179 ft. **Site 5 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	EMPTY LOT
Address:	73-87 GERRY STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9704207 / 2006-11-14
Facility ID:	9704207
Facility Type:	ER
DER Facility ID:	180502
Site ID:	218170
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1996-05-14
Investigator:	CHAWLA
Referred To:	Not reported
Reported to Dept:	1997-07-09
CID:	311
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-09
Spill Record Last Update:	2006-11-14
Spiller Name:	SAME
Spiller Company:	PFIZER INC
Spiller Address:	630 FLUSHING AVE
Spiller Company:	001
Contact Name:	THOMAS SNEE
DEC Memo:	""
Remarks:	"CALLER STATES AN ENVIRONMENTAL STUDY WAS DONE ON THE PROPERTY AND FOUND THE SOIL TO BE CONTAMINATED. SPILL NUMBER REQUESTED BY REGIONAL OFFICE."

All Materials:

Site ID:	218170
Operable Unit ID:	1050080
Operable Unit:	01
Material ID:	333467
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

EMPTY LOT (Continued) **S104501441**

Units:	G
Recovered:	.00
Oxygenate:	Not reported
Name:	73-87 GERRY ST
Address:	73-87 GERRY STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9516449 / 2000-02-02
Facility ID:	9516449
Facility Type:	ER
DER Facility ID:	180502
Site ID:	137143
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1996-03-21
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-03-21
CID:	233
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-03-21
Spill Record Last Update:	2003-02-11
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	THOMAS KNEE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE Originally assinged to Tomasello. Closed and cross-referenced to 9704207 on 2/2/00."
Remarks:	"construction work at site uncovered contaiminated soil appears gasoline was spilled at site at some time in past "

All Materials:

Site ID:	137143
Operable Unit ID:	1027420
Operable Unit:	01
Material ID:	352967
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B56
WSW
< 1/8
0.037 mi.
197 ft.

LOT 16,TAXBLOCK 2269
GERRY STREET
BROOKLYN, NY 11206

Site 6 of 48 in cluster B

NY E DESIGNATION

S110242354
N/A

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 16,TAXBLOCK 2269
Address:	GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	16
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

C57
East
< 1/8
0.038 mi.
201 ft.

CON EDISON
76 BARTLETT ST
BROOKLYN, NY 11206

Site 2 of 16 in cluster C

NY MANIFEST

S119077394
N/A

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	76 BARTLETT ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004829572
Facility Status:	Not reported
Location Address 1:	76 BARTTLET ST
Code:	BP
Location Address 2:	SB 7020
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004829572
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S119077394**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/25/2015
Trans1 Recv Date:	08/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004829572
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002625245GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C58 **CON EDISON** **NJ MANIFEST** **S120675885**
East **76 BARTLETT ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.038 mi.
201 ft. **Site 3 of 16 in cluster C**

Relative:
Higher

Actual:
15 ft.

NJ MANIFEST:

EPA Id:	NYP004829572
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002625245GBF
EPA ID:	NYP004829572
Date Shipped:	8/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675885**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C59 **CON EDISON** **RCRA NonGen / NLR** **1019907052**
East **76 BARTLETT ST** **FINDS** **NYP004829572**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.038 mi.
201 ft. **Site 4 of 16 in cluster C**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/25/2015
Facility name:	CON EDISON
Facility address:	76 BARTLETT ST BROOKLYN, NY 11206
EPA ID:	NYP004829572
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/25/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1019907052**

Registry ID: 110069683541

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019907052
Registry ID: 110069683541
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069683541

B60 **THROOP BUILDINGS** **NJ MANIFEST** **S117987473**
NNW **72 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.038 mi.
203 ft. **Site 7 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

NJ MANIFEST:
EPA Id: NYR000197897
Mail Address: FLUSHING AVE UNIT 1D
Mail City/State/Zip: BROOKLYN, NY 11205
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: SIMON DUSHINSKY
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 010916566JJK
EPA ID: NYR000197897
Date Shipped: 1/2/2013
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported

THROOP BUILDINGS (Continued) **S117987473**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	47,000.00 Pounds

Manifest Number:	010916569JJK
EPA ID:	NYR000197897
Date Shipped:	1/2/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	49,500.00 Pounds

Manifest Number:	010914714JJK
EPA ID:	NYR000197897
Date Shipped:	1/10/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	43,900.00 Pounds

Manifest Number:	010916518JJK
EPA ID:	NYR000197897
Date Shipped:	12/12/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008

THROOP BUILDINGS (Continued) **S117987473**

Hand Code: Not reported
Quantity: 52,400.00 Pounds

Manifest Number: 010916521JJK
EPA ID: NYR000197897
Date Shipped: 12/12/2012
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11205
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 44,700.00 Pounds

Manifest Number: 010916529JJK
EPA ID: NYR000197897
Date Shipped: 12/12/2012
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported

THROOP BUILDINGS (Continued) **S117987473**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	37,640.00 Pounds

Manifest Number:	010916561JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	46,780.00 Pounds

Manifest Number:	010916563JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	52,640.00 Pounds

Manifest Number:	010916517JJK
EPA ID:	NYR000197897
Date Shipped:	12/12/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11205
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 37,240.00 Pounds

Manifest Number: 010916523JJK
EPA ID: NYR000197897
Date Shipped: 12/12/2012
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11205
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 40,500.00 Pounds

THROOP BUILDINGS (Continued) **S117987473**

Manifest Number:	010916538JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	42,600.00 Pounds

Manifest Number:	010916544JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	45,780.00 Pounds

Manifest Number:	010916546JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	43,320.00 Pounds

Manifest Number:	010916531JJK
EPA ID:	NYR000197897
Date Shipped:	12/12/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	41,620.00 Pounds

Manifest Number:	010916532JJK
EPA ID:	NYR000197897
Date Shipped:	12/12/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	43,620.00 Pounds
Manifest Number:	010916537JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	45,860.00 Pounds
Manifest Number:	010916553JJK
EPA ID:	NYR000197897

THROOP BUILDINGS (Continued) **S117987473**

Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	54,640.00 Pounds

Manifest Number:	010916557JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	44,960.00 Pounds

Manifest Number:	010916559JJK
EPA ID:	NYR000197897
Date Shipped:	12/13/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	46,840.00 Pounds

Manifest Number:	010916568JJK
EPA ID:	NYR000197897
Date Shipped:	1/2/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

THROOP BUILDINGS (Continued) **S117987473**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11205
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	42,520.00 Pounds

B61 **CON EDISON** **NY MANIFEST** **S119076255**
NNW **72-74 THROOP AVE & GERRY ST** **N/A**
< 1/8 **BROOKLYN, NY 11234**
0.038 mi.
203 ft. **Site 8 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	72-74 THROOP AVE & GERRY ST
City,State,Zip:	BROOKLYN, NY 11234
Country:	USA
EPA ID:	NYP004801981
Facility Status:	Not reported
Location Address 1:	72 THROOP AVE
Code:	BP
Location Address 2:	SB 42768
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004801981
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193

CON EDISON (Continued) **S119076255**

Trans2 State ID:	Not reported
Generator Ship Date:	07/02/2015
Trans1 Recv Date:	07/02/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004801981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014466557JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B62 **CON EDISON** **NY MANIFEST** **S117738928**
NNW **72 THROOP AV** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.038 mi.
203 ft. **Site 9 of 48 in cluster B**

Relative: NY MANIFEST:
Lower

Name:	CON EDISON
Address:	72 THROOP AV
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA

Actual:
13 ft.

CON EDISON (Continued) **S117738928**

EPA ID:	NYP004720090
Facility Status:	Not reported
Location Address 1:	72 THROOP AV
Code:	BP
Location Address 2:	SB42758
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004720090
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/28/2015
Trans1 Recv Date:	01/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004720090
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620437GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117738928**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B63 **72 THROOP AVENUE** **NY VCP** **S118943194**
NNW **72 THROOP AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.038 mi.
203 ft. **Site 10 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

VCP NYC:

Project ID:	12CVCP055K
Project Name:	72 THROOP AVENUE
Project Address:	72 THROOP AVENUE
Borough:	BROOKLYN

VCP NYC:

Project ID:	12CVCP055K
File Name:	2012-05-04.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP055K/2012-05-04.12CVCP055K.72_Throop_Avenue.RIR.pdf

Project ID:	12CVCP055K
File Name:	2012-09-11.RAWP_Final
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP055K/2012-09-11.12CVCP055K.72_Throop_Avenue.RAWP_Final.pdf

Project ID:	12CVCP055K
File Name:	2012-05-04.FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP055K/2012-05-04.12CVCP055K.72_Throop_Avenue.FactSheet1.pdf

Project ID:	12CVCP055K
File Name:	2012-09-14.FactSheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP055K/2012-09-14.12CVCP055K.FactSheet2.pdf

Project ID:	12CVCP055K
File Name:	2012-09-18.Translated_FactSheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP055K/2012-09-18.12CVCP055K.Translated_FactSheet2.pdf

72 THROOP AVENUE (Continued) **S118943194**

Project ID: 12CVCP055K
File Name: 2012-09-18.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP055K/2012-09-18.12CVCP055K.Translated_CPS.pdf

Project ID: 12CVCP055K
File Name: 2012-09-12.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP055K/2012-09-12.12CVCP055K.Decision_Document.pdf

---

B64 **CON EDISON** **RCRA NonGen / NLR** **1019904770**
NNW **72-74 THROOP AVE & GERRY ST** **FINDS** **NYP004801981**
< 1/8 **BROOKLYN, NY 11234** **ECHO**
0.038 mi.
203 ft. **Site 11 of 48 in cluster B**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:
Date form received by agency: 07/02/2015
Facility name: CON EDISON
Facility address: 72-74 THROOP AVE & GERRY ST
BROOKLYN, NY 11234
EPA ID: NYP004801981
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/02/2015
Site name: CON EDISON
Classification: Large Quantity Generator

CON EDISON (Continued) **1019904770**

Violation Status: No violations found

FINDS:

Registry ID: 110069648279

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904770
Registry ID:	110069648279
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069648279

B65 **CON EDISON** **NJ MANIFEST** **S120673454**
NNW **72-74 THROOP AVE & GERRY ST** **N/A**
< 1/8 **BROOKLYN, NY 11234**
0.038 mi.
203 ft. **Site 12 of 48 in cluster B**

Relative: **Lower**
Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYP004801981
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014466557JJK
EPA ID:	NYP004801981
Date Shipped:	7/2/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120673454**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B66 **LOT 29,TAXBLOCK 2266** **NY E DESIGNATION** **S110242381**
NNW **72 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.038 mi.
203 ft. **Site 13 of 48 in cluster B**

Relative: **Lower**

Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 29,TAXBLOCK 2266
Address:	72 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	29
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

LOT 29,TAXBLOCK 2266 (Continued) **S110242381**

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date: Not reported

B67 **THROOP BUILDINGS** **RCRA-LQG** **1015747317**
NNW **72 THROOP AVE** **NY MANIFEST** **NYR000197897**
< 1/8 **BROOKLYN, NY 11206**
0.038 mi.
203 ft. **Site 14 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

RCRA-LQG:
Date form received by agency: 06/03/2014
Facility name: THROOP BUILDINGS
Facility address: 72 THROOP AVE
BROOKLYN, NY 11206
EPA ID: NYR000197897
Mailing address: FLUSHING AVE
UNIT 1D
BROOKLYN, NY 11205
Contact: SIMON DUSHINSKY
Contact address: FLUSHING AVE UNIT 1D
BROOKLYN, NY 11205
Contact country: US
Contact telephone: 718-246-4762
Contact email: SIMON5134@VERIZON.NET
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: SIMON DUSHINSKY
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/31/2012
Owner/Op end date: Not reported

THROOP BUILDINGS (Continued) **1015747317**

Owner/operator name: THROOP WALLABOUT REALTY LLC
Owner/operator address: FLUSHING AVE
BROOKLYN, NY 11206
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/31/2012
Owner/Op end date: Not reported

Owner/operator name: THROOP WALLABOUT REALTY LLC
Owner/operator address: FLUSHING AVE UNIT 1D
BROOKLYN, NY 11206
Owner/operator country: US
Owner/operator telephone: 718-246-4762
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/31/2012
Owner/Op end date: Not reported

Owner/operator name: THROOP WALLABOUT REALTY LLC
Owner/operator address: FLUSHING AVE UNIT 1D
BROOKLYN, NY 11205
Owner/operator country: US
Owner/operator telephone: 718-246-4762
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/31/2012
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

THROOP BUILDINGS (Continued) **1015747317**

Historical Generators:
Date form received by agency: 06/27/2013
Site name: THROOP WALLABOUT REALTY LLC THROOP BUILDINGS
Classification: Not a generator, verified

Date form received by agency: 11/29/2012
Site name: THROOP WALLABOUT REALTY LLC THROOP BUILDINGS
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/12/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NY MANIFEST:
Name: THROOP WALLABOUT REALTY LLC THROOP BUILDINGS
Address: 72 THROOP AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYR000197897
Facility Status: Not reported
Location Address 1: 72 THROOP AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000197897
Mailing Name: THROOP WALLABOUT REALTY LLC THROOP BUILDINGS
Mailing Contact: THROOP WALLABOUT REALTY LLC
Mailing Address 1: 505 FLUSHING AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11205
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

THROOP BUILDINGS (Continued) **1015747317**

Year:	2013
Trans1 State ID:	PAD146714878
Trans2 State ID:	Not reported
Generator Ship Date:	01/10/2013
Trans1 Recv Date:	01/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/10/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000197897
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	010914714JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	43900
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

E68
SW
< 1/8
0.040 mi.
210 ft.

LOT 47,TAXBLOCK 2269
41 BARTLETT STREET
BROOKLYN, NY 11206

Site 1 of 19 in cluster E

NY E DESIGNATION

EDR ID Number: S110242427
EPA ID Number: N/A

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 47,TAXBLOCK 2269
Address:	41 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	47
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

E69
SSW
< 1/8
0.042 mi.
220 ft.

LOT 11,TAXBLOCK 2272
36 BARTLETT STREET
BROOKLYN, NY

Site 2 of 19 in cluster E

NY E DESIGNATION

EDR ID Number: S110242343
EPA ID Number: N/A

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 11,TAXBLOCK 2272
Address:	36 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	11
Tax Block:	2272
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

D70 **THROOP TRANSMISSION** **EDR Hist Auto** **1021093924**
NNW **55 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.042 mi.
222 ft. **Site 2 of 19 in cluster D**

Relative: EDR Hist Auto
Lower

Actual:
13 ft.

Year:	Name:	Type:
1995	THROOP TRANSMISSION	Automotive Transmission Repair Shops
1996	THROOP TRANSMISSION	Automotive Transmission Repair Shops
1997	THROOP TRANSMISSION	Automotive Transmission Repair Shops
1998	THROOP TRANSMISSION	Automotive Transmission Repair Shops
1999	THROOP TRANSMISSION	Automotive Transmission Repair Shops
2000	THROOP TRANSMISSION	Automotive Transmission Repair Shops

---

B71 **LOT 14,TAXBLOCK 2269** **NY E DESIGNATION** **S110242349**
WSW **GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.044 mi.
233 ft. **Site 15 of 48 in cluster B**

Relative: E DESIGNATION:
Higher

Actual:
14 ft.

Name:	LOT 14,TAXBLOCK 2269
Address:	GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	14
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

B72 **MAGIC AUTO REPAIR SHOP** **NY AST** **A100294927**
NW **398 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.044 mi.
234 ft. **Site 16 of 48 in cluster B**

Relative: AST:
Lower

Actual:
13 ft.

Name:	MAGIC AUTO REPAIR SHOP
Address:	398 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610019
Program Type:	PBS
UTM X:	588934.06688

MAGIC AUTO REPAIR SHOP (Continued) **A100294927**

UTM Y:	4506261.87959
Expiration Date:	09/26/2010
Site Type:	Other

Affiliation Records:

Site Id:	353126
Affiliation Type:	Facility Owner
Company Name:	NELSON E. FABIAN
Contact Type:	OWNER
Contact Name:	NELSON FABIAN
Address1:	398 WALLABOUT ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 302-2396
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-09-26

Site Id:	353126
Affiliation Type:	Mail Contact
Company Name:	NELSON E. FABIAN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	MAGIC AUTO REPAIR SHOP
Address2:	398 WALLABOUT STREET
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 302-2396
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-09-26

Site Id:	353126
Affiliation Type:	Facility Operator
Company Name:	MAGIC AUTO REPAIR SHOP
Contact Type:	Not reported
Contact Name:	NELSON E. FABIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 302-2396
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-09-26

Site Id:	353126
Affiliation Type:	Emergency Contact

MAGIC AUTO REPAIR SHOP (Continued) **A100294927**

Company Name:	NELSON E. FABIAN
Contact Type:	Not reported
Contact Name:	INDIRA FAIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 302-2396
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-09-26

Tank Info:

Tank Number:	001
Tank Id:	208130
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	B01 - Tank External Protection - Painted/Asphalt Coating
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	400
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

B73 **LOT 25,TAXBLOCK 2266** **NY E DESIGNATION** **S110242373**
NW **398 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.044 mi.
234 ft. **Site 17 of 48 in cluster B**

Relative: E DESIGNATION:
Lower

Actual: Name:	LOT 25,TAXBLOCK 2266
13 ft. Address:	398 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	25
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K

LOT 25,TAXBLOCK 2266 (Continued) **S110242373**

Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

B74 **398 WALLABOUT STREET** **NY Spills** **S104509519**
NW **398 WALLABOUT ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.044 mi.
234 ft. **Site 18 of 48 in cluster B**

Relative: SPILLS:
Lower

Actual:
13 ft.

Name:	398 WALLABOUT STREET
Address:	398 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9912454 / 2005-01-28
Facility ID:	9912454
Facility Type:	ER
DER Facility ID:	129337
Site ID:	152358
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	2000-01-31
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2000-01-31
CID:	281
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-31
Spill Record Last Update:	2005-01-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NYC FIRE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN COMENALE ONSITE 3:40 PM 1/31/00 MET WITH DISTRICT CHEIF AND POINTED TO LT. STEVE BILOTTI NYFD (HAZ-MAT) WHILE 2 HAZ-MAT MEN

398 WALLABOUT STREET (Continued) **S104509519**

ENTERED BUILDING THEY COUNTED FULL DRUMS TOTALING ABOUT 600 GALLONS OF WHAT WAS THOUGHT TO BE TRICHLOR. THEY HAD ALREADY REMOVED THE TWO MEN AFFECTED BY THE CHEMICALS(SOLVENTS)AND POSSIBLE MEK ON SITE(PID 2K RANGE). A REPORT OF ONE OF THE MENS SNEAKERS AHD MELTED DIDN'T PAN OUT THE HAZ-MAT ENTRY TEAM HAD ph STRIP PAPER ON THERE SARANAC ARMS THAT DID NOT SHOW ACIDS OR CAUSTICS. THE OWNER OF VARTEX INSTRUMENT CORP. CAN BE CONTACTED AT WORK 718-486-5050 JOHN VARTOUGHIN AND AT HOME 718 779-3151 THIS INFORMATION WAS OBTAINED FROM THE FIRE MARSHALL LT. JOANN MILLER(394) THE MEN ARE 50 AND 71 YEARS OF AGE AND BOTH WERE TAKEN TO WOODHULL HOSPITAL FOR TREATMENT. SARGENT PALLADINO OF THE NYPD BLUE INDICATED THAT THEY COULD SECURE THE SITE. CHRIS HAAS OF NYCDEP WAS ONSITE AND TUCKER OF THE DEPARTMENT OF HEALTH (NYC?) NYFD EMS AND OTHERS ON SITE OUTSIDE THE HAZ-MAT TAPE. PICTURESINTO BASEMENT OF POOLING TRICHLOR ON DIRT FLOOR PROBABLE SOIL CONTAMINATION FOUR ROOSTERS ALSO CAME TO AND WERE REMOVED FROM THE SITE. 3/23/04 - AUSTIN - ORIG. ASSIGNED TO COMENALE - NO RECORD OF THIS SITE IN REMEDIATION PROGRAM - PROPERTY SEARCH SHOWS THIS LOCATION AS A PARKING GARAGE (?) - NO LONGER A SPILLS PROGRAM MATTER - CLOSED - END"

Remarks: "HAZ MAT INCIDENT AT ABOVE LOCATION. 2 SUBJECTS IN CARDIAC ARREST. NYC FIRE REQUESTING CALL BACK."

All Materials:

Site ID:	152358
Operable Unit ID:	1091161
Operable Unit:	01
Material ID:	294335
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B75 **LOT 24,TAXBLOCK 2266** **NY E DESIGNATION** **S117676042**
NW **396 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.044 mi.
234 ft. **Site 19 of 48 in cluster B**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 24,TAXBLOCK 2266
Address:	396 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	24
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol

LOT 24,TAXBLOCK 2266 (Continued) **S117676042**

Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

E76 **LOT 48,TAXBLOCK 2269** **NY E DESIGNATION** **S110242430**
SW **39 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.044 mi.
234 ft. **Site 3 of 19 in cluster E**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 48,TAXBLOCK 2269
Address: 39 BARTLETT STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 48
Tax Block: 2269
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

C77 **CON EDISON** **NJ MANIFEST** **S120678585**
ESE **95 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.045 mi.
236 ft. **Site 5 of 16 in cluster C**

Relative: **Higher**
Actual: **16 ft.**

NJ MANIFEST:
EPA Id: NYP004884868
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported

CON EDISON (Continued) **S120678585**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015322133JJK
EPA ID:	NYP004884868
Date Shipped:	12/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C78 **CON EDISON** **RCRA NonGen / NLR** **1019909443**
ESE **95 THROOP AVE** **FINDS** **NYP004884868**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.045 mi.
236 ft. **Site 6 of 16 in cluster C**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/29/2016
Facility name:	CON EDISON
Facility address:	95 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004884868
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/29/2016
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110069661645

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019909443**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019909443
Registry ID: 110069661645
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069661645

B79 **LOT 23,TAXBLOCK 2266** **NY E DESIGNATION** **S110242367**
NW **394 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.045 mi.
236 ft. **Site 20 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:
Name: LOT 23,TAXBLOCK 2266
Address: 394 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 23
Tax Block: 2266
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

B80 **LOT 22,TAXBLOCK 2266** **NY E DESIGNATION** **S110242366**
WNW **392 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.046 mi.
241 ft. **Site 21 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:
Name: LOT 22,TAXBLOCK 2266
Address: 392 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 22
Tax Block: 2266
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009

LOT 22,TAXBLOCK 2266 (Continued) **S110242366**

Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

B81 **LOT 21,TAXBLOCK 2266** **NY E DESIGNATION** **S110242364**
WNW **390 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.047 mi.
248 ft. **Site 22 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:
Name: LOT 21,TAXBLOCK 2266
Address: 390 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 21
Tax Block: 2266
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

B82 **390 WALLABOUT STREET** **NY VCP** **S118943195**
WNW **390 WALLABOUT STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.047 mi.
248 ft. **Site 23 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

VCP NYC:
Project ID: 12CVCP056K
Project Name: 390 WALLABOUT STREET
Project Address: 390 WALLABOUT STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 12CVCP056K
File Name: 2012-04-30.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP056K/2012-04-30.12CVCP056K.390_Wallabout_Street.RIR.pdf

Project ID: 12CVCP056K
File Name: 2012-06-11.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP056K/2012-06-11.12CVCP056K.RAWP.pdf

Project ID: 12CVCP056K
File Name: 2012-04-30.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP056K/2012-04-30.12CVCP056K.390_Wallabout_Street.FactSheet1.pdf

Project ID: 12CVCP056K
File Name: 2012-07-01.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP056K/2012-07-01.12CVCP056K.FactSheet2.pdf

Project ID: 12CVCP056K
File Name: 2012-07-03.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP056K/2012-07-03.12CVCP056K.Translated_FactSheet2.pdf

Project ID: 12CVCP056K
File Name: 2012-07-03.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP056K/2012-07-03.12CVCP056K.Translated_CPS.pdf

Project ID: 12CVCP056K
File Name: 2012-06-28.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CVCP056K/2012-06-28.12CVCP056K.Decision_Document.pdf

---

B83 **VENT PIPE** **NY Spills** **S111456487**
WSW **63 GREY ROAD** **N/A**
< 1/8 **SOUTH FALLSBURGH, NY**
0.048 mi.
252 ft. **Site 24 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

SPILLS:
Name: VENT PIPE
Address: 63 GREY ROAD
City,State,Zip: SOUTH FALLSBURGH, NY
Spill Number/Closed Date: 1110386 / 2014-06-09

VENT PIPE (Continued) **S111456487**

Facility ID:	1110386
Facility Type:	ER
DER Facility ID:	412696
Site ID:	458220
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	5328
Spill Date:	2011-11-21
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	2011-11-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-11-22
Spill Record Last Update:	2014-06-11
Spiller Name:	Mike Taylor
Spiller Company:	Combined Energy Systems
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"11/22/11 Driver could not hear whistle, approx 5 to 10 gallons out of vent to soil. One drum full of pcs was collected. Homeowner not happy, wants more removed along with his well sampled. Steve Kalka has been hired to take water sample and access soil...mm See edocs for email response of 2/6/12. DT 7/9/13- Site meeting. Tom Chi, Steve Kalka, Deborah Thompson, Mike Taylor, and Energi Insurance on site. Discussed spill cleanup history and noted spill area. Area of initial cleanup/soil removal was limited to area under deck only; no cleanup performed outside of under deck area adjacent to tank. Recent test pit was done just downgradient of cleanup area towards pool that demonstrated impact. Shallow exposed bedrock is visible. Mr. Taylor explained that spill occurred due to plastic cap in a bung opening on top of a/g 550 tank instead of a metal cap. Tank was overfilled causing oil to come out of plastic cap on bung opening. Inspected whole house treatment system. Only one carbon tank followed by sediment filter and a UV light. Required that system be upgraded to be in compliance with DOH specs. Site potable well is reported to be some 400 feet deep and is some 40 feet from spill location. Required that well be checked for presence of free phase product. Discussed additional work requirements to delineate impacts and remediate. DT Consulting to submit work plan to Ins. Co. and then to DEC for subsurface investigation. DT 8/21/13- DT Consulting reports that subsurface investigation was performed and report to be sent to DEC in next 7-10 days. DT Subsurface Inv. conducted; no significant soil or gw impacts found. POET to remain in place and monitored quarterly. 6/9/14- Received 4 quarterly POET system sample results. Raw water has been non-detect. No Further Remeidal Action necessary at this time. DT"

VENT PIPE (Continued) **S111456487**

Remarks: "No Whisle Clean up done"

All Materials:
Site ID: 458220
Operable Unit ID: 1208330
Operable Unit: 01
Material ID: 2205643
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

E84 **LOT 49,TAXBLOCK 2269** **NY E DESIGNATION** **S110242432**
SW **37 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.049 mi.
258 ft. **Site 4 of 19 in cluster E**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 49,TAXBLOCK 2269
Address: 37 BARTLETT STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 49
Tax Block: 2269
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

B85 **LOT 20,TAXBLOCK 2266** **NY E DESIGNATION** **S110242363**
WNW **388 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.049 mi.
259 ft. **Site 25 of 48 in cluster B**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 20,TAXBLOCK 2266
Address: 388 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 20
Tax Block: 2266
Borough Code: Not reported

LOT 20,TAXBLOCK 2266 (Continued) **S110242363**

E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

B86 **LOT 49,TAXBLOCK 2266** **NY E DESIGNATION** **S120838983**
West **GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.050 mi.
264 ft. **Site 26 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 49,TAXBLOCK 2266
Address:	GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	49
Tax Block:	2266
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

E87 **J&M AUTO SERVICE CORP.** **NY UST** **U004053200**
SSW **30 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.050 mi.
266 ft. **Site 5 of 19 in cluster E**

Relative:
Higher

Actual:
14 ft.

UST:

Name:	J&M AUTO SERVICE CORP.
Address:	30 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-610233 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588973.26349
UTM Y:	4506078.08264
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	365192
Affiliation Type:	Facility Owner
Company Name:	ROSALINDA JOSE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	620 EAGLE AVENUE
Address2:	Not reported
City:	WEST HEMPSTEAD
State:	NY
Zip Code:	11552
Country Code:	001
Phone:	(516) 486-8471
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-05-01

Site Id:	365192
Affiliation Type:	Mail Contact
Company Name:	2001 HIGH TECH AUTO SERVICE CORP.
Contact Type:	Not reported
Contact Name:	JULIO C. JOSE
Address1:	30 BARTLETT STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 387-5373
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-06-09

Site Id:	365192
Affiliation Type:	Facility Operator
Company Name:	2001 HIGH TECH AUTO SERVICE CORP.
Contact Type:	Not reported
Contact Name:	JULIO C. JOSE
Address1:	Not reported

J&M AUTO SERVICE CORP. (Continued) **U004053200**

Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-5373
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-23

Site Id:	365192
Affiliation Type:	Emergency Contact
Company Name:	ROSALINDA JOSE
Contact Type:	Not reported
Contact Name:	JULIO C. JOSE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 387-5373
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-03-23

Tank Info:

Tank Number:	1
Tank ID:	212178
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	01/07/1998
Date Tank Closed:	08/12/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
L00 - Piping Leak Detection - None

J&M AUTO SERVICE CORP. (Continued) **U004053200**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

E88 **LOT 9,TAXBLOCK 2272** **NY E DESIGNATION** **S110242451**
SSW **30 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.050 mi.
266 ft. **Site 6 of 19 in cluster E**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 9,TAXBLOCK 2272
Address:	30 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	9
Tax Block:	2272
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

B89 **LOT 19,TAXBLOCK 2266** **NY E DESIGNATION** **S110242360**
WNW **386 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.051 mi.
269 ft. **Site 27 of 48 in cluster B**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 19,TAXBLOCK 2266
Address:	386 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	19
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b

LOT 19,TAXBLOCK 2266 (Continued) **S110242360**

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

B90 **386 AND 388 WALLABOUT STREET** **NY VCP** **S118943167**
WNW **386 AND 388 WALLABOUT STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.051 mi.
269 ft. **Site 28 of 48 in cluster B**

Relative: Higher
Actual: 14 ft.

VCP NYC:
Project ID: 12CBCP025K
Project Name: 386 AND 388 WALLABOUT STREET
Project Address: 386 AND 388 WALLABOUT STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 12CBCP025K
File Name: 2011-08-16.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP025K/2011-08-16.12CBCP025K.386_and_388_Wallabout_Street.RIR.pdf

Project ID: 12CBCP025K
File Name: 2011-08-18.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP025K/2011-08-18.12CBCP025K.386_and_388_Wallabout_Street.RAWP_Draft.pdf

Project ID: 12CBCP025K
File Name: 2011-08-17.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP025K/2011-08-17.12CBCP025K.386_and_388_Wallabout_Street.Fact_Sheet.pdf

---

B91 **PFIZER INC/GERRY ST** **NY LTANKS** **S100493659**
West **PFIZER INC/GERRY ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.052 mi.
273 ft. **Site 29 of 48 in cluster B**

Relative: Higher
Actual: 14 ft.

LTANKS:
Name: PFIZER INC/GERRY ST
Address: PFIZER INC/GERRY ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9203348 / 1992-06-22
Facility ID: 9203348
Site ID: 204940
Spill Date: 1992-06-19

PFIZER INC/GERRY ST (Continued) **S100493659**

Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1992-06-22
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1992-06-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-06-23
Spill Record Last Update:	2002-11-29
Spiller Name:	Not reported
Spiller Company:	PFIZER INC
Spiller Address:	630 FLUSHING AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	170254
DEC Memo:	""
Remarks:	"CONTAMINATED SOIL STOCKPILED IN DUMPSTERS AFTER TANK PULL. SAMPLING, TESTING & WILL DISPOSE. REQUESTS CALLBACK."

All Materials:

Site ID:	204940
Operable Unit ID:	967193
Operable Unit:	01
Material ID:	411149
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

B92 **LOT 18,TAXBLOCK 2266** **NY E DESIGNATION** **S110242358**
WNW **384 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.053 mi.
282 ft. **Site 30 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 18,TAXBLOCK 2266
Address:	384 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	18
Tax Block:	2266

LOT 18,TAXBLOCK 2266 (Continued) **S110242358**

Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

E93 **LOT 50,TAXBLOCK 2269** **NY E DESIGNATION** **S110242435**
SW **35 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.054 mi.
283 ft. **Site 7 of 19 in cluster E**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 50,TAXBLOCK 2269
Address:	35 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	50
Tax Block:	2269
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported

B94 **LOT 17,TAXBLOCK 2266** **NY E DESIGNATION** **S110242356**
WNW **382 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.056 mi.
297 ft. **Site 31 of 48 in cluster B**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 17,TAXBLOCK 2266
Address:	382 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	17
Tax Block:	2266
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009

LOT 17,TAXBLOCK 2266 (Continued) **S110242356**

Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

F95 **LOT 45,TAXBLOCK 2272** **NY E DESIGNATION** **S110242420**
South **11 WHIPPLE STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.057 mi.
299 ft. **Site 1 of 19 in cluster F**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 45,TAXBLOCK 2272
Address: 11 WHIPPLE STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 45
Tax Block: 2272
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

F96 **11 WHIPPLE STREET** **NY VCP** **S118943632**
South **11 WHIPPLE STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.057 mi.
299 ft. **Site 2 of 19 in cluster F**

Relative:
Higher

Actual:
14 ft.

VCP NYC:
Project ID: 17CVCP011K
Project Name: 11 WHIPPLE STREET
Project Address: 11 WHIPPLE STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 17CVCP011K
File Name: 2014-02-11.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP009K/2014-02-11.14EHAN406K.17CVCP009K.11_Whipple_Street.report.Revised_RIR.FINAL.pdf

Project ID: 17CVCP011K
File Name: 2016-08-23.RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP009K/2016-08-03.17CVCP009K.14EHAN406K.11_Whipple_Street.report.Revised_RAWP_EBCv2.pdf

Project ID: 17CVCP011K
File Name: 2016-08-10.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP009K/2016-08-10.14EHAN406K.17CVCP009K.11_Whipple_Street.doc.Factsheet-1.pdf

Project ID: 17CVCP011K
File Name: 2016-08-10.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP009K/2016-08-10.14EHAN406K.17CVCP009K.11_Whipple_Street.doc.Translated_Factsheet-1.pdf

Project ID: 17CVCP011K
File Name: 2016-08-10.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP009K/2016-08-10.14EHAN406K.17CVCP009K.11_Whipple_Street.doc.Translated_CPS.pdf

---

B97 **PFIZER SITES B AND D** **NY ENG CONTROLS** **S106906497**
WSW **59-71 GERRY ST. AND 73-87 GERRY ST.** **NY INST CONTROL** **N/A**
< 1/8 **BROOKLYN, NY 11206** **NY VCP**
0.057 mi.
300 ft. **Site 32 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

ENG CONTROLS:
Name: PFIZER SITES B AND D
Address: 59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip: BROOKLYN, NY 11206
Site Code: 58206
HW Code: V00350
Control Code: 36
Control Type: ENG
Date Record Added: 07/09/2018
Date Rec Updated: 07/09/2018

PFIZER SITES B AND D (Continued) **S106906497**

Updated By: MXYAU

Site Description: Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D) is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium

PFIZER SITES B AND D (Continued) **S106906497**

sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1.

PFIZER SITES B AND D (Continued) **S106906497**

Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February 2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside

PFIZER SITES B AND D (Continued) **S106906497**

	the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.
Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-06-27 16:53:00
Record Upd:	2013-09-20 14:18:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Barbara Wong
Owner Company:	Pfizer, Inc.
Owner Address:	100 Route 206N, M/S 401
Owner Addr2:	M/S 401
Owner City,St,Zip:	Peapack, NJ 07977
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	47-40 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Not reported
Owner Company:	Congregation Divrei Yoel
Owner Address:	144 Spencer Street, #612
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	Williamsburg Branch
Owner Addr2:	240 Division Avenue
Owner City,St,Zip:	Brooklyn, NY 11211

PFIZER SITES B AND D (Continued) **S106906497**

Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	YGS, Inc. f/k/a Congregation YGS
Owner Address:	174 Rodney Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Juda Klein
Owner Company:	58 Gerry Street, LLC
Owner Address:	236 Broadway
Owner Addr2:	2nd Floor
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Berish Ekstein and Joseph Jacob
Owner Address:	85 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Wolf Englender
Owner Company:	Bais Ruchel High School, Inc.
Owner Address:	82 Lee Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Yoel Kaufman
Owner Address:	81 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Benjamin Perlstein
Owner Address:	94 Skillman Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America

PFIZER SITES B AND D (Continued) **S106906497**

Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Simon Strulovic
Owner Address:	150 Heyward Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	V00350
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,2-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350

PFIZER SITES B AND D (Continued) **S106906497**

Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,1,2,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)PYRENE

PFIZER SITES B AND D (Continued) **S106906497**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224101
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2016-09-14 10:26:00
Record Updated:	2016-09-14 10:26:00
Updated By:	IXMUNTEA
Crossref ID:	2-612842
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2018-01-26 17:41:00
Record Updated:	2018-01-26 17:41:00
Updated By:	JAAVERSA
Crossref ID:	D2-0010-0703
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-07-26 14:24:00
Record Updated:	2018-07-26 14:24:00
Updated By:	MXYAU
Crossref ID:	2016000368538
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:42:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2018000111646
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:00:00
Record Updated:	2018-07-06 11:00:00
Updated By:	MXYAU
Crossref ID:	2018000088966
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:01:00
Record Updated:	2018-07-06 11:01:00
Updated By:	MXYAU
Crossref ID:	2017000436670
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:40:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2014000220216
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:02:00
Record Updated:	2018-07-06 11:02:00
Updated By:	MXYAU
Crossref ID:	2016000368537
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier

PFIZER SITES B AND D (Continued) **S106906497**

Record Added Date:	2017-11-29 16:43:00
Record Updated:	2017-11-29 16:43:00
Updated By:	MXYAU
Crossref ID:	00-TEMP-02-59(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Name:	PFIZER SITES B AND D
Address:	59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip:	BROOKLYN, NY 11206
Site Code:	58206
HW Code:	V00350
Control Code:	13
Control Type:	ENG
Date Record Added:	07/09/2018
Date Rec Updated:	07/09/2018
Updated By:	MXYAU
Site Description:	Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground

PFIZER SITES B AND D (Continued) **S106906497**

Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D) is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable

PFIZER SITES B AND D (Continued) **S106906497**

groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1. Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February

PFIZER SITES B AND D (Continued) **S106906497**

2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.

Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-06-27 16:53:00
Record Upd:	2013-09-20 14:18:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Barbara Wong
Owner Company:	Pfizer, Inc.
Owner Address:	100 Route 206N, M/S 401
Owner Addr2:	M/S 401
Owner City,St,Zip:	Peapack, NJ 07977
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	47-40 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	Oholei Shloma

PFIZER SITES B AND D (Continued) **S106906497**

Owner Address:	517 Flushing Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Not reported
Owner Company:	Congregation Divrei Yoel
Owner Address:	144 Spencer Street, #612
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	Williamsburg Branch
Owner Addr2:	240 Division Avenue
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	YGS, Inc. f/k/a Congregation YGS
Owner Address:	174 Rodney Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Juda Klein
Owner Company:	58 Gerry Street, LLC
Owner Address:	236 Broadway
Owner Addr2:	2nd Floor
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Berish Ekstein and Joseph Jacob
Owner Address:	85 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Wolf Englender
Owner Company:	Bais Ruchel High School, Inc.
Owner Address:	82 Lee Avenue

PFIZER SITES B AND D (Continued) **S106906497**

Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Yoel Kaufman
Owner Address:	81 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Benjamin Perlstein
Owner Address:	94 Skillman Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Simon Strulovic
Owner Address:	150 Heyward Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	V00350
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene

PFIZER SITES B AND D (Continued) **S106906497**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,2-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,1,2,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN

PFIZER SITES B AND D (Continued) **S106906497**

Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224101
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2016-09-14 10:26:00
Record Updated:	2016-09-14 10:26:00
Updated By:	IXMUNTEA
Crossref ID:	2-612842
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2018-01-26 17:41:00
Record Updated:	2018-01-26 17:41:00
Updated By:	JAAVERSA
Crossref ID:	D2-0010-0703
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-07-26 14:24:00
Record Updated:	2018-07-26 14:24:00
Updated By:	MXYAU
Crossref ID:	2016000368538
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:42:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2018000111646
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:00:00
Record Updated:	2018-07-06 11:00:00
Updated By:	MXYAU
Crossref ID:	2018000088966
Cross Ref Type Code:	25

PFIZER SITES B AND D (Continued) **S106906497**

Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:01:00
Record Updated:	2018-07-06 11:01:00
Updated By:	MXYAU
Crossref ID:	2017000436670
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:40:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2014000220216
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:02:00
Record Updated:	2018-07-06 11:02:00
Updated By:	MXYAU
Crossref ID:	2016000368537
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:43:00
Record Updated:	2017-11-29 16:43:00
Updated By:	MXYAU
Crossref ID:	00-TEMP-02-59(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

Name:	PFIZER SITES B AND D
Address:	59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip:	BROOKLYN, NY 11206
Site Code:	58206
HW Code:	V00350
Control Code:	12
Control Type:	ENG
Date Record Added:	07/09/2018
Date Rec Updated:	07/09/2018
Updated By:	MXYAU
Site Description:	Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and

PFIZER SITES B AND D (Continued) **S106906497**

Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D) is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the

PFIZER SITES B AND D (Continued) **S106906497**

eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1. Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature

PFIZER SITES B AND D (Continued) **S106906497**

and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February 2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.

Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-06-27 16:53:00
Record Upd:	2013-09-20 14:18:00
Updated By:	ldennist
Own Op:	Applicant/Requestor

PFIZER SITES B AND D (Continued) **S106906497**

Sub Type:	P03
Owner Name:	Barbara Wong
Owner Company:	Pfizer, Inc.
Owner Address:	100 Route 206N, M/S 401
Owner Addr2:	M/S 401
Owner City,St,Zip:	Peapack, NJ 07977
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	47-40 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Not reported
Owner Company:	Congregation Divrei Yoel
Owner Address:	144 Spencer Street, #612
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	Williamsburg Branch
Owner Addr2:	240 Division Avenue
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	YGS, Inc. f/k/a Congregation YGS
Owner Address:	174 Rodney Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E

PFIZER SITES B AND D (Continued) **S106906497**

Owner Name:	Juda Klein
Owner Company:	58 Gerry Street, LLC
Owner Address:	236 Broadway
Owner Addr2:	2nd Floor
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Berish Ekstein and Joseph Jacob
Owner Address:	85 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Wolf Englender
Owner Company:	Bais Ruchel High School, Inc.
Owner Address:	82 Lee Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Yoel Kaufman
Owner Address:	81 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Benjamin Perlstein
Owner Address:	94 Skillman Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Simon Strulovic
Owner Address:	150 Heyward Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	V00350
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN

PFIZER SITES B AND D (Continued) **S106906497**

Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,2-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,1,2,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

PFIZER SITES B AND D (Continued) **S106906497**

HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224101
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2016-09-14 10:26:00
Record Updated:	2016-09-14 10:26:00
Updated By:	IXMUNTEA
Crossref ID:	2-612842
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2018-01-26 17:41:00
Record Updated:	2018-01-26 17:41:00
Updated By:	JAAVERSA
Crossref ID:	D2-0010-0703

PFIZER SITES B AND D (Continued) **S106906497**

Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-07-26 14:24:00
Record Updated: 2018-07-26 14:24:00
Updated By: MXYAU
Crossref ID: 2016000368538
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:42:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2018000111646
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:00:00
Record Updated: 2018-07-06 11:00:00
Updated By: MXYAU
Crossref ID: 2018000088966
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:01:00
Record Updated: 2018-07-06 11:01:00
Updated By: MXYAU
Crossref ID: 2017000436670
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:40:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2014000220216
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:02:00
Record Updated: 2018-07-06 11:02:00
Updated By: MXYAU
Crossref ID: 2016000368537
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:43:00
Record Updated: 2017-11-29 16:43:00
Updated By: MXYAU
Crossref ID: 00-TEMP-02-59(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: PFIZER SITES B AND D
Address: 59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip: BROOKLYN, NY 11206
Site Code: 58206
HW Code: V00350
Control Code: 15
Control Type: ENG
Date Record Added: 07/09/2018
Date Rec Updated: 07/09/2018

PFIZER SITES B AND D (Continued) **S106906497**

Updated By: MXYAU
Site Description: Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D) is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium

PFIZER SITES B AND D (Continued) **S106906497**

sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1.

PFIZER SITES B AND D (Continued) **S106906497**

Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February 2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside

PFIZER SITES B AND D (Continued) **S106906497**

	the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.
Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-06-27 16:53:00
Record Upd:	2013-09-20 14:18:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Barbara Wong
Owner Company:	Pfizer, Inc.
Owner Address:	100 Route 206N, M/S 401
Owner Addr2:	M/S 401
Owner City,St,Zip:	Peapack, NJ 07977
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	47-40 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Not reported
Owner Company:	Congregation Divrei Yoel
Owner Address:	144 Spencer Street, #612
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	Williamsburg Branch
Owner Addr2:	240 Division Avenue
Owner City,St,Zip:	Brooklyn, NY 11211

PFIZER SITES B AND D (Continued) **S106906497**

Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	YGS, Inc. f/k/a Congregation YGS
Owner Address:	174 Rodney Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Juda Klein
Owner Company:	58 Gerry Street, LLC
Owner Address:	236 Broadway
Owner Addr2:	2nd Floor
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Berish Ekstein and Joseph Jacob
Owner Address:	85 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Wolf Englender
Owner Company:	Bais Ruchel High School, Inc.
Owner Address:	82 Lee Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Yoel Kaufman
Owner Address:	81 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Benjamin Perlstein
Owner Address:	94 Skillman Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America

PFIZER SITES B AND D (Continued) **S106906497**

Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Simon Strulovic
Owner Address:	150 Heyward Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	V00350
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,2-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350

PFIZER SITES B AND D (Continued) **S106906497**

Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	1,1,2,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)PYRENE

PFIZER SITES B AND D (Continued) **S106906497**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224101
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2016-09-14 10:26:00
Record Updated:	2016-09-14 10:26:00
Updated By:	IXMUNTEA
Crossref ID:	2-612842
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2018-01-26 17:41:00
Record Updated:	2018-01-26 17:41:00
Updated By:	JAAVERSA
Crossref ID:	D2-0010-0703
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-07-26 14:24:00
Record Updated:	2018-07-26 14:24:00
Updated By:	MXYAU
Crossref ID:	2016000368538
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:42:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2018000111646
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:00:00
Record Updated:	2018-07-06 11:00:00
Updated By:	MXYAU
Crossref ID:	2018000088966
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:01:00
Record Updated:	2018-07-06 11:01:00
Updated By:	MXYAU
Crossref ID:	2017000436670
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:40:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2014000220216
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:02:00
Record Updated:	2018-07-06 11:02:00
Updated By:	MXYAU
Crossref ID:	2016000368537
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier

PFIZER SITES B AND D (Continued) **S106906497**

Record Added Date: 2017-11-29 16:43:00
Record Updated: 2017-11-29 16:43:00
Updated By: MXYAU
Crossref ID: 00-TEMP-02-59(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

INST CONTROL:
Name: PFIZER SITES B AND D
Address: 59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip: BROOKLYN, NY 11206
Site Code: 58206
Control Name: Deed Restriction
HW Code: V00350
Control Code: A
Control Type: INST
Dt record added: 07/09/2018
Dt rec updated: 07/09/2018
Updated By: MXYAU
Site Code: 58206
Site Description: Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to

PFIZER SITES B AND D (Continued) **S106906497**

Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D) is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper

PFIZER SITES B AND D (Continued) **S106906497**

intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1. Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor

PFIZER SITES B AND D (Continued) **S106906497**

extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February 2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-06-27 16:53:00
Record Upd: 2013-09-20 14:18:00
Updated By: ldennist
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Barbara Wong
Owner Company: Pfizer, Inc.
Owner Address: 100 Route 206N, M/S 401
Owner Addr2: M/S 401
Owner City,St,Zip: Peapack, NJ 07977
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York State Department of Environmental Conservation
Owner Address: 47-40 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: Applicant/Requestor

PFIZER SITES B AND D (Continued) **S106906497**

Sub Type: P03
Owner Name: Sol Moskovits
Owner Company: Oholei Shloma
Owner Address: 517 Flushing Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Not reported
Owner Company: Congregation Divrei Yoel
Owner Address: 144 Spencer Street, #612
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library
Owner Address: Williamsburg Branch
Owner Addr2: 240 Division Avenue
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: Oholei Shloma
Owner Address: 517 Flushing Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Sol Moskovits
Owner Company: YGS, Inc. f/k/a Congregation YGS
Owner Address: 174 Rodney Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Juda Klein
Owner Company: 58 Gerry Street, LLC
Owner Address: 236 Broadway
Owner Addr2: 2nd Floor
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Berish Ekstein and Joseph Jacob
Owner Address: 85 Gerry Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: Owner
Sub Type: 06

PFIZER SITES B AND D (Continued) **S106906497**

Owner Name: Wolf Englender
Owner Company: Bais Ruchel High School, Inc.
Owner Address: 82 Lee Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Yoel Kaufman
Owner Address: 81 Gerry Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Benjamin Perlstein
Owner Address: 94 Skillman Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Simon Strulovic
Owner Address: 150 Heyward Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: V00350
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN

PFIZER SITES B AND D (Continued) **S106906497**

Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,2-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,1,2,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported

PFIZER SITES B AND D (Continued) **S106906497**

HW Code: V00350
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224101
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-09-14 10:26:00
Record Updated: 2016-09-14 10:26:00
Updated By: IXMUNTEA
Crossref ID: 2-612842
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2018-01-26 17:41:00
Record Updated: 2018-01-26 17:41:00
Updated By: JAAVERSA
Crossref ID: D2-0010-0703
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-07-26 14:24:00
Record Updated: 2018-07-26 14:24:00
Updated By: MXYAU
Crossref ID: 2016000368538
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:42:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2018000111646
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:00:00
Record Updated: 2018-07-06 11:00:00

PFIZER SITES B AND D (Continued) **S106906497**

Updated By: MXYAU
Crossref ID: 2018000088966
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:01:00
Record Updated: 2018-07-06 11:01:00
Updated By: MXYAU
Crossref ID: 2017000436670
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:40:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2014000220216
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:02:00
Record Updated: 2018-07-06 11:02:00
Updated By: MXYAU
Crossref ID: 2016000368537
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:43:00
Record Updated: 2017-11-29 16:43:00
Updated By: MXYAU
Crossref ID: 00-TEMP-02-59(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: PFIZER SITES B AND D
Address: 59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip: BROOKLYN, NY 11206
Site Code: 58206
Control Name: Site Management Plan
HW Code: V00350
Control Code: 32
Control Type: INST
Dt record added: 07/09/2018
Dt rec updated: 07/09/2018
Updated By: MXYAU
Site Code: 58206
Site Description: Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment

PFIZER SITES B AND D (Continued) **S106906497**

building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D) is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described

PFIZER SITES B AND D (Continued) **S106906497**

separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1. Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to

PFIZER SITES B AND D (Continued) **S106906497**

contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February 2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

PFIZER SITES B AND D (Continued) **S106906497**

Dell: Not reported
Record Add: 2011-06-27 16:53:00
Record Upd: 2013-09-20 14:18:00
Updated By: ldennist
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Barbara Wong
Owner Company: Pfizer, Inc.
Owner Address: 100 Route 206N, M/S 401
Owner Addr2: M/S 401
Owner City,St,Zip: Peapack, NJ 07977
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York State Department of Environmental Conservation
Owner Address: 47-40 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Sol Moskovits
Owner Company: Oholei Shloma
Owner Address: 517 Flushing Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Not reported
Owner Company: Congregation Divrei Yoel
Owner Address: 144 Spencer Street, #612
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library
Owner Address: Williamsburg Branch
Owner Addr2: 240 Division Avenue
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: Oholei Shloma
Owner Address: 517 Flushing Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Sol Moskovits
Owner Company: YGS, Inc. f/k/a Congregation YGS
Owner Address: 174 Rodney Street

PFIZER SITES B AND D (Continued) **S106906497**

Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Juda Klein
Owner Company: 58 Gerry Street, LLC
Owner Address: 236 Broadway
Owner Addr2: 2nd Floor
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Berish Ekstein and Joseph Jacob
Owner Address: 85 Gerry Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Wolf Englender
Owner Company: Bais Ruchel High School, Inc.
Owner Address: 82 Lee Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Yoel Kaufman
Owner Address: 81 Gerry Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Benjamin Perlstein
Owner Address: 94 Skillman Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Simon Strulovic
Owner Address: 150 Heyward Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: V00350
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TOLUENE

PFIZER SITES B AND D (Continued) **S106906497**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,2-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,1,2,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZENE
Waste Quantity: UNKNOWN

PFIZER SITES B AND D (Continued) **S106906497**

Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224101
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-09-14 10:26:00
Record Updated: 2016-09-14 10:26:00
Updated By: IXMUNTEA
Crossref ID: 2-612842
Cross Ref Type Code: 18

PFIZER SITES B AND D (Continued) **S106906497**

Cross Ref Type: PBS No.
Record Added Date: 2018-01-26 17:41:00
Record Updated: 2018-01-26 17:41:00
Updated By: JAAVERSA
Crossref ID: D2-0010-0703
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-07-26 14:24:00
Record Updated: 2018-07-26 14:24:00
Updated By: MXYAU
Crossref ID: 2016000368538
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:42:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2018000111646
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:00:00
Record Updated: 2018-07-06 11:00:00
Updated By: MXYAU
Crossref ID: 2018000088966
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:01:00
Record Updated: 2018-07-06 11:01:00
Updated By: MXYAU
Crossref ID: 2017000436670
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:40:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2014000220216
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:02:00
Record Updated: 2018-07-06 11:02:00
Updated By: MXYAU
Crossref ID: 2016000368537
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:43:00
Record Updated: 2017-11-29 16:43:00
Updated By: MXYAU
Crossref ID: 00-TEMP-02-59(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: PFIZER SITES B AND D
Address: 59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip: BROOKLYN, NY 11206
Site Code: 58206

PFIZER SITES B AND D (Continued) **S106906497**

Control Name: Landuse Restriction
HW Code: V00350
Control Code: 25
Control Type: INST
Dt record added: 07/09/2018
Dt rec updated: 07/09/2018
Updated By: MXYAU
Site Code: 58206
Site Description: Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D)

PFIZER SITES B AND D (Continued) **S106906497**

is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of

PFIZER SITES B AND D (Continued) **S106906497**

Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1. Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February 2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further

PFIZER SITES B AND D (Continued) **S106906497**

	downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.
Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-06-27 16:53:00
Record Upd:	2013-09-20 14:18:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Barbara Wong
Owner Company:	Pfizer, Inc.
Owner Address:	100 Route 206N, M/S 401
Owner Addr2:	M/S 401
Owner City,St,Zip:	Peapack, NJ 07977
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	47-40 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Not reported
Owner Company:	Congregation Divrei Yoel
Owner Address:	144 Spencer Street, #612
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America

PFIZER SITES B AND D (Continued) **S106906497**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library
Owner Address: Williamsburg Branch
Owner Addr2: 240 Division Avenue
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Not reported
Owner Company: Oholei Shloma
Owner Address: 517 Flushing Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Sol Moskovits
Owner Company: YGS, Inc. f/k/a Congregation YGS
Owner Address: 174 Rodney Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: E
Owner Name: Juda Klein
Owner Company: 58 Gerry Street, LLC
Owner Address: 236 Broadway
Owner Addr2: 2nd Floor
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Berish Ekstein and Joseph Jacob
Owner Address: 85 Gerry Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Wolf Englender
Owner Company: Bais Ruchel High School, Inc.
Owner Address: 82 Lee Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Yoel Kaufman
Owner Address: 81 Gerry Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: Owner

PFIZER SITES B AND D (Continued) **S106906497**

Sub Type: A
Owner Name: Not reported
Owner Company: Benjamin Perlstein
Owner Address: 94 Skillman Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: A
Owner Name: Not reported
Owner Company: Simon Strulovic
Owner Address: 150 Heyward Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: V00350
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,2-DICHLOROETHANE

PFIZER SITES B AND D (Continued) **S106906497**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,1,2,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN

PFIZER SITES B AND D (Continued) **S106906497**

Waste Code: Not reported
HW Code: V00350
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224101
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2016-09-14 10:26:00
Record Updated: 2016-09-14 10:26:00
Updated By: IXMUNTEA
Crossref ID: 2-612842
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2018-01-26 17:41:00
Record Updated: 2018-01-26 17:41:00
Updated By: JAAVERSA
Crossref ID: D2-0010-0703
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-07-26 14:24:00
Record Updated: 2018-07-26 14:24:00
Updated By: MXYAU
Crossref ID: 2016000368538
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:42:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2018000111646
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:00:00
Record Updated: 2018-07-06 11:00:00
Updated By: MXYAU
Crossref ID: 2018000088966
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:01:00
Record Updated: 2018-07-06 11:01:00
Updated By: MXYAU
Crossref ID: 2017000436670
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:40:00
Record Updated: 2017-11-29 16:42:00
Updated By: MXYAU
Crossref ID: 2014000220216
Cross Ref Type Code: 25

PFIZER SITES B AND D (Continued) **S106906497**

Cross Ref Type: County Recording Identifier
Record Added Date: 2018-07-06 11:02:00
Record Updated: 2018-07-06 11:02:00
Updated By: MXYAU
Crossref ID: 2016000368537
Cross Ref Type Code:
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-29 16:43:00
Record Updated: 2017-11-29 16:43:00
Updated By: MXYAU
Crossref ID: 00-TEMP-02-59(I
Cross Ref Type Code:
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

VCP:
Name: PFIZER SITES B AND D
Address: 59-71 GERRY ST. AND 73-87 GERRY ST.
City,State,Zip: BROOKLYN, NY 11206
Program Type: VCP
Site Code: 58206
HW Code: V00350
Site Class: C
SWIS: 2401
Region: 2
Town: New York City
Acres: 1.47
Date Record Added: 11/30/2000
Date Record Updated: 09/26/2018
Updated By: JHOCONNE
Site Description: Location: The site is comprised of several properties in the southeast Williamsburg neighborhood of Brooklyn, located at the following addresses: 191 Harrison Avenue and 60-66 Gerry Street (Block 2269, Lot 1) defined as OU-1; 59-71 Gerry Street (aka 177 Harrison Avenue) (Block 2266, part of Lot 1 and Lot 52) defined as Operable Unit 2 (OU-2); and 73-87 Gerry Street (Block 2266, Lots 45-50) defined as OU-3. It should be noted that any references herein to Pfizer Site B and Pfizer Site D are names historically designated by Pfizer Inc. for their properties and do not refer to Department-designated sites or operable units. Site Features: The total size of the site is 1.47 acres. The OU-1 property at 191 Harrison Avenue and 60-66 Gerry Street is currently vacant and paved. OU-1 is surrounded on three sides by a condemned and vacant apartment building which is not part of the site. The OU-2 property at 59-71 Gerry Street is currently occupied by a high school for girls (Bais Ruchel High School) and a paved area adjacent to the school building. The ou-3 property at 73-87 Gerry Street is occupied by 3 newly-constructed family houses and paved areas. Current Zoning and Land Use: The site is located in a commercial district overlay within a residential zoning district. Some portions of the property are currently vacant and paved; however, a part of OU-2 is occupied by a high school for girls and 3 newly-constructed family houses occupy a portion of OU-3. Past Use of the Site: Pfizer leased what is now OU-2 (59-71 Gerry Street) from the previous owner from 1954 to 2004; aside from occasional use as a parking lot, it was vacant from the 1950s

PFIZER SITES B AND D (Continued) **S106906497**

until remediation and redevelopment began in 2011. OU-3 (73-87 Gerry St.) was purchased by Pfizer in 1964 and was used as a warehouse for the storage of raw materials/dry goods, spare equipment parts, and packaging materials. Prior to Pfizer s ownership, it was used as a garage and truck rental facility. OU-1 (60-66 Gerry Street) was formerly leased from Pfizer by Arlington Press, a company that specializes in labels and package inserts for the pharmaceutical industry. It is also believed that a tetrachloroethylene (PCE) reclamation facility operated at 66 Gerry Street circa 1955, prior to Pfizer ownership, based on a building permit document from that time. Soil removal activities were performed on OU-3 in 2002 (prior to the site entering the VCP), and included the excavation of 9 Underground Storage Tanks (USTs), 2 tank-like structures, and removal of 4,735 tons of petroleum VOC-impacted soil and 18,449 gallons of groundwater (including perched groundwater). The excavation was then backfilled with clean material. Operable Units: The site consists of three Operable Units due to separate ownership and timing of development schedules for different parcels. An operable unit represents a portion of a remedial program for a site, which for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release, or exposure pathway resulting from the site contamination. The property at 191 Harrison Avenue and 60-66 Gerry Street, located on the southeast corner of Gerry Street and Harrison Avenue, (known as Pfizer Site D) is Operable Unit 1 (OU-1). The property at 59-71 Gerry Street (aka 177 Harrison Ave.) or the western portion of Pfizer Site B is OU-2. The property located at 73-87 Gerry Street, which is the eastern portion of Pfizer Site B, is OU-3. Site Geology and Hydrogeology: The site is underlain by a layer of fill material approximately 8 to 10 feet thick. Beneath the fill layer is a green clay/silt stratum of approximately 2 to 3 feet thick, followed by a brown fine to medium sand stratum with small amounts of clay and silt of approximately 15 feet. Beneath the sand is a silt/clay layer which has been identified as a confining layer. Groundwater is approximately 6 to 10 feet below surface grade. Groundwater flow direction is generally to the north, with some radial flow to the northwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), specifically tetrachloroethene (PCE) and its degradation products, in soil and groundwater on OU1, metals and semi-volatile organic compounds (SVOCs) in soil across the entire site. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Completion of Remediation Contamination is described separately for each of the Operable Units (OUs). For a description of the OUs, please refer to the Site Description. Nature and Extent of Contamination - OU-1: The primary contaminants of concern in all media on OU-1 were chlorinated VOCs. Soil - Chlorinated VOCs were detected in soil at elevated levels in a discrete area beneath the eastern portion of OU-1, primarily 8 to 15 feet below grade (fbg). PCE was detected in 4 soil borings at a maximum concentration of 280 parts per million (ppm), compared to the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.3 ppm. Trichloroethene (TCE) was detected in 3 soil borings at a maximum concentration of 4.2 ppm, compared to the PGWSCO of 0.47 ppm. Cis-1,2-dichloroethene (DCE) was detected in 5 borings at a maximum concentration of 120 ppm, compared

PFIZER SITES B AND D (Continued) **S106906497**

to the PGWSCO of 0.25 ppm. Vinyl chloride was detected in 4 borings at a maximum of 1.2 ppm, compared to the PGWSCO of 0.02 ppm. Some metals and SVOCs were detected in soil above the Restricted-Residential use SCOs, but were not considered contaminants of concern. Groundwater - The same chlorinated VOCs that were present in soil were also present at elevated concentrations in the groundwater beneath OU-1, in similar locations as the contaminated soil. The highest concentrations were present in the 9-19 fbg depth range, with contaminants detected at lesser concentrations in deeper intervals. During recent groundwater monitoring in April 2018, PCE and TCE were non-detect; cis-DCE as high as 1,700 parts per billion (ppb); and vinyl chloride as high as 7,800 ppb. The applicable groundwater standard for these contaminants is 5 ppb for PCE, TCE, and cis-DCE and 2 ppb for vinyl chloride. Soil vapor - Chlorinated VOCs were present in soil vapor at elevated concentrations throughout OU-1. Near the source of contamination beneath the paved courtyard, PCE was detected in soil vapor at 37,000 micrograms per cubic meter (g/m3); TCE was detected at 4,700 g/m3; and cis-DCE at 1,500 g/m3. These contaminants were also present in soil vapor samples closer to the site boundaries, but at much lesser concentrations which were seen to decrease with increasing distance from the contaminated soil and groundwater. In off-site samples, PCE was detected as high as 430 g/m3 at the vacant, unpaved lot to the east of the site; 38 g/m3 in the sidewalk to the south of the site (the northeastern sidewalk of Bartlett Street); and 76 g/m3 in the sidewalk to the southwest of the site (beneath the northeastern sidewalk of Harrison Avenue). No significant impacts were observed outside of the high school across Harrison Ave. ? Nature and Extent of Contamination - OU-2: The primary contaminants of concern on OU-2 were SVOCs and metals related to urban fill in the soil, and chlorinated VOCs in the groundwater and soil vapor which have been determined to originate from OU-1. Soil - Prior to remediation, soil on OU-2 contained metals and SVOCs indicative of urban fill to depths of approximately 10 feet below grade. Metals that exceeded applicable soil cleanup objectives (SCOs) included lead as high as 6,730 ppm; mercury as high as 16.1 ppm; arsenic as high as 20.5 ppm; chromium as high as 33.6 ppm; and barium as high as 2,000 ppm. SVOCs include benzo(a)anthracene as high as 250 ppm; chrysene as high as 270 ppm; benzo(a)pyrene as high as 220 ppm; indeno(1,2,3-cd)pyrene as high as 110 ppm; and dibenz(a,h)anthracene as high as 58 ppm. As part of the remediation of this OU, soil was excavated from contaminated hot-spots. Groundwater - During the most recent groundwater sampling event in March 2018, limited VOCs were detected in groundwater on the sidewalk adjacent to Lot 52. Cis-1,2-DCE was detected at 210 ppb and vinyl chloride was detected at 75 ppb; these chlorinated solvents can be attributed to contamination at OU-1. Soil vapor - Chlorinated solvents have been detected in soil vapor. Prior to remediation, PCE was detected in soil vapor at 659 g/m3 and TCE was detected at 19 g/m3. A sub-slab depressurization system and vapor barrier were installed in the high school building as part of the remediation and redevelopment. Nature and Extent of Contamination - OU-3: The primary contaminants of concern on OU-3 were chlorinated VOCs in groundwater and soil vapor, and SVOCs and metals related to historic fill in the soil. Soil - VOCs in soil at OU-3 were addressed under previous remedial actions. Soil removal activities were performed in 2002, prior to entry in the Department s VCP. Some SVOCs and metals are still present in shallow soil (0 to 2 fbg) on OU-3, in areas that were not previously

PFIZER SITES B AND D (Continued) **S106906497**

excavated. Metals included lead as high as 2,020 ppm; mercury as high as 61.4 ppm; arsenic as high as 307 ppm; barium as high as 1,250 ppm; and chromium as high as 75.7 ppm. SVOCs included benzo(a)anthracene as high as 75 ppm; chrysene as high as 87 ppm; benzo(a)pyrene as high as 59 ppm; indeno(1,2,3-cd)pyrene as high as 43 ppm; and dibenz(a,h)anthracene as high as 25 ppm. These contaminants exceeded their respective soil cleanup objectives for Restricted Residential use. Site-related soil contamination did not extend off-site based on the available data. Groundwater - In 2006, an air sparge/soil vapor extraction (AS/SVE) system was installed to address groundwater contamination remaining at the site following the soil and tank excavations. The system was operated from October 2006 to February 2011. Quarterly groundwater monitoring performed during that time period indicated that the system was effective at treating petroleum-related VOCs in groundwater. The primary contaminants of concern that remained in groundwater following operation of the AS/SVE system were chlorinated VOCs, which were present in the northeast corner of the site. During the most recent groundwater monitoring in March 2018, PCE was detected at 16 ppb; TCE at 26 ppb; cis-DCE at 840 ppb; and vinyl chloride at 26 ppb. It has been determined that these contaminants in groundwater at OU-3 are originating at OU-1. There is no off-site migration of contaminated groundwater that originates from OU-3 specifically. Contaminated groundwater emanating from OU-1 migrates toward OU-3 and further downgradient of OU-3. Soil vapor Recent soil vapor data is limited regarding overall site coverage. Two soil vapor sampling points in the northwestern portion of OU-3 were monitored quarterly from August 2010 through February 2012. During the last sampling event from these locations, PCE was detected at 19 g/m3 with other VOCs at lower concentrations. Directly across the street from and upgradient of the site (beneath the southwestern sidewalk of Gerry Street, just outside the boundary of OU-1), PCE was detected in soil vapor at 76,000 g/m3. A sub-slab depressurization system and vapor barrier were installed in new buildings as part of the remediation and redevelopment.

Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-06-27 16:53:00
Record Upd:	2013-09-20 14:18:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Barbara Wong
Owner Company:	Pfizer, Inc.
Owner Address:	100 Route 206N, M/S 401
Owner Addr2:	M/S 401
Owner City,St,Zip:	Peapack, NJ 07977
Owner Country:	United States of America

PFIZER SITES B AND D (Continued) **S106906497**

Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	47-40 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Not reported
Owner Company:	Congregation Divrei Yoel
Owner Address:	144 Spencer Street, #612
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	Williamsburg Branch
Owner Addr2:	240 Division Avenue
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Oholei Shloma
Owner Address:	517 Flushing Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Sol Moskovits
Owner Company:	YGS, Inc. f/k/a Congregation YGS
Owner Address:	174 Rodney Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Juda Klein
Owner Company:	58 Gerry Street, LLC
Owner Address:	236 Broadway
Owner Addr2:	2nd Floor
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner

PFIZER SITES B AND D (Continued) **S106906497**

Sub Type:	A
Owner Name:	Not reported
Owner Company:	Berish Ekstein and Joseph Jacob
Owner Address:	85 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Wolf Englender
Owner Company:	Bais Ruchel High School, Inc.
Owner Address:	82 Lee Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Yoel Kaufman
Owner Address:	81 Gerry Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Benjamin Perlstein
Owner Address:	94 Skillman Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Simon Strulovic
Owner Address:	150 Heyward Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	V00350
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)ANTHRACENE

PFIZER SITES B AND D (Continued) **S106906497**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,2-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: 1,1,2,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00350
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN

PFIZER SITES B AND D (Continued) **S106906497**

Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00350
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224101
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2016-09-14 10:26:00
Record Updated:	2016-09-14 10:26:00
Updated By:	IXMUNTEA
Crossref ID:	2-612842
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2018-01-26 17:41:00
Record Updated:	2018-01-26 17:41:00
Updated By:	JAAVERSA
Crossref ID:	D2-0010-0703
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-07-26 14:24:00
Record Updated:	2018-07-26 14:24:00
Updated By:	MXYAU
Crossref ID:	2016000368538
Cross Ref Type Code:	25

PFIZER SITES B AND D (Continued) **S106906497**

Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:42:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2018000111646
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:00:00
Record Updated:	2018-07-06 11:00:00
Updated By:	MXYAU
Crossref ID:	2018000088966
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:01:00
Record Updated:	2018-07-06 11:01:00
Updated By:	MXYAU
Crossref ID:	2017000436670
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:40:00
Record Updated:	2017-11-29 16:42:00
Updated By:	MXYAU
Crossref ID:	2014000220216
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-07-06 11:02:00
Record Updated:	2018-07-06 11:02:00
Updated By:	MXYAU
Crossref ID:	2016000368537
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-29 16:43:00
Record Updated:	2017-11-29 16:43:00
Updated By:	MXYAU
Crossref ID:	00-TEMP-02-59(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

B98 **SITE B PFIZER** **NY BROWNFIELDS** **S121933747**
WSW **59-71 GERRY STREET AND 73-87 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.057 mi.
300 ft. **Site 33 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

BROWNFIELDS:

Name:	SITE B PFIZER
Address:	59-71 GERRY STREET AND 73-87 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Program:	BCP
Site Code:	333571
Acres:	0.8
HW Code:	C224101
SWIS:	2401
Town:	New York City
Record Added Date:	11/10/2004

SITE B PFIZER (Continued) **S121933747**

Record Updated Date:	02/15/2007
Update By:	KXCarpen
Site Description:	Site B is located in the eastern portion of the Pfizer facility and is bordered on the north by a poultry market and vacant land, a three-story apartment building, and an auto body garage and yard; on the south by Gerry St.; on the east by a portion of the auto body garage and yard, and a storage lot; and on the west by Harrison Ave.. Building demolishing in 1996 has left a reinforced concrete slab across half of the eastern portion of site B. The western portion of site B is covered with gravel and is being used as a parking lot. The site is being investigated and remediated under VP Agreement ? see site no. V00350.
Env Problem:	Based upon preliminary investigations, Pfizer completed on-site and off-site delineation of petroleum related impacts in the fill material and conducted an Interim Remedial Measure (IRM) in December 2002. IRM included removal the removal of 4,735 tons of petroleum related impacted soils and more than 18,000 gallons of groundwater (including perched groundwater). In addition, nine UST?s and other subsurface structures were removed and properly disposed off-Site. Investigations indicate a plume of groundwater contamination that extends north to the property border. Soil gas investigation is on-going.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	PFIZER, INC.
Owner Address:	235 EAST 42ND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10017
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	JOHN KEITH
Owner Company:	PFIZER INC.
Owner Address:	235 EAST 42ND STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10017
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported

SITE B PFIZER (Continued) **S121933747**

Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

C99 **ROADWAY** **NY Spills** **S109060663**
SE **THROUGHP AVE/WHIPPLE** **N/A**
< 1/8 **BROOKLYNN, NY**
0.057 mi.
302 ft. **Site 7 of 16 in cluster C**

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name:	ROADWAY
Address:	THROUGHP AVE/WHIPPLE
City,State,Zip:	BROOKLYNN, NY
Spill Number/Closed Date:	0713265 / 2008-03-17
Facility ID:	0713265
Facility Type:	ER
DER Facility ID:	344535
Site ID:	394991
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2008-03-14
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2008-03-14
CID:	81
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-15
Spill Record Last Update:	2008-03-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CATHY PERKINS
DEC Memo:	"Small roadway spill. closed."
Remarks:	"Has been cleaned up from roadway. May have entered sewer."

All Materials:

Site ID:	394991
Operable Unit ID:	1151938
Operable Unit:	01
Material ID:	2142705
Material Code:	1511A
Material Name:	power steering fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00

ROADWAY (Continued) **S109060663**

Units: G
Recovered: .00
Oxygenate: Not reported

D100 **WALLABOUT STREET AND** **NY Spills** **S103936442**
NNW **THROOP AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.057 mi.
302 ft. **Site 3 of 19 in cluster D**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:

Name:	WALLABOUT STREET AND
Address:	THROOP AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9900765 / 1999-06-22
Facility ID:	9900765
Facility Type:	ER
DER Facility ID:	212652
Site ID:	260055
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	D3
SWIS:	2401
Spill Date:	1999-04-20
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	1999-04-20
CID:	282
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-20
Spill Record Last Update:	1999-10-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MR JOHN DIELE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN "
Remarks:	"dep got a call from the nyc sanatation that there were abandoned drums one was 55 gallon(waste oil in it (not spilled) and there was a 15 gallon drum of containg axle grease(not spilled) ****6/22/99 NO DRUMS FOUND *****"

All Materials:

Site ID:	260055
Operable Unit ID:	1079528
Operable Unit:	01
Material ID:	307887
Material Code:	0022

WALLABOUT STREET AND (Continued) **S103936442**

Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D101 **CON EDISON - TRANSFORMER MANHOLE 198** **RCRA-LQG 1016967054**
NNW **WALLABOUT ST C 32W THROOP AVE** **NY MANIFEST NYP004399176**
< 1/8 **BROOKLYN, NY 11206**
0.057 mi.
303 ft. **Site 4 of 19 in cluster D**

Relative:
Lower

Actual:
13 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - TRANSFORMER MANHOLE 198
Facility address:	WALLABOUT ST C 32W THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004399176
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	12/03/2013
Owner/Op end date:	Not reported

CON EDISON - TRANSFORMER MANHOLE 198 (Continued) **1016967054**

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/03/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/03/2013
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 12/03/2013
Site name: CON EDISON
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: WALLABOUT ST & THROOP AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004399176
Facility Status: Not reported
Location Address 1: WALLABOUT ST & THROOP AVE
Code: BP
Location Address 2: TM 198

CON EDISON - TRANSFORMER MANHOLE 198 (Continued) **1016967054**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004399176
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/2013
Trans1 Recv Date:	12/03/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004399176
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299265GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	G - Gallons (liquids only)* (8.3 pounds)

CON EDISON - TRANSFORMER MANHOLE 198 (Continued) **1016967054**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

G102 **COMMERCIAL LOT** **NY Spills** **S109061916**
NE **650 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.059 mi.
309 ft. **Site 1 of 5 in cluster G**

Relative: **Higher**
Actual: **14 ft.**

SPILLS:

Name:	SERVICE BOX 15648
Address:	650 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0000431 / 2002-01-17
Facility ID:	0000431
Facility Type:	ER
DER Facility ID:	119367
Site ID:	139733
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-04-11
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-04-11
CID:	205
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-11
Spill Record Last Update:	2002-01-23
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #130848 Notes: 4-11-00 1000hrs 6gal pure oil in SB 15648. Cleanup pending sample results. 4-12-00 0155hrs LSN

COMMERCIAL LOT (Continued) **S109061916**

00-03517 <1ppm PCB 4-25-00 1520hrs Cleanup completed. Double washed with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump."

Remarks: "CALLER FOUND 6 GALLONS ON LAND IN SERVICE BOX. CON ED # 130848."

All Materials:

Site ID:	139733
Operable Unit ID:	822125
Operable Unit:	01
Material ID:	288680
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERCIAL LOT
Address:	650 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0800660 / 2016-02-19
Facility ID:	0800660
Facility Type:	ER
DER Facility ID:	119367
Site ID:	396451
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-04-15
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2008-04-16
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-16
Spill Record Last Update:	2016-02-19
Spiller Name:	KEITH WILLIAMS
Spiller Company:	Not reported
Spiller Address:	650 BROADWAY
Spiller Company:	001
Contact Name:	KEITH WILLIAMS
DEC Memo:	"Patel responded to the site of a junk yard. 04/18/08-Hiralkumar Patel. visited site on 04/16/08. met Joe Ehrenfeld at junk yard. during site visit found multiple spots of contaminated soil and some puddles of oil under junk. found oil going into onsite drains. as per Joe, all drains at the site are not connected to city sewer. found

COMMERCIAL LOT (Continued) **S109061916**

speedy dry around aboveground waste oil tanks. Joe mentioned that oil overfilled and spilled on concrete surface. typical junk yard site. asked Joe to clean areas. Joe mentioned that property has been sold and new owner is planning to build residential complex. Joe mentioned that new owner has did some sampling at the site. as per Joe, property sold to White Gloves, who are located next to the subject site. subject site has two 275 gal ASTs. no PBS record found. less than --------- Lee Avenue Garage Inc. Iser Ehrenfeld **owner of 650 Broadway** Joe Ehrenfeld 650 Broadway Brooklyn, NY Ph. (718) 388-6470 email: leeavgrage@aol.com alternate addresses for 650 Broadway: 89-95 Bartlett St 654-660 Broadway 648 Broadway from city records, owner of subject site is M&G Housing Corp. and city record shows that property has been included in a tax lien sale. less than -------- met Erry Frankel at White Glove. she doesn't know about any contract or transaction for next door property. she will ask someone in upper management and will call back. White Gloves 85 Bartlett Street Brooklyn, NY Attn.: Etty Frankel Ph. (718) 387-8181 Ext. 109 during conversation, Joe mentiond that site at 646 Broadway was also his property in past and they sold it. currently site 646 Broadway is under construction. M&G Housing Corp. **owner of 646 Broadway** 26 Rutledge Street Brooklyn, NY contractor for 646 Broadway: Delux builders Ph. (718) 625-6476 result of site visit: - no PBS record found for two 275 gal waste oil AST at 650 Broadway - from city record search found that 646 Broadway (which is currently under construction) and 650 Broadway (where Junk yard is located) both properties are owned by M&G Housing Corp. - as per Joe, new owner will develop residential complex actions required: - registration of waste oil tanks at 650 Broadway - soil investigation/remediation at 650 Broadway need to send letter for after confirming current owner and potential buyer of the suject site. may requires report review for any investigation at 646 Broadway, as it was part of junk yard and now under development. see pics on e-docs. 4/25/08- CSL sent to Iser Ehrenfeld 12/06/11- DECP iper received and reviewed phase II from charles sosik of EBC . A total of 10 soil borings (B1- B10) were advanced on June 24, 2011. Soil sample results were compared to the Unrestricted Use and Restricted Residential Use Soil Cleanup Objectives (SCOs) as presented in NYSDEC CP51 Soil Cleanup Guidance (10/21/10). Analytical data for the soil samples are summarized in Tables 1 and 2, and a copy of the laboratory analytical report is included in Appendix B. As presented in Tables 1 and 2, there were no VOCs reported above unrestricted use SCOs in any of the sample locations. Two SVOC parameters were reported above unrestricted SCOs and four were reported above restricted residential SCOs in the 5-10 foot interval of boring B8. There were no other SVOC parameters reported at elevated levels in the remaining samples. Groundwater sample results were compared to the water quality standards specified in NYSDEC Groundwater Quality Standards (GQSs). Analytical data for the groundwater samples are summarized in Tables 3 and 4 and a copy of the laboratory analytical report is included in Appendix B. VOCs were reported above standards at a single location (B6) with MTBE at a concentration of 15 ug/L (standard = 10 ug/L) and toluene at a concentration of 40 ug/L (standard = 5 ug/L). SVOCs were also reported above standards in a single location (B7), with chrysene at a concentration of 5.9 ug/L and a J qualifier (standard = 0.002 or MDL). Although much of the surface of the site is heavily stained from historic use as a truck repair facility there were no VOC parameters reported above unrestricted SCOs in the soil samples.

COMMERCIAL LOT (Continued) **S109061916**

Based on the parameters detected and the concentrations reported, the SVOCs reported above unrestricted and restricted residential SCOs in the B8 location were related to historic fill materials and not petroleum from the historic use of the property.EBC recommends scraping off the top several inches of soil above the asphalt/concrete cap and properly disposing of this material off-site. 2/18/16- DEC Piper reviewed case. Based on previous inspections and phase II received, no further action is warranted regarding the remaining contaminants. Low level gw contamination will be remediated through natural attenuation. The property is currently vacant as of Sep 2014. Spill closed. "

Remarks: "DUMPING OIL ABOUT 250 GALLONS LOOKING FOR DEC TO REPORT"

All Materials:

Site ID:	396451
Operable Unit ID:	1153420
Operable Unit:	01
Material ID:	2144175
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	250.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B103 **LOT 16,TAXBLOCK 2266** **NY E DESIGNATION** **S110242353**
WNW **380 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.059 mi.
313 ft. **Site 34 of 48 in cluster B**

Relative: Higher
Actual: 14 ft.

E DESIGNATION:

Name:	LOT 16,TAXBLOCK 2266
Address:	380 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	16
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation

LOT 16,TAXBLOCK 2266 (Continued) **S110242353**

Lot Remediation Date: Not reported

D104 **CON EDISON** **NY MANIFEST** **S121967134**
North **622 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11249**
0.060 mi.
315 ft. **Site 5 of 19 in cluster D**

Relative: **Lower**

Actual: **13 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	622 BROADWAY
City,State,Zip:	BROOKLYN, NY 11249
Country:	USA
EPA ID:	NYP004512307
Facility Status:	Not reported
Location Address 1:	FRONT OF 622 BROADWAY
Code:	BP
Location Address 2:	SB15638
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004512307
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/25/2014
Trans1 Recv Date:	04/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004512307
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002418216GBF
Import Indicator:	N
Export Indicator:	N

CON EDISON (Continued) **S121967134**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D105 **CON EDISON SERVICE BOX: 15638** **RCRA NonGen / NLR** **1017773448**
North **622 BROADWAY** **FINDS** **NYP004512307**
< 1/8 **BROOKLYN, NY 11249**
0.060 mi.
315 ft. **Site 6 of 19 in cluster D**

Relative: **Lower**

Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/25/2014
Facility name:	CON EDISON SERVICE BOX: 15638
Facility address:	622 BROADWAY BROOKLYN, NY 11249
EPA ID:	NYP004512307
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON SERVICE BOX: 15638 (Continued) **1017773448**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/25/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 04/25/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063777685

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

D106 **CON EDISON** **NY MANIFEST** **S117063540**
North **622 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11249**
0.060 mi.
315 ft. **Site 7 of 19 in cluster D**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 622 BROADWAY
City,State,Zip: BROOKLYN, NY 11249
Country: USA
EPA ID: NYP004559654
Facility Status: Not reported
Location Address 1: FO 662 BROADWAY
Code: BP

CON EDISON (Continued) **S117063540**

Location Address 2:	SB 15638
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11221
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004559654
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/10/2014
Trans1 Recv Date:	06/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004559654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002424483GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50

CON EDISON (Continued) **S117063540**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D107 **CON EDISON** **NY MANIFEST** **S121967243**
North **FRONT OF 622 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.060 mi.
315 ft. **Site 8 of 19 in cluster D**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 622 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004689915
Facility Status:	Not reported
Location Address 1:	FRONT OF 622 BROADWAY
Code:	BP
Location Address 2:	SB15638
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004689915
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S121967243**

Generator Ship Date:	11/04/2014
Trans1 Recv Date:	11/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004689915
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416903GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D108 **CON EDISON SERVICE BOX: 15638** **RCRA NonGen / NLR** **1017778050**
North **622 BROADWAY** **NYP004559654**
< 1/8 **BROOKLYN, NY 11249**
0.060 mi.
315 ft. **Site 9 of 19 in cluster D**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	07/10/2014
Facility name:	CON EDISON SERVICE BOX: 15638
Facility address:	622 BROADWAY BROOKLYN, NY 11249
EPA ID:	NYP004559654

Actual:
13 ft.

CON EDISON SERVICE BOX: 15638 (Continued) **1017778050**

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/10/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 06/10/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

C109 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S106703168**
ESE **113 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.060 mi.
315 ft. **Site 8 of 16 in cluster C**

Relative: Higher
Actual: 16 ft.

LTANKS:
Name: CLOSED-LACKOF RECENT INFO
Address: 113 THROOP AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8707623 / 2003-03-04
Facility ID: 8707623
Site ID: 102990
Spill Date: 1987-12-05
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported

CLOSED-LACKOF RECENT INFO (Continued) **S106703168**

SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1987-12-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-12-07
Spill Record Last Update:	2003-03-14
Spiller Name:	Not reported
Spiller Company:	ALL SAINTS SCHOOL
Spiller Address:	113 THROOP AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	91146
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED / / : Action Unknown. 03/04/2003-Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"2.5K TANK FAILED WITH A LEAK RATE OF -.402G/HR. CONTACT: SISTER DONNA MURPHY (718) 782-0569. 8/5/88 : L R =-0.14 GPH, 2.5K TANK FAILED RE-TEST,PETRO-TITE TANK ONLY.CLOSED DUE TO LACK OF ANY RECENT INFO-DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID:	8707623
Spill Number:	8707623
Spill Tank Test:	1532544
Site ID:	102990
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	102990
Operable Unit ID:	911963
Operable Unit:	01
Material ID:	466561
Material Code:	0001A
Material Name:	#2 fuel oil

CLOSED-LACKOF RECENT INFO (Continued) **S106703168**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

D110 **CON EDISON** **NY MANIFEST** **S117740630**
NE **648 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.060 mi.
316 ft. **Site 10 of 19 in cluster D**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	648 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004738043
Facility Status:	Not reported
Location Address 1:	648 BROADWAY
Code:	BP
Location Address 2:	M15648
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738043
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2015
Trans1 Recv Date:	02/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738043
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117740630**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610897GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D111 **CON EDISON** **RCRA NonGen / NLR** **1018279013**
NE **648 BROADWAY** **FINDS** **NYP004738043**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.060 mi.
316 ft. **Site 11 of 19 in cluster D**

Relative: RCRA NonGen / NLR:
Higher

Date form received by agency:	02/25/2015
Facility name:	CON EDISON
Facility address:	648 BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004738043
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

Actual:
14 ft.

CON EDISON (Continued) **1018279013**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/25/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067685160

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018279013
Registry ID: 110067685160
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067685160

D112 **CON EDISON** **NJ MANIFEST** **S120667860**
NE **648 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.060 mi.
316 ft. **Site 12 of 19 in cluster D**

Relative:
Higher

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004738043
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610897GBF
EPA ID:	NYP004738043
Date Shipped:	2/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667860**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B113 **PFIZER INC. SITE BAND D** **NY UST** **U004277386**
WSW **60-66 GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.060 mi.
317 ft. **Site 35 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

UST:

Name:	PFIZER INC. SITE BAND D
Address:	60-66 GERRY STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-612842 / Unregistered
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Other

Affiliation Records:

Site Id:	566007
Affiliation Type:	Facility Owner
Company Name:	58 GERRY STREET LLC
Contact Type:	AUTHORIZED SIGNER
Contact Name:	JUDA KLEIN
Address1:	236 BROADWAY 2ND FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 360-8043
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-01-18

Site Id:	566007
Affiliation Type:	Mail Contact
Company Name:	GZA GEO ENVIRONMENTAL, INC.
Contact Type:	Not reported
Contact Name:	MELISSA DULINSKI/DAVID WINSLOW
Address1:	55 LANE ROAD
Address2:	SUITE 407
City:	FAIRFIELD
State:	NJ
Zip Code:	07004
Country Code:	001
Phone:	(973) 774-3300
EMail:	MELISSA.DULINSKI@GZA.COM

PFIZER INC. SITE BAND D (Continued) **U004277386**

Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-01-18

Site Id:	566007
Affiliation Type:	Emergency Contact
Company Name:	58 GERRY STREET LLC
Contact Type:	Not reported
Contact Name:	JUDA KLEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 360-8043
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-01-18

Tank Info:

Tank Number:	1
Tank ID:	274822
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/03/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MRBARROW
Last Modified:	01/18/2018

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	2
Tank ID:	274823
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/03/2018
Registered:	True

PFIZER INC. SITE BAND D (Continued) **U004277386**

Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 01/18/2018

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 3
Tank ID: 274824
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/03/2018
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 01/18/2018

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground

B114 **ARLINGTON PRESS-191 HARRISON AVE** **RCRA-LQG** **1000257521**
WSW **191 HARRISON AVE** **FINDS** **NYD001513779**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.060 mi.
317 ft. **Site 36 of 48 in cluster B**

Relative:
Higher

Actual:
14 ft.

RCRA-LQG:
Date form received by agency: 03/01/2016
Facility name: PFIZER INC
Facility address: 60 GERRY STREET
BROOKLYN, NY 11206
EPA ID: NYD001513779
Mailing address: ROUTE 206N (M/S 401)
PEAPACK, NJ 07977
Contact: BARBARA WONG
Contact address: ROUTE 206N (M/S 401)

ARLINGTON PRESS-191 HARRISON AVE (Continued) **1000257521**

PEAPACK, NJ 07977
Contact country: US
Contact telephone: 917-375-2319
Contact email: BARBARA.WONG@PFIZER.COM
EPA Region: 02
Land type: Private
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: PFIZER INC
Owner/operator address: EAST 42ND STREET (M/S 219/8/2)
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: 212-733-2323
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1955
Owner/Op end date: Not reported

Owner/operator name: PFIZER INC
Owner/operator address: EAST 42ND ST
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1955
Owner/Op end date: Not reported

Owner/operator name: ARLINGTON PRESS INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: Not reported
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner

ARLINGTON PRESS-191 HARRISON AVE (Continued) **1000257521**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2007
Site name: ARLINGTON PRESS
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: ARLINGTON PRESS
Classification: Small Quantity Generator

Date form received by agency: 05/02/1989
Site name: ARLINGTON PRESS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS

ARLINGTON PRESS-191 HARRISON AVE (Continued) **1000257521**

CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Amount (Lbs): 781925.8

Waste code: U210
Waste name: ETHENE, TETRACHLORO-
Amount (Lbs): 449000

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/13/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 12/21/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110070148724

Environmental Interest/Information System
HAZARDOUS WASTE BIENNIAL REPORTER

Registry ID: 110004335112

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that

ARLINGTON PRESS-191 HARRISON AVE (Continued) **1000257521**

discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000257521
Registry ID:	110004335112
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004335112

F115 **LOT 46,TAXBLOCK 2272** **NY E DESIGNATION** **S110242424**
South **9 WHIPPLE STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.060 mi.
318 ft. **Site 3 of 19 in cluster F**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 46,TAXBLOCK 2272
Address:	9 WHIPPLE STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	46
Tax Block:	2272
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

E116 **LOT 6,TAXBLOCK 2272** **NY E DESIGNATION** **S110242445**
SSW **24 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.062 mi.
326 ft. **Site 8 of 19 in cluster E**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 6,TAXBLOCK 2272
Address:	24 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	6
Tax Block:	2272
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

C117 **ALL SAINTS R C CHURCH** **NY UST** **U000405431**
ESE **115 THROOP AVE** **NY AST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.062 mi.
328 ft. **Site 9 of 16 in cluster C**

Relative:
Higher

Actual:
16 ft.

UST:

Name:	ALL SAINTS R C CHURCH
Address:	115 THROOP AVE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-364673 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/07/2018
UTM X:	589180.91891
UTM Y:	4506045.62278
Site Type:	School

Affiliation Records:

Site Id:	18493
Affiliation Type:	Facility Owner
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	PASTOR
Contact Name:	WILLIAM CHACON
Address1:	115 THROOP AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206

ALL SAINTS R C CHURCH (Continued) **U000405431**

Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-03-21

Site Id:	18493
Affiliation Type:	Mail Contact
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	115 THROOP AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18493
Affiliation Type:	Facility Operator
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	Not reported
Contact Name:	ALL SAINTS R C CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18493
Affiliation Type:	Emergency Contact
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	Not reported
Contact Name:	ALL SAINTS R C CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

ALL SAINTS R C CHURCH (Continued) **U000405431**

Tank Info:

Tank Number:	001
Tank ID:	22628
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2800
Install Date:	06/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	01
Date Test:	09/01/1988
Next Test Date:	10/11/2016
Pipe Model:	Not reported
Modified By:	MRBARROW
Last Modified:	04/14/2017

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Number:	004
Tank ID:	22631
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	03/01/1985
Date Tank Closed:	09/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	01/01/1998
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

ALL SAINTS R C CHURCH (Continued) **U000405431**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G07 - Tank Secondary Containment - Excavation Liner
J02 - Dispenser - Suction Dispenser

AST:

Name:	ALL SAINTS R C CHURCH
Address:	115 THROOP AVE
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-364673
Program Type:	PBS
UTM X:	589180.91891
UTM Y:	4506045.62278
Expiration Date:	01/07/2018
Site Type:	School

Affiliation Records:

Site Id:	18493
Affiliation Type:	Facility Owner
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	PASTOR
Contact Name:	WILLIAM CHACON
Address1:	115 THROOP AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-03-21

Site Id:	18493
Affiliation Type:	Mail Contact
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	115 THROOP AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

ALL SAINTS R C CHURCH (Continued) **U000405431**

Site Id:	18493
Affiliation Type:	Facility Operator
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	Not reported
Contact Name:	ALL SAINTS R C CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18493
Affiliation Type:	Emergency Contact
Company Name:	ALL SAINTS R C CHURCH
Contact Type:	Not reported
Contact Name:	ALL SAINTS R C CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	002
Tank Id:	22629
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported

ALL SAINTS R C CHURCH (Continued) **U000405431**

Install Date:	01/01/1956
Capacity Gallons:	1080
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	003
Tank Id:	22630
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	01/01/1985
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

D118 **SOSA DIAGNOSTIC REPAIR INC.** **NY AST** **A100304674**
North **620 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.062 mi.
329 ft. **Site 13 of 19 in cluster D**

Relative: AST:
Lower

Actual:
13 ft.

Name:	SOSA DIAGNOSTIC REPAIR INC.
Address:	620 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610529

SOSA DIAGNOSTIC REPAIR INC. (Continued) **A100304674**

Program Type: PBS
UTM X: 589019.78137
UTM Y: 4506324.61052
Expiration Date: 04/04/2022
Site Type: Other

Affiliation Records:

Site Id: 379408
Affiliation Type: Facility Owner
Company Name: FIDEL SOSA
Contact Type: OWNER
Contact Name: FIDEL SOSA
Address1: 91-50 114TH STREET
Address2: Not reported
City: RICHMOND HILL
State: NY
Zip Code: 11418
Country Code: 001
Phone: (718) 846-3878
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-07-18

Site Id: 379408
Affiliation Type: Mail Contact
Company Name: SOSA DIAGNOSTIC REPAIR INC.
Contact Type: Not reported
Contact Name: WILLIAM SOSA
Address1: 91-50 114TH STREET
Address2: Not reported
City: RICHMOND HILL
State: NY
Zip Code: 11418
Country Code: 001
Phone: (347) 234-3274
EMail: CRAZY4CASSY@MSN.COM
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-02-01

Site Id: 379408
Affiliation Type: Facility Operator
Company Name: SOSA DIAGNOSTIC REPAIR INC.
Contact Type: Not reported
Contact Name: FIDEL SOSA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 388-7399
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-04-04

SOSA DIAGNOSTIC REPAIR INC. (Continued) **A100304674**

Site Id:	379408
Affiliation Type:	Emergency Contact
Company Name:	FIDEL SOSA
Contact Type:	Not reported
Contact Name:	WILLIAM SOSA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 234-3274
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-04-04

Tank Info:

Tank Number:	001
Tank Id:	216665
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	I01 - Overfill - Float Vent Valve
	B01 - Tank External Protection - Painted/Asphalt Coating
	J01 - Dispenser - Pressurized Dispenser
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	K01 - Spill Prevention - Catch Basin
	A01 - Tank Internal Protection - Epoxy Liner
	E00 - Piping Secondary Containment - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	L00 - Piping Leak Detection - None
	D00 - Pipe Type - No Piping
	G00 - Tank Secondary Containment - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1975
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

B119 **CON EDISON MANHOLE: 494** **RCRA NonGen / NLR** **1016970899**
West **378 WALLABOUT ST** **NY MANIFEST** **NYP004446282**
< 1/8 **BROOKLYN, NY 11206**
0.062 mi.
330 ft. **Site 37 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/19/2014
Facility name:	CON EDISON MANHOLE: 494
Facility address:	378 WALLABOUT ST BROOKLYN, NY 11206
EPA ID:	NYP004446282
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/19/2014
Site name:	CON EDISON MANHOLE: 494
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	378 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004446282
Facility Status:	Not reported
Location Address 1:	F/O 378 WALL ABOUT ST
Code:	BP
Location Address 2:	SB494
Total Tanks:	Not reported

CON EDISON MANHOLE: 494 (Continued) **1016970899**

Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004446282
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2014
Trans1 Recv Date:	02/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004446282
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772874JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1

CON EDISON MANHOLE: 494 (Continued) **1016970899**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B120
West
< 1/8
0.062 mi.
330 ft.

LOT 15,TAXBLOCK 2266
378 WALLABOUT STREET
BROOKLYN, NY

NY E DESIGNATION **S110242352**
N/A

Site 38 of 48 in cluster B

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 15,TAXBLOCK 2266
Address:	378 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	15
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

E121
South
< 1/8
0.063 mi.
332 ft.

LOT 147,TAXBLOCK 2272
5 WHIPPLE STREET
BROOKLYN, NY

NY E DESIGNATION **S110242350**
N/A

Site 9 of 19 in cluster E

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 147,TAXBLOCK 2272
Address:	5 WHIPPLE STREET
City,State,Zip:	BROOKLYN, NY

LOT 147,TAXBLOCK 2272 (Continued) **S110242350**

Tax Lot(s):	147
Tax Block:	2272
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

G122 **CON EDISON - MANHOLE 15641** **RCRA-LQG** **1014396248**
ENE **662 BROADWAY** **NJ MANIFEST** **NYP004184289**
< 1/8 **BROOKLYN, NY 11206** **NY MANIFEST**
0.063 mi.
335 ft. **Site 2 of 5 in cluster G**

Relative: **Higher**

Actual: **16 ft.**

RCRA-LQG:

Date form received by agency:	03/23/2010
Facility name:	CON EDISON - MANHOLE 15641
Facility address:	662 BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004184289
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLYN MURRAY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-2808
Contact email:	MURRAYFR@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

CON EDISON - MANHOLE 15641 (Continued) **1014396248**

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/14/2009
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/14/2009
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/14/2009
Site name:	CON EDISON
Classification:	Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code:	D008
. Waste name:	LEAD

Violation Status: No violations found

CON EDISON - MANHOLE 15641 (Continued) **1014396248**

NJ MANIFEST:

EPA Id:	NYP004184289
Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894723GBF
EPA ID:	NYP004184289
Date Shipped:	07/22/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/22/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/27/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON - MANHOLE 15641 (Continued) **1014396248**

Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 200 G

NY MANIFEST:
Name: CONSOLIDATED EDISON MH15861
Address: 662 BROADWAY
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004184289
Facility Status: Not reported
Location Address 1: 662 BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004184289
Mailing Name: CONSOLIDATED EDISON MH15861
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/22/2009
Trans1 Recv Date: 07/22/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/27/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004184289
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported

CON EDISON - MANHOLE 15641 (Continued) **1014396248**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894723GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

E123 **58 GERRY ST LLC** **NY Spills** **S121462321**
WSW **58 GERRY ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.064 mi.
337 ft. **Site 10 of 19 in cluster E**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	58 GERRY ST LLC
Address:	58 GERRY ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1707889 / Not Reported
Facility ID:	1707889
Facility Type:	ER
DER Facility ID:	517843
Site ID:	564269
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2017-11-17
Investigator:	MXYAU

58 GERRY ST LLC (Continued) **S121462321**

Referred To:	Not reported
Reported to Dept:	2017-11-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2017-11-17
Spill Record Last Update:	2017-11-28
Spiller Name:	Not reported
Spiller Company:	58 GERRY ST LLC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DAVID WINSLOW
DEC Memo:	"11/27/17-Lin- Alternate address 50-64 Gerry Street and 187-193 Harrison Ave. No PBS or other spill found. Active construction site. Called Melissa from GZA. Per Melissa, the site is under the Voluntary cleanup program. Three (3) 550 gasoline tanks were discovered. Commercial/residential use. Eastern environmental will be performing the cleanup this week and will collect endpoint samples. Eastern Environmental contact: Scott Hamarich 631-727-2700 Project manager from NYSDEC: Mandy Yau "
Remarks:	"found contamination during excavation"

All Materials:

Site ID:	564269
Operable Unit ID:	1312217
Operable Unit:	01
Material ID:	2319510
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

D124 **CON EDISON** **NJ MANIFEST** **S120672812**
NNE **BROADWAY & GERRY ST** **N/A**
< 1/8 **BROOKLYN, NY 11235**
0.064 mi.
339 ft. **Site 14 of 19 in cluster D**

Relative: **Lower**

Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYP004794491
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported

CON EDISON (Continued) **S120672812**

SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624575GBF
EPA ID:	NYP004794491
Date Shipped:	6/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D125
NNE
< 1/8
0.064 mi.
339 ft.

CON EDISON
BROADWAY & GERRY ST
BROOKLYN, NY 11235

Site 15 of 19 in cluster D

RCRA NonGen / NLR | **1019904164** / **NYP004794509**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/15/2015
Facility name:	CON EDISON
Facility address:	BROADWAY & GERRY ST BROOKLYN, NY 11235
EPA ID:	NYP004794509
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/15/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

D126
NNE
< 1/8
0.064 mi.
339 ft.

CON EDISON
BROADWAY & GERRY ST
BROOKLYN, NY 11235

Site 16 of 19 in cluster D

NY MANIFEST | **S119075887** / **N/A**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	BROADWAY & GERRY ST
City,State,Zip:	BROOKLYN, NY 11235
Country:	USA
EPA ID:	NYP004794491

CON EDISON (Continued) **S119075887**

Facility Status:	Not reported
Location Address 1:	OPP SW COR BROADWAY & GEORGIA ST
Code:	BP
Location Address 2:	SB 5634
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004794491
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/15/2015
Trans1 Recv Date:	06/15/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004794491
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624575GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S119075887**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D127 **CON EDISON** **RCRA NonGen / NLR** **1019904163**
NNE **BROADWAY & GERRY ST** **FINDS** **NYP004794491**
< 1/8 **BROOKLYN, NY 11235** **ECHO**
0.064 mi.
339 ft. **Site 17 of 19 in cluster D**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/15/2015
Facility name:	CON EDISON
Facility address:	BROADWAY & GERRY ST BROOKLYN, NY 11235
EPA ID:	NYP004794491
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

CON EDISON (Continued) **1019904163**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/15/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069691756

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019904163
Registry ID: 110069691756
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069691756

D128 **CON EDISON** **NJ MANIFEST** **S120672813**
NNE **BROADWAY & GERRY ST** **N/A**
< 1/8 **BROOKLYN, NY 11235**
0.064 mi.
339 ft. **Site 18 of 19 in cluster D**

Relative: **Lower**
Actual: **13 ft.**

NJ MANIFEST:
EPA Id: NYP004794509
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002624574GBF
EPA ID: NYP004794509

CON EDISON (Continued) **S120672813**

Date Shipped:	6/15/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D129 **CON EDISON** **NY MANIFEST** **S119075888**
NNE **BROADWAY & GERRY ST** **N/A**
< 1/8 **BROOKLYN, NY 11235**
0.064 mi.
339 ft. **Site 19 of 19 in cluster D**

Relative: NY MANIFEST:
Lower

Name:	CON EDISON
Address:	BROADWAY & GERRY ST
City,State,Zip:	BROOKLYN, NY 11235
Country:	USA
EPA ID:	NYP004794509
Facility Status:	Not reported
Location Address 1:	OPP W BROADWAY & GERRY ST
Code:	BP
Location Address 2:	SB 15633
Total Tanks:	Not reported

Actual:
13 ft.

CON EDISON (Continued) **S119075888**

Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004794509
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/15/2015
Trans1 Recv Date:	06/15/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004794509
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624574GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1

CON EDISON (Continued) **S119075888**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C130 **CON EDISON** **NY MANIFEST** **S117062656**
SE **34 WHIPPLE ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.065 mi.
345 ft. **Site 10 of 16 in cluster C**

Relative: **Higher**

Actual: **16 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	34 WHIPPLE ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004550265
Facility Status:	Not reported
Location Address 1:	34 WHIPPLE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004550265
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2014
Trans1 Recv Date:	06/02/2014

CON EDISON (Continued) **S117062656**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004550265
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013255006JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C131 **CON EDISON TRANSFORMER VAULT: 201** **RCRA NonGen / NLR** **1017777139**
SE **34 WHIPPLE ST** **NYP004550265**
< 1/8 **BROOKLYN, NY 11206**
0.065 mi.
345 ft. **Site 11 of 16 in cluster C**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/02/2014
Facility name:	CON EDISON TRANSFORMER VAULT: 201
Facility address:	34 WHIPPLE ST BROOKLYN, NY 11206
EPA ID:	NYP004550265
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003

CON EDISON TRANSFORMER VAULT: 201 (Continued) **1017777139**

Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/02/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 06/02/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

E132 **LOT 52,TAXBLOCK 2269** **NY E DESIGNATION** **S110242437**
SW **31 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.066 mi.
346 ft. **Site 11 of 19 in cluster E**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:
Name: LOT 52,TAXBLOCK 2269
Address: 31 BARTLETT STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 52
Tax Block: 2269
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

LOT 52,TAXBLOCK 2269 (Continued) **S110242437**

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

E133 **LOT 108,TAXBLOCK 2272** **NY E DESIGNATION** **S110242341**
SSW **BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.066 mi.
347 ft. **Site 12 of 19 in cluster E**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 108,TAXBLOCK 2272
Address: BARTLETT STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 108
Tax Block: 2272
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

B134 **LOT 14,TAXBLOCK 2266** **NY E DESIGNATION** **S110242348**
West **376 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.066 mi.
348 ft. **Site 39 of 48 in cluster B**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:
Name: LOT 14,TAXBLOCK 2266
Address: 376 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 14
Tax Block: 2266
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations

LOT 14,TAXBLOCK 2266 (Continued) **S110242348**

Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

B135 **WALLABOUT BUILDINGS** **RCRA NonGen / NLR** **1016451760**
West **376-382 WALLABOUT ST** **FINDS** **NYR000203521**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.066 mi. **NY MANIFEST**
348 ft. **Site 40 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:
Date form received by agency: 04/29/2014
Facility name: WALLABOUT BUILDINGS
Facility address: 376-382 WALLABOUT ST
BROOKLYN, NY 11206
EPA ID: NYR000203521
Mailing address: FLUSHING AVE UNIT 1D
BROOKLYN, NY 11205
Contact: SIMON DUSHINSKY
Contact address: FLUSHING AVE UNIT 1D
BROOKLYN, NY 11205
Contact country: US
Contact telephone: 718-246-4762
Telephone ext.: 220
Contact email: SIMON5134@VERIZON.NET
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: SIMON DUSHINSKY
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/31/2012
Owner/Op end date: Not reported

Owner/operator name: THROOP WALLABOUT REALTY LLC
Owner/operator address: FLUSHING AVE UNIT 1D
BROOKLYN, NY 11205
Owner/operator country: US
Owner/operator telephone: 718-246-4762
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner

WALLABOUT BUILDINGS (Continued) **1016451760**

Owner/Op start date: 05/31/2012
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/23/2013
Site name: WALLABOUT BUILDINGS
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110056331134

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016451760
Registry ID: 110056331134
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056331134

NY MANIFEST:
Name: WALLABOUT BUILDINGS

WALLABOUT BUILDINGS (Continued) **1016451760**

Address:	376-382 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYR000203521
Facility Status:	Not reported
Location Address 1:	376-382 WALLABOUT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000203521
Mailing Name:	WALLABOUT BUILDINGS
Mailing Contact:	WALLABOUT BUILDINGS
Mailing Address 1:	505 FLUSHING AVE UNIT 1D
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	11/22/2013
Trans1 Recv Date:	11/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000203521
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	012192877JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110

WALLABOUT BUILDINGS (Continued) **1016451760**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	55760
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B136 **376-382 WALLABOUT STREET** **NY VCP** **S118943287**
West **376-382 WALLABOUT STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.066 mi.
348 ft. **Site 41 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

VCP NYC:

Project ID:	13CVCP150K
Project Name:	376-382 WALLABOUT STREET
Project Address:	376-382 WALLABOUT STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	13CVCP150K
File Name:	2013-06-13.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/2013-06-13.13CVCP150K.RIR.pdf

Project ID:	13CVCP150K
File Name:	2013-06-13.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/2013-07-25.13CVCP151M.376-382_Wallabout.RAWP.V3.pdf

Project ID:	13CVCP150K
File Name:	2013-06-14.FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/2013-06-14.13CVCP150K.FactSheet1.pdf

Project ID:	13CVCP150K
File Name:	2013-06-14.Translated_FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/2013-06-14.13CVCP150K.Translated_FactSheet1.pdf

Project ID:	13CVCP150K
File Name:	2013-06-14.Translated_CPS

376-382 WALLABOUT STREET (Continued) **S118943287**

URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/2013-06-14.13CVCP150K.Translated_CPS.pdf

Project ID: 13CVCP150K
File Name: 2013-09-18.Stipulation_List
URL: http://www.nyc.gov/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/Stipulation Letter -376 Wallabout Street Brooklyn NY%3C/td%3E%3Ctd%3EEBC%3C/td%3E%3Ctd%3ESeptember 2013.pdf

Project ID: 13CVCP150K
File Name: 2013-10-31.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/2013-10-31.13CVCP150K.376-382_Wallabout_Street.Fact_Sheet-2.pdf

Project ID: 13CVCP150K
File Name: 2013-10-31.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP150K/2013-10-31.13CVCP150K.376-382_Wallabout_Street.Translated.Fact_Sheet-2.pdf

---

F137 **CON EDISON SERVICE BOX: 7977** **RCRA NonGen / NLR 1016961050**
SSE **18 WHIPPLE ST FRONT OF** **NY MANIFEST NYP004334918**
< 1/8 **BROOKLYN, NY 11206**
0.066 mi.
350 ft. **Site 4 of 19 in cluster F**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:
Date form received by agency: 08/25/2013
Facility name: CON EDISON SERVICE BOX: 7977
Facility address: 18 WHIPPLE ST FRONT OF
BROOKLYN, NY 11206
EPA ID: NYP004334918
Mailing address: IRVING PL, RM 828
NEW YORK, NY 10003
Contact: ANTHONY SIGNORE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

CON EDISON SERVICE BOX: 7977 (Continued) **1016961050**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/25/2013
Site name: CON EDISON SERVICE BOX: 7977
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 18 WHIPPLE ST FRONT OF
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004334918
Facility Status: Not reported
Location Address 1: OPP 18 WHIPPLE STREET
Code: BP
Location Address 2: SERVICE BOX # 7977
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004334918
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/25/2013
Trans1 Recv Date: 07/25/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004334918
Trans1 EPA ID: Not reported

CON EDISON SERVICE BOX: 7977 (Continued) **1016961050**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002085865GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

E138 **29 BARTLETT STREET** **NY Spills** **S102150626**
SW **29 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.068 mi.
357 ft. **Site 13 of 19 in cluster E**

Relative: SPILLS:
Higher

Name:	29 BARTLETT STREET
Address:	29 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9506117 / 1995-08-24
Facility ID:	9506117
Facility Type:	ER
DER Facility ID:	115355
Site ID:	134249
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1995-08-17

Actual:
14 ft.

29 BARTLETT STREET (Continued) **S102150626**

Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1995-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	1995-08-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-09-27
Spill Record Last Update:	1995-09-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY "
Remarks:	"RECEIVING OIL DELIVERY AND FUEL LINE BROKE - REQUESTING RESPONDER - FROM DEC - 08/24/95, HPD - PUT SPEEDY DRY ON THE SIDEWALK (INFO FROM DEP, MARTY)"

All Materials:

Site ID:	134249
Operable Unit ID:	1020915
Operable Unit:	01
Material ID:	364097
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E139 **29-31 BARTLETT STREET** **NY AST** **A100360413**
SW **29-31 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.068 mi.
357 ft. **Site 14 of 19 in cluster E**

Relative:
Higher

Actual:
14 ft.

AST:

Name:	29-31 BARTLETT STREET
Address:	29-31 BARTLETT STREET
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-611766
Program Type:	PBS
UTM X:	588938.17226
UTM Y:	4506062.97785

29-31 BARTLETT STREET (Continued) **A100360413**

Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 461541
Affiliation Type: Facility Owner
Company Name: NYC DEPT OF HOUSING PRESERVATION & DEV.
Contact Type: EXEC DIR
Contact Name: JOHN E. GEARRITY
Address1: 100 GOLD STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 863-7172
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-03-02

Site Id: 461541
Affiliation Type: Mail Contact
Company Name: NYC DEPT OF HOUSING PRESERVATION & DEV.
Contact Type: Not reported
Contact Name: ASST. COMM.-DPM
Address1: 100 GOLD STREET
Address2: 7T-2
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 863-7172
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-03-02

Site Id: 461541
Affiliation Type: Facility Operator
Company Name: 29-31 BARTLETT STREET
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: N/A
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-05-03

Site Id: 461541
Affiliation Type: Emergency Contact
Company Name: NYC DEPT OF HOUSING PRESERVATION & DEV.

29-31 BARTLETT STREET (Continued) **A100360413**

Contact Type:	Not reported
Contact Name:	DEREK PARSONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 559-4337
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-05-03

Tank Info:

Tank Number:	001
Tank Id:	243081
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	D00 - Pipe Type - No Piping
	L00 - Piping Leak Detection - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	K00 - Spill Prevention - None
	J00 - Dispenser - None
	G00 - Tank Secondary Containment - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/06/1990
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/17/2012
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

H140
NW
< 1/8
0.068 mi.
359 ft.

LOT 33,TAXBLOCK 2250
66 THROOP AVENUE
BROOKLYN, NY 11206

Site 1 of 16 in cluster H

NY E DESIGNATION **S110242391**
N/A

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 33,TAXBLOCK 2250
Address:	66 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	33
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

H141
NW
< 1/8
0.069 mi.
364 ft.

VARTEX INSTRUMENT CORP
311 WALLABOUT ST
BROOKLYN, NY 11206

Site 2 of 16 in cluster H

RCRA NonGen / NLR **1004761306**
FINDS **NYR000084483**
ECHO
NY E DESIGNATION
NY MANIFEST

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	VARTEX INSTRUMENT CORP
Facility address:	311 WALLABOUT ST BROOKLYN, NY 11206
EPA ID:	NYR000084483
Mailing address:	PO BOX 780075 MASPETH, NY 11378-0075
Contact:	JOHN VARTOUGHIAN
Contact address:	PO BOX 780075 MASPETH, NY 11378-0075
Contact country:	US
Contact telephone:	718-779-3151
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	VARTEX INTERNATIONAL LTD
Owner/operator address:	PO BOX 780075

VARTEX INSTRUMENT CORP (Continued) **1004761306**

MASPETH, NY 11378
Owner/operator country: US
Owner/operator telephone: 718-779-3151
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: VARTEX INTERNATIONAL LTD
Owner/operator address: PO BOX 780075
MASPETH, NY 11378
Owner/operator country: US
Owner/operator telephone: 718-779-3151
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: VARTEX INSTRUMENT CORP
Classification: Not a generator, verified

Date form received by agency: 02/09/2000
Site name: VARTEX INSTRUMENT CORP
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D003
. Waste name: REACTIVE WASTE

Violation Status: No violations found

VARTEX INSTRUMENT CORP (Continued) **1004761306**

FINDS:

Registry ID: 110004561206

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004761306
Registry ID:	110004561206
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004561206

E DESIGNATION:

Name:	LOT 36,TAXBLOCK 2250
Address:	311 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	36
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NY MANIFEST:

Name:	VARTEX INSTRUMENT CORP
Address:	311 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYR000084483
Facility Status:	Not reported
Location Address 1:	311 WALLOBOUT ST

VARTEX INSTRUMENT CORP (Continued) **1004761306**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000084483
Mailing Name:	VARTEX INSTRUMENT CORP
Mailing Contact:	JOHN VARTOUGHIAN
Mailing Address 1:	311 WALLOBOUT ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184763897

NY MANIFEST:

Document ID:	NYG2260503
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	NYPD1010
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2000
Trans1 Recv Date:	02/25/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/29/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000084483
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D040 - TRICHLOROETHYLENE 0.5 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

VARTEX INSTRUMENT CORP (Continued) **1004761306**

Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	P - Pounds
Number of Containers:	007
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

H142 **LOT 37,TAXBLOCK 2250** **NY E DESIGNATION** **S110242399**
NW **311 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.069 mi.
364 ft. **Site 3 of 16 in cluster H**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 37,TAXBLOCK 2250
Address:	311 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	37
Tax Block:	2250
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

H143 **311-313 WALLABOUT STREET** **NY VCP** **S118943458**
NW **311-313 WALLABOUT STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.069 mi.
364 ft. **Site 4 of 16 in cluster H**

Relative:
Lower

Actual:
13 ft.

VCP NYC:
Project ID: 15CVCP068K
Project Name: 311-313 WALLABOUT STREET
Project Address: 311-313 WALLABOUT STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP068K
File Name: 2015-01-06.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP068K/2015-01-06.15EHAN077K.313_Wallabout.report.Remedial Investigation Report_V2.pdf

Project ID: 15CVCP068K
File Name: 2015-01-26.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP068K/2015-01-26.15CVCP069K.15EHAN077K.313_Wallabout.report.RAWP_DRAFT.pdf

Project ID: 15CVCP068K
File Name: 2015-01-29.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP068K/2015-01-30.15CVCP077K.313_Wallabout.Factsheet-1.pdf

Project ID: 15CVCP068K
File Name: 2015-01-30.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP068K/2015-01-29.15CVCP068K.doc.3131_Wallabout_Street.Translated_FactSheet-1.rx.pdf

Project ID: 15CVCP068K
File Name: 2015-01-30.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP068K/2015-01-29.15CVCP068K.doc.3131_Wallabout_Street.Translated_CPS.rx.pdf

---

B144 **LOT 43,TAXBLOCK 2250** **NY E DESIGNATION** **S122872744**
WNW **301 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.069 mi.
366 ft. **Site 42 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:
Name: LOT 43,TAXBLOCK 2250
Address: 301 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 43
Tax Block: 2250
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K

LOT 43,TAXBLOCK 2250 (Continued) **S122872744**

Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

B145 **LOT 38,TAXBLOCK 2250** **NY AST** **U001841022**
NW **307 WALLABOUT STREET** **NY E DESIGNATION** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.070 mi.
368 ft. **Site 43 of 48 in cluster B**

Relative:
Lower

Actual:
13 ft.

AST:
Name: 307 WALLABOUNT STREET
Address: 307 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY 11220
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-481343
Program Type: PBS
UTM X: 588938.49217
UTM Y: 4506227.98805
Expiration Date: N/A
Site Type: Unknown

Affiliation Records:
Site Id: 21519
Affiliation Type: Facility Owner
Company Name: CITY OF NY%NYC PUBLIC DEV CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 161 WILLIAM STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 619-5000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21519
Affiliation Type: Mail Contact
Company Name: CITY OF NY%NYC PUBLIC DEV CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 161 WILLIAM STREET
Address2: Not reported
City: NEW YORK

LOT 38,TAXBLOCK 2250 (Continued) **U001841022**

State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 619-5000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21519
Affiliation Type: Facility Operator
Company Name: 307 WALLABOUNT STREET
Contact Type: Not reported
Contact Name: CITY OF NY%NYC PUBLIC DEV CORP
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 619-5000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21519
Affiliation Type: Emergency Contact
Company Name: CITY OF NY%NYC PUBLIC DEV CORP
Contact Type: Not reported
Contact Name: DAN KURTZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 625-6085
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 41124
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None

LOT 38,TAXBLOCK 2250 (Continued) **U001841022**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	05/01/1961
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

E DESIGNATION:

Name:	LOT 38,TAXBLOCK 2250
Address:	307 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	38
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

F146 **LOT 5,TAXBLOCK 2274** **NY E DESIGNATION** **S110242434**
SSE **16 WHIPPLE STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.070 mi.
369 ft. **Site 5 of 19 in cluster F**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 5,TAXBLOCK 2274
Address:	16 WHIPPLE STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	5
Tax Block:	2274
Borough Code:	Not reported
E-No:	E-238

LOT 5,TAXBLOCK 2274 (Continued) **S110242434**

Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #4 Fuel Oil for space heating and hot water systems
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

B147 **LOT 44,TAXBLOCK 2250** **NY E DESIGNATION** **S122872745**
WNW **299 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.070 mi.
371 ft. **Site 44 of 48 in cluster B**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 44,TAXBLOCK 2250
Address:	299 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	44
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

B148 **299-301 WALLABOUT STREET** **NY VCP** **S118943558**
WNW **299-301 WALLABOUT STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.070 mi.
371 ft. **Site 45 of 48 in cluster B**

Relative: **Lower**
Actual: **13 ft.**

VCP NYC:

Project ID:	16CVCP008K
Project Name:	299-301 WALLABOUT STREET
Project Address:	299-301 WALLABOUT STREET
Borough:	BROOKLYN

299-301 WALLABOUT STREET (Continued) **S118943558**

VCP NYC:

Project ID:	16CVCP008K
File Name:	2015-07-23.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2015-07-23.15EH-A275K.report.RIR_revised.EBC.pdf
Project ID:	16CVCP008K
File Name:	2015-08-18.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2015-08-18.16CVCP008K.15EH-A275K.report.295-297_Wallabout_Street_RAWP_Draft.EBC.pdf
Project ID:	16CVCP008K
File Name:	2015-08-17.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2015-08-17.16CVCP008K.15EH-A275K.295_Wallabout_FactSheet-1.pdf
Project ID:	16CVCP008K
File Name:	2015-08-17.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2015-08-17.15EH-A275K.295_Wallabout_Translated_Factsheet-1.pdf
Project ID:	16CVCP008K
File Name:	2015-08-17.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2015-08-17.15EH-A275K.295_Wallabout_Translated_CPS.pdf
Project ID:	16CVCP008K
File Name:	2016-03-30.Decision_Document
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2016-03-30.16CVCP008K.notice.Decision_Document.OER.pdf
Project ID:	16CVCP008K
File Name:	2016-08-25.Factsheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2016-08-25.16CVCP008K.299-301_Wallabout_FactSheet-2.pdf
Project ID:	16CVCP008K
File Name:	2016-08-25.Translated_Factsheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP008K/2016-08-23.16CVCP008K.299-301_Wallabout_Translated_Factsheet-2.pdf

---

B149 **LOT 40,TAXBLOCK 2250** **NY E DESIGNATION** **S110242406**
WNW **305 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.071 mi.
374 ft. **Site 46 of 48 in cluster B**

Relative: E DESIGNATION:
Lower

Name:	LOT 40,TAXBLOCK 2250
Address:	305 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	40

Actual:
13 ft.

LOT 40,TAXBLOCK 2250 (Continued) **S110242406**

Tax Block: 2250
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

F150 **LOT 6,TAXBLOCK 2274** **NY E DESIGNATION** **S110242446**
SSE **WHIPPLE STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.071 mi.
377 ft. **Site 6 of 19 in cluster F**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 6,TAXBLOCK 2274
Address: WHIPPLE STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 6
Tax Block: 2274
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - #4 Fuel Oil for space heating and hot water systems
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

F151 **LOT 1,TAXBLOCK 2274** **NY E DESIGNATION** **S110242339**
SSE **2 WHIPPLE STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.072 mi.
381 ft. **Site 7 of 19 in cluster F**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 2274
Address:	2 WHIPPLE STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	1
Tax Block:	2274
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #4 Fuel Oil for space heating and hot water systems
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

B152 **CON EDISON SERVICE BOX: 7969** **RCRA NonGen / NLR** **1016970892**
West **372 WALLABOUT ST** **NY MANIFEST** **NYP004446217**
< 1/8 **BROOKLYN, NY 11206**
0.073 mi.
388 ft. **Site 47 of 48 in cluster B**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/19/2014
Facility name:	CON EDISON SERVICE BOX: 7969
Facility address:	372 WALLABOUT ST BROOKLYN, NY 11206
EPA ID:	NYP004446217
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON SERVICE BOX: 7969 (Continued) **1016970892**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/19/2014
Site name: CON EDISON SERVICE BOX: 7969
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 372 WALLABOUT ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004446217
Facility Status: Not reported
Location Address 1: 374 WALLABOUT ST & HARRISON AVE
Code: BP
Location Address 2: SB7969
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004446217
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/19/2014
Trans1 Recv Date: 02/19/2014
Trans2 Recv Date: Not reported

CON EDISON SERVICE BOX: 7969 (Continued) **1016970892**

TSD Site Recv Date:	02/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004446217
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772514JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

F153 **LOT 49,TAXBLOCK 2272** **NY E DESIGNATION** **S110242433**
South **WHIPPLE STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.074 mi.
389 ft. **Site 8 of 19 in cluster F**

Relative:
Higher

Actual:
14 ft.

E DESIGNATION:

Name:	LOT 49,TAXBLOCK 2272
Address:	WHIPPLE STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	49
Tax Block:	2272
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009

LOT 49,TAXBLOCK 2272 (Continued) **S110242433**

Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

F154 **LOT 51,TAXBLOCK 2272** **NY E DESIGNATION** **S110242436**
SSW **665 FLUSHING AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.074 mi.
393 ft. **Site 9 of 19 in cluster F**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 51,TAXBLOCK 2272
Address: 665 FLUSHING AVENUE
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 51
Tax Block: 2272
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

F155 **LOT 52,TAXBLOCK 2272** **NY E DESIGNATION** **S110242438**
SSW **665 FLUSHING AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.074 mi.
393 ft. **Site 10 of 19 in cluster F**

Relative: **Higher**
Actual: **14 ft.**

E DESIGNATION:
Name: LOT 52,TAXBLOCK 2272
Address: 665 FLUSHING AVENUE
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 52
Tax Block: 2272
Borough Code: BK

LOT 52,TAXBLOCK 2272 (Continued) **S110242438**

E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported

H156 **LOT 42,TAXBLOCK 2250** **NY E DESIGNATION** **S122872743**
WNW **WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.075 mi.
397 ft. **Site 5 of 16 in cluster H**

Relative: E DESIGNATION:
Lower

Actual: Name:	LOT 42,TAXBLOCK 2250
13 ft. Address:	WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	42
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

B157 **CON EDISON** **NY MANIFEST** **S117676297**
WNW **295 WALLABOUT ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.075 mi.
397 ft. **Site 48 of 48 in cluster B**

Relative: NY MANIFEST:
Lower

Actual: Name:	CON EDISON
13 ft. Address:	295 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA

CON EDISON (Continued) **S117676297**

EPA ID: NYP004858587
Facility Status: Not reported
Location Address 1: 295 WALLABOUT ST
Code: BP
Location Address 2: SB 7970
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004858587
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 10/22/2015
Trans1 Recv Date: 10/22/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/22/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004858587
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002622208GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S117676297**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

H158 **CON EDISON SERVICE BOX: 42764** **RCRA NonGen / NLR** **1016967344**
NNW **45 THROOP AVE** **NY MANIFEST** **NYP004409629**
< 1/8 **BROOKLYN, NY 11206**
0.076 mi.
400 ft. **Site 6 of 16 in cluster H**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/20/2014
Facility name:	CON EDISON SERVICE BOX: 42764
Facility address:	45 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004409629
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON SERVICE BOX: 42764 (Continued) **1016967344**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/20/2013
Site name: CON EDISON SERVICE BOX: 42764
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 45 THROOP AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004409629
Facility Status: Not reported
Location Address 1: 45 THROOP AVE
Code: BP
Location Address 2: SB42764
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11217
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004409629
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 12/20/2013
Trans1 Recv Date: 12/20/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004409629
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105

CON EDISON SERVICE BOX: 42764 (Continued) **1016967344**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002300677GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

G159 **CON EDISON** **NJ MANIFEST** **S120672588**
ENE **BARTLETT ST & BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11223**
0.076 mi.
401 ft. **Site 3 of 5 in cluster G**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYP004791927
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

Actual:
15 ft.

CON EDISON (Continued) **S120672588**

Date Change: Not reported

Manifest:
Manifest Number: 014473275JJK
EPA ID: NYP004791927
Date Shipped: 6/9/2015
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

G160 **CON EDISON** **NY MANIFEST** **S118256735**
ENE **BARTLETT ST & BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11223**
0.076 mi.
401 ft. **Site 4 of 5 in cluster G**

Relative: NY MANIFEST:
Higher
Name: CON EDISON
Actual: Address: BARTLETT ST & BROADWAY
15 ft. City,State,Zip: BROOKLYN, NY 11223
Country: USA
EPA ID: NYP004791927

CON EDISON (Continued) **S118256735**

Facility Status:	Not reported
Location Address 1:	BARTLETT ST & BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11223
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004791927
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/09/2015
Trans1 Recv Date:	06/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004791927
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014473275JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S118256735**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

G161 **CON EDISON** **RCRA NonGen / NLR** **1019325073**
ENE **BARTLETT ST & BROADWAY** **NYP004791927**
< 1/8 **BROOKLYN, NY 11223**
0.076 mi.
401 ft. **Site 5 of 5 in cluster G**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON
Site name:	CON EDISON - MANHOLE 15649
Facility address:	BARTLETT ST & BROADWAY BROOKLYN, NY 11223
EPA ID:	NYP004791927
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/09/2015
Owner/Op end date:	Not reported

CON EDISON (Continued) **1019325073**

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/09/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/09/2015
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 06/09/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 4000

Violation Status: No violations found

F162
SSW
< 1/8
0.077 mi.
405 ft.

LOT 53,TAXBLOCK 2272
663 FLUSHING AVENUE
BROOKLYN, NY 11206

Site 11 of 19 in cluster F

NY E DESIGNATION

S110242440
N/A

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 53,TAXBLOCK 2272
Address:	663 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	53
Tax Block:	2272
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

F163
SSE
< 1/8
0.078 mi.
410 ft.

LOT 24,TAXBLOCK 2274
687 FLUSHING AVENUE
BROOKLYN, NY

Site 12 of 19 in cluster F

NY E DESIGNATION

S117676043
N/A

Relative:
Higher

Actual:
15 ft.

E DESIGNATION:

Name:	LOT 24,TAXBLOCK 2274
Address:	687 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	24
Tax Block:	2274
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #4 Fuel Oil for space heating and hot water systems
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

F164 **687 FLUSHING AVENUE** **NY VCP** **S121796992**
SSE **687 FLUSHING AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.078 mi.
410 ft. **Site 13 of 19 in cluster F**

Relative:
Higher

Actual:
15 ft.

VCP NYC:
Project ID: 18CVCP024K
Project Name: 687 FLUSHING AVENUE
Project Address: 687 FLUSHING AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 18CVCP024K
File Name: 2015-09-22.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP024K/2015-09-22.14TMP0153K.687_Flushing_Ave.RIR.pdf

Project ID: 18CVCP024K
File Name: 2017-09-28.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP024K/2017-09-28.14TMP0153K.RAPRAWP.RAWP PDF.pdf

Project ID: 18CVCP024K
File Name: 2017-10-16.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP024K/2017-10-16.14TMP0153K.687_Flushing_Ave.Factsheet_1.pdf

Project ID: 18CVCP024K
File Name: 2017-10-16.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP024K/2017-10-16.14TMP0153K.687_Flushing_Ave_Translated_Factsheet_1.OER.pdf

Project ID: 18CVCP024K
File Name: 2017-10-16.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/18CVCP024K/2017.10.16.14TMP0153K_687_Flushing_Ave_Translated_CPS.pdf

---

E165 **PFIZER INC** **NY E DESIGNATION** **S117675753**
SW **191 HARRISON AVE** **NY MANIFEST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.079 mi.
416 ft. **Site 15 of 19 in cluster E**

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:
Name: LOT 1,TAXBLOCK 2269
Address: 191 HARRISON AVENUE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 1
Tax Block: 2269
Borough Code: Not reported
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

PFIZER INC (Continued) **S117675753**

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

NY MANIFEST:
Name: PFIZER INC
Address: 191 HARRISON AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYD001513779
Facility Status: Not reported
Location Address 1: 60 GERRY STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001513779
Mailing Name: PFIZER INC
Mailing Contact: BARBARA WONG
Mailing Address 1: 100 ROUTE 206N (M/S 401)
Mailing Address 2: Not reported
Mailing City: PEAPACK
Mailing State: NJ
Mailing Zip: 07977
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9173753219

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2016
Trans1 State ID: NJD080631369
Trans2 State ID: Not reported
Generator Ship Date: 07/06/2016
Trans1 Recv Date: 07/06/2016
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/08/2016
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001513779
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD980536593
TSDF ID 2: Not reported
Manifest Tracking Number: 000969557VES

PFIZER INC (Continued) **S117675753**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

E166 **ARLINGTON PRESS** **NJ MANIFEST** **S120665298**
SW **191 HARRISON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.079 mi.
416 ft. **Site 16 of 19 in cluster E**

Relative: NJ MANIFEST:
Lower

EPA Id:	NYD001513779
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	7184867474
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	000000

Actual:
13 ft.

ARLINGTON PRESS (Continued) **S120665298**

Manifest:

Manifest Number:	001010112VES
EPA ID:	NYD001513779
Date Shipped:	5/13/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	001010114VES
EPA ID:	NYD001513779
Date Shipped:	5/18/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported

ARLINGTON PRESS (Continued) **S120665298**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000968981VES
EPA ID:	NYD001513779
Date Shipped:	3/26/2018
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ARLINGTON PRESS
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/26/2018

ARLINGTON PRESS (Continued) **S120665298**

Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/26/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
Manifest Number:	000968981VES
EPA ID:	NYD001513779
Date Shipped:	3/26/2018
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	ARLINGTON PRESS
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/26/2018
Waste SEQ ID:	2
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/26/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
Manifest Number:	000926246VES
EPA ID:	NYD001513779

ARLINGTON PRESS (Continued) **S120665298**

Date Shipped:	5/22/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000972680VES
EPA ID:	NYD001513779
Date Shipped:	4/16/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

ARLINGTON PRESS (Continued) **S120665298**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000972055VES
EPA ID:	NYD001513779
Date Shipped:	6/10/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

ARLINGTON PRESS (Continued) **S120665298**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	001010037VES
EPA ID:	NYD001513779
Date Shipped:	7/8/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000972681VES
EPA ID:	NYD001513779
Date Shipped:	5/11/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

ARLINGTON PRESS (Continued) **S120665298**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	001010113VES
EPA ID:	NYD001513779
Date Shipped:	5/14/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

ARLINGTON PRESS (Continued) **S120665298**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000926245VES
EPA ID:	NYD001513779
Date Shipped:	6/4/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

ARLINGTON PRESS (Continued) **S120665298**

Manifest Number:	000972679VES
EPA ID:	NYD001513779
Date Shipped:	4/13/2015
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD000692061
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

F167 **TULIP GROVE HOMES** **NJ MANIFEST** **S120678981**
SSW **661 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.079 mi.
418 ft. **Site 14 of 19 in cluster F**

Relative: **Lower**

Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYR000203539
Mail Address:	BOERUM ST SUITE 401
Mail City/State/Zip:	BROOKLYN, NY 11206
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOEL KOHN
Comments:	Not reported
SIC Code:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014730485JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014730498JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737509JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737511JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206

TULIP GROVE HOMES (Continued) **S120678981**

Reason Load Was Rejected:	Not reported
Manifest Number:	014737512JJK
EPA ID:	NYR000203539
Date Shipped:	8/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	014730499JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737504JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014738254JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	015303222JJK
EPA ID:	NYR000203539
Date Shipped:	12/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967

TULIP GROVE HOMES (Continued) **S120678981**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737505JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737518JJK
EPA ID:	NYR000203539
Date Shipped:	12/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	014737522JJK
EPA ID:	NYR000203539
Date Shipped:	12/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	015303220JJK
EPA ID:	NYR000203539
Date Shipped:	12/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737513JJK
EPA ID:	NYR000203539
Date Shipped:	8/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737503JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737508JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015

TULIP GROVE HOMES (Continued) **S120678981**

TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737510JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	014737523JJK
EPA ID:	NYR000203539
Date Shipped:	12/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	014730496JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	014737506JJK
EPA ID:	NYR000203539
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

TULIP GROVE HOMES (Continued) **S120678981**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11206
Reason Load Was Rejected:	Not reported

F168 **TULIP GROVE HOMES** **RCRA-LQG** **1016451761**
SSW **661 FLUSHING AVENUE** **NYR000203539**
< 1/8 **BROOKLYN, NY 11206**
0.079 mi.
418 ft. **Site 15 of 19 in cluster F**

Relative: **Lower**

Actual: **13 ft.**

RCRA-LQG:

Date form received by agency:	02/03/2016
Facility name:	TULIP GROVE HOMES
Facility address:	661 FLUSHING AVENUE BROOKLYN, NY 11206
EPA ID:	NYR000203539
Mailing address:	MYRTLE AVENUE, #380 BROOKLYN, NY 11205
Contact:	JOEL KOHN
Contact address:	BOERUM STREET, SUITE 401 BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	917-306-2610
Contact email:	JOEL@FINGERTECUSA.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the

TULIP GROVE HOMES (Continued) **1016451761**

cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	661F REALTY LLC
Owner/operator address:	BOERUM STREET, SUITE 401 BROOKLYN, NY 11206
Owner/operator country:	US
Owner/operator telephone:	917-306-2610
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/22/2015
Owner/Op end date:	Not reported

Owner/operator name:	JOEL KOHN
Owner/operator address:	BOERUM STREET, SUITE 401 BROOKLYN, NY 11206
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/22/2015
Owner/Op end date:	Not reported

Owner/operator name:	MICHUEL KLEIN
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/16/2013
Owner/Op end date:	Not reported

Owner/operator name:	156-158 SKILLMAN CORP
Owner/operator address:	MYRTLE AVE #380 BROOKLYN, NY 11205
Owner/operator country:	US
Owner/operator telephone:	347-489-2031
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

TULIP GROVE HOMES (Continued) **1016451761**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/16/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/04/2015
Site name: TULIP GROVE HOMES
Classification: Large Quantity Generator

Date form received by agency: 04/29/2014
Site name: TULIP GROVE HOMES
Classification: Not a generator, verified

Date form received by agency: 10/23/2013
Site name: TULIP GROVE HOMES
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 1648860

Violation Status: No violations found

F169 **LOT 54,TAXBLOCK 2272** **NY E DESIGNATION** **S110242442**
SSW **661 FLUSHING AVENUE** **NY MANIFEST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.079 mi.
418 ft. **Site 16 of 19 in cluster F**

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 54,TAXBLOCK 2272
Address:	661 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	54
Tax Block:	2272
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NY MANIFEST:

Name:	TULIP GROVE HOMES
Address:	661 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYR000203539
Facility Status:	Not reported
Location Address 1:	661 FLUSHING AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000203539
Mailing Name:	TULIP GROVE HOMES
Mailing Contact:	661 F REALITY LLC
Mailing Address 1:	12 BOERUM ST #401
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3474892031

LOT 54,TAXBLOCK 2272 (Continued) **S110242442**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	12/08/2015
Trans1 Recv Date:	12/08/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000203539
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	015303219JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	49240
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

F170
SSW
< 1/8
0.079 mi.
418 ft.

661 FLUSHING AVENUE
661 FLUSHING AVENUE
NEW YORK CITY, NY

Site 17 of 19 in cluster F

NY VCP **S118943290**
N/A

Relative:
Lower

Actual:
13 ft.

VCP NYC:
Project ID: 13CVCP153K
Project Name: 661 FLUSHING AVENUE
Project Address: 661 FLUSHING AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 13CVCP153K
File Name: 2013-06-25.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP153K/2013-06-25.13CVCP153K.661-Flushing_Avenue.RIR_web.pdf

Project ID: 13CVCP153K
File Name: 2013-06-25.RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP153K/2013-07-25.13CVCP153K.661-Flushing_Avenue.RAWP_final.web - Shortcut.lnk

Project ID: 13CVCP153K
File Name: 2013-06-24.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP153K/2013-06-24.13CVCP153K.661-Flushing_Ave.FactSheet-1.pdf

Project ID: 13CVCP153K
File Name: 2013-06-25.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP153K/2013-06-25.13CVCP153K.661-Flushing_Avenue.Translated_Factsheet-1.pdf

Project ID: 13CVCP153K
File Name: 2013-06-25.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP153K/2013-06-25.13CVCP153K.661-Flushing_Avenue.Translated_Factsheet-1.pdf

Project ID: 13CVCP153K
File Name: 2015-02-05.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP153K/2015-02-03.13CVCP153K.doc.661_Flushing_Avenue.FactSheet-2.pdf

Project ID: 13CVCP153K
File Name: 2015-02-05.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP153K/2015-02-04.13CVCP153K.doc.661_Flushing_Ave.Translated_FactSheet-2.pdf

F171 **CON EDISON** **RCRA NonGen / NLR** **1014396428**
South **WHIPPLE ST & FLUSHING AVE** **NJ MANIFEST** **NYP004186920**
< 1/8 **BROOKLYN, NY 11206** **NY MANIFEST**
0.080 mi.
422 ft. **Site 18 of 19 in cluster F**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	WHIPPLE ST & FLUSHING AVE BROOKLYN, NY 11206
EPA ID:	NYP004186920
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	CAROLINE ISKANDER
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	718-666-4714
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/27/2009
Site name:	CON EDISON
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004186920
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported

CON EDISON (Continued) **1014396428**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894772GBF
EPA ID:	NYP004186920
Date Shipped:	07/31/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/31/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/01/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 G

CON EDISON (Continued) **1014396428**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	WHIPPLE ST & FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004186920
Facility Status:	Not reported
Location Address 1:	WHIPPLE ST & FLUSHING AVE - MH497
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11202
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004186920
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2009
Trans1 Recv Date:	07/31/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004186920
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894772GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **1014396428**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

I172 **CON EDISON - MANHOLE M15650** **RCRA-LQG** **1024891304**
East **676 BROADWAY** **NYP005094628**
< 1/8 **BROOKLYN, NY 11206**
0.080 mi.
422 ft. **Site 1 of 6 in cluster I**

Relative: **Higher**

Actual: **17 ft.**

RCRA-LQG:

Date form received by agency:	04/10/2018
Facility name:	CON EDISON - MANHOLE M15650
Facility address:	676 BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP005094628
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	ALYSSA SOTTO
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	SOTTOA@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than

CON EDISON - MANHOLE M15650 (Continued) **1024891304**

100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/09/2017
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE
	NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/09/2017
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

. Waste code:	D008
. Waste name:	LEAD

Violation Status: No violations found

I173 **CON EDISON - MANHOLE M15650** **NY MANIFEST** **S121968226**
East **676 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.080 mi.
422 ft. **Site 2 of 6 in cluster I**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE M15650
Address:	676 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP005094628
Facility Status:	Not reported
Location Address 1:	676 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005094628
Mailing Name:	CON EDISON - MANHOLE M15650
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C174 **EMS BATT 57 @ WOODHULL HOSPITAL** **NY UST** **U004046659**
SE **131 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.080 mi.
425 ft. **Site 12 of 16 in cluster C**

Relative:
Higher

Actual:
17 ft.

UST:

Name:	EMS BATT 57 @ WOODHULL HOSPITAL
Address:	131 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-609575 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	05/25/2024
UTM X:	589201.42721
UTM Y:	4506014.43073
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	55635
Affiliation Type:	Facility Owner

EMS BATT 57 @ WOODHULL HOSPITAL (Continued) **U004046659**

Company Name:	F.D.N.Y.
Contact Type:	FACILITIES COMPIANCE COORDINATOR
Contact Name:	CASSANDRA RICHARD
Address1:	9 METROTECH CENTER
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-11-29

Site Id:	55635
Affiliation Type:	Mail Contact
Company Name:	FDNY FACILITIES
Contact Type:	Not reported
Contact Name:	CASSANDRA RICHARD
Address1:	48-34 35TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6569
EMail:	CASSANDRA.RICHARD@FDNY.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-29

Site Id:	55635
Affiliation Type:	Facility Operator
Company Name:	EMS BATT 57 @ WOODHULL HOSPITAL
Contact Type:	Not reported
Contact Name:	CASSANDRA RICHARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 302-5662
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-29

Site Id:	55635
Affiliation Type:	Emergency Contact
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	EOC/NOTIFICATION DESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported

EMS BATT 57 @ WOODHULL HOSPITAL (Continued) **U004046659**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Tank Info:

Tank Number:	001
Tank ID:	178909
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2500
Install Date:	05/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
L04 - Piping Leak Detection - Groundwater Well
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
F99 - Pipe External Protection - Other
H05 - Tank Leak Detection - In-Tank System (ATG)

C175 **CON EDISON** **NY MANIFEST** **S119077450**
SE **131 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.080 mi.
425 ft. **Site 13 of 16 in cluster C**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	131 THROOP AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004831042
Facility Status:	Not reported
Location Address 1:	FLUSHINGS THROOP
Code:	BP
Location Address 2:	VS 5390
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004831042
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/27/2015
Trans1 Recv Date:	08/27/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/28/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004831042
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624965GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S119077450**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C176 **CON EDISON** **NJ MANIFEST** **S120676024**
SE **131 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.080 mi.
425 ft. **Site 14 of 16 in cluster C**

Relative:
Higher

Actual:
17 ft.

NJ MANIFEST:

EPA Id:	NYP004831042
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624965GBF
EPA ID:	NYP004831042
Date Shipped:	8/27/2015
TSDF EPA ID:	NJD991291105

CON EDISON (Continued) **S120676024**

Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C177 **EMS BATT 57 @ WOODHULL HOSPITAL** **NY AST** **A100382393**
SE **131 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.080 mi.
425 ft. **Site 15 of 16 in cluster C**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	EMS BATT 57 @ WOODHULL HOSPITAL
Address:	131 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609575
Program Type:	PBS
UTM X:	589201.42721
UTM Y:	4506014.43073
Expiration Date:	05/25/2024
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

EMS BATT 57 @ WOODHULL HOSPITAL (Continued) **A100382393**

Affiliation Records:

Site Id:	55635
Affiliation Type:	Facility Owner
Company Name:	F.D.N.Y.
Contact Type:	FACILITIES COMPIANCE COORDINATOR
Contact Name:	CASSANDRA RICHARD
Address1:	9 METROTECH CENTER
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-11-29

Site Id:	55635
Affiliation Type:	Mail Contact
Company Name:	FDNY FACILITIES
Contact Type:	Not reported
Contact Name:	CASSANDRA RICHARD
Address1:	48-34 35TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6569
EMail:	CASSANDRA.RICHARD@FDNY.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-29

Site Id:	55635
Affiliation Type:	Facility Operator
Company Name:	EMS BATT 57 @ WOODHULL HOSPITAL
Contact Type:	Not reported
Contact Name:	CASSANDRA RICHARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 302-5662
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-29

Site Id:	55635
Affiliation Type:	Emergency Contact
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	EOC/NOTIFICATION DESK

EMS BATT 57 @ WOODHULL HOSPITAL (Continued) **A100382393**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Tank Info:

Tank Number:	001A
Tank Id:	249304

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1999
Capacity Gallons:	25
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	diesel

C178 **CON EDISON** **RCRA NonGen / NLR** **1019907176**
SE **131 THROOP AVE** **FINDS** **NYP004831042**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.080 mi.
425 ft. **Site 16 of 16 in cluster C**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/27/2015
Facility name:	CON EDISON
Facility address:	131 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004831042

CON EDISON (Continued) **1019907176**

Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/27/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069687271

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019907176
Registry ID: 110069687271
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069687271

J179
WNW
< 1/8
0.081 mi.
429 ft.

LOT 45,TAXBLOCK 2250
WALLABOUT STREET
BROOKLYN, NY 11206

Site 1 of 17 in cluster J

NY E DESIGNATION **S122872747**
N/A

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 45,TAXBLOCK 2250
Address:	WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	45
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

H180
NW
< 1/8
0.081 mi.
429 ft.

LOT 129,TAXBLOCK 2250
THROOP AVENUE
BROOKLYN, NY 11206

Site 7 of 16 in cluster H

NY E DESIGNATION **S110242345**
N/A

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 129,TAXBLOCK 2250
Address:	THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	129
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

H181 **LOT 32,TAXBLOCK 2250** **NY E DESIGNATION** **S110242389**
NW **62 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.081 mi.
429 ft. **Site 8 of 16 in cluster H**

Relative: E DESIGNATION:
Lower

Actual:
13 ft.

Name:	LOT 32,TAXBLOCK 2250
Address:	62 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	32
Tax Block:	2250
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

K182 **LOT 1,TAXBLOCK 2266** **NY E DESIGNATION** **S110242337**
West **HARRISON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.082 mi.
431 ft. **Site 1 of 14 in cluster K**

Relative: E DESIGNATION:
Lower

Actual:
13 ft.

Name:	LOT 1,TAXBLOCK 2266
Address:	HARRISON AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	1
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

LOT 1,TAXBLOCK 2266 (Continued) **S110242337**

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

F183 **LOT 55,TAXBLOCK 2272** **NY E DESIGNATION** **S110242443**
SSW **659 FLUSHING AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.082 mi.
432 ft. **Site 19 of 19 in cluster F**

Relative: **Lower**

Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 55,TAXBLOCK 2272
Address:	659 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	55
Tax Block:	2272
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

E184 **ACE RAPID CLEANERS** **EDR Hist Cleaner** **1018500263**
SSW **209 HARRISON AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.083 mi.
438 ft. **Site 17 of 19 in cluster E**

Relative: **Lower**

Actual: **13 ft.**

EDR Hist Cleaner

Year:	Name:	Type:
1970	ACE RAPID CLEANERS	Drycleaning Plants, Except Rugs
1971	ACE RAPID CLEANERS	Drycleaning Plants, Except Rugs
1972	ACE RAPID CLEANERS	Drycleaning Plants, Except Rugs
1973	ACE RAPID CLEANERS	Drycleaning Plants, Except Rugs
1974	ACE RAPID CLEANERS	Drycleaning Plants, Except Rugs
1975	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1976	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1977	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1978	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1979	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1980	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1982	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1983	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1985	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1986	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs

ACE RAPID CLEANERS (Continued) **1018500263**

1987	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1988	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1989	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1990	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1991	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1992	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1993	209 HARRISON CLEANERS INC	Drycleaning Plants, Except Rugs
1995	ACE RAPID CLEANERS INC	Drycleaning Plants, Except Rugs
1996	ACE RAPID CLEANERS INC	Drycleaning Plants, Except Rugs
1997	ACE RAPID CLEANERS INC	Drycleaning Plants, Except Rugs

E185 **HARRISON/YORKTOWN/ACE RAPID DRYCLEANERS** **NY DRYCLEANERS** **S106435386**
SSW **209 HARRISON AVENUE #A** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.083 mi.
438 ft. **Site 18 of 19 in cluster E**

Relative: DRYCLEANERS:
Lower

Name:	HARRISON/YORKTOWN/ACE RAPID DRYCLEANERS
Address:	209 HARRISON AVENUE #A
City,State,Zip:	BROOKLYN, NY 11206
Facility ID:	2-6104-00956
Phone Number:	718-486-9164
Region:	Not reported
Registration Effective Date:	8/5/2005
Inspection Date:	18MAY18
Install Date:	-/05/18
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Actual:
13 ft.

E186 **ACE RAPID CLEANERS** **RCRA NonGen / NLR** **1000129464**
SSW **209 HARRISON AVE** **ICIS** **NYD045446994**
< 1/8 **BROOKLYN, NY 11206** **US AIRS**
0.083 mi. **NY MANIFEST**
438 ft. **Site 19 of 19 in cluster E**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	01/01/2007
Facility name:	ACE RAPID CLEANERS
Facility address:	209 HARRISON AVE BROOKLYN, NY 11206
EPA ID:	NYD045446994
Mailing address:	HARRISON AVE BROOKLYN, NY 11206
Contact:	Not reported
Contact address:	HARRISON AVE BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
13 ft.

ACE RAPID CLEANERS (Continued) **1000129464**

Owner/Operator Summary:
Owner/operator name: HAROLD GREENSTEIN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: HAROLD GREENSTEIN
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ACE RAPID CLEANERS
Classification: Not a generator, verified

Date form received by agency: 04/05/1995
Site name: ACE RAPID CLEANERS
Classification: Not a generator, verified

Date form received by agency: 12/24/1985
Site name: ACE RAPID CLEANERS
Classification: Large Quantity Generator

ACE RAPID CLEANERS (Continued) **1000129464**

Hazardous Waste Summary:

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

ICIS:

Enforcement Action ID: NY000A0000261040095600310
FRS ID: 110004355830
Action Name: HARRISON DRY CLEANERS 36047R311200310
Facility Name: HARRISON DRY CLEANERS
Facility Address: 209 HARRISON AVE
BROOKLYN, NY 112065034
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.70023
Longitude in Decimal Degrees: -73.94725
Permit Type Desc: Not reported
Program System Acronym: NY0000002610400956
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040095600305
FRS ID: 110004355830
Action Name: HARRISON DRY CLEANERS 36047R311200305
Facility Name: HARRISON DRY CLEANERS
Facility Address: 209 HARRISON AVE
BROOKLYN, NY 112065034
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.70023
Longitude in Decimal Degrees: -73.94725
Permit Type Desc: Not reported
Program System Acronym: NY0000002610400956
Facility NAICS Code: 812320

ACE RAPID CLEANERS (Continued) **1000129464**

Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040095600301
FRS ID: 110004355830
Action Name: HARRISON DRY CLEANERS 36047R311200301
Facility Name: HARRISON DRY CLEANERS
Facility Address: 209 HARRISON AVE
BROOKLYN, NY 112065034
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.70023
Longitude in Decimal Degrees: -73.94725
Permit Type Desc: Not reported
Program System Acronym: NY0000002610400956
Facility NAICS Code: 812320
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1000129464
Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-11-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-06-07 00:00:00
Activity Status Date: Not reported

ACE RAPID CLEANERS (Continued) **1000129464**

Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002610400956
Facility Registry ID:	110004355830
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2004-04-12 00:00:00
Activity Status Date:	2004-04-12 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved
Region Code:	02
Programmatic ID:	AIR NY0000002610400956
Facility Registry ID:	110004355830
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2005-06-08 00:00:00
Activity Status Date:	2005-06-08 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved
Region Code:	02
Programmatic ID:	AIR NY0000002610400956
Facility Registry ID:	110004355830
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2005-08-01 00:00:00
Activity Status Date:	2005-08-01 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved
Region Code:	02
Programmatic ID:	AIR NY0000002610400956
Facility Registry ID:	110004355830
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2003-11-17 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002610400956
Facility Registry ID:	110004355830
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN

ACE RAPID CLEANERS (Continued) **1000129464**

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-06-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-04-12 00:00:00
Activity Status Date: 2004-04-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-06-08 00:00:00
Activity Status Date: 2005-06-08 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

US AIRS MINOR:
Envid: 1000129464
Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-11-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

ACE RAPID CLEANERS (Continued) **1000129464**

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-06-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-04-12 00:00:00
Activity Status Date: 2004-04-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-06-08 00:00:00
Activity Status Date: 2005-06-08 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-08-01 00:00:00
Activity Status Date: 2005-08-01 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-11-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ACE RAPID CLEANERS (Continued) **1000129464**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-06-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-04-12 00:00:00
Activity Status Date: 2004-04-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400956
Facility Registry ID: 110004355830
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-06-08 00:00:00
Activity Status Date: 2005-06-08 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

NY MANIFEST:
Name: ACE RAPID CLNRS
Address: 209 HARRISON AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYD045446994
Facility Status: Not reported
Location Address 1: 209 HARRISON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:

ACE RAPID CLEANERS (Continued) **1000129464**

EPAID:	NYD045446994
Mailing Name:	ACE RAPID CLNRS
Mailing Contact:	ACE RAPID CLNRS
Mailing Address 1:	209 HARRISON AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183881218

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD000564908
Trans2 State ID:	MIT270012321
Generator Ship Date:	04/18/2018
Trans1 Recv Date:	04/18/2018
Trans2 Recv Date:	04/24/2018
TSD Site Recv Date:	04/27/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD045446994
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	017160529JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	130
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported

ACE RAPID CLEANERS (Continued) **1000129464**

Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
8 additional NY MANIFEST: record(s) in the EDR Site Report.

J187 **LOT 46,TAXBLOCK 2250** **NY E DESIGNATION** **S110242422**
WNW **291 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.083 mi.
439 ft. **Site 2 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:
Name: LOT 46,TAXBLOCK 2250
Address: 291 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 46
Tax Block: 2250
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

K188 **V4821** **RCRA NonGen / NLR** **1007206956**
WSW **48 GERRY STREET** **NY MANIFEST** **NYP004034575**
< 1/8 **NEW YORK CITY, NY 11206**
0.083 mi.
439 ft. **Site 2 of 14 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/03/2001
Facility name: V4821
Facility address: 48 GERRY STREET
NEW YORK CITY, NY 11206
EPA ID: NYP004034575
Mailing address: CONSOLIDATED EDISON INC.
4 IRVING PLACE -- ROOM 300
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS

V4821 (Continued) **1007206956**

Contact address: CONSOLIDATED EDISON INC.
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/02/2001
Site name: V4821
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V4821
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Address: 48 GERRY STREET
City,State,Zip: NEW YORK CITY, NY 11206
Country: USA
EPA ID: NYP004034575
Facility Status: Not reported
Location Address 1: V2107-2-48 GERRY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: N/S
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004034575
Mailing Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Mailing Contact: FRANKLIN MURRAY

V4821 (Continued) **1007206956**

Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0256410
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	31877AJ
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/1999
Trans1 Recv Date:	01/08/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/11/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004034575
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	02945
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

J189 **LOT 9,TAXBLOCK 2266** **NY E DESIGNATION** **S110242450**
West **366 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.084 mi.
444 ft. **Site 3 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 9,TAXBLOCK 2266
Address:	366 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	9
Tax Block:	2266
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

J190 **CON EDISON SERVICE BOX: 7968** **RCRA NonGen / NLR** **1016970893**
West **366 WALLABOUT ST** **NY MANIFEST** **NYP004446225**
< 1/8 **BROOKLYN, NY 11206**
0.084 mi.
444 ft. **Site 4 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/19/2014
Facility name:	CON EDISON SERVICE BOX: 7968
Facility address:	366 WALLABOUT ST BROOKLYN, NY 11206
EPA ID:	NYP004446225
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON SERVICE BOX: 7968 (Continued) **1016970893**

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/19/2014
Site name: CON EDISON SERVICE BOX: 7968
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 366 WALLABOUT ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004446225
Facility Status: Not reported
Location Address 1: 366 WALLABOUT ST & HARRISON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004446225
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported

CON EDISON SERVICE BOX: 7968 (Continued) **1016970893**

Generator Ship Date:	02/19/2014
Trans1 Recv Date:	02/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004446225
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697886JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

L191 **LOT 3,TAXBLOCK 2272** **NY E DESIGNATION** **S110242384**
SSW **207 HARRISON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.085 mi.
451 ft. **Site 1 of 32 in cluster L**

Relative: E DESIGNATION:
Lower

Actual: Name:	LOT 3,TAXBLOCK 2272
13 ft. Address:	207 HARRISON AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	3
Tax Block:	2272

LOT 3,TAXBLOCK 2272 (Continued) **S110242384**

Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

L192 **207 HARRISON AVENUE** **NY VCP** **S118943213**
SSW **207 HARRISON AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.085 mi.
451 ft. **Site 2 of 32 in cluster L**

Relative:
Lower

Actual:
13 ft.

VCP NYC:

Project ID:	13CVCP074K
Project Name:	207 HARRISON AVENUE
Project Address:	207 HARRISON AVENUE
Borough:	BROOKLYN

VCP NYC:

Project ID:	13CVCP074K
File Name:	2012-09-12.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-09-12.13CVCP074K.207_Harrison_Ave.RIR.pdf
Project ID:	13CVCP074K
File Name:	2012-09-12.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-09-12.13CVCP074K.207_Harrison_Ave.RAWP_Draft.pdf
Project ID:	13CVCP074K
File Name:	2012-09-12.FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-09-12.13CVCP074K.207_Harrison_Ave.FactSheet1.pdf
Project ID:	13CVCP074K
File Name:	2012-09-13.Translated_FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-09-13.13CVCP074K.207_Harrison_Ave.Translated_FactSheet1.pdf
Project ID:	13CVCP074K
File Name:	2012-09-13.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-09-13.13CVCP074K.207_Harrison_Ave.Translated_Community_Protection_Statement.pdf

207 HARRISON AVENUE (Continued) **S118943213**

Project ID: 13CVCP074K
File Name: 2012-10-10.Stipulation_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-10-10.13CVCP074K.207_Harrison_Ave.Stipulation_List.pdf

Project ID: 13CVCP074K
File Name: 2012-10-17.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-10-17.13CVCP074K.207_Harrison_Ave.Decision_Document.pdf

Project ID: 13CVCP074K
File Name: 2012-11-08.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-11-08.13CVCP074K.207_Harrison_Ave.FactSheet2.pdf

Project ID: 13CVCP074K
File Name: 2012-11-12.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP074K/2012-11-12.13CVCP074K.207_Harrison_Ave.Translated_FactSheet2.pdf

---

J193 **LOT 48,TAXBLOCK 2250** **NY E DESIGNATION** **S110242429**
WNW **289 WALLABOUT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.087 mi.
461 ft. **Site 5 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:
Name: LOT 48,TAXBLOCK 2250
Address: 289 WALLABOUT STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 48
Tax Block: 2250
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

M194 **APARTMENT BUILDING** **NY Spills** **S104951601**
North **613 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.088 mi.
466 ft. **Site 1 of 5 in cluster M**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	APARTMENT BUILDING
Address:	613 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Spill Number/Closed Date:	0013601 / 2009-12-14
Facility ID:	0013601
Facility Type:	ER
DER Facility ID:	264684
Site ID:	328889
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-03-28
Investigator:	RVKETANI
Referred To:	MOORE
Reported to Dept:	2001-03-28
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-28
Spill Record Last Update:	2009-12-14
Spiller Name:	SLAVIK
Spiller Company:	WALLABOUT DEVELOPMENT, LLC
Spiller Address:	613 BROADWAY
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE assigned to C. Whitfield in backlog initiative; no file received from region. Original 3/28/01 site info indicates caller was a contractor asked for quote for soil cleanup as part of construction project. The caller was not selected for the work due to price. A search of spills database by location did not reveal any other spill report, however, Property Shark indicated the location is also known as 331 - 341 Wallabout Street. On May 1, 2001 Wallabout Development, LLC was registered with NYSDOS. This location is now occupied by a 7 story 101' X 72' condo built in 2001 owned by Wallabout Development. Next step is to pursue new owner for documentation of soil removal or close administratively. 10/2/09 - Austin - Spill transferred from Albany staff to Ketani, for further investigation - end 10/27/09 - Raphael Ketani. The spill was discovered or took place on 3/28/01. It consisted of a call from someone at a construction company to PTC, an oil spill cleanup contractor. PTC called in the spill, but the nature of the spill was not known. The spill site address is 613 Broadway. However, the previous DEC case manager thought that the site was the location of a condo building that was under construction. This

APARTMENT BUILDING (Continued) **S104951601**

location is 614 Broadway and is listed in Property Shark as the same block and lot as 331-341 Wallabout Street. The block and lot is listed in Property Shark as 2251 and 7501, but ACRIS lists the block as 1003. On top of this, Property Shark doesn't list the address 613. The closest one is 607 and this belongs to the Lindsay Park Houses. So it is not clear whether the condo building is the correct spill location. If 614 Broadway is the correct address, then the condominium building is the correct site. The construction company was Wallabout Development, LLC, 341 Wallabout Street, Ste 1A, Brooklyn, 11206. The general builder was Wallabout Development, Inc., 1454 42 Street, Brooklyn, 11219. Mr. Slavik (917) 364-5803 was the last contact at Wallabout. The site is near the intersection of Manhattan Avenue and Broadway. There is no PBS registration, nor a case file, nor any E-docs. I will make a site visit. 12/7/09 - Raphael Ketani. I made an unannounced site visit. The building is of relatively new construction. It is a brick apartment building and sits at the corner of Wallabout Street and Broadway. A side entrance had the address 610 Broadway. A doctor's office is at 341 Wallabout Street. I could not locate the other alternate address, 331 Wallabout Street. I did not see a management company address or name plate in the lobby for the building. There were no oil odors. I rechecked the block and lot information with the address of 331 to 341 Wallabout Street. ACRIS indicated that the block and lot were 2251 and 1003. The owner appears to be Broadway Wallabout Realty, LLC, 341 Wallabout Street, apt 1A, Brklyn, 11206. 12/8/09 - Raphael Ketani. I contacted Mr. Slavik, the last known party who was involved in the building construction. He told me to contact K I Construction (718) 387-0400. I contacted K I Construction and spoke to one of the owners, Aron Kapelyus. He said that the building was built 6 years ago. However, before this, it was a vacant lot for 15 years. Mr. Kapelyus said that the lot was dug out in order to construct the foundation. I asked him whether the basement is one level or two levels. He said that it was just one level and that the digging went down 6 feet. I asked him where the oil contaminated soil was sent to. He said that there was no oil contaminated soil. I asked him whether he can send me copies of the soil disposal manifests. He said that he has none. I asked him whether he can send me a copy of the construction plan for the foundation. He said that he will e-mail it to me. He passed my call to Carol, his secretary, and she took down my e-mail information. 12/14/09 - Raphael Ketani. I never received the plans for the foundation, nor the excavation for the foundation. As the contaminated soil was most likely removed as part of the soil excavation to at least 6 feet below grade, as there were no oil odors in the lobby, nor visible impacts from any contaminated soil, as there is no further information regarding the spill, and as there doesn't appear to be any threat to human safety, or the environment, I am closing the spill case."

Remarks: "CALLER WAS CONTACTED TO GIVE A PRICE ON A CLENA UP JOB AT THE ABOVE LOCATION SITE IS UNDER CONSTRUCTION AFTER CALLER GAVE HIS PRICE THEY TOLD HIM IT WAS TOO MUCH HE IS REPORTING SPILL TO COVER HIMSELF UNK WHEN SPILL OCCURED OR IF IT MAY HAVE ALREADY BEEN REPORTED"

All Materials:

Site ID:	328889
Operable Unit ID:	835084
Operable Unit:	01
Material ID:	540309
Material Code:	0001A

APARTMENT BUILDING (Continued) **S104951601**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H195 **LOT 29,TAXBLOCK 2250** **NY E DESIGNATION** **S110242380**
NW **56 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.088 mi.
467 ft. **Site 9 of 16 in cluster H**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 29,TAXBLOCK 2250
Address:	56 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	29
Tax Block:	2250
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

J196 **SERVICE BOX # 7967** **NY Spills** **S106970181**
West **285 WALLABOUT ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.089 mi.
469 ft. **Site 6 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:

Name:	SERVICE BOX # 7967
Address:	285 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0505280 / 2005-09-28
Facility ID:	0505280
Facility Type:	ER
DER Facility ID:	296672
Site ID:	350231

SERVICE BOX # 7967 (Continued) **S106970181**

DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-07-29
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-08-01
CID:	77
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-01
Spill Record Last Update:	2005-09-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN.
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT DESK'
DEC Memo:	"160131. 7/29/2005 10:45 HRS J. LOPEZ #38003 MECH A REPORTS FINDING APPROX 3 PTS OF UNKNOWN OIL ON APPROX 50 GALS OF WATER IN SB7967. THIS WAS FOUND WHILE CUTTING THE SERVICE ON A DEMO JOB ACCT#44559. THERE WAS NO SMOKE, FIRE, OR INJURIES RELATED TO THE SPILL, NOR WERE ANY SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. THE SOURCE AND CAUSE OF THE SPILL IS UNKNOWN. THE STANDING WATER IN THE STRUCTURE HAD NO MOVEMENT. ENV STOP TAG#22809 WAS PLACED, AND ONE LIQUID SAMPLE TAKEN ON E PRIORITY FOR PCB ANALYSIS ON CHAIN OF CUSTODY# EE08259. THE SAMPLE WILL BE TAKEN BACK TO 3RD AVE YARD FOR PICK UP BY COURIER. J ANDERSON Lab Sequence Number: 05-07849-001 Aroclor 1242 < 1.0 ppm EPA 608/8082 Aroclor 1254 < 1.0 ppm EPA 608/8082 Aroclor 1248 < 1.0 ppm EPA 608/8082 Aroclor 1260 < 1.0 ppm EPA 608/8082 ========== 7/31/2005 12:07 HRS. -- A. GLODOWSKI OF BROOKLYN ENV OPS REPORTS ON LOCATION FOR CLEANUP AND FOUND CAR PARKED OVER MANHOLE WITH OUT-OF-STATE LICENSE PLATES. 7/31/2005 12:12 HRS. -- AS PER BROOKLYN ENV OPS SUPERVISOR B. BRIAN, INCIDENT TO REMAINS ON 72-HOUR DEMINIMIS AT THIS TIME. WILL ATTEMPT AGAIN ON FUTURE SHIFT. -- W.W. #17344 -- UPDATE 01-AUG-2005 06:25 HRS. AS PER A CONVERSATION BETWEEN ENVIR. OPER. B.BROWN & E.VESCE, INCIDENT 160131 WILL NOT BE MEETING THE 72HR CLOCK AND WILL BE RECLASSIFIED AS SPILL - OIL (UNKNOWN TYPE) DUE TO OUT OF STATE CAR OVER STRUCTURE. C.HOGAN 07511 UPDATE 01-AUG-2005 11:40 HRS. ENVIR. OPER. MECH-A R.VEGA EMP# 04005 REPORTS: DBL. WASHED STRUCTURE WITH BIOGEN 760 NO SUMP IN STRUCTURE, ENVIR. TAG# 22809 REMOVED. CLEANUP COMPLETE 100%. C.HOGAN 07511 Closed. 9-28-05. GB "
Remarks:	"3 PINTS OF UNKN OIL ON 50 GALS WATER. CLEAN UP PENDING VEHICLE REMOVAL FROM ACCESS POINT. COMING OFF 72HR CLOCK. LAB RESULTS LESS THAN 1PPM. CON ED REF 160131."

All Materials:

Site ID:	350231
Operable Unit ID:	1107811

SERVICE BOX # 7967 (Continued) **S106970181**

Operable Unit:	01
Material ID:	2097697
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K197 **BAIS RUCHEL HIGH SCHOOL INC** **RCRA-LQG** **1014919590**
WSW **177 HARRISON AVE** **NJ MANIFEST** **NYR000183780**
< 1/8 **BROOKLYN, NY 11206** **NY MANIFEST**
0.090 mi.
476 ft. **Site 3 of 14 in cluster K**

Relative:
Lower

Actual:
13 ft.

RCRA-LQG:

Date form received by agency:	04/24/2012
Facility name:	BAIS RUCHEL HIGH SCHOOL INC
Facility address:	177 HARRISON AVE BROOKLYN, NY 11206
EPA ID:	NYR000183780
Mailing address:	LEE AVE CO UTA BROOKLYN, NY 11211
Contact:	WOLF ENGLENDER
Contact address:	LEE AVE BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	718-963-9260
Telephone ext.:	1277
Contact email:	WOLFE@UTAW.ORG
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONGREGATION YGS
Owner/operator address:	RODNEY ST BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	718-963-9260
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/11/2004
Owner/Op end date: Not reported

Owner/operator name: CONGREGATION YGS
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/11/2004
Owner/Op end date: Not reported

Owner/operator name: CONGREGRATION YGS
Owner/operator address: RODNEY ST
BROOKLYN, NY 11211
Owner/operator country: US
Owner/operator telephone: 718-963-9260
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/11/2004
Owner/Op end date: Not reported

Owner/operator name: CONGREGRATION YGS
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/11/2004
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/14/2012
Site name: BAIS RUCHEL HIGH SCHOOL INC
Classification: Not a generator, verified

Date form received by agency: 09/07/2011
Site name: BAIS RUCHEL HIGH SCHOOL INC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYR000183780
Mail Address: 82 LEE AVE
Mail City/State/Zip: BROOKLYN, NY 11211
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: WOLF ENGLENDER
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 008928193JJK
EPA ID: NYR000183780
Date Shipped: 10/24/2011
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	38,880.00 Pounds

Manifest Number:	008930788JJK
EPA ID:	NYR000183780
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	42,480.00 Pounds

Manifest Number:	008928177JJK
EPA ID:	NYR000183780
Date Shipped:	10/24/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11211
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 48,620.00 Pounds

Manifest Number: 008930773JJK
EPA ID: NYR000183780
Date Shipped: 10/6/2011
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11211
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 45,680.00 Pounds

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Manifest Number:	008930786JJK
EPA ID:	NYR000183780
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	44,780.00 Pounds

Manifest Number:	008930789JJK
EPA ID:	NYR000183780
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	38,660.00 Pounds

Manifest Number:	008930777JJK
EPA ID:	NYR000183780
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	39,280.00 Pounds

Manifest Number:	008930801JJK
EPA ID:	NYR000183780
Date Shipped:	10/7/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	41,220.00 Pounds

Manifest Number:	008928170JJK
EPA ID:	NYR000183780
Date Shipped:	10/24/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	39,220.00 Pounds
Manifest Number:	008928174JJK
EPA ID:	NYR000183780
Date Shipped:	10/24/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	45,140.00 Pounds
Manifest Number:	008930800JJK
EPA ID:	NYR000183780

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Date Shipped:	10/7/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	45,620.00 Pounds

Manifest Number:	008930802JJK
EPA ID:	NYR000183780
Date Shipped:	10/7/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	44,780.00 Pounds

Manifest Number:	008930776JJK
EPA ID:	NYR000183780
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	41,580.00 Pounds

Manifest Number:	008930794JJK
EPA ID:	NYR000183780
Date Shipped:	10/7/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	40,360.00 Pounds

Manifest Number:	008928171JJK
EPA ID:	NYR000183780
Date Shipped:	10/24/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	49,440.00 Pounds

Manifest Number:	008930779JJK
EPA ID:	NYR000183780
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	40,220.00 Pounds

Manifest Number:	008930798JJK
EPA ID:	NYR000183780
Date Shipped:	10/7/2011
TSDF EPA ID:	NJD991291105

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	46,540.00 Pounds

Manifest Number:	008928185JJK
EPA ID:	NYR000183780
Date Shipped:	10/24/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	41,880.00 Pounds

Manifest Number:	008930780JJK
EPA ID:	NYR000183780
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11211
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	44,660.00 Pounds

Manifest Number:	008928172JJK
EPA ID:	NYR000183780
Date Shipped:	10/24/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 11211
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 36,500.00 Pounds

NY MANIFEST:
Name: BAIS RUCHEL HIGH SCHOOL INC
Address: 177 HARRISON AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYR000183780
Facility Status: Not reported
Location Address 1: 177 HARRISON AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000183780
Mailing Name: BAIS RUCHEL HIGH SCHOOL INC
Mailing Contact: CONGREGATION YGS
Mailing Address 1: 174 RODNEY STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11211
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7189639260

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 10/24/2011
Trans1 Recv Date: 10/24/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/24/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported

BAIS RUCHEL HIGH SCHOOL INC (Continued) **1014919590**

Generator EPA ID:	NYR000183780
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	008928170JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	39220.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

K198 **177 HARRISON AVENUE** **NY VCP** **S118943163**
WSW **177 HARRISON AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.090 mi.
476 ft. **Site 4 of 14 in cluster K**

Relative:
Lower

Actual:
13 ft.

VCP NYC:

Project ID:	12CBCP019K
Project Name:	177 HARRISON AVENUE
Project Address:	177 HARRISON AVENUE
Borough:	BROOKLYN

VCP NYC:

Project ID:	12CBCP019K
File Name:	2011-06-29.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP019K/2011-06-29.12CBCP019K.177_Harrison_Ave.RIR.pdf

177 HARRISON AVENUE (Continued) **S118943163**

Project ID:	12CBCP019K
File Name:	2011-07-22.FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP019K/2011-07-22.12CBCP019K.177_Harrison_Ave.FactSheet1.pdf
Project ID:	12CBCP019K
File Name:	2011-07-22.RAWP_Final
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP019K/2011-07-22.12CBCP019K.177_Harrison_Ave.RAWP_Final.pdf
Project ID:	12CBCP019K
File Name:	2011-08-24.Decision_Document
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP019K/2011-08-24.12CBCP019K.177_Harrison_Ave.Decision_Document.pdf
Project ID:	12CBCP019K
File Name:	2011-09-28.FactSheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP019K/2011-09-28.12CBCP019K.177_Harrison_Ave.FactSheet2.pdf

---

L199 **MANHOLE #73645** **NY Spills** **S106969804**
SW **HARRISON AVE NEAR BARTLETT ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.091 mi.
482 ft. **Site 3 of 32 in cluster L**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	MANHOLE #73645
Address:	HARRISON AVE NEAR BARTLETT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0504634 / 2005-09-23
Facility ID:	0504634
Facility Type:	ER
DER Facility ID:	295936
Site ID:	349511
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	2401
Spill Date:	2005-07-17
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-07-18
CID:	407
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-18
Spill Record Last Update:	2005-09-23
Spiller Name:	Not reported
Spiller Company:	UNKNOWN ATTHIS TIME

MANHOLE #73645 (Continued) **S106969804**

Spiller Address: Not reported
Spiller Company: 001
Contact Name: ERT DESK'
DEC Memo: "159806. 7/17/2005 20:10 HRS. E. WILLIAMS #56346, O/S WITH ENVIRONMENTAL OPS, REPORTS WHILE ON LOCATION TO FLUSH MANHOLE FOR UNDERGROUND PLANNING (ACCT # C7515) AT 20:00 HRS. FOUND APPROX. 1 PINT UNKNOWN OIL ON APPROX. 70 GAL WATER IN MH-73645. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE OR SMOKE INVOLVED. ENV STOP TAG 48268 PLACED. LIQUID SAMPLE TAKEN. CHAIN OF CUSTODY FORM DD-11375 MARKED FOR E PRIORITY TURNAROUND 24-HOUR DEMINIMIS. CLEANUP PENDING PCB RESULTS FROM CHEM LAB. W. WAINWRIGHT #17344 UPDATE 7-18-05 06:30 HRS LAB SEQ# 05-07285-001 <1.0 PPM. UPDATE 7/18/05 12:55 HRS ENV OPS FERNANDEZ REPORTS THE STRUCTURE WAS DOUBLE WASHED WITH BIO-GEN 760, A SEALED SUMP WAS FOUND, AND THE ENV TAG REMAINS IN PLACE DUE TO ROCKS AND WOOD IN STRUCTURE TO BE REMOVED BY ENV OPS ON THE NEXT SHIFT. J ANDERSON UPDATE: 7/18/05 - 1815. D. LICHTENSTEIN - ENV. OPS., REPORTS VEHICLE HAS LOST SUCTION. HE WILL HAVE TO DRIVE BACK TO THE 3RD AVE YD, DUMP HIS TRUCK, TURN IT IN AND PICK UP ANOTHER VEHICLE TO COMPLETE THIS JOB. OTHER CREWS ARE BUSY WITH #9 AND THE FOD. THERE IS NOT ENOUGH TIME TO FINISH THIS JOB WITHIN THE 24 HR TIME LIMIT. THIS INCIDENT IS NOW OFF THE 24 HR CLOCK. TJ - 50495. UPDATE: 7/19/05 - 0250. D. LICHTENSTEIN - 08078 - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH BIO GEN 760. SUMP FOUND SEALED. NO DRAINS. TAG # 48266 REMOVED. TJ - 50495. Closed. 9-23-05. GB "
Remarks: "Amount is 1 pint in 70 gallons of water no to the 5 ?'s, taken off of 24 hour program, con ed #159806"

All Materials:
Site ID: 349511
Operable Unit ID: 1107109
Operable Unit: 01
Material ID: 2097005
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

L200 **BARTLETT ST & HARRISON** **NY Spills** **S106014127**
SW **BARTLETT STREET/HARRISON** **N/A**
< 1/8 **BROOKLYN, NY**
0.091 mi.
482 ft. **Site 4 of 32 in cluster L**

Relative: SPILLS:
Lower
Actual: Name: BARTLETT ST & HARRISON
13 ft. Address: BARTLETT STREET/HARRISON
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0330009 / 2003-05-16
Facility ID: 0330009
Facility Type: ER
DER Facility ID: 59300
Site ID: 60814

BARTLETT ST & HARRISON (Continued) **S106014127**

DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	2401
Spill Date:	2003-05-16
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2003-05-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-19
Spill Record Last Update:	2003-05-19
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE No Action taken."
Remarks:	"Anonomous caller reports School bus leaking diesel and oil at the intersection of Bartlett Street and Harrison in Brooklyn"

All Materials:

Site ID:	60814
Operable Unit ID:	881429
Operable Unit:	01
Material ID:	496509
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	60814
Operable Unit ID:	881429
Operable Unit:	01
Material ID:	496507
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L201 **PFIZER INC** **CORRACTS** **1000443177**
SW **11 BARTLETT ST** **RCRA-LQG** **NYD001374214**
< 1/8 **BROOKLYN, NY 11206** **RAATS**
0.093 mi. **FINDS**
490 ft. **Site 5 of 32 in cluster L** **ECHO**

Relative: Lower

Actual: 13 ft.

CORRACTS:

EPA ID:	NYD001374214
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19940419
Action:	CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority
NAICS Code(s):	Not reported
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD001374214
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19920922
Action:	CA050 - RFA Completed
NAICS Code(s):	Not reported
Original schedule date:	Not reported
Schedule end date:	Not reported

RCRA-LQG:

Date form received by agency:	03/04/2008
Facility name:	PFIZER INC
Facility address:	13 BARTLETT ST BROOKLYN, NY 11206
EPA ID:	NYD001374214
Mailing address:	RTE 206 NORTH PEAPACK, NJ 07977
Contact:	RUSSELL G DOWNEY
Contact address:	RTE 206 NORTH PEAPACK, NJ 07977
Contact country:	US
Contact telephone:	908-901-6079
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	PFIZER INC

PFIZER INC (Continued) **1000443177**

Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1851
Owner/Op end date: Not reported

Owner/operator name: PFIZER INC
Owner/operator address: ROUTE 206 NORTH M/S 611
PEAPACK, NJ 07977
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1851
Owner/Op end date: Not reported

Owner/operator name: PFIZER INC
Owner/operator address: ROUTE 206 NORTH M/S 611
PEAPACK, NJ 07977
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1851
Owner/Op end date: Not reported

Owner/operator name: PFIZER INC
Owner/operator address: RTE 206 NORTH
PEAPACK, NJ 07977
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1851
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No

PFIZER INC (Continued) **1000443177**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/03/2008
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 03/03/2008
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 01/01/2006
Site name: PFIZER INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PFIZER INC
Classification: Not a generator, verified

Date form received by agency: 03/01/1990
Site name: PFIZER INC BROOKLYN PLANT
Classification: Large Quantity Generator

Date form received by agency: 11/19/1980
Site name: PFIZER INC
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: PFIZER INC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: B007
. Waste name: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003

PFIZER INC (Continued) **1000443177**

. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D009
. Waste name: MERCURY

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U044

PFIZER INC (Continued) **1000443177**

. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U115
. Waste name: ETHYLENE OXIDE (I,T) (OR) OXIRANE (I,T)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U188
. Waste name: PHENOL

. Waste code: U219
. Waste name: THIOUREA

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Corrective Action Summary:
Event date: 09/22/1992
Event: RFA COMPLETED

Event date: 04/19/1994
Event: CA PRIORITIZATION-MEDIUM CA PRIORITY

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/01/1987
Date achieved compliance: 06/01/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General

PFIZER INC (Continued) **1000443177**

Date violation determined: 06/24/1985
Date achieved compliance: 07/24/1985
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 12/30/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 3000
Paid penalty amount: 3000

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/01/1985
Date achieved compliance: 08/11/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/11/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/05/1985
Date achieved compliance: 08/11/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/11/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/05/1985
Date achieved compliance: 08/01/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/11/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/14/1984

PFIZER INC (Continued) **1000443177**

Date achieved compliance: 08/20/1984
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/31/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 10000
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 10/09/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/01/1987
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 06/01/1987
Evaluation lead agency: State

Evaluation date: 04/08/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/16/1986
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/24/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/24/1985
Evaluation lead agency: EPA

Evaluation date: 03/28/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/01/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 08/11/1985
Evaluation lead agency: State

Evaluation date: 02/05/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General

PFIZER INC (Continued) **1000443177**

Date achieved compliance: 08/01/1985
Evaluation lead agency: State

Evaluation date: 02/05/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 08/11/1985
Evaluation lead agency: State

Evaluation date: 08/20/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 06/18/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/14/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 08/20/1984
Evaluation lead agency: EPA

RAATS:
No Details: Please contact your EDR Account Executive for more information about this site

FINDS:

Registry ID: 110042026642

Environmental Interest/Information System
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit

PFIZER INC (Continued) **1000443177**

Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000443177
Registry ID:	110042026642
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110042026642

M202 **VAULT 3871** **NY Spills** **S103937163**
North **MOORE AND LEONARD ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.093 mi.
490 ft. **Site 2 of 5 in cluster M**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	VAULT 3871
Address:	MOORE AND LEONARD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9901618 / 2002-04-03
Facility ID:	9901618
Facility Type:	ER
DER Facility ID:	168749
Site ID:	202877
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-05-11
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-05-11
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-05-11
Spill Record Last Update:	2002-04-03
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	RIHCARD ROACH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT DEC INSPECTOR NOTES 5-12-99 ERT Ron Consentino Capacity

VAULT 3871 (Continued) **S103937163**

245 gal. Drained 215 gal. D= 30 gal. Liquid removed from structure Cement sump PCB - 9ppm historical Sample from vault - 11 from transfromer -14 Removing transformer today, cables cut. CON ED E2MIS NOTES 6-01-99 Approx. 35 gals. of oil on 400 gals. of water, no sewer connection in structure; no sewers or wayerways affected. Records indicate 9ppm PCB count. Lab Results;Lab seq#99-04906 11ppm 2236hrs. Update A bottom leaker, TM capacity is 245 gals. 5-12-99 Update 0332hrs. Removed 215 gals. oil from transformer Update 5-12-99 Lab Seq#99-04913 14ppm from inside of VS 3871 UPDATE 5-12-99 13:00HRS R. VEGA REPORTS, TRANSFORMER WAS REMOVED AND HE COMPLETED CLEANUP USING SLIX & ENV. STOP TAG # 07102 REMOVED. INCIDENT IS CLOSED. "

Remarks: "trapped in concrete vault 124806 - con ed #"

All Materials:

Site ID:	202877
Operable Unit ID:	1080376
Operable Unit:	01
Material ID:	305152
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	35.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N203 **LOT 16,TAXBLOCK 2274** **NY E DESIGNATION** **S110242355**
SE **134 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.093 mi.
491 ft. **Site 1 of 14 in cluster N**

Relative: **Higher**
Actual: **17 ft.**

E DESIGNATION:

Name:	LOT 16,TAXBLOCK 2274
Address:	134 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	16
Tax Block:	2274
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - #4 Fuel Oil for space heating and hot water systems
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

N204 **CON EDISON** **NY MANIFEST** **S121967538**
SE **701 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.094 mi.
494 ft. **Site 2 of 14 in cluster N**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	701 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP005021290
Facility Status:	Not reported
Location Address 1:	701 FLUSHING AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005021290
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N205 **CON EDISON - SERVICE BOX 7425** **RCRA-LQG** **1024890632**
SE **701 FLUSHING AVE** **NYP005021290**
< 1/8 **BROOKLYN, NY 11206**
0.094 mi.
494 ft. **Site 3 of 14 in cluster N**

Relative:
Higher

Actual:
17 ft.

RCRA-LQG:

Date form received by agency:	04/10/2018
Facility name:	CON EDISON - SERVICE BOX 7425
Facility address:	701 FLUSHING AVE BROOKLYN, NY 11206
EPA ID:	NYP005021290
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	ALYSSA SOTTO
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	SOTTOA@CONED.COM
EPA Region:	02

CON EDISON - SERVICE BOX 7425 (Continued) **1024890632**

Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-460-2757
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/18/2017
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-460-2757
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/18/2017
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No

CON EDISON - SERVICE BOX 7425 (Continued) **1024890632**

Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

K206 **CON ED - MH 485** **RCRA NonGen / NLR** **1007206268**
WSW **GERRY ST & HARRISON AVE** **NY MANIFEST** **NYP004006821**
< 1/8 **BROOKLYN, NY 11206**
0.094 mi.
498 ft. **Site 5 of 14 in cluster K**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:
Date form received by agency: 02/28/1998
Facility name: CON ED - MH 485
Facility address: GERRY ST & HARRISON AVE
BROOKLYN, NY 11206-0000
EPA ID: NYP004006821
Mailing address: CONSOLIDATED EDISON INC
4 IRVING PL RM 300
NEW YORK, NY 10003-0000
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC
NEW YORK, NY 10003-0000
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/27/1998
Site name: CON ED - MH 485
Classification: Not a generator, verified

Date form received by agency: 02/26/1998

CON ED - MH 485 (Continued) **1007206268**

Site name: CON ED - MH 485
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: GERRY ST & HARRISON AVE
City,State,Zip: BROOKLYN, NY 11206-0000
Country: USA
EPA ID: NYP004006821
Facility Status: Not reported
Location Address 1: MH485 - HARRISON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004006821
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYG0250407
Manifest Status: C
seq: Not reported
Year: 1997
Trans1 State ID: SM1563
Trans2 State ID: Not reported
Generator Ship Date: 05/13/1997
Trans1 Recv Date: 05/13/1997
Trans2 Recv Date: / /
TSD Site Recv Date: 05/14/1997
Part A Recv Date: 05/27/1997
Part B Recv Date: 05/23/1997
Generator EPA ID: NYP004006821
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported

CON ED - MH 485 (Continued) **1007206268**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	04325
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

K207 **UNDER GROUND TRANFORMER VAULT** **NY Spills** **S118459783**
WSW **HARRISON AVE AND GERRY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.094 mi.
498 ft. **Site 6 of 14 in cluster K**

Relative: SPILLS:
Lower

Actual: Name:	UNDER GROUND TRANFORMER VAULT
13 ft. Address:	HARRISON AVE AND GERRY STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1508657 / 2016-02-10
Facility ID:	1508657
Facility Type:	ER
DER Facility ID:	471585
Site ID:	517229
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2015-11-20
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2015-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-11-20
Spill Record Last Update:	2016-02-10

UNDER GROUND TRANFORMER VAULT (Continued) **S118459783**

Spiller Name:	ERTDESK
Spiller Company:	CON ED
Spiller Address:	HARRISON AVE AND GERRY STREET
Spiller Company:	999
Contact Name:	ERTDESK
DEC Memo:	"11/23/15- Ahmed - ConEd EMIS#243594 9 gallons oil on 400 gallons water contained in the vault structure. 2/10/16 - Austin - Con Ed contained and removed the spill; source was leaking transformer, which was replaced - See document files for further information - Spill closed - end"
Remarks:	"Spill contained to the vault. Clean up will start as soon as feeder is taken out of service."

All Materials:

Site ID:	517229
Operable Unit ID:	1266315
Operable Unit:	01
Material ID:	2270193
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	9.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

H208 **LOT 28,TAXBLOCK 2250** **NY E DESIGNATION S110242378**
NW **54 THROOP AVENUE** **NY MANIFEST N/A**
< 1/8 **BROOKLYN, NY 11206**
0.094 mi.
498 ft. **Site 10 of 16 in cluster H**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 28,TAXBLOCK 2250
Address:	54 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	28
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol

LOT 28,TAXBLOCK 2250 (Continued) **S110242378**

Lot Remediation Date: Not reported

NY MANIFEST:
Name: THROOP UNITS LLC
Address: 54 THROOP AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYR000231548
Facility Status: Not reported
Location Address 1: 54 THROOP AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000231548
Mailing Name: THROOP UNITS LLC
Mailing Contact: THROOP UNITS LLC
Mailing Address 1: 52 THROOP AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11206
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2017
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 05/15/2017
Trans1 Recv Date: 05/15/2017
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/15/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000231548
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: PAD085690592
TSDF ID 2: Not reported
Manifest Tracking Number: 010444132FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N

LOT 28,TAXBLOCK 2250 (Continued) **S110242378**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	26820
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
46 additional NY MANIFEST: record(s) in the EDR Site Report.

H209 **THROOP UNITS LLC** **RCRA-LQG** **1023679176**
NW **54 THROOP AVE** **NYR000231548**
< 1/8 **BROOKLYN, NY 11206**
0.094 mi.
498 ft. **Site 11 of 16 in cluster H**

Relative: RCRA-LQG:
Lower

Actual: Date form received by agency: 02/23/2018
13 ft.

Facility name:	THROOP UNITS LLC
Facility address:	54 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYR000231548
Mailing address:	LEE AVE BROOKLYN, NY 11211
Contact:	SOLOMON SCHWIMMER
Contact address:	LEE AVE BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	917-202-4746
Contact email:	SSCHWIMMER@TGANY.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting

THROOP UNITS LLC (Continued) **1023679176**

from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	SOLOMON SCHWIMMER
Owner/operator address:	LEE AVE
	BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	917-202-4746
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/23/2017
Owner/Op end date:	Not reported

Owner/operator name:	THROOP UNITS LLC
Owner/operator address:	LEE AVE - UNIT 554
	BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	917-202-4746
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/23/2016
Owner/Op end date:	Not reported

Owner/operator name:	SOLOMON SCHWIMMER
Owner/operator address:	LEE AVE
	BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	917-202-4746
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/23/2017
Owner/Op end date:	Not reported

Owner/operator name:	SOLOMON SCHWIMMER
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/23/2016
Owner/Op end date:	Not reported

THROOP UNITS LLC (Continued) **1023679176**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 06/16/2017
- Site name: THROOP UNITS LLC
- Classification: Not a generator, verified

- Date form received by agency: 05/01/2017
- Site name: THROOP UNITS LLC
- Classification: Large Quantity Generator

Hazardous Waste Summary:

- . Waste code: D008
- . Waste name: LEAD

Violation Status: No violations found

K210 **DRUM RUN** **NY Spills** **S109581900**
WSW **GERRY ST & HARRISON AVE INTERSECTION** **N/A**
< 1/8 **BROOKLYN, NY**
0.095 mi.
499 ft. **Site 7 of 14 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:
- Name: DRUM RUN
- Address: GERRY ST & HARRISON AVE INTERSECTION
- City,State,Zip: BROOKLYN, NY
- Spill Number/Closed Date: 0900534 / 2009-04-20
- Facility ID: 0900534
- Facility Type: ER
- DER Facility ID: 361657
- Site ID: 412477
- DEC Region: 2
- Spill Cause: Abandoned Drums
- Spill Class: C4
- SWIS: 2401
- Spill Date: 2009-04-15
- Investigator: HRAHMED
- Referred To: Not reported
- Reported to Dept: 2009-04-15
- CID: Not reported

DRUM RUN (Continued) **S109581900**

Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-15
Spill Record Last Update:	2009-04-20
Spiller Name:	GAVIN NAVARRO
Spiller Company:	UNKNOWN
Spiller Address:	GARY ST & HARRISON AVE INTERSECTION
Spiller Company:	999
Contact Name:	GAVIN NAVARRO
DEC Memo:	"04/20/09-HRAHMED-One drum was found at this location during drum run on 04/16/09. Fenley & Nicol Emptied that drum. NYC DEP and Sanitation was notified. This case is closed. "
Remarks:	"DEP reporting that a half-full 55 gallon drum of unknown petroleum, possibly waste oil, abandoned."

All Materials:

Site ID:	412477
Operable Unit ID:	1168945
Operable Unit:	01
Material ID:	2160578
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

K211 **MANHOLE 1144** **NY Spills** **S106012844**
WSW **GERRY ST/HARRISON AV** **N/A**
< 1/8 **BROOKLYN, NY**
0.095 mi.
499 ft. **Site 8 of 14 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:

Name:	MANHOLE 1144
Address:	GERRY ST/HARRISON AV
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0300137 / 2003-07-18
Facility ID:	0300137
Facility Type:	ER
DER Facility ID:	187060
Site ID:	226631
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	2401
Spill Date:	2003-04-04
Investigator:	AERODRIG

MANHOLE 1144 (Continued) **S106012844**

Referred To:	Not reported
Reported to Dept:	2003-04-04
CID:	398
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-04
Spill Record Last Update:	2003-07-18
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	KEVIN MCARDLE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ E2MIS 147774 4/4/03 02:45 HRS. G. MOORE #18872, SR. FIELD OPERATOR WITH F.O.D., REPORTS WHILE LOCATING FAULT ON FEEDER 6B42 AT 02:40 HRS. FOUND APPROX. 20 GAL. TRANSFORMER OIL ON APPROX. 200 GAL. WATER. HE CAN SEE OIL LEAKING FROM TRANSFORMER AND REPORTS TM IS FULL OF WATER. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE OR SMOKE INVOLVED. ENV. STOP TAG # 22574 PLACED. LIQUID SAMPLE TAKEN FROM SPILL ON E PRIORITY TURNAROUND. DUE TO AMOUNT OF OIL, F.O.D. TO REMAIN ON LOCATION UNTIL RELIEVED BY ENV. OPS. AND CLEANUP TO BE DONE AS 50-499 PPM USING AN OVER 50 TANKER. NETWORKS WILL ALSO NEED TO TAKE AN OIL SAMPLE FROM UNIT FOR PCB TEST. Info from ECC Warehouse: Historical PCB Count 10 ppm as of 7/16/1987, Lab Seq # 615207. Transformer manufactured by GE, Serial # M135241, manufactured and installed in 1986. 02:55 HRS. -- NOTIFIED GENE WILLIAMS, O.S. BROOKLYN ENV. OPS. 03:00 HRS. -- NOTIFIED RON JAMES OF BROOKLYN/QUEENS EH&S. 03:05 HRS. -- CONTACTED CORPORATE TRANSPORTATION, BILL NEVIN REPORTS NO TANKER AVAILABLE UNTIL 7AM SHIFT. 03:10 HRS. -- NOTIFED K. HUFFORD & W. ECKSTEIN OF BROOKLYN ENV. OPS. TO RESPOND WITH VACTOR (AFTER COMPLETING CURRENT FLUSH JOB FOR F.O.D.) 03:19 HRS. -- NOTIFIED K. McARDLE OF C.I.G. 03:23 HRS. -- NOTIFIED J. MIDDLETON OF BROOKLYN ENV. OPS. TO RETURN TO YARD AND TAKE SPILL VAN TO CLEANUP (AFTER COMPLETING CURRENT FLUSH JOB FOR F.O.D.) UPDATE 4/4/03 04:57 HRS. -- R. COSENTINO REPORTS HE IS ON WAY TO LOCATION. HE SPOKE TO R. JAMES WHO INFORMED HIM THAT THE SAMPLE TAKEN BY F.O.D. WAS FROM LOCATION WHERE OIL WAS SPILLING OUT OF TRANSFORMER & THEREFORE IT WILL BE SUFFICIENT FOR TESTING PURPOSES -- NO ADDITIONAL SAMPLE FROM UNIT REQUIRED. UPDATE 4/4/03 05:00 HRS. -- GENE WILLIAMS REPORTS HE IS ON LOCATION AND SPILL VAN SHOULD BE RESPONDING SHORTLY. HE WILL HAVE 6AM VACTOR CREW RESPOND TO LOCATION TO FLUSH LINE MANHOLE AND SET UP FOR CLEANUP WITH TANKER IN A.M. 4/4/03 05:25 -- EPA ID # NYP004109435 ISSUED BY D. KINDBERG OF E.R.T. -- W.W. #17344 -- UPDATE 04-APR-2003 06:30 HRS. HISTORICAL SEWER CONNECTION PLATES INDICATE NO SEWER CONNECTION IN STRUCTURE. UPDATE - 04-APR-2003 06:59 HRS.. LSN# 03-02813 , SAMPLE TYPE: OIL, AROCLOR: 1260, RESULT: < 1. PPM. UPDATE 4-4-03 1050 HRS R. COSENTINO ENVIR REP REPORTS AT 0830 HRS AND UNDER 50 PPM TANKER ARRIVED ON LOCATION. IT WILL START TO REMOVE ALL LIQUID FROM STRCUTURE WHEN SAFE. FLUSH OS J.

MANHOLE 1144 (Continued) **S106012844**

DEKANCHUK WILL REPORT HOW MUCH LIQUID WERE REMOVED FROM STRUCTURE. THEY FOUND B.PHASE BUSHING LEAKING. I&A NETWORK CREW ARRIVED ON LOCATION TO DRAIN TRANSF. THEY WILL START TO DRAIN TRANSF WHEN FDR. IS GRD AND READY FOR WORK. THEY WILL CALL WITH HOW MUCH OIL WAS DRAIN FROM TRANSF. DEP DID NOT COME TO LOCATION AS OF 1100 HRS LAZ # 04425 UPDATE 4-4-03 1130 HRS J. DEKANCHUK OS FLUSH DEPT REPORTS THEY DRAINED ALL LIQUIDS FROM STRUCTURE. UNDER 50 PPM TANKER REMOVED 2300 GALLONS WATER & OIL . TRANSF STILL HAS TO BE DRAINED. ENVIRONMENTAL OPS EMPLOYEES ESPONDA & RYAN PERFORMED A PRELIMINARY CLEANUP, THE DOUBLE WASHED STRUCTURE WITH BIO GEN 760. TAG REMAINS IN PLACE PENDING TRANSFORMER REMOVAL.... UPDATE 4/4/03 18:15 HRS. -- E. DITRENTO #52669 OF EQUIPMENT GROUP REPORTS 320 GALS OF OIL WAS DRAINED FROM THE TRANSFORMER AND CAPACITY WAS 340 GAL. (THIS INDICATES 20 GALS. OIL MISSING, WHICH MATCHES SPILL AMOUNT ORIGNALLY REPORTED). UPDATE 4-17-03 1600 HRS G. KERN MECH A FLUSH DEPT REPORTS CLEANUP IS COMPLETED . HE DOUBLE WASH STRUCTURE WITH BIO-JEN 760. HE REMOVED ALL LIQUIDS WITH HIS VACTOR. THEY DID NOT FINE A SUMP OR SEWER CONNECTION. THEY REMOVED AND INSTALLED NEW TRANSF. E.S.TAG # 22574 REMOVED. LAZ # 04425"

Remarks: "ON 200 GALS OF WATER. 10 PPM PCB TAKEN IN '97."

All Materials:

Site ID:	226631
Operable Unit ID:	866204
Operable Unit:	01
Material ID:	508212
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H212 **LOT 25,TAXBLOCK 2250** **NY E DESIGNATION** **S110242372**
NW **116 WALTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.096 mi.
505 ft. **Site 12 of 16 in cluster H**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 25,TAXBLOCK 2250
Address:	116 WALTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	25
Tax Block:	2250
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported

LOT 25,TAXBLOCK 2250 (Continued) **S110242372**

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

H213 **116 WALTON STREET** **NY VCP** **S118943348**
NW **116 WALTON STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.096 mi.
505 ft. **Site 13 of 16 in cluster H**

Relative: **Lower**
Actual: **13 ft.**

VCP NYC:
Project ID: 14CVCP212K
Project Name: 116 WALTON STREET
Project Address: 116 WALTON STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 14CVCP212K
File Name: 2013-12-24.RIR
URL: http://www.nyc.gov/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP212K/2013-12-10.14EH-A233K.116_Walton_Street.RIR_EI_SC_clean.pdf

Project ID: 14CVCP212K
File Name: 2013-12-24.RAWP_Draft
URL: http://www.nyc.gov/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP212K/2013-11-4.14EH-A233K.116_Walton.report.RAWP_EI_SC_clean.pdf

Project ID: 14CVCP212K
File Name: 2013-12-24.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP212K/2013-12-24.FactSheet-1.pdf

Project ID: 14CVCP212K
File Name: 2013-12-24.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP212K/2013-12-24.Translated Factsheet-1.pdf

Project ID: 14CVCP212K
File Name: 2013-12-24.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP212K/2013-12-24.Translated_CPS.pdf

---

L214 **MANHOLE #42919** **NY Spills** **S106016657**
SSW **THOMPKINS & FLUSHING AVS** **N/A**
< 1/8 **BROOKLYN, NY**
0.099 mi.
522 ft. **Site 6 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:
Name: MANHOLE #42919
Address: THOMPKINS & FLUSHING AVS
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0304585 / 2004-10-13
Facility ID: 0304585

MANHOLE #42919 (Continued) **S106016657**

Facility Type:	ER
DER Facility ID:	62884
Site ID:	65498
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-07-30
Investigator:	AERODRIG
Referred To:	Not reported
Reported to Dept:	2003-07-31
CID:	255
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-31
Spill Record Last Update:	2004-10-13
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	SEAN MCKEEVER
DEC Memo:	"E2MIS 149554 7/30/03 - 1040 R. SACCOMAGNO - 14510 - U.G., WHILE DOING PRE-INSPECTS ON FDR 6B55, REPORTS FINDING APPROX 1 QT OF AN UNKNOWN OIL ON APPROX 30 GALS OF WATER IN MH42919. SPILL IS CONTAINED. NO SEWER CONNECTIONS. NO SUMPS. PCB SAMPLE TAKEN. CLEANUP PENDING LAB RESULT. 7/30/03=1830hrs QC ID: 01-200307300623 TOTAL PCB < 1.0 ppm UPDATE @ 0330 HRS 11/18/03 A.GLODWSKI ENVIROMENTAL OPS REPOARTS STRUCTURE DOUBLE WASHED WITH COAGULANT & BIOGEN 760. TAG REMAINS IN PLACE PENDING UNDERGROUND WORK Update - 11/18/03 - 1340hrs J. Delarosa Mech A, Env. Ops reports double washed with 760 biogen. UG was on location and cut out joint. Made safe. Clean up completed. Removed env. stop tag # 11265. No sump found in structure."
Remarks:	"1 quart on 30 gallons of water - default in structure found. Con Edison #149554"

All Materials:

Site ID:	65498
Operable Unit ID:	871394
Operable Unit:	01
Material ID:	505441
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L215
SSW
< 1/8
0.099 mi.
522 ft.

CONED MANHOLE #7420
FLUSHING/THOMPKINS
BROOKLYN, NY

Site 7 of 32 in cluster L

NY Spills **S106469230**
N/A

Relative:
Lower

Actual:
13 ft.

SPILLS:

Name:	CONED MANHOLE #7420
Address:	FLUSHING/THOMPKINS
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0401891 / 2004-09-09
Facility ID:	0401891
Facility Type:	ER
DER Facility ID:	119626
Site ID:	140065
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-05-20
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-05-20
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-20
Spill Record Last Update:	2004-09-09
Spiller Name:	ERT DESK
Spiller Company:	CONED MANHOLE #7420
Spiller Address:	FLUSHING/THOMPKINS
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"e2mis # 153501 P.FRANZI #20 REPORTS WHILE WORKING ON SCH.FEEDER 6B55 REPORTS APPROX 1-QUART OF DIELECTRIC FLUID LEAKED FROM A RESEVOIR TANK IN MH-7420 .ALSO REPORTS THERE IS A SEWER CONNECTION IN STRUCTURE THERE IS OIL IN SEWER.UNABLE TO REPORT AMOUNT. NO FIRE OR SMOKE. 1 SAMPLE TAKEN ENVIR TAG#26123 PLACED. FOD crew on location. Inspected structure and found small amount of oil on floor. Determined some may have spilled into sewer connection. Clean up in progress as 50-499. LSN 04-03936: PCBs 2 PPM. 5/21/04=0110HRS LABARBERA ENVIR OPPS REPORTS CLEANUP COMPLETED. DOULBED WASHED STRUCTURE USING BIO-GEN 760. ALL LIQUIDS REMOVED. CLEANED AND SEALED SUMP. PER MR. JACOBI THERE WAS NO SUMP. THE ENVIRONMENTAL OPS CREW CLEANED THE SEWER CONECTION AND THEN CEMENTED THE SEWER CONNECTION. E. VESCE"
Remarks:	"came from a resevior tank: found some went intop a sewer conection, not sure how much; NOT CLEANED UP, DISPATCHING CREWS : Update: 1 quart of unknown type oil. Tank is underground. Release is secured. John Higgins "

All Materials:

Site ID:	140065

CONED MANHOLE #7420 (Continued) **S106469230**

Operable Unit ID:	883744
Operable Unit:	01
Material ID:	493082
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

L216 **PFIZER INC** **NJ MANIFEST** **S109533642**
SW **11 BARTLETT STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.099 mi.
523 ft. **Site 8 of 32 in cluster L**

Relative: **Lower**

Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYD001374214
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	X
TSDF Flag:	X
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000237129VES
EPA ID:	NYD001374214
Date Shipped:	08/05/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD000692061
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/05/2008
Date Trans2 Transported Waste:	08/08/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

PFIZER INC (Continued) **S109533642**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/08/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D007
Hand Code:	H141
Quantity:	2275 K

Manifest Number:	000113111VES
EPA ID:	NYD001374214
Date Shipped:	06/11/2007
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/11/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/11/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

PFIZER INC (Continued) **S109533642**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	H14
Quantity:	546 KG

Manifest Number:	000160183VES
EPA ID:	NYD001374214
Date Shipped:	02/25/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/25/2008
Date Trans2 Transported Waste:	02/29/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/29/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

PFIZER INC (Continued) **S109533642**

Waste:
- Manifest Year: Not reported
- Waste Code: D008
- Hand Code: H141
- Quantity: 200 P

L217 **PFIZER INC BROOKLYN PLANT** **NY Spills** **S102150583**
SW **11 BARTLETT ST** **NY MANIFEST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.099 mi.
523 ft. **Site 9 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:
- Name: 11 BARTLETT STREET
- Address: 11 BARTLETT STREET
- City,State,Zip: BROOKLYN, NY
- Spill Number/Closed Date: 9505760 / 1995-08-10
- Facility ID: 9505760
- Facility Type: ER
- DER Facility ID: 226177
- Site ID: 278551
- DEC Region: 2
- Spill Cause: Unknown
- Spill Class: C4
- SWIS: 2401
- Spill Date: 1995-08-09
- Investigator: KSTANG
- Referred To: Not reported
- Reported to Dept: 1995-08-10
- CID: Not reported
- Water Affected: Not reported
- Spill Source: Commercial/Industrial
- Spill Notifier: Other
- Cleanup Ceased: 1995-08-10
- Cleanup Meets Std: True
- Last Inspection: Not reported
- Recommended Penalty: False
- UST Trust: False
- Remediation Phase: 0
- Date Entered In Computer: 1995-09-13
- Spill Record Last Update: 2004-09-30
- Spiller Name: Not reported
- Spiller Company: PFISER, INC
- Spiller Address: 630 FLUSHING AVENUE
- Spiller Company: 001
- Contact Name: Not reported
- DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 10/10/95: This is additional information about material spilled from the translation of the old spill file: MERCURY & LEAD."
- Remarks: "UNDERGROUND CONTAMINATION FOUND AT OLD CHEMICAL FACILITY THAT IS BEING DEMOLISHED - REFER TO SPILL #95-05769"

All Materials:
- Site ID: 278551
- Operable Unit ID: 1016657

PFIZER INC BROOKLYN PLANT (Continued) **S102150583**

Operable Unit:	01
Material ID:	556632
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	PFIZER INC BROOKLYN PLANT
Address:	11 BARTLETT ST
City,State,Zip:	BROOKLYN, NY 11206-5001
Country:	USA
EPA ID:	NYD001374214
Facility Status:	Not reported
Location Address 1:	13 BARTLETT STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001374214
Mailing Name:	PFIZER INC BROOKLYN PLANT
Mailing Contact:	HETTENBACH JR SEN PROC EN
Mailing Address 1:	11 BARTLETT ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	5001
Mailing Country:	USA
Mailing Phone:	2125731686

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NJD080631369
Trans2 State ID:	NJD000692061
Generator Ship Date:	09/19/2008
Trans1 Recv Date:	09/19/2008
Trans2 Recv Date:	09/23/2008
TSD Site Recv Date:	09/25/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001374214
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

PFIZER INC BROOKLYN PLANT (Continued) **S102150583**

TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000224999VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2730.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	12.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

H218 **52-56 THROOP AVENUE** **NY VCP** **S118943605**
NW **52-56 THROOP AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.099 mi.
524 ft. **Site 14 of 16 in cluster H**

Relative:
Lower

Actual:
13 ft.

VCP NYC:

Project ID:	16CVCP068K
Project Name:	52-56 THROOP AVENUE
Project Address:	52-56 THROOP AVENUE
Borough:	BROOKLYN

VCP NYC:

Project ID:	16CVCP068K
File Name:	2016-05-13.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP068K/2016-05-13.16EH-A26K.RIR.EBC_v3.pdf

Project ID:	16CVCP068K
File Name:	2016-05-13.RAWP
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/1

52-56 THROOP AVENUE (Continued) **S118943605**

6CVCP068K/2016-05-13.16CVCP068K.RAP_report.EBC_V2.pdf

Project ID: 16CVCP068K
File Name: 2016-05-19.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP068K/2016-05-19.16EHAN262K.admin.52-56_Throop_Fact Sheet 1.pdf

Project ID: 16CVCP068K
File Name: 2016-05-19.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP068K/2016-05-19.16EHAN262K.admin.Translated_FS-1.pdf

Project ID: 16CVCP068K
File Name: 2016-05-19.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP068K/2016-05-19.16EHAN262K.admin.Translated_CPS.pdf

---

H219 **THROOP UNITS LLC** **PA MANIFEST** **S123093926**
NW **52 THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.099 mi.
524 ft. **Site 15 of 16 in cluster H**

Relative: **Lower**

Actual: **13 ft.**

Manifest Details:

Year:	2017
Manifest Number:	010444016FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/09/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	30000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	010444144FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/12/2017
Mailing Address:	Not reported

THROOP UNITS LLC (Continued) **S123093926**

Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	22000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	010444140FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/12/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	30000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	010444009FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/10/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

THROOP UNITS LLC (Continued) **S123093926**

TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	24000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	010444019FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/10/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	26000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	010444143FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/12/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC

THROOP UNITS LLC (Continued) **S123093926**

TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	23000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	010444011FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/11/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	28000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	010444010FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/10/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA

THROOP UNITS LLC (Continued) **S123093926**

Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	28000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	010444052FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/10/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	30000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	010444057FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000231548
Generator Date:	05/10/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1

THROOP UNITS LLC (Continued) **S123093926**

Waste Number:	D008
Container Number:	1
Container Type:	Dump truck
Waste Quantity:	28000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
35 additional PA_MANIFEST: record(s) in the EDR Site Report.

H220 **LOT 27,TAXBLOCK 2250** **NY E DESIGNATION** **S110242376**
NW **52 THROOP AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.099 mi.
524 ft. **Site 16 of 16 in cluster H**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 27,TAXBLOCK 2250
Address:	52 THROOP AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	27
Tax Block:	2250
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

L221 **VAULT 1336 & 1473** **NY Spills** **S106011290**
SSW **FLUSHING AVE & TOMPKINS** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
537 ft. **Site 10 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:

Name:	VAULT 1336 & 1473
Address:	FLUSHING AVE & TOMPKINS
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0211143 / 2003-09-29
Facility ID:	0211143

VAULT 1336 & 1473 (Continued) **S106011290**

Facility Type:	ER
DER Facility ID:	265729
Site ID:	330346
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-02-05
Investigator:	AERODRIG
Referred To:	Not reported
Reported to Dept:	2003-02-06
CID:	205
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-06
Spill Record Last Update:	2003-09-29
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ Con Ed e2mis #147073: 2/5/03 - 1300 N. FRUSTACI - 14575 - BQE, WHILE DOING INSPECTIONS FOUND APPROX 2 OZ OF AN UNKNOWN OIL ON 100 GALS OF WATER IN BOTH V1336 (6B55) & V1473 (6B56). SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO THE SPILL. NO PRIVATE PROPERTY AFFECTED. STRUCTURES ARE CONNECTED WITH A WEEP HOLE. NO MOVEMENT IN THE WATER. NO SUBSTANTIAL CRACKS IN THE STRUCTURES. THERE IS A CONCRETE SUMP IN V1473 WITH A DEFECTIVE SUMP PUMP IN IT. BOTH STRUCTURES PRESSURE TESTED AND HELD PRESSURE. 2 LBS OF PRESSURE WERE FOUND IN EA STRUCTURE BEFORE THEY WERE PRESSURE TESTED. OIL LEVELS & TEMPS ARE GOOD IN EA STRUCTURE. TAG # 39200 PLACED IN EA STRUCTURE. PCB SAMPLES TAKEN FROM EA STRUC. CHAIN OF CUSRODY FORM # CC11214 FILLED OUT AND MARKED 'E' (WITHIN 8 HRS) PRIORITY. CLEANUP PENDING LAB RESULTS. 2/5/03=2200HRS BOTH SAMPLES RETURNED# 03-01062-002 V-1473=<1PPM # 03-01062-001 V-1336 <1.PPM UPDATE 2-6-03 1045 HRS K QUEST MECH A FLUSH DEPT REPORTS THEY WILL BE UNABLE TO COMPLETE THIS CLEANUP DUE TO THE SECONDARY (GAP) PROBLEM IN STRUCTURE. SERV BUR ON LOCATION TO TRY AND CORRECT PROBLEM. STRUCTURE ALSO IS MAKING WATER . HE LOADED TRUCK UP TRYING TO REMOVE LIQUIDS FROM THIS STRUCTURE. WILL TAKE THIS OFF THE 24 HRS DEMINIMIS PROGRAM. UPDATE 2-6-03 1310 HRS. SERV BUR REPORTS SECONDARY (GAP PROBLEM WAS CORRECTED. LAZ # 04425 UPDATE: 3/20/03 - 1230 W. TUDY - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING BOTH STRUCTURES WITH BULLDOG. LIQUID WASTE REMOVED BY ASTORIA UNDER 50 TANKER. SOIL WASTE REMOVED BY VACTOR. TAGS #'D39200 WERE REMOVED FROM BOTH STUCTURES."
Remarks:	"2oz spill between vaults. con ed # 147073. samples taken less than 1ppm. cleanup not completed yet. water leak also present."

VAULT 1336 & 1473 (Continued) **S106011290**

All Materials:

Site ID:	330346
Operable Unit ID:	864325
Operable Unit:	01
Material ID:	514502
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L222 **MANHOLE 20779** **NY Spills** **S113493064**
SSW **HARRISON AVE AND FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
537 ft. **Site 11 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:

Name:	MANHOLE 20779
Address:	HARRISON AVE AND FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1300441 / 2013-07-08
Facility ID:	1300441
Facility Type:	ER
DER Facility ID:	436060
Site ID:	480768
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2013-04-13
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2013-04-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-04-13
Spill Record Last Update:	2013-07-08
Spiller Name:	Not reported
Spiller Company:	CONN ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"7/8/13 - Austin - 2 gals. unk. oil in vault - Con Ed contained and cleaned up the spill - See eDocs files for further information -

MANHOLE 20779 (Continued) **S113493064**

Spill closed - end"
Remarks: "Caller advised 2qts of unknown oil spilled into a manhole and soil. Clean up is pending."

All Materials:
Site ID: 480768
Operable Unit ID: 1230554
Operable Unit: 01
Material ID: 2229172
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .50
Units: G
Recovered: Not reported
Oxygenate: Not reported

L223 **MANHOLE** **NY Spills** **S113406129**
SSW **HARRISON AVE AND FLUSHING** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
537 ft. **Site 12 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:
Name: MANHOLE
Address: HARRISON AVE AND FLUSHING
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1300013 / 2013-05-14
Facility ID: 1300013
Facility Type: ER
DER Facility ID: 435588
Site ID: 480319
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2013-04-01
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2013-04-01
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-04-01
Spill Record Last Update: 2013-05-14
Spiller Name: ERT
Spiller Company: CON ED
Spiller Address: HARRISON AVE AND FLUSHING
Spiller Company: 999

MANHOLE (Continued) **S113406129**

Contact Name: ERT
DEC Memo: "5/14/13 - Austin - 1 quart unk. oil found atop 15 gals water - Con Ed contained and cleaned up the spill, no surce found - See eDocs files for further information - Spill closed - end"
Remarks: "on earthen bottom, c/u complete"

All Materials:
Site ID: 480319
Operable Unit ID: 1230084
Operable Unit: 01
Material ID: 2227926
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .25
Units: G
Recovered: .25
Oxygenate: Not reported

Site ID: 480319
Operable Unit ID: 1230084
Operable Unit: 01
Material ID: 2227927
Material Code: 0060A
Material Name: wastewater
Case No.: Not reported
Material FA: Other
Quantity: 15.00
Units: G
Recovered: 15.00
Oxygenate: Not reported

J224 **HOO CORP.** **NY UST** **U004047146**
WNW **94 WALLTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.103 mi.
542 ft. **Site 7 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

UST:
Name: HOO CORP.
Address: 94 WALLTON STREET
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-608305 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 588816.43859
UTM Y: 4506270.12989
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 30157
Affiliation Type: Facility Owner
Company Name: HOO CORP.
Contact Type: OFFICER
Contact Name: JACK ROSENWASSER

HOO CORP. (Continued) **U004047146**

Address1:	200 HEWES ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(347) 452-3888
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-07-13

Site Id:	30157
Affiliation Type:	Mail Contact
Company Name:	HOO CORP.
Contact Type:	Not reported
Contact Name:	JACK ROSENWASSER
Address1:	200 HEWES STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(347) 452-3888
EMail:	JBROSENWASSER@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-07-13

Site Id:	30157
Affiliation Type:	Facility Operator
Company Name:	HOO CORP
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 452-3888
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-31

Site Id:	30157
Affiliation Type:	Emergency Contact
Company Name:	HOO CORP
Contact Type:	Not reported
Contact Name:	JACK ROSENWASSER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

HOO CORP. (Continued) **U004047146**

Phone:	(347) 452-3888
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-31

Tank Info:

Tank Number:	001
Tank ID:	65014
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1500
Install Date:	09/16/1971
Date Tank Closed:	06/13/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	08/08/2017
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	07/13/2018

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

J225 **LOT 14,TAXBLOCK 2250** **NY E DESIGNATION** **S110242347**
WNW **94 WALTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.103 mi.
542 ft. **Site 8 of 17 in cluster J**

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:

Name:	LOT 14,TAXBLOCK 2250
Address:	94 WALTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	14
Tax Block:	2250
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported

LOT 14,TAXBLOCK 2250 (Continued) **S110242347**

Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

L226 **BP SERVICE STATION #36714** **NY UST** **U001839090**
SSW **655 FLUSHING AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.104 mi.
547 ft. **Site 13 of 32 in cluster L**

Relative: **Lower**

Actual: **13 ft.**

UST:
Name: BP SERVICE STATION #36714
Address: 655 FLUSHING AVENUE
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-337439 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/29/2022
UTM X: 588912.52567
UTM Y: 4506011.78560
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 16176
Affiliation Type: Facility Owner
Company Name: SPARTAN 5 PROPERTIES LLC
Contact Type: RETAIL COMPLIANCE COORDINATOR
Contact Name: JESSICA VISLOCKY
Address1: 3333 NEW HYDE PARK RD, SUITE 201
Address2: Not reported
City: NEW HYDE PARK
State: NY
Zip Code: 11042
Country Code: 001
Phone: (516) 365-8700
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-10

Site Id: 16176
Affiliation Type: Mail Contact
Company Name: BP PRODUCTS NORTH AMERICA, INC.
Contact Type: Not reported
Contact Name: JESSICA VISLOCKY

BP SERVICE STATION #36714 (Continued) **U001839090**

Address1:	PO BOX 6038
Address2:	Not reported
City:	ARTESIA
State:	CA
Zip Code:	90702
Country Code:	001
Phone:	(718) 781-2693
EMail:	JESSICA.VISLOCKY@BP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-10

Site Id:	16176
Affiliation Type:	Facility Operator
Company Name:	BP SERVICE STATION #36714
Contact Type:	Not reported
Contact Name:	RAM JAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-6967
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-10-06

Site Id:	16176
Affiliation Type:	Emergency Contact
Company Name:	SPARTAN 5 PROPERTIES LLC
Contact Type:	Not reported
Contact Name:	JESSICA VISLOCKY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 781-2693
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-10

Tank Info:

Tank Number:	001
Tank ID:	28655
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1968
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

BP SERVICE STATION #36714 (Continued) **U001839090**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 28656
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 28657
Tank Status: Closed Prior to Micro Conversion, 03/91

BP SERVICE STATION #36714 (Continued) **U001839090**

Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1968
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	004
Tank ID:	28658
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1968
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

BP SERVICE STATION #36714 (Continued) **U001839090**

J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 28659
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 28660
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None

BP SERVICE STATION #36714 (Continued) **U001839090**

I00 - Overfill - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 007
Tank ID: 28661
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 008
Tank ID: 28662
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

BP SERVICE STATION #36714 (Continued) **U001839090**

Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 009
Tank ID: 28663
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 010
Tank ID: 28664
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

BP SERVICE STATION #36714 (Continued) **U001839090**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 011
Tank ID: 28665
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1968
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 28666
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550

BP SERVICE STATION #36714 (Continued) **U001839090**

Install Date:	12/01/1968
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	101
Tank ID:	28667
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	07/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	34
Date Test:	10/15/2013
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LABATIST
Last Modified:	02/20/2019

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
B08 - Tank External Protection - Retrofitted Impressed Current

BP SERVICE STATION #36714 (Continued) **U001839090**

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number:	102
Tank ID:	28668
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	07/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	10/15/2013
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MFLEONAR
Last Modified:	10/31/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B08 - Tank External Protection - Retrofitted Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number:	103
Tank ID:	28669
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	07/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	34
Date Test:	10/15/2013

BP SERVICE STATION #36714 (Continued) **U001839090**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LABATIST
Last Modified: 02/20/2019

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B08 - Tank External Protection - Retrofitted Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 104
Tank ID: 28670
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 07/01/1990
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 10/15/2013
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MFLEONAR
Last Modified: 10/31/2017

Equipment Records:

B08 - Tank External Protection - Retrofitted Impressed Current
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E04 - Piping Secondary Containment - Double walled UG
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass

BP SERVICE STATION #36714 (Continued) **U001839090**

Tank Number:	105
Tank ID:	28671
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	07/01/1990
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	10/15/2013
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MFLEONAR
Last Modified:	10/31/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
B08 - Tank External Protection - Retrofitted Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

---

L227 **BP WEST COAST PRODUCTS LLC - BP 36714** **RCRA-SQG** **1015754391**
SSW **655 FLUSHING AVE** **NYR000198119**
< 1/8 **BROOKLYN, NY 11206**
0.104 mi.
547 ft. **Site 14 of 32 in cluster L**

Relative: **Lower**

Actual: **13 ft.**

RCRA-SQG:

Date form received by agency:	12/20/2012
Facility name:	BP WEST COAST PRODUCTS LLC - BP 36714
Facility address:	655 FLUSHING AVE BROOKLYN, NY 11206
EPA ID:	NYR000198119
Mailing address:	PO BOX 80249 RANCHO SANTA MARGARITA, CA 92668
Contact:	MARK OKAMOTO
Contact address:	PO BOX 6038 ARTESIA, CA 90702
Contact country:	US
Contact telephone:	723-743-0901
Contact email:	MARK.OKAMOTO@BP.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous

BP WEST COAST PRODUCTS LLC - BP 36714 (Continued) **1015754391**

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	BP WEST COAST PRODUCTS LLC
Owner/operator address:	PO BOX 6038
	ARTESIA, CA 90702
Owner/operator country:	US
Owner/operator telephone:	714-670-3928
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/13/1970
Owner/Op end date:	Not reported

Owner/operator name:	BP WEST COAST PRODUCTS LLC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	11/13/1970
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

. Waste code:	D018
. Waste name:	BENZENE

BP WEST COAST PRODUCTS LLC - BP 36714 (Continued) **1015754391**

Violation Status: No violations found

L228
SSW
< 1/8
0.104 mi.
547 ft.

BP WEST COAST PRODUCTS LLC - BP 36714 **NJ MANIFEST** **S120678949**
655 FLUSHING AVE **N/A**
BROOKLYN, NY 11206

Site 15 of 32 in cluster L

Relative:
Lower

Actual:
13 ft.

NJ MANIFEST:

EPA Id:	NYR000198119
Mail Address:	PO BOX 80249
Mail City/State/Zip:	RANCHO SANTA MARGARITA, CA 92668
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	MARK OKAMOTO
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	012238209JJK
EPA ID:	NYR000198119
Date Shipped:	11/3/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

BP WEST COAST PRODUCTS LLC - BP 36714 (Continued) **S120678949**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	RANCHO SANTA MARGARITA, CA 92668
Reason Load Was Rejected:	Not reported

Manifest Number:	012238071JJK
EPA ID:	NYR000198119
Date Shipped:	4/21/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	RANCHO SANTA MARGARITA, CA 92668
Reason Load Was Rejected:	Not reported

L229
SSW
< 1/8
0.104 mi.
547 ft.

BP WEST COAST PRODUCTS LLC - BP 36714
655 FLUSHING AVE
BROOKLYN, NY 11206

Site 16 of 32 in cluster L

NY MANIFEST **S118091545**
N/A

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	BP WEST COAST PRODUCTS LLC - BP 36714
Address:	655 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYR000198119
Facility Status:	Not reported
Location Address 1:	655 FLUSHING AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000198119
Mailing Name:	BP WEST COAST PRODUCTS LLC - BP 36714
Mailing Contact:	BP PRODUCTS OF NORTH AMERICA
Mailing Address 1:	PO BOX 80249
Mailing Address 2:	Not reported
Mailing City:	RANCHO SANTA MARGARITA
Mailing State:	CA
Mailing Zip:	92688
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9494605200

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NJR000023036
Trans2 State ID:	Not reported
Generator Ship Date:	12/04/2017
Trans1 Recv Date:	12/04/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/05/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000198119
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	012238449JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

BP WEST COAST PRODUCTS LLC - BP 36714 (Continued) **S118091545**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access additional NY MANIFEST: detail in the EDR Site Report.

L230 **P & C SERVICE STATION CORP** **EDR Hist Auto** **1020578141**
SSW **655 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.104 mi.
547 ft. **Site 17 of 32 in cluster L**

Relative: EDR Hist Auto
Lower

Actual:
13 ft.

Year:	Name:	Type:
1985	P & C SERVICE STATION CORP	Gasoline Service Stations
1986	P & C SERVICE STATION CORP	Gasoline Service Stations
1987	P & C SERVICE STATION CORP	Gasoline Service Stations
1988	P & C SERVICE STATION CORP	Gasoline Service Stations
1989	P & C SERVICE STATION CORP	Gasoline Service Stations
1990	P & C SERVICE STATION CORP	Gasoline Service Stations
1991	P & C SERVICE STATION CORP	Gasoline Service Stations
1992	P & C SERVICE STATION CORP	Gasoline Service Stations
1993	P & C SERVICE STATION CORP	Gasoline Service Stations
1994	P & C SERVICE STATION CORP	Gasoline Service Stations
1994	P & C SVCE STA	Gasoline Service Stations
1995	P & C SVCE STA	Gasoline Service Stations
1995	P & C SERVICE STATION CORP	Gasoline Service Stations
1996	P & C SERVICE STATION CORP	Gasoline Service Stations
1997	P & C SERVICE STATION CORP	Gasoline Service Stations
1998	P & C SERVICE STATION CORP	Gasoline Service Stations
1999	P & C SERVICE STATION CORP	Gasoline Service Stations
2000	P & C SERVICE STATION CORP	Gasoline Service Stations
2001	P & C SERVICE STATION CORP	Gasoline Service Stations

L231 **AMOCO** **NY Spills** **S105141059**
SSW **655 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.104 mi.
547 ft. **Site 18 of 32 in cluster L**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	AMOCO
Address:	655 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0402082 / 2004-05-26
Facility ID:	0402082
Facility Type:	ER
DER Facility ID:	215665
Site ID:	264646
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2004-05-25
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2004-05-25
CID:	403
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-25
Spill Record Last Update:	2004-10-14
Spiller Name:	BART
Spiller Company:	Not reported
Spiller Address:	FLUSHING/TOMPKINS
Spiller Company:	001
Contact Name:	BART
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 5/25/04 Amoco station adjacent to excavation. Keyspan will manifest and remove soil they pulled but will not go to clean endpoints. (notes from Sangesland) 5/25/04 Bart Polizotti(Keyspan) confirmed address of Amoco station as 655 Flushing Ave at Tompkins Ave, not Thompson. See Amoco spill #0104597. (KMF) 5/26/04 Site visit with J. Sun. Keyspan contractor, Hallen, trenching along Flushing Avenue and around Harrison St. No odors detected from trench while on-site. No water in excavation. Contractor from Hallen stated contamination was spotty. Will be hiring Miller Environmental to remove and dispose of contaminated soil. While on site, attempted to locate the monitoring wells put in by Delta to address spill #0104597. MW-5 and MW-7 were possibly under plates. Contractor stated that they did not remove any wells. Two Pfizer buildings, one located across Flushing Ave and one across Bartlett St. The one on Bartlett has a Charter School and playground area south of school. Remediation work to be done under spill #0104597."
Remarks:	"gas construction crew installing 300 feet of gas line noticed odor of gasoline in the soil they excavated."

AMOCO (Continued) **S105141059**

All Materials:

Site ID:	264646
Operable Unit ID:	885937
Operable Unit:	01
Material ID:	493265
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	BP AMOCO STATION #12662
Address:	655 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0104597 / Not Reported
Facility ID:	0104597
Facility Type:	ER
DER Facility ID:	215665
Site ID:	196822
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	2001-07-30
Investigator:	RJFENG
Referred To:	SULFATE INJECT FULL SCALE MONITORING, 2Q2012
Reported to Dept:	2001-07-30
CID:	270
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	2004-06-29
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2001-07-30
Spill Record Last Update:	2018-04-24
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"3/14/03 REASSIGNED FROM ROMMEL TO VOUGHT. 12/4/03 Reassigned from Vought to Foley. See spill #8401982. See PIN file 4393. HISTORY: Leaks were detected and repaired at the threaded bushings of the piping run in 1984. MWs and an extraction well were installed in 1985. LNAPL was detected in 10 of 11 on-site wells ranging in thickness from trace to approx 1'. A product recovery system(scavenger pumps) was installed and activated. Approx 3000gal of LNAPL was removed. In 1990, the 12X550gal tanks were removed and new 4000gal double-walled tanks, islands and dispensers were

AMOCO (Continued) **S105141059**

installed. Subsequent to the rebuild, four new MWs were installed. Approx 0.06' LNAPL was observed in one well. Tyree had monitored these wells from 1990 to 1995. In July 1995, Tyree also installed three temporary wells in the sidewalk across Bartlett St. No BTEX or MTBE above GW standards was detected in these. In Oct 1997, Baltec installed MW-5 which contained VOCs above standards. The site transitioned to Delta in APril 1999. In May 1999, an EFR event was conducted on MW-3. Approx 700gal of impacted GW was treated(approx 9lbs VOCs removed). The results of the EFR event indicated that the residual contamination was no longer significantly volatile and therefore indicative of an older release. In July 2001, LNAPL was observed in tank mat well TW-1 during routine monitoring events at a thickness of 0.41' and was determined to be fresh. Spill #0114597 was reported. THe LNAPL may have been related to a leaking impact valve at dispenser 5/6 which was discovered 6/11/01 and repaired 6/12/01. LNAPL was last detected in TW-1 in 1/02. An EFR program was initiated in 7/01. Between 7/01 and 2/02, nine EFR events were conducted on tank mat well TW-1. Approx 1gal of LANPL, 4116gal water and a total mass of 255lbs of VOCs were recovered and treated. Between 3/6/02 and 4/24/02, six MWs were installed and VOCs in excess of soil cleanup objectives were detected in all samples. Between 9/22/03 and 10/27/03, spill containment was installed around the submersible pumps, deep spill containment boxes were installed under the dispensers, 50' of steel piping was replaced with double walled fiberglass, anad leak detection was installed at each spill containment box and tied to the Veeder Root. 12/8/03 Received Line Closure and Dispenser Upgrade Report (Delta, 12/4/03). Depth to groundwater approx 6-7'bgs. VOCs were not detected above TAGM cleanup objectives in any of the soil samples collected. Soil samples were collected from beneath the three dispensers(2.5-3.5'bgs). Three post-ex soil samples were collected along the product piping(3-3.5'bgs). Four samples were collected during the sump upgrade(2.5-3'bgs). 3/19/04 Received 2Q, 3Q, and 4Q 2002 reports. Dissolved BTEX and MTBE at high concentrations. 0.01ft LNAPL detected in MW-3 10/8/02, 0.13ft in MW-3 on 7/17/02 and 4/15/02. 5/4/04 Overdue for tightness test since 5/1/02. Spartan Petroleum Corp. was previous owner. 5/25/04 Keyspan was installing 300ft of natural gas line and noticed a gasoline odor in the soil they excavated. Reported spill #0402082. See notes. 5/26/04 Stip mailed out and due back 6/28/04. Two Pfizer buildings, one located across Flushing Ave and one across Bartlett St. The one on Bartlett has a Charter School and playground area south of school(crossgradient of station). Delta was on-site to collect endpoints from Keyspan excavation. One of four (composite) endpoints returned with VOCs in excess of soil cleanup objectives. 5/28/04 1Q03, 2Q03, 3Q03, 4Q03 and 1Q04 monitoring reports submitted. 1Q04 BTEX from ND(MW-7,12,A) to 35,740ppb(MW-F). MTBE from ND(MW-6,7,12) to 39,300ppb(MW-9). 6/29/04 Stip executed by T. Kunkel. 7/6/04 Passing tank test results submitted. Investigation Report due 8/28/04. 8/17/04 2Q04 monitoring report received. BTEX from ND(MW-6,7,12,A) to 62870ppb(MW-F). MTBE from ND(MW-6,7,12) to 18500ppb(MW-9). 8/31/04 Received Investigation Summary Report. Delineation complete. RAP due 10/27/04. 11/18/04 A. Lapine update- On November 11, 12, and 15th, Delta collected ground water samples for geochemical analysis in support of a potential Biostimulation Remedial Action Plan. The suite of analytes are extensive, so the laboratory analysis usually takes a few weeks. Awaiting a status from the lab and plan on a requesting a rushed turnaround. Will expedite

AMOCO (Continued) **S105141059**

the preparation of the report. 1/14/05 Received RAP for biological stimulation. MW-1, MW-5, MW-11 and MW-13 are proposed to be used to inject nitrate/sulfate solutions into the subsurface. A workplan describing the specific application of nitrate and sulfate solutions with regard to quantity, concentration and expected rate of injection, as well as a future monitoring program to determine a level of effectiveness will be submitted upon approval of the RAP. An exposure assessment was conducted identifiying chemicals of concern(COC), identifying potential receptors and exposure pathways, determining complete exposure pathways, estimating COC concentrations at points of exposure(POE) for each complete pathway, estimating potential baseline exposure at POEs and estimating site-specific target levels(SSTLs). The assessment concluded concentrations of BTEX and MTBE are protective of potential receptors. Delta conducted geochemical sampling from 11/11/04 to 11/23/04. Samples from MW-6 and MW-7 were from upgradient to assess conditions outside of the impacted zone. Samples from MW-4, MW-5 and MW-11 were within the impact zone. The evidence suggests: Dissolves oxygen levels are depressed in the source zone and recover in downgradient wells. ORP readings support depletion of electron acceptors in the source zone, as compared to upgradient background. Nitrate concentrations are depleted in the source zone, as compared to upgradient and downgradient(nitrate-reducing activity). Concentrations of dissolved manganese increases in the source zone(manganese-reducing activity). Concentrations of ferrous iron increases in the source zone(iron-reducing activity). Concentrations of sulfate are depleted in the source zone(sulfate-reducing activity). Highly elevated concentrations of dissolved methane in the impacted zone indicate methanogenic biological activity. Introduction of exogenous nitrate and sulfate solutions (by injection into existing wells), will provide for additional electron acceptors to increase the rate of biodegredation. 3/22/05 Approved RAP which is to be implemented by 7/21/05. Delta to submit workplan outlining specific application of nitrate and sulfate solutions with regard to quantity, conc, and rate of injection in addition to OMMP. 4/27/05 Portfolio meeting- Injection workplan to be submitted 6/05, O&M 7/05, RAP implementation by 9/05. 7/15/05 4Q04- DTW 5 to 7'bgs, northeast. No LNAPL present. BTEX from ND(MW-6,7,14,15,16) to 51170ppb(MW-13). MTBE from ND(MW-6,7,13,14,16) to 3170ppb(MW-9). 11/8/05: Reviewed quarterly report dated October 27, 2005. Twelve of 16 wells were sampled on January 27, 2005. No free product. Max BTEX is 8,950 ppb (MW12), max MTBE 702ppb (MW12). Contamination in all on-site wells. Increased BTEX concentration in MWs-2,12,& 17. 11/25/05 2Q05 - Fifteen wells sampled on 4/29/05. Max BTEX 66,750 (MW13), max MTBE 1,210 (MW10). Fluctuating contaminant trends. 3Q05 - DTW 6.10-7.66'bgs. BTEX from ND(MW-6,7,14,15) to 58980ppb(MW-13). MTBE from ND(MW-6,7,14) to 1000ppb(MW-10). 3/3/06 All 16 wells sampled 10/20/05. MW-8 was paved over. DTW 5.36-7.79'bgs. No LNAPL present. BTEX from ND(MW-6,7,14,15) to 23770ppb(MW-13). MTBE from ND(MW-6,7,14) to 816ppb(MW-9). Off-site wells are non-detect. Evaluating biostimulation as remedial strategy. 3/16/06 Meeting held with BP and Delta. K. Endriss of BP was questioning biostimulation as a strategy. There will be an internal review prior to submitting RAP and OM&M Plan. 6/8/2006 - Feng - project reassigned to RJFeng. (RJF) 9/22/2006 - Feng - Quarterly Monitoring Report, 1Q2006, 8/17/2006, by Delta. Groundwater sampling and gauging on 1/30/2006. 14 of the 16 monitoring wells were sampled. MW-6 was not sampled due to an obstruction. MW-16 was not sampled due

AMOCO (Continued) **S105141059**

to an insufficient volume of water in the well. Groundwater flows to east at the depth of 5.37' to 7.67' bg. MW-1, 128.6 ppb BTEX, 7.5 ppb MTBE. MW-2, 8,513 ppb BTEX (381 ppb B, 2,670 ppb T, 382 ppb E, 5,080 ppb X), 63.6 ppb MTBE. MW-3, 4,239 ppb BTEC (3,790 ppb B, 102 ppb T, 48 ppb E, 299 ppb X), 591 ppb MTBE. MW-4, 232 ppb BTEX, 13.6 ppb MTBE. MW-5, 2,801 ppb BTEX, 57.2 ppb MTBE. MW-7, ND. MW-9, 974.8 ppb BTEX, 2,270 ppb MTBE. MW-10, 263.6 ppb BTEX, 163 ppb MTBE. MW-11, 8,220 ppb BTEX (1,920 ppb B, 1,300 ppb T, 1,330 ppb E, 3,670 ppb X), 788 ppb MTBE. MW-12, 4,933 ppb BTEX (1,780 ppb B, 480 ppb T, 573 ppb E, 2,100 ppb X), 39.2 ppb MTBE. MW-13, 15,550 ppb BTEX (4,200 ppb B, 5,040 ppb T, 1,190 ppb E, 5,120 ppb X), 67.8 ppb MTBE. MW-14, ND. MW-15, ND. MW-17, 974.2 ppb BTEX, 43.1 ppb MTBE. (RJF) 9/28/2006 - Feng - Portfolio meeting with BP and Delta. RAP plan changed. Delta began engineering design/construction of the automatic bio-stimulation system. Sulfate injection plan and O&M plan will be submitted. Sulfate concentration will be monitored downgradient which should not exceed the groundwater standard. (RJF) 12/6/2006 - Feng - Quarterly Monitoring Report, 2Q2006, 11/27/2006, by Delta. Groundwater sampled and gauged 5/5/2006. 14 of 16 monitoring wells were sampled. MW-6 was not sampled due to an obstruction. MW-16 was not sampled due to insufficient volume of water in the well. DTW 4.9' to 7.24'. Flows northeast. No LNAPL. BTEX range ND to 45,980 ppb (MW-13). MTBE range ND to 2,660 ppb (MW-9). (RJF) 6/12/2007 - Feng - Quarterly Monitoring Report, 3Q2006, 1/29/2007. Groundwater sampled 7/24/2006. 14/16 monitoring wells were sampled. DTW 5.52' to 7.21' bg. No LNAPL. Flows to northeast. MW-1, 88.3 ppb BTEX, 7.9 ppb MTBE. MW-2, 6,765 ppb BTEX, 30 ppb MTBE. MW-3, 4,027 ppb BTEX, 198 ppb MTBE. MW-4, 104 ppb BTEX, 8.5 ppb BTEX. MW-5, 980 ppb BTEX, 29.3 ppb MTBE. MW-6, not accessible. MW-7, ND. MW-9, 589 ppb BTEX, 434 ppb MTBE. MW-10, 159 ppb BTEX, 124 ppb MTBE. MW-11, 3,506 ppb BTEX, 163 ppb MTBE. MW-12, 4,550 ppb BTEX, 50.4 ppb MTBE. MW-13, 23,940 ppb BTEX, 34.2 ppb MTBE. MW-14 and MW-15, ND. MW-16, not enough water. MW-17, 807 ppb BTEX, 44.2 ppb MTBE. (RJF) 7/24/2007 - Feng - 4Q2006, 4/30/2007. Groundwater sampled 10/30/2006. 12/15 monitoring wells were sampled. DTW 5.79' to 7.21' bg. Flows to northeast. LNAPL in MW-13 (0.05'). MW-1, 132 ppb BTEX, 4.8 ppb MTBE. MW-2, 28,400 ppb BTEX, 27 ppb MTBE. MW-3, 3,627 ppb BTEX, 253 ppb MTBE. MW-4, 203 ppb BTEX, 5.1 ppb MTBE. MW-5, 707 ppb BTEX, 7.7 ppb MTBE. MW-6, not accessible. MW-7, 209 ppb BTEX, 14.3 ppb MTBE. MW-9, 358 ppb BTEX, 139 ppb MTBE. MW-11, 264 ppb BTEX, 112 ppb MTBE. MW-12, 5,312 ppb BTEX, 496 ppb MTBE. MW-13, 762 ppb BTEX, 53.8 ppb MTBE. MW-14, MW-15, ND. MW-16 and MW-17, not accessible. 1Q2007, 5/7/2007. Groundwater sampled 1/5/2007. 15/16 monitoring wells were sampled. DTW 5.71' to 8.98' bg. Flows to northeast. No LNAPL. MW-1, 161 ppb BTEX, 4.4 ppb MTBE. MW-2, 29,260 ppb BTEX, 19.8 ppb MTBE. MW-3, 149 ppb BTEX, 639 ppb MTBE. MW-4, 277.5 ppb BTEX, 6.1 ppb MTBE. MW-5, 2,013 ppb BTEX, 20.1 ppb MTBE. MW-6, not accessible. MW-7, Nd. MW-9, 837 ppb BTEX, 285 ppb MTBE. MW-10, 2.51 ppb BTEX, 108 ppb MTBE. MW-11, 4,532 ppb BTEX, 330 ppb MTBE. MW-12, 24,563 ppb BTEX, 1,200 ppb MTBE. MW-13, 2,935 ppb BTEX, 23.8 ppb MTBE. MW-14, MW-15 and MW-16, ND. MW-17, 1,428 ppb BTEX, 24 ppb MTBE. (RJF) 12/12/2007 - Feng - 2Q2007, 8/30/2007. Active Service Station. The monitoring well network was gauged and sampled on 4/4/2007. 15/16 monitoring wells were gauged. DTW 5.31' to 6.81' bg. Flows to northeast. No LNAPL. 14/16 monitoring wells were sampled. BTEX range ND to 12,400 ppb (MW-11). MTBE range ND to 671 ppb (MW-9). (RJF) 1/8/2008 - Feng - 3Q2007, 11/5/2007. Active Service Station. The monitoring well network was gauged and

AMOCO (Continued) **S105141059**

sampled on 7/13/2007. 12/16 monitoring wells were gauged. DTW 5.64' to 7.91' bg. Flows to northeast. No LNAPL. 12 monitoring wells were sampled. BTEX range ND to 40,760 ppb (MW-13). MTBE range ND to 2,040 ppb (MW-3). (RJF) 2/13/2008 - Feng - 4Q2007, 11/19/2007. Active service station. the monitoring well network was gauged and sampled on 10/3/2007. 14/16 monitoring wells were gauged. DTW 6.51' to 7.87' bg. Flows to northeast. No LNAPL. 13 monitoring wells were sampled. BTEX range ND to 8,190 ppb (MW-11). MTBE range ND to 249 ppb (MW-3). (RJF) 3/20/2008 - Feng - Email to K. Endriss (BP) for the status of biostimulation/sulfate solution injection. (RJF) 6/16/2008 - Feng - 1Q2008, 2/15/2008. Active service station. The monitoring well network was gauged and sampled on January 21, 2008. 12 monitoring wells. DTW 5.72' to 7.39' bg. Flows to northeast. No LNAPL. BTEX range ND to 29,200 ppb (MW-13). MTBE range N Dto 470 ppb (MW-3). (RJF) 8/26/2008 - Reviewed the Work Plan Addendum Bio-Stimulation Remediation Pilot Study, dated July 29, 2008, by Delta. The work proposed in this work plan was orginally proposed in the approved RAP dated 1/13/2005. A pilot study will be performed to address DEC's concern regarding the application of elevated sulfate concentrations. 784 lbs of magnesium sulfate will be mixed with 1,000 gallons of tap water (75,000 mg/L) will be added into MW-1 by gravity. DTW of all monitoring wells will gauged immediately after the application. Gauging and sampling of the wells will be performed the day after the application and then on weekly basis for 12 weeks. (RJF) 9/12/2008 - Comments on the Work Plan Addendum Bio-Stimulation Remediation Pilot Study were provided to Delta. 11/10/2008 - 2Q2008, 8/7/2008, by Delta. Active Service station. the monitoring well network was gauged and sampled on 4/25/2008. 14 wells were gauged. No LNAPL. DTW 6.01' to 7.60' bg. Flows to northeast. MW-6 and MW-7 were not found and not gauged. 13 wells were sampled. MW-16 didn't have sufficient volume for sampling. BTEX range ND to 29,100 ug/L (MW-13). MTBE range ND to 1,000 ug/L (MW-9). 10/28/2008 - 3Q2008, 9/29/2008, by EnviroTrac. Active BP service station. The monitoring well network was gauged and sampled on 7/14/2008. 14 wells were gauged. No LNAPL. DTW 5.90' to 7.72' bg. Flows to northeast. 13 wells were sampled. MW-6 and MW-7 couldn't be located. MW-16 has insufficient sample volume. Max benzene 4,500 ug/L (MW-13). Max BTEX 26,200 ug/L (MW-13). Max MTBE 650 ug/L (MW-9). (RJF) 3/4/2009 - 4Q2008, 1/5/2009, by EnviroTrac. Active BP Service Station. The monitoring well network was gauged and sampled on 10/2/008. 14 wells were gauged. NO LNAPL. DTW 5.75' to 8.25' bg. Flows to northeast. 13 wells were sampled. 3 wells were not sampled, MW-6 and MW-7 were paved over and MW-16 was dry. Max benzene 2,500 ug/L (MW-13). Max BTEX 13,970 ug/L (MW-13). Max MTBE 410 ug/L (MW-9). (RJF) 5/21/2009 - Reviewed Drilling Work Plan, dated 3/31/2009, by Delta. Delta is installing 2 monitoring wells at the site. Proposed MW-18 will be in downgradient instead replacing the two wells across street. Work plan is approved. SHARA due within 90 days, August 21, 2009. (RJF) 1/8/2010 - Reviewed Subsurface Hydrocarbon Assessment Report Addendum, dated 10/16/2009, by Delta. Between June 18 and June 19, 2009, Envirotrac, on behalf of Atlantic Richfield, advanced two soil borings (MW-18 and MW-19) to 12 feet and 15 feet respectively, using Geoprobe 6620 hollow stem auger and direct push, macro-core sampling unit. 2 soil samples were collected. MW-19 (6-6.5'), NO PID, VOCs ND. MW-19 (14.5-15'), NO PID, VOCs ND. On July 13, 2009, all the wells were gauged and sampled. DTW 5.89' (MW-13) to 7.46' (MW-16). BTEX range ND to 3,450 ug/L (MW-13). MTBE range ND to 470 ug/L (MW-9). MW-18, VOCs ND. MW-19, 0.61 ug/L

AMOCO (Continued) **S105141059**

benzene, 0.61 ug/L total VOCs. The sulfate injection pilot is scheduled for October 21, 22, 2009, and will has a 12-week monitoring plan. (RJF) 6/9/2010 - 4Q2009, 1/17/2010, by EnviroTrac. The monitoring well network was gauged and sampled on 10/6/2009. 16 wells were gauged. NO LNAPL. DTW 6.22 - 7.58' bg. Flows to northeast. 15 wells were sampled. MW-16 with insufficient water, not sampled. Max benzene 2,600 ug/L (MW-11). Max BTEX 4,280 ug/L (MW-11). Max MTBE 280 ug/L (MW-3). 1Q2010, 4/9/2010, by EnviroTrac. The monitoring well network was gauged and sampled on 1/15/2010. 16 monitoring wells were gauged. NO LNAPL. DTW 6.19 - 7.92' bg. Flows to northeast. 15 wells were sampled. MW-16 with insufficient water, not sampled. Max benzene 3,900 ug/L (MW-3). Max BTEX 5,160 ug/L (MW-11). Max MTBE 810 ug/L (MW-3). 2Q2010, 5/19/2010, by EnviroTrac. The monitoring well network was gauged and sampled on 4/9/2010. 16 wells were gauged. NO LNAPL. DTW 5.59 - 7.33' bg. Flows to northeast. 15 wells were sampled. MW-16 not enough water, not sampled. Max benzene 3,900 ug/L (MW-13). Max BTEX 21,780 ug/L (MW-13). Max MTBE 530 ug/L (MW-3). 6/21/2010 - Enhanced Bioremediation Pilot Summary and Full Scale Application Work Plan, dated 4/1/2010, by Delta. On 10/20/2009, pre-application groundwater monitoring including gauging for DTW, well depth, sampling for BTEX, MTBE, sulfate and sulfide. On 10/21, 22/2009, a 1,000 gallon of 28,000 mg?L sulfate solution was added to MW-1. Post-application groundwater monitoring for sulfate and sulfide was conducted, 10/23, 11/4, 11/12, 11/20, 11/24, 12/4, 12/11, 12/16, 12/22, 12/29/2009, 1/15/2010 and 2/19/2010. Some orders of magnitude of sulfate was detected in MW-2, MW-4, MW-12 and MW-13. The concentration of sulfate up to 27,000 mg/L was dissipated in MW-1 within 120 days. Delta proposes to apply full scale, adding 500 gallon MgSO4 at 28,000 mg/L into MW-1, MW-3, MW-5 and MW-13 for 12 events in 36 months, namely quarterly application. Gauging and monthly sampling will be conducted. Reviewed the quarterly report. comments to Delta. MW-2, MW-4, MW-12 and MW-13 seem not show effectiveness on remediating the dissolved as the BTEX/MTBE concentration is still remaining the similar level after the pilot application. And question if sulfate addition is still an appropriate remedy. 6/28/2010 - approve the full scale application work plan, dated 4/1/2010. The work plan implementation and results shall be included in the quarterlys, and a report summarize the remedy shall be submitted after the 36-months application activities. 8/6/10 Spill case temporarily transferred from June Feng to J.A. Maisonave. - JAM 4/11/2011 - Spill transferred back to JFeng. 6/27/2011 - received 2Q2011. eDoc. JF 9/15/2011 - 2Q2011, 6/27/2011, by Antea Group. Groudwater samples were collected on April 5, 2011. 15 wells were sampled. Max BTEX 12,490 ug/L (MW-13). Moderate BTEX with high benzene in multiple wells. Benzene 3,700 ug/L (MW-3). Max MTBE 550 ug/L (MW-3). 11/7/2011 - 3Q2011, 10/11/2011, by Antea Group. Groundwater samples were collected on July 22, 2011. 14 wells were sampled. High/moderate BTEX and MTBE in multiple wells. MW-3, 1,644 ug/L BTEX, 68 ug/L MTBE. MW4, 392 ug/L BTEX, 5 ug/L MTBE. MW-5, 875 ug/L BTEX, 77 ug/L MTBE. MW-9, 990 ug/L BTEX, 390 ug/L MTBE. MW-10, 1,040 ug/L BTEX, 90 ug/L MTBE. MW-11, 1,652 ug/L BTEX, 20 ug/L MTBE. MW-12, 1,240 ug/L BTEX, 7.7J ug/L MTBE. MW-13, 14,100 ug/L BTEX, less than 10 ug/L MTBE. 5/2/2012 - 1Q2012, 3/28/2012, by Antea Group. Groundwater samples were collected on 1/3/2012. High BTEX and MTBE in multiple wells. MW-2, 1,708 ug/L BTEX, less than 5.0 ug/L MTBE. MW-3, 2,074 ug/L BTEX, 160 ug/L MTBE. MW-4, 354 ug/L BTEX, 3.3J MTBE. MW-5, 1,236 ug/L BTEX, 25 ug/L MTBE. MW-9, 1,852 ug/L BTEX, 210 ug/L MTBE.

AMOCO (Continued) **S105141059**

MW-11, 142 ug/L BTEX, less than 2.5 ug/L MTBE. MW-12, 1,479 ug/L BTEX, 6.1 ug/L MTBE. MW-13, 12,500 ug/L BTEX, less than 5.0 ug/L MTBE. MW-17, 488 ug/L BTEX, 20 ug/L MTBE. 7/20/2012 - 2Q2012, 7/5/2012, by Antea Group. Groundwater samples were collected on April 16, 2012. The next sampling is scheduled for July 2012. MW-2, 2,085 BTEX, 5.4 MTBE. MW-3, 1,782 BTEX, 99 MTBE. MW-4, 264 BTEX, 19 MTBE. MW-5, 2,210 BTEX, 8.8 MTBE. MW-9, 2,082 BTEX, 310 MTBE. MW-10, 1,550 BTEX, 43 MTBE. MW-11, 407 BTEX, 6.2 MTBE. MW-12, 2,250 BTEX, 8.6 MTBE. MW-13, 4,430 BTEX, 6.1 MTBE. MW-17, 381 BTEX, 2.8 MTBE. Table with sulfate sampling is also attached. 11/30/2012 - 3Q2012, 9/27/2012, by Antea Group. The groundwater was sampled July 19, 2012. The next sampling will be in October 2012. MW-1, 145 BTEX, 18 MTBE. MW-2, 7,010 BTEX, less than 5.0 MTBE. MW-3, 147 BTEX, 3 MTBE. MW-4, 142 BTEX, 17 MTBE. MW-5, 54.9 BTEX, less than 0.5 MTBE. MW-9, 1,027 BTEX, 400 MTBE. MW-10, 2,170 BTEX, 62 MTBE. MW-11, 239 BTEX, 5.2 MTBE. MW-12, 1,376 BTEX, 4.1J MTBE. MW-13, 3,610 BTEX, less than 5.0 MTBE. MW-17, 638 BTEX, less than 2.5 MTBE. 3/29/2013 - 4Q2012, 12/27/2012, by Antea Group. The groundwater was sampled on 10/26/2012. The next sampling will be in 1/2013. MW-2, 5,750 BTEX, 6.1 MTBE. MW-3, 435 BTEX, 150 MTBE. MW-4, 105 BTEX, 12 MTBE. MW-5, 663 BTEX, less than 0.5 MTBE. MW-9, 1,008 BTEX, 240 MTBE. MW-10, 1,598 BTEX, 87 MTBE. MW-11, 31.2 BTEX, 2.1 MTBE. MW-12, 516 BTEX, less than 2.5 MTBE. MW-13, 13,960 BTEX, less than 5.0 MTBE. MW-15, 3.0 BTEX, 10 MTBE. 9/30/2013 - 1Q2013, 3/29/2013, by Antea Group. The groundwater sample was collected on 1/23/2013. MW-2, 3,780 BTEX. MW-3, 348 BTEX, 190 MTBE. MW-4, 121 BTEX, 14 MTBE. MW-5, 1,790 BTEX. MW-9, 1,115 BTEX, 200 MTBE. MW-10, 30 BTEX, 45 MTBE. MW-11, 104 BTEX, 11 MTBE. MW-12, 1,691 BTEX. MW-13, 5,970 BTEX. 2Q2013, 6/28/2013, by Antea Group. The groundwater was sampled on 4/10/2013. MW-2, 4,420 BTEX. MW-3, 768 BTEX, 150 MTBE. MW-4, 94.7 BTEX, 10 MTBE. MW-5, 2,140 BTEX. MW-9, 1,107 BTEX, 1,100 MTBE. MW-10, 9.6 BTEX, 37 MTBE. MW-11, 497 BTEX, 16 MTBE. MW-12, 1,960 BTEX, 5.2 MTBE. MW-13, 3,360 BTEX. Bioremediation Workplan Updates, 5/28/2013, by Antea Group. The workplan updates was submitted to BP. Antea Group proposed to ease the application of sulfate solution. The sampling data show the sulfate concentration has increased and should promote the bioremediation. And the trend of BTEX and MTBE have also shown decreasing during the same timeframe as the supplemental sulfate solution were introduced which is an indication of bioremediation occuring. 12/5/13-Vought- Meeting with RSE, DEC John, DEC Hussein, DEC Ketani and Vought sent email: Dear Mr. Onufrak, The New York State Department of Environmental Conservation (the Department) is sending this email to confirm the conversation between yourself, myself and Randy Austin today. BP Amoco will be calling out a contractor to vacuum out well BMW-11 adjacent to the Former Pfizer property at 630 Flushing Avenue and across from the BP Amoco located at 655 Flushing Avenue. The VEFR event on well BMW-11 will occur no later than COB, tomorrow Friday, December 6, 2013. The Department made notification of this discovery to you as a representative of BP Amoco to ensure that if it is determined that the product originated from the BP Amoco site, that BP Amoco has the opportunity to remedy the problem before the Department mobilizes a contractor using the New York State Spill Fund. The contact for the Pfizer property is Mr. Mathew Basso and he can be reached at 908-901-7096. Please contact Randy Austin at 718-482-4929 or June Feng at x4988 if you have any questions as I will be on vacation starting tomorrow. We look forward to your response confirming the above as well as meeting with you and

AMOCO (Continued) **S105141059**

Antea Group to discuss the data for both sites after it has been reviewed by all parties. Vought received reply from Nick that Nick, Thanks again for your cooperation on this one. Please submit the FOIL Request for the Pfizer site through June so that she may expedite it and we can all discuss. Vought sent reply that Nick, Thanks again for your cooperation on this one. Please submit the FOIL Request for the Pfizer site through June so that she may expedite it and we can all discuss . 12/6/13-Vought-Received copy of email from Antea (Meyer) that Hello, Antea Group, on behalf of BP, dispatched a vac truck this morning to evacuate the well in question. They are leaving the site now. This morning, there was approximately one gallon of NAPL present in the well. We proceeded to extract a sample, which will be sent for forensics analysis. Over the course of 6-hour event, approximately 637 gallons of water were removed from the well. There was no measurable NAPL thickness observed in the ~2,000 capacity tank on the truck. There was no NAPL present in the well upon departure. We ll be in contact with June regarding an updated FOIA request. Thank you. Chris . DEC Austin sent email that Thanks, Chris, for your report. We appreciate the actions taken by BP Amoco in this matter, and we will now address the origin of that petroleum product in well BMW-11. The DEC project managers handling these two adjoining site remediation projects will review the data available for both locations, and we will then develop a course action from there. Antea (Meyer) sent email to DEC Feng that Hello June, Attached is a copy of the FOIA request we've been submitting monthly. Other than an updated spill report (attached) we haven't received any deliverables....while we assumed that meant there was no new information, these recent events might suggest otherwise. Can you provide any new information? Thank you. Chris 12/18/13-Vought-Vought sent email inquiry to Meyer as to when forensic results of samples will be received. Voutht also sent email to Meyer that Chris, I am going to field this one while June is out on sick. I noted a large amount of documents in our files and want to be sure that you have them all. I am needing a bit more clarification on what documents you have already or the date of the original FOIA request (so that I can send you the new info, if any). Feel free to call me on my cell at 917-577-1728 as well. Vought also sent email to all parties that I thought to send an email so that I may keep everyone informed (including both BP and their consultant, Antea Group copied above). June has been out on extended sick leave from the office and will hopefully be returning on 12/23. As she is the BP portfolio manager, she will have to review both the BP Amoco file at 655 Flushing Avenue as well as the Pfizer file at 630 Flushing Avenue for concurrence with Raphael's and Pfizer's findings. BP and Antea based on recent activities have submitted a FOIL request to June to obtain and review the files as well so that we may open up an constructive conversation based on real data and they may respond cooperatively, if need be. I will see to completion of this FOIL Request today and respond back to Antea so that they may begin review. As soon as June completes her review (and initial discussion of her findings with Randy and I) we will then discuss internally to the Region (eg with you, Raphael and Hassan) before possibly approaching BP with investigatory requirements on the Pfizer property. If Raphael thinks it appropriate, he is free to forward this email to Roux as well so that they may be informed. Thanks everyone for their patience. Vought called and spoke to Meyer after Meyer resent list of documents he already had. Meyer also noted that there was multiple feet of product in well which was calculated to a

AMOCO (Continued) **S105141059**

approximately one gallon volume recovered. Meyer also noted that since 2004 BP was adding a marker to their product and as such the product sample was not sent for fingerprinting but for identification of the Marker. Meyer acklowledged that even if Marker was not present that product could be from a spill prior to 2004 (Spill was reported in 2001). 12/20/13-Vought-Prepared CD with FOIL file updates for Meyer and left with DEC Silva under FOIL #R2-13-3589. Vought cc'd all parties on email with same info as well. DEC Requires: 1)Fingerprinting results of product. 2/6/2014 - reviewed Investigation Work Plan, dated 2/4/2014, by Antea Group. Proposed to install 4 monitoring wells, i.e. one monitoring well in the west sidewalk of Harrison Ave, one monitoring well in the north sidewalk of Flushing Ave, one monitoring well in the south sidewalk of Bartlett Street, and one monitoring well in the south sidewalk of Flushing Ave. The work plan also proposed to start monthly gauging BMW-11 to determine if NAPL is present. The work plan is approved. Letter to BP and copied Antea, Roux, and Pfizer. 11/19/2014 - 4Q2014, 11/17/2014, by Antea Group. Groundwater was sampled 10/9/2014. MW-11, 1,165 BTEX. MW-10, 747 BTEX. MW-12, 1,670 BTEX. B-103, 23 MTBE. MW-13, 4,900 BTEX. B-104, 399 BTEX. B-102, 1,196 BTEX, 110 MTBE. MW-5, 720 BTEX, 16 MTBE. MW-17, 375 BTEX. MW-16, 535 BTEX, 400 MTBE. MW-3, 1,553 BTEX. MW-2, 0.03 feet LNAPL. In the email from Chris Meyer of Antea Group In sending this to you, I thought it worth following up on our August request to abandon the well that Pfizer installed, as well as our additional deep aquifer delineation wells. That report explained how the LNAPL observed in BMW-11 is not an indication of a larger issue and that the overall sustained recoverability of that material is negligible. 4/1/2015 - Reviewed Subsurface Investigation Report, dated 8/14/2014. BP installed four (4) deep monitoring wells around their station site and started monitoring. BP submitted the investigation report and requested to abandon the four deep wells (MWB-101/B-101 to MWB-104/B-104) they installed and the deep wells (BMW-11) that Pfizer installed based on their investigation and mainly modeling. Utilizing the models, BP/Antea Group ESTIMATED the Oil Specific Volume (OSV) in the four deep wells, i.e. B-101 (0.0003), B-102 (0.019), B-103 (0.04) and B-104 (0.004) and extends or infer that results through the entire smear zone which conclude that there is no recoverable LNAPL on a sustainable basis. The potential LNAPL migration velocity remain low even in maximum LNAPL saturation, i.e. 1.81x10-3 feet/year in B-103, but still below the suggested remediation metric. A baildown test was done on BMW-11 when thickness of LNAPL was 5.04 feet on 6/2/2014 and found extremely low LNAPL recharge rate as their gauging data shows. The LNAPL came back to 1.41 feet in 9/22/2014 gauging event and now 3 feet as of 2/2015. The LNAPL transmissivity was estimated to be 0.009 feet2/day which below the range of LNAPL transmissivity (0.1 to 0.8 ft2/day) suggested as the lower limit for LNAPL removal using hydraulic or pneumatic recovery system and that a sustainable LNAPL yield from BMW-11 is unrealistic. In the Technical Memorandum (App. F), the technician provided that a passive skimmer pump might recover 1.5 gallons (9.5% of the LNAPL within the capture zone) over 3 years of operation, and a skimmer pump with groundwater pumpage might recover 73 gallons (50% of LNAPL within the capture zone) over 3 years of operation. But in the Future Plan part, they stated LNAPL in BMW-11 is not migrating or recoverable due to limiting characteristics supported by the transmissivity and LDRM recovery simulations. And they requested to abandon these wells. 4/13/2015 -

AMOCO (Continued) **S105141059**

email to Central Office Bill Ottaway for technical support and advice on the abandonment of BMW-11. Attached with the email the summary of spill history. 7/23/2015 - email to Chris Meyer of Antea Group We have discussed this site with the Bureau of Technical Support (BTS) in Central Office regarding BP s request to abandon monitoring well BMW-11 which was installed by Pfizer as part of their own spill investigation. BMW-11 showed the presence of LNAPL up to 7 feet and it is still 3 feet at this time. As discussed, despite the estimated/calculated transmissivity, we cannot ignore the fact that the LNAPL continues come into the monitoring well. Once the LNAPL is in the well, it is considered feasible to be recovered. We also discussed that the transmissivity could be used as tool, but should not represent the ultimate rationale and worthiness in determining the implementability of the remedy. Low transmissivity makes conventional mechanical recovery (pumps, vacuum) less efficient or practical but does not mean that there are no other recovery options. We recommend that BP try passive recovery methods, such as bailing, absorbent socks, or well skimmers on regular basis. According to the boring log of BMW-11, the well screen is approximately 7 feet below water table which also raises the question of how the LNAPL is entering the well. There is a need to understand where the LNAPL is flowing relative to the lithology. We also discussed with BTS how further delineation might eventually be required in the Pfizer parking lot and the sidewalk to delineate the extent of the LNAPL. For the large spill on-site at the BP Station, further remediation shall be required. Soil vapor extraction or soil vapor venting were suggested by BTS for an on-onsite remedy. BTS also noted these methods will encourage air movement in the soil which may recover the residual contamination and may also bring on-site product into the wells so that it may become feasible to be recovered. If you would like to discuss, please let us know as always. 9/30/2015 - 2Q2015, 6/22/2015. Groundwater was sampled on 4/21/2015. MW-2, 11,020 BTEX. MW-3, 2,279 BTEX, 100 MTBE. MW-4, 366 BTEX. MW-5, 1,353 BTEX, 51 MTBE. MW-9, 436 BTEX, 200 MTBE. MW-10, 227 BTEX. MW-11, 4,390 BTEX. MW-12, 3,730 BTEX. MW-13, 8,630 BTEX. MW-17, 2,330 BTEX, 160 MTBE. 3Q2015, 9/30/2015. Groundwater was sampled on 7/22/2015. Beginning 8/17/2015, BP has initiated monthly gauging of well BMW-11 and monthly LNAPL recovery in BMW-11 via low-flow pumping and hand bailing. 0.69 gallon of LNAPL was recovered on 8/17/2015. MW-3, 1,464 BTEX, 130 MTBE. MW-4, 171 BTEX. MW-5, 1,163 BTEX, 42 MTBE. MW-9, 496 BTEX, 110 MTBE. MW-10, 1,123 BTEX, 61 MTBE. MW-11, 3,300 BTEX, 12 MTBE. MW-12, 5,080 BTEX. MW-13, 11,820 BTEX. MW-17, 1,450 BTEX, 87 MTBE. 12/3/2015 - 4Q2015, 12/3/2015. Groundwater was monitored on 10/20/2015. MW-3, 763 BTEX, 57 MTBE. MW-4, 133 BTEX. MW-5, 953 BTEX, 36 MTBE. MW-9, 948 BTEX, 150 MTBE. MW-10, 249 BTEX, 75 MTBE. MW-11, 2,157 BTEX, 12 J MTBE. MW-12, 2,984 BTEX. MW-13, 5,080 BTEX. MW-17, 1,773 BTEX, 92 MTBE. 0.08 gallons and 0.02 gallons of product were recovered from BMW-11 in this quarter. As of 11/5/2015, 0.14' LNAPL in BMW-11. 3/17/2016 - 1Q2016, 3/17/2016. Groundwater was monitored on 1/19/2016. MW-2, 5,580 BTEX. MW-3, 1,255 BTEX, 75 MTBE. MW-4, 164 BTEX. MW-5, 738 BTEX, 38 MTBE. MW-9, 213 BTEX, 73 MTBE. MW-11, 1,144 BTEX. MW-12, 2,770 BTEX. MW-13, 8,360 BTEX. MW-15, 10.8 BTEX, 10 MTBE. MW-17, 877 BTEX, 47 MTBE. MW-19, 150 MTBE. On 1/19/2016, LNAPL recovered from BMW-11 was 0.08 gallons, and on 2/22/2016 it was 0.02 gallons. Total recovery so far 2.60 gallons. 3/30/2016 Feng - This spill is transferred from J. Feng to J. Vought as per J. Vought. 10/6/2016 - Feng - This spill is transferred from J. Vought to J.

AMOCO (Continued) **S105141059**

Feng as per J. Vought. 10/17/2016 - Feng - 2Q2016, 6/24/2016. Monitoring on 4/14/2016. Note the table is not updated with the 2nd quarter sampling results. MW-2, 5,314 BTEX. MW-3, 1,149 BTEX, 54 MTBE. MW-4, 202.8 BTEX. MW-5, 700 BTEX, 27 MTBE. MW-9, 151.1 BTEX, 61 MTBE. MW-10, 83 BTEX. MW-11, 2,341 BTEX. MW-12, 2,320 BTEX. MW-13, 4,220 BTEX. MW-15, 5.1 Benzene. MW-17, 656 BTEX, 32 MTBE. 3Q2016, 9/2/2016. Monitoring on 7/12/2016. MW-3, 1,403 BTEX, 75 MTBE. MW-4, 232 BTEX. MW-5, 764 BTEX, 36 MTBE. MW-9, 149 BTEX, 49 MTBE. MW-10, 238 BTEX, 6 MTBE. MW-11, 2,459 BTEX. MW-12, 1,257 BTEX. MW-13, 9,010 BTEX. MW-17, 805 BTEX, 33 MTBE. BMW-11, No Product. 12/22/2016 - 4Q2016, 12/22/2016. Monitoring on 10/24/2016. MW-2, not sampled, sock present. MW-3, 1,024 BTEX, 40 MTBE. MW-4, 163 BTEX. MW-5, 617 BTEX, 33 MTBE. MW-9, 98.6 BTEX, 51 MTBE. MW-10, 229 BTEX. MW-11, 1,897 BTEX. MW-12, 505 BTEX. MW-13, 3,490 BTEX. MW-17, 264 BTEX, 21 MTBE. BMW-11, LNAPL 0.42', recovered 0.5 gallon. 5/4/2017 - Feng - 1Q2017, 3/31/2017. Monitoring on 1/5/2017. BMW-11, no product, total recovered 4.30 gallons to date. MW-2, not sampled, sock in well. MW-3, 1,928 BTEX, 54 MTBE. MW-4, 190 BTEX. MW-5, 821 BTEX, 20 MTBE. MW-9, 274 BTEX, 96 MTBE. MW-10, 79.8 BTEX. MW-11, 2,660 BTEX. MW-12, 487 BTEX. MW-13, 3,670 BTEX. MW-17, 464 BTEX, 21 MTBE. 5/31/2017 - Feng - This spill is transferred from June Feng to Jeffrey Vought as per Jeffrey Vought. 8/3/17-Vought-Received email from Antea(Meyer) dated 6/9/17 that Jeff, I ve attached our proposed remedial action plan for the above-referenced site. We ll need agency approval in order to obtain the permits required to drill in the sidewalk. If you have any questions or would like to discuss, please let me know. Have a great weekend. Vought added attached RAWP to D2 and reviewed: Remedial Action Work Plan - In Situ Activated Carbon Product Application (Antea)-6/9/17. RAWP contains review of site history and contaminant distribution, review of historical remedial activities, evaluation of MNA and ISCO injection, and a proposal for carbon injection. The subject site is located in an urban area characterized by commercial properties and mixed residential/retail development. Adjacent to and northwest of the subject site, across Bartlett Street, are commercial/residential office buildings. The former Children Charter School, now vacant, is located to the west of the subject site. Adjacent to and northeast of the subject site, across Harrison Avenue, are a vacant lot and multi-story residential buildings with first floor retail. Adjacent to the south of the subject site, across Flushing Avenue, are additional vacant commercial buildings. Sensitive receptor survey performed and The closest hydraulically down gradient basement property is a mixed-use, residential/retail building located approximately 60 ft northeast of the subject site, across Harrison Avenue . Groundwater is 5-8'bg and flows in an east-northeasterly direction as well as in a westerly direction . Of note, a silt/clay lens extends under the subject and surrounding properties, ranging in depth from approximately 5 to 20 feet bgs, and appears continuous throughout the subject site and surrounding areas. Total of twenty three monitoring wells installed at site. SIte history includes: product recovery system from 1985 to 1990 with removal of approximately 3000-gallons of NAPL, site raize and rebuild in 1990 with removal of old tanks and replacement with new tanks; manual baling from 1990-1995; delineation across Bartlett street with no recorded impact; LNAPL was last detected in TW-1 in January 2002. In accordance with the off-site investigation completed in May 2014, Antea Group has conducted deep aquifer assessment and sampling, including monthly gauging of the off-site Pfizer well,

AMOCO (Continued) **S105141059**

BMW-11. The investigation results previously summarized in the Investigation Summary Report, dated August 14, 2014, indicated an absence of a LNAPL pathway between BMW-11 and the gas station across Flushing Avenue. LNAPL has been observed in BMW- 11 consistently since gauging was initiated in February 2014. The persistence of LNAPL in BMW-11 indicates the LNAPL is associated with a historical spill unrelated to the subject property. Therefore, Antea Group has submitted requests in Ground Water Monitoring Reports submitted to the NYSDEC for the subject site dated November 17, 2014, March 31, 2015 and June 22, 2015 to discontinue monthly gauging of BMW-11 and abandon the deep aquifer wells. The contamination found in BMW-11 is not related to contamination found at the BP property, as reported in the Investigation Summary Report. All historical groundwater analytical data is presented in Table 1. Since April 2015, monitoring wells MWB-101, MWB-102, MWB-103, and MWB-104 have been eliminated from the monitoring well network. Additional details of this investigation were previously reported in the Investigation Summary Report, dated August 14, 2014. In April 1985, a product recovery system, consisting of a groundwater depression pump and product scavenger (skimmer) pump in a single recovery well, a 550-gallon oil water separator, and a 550-gallon UST for recovered product, was installed and activated. To enhance the remediation system five ejector pumps were installed at various times in monitoring wells MW-1, MW-2, MW-3, MW-6, MW-8, and MW-9 to increase product recovery from the site. The product recovery system operated until the summer of 1990, at which time the site was razed and rebuilt. Approximately 3,000 gallons of LNAPL were removed by the recovery system. A total of seven full-scale biostimulation events were completed between May 2011 and December 2012. The events consisted of 2,000 gallon injections of 28,000 mg/L sodium sulfate solution into four injection wells, followed by consistent monitoring events post application. Each event included 28,000 mg/L of sulfate solution [2,000 gallons of a sulfate solution, 500 gallons per well per application] gravity fed into monitoring wells MW-1, MW-3, MW-5, and MW-13. On December 6, 2013, an emergency VEFR event was conducted in response to a NYSDEC request for LNAPL removal from third party monitoring well BMW-11, located in the southern sidewalk along Flushing Avenue adjacent to the Former Pfizer building located at 630 Flushing Avenue, across from the subject site. Initial gauging of monitoring well BMW-11 identified 6.53 ft of product. Post event gauging identified no product remained in the well following the VEFR event. A total of 637 gallons of liquid was recovered during this event, including approximately 1.06 gallons of product. The product accumulating in BMW-11 has periodically been removed from the well by utilizing a peristaltic pump, drummed on-site and disposed of at a treatment facility off-site. The NAPL present in well BMW-11 is currently being addressed via a petroleum-absorbent sock in the well which is inspected on a monthly basis, periodically removed from the well once fully saturated, and replaced. The saturated socks are drummed on-site and disposed of at a treatment facility off-site. The Investigation Summary Report, dated August 14, 2014, summarized an absence of a LNAPL pathway between BMW-11 and the gas station across Flushing Avenue. Therefore, the persistence of LNAPL in BMW-11 is associated with a historical spill unrelated to the subject property. Based on this information, the focus of this Remedial Action Work Plan is limited to on-site soil and ground water impacts only. LNAPL measurements have been monitored in on-site monitoring well MW-2

AMOCO (Continued) **S105141059**

since July 2014 and reported to the NYSDEC as part of the ongoing quarterly groundwater monitoring program for the subject site. During this time frame, LNAPL thicknesses have ranged between zero and 0.03 ft. The LNAPL is removed from MW-2 by a petroleum absorbent sock which is installed in the well, inspected on a monthly basis, periodically removed from the well once fully saturated, and replaced. The saturated socks are drummed on-site and disposed of at a treatment facility offsite. Contains proposal for 8,250 pounds of activated carbon product and 5,250 gallons of water will be mixed on-site 8/3/17-Vought-Sent email to Meyer/Onufrak that Gentlemen, I must admit I was bit overzealous in my consideration of closure of the above site as I did not recall the product in BMW11 which was noted in the text of the RAWP as I went straight to the tables in the back of the Plan. I am thinking we should discuss the site at our quarterly next week and that the carbon application is not needed at the site, however, the free product in BMW-11 is certainly a continued concern. I recall an email from our DEC Central Office Bureau of Technical Services in July of 2015 that noted As discussed, despite the estimated/calculated transmissivity, we cannot ignore the fact that the LNAPL continues come into the monitoring well. Once the LNAPL is in the well, it is considered feasible to be recovered. We also discussed that the transmissivity could be used as tool, but should not represent the ultimate rationale and worthiness in determining the implementability of the remedy. Low transmissivity makes conventional mechanical recovery (pumps, vacuum) less efficient or practical but does not mean that there are no other recovery options. We recommend that BP try passive recovery methods, such as bailing, absorbent socks, or well skimmers on regular basis. We should focus on whether passive recovery methods are feasible at this point and a key piece of information that is needed is the current product thickness at BMW-11. It would be great to have this information before our discussion on Tuesday. Sorry for jumping to conclusions gentlemen and on to 1128 East Gunhill Road . 8/4/17-Vought-Sent email to Meyer/Onufrak that Gentlemen, After further review I would hold on going out to MW-11 before our meeting as sock removal and product measurement, after allowing time for equilibrium to be reached, is also necessary on MW-2. We can discuss further next Tuesday. Chris, I did not realize you were on vacation and thanks for taking my call yesterday on your time off. Enjoy! 8/8/17-Vought-BP Quaterly Review Meeting - Vought/Meyer/Onufrak. Antea will remove socks from MW-2 and BMW-11 and allow time for stabilization followed by well monitoring and submission of results. Product trends on BMW-11 show decreasing product thicknesses and were most recently 0.3 feet thick. DEC Requires: 1)Removal of absorbent socks from MW2 and BMW-11, allowance for time to stabilize and then product monitoring and submission of results to DEC. 2)cc to Antea (Meyer) 12/12/17 - Austin - Assigned from Vought to Feng - end 2/20/2018 - Feng - Skype meeting among BP Nick Onufrak, Antea Group Chris Meyer and Glen Shrank, DEC Andre Obligado and June Feng. Antea has removed the absorbent sock in BMW-11 and still found LNAPL of 0.5 feet after 30 days. DEC agreed no remediation needed for onsite, but they need to remove the LNAPL in BMW-11 (at least or less than 0.1 feet) before spill could be closed. 4/24/2018 - Feng - 4Q2017, 2/26/2018. Monitoring on 12/5/2017. MW-2, 2,186 BTEX. MW-3, 1,154 BTEX, 21,8 MTBE. MW-4, 93.3 BTEX. 682.2 BTEX, 22 MTBE. MW-9, 1,684 BTEX, 33.8 MTBE. MW-10, 1,066 BTEX. MW-11, 1,887 BTEX. MW-12, 491 BTEX. MW-13, 2,002 BTEX. BMW-11, 0.25’ LNAPL. sock installed. 1Q2018,

AMOCO (Continued) **S105141059**

3/28/2018. Monitoring on 1/24/2018. MW-2, 1,638 BTEX. MW-3, 869.8 BTEX. MW-4, 101.7 BTEX. MW-5, 1,447 BTEX, 22.1 MTBE. MW-9, 832.7 BTEX, 39.9 MTBE. MW-10, 538.4 BTEX. MW-11, 1,622 BTEX. MW-12, 1,119 BTEX. MW-13, 4,797 BTEX. MW-17, 901.8 BTEX, 12.1 MTBE. BMW-11, sock in well, replaced. "

Remarks: "contaminated soil discovered from samples"

All Materials:

Site ID: 196822
Operable Unit ID: 842985
Operable Unit: 01
Material ID: 533080
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: True

Site ID: 196822
Operable Unit ID: 842985
Operable Unit: 01
Material ID: 2099353
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

Site ID: 196822
Operable Unit ID: 842985
Operable Unit: 01
Material ID: 2099354
Material Code: 2645A
Material Name: BTEX
Case No.: Not reported
Material FA: Oxygenates
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

Name: AMOCO
Address: 655 FLUSHING AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8401982 / 2003-02-27
Facility ID: 8401982
Facility Type: ER
DER Facility ID: 215665
Site ID: 196823
DEC Region: 2
Spill Cause: Unknown

AMOCO (Continued) **S105141059**

Spill Class:	D4
SWIS:	2401
Spill Date:	1984-10-26
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	Not reported
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-06-10
Spill Record Last Update:	2004-10-19
Spiller Name:	Not reported
Spiller Company:	AMOCO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT K. O'Dowd Notes: Old PIN job. Synopsis from ISR. 8 monitoring wells. Avg DTW 6'bgs. Quarterly sampling. Big file in field office. 09/25/95: PIN-4393 - ASSIGNED TO CHRIS FOR TRACKING PURPOSES. Benzene concentrations: 4/96 MW-1 1600ppb MW-2 1100ppb MW-3 6400ppb MW-4 110ppb 7/96 MW-1 990ppb MW-2 830ppb MW-3 4400ppb MW-4 470ppb 10/96 MW-1 1400ppb MW-2 960ppb MW-3 5600ppb MW-4 210ppb 1/97 MW-1 1200ppb MW-2 1800ppb MW-3 6800ppb MW-4 66ppb 4/97 MW-1 1400ppb MW-2 1300ppb MW-3 8400ppb MW-4 100ppb 8/97 MW-1 700ppb MW-2 1200ppb MW-3 5800ppb MW-4 300ppb TW-1 330ppb TW-2 730ppb TW-3 280ppb TW-4 87ppb 8/4/97 Spoke with Keith Butler, Baltec (914-273-2626). He will be looking to install 2 additional wells. May want to use peroxide injection in future. Told him we need to get some past history on the site. 8/9/97 Spoke with K. Butler. Found 4 additional MWs at site. Total of 8 wells. Therefore he feels it is delineated well. Instead of peroxide, he will likely use ORC socks. 8/20/97 While on site to investigate optimal locations for additional MWs, Baltec located 4 existing tank mat wells. The wells were designated TW-1, TW-2, TW-3 and TW-4. 8/25/97 At this sampling event, it was determined that all tank mat wells required redevelopment. They contain approx 2' silt, which is likely clogging the screened interval creating lower hydraulic conductivity across screen. This may explain BTEX depression around TW-1 and TW-2. In order to further delineate the soil/GW quality across site and to obtain more accurate understanding of GW flow pathways, Baltec intends to install one additional onsite MW in the NE corner of the site. Baltec will also redevelop TW-1 through TW-4 during the 4th quarter. 10/20/97 Voicemail from K. Butler. Old MWs were damaged. Would like to install additional wells. 10/21/97 Installed one additional well on NE corner(Harrison St & Flushing Ave.). Noticed three more wells offsite (2 on sidewalk across street on Bartlett St and 1 across street on Flushing Ave.) Wells are fine, tied in and surveyed. GW flow direction is NE. 02/27/2003-AUSTIN As per directive to close out spills with no recent history,close out. 3/14/03 REASSIGNED FROM TOMASELLO TO VOUGHT. 12/3/03 Reassigned from

AMOCO (Continued) **S105141059**

Vought to Foley. See spill #0104597. "
Remarks: ""

All Materials:
Site ID: 196823
Operable Unit ID: 894338
Operable Unit: 01
Material ID: 482068
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

I232 **VS 2973** **NY Spills** **S103573155**
East **WIPPLE ST/BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.104 mi.
550 ft. **Site 3 of 6 in cluster I**

Relative: SPILLS:
Higher
Name: VS 2973
Actual: Address: WIPPLE ST/BROADWAY
18 ft. City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9808993 / 2002-10-31
Facility ID: 9808993
Facility Type: ER
DER Facility ID: 163153
Site ID: 195838
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1998-10-19
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-10-19
CID: 233
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-10-19
Spill Record Last Update: 2002-10-31
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported

VS 2973 (Continued) **S103573155**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Con Ed e2mis #120625: J.CAMPANILE #51238 O.S NETWORKS REPORTS WHILE DOING ROUTINE 25 YEAR VISUAL INSPECTION OF VS2973, FOUND UNIT BELOW MIN & LEAKING OIL. APPROX 30 GALLONS OF TRANFORMER OIL HAS LEAKED OUT OF UNIT ONTO FLOOR OF VAULT. UNIT NOT TESTED AT THIS TIME, HISTORICAL RECORDS SHOW 5 PPM AS OF 5/25/95. SEQUENCE #95-04786. RETRO FILL OF UNIT DATED 9/14/94. NO SEWERS OR WATERWAYS AFFECTED, NO SUMP PUMP IN VAULT. STOP TAG #08577 PLACED, SAMPLE TO BE TAKEN FROM UNIT UPON REMOVAL OF FEEDER 6B47 FROM SERVICE. CLEANUP TO BE TREATED AS 50-499 PPM DISREGARD MATERIAL HISTORY OF 5PPM. UPDATE 10-20-98 CHEM LAB RESULTS 98-11269 4PPM UPDATE 10-20-98 EQUIP DRAINED AND REMOVED UNIT UPDATE: 10/20/98 - 1430 K. QUEST - 55475 - ENV. OPS., REPORTS 4 PPM CLEANUP COMPLETE WITH SLIX AND TAG #08577 REMOVED."

Remarks: "spill contained in vs leak from transformer unk exact cause spill will be cleaned after lab test results"

All Materials:

Site ID:	195838
Operable Unit ID:	1070183
Operable Unit:	01
Material ID:	566482
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L233 **TRANSFORMER VAULT 1473** **NY Spills** **S108294915**
SSW **2 TOMPKINS AVE AT FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.105 mi.
556 ft. **Site 19 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

SPILLS:

Name:	TRANSFORMER VAULT 1473
Address:	2 TOMPKINS AVE AT FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0607919 / 2007-02-16
Facility ID:	0607919
Facility Type:	ER
DER Facility ID:	321502
Site ID:	371760
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-10-11
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-10-11
CID:	78
Water Affected:	Not reported
Spill Source:	Unknown

TRANSFORMER VAULT 1473 (Continued) **S108294915**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-12
Spill Record Last Update:	2007-02-16
Spiller Name:	Not reported
Spiller Company:	Con Edison
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ERTS
DEC Memo:	"02/16/07 - See e-docs for Con Ed report detailing cleanup and closure. 202864. see eDocs"
Remarks:	"clean up pending transformer removal refernce #202864 "

All Materials:

Site ID:	371760
Operable Unit ID:	1129513
Operable Unit:	01
Material ID:	2119181
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L234 **CON EDISON - VAULT 1473** **RCRA-LQG** **1024891655**
SSW **2 TOMPKINS AVE** **NYP005131800**
< 1/8 **BROOKLYN, NY 11206**
0.105 mi.
556 ft. **Site 20 of 32 in cluster L**

Relative:
Lower

Actual:
13 ft.

RCRA-LQG:

Date form received by agency:	04/10/2018
Facility name:	CON EDISON - VAULT 1473
Facility address:	2 TOMPKINS AVE BROOKLYN, NY 11206
EPA ID:	NYP005131800
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	ALYSSA SOTTO
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	SOTTOA@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any

CON EDISON - VAULT 1473 (Continued) **1024891655**

residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/24/2017
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/24/2017
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

CON EDISON - VAULT 1473 (Continued) **1024891655**

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

L235
SSW
< 1/8
0.105 mi.
556 ft.

CON EDISON **RCRA NonGen / NLR** **1018279685**
2 TOMPKINS AVE **NYP004745261**
BROOKLYN, NY 11206

Site 21 of 32 in cluster L

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON
Site name:	CON EDISON - VAULT 1336
Facility address:	2 TOMPKINS AVE BROOKLYN, NY 11206
EPA ID:	NYP004745261
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/07/2015
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/07/2015
Owner/Op end date:	Not reported

CON EDISON (Continued) **1018279685**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 03/07/2015
- Site name: CON EDISON
- Classification: Not a generator, verified

- Date form received by agency: 03/07/2015
- Site name: CON EDISON
- Classification: Large Quantity Generator

Hazardous Waste Summary:

- . Waste code: D008
- . Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
- Waste code: D008
- Waste name: LEAD
- Amount (Lbs): 2500

Violation Status: No violations found

L236 **CON EDISON** **RCRA NonGen / NLR** **1018279705**
SSW **2 TOMPKINS AVE** **FINDS** **NYP004745469**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.105 mi.
556 ft. **Site 22 of 32 in cluster L**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:
- Date form received by agency: 03/07/2015
- Facility name: CON EDISON
- Facility address: 2 TOMPKINS AVE
  BROOKLYN, NY 11206
- EPA ID: NYP004745469
- Mailing address: IRVING PL, 15TH FL NE
  NEW YORK, NY 10003
- Contact: THOMAS TEELING

CON EDISON (Continued) **1018279705**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/07/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067694926

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018279705
Registry ID: 110067694926
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067694926

L237
SSW
< 1/8
0.105 mi.
556 ft.

CON EDISON
2 TOMPKINS AVE
BROOKLYN, NY 11206

Site 23 of 32 in cluster L

NJ MANIFEST **S120668507**
N/A

Relative:
Lower

Actual:
13 ft.

NJ MANIFEST:

EPA Id:	NYP004745469
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014087089JJK
EPA ID:	NYP004745469
Date Shipped:	3/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120668507**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L238 **CON EDISON** **NY MANIFEST** **S117741302**
SSW **2 TOMPKINS AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.105 mi.
556 ft. **Site 24 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	2 TOMPKINS AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004745261
Facility Status:	Not reported
Location Address 1:	2 TOMPKINS AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004745261
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/2015
Trans1 Recv Date:	03/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004745261
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117741302**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091031JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	2 TOMPKINS AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004745469
Facility Status:	Not reported
Location Address 1:	TOMPKINS ST & FLUSHING AV
Code:	BP
Location Address 2:	V1336
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004745469
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S117741302**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/2015
Trans1 Recv Date:	03/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004745469
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014087089JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117741302**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

L239 **CON EDISON - VAULT 1473** **NY MANIFEST** **S121968586**
SSW **2 TOMPKINS AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.105 mi.
556 ft. **Site 25 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

Name:	CON EDISON - VAULT 1473
Address:	2 TOMPKINS AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP005131800
Facility Status:	Not reported
Location Address 1:	2 TOMPKINS AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005131800
Mailing Name:	CON EDISON - VAULT 1473
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

L240 **CON EDISON** **NJ MANIFEST** **S120668487**
SSW **2 TOMPKINS AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.105 mi.
556 ft. **Site 26 of 32 in cluster L**

Relative: **Lower**
Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYP004745261
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported

CON EDISON (Continued) **S120668487**

County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091031JJK
EPA ID:	NYP004745261
Date Shipped:	3/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	014091035JJK
EPA ID:	NYP004745261
Date Shipped:	3/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120668487**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	014091032JJK
EPA ID:	NYP004745261
Date Shipped:	3/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON (Continued) **S120668487**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	014091034JJK
EPA ID:	NYP004745261
Date Shipped:	3/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003

CON EDISON (Continued) **S120668487**

Reason Load Was Rejected:	Not reported
Manifest Number:	014091033JJK
EPA ID:	NYP004745261
Date Shipped:	3/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N241 **MANHOLE #1000** **NY Spills** **S106469702**
SE **THRO0P AVE & FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.106 mi.
562 ft. **Site 4 of 14 in cluster N**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	MANHOLE #1000
Address:	THRO0P AVE & FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0402435 / 2004-09-15
Facility ID:	0402435
Facility Type:	ER

MANHOLE #1000 (Continued) **S106469702**

DER Facility ID:	257685
Site ID:	319830
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-06-04
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-06-04
CID:	407
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-04
Spill Record Last Update:	2004-09-15
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"e2mis no 153699 CARSON FOUND APPROX. 1 PT OF UNKNOWN OIL ON APPROX. 1 GAL OF WATER. THERE APPEARS TO BE A DRAIN IN STRUCTURE AFFECTED BY THE OIL. ALSO THERE ARE SIGNS OF OIL COMING FROM A DUCT DRIPPING DOWN THE CONCRETE WALL AND ON TO THE CONCRETE FLOOR. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. LIQ. SAMPLE TAKEN FROM SPILL. CLEANUP PENDING TEST RESULTS. GENE WILLIAMS REPORTS PUT A SNAKE INTO THE DRAIN AND IT WENT IN ABOUT 3 FEET. AND THERE IS OIL AND WATER IN THAT DRAIN. WILLIAMS O/S ENVIROMENTAL OPS REPORTS INITIATING CLEANUP OF MUD AND DEBRIS AWAITING TANKER. CONSENTINO ENVIROMENTAL OPS MANAGER REPORTS OIL LEAK FROM CUT IN CAP 3C 2/O. CABLE GOES NORTH. OF THE 1 PINT OF OIL ONLY 1 TO 2 OZ OF OIL WENT INTO THE DRAIN OPENING. THE OIL WAS REMOVED AND GENE WILLIAMS RODDED THE DRAIN AND FOUND IT TO BE CLOGGED WITH DIRT. # 9 RECAPPED AND SEALED 3C 2/O TO STOP LEAK. GENE WILLIAMS REMOVED OIL AND WATER FROM THE DRAIN. FLUSH DEPT WILL CLEAN AND DOUBLE WASH AND SEAL DRAIN OPENING. SAMPLE PENDING. Lab Sequence Number: 04-04378-001: PCBs < 1 ppm UPDATE: 05-JUN-2004 0205HRS MIDDLETON REPORTS DOUBLE WASHED STRUCTURE WITH BIO GEN 760. REMOVE ALL LIQUIDS FROM STRUCTURE DRAIN WAS CEMENTED. TAG # 39209 WAS REMOVED. CLEANUP COMPLETE 100%"
Remarks:	"Amount 1 pint of oil in 1 gallon of water"

All Materials:

Site ID:	319830
Operable Unit ID:	884120
Operable Unit:	01
Material ID:	490054
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

MANHOLE #1000 (Continued) **S106469702**

Units: G
Recovered: .00
Oxygenate: Not reported

N242 **MANHOLE 7898** **NY Spills** **S104652141**
SE **THORNTON & THROOP AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.107 mi.
565 ft. **Site 5 of 14 in cluster N**

Relative:
Higher

Actual:
18 ft.

SPILLS:
Name: MANHOLE 7898
Address: THORNTON & THROOP AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0001002 / 2001-12-28
Facility ID: 0001002
Facility Type: ER
DER Facility ID: 216276
Site ID: 265435
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2000-04-25
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-04-25
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-04-25
Spill Record Last Update: 2001-12-28
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #131025 Notes: 4-25-00 1240hrs Undiaperable sheen on 200gal water in manhole 7898. No oil filled equipment in hole. One liquid sample taken. 4-25-00 2238hrs LSN 00-0417 <1ppm PCB 4-26-00 1100hrs Cleanup completed by double wahsing with slix. Liquids removed by tanker, solids by vactor."
Remarks: "sheen on top of 200 gallons water. con ed #131025"

All Materials:
Site ID: 265435
Operable Unit ID: 822698
Operable Unit: 01
Material ID: 289229

MANHOLE 7898 (Continued) **S104652141**

Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N243 **WOODHULL LAUNDROMAT** **EDR Hist Cleaner** **1018434799**
SE **698 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.110 mi.
581 ft. **Site 6 of 14 in cluster N**

Relative: EDR Hist Cleaner
Higher

Actual:
17 ft.

Year:	Name:	Type:
1997	WOODHULL LAUNDROMAT	Garment Pressing And Cleaners' Agents
1998	WOODHULL LAUNDROMAT	Garment Pressing And Cleaners' Agents

---

K244 **MANHOLE 468** **NY Spills** **S104787837**
West **WALLABOUT ST/HARRISON AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.111 mi.
588 ft. **Site 9 of 14 in cluster K**

Relative: SPILLS:
Lower

Actual:
13 ft.

Name:	MANHOLE 468
Address:	WALLABOUT ST/HARRISON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0005173 / 2001-10-25
Facility ID:	0005173
Facility Type:	ER
DER Facility ID:	231752
Site ID:	285893
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-07-31
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-07-31
CID:	389
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-31

MANHOLE 468 (Continued) **S104787837**

Spill Record Last Update:	2001-10-25
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis Notes: 7/31/00 1qt unknown oil on 50gal water in manhole. Sample taken and returned 5ppm PCB. Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump was found. "
Remarks:	"caller repoting a spill of material from unk source coned#132629 samples taken clean up pending lab results"

All Materials:

Site ID:	285893
Operable Unit ID:	826228
Operable Unit:	01
Material ID:	549905
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K245 **CON EDISON SERVICE BOX: 20766** **RCRA NonGen / NLR 1016970900**
West **HARRISON AVE & WALLABOUT** **NY MANIFEST NYP004446290**
< 1/8 **BROOKLYN, NY 11206**
0.111 mi.
588 ft. **Site 10 of 14 in cluster K**

Relative: **Lower**

Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/19/2014
Facility name:	CON EDISON SERVICE BOX: 20766
Facility address:	HARRISON AVE & WALLABOUT SW COR BROOKLYN, NY 11206
EPA ID:	NYP004446290
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

CON EDISON SERVICE BOX: 20766 (Continued) **1016970900**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/19/2014
Site name: CON EDISON SERVICE BOX: 20766
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: HARRISON AVE & WALLABOUT
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004446290
Facility Status: Not reported
Location Address 1: SEC WALLABOUT & HARRSION AVE
Code: BP
Location Address 2: SB20766
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004446290
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 02/20/2014

CON EDISON SERVICE BOX: 20766 (Continued) **1016970900**

Trans1 Recv Date:	02/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004446290
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697911JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

K246 **CON EDISON** **NY MANIFEST** **S117741123**
West **HARRISSON & WALLABOUT ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.111 mi.
588 ft. **Site 11 of 14 in cluster K**

Relative: NY MANIFEST:
Lower

Name:	CON EDISON
Address:	HARRISSON & WALLABOUT ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004743332
Facility Status:	Not reported

Actual:
13 ft.

CON EDISON (Continued) **S117741123**

Location Address 1:	HARRISON PL & WALLABOUT ST
Code:	BP
Location Address 2:	M73655
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004743332
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/04/2015
Trans1 Recv Date:	03/04/2015
Trans2 Recv Date:	03/06/2015
TSD Site Recv Date:	03/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004743332
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002621305GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117741123**

Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

K247 **CON EDISON** **NJ MANIFEST** **S120668321**
West **HARRISSON & WALLABOUT ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.111 mi.
588 ft. **Site 12 of 14 in cluster K**

Relative: **Lower**

Actual: **13 ft.**

NJ MANIFEST:

EPA Id:	NYP004743332
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002621305GBF
EPA ID:	NYP004743332
Date Shipped:	3/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported

CON EDISON (Continued) **S120668321**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K248 **CON EDISON** **RCRA NonGen / NLR** **1018279510**
West **HARRISSON & WALLABOUT ST** **FINDS** **NYP004743332**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.111 mi.
588 ft. **Site 13 of 14 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/04/2015
Facility name:	CON EDISON
Facility address:	HARRISSON & WALLABOUT ST BROOKLYN, NY 11206
EPA ID:	NYP004743332
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

CON EDISON (Continued) **1018279510**

Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:
Date form received by agency: 03/04/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067691509

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018279510
Registry ID: 110067691509
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067691509

N249 **CON EDISON** **RCRA NonGen / NLR** **1019906525**
SE **THROOP AVE & FLUSHING AVE** **FINDS** **NYP004822066**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.112 mi.
591 ft. **Site 7 of 14 in cluster N**

Relative:
Higher

Actual:
18 ft.

RCRA NonGen / NLR:
Date form received by agency: 08/11/2015
Facility name: CON EDISON
Facility address: THROOP AVE & FLUSHING AVE
BROOKLYN, NY 11233
EPA ID: NYP004822066
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported

CON EDISON (Continued) **1019906525**

Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/11/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069659195

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906525
Registry ID: 110069659195
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069659195

N250
SE
< 1/8
0.112 mi.
591 ft.

CON EDISON
THROOP AVE & FLUSHING AVE
BROOKLYN, NY 11233

Site 8 of 14 in cluster N

NJ MANIFEST **S120675300**
N/A

Relative:
Higher

Actual:
18 ft.

NJ MANIFEST:

EPA Id:	NYP004822066
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619643GBF
EPA ID:	NYP004822066
Date Shipped:	8/11/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675300**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J251 **LOT 12,TAXBLOCK 2250** **NY E DESIGNATION** **S110242344**
WNW **90 WALTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.112 mi.
592 ft. **Site 9 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

E DESIGNATION:

Name:	LOT 12,TAXBLOCK 2250
Address:	90 WALTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	12
Tax Block:	2250
Borough Code:	Not reported
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

I252 **CON EDISON SERVICE BOX: 15159** **RCRA NonGen / NLR** **1016677659**
ENE **12 MANHATTAN AVE** **FINDS** **NYP004313276**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.112 mi. **NY MANIFEST**
594 ft. **Site 4 of 6 in cluster I**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/15/2013
Facility name:	CON EDISON SERVICE BOX: 15159
Facility address:	12 MANHATTAN AVE BROOKLYN, NY 11206
EPA ID:	NYP004313276
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	ANTHONY SIGNORE
Contact address:	Not reported

CON EDISON SERVICE BOX: 15159 (Continued) **1016677659**

Not reported
Contact country: Not reported
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/15/2013
Site name: CON EDISON SERVICE BOX: 15159
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058877149

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677659
Registry ID: 110058877149
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058877149

NY MANIFEST:
Name: CON EDISON
Address: 12 MANHATTAN AVE

CON EDISON SERVICE BOX: 15159 (Continued) **1016677659**

City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004313276
Facility Status:	Not reported
Location Address 1:	12 MANHATTAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004313276
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/15/2013
Trans1 Recv Date:	05/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004313276
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002018127GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported

CON EDISON SERVICE BOX: 15159 (Continued) **1016677659**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

L253 **MEL-BERN NUMBER FOUR CORP** **EDR Hist Auto** **1020379873**
SSW **645 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.113 mi.
596 ft. **Site 27 of 32 in cluster L**

Relative: EDR Hist Auto
Lower

Actual: **13 ft.**

Year:	Name:	Type:
1971	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1972	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1973	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1974	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1976	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1977	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1978	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1979	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1980	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1982	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations
1983	MEL-BERN NUMBER FOUR CORP	Gasoline Service Stations

N254 **709-715 FLUSHING AVE** **NY AST** **U004107550**
ESE **709-715 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.114 mi.
601 ft. **Site 9 of 14 in cluster N**

Relative: AST:
Higher

Actual: **18 ft.**

Name:	709-715 FLUSHING AVE
Address:	709-715 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed

709-715 FLUSHING AVE (Continued) **U004107550**

Facility Id: 2-610576
Program Type: PBS
UTM X: 589184.93104
UTM Y: 4506046.22624
Expiration Date: N/A
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 381757
Affiliation Type: Facility Owner
Company Name: FLUSHING 1 REALTY, LLC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 15 CALDER PL.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (718) 499-5100
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-09-11

Site Id: 381757
Affiliation Type: Mail Contact
Company Name: P.W. GROSSER CONSULTING
Contact Type: Not reported
Contact Name: KRIS ALMSKOG
Address1: 630 JOHNSON AVE
Address2: SUITE 7
City: BOHEMIA
State: NY
Zip Code: 11716-2618
Country Code: 001
Phone: (631) 589-6353
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 2007-05-21

Site Id: 381757
Affiliation Type: Facility Operator
Company Name: 709-715 FLUSHING AVE
Contact Type: Not reported
Contact Name: FLUSHING 1 REALTY, LLC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 499-5100
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 2007-05-21

709-715 FLUSHING AVE (Continued) **U004107550**

Site Id:	381757
Affiliation Type:	Emergency Contact
Company Name:	FLUSHING 1 REALTY, LLC.
Contact Type:	Not reported
Contact Name:	MICHAEL SBEGLIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 939-5450
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2007-05-21

Tank Info:

Tank Number:	01
Tank Id:	217309
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	03/30/1970
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/03/2007
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	gasoline

Tank Number:	02
Tank Id:	217310

709-715 FLUSHING AVE (Continued) **U004107550**

Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 03/30/1970
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/03/2007
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: gasoline

Tank Number: 03
Tank Id: 217311
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported

709-715 FLUSHING AVE (Continued) **U004107550**

Install Date:	03/30/1970
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/03/2007
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	gasoline

Tank Number:	04
Tank Id:	217312
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	03/30/1970
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/03/2007
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	gasoline

J255 **LOT 10,TAXBLOCK 2250** **NY RES DECL** **S110242342**
WNW **88 WALTON STREET** **NY E DESIGNATION** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.115 mi.
605 ft. **Site 10 of 17 in cluster J**

Relative: ENV RES DECL:
Lower

Name:	LOT 10,TAXBLOCK 2250
Address:	88 WALTON STREET
City,State,Zip:	BROOKLYN, NY 11206
Borough:	BK

Actual:
13 ft.

LOT 10,TAXBLOCK 2250 (Continued) **S110242342**

Tax Block: 2250
Tax Lot: 10

Reference Number: R-15
Date Recorded: 3/18/2003
Satisfaction Date: Not reported
CEQR Number: 02DCP013K
Application Number: 010719 ZMK
Recording Reference Number: 2003000052129
Type: Hazmat
Lot Remediation Date: Not reported

E DESIGNATION:
Name: LOT 10,TAXBLOCK 2250
Address: 88 WALTON STREET
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 10
Tax Block: 2250
Borough Code: BK
E-No: E-238
Effective Date: 12/22/2009
Satisfaction Date: Not reported
Ceqr Number: 09HPD019K
Ulurp Number: 090413ZMK
Zoning Map No: 13b

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

J256 **88 WALTON STREET** **NY VCP** **S118943506**
WNW **88 WALTON STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.115 mi.
605 ft. **Site 11 of 17 in cluster J**

Relative:
Lower

Actual:
13 ft.

VCP NYC:
Project ID: 15CVCP117K
Project Name: 88 WALTON STREET
Project Address: 88 WALTON STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP117K
File Name: 2015-03-01.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP117K/2015-03-24.15RHAN331K.report.RIR.EBC.pdf

Project ID: 15CVCP117K
File Name: 2015-04-20.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP117K/2015-04-20.15RHAN331K.report.86-90_Walton_Street_RAWP_clean.EBC_OER.pdf

Project ID: 15CVCP117K
File Name: 2015-04-01.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP117K/2015-04-01.15CVCP117K.doc.88_Walton_Street_Factsheet-1.pdf

Project ID: 15CVCP117K
File Name: 2015-04-01.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP117K/2015-03-31.15CVCP117K.doc.Translated_FS1.OER.pdf

Project ID: 15CVCP117K
File Name: 2015-04-01.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP117K/2015-03-31.15CVCP117K.doc.Translated_CPS.OER.pdf

---

K257 **LOT 37,TAXBLOCK 2249** **NY E DESIGNATION** **S121343923**
West **174 HARRISON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.116 mi.
610 ft. **Site 14 of 14 in cluster K**

Relative:
Lower

Actual:
13 ft.

E DESIGNATION:
Name: LOT 37,TAXBLOCK 2249
Address: 174 HARRISON AVENUE
City,State,Zip: BROOKLYN, NY 11206
Tax Lot(s): 37
Tax Block: 2249
Borough Code: BK
E-No: E-427
Effective Date: 10/31/2017
Satisfaction Date: Not reported
Ceqr Number: 15DCP117K
Ulurp Number: 150278ZMK, 150277ZRK
Zoning Map No: 13b

LOT 37,TAXBLOCK 2249 (Continued) **S121343923**

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

M258 **DRUM RUN** **NY Spills** **S108638863**
NNW **BROADWAY & WALTON ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.116 mi.
612 ft. **Site 3 of 5 in cluster M**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:
Name: DRUM RUN
Address: BROADWAY & WALTON ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0704064 / 2007-08-09
Facility ID: 0704064
Facility Type: ER
DER Facility ID: 333558
Site ID: 384146
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: C3
SWIS: 2401
Spill Date: 2007-07-11
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2007-07-11
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-07-11
Spill Record Last Update: 2007-08-09
Spiller Name: NYCDEP HAZMAT
Spiller Company: Not reported
Spiller Address: BROADWAY & WALTON ST
Spiller Company: 001
Contact Name: NYCDEP HAZMAT
DEC Memo: "added to drum run. 08/09/07 Drum was found on 08/07/07, was pumped out, list was sent to Sanitation to pick up the empty drum."
Remarks: "ONE 55 GALLON DRUM ON SIDEWALK NEEDS TO BE PICKED UP"

All Materials:
Site ID: 384146

DRUM RUN (Continued) **S108638863**

Operable Unit ID:	1141456
Operable Unit:	01
Material ID:	2131669
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I259 **CON EDISON - SERVICE BOX 15646** **RCRA-LQG** **1018278246**
East **685 BROADWAY** **NYP004730065**
< 1/8 **BROOKLYN, NY 11206**
0.117 mi.
617 ft. **Site 5 of 6 in cluster I**

Relative:
Higher

Actual:
18 ft.

RCRA-LQG:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON - SERVICE BOX 15646
Facility address:	685 BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004730065
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

CON EDISON - SERVICE BOX 15646 (Continued) **1018278246**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/10/2015
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/10/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/10/2015
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 02/10/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD

CON EDISON - SERVICE BOX 15646 (Continued) **1018278246**

Amount (Lbs): 3000

Violation Status: No violations found

I260 **CON EDISON** **NY MANIFEST** **S117739915**
East **685 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.117 mi.
617 ft. **Site 6 of 6 in cluster I**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	685 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004730065
Facility Status:	Not reported
Location Address 1:	685 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004730065
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/10/2015
Trans1 Recv Date:	02/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004730065
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001084510GBF

CON EDISON (Continued) **S117739915**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

O261 **CON EDISON** **RCRA NonGen / NLR** **1016969041**
South **149 HOPKINS ST** **NY MANIFEST** **NYP004426862**
< 1/8 **BROOKLYN, NY 11206**
0.117 mi.
618 ft. **Site 1 of 4 in cluster O**

Relative: RCRA NonGen / NLR:
Higher

Date form received by agency:	02/01/2015
Facility name:	CON EDISON
Facility address:	149 HOPKINS ST BROOKLYN, NY 11206
EPA ID:	NYP004426862
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Actual:
15 ft.

CON EDISON (Continued) **1016969041**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/01/2015
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 02/27/2014
Site name: CON EDISON SERVICE BOX: 7146
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 149 HOPKINS ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004722955
Facility Status: Not reported
Location Address 1: 149 HOPKINS ST
Code: BP
Location Address 2: SB7146
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004722955
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON (Continued) **1016969041**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	02/01/2015
Trans1 Recv Date:	02/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004722955
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	007748139FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	149 HOPKINS ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004426862
Facility Status:	Not reported
Location Address 1:	AT FRONT OF 149 HOPKINS ST

CON EDISON (Continued) **1016969041**

Code: BP
Location Address 2: SB7146
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004426862
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 01/27/2014
Trans1 Recv Date: 01/27/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/31/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004426862
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002329403GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: Y
Manifest Ref Number: Not reported
Alt Facility RCRA ID: NJD991291105
Alt Facility Sign Date: 31-Jan-2014 00:00:00
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **1016969041**

Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

J262 **HARRISON WALTON PROPERTY MANAGEMENT LLC** **NY MANIFEST** **S118708624**
WNW **86-90 WALTON ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.117 mi.
620 ft. **Site 12 of 17 in cluster J**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

Name:	HARRISON WALTON PROPERTY MANAGEMENT LLC
Address:	86-90 WALTON ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYR000226365
Facility Status:	Not reported
Location Address 1:	86-90 WALTON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000226365
Mailing Name:	HARRISON WALTON PROPERTY MANAGEMENT LLC
Mailing Contact:	HARRISON WALTON PROPERTY MANAGEMENT
Mailing Address 1:	200 BROADWAY SUITE 170
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11211
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3474895479

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	PAD146714878

HARRISON WALTON PROPERTY MANAGEMENT LLC (Continued) **S118708624**

Trans2 State ID:	Not reported
Generator Ship Date:	05/26/2016
Trans1 Recv Date:	05/26/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/26/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000226365
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	015978935JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	38120
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

J263 **160-163 HARRISON AVENUE, 86-90 WALTON STREET** **NY UST** **U004272332**
WNW **86-90 WALTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.117 mi.
620 ft. **Site 13 of 17 in cluster J**

Relative: UST:
Lower

Name:	160-163 HARRISON AVENUE, 86-90 WALTON STREET
Address:	86-90 WALTON STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-612741 / Unregulated/Closed

Actual:
13 ft.

160-163 HARRISON AVENUE, 86-90 WALTON STREET (Continued) **U004272332**

Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	555122
Affiliation Type:	Facility Owner
Company Name:	HARRISON WALTON PROPERTY MANAGEMENT LLC
Contact Type:	OWNER
Contact Name:	BENJAMIN SILBERSTEIN
Address1:	151 ACRES ROAD #301
Address2:	Not reported
City:	MONROE
State:	NY
Zip Code:	10950
Country Code:	001
Phone:	(718) 301-1800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-09-07

Site Id:	555122
Affiliation Type:	Mail Contact
Company Name:	JIH BUILDERS GROUP LLC
Contact Type:	Not reported
Contact Name:	ISAAC HIRSCH
Address1:	389 WILLOUGHBY AVENUE
Address2:	SUITE #207
City:	BROOKLYN
State:	NY
Zip Code:	11205
Country Code:	001
Phone:	(718) 522-2750
EMail:	ISAACH@JIHBUILDERS.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-07-21

Site Id:	555122
Affiliation Type:	Facility Operator
Company Name:	160-163 HARRISON AVENUE, 86-90 WALTON STREET
Contact Type:	Not reported
Contact Name:	SAM KOHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW

160-163 HARRISON AVENUE, 86-90 WALTON STREET (Continued) **U004272332**

Date Last Modified: 2017-07-21

Site Id: 555122
Affiliation Type: Emergency Contact
Company Name: HARRISON WALTON PROPERTY MANAGEMENT LLC
Contact Type: Not reported
Contact Name: ABE SILBERSTEIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 541-3534
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-09-07

Tank Info:

Tank Number: NO. 1
Tank ID: 270058
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/08/2016
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 09/07/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

J264 **HARRISON WALTON PROPERTY MANAGEMENT LLC** **RCRA NonGen / NLR** **1018281259**
WNW **86-90 WALTON ST** **FINDS** **NYR000226365**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.117 mi.
620 ft. **Site 14 of 17 in cluster J**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/18/2017
Facility name:	HARRISON WALTON PROPERTY MANAGEMENT LLC
Facility address:	86-90 WALTON ST BROOKLYN, NY 11206
EPA ID:	NYR000226365
Mailing address:	BROADWAY SUITE 170 BROOKLYN, NY 11211
Contact:	ABRAHAM SILBERSTEIN
Contact address:	BROADWAY SUITE 170 BROOKLYN, NY 11211
Contact country:	US
Contact telephone:	718-541-3534
Contact email:	ABEDATA200@GMAIL.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	HARRISON WALTON PROPERTY MANAGEMENT LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	09/11/2000
Owner/Op end date:	Not reported

Owner/operator name:	HARRISON WALTON PROPERTY MANAGEMENT LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	09/11/2000
Owner/Op end date:	Not reported

Owner/operator name:	HARRISON WALTON PROPERTY MANAGEMENT LLC
Owner/operator address:	BROADWAY SUITE 170 BROOKLYN, NY 11211
Owner/operator country:	US
Owner/operator telephone:	718-541-3534
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

HARRISON WALTON PROPERTY MANAGEMENT LLC (Continued) **1018281259**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 09/11/2000
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/12/2016
Site name: HARRISON WALTON PROPERTY MANAGEMENT LLC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110067676330

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018281259
Registry ID: 110067676330
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067676330

J265
West
< 1/8
0.117 mi.
620 ft.

LOT 4,TAXBLOCK 2250
161 HARRISON AVENUE
BROOKLYN, NY 11206

Site 15 of 17 in cluster J

NY RES DECL **S110242404**
NY E DESIGNATION **N/A**

Relative:
Lower

Actual:
13 ft.

ENV RES DECL:

Name:	LOT 4,TAXBLOCK 2250
Address:	161 HARRISON AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Borough:	BK
Tax Block:	2250
Tax Lot:	4
Reference Number:	R-15
Date Recorded:	3/18/2003
Satisfaction Date:	Not reported
CEQR Number:	02DCP013K
Application Number:	010719 ZMK
Recording Reference Number:	2003000052129
Type:	Hazmat
Lot Remediation Date:	Not reported

E DESIGNATION:

Name:	LOT 4,TAXBLOCK 2250
Address:	161 HARRISON AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	4
Tax Block:	2250
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

O266 **CON EDISON** **NJ MANIFEST** **S120678575**
South **161 HOPKINS ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.118 mi.
625 ft. **Site 2 of 4 in cluster O**

Relative:
Higher

Actual:
16 ft.

NJ MANIFEST:

EPA Id:	NYP004884744
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015322132JJK
EPA ID:	NYP004884744
Date Shipped:	12/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120678575**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

O267 **CON EDISON** **RCRA NonGen / NLR** **1019909431**
South **161 HOPKINS ST** **FINDS** **NYP004884744**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.118 mi.
625 ft. **Site 3 of 4 in cluster O**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/29/2016
Facility name:	CON EDISON
Facility address:	161 HOPKINS ST BROOKLYN, NY 11206
EPA ID:	NYP004884744
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/29/2016
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1019909431**

Registry ID: 110069661529

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019909431
Registry ID: 110069661529
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069661529

L268 **ACP BK I, LLC** **NY UST** **U004064026**
SSW **630 FLUSHING AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.119 mi.
629 ft. **Site 28 of 32 in cluster L**

Relative:
Lower

Actual:
13 ft.

UST:
Name: ACP BK I, LLC
Address: 630 FLUSHING AVENUE
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-017329 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 588859.39158
UTM Y: 4505974.41463
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 125
Affiliation Type: Mail Contact
Company Name: ACUMEN CAPITAL PARTNERS, LLC
Contact Type: Not reported
Contact Name: JEFF ROSENBLUM
Address1: 630 FLUSHING AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11206
Country Code: 001
Phone: (718) 360-9500
EMail: JROSENBLUM@ACUMENNY.COM
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-07-06

Site Id: 125
Affiliation Type: Facility Operator

ACP BK I, LLC (Continued) **U004064026**

Company Name:	ACP BK I, LLC
Contact Type:	Not reported
Contact Name:	KRIS BLONARIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 203-4715
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-06

Site Id:	125
Affiliation Type:	Emergency Contact
Company Name:	ACP BK I, LLC
Contact Type:	Not reported
Contact Name:	JEFF ROSENBLUM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 360-9500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-06

Site Id:	125
Affiliation Type:	Facility Owner
Company Name:	ACP BK I, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	JEFF ROSENBLUM
Address1:	630 FLUSHING AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 360-9500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-06

Tank Info:

Tank Number:	002
Tank ID:	30762
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	12/01/1933

ACP BK I, LLC (Continued) **U004064026**

Date Tank Closed: 06/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 30767
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 18000
Install Date: 12/01/1955
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

ACP BK I, LLC (Continued) **U004064026**

Tank Number:	005
Tank ID:	30763
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	30000
Install Date:	12/01/1955
Date Tank Closed:	06/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	006
Tank ID:	30764
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	30000
Install Date:	12/01/1955
Date Tank Closed:	06/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

ACP BK I, LLC (Continued) **U004064026**

H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number:	007
Tank ID:	30765
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	30000
Install Date:	12/01/1955
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	008
Tank ID:	30766
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	30000
Install Date:	12/01/1955
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

ACP BK I, LLC (Continued) **U004064026**

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	209
Tank ID:	30770
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	1500
Install Date:	12/01/1977
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	210
Tank ID:	30771
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

ACP BK I, LLC (Continued) **U004064026**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 21A
Tank ID: 30772
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1972
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: D1E
Tank ID: 30768
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1932
Date Tank Closed: Not reported

ACP BK I, LLC (Continued) **U004064026**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	FO-1
Tank ID:	41683
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	20000
Install Date:	04/01/1991
Date Tank Closed:	05/01/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B03 - Tank External Protection - Original Impressed Current
D01 - Pipe Type - Steel/Carbon Steel/Iron
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
F06 - Pipe External Protection - Wrapped

ACP BK I, LLC (Continued) **U004064026**

Tank Number:	FO-2
Tank ID:	41684
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	20000
Install Date:	04/01/1991
Date Tank Closed:	05/01/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NTFREEMA
Last Modified:	04/14/2017

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B03 - Tank External Protection - Original Impressed Current
D01 - Pipe Type - Steel/Carbon Steel/Iron
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
F06 - Pipe External Protection - Wrapped

Tank Number:	G01
Tank ID:	56702
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

ACP BK I, LLC (Continued) **U004064026**

I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	G02
Tank ID:	56703
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number:	G03
Tank ID:	56704
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

ACP BK I, LLC (Continued) **U004064026**

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number:	G04
Tank ID:	56705
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number:	G05
Tank ID:	56706
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

ACP BK I, LLC (Continued) **U004064026**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number: G06
Tank ID: 56707
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: GAS
Tank ID: 30769
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1932
Date Tank Closed: Not reported

ACP BK I, LLC (Continued) **U004064026**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	GST
Tank ID:	30773
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	2000
Install Date:	12/01/1930
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	P10

ACP BK I, LLC (Continued) **U004064026**

Tank ID:	30777
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number:	PK6
Tank ID:	30778
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

ACP BK I, LLC (Continued) **U004064026**

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: PK7
Tank ID: 30774
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1951
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Number: PK8
Tank ID: 30775
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1932
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

ACP BK I, LLC (Continued) **U004064026**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser

Tank Number:	PK9
Tank ID:	30776
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

L269 **ACUMEN PARTNERS LLC** **NY LTANKS** **U003074670**
SSW **630 FLUSHING AVE** **NY AST** **N/A**
< 1/8 **BROOKLYN, NY 11206** **NY VCP**
0.119 mi. **NY Spills**
629 ft. **Site 29 of 32 in cluster L** **NY MANIFEST**

Relative:
Lower

Actual:
13 ft.

LTANKS:

Name:	TEXACO STATION, PFIZER INC - MISC
Address:	630 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9901811 / 2006-03-31
Facility ID:	9901811
Site ID:	201034
Spill Date:	1999-05-17
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility

ACUMEN PARTNERS LLC (Continued) **U003074670**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1999-05-17
CID:	257
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-05-17
Spill Record Last Update:	2006-03-31
Spiller Name:	Not reported
Spiller Company:	TEXACO STATION
Spiller Address:	630 FLUSHING AVE
Spiller County:	001
Spiller Contact:	THOMAS SNEE
Spiller Phone:	(718) 780-8686
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244426
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 1/2/2004 Reassigned from Rommel to Sun. (Also refer to Spill # 93-03325 for this site) 07/08/04 This spill is closed. To be investigated and remediated under Spill #93-03325. 01/12/06-The spill is reopened since this spill was caused by gasoline, while Spill #93-03325 was caused by #6 fuel oil. 1/12/2006 - Feng - Called Pfizer Inc and spoke with Manuel Lopez (718-780-0947). He remembers that they have been sent the some report to DEC. He would contact his engineer and find the information DEC need and get back to DEC. (RJF) 1/12/2006 - Feng - Faxed the two spill report to Samantha Plourde (718-780-8380) and request to send 1) tank closure report, 2) any other site investigation/site assessment, to DEC. (RJF) 1/27/2006 - Feng - Reviewed the Tank Closure Report of 12/10/1999, sent on 1/20/2006 by Pfizer. These 6 USTs were discovered during pre-construction activities in the northwestern corner. The site was a former Texaco gasoline station some time in the 1940's. 6 USTs in the northwestern corner of the site were confirmed by the insurance maps. Pfizer registered and removed the USTs performed from 5/17/1999 to 9/30/1999. 6 soil boringw were done prior the removal activities. Analyticals show SB-6 (10'-12' bg) with high contamination, 840 ppb Toluene, 10,000 ppb Ethylbenzene, 51,800 ppb Xylene, 20,000 ppb 1,3,5-Trimethylbenzene, and 40,000 ppb 1,2,4-Trimethylbenzene. To further delineate the SB-6, SB-6A to SB-6E (12'-14')were drilled and sampled, lab result indicated low VOCs. And removed all the soil above the clay layer (12' bg plus 0.5'-1.0' of the clay). The tankks found no carcks or holes. After tank removal, precipitation occurred for several days and the rain water run into the excavation, water removed and tested, found 6,047 ppb BTEX. All the piping associated with the USTs were removed. Soil removal extented to where the pre-USt removal soil samples contained concentration of VOCs below DEC STARS. Total of 286.18 tons of soil were removed. The report attached with lab analyticals sheet for soil sample, but not indiated

ACUMEN PARTNERS LLC (Continued) **U003074670**

the location of sample taken and not mentioned in the narrative text. Backfilled with clean sand and permanent asphalt pavement was placed on top. Requested spill closure. (RJF) 1/27/2006 - Feng - Send letter to Pfizer request of 1) groundwater sample in the vicinity of the former SB-6 boring location, 2) clarification of the soil sample presented in the lab report attached in App C. Result due 4/3/2006. Faxed to Scott Glash (Roux). (RJF) 02/09/06: This spill transferred from R.Feng to S.Kraszewski. 03/06/06: Recieved letter from Pfizer, dated March 2, 2006. Pfizer is requesting that the Department suspend the April 3rd deadline for the subsurface investigation. Pfizer believes that the Department is not familiar with all documentaiton related to this spill. Pfizer will collect and review all historic documentation and correspondence related to the closure and removal of the gasoline USTs. This information will be submitted to the DEC by March 15, 2006. Pfizer believes that based on the contents of this letter that an additional investigation will not be necessary. - SK 03/24/06: Received detailed summary of closure activities from Pfizer. Currently under review. - SK 03/27/06: Reviewed all documents for the UST closure. This additional information was sent in response to the DEC's request for a complete subsurface delineation both on-site and off-site. Pfizer believes that with the information supplied in this closure summary that there is no need for further investigation and NFA should be issued. Pfizer has also included documentation and explanations in response to R.Feng's letter issued January 2006 and previous DEc requests: No post-exc samples taken: Pfizer contests that retrieving samples would cause stockpiling of contaminated soil and leave the excavation open, which is a hazard. Instead, they conducted soil borings to eliminate the hazards associated with an open excavation. Furthermore, Pfizer feels that the soil borings properly delineated the horizontal extent of the contamination since they were conducted until no VOCs were detected by PID. Rainwater from the excavation was sampled and found to contain high levels of BTEX: It was a waste characterization sample, a composite from several sources. Pfizer states this water sample was mixture of rainwater from the USTs, the excavation and waste water used to clean each UST. A soil samples with highly elevated VOC concentrations was detected but it was not mentioned in the report summary nor is it given a location on the site plan: This sample was alos a composite sample, collected from each UST. Sand material was discovered within the USTs and this sample was used to characterize the tank solids for proper disposal. It did not come from the excavation. R.Feng requests GW samples: Pfizer attached results from two GW samples taken from the former tank area in June 2004. The samples were takenf rom 8 to 10 fbg using low-flow purging techniques. Actetone was detected in both samples, a common laboratory contaminant. Naphthalene and Xylenes were detcted but below GW standards. Boring logs, PID logs, information of perched GW and explanations of work methods are also included in response to a February 2000 letter from DEC to provide information for these shortcomings in the UST closure report from 1999. - SK 03/27/03: Called Manuel Lopez to ask about the report. He said it would be best to contact Omar at Roux & Associates. I called and left Omar (631-232-2600) a voicemail to call me back. - SK 03/28/06: Rob Kovacs for Roux and Associates called in place of Omar. I asked Rob about the clay layer and he said based on historic production wells used by Pfizer and Roux & Associates' experience with the surrounding area they have mapped out the extent of the clay layer. Rob is emailing me

ACUMEN PARTNERS LLC (Continued) **U003074670**

Remarks:	a map with the known extent of the clay layer. - SK 03/31/06: Received PDF of the geologic cross section for that area and an overhead map. After careful consultation and consideration with supervisor J.Kolleeny, we feel that based on all of the available information at hand, this spill poses no threat to GW, the environment or the public. NFA letter sent out. Closed out. - SK " "TOOK 65 BORING AND RECEIVED TEST RESULTS BACK THIS MORNING SHOW CONTAMINATED SOIL"

All Materials:

Site ID:	201034
Operable Unit ID:	1076587
Operable Unit:	01
Material ID:	305339
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AST:

Name:	ACP BK I, LLC
Address:	630 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-017329
Program Type:	PBS
UTM X:	588859.39158
UTM Y:	4505974.41463
Expiration Date:	N/A
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	125
Affiliation Type:	Mail Contact
Company Name:	ACUMEN CAPITAL PARTNERS, LLC
Contact Type:	Not reported
Contact Name:	JEFF ROSENBLUM
Address1:	630 FLUSHING AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 360-9500
EMail:	JROSENBLUM@ACUMENNY.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-06

Site Id:	125
Affiliation Type:	Facility Operator

ACUMEN PARTNERS LLC (Continued) **U003074670**

Company Name:	ACP BK I, LLC
Contact Type:	Not reported
Contact Name:	KRIS BLONARIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 203-4715
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-06

Site Id:	125
Affiliation Type:	Emergency Contact
Company Name:	ACP BK I, LLC
Contact Type:	Not reported
Contact Name:	JEFF ROSENBLUM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 360-9500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-06

Site Id:	125
Affiliation Type:	Facility Owner
Company Name:	ACP BK I, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	JEFF ROSENBLUM
Address1:	630 FLUSHING AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 360-9500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-06

Tank Info:

Tank Number:	001
Tank Id:	30761
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

ACUMEN PARTNERS LLC (Continued) **U003074670**

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/1993
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	463
Tank Id:	30779
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017

ACUMEN PARTNERS LLC (Continued) **U003074670**

Material Name: #2 fuel oil (on-site consumption)

Tank Number: EG-01
Tank Id: 64111
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1975
Capacity Gallons: 62
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NTFREEMA
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: F03
Tank Id: 53532
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
G01 - Tank Secondary Containment - Diking (Aboveground)
H99 - Tank Leak Detection - Other
B07 - Tank External Protection - Retrofitted Sacrificial Anode

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 10/01/1974

ACUMEN PARTNERS LLC (Continued) **U003074670**

Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1996
Register:	True
Modified By:	dxliving
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	FP-01
Tank Id:	64112
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1973
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	FP-02
Tank Id:	64113
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)

ACUMEN PARTNERS LLC (Continued) **U003074670**

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	diesel

VCP:

Name:	PFIZER INC. (CITRIC BLOCK)
Address:	630 FLUSHING AVE.
City,State,Zip:	BROOKLYN, NY
Program Type:	VCP
Site Code:	56802
HW Code:	V00067
Site Class:	C
SWIS:	2401
Region:	2
Town:	New York City
Acres:	1.75
Date Record Added:	11/30/2000
Date Record Updated:	03/23/2007
Updated By:	dcwalsh
Site Description:	The Citric Block Site is located in the Williamsburg section of Brooklyn, New York. Gerry Street, Harrison Avenue, and Union Avenue border the Citric Block Site to the north, east, and west, respectively, while Flushing Avenue border the Citric Block Site to the south . The Citric Block Site is situated within a high-density, mixed urban residential commercial industrial zone, approximately one mile east-southeast of the East River. Pfizer decommissioned the Citric Block Site for future redevelopment and/or beneficial use. As part of the decommissioning process, all Citric Block Site buildings were demolished, with demolition activities being completed in August 1995. Presently, the reinforced-concrete slab foundation is the only aboveground remnant of the former buildings. The concrete slab is continuous throughout most of the Citric Block Site, and varies in thickness between approximately O.5 and 1.5 feet. The remaining portion of the Citric Block Site is covered with asphalt pavement approximately two inches thick with a four-inch aggregate subgrade. The entire Citric Block Site is surrounded by a 10-ft high chain-link fence, and is under continuous security surveillance. The Citric Block Site was developed for chemical manufacturing between 1854 and 1888 and it operated continuously until 1985, and was demolished in 1995. Redevelopment is likely to include paved areas for outdoor activities in the center of the Citric Block Site and a small park in the western portion. The remainder of the Citric Block Site would be Capped by either the existing concrete slab or by new pavement. The cap will prevent any direct exposure of future users of the property with fill material. Institutional controls involving Deed

ACUMEN PARTNERS LLC (Continued) **U003074670**

	restrictions have been implemented. The property can be used for industrial/ commercial usage. Site Management Plan requires proper management of all future subgrade construction activities and proper notification to the Department.
Env Problem:	The site has been cleaned up. Post remedial groundwater monitoring was satisfactory.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Applicant/Requestor
Sub Type:	ZZZ
Owner Name:	JOHN S KEITH,MGR.
Owner Company:	PFIZER, INC.-US PHARMACEUTICALS GROU
Owner Address:	235 EAST 42ND ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10017-5755
Owner Country:	United States of America
HW Code:	V00067
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00067
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00067
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	D2-0001-96-05(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

SPILLS:

Name:	FORMER PFIZER PROPERTY
Address:	630 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Spill Number/Closed Date:	1011062 / 2014-01-14
Facility ID:	1011062
Facility Type:	ER
DER Facility ID:	399574
Site ID:	444686
DEC Region:	2
Spill Cause:	Unknown

ACUMEN PARTNERS LLC (Continued) **U003074670**

Spill Class:	C4
SWIS:	2401
Spill Date:	2011-02-01
Investigator:	RVKETANI
Referred To:	011414 SPILL CLOSURE MEETING
Reported to Dept:	2011-02-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-02-01
Spill Record Last Update:	2014-01-16
Spiller Name:	Not reported
Spiller Company:	PFIZER, INC.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RUSSEL DOWNEY
DEC Memo:	"02/02/11- Zhune spoke to Russel Downey 908-413-0811. Site is a Pfizer Factory. Property is going to be sold. During investigation found groundwater contamination. Requested report. Mr. Russel will send the report. 04/04/12-Roux Associates sent the Petroleum Investigation Report dated June 24, 2011. Property solution performed Phase I and Pase II subsurface invetigation activities at site E and F on behalf of Acumen Capital Partner, LLC (Acumen)(buyer). PhaseII.- Included the completion of 24 soil borings, with the collection of 24 soil borings samples and 7 groundwater samples were collected from temporary well. Of the 24 borings completed 12 were located on Site E and 12 were located on Site F. Four (4) of the seven groundwater samples were collected on Site E, and the remaining three collected on Site F. Only The propety solution's borings designated SB-19,SB-20/GW-20, SB-21, SB-22/GW-22, SB-23, SB-24 and SB-25 were completed within the former Main Plant near the former Fitness Center. The analytical results inidcated that soil and groundwater collected from boring SB-22/GW-22 (located within the Former Fitness Center) contained elevated concentrations of VOCs. The soil samples collected from the four (4) borings located near SB-22 as well as borings located at the west end of the former Main Plant (SB-19 and SB-20) did not have any exceedances. The groundwater sample collected from boring SB-20/GW-20) at 15 to 16 ft bls. detected VOCs below the applicable limit. In response to the identification of groundwater impacts in phase II beneath the Main Plant, Roux Associates on behalf of Pfizer conducted focused investigation activities in April, May and June 2011. The focused investigation included the installation of four(4) deep wells BMW-10, BMW-11, BMW-12, BMW-13 and a total of three (3) soil borings TPNE, TPSE, TPSW. Groundwater samples were collected from wells BMW-10 trough BMW-13 and soil borings TPNE, TPSE, TPSW. The analytical results indicated the following VOCs (BTEX, 1,3,5 trimethybenzene, Isopropylbenzene, naphthalene, n-propylbenzene, and p-isopropyltoluene) were detected above the acceptable limits in the groundwater sample collected from BMW-11. LNAPL was found in well BMW-11 at a thickness of 2.76 feet. A sample

ACUMEN PARTNERS LLC (Continued) **U003074670**

of LNAPL was collected for gas chromatography product characterization analysis. The LNAPL was identified as leaded gasoline. The groundwater sample collected from boring TPNE indicated the following VOCS(BTEX, 1,3,5 trimethybenzene,Isopropylbenzene, MTBE, naphthalene and n-propylbenzene) detected above the acceptable limits. BP evaluated Groundwater flow directions in shallow perched water. BP reported groundwater flow to be in the northeast direction at the BP service station. Pfizer's assessment evaluated Groundwater flow directions in deep water. Pfizer reported that Groundwater flow in the deep zone was to the southwest. 04/11/12- Roux Associated Inc. sent the Supplemental Petroleum Investigation Report dated July 22,2011 05/07/12-This spill has been transferred to Hassan Hussein of the Hazardous Material Unit. 1/24/2013 - Raphael Ketani. The spill case for this Commercial Property at 630 Flushing Avenue, Brooklyn, 11206 was transferred to me. The spill was called in on 2/1/11 due to the discovery of oil contaminated soil samples. The block and lot are 1720 and 1. The deed date is 2/11/11. The property was sold by Pfizer, Inc., 235 East 42nd Street, NY, 10017 to Acumen Capital Partners (ACP) BK I, LLC, 37-18 Northern Blvd., Ste. 300, LIC, 11101. PBS is #2-017329. There were 31 tanks. Twenty five (25) were closed, 1 was converted to non-regulatory use and 5 are active. The tank sizes ranged from 62 gals. to 30,000 gal. The products contained were #6 oil, #2 oil, diesel, gasoline and other. Presently, there are 6 active tanks. They range in size from 62 gals. to 20,000 gals. The two 20,000 gal. tanks contain #6 oil and others (300 gal., 275 gal. and 62 gal.) contain diesel fuel. A 275 gal. tank contains #2 heating oil is also active. 3/18/13 - Raphael Ketani. Matthew (Mat) Carroll, P.E., of Tenen Environmental, LLC (646) 606-2332, ext 103 [121 West 27th Street, Suite 1004, New York, NY 10001, mcarroll@tenen-env.com] called today regarding the site. He is the new consultant for ACP. I tried to contact him, but could only leave a message. Mr. Carroll called me back. He said that Pfizer is still involved in the remediation of the property, even though ACP bought the site. They are the responsible party. Mr. Carroll will send me the two ROUX reports for my review. However, Pfizer is contending that there is a gas station upgradient which is the source of the contamination. Mr. Carroll sent me the following contact information: Please address all correspondence related for Spill #1011062 to: Robert Kovacs, Sr. Environmental Scientist Roux Associates, Inc. 209 Shafter Street Islandia, New York 11749 rkovacs@rouxinc.com Please also cc Pfizer, the site owner and myself. Office addresses and email addresses are as follows: Matthew R. Basso, MS, CHMM Manager, ERT Pfizer 100 Route 206N (M/S 414) Peapack, NJ 07977 Matt.Basso@pfizer.com Jeffrey Rosenblum ACP BK 1 LLC The Standard Motor Products Building 37-18 Northern Boulevard, Suite 300 Long Island City, NY 11101 jrosenblum@acumenny.com 3/28/13 - Raphael Ketani. I reviewed the 6/24/11 Petroleum Investigation Report which was produced by Roux Associates, Inc. for Pfizer. Groundwater impacts were found under the main plant on the north side where the former Fitness Center used to be. Roux did investigations during April, May and June of 2011. Borings and wells were installed. The data indicates that the source is the BP Service Station (formerly AMOCO; active spill #0104597) to the north at 655 Flushing Avenue. The BP investigation was limited to the shallow soil and groundwater above the silty clay (which averages 10 feet bgs). Pfizer investigated the groundwater in the deeper zone. Roux states in the report that their evidence for BP being the source is the following: 1) BP is 70 feet away from the main building (site

ACUMEN PARTNERS LLC (Continued) **U003074670**

E) and has a long history of impacts to the the soil and the groundwater 2) petroleum contamination was found beneath the Pfizer main plant as part of utility work which took place by the utility company (they don't state who this is, but it was probably Con Ed) - the utility company filed reports regarding the contamination 3) the deeper groundwater zone is hydraulically downgradient from BP 4) almost 3 feet of NAPL was found on the south side of Flushing Avenue and the fingerprint of the oil indicated that it was leaded gasoline 5) Roux identified extremely elevated VOC concentrations in the deeper groundwater zone - there were 38,700 ppb of total BTEX in the groundwater 8 feet south of BP in the deeper zone 6) Pfizer had 2 small USTs under the north part of the main buildng (former Fitness Center) - the soil results did not indicate any impacts from the USTs - the USTs were in 12 inches of concrete in an intact vault and were decommissioned in 1988 7) information from Pfizer and BP for routine groundwater sampling provides data from the south side of Flushing Avenue supporting that the Pfizr USTs did not leak 8) MTBE is present in the deeper groundwater samples from the Pfizer site, but the timing does not support that the impacts are related to the Pfizer operations - Pfizer decommissioned the USTs in 1988 before the widespread use of MTBE in 1992 - MTBE bearing gasoline was stored at BP for years and BP had many releases of gas - in 2001 there was a gasoline release with MTBE where the MTBE concentrations were up to 385,000 ppb in the groundwater The main plant consists of buildings 55, 16, 16A, warehouse A and warehouse AA. The majority of the main plant (site E) is buildings 16 and 16A - 8 story buildings.
Operations at the plant ceased during November 2008. On 2/11/11, the ownership changed to Acumen Capital Partners (ACP) BK I LLC. Site F is the parking lot to the south. Property Solutions performed the Phase II during October 2010 and January 2011 for sites E and F. They did 24 borings. Seven (7) gorundwater samples were taken from temporary wells. Twelve (12) borings were performed at site E and 12 borings were performed at site F. Four (4) groundwater samples were taken at site E and 3 groundwater samples were taken at site F. A small portion of the sampling was done near the former Fitness Center in warehouse A and pertains to this investigation. The borings and wells were SB-19, SB-20/GW20, SB-21, SB-22/GW-22, SB-23 to SB-25. Groundwater from G-22 was taken on 1/6/11 and had elevated VOCs of gasoline. The sample was collected at 16.5 to 20 feet bgs, below the perched water table at 10 feet bgs. Anthropogenic fill is present from 5 to 12 feet bgs. Silty clay is present throughout the area and is 15 feet thick. The Upper Glacial Aquifer underlies the silty clay at 20 to 30 feet bgs. Thin perched lenses of groundwater are present throughout the area. A perched water table is present at 5 to 8 feet below the site. The perched water table follows the surficial topography of the clay. The clay is 6 feet below the southwest part of the BP site and 11 feet below the northeast part of the site. The BP wells are in the perched horizon. BP reported that the groundwater flowed to the northeast. Permanent wells BMW-10 to BMW-13 indicate that the deeper groundwater flows to the southwest. The deeper groundwater is likely affected by pumping by NYCT for its subway tunnels. Their pumping wells are to the west of the main building. The pumping also likely affects the vertical gradient. Gauging took place at BMW-10 to BMW-13 on May 3 to June 8 during 2011. LNAPL was found to be 2.76 feet thick at BMW-11 on 6/8/11. Property Solutions did borings SB-19 to SB-25 near the Fitness Center. Only SB-22 at 7.5 to 8 feet bgs had soil VOCs that were above the unrestricted CP-51

ACUMEN PARTNERS LLC (Continued) **U003074670**

standards. There were 5 VOCs above the standards. Naphthalene at 16,000 ppb, n-butylbenzene at 14,000 ppb, n-propylbenzene at 7000 ppb, ethylbenzene at 2300 ppb. The soil samples from the rest of the borings had results that were below the unrestricted standards. On 1/26/11, Property Solutions collected groundwater samples from GW-20 and GW-22. Low levels of BTEX were detected at 15 to 16 feet bgs. The sample from GW-22 beneath the Fitness Center had many VOC hits that were above the unrestricted standards. Permanent well BMW-11 had many VOC hits that were above the unrestrictted standards. From 6/6/11 to 6/8/11, Roux took groundwater samples from 3 borings. All had samples with exceedences. Groundwater samples from boring TPNE (in the sidewalk at the south edge of the BP station) were taken at 13 to 15 feet bgs, 15 to 17 feet bgs, and at 17 to 19 feet bgs. There were many VOC exceedences amongst the samples. The highest BTEX result was from the sample from 13 to 15 feet bgs. The groundwater samples that were taken at 15 to 17 feet bgs and at 17 to 19 feet bgs from boring TPSW directly downgradient (southwest) of the station had low VOC hits. I finished my reivew of the 6/24/11 Petroleum Investigation Report. I looked at Plate 1 - Generalized Hydrogeological Cross Section - of the report. All of the wells - temporary and permanent - were partially screened at the top in the silty clay. This is not proper practice. There is no explanation in the report why this was done. Any groundwater samples that would be taken from these wells would entrain some of the clay sediment due to disturbance of the clay as a result of the collection process. So, the geochemistry of the groundwater is not representative of just the Upper Glacial Aquifer. Analytes which had adhered to the clay flakes were incoporated in each groundwater sample. Additionally, water samples which are taken from soil borings typically do not have as high concentrations of analytes as would samples from permanent wells. Also, from the boring logs in the report, it is not entirely clear that the perched aquifer and the glacial aquifer are truely separated at a distance. If the NYCT is pumping groundwater, then their actions could cause some groundwater to seep down from above. _____ Comments by Ketani: ---------- The soil results from SB-22 for the sample from 7.5 to 8 feet bgs in the former diesel and gasoline USTs area(the former Fitness Center) had naphthalene and n-butylbenzene hits above 10,000 ppb. The ethylbenzene hit was 2,300 ppb and the n-propylbenzene hit was 7,000 ppb. Though the soil results for the samples from SB-21 and SB-23 to SB-25 which surround SB-22 did not have exceedences or were non-detect. The groundwater results from temporary well GW-22 in the former diesel and gasoline USTs area had high VOC exceedences in the sample from 16.5 to 20 feet bgs. However, the groundwater results from temporary well TPSW about 65 feet to the east and permanent well BMW-10 about 35 feet to the east have a small number of very low hits and no exceedences. These soil and groundwater results suggest that one of the UST systems probably leaked. More borings and permanent wells need to be installed in this area. Additionally, the BP Service Station that is referred to in the report has an active spill number, #0104597. According to a report in the e-docs, groundwater flow in the perched water table is due northeast, away from the Pfizer site. Also, MTBE was introduced to gasoline nationally during 1979. So, it is not impossible that there used to be MTBE bearing gasoline in the gas UST below the former fitness center location before the tank was removed during 1988. 3/29/13 - Raphael Ketani. Next, I reviewed the Roux Supplement to Petroleum Investigation Report dated 7/22/11. Of

ACUMEN PARTNERS LLC (Continued) **U003074670**

significance was that staff from Roux stated in this Supplement report that the former DEC case manager should obtain all of the UST and piping information for the BP Service Station from the respective DEC file. They also stated that the Phase I and the Phase II were not done for Pfizer. So, Pfizer can't vouch for the reliability of the reports. Also, they stated, Acumen Captial Partners may consider the reports to be confidential and may not feel comfortable releasing them to the DEC. However, Roux did provide some information regarding the USTs under the Pfizer site and neighboring facilities in this Supplement report. The staff from Roux stated that tank closure reports weren't required to be submitted when the tanks were decommissioned during 1988. They state that soil samples were collected from TPNE, TPSW, TPSE, BMW-10 to BMW-13, but the samples were not submitted to the laboratory for analysis. The information contained in the report consisted of documents related to the UST decommissioning which took place throughout the site and Sanborn maps. The 550 gal. diesel UST (#211) and the 550 gal. gasoline UST (#212) under the Fitness Center were pressure tested during 1984 and held the pressure (9/27/84 and 10/24/84 Tone Gasoline Tank and Pump Inc. letters). In a 12/28/88 tank decommissioning letter, it is stated that tanks #211 and #212 in the former Wha garage were cut up from 12/13/88 to 12/16/88. In the process of cutting them up, it was noticed that the gasoline UST had leaked into the vault. The gasoline was collected and the vault was ventilated in order to remove the vapors. It was noticed that the floor of the vault was pitted due to leaked gasoline. However, it was reported in the letter that the tank removal crew did not notice signs of chipping of the floor or any loose concrete. _____ Comments by Ketani: ---------- From the information in the 7/22/11 report, it is apparent that there was at least a gasoline spill. How the gasoline UST could have passed its integrity test in 1984 and be found to have leaked anyway is not clear. There are no details regarding how the testing was performed. So the test may not have been valid compared to later integrity testing methods. Additionally, the pitted floor suggests that the leaking had been going on for some time. Also, there still is no information regarding the locations of the associated piping for the USTs and the locations of the pump islands. Clearly, more investigation needs to be done. A draft letter was submitted to Hassan Hussein, EE III and head of Unit C, requesting that a work plan be submitted for conducting an investigation around and under the vault, next to any remaining piping and in the vicinity of the pump islands. Soil and groundwater sampling was requested. The letter was approved by Mr. Hussein and was sent out. A due date of April 30 was set for submission of the work plan. 4/15/13 - Raphael Ketani. Mr. Kovacs (631) 232-2600 tried to call me today regarding the March 29, 2013 letter and left a voice message. I tried to contact him, but could only leave a voice message. 4/16/13 - Raphael Ketani. Mr. Kovacs and I discussed the site and the soil and groundwater results for SB-22 and GW-22, respectively. I pointed out that the soil contamination results from the surrounding borings at the same level did not have exceedences. Also, the groundwater results for GW-22 were higher than a sidegradient well that was sampled at the same depth. I added that there was a letter in the Roux 7/22/11 report which stated that a gasoline leak had been discovered. Mr. Kovacs argued that all of the contamination was from the BP site across the street. I reiterated that the soil and groundwater results and the letter suggested a local source of

ACUMEN PARTNERS LLC (Continued) **U003074670**

contamination. I asked him for soil and groundwater contamination delineation. Mr. Kovacs stated that the tank vault was in the former loading dock area, which had been filled in with 4 feet of concrete. However, they had cored thick concrete before. So they could do borings in this area. Mr. Kovacs added that Pfizer was not objecting to doing more investigative work in this area, but that they wanted to make sure everyone was on the same page and that the DEC was considering the groundwater flow from the northeast from the BP site. I repeated my previous statement that the DEC had determined that there is a local source of contamination under the former Pfizer site and that delineation is being required. Mr. Kovacs stated that he will talk to the people at Pfizer. With that, the conversation ended. 4/17/13 - Raphael Ketani. Mr. Kovacs sent me an e-mail requesting an extension of the deadline for submitting the work plan. He asked for a deadline of June 3, 2013. I granted his request. 6/4/13 - Raphael Ketani. I reviewed the Work Plan for Additional Petroleum Investigation Activities dated 5/29/13 and submitted by Roux Associates on behalf of Pfizer, Inc. The work plan contained the same information and arguments as I had read in the previous 6/24/11 Petroleum Investigation Report and the Supplement to Petroleum Investigation Report dated 7/22/11. Roux Associates added that the timing of the use of the gasoline and diesel USTs below the former fitness center and the soil data generated by Property Solutions does not support that the impacts associated with spill #1011062 are related to the Pfizer operations. Pfizer removed the USTs in 1988 before the widespread us of high concentrations of MTBE beginning in 1992. There was no MTBE in the soil samples below the Pfizer site where the USTs used to be. High concentrations of MTBE were found in the groundwater beneath the former fitness center. Property Solutions collected 7 soil samples from 5 borings in the vicinity of the USTs and found only slight soil contamination in one sample. In the work plan, Roux proposes conducting three tasks. Task 1 would be to do one round of groundwater gauging and sampling at wells BMW-10 to 13. Roux would request that the DEC gain access for them to the wells on the BP site. They will have the samples tested only via method 8260. Task 2 would involve submitting a report of their findings. Roux will make recommendations for either additional investigations, or to close the spill case, or to link the spill case to the BP site. Task 3 involved having a meeting with the DEC to discuss their findings and additional data. I drafted a response letter for the review of Mr. Hussein. In the letter, I explained that the information and statements that were in the 5/29/13 work plan were the same as were included in the 6/24/11 Petroleum Investigation Report and the Supplement to Petroleum Investigation Report dated 7/22/11. So, the Department was again requesting that a soil and groundwater investigation take place as previously requested in our 3/29/13 letter. I added that we will send a letter to Acumen requesting their cooperation for allowing the wells to be installed. However, it would be up to Pfizer to obtain permission from BP for gaining access to their wells. I set a deadline of 7/12/13 for submission of a new work plan. 6/5/13 - Raphael Ketani. Mr. Hussein approved the letter and it was sent out. 6/6/13 - Raphael Ketani. In response to the 6/5/13 letter, Matthew Basso of Pfizer called me. He tried to explain to me that Pfizer wasn't responsible for the contamination under the vault. He used the same information as had been presented in the 6/24/11 report and the 7/22/11 report. I explained to him that his discussion wasn't going to change the Department's request for a soil and

ACUMEN PARTNERS LLC (Continued) **U003074670**

groundwater investigation. I added the lower groundwater hits of the deep well to the northeast, the finding of free product in the vault, the discovery of soil contamination in the unsaturated zone below the vault and the presence of high contamination in the groundwater just under the vault. Mr. Basso explained that he had witnessed the consultants for the BP station across the street doing remedial work. He said that they were injecting treatment solutions. Mr. Basso added that the gas station has lost a lot of product and it is going under the former Pfizer site. I told Mr. Basso that the Department was aware of the problems at the BP station and that they were being addressed. I did admit to him that some of the contamination may be going under part of the former Pfizer site, but that the contamination in the former vault area was a different matter that was solely the responsibility of Pfizer. Mr. Basso stated that the groundwater was flowing from the BP site to the former Pfizer building. I told him that this was not true for the perched water table. He also stated that he didn't believe the new owners of the property, Acumen, would allow Pfizer to drill through the floor of the former fitness center. I told him that I will write a letter requesting Acumen's cooperation regarding the investigation. At the end of the conversation, Mr. Basso requested a meeting with the DEC. I told him to talk to everyone at his end and get them to agree on a date for next week. He said that he will do this. Later, Mr. Kovacs (631) 232-2600 sent me an e-mail stating that Pfizer, Acumen and Roux would be able to meet with staff from the DEC on monday, June 10th, at 2:00PM. I confirmed that this was an acceptable meeting time. A draft letter was submitted to Mr. Hussein which requested the cooperation of Acumen in allowing Roux Associates to conduct an investigation in the vicinity of the vault. Mr. Hussein approved the letter and it was sent out. 6/10/13 - Raphael Ketani. The meeting took place as scheduled. In attendance were Matthew Basso from Pfizer, Robert Kovacs and Charlie McGuckin from Roux Associates, and Hassan Hussein and myself. The former Pfizer site and the BP gas station to the north were discussed. Mr. Kovacs and Mr. McGuckin presented the same information as I had read from previous reports. They showed one new map which showed that, at one time, the Wallabout Creek had flowed near the vicinity of the former vault and in adjacent areas. So the area contained stream sediments. Mr. Kovacs and Mr. McGuckin stated that the gas contamination in the former vault area was from the BP site due to deep groundwater flow towards the southwest in the regional aquifer. They commented that the NYCT was pumping from a well to the southwest for the G train line. So, this well had moved groundwater flow to the southwest. I stated that groundwater flow was to the northeast in the perched water table and to the southwest in the regional aquifer. I stated that the gas contamination in the vicinity of the vault was from a former gas UST that had been observed to have leaked. I also stated that there was gas contamination in the shallow unsaturated soil in the vicinity of the vault. So the contamination in the immediate vicinity had come from the UST, not the BP site. They countered that the gasoline below the vault contained MTBE and this chemical was not in the Pfizer gas UST when it was removed in 1988. They also stated that the groundwater analytes had the signature of BP gas. I told the Roux consultants that the wells were never screened properly. Some were screened in the clay. So it is not clear what the true groundwater chemical makeup is. I requested a work plan for conducting 4 soil borings around the former vault location, installing a properly

ACUMEN PARTNERS LLC (Continued) **U003074670**

screened well in the shallow zone and another in the deeper regional aquifer, and to take a Shelby tube sample and do permeability testing for the confining layer between the two bodies of groundwater. Mr. McGuckin objected to the request for more investigating. He said that Pfizer had done enough to determine subsurface conditions and that there was no point in doing more work. He again stated that all of the contamination was due to the spilling at the BP station. He added that there was a well 75 feet to the east of the Pfizer vault with 3 feet of product in it. Mr. Basso stated that this gasoline could be fingerprinted to prove that it belonged to BP. I added that more soil and groundwater data must be obtained in order to determine the subsurface conditions and in order to determine where the contamination had originated from. Otherwise, BP will not accept responsibility with so little information. Mr. Basso said that he will approach his management with the DEC demand and our argument why more work needed to be done. Following this meeting, Mr. Hussein and I had a meeting with June Feng, the DEC project manager for the BP station at 655 Flushing Avenue, Brooklyn (spill case #0104597). Specifically, we asked her whether the BP investigation had done off site delineation of the spill and whether there presently were leaking USTs and product on the groundwater. Ms. Feng said that, presently, there were no leaking USTs and no product on the groundwater. She said that wells were only installed on the BP property. I told her about the 3 feet of product that had been found in the Roux Associates well BMW-11, which was about 100 feet east of the vault in question and downgradient from the BP station (as regards the deeper aquifer flow). Ms. Feng asked whether the gasoline had ever been fingerprinted. I told her No. She said that she could not understand how gasoline could make its way down from the perched water table to the regional aquifer. I told her I was not sure either how this had happened, but the Roux Associates consultants were stating that this happened. She then asked whether the gasoline could have followed a utility conduit. I told her that this was possible, but I wasn't sure it would stay in the aquifer as gasoline floats on water. Ms. Feng and I thought about how the gasoline could have ended up below a perched water table, but we did not find an answer. 6/11/13 - Raphael Ketani. Ms. Feng sent me a c-c for an e-mail she had sent to Nicholas Onufrak of BP. She warned him that Pfizer and their consultants were telling the DEC that the gasoline contamination was from the 655 Flushing Avenue site. Later, Mr. Onufrak responded back that he had received the e-mail. 6/12/13 - Raphael Ketani. Mr. Basso sent me an e-mail in which he stated that Pfizer was working on a work plan and intended to submit it by July 12, 2013. 7/22/13 - Raphael Ketani. I reviewed the 7/18/13 Workplan for Additional Focused Subsurface Investigation. The work plan was written in response to the DEC 3/29/13 letter in which additional investigative work was requested around the vault. ROUX also made the same arguments that the source of the contamination under the former Pfizer plant is from the BP service station across the street. They also recapped the results of the previous investigations from 2011. They state that NAPL was found on 6/8/11 at BMW-11 and was identified as leaded gasoline. Also, they state in the report that, given the geologic and hydrogeologic conditions in the subsurface and the presence of NAPL in the deep groundwater zone downgradient of the BP station and the presence of MTBE in the groundwater, it is strongly suggested that the impacts at SB-22/GW-22 are not the result of former Pfizer operations, but the result of the long history of

ACUMEN PARTNERS LLC (Continued) **U003074670**

releases from the BP station. ROUX will do a focused field investigation involving a Phase I and, if necessary, a Phase II. After the work is done, a summary report will be prepared and a meeting with DEC staff will be requested to discuss the results and determine what should happen next. The Phase II will be performed only if contaminated soil is found below the former UST locations. Five shallow soil borings will be performed around the vault and dispenser area to the top of the silty clay. Soil and groundwater samples will be analyzed via methods 8260 and 8270. The perched water table samples will be collected from 3 temporary wells. Only temporary wells can be installed due to the height restrictions inside of the Fitness Center (it will only accomodate small equipment). Undisturbed soil samples will be collected from the silty clay and the sandy layer below it for permeability testing. If there are no discernable soil impacts in the shallow soil, then they will bore down below the silty clay layer and sample the soil just above the deep groundwater. The existing deep wells BMW-10 to BMW-13 will be gauged and sampled. If the Phase II is necessary, then two additional wells will be installed at two more locations within the Fitness Center footprint and the groundwater will be sampled beneath the silty clay. The Phase II would also involve the collection of additional perched water samples. I looked at the proposed soil boring and well locations depicted in Figure 7 of the report. The locations seemed reasonable. I drafted a letter for the review of Mr. Hussein in which I stated that the Department had approved the 7/18/13 work plan. 7/24/13 - Raphael Ketani. Mr. Hussein approved the letter and it was sent out today. 10/15/13 - Raphael Ketani. As there has been no word regarding activity at the site, I sent an e-mail to the three individuals involved in the spill case from Pfizer and Roux (Mr. Basso at (908) 901-7096/bassom@pfizer.com; Mr. Kovacs at (631) 232-2600/rkovacs@rouxinc.com; Mr. McGuckin at (631) 232-2600/cmcguckin@rouxinc.com). The e-mail mentioned that the 7/18/13 work plan had been approved and reports were due to the Department on September 19 (phase I) and on October 8 (phase II). I requested updated information regarding the investigation around the vault. In response to my e-mail, Mr. Basso sent me the message: The Pfizer /Roux project team met today to review the Phase I /Phase II data, that includes comprehensive soil sampling data, perched groundwater zone data, deep groundwater gauge data as obtained as part of the approved Workplan. Today we also reviewed schedule, where Pfizer had earmarked a touchbase meeting for its internal team in early October, and wrap-up to document the Phase I/Phase II results and conclusions this week. My apologize for this delay, and we met today in order to prepare an update for NYSDEC on this project. Please note: we had significant technical difficulty to get the smallest made geoprobe rig into the interior study location of the Acumen Capital Partners building to successfully achieve the intrusive sampling, and needed to arrange for the right equipment, which slowed our progress. I will ask that Roux Associates follow-up on my e-mail to better communicate the schedule for submitting to DEC the WorkPlan Report. Via this email I am keeping the site owner (Acumen) informed of our progress. Best regards, Matt Basso, MS, CHMM Later, Mr. Kovacs sent me an e-mail stating that the Phase I was completed, but with great difficulty. They had to find a drilling machine that was small enough to fit into the health club and they had to hire a specialized drilling company to drill through 7 feet of concrete. However, they did the soil borings, took soil and perched

ACUMEN PARTNERS LLC (Continued) **U003074670**

groundwater samples and gauged the deep groundwater wells. They hope to get permission from BP to gauge their on site wells, also. The report will be submitted on November 15, 2013. 11/20/13 - Raphael Ketani. I reviewed the ROUX Associates Additional Focused Subsurface Investigation report dated 11/13/13. During 9/9/13 and 9/10/13, ROUX Associates drilled 5 soil borings - RSB-1 to RSB-5. RSB-1 was adjacent to the location of SB-22/GW-22 and RSB-5 was very close by. The other borings were installed radially around the former UST locations (1 550 gal. diesel UST-west and 1 550 gal. gas UST-east) and the former dispenser location. According to the report, the UST had been removed during 1988 and the vault was filled with concrete. (It should be noted that the introduction of MTBE in gasoline took place nationally in the U.S. during 1979 and was banned by New York State beginning on January 1, 2004.) Before the borings took place, the 7 feet of concrete was cored on 8/26/13 and 8/27/13. The bottom 6 inches of concrete at RSB-1 was collected for permeability testing. The soil was bored just into the confining silt and clay layer. The boring terminated at the groundwater at 16 to 19 feet below grade. The soil and groundwater samples were tested via methods 8260 and 8270. Two (2) soil cores were collected for permeability testing and grain size analysis from boring RSB-4A (1 foot from RSB-4). The collection device was pushed using the Geoprobe hammer. One sample consisted of shallow fill at 2 to 4 feet bgs and the other sample consisted of silt and clay at 8 to 10 feet bgs. The 2 to 4 foot sample from RSB-4A was 71.5% sand and 28.1% fines (due to the high sand content, the permeability test couldn't be performed). The 8 to 10 foot sample was 47.5% sand and 52.2% silt and clay. This sample tested at a permeability of 2.7 x 10-4 cm/sec. However, there were microfractures in the sample. The true permeability was estimated as probably being 10-5 cm/sec. Based on previous soil investigations at the Citric Block near the former Main Building, on the north side of Flushing Avenue, Shelby Tube samples had been collected by ROUX at 8 feet bgs during 1996. These soil samples had permeabilities of 2.87 x 10-7 to 1.8 x 10-6 cm/sec. Though, as regards the permeability of the concrete core, it had not been tested at the time of the writing of this report. This data will be submitted later. The soil sample that had been collected years ago from SB-22 at a depth of 7.5' to 8' had 5 VOC hits from 1900 ppb to 16,000 ppb, but no MTBE. RSB-1 (to the east and next to SB-22) = 7' sample 15 VOC hits from 100 ppb to 1200 ppb with 390 ppb MTBE; 11' sample almost entirely non-detect with 2300 ppb MTBE; 13' sample almost entirely non-detect with 3700 ppb MTBE RSB-2 (next to former east side of gas UST) = almost entirely non-detect RSB-3 (downgradient of the USTs) = 9' sample with 13 VOC hits from 3000 ppb to 62,000 ppb but no MTBE; 14' sample almost entirely non-detect RSB-4 (far west of SB-22) = 6.5' sample 11 VOC hits from 57 ppb to 8200 ppb but no MTBE; 8' sample 13 VOC hits from 89 ppb to 8500 ppb but no MTBE RSB-5 (very near and to the northwest of SB-22) = 7' and 9.5' samples almost entirely non-detect Except for 24,000 ppb of naphthalene in the 8.5' to 10.5' sample from RSB-3, there were no SVOC hits for any of the RSB samples. Groundwater was found at 0.5' to 2.5' below the former location of the USTs (perched groundwater) and at 10' to 13.5' below the former USTs location (deep groundwater). Deep wells BMW-10 to BMW-13 were gauged on 9/10/13. However, BP would not let ROUX have access to their wells on the gas station property. Attempts were made to collect groundwater from the perched water table at RSB-1, RSB-2 and RSB-4. ROUX was successful in collecting perched groundwater only from RSB-2. GW-22 (screened deep

ACUMEN PARTNERS LLC (Continued) **U003074670**

16'-22') = 13 VOCs from 5.9 ppb to 3900 ppb, 10 VOCs 100 ppb or above, 3 VOCs 1000 ppb or above, 3900 ppb MTBE BMW-11 (deep water) = 6.83' product on 9/10/13, other series wells without product; 9 VOCs with 6 hits from 240 ppb to 6100 ppb, no MTBE BMW-12 and BMW-13 almost entirely non-detect (deep) TPNE highest VOC concentrations in this series in 2011 with 7 VOC hits to 17,600 ppb and MTBE 200 ppb TPSE at all levels (13'-15', 15'-17', 17'-19') had the same VOC hits at about the same concentrations, except the sample from the 13'-15' interval had generally slightly higher concentrations TPSW was almost entirely non-detect RSB-2 (perched at 7'-9') had 6 VOC hits from 16 ppb to 120 ppb, but no MTBE SVOCs were almost entirely non-detect for RSB-2, except for 54 ppb of naphthalene As part of my review, I reviewed reports for the BP site (spill #0104597). I looked at the groundwater flow maps and analytical results in the 3rd Quarter 2004 Quarterly Monitoring Report dated 7/25/05 and the groundwater flow map in the 2nd Quarter 2013 Quarterly Monitoring Report dated 6/28/13. I determined that groundwater flow in the perched horizon is to the northeast while groundwater flow in the regional aquifer is to the southwest. 11/25/13 - Raphael Ketani. I sent a quick e-mail to Mr. Kovacs requesting that Pfizer and ROUX immediately begin product recovery events in order to contain any plumes emanating from BMW-11. 11/26/13 - Raphael Ketani. I drafted a review letter for editing by Mr. Hussein. I stated in the letter that the Department had approved the report. However, the data in the report and the case file indicated that additional work needed to take place. I determined that groundwater was flowing from upgradient to under the former Pfizer site through the deep groundwater horizon. However, there was evidence of contamination from onsite, also. The Department was requiring delineation of the soil contamination downgradient from the former vault and downgradient from BMW-11. Pfizer was also asked to immediately begin product collection at BMW-11 and to submit monthly gauging and product collection reports. A deadline of January 10, 2013 was set for the submission of a delineation work plan. Mr. Hussein approved the letter. 11/27/13 - Raphael Ketani. The AFSI report review letter was sent to Mr. Basso at (908) 901-7096/bassom@pfizer.com, Mr. Kovacs at (631) 232-2600/rkovacs@rouxinc.com and Mr. Rosenblum. After having sent the letter, I met with June Feng, the case manager of the BP Station site to the north. I explained that the data indicated that the source of the product at BMW-11 was the BP site. I showed her some pages from various reports describing the subsurface conditions below the Pfizer site and ROUX Associates' findings. I asked her to contact Nicholas Onufrak, the BP representative, regarding this matter and to try and have BP take over the product collection at BMW-11. 12/2/13 - Raphael Ketani. I met with Jeff Vought, Ms. Feng's supervisor, regarding the former Pfizer site and the BP site. I explained the data and showed him the Additional Focused Subsurface Investigation report (AFSI). I also explained that the perched groundwater was flowing northeast, away from the former Pfizer site, while the deeper groundwater was flowing toward the site. He noted what I had told him, but wasn't convinced that the source of the contamination under the Pfizer site was from the BP station. At the end of the day, Mr. Kovacs sent a response e-mail regarding the DEC 11/27/13 AFSI review and response letter. In short, Mr. Kovacs wrote that the responsibility for the contamination lied with the BP station and that Pfizer was not going to do further delineation nor collect the 7 feet of product from BMW-11 which was next to the school. He wrote that I should contact

ACUMEN PARTNERS LLC (Continued) **U003074670**

BP and have them do the VEFRing. 12/3/13 - Raphael Ketani. In response to Mr. Kovacs 12/2/13 e-mail, I sent him a response e-mail (with C-Cs to Mr. Basso, Mr. Rosenblum and Mr. Hussein) stating that Pfizer and ROUX had to evacuate BMW-11 immediately as this well had 7 feet of gasoline and it was right next to the school indicated in Figure 2 of the AFSI. ROUX's claim that the gasoline had originated from the BP station hadn't been proven and the product was under the former Pfizer site. So it was Pfizer's responsibility. I added that if Pfizer and ROUX fail to send me an e-mail by December 6 (friday) stating that VEFRing is taking place, then the DEC will open up a PIN case, have its contractor do the work and continue to VEFR the well as required by DEC. I also wrote that our contractor will do the delineation work, bill the DEC, and the DEC will pass the costs along to the Attorney General who will sue Pfizer. A series of response e-mails followed from Mr. Basso. In summation, he said that Pfizer staff were in consultation regarding the presence of gasoline in BMW-11. It was also explained that the building next to BMW-11 was not a school. I asked Mr. Basso to get someone into the building to do indoor air surveying for vapors with a PID meter. Later, I sent Mr. Basso an e-mail stating that I wanted to make a site visit tomorrow to see for myself what the conditions are who is using the former Pfizer building. Mr. Basso agreed to the site visit. 12/4/13 - Raphael Ketani. A site meeting and inspection took place at 2:00PM as planned. In attendance were Mr. Kovacs (631) 232-2600, Mr. Basso (908) 901-7096, Mr. Rosenblum, Mr. Hussein and myself. At the beginning of the lobby entrance, I saw a wall on the left side with many placards indicating the various businesses that were using the former Pfizer main building. Most of the business appeared to be food processing and management companies (i.e. ice cream manufacturing, manufacturing of meals for homebound people, etc.). However, Mr. Rosenblum pointed out that there were some high tech business and his office. He also stated that the businesses were on the upper floors and that the first floor, where we were, was vacant. Next, we went to the former fitness center. Throughout the first floor, I sensed various odors, but all were light and none were noxious. There was one odor from food cooking. The PID meter did not detect any vapors anywhere at the first floor. Mr. Kovacs had the same brand and model of PID meter and his didn't detect any vapors, either. We went to the former fitness center. I continued to take pictures. There were no PID detections. Mr. Kovacs and Mr. Basso explained to everyone that the vault was below the floor and how the soil boring operation went. We saw many places where a piece of floor tile had been removed in order to do a boring and we saw the filled boring holes. Mr. Kovacs showed me where SB-22 had been and where RSB-3 was. He explained that the floor was only 1 or 2 feet thick at the location of RSB-3. Whereas, they had to go through 7 feet of concrete at the location of SB-22. Next, we walked to the first floor level of warehouse A (the eastern part of the main building). Mr. Basso showed us where BMW-11 was. We could also see the BP station across the street. Mr. Hussein, Mr. Basso, Mr. Kovacs and myself discussed the product in BMW-11 and that the data in the ROUX reports showed deep groundwater flow from the BP station and to the Pfizer site. Mr. Basso and Mr. Kovacs stated that there had been many spills at the BP station over the course of many decades. The problem of how the gasoline could get from the perched aquifer to the deeper aquifer was discussed. Mr. Hussein mentioned that there were only wells in the perched horizon at BP. Mr. Kovacs mentioned that BP had installed a lot of tanks and

ACUMEN PARTNERS LLC (Continued) **U003074670**

that they had stacked the tanks on top of each other. He stated that he thought BP had stacked the tanks so deep that they penetrated through the confining silty clay layer. Mr. Hussein agreed that the data seemed to suggest the contamination was from the BP station. He stated that delineating the contamination could be done in two ways. First, BP could be asked to do the work. If they were to refuse, then the State would have its own contractor do the work and install deep wells at the BP station in order to determine the deep groundwater flow direction. Mr. Basso stated Pfizer was deferring to BP to do the delneation work. He added that if BP were to do the delineation and groundwater monitoring, then he would gladly give them access to the Pfizer wells. Mr. Hussein asked Mr. Basso for an Executive Summary describing the current environmental conditions and the information that Pfizer and ROUX have found so far. We left this part of the building and entered the middle (building 16) warehouse area. Again, no vapors were detected. There was nothing much to see here. So, we went down to the partial basement. Once inside the partial basement, there was a moderate odor of #2 oil. My meter registered about 1.7 ppm of total VOC vapors. Mr. Kovacs' meter detected the same concentration of vapors. A man was in the basement and he told us that he had just finished cleaning a machine (he didn't say what type of machine it was). I asked him whether any oil had been spilled. He said very little oil had been released. However, he mentioned that he had used a spray cleaner to remove the oil from the surfaces of the machine. We went further into the basement. It was well lit, 78 degrees Fahrenheit and the floor was clean. There was no active ventilation taking place, even though there was a means for the indoor air to be circulated and removed. So the oil vapors were everywhere. Mr. Kovacs stated that we were standing 10 feet below grade. So, we were below the water table, but the walls were dry. Mr. Kovacs pointed out the sump and the sump pumps. The pumps weren't running. I put the nose of the PID meter into a hole through the steel plate covering the sump, but the vapors that were being detected seemed to remain the same. The vapors were actually higher about a few feet above the steel plate. There was nothing else to see. So we left the basesment and exited onto Flushing Avenue. I took some pictures outside and the meeting ended. 12/5/13 - Raphael Ketani. Jeff Vought, a supervisor in the Spills Unit, was told about the Pfizer site visit and my findings. I had previously talked to him about the data for this site. He contacted Randall Austin, the Regional Spills Engineer, and they contacted Nicholas Onufrak, Project Manager, at the Atlantic Richfield Company (the owners of the BP station). Mr. Onufrak agreed to send a vacuum truck over to suck out the well during the morning of 12/6/13. He also agreed to do at least one more vacuum event. Mr. Onufrak will look at the data for the Pfizer site and decide whether BP is responsible for the gasoline. Mr. Onufrak's contact information is: Atlantic Richfield Company, 1 West Pennsylvania Avenue, Ste. 440, Towson, MD, 21204. Later, Mr. Basso sent me the Executive Summary. I reviewed the document. The majority of the content consisted of Mr. Basso writing that BP was the source of the contamination below the former Pfizer site. He did state that there were soil impacts below the former fitness center. However, he claimed that they were minor and that the results should be compared to the Commercial Soil Standards. At the end of the document, Mr. Basso requested closure of the spill case. 12/6/13 - Raphael Ketani. Mr. Onufrak sent staff at the DEC Spills Unit and myself an e-mail today. He wrote that the evacuation of the

ACUMEN PARTNERS LLC (Continued) **U003074670**

well took place. One gallon of NAPL was recovered. A sample was collected for forensic analysis. The vac truck operator collected 637 gals. of total liquids. There was no measureable NAPL in the truck. June Feng, the project manager for the BP spill case, will be contacted by BP. 12/18/13 - Raphael Ketani. I e-mailed Mr. Kovacs regarding BMW-11. I stated that BP had evacuated only 1 gallon of product, but ROUX had measured 7 feet of product in the well several months ago. Mr. Kovacs responded that the well is two inches in diameter and that Antea Group, BP's consultant, had also measured 7 feet of product when they gauged the well before evacuating it on December 6, 2013. 1/14/14 - Raphael Ketani. A planned followup site visit took place in the partial basement of the main former Pfizer building. In attendance were Mr. Rosenbloom and Gavin Cato of ROUX. I walked around the basement with my PID meter. The basement air was at 76 degrees Fahrenheit. There were no oil odors. I put the nose of the meter above my head, at the sump and at the opening to several floor drains. The PID meter didn't detect any volatile chemicals. After this, I left the site. Later, I met with Mr. Hussein to discuss my site visit, the soil and groundwater analytical results and the other data regarding the site. Based upon our discussion and the information regarding the case, Mr. Hussein approved the closure of the spill case. Based upon the information in the spill case, I have determined that there is no threat to the public or the environment from the residual contamination below the site. Therefore, I am closing the spill case effective 1/14/14. As the building is currently being used for commercial purposes and will be used in this fashion for the foreseeable future, I am making this closure in consideration of a comparison of the soil data to the New York State commercial standards. 1/16/14 - Raphael Ketani. A spill closure letter was sent to Mr. Basso. In the letter, I wrote that the Department was requesting that Pfizer leave their wells open so that British Petroleum can use them for groundwater gauging, sampling and product recovery as part of their investigation and remedial efforts."
Not reported

Remarks: "SOIL SAMPLES POSITIVE FOR PETRO. CONTAMINATION, CLEANUP PENDING."

All Materials:

Site ID:	444686
Operable Unit ID:	1195130
Operable Unit:	01
Material ID:	2191146
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	PFIZER, INC.
Address:	630 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0203912 / 2003-09-17
Facility ID:	0203912
Facility Type:	ER
DER Facility ID:	244426

ACUMEN PARTNERS LLC (Continued) **U003074670**

Site ID:	302547
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2002-07-14
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	2002-07-14
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-14
Spill Record Last Update:	2013-12-26
Spiller Name:	NATHAN EDESON
Spiller Company:	PFIZER, INC.
Spiller Address:	630 FLUSHING AVENUE
Spiller Company:	001
Contact Name:	NATHAN EDESON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHAO/DEMEO 7/14/2002 - 21:05pm: Ms Zhao spoke with Nathan Edeson. Spill has been contained. There is no drains or valves involved. Clean up was in progress by contractor Tradewind by the time of contact. Zhao has requested clean up statement from Tradewind and will follow-up on it. 7/16/2002 - A follow up call Zhao made to Mr Edeson. Spill cause was found due to the gauge system, not the pump. Tradewind went back yesterday and have got clean up completed. Clean up statement will be furnished within two days by Tradewind. Mr Edeson will then forward it to DEC with some requested clean up pictures. 9/17/2003 - Spill closed upon a site visit on 9/15/2003 and final clean up statement received on 9/16/2003."
Remarks:	"BUILDING 16 (MAIN BUILDING), FIRST FLOOR. LEAK FROM A PUMP ON THEIR HEATING SYSTEM. MOST WAS CONFINED WITHIN THE BUILDING. ABOUT 5 GALLONS SPILLED ONTO THE SIDEWALK. SPEEDY DRI APPLIED BY PLANT EMPLOYEES. TRADEWIND ENVIRONMENTAL WAS CONTACTED FOR CLEAN UP. SIDEWALK HAS BEEN CLEANED UP. THEY'RE NOW WORKING INSIDE. PUMP TAKEN OUT OF SERVICE FOR REPAIRS."

All Materials:

Site ID:	302547
Operable Unit ID:	855198
Operable Unit:	01
Material ID:	552611
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	30.00
Oxygenate:	Not reported

ACUMEN PARTNERS LLC (Continued) **U003074670**

Name:	630 FLUSHING AVENUE
Address:	630 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9505769 / 1995-08-10
Facility ID:	9505769
Facility Type:	ER
DER Facility ID:	244426
Site ID:	302548
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	1995-08-09
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1995-08-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	1995-08-10
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-09-13
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 10/10/95: This is additional information about material spilled from the translation of the old spill file: MERCURY & LEAD."
Remarks:	"BLDG WAS OLD PHARACUTACAL BLDG - SOIL SAMPLES CAME BACK POSITIVE -BLDG HAS BEEN DEMOLISHED - REQ DEC CALL TO TOM SHEE (718) 780-8686"

All Materials:

Site ID:	302548
Operable Unit ID:	1016666
Operable Unit:	01
Material ID:	363761
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	PFIZER
Address:	630 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0013515 / 2003-06-16

ACUMEN PARTNERS LLC (Continued) **U003074670**

Facility ID:	0013515
Facility Type:	ER
DER Facility ID:	244426
Site ID:	201032
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-03-27
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-03-27
CID:	397
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-27
Spill Record Last Update:	2013-12-26
Spiller Name:	MIKE TROCHIO
Spiller Company:	PHIZER
Spiller Address:	630 FLUSHING AVE
Spiller Company:	001
Contact Name:	MIKE TROCHIO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 4/2/2001 Sangesland and NYCDEP Wai Man Wan made a site visit to the Pfizer facility to look for a reported Acetone leak. After initial inspection, DEC - ECO Shawn Dussault arrived to make a similar inspection of the roof top equipment. According to Pfizer Engineer Mr. Daniel Shiel the following is a description of the process and then the system problem: Process: Acetone is used in the process of coating pills. After the material leaves the pills bath area, the vapor acetone is collected and piped to a chiller/condensor on the plant roof. This Edwards Unit chiller/condensor has 3 stages which drops the vapor temperature in 3 steps to 85'F below zero. At that point the acetone is in liquid form and is recovered via pipe and collected. This material is then tanked and removed from the site. (Pfizer states that a company purchases this recondensed acetone from them). Problem: Somewhere in the second stage of this unit is a leak. The Pfizer representitive stated that there is probably a crack in the line someplace, but the exact location has not been found. Pfizer states that they first became aware of the problem in early March 2001 and took the system out of service for approx. 10 days to perform routine maintenance to the unit and to try to find the problem. The specific problem was not found and not fixed. The equipment was put back into operation. At the site visit, it was clear that acetone was leaking to the atmosphere. Pfizer says that they have done a mass balance which shows that they are still retreaving approx. 91% of the total process acetone, above their legal limit (limit is someplace in the low 80's %). Pfizer also had LEL meters on the equipment to show that they have remained below approx 50% of the LEL explosive limits. However, there is no alarm on

ACUMEN PARTNERS LLC (Continued) **U003074670**

this meter. The meter is read several times per day by plant personnel. Pfizer rep also said the units are actually 2 separate parallel process lines running at the same time. He believes that the leak is only in one side of the system. The system can operate with only one side of the process system in operation, only at a lower volume and therefore a lower pill production rate. In order to repair the system, the unit would need to be lifted off the roof of the building, lowered to the street level, opened and re-welded. Pfizer said they had an equipment rep on site later today to quote them on the cost and time needed to build a replacement unit. ECO Dussault issued 2 tickets. 6NYCRR Part 595.3.a.2.ii and .iii with a May 17, 2001 court appearance date. Since this is a release to the atmosphere it may include the NYSDEC Air Unit. Since it is a material AFTER production (of the pills) it may be considered by NYSDEC RCRA Dept. 4/3/2001 Officer Dussault spoke with Dan Shiel (Pfizer) later on the afternoon of 4/2. Mr. Shiel said that Pfizer met with the manufacturer of the Edwards unit and he said it would take about 6 to 8 weeks to build and install a new unit. Until that time, Mr. Shiel said they may try to find a way to run just the first and third stage of the system and bypass the second unit. This will still allow some condensation of the process acetone and may allow the production line to operate (perhaps at a reduced rate) "

Remarks: "caller states that the compnay has had a leak since june on the roof of the building from the edwards unit. the do not want to fix this due to the down time and the cost. dennis pappas engineer of charge"

All Materials:

Site ID:	201032
Operable Unit ID:	834992
Operable Unit:	01
Material ID:	540227
Material Code:	0024B
Material Name:	2-propanone
Case No.:	00067641
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	PFIZER INC - MISC
Address:	630 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9303325 / 2006-04-05
Facility ID:	9303325
Facility Type:	ER
DER Facility ID:	244426
Site ID:	201033
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	2401
Spill Date:	1993-06-14
Investigator:	SWKRASZE
Referred To:	REFER TO VCP #V00124
Reported to Dept:	1993-06-14
CID:	Not reported

ACUMEN PARTNERS LLC (Continued) **U003074670**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-06-18
Spill Record Last Update:	2013-12-24
Spiller Name:	Not reported
Spiller Company:	PFIZER
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 7/6/04 - AUSTIN - TRANSFERRED FROM GARDINEER TO SUN - RELATED TO SPILL #990181 - END 07/08/04-Sun- Also refer to Spill # 99-01811 for the same site. 02/09/06: This spill transferred from R.Feng to S.Kraszewski. 03/06/06: Recieved letter from Pfizer, dated March 2, 2006. The letter states that the Department's verbal request for documentation of UST closure from 1993 is unnecessary since significant remedial work has taken place to address this spill since 1993 and also an NFA letter has been issued. The NFA supposedly declares that the VCA (Voluntary Cleanup Agreement) performed by Pfizer has been completed. SK spoke with Manuel Lopez, Director of Environmental Health and Safety for Pfizer. I requested a copy of the NFA letter be faxed for confirmation. - SK 03/07/06: Reviewed NFA letter faxed by Pfizer. Will discuss with J.Kolleeny and K.Tang. - SK 04/05/06: Apparently, when this site became involved with the Voluntary Clean-Up Agreement (VCP) the spill number should have been closed. This spill closed out. - SK "
Remarks:	"ENZEP DIVISOR OF ENSI TO DO WORK 6 BOROUGHS TAKEN EACH BORINGS SHOW CONTAMINATION ON SOIL AND GROUND WATER. WILL REMOVE TANKS 6/21/ WOULD LIKE DEC TO VISIT SITE. 2 TANKS 3000-10000 ONE OTHER FILLED. CASE FILE BEING HANDLED BY HAZ. WASTE SECTION."

All Materials:

Site ID:	201033
Operable Unit ID:	985217
Operable Unit:	01
Material ID:	396903
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	ACUMEN PARTNERS LLC
Address:	630 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206-5026

ACUMEN PARTNERS LLC (Continued) **U003074670**

Country:	USA
EPA ID:	NYD986936904
Facility Status:	Not reported
Location Address 1:	630 FLUSHING AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986936904
Mailing Name:	ACUMEN PARTNERS LLC
Mailing Contact:	CRAIG COMNIE
Mailing Address 1:	630 FLUSHING AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9176232210

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2016
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	11/02/2016
Trans1 Recv Date:	11/02/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/09/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986936904
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	009795905FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported

ACUMEN PARTNERS LLC (Continued) **U003074670**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	39620
Units:	P - Pounds
Number of Containers:	1
Container Type:	CM - Metal boxes, cases, roll-offs
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

L270 **ACP BK I LLC - 630 FLUSHING AVE** **RCRA-LQG** **1000458301**
SSW **630 FLUSHING AVE** **ICIS** **NYD986936904**
< 1/8 **BROOKLYN, NY 11206** **US AIRS**
0.119 mi. **NJ MANIFEST**
629 ft. **Site 30 of 32 in cluster L**

Relative: **Lower**

Actual: **13 ft.**

RCRA-LQG:

Date form received by agency:	03/02/2012
Facility name:	FORMER PFIZER MAIN PLANT
Facility address:	630 FLUSHING AVENUE BROOKLYN, NY 11206
EPA ID:	NYD986936904
Mailing address:	ROUTE 206 NORTH M/S 613 PEAPACK, NJ 07977
Contact:	MATTHEW R BASSO
Contact address:	ROUTE 206 NORTH M/S 613 PEAPACK, NJ 07977
Contact country:	US
Contact telephone:	908-901-7096
Contact email:	MATT.BASSO@PFIZER.COM
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Owner/Operator Summary:

Owner/operator name:	ACP BK I LLC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/11/2011
Owner/Op end date:	Not reported

Owner/operator name:	ACP BK I LLC
Owner/operator address:	NORTHERN BOULEVARD
	LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	718-360-9503
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/11/2011
Owner/Op end date:	Not reported

Owner/operator name:	PFIZER INC
Owner/operator address:	235 EAST 42ND STREET
	NEW YORK, NY 10017
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1849
Owner/Op end date:	Not reported

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1849
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 03/08/2010
Site name: PFIZER INC. BROOKLYN PLANT
Classification: Large Quantity Generator

Date form received by agency: 03/03/2008
Site name: PFIZER INC. - BROOKLYN PLANT
Classification: Large Quantity Generator

Date form received by agency: 01/01/2007
Site name: PFIZER INC.
Classification: Large Quantity Generator

Date form received by agency: 02/10/2006
Site name: PFIZER INC.
Classification: Large Quantity Generator

Date form received by agency: 02/09/2006
Site name: PFIZER INC.
Classification: Large Quantity Generator

Date form received by agency: 02/26/2004
Site name: PFIZER INC.
Classification: Large Quantity Generator

Date form received by agency: 02/25/2002
Site name: PFIZER INC.
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 03/04/1998
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 03/26/1996
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 03/28/1994
Site name: PFIZER INC

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Classification: Large Quantity Generator

Date form received by agency: 02/28/1992
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 01/22/1991
Site name: PFIZER INC BROOKLYN PLT
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: B001
. Waste name: PCB oil (concentrated) from transformers, capacitors, etc.

. Waste code: B007
. Waste name: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P022
. Waste name: CARBON DISULFIDE

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: U001
. Waste name: ACETALDEHYDE (I) (OR) ETHANAL (I)

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U043
. Waste name: ETHENE, CHLORO- (OR) VINYL CHLORIDE

. Waste code: U069
. Waste name: 1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE

. Waste code: U077
. Waste name: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U122
. Waste name: FORMALDEHYDE

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

. Waste code: U123
. Waste name: FORMIC ACID (C,T)

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U169
. Waste name: BENZENE, NITRO- (OR) NITROBENZENE (I,T)

. Waste code: U188
. Waste name: PHENOL

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

. Waste code: X001
. Waste name: WASTE OILS

Facility Has Received Notices of Violations:
Regulation violated: SR - 6nycrr372.2(a)(8)(i)(a)(2)
Area of violation: Generators - General
Date violation determined: 04/06/1998
Date achieved compliance: 05/07/1998
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/20/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 09/02/1994
Date achieved compliance: 09/27/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/02/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/14/1992
Date achieved compliance: 03/24/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/14/1992

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 02/26/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 12/05/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/10/1998
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/07/1998
Evaluation lead agency: EPA

Evaluation date: 06/29/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/27/1994
Evaluation lead agency: State

Evaluation date: 03/31/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/13/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/24/1992
Evaluation lead agency: State

ICIS:
Enforcement Action ID: NY000A0000261040020700311
FRS ID: 110000323294
Action Name: ACP BK I LLC - 630 FLUSHING AVE 360470000800311
Facility Name: ACP BK I LLC - 630 FLUSHING AVE
Facility Address: 630 FLUSHING AVE
BROOKLYN, NY 11206
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 2834

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.700102
Longitude in Decimal Degrees:	73.9465248
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400207
Facility NAICS Code:	325412
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261040020700310
FRS ID:	110000323294
Action Name:	ACP BK I LLC - 630 FLUSHING AVE 360470000800310
Facility Name:	ACP BK I LLC - 630 FLUSHING AVE
Facility Address:	630 FLUSHING AVE BROOKLYN, NY 11206
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	2834
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.700102
Longitude in Decimal Degrees:	73.9465248
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400207
Facility NAICS Code:	325412
Tribal Land Code:	Not reported

US AIRS (AFS):

Envid:	1000458301
Region Code:	02
County Code:	NY047
Programmatic ID:	AIR NY0000002610400207
Facility Registry ID:	110000323294
D and B Number:	Not reported
Facility Site Name:	ACP BK I LLC - 630 FLUSHING AVE
Primary SIC Code:	2834
NAICS Code:	325412
Default Air Classification Code:	SMI
Facility Type of Ownership Code:	Not reported
Air CMS Category Code:	SMI
HPV Status:	Not reported

US AIRS (AFS):

Region Code:	02
Programmatic ID:	AIR NY0000002610400207
Facility Registry ID:	110000323294
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date:	2003-03-14 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2003-03-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2003-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2005-08-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2006-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2008-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2008-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2008-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2009-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Date: 2011-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2013-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2013-09-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2013-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 1997-10-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 1999-02-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2003-03-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2003-03-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2003-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2005-08-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2006-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2008-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2008-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2008-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2008-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2009-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2011-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2013-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Date: 2013-09-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: New Source Performance Standards
Activity Date: 2013-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1978-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-11-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-06-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-08-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-03-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-02-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Region Code:	02
Programmatic ID:	AIR NY0000002610400207
Facility Registry ID:	110000323294
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1990-07-19 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610400207
Facility Registry ID:	110000323294
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1990-08-09 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610400207
Facility Registry ID:	110000323294
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2001-08-22 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610400207
Facility Registry ID:	110000323294
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2003-03-14 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610400207
Facility Registry ID:	110000323294
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2003-03-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-08-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Date: 2008-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-09-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-07-27 00:00:00
Activity Status Date: 2005-07-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-03-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-03-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-08-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2009-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Date: 2011-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-09-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2003-03-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2003-03-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2003-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2005-08-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2006-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2008-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2008-08-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2008-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2009-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2011-01-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2013-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2013-09-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400207
Facility Registry ID: 110000323294
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: Title V Permits
Activity Date: 2013-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NJ MANIFEST:
EPA Id: NYD986936904
Mail Address: 630 FLUSHING AVE.
Mail City/State/Zip: BROOKLYN 11206
Facility Phone: 7187808447
Emergency Phone: 7187808447
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: 000000

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Manifest:

Manifest Number:	000181191VES
EPA ID:	NYD986936904
Date Shipped:	01/15/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/15/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/16/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	10 P
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	30 P
Manifest Year:	Not reported
Waste Code:	U002
Hand Code:	H141
Quantity:	140 P

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	1 P
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	10 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	1 P
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	55 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	90 P
Manifest Number:	NJA5032699
EPA ID:	NYD986936904
Date Shipped:	01/21/2005
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/21/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/21/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	02070521
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5261578
EPA ID:	NYD986936904
Date Shipped:	12/12/2005
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/12/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/12/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	02210621
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5102734
EPA ID:	NYD986936904
Date Shipped:	08/24/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/24/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/24/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09200421
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5107388
EPA ID:	NYD986936904
Date Shipped:	10/05/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/05/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	11030425
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5319271
EPA ID:	NYD986936904
Date Shipped:	04/24/2006
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/24/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/24/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06150622

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	000019346VES
EPA ID:	NYD986936904
Date Shipped:	03/22/2007
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/22/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/22/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H14
Quantity:	552 P

Manifest Number:	NJA5031016
EPA ID:	NYD986936904
Date Shipped:	07/20/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/20/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/20/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08090425
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5034471
EPA ID:	NYD986936904
Date Shipped:	04/30/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/30/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/30/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05140421
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	000182485VES
EPA ID:	NYD986936904
Date Shipped:	11/10/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/10/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/10/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11206

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Reason Load Was Rejected: Not reported

Waste:

Manifest Year: Not reported
Waste Code: U123
Hand Code: H141
Quantity: 2 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 20 P

Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 20 P

Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 400 P

Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 5 P

Manifest Year: Not reported
Waste Code: U165
Hand Code: H141
Quantity: 30 P

Manifest Year: Not reported
Waste Code: U134
Hand Code: H141
Quantity: 10 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 10 P

Manifest Year: Not reported
Waste Code: F002
Hand Code: H141
Quantity: 200 P

Manifest Year: Not reported
Waste Code: D022
Hand Code: H141
Quantity: 40 P

Manifest Year: Not reported
Waste Code: D002
Hand Code: H141
Quantity: 80 P

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	10 P

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	40 P

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	40 P

Manifest Number:	000884206JJK
EPA ID:	NYD986936904
Date Shipped:	03/21/2008
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/21/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/21/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	150 G

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H061
Quantity:	150 G

Manifest Number:	NJA5108024
EPA ID:	NYD986936904
Date Shipped:	04/19/2005
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/19/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/19/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05270521
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5024147
EPA ID:	NYD986936904
Date Shipped:	09/30/2005
TSDF EPA ID:	NJD980536593

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/30/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/30/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	11150525
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5264924
EPA ID:	NYD986936904
Date Shipped:	10/27/2005
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/27/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/27/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01100621
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5034411
EPA ID:	NYD986936904
Date Shipped:	04/16/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/16/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/16/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Manifest Discrepancy Type:	Not reported
Data Entry Number:	05030422
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5034426
EPA ID:	NYD986936904
Date Shipped:	04/20/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/20/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/20/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05040421
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5034449
EPA ID:	NYD986936904
Date Shipped:	04/27/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/27/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/27/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05100425
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5034499
EPA ID:	NYD986936904
Date Shipped:	05/07/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/07/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/07/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05180425
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5030661
EPA ID:	NYD986936904
Date Shipped:	06/04/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD002454544
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/04/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/04/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06170425
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Manifest Number:	000019390VES
EPA ID:	NYD986936904

ACP BK I LLC - 630 FLUSHING AVE (Continued) **1000458301**

Date Shipped:	04/23/2007
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/23/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/23/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11206
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H14
Quantity:	1398 P

L271 **PFIZER INC. BROOKLYN PLANT** **NY CBS** **S100560594**
SSW **630 FLUSHING AVENUE** **NY CBS AST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.119 mi.
629 ft. **Site 31 of 32 in cluster L**

Relative: **Lower**

Actual: **13 ft.**

CBS:

Name:	PFIZER INC. BROOKLYN PLANT
Address:	630 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11206
CBS Number:	2-000082

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 588848.06590
UTMY: 4505936.29761

CBS AST:
CBS Number: 2-000082
ICS Number: 2-017329
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: D
Telephone: (718) 780-8880
Facility Town: NEW YORK CITY
Region: STATE
Expiration Date: 04/18/2002
Total Capacity of All Active Tanks(gal): 30000
Operator: PFIZER INC.
Emergency Contact: PFIZER SECURITY
Emergency Phone: (718) 780-8880
Owner Name: PFIZER INC. BROOKLYN PLANT
Owner Address: 630 FLUSHING AVENUE
Owner City,St,Zip: BROOKLYN, NY 11206
Owner Telephone: (718) 780-8880
Owner Type: Corporate/Commercial
Owner Sub Type: Not reported
Mail Name: PFIZER INC.
Mail Contact Addr: 630 FLUSHING AVENUE
Mail Contact Addr2: Not reported
Mail Contact Contact: THOMAS J. SNEE
Mail Contact City,St,Zip: BROOKLYN, NY 11206
Mail Phone: (718) 780-8880

Tank Id: BT-02
CAS Number: 67641
Federal ID: Not reported
Tank Status: In Service
Install Date: 04/00
Tank Closed: Not reported
Capacity (Gal): 10000
Chemical: 2-Propanone
Tank Location: Indoors, Aboveground
Tank Type: Stainless steel alloy
Total Tanks: 3
Tank Secret: False
Tank Secondary Containment: Prefabricated Steel Dike
Tank Error Status: No Missing Data
Date Entered: 04/17/2000
Certified Date: 11/21/2000
Substance: Single Hazardous Substance on DEC List
Internal Protection: None
External Protection: None
Pipe Location: Aboveground
Pipe Type: Wrapped Steel

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	Interstitial Monitoring
Overfill Protection:	23
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	BT-01
CAS Number:	67641
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	04/00
Tank Closed:	Not reported
Capacity (Gal):	10000
Chemical:	2-Propanone
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	Prefabricated Steel Dike
Tank Error Status:	No Missing Data
Date Entered:	04/17/2000
Certified Date:	11/21/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	Interstitial Monitoring
Overfill Protection:	23
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	BT-03
CAS Number:	67641
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	04/00
Tank Closed:	Not reported
Capacity (Gal):	10000
Chemical:	2-Propanone
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	Prefabricated Steel Dike
Tank Error Status:	No Missing Data
Date Entered:	04/17/2000
Certified Date:	11/21/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	Interstitial Monitoring
Overfill Protection:	23
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	22-S9
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/40
Tank Closed:	03/91

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Capacity (Gal):	580
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	07/05/1989
Certified Date:	11/21/2000
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	12A01
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/40
Tank Closed:	03/91
Capacity (Gal):	2640
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	07/05/1989
Certified Date:	11/21/2000
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	12A02
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/40
Tank Closed:	03/91
Capacity (Gal):	2640
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	07/05/1989
Certified Date:	11/21/2000
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	12A03
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/40
Tank Closed:	03/91
Capacity (Gal):	1300
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	07/05/1989
Certified Date:	11/21/2000
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	12B3A
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/40

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Tank Closed:	03/91
Capacity (Gal):	637
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	07/05/1989
Certified Date:	11/21/2000
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	22-KA
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/40
Tank Closed:	03/91
Capacity (Gal):	500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	07/05/1989
Certified Date:	11/21/2000
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Pipe Location:	Not reported
Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91
Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Tank Id:	18-04
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/40
Tank Closed:	03/91
Capacity (Gal):	500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	07/05/1989
Certified Date:	11/21/2000
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	08/20/91

PFIZER INC. BROOKLYN PLANT (Continued) **S100560594**

Is It There:	False
Delinquent:	False
Date Expired:	07/05/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	12/27/2001

Click this hyperlink while viewing on your computer to access
13 additional NY_AST_CBS: record(s) in the EDR Site Report.

P272 **CITGO/ 594 BROADWAY** **NY Spills** **S102672996**
NNW **594 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.120 mi.
632 ft. **Site 1 of 11 in cluster P**

Relative: **Lower**

Actual: **13 ft.**

SPILLS:

Name:	CITGO/ 594 BROADWAY
Address:	594 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9507227 / Not Reported
Facility ID:	9507227
Facility Type:	ER
DER Facility ID:	70215
Site ID:	74922
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1995-08-31
Investigator:	JAKOLLEE
Referred To:	SITE INVES.REPORT DUE 7-22-08.
Reported to Dept:	1995-09-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	4
Date Entered In Computer:	1948-12-27
Spill Record Last Update:	2011-12-14
Spiller Name:	JOSEPH MACCHIA, JR
Spiller Company:	NORTHLAND MARKETING
Spiller Address:	251 LOMBARDY ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"-Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 12/29/2003 Reassigned from Rommel to Sun. 11/03/05-File Update by Sun: A stipulation Agreement was mailed to Susion Developers LLC on 11/03/05 and required to be signed and returned by 11/25/05. (Sun) 11/18/05-File Update by Sun: Final New Order of Consent was sent to Howard D. Stave, Esq. (Attorney for Northland) on 11/15/05. (Sun)

CITGO/ 594 BROADWAY (Continued) **S102672996**

02/21/06-File Update by Sun: On 02/10/06, Sun received Phase I and II Environmental Investigation Report fro the Responsible Party, Leo Lefkowitz (718-218-7880). Review of the above reports is in progress. (Sun) 06/15/06-Sun: Phase II investigation report showed two soil samples were taken on South Cellar 2' below follor level and one soil sample was taken on North Cellar 2' below Floor Level. Additional investigation is required. (Sun) 10/19/06-The Legal Department received a fax copy (pdf version) of signed Stipulation Agreement from Responsible Party, Sosoin Developers LLC. The Department requires an original of signed Stipulation to be executed by DEC Regional Director. (Sun) 11/13/06-Sun called John Urda, DEC's Assistant Regional Attorney about the execution of Stipulation Agreement. He said that he still has not received the original of signed stips by RP. He will call RP's Lawyer, David Yudelson. (Sun) 11/29/06: The Stipulation Agreement was signed by RP on 10/30/06 and executed by DEC on 11/29/06. 03/12/07: A copy of executed stipulation agreement was mailed to Sosoin Development, LLC and also sent to David Yudelson of Sive, Paget & Riesel, P.C. (Sun) 03/12/07: Sun received from David Yudelson the Investigation Work Plan on 03/12/07. (Sun) 05/11/07: Sun approves the Site Investigation Work Plan with some conditions. The Site Investigation Summary Report is due 08/13/07. (Sun) 07/08/08-Sun: Sun sent thr following email to David Yudelson, Dear Mr. Yudelson: On May 11, 2007, the Department approved a Site Investigation Work Plan submitted by P.W. Grosser Consulting, dated February 8, 2007 for the above referenced site. The Department requires that a Final Investigation Report be submitted by August 13, 2007. As of today, the Department has not received the subject report. Therefore, you will be given two weeks to submit, via email or mail, a copy of the Final Investigation Report . A Final Investigation Report must be received by July 22 2008 or the case will be referred to the Department's Legal Affairs office for initial enforcement proceedings. (Sun) 7/8/08-Sun: Sun received the following email from David Yudelson, Joe - thank you for the email. I have not been in contact with the former client for many months. I will reach out to them and find out what the story is. I will report back. Dave. (Sun) 7/15/08-Sun: Sun sent the following email to David Yudelson, Hi David, Thanks for your response. Can you tell me the phone No and email address of your former client, Sosoin Developers, LLC and its owner, Mr. Leo Lefkowitz. My certified mail to him was twice returned as undeliverable. I need to speak to him. He has signed the Stipulation Agreement. Your information is very important to DEC to complete the cleanup of this site by Mr. Lefkowitz. Your response is urgently requested. (sun)

---------- 7/24/08: Reassigned from Joe sun to Chanda. 5/27/09 This spill case transferred from K. Chanda to J.A. Maisonave. - JAM 12/14/11: This spill case transferred from J. Maisonave to J. Kolleeny. - JK"

Remarks: "SOIL CONTAMINATED IN REMOTE FILLS. POOR HOUSEKEEPING AROUND WASTE OIL FILL SLOWLY BUBBLING. DIVORCED FILL LINES."

All Materials:

Site ID:	74922
Operable Unit ID:	1018060
Operable Unit:	01
Material ID:	361657
Material Code:	0009
Material Name:	gasoline

CITGO/ 594 BROADWAY (Continued) **S102672996**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	74922
Operable Unit ID:	1018060
Operable Unit:	01
Material ID:	361658
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P273 **RICHARDS AUTO REPAIR SHOP** **RCRA NonGen / NLR** **1001482986**
NNW **594 BROADWAY** **FINDS** **NYU005001185**
< 1/8 **BROOKLYN, NY 99999** **ECHO**
0.120 mi.
632 ft. **Site 2 of 11 in cluster P**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RICHARDS AUTO REPAIR SHOP
Facility address:	594 BROADWAY BROOKLYN, NY 99999
EPA ID:	NYU005001185
Mailing address:	DUPONT ST PLAINVIEW, NY 11803
Contact:	Not reported
Contact address:	DUPONT ST PLAINVIEW, NY 11803
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NON REGULATED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, NY 99999
Owner/operator country:	US
Owner/operator telephone:	516-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

RICHARDS AUTO REPAIR SHOP (Continued) **1001482986**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NON REGULATED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, NY 99999
Owner/operator country: US
Owner/operator telephone: 516-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RICHARDS AUTO REPAIR SHOP
Classification: Not a generator, verified

Date form received by agency: 03/04/1999
Site name: RICHARDS AUTO REPAIR SHOP
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/23/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110008115128

Environmental Interest/Information System

RICHARDS AUTO REPAIR SHOP (Continued) **1001482986**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001482986
Registry ID:	110008115128
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008115128

P274 **SUSION DEVELPORS LLC** **NY UST** **U001330304**
NNW **594 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.120 mi.
632 ft. **Site 3 of 11 in cluster P**

Relative: **Lower**

Actual: **13 ft.**

UST:

Name:	SUSION DEVELPORS LLC
Address:	594 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-600870 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588985.46857
UTM Y:	4506365.25263
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	22842
Affiliation Type:	Facility Owner
Company Name:	SUSION DEVELPORS LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	545 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 218-7880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22842
Affiliation Type:	Mail Contact
Company Name:	SUSION DEVELPORS LLC
Contact Type:	Not reported
Contact Name:	LEO LEFKOWITZ

SUSION DEVELPORS LLC (Continued) **U001330304**

Address1:	545 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 218-7880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22842
Affiliation Type:	Facility Operator
Company Name:	SUSION DEVELPORS LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22842
Affiliation Type:	Emergency Contact
Company Name:	SUSION DEVELPORS LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	44168
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

SUSION DEVELPORS LLC (Continued) **U001330304**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 10
Tank ID: 44177
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 11
Tank ID: 53192
Tank Status: Closed - Removed

SUSION DEVELPORS LLC (Continued) **U001330304**

Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	07/01/1997
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	2
Tank ID:	44169
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	09
Date Test:	08/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

SUSION DEVELPORS LLC (Continued) **U001330304**

Tank Number: 3
Tank ID: 44170
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 4
Tank ID: 44171
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating

SUSION DEVELPORS LLC (Continued) **U001330304**

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 5
Tank ID: 44172
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number: 6
Tank ID: 44173
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

SUSION DEVELPORS LLC (Continued) **U001330304**

Equipment Records:

F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	7
Tank ID:	44174
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	09
Date Test:	08/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number:	8
Tank ID:	44175
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

SUSION DEVELPORS LLC (Continued) **U001330304**

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 9
Tank ID: 44176
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 09
Date Test: 08/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating

P275 **A G IGNITION** **EDR Hist Auto** **1020200142**
NNW **594 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.120 mi.
632 ft. **Site 4 of 11 in cluster P**

Relative: EDR Hist Auto
Lower

Actual:
13 ft.

Year:	Name:	Type:
1986	A G IGNITION	Gasoline Service Stations
1987	A G IGNITION	Gasoline Service Stations
1988	A G IGNITION	Gasoline Service Stations
1989	A G IGNITION	Gasoline Service Stations
1990	A G IGNITION	Gasoline Service Stations
1991	A G IGNITION	Gasoline Service Stations
1992	A G IGNITION	Gasoline Service Stations
1993	A G IGNITION	Gasoline Service Stations
1994	A G IGNITION	Gasoline Service Stations
1995	RICHARD AUTO REPAIR	General Automotive Repair Shops
1996	RICHARD AUTO REPAIR	General Automotive Repair Shops
1997	BERMEO RICHARD	General Automotive Repair Shops
1998	BERMEO RICHARD	General Automotive Repair Shops
1999	BERMEO RICHARD	General Automotive Repair Shops
2000	BERMEO RICHARD	General Automotive Repair Shops
2001	RICHARD AUTO REPAIR	General Automotive Repair Shops
2002	FUEL EXPRESS GASOLINE CORP	Gasoline Service Stations, NEC
2002	RICHARD AUTO REPAIR	General Automotive Repair Shops
2003	FUEL EXPRESS GASOLINE CORP	Gasoline Service Stations, NEC
2004	FUEL EXPRESS GASOLINE CORP	Gasoline Service Stations, NEC
2005	FUEL EXPRESS GASOLINE CORP	Gasoline Service Stations, NEC

P276 **ELLAYAH DELI GROCERY** **NY Spills** **S116554395**
NNW **590 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.120 mi.
633 ft. **Site 5 of 11 in cluster P**

Relative: SPILLS:
Lower

Actual:
13 ft.

Name:	ELLAYAH DELI GROCERY
Address:	590 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1400390 / 2014-04-11
Facility ID:	1400390
Facility Type:	ER
DER Facility ID:	448539
Site ID:	493627
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2014-04-11
Investigator:	SXMAHAT
Referred To:	Not reported
Reported to Dept:	2014-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

ELLAYAH DELI GROCERY (Continued) **S116554395**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-04-11
Spill Record Last Update:	2014-04-11
Spiller Name:	Not reported
Spiller Company:	ELLAYAH DELI GROCERY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	N/A
DEC Memo:	"Refer to the DEP (Confromation number : C1-1-957-418-557) "
Remarks:	"The following information was received through the DEC website Report an Environmental Violation Online or sent directly by the complainant to an OPP dispatch mailbox: Who Did It: Ellayah Deli grocery, located at 590 Broadway Brooklyn, NY 11206 What Occurred: I had observed on multiple occasions employees from this grocery are illegally disposing of their used Cooking oil (Grease) into the Street drain located in at the corner of Throop And Walton street (in front of 147 Walton st) When Did It Occur: On daily basis County: Kings Municipality: Brooklyn Location Or Address: 590 Broadway Brooklyn, NY 11206 How Did It Occur: Complainants Name: SAM"

All Materials:

Site ID:	493627
Operable Unit ID:	1243140
Operable Unit:	01
Material ID:	2243803
Material Code:	0046A
Material Name:	cooking grease
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

L277 **MANHOLE #997** **NY Spills** **S103938828**
SSW **FLUSHING AVE & DELMONACO** **N/A**
< 1/8 **BROOKLYN, NY**
0.121 mi.
640 ft. **Site 32 of 32 in cluster L**

Relative: SPILLS:
Lower

Actual:
13 ft.

Name:	MANHOLE #997
Address:	FLUSHING AVE & DELMONACO
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9903465 / 1999-10-20
Facility ID:	9903465
Facility Type:	ER
DER Facility ID:	145373
Site ID:	172742
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-06-25

MANHOLE #997 (Continued) **S103938828**

Investigator:	COMENALE
Referred To:	Not reported
Reported to Dept:	1999-06-25
CID:	390
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-25
Spill Record Last Update:	2000-06-07
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	MIKE CESARE
DEC Memo:	""
Remarks:	"CLEAN UP IS PENDING LAB RESULTS CON ED #125763"

All Materials:

Site ID:	172742
Operable Unit ID:	1078064
Operable Unit:	01
Material ID:	303378
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P278 **CON EDISON SERVICE BOX: 42766** **RCRA NonGen / NLR** **1016967394**
NNW **147 WALTON ST** **NY MANIFEST** **NYP004410114**
< 1/8 **BROOKLYN, NY 11234**
0.122 mi.
642 ft. **Site 6 of 11 in cluster P**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/20/2014
Facility name:	CON EDISON SERVICE BOX: 42766
Facility address:	147 WALTON ST BROOKLYN, NY 11234
EPA ID:	NYP004410114
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

CON EDISON SERVICE BOX: 42766 (Continued) **1016967394**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/20/2013
Site name: CON EDISON SERVICE BOX: 42766
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 147 WALTON ST
City,State,Zip: BROOKLYN, NY 11234
Country: USA
EPA ID: NYP004410114
Facility Status: Not reported
Location Address 1: 147 WALTON ST
Code: BP
Location Address 2: SB42766
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004410114
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

CON EDISON SERVICE BOX: 42766 (Continued) **1016967394**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/2013
Trans1 Recv Date:	12/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004410114
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300704GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

M279 **CON EDISON** **RCRA NonGen / NLR** **1019909469**
North **22-66 LEONARD ST** **FINDS** **NYP004885196**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.122 mi.
642 ft. **Site 4 of 5 in cluster M**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/30/2016
Facility name:	CON EDISON
Facility address:	22-66 LEONARD ST BROOKLYN, NY 11206
EPA ID:	NYP004885196
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/30/2016
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069665384

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019909469**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019909469
Registry ID:	110069665384
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069665384

M280 **CON EDISON** **NJ MANIFEST** **S120678616**
North **22-66 LEONARD ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.122 mi.
642 ft. **Site 5 of 5 in cluster M**

Relative:
Lower

Actual:
13 ft.

NJ MANIFEST:

EPA Id:	NYP004885196
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015322136JJK
EPA ID:	NYP004885196
Date Shipped:	12/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

CON EDISON (Continued) **S120678616**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N281 **CON EDISON** **NY MANIFEST** **S117314130**
ESE **719 FLUSHING AVE** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.123 mi.
652 ft. **Site 10 of 14 in cluster N**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	719 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004611646
Facility Status:	Not reported
Location Address 1:	719 FLUSHING AVE
Code:	BP
Location Address 2:	SB 7422
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004611646
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CON EDISON (Continued) **S117314130**

Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/29/2014
Trans1 Recv Date:	07/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004611646
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615573GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

J282 **NYC DEPT OF EDUCATION - PS 318K** **RCRA NonGen / NLR** **1000552941**
WNW **101 WALTON ST** **FINDS** **NYD986953461**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.126 mi. **NY MANIFEST**
665 ft. **Site 16 of 17 in cluster J**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/18/2017
Facility name:	NYC DEPT OF EDUCATION - PS 318K
Facility address:	101 WALTON ST BROOKLYN, NY 11206
EPA ID:	NYD986953461
Mailing address:	WALTON ST BROOKLYN, NY 11206
Contact:	BERNARD P ORLAN
Contact address:	VERNON BLVD LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	718-361-3808
Contact email:	BORLAN@SCHOOLS.NYC.GOV
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYC DEPT OF EDUCATION
Owner/operator address:	VERNON BLVD LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	718-361-3808
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	09/01/1968
Owner/Op end date:	Not reported

Owner/operator name:	NYC DEPT OF EDUCATION
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	09/01/1968
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

NYC DEPT OF EDUCATION - PS 318K (Continued) **1000552941**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 07/28/2015
Site name: NYC DEPT OF EDUCATION - PS 318K
Classification: Large Quantity Generator

Date form received by agency: 01/01/2007
Site name: INTERMEDIATE SCHOOL 318
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: INTERMEDIATE SCHOOL 318
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: INTERMEDIATE SCHOOL 318
Classification: Not a generator, verified

Date form received by agency: 05/30/1991
Site name: INTERMEDIATE SCHOOL 318
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: B007
. Waste name: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED

NYC DEPT OF EDUCATION - PS 318K (Continued) **1000552941**

IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P028
. Waste name: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

. Waste code: P030
. Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

. Waste code: P092
. Waste name: MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE

. Waste code: P098
. Waste name: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

. Waste code: P106
. Waste name: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

. Waste code: U032
. Waste name: CALCIUM CHROMATE (OR) CHROMIC ACID H2CRO4, CALCIUM SALT

. Waste code: U103
. Waste name: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Violation Status: No violations found

FINDS:

Registry ID: 110004467229

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

NYC DEPT OF EDUCATION - PS 318K (Continued) **1000552941**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000552941
Registry ID:	110004467229
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004467229

NY MANIFEST:

Name:	I S 318 K
Address:	101 WALTON ST
City,State,Zip:	BROOKLYN, NY 11206-4311
Country:	USA
EPA ID:	NYD986953461
Facility Status:	Not reported
Location Address 1:	101 WALTON STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986953461
Mailing Name:	I S 318 K
Mailing Contact:	ALAN FIERSTEIN
Mailing Address 1:	101 WALTON STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187820589

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2013

NYC DEPT OF EDUCATION - PS 318K (Continued) **1000552941**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986953461
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	004163918FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

J283 **I.S. 318 - BROOKLYN K318** **NY AST** **U003394304**
WNW **101 WALTON STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.126 mi.
665 ft. **Site 17 of 17 in cluster J**

Relative:
Higher

Actual:
14 ft.

AST:

Name:	I.S. 318 - BROOKLYN K318
Address:	101 WALTON STREET
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-355682
Program Type:	PBS
UTM X:	588859.60558

I.S. 318 - BROOKLYN K318 (Continued) **U003394304**

UTM Y: 4506335.19617
Expiration Date: 06/28/2023
Site Type: School

Affiliation Records:

Site Id: 17736
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: MANAGER, FUEL DIVISION
Contact Name: MUNENDRA SHARMA
Address1: 44-36 VERNON BOULEVARD
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5752
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2018-07-17

Site Id: 17736
Affiliation Type: Mail Contact
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: MUNENDRA SHARMA
Address1: FIELD OPERATIONS - FUEL DIVISION
Address2: 44-36 VERNON BOULEVARD
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5752
EMail: MSHARMA@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-04-10

Site Id: 17736
Affiliation Type: Facility Operator
Company Name: I.S. 318 - BROOKLYN K318
Contact Type: Not reported
Contact Name: SALVATORE CALDERONE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 782-0589
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-02-26

Site Id: 17736
Affiliation Type: Emergency Contact

I.S. 318 - BROOKLYN K318 (Continued) **U003394304**

Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-12-06

Tank Info:

Tank Number:	001
Tank Id:	34716
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	L00 - Piping Leak Detection - None
	E00 - Piping Secondary Containment - None
	I04 - Overfill - Product Level Gauge (A/G)
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
	K00 - Spill Prevention - None
	G02 - Tank Secondary Containment - Vault (w/access)
	I05 - Overfill - Vent Whistle
	C03 - Pipe Location - Aboveground/Underground Combination
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1967
Capacity Gallons:	15000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	02/26/2018
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34717
Material Code:	0003

I.S. 318 - BROOKLYN K318 (Continued) **U003394304**

Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1967
Capacity Gallons:	15000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	02/26/2018
Material Name:	#4 fuel oil (on-site consumption)

N284 **CON EDISON** **NY MANIFEST** **S117740216**
SSE **185 HOPKINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.128 mi.
674 ft. **Site 11 of 14 in cluster N**

Relative: **Higher**
Actual: **18 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	185 HOPKINS ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004733754
Facility Status:	Not reported
Location Address 1:	185 HOPKINS ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004733754
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON (Continued) **S117740216**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/18/2015
Trans1 Recv Date:	02/18/2015
Trans2 Recv Date:	02/23/2015
TSD Site Recv Date:	02/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004733754
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620522GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117740216**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N285 **CON EDISON - SERVICE BOX 8549** **NJ MANIFEST** **S120667457**
SSE **185 HOPKINS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.128 mi.
674 ft. **Site 12 of 14 in cluster N**

Relative:
Higher

Actual:
18 ft.

NJ MANIFEST:

EPA Id:	NYP004733754
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002620522GBF
EPA ID:	NYP004733754
Date Shipped:	2/18/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON - SERVICE BOX 8549 (Continued) **S120667457**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N286 **CON EDISON - SERVICE BOX 8549** **RCRA-LQG** **1018278596**
SSE **185 HOPKINS ST** **NYP004733754**
1/8-1/4 **BROOKLYN, NY 11206**
0.128 mi.
674 ft. **Site 13 of 14 in cluster N**

Relative: **Higher**

Actual: **18 ft.**

RCRA-LQG:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON - SERVICE BOX 8549
Facility address:	185 HOPKINS ST BROOKLYN, NY 11206
EPA ID:	NYP004733754
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

CON EDISON - SERVICE BOX 8549 (Continued) **1018278596**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/18/2015
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/18/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/18/2015
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 02/18/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD

CON EDISON - SERVICE BOX 8549 (Continued) **1018278596**

Amount (Lbs): 16600

Violation Status: No violations found

P287 **CON EDISON - MANHOLE 15628** **RCRA-LQG** **1016451599**
NNW **584 BROADWAY** **FINDS** **NYP004306957**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.131 mi. **NY MANIFEST**
690 ft. **Site 7 of 11 in cluster P**

Relative:
Lower

Actual:
13 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 15628
Facility address:	584 BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004306957
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/02/2013
Owner/Op end date:	Not reported
Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US

CON EDISON - MANHOLE 15628 (Continued) **1016451599**

Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/02/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/02/2013
Site name: CON EDISON MANHOLE: 15628
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110056327737

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CON EDISON - MANHOLE 15628 (Continued) **1016451599**

ECHO:
- Envid: 1016451599
- Registry ID: 110056327737
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056327737

NY MANIFEST:
- Name: CON EDISON
- Address: 584 BROADWAY
- City,State,Zip: BROOKLYN, NY 11206
- Country: USA
- EPA ID: NYP004306957
- Facility Status: Not reported
- Location Address 1: 584 BROADWAY
- Code: BP
- Location Address 2: Not reported
- Total Tanks: Not reported
- Location City: BROOKLYN
- Location State: NY
- Location Zip: 11206
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYP004306957
- Mailing Name: CON EDISON
- Mailing Contact: TOM TEELING
- Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
- Mailing Address 2: Not reported
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124603770

NY MANIFEST:
- Document ID: Not reported
- Manifest Status: Not reported
- seq: Not reported
- Year: 2013
- Trans1 State ID: NJD003812047
- Trans2 State ID: Not reported
- Generator Ship Date: 05/02/2013
- Trans1 Recv Date: 05/02/2013
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 05/02/2013
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004306957
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID 1: NJD991291105
- TSDF ID 2: Not reported
- Manifest Tracking Number: 002017392GBF
- Import Indicator: N
- Export Indicator: N
- Discr Quantity Indicator: N

CON EDISON - MANHOLE 15628 (Continued) **1016451599**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N288 **EMS @ WOODHULL HOSPITAL** **NY UST** **U003652107**
SE **720 FLUSHING AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.133 mi.
703 ft. **Site 14 of 14 in cluster N**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	EMS @ WOODHULL HOSPITAL
Address:	720 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-604099 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589263.58996
UTM Y:	4506016.94248
Site Type:	Other

Affiliation Records:

Site Id:	25983
Affiliation Type:	Facility Owner
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	9 METROTECH CENTER
Address2:	Not reported

EMS @ WOODHULL HOSPITAL (Continued) **U003652107**

City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-15

Site Id:	25983
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY FIRE DEPARTMENT
Contact Type:	Not reported
Contact Name:	DIRECTOR-FDNY BLDG MAINT
Address1:	48-34 35TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25983
Affiliation Type:	Facility Operator
Company Name:	EMS @ WOODHULL HOSPITAL
Contact Type:	Not reported
Contact Name:	EMS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25983
Affiliation Type:	Emergency Contact
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	JOSEPH MASTROPIETRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported

EMS @ WOODHULL HOSPITAL (Continued) **U003652107**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	56687
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	2500
Install Date:	05/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	cgfreedm
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D08 - Pipe Type - Equivalent Technology
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
F99 - Pipe External Protection - Other
H05 - Tank Leak Detection - In-Tank System (ATG)

O289 **CON EDISON - VS 2314** **RCRA NonGen / NLR** **1008195512**
SSW **93 HOPKINS ST** **NY MANIFEST** **NYP004106852**
1/8-1/4 **BROOKLYN, NY 11215**
0.134 mi.
709 ft. **Site 4 of 4 in cluster O**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/27/2004
Facility name:	CON EDISON - VS 2314
Facility address:	93 HOPKINS ST BROOKLYN, NY 11215
EPA ID:	NYP004106852
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	4 IRVING PLACE NEW YORK, NY 10003
Contact country:	US

CON EDISON - VS 2314 (Continued) **1008195512**

Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/04/2003
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/04/2003
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/26/2004
Site name: CON EDISON - VS 2314
Classification: Not a generator, verified

Date form received by agency: 02/25/2004

CON EDISON - VS 2314 (Continued) **1008195512**

Site name: CON EDISON - VS 2314
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: B002
. Waste name: Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 93 HOPKINS ST
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004106852
Facility Status: Not reported
Location Address 1: V2314-93 HOPKINS ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004106852
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0459018
Manifest Status: Not reported
seq: 01
Year: 2003
Trans1 State ID: 46235JM
Trans2 State ID: Not reported
Generator Ship Date: 02/06/2003
Trans1 Recv Date: 02/06/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/06/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004106852
Trans1 EPA ID: NYD006982359

CON EDISON - VS 2314 (Continued) **1008195512**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01082
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q290 **CON EDISON SERVICE BOX: 9097** **RCRA NonGen / NLR** **1016974417**
ENE **32 VARET ST** **NY MANIFEST** **NYP004482386**
1/8-1/4 **BROOKLYN, NY 11206**
0.138 mi.
726 ft. **Site 1 of 7 in cluster Q**

Relative: **Higher**

Actual: **17 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/28/2014
Facility name:	CON EDISON SERVICE BOX: 9097
Facility address:	32 VARET ST BROOKLYN, NY 11206
EPA ID:	NYP004482386
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON SERVICE BOX: 9097 (Continued) **1016974417**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/28/2014
Site name: CON EDISON SERVICE BOX: 9097
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 32 VARET ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004482386
Facility Status: Not reported
Location Address 1: FRONT OF 32 VARET ST
Code: BP
Location Address 2: SB9097
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004482386
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014

CON EDISON SERVICE BOX: 9097 (Continued) **1016974417**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2014
Trans1 Recv Date:	03/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004482386
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407024GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R291 **CON EDISON** **RCRA NonGen / NLR** **1019902665**
East **BROADWAY & DEBEVOISE ST** **NYP004776399**
1/8-1/4 **BROOKLYN, NY 11206**
0.140 mi.
741 ft. **Site 1 of 19 in cluster R**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/29/2015
Facility name:	CON EDISON
Facility address:	BROADWAY & DEBEVOISE ST BROOKLYN, NY 11206
EPA ID:	NYP004776399
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/29/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

R292 **CON EDISON** **RCRA NonGen / NLR** **1019906799**
East **BROADWAY & DEBEVOISE ST** **FINDS** **NYP004826572**
1/8-1/4 **BROOKLYN, NY 11237** **ECHO**
0.140 mi.
741 ft. **Site 2 of 19 in cluster R**

Relative: **Higher**
Actual: **21 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/19/2015
Facility name:	CON EDISON
Facility address:	BROADWAY & DEBEVOISE ST BROOKLYN, NY 11237
EPA ID:	NYP004826572

CON EDISON (Continued) **1019906799**

Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/19/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069672018

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906799
Registry ID: 110069672018
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069672018

R293 **CON EDISON** **NJ MANIFEST** **S120675607**
East **BROADWAY & DEBEVOISE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.140 mi.
741 ft. **Site 3 of 19 in cluster R**

Relative:
Higher

Actual:
21 ft.

NJ MANIFEST:

EPA Id:	NYP004826572
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624845GBF
EPA ID:	NYP004826572
Date Shipped:	8/19/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675607**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q294 **CON EDISON** **NY MANIFEST** **S121968133**
NE **30 MANHATTAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.144 mi.
762 ft. **Site 2 of 7 in cluster Q**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	30 MANHATTAN AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP005087006
Facility Status:	Not reported
Location Address 1:	30 MANHATTAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005087006
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q295
NE
1/8-1/4
0.144 mi.
762 ft.

CON EDISON - VAULT SUBMERSIBLE 5661
30 MANHATTAN AVE
BROOKLYN, NY 11206

Site 3 of 7 in cluster Q

RCRA-LQG | **1024891213** / **NYP005087006**

Relative:
Higher

Actual:
15 ft.

RCRA-LQG:

Date form received by agency:	04/10/2018
Facility name:	CON EDISON - VAULT SUBMERSIBLE 5661
Facility address:	30 MANHATTAN AVE BROOKLYN, NY 11206
EPA ID:	NYP005087006
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	ALYSSA SOTTO
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	SOTTOA@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/24/2017
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

CON EDISON - VAULT SUBMERSIBLE 5661 (Continued) **1024891213**

Owner/Op start date: 05/24/2017
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: B002
. Waste name: Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

S296 **CON EDISON MANHOLE: 466** **RCRA-VSQG** **1016451597**
West **WALTON ST & HARRISON AVE SW** **FINDS** **NYP004306924**
1/8-1/4 **BROOKLYN, NY 11217** **ECHO**
0.145 mi.
763 ft. **Site 1 of 5 in cluster S**

Relative:
Higher

Actual:
14 ft.

RCRA-VSQG:
Date form received by agency: 05/02/2013
Facility name: CON EDISON MANHOLE: 466
Facility address: WALTON ST & HARRISON AVE SW
COR
BROOKLYN, NY 11217
EPA ID: NYP004306924
Mailing address: VING PL, RM 828
NEW YORK, NY 10003
Contact: CHRISTOPHER MARRAZZO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 718-802-5194
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time;

CON EDISON MANHOLE: 466 (Continued) **1016451597**

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110056327719

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016451597
Registry ID:	110056327719
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056327719

S297 **CON EDISON MANHOLE: 20772** **RCRA-VSQG** **1016451596**
West **HARRISON AVE & WALTON ST** **FINDS** **NYP004306916**
1/8-1/4 **BROOKLYN, NY 11217** **ECHO**
0.145 mi.
763 ft. **Site 2 of 5 in cluster S**

Relative:
Higher

Actual:
14 ft.

RCRA-VSQG:

Date form received by agency:	05/02/2013
Facility name:	CON EDISON MANHOLE: 20772
Facility address:	HARRISON AVE & WALTON ST BROOKLYN, NY 11217
EPA ID:	NYP004306916
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	CHRISTOPHER MARRAZZO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	718-802-5194
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110056327700

CON EDISON MANHOLE: 20772 (Continued) **1016451596**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016451596
Registry ID: 110056327700
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056327700

T298 **PFIZER INC BROOKLYN PLANT** **RCRA NonGen / NLR** **1000871470**
WSW **338 WALLABOUT ST** **FINDS** **NY0000055384**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.149 mi. **NY MANIFEST**
787 ft. **Site 1 of 4 in cluster T**

Relative: Lower
Actual: 13 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: PFIZER INC BROOKLYN PLANT
Facility address: 338 WALLABOUT ST
BROOKLYN, NY 11206-4923
EPA ID: NY0000055384
Mailing address: FLUSHING AVE
BROOKLYN, NY 11206-5092
Contact: Not reported
Contact address: FLUSHING AVE
BROOKLYN, NY 11206-5092
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PFIZER INC
Owner/operator address: 630 FLUSHING AVE
BROOKLYN, NY 11206
Owner/operator country: US
Owner/operator telephone: 718-780-8686
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PFIZER INC
Owner/operator address: 630 FLUSHING AVE

PFIZER INC BROOKLYN PLANT (Continued) **1000871470**

BROOKLYN, NY 11206
Owner/operator country: US
Owner/operator telephone: 718-780-8686
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PFIZER INC BROOKLYN PLANT
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: PFIZER INC BROOKLYN PLANT
Classification: Not a generator, verified

Date form received by agency: 03/03/1998
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 03/29/1996
Site name: PFIZER INC
Classification: Large Quantity Generator

Date form received by agency: 11/08/1993
Site name: PFIZER INC BROOKLYN PLANT
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

PFIZER INC BROOKLYN PLANT (Continued) **1000871470**

Violation Status: No violations found

FINDS:

Registry ID: 110000881920

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000871470
Registry ID:	110000881920
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000881920

NY MANIFEST:

Name:	PFIZER INC
Address:	338 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206-5098
Country:	USA
EPA ID:	NY0000055384
Facility Status:	Not reported
Location Address 1:	338 WALLABOUT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000055384
Mailing Name:	PFIZER INC
Mailing Contact:	TOM SNEE
Mailing Address 1:	630 FLUSHING AVE
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187808686

NY MANIFEST:

Document ID:	NYB8445087
Manifest Status:	Not reported
seq:	01
Year:	1998

PFIZER INC BROOKLYN PLANT (Continued) **1000871470**

Trans1 State ID:	NYJA334
Trans2 State ID:	Not reported
Generator Ship Date:	10/09/1998
Trans1 Recv Date:	10/09/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/15/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000055384
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00816
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R299 **CON EDISON** **RCRA NonGen / NLR** **1019903528**
ESE **720 BROADWAY** **FINDS** **NYP004786687**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.154 mi.
813 ft. **Site 4 of 19 in cluster R**

Relative:
Higher

Actual:
22 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/27/2015
Facility name:	CON EDISON
Facility address:	720 BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004786687
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported

CON EDISON (Continued) **1019903528**

Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/27/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069666622

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019903528
Registry ID: 110069666622
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069666622

R300
ESE
1/8-1/4
0.154 mi.
813 ft.

CON EDISON
720 BROADWAY
BROOKLYN, NY 11206

Site 5 of 19 in cluster R

NJ MANIFEST **S120672133**
N/A

Relative:
Higher

Actual:
22 ft.

NJ MANIFEST:

EPA Id:	NYP004786687
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624459GBF
EPA ID:	NYP004786687
Date Shipped:	5/27/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120672133**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R301 **CON EDISON** **NY MANIFEST** **S119075512**
ESE **720 BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.154 mi.
813 ft. **Site 6 of 19 in cluster R**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	720 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004786687
Facility Status:	Not reported
Location Address 1:	718 BROADWAY
Code:	BP
Location Address 2:	SB 15658
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004786687
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/27/2015
Trans1 Recv Date:	05/27/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/28/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004786687
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S119075512**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624459GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

U302 **CON EDISON** **NY MANIFEST** **S117064268**
NE **46 MANHATTAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.157 mi.
829 ft. **Site 1 of 5 in cluster U**

Relative: NY MANIFEST:
Higher

Actual: Name:	CON EDISON
15 ft. Address:	46 MANHATTAN AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004567442
Facility Status:	Not reported
Location Address 1:	46 MANHATTAN AVE
Code:	BP
Location Address 2:	SB 15153
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206

CON EDISON (Continued) **S117064268**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004567442
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/17/2014
Trans1 Recv Date: 06/17/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/18/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004567442
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013255337JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S117064268**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

U303 **CON EDISON SERVICE BOX: 15153** **RCRA NonGen / NLR** **1017778792**
NE **46 MANHATTAN AVE** **FINDS** **NYP004567442**
1/8-1/4 **BROOKLYN, NY 11206**
0.157 mi.
829 ft. **Site 2 of 5 in cluster U**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/17/2014
Facility name:	CON EDISON SERVICE BOX: 15153
Facility address:	46 MANHATTAN AVE BROOKLYN, NY 11206
EPA ID:	NYP004567442
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/17/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

CON EDISON SERVICE BOX: 15153 (Continued) **1017778792**

Date form received by agency: 06/17/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063822966

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

T304 **255 WALLABOUT ST/PFIZER** **NY LTANKS** **S102671554**
WSW **255 WALLABOUT STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.157 mi.
831 ft. **Site 2 of 4 in cluster T**

Relative: **Lower**
Actual: **13 ft.**

LTANKS:

Name:	255 WALLABOUT ST/PFIZER
Address:	255 WALLABOUT STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9005003 / 2006-11-14
Facility ID:	9005003
Site ID:	219704
Spill Date:	1990-08-06
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	CHAWLA
Referred To:	Not reported
Reported to Dept:	1990-08-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-08-08
Spill Record Last Update:	2006-11-14
Spiller Name:	Not reported
Spiller Company:	PFIZER INC
Spiller Address:	11 BARTLETT STREET
Spiller County:	001

255 WALLABOUT ST/PFIZER (Continued) **S102671554**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	181700
DEC Memo:	""
Remarks:	"CONTAMINATED SOIL DISCOVERED UPON EXCAVATION OF TANK."

All Materials:

Site ID:	219704
Operable Unit ID:	945487
Operable Unit:	01
Material ID:	436074
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

T305 **FORMER PFIZER SITE C** **NY BROWNFIELDS S121343849**
WSW **334 WALLABOUT STREET** **NY E DESIGNATION N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.158 mi.
833 ft. **Site 3 of 4 in cluster T**

Relative: **Lower**

Actual: **12 ft.**

BROWNFIELDS:

Name:	FORMER PFIZER SITE C
Address:	334 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Program:	BCP
Site Code:	579698
Acres:	2.55
HW Code:	C224288
SWIS:	2401
Town:	New York City
Record Added Date:	11/20/2018
Record Updated Date:	12/28/2018
Update By:	BRHUMPHR
Site Description:	Location The site to be remediated and redeveloped is located in the Brooklyn Triangle section of Kings County and is comprised of four tax parcels totaling 110,040 square feet (2.55 acres). The site is located in the City of New York and Borough of Brooklyn. The irregular shaped site occupies a full block with approximately 485 ft. of frontage along Wallabout Street, 200 feet of frontage on Harrison Avenue, 225 feet of frontage on Union Avenue and 600 feet of frontage on Gerry Street. Site Features There are no structures presently on the site. Current Zoning and Land Use The lot is currently used for the storage of scaffolding and related construction equipment. The property is surrounded by an 8 ft high chain-link fence with one gate on Wallabout Street. The western portion of the site is zoned R8A while the central portion is zoned R7D and the eastern portion is zoned R7A. The lot is currently used for the storage of scaffolding and related construction equipment. Surrounding land use includes residential apartment buildings to the

FORMER PFIZER SITE C (Continued) **S121343849**

west, former Pfizer Site A to the north, commercial (warehouses), residential buildings and a private school (Bais Ruchel High School) to the east and the and a charter school (Beginning with Children) to the south. The closest school (Bais Ruchel High School) is located 60 feet to the east. Beginning with Children Charter School is located 70 feet to the south and PS 318 is located 375 feet to the north. Past Use of the Site The historic use of the site includes residential homes, Pfizer chemical works and varnish manufacturing in 1887-1918, a lumber yard and the Pfizer chemical works in 1935. By 1947 the Pfizer chemical works occupied the entire property and continued you to do so through the 1995 when the buildings were demolished. Site Geology and Hydrogeology Subsurface soils at the site consist of historic fill materials to a depth of approximately 4 to 13 feet below the surface followed a thick silt and clay layer. According to the USGS topographic map for the area (Central Park Quadrangle), the elevation of the property is approximately 18 feet above the National Geodetic Vertical Datum (NGVD). The area topography is generally flat with little relief and no significant elevation changes. Groundwater occurs beneath the site at a depth of approximately 8-13 feet below grade under perched water table conditions. Based on previous studies performed at the site, groundwater flow is generally west to southwest. No portion of the site is located within a designated flood zone area.

Env Problem:	Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	P03
Owner Name:	Charles Krieger
Owner Company:	Harrison Realty LLC
Owner Address:	505 Flushing Avenue, No. 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Piku Scaffolding
Owner Address:	334 Wallabout Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America

FORMER PFIZER SITE C (Continued) **S121343849**

Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue at Seigel Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Charles Krieger
Owner Company:	Harrison Realty LLC
Owner Address:	505 Flushing Avenue, No. 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

E DESIGNATION:

Name:	LOT 14,TAXBLOCK 2265
Address:	334 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	14
Tax Block:	2265
Borough Code:	BK
E-No:	E-427
Effective Date:	10/31/2017
Satisfaction Date:	Not reported
Ceqr Number:	15DCP117K
Ulurp Number:	150278ZMK, 150277ZRK
Zoning Map No:	13b
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

FORMER PFIZER SITE C (Continued) **S121343849**

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

P306 **CON EDISON - TM 1358** **RCRA NonGen / NLR** **1008195668**
NW **THROOP AVE & LORIMER ST** **NY MANIFEST** **NYP004111993**
1/8-1/4 **BROOKLYN, NY 11206**
0.159 mi.
841 ft. **Site 8 of 11 in cluster P**

Relative: **Lower**

Actual: **13 ft.**

RCRA NonGen / NLR:
Date form received by agency: 02/27/2004
Facility name: CON EDISON - TM 1358
Facility address: THROOP AVE & LORIMER ST
BROOKLYN, NY 11206
EPA ID: NYP004111993
Mailing address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact: ANTHONY DRUMMINGS
Contact address: 4 IRVING PLACE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/14/2003
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/14/2003
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CON EDISON - TM 1358 (Continued) **1008195668**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/26/2004
Site name:	CON EDISON - TM 1358
Classification:	Not a generator, verified

Date form received by agency:	02/25/2004
Site name:	CON EDISON - TM 1358
Classification:	Large Quantity Generator

Hazardous Waste Summary:

. Waste code:	B002
. Waste name:	Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

Violation Status: No violations found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	THROOP AVE & LORIMER ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004111993
Facility Status:	Not reported
Location Address 1:	THROPP AVE & LORAINE TM1358
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004111993
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON - TM 1358 (Continued) **1008195668**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0618345
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	46109JM
Trans2 State ID:	Not reported
Generator Ship Date:	06/14/2003
Trans1 Recv Date:	06/14/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/16/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004111993
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01991
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V307 **CON EDISON** **RCRA NonGen / NLR** **1018278598**
ESE **743 FLUSHING AVE SB7432** **NYP004733770**
1/8-1/4 **BROOKLYN, NY 11206**
0.159 mi.
841 ft. **Site 1 of 12 in cluster V**

Relative:
Higher

Actual:
23 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/18/2015
Facility name:	CON EDISON
Facility address:	743 FLUSHING AVE SB7432 BROOKLYN, NY 11206
EPA ID:	NYP004733770
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/18/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

V308 **CON EDISON** **NY MANIFEST** **S117740218**
ESE **743 FLUSHING AVE SB7432** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.159 mi.
841 ft. **Site 2 of 12 in cluster V**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	743 FLUSHING AVE SB7432
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004733770

CON EDISON (Continued) **S117740218**

Facility Status:	Not reported
Location Address 1:	751 FLUSHING AVE
Code:	BP
Location Address 2:	SB 7432
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004733770
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/18/2015
Trans1 Recv Date:	02/18/2015
Trans2 Recv Date:	02/23/2015
TSD Site Recv Date:	02/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004733770
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620523GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117740218**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V309 **CON EDISON** **RCRA NonGen / NLR** **1018278597**
ESE **743 FLUSHING AVE SB7432** **FINDS** **NYP004733762**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.159 mi.
841 ft. **Site 3 of 12 in cluster V**

Relative:
Higher

Actual:
23 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/18/2015
Facility name:	CON EDISON
Facility address:	743 FLUSHING AVE SB7429 BROOKLYN, NY 11206
EPA ID:	NYP004733762
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

CON EDISON (Continued) **1018278597**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/18/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067707930

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278597
Registry ID: 110067707930
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067707930

V310 **CON EDISON** **NY MANIFEST** **S117740217**
ESE **743 FLUSHING AVE SB7429** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.159 mi.
841 ft. **Site 4 of 12 in cluster V**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:
Name: CON EDISON
Address: 743 FLUSHING AVE SB7429
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004733762
Facility Status: Not reported
Location Address 1: 743 FLUSHING AVE
Code: BP
Location Address 2: SB 7429
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004733762
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR

CON EDISON (Continued) **S117740217**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/18/2015
Trans1 Recv Date:	02/18/2015
Trans2 Recv Date:	02/23/2015
TSD Site Recv Date:	02/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004733762
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620905GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S117740217**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V311 **CON EDISON** **NJ MANIFEST** **S120667459**
ESE **743 FLUSHING AVE SB7432** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.159 mi.
841 ft. **Site 5 of 12 in cluster V**

Relative:
Higher

Actual:
23 ft.

NJ MANIFEST:

EPA Id:	NYP004733770
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002620523GBF
EPA ID:	NYP004733770
Date Shipped:	2/18/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON (Continued) **S120667459**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

V312 **CON EDISON** **NJ MANIFEST** **S120667458**
ESE **743 FLUSHING AVE SB7429** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.159 mi.
841 ft. **Site 6 of 12 in cluster V**

Relative:
Higher

Actual:
23 ft.

NJ MANIFEST:

EPA Id:	NYP004733762
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002620905GBF
EPA ID:	NYP004733762
Date Shipped:	2/18/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120667458**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R313 **CON EDISON** **NY MANIFEST** **S117742015**
ESE **FLUSHING & BROADWAY VAULT 5439** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.160 mi.
844 ft. **Site 7 of 19 in cluster R**

Relative: **Higher**
Actual: **23 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FLUSHING & BROADWAY VAULT 5439
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004752739
Facility Status:	Not reported
Location Address 1:	OPP 745 FLUSHING AV
Code:	BP
Location Address 2:	V5439
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004752739
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117742015**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/17/2015
Trans1 Recv Date:	03/17/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004752739
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091069JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R314 **CON EDISON** **NJ MANIFEST** **S120675049**
ESE **722 BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.160 mi.
846 ft. **Site 8 of 19 in cluster R**

Relative:
Higher

Actual:
23 ft.

NJ MANIFEST:

EPA Id:	NYP004819375
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624693GBF
EPA ID:	NYP004819375
Date Shipped:	8/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675049**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R315 **CON ED** **NY MANIFEST** **S118258674**
ESE **722 BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.160 mi.
846 ft. **Site 9 of 19 in cluster R**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON ED
Address:	722 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004819375
Facility Status:	Not reported
Location Address 1:	722 BROADWAY
Code:	BP
Location Address 2:	SB 15658
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004819375
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/2015
Trans1 Recv Date:	08/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004819375
Trans1 EPA ID:	Not reported

CON ED (Continued) **S118258674**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624693GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R316 **CON EDISON** **RCRA NonGen / NLR** **1019906284**
ESE **722 BROADWAY** **NYP004819375**
1/8-1/4 **BROOKLYN, NY 11206**
0.160 mi.
846 ft. **Site 10 of 19 in cluster R**

Relative: RCRA NonGen / NLR:
Higher

Date form received by agency:	08/06/2015
Facility name:	CON EDISON
Facility address:	722 BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004819375
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

Actual:
23 ft.

CON EDISON (Continued) **1019906284**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/06/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

R317 **CON EDISON** **NJ MANIFEST** **S120669507**
ESE **745 FLUSHING AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.161 mi.
850 ft. **Site 11 of 19 in cluster R**

Relative:
Higher

Actual:
23 ft.

NJ MANIFEST:
EPA Id: NYP004756904
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002621089GBF
EPA ID: NYP004756904
Date Shipped: 3/14/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047

CON EDISON (Continued) **S120669507**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R318 **CON EDISON** **RCRA NonGen / NLR** **1018280784**
ESE **745 FLUSHING AVE** **FINDS** **NYP004756904**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.161 mi.
850 ft. **Site 12 of 19 in cluster R**

Relative: **Higher**
Actual: **23 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/24/2015
Facility name:	CON EDISON
Facility address:	745 FLUSHING AVE BROOKLYN, NY 11206
EPA ID:	NYP004756904
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

CON EDISON (Continued) **1018280784**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/24/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067682047

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018280784
Registry ID: 110067682047
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067682047

R319 **CON EDISON** **NY MANIFEST** **S118088146**
ESE **745 FLUSHING AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.161 mi.
850 ft. **Site 13 of 19 in cluster R**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	745 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004756904
Facility Status:	Not reported
Location Address 1:	745 FLUSHING AVE
Code:	BP
Location Address 2:	SB 7429
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004756904
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	SB 7429
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/24/2015
Trans1 Recv Date:	03/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004756904
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002621089GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118088146**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

W320 **CON EDISON** **RCRA NonGen / NLR** **1019906467**
SSE **164 THROOP AVE** **FINDS** **NYP004821365**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.162 mi.
853 ft. **Site 1 of 10 in cluster W**

Relative: **Higher**

Actual: **20 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/10/2015
Facility name:	CON EDISON
Facility address:	164 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004821365
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No

CON EDISON (Continued) **1019906467**

Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/10/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069653850

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906467
Registry ID:	110069653850
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069653850

W321 **CON EDISON** **NY MANIFEST** **S119077137**
SSE **164 THROOP AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.162 mi.
853 ft. **Site 2 of 10 in cluster W**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	164 THROOP AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004821365
Facility Status:	Not reported
Location Address 1:	164TH & THROOP AVE
Code:	BP
Location Address 2:	SB 42783

CON EDISON (Continued) **S119077137**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004821365
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2015
Trans1 Recv Date:	08/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004821365
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002612241GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds

CON EDISON (Continued) **S119077137**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

W322 **CON EDISON** **NJ MANIFEST** **S120675233**
SSE **164 THROOP AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.162 mi.
853 ft. **Site 3 of 10 in cluster W**

Relative:
Higher

Actual:
20 ft.

NJ MANIFEST:

EPA Id:	NYP004821365
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002612241GBF
EPA ID:	NYP004821365
Date Shipped:	8/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON (Continued) **S120675233**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q323 **GRAYCO CORP.** **NY AST** **A100294254**
ENE **29 COOK STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.162 mi.
853 ft. **Site 4 of 7 in cluster Q**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	GRAYCO CORP.
Address:	29 COOK STREET
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608645
Program Type:	PBS
UTM X:	589320.34927
UTM Y:	4506260.12006
Expiration Date:	03/19/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30497
Affiliation Type:	Facility Owner
Company Name:	GRAYCO CORP.
Contact Type:	MANAGER
Contact Name:	DAVID GROSS
Address1:	300 MERRICK ROAD, SUITE 204
Address2:	Not reported
City:	LYNBROOK
State:	NY
Zip Code:	11563
Country Code:	001
Phone:	(917) 325-1140

GRAYCO CORP. (Continued) **A100294254**

EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-01-11

Site Id: 30497
Affiliation Type: Mail Contact
Company Name: GRAYCO CORP.
Contact Type: Not reported
Contact Name: DAVID GROSS
Address1: 300 MERRICK ROAD
Address2: SUITE 204
City: LYNBROOK
State: NY
Zip Code: 11563
Country Code: 001
Phone: (516) 596-1818
EMail: DG61@AOL.COM
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-01-11

Site Id: 30497
Affiliation Type: Facility Operator
Company Name: GRAYCO CORP.
Contact Type: Not reported
Contact Name: EDUARDO DIAZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 523-8996
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-02-10

Site Id: 30497
Affiliation Type: Emergency Contact
Company Name: GRAYCO CORP.
Contact Type: Not reported
Contact Name: DAVID GROSS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 325-1140
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-01-11

GRAYCO CORP. (Continued) **A100294254**

Tank Info:

Tank Number:	001
Tank Id:	65433
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1984
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	01/11/2018
Material Name:	#2 fuel oil (on-site consumption)

324
SW
1/8-1/4
0.162 mi.
855 ft.

PFIZER (ORGANICS/SUCIAC BLOCK) **NY VCP** **S104323903**
CENTRAL PORTION OF PFIZER FACILITY, 630 FLUSHING A **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
12 ft.

VCP:

Name:	PFIZER (ORGANICS/SUCIAC BLOCK)
Address:	CENTRAL PORTION OF PFIZER FACILITY, 630 FLUSHING A
City,State,Zip:	BROOKLYN, NY
Program Type:	VCP
Site Code:	58107
HW Code:	V00124
Site Class:	C
SWIS:	2401
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	03/23/2007
Updated By:	dcwalsh

PFIZER (ORGANICS/SUCIAC BLOCK) (Continued) **S104323903**

Site Description:	The "Organics/Suciac Block" site is located in the central portion of the Pfizer Inc. facility in the Williamsburg section of Brooklyn, NY. Gerry Street, Harrison Avenue, Union Avenue and Wallabout Street border this block. The site was first developed for chemical manufacturing between 1854-1888. Operations continued there until 1989 and all buildings were demolished by March of 1995. The Organic/Suciac block is situated within a high-density, mixed urban/commercial/ industrial zone. Pfizer decommissioned the Organic/Suciac block with the intent to utilize it for future redevelopment and/or beneficial use. As part of the decommissioning process, all buildings were demolished. The present concrete slab is continuous throughout the Block and varies in thickness from 0.5 and 1.5 feet. In 1997, waste from the site was excavated and disposed off site, which included 18.12 tons of mercury and lead hazardous soils. Also, a total of 1,930 tons of benzene hazardous soils were excavated and disposed off-site. In 1999/2000, the excavated soil (approximately 420.3 tons) was classified as a petroleum contaminated non-hazardous material, and was transported off-site and disposed. Institutional Controls: On June 22, 2001, Pfizer presented the deed restrictions for recording in the Kings County Registrar s Office. These restrictions state that unless additional response actions are performed at the Site to allow its use for residential purposes, the Site shall be prohibited from being used for purposes other that industrial, commercial and/or recreational purposes without the expressed written permission from the Department.
Env Problem:	In 1997, waste from the site was excavated and disposed off site, which included 18.12 tons of mercury and lead hazardous soils. Also, a total of 1,930 tons of benzene hazardous soils were excavated and disposed off-site. In 1999/2000, the excavated soil (approximately 420.3 tons) was classified as a petroleum contaminated non-hazardous material, and was transported off-site and disposed. Institutional Controls: On June 22, 2001, Pfizer presented the deed restrictions for recording in the Kings County Registrar s Office. These restrictions state that unless additional response actions are performed at the Site to allow its use for residential purposes, the Site shall be prohibited from being used for purposes other that industrial, commercial and/or recreational purposes without the expressed written permission from the Department.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Applicant/Requestor
Sub Type:	ZZZ
Owner Name:	JOHN KEITH,MGR
Owner Company:	Pfizer, Inc.
Owner Address:	235 EAST 42ND ST.
Owner Addr2:	Not reported

PFIZER (ORGANICS/SUCIAC BLOCK) (Continued) **S104323903**

Owner City,St,Zip:	NEW YORK, NY 10017-5755
Owner Country:	United States of America
HW Code:	V00124
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00124
Waste Type:	Both (Petro and Haz)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	D2-0001-97-02(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

P325 **CON EDISON MANHOLE: 200** **RCRA NonGen / NLR** **1016969930**
NNW **LORIMER ST & BROADWAY** **NY MANIFEST** **NYP004436226**
1/8-1/4 **BROOKLYN, NY 11206**
0.163 mi.
859 ft. **Site 9 of 11 in cluster P**

Relative: **Lower**

Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/06/2014
Facility name:	CON EDISON MANHOLE: 200
Facility address:	LORIMER ST & BROADWAY 249 FEET N OF BROOKLYN, NY 11206
EPA ID:	NYP004436226
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

CON EDISON MANHOLE: 200 (Continued) **1016969930**

Used oil transporter: No

Historical Generators:
Date form received by agency: 02/06/2014
Site name: CON EDISON MANHOLE: 200
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: LORIMER ST & BROADWAY
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004436226
Facility Status: Not reported
Location Address 1: EAST SIDE OF LORIMER 250 FT NORTH OF BROADWAY
Code: BP
Location Address 2: MH200
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11211
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004436226
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 02/06/2014
Trans1 Recv Date: 02/06/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/11/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004436226
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002300962GBF

CON EDISON MANHOLE: 200 (Continued) **1016969930**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

P326 **MTA NYCT - LORIMER ST STATION J-LINE** **RCRA NonGen / NLR** **1004761237**
NNW **LORIMER ST & BROADWAY** **NY MANIFEST** **NYR000082131**
1/8-1/4 **BROOKLYN, NY 11206**
0.163 mi.
859 ft. **Site 10 of 11 in cluster P**

Relative: **Lower**

Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT - LORIMER ST STATION J-LINE
Facility address:	LORIMER ST & BROADWAY BROOKLYN, NY 11206
EPA ID:	NYR000082131
Mailing address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact:	WILLIAM JEHLE
Contact address:	BROADWAY 3RD FLOOR NEW YORK, NY 10004
Contact country:	US
Contact telephone:	646-252-3500
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

MTA NYCT - LORIMER ST STATION J-LINE (Continued) **1004761237**

Owner/Operator Summary:

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 3RD FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	646-252-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MTA NEW YORK CITY TRANSIT
Owner/operator address:	2 BROADWAY 3RD FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	646-252-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/01/2006
Site name:	MTA NYCT - LORIMER ST STATION J-LINE
Classification:	Not a generator, verified

Date form received by agency:	05/03/2000
Site name:	MTA NYCT - LORIMER ST STATION J-LINE
Classification:	Large Quantity Generator

Hazardous Waste Summary:

MTA NYCT - LORIMER ST STATION J-LINE (Continued) **1004761237**

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Name: NEW YORK CITY TRANSIT AUTHORITY
Address: LORIMER ST & BROADWAY
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYR000082131
Facility Status: Not reported
Location Address 1: LORIMAR ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000082131
Mailing Name: NEW YORK CITY TRANSIT AUTHORITY
Mailing Contact: KARNATI PAUL
Mailing Address 1: 2 BROADWAY 3RD FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 6462523500

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYR000093831
Trans2 State ID: Not reported
Generator Ship Date: 02/20/2014
Trans1 Recv Date: 02/20/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000082131
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: 006925056FLE
Import Indicator: N
Export Indicator: N

MTA NYCT - LORIMER ST STATION J-LINE (Continued) **1004761237**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

P327 **CON EDISON** **RCRA NonGen / NLR** **1014396188**
NNW **LORIMER ST & BROADWAY** **NJ MANIFEST** **NYP004183687**
1/8-1/4 **BROOKLYN, NY 11206** **NY MANIFEST**
0.163 mi.
859 ft. **Site 11 of 11 in cluster P**

Relative:
Lower

Actual:
13 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	LORIMER ST & BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004183687
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	CAROLINE ISKANDER
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	718-666-4714
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON (Continued) **1014396188**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/14/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004183687
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: CAROLINE ISKANDER
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 000894697GBF
EPA ID: NYP004183687
Date Shipped: 07/21/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 07/21/2009
Date Trans2 Transported Waste: Not reported

CON EDISON (Continued) **1014396188**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/23/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	200 G

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	LORIMER ST & BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004183687
Facility Status:	Not reported
Location Address 1:	LORIMER ST & BROADWAY - MH14480
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11202
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004183687
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **1014396188**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2009
Trans1 Recv Date:	07/21/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004183687
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894697GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **1014396188**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q328 **COOK STREET HOUSING** **NY UST** **U004129097**
ENE **40 VARET STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.166 mi.
874 ft. **Site 5 of 7 in cluster Q**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	COOK STREET HOUSING
Address:	40 VARET STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-610972 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589292.49035
UTM Y:	4506319.62932
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	406762
Affiliation Type:	Mail Contact
Company Name:	COOK STREET HOUSING, LLC
Contact Type:	Not reported
Contact Name:	DEBBIE KENYON
Address1:	316 DOUGLASS ST., 2ND FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(914) 833-3000
EMail:	DKENYON@LMDERPARTNERS.COM
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2009-01-05

Site Id:	406762
Affiliation Type:	Facility Operator
Company Name:	COOK STREET HOUSING
Contact Type:	Not reported
Contact Name:	DEBBIE KENYON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 833-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2009-01-05

Site Id:	406762

COOK STREET HOUSING (Continued) **U004129097**

Affiliation Type:	Emergency Contact
Company Name:	COOK STREET HOUSING, LLC
Contact Type:	Not reported
Contact Name:	DEBBIE KENYON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 833-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2009-01-05

Site Id:	406762
Affiliation Type:	Facility Owner
Company Name:	COOK STREET HOUSING, LLC
Contact Type:	DIR & MEMBER
Contact Name:	RONALD MOELIS
Address1:	316 DOUGLASS STREET, 2ND FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(914) 833-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2009-01-05

Tank Info:

Tank Number:	001
Tank ID:	226172
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	01/29/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	dxliving
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None

COOK STREET HOUSING (Continued) **U004129097**

D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Q329 **CON EDISON - MANHOLE 16055** **RCRA-LQG** **1016677269**
NE **60 MOORE ST** **FINDS** **NYP004308326**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.167 mi. **NY MANIFEST**
884 ft. **Site 6 of 7 in cluster Q**

Relative: **Higher**

Actual: **17 ft.**

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 16055
Facility address:	60 MOORE ST BROOKLYN, NY 11206
EPA ID:	NYP004308326
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

CON EDISON - MANHOLE 16055 (Continued) **1016677269**

Owner/Operator Type: Operator
Owner/Op start date: 05/07/2013
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/07/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/07/2013
Site name: CON EDISON MANHOLE: 16055
Classification: Not a generator, verified

Date form received by agency: 05/07/2013
Site name: CON EDISON MANHOLE: 16055
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110058870663

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

CON EDISON - MANHOLE 16055 (Continued) **1016677269**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677269
Registry ID:	110058870663
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058870663

NY MANIFEST:

Name:	CON EDISON
Address:	60 MOORE ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004308326
Facility Status:	Not reported
Location Address 1:	60 MOORE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004308326
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/2013
Trans1 Recv Date:	05/07/2013
Trans2 Recv Date:	Not reported

CON EDISON - MANHOLE 16055 (Continued) **1016677269**

TSD Site Recv Date:	05/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004308326
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002017502GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R330 **CON EDISON** **NY MANIFEST** **S118088145**
ESE **749 FLUSHING AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.168 mi.
888 ft. **Site 14 of 19 in cluster R**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	749 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004756896
Facility Status:	Not reported
Location Address 1:	749 FLUSHING AVE
Code:	BP

Actual:
23 ft.

CON EDISON (Continued) **S118088145**

Location Address 2:	SB 7432
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004756896
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/24/2015
Trans1 Recv Date:	03/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004756896
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618940GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100

CON EDISON (Continued) **S118088145**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R331 **CON EDISON** **RCRA NonGen / NLR** **1018280783**
ESE **749 FLUSHING AVE** **FINDS** **NYP004756896**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.168 mi.
888 ft. **Site 15 of 19 in cluster R**

Relative:
Higher

Actual:
23 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/24/2015
Facility name:	CON EDISON
Facility address:	749 FLUSHING AVE BROOKLYN, NY 11206
EPA ID:	NYP004756896
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1018280783**

Historical Generators:
Date form received by agency: 03/24/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067682038

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018280783
Registry ID: 110067682038
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067682038

R332 **CON EDISON** **NJ MANIFEST** **S120669506**
ESE **749 FLUSHING AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.168 mi.
888 ft. **Site 16 of 19 in cluster R**

Relative: **Higher**
Actual: **23 ft.**

NJ MANIFEST:
EPA Id: NYP004756896
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002618940GBF
EPA ID: NYP004756896
Date Shipped: 3/24/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047

CON EDISON (Continued) **S120669506**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R333 **CON EDISON** **NY MANIFEST** **S117742012**
ESE **FLUSHING & BROADWAY VAULT 5606** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.168 mi.
888 ft. **Site 17 of 19 in cluster R**

Relative: **Higher**
Actual: **23 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FLUSHING & BROADWAY VAULT 5606
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004752705
Facility Status:	Not reported
Location Address 1:	749 FLUSHING AV
Code:	BP
Location Address 2:	V5606
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201

CON EDISON (Continued) **S117742012**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004752705
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/17/2015
Trans1 Recv Date: 03/17/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/19/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004752705
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014091067JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 2000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S117742012**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

---

334 North 1/8-1/4 0.170 mi. 896 ft. **LINDSAY PARK HOUSING CORP** **NY LTANKS** **S109829698**
54 BOERUM ST **N/A**
BROOKLYN, NY

Relative: Lower
Actual: 13 ft.

LTANKS:

Name:	LINDSAY PARK HOUSING CORP
Address:	54 BOERUM ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0906148 / 2010-10-27
Facility ID:	0906148
Site ID:	418462
Spill Date:	2009-08-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2009-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-08-26
Spill Record Last Update:	2010-10-27
Spiller Name:	JAY SILVERBERG
Spiller Company:	LINDSAY PARK HOUSING CORP
Spiller Address:	54 BOERUM ST
Spiller County:	999
Spiller Contact:	BOB URBAN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	367555
DEC Memo:	"CSL letter pepared by Sangesland and forwarded to Zhune for signature Mr. Jay Silverberg Lindsay Park Housing Corp 202 Union Ave Brooklyn, NY 11211 10/06/09-Hiralkumar Patel. discussed with DEC Austin about multiple spill numbers (0701867, 0905544, 0906148 & 0905433) under Lindsey Park Housing Corp.. as same management and same contractor working at the site, transferred case 0906148 to

LINDSAY PARK HOUSING CORP (Continued) **S109829698**

Patel. 11/10/09-Hiralkumar Patel. 2:15 PM:- visited site. met Tom from Protest and Mr. Silverberg. 550 gal diesel tank removed and excavation was backfilled. contaminated soil found at the site. contamination at this site will be removed, once protest done working with other buildings where major contamination found. will remove clean fill and any contamiantion. 01/22/10-Hiralkumar Patel. 3:22 PM:- spoke with Tom at Protest. asked him to send updates. 04/12/10-Hiralkumar Patel. 3:17 PM:- received email from Tom. he mentioned that removal of contaminated soil has been completed and will submit report soon. 05/11/10-Hiralkumar Patel. 11:11 AM:- received email from Tom with updates. cleanup completed. will submit report. 2:53 PM:- sent letter to Mr. Silberberg requiring endpoint samples. letter emailed to Mr. Silverberg and Tom. 06/25/10-Hiralkumar Patel. 1:15 PM:- office meeting with DEC Urda, DEC Morenzi, DEC Austin, Mr. Silverberg, Tom, Scott Smiw and Chris O'Donnell. during meeting, agreed upon following: - completion of excavation work at 31 Leonard Street - installation of 6 inch monitoring wells around USTs at 67 Manhattan Ave and pump out of product (as an interim measure before excavation starts) - either installation of soil boring (and three monitoring wells based on results of groundwater sample from soil boring) or soil excavation at 24 Boerum Street and 54 Boerum Street - installation of 6 inch monitoring wells around previously abandoned USTs at 30 Montrose avenue Tom will submit revised work plan for 30 Montrose Ave and work plan for wells installation at 67 Manhattan Ave and boring/well installation at 24 and 54 Boerum Street. site visit needed during collection of endpoint samples from north end of excavation at 31 Leonard Street. DEC Urda asked to issue multi-sites STIP. 09/21/10-Hiralkumar Patel. 11:07 AM:- received email from DEC Urda with copy of signed STIP. DEC regional director signed STIP on 09/16/10. as per the CAP of the signed STIP, following documents are due: - a work plan for free phase product removal at 67 Manhattan Ave is due by end of 10/01/10 - an interim spill cleaup report for 31 Leonard Street is due now - tank closure report for buildings 24 Boerum and 54 Boerum street are due on 12/21/10 - a remedial investigation report for groundwater investigation at 30 Montrose is due on 02/28/11 10/27/10-Hiralkumar Patel. 9:46 AM:- received report from Protest. abstract: - a 550 gal diesel tank was removed - final excavation was 25 ft long, 5 ft wide and 13 ft deep - endpoint sidewall samples were collected at 12 ft depth - two endpoint bottom samples were collected at 14 ft depth - no VOC contamination found in any endpoint sample - minor SVOC contamination found in samples based on submitted report, case closed. 1:49 PM:- sent spill closure letter to Mr. Silverberg. letter emailed to Mr. Silverberg (jadius7@aol.com) and Tom. **see also spill #s: 0103137, 0701867, 0905433, 0905544 and 1000673.**"

Remarks: "Removed tank on 8/18/09, no soil or other contamination noted at that time; just received the test results showing oil contamination. 550 gallon in ground diesel tank."

All Materials:

Site ID:	418462
Operable Unit ID:	1174632
Operable Unit:	01
Material ID:	2167005
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported

LINDSAY PARK HOUSING CORP (Continued) **S109829698**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

W335 **CON EDISON** **NY MANIFEST** **S117740680**
SSE **168 THROOP AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.170 mi.
898 ft. **Site 4 of 10 in cluster W**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	168 THROOP AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004738357
Facility Status:	Not reported
Location Address 1:	168 THROOP AV
Code:	BP
Location Address 2:	SB42783
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738357
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2015
Trans1 Recv Date:	02/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738357
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117740680**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610271GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	168 THROOP AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004738571
Facility Status:	Not reported
Location Address 1:	168 THROOP AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738571
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117740680**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2015
Trans1 Recv Date:	02/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738571
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610787GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

W336
SSE
1/8-1/4
0.170 mi.
898 ft.

CON EDISON
168 THROOP AVE
BROOKLYN, NY 11206

Site 5 of 10 in cluster W

NJ MANIFEST **S120667904**
N/A

Relative:
Higher

Actual:
21 ft.

NJ MANIFEST:

EPA Id:	NYP004738571
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610787GBF
EPA ID:	NYP004738571
Date Shipped:	2/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667904**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

W337 **CON EDISON** **RCRA NonGen / NLR** **1018279061**
SSE **168 THROOP AVE** **FINDS** **NYP004738571**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.170 mi.
898 ft. **Site 6 of 10 in cluster W**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/05/2016
Facility name:	CON EDISON
Site name:	CON EDISON - MANHOLE 1036
Facility address:	168 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004738571
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/25/2015
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner

CON EDISON (Continued) **1018279061**

Owner/Op start date: 02/25/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/25/2015
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 02/25/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 3000

Violation Status: No violations found

FINDS:

Registry ID: 110067685400

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1018279061**

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279061
Registry ID:	110067685400
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067685400

W338 **CON EDISON** **NJ MANIFEST** **S120667884**
SSE **168 THROOP AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.170 mi.
898 ft. **Site 7 of 10 in cluster W**

Relative:
Higher

Actual:
21 ft.

NJ MANIFEST:

EPA Id:	NYP004738357
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610271GBF
EPA ID:	NYP004738357
Date Shipped:	2/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON (Continued) **S120667884**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

W339 **CON EDISON** **RCRA NonGen / NLR** **1018279041**
SSE **168 THROOP AVE** **NYP004738357**
1/8-1/4 **BROOKLYN, NY 11206**
0.170 mi.
898 ft. **Site 8 of 10 in cluster W**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/25/2015
Facility name:	CON EDISON
Facility address:	168 THROOP AVE BROOKLYN, NY 11206
EPA ID:	NYP004738357
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON (Continued) **1018279041**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/25/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

X340 **169 LORIMER STREET** **NY VCP** **S121133128**
NW **169 LORIMER STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.172 mi.
909 ft. **Site 1 of 6 in cluster X**

Relative:
Higher

Actual:
14 ft.

VCP NYC:
Project ID: 17CVCP042K
Project Name: 169 LORIMER STREET
Project Address: 169 LORIMER STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 17CVCP042K
File Name: 2017-01-03.RIR_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP042K/2016-10-24.17TMP0056K.RIR Phase II Report.compiled.Additional Sampling_Final.pdf

Project ID: 17CVCP042K
File Name: 2017-01-03.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP042K/2016-12-12.17TMP0056K.RAPRAWP.compiled.v2_EBC.pdf

Project ID: 17CVCP042K
File Name: 2017-01-03.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP042K/2017-01-03.17TMP0056K.Fact Sheet 1 (NYC VCP Application Fact Sheet).OER.pdf

Project ID: 17CVCP042K
File Name: 2017-01-03.Translated_Factsheet-1
URL: http://www.nyc.gov/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP042K/2017-01-03.17TMP0056K.Translations - Fact Sheet 1 & CPS.Translated_FS-1.pdf

Project ID: 17CVCP042K
File Name: 2017-01-03.Translated_CPS
URL: http://www.nyc.gov/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP042K/2017-01-03.17TMP0056K.Translations - Fact Sheet 1 & CPS.CPS.pdf

Y341 **NYC DEPT OF EDUCATION - PS 148K** **RCRA-SQG** **1001028884**
South **185 ELLERY ST** **NY MANIFEST** **NYR000011163**
1/8-1/4 **BROOKLYN, NY 11206**
0.172 mi.
910 ft. **Site 1 of 2 in cluster Y**

Relative:
Higher

Actual:
20 ft.

RCRA-SQG:

Date form received by agency:	10/21/2014
Facility name:	NYC DEPT OF EDUCATION - PS 148K
Facility address:	185 ELLERY ST BROOKLYN, NY 11206
EPA ID:	NYR000011163
Mailing address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact:	ALEXANDER LEMPERT
Contact address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	718-472-8501
Contact email:	ALEMPERT@NYCSCA.ORG
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NYC DEPT OF EDUCATION
Owner/operator address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	718-472-8501
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	02/14/1907
Owner/Op end date:	Not reported

Owner/operator name:	NYC DEPT OF EDUCATION
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	718-472-8501
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	02/14/1907
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

NYC DEPT OF EDUCATION - PS 148K (Continued) **1001028884**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2007
Site name: NYC BD OF ED - PUBLIC SCHOOL 148 BKLYN
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: NYC BD OF ED - PUBLIC SCHOOL 148 BKLYN
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NYC BD OF ED - PUBLIC SCHOOL 148 BKLYN
Classification: Not a generator, verified

Date form received by agency: 08/10/1995
Site name: NYC BD OF ED - PUBLIC SCHOOL 148 BKLYN
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: B004
. Waste name: PCB articles containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs, excluding small capacitors. This includes oil-filled electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

. Waste code: B007
. Waste name: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:

Name: NYC BOARD OF EDUCATION
Address: 185 KELLY ST
City,State,Zip: BROOKLYN, NY 11205
Country: USA
EPA ID: NYR000011163

NYC DEPT OF EDUCATION - PS 148K (Continued) **1001028884**

Facility Status:	Not reported
Location Address 1:	185 KELLEY STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11205
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000011163
Mailing Name:	NYC BOARD OF EDUCATION
Mailing Contact:	JACK BRUCCULERI
Mailing Address 1:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183495660

NY MANIFEST:

Document ID:	NJA2116685
Manifest Status:	K
seq:	Not reported
Year:	1995
Trans1 State ID:	50082
Trans2 State ID:	S6993
Generator Ship Date:	08/12/1995
Trans1 Recv Date:	08/12/1995
Trans2 Recv Date:	10/26/1995
TSD Site Recv Date:	10/27/1995
Part A Recv Date:	/ /
Part B Recv Date:	11/07/1995
Generator EPA ID:	NYR000011163
Trans1 EPA ID:	NY0000551218
Trans2 EPA ID:	NJD980772768
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

NYC DEPT OF EDUCATION - PS 148K (Continued) **1001028884**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00500
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V342 **CON EDISON** **NY MANIFEST** **S117742010**
ESE **FLUSHING AVE & BROADWAY VLT572** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.172 mi.
910 ft. **Site 7 of 12 in cluster V**

Relative:
Higher

Actual:
24 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FLUSHING AVE & BROADWAY VLT572
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004752689
Facility Status:	Not reported
Location Address 1:	751 FLUSHING AV
Code:	BP
Location Address 2:	V5728
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004752689
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/17/2015
Trans1 Recv Date:	03/17/2015
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S117742010**

TSD Site Recv Date:	03/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004752689
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091066JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X343 **165-169 LORIMER STREET** **NY UST** **U004313177**
NW **165-169 LORIMER STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.173 mi.
914 ft. **Site 2 of 6 in cluster X**

Relative: UST:
Higher

Name:	165-169 LORIMER STREET
Address:	165-169 LORIMER STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-613030 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A

Actual:
14 ft.

165-169 LORIMER STREET (Continued) **U004313177**

UTM X: Not reported
UTM Y: Not reported
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 588395
Affiliation Type: Facility Owner
Company Name: LORIMER HOMES LLC
Contact Type: NOT LISTED
Contact Name: LEOPOLD WEINSTOCK
Address1: 199 LEE AVENUE, SUITE 376
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 522-7305
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-05-13

Site Id: 588395
Affiliation Type: Mail Contact
Company Name: LEOPOLD WEINSTOCK
Contact Type: Not reported
Contact Name: GREEN PARK MANAGEMENT
Address1: 65 LYNCH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11206
Country Code: 001
Phone: (347) 756-1188
EMail: LEOW450@GMAIL.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-05-13

Site Id: 588395
Affiliation Type: Facility Operator
Company Name: 165-169 LORIMER STREET
Contact Type: Not reported
Contact Name: LEOPOLD WEINSTOCK, GREENPARK MGMT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 756-1188
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-05-13

Site Id: 588395
Affiliation Type: Emergency Contact

165-169 LORIMER STREET (Continued) **U004313177**

Company Name:	LORIMER HOMES LLC
Contact Type:	Not reported
Contact Name:	LEOPOLD WEINSTOCK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 756-1188
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-05-13

Tank Info:

Tank Number:	01
Tank ID:	280573
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	03/18/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	06/05/2019

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Number:	02
Tank ID:	280574
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	03/18/2019
Registered:	True

165-169 LORIMER STREET (Continued) **U004313177**

Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: ACDANIEL
Last Modified: 06/05/2019

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Number: 03
Tank ID: 280575
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 03/18/2019
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: ACDANIEL
Last Modified: 06/05/2019

Equipment Records:

G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None

Tank Number: 04
Tank ID: 280576

165-169 LORIMER STREET (Continued) **U004313177**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	03/18/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	06/05/2019

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Number:	05
Tank ID:	280577
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	300
Install Date:	Not reported
Date Tank Closed:	03/18/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	06/05/2019

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

165-169 LORIMER STREET (Continued) **U004313177**

J00 - Dispenser - None
G00 - Tank Secondary Containment - None

U344 **CON EDISON SERVICE BOX: 15152** **RCRA NonGen / NLR** **1016454122**
NE **50 MANHATTAN AVE** **FINDS** **NYP004310744**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.173 mi. **NY MANIFEST**
914 ft. **Site 3 of 5 in cluster U**

Relative: Higher

Actual: 15 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/10/2013
Facility name:	CON EDISON SERVICE BOX: 15152
Facility address:	50 MANHATTAN AVE BROOKLYN, NY 11206
EPA ID:	NYP004310744
Mailing address:	VING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/10/2013
Site name:	CON EDISON SERVICE BOX: 15152
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110056509158

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

CON EDISON SERVICE BOX: 15152 (Continued) **1016454122**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016454122
Registry ID:	110056509158
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056509158

NY MANIFEST:

Name:	CON EDISON
Address:	50 MANHATTAN AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004310744
Facility Status:	Not reported
Location Address 1:	50 MANHATTAN
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004310744
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/2013
Trans1 Recv Date:	05/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2013
Part A Recv Date:	Not reported

CON EDISON SERVICE BOX: 15152 (Continued) **1016454122**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004310744
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002017921GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R345 **CON EDISON - MANHOLE M1032** **RCRA-LQG** **1024891286**
East **13 GRAHAM AVE** **NYP005093158**
1/8-1/4 **BROOKLYN, NY 11206**
0.174 mi.
917 ft. **Site 18 of 19 in cluster R**

Relative: RCRA-LQG:
Higher

Date form received by agency:	04/10/2018
Facility name:	CON EDISON - MANHOLE M1032
Facility address:	13 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP005093158
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	ALYSSA SOTTO
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003

Actual:
22 ft.

CON EDISON - MANHOLE M1032 (Continued) **1024891286**

Contact country: US
Contact telephone: 212-460-2757
Contact email: SOTTOA@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-460-2757
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 06/07/2017
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: 212-460-2757
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/07/2017
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

CON EDISON - MANHOLE M1032 (Continued) **1024891286**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

R346 **CON EDISON - MANHOLE M1032** **NY MANIFEST** **S121968207**
East **13 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.174 mi.
917 ft. **Site 19 of 19 in cluster R**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:
Name: CON EDISON - MANHOLE M1032
Address: 13 GRAHAM AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP005093158
Facility Status: Not reported
Location Address 1: 13 GRAHAM AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005093158
Mailing Name: CON EDISON - MANHOLE M1032
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

S347 **70 UNION AVENUE** **NY UST** **U004078635**
West **70 UNION AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.177 mi.
937 ft. **Site 3 of 5 in cluster S**

Relative:
Higher

Actual:
14 ft.

UST:

Name:	70 UNION AVENUE
Address:	70 UNION AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-610501 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588687.84510
UTM Y:	4506191.98659
Site Type:	Other

Affiliation Records:

Site Id:	377704
Affiliation Type:	Facility Owner
Company Name:	MR. CHESKEL SCHWIMMER
Contact Type:	MEMBER
Contact Name:	CHESKEL SCHWIMMER
Address1:	BROOKLYN NAVY YARD, BLDG. 664
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11205
Country Code:	001
Phone:	(718) 522-5512
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-26

Site Id:	377704
Affiliation Type:	Mail Contact
Company Name:	HYDROTECH ENVIRONMENTAL CORP.
Contact Type:	Not reported
Contact Name:	YASH SAHA
Address1:	1111 FULTON STREET
Address2:	2ND FLOOR
City:	BROOKLYN
State:	NY
Zip Code:	11238
Country Code:	001
Phone:	(718) 636-0800
EMail:	YSAHA@HYDROTECHENVIRONMENTAL.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-26

Site Id:	377704
Affiliation Type:	Facility Operator
Company Name:	70 UNION AVENUE
Contact Type:	Not reported
Contact Name:	MR. AVI
Address1:	Not reported

70 UNION AVENUE (Continued) **U004078635**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 577-5045
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-26

Site Id:	377704
Affiliation Type:	Emergency Contact
Company Name:	MR. CHESKEL SCHWIMMER
Contact Type:	Not reported
Contact Name:	MR. AVI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 377-5045
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-02-26

Tank Info:

Tank Number:	001
Tank ID:	216093
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1958
Date Tank Closed:	02/12/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	dxliving
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None

70 UNION AVENUE (Continued) **U004078635**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Number: 002
Tank ID: 216094
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1958
Date Tank Closed: 02/12/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: dxliving
Last Modified: 04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 216095
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1958
Date Tank Closed: 02/12/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

70 UNION AVENUE (Continued) **U004078635**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: dxliving
Last Modified: 04/14/2017

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Number: 004
Tank ID: 216096
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1958
Date Tank Closed: 02/12/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: dxliving
Last Modified: 04/14/2017

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 005
Tank ID: 216097
Tank Status: Closed - Removed

70 UNION AVENUE (Continued) **U004078635**

Material Name:	Closed - Removed
Capacity Gallons:	1080
Install Date:	01/01/1958
Date Tank Closed:	02/12/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	dxliving
Last Modified:	04/14/2017

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Number:	006
Tank ID:	220141
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	06/15/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	dxliving
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

70 UNION AVENUE (Continued) **U004078635**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None

S348 **HYDRO TECH** **NY Spills** **S104193417**
West **70 UNION AVENUE** **NY MANIFEST** **N/A**
1/8-1/4 **BROOK LYN, NY 10001**
0.177 mi.
937 ft. **Site 4 of 5 in cluster S**

Relative: **Higher**
Actual: **14 ft.**

SPILLS:

Name:	VACANT PROPERTY
Address:	70 UNION AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0702983 / 2011-05-25
Facility ID:	0702983
Facility Type:	ER
DER Facility ID:	247445
Site ID:	382817
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-06-12
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2007-06-12
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-06-12
Spill Record Last Update:	2011-05-25
Spiller Name:	CHESKL SCHWIMMER
Spiller Company:	VACANT PROPERTY
Spiller Address:	70 UNION AVE
Spiller Company:	001
Contact Name:	CHESKL SCHWIMMER
DEC Memo:	"A new spill was called in for this site where a new abandoned UST was found. This site is already being managed by Sangesland. This tank was removed during summer 2007. A tank closure report was submitted to DEC in Sept 2007. All documents associated to this site are in eDocs of Spill #9930010."
Remarks:	"WHILE DIGGING CAME UPON A 275 GALLON TANK AND CONTAMINATED SOIL"

All Materials:

Site ID:	382817
Operable Unit ID:	1140199

HYDRO TECH (Continued) **S104193417**

Operable Unit:	01
Material ID:	2130257
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CARBOYS AUTO SALVAGE
Address:	70 UNION AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9930010 / 2019-02-04
Facility ID:	9930010
Facility Type:	ER
DER Facility ID:	247445
Site ID:	306367
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	2401
Spill Date:	1999-07-28
Investigator:	RJWHITCH
Referred To:	Not reported
Reported to Dept:	1999-07-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-28
Spill Record Last Update:	2019-02-04
Spiller Name:	Not reported
Spiller Company:	CARBOYS AUTO SALVAGE
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	MR. ALALIEWIE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sangesland gave written notice directly to Mr. Alaliewie (owner of site) to do the following work within 30 days of 7/28/99: 1)Surface removal down to pavement or top 2 feet of soil in contaminated work area. (owner says site is paved under gravel) 2)A subsurface investigation via geoprobes of the yard area 3)Installation of asphalt or other solid surface in work area 4)Prepare a report outlining proposed method of site remediation. A list of contractors was provided to the owner. It was explained to him that he can hire one of these, or someone of his own choice. 9/26/2000 Mr. Jules Kimel (718-996-3260) called requesting closure of this spill number because he wants to sell the lot to build an

HYDRO TECH (Continued) **S104193417**

Edwards supermarket/mall. Mr. Kimel said he was the owner along with Mr. Cici and that Mr. Sam Alaliewie was just a tenent on the site. Mr. Kimel was told that a site investigation & cleanup would be required before the spill number would be closed out. Jules Kimel 27 85 West 5th St #7A Brooklyn 11224 Frank Cici 69-26 53rd Rd maspeth 11378 9/26/2000 Mr. Sammy Alaliewie called back to say the site was cleaned last year and NYC did 8 soil borings when they were planning on buying the site to build housing. Sangesland told Sammy to track down a copy of the environmental report related to the 8 soil borings and submit it to the DEC. If the report shows the subsurface is clean then the DEC will consider closing the site out. 9/28/2000 Real Estate Broker - John Fischer 718-677-5700 was told of the situation and what needs to be done. 4/3/2006 Sangesland sent a Notice of Violation letter to: Willboro Properties Ltd. c/o Klein & Solomon, 275 Madison Ave - 11th Flr, NYC 10016 Letter gives a June 15,2006 deadline to provide DEC with results of soil boring work on the site to prove the site has been cleaned up adequately. 4/6/2006 Sangesland received a voice message from someone named Mr. Schwimer at 718-522-5512. He did not identify how he was related to the site nor did he say what he was lookin for. Sangesland returned the call and left a voice message at a machine which once again did NOT identify who they were. 4/13/2006 Sangesland called Mr. John Fischer (Real Estate Broker) he said that he was NOT involved in the final transaction. He knows nothing about the current owners or what they may or may not have done on the site. 4/25/2006 Dave Glass (212-221-8303) has been hired by the property owner to remediate the site. 6/21/2006 Sangesland received a Proposed Work Plan prepared by David Glass at TRC environmental (212-221-7822). The report was inadequate to what was requested in the April 3, 2006 letter. When Sangesland asked Mr. Glass if he was the legal representitive of the owner for this site, Mr. Glass specifically said he was NOT. When Sangesland asked for the name and contact information for the owner of the property, Mr. Glass said that he did not know . 6/22/2006 Sangesland spoke with Mr. Ed Klein at Klein & Solomon (law firm listed on NYC Tax records as legal address for Willboro Properties LLC). Mr. Klein said he heard of Willboro Properties, but didn't know the details. He said he would look into it and get back to the DEC with the proper contacts for the property owner. 6/22/2006 Mr. Glass from TRC called Sangesland again asking why DEC needed to know who the property owner was. Sangesland said that the DEC can/will only deal with the property owner or his designated representitive . Sangesland stated that the report submitted by Mr. Glass was inadequate and that the DEC would like to prepare a Stipulation Agreement to be reviewed and signed by the property owner. This agreement will lay out the specific work required along with establishing a schedule for when the work will be done. Mr. Glass stated that the owners do not want to be identified, they do not want a stipulation agreement and they do not want a schedule of when the work must be done on the site. 7/11/2006 Sangesland and John Urda (DEC Legal Dept) spoke with Mr. Solomon at Klein & Solomon again asking for property owner name/contacts. Mr. Solomon said he would look into it . 7/12/2006 Mr. Solomon called Sangesland to say that his firm no longer represents the owner and he has no additional information on the property. Sangesland responded that the April 3, 2006 letter to Klein & Solomon apparently made it through to the owner. So obviously someone at their law firm knows how to get in touch with the owner. 7/13/2006 Sangesland submitted a Case

HYDRO TECH (Continued) **S104193417**

Initiation Form to John Urda (DEC Legal) for this site. DEC spills would like to find the name/contact of the property owner and to get them to sign a Stipulation Agreement or an Order on Consent. 3/20/2007 Soil and groundwater sampling work was done in Dec 2006 by Hydrotech Environmental Corp. (631-462-5866). The initial report was found to have some problems with the well depth and screening of the wells, so another round of samples were requested. This second round of groundwater samples were taken on Feb 12, 2007. The results show a problem with high levels of cis-1,2-Dichloroethene = 2,060 ug/L in the area of MW-1 in the North edge of the property associated with the former tank farm of the former gas station. This compound is normally associated with a breakdown of PERC which is normally associated with dry cleaners or sometimes used as a parts washer in automotive service stations. Sangesland reviewed the report (see e-docs) and sent the following response via e-mail to Mr. Saha at Hydrotech Environmental:
****

****** e-mail to Mr. Saha dated 3/20/07: Yash Saha, The NYSDEC has reviewed your Technical Submital dated March 7, 2007 for the subject site, and we have the following questions/requirements for the site. The primary area of concern is around MW-1. 1) Please provide a detailed scaled layout of this portion of the property, showing the locations of the: a) Former tank field (current drawings show this location different from the old Sanborn maps, where are the site photos taken during excavation?) b) remote fill pipes c) pump islands d) location of MW-1 in relation to the old station structures. 2) A hit of cis-1,2-Dichloroethene = 2,060 ug/L will need to be further delineated and remediated in some fashion. Where is the source? (is it from offsite from the East side of Harrison Ave?, from the prior gas station on this corner?) This material is normally believed to be a breakdown of PERC from either a dry cleaner or a parts washer from a service station. If it was from the former gas station, is there a former drywell hot spot on the property that was used as a drain? How long ago was the station closed? Where is the groundwater flow moving the contamination? What are the receptors? If Hydrotech will be arguing that there is no offsite impact, then a groundwater sample from offsite will be required (DEC may request to be present for this sample) 3) There is a serious concern that there are high levels of VOC's in the groundwater at a depth of 6 ft below grade in an area where a new building is being built. The DEC will need information on the type of building going up on the site (residential or industrial). Also, will the building have a basement? In addition, depending upon the degree of remediation involved, some form of mechanical barrier will probably need to be installed under the slab floor of the new building to prevent vapor intrusion into the new structure. 4) Has this building site been processed through the NYC E-designation program? If so, what is the case number? If not, then the site is assumed to be remaining as industrial in nature? Please get back to me with answers to these questions. Thank you, Steven Sangesland Environmental Engineer 1 NYSDEC - Spills Remediation Group
****

********** 12/26/07-Hiralkumar Patel. received call from Ms. Saha (718-636-0800). she wants meeting with DEC project manager. 12/4/2008 - Sangesland received a quarterly sampling status report for a single MW on the south corner of the site (corner Walton & Union St). These samples from June & Oct 2008 appear clean or minor. 1/14/2009 - Sangesland spoke to Yasha at HydroTech Environmental. Requested copy

HYDRO TECH (Continued) **S104193417**

of building drawings (HydroTech says building is now complete) showing a vapor barrier under the basement slab. Also copies of all environmental reports from the last few years and a meeting here at DEC to review site status. 5/6/2010 - Sangesland spoke again with Yasha at HydroTech. She submitted a Vapor Barrier System Design Specification for a building THAT HAS NOT YET BEEN BUILT????? Sangesland told her that the spill case will be closed out after Sangesland visits the site and actually sees the vapor barrier installed in the foundation. Only comment on the HydroTech report (Feb 26, 2010) is to change from 30 mil barrier to 40 mil barrier. Notification was sent to HydroTech. 5/24/2011 - Sangesland sent a letter to the owner stating that no additional water samples will be needed from MW#1. Also, once the 40Mil vapor barrier has been laid down, the NYSDEC will close out the spill case. 7/5/2011 - Sangesland received a copy of a Vapor Barrier Specification/Drawings (signed by a PE) and dated June 3, 2011 (see eDocs). The document is acceptible to NYSDEC. Sangesland requested to witness the barrier installation and Field Testing/Vacuum Test as per the specification (Section 1.13.C.1.a) After the installation is complete and a PE has signed off that the installation was completed as per the specification , then the spill cases will be closed out. 8/21/2013 - Sangesland still has NOT received the vapor barrier installation is complete statement from a PE. as per 7/5/2011 request above. In addition on 8/2/2013 sangesland sent the following e-mail requesting a summary of all work done on the site INCLUDING the Perc TCE issues:
********** To: Ezgi Karayel Ezgi, Back in March 2007 I responded to a Feb 2007 submittal from Hydrotech with a specific question. Please take a look at that request and incorporate an answer into your summary report: From March 2007 e-mail to Yash: 2) A hit of cis-1,2-Dichloroethene = 2,060 ug/L will need to be further delineated and remediated in some fashion. Where is the source? (is it from offsite from the East side of Harrison Ave?, from the prior gas station on this corner?) This material is normally believed to be a breakdown of PERC from either a dry cleaner or a parts washer from a service station. If it was from the former gas station, is there a former drywell hot spot on the property that was used as a drain? (Steve believes this is true) How long ago was the station closed? Where is the groundwater flow moving the contamination? What are the receptors? If Hydrotech will be arguing that there is no offsite impact, then a groundwater sample from offsite will be required (DEC may request to be present for this sample) Please update your report and resubmit. Thanks, Steve Sangesland
****
11/5/2013 - as per J. Vought, spill is assigned to J. Feng. 2/14/2014 - email case review comments to HydroTech. Spill closure is denied. More information and clarification are required. 3/30/2016 Feng This spill is transferred from J. Feng to V. Brevdo as per J. Vought. 2/2/18 - Spill transferred to Central Office spills. 02/04/19 - Spill closed not meeting standards. Central office staff made a site visit on 03/01/18 and discovered the parcel has been developed with a new building. The building has been outfitted with a vapor barrier (per NYC building code) and an SSDS to address any residual CIS 1,2 DCE vapors. - RJW"

Remarks: "SITE IS A JUNK YARD WITH WIDESPREAD OIL CONTAMINATION AROUND THE YARD. CARS ARE LEFT DRAINING DIRECTLY INTO THE SOIL AND CAR ENGINES ARE LEFT TO DRAIN/LEAK ON THE GROUND. INVESTIGATION IS A RESULT OF A

HYDRO TECH (Continued) **S104193417**

DEC-ENCON/NYPD SWEEP. OTHER LEGAL ACTIONS HAVE BEEN TAKEN BY NYPD AND ENCON."

All Materials:

Site ID:	306367
Operable Unit ID:	1089894
Operable Unit:	01
Material ID:	293693
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	HYDRO TECH
Address:	70 UNION AVENUE
City,State,Zip:	BROOK LYN, NY 10001
Country:	USA
EPA ID:	NYR000146126
Facility Status:	Not reported
Location Address 1:	70 UNION AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOK LYN
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000146126
Mailing Name:	HYDRO TECH
Mailing Contact:	CAS DEVELOPERS LLC
Mailing Address 1:	1111 FULTON ST
Mailing Address 2:	2ND FLOOR
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11238
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6314335048

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2007
Trans1 Recv Date:	07/31/2007
Trans2 Recv Date:	Not reported

HYDRO TECH (Continued) **S104193417**

TSD Site Recv Date:	07/31/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000146126
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	003121716JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	58280
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

S349 **CAS DEVELOPERS LLC** **RCRA-VSQG** **1010329016**
West **70 UNION AVE** **NJ MANIFEST** **NYR000146126**
1/8-1/4 **BROOKLYN, NY 10001**
0.177 mi.
937 ft. **Site 5 of 5 in cluster S**

Relative:
Higher

Actual:
14 ft.

RCRA-VSQG:

Date form received by agency:	12/21/2012
Facility name:	CAS DEVELOPERS LLC
Facility address:	70 UNION AVE BROOKLYN, NY 10001
EPA ID:	NYR000146126
Mailing address:	BROOKLYN NAVY YARD BLDG 664 BROOKLYN, NY 10001

CAS DEVELOPERS LLC (Continued) **1010329016**

Contact: CHESKEL SCHWIMMER
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 718-522-5512
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: CHESKEL SCHWIMMER
Owner/operator address: BROOKLYN NAVY YARD, BLDG 664
BROOKLYN, NY 10001
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/01/2006
Owner/Op end date: Not reported

Owner/operator name: CHESICEL SCHWIMMER
Owner/operator address: BROOKLYN NAVY YARD BLDG 664
BROOKLYN, NY 10001
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/01/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No

CAS DEVELOPERS LLC (Continued) **1010329016**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/16/2008
Site name: CAS DEVELOPERS LLC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/13/2007
Site name: WILLBORO PROPERTIES LLC
Classification: Large Quantity Generator

Date form received by agency: 04/12/2007
Site name: WILLBORO PROPERTIES LLC
Classification: Large Quantity Generator

Date form received by agency: 04/12/2007
Site name: WILLBORO PROPERTIES LLC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/04/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

NJ MANIFEST:
EPA Id: NYR000146126
Mail Address: BROOKLYN NAVY YARD
Mail City/State/Zip: BROOKLYN, NY 10001
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: CHESKEL SCHWIMMER
Comments: Not reported
SIC Code: Not reported
County: NY047

CAS DEVELOPERS LLC (Continued) **1010329016**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003121714JJK
EPA ID:	NYR000146126
Date Shipped:	07/30/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/30/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	66700 P

Manifest Number:	003121719JJK

CAS DEVELOPERS LLC (Continued) **1010329016**

EPA ID:	NYR000146126
Date Shipped:	07/31/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/31/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/31/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	59160 P

Manifest Number:	003121767JJK
EPA ID:	NYR000146126
Date Shipped:	07/31/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CAS DEVELOPERS LLC (Continued) **1010329016**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/31/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/31/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	61260 P

Manifest Number:	003121679JJK
EPA ID:	NYR000146126
Date Shipped:	07/30/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/30/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

CAS DEVELOPERS LLC (Continued) **1010329016**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	61620 P

Manifest Number:	003121718JJK
EPA ID:	NYR000146126
Date Shipped:	07/31/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/31/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/31/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CAS DEVELOPERS LLC (Continued) **1010329016**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	56020 P

Manifest Number:	003121712JJK
EPA ID:	NYR000146126
Date Shipped:	07/03/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/03/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

CAS DEVELOPERS LLC (Continued) **1010329016**

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H11
Quantity: 62680 P

Manifest Number: 003121716JJK
EPA ID: NYR000146126
Date Shipped: 07/31/2007
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000029967
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 07/31/2007
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 07/31/2007
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: BROOKLYN, NY 10001
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H11
Quantity: 58280 P

Manifest Number: 003121715JJK
EPA ID: NYR000146126

CAS DEVELOPERS LLC (Continued) **1010329016**

Date Shipped:	07/30/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/30/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	64400 P

Manifest Number:	003121721JJK
EPA ID:	NYR000146126
Date Shipped:	07/30/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

CAS DEVELOPERS LLC (Continued) **1010329016**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/30/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	58500 P

Manifest Number:	003121713JJK
EPA ID:	NYR000146126
Date Shipped:	07/30/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/30/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CAS DEVELOPERS LLC (Continued) **1010329016**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	65620 P

Manifest Number:	003121720JJK
EPA ID:	NYR000146126
Date Shipped:	07/31/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/31/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/31/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

CAS DEVELOPERS LLC (Continued) **1010329016**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	60040 P

Manifest Number:	003121717JJK
EPA ID:	NYR000146126
Date Shipped:	07/30/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/30/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/31/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 10001
Reason Load Was Rejected:	Not reported

Waste:

CAS DEVELOPERS LLC (Continued) **1010329016**

Manifest Year: Not reported
Waste Code: D008
Hand Code: H11
Quantity: 60220 P

X350 **153 LORIMER STREET** **NY VCP** **S118943424**
WNW **153 LORIMER STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.178 mi.
940 ft. **Site 3 of 6 in cluster X**

Relative:
Higher

Actual:
15 ft.

VCP NYC:
Project ID: 15CVCP031K
Project Name: 153 LORIMER STREET
Project Address: 153 LORIMER STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP031K
File Name: 2013-10-15.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-15.14CVCP184K.149-153_Lorimer_Street.RIR.pdf

Project ID: 15CVCP031K
File Name: 2013-10-11.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-11.14CVCP184K.149-153_Lorimer_Street.FactSheet-1.pdf

Project ID: 15CVCP031K
File Name: 2013-10-11.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-11.14CVCP184K.149-153_Lorimer_Street.Translated_Factsheet1.pdf

Project ID: 15CVCP031K
File Name: 2013-10-11.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-11.14CVCP184K.149-153_Lorimer_Street.Translated_Community_Protection_Statement.pdf

Project ID: 15CVCP031K
File Name: 2014-10-07.FactSheet-1_Updated
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP031K/2014-10-07.15CVCP031K.doc.FactSheet-1_153-Lorimer_Street_Updated.pdf

Project ID: 15CVCP031K
File Name: 2014-10-30.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP031K/2014-10-16.15CVCP031K.report.RAWP.EBC.pdf

Project ID: 15CVCP031K
File Name: 2014-12-17.Stipulation_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP031K/2014-12-17.15CVCP031K.report.Revised_Stip_Letter.pdf

153 LORIMER STREET (Continued) **S118943424**

Project ID:	15CVCP031K
File Name:	2014-12-22.Decision_Document
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP031K/2014-12-22.15CVCP031K.doc.Decision_Document.OER.pdf
Project ID:	15CVCP031K
File Name:	2015-09-18.FactSheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP031K/2015-09-18.15CVCP031K.doc.Factsheet-2.SHolberton.pdf
Project ID:	15CVCP031K
File Name:	2015-09-18.Translated_FactSheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP031K/2015-09-18.15CVCP031K.doc.Translated_Factsheet-2.pdf

---

Z351 **CON EDISON** **NY MANIFEST** **S117319481**
ENE **43 COOK ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.178 mi.
942 ft. **Site 1 of 14 in cluster Z**

Relative: **Higher**

Actual: **19 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	43 COOK ST
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP004672929
Facility Status:	Not reported
Location Address 1:	43 COOK ST
Code:	BP
Location Address 2:	STRUCTURE # 9130
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004672929
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported

CON EDISON (Continued) **S117319481**

Generator Ship Date:	10/06/2014
Trans1 Recv Date:	10/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004672929
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617543GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z352 **CON EDISON** **NY MANIFEST** **S117314070**
ENE **43 COOK ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.178 mi.
942 ft. **Site 2 of 14 in cluster Z**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	43 COOK ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004696080

Actual:
19 ft.

CON EDISON (Continued) **S117314070**

Facility Status:	Not reported
Location Address 1:	43 COOK ST
Code:	BP
Location Address 2:	SB9130
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004696080
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/17/2014
Trans1 Recv Date:	11/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004696080
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417049GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117314070**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	43 COOK ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004611026
Facility Status:	Not reported
Location Address 1:	43 COOK ST
Code:	BP
Location Address 2:	STRUCTURE 9130
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004611026
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/29/2014
Trans1 Recv Date:	07/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON (Continued) **S117314070**

Generator EPA ID:	NYP004611026
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615439GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X353 **151 LORIMER STREET** **NY VCP** **S118943323**
WNW **151 LORIMER STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.179 mi.
947 ft. **Site 4 of 6 in cluster X**

Relative:
Higher

Actual:
15 ft.

VCP NYC:

Project ID:	14CVCP184K
Project Name:	151 LORIMER STREET
Project Address:	151 LORIMER STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	14CVCP184K
File Name:	2013-10-15.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-15.14CVCP184K.149-153_Lorimer_Street.RIR.pdf

151 LORIMER STREET (Continued) **S118943323**

Project ID: 14CVCP184K
File Name: 2013-10-11.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-11.14CVCP184K.149-153_Lorimer_Street.FactSheet-1.pdf

Project ID: 14CVCP184K
File Name: 2013-10-11.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-11.14CVCP184K.149-153_Lorimer_Street.Translated_Factsheet1.pdf

Project ID: 14CVCP184K
File Name: 2013-10-11.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-10-11.14CVCP184K.149-153_Lorimer_Street.Translated_Community_Protection_Statement.pdf

Project ID: 14CVCP184K
File Name: 2014-08-20.FactSheet-1_Updated
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2013-08-21.14CVCP184K.doc.FactSheet-1_151-Lorimer_Street_Updated.pdf

Project ID: 14CVCP184K
File Name: 2014-09-15.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2014-09-15.14CVCP184K.report.RAWP_Draft.pdf

Project ID: 14CVCP184K
File Name: 2014-12-16.Stipulation_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2015-07-16.14CVCP184K.report.Stipulation_List_Revised.pdf

Project ID: 14CVCP184K
File Name: 2014-09-17.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2014-09-17.14CVCP184K.doc.Decision_Document.OER.pdf

Project ID: 14CVCP184K
File Name: 2014-11-14.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2014-11-13.14CVCP184K.Factsheet-2.pdf

Project ID: 14CVCP184K
File Name: 2014-11-14.Translated_FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2014-11-13.14CVCP184K.Factsheet-2.pdf

Project ID: 14CVCP184K
File Name: 2017-02-24.RAR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2017-02-24.14CVCP184K.report.RAR_v2_Complete.pdf

Project ID: 14CVCP184K
File Name: 2017-03-28.Notice_Of_Completion
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2017-03-28.14EH-A132K.notice.Notice_Of_Completion_OER.pdf

151 LORIMER STREET (Continued) **S118943323**

Project ID: 14CVCP184K
File Name: 2017-03-20.FactSheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2017-03-20.14CVCP184K.doc.151-Lorimer.FactSheet-3.pdf

Project ID: 14CVCP184K
File Name: 2017-03-20.Translated_FactSheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP184K/2017-03-20.14CVCP184K.Translated_FactSheet-3.pdf

---

V354 **CON EDISON** **NY MANIFEST** **S117067055**
ESE **755 FLUSHING** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.180 mi.
950 ft. **Site 8 of 12 in cluster V**

Relative: Higher
Actual: 24 ft.

NY MANIFEST:
Name: CON EDISON
Address: 755 FLUSHING
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004597811
Facility Status: Not reported
Location Address 1: 755 FLUSHING
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004597811
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 07/16/2014
Trans1 Recv Date: 07/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/16/2014
Part A Recv Date: Not reported

CON EDISON (Continued) **S117067055**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004597811
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013256038JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z355 **35 GRAHM AVE.** **NY LTANKS** **S102672170**
ENE **35 GRAHM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.180 mi.
952 ft. **Site 3 of 14 in cluster Z**

Relative: **Higher**
Actual: **19 ft.**

LTANKS:

Name:	35 GRAHM AVE.
Address:	35 GRAHM AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9302281 / 1993-05-19
Facility ID:	9302281
Site ID:	68726
Spill Date:	1993-05-19
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	D4

35 GRAHM AVE. (Continued) **S102672170**

Cleanup Ceased:	1993-05-19
SWIS:	2401
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-05-20
Spill Record Last Update:	1993-07-19
Spiller Name:	Not reported
Spiller Company:	COASTAL OIL
Spiller Address:	31-70 COLLEGE PT. BLVD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	65422
DEC Memo:	""
Remarks:	"SPILL WENT ON SIDEWALK. CUSTOMER ORDERED TOO MUCH OIL - DRIVER OVERFILLED - NOTIFIED DEP - DRIVER CONTAINED AND PUT DOWN SD - COASTAL SENDING CLEANUP MAN."

All Materials:

Site ID:	68726
Operable Unit ID:	980720
Operable Unit:	01
Material ID:	556994
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

T356 **FORMER PFIZER SITE A** **NY BROWNFIELDS** **S123159099**
WSW **243-271 WALLABOUT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.181 mi.
955 ft. **Site 4 of 4 in cluster T**

Relative: BROWNFIELDS:
Lower

Name:	FORMER PFIZER SITE A
Address:	243-271 WALLABOUT STREET
City,State,Zip:	BROOKLYN, NY 11206
Program:	BCP
Site Code:	576972
Acres:	1.64
HW Code:	C224284

Actual:
13 ft.

FORMER PFIZER SITE A (Continued) **S123159099**

SWIS:	2401
Town:	New York City
Record Added Date:	09/10/2018
Record Updated Date:	10/19/2018
Update By:	LSZINOMA
Site Description:	Location The Site to be remediated and redeveloped is located in the Brooklyn Triangle section of Kings County and is comprised of four tax parcels totaling 71,305 square feet (1.63 acres). The Site is located in the City of New York and Borough of Brooklyn. The irregular shaped Site occupies a full block with has approximately 450 ft of frontage along Wallabout Street, 200 feet of frontage on Harrison Avenue, 260 feet of frontage on Union Avenue and 275 feet of frontage on Walton Street. Site Features The Site is currently owned by Harrison Realty LLC. There are no structures presently on the Site. All of the lots are currently used for the storage of trucks and construction equipment. The property is surrounded by an 8 ft high chain-link fence with two gates each on Wallabout Street and Harrison Street, and one gate on Walton Street. Current Zoning and Land Use The western portion of the Site is zoned R8A while the central portion is zoned R7D and the eastern portion is zoned R7A. Surrounding land use includes residential apartment buildings to the west, residential apartment buildings and a public school (IS 318) to the north, commercial (warehouses), residential buildings and a private school (Bais Ruchel High School) to the east and the former Pfizer Site C and a charter school (Beginning with Children) to the south. The closest school (Bais Ruchel High School) is located 120 feet to the east. PS 318 is located 150 feet to the north and the Charter School is located 325 feet to the south. Past Use of the Site The historic use of the Site includes taxi-fleet maintenance garages, a lumberyard and as a storage facility for Pfizer Inc. Site Geography and Geology Subsurface soils at the Site consist of historic fill materials to a depth of approximately 7 to 10 feet below the surface followed by silty-clay and fine sand. According to the USGS topographic map for the area (Central Park Quadrangle), the elevation of the property is approximately 16 feet above the National Geodetic Vertical Datum (NGVD). The area topography is generally flat with little relief and no significant elevation changes. Groundwater occurs beneath the Site at a depth of approximately 6-10 feet below grade under perched water table conditions. Based on previous studies performed at the Site, groundwater flow is generally to the east. No portion of the Site is located within a designated flood zone area.
Env Problem:	Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported

FORMER PFIZER SITE A (Continued) **S123159099**

Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	P02
Owner Name:	Charles Krieger
Owner Company:	Harrison Realty LLC
Owner Address:	505 Flushing Avenue, No. 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P02
Owner Name:	Charles Krieger
Owner Company:	Harrison Realty LLC
Owner Address:	505 Flushing Avenue, No. 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bushwick Branch
Owner Address:	340 Bushwick Avenue at Seigel Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

U357 **CON ED - VS 5285** **RCRA NonGen / NLR** **1007206261**
NNE **SEIGAL ST & MANHATTAN AVE** **NY MANIFEST** **NYP004006680**
1/8-1/4 **BROOKLYN, NY 11206**
0.182 mi.
960 ft. **Site 4 of 5 in cluster U**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/28/1998
Facility name:	CON ED - VS 5285
Facility address:	SEIGAL ST & MANHATTAN AVE BROOKLYN, NY 11206-0000
EPA ID:	NYP004006680
Mailing address:	CONSOLIDATED EDISON INC

CON ED - VS 5285 (Continued) **1007206261**

4 IRVING PL - ROOM 300
NEW YORK, NY 10003-0000
Contact: ANTHONY DRUMMINGS
Contact address: CONSOLIDATED EDISON INC
NEW YORK, NY 10003-0000
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/27/1998
Site name: CON ED - VS 5285
Classification: Not a generator, verified

Date form received by agency: 02/26/1998
Site name: CON ED - VS 5285
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: SEIGAL ST & MANHATTAN AVE
City,State,Zip: BROOKLYN, NY 11206-0000
Country: USA
EPA ID: NYP004006680
Facility Status: Not reported
Location Address 1: V5285 - SEIGAL ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:

CON ED - VS 5285 (Continued) **1007206261**

EPAID:	NYP004006680
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYG0249696
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	80336AB
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/1997
Trans1 Recv Date:	05/12/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/13/1997
Part A Recv Date:	05/27/1997
Part B Recv Date:	06/12/1997
Generator EPA ID:	NYP004006680
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00001
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported

CON ED - VS 5285 (Continued) **1007206261**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00001
Units:	Y - Cubic yards* (.85 tons)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

U358 **CON ED-V5285** **NY MANIFEST** **S109064683**
NNE **SEIGAL ST & MANHATTAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11222**
0.182 mi.
960 ft. **Site 5 of 5 in cluster U**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON ED-V5285
Address:	SEIGAL ST & MANHATTAN AVE
City,State,Zip:	BROOKLYN, NY 11222
Country:	USA
EPA ID:	NYZ004019618
Facility Status:	Not reported
Location Address 1:	SEIGAL ST & MANHATTAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11222
Location Zip 4:	0000

NY MANIFEST:

EPAID:	NYZ004019618
Mailing Name:	CON ED-V5285
Mailing Contact:	Not reported
Mailing Address 1:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AA359 **NYCT - BROADWAY-LORIMER SUBSTATION** **RCRA-SQG** **1010787683**
WNW **143 LORIMER ST** **NJ MANIFEST** **NYR000156547**
1/8-1/4 **BROOKLYN, NY 11206** **NY MANIFEST**
0.182 mi.
961 ft. **Site 1 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

RCRA-SQG:

Date form received by agency:	03/27/2008
Facility name:	NYCT - BROADWAY-LORIMER SUBSTATION
Facility address:	143 LORIMER ST BROOKLYN, NY 11206
EPA ID:	NYR000156547
Mailing address:	BROADWAY - A27.63 NEW YORK, NY 10004
Contact:	SHERRY L BULKLEY
Contact address:	BROADWAY - A27.63 NEW YORK, NY 10004
Contact country:	US
Contact telephone:	646-252-5774
Contact email:	SHERRYBULKLEY@NYCT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	BROADWAY - A27.63 NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK CITY TRANSIT
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/1968
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

NYCT - BROADWAY-LORIMER SUBSTATION (Continued) **1010787683**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/26/2008
Site name:	NYCT - BROADWAY-LORIMER SUBSTATION
Classification:	Small Quantity Generator

Hazardous Waste Summary:

. Waste code:	D008
. Waste name:	LEAD

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYR000156547
Mail Address:	BROADWAY - A27.63
Mail City/State/Zip:	NEW YORK, NY 10004
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	SHERRY L BULKLEY
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000958016GBF
EPA ID:	NYR000156547
Date Shipped:	06/29/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

NYCT - BROADWAY-LORIMER SUBSTATION (Continued) **1010787683**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/29/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/29/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	238 P

NY MANIFEST:

Name:	NYCT - BROADWAY-LORIMER SUBSTATION
Address:	143 LORIMER ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYR000156547
Facility Status:	Not reported
Location Address 1:	143 LORIMER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000156547
Mailing Name:	NYCT - BROADWAY-LORIMER SUBSTATION
Mailing Contact:	NYCT - BROADWAY-LORIMER SUBSTATION

NYCT - BROADWAY-LORIMER SUBSTATION (Continued) **1010787683**

Mailing Address 1:	2 BROADWAY RM 27TH FL RM A27.63
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/29/2009
Trans1 Recv Date:	06/29/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000156547
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	000958016GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	238.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NYCT - BROADWAY-LORIMER SUBSTATION (Continued) **1010787683**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q360 **CON EDISON** **NY MANIFEST** **S117066035**
ENE **51 VARET ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.183 mi.
964 ft. **Site 7 of 7 in cluster Q**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	51 VARET ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004586509
Facility Status:	Not reported
Location Address 1:	51 VARET ST
Code:	BP
Location Address 2:	TM 199
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586509
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/05/2014
Trans1 Recv Date:	07/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586509
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774065JJK
Import Indicator:	N

CON EDISON (Continued) **S117066035**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

---

361 North 1/8-1/4 0.186 mi. 981 ft. **LINDSAY PARK HOUSING CORP** **NY UST** **U003127541**
31 LEONARD STREET **N/A**
BROOKLYN, NY 11206

Relative: Higher

Actual: 14 ft.

UST:

Name:	LINDSAY PARK HOUSING CORP
Address:	31 LEONARD STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-093254 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589007.28880
UTM Y:	4506449.38534
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2454
Affiliation Type:	Facility Owner
Company Name:	LINDSAY PARK HOUSING CORP
Contact Type:	MANAGING AGENT
Contact Name:	JAY SILVERBERG

LINDSAY PARK HOUSING CORP (Continued) **U003127541**

Address1:	202 UNION AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 782-9000
EMail:	JADIUS7@AOL.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-08-13

Site Id:	2454
Affiliation Type:	Mail Contact
Company Name:	LINDSAY PARK HOUSING CORP
Contact Type:	Not reported
Contact Name:	JAY SILVERBERG
Address1:	202 UNION AVENUE
Address2:	SUITE H
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 782-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-12-16

Site Id:	2454
Affiliation Type:	Facility Operator
Company Name:	LINDSAY PARK HOUSING CORP
Contact Type:	Not reported
Contact Name:	EVELYN MAGAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 782-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-08-13

Site Id:	2454
Affiliation Type:	Emergency Contact
Company Name:	LINDSAY PARK HOUSING CORP
Contact Type:	Not reported
Contact Name:	JOHN WHITE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

LINDSAY PARK HOUSING CORP (Continued) **U003127541**

Phone:	(718) 322-8999
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	4297
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	04/01/1964
Date Tank Closed:	10/15/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Number:	002
Tank ID:	4298
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	04/01/1964
Date Tank Closed:	06/20/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN

LINDSAY PARK HOUSING CORP (Continued) **U003127541**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AA362 **CON EDISON - MANHOLE 391** **NY MANIFEST** **S121967941**
WNW **133 HARRISON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.186 mi.
982 ft. **Site 2 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:
Name: CON EDISON - MANHOLE 391
Address: 133 HARRISON ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP005064977
Facility Status: Not reported
Location Address 1: 133 HARRISON ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005064977
Mailing Name: CON EDISON - MANHOLE 391
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AA363 **CON EDISON - MANHOLE 391** **RCRA-LQG** **1024891027**
WNW **133 HARRISON ST** **NYP005064977**
1/8-1/4 **BROOKLYN, NY 11206**
0.186 mi.
982 ft. **Site 3 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

RCRA-LQG:

Date form received by agency:	04/10/2018
Facility name:	CON EDISON - MANHOLE 391
Facility address:	133 HARRISON ST BROOKLYN, NY 11206
EPA ID:	NYP005064977
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	ALYSSA SOTTO
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	SOTTOA@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/13/2017
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner

CON EDISON - MANHOLE 391 (Continued) **1024891027**

Owner/Op start date: 04/13/2017
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

Z364 **L.J.S.T. REALTY** **NY AST** **A100294723**
ENE **45 COOK STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.188 mi.
991 ft. **Site 4 of 14 in cluster Z**

Relative: **Higher**
Actual: **20 ft.**

AST:
Name: L.J.S.T. REALTY
Address: 45 COOK STREET
City,State,Zip: BROOKLYN, NY 11206
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-607392
Program Type: PBS
UTM X: 589366.81148
UTM Y: 4506255.90681
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 29245
Affiliation Type: Facility Owner
Company Name: L.J.S.T. REALTY
Contact Type: MANAGER
Contact Name: JOSEPH DIURNO
Address1: 48 GRAHAM AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11206

L.J.S.T. REALTY (Continued) **A100294723**

Country Code:	001
Phone:	(718) 388-7400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-02-21

Site Id:	29245
Affiliation Type:	Mail Contact
Company Name:	L.J.S.T. REALTY
Contact Type:	Not reported
Contact Name:	JOE
Address1:	48 GRAHAM AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 388-7400
EMail:	JOE@PRIINC.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-12-08

Site Id:	29245
Affiliation Type:	Facility Operator
Company Name:	L.J.S.T. REALTY
Contact Type:	Not reported
Contact Name:	JOSE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-7400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29245
Affiliation Type:	Emergency Contact
Company Name:	L.J.S.T. REALTY
Contact Type:	Not reported
Contact Name:	JOSE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-7400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

L.J.S.T. REALTY (Continued) **A100294723**

Tank Info:

Tank Number:	001
Tank Id:	62877
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	L09 - Piping Leak Detection - Exempt Suction Piping
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/14/1935
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/14/2011
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Z365 **CON EDISON SERVICE BOX: 9130** **RCRA NonGen / NLR** **1017773038**
ENE **45 COOK ST** **FINDS** **NYP004508164**
1/8-1/4 **BROOKLYN, NY 11206**
0.188 mi.
991 ft. **Site 5 of 14 in cluster Z**

Relative:
Higher

Actual:
20 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/22/2014
Facility name:	CON EDISON SERVICE BOX: 9130
Facility address:	45 COOK ST BROOKLYN, NY 11206
EPA ID:	NYP004508164
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON SERVICE BOX: 9130 (Continued) **1017773038**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 04/22/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 04/22/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063806751

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Z366 **CON EDISON** **NY MANIFEST** **S117058681**
ENE **45 COOK ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.188 mi.
991 ft. **Site 6 of 14 in cluster Z**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	45 COOK ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA

CON EDISON (Continued) **S117058681**

EPA ID:	NYP004508164
Facility Status:	Not reported
Location Address 1:	45 COOK ST
Code:	BP
Location Address 2:	SB9130
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508164
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRIVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508164
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417960GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117058681**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V367 **CON EDISON** **NY MANIFEST** **S117059379**
ESE **5 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.188 mi.
994 ft. **Site 9 of 12 in cluster V**

Relative:
Higher

Actual:
24 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	5 GRAHAM AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004515466
Facility Status:	Not reported
Location Address 1:	5 GRAHAM AVE
Code:	BP
Location Address 2:	SB19008
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004515466
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **S117059379**

seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/29/2014
Trans1 Recv Date:	04/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004515466
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417466GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V368
ESE
1/8-1/4
0.188 mi.
994 ft.

CON EDISON SERVICE BOX: 14008
5 GRAHAM AVE
BROOKLYN, NY 11206

Site 10 of 12 in cluster V

RCRA NonGen / NLR **1017773755**
FINDS **NYP004515466**

Relative:
Higher

Actual:
24 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/29/2014
Facility name:	CON EDISON SERVICE BOX: 14008
Facility address:	5 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP004515466
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/29/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	04/29/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063791605

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON SERVICE BOX: 14008 (Continued) **1017773755**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Z369 **CON EDISON** **NY MANIFEST** **S117315364**
East **OPP 46 COOK ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.189 mi.
1000 ft. **Site 7 of 14 in cluster Z**

Relative:
Higher

Actual:
20 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 46 COOK ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004625232
Facility Status:	Not reported
Location Address 1:	OPP 46 COOK ST
Code:	BP
Location Address 2:	SB 9130
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004625232
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/12/2014
Trans1 Recv Date:	08/12/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004625232

CON EDISON (Continued) **S117315364**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616312GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V370 **CON EDISON** **RCRA NonGen / NLR** **1019907579**
ESE **BROADWAY & GRAHAM AVE** **NYP004835746**
1/8-1/4 **BROOKLYN, NY 11235**
0.191 mi.
1008 ft. **Site 11 of 12 in cluster V**

Relative: RCRA NonGen / NLR:
Higher

Date form received by agency:	09/08/2015
Facility name:	CON EDISON
Facility address:	BROADWAY & GRAHAM AVE BROOKLYN, NY 11235
EPA ID:	NYP004835746
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770

Actual:
24 ft.

CON EDISON (Continued) **1019907579**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/08/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

V371 **CON EDISON** **NJ MANIFEST** **S120676449**
ESE **BROADWAY & GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11235**
0.191 mi.
1008 ft. **Site 12 of 12 in cluster V**

Relative:
Higher

Actual:
24 ft.

NJ MANIFEST:
EPA Id: NYP004835746
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 014470903JJK
EPA ID: NYP004835746
Date Shipped: 9/8/2015
TSDF EPA ID: NJD002200046

CON EDISON (Continued) **S120676449**

Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

X372 **NYCTA - 22 THROOP AVE** **RCRA NonGen / NLR** **1000912691**
NW **22 THROOP AVE** **FINDS** **NY0000902171**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.191 mi. **NY MANIFEST**
1010 ft. **Site 5 of 6 in cluster X**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYCTA - 22 THROOP AVE
Facility address:	22 THROOP AVE BROOKLYN, NY 11206-2911
EPA ID:	NY0000902171
Mailing address:	JAY ST ROOM 809 BROOKLYN, NY 11201
Contact:	Not reported
Contact address:	JAY ST ROOM 809 BROOKLYN, NY 11201
Contact country:	US
Contact telephone:	Not reported

NYCTA - 22 THROOP AVE (Continued) **1000912691**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK CITY TRANSIT AUTHORITY
Owner/operator address: 370 JAY ST ROOM 809
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: 718-330-4581
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Other
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK CITY TRANSIT AUTHORITY
Owner/operator address: 370 JAY ST ROOM 809
BROOKLYN, NY 11201
Owner/operator country: US
Owner/operator telephone: 718-330-4581
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYCTA - 22 THROOP AVE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NYCTA - 22 THROOP AVE

NYCTA - 22 THROOP AVE (Continued) **1000912691**

Classification: Not a generator, verified

Date form received by agency: 03/20/1996
Site name: 22 THROOP AVE / NYCT
Classification: Large Quantity Generator

Date form received by agency: 10/26/1994
Site name: NYCTA - 22 THROOP AVE
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

FINDS:

Registry ID: 110000805898

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000912691
Registry ID: 110000805898
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000805898

NY MANIFEST:
Name: NYCTA
Address: 22 THROOP AVE
City,State,Zip: BROOKLYN, NY 11206-2911
Country: USA
EPA ID: NY0000902171
Facility Status: Not reported
Location Address 1: 22 THROOP AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NYCTA - 22 THROOP AVE (Continued) **1000912691**

NY MANIFEST:

EPAID:	NY0000902171
Mailing Name:	NYCTA
Mailing Contact:	JOSE E LIBREROZ
Mailing Address 1:	112 THROOP AVENUE STA -RM 809
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183304581

NY MANIFEST:

Document ID:	NJA2172788
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	S5811
Trans2 State ID:	Not reported
Generator Ship Date:	10/04/1995
Trans1 Recv Date:	10/04/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/04/1995
Part A Recv Date:	10/17/1995
Part B Recv Date:	10/20/1995
Generator EPA ID:	NY0000902171
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	39508
Units:	P - Pounds
Number of Containers:	083
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

NYCTA - 22 THROOP AVE (Continued) **1000912691**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z373 **PS 257K SCHOOL** **RCRA-LQG** **1004755781**
East **60 COOK ST** **NY MANIFEST** **NY0000375469**
1/8-1/4 **BROOKLYN, NY 11206**
0.192 mi.
1013 ft. **Site 8 of 14 in cluster Z**

Relative:
Higher

Actual:
20 ft.

RCRA-LQG:

Date form received by agency:	02/20/2014
Facility name:	PS 257K SCHOOL
Facility address:	60 COOK ST BROOKLYN, NY 11206
EPA ID:	NY0000375469
Mailing address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact:	ALEXANDER LEMPERT
Contact address:	THOMSON AVE LONG ISLAND CITY, NY 11101
Contact country:	US
Contact telephone:	718-472-8501
Contact email:	ALEMPERT@NYCSCA.ORG
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NYC BOARD OF EDUCATION
Owner/operator address:	28-11 QUEENS PLZ N LONG ISLAND CITY, NY 11101
Owner/operator country:	Not reported
Owner/operator telephone:	718-349-5600
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	NYC DEPARTMENT OF EDUCATION
Owner/operator address:	VERNON BLVD LONG ISLAND CITY, NY 11101
Owner/operator country:	US
Owner/operator telephone:	Not reported

PS 257K SCHOOL (Continued) **1004755781**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: 01/01/1900
Owner/Op end date: Not reported

Owner/operator name: NYC DEPARTMENT OF EDUCATION
Owner/operator address: VERNON BLVD
LONG ISLAND CITY, NY 11101
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1900
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2007
Site name: NYC BD OF ED - PUBLIC SCHOOL 257 BKLYN
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: NYC BD OF ED - PUBLIC SCHOOL 257 BKLYN
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 08/10/1995
Site name: NYC BD OF ED - PUBLIC SCHOOL 257 BKLYN
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: B004
. Waste name: PCB articles containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs, excluding small capacitors. This includes oil-filled

PS 257K SCHOOL (Continued) **1004755781**

electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Name: NYC BOARD OF EDUCATION
Address: 60 COOK ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NY0000375469
Facility Status: Not reported
Location Address 1: 60 COOK ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000375469
Mailing Name: NYC BOARD OF EDUCATION
Mailing Contact: JACK BRUCCULERI
Mailing Address 1: 28-11 QUEENS PLAZA NORTH
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7183616094

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NJD054126164
Trans2 State ID: Not reported
Generator Ship Date: 08/22/2013
Trans1 Recv Date: 08/22/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000375469
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: MAC300017498
TSDF ID 2: Not reported

PS 257K SCHOOL (Continued) **1004755781**

Manifest Tracking Number:	011979719JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H039
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	930
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	B004
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z374 **P.S. 257 - BROOKLYN K257** **NY AST** **U003394210**
East **60 COOK STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.192 mi.
1013 ft. **Site 9 of 14 in cluster Z**

Relative:
Higher

Actual:
20 ft.

AST:

Name:	P.S. 257 - BROOKLYN K257
Address:	60 COOK STREET
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-354279
Program Type:	PBS
UTM X:	589435.50551
UTM Y:	4506226.80760
Expiration Date:	06/28/2023
Site Type:	School

Affiliation Records:

Site Id:	17608
Affiliation Type:	Facility Owner

P.S. 257 - BROOKLYN K257 (Continued) **U003394210**

Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Site Id:	17608
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	MSHARMA@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-04-10

Site Id:	17608
Affiliation Type:	Facility Operator
Company Name:	P.S. 257 - BROOKLYN K257
Contact Type:	Not reported
Contact Name:	SALVATORE CALDERONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-7128
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-28

Site Id:	17608
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported

P.S. 257 - BROOKLYN K257 (Continued) **U003394210**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 210-7918
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2018-12-06

Tank Info:

Tank Number: 001
Tank Id: 34475
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1962
Capacity Gallons: 7500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MFLEONAR
Last Modified: 02/28/2018
Material Name: #4 fuel oil (on-site consumption)

Tank Number: 002
Tank Id: 34476
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

P.S. 257 - BROOKLYN K257 (Continued) **U003394210**

F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1962
Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MFLEONAR
Last Modified:	02/28/2018
Material Name:	#4 fuel oil (on-site consumption)

Z375 **CON EDISON SERVICE BOX: 9101** **RCRA NonGen / NLR** **1016970428**
ENE **47 GRAHAM AVE** **NY MANIFEST** **NYP004441374**
1/8-1/4 **BROOKLYN, NY 11206**
0.194 mi.
1022 ft. **Site 10 of 14 in cluster Z**

Relative: **Higher**
Actual: **19 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/13/2014
Facility name:	CON EDISON SERVICE BOX: 9101
Facility address:	47 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP004441374
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON SERVICE BOX: 9101 (Continued) **1016970428**

On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/13/2014
Site name:	CON EDISON SERVICE BOX: 9101
Classification:	Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:

Name:	CON ED
Address:	47 GRAHAM AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004441374
Facility Status:	Not reported
Location Address 1:	FRONT OF 47 GRAHAM AV
Code:	BP
Location Address 2:	STRUCTURE 9101
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004441374
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/13/2014
Trans1 Recv Date:	02/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/18/2014

CON EDISON SERVICE BOX: 9101 (Continued) **1016970428**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004441374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329670GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AB376 **CON EDISON SERVICE BOX: 12998** **RCRA NonGen / NLR** **1017778914**
ENE **51 GRAHAM AVE** **NYP004568747**
1/8-1/4 **BROOKLYN, NY 11206**
0.195 mi.
1028 ft. **Site 1 of 8 in cluster AB**

Relative:
Higher

Actual:
19 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/18/2014
Facility name:	CON EDISON SERVICE BOX: 12998
Facility address:	51 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP004568747
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported

CON EDISON SERVICE BOX: 12998 (Continued) **1017778914**

Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/18/2014
Site name: CON EDISON
Classification: Small Quantity Generator

Date form received by agency: 06/18/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

AB377 **CON EDISON** **NY MANIFEST** **S117064391**
ENE **51 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.195 mi.
1028 ft. **Site 2 of 8 in cluster AB**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:
Name: CON EDISON
Address: 51 GRAHAM AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004568747
Facility Status: Not reported
Location Address 1: FO 51 GRAHAM AVE
Code: BP
Location Address 2: STRUCTRUE 12998
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

CON EDISON (Continued) **S117064391**

NY MANIFEST:

EPAID:	NYP004568747
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/18/2014
Trans1 Recv Date:	06/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004568747
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502579GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117064391**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z378 **CON EDISON SERVICE BOX: 14005** **RCRA NonGen / NLR** **1017773571**
East **44 GRAHAM AVE** **FINDS** **NYP004513560**
1/8-1/4 **BROOKLYN, NY 11206**
0.197 mi.
1041 ft. **Site 11 of 14 in cluster Z**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/28/2014
Facility name:	CON EDISON SERVICE BOX: 14005
Facility address:	44 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP004513560
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/28/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency: 04/28/2014

CON EDISON SERVICE BOX: 14005 (Continued) **1017773571**

Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063781670

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Z379 **CON EDISON** **NY MANIFEST** **S117059202**
East **44 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.197 mi.
1041 ft. **Site 12 of 14 in cluster Z**

Relative:
Higher

Actual:
21 ft.

NY MANIFEST:
Name: CON EDISON
Address: 44 GRAHAM AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004513560
Facility Status: Not reported
Location Address 1: 44 GRAHAM AVE
Code: BP
Location Address 2: SB14005
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004513560
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported

CON EDISON (Continued) **S117059202**

Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2014
Trans1 Recv Date:	04/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004513560
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002418171GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z380 **CON EDISON SERVICE BOX: 14001** **RCRA NonGen / NLR** **1016973340**
ENE **VARET ST & GRAHAM AVE** **NY MANIFEST** **NYP004471389**
1/8-1/4 **BROOKLYN, NY 11206**
0.198 mi.
1048 ft. **Site 13 of 14 in cluster Z**

Relative:
Higher

Actual:
19 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/19/2014
Facility name:	CON EDISON SERVICE BOX: 14001
Facility address:	VARET ST & GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP004471389
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/19/2014
Site name:	CON EDISON SERVICE BOX: 14001
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	VARET ST & GRAHAM AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004471389
Facility Status:	Not reported
Location Address 1:	VARET ST & GRAHAM AVE.
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 14001 (Continued) **1016973340**

Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004471389
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2014
Trans1 Recv Date:	03/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004471389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697506JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1

CON EDISON SERVICE BOX: 14001 (Continued) **1016973340**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X381 **196 MIDDLETON STREET** **NY VCP** **S118943474**
NW **196 MIDDLETON STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.199 mi.
1053 ft. **Site 6 of 6 in cluster X**

Relative:
Higher

Actual:
15 ft.

VCP NYC:

Project ID:	15CVCP085K
Project Name:	196 MIDDLETON STREET
Project Address:	196 MIDDLETON STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	15CVCP085K
File Name:	2014-12-31.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2014-12-31.15CVCP085K.report.196_Middleton_RIR_Final.EBC.pdf

Project ID:	15CVCP085K
File Name:	2015-07-06.RAWP_Final
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2015-07-06.15CVCP085K.report.196_Middleton_RAWP_FINAL.EBC.pdf

Project ID:	15CVCP085K
File Name:	2015-03-12.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2015-03-12.15CVCP085K.196_Middleton_Factsheet-1.pdf

Project ID:	15CVCP085K
File Name:	2015-03-12.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2015-03-12.15CVCP085K.196_Middleton_Translated_Factsheet-1.pdf

Project ID:	15CVCP085K
File Name:	2015-02-20.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2015-02-20.15CVCP085K.196_Middleton_Translated_CPS.pdf

Project ID:	15CVCP085K
File Name:	2015-07-16.Decision_Document
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2015-07-16.15EH-A150K.notice.196_Middleton_Decision_Document

196 MIDDLETON STREET (Continued) **S118943474**

.OER.pdf

Project ID: 15CVCP085K
File Name: 2015-09-14.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2015-09-14.15CVCP085K.196_Middleton_Factsheet-2.pdf

Project ID: 15CVCP085K
File Name: 2015-09-14.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP085K/2015-09-14.15CVCP085K.196_Middleton_Translated_Factsheet-2.pdf

---

W382 **179 THROOP AVENUE** **NY VCP** **S118943614**
SSE **179 THROOP AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.201 mi.
1059 ft. **Site 9 of 10 in cluster W**

Relative: **Higher**

Actual: **25 ft.**

VCP NYC:
Project ID: 16CVCP079K
Project Name: 179 THROOP AVENUE
Project Address: 179 THROOP AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 16CVCP079K
File Name: 2016-06-10.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2016-05-17.16CVCP079K.Woodhull_Medical_Center.179_Throop_Avenue.RIR.pdf

Project ID: 16CVCP079K
File Name: 2016-08-23.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2016-06-14 16CVCP079K 179_Throop_Avenue_RAWP_final.pdf

Project ID: 16CVCP079K
File Name: 2016-06-10.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2016-06-10 16CVCP079K Woodhull_Medical_Center 179_Throop_Avenue Factsheet-1.pdf

Project ID: 16CVCP079K
File Name: 2016-06-10.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2016-06-13.16CVCP079K.Woodhull_Medical_Center.179_Throop_Ave.Translated_Factsheet-1.pdf

Project ID: 16CVCP079K
File Name: 2016-06-10.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2016-06-13.16CVCP079K.Woodhull_Medical_Center.179_Throop_Ave.Community_Protection_Statement.pdf

Project ID: 16CVCP079K
File Name: 2016-08-23.Decision_Document

179 THROOP AVENUE (Continued) **S118943614**

URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2016-08-15.16CVCP079K.179_Throop_Avenue.doc.Decision_Document.pdf

Project ID: 16CVCP079K
File Name: 2016-08-23.Stip_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2016-08-09.16CVCP079K.Stipulation_List_final.pdf

Project ID: 16CVCP079K
File Name: 2017-06-27.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2017-06-27.16TMP0385K.Fact Sheet 2 (NYC VCP Remediation Start).OER.pdf

Project ID: 16CVCP079K
File Name: 2017-06-27.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP079K/2017-06-27.16TMP0385K.Translations - Fact Sheet 2.OER.pdf

---

W383 **WOODHULL REDEVELOPMENT** **NY UST** **U004277385**
SSE **179 THROOP AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.201 mi.
1059 ft. **Site 10 of 10 in cluster W**

Relative:
Higher

Actual:
25 ft.

UST:
Name: WOODHULL REDEVELOPMENT
Address: 179 THROOP AVENUE
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-612838 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: Not reported
UTM Y: Not reported
Site Type: Other

Affiliation Records:
Site Id: 565510
Affiliation Type: Facility Owner
Company Name: COMMUNILIFE WOODHULL ASSOCIATES, LP
Contact Type: PROJECT MANAGER
Contact Name: DORINA ALIU
Address1: 214 WEST 29TH STREET, 8TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10001
Country Code: 001
Phone: (212) 219-1618
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-01-02

WOODHULL REDEVELOPMENT (Continued) **U004277385**

Site Id:	565510
Affiliation Type:	Mail Contact
Company Name:	HYDROTECH ENVIRONMENTAL
Contact Type:	Not reported
Contact Name:	DORINA ALIU
Address1:	15 OCEAN AVENUE
Address2:	2ND FL
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(347) 249-1880
EMail:	DALIU@HYDROTECHENVIRONMENTAL.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-01-02

Site Id:	565510
Affiliation Type:	Facility Operator
Company Name:	WOODHULL REDEVELOPMENT
Contact Type:	Not reported
Contact Name:	MEGA CONTRACTING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-01-02

Tank Info:

Tank Number:	001
Tank ID:	274724
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	Not reported
Date Tank Closed:	06/19/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DMPOKRZY
Last Modified:	01/02/2018

Equipment Records:

J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

WOODHULL REDEVELOPMENT (Continued) **U004277385**

I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None

Tank Number: 002
Tank ID: 274725
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 06/23/2017
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DMPOKRZY
Last Modified: 01/02/2018

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 274726
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 07/10/2017
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DMPOKRZY

WOODHULL REDEVELOPMENT (Continued) **U004277385**

Last Modified: 01/02/2018

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

AA384 **100 UNION AVENUE REDEVELOPMENT SITE** **NY BROWNFIELDS** **S117676130**
WNW **100 UNION AVENUE** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.201 mi.
1060 ft. **Site 4 of 14 in cluster AA**

Relative: **Higher**
Actual: **16 ft.**

BROWNFIELDS:

Name:	100 UNION AVENUE REDEVELOPMENT SITE
Address:	100 UNION AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Program:	BCP
Site Code:	569083
Acres:	0.24
HW Code:	C224274
SWIS:	2401
Town:	New York City
Record Added Date:	04/17/2018
Record Updated Date:	07/09/2018
Update By:	JHOCONNE
Site Description:	Location: The site is located in an urban area at 100 Union Avenue, Brooklyn (aka 100 to 118 Union Avenue and 180 Middleton Street). The site is located on the east side of Union Avenue between Middleton and Lorimer Streets and is bordered by Middleton Street to the north; Union Avenue to the west; a vacant lot, a 2-story residential building and a NYC Transit substation building to the south; and a 6-story residential building to the east. Site Features: The site is 10,566 square feet (0.24 acres) in area and currently consists of a vacant lot with no developments. The site is covered with bare soil and is surrounded by a plywood fence along the two bounding streets and four adjacent properties. Current Zoning and Land Use: The site is zoned R6A (residential district) with C2-4 commercial overlay and is currently vacant. Past Use of the Site: The site was historically occupied by a church and residential dwellings prior to 1887. The site then became vacant through 1950. A 1-story building located in the northern portion of the site was used for auto sales between 1965 through 2014 and the southern portion was used as a junk yard from 1992 through 2014. Site Geology and Hydrology: The site is generally level and is at an elevation of approximately 16 feet above sea level. The geology of Kings County consists of unconsolidated glacial deposits. Groundwater beneath the site was encountered at depths ranging between 10.39 to 12.94 feet. Regional groundwater flow direction in the vicinity of the site is toward the southwest.

100 UNION AVENUE REDEVELOPMENT SITE (Continued) **S117676130**

Env Problem:	Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	P03
Owner Name:	Isaac Feuerwerger
Owner Company:	100 Union Holdings LLC
Owner Address:	545 Broadway, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Isaac Feuerwerger
Owner Company:	100 Union Holdings LLC
Owner Address:	545 Broadway, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Williamsburgh Branch
Owner Address:	240 Division Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Isaac Feuerwerger
Owner Company:	Carnegie Management Inc.
Owner Address:	545 Broadway, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206

100 UNION AVENUE REDEVELOPMENT SITE (Continued) **S117676130**

Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

E DESIGNATION:

Name:	LOT 3,TAXBLOCK 2242
Address:	100 UNION AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Tax Lot(s):	3
Tax Block:	2242
Borough Code:	BK
E-No:	E-238
Effective Date:	12/22/2009
Satisfaction Date:	Not reported
Ceqr Number:	09HPD019K
Ulurp Number:	090413ZMK
Zoning Map No:	13b
Description:	Air Quality - Natural Gas Heat & Hot Water
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

AA385 **100 UNION AVENUE** **NY VCP** **S118943565**
WNW **100 UNION AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.201 mi.
1060 ft. **Site 5 of 14 in cluster AA**

Relative:
Higher

Actual:
16 ft.

VCP NYC:

Project ID:	16CVCP018K
Project Name:	100 UNION AVENUE
Project Address:	100 UNION AVENUE
Borough:	BROOKLYN

VCP NYC:

Project ID:	16CVCP018K
File Name:	2015-11-18.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP018K/2015-11-18.14EH-A461K.Report.RIR.OER_hz_sc.pdf
Project ID:	16CVCP018K
File Name:	2015-11-16.RAWP_draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP018K/2015-11-16.14EHA461K.100_Union_Avenue.Report.RAWP_v2.HTE.pdf

100 UNION AVENUE (Continued) **S118943565**

Project ID: 16CVCP018K
File Name: 2015-12-09.Factsheet-1
URL: Not reported

Project ID: 16CVCP018K
File Name: 2015-12-09.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP018K/2015-12-09.16CVCP018K.doc.100_Union_Ave.Translated_Factsheet-1.pdf

Project ID: 16CVCP018K
File Name: 2015-12-09.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP018K/2015-12-09.16CVCP018K.doc.100_Union_Ave.Translated_CPS.pdf

---

AC386 **CON EDISON - 67 MANHATTAN AVE** **RCRA NonGen / NLR** **1001119359**
NNE **67 MANHATTAN AVE** **NY MANIFEST** **NYR000026468**
1/8-1/4 **BROOKLYN, NY 11211**
0.202 mi.
1065 ft. **Site 1 of 4 in cluster AC**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: CON EDISON - 67 MANHATTAN AVE
Facility address: 67 MANHATTAN AVE
BROOKLYN, NY 11211
EPA ID: NYR000026468
Mailing address: IRVING PL ROOM 300
NEW YORK, NY 10003
Contact: Not reported
Contact address: IRVING PL ROOM 300
NEW YORK, NY 10003
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LINDSAY PARK HOUSING CORP
Owner/operator address: 202 UNION AVE
BROOKLYN, NY 11206
Owner/operator country: US
Owner/operator telephone: 718-782-9000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LINDSAY PARK HOUSING CORP
Owner/operator address: 202 UNION AVE

CON EDISON - 67 MANHATTAN AVE (Continued) **1001119359**

BROOKLYN, NY 11206
Owner/operator country: US
Owner/operator telephone: 718-782-9000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CON EDISON - 67 MANHATTAN AVE
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: CON EDISON - 67 MANHATTAN AVE
Classification: Small Quantity Generator

Date form received by agency: 07/11/1996
Site name: CON EDISON - 67 MANHATTAN AVE
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/02/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported

CON EDISON - 67 MANHATTAN AVE (Continued) **1001119359**

Date achieved compliance: Not reported
Evaluation lead agency: EPA

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 67 MANHATTAN AVE
City,State,Zip: BROOKLYN, NY 11211
Country: USA
EPA ID: NYR000026468
Facility Status: Not reported
Location Address 1: 67 MANHATTAN AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11211
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000026468
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: MAQ0257876
Manifest Status: Not reported
seq: Not reported
Year: 2005
Trans1 State ID: MAD039322250
Trans2 State ID: MAD039322250
Generator Ship Date: 07/20/2005
Trans1 Recv Date: 07/20/2005
Trans2 Recv Date: 07/22/2005
TSD Site Recv Date: 07/25/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000026468
Trans1 EPA ID: 614171ME
Trans2 EPA ID: 614171ME
TSDF ID 1: MAD053452637
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported

CON EDISON - 67 MANHATTAN AVE (Continued) **1001119359**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15421
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AC387 **CON EDISON MANHOLE: 55943** **RCRA NonGen / NLR** **1016677468**
NNE **67 MANHATTAN AVE** **FINDS** **NYP004311049**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.202 mi. **NY MANIFEST**
1065 ft. **Site 2 of 4 in cluster AC**

Relative: Higher

Actual: 17 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/10/2013
Facility name:	CON EDISON MANHOLE: 55943
Facility address:	67 MANHATTAN AVE BROOKLYN, NY 11206
EPA ID:	NYP004311049
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	ANTHONY SIGNORE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	718-666-4714
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CON EDISON MANHOLE: 55943 (Continued) **1016677468**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/10/2013
Site name: CON EDISON MANHOLE: 55943
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058875025

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677468
Registry ID: 110058875025
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058875025

NY MANIFEST:
Name: CON EDISON
Address: 67 MANHATTAN AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004311049
Facility Status: Not reported
Location Address 1: FO 67 MANHATTAN AVE AND MCKIBBIN
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004311049
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY

CON EDISON MANHOLE: 55943 (Continued) **1016677468**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/2013
Trans1 Recv Date:	05/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004311049
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002017495GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON MANHOLE: 55943 (Continued) **1016677468**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AC388 **LINDSAY PARK HOUSING CORP** **NY UST** **U003127540**
NNE **67 MANHATTAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.202 mi.
1065 ft. **Site 3 of 4 in cluster AC**

Relative:
Higher

Actual:
17 ft.

UST:

Name:	LINDSAY PARK HOUSING CORP
Address:	67 MANHATTAN AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-093246 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589192.63296
UTM Y:	4506498.16511
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2453
Affiliation Type:	Facility Owner
Company Name:	LINDSAY PARK HOUSING CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	202 UNION AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 782-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-11-04

Site Id:	2453
Affiliation Type:	Mail Contact
Company Name:	LINDSAY PARK HOUSING CORP.
Contact Type:	Not reported
Contact Name:	JAY SILVERBERG
Address1:	202 UNION AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 782-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-11-04

Site Id:	2453

LINDSAY PARK HOUSING CORP (Continued) **U003127540**

Affiliation Type:	Facility Operator
Company Name:	LINDSAY PARK HOUSING CORP
Contact Type:	Not reported
Contact Name:	JIM BRYANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 388-7012
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-09-29

Site Id:	2453
Affiliation Type:	Emergency Contact
Company Name:	LINDSAY PARK HOUSING CORP
Contact Type:	Not reported
Contact Name:	JIM BRYANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 388-7012
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-09-29

Tank Info:

Tank Number:	001
Tank ID:	4295
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	45500
Install Date:	04/01/1964
Date Tank Closed:	07/31/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MXLAY
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None

LINDSAY PARK HOUSING CORP (Continued) **U003127540**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	002
Tank ID:	4296
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	45000
Install Date:	04/01/1964
Date Tank Closed:	08/21/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MXLAY
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	003
Tank ID:	61542
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	04/01/1964
Date Tank Closed:	09/07/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN

LINDSAY PARK HOUSING CORP (Continued) **U003127540**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: NRLOMBAR
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D10 - Pipe Type - Copper

Tank Number: 004
Tank ID: 61543
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1964
Date Tank Closed: 08/10/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MXLAY
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 61544
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1964
Date Tank Closed: 08/12/2009
Registered: True

LINDSAY PARK HOUSING CORP (Continued) **U003127540**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MXLAY
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D10 - Pipe Type - Copper

Tank Number: 006
Tank ID: 61545
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1964
Date Tank Closed: 08/14/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MXLAY
Last Modified: 04/14/2017

Equipment Records:

D10 - Pipe Type - Copper
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 61546

LINDSAY PARK HOUSING CORP (Continued) **U003127540**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1964
Date Tank Closed: 08/19/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MXLAY
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 61547
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 04/01/1964
Date Tank Closed: 08/26/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MXLAY
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D10 - Pipe Type - Copper
C02 - Pipe Location - Underground/On-ground

LINDSAY PARK HOUSING CORP (Continued) **U003127540**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	009
Tank ID:	61548
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	04/01/1964
Date Tank Closed:	09/22/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MXLAY
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D10 - Pipe Type - Copper

Tank Number:	010
Tank ID:	61549
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	04/01/1964
Date Tank Closed:	09/24/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MXLAY
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None

LINDSAY PARK HOUSING CORP (Continued) **U003127540**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AD389 **TM2554** **RCRA NonGen / NLR** **1007207456**
WSW **322 WALLABOUT STREET** **NYP004046181**
1/8-1/4 **NEW YORK, NY 11231**
0.202 mi.
1066 ft. **Site 1 of 4 in cluster AD**

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/03/2001
Facility name:	TM2554
Facility address:	322 WALLABOUT STREET NEW YORK, NY 11231
EPA ID:	NYP004046181
Mailing address:	CONSOLIDATED EDISON INC. 4 IRVING PLACE -- ROOM 300 NEW YORK, NY 10003
Contact:	ANTHONY DRUMMINGS
Contact address:	CONSOLIDATED EDISON INC. NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/02/2001
Site name:	TM2554
Classification:	Not a generator, verified

Date form received by agency: 01/01/2001

TM2554 (Continued) **1007207456**

Site name: TM2554
Classification: Large Quantity Generator

Violation Status: No violations found

AE390 **WALTON APARTMENTS** **NY UST** **U004248210**
West **63 WALTON STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.202 mi.
1066 ft. **Site 1 of 7 in cluster AE**

Relative:
Higher

Actual:
14 ft.

UST:
Name: WALTON APARTMENTS
Address: 63 WALTON STREET
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-612525 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 588665.37028
UTM Y: 4506154.36290
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 522465
Affiliation Type: Facility Owner
Company Name: 53-63 WALTON LLC
Contact Type: MEMBER
Contact Name: HEYME BLEIER
Address1: 829 KENT AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11205
Country Code: 001
Phone: (718) 387-1806
EMail: STEINBESTDIST@THEJNET.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2016-02-05

Site Id: 522465
Affiliation Type: Mail Contact
Company Name: 53-63 WALTON LLC
Contact Type: MEMBER
Contact Name: HEYME BLEIER
Address1: 829 KENT AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11205
Country Code: 001
Phone: (718) 387-1806
EMail: STEINBESTDIST@THEJNET.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2016-02-05

WALTON APARTMENTS (Continued) **U004248210**

Site Id:	522465
Affiliation Type:	Facility Operator
Company Name:	WALTON APARTMENTS
Contact Type:	Not reported
Contact Name:	HEYME BLEIER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-1806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-02-05

Site Id:	522465
Affiliation Type:	Emergency Contact
Company Name:	53-63 WALTON LLC
Contact Type:	Not reported
Contact Name:	HEYME BLEIER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 387-1806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-02-05

Tank Info:

Tank Number:	001
Tank ID:	260453
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	07/18/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LSZINOMA
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

WALTON APARTMENTS (Continued) **U004248210**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None

AA391 **CON EDISON - TRANSFORMER MANHOLE 200** **NJ MANIFEST** **S120677934**
WNW **HARRISON AVE & UNION AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.203 mi.
1070 ft. **Site 6 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

NJ MANIFEST:

EPA Id:	NYP004875098
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015320898JJK
EPA ID:	NYP004875098
Date Shipped:	12/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON - TRANSFORMER MANHOLE 200 (Continued) **S120677934**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AA392 **CON EDISON - TRANSFORMER MANHOLE 200** **RCRA-LQG** **1019325975**
WNW **HARRISON AVE & UNION AVE** **NYP004875098**
1/8-1/4 **BROOKLYN, NY 11206**
0.203 mi.
1070 ft. **Site 7 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

RCRA-LQG:

Date form received by agency:	02/26/2016
Facility name:	CON EDISON - TRANSFORMER MANHOLE 200
Facility address:	HARRISON AVE & UNION AVE BROOKLYN, NY 11206
EPA ID:	NYP004875098
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	THERESA BURKARD
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2262
Contact email:	BURKARDT@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.

CON EDISON - TRANSFORMER MANHOLE 200 (Continued) **1019325975**

Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/02/2015
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/02/2015
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D008
Waste name: LEAD
Amount (Lbs): 3000

CON EDISON - TRANSFORMER MANHOLE 200 (Continued) **1019325975**

Violation Status: No violations found

AA393 **CON EDISON - MANHOLE 392** **NJ MANIFEST** **S120665719**
WNW **UNION AVE HARRISON AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.203 mi.
1070 ft. **Site 8 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

NJ MANIFEST:

EPA Id:	NYP004184263
Mail Address:	4 IRVING PLACE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894756GBF
EPA ID:	NYP004184263
Date Shipped:	07/27/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/27/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

CON EDISON - MANHOLE 392 (Continued) **S120665719**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	400 G

AA394 **CON ED** **NY MANIFEST** **S118563725**
WNW **HARRISON AVE & UNION AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.203 mi.
1070 ft. **Site 9 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

NY MANIFEST:

Name:	CON ED
Address:	HARRISON AVE & UNION AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004875098
Facility Status:	Not reported
Location Address 1:	HARRISON AVE & UNION AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004875098
Mailing Name:	CON ED
Mailing Contact:	CON ED
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AA395 **CON EDISON - MANHOLE 392** **RCRA-LQG** **1014396246**
WNW **UNION AVE HARRISON AVE** **NY MANIFEST** **NYP004184263**
1/8-1/4 **BROOKLYN, NY 11206**
0.203 mi.
1070 ft. **Site 10 of 14 in cluster AA**

Relative:
Higher

Actual:
15 ft.

RCRA-LQG:

Date form received by agency:	03/23/2010
Facility name:	CON EDISON - MANHOLE 392
Facility address:	UNION AVE HARRISON AVE BROOKLYN, NY 11206
EPA ID:	NYP004184263
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLYN MURRAY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-2808
Contact email:	MURRAYFR@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/14/2009
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner

CON EDISON - MANHOLE 392 (Continued) **1014396246**

Owner/Op start date: 07/14/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/14/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: UNION AVE & HARRISON AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004184263
Facility Status: Not reported
Location Address 1: UNION AVE HARRISON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004184263
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON - MANHOLE 392 (Continued) **1014396246**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/27/2009
Trans1 Recv Date:	07/27/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/28/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004184263
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894756GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AF396 **CON EDISON SERVICE BOX: 7281** **RCRA NonGen / NLR** **1016965704**
SSE **204 ELLERY ST** **NY MANIFEST** **NYP004385704**
1/8-1/4 **BROOKLYN, NY 11206**
0.205 mi.
1081 ft. **Site 1 of 3 in cluster AF**

Relative:
Higher

Actual:
26 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/05/2013
Facility name:	CON EDISON SERVICE BOX: 7281
Facility address:	204 ELLERY ST BROOKLYN, NY 11206
EPA ID:	NYP004385704
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	11/05/2013
Site name:	CON EDISON SERVICE BOX: 7281
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	204 ELLERY ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004385704
Facility Status:	Not reported
Location Address 1:	204 ELLERY BR
Code:	BP
Location Address 2:	SB 7281
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 7281 (Continued) **1016965704**

Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004385704
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/05/2013
Trans1 Recv Date:	11/05/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/08/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004385704
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002236671GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1

CON EDISON SERVICE BOX: 7281 (Continued) **1016965704**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AB397 **CON EDISON - MANHOLE 14001** **RCRA-LQG** **1014396249**
ENE **64 GRAHAM AVE** **NJ MANIFEST** **NYP004184297**
1/8-1/4 **BROOKLYN, NY 11206** **NY MANIFEST**
0.211 mi.
1113 ft. **Site 3 of 8 in cluster AB**

Relative: **Higher**
Actual: **20 ft.**

RCRA-LQG:

Date form received by agency:	03/23/2010
Facility name:	CON EDISON - MANHOLE 14001
Facility address:	64 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP004184297
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLYN MURRAY
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-2808
Contact email:	MURRAYFR@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

CON EDISON - MANHOLE 14001 (Continued) **1014396249**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/14/2009
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/14/2009
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/14/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004184297
Mail Address: 4 IRVING PLACE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: FRANKLYN MURRAY
Comments: Not reported

CON EDISON - MANHOLE 14001 (Continued) **1014396249**

SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894726GBF
EPA ID:	NYP004184297
Date Shipped:	07/22/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/22/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/27/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 G

CON EDISON - MANHOLE 14001 (Continued) **1014396249**

NY MANIFEST:

Name:	CONSOLIDATED EDISON MH1401
Address:	64 GRAHAM AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004184297
Facility Status:	Not reported
Location Address 1:	64 GRAHAM AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004184297
Mailing Name:	CONSOLIDATED EDISON MH1401
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2009
Trans1 Recv Date:	07/22/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/27/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004184297
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894726GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON - MANHOLE 14001 (Continued) **1014396249**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE398 **CON EDISON SERVICE BOX: 7907** **NJ MANIFEST** **S120665941**
West **55 WALTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.213 mi.
1122 ft. **Site 2 of 7 in cluster AE**

Relative:
Higher

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004288635
Mail Address:	IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JUAN RODRIGUEZ
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003007739GBF
EPA ID:	NYP004288635
Date Shipped:	2/17/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON SERVICE BOX: 7907 (Continued) **S120665941**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AE399 **CON EDISON SERVICE BOX: 7907** **RCRA NonGen / NLR** **1016150192**
West **55 WALTON ST** **FINDS** **NYP004288635**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.213 mi. **NY MANIFEST**
1122 ft. **Site 3 of 7 in cluster AE**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/28/2017
Facility name:	CON EDISON SERVICE BOX: 7907
Facility address:	55 WALTON ST BROOKLYN, NY 11211
EPA ID:	NYP004288635
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	JUAN RODRIGUEZ
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	347-865-5931
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON SERVICE BOX: 7907 (Continued) **1016150192**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/12/2013
Site name: CON EDISON SERVICE BOX: 7907
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110055430644

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016150192
Registry ID: 110055430644
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055430644

NY MANIFEST:
Name: CON EDISON
Address: 55 WALTON ST
City,State,Zip: BROOKLYN, NY 11211
Country: USA
EPA ID: NYP004288635
Facility Status: Not reported
Location Address 1: 55 WALTON ST
Code: BP
Location Address 2: SERV BOX 7907
Total Tanks: Not reported

CON EDISON SERVICE BOX: 7907 (Continued) **1016150192**

Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004288635
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/12/2013
Trans1 Recv Date:	02/12/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/12/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004288635
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840391JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1

CON EDISON SERVICE BOX: 7907 (Continued) **1016150192**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG400 **CON EDISON** **RCRA NonGen / NLR** **1014396431**
ESE **FLUSHING AVE & BROADWAY** **NJ MANIFEST** **NYP004186953**
1/8-1/4 **BROOKLYN, NY 11206** **NY MANIFEST**
0.213 mi.
1124 ft. **Site 1 of 13 in cluster AG**

Relative:
Higher

Actual:
26 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	FLUSHING AVE & BROADWAY BROOKLYN, NY 11206
EPA ID:	NYP004186953
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	CAROLINE ISKANDER
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	718-666-4714
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/27/2009

CON EDISON (Continued) **1014396431**

Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004835597
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002625214GBF
EPA ID: NYP004835597
Date Shipped: 9/8/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported

CON EDISON (Continued) **1014396431**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

EPA Id:	NYP004186953
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894835GBF
EPA ID:	NYP004186953
Date Shipped:	08/06/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	NJD003812047
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/06/2009
Date Trans2 Transported Waste:	08/10/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/10/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON (Continued) **1014396431**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 G

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	FLUSHING AVE & BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004186953
Facility Status:	Not reported
Location Address 1:	FLUSHING AVE & BROADWAY MH #7435
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004186953
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/2009
Trans1 Recv Date:	08/06/2009

CON EDISON (Continued) **1014396431**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/10/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004186953
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894835GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG401 **CON EDISON** **NY MANIFEST** **S117736988**
ESE **FLUSHING AVE AND BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.213 mi.
1124 ft. **Site 2 of 13 in cluster AG**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	FLUSHING AVE AND BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004594404
Facility Status:	Not reported
Location Address 1:	FLUSHING AVE AND BROADWAY

Actual:
26 ft.

CON EDISON (Continued) **S117736988**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004594404
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/11/2014
Trans1 Recv Date:	07/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004594404
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774488JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117736988**

Quantity:	1500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG402 **CONSOLIDATED EDISON** **NY MANIFEST** **S109064806**
ESE **BROADWAY & FLUSHING AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.213 mi.
1124 ft. **Site 3 of 13 in cluster AG**

Relative:
Higher

Actual:
26 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	BROADWAY & FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP004157848
Facility Status:	Not reported
Location Address 1:	BROADWAY & FLUSHING AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004157848
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2008
Trans1 State ID:	NYD006982359

CONSOLIDATED EDISON (Continued) **S109064806**

Trans2 State ID:	Not reported
Generator Ship Date:	04/11/2008
Trans1 Recv Date:	04/11/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/14/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004157848
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001437488FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG403 **CON EDISON** **NY MANIFEST** **S117067134**
ESE **BROADWAY & FLUSHING AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.213 mi.
1124 ft. **Site 4 of 13 in cluster AG**

Relative: **Higher**
Actual: **26 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	BROADWAY & FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA

CON EDISON (Continued) **S117067134**

EPA ID:	NYP004598736
Facility Status:	Not reported
Location Address 1:	BROADWAY & FLUSHING AVE
Code:	BP
Location Address 2:	MH 1027
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004598736
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004598736
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774100JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117067134**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG404 **CON EDISON** **RCRA NonGen / NLR** **1019907565**
ESE **FLUSHING AVE & BROADWAY** **NYP004835597**
1/8-1/4 **BROOKLYN, NY 11233**
0.213 mi.
1124 ft. **Site 5 of 13 in cluster AG**

Relative:
Higher

Actual:
26 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/08/2015
Facility name:	CON EDISON
Facility address:	FLUSHING AVE & BROADWAY BROOKLYN, NY 11233
EPA ID:	NYP004835597
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

CON EDISON (Continued) **1019907565**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/08/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

AG405
ESE
1/8-1/4
0.213 mi.
1124 ft.

MTA NYCT - FLUSHING AVE STATION J-LINE **RCRA NonGen / NLR** **1004761232**
FLUSHING AVE & BROADWAY **NY MANIFEST** **NYR000082081**
BROOKLYN, NY 11206

Site 6 of 13 in cluster AG

Relative:
Higher

Actual:
26 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: MTA NYCT - FLUSHING AVE STATION J-LINE
Facility address: FLUSHING AVE & BROADWAY
BROOKLYN, NY 11206
EPA ID: NYR000082081
Mailing address: BROADWAY 3RD FLOOR
NEW YORK, NY 10004
Contact: WILLIAM JEHLE
Contact address: BROADWAY 3RD FLOOR
NEW YORK, NY 10004
Contact country: US
Contact telephone: 646-252-3500
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 3RD FLOOR
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: 646-252-3500
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MTA NEW YORK CITY TRANSIT
Owner/operator address: 2 BROADWAY 3RD FLOOR
NEW YORK, NY 10004
Owner/operator country: US
Owner/operator telephone: 646-252-3500
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal

MTA NYCT - FLUSHING AVE STATION J-LINE (Continued) **1004761232**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MTA NYCT - FLUSHING AVE STATION J-LINE
Classification: Not a generator, verified

Date form received by agency: 05/03/2000
Site name: MTA NYCT - FLUSHING AVE STATION J-LINE
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NY MANIFEST:
Name: NYCTA
Address: FLUSHING AVE & BROADWAY
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYR000082081
Facility Status: Not reported
Location Address 1: FLUSHING AVE & BROADWAY
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: 10004
Location Zip 4: Not reported

MTA NYCT - FLUSHING AVE STATION J-LINE (Continued) **1004761232**

NY MANIFEST:

EPAID:	NYR000082081
Mailing Name:	NYCTA
Mailing Contact:	TEEDA MOORE
Mailing Address 1:	2 BROADWAY - 3RD FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462523508

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	02/14/2011
Trans1 Recv Date:	02/14/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/14/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000082081
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000202152WAS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	360.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008

MTA NYCT - FLUSHING AVE STATION J-LINE (Continued) **1004761232**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE406 **M.B.M. MFG.** **NY UST** **U004047473**
West **70 LORIMER STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.215 mi.
1137 ft. **Site 4 of 7 in cluster AE**

Relative:
Higher

Actual:
14 ft.

UST:

Name:	M.B.M. MFG.
Address:	70 LORIMER STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-608469 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/04/2008
UTM X:	588573.89903
UTM Y:	4506167.75521
Site Type:	Other

Affiliation Records:

Site Id:	30321
Affiliation Type:	Facility Owner
Company Name:	DAVID GOLDSTEIN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	127 SEVEN SPRING ROAD
Address2:	Not reported
City:	MONROE
State:	NY
Zip Code:	10950
Country Code:	001
Phone:	(845) 783-9859
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30321
Affiliation Type:	Mail Contact
Company Name:	DAVID GOLDSTEIN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	127 SEVEN SPRING ROAD
Address2:	Not reported
City:	MONROE
State:	NY
Zip Code:	10950
Country Code:	001

M.B.M. MFG. (Continued) **U004047473**

Phone:	(845) 783-9859
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30321
Affiliation Type:	Facility Operator
Company Name:	M.B.M. MFG.
Contact Type:	Not reported
Contact Name:	DAVID GOLDSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 782-5342
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30321
Affiliation Type:	Emergency Contact
Company Name:	DAVID GOLDSTEIN
Contact Type:	Not reported
Contact Name:	DAVID GOLDSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-1624
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	65219
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	00
Date Test:	Not reported

M.B.M. MFG. (Continued) **U004047473**

Next Test Date: 10/11/2016
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 02/01/2018

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Y407 **CON EDISON** **RCRA NonGen / NLR** **1014396174**
South **747 PARK AVE** **NJ MANIFEST** **NYP004183547**
1/8-1/4 **BROOKLYN, NY 11206** **NY MANIFEST**
0.217 mi.
1146 ft. **Site 2 of 2 in cluster Y**

Relative:
Higher

Actual:
28 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/01/2016
Facility name: CON EDISON
Facility address: 747 PARK AVE
BROOKLYN, NY 11206
EPA ID: NYP004183547
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: CAROLINE ISKANDER
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 718-666-4714
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

CON EDISON (Continued) **1014396174**

Historical Generators:
Date form received by agency: 07/14/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004183547
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894713GBF
EPA ID:	NYP004183547
Date Shipped:	07/28/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/28/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

CON EDISON (Continued) **1014396174**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 G

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	747 PARK AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004183547
Facility Status:	Not reported
Location Address 1:	744 PARK AVE & DELMONICA PL - MH1085
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11202
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004183547
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2009
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/28/2009
Trans1 Recv Date:	07/28/2009
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **1014396174**

TSD Site Recv Date:	07/28/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004183547
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894713GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z408 **CON ED** **NY MANIFEST** **S118464072**
ENE **56 VARET ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.221 mi.
1165 ft. **Site 14 of 14 in cluster Z**

Relative: **Higher**
Actual: **21 ft.**

NY MANIFEST:

Name:	CON ED
Address:	56 VARET ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004861528
Facility Status:	Not reported
Location Address 1:	56 VARET ST
Code:	BP

CON ED (Continued) **S118464072**

Location Address 2:	SB 9101
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004861528
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/28/2015
Trans1 Recv Date:	10/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/28/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004861528
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245013JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000

CON ED (Continued) **S118464072**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AA409 **CON EDISON** **NJ MANIFEST** **S120676214**
WNW **UNION AVE & MIDDLETON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.221 mi.
1165 ft. **Site 11 of 14 in cluster AA**

Relative:
Higher

Actual:
16 ft.

NJ MANIFEST:

EPA Id:	NYP004833097
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624989GBF
EPA ID:	NYP004833097
Date Shipped:	9/1/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON (Continued) **S120676214**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AA410 **CON ED** **NY MANIFEST** **S119077531**
WNW **UNION AVE & MIDDLETON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.221 mi.
1165 ft. **Site 12 of 14 in cluster AA**

Relative: **Higher**
Actual: **16 ft.**

NY MANIFEST:

Name:	CON ED
Address:	UNION AVE & MIDDLETON ST
City,State,Zip:	BROOKLYN, NY 11211
Country:	USA
EPA ID:	NYP004833097
Facility Status:	Not reported
Location Address 1:	MIDDLETON ST AND UNION AVE
Code:	BP
Location Address 2:	SB 15372
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004833097
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON ED (Continued) **S119077531**

Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/01/2015
Trans1 Recv Date: 09/01/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/03/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004833097
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002624989GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AA411 **CON EDISON** **RCRA NonGen / NLR** **1019907354**
WNW **UNION AVE & MIDDLETON ST** **FINDS** **NYP004833097**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.221 mi.
1165 ft. **Site 13 of 14 in cluster AA**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/01/2015
Facility name:	CON EDISON
Facility address:	UNION AVE & MIDDLETON ST BROOKLYN, NY 11211
EPA ID:	NYP004833097
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/01/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069690864

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019907354**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019907354
Registry ID: 110069690864
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069690864

AB412 **30 FAMILY APT HOUSE** **NY AST** **U003384666**
ENE **77 VARET ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.222 mi.
1174 ft. **Site 4 of 8 in cluster AB**

Relative:
Higher

Actual:
20 ft.

AST:
Name: 30 FAMILY APT HOUSE
Address: 77 VARET ST
City,State,Zip: BROOKLYN, NY 11206
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-116823
Program Type: PBS
UTM X: 589378.15524
UTM Y: 4506304.53183
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 3952
Affiliation Type: Facility Owner
Company Name: 77 VARET ST HOLDING CORP C/O ABECO MANAGEMENT
Contact Type: MANAGER
Contact Name: ABE BETESH
Address1: 114 AVENUE T
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11223
Country Code: 001
Phone: (718) 265-1200
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-06-15

Site Id: 3952
Affiliation Type: Mail Contact
Company Name: 77 VARET ST HOLDING CORP
Contact Type: Not reported
Contact Name: 77 VARET HOLDING CORP.
Address1: C/O ABECO MANAGEMENT CORP.
Address2: 114 AVENUE T
City: BROOKLYN
State: NY
Zip Code: 11223
Country Code: 001

30 FAMILY APT HOUSE (Continued) **U003384666**

Phone: (718) 265-1200
EMail: ABE@ABECOMANAGEMENT.COM
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-06-15

Site Id: 3952
Affiliation Type: Facility Operator
Company Name: 30 FAMILY APT HOUSE
Contact Type: Not reported
Contact Name: GEORGE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 807-8431
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-06-15

Site Id: 3952
Affiliation Type: Emergency Contact
Company Name: 77 VARET ST HOLDING CORP C/O ABECO MANAGEMENT
Contact Type: Not reported
Contact Name: GEORGE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 807-8431
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-06-15

Tank Info:

Tank Number: 001
Tank Id: 4168
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

30 FAMILY APT HOUSE (Continued) **U003384666**

	L09 - Piping Leak Detection - Exempt Suction Piping
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/01/1980
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/10/2010
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AB413 **CON EDISON SERVICE BOX: 9102** **RCRA NonGen / NLR** **1016973341**
ENE **77 VARET ST** **NY MANIFEST** **NYP004471397**
1/8-1/4 **BROOKLYN, NY 11206**
0.222 mi.
1174 ft. **Site 5 of 8 in cluster AB**

Relative:
Higher

Actual:
20 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/19/2014
Facility name:	CON EDISON SERVICE BOX: 9102
Facility address:	77 VARET ST BROOKLYN, NY 11206
EPA ID:	NYP004471397
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

CON EDISON SERVICE BOX: 9102 (Continued) **1016973341**

Used oil transporter: No

Historical Generators:
Date form received by agency: 03/19/2014
Site name: CON EDISON SERVICE BOX: 9102
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 77 VARET ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004471397
Facility Status: Not reported
Location Address 1: F/O 77 VARET ST
Code: BP
Location Address 2: MH 9102
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004471397
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 03/19/2014
Trans1 Recv Date: 03/19/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/21/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004471397
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011694054JJK

CON EDISON SERVICE BOX: 9102 (Continued) **1016973341**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AH414 **221 MIDDLETON STREET** **NY VCP** **S118943256**
NW **221 MIDDLETON STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.223 mi.
1178 ft. **Site 1 of 5 in cluster AH**

Relative:
Higher

Actual:
15 ft.

VCP NYC:

Project ID:	13CVCP119K
Project Name:	221 MIDDLETON STREET
Project Address:	221 MIDDLETON STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	13CVCP119K
File Name:	2013-04-11.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP119K/2013-04-11.13CVCP119K.RIR.pdf

Project ID:	13CVCP119K
File Name:	2013-04-11.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP119K/2013-04-11.13CVCP119K.RAWP_Draft.pdf

Project ID:	13CVCP119K

221 MIDDLETON STREET (Continued) **S118943256**

File Name: 2013-04-11.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP119K/2013-04-11.13CVCP119K.FactSheet1.pdf

Project ID: 13CVCP119K
File Name: 2013-04-11.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP119K/2013-04-11.13CVCP119K.Translated_FactSheet1.pdf

Project ID: 13CVCP119K
File Name: 2013-04-11.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP119K/2013-04-11.13CVCP119K.Translated_CPS.pdf

---

415 NE 1/8-1/4 0.223 mi. 1180 ft. **LES-LEV CORP** **NY AST** **U003386747**
73 GRAHAM AVE **N/A**
BROOKLYN, NY 11206

Relative: Higher
Actual: 18 ft.

AST:
Name: LES-LEV CORP
Address: 73 GRAHAM AVE
City,State,Zip: BROOKLYN, NY 11206
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-246832
Program Type: PBS
UTM X: 589307.41225
UTM Y: 4506444.06133
Expiration Date: 07/07/2022
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 9672
Affiliation Type: Facility Owner
Company Name: LES-LEV CORP. C/O HSCMGMT CORP
Contact Type: MANAGING AGENT
Contact Name: JOSH KOPPEL
Address1: 850 BRONX RIVER RD, 108
Address2: Not reported
City: YONKERS
State: NY
Zip Code: 10708
Country Code: 001
Phone: (718) 761-3062
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-07-31

Site Id: 9672
Affiliation Type: Mail Contact
Company Name: HSC MGMT CORP
Contact Type: Not reported
Contact Name: JOSH KOPPEL

LES-LEV CORP (Continued) **U003386747**

Address1:	850 BRONX RIVER RD STE 108
Address2:	Not reported
City:	YONKERS
State:	NY
Zip Code:	10708
Country Code:	001
Phone:	(914) 237-1600
EMail:	JOSH.KOPPEL@HSCMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-31

Site Id:	9672
Affiliation Type:	Facility Operator
Company Name:	LES-LEV CORP
Contact Type:	Not reported
Contact Name:	JORGE PAZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 244-6299
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-31

Site Id:	9672
Affiliation Type:	Emergency Contact
Company Name:	LES-LEV CORP. C/O HSCMGMT CORP
Contact Type:	Not reported
Contact Name:	JOSH KOPPEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 237-1600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-31

Tank Info:

Tank Number:	001
Tank Id:	10623
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

LES-LEV CORP (Continued) **U003386747**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1949
Capacity Gallons:	2000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	10/25/2017
Material Name:	#2 fuel oil (on-site consumption)

AG416 **CON EDISON - MANHOLE 14010** **NY MANIFEST** **S123692313**
East **10 GRAHAM AVE** **N/A**
1/8-1/4 **NEW YORK, NY 11206**
0.224 mi.
1181 ft. **Site 7 of 13 in cluster AG**

Relative: **Higher**
Actual: **25 ft.**

NY MANIFEST:

Name:	CON EDISON - MANHOLE 14010
Address:	10 GRAHAM AVE
City,State,Zip:	NEW YORK, NY 11206
Country:	USA
EPA ID:	NYP005186897
Facility Status:	Not reported
Location Address 1:	10 GRAHAM AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005186897
Mailing Name:	CON EDISON - MANHOLE 14010
Mailing Contact:	ANNAMARIE MOYLAN
Mailing Address 1:	4 IRVING PLACE 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602278

CON EDISON - MANHOLE 14010 (Continued) **S123692313**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE417 **45 WALTON STREET** **NY VCP** **S118943517**
West **45 WALTON STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.224 mi.
1185 ft. **Site 5 of 7 in cluster AE**

Relative:
Lower

Actual:
13 ft.

VCP NYC:
Project ID: 15CVCP129K
Project Name: 45 WALTON STREET
Project Address: 45 WALTON STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP129K
File Name: 2014-07-30.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-07-30.15CVCP012K.43_Walton_Street.report.Revised_RIR.EBC.pdf

Project ID: 15CVCP129K
File Name: 2015-05-07.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP129K/2015-05-07.15CVCP129K.report.45_Walton_RAWP_FINAL.pdf

Project ID: 15CVCP129K
File Name: 2014-08-08.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-08-08.15CVCP012K.43-Walton_Street.Factsheet-1.pdf

Project ID: 15CVCP129K
File Name: 2014-08-08.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-08-08.15CVCP012K.43_Walton_Street.Translated_FactSheet-1.pdf

Project ID: 15CVCP129K
File Name: 2014-08-08.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-08-08.15CVCP012K.43_Walton_Street.Translated_CPS.pdf

Project ID: 15CVCP129K
File Name: 2015-05-07.Decision_Document
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP129K/2015-05-07.15EHAN480K.notice.45_Walton_Decision_Document.OER.pdf

Project ID: 15CVCP129K
File Name: 2015-05-12.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP129K/2015-05-12.15CVCP129K.45_Walton_street.Factsheet-2.pdf

Project ID: 15CVCP129K
File Name: 2015-05-12.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP129K/2015-05-12.15CVCP129K.45_Walton_street.Translated_FactSheet-

45 WALTON STREET (Continued) **S118943517**

2.pdf

AC418 **LOTUS CLEANERS** **RCRA-VSQG** **1004758895**
NNE **80 MANHATTAN AVE** **ICIS** **NYD987029188**
1/8-1/4 **BROOKLYN, NY 11206** **US AIRS**
0.225 mi. **FINDS**
1189 ft. **Site 4 of 4 in cluster AC** **ECHO**
NY DRYCLEANERS
Relative: Higher **NY MANIFEST**

Actual: 19 ft.

RCRA-VSQG:

Date form received by agency:	01/01/2007
Facility name:	MARS CLEANERS
Facility address:	80 MANHATTAN AVE BROOKLYN, NY 11206
EPA ID:	NYD987029188
Mailing address:	MANHATTAN AVE BROOKLYN, NY 11206
Contact:	SHUANG YUAN KAO
Contact address:	MANHATTAN AVE BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	718-963-1594
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SHUANG YUAN KAO
Owner/operator address:	43-61 149TH ST FLUSHING, NY 11355
Owner/operator country:	US
Owner/operator telephone:	718-461-7593
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	SHUANG YUAN KAO

LOTUS CLEANERS (Continued) **1004758895**

Owner/operator address: 43-61 149TH ST
FLUSHING, NY 11355
Owner/operator country: US
Owner/operator telephone: 718-461-7593
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: MARS CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/13/1996
Site name: MARS CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

ICIS:
Enforcement Action ID: NY000A0000261040105000313
FRS ID: 110002367028

LOTUS CLEANERS (Continued) **1004758895**

Action Name:	LOTUS CLEANERS 36047R071500313
Facility Name:	LOTUS CLEANERS
Facility Address:	80 MANHATTAN AVE BROOKLYN, NY 112062547
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.705054
Longitude in Decimal Degrees:	-73.944522
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610401050
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS (AFS):

Envid:	1004758895
Region Code:	02
County Code:	NY047
Programmatic ID:	AIR NY0000002610401050
Facility Registry ID:	110002367028
D and B Number:	Not reported
Facility Site Name:	LOTUS CLEANERS
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	SMI
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS (AFS):

Region Code:	02
Programmatic ID:	AIR NY0000002610401050
Facility Registry ID:	110002367028
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2000-07-22 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610401050
Facility Registry ID:	110002367028
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2001-07-19 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation

LOTUS CLEANERS (Continued) **1004758895**

Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401050
Facility Registry ID: 110002367028
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-05-10 00:00:00
Activity Status Date: 2005-05-10 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610401050
Facility Registry ID: 110002367028
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401050
Facility Registry ID: 110002367028
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-07-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:

Registry ID: 110002367028

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR SYNTHETIC MINOR

LOTUS CLEANERS (Continued) **1004758895**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004758895
Registry ID:	110002367028
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002367028

DRYCLEANERS:

Name:	LOTUS/MARS CLEANERS
Address:	80 MANHATTAN AVE.
City,State,Zip:	BROOKLYN, NY 11206
Facility ID:	2-6104-01050
Phone Number:	718-963-1594
Region:	Not reported
Registration Effective Date:	7/8/2003 13:32:59:26
Inspection Date:	15SEP1
Install Date:	95/98/17
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

NY MANIFEST:

Name:	RMA CLNRS
Address:	80 MANHATTAN AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYD987029188
Facility Status:	Not reported
Location Address 1:	80 MANHATTAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987029188
Mailing Name:	RMA CLNRS
Mailing Contact:	RMA CLNRS
Mailing Address 1:	80 MANHATTAN AVE

LOTUS CLEANERS (Continued) **1004758895**

Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189631594

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIT270012321
Generator Ship Date:	10/16/2018
Trans1 Recv Date:	10/16/2018
Trans2 Recv Date:	10/30/2018
TSD Site Recv Date:	10/30/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029188
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	019128607JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	130
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

LOTUS CLEANERS (Continued) **1004758895**

Click this hyperlink while viewing on your computer to access
2 additional NY MANIFEST: record(s) in the EDR Site Report.

AB419 **CON EDISON** **NJ MANIFEST** **S120677364**
ENE **76 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.226 mi.
1191 ft. **Site 6 of 8 in cluster AB**

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:

EPA Id:	NYP004846026
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014086221JJK
EPA ID:	NYP004846026
Date Shipped:	9/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON (Continued) **S120677364**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AB420 **CON EDISON** **RCRA NonGen / NLR** **1019908449**
ENE **76 GRAHAM AVE** **NYP004846026**
1/8-1/4 **BROOKLYN, NY 11206**
0.226 mi.
1191 ft. **Site 7 of 8 in cluster AB**

Relative:
Higher

Actual:
19 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/30/2015
Facility name:	CON EDISON
Facility address:	76 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYP004846026
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/30/2015
Site name:	CON EDISON

CON EDISON (Continued) **1019908449**

Classification: Small Quantity Generator

Violation Status: No violations found

AB421 **CON EDISON** **NY MANIFEST** **S118463061**
ENE **76 GRAHAM AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.226 mi.
1191 ft. **Site 8 of 8 in cluster AB**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	76 GRAHAM AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004846026
Facility Status:	Not reported
Location Address 1:	76 GRAHAM AVE
Code:	BP
Location Address 2:	SB 12996
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004846026
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/30/2015
Trans1 Recv Date:	09/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004846026
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014086221JJK
Import Indicator:	N

CON EDISON (Continued) **S118463061**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AI422 **V2107** **RCRA NonGen / NLR** **1007206769**
SW **2-48 GERRY** **NY MANIFEST** **NYP004018420**
1/8-1/4 **BROOKLYN, NY 11206**
0.226 mi.
1194 ft. **Site 1 of 5 in cluster AI**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/03/2001
Facility name:	V2107
Facility address:	2-48 GERRY BROOKLYN, NY 11206
EPA ID:	NYP004018420
Contact:	ANTHONY DRUMMINGS
Contact address:	2-48 GERRY BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No

V2107 (Continued) **1007206769**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/02/2001
Site name: V2107
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V2107
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Address: 2-48 GERRY
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004018420
Facility Status: Not reported
Location Address 1: 4048 METROPOLITAN AVE & RIVEN
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004018420
Mailing Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE0256724

V2107 (Continued) **1007206769**

Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	20854AD
Trans2 State ID:	Not reported
Generator Ship Date:	01/06/1999
Trans1 Recv Date:	01/06/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004018420
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	13386
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AI423 **V1821** **RCRA NonGen / NLR** **1007206768**
SW **2 GERRY STREET** **NY MANIFEST** **NYP004018412**
1/8-1/4 **BROOKLYN, NY 11206**
0.226 mi.
1194 ft. **Site 2 of 5 in cluster AI**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	01/03/2001
Facility name:	V1821
Facility address:	2 GERRY STREET BROOKLYN, NY 11206
EPA ID:	NYP004018412
Contact:	ANTHONY DRUMMINGS

Actual:
12 ft.

V1821 (Continued) **1007206768**

Contact address: 2 GERRY STREET
BROOKLYN, NY 11206
Contact country: US
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/02/2001
Site name: V1821
Classification: Not a generator, verified

Date form received by agency: 01/01/2001
Site name: V1821
Classification: Large Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Address: 2 GERRY STREET
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004018412
Facility Status: Not reported
Location Address 1: V4209 BRAGG ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: NEW YORK
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004018412
Mailing Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Mailing Contact: FRANKLIN MURRAY

V1821 (Continued) **1007206768**

Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0252090
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	43790A
Trans2 State ID:	Not reported
Generator Ship Date:	01/07/1999
Trans1 Recv Date:	01/07/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004018412
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	11745
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AI424 **NYCTA** **NY MANIFEST** **S119078495**
SW **FLUSHING & UNION AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.227 mi.
1197 ft. **Site 3 of 5 in cluster AI**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	NYCTA
Address:	FLUSHING & UNION AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYR000043455
Facility Status:	Not reported
Location Address 1:	FLUSHING AVE STA & UNION ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	Not reported
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000043455
Mailing Name:	NYCTA
Mailing Contact:	GERALD WENZ
Mailing Address 1:	370 JAY ST - RM 819
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182434581

NY MANIFEST:

Document ID:	NJA5222860
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	S8424
Trans2 State ID:	Not reported
Generator Ship Date:	12/10/2004
Trans1 Recv Date:	12/10/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000043455
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

NYCTA (Continued) **S119078495**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01000
Units:	P - Pounds
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AI425 **MTA NYCT - FLUSHING AVE STATION G LINE** **RCRA-VSQG** **1001203025**
SW **FLUSHING & UNION AVE** **NJ MANIFEST** **NYR000043455**
1/8-1/4 **BROOKLYN, NY 11206**
0.227 mi.
1197 ft. **Site 4 of 5 in cluster AI**

Relative: **Lower**
Actual: **12 ft.**

RCRA-VSQG:

Date form received by agency:	01/01/2007
Facility name:	MTA NYCT - FLUSHING AVE STATION G LINE
Facility address:	FLUSHING & UNION AVE BROOKLYN, NY 11206
EPA ID:	NYR000043455
Mailing address:	BROADWAY - 2ND FLOOR NEW YORK, NY 10004
Contact:	THOMAS A ABDALLAH
Contact address:	BROADWAY - 2ND FLOOR NEW YORK, NY 10004
Contact country:	US
Contact telephone:	646-252-3500
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

MTA NYCT - FLUSHING AVE STATION G LINE (Continued) **1001203025**

hazardous waste

Owner/Operator Summary:

Owner/operator name:	NYCT
Owner/operator address:	FLUSHING & UNION AVE BROOKLYN, NY 11206
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1920
Owner/Op end date:	Not reported

Owner/operator name:	MTA NYCT
Owner/operator address:	BROADWAY - 2ND FLOOR NEW YORK, NY 10004
Owner/operator country:	Not reported
Owner/operator telephone:	646-252-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1920
Owner/Op end date:	Not reported

Owner/operator name:	MTA NYCT
Owner/operator address:	BROADWAY - 2ND FLOOR NEW YORK, NY 10004
Owner/operator country:	US
Owner/operator telephone:	646-252-3500
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1920
Owner/Op end date:	Not reported

Owner/operator name:	NYCT
Owner/operator address:	FLUSHING & UNION AVE BROOKLYN, NY 11206
Owner/operator country:	Not reported
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1920
Owner/Op end date:	Not reported

Handler Activities Summary:

MTA NYCT - FLUSHING AVE STATION G LINE (Continued) **1001203025**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006
Site name: MTA NYCT - FLUSHING AVE STATION G LINE
Classification: Small Quantity Generator

Date form received by agency: 08/18/2003
Site name: MTA NYCT - FLUSHING AVE STATION G LINE
Classification: Small Quantity Generator

Date form received by agency: 07/25/1997
Site name: MTA NYCT - FLUSHING AVE STATION
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

NJ MANIFEST:

EPA Id: NYR000043455
Mail Address: 370 JAY ST - ROOM 819
Mail City/State/Zip: BROOKLYN 11201
Facility Phone: 7182434581
Emergency Phone: Not reported
Contact: GEARLD WEN
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

MTA NYCT - FLUSHING AVE STATION G LINE (Continued) **1001203025**

Manifest:

Manifest Number:	NJA5006923
EPA ID:	NYR000043455
Date Shipped:	03/03/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/03/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/03/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03300425
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5222860
EPA ID:	NYR000043455
Date Shipped:	12/10/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/10/2004

MTA NYCT - FLUSHING AVE STATION G LINE (Continued) **1001203025**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/10/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01240525
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5025287
EPA ID:	NYR000043455
Date Shipped:	08/05/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/05/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

MTA NYCT - FLUSHING AVE STATION G LINE (Continued) **1001203025**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08310421
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5104626
EPA ID:	NYR000043455
Date Shipped:	04/28/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/28/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/28/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05110421
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

AI426 **CON EDISON MANHOLE: 38077** **RCRA NonGen / NLR** **1016971418**
SW **MARCY AVE & FLUSHING AVE** **NY MANIFEST** **NYP004451571**
1/8-1/4 **BROOKLYN, NY 11206**
0.227 mi.
1197 ft. **Site 5 of 5 in cluster AI**

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/25/2014
Facility name:	CON EDISON MANHOLE: 38077
Facility address:	MARCY AVE & FLUSHING AVE 45 FEET N OF BROOKLYN, NY 11206
EPA ID:	NYP004451571
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/25/2014
Site name:	CON EDISON MANHOLE: 38077
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	MARCY AVE & FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004451571
Facility Status:	Not reported
Location Address 1:	446 MARCY AVE
Code:	BP
Location Address 2:	SB38077

CON EDISON MANHOLE: 38077 (Continued) **1016971418**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004451571
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2014
Trans1 Recv Date:	02/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004451571
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360100GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)

CON EDISON MANHOLE: 38077 (Continued) **1016971418**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AJ427 **CON EDISON** **NY MANIFEST** **S116551573**
East **39 DEBEVOICE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.228 mi.
1203 ft. **Site 1 of 2 in cluster AJ**

Relative:
Higher

Actual:
23 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	39 DEBEVOICE ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004500856
Facility Status:	Not reported
Location Address 1:	39 DEBEVOICE ST
Code:	BP
Location Address 2:	SB4149
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004500856
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/2014

CON EDISON (Continued) **S116551573**

Trans1 Recv Date:	04/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004500856
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407686GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE428 **43 WALTON STREET** **NY VCP** **S118943406**
West **43 WALTON STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.229 mi.
1209 ft. **Site 6 of 7 in cluster AE**

Relative:
Lower

Actual:
13 ft.

VCP NYC:

Project ID:	15CVCP012K
Project Name:	43 WALTON STREET
Project Address:	43 WALTON STREET
Borough:	BROOKLYN

VCP NYC:

43 WALTON STREET (Continued) **S118943406**

Project ID: 15CVCP012K
File Name: 2014-07-30.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-07-30.15CVCP012K.43_Walton_Street.report.Revised_RIR.EBC.pdf

Project ID: 15CVCP012K
File Name: 2014-08-11.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-08-11.15CVCP012K.43_Walton_Street.report.RAWP_DRAFT.pdf

Project ID: 15CVCP012K
File Name: 2014-08-08.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-08-08.15CVCP012K.43-Walton_Street.Factsheet-1.pdf

Project ID: 15CVCP012K
File Name: 2014-08-08.Translated_FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-08-08.15CVCP012K.43_Walton_Street.Translated_FactSheet-1.pdf

Project ID: 15CVCP012K
File Name: 2014-08-08.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP012K/2014-08-08.15CVCP012K.43_Walton_Street.Translated_CPS.pdf

---

AG429 **WOODHULL MEDICAL CENTER** **PA MANIFEST** **S112070521**
ESE **760 BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.230 mi.
1215 ft. **Site 8 of 13 in cluster AG**

Relative:
Higher

Actual:
28 ft.

Manifest Details:

Year:	2018
Manifest Number:	011655431FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	01/23/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	20
Unit:	Pounds

WOODHULL MEDICAL CENTER (Continued) **S112070521**

Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2018
Manifest Number:	011655841FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	02/06/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2018
Manifest Number:	011655999FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	02/27/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	40
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

WOODHULL MEDICAL CENTER (Continued) **S112070521**

Year:	2018
Manifest Number:	011642527FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	05/01/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U058
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	20
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011654803FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	04/17/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	120
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011655381FLE
Manifest Type:	TSD Copy

WOODHULL MEDICAL CENTER (Continued) **S112070521**

Generator EPA Id:	NYD981560972
Generator Date:	04/04/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011655389FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	04/04/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U010
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	40
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011655390FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	04/04/2018
Mailing Address:	Not reported

WOODHULL MEDICAL CENTER (Continued) **S112070521**

Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	40
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011656446FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	05/15/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	100
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011656449FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD981560972
Generator Date:	05/15/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

WOODHULL MEDICAL CENTER (Continued) **S112070521**

TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	40
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
476 additional PA_MANIFEST: record(s) in the EDR Site Report.

AG430 **NYC-HH - WOODHULL HOSPITAL** **NY Spills** **S106534422**
ESE **760 BROADWAY** **NY AIRS** **N/A**
1/8-1/4 **BROOKLYN, NY 11206** **NY MANIFEST**
0.230 mi.
1215 ft. **Site 9 of 13 in cluster AG**

Relative:
Higher

Actual:
28 ft.

SPILLS:

Name:	WOODHULL EMS HHC
Address:	760 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9811749 / Not Reported
Facility ID:	9811749
Facility Type:	ER
DER Facility ID:	270660
Site ID:	158462
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1998-12-17
Investigator:	ADZHITOM
Referred To:	ADDITIONAL EXCAVATION MAPS REQUESTED
Reported to Dept:	1998-12-17
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	1998-12-17
Spill Record Last Update:	2019-03-26
Spiller Name:	TOM SEGULJIC
Spiller Company:	WOODHULL HOSPITAL

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Spiller Address: 720 FLUSHING AVE
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY 12/22/98 1000 Spoke to Tom Seguljic at HRP (consultant) removing 2x550 gaoline - formerly used to fuel ambulances. Not installing new tanks. Contractor pulling tanks: AquaX - Peter Combats. Fill on top of tank - one dispenser island. Registration #2-406864. Encountered less than a shovel full of contamiantion when they broke through the concrete pad on top. Will collect excavation samples and submit tank closure report. 1/25/99 Tom Seguljic called. They performed borings to groundwater. There was a sheen on the wt. He thinks remediation will be required. He will submit TP report and results of borings when lab analysis is available. 2/16/99 Tom Seguljic called. Mailing report. Groundwater and soil contamination. Wanted to know if we require STIP/CAP etc. I said yes. TRANSFERRED FROM Y.KRIMGOLD. 10/07/05 DDC removed the site from LiRo's list because the tanks in question were owned by NYC Health and Hospital Corporation which was responsible for the site investigation and remediation. AZ 1/13/2006 Trying to obtain info on contacts from HHC Corporation. AZ 1/18/2006 Site should be investigated and remediated. I called J. Aliberti and requested information on HHC. I was given the following information: Ruth Kalbitzer - telephone number(212) 788-3312. I called this number and left a message. AZ 1/19/2006 Received a message from Wayne McNulty (Legal Affairs HHC) 212-788-3300. Left a message for him. Contacted Wayne McNulty (Legal Affairs HHC). He informed me that Mark Walter (attorney ph. 212-788-3300) is handling this case. He will be back on Monday and will contact me regarding this case. I contacted Tom Seguljic (HRP)518-899-3011. His company handled this project before. The site was handled by Jacob Krimgold. J. Krimgold approved a remedial plan. Consultants installed wells and encountered free phase - 0.08'(MW-10)-0.9'(MW-9). Also dissolved plume in a range of 15,000 ppb. DEC requested to design a remedial system and IRM. It has not been done. AZ 1/24/2006 I left a message for Mark Walter (HHC Legal). 1/25/2006 I contacted Mark Walter (Legal Affairs HHC) at 212-788-3303. He will contact the facility and get back to me in a day or two. I updated him on the site history. AZ 1/27/2006 I contacted Mark Walter (Legal Affairs HHC). He told me that Patrick Sullivan (ph. 718-963-8006 - Deputy Executive Director for Support Services) will be in charge for the site clean up. HRP will be there consultants. Consultants will assess the situation and submit a work plan and time time table next week. AZ 1/31/2006 I contacted Jeff Sotek (HRP-518-899-3011). We discussed Remedial Action Work Plan for the site. Initially there were 9 wells. I recommended to inspect, map, develop and sample all wells prior to conducting any work. They will proceed with the field work during this week. AZ 2/21/2006 Contacted Jeff Sotek (HRP-518-899-3011 Ext. 206). GW results are in. Report will be ready by the end of this week. I left a message for Jeffry. AZ 2/22/2006 Jeff Sotek (HRP). HRP completed the field work. Free phase was found in 2 wells - MW-2 and MW-5. About 2' of product was found in MW-5. MW-9, 10 have sheen. A report will be issued on Monday. Remedial Action Work Plan is to follow. I requested to send a vac truck to the facility to pump out the free phase immediately. AZ 2/28/2006 Reviewed groundwater sampling results and report by HRP Associates. The report indicates that dissolved contamination phase is present at concentrations up to around 20,000 ppb. The report has

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

deficiencies: no measurment of free phase thickness was performed, plume map and total VOC contcentrations were not submitted. I contacted Jeff Sotek and conveyed my comments. I requested to start vac truck operations immeadiately. He replied that vac truck operations will start this week. Remedial Action Work Plan will be submitted to DEC. AZ 3/2/2006 Contacted Jeff Sotek. He informed me that the vac truck operations will start on Friday March 3, 2006. I instructed him to arange future vac truck visits based on the recharge. AZ 3/16/2006 Received and reviewed a report from Warren & Penzer (Chet Bijoor 212-922-0077). They will take over this project. On March 3, 2006, they pumped product from MW-2, MW-5, VE-1,OB-1, OB-2and OB-3. 78 gallons of fluid and 29 gallons of free product was pumped. They are preparing a report for DEC (RAWP). AZ 6/13/2006 Contacted Warren & Penzer (Chet Bijoor 212-922-0077). Three pump outs were performed 14-20 gal of free product removed. Product levels are dropping. They are revising design plans. AZ 7/6/2006 Received update from Warren & Penzer (Chet Bijoor 212-922-0077). Pump out was performed last week - 75 gal of free product and water mixture was removed. AZ 8/15/2006 Reviewed Interim Progress report from Warren & Penzer. Pump out was performed on July 28, 2006 - 43 gallons of free product and water mixture was removed. AZ 11/21/2006 Reviewed Interim Progress report from Warren & Penzer received on November 16, 2006. Pump out was performed on October 20, 2006 - 106 gallons of free product and water mixture were removed. Eight gallons of product was pumped out. AZ 7-10-2007 Reviewed Remedial Action/Design Work Plan Report by Warren & Penzer submitted on May 25, 2007. The report is lacking important information: no IRM summary was included, no tables with free product thickness data were included, no free product isopleth map was included, no summary of soil sampling results included. The report proposed, as a remedial measure, a combination of SVE system for soil remediation and a vacuum truck for free phase as a secondary means. Total BTEX in groundwater ranged from less than 0.5 ppb to 13,600 ppb in MW-10. I left a message for Chet Bijoor (Warren & Penzer 212-922-0077). AZ 7-11-2007 I called Chet Bijoor and asked him about the deficiencies of the report. He said that he will call me back. AZ 7-12-2007 Joan Caiazzo (Facility Operation Area Senior Associate Director 718-963-8789). I requested to expedite the site remediation and submittal of the modified report. AZ 7-12-2007 I called Chet Bijoor (Warren & Penzer). I told him that the report contains a number of deficiencies. These deficiencies should be corrected. Chet told me that no pump outs were performed since November. Although, monitoring was performed. DEC has not received any monitoring reports since November 2006. AZ 7-16-2007 A letter to the consultant and the hospital was discussed with V.Brevdo and sent out: NYSDEC has not received any Monitoring Reports since November 2006. Therefore, the current status of the free product plume is unknown. In addition, the report is lacking IRM summary, free phase product thickness data, free phase product isopleth map or a similar plan with free phase product thickness information. On page 2 of the report was stated that the free phase product recovery and level measurements are provided in Appendix B. However, this Appendix appears to be missing. The remedial plan proposed an SVE system to treat soil contamination but no summary of soil sampling results was included in the report. The dissolved phase groundwater contamination was detected at the site but no remedy for the dissolved phase was proposed. Permanent remedial system could be used at the site to treat free phase and dissolved phase groundwater contamination.

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Please note, that the Department will be able to make a decision regarding remedial system selection only when all missing information is submitted to DEC. The remedial plan should include a monitoring plan and an implementation schedule. A schematic plan of the remedial system should be included in the proposal. Major parameters of the remedial system such as computations of drawdown, pumping rates and radius of influence; the capture zone, system monitoring parameters and frequency, and reporting frequency should specified in the report. The submittal of the remedial plan was significantly delayed. A revised remediation plan should be submitted to DEC within two weeks of the receipt of this letter. AZ 8-3-2007 I requested that Chet Bijoor submit hard copies with all info which was requested by DEC. Wells will be monitored next week. Consultant will submit the monitoring report with the results of well monitoring. Neither IRM nor gw monitoring was performed since November 2006. AZ 8-7-2007 I contacted Chet Bijoor and requested that the following items should be submitted to DEC: Free phase isopleth map or a block diagram map; 2. Dissolved phase map with historical data for total VOCs and SVOCs information. It also may be presented as block diagrams; 3. Free phase table; 4. Soil contamination plume map. Chet Bijoor responded that this info will be submitted to DEC within ten days. AZ 8-23-2007 An e-mail was sent to Chet Bijoor: I need hard copies of all figures. Results of the latest monitoring should be included in this report. Your analysis of the submitted data, old and new, together with the remediation action plan should be submitted to DEC. AZ 8-31-2007 I contacted Chet Bijoor via telephone and requested that the report with updated figures and tables should be submitted to DEC within next ten days. AZ 3-20-2008 Contacted Joan Caiazzo. She informed that she was reassigned and the person in charge is Lisa Scott-McKenze Senior Associate Executive Director 718-963-8007 and Kein Anderson (Deputy). Left a message for Lisa Scott-McKenze. AZ 3-20-2008 An e-mail was sent to Warren and Panzer and Kein Anderson (Woodhull Hospital): Dear Chet, I have reviewed Groundwater Monitoring Report for the above site submitted to DEC on February 7, 2008. The report lacks some important information and has to be modified. The report's deficiencies are discussed below: The report does not contain free product thickness monitoring data collected in August 2007. The report states that Warren and Panzer visited the site on August 7, 8 and 9, 2007, and performed groundwater investigation. However, free product data for MW-2 and MW-5 obtained as a result of this investigation were not reflected in Fig. 5 (Historical Free Product Reference). Historical free product data should be tabulated. DEC has previously requested in writing that a table with historical free product levels should be complied and submitted to DEC. The report is proposing installation of an internal combustion engine that will extract the product vapors and remove product. Unfortunately, Warren and Panzer did include any description or details regarding the proposed system. In August 2007, DEC sent a letter to Warren and Panzer. This letter requested that a schematic plan of the remedial system should be included in the remedial system proposal, as well as major parameters of the proposed system. The report dated February 5, 2008, does not contain this information. Detailed description of the proposed remedial system (internal combustion engine) which will address free product plume, its schematic plan and case studies should be submitted to the Department. The remedial plan should include a monitoring plan and an implementation schedule. System monitoring parameters, monitoring frequency, and reporting frequency

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

should specified in the report. A modified groundwater monitoring report containing detailed remedial system proposals should be submitted to DEC. Please note, that the Department will be able to make a decision regarding remedial system selection only when all missing information is submitted to DEC. AZ 5-30-2008 I contacted Brian Shaw @212-922-0077 regarding the modified Groundwater Monitoring Report dated April 11, 2008. The report had a number of deficiencies: 1. Figures 2 and 5 are not legible 2. The latest product thickness data is not reflected in Historical Free Product map (Figure 5) 3. Groundwater contour map was not included in the report. Groundwater flow direction is not shown on the plans. Historical groundwater plume data map with groundwater flow direction should be submitted to DEC. Figure 2 and 5 should be revised the so the mapped information is legible and submitted to DEC. Some groundwater plume delineation might be necessary. Revised info will be submitted to DEC. New proposals for a remedial strategy will be submitted to DEC. AZ 6-23-2008 Contacted Brian (Warren and Penzer). Reminded him that the revised remedial strategy should be submitted to DEC. He suggested a meeting to discuss this site. I concurred but suggested that the RP representative attends the meeting. Brian will get everybody availability and will call me back. AZ 6-25-2008 I left a message for Joan Caiazzo (Facility Operation Area Senior Associate Director 718-963-8789). AZ 6-26-2009 Received a phone call from Joan Caiazzo. She is no longer in charge of this project. The person in charge is Kein Andersen Facility Operation Manager 718-963-6869. I left a message for Kein Andersen. AZ 6-26-2008 Contacted Associate Executive Director 718-963-6869. We discussed the project. I listed DEC concerns It was agreed to set up a meeting on the week of July 14, 2008. AZ 7-18-2008 An e-mail was sent to Warren and Penzer and Woodhull Hospital: On July 17, 2008, Representatives of Woodhull Hospital and Warren & Panzer attended a meeting with NYSDEC. The goal of the meeting was to discuss the status of remediation at the above site. Since last sampling at the site was done in August 2007, another round of well gauging and groundwater sampling should be performed. Groundwater wells will be sampled for VOC contaminants. A monitoring report including the free product table and map, dissolved phase groundwater data summary and figures with historic data should be submitted to the NYSDEC within six (6) weeks. The data shall include total VOCs. If the groundwater monitoring determines that there is appreciable amount of free product present in any of the wells, a product pump out should be performed to remove the free product. The product pump out report should also include data on the amount of product removed as well the amount of GROUNDWATER with dissolved removed. Quarterly groundwater monitoring should be implemented thereafter. Monitoring reports will be submitted to the NYSDEC within four (4) weeks of the sampling event. Warren and Penzer should conduct soil sampling at the site. A plan with proposed soil borings should be submitted to DEC. Soil borings should be advanced throughout the site including locations in the vicinity of former soil borings WH-13 and WH-14. Wells, if installed, should be developed, purged sampled. Soil Sampling report should be submitted within eight weeks for NYSDEC review. Upon collection of the field data, a revised remedial strategy report based on the findings should be prepared by Warren and Penzer and submitted to the NYSDEC within 8 weeks for review. AZ 11-3-2008 An e-mail was sent to Bryan Shaw (Warren and Penzer), Woodhull Hospital and V.B.: I have reviewed a Monitoring Report for the above site submitted on September 8, 2008.

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

The report contains several deficiencies. In the previous correspondence with Warren and Penzer and at the meeting on July 17, 2008, DEC requested that a monitoring report must include a free product table and map. However, the submitted report does not contain a table with free product measurements. Also, according to the report, Figure 5 provides data collected from the monitoring events. However, submitted Figure 5 does not contain the latest free product data. Current free product data and free product tables should be included in a revised report and the revised report submitted to DEC within ten days. At the July 17, 2008, meeting Warren and Penzer stated that a soil sampling will be conducted. The soil sampling plan is overdue and should be submitted within ten days. The total VOC concentrations in MW-3, MW-9 and MW-10 require immediate attention. Warren and Penzer should submit to DEC a remedial strategy addressing dissolved phase groundwater plume. These remedial proposals should be submitted within ten days. Recovery wells installation is approved. Recovery wells should address free phase petroleum and the dissolved phase product. Warren and Penzer should submit design proposals for remediation of the dissolved phase groundwater contamination within ten days. Submitted groundwater and soil tables should contain NYSDEC Guidance Values. Laboratory data (STARS list of VOC and SVOC compounds) should be compared to NYSDEC Guidance Values and exceedances should indicated by bold print. Corrected groundwater tables should be included in the revised report and submitted to NYSDEC. Interim Remedial Activities (IRM) should be performed. Free phase product should be evacuated using peristaltic pump. Amount of the evacuated product should be recorded and included in monthly progress reports. Brief site progress reports describing field and laboratory activities should be submitted to DEC on a monthly basis. First monthly progress report is due by November 18, 2008. AZ 11-4-2008 I contacted Bryan Shaw. I requested that a recovery well is installed near MW-10 to remediate the dissolved phase plume. Soil borings were advanced. Bryan stated that soil contamination is concentrated around the former piping which has not been removed. I suggested considering hot spot soil excavation. AZ 11-20-2008 Received a modified report from W&P. W&P performed a product extraction event on 11/10/08. They are currently waiting for the report from the vendor to determine the product collected from groundwater. Once they receive the report they will expedite a long term remediation strategy in a formal RA report. W&P plans on performing another extraction early next month. AZ 12-24-2008 Received a modified report from W&P. They performed an enhanced fluid recovery on November 10, 2008. Approximately 2 gallons of vapor phase product was removed from MW-2 and RW-2. Approximately 958 gallons of impacted groundwater was removed from MW-2 and approximately 270 gallons from RW-2. Each well was vented for approximately 4 hours each. Another EFR is scheduled for January 12, 2009 in which they will check the influence on MW-9 and 10. An e-mail was sent to Bryan Shaw: A hard copy of the report to be submitted to DEC for a review. Please indicate how vapor phase was measured. Also, free product portion of the impacted groundwater should be measured. DEC previously informed W&P about this requirement. Soil sampling results in Table 1 should be compared to the DEC Guidelines Values and exceedances indicated in bold print. Separate maps for dissolved groundwater results and plume, and free phase plume map similar to what was presented in Fig. 2 (soil sampling results/plume) should be included in the report. Monthly progress reports should be submitted

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

to DEC. AZ 8-24-09 Received Remedial Action Work Plan (RAWP) dated July 8, 2009. The plan stated that Enhanced Fluid Recovery (EFR) was performed at the site as IRM. The report proposed a combination of two techniques for the site remediation: EFR and Chemical Oxidation (Regenox in-situ treatment). I contacted Bryan Shaw of WP and informed him that the report is missing essential information. The report is missing tables containing free phase product measurements in all monitored wells, free phase plume maps, tables with dissolved VOC concentrations, dissolved plume maps, tables containing soil contaminant concentrations and soil contamination plume maps. Results of the quarterly monitoring events should be included in RAWP. Free phase and dissolved data were previously requested by DEC on numerous occasions. RAWP can not be reviewed without this essential information. RAWP should be revised and resubmitted together with the e-version to DEC. The following e-mail was sent to Warren and Penzer, Woodhull Hospital; and V. Brevdo: Brian, I received Remedial Action Work Plan (RAWP) dated July 8, 2009. The plan stated that Enhanced Fluid Recovery (EFR) was performed at the site as IRM. The report proposed a combination of two techniques for the site remediation: EFR and Chemical Oxidation (Regenox in-situ treatment). The report is missing essential information: tables containing free phase product measurements in all monitoring wells, free phase plume maps, tables with dissolved VOC concentrations, dissolved plume maps, tables containing soil contaminant concentrations and soil contamination plume maps. Results of the quarterly monitoring should be included in RAWP. Free phase and dissolved data were previously requested by DEC on several occasions. RAWP can not be reviewed without this essential information. RAWP should be revised and resubmitted together with the e-version on a cd to DEC. Also, no quarterly monitoring reports were received from Warren and Penzer since December 2008. Quarterly Monitoring Reports should be submitted on time. AZ 6-8-2011 Received an e-mail from S. Frank LiRo stating that NYC Health and Hospitals Corp. contracted LiRo to help them with this spill. LiRo sampled at the site this spring and will submit a monitoring report on behalf of Health and Hospitals. They are repairing a bunch of the site monitoring wells as many of the roadboxes were in bad shape. Their intent is to come up with a remedial action plan. I forwarded to LiRo Remedial Action Work Plan (RAWP) dated July 8, 2009 by Warren and Penzer. AZ 10-19-2011 A letter and groundwater monitoring report dated 6-21-2011 and issued by LiRo stated that product was detected in two of the on-site monitoring wells, including MW-05 (up to 0.01 ft) and MW-02 (up to 0.43 ft). Data from nearby wells indicate that the free product is limited to a small area. Persistent groundwater contamination is evident in the area of the former USTs. A number of the site well casings were in poor condition. NYCHHC and LiRo have implemented a well repair program to secure and stabilize the wells. LiRo will prepare a revised Remedial Action Report and based on our discussion, the revised report will include the following: A summary table showing historical free product thickness levels and a free product extents map; Data summary tables and contaminant plume maps for soil and groundwater; Better documentation of existing contaminant levels and the basis for the remedial recommendations; and, A storage tank inventory to confirm that all USTs have been accounted for at the site. AZ 11-16-2011 LiRo submitted groundwater monitoring report for the above site dated July 26,2011. The report stated that no free phase was encountered on June 28 and 29, 2011. VOCs were detected in 13 of the 16 wells sampled. 3 wells had general

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

increase in BTEX concentrations. Concentrations ranged from ND to 69,200 ppb MTBE was detected above TOGS values in 10 samples and ranged from 0.5 to 10,000 ppb. LiRo will prepare a revised Remedial Action Plan and submit to DEC. AZ 1-19-2012 The following email was sent to S. Frank/F.Ashkan/V. brevdo: Dear Steve, I have reviewed Groundwater Monitoring Report dated October 18, 2012, for the above site. The report stated that trace of product was detected in well MW-02. Elevated PID readings were detected upon opening four wells (up to 1,841 ppb). Total VOCs were detected up to 12,600 ppb in 12 of the 15 wells sampled. MTBE was detected (up to 2,700 ppb) in seven of the 15 samples collected. The report proposed that a Revised Remedial Action Plan will be prepared following four quarters of groundwater monitoring on-site. This proposal is unacceptable. This site has been monitored for a prolonged period of time and enough monitoring data has been collected. A remedial system has to be designed to address the existing contamination. A Remedial Action Work Plan should be submitted to DEC within 30 days of this email. Also, this site should be discussed at the upcoming DEC/DDC meeting. AZ This email was forwarded to Kein Anderson (Kein.Anderson@woodhullhc.nychhc.org) who is a Woodhull Hospital Rep. AZ 6-25-2012 Reviewed Revised Remedial Action Report for this site dated March 21, 2012.The report stated that historically free product was detected in six site monitoring wells. Currently MW-2 contained 0.48 ft. of free product. Concentrations of total VOCs ranged from 2.69 ppb to above 27,650 ppb in well MW-05. The free product and contaminated soils are the likely source of the dissolved phase contamination. The remedial action report discussed five remedial technologies including technologies that may be implemented at the site: groundwater and free product extraction and treatment, excavation with off-site treatment and/or disposal and in-situ chemical oxidation injection (ISCO). Three different options were proposed for excavation: 222 cubic yard excavation, 1,000 cubic yard excavation and 3,500 cubic yard excavation. In order to select the best remedial option, I contacted S. Frank of LiRo and asked to submit three additional plume maps which would show different options for excavations including excavation areas. The excavation plans should be superimposed on free phase, groundwater and soil contaminant maps. LiRo will submit these maps for review. 6-27-2012 LiRo submitted requested maps for review. I asked LiRo if it is possible to add area around borings SB-13 and SB-15 with very high VOC concentrations to the excavation area. AZ 8-15-2012 Reviewed Groundwater Monitoring Report dated March 2012. Product was detected in MW-02. Elevated PID readings were detected upon opening wells in MW-2,MW-05,MWB-VE1, MWOB3D in a range of 123-1,458 ppb. VOC were detected in 14 of 15 wells sampled and ranged from 2.69 ppb to 27,650 ppb in MW-05. Four wells have had general overall increase in BTEX concentrations.MTBE ranged from 2.3 ppb to 4,400 ppb. AZ 10-10-2012 Reviewed Groundwater Monitoring Report dated May 18, 2012. product was detected in two wells. PID reading were recorded upon opening wells up to 1,296 ppb. Total VOCs in gw were up to 9,701 ppb in MWOB3D.AZ 10-22-12 An e-mail received from S. Frank: Alex, LiRo and NYCHHC discussed adding spot excavations that you requested at SB-13 and SB-15 at the Woodhull Hospital Site. The planned Alternative 4 excavation area could be expanded to include location SB-13 which had relatively high soil contaminant levels (total BTEX in soil on the order of 300 ppm). Location SB-15 is physically separated from the Alternative 4 excavation area and contaminant levels were much lower (Total BTEX in soil on the order

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

of 35 ppm) at the SB-15 location. We do not believe the residual contamination at SB-15 significantly contributes to the groundwater contamination at the site and do not feel that the additional cost of excavation at SB-15 is warranted. Please send a letter if our revised Remedial Action Plan is acceptable and we will move forward with the Site remediation. Thanks Steve Frank LiRo Engineers, Inc. I contacted S. Frank and discussed the proposed excavation. Exceedances in xylene are more than two orders of magnitude in the area of SB-15. This area should be addressed. Excavation or SVE system could be possible remedial options for this area. S. Frank will discuss site remediation with Woodhull hospital and send me a revised proposal. AZ 5-20-2016 I have contacted S. Frank and asked about the status of this site. He will get back to me with the update. AZ 5-23-2016 In response to DEC's request for additional excavation in the areas of historical boring locations SB-13 and SB-15, LiRo proposed an amended excavation plan. The plan consists of excavation in three discrete areas of contaminated soil The dimensions and depth are based on historical soil data which indicate contaminated soil to a depth of 10 feet in the main and SB-13 excavation areas and to a depth of 5 feet in the SB-15 excavation area. Because the added excavation areas (at SB-13 and SB-15) are very close to a retaining wall foundation, extreme caution will be exercised to protect the integrity of the foundation. The western extent of the excavations may be limited as necessary for protecting the foundation. If dewatering is required, water from the excavations will be removed using a vacuum truck. Once the excavations are complete, five soil samples will be collected from each area (four side walls and bottom of each excavation). These end point samples will be submitted for NYSDEC CP-51 Table 2 VOCs using method 8260. After completion of the sampling, Klozur CR - a self-activated persulfate oxidation system which couples chemical oxidation with aerobic and anaerobic bioremediation processes will be applied in the excavation to oxidize and bioremediate residual petroleum contamination. I left a message for S. Frank. Discussed the site with S. Frank. LiRo will resubmit the report with the following modifications: two bottom soil samples will be collected. Also, if groundwater is encountered in the excavation, a groundwater sample should be collected. AZ 6-3-2016 The following e-mail was sent to S. Frank and V. Brevdo: Dear Steve, I have reviewed the Amended Revised Remedial Action Plan for Woodhull Medical and Mental Health Center issued to NYSDEC on May 27, 2016. The Work Plan calls for the excavation of three discrete areas of contaminated soil. I concur with this plan. The Responsible Party and its contractors are solely responsible for the safe execution of all invasive work performed at the site, and in particular, are responsible for identifying subsurface utilities and safeguarding the structural integrity of any excavations, buildings, utilities, and other structures both on- and off-site that may be adversely affected by the work. The Responsible Party and its contractors must obtain any local, state or federal permits or approvals that may be required to perform the work necessary to address this spill. Furthermore, the Responsible Party and its contractors are solely responsible for the implementation of all appropriate health and safety measures during the performance of this work. Sincerely, Alex Zhitomirsky - Engineering Geologist 2 NYS Department of Environmental Conservation 47-40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 - Fax: 718.482.6390 Email: alexander.zhitomirsky@dec.ny.gov 4-10-2018 Left a message for Scott Yanuck at 631-673-0612 (Laurel Environmental). He called me back.

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

They are preparing a remedial proposal for Woodhull Hospital. AZ 3-26-2019 Reviewed Groundwater Monitoring Report by Laurel Env. (LEA) dated October 29, 2018, and received on November 29, 2018. Laurel performed groundwater monitoring and sampling at the site in October 2018. Samples were collected from ten of the fifteen pre-existing wells. The five wells not sampled either contained free product, were destroyed or couldn't be located. Product was detected in in the monitoring well MW-2 at the thickness of 0.75'. Total VOCs concentrations in groundwater were up to 15,782 ppb ppb in MW-5.AZ 3-26-2019 I have discussed the site with Scott Yanuck at 631-673-0612 (Laurel Environmental). He proposed a soil delineation and a follow-up soil excavation. They will submit to DEC a Work Plan for the soil delineation. AZ"

Remarks: "tank being removed odor on soil unknown cause at this time tank will be removed on tuesday and they will have more info at that time"

All Materials:

Site ID:	158462
Operable Unit ID:	1069013
Operable Unit:	01
Material ID:	312035
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WOODHULL EMS HHC -DDC
Address:	760 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9814981 / 2005-01-24
Facility ID:	9814981
Facility Type:	ER
DER Facility ID:	270660
Site ID:	158463
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1999-03-17
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1999-03-17
CID:	252
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-17

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Spill Record Last Update:	2005-01-24
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	JEFF FOTEK
DEC Memo:	"The spill is referred to spill # 9811749 and closed in consultation with Alex. -II (01/24/05)."
Remarks:	"HISTORICAL SPILL-SOIL FOUND TO BE CONTAMINATED DURING ON SITE CONSTRUCTION ACTIVITIES."

All Materials:

Site ID:	158463
Operable Unit ID:	1076006
Operable Unit:	01
Material ID:	556038
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WOODHULL MED CENTER
Address:	760 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1203508 / 2016-04-15
Facility ID:	1203508
Facility Type:	ER
DER Facility ID:	270660
Site ID:	466331
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2012-07-11
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2012-07-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-11
Spill Record Last Update:	2016-04-15
Spiller Name:	Not reported
Spiller Company:	WOODHULL MED CENTER
Spiller Address:	Not reported
Spiller Company:	999

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Contact Name: JESSE CRAWFORD
DEC Memo: "07/11/12- zhune spoke to Carol Castana(718-714-6898 from Empire Environmental. She said they found petroleum contamination while doing sidewalk flag where an old fill box was closed in 2010. Alfred Cigarra- Hospital contact. Facility Mnagement. 718-963-5874 07/11/12- Carol From Empire Environmental sent the foolowing email: As a follow-up to our conversation today, Empire Environmental Services was on site today at 760 Broadway, Brooklyn to replace 1 x sidewalk flag (5 x 5) at Woodhull Medical Center. Upon breaking up the concrete flag it was noted that there was petroleum contamination present under the sidewalk. The sidewalk flag that was being replaced is the location of a closed fillbox. The contamination present is not fresh product. In 2010 Empire Environmental closed the existing fillbox and installed a new fillbox in a different location. When the fillbox was closed we did not remove the concrete sidewalk flag, but repaired the concrete flag. At that time we obtained a Dept of Transportation (DOT) permit to perform the work on the sidewalk. In June 2012 the DOT issued a violation to Empire for repairing the sidewalk flag instead of replacing it, which is the reason why we were on site today. We will be placing a vapor barrier between the contaminated soil and the new concrete. This is a very busy pedestrian area and the sidewalk can not remain opened while the Medical Center determines its next course of action. 8/14/12-Alfred Cegarra sent the following email. Plan of Correction Woodhull Hospital will be working with it s consultants in order to determine the best course of action in order to meet the new oil burning regulations (Local Law 43). One of the proposed plans would require removing the existing no. 6 oil tanks that are buried under the sidewalk in favor of new oil tanks. This is the same location that Empire Environmental Services removed the residual oil from prior to repairing the sidewalk. The excavation of the old tanks (and related piping) will allow us to better examine the area in question and if needed, allow us to remove any remaining traces that may have been missed by Empire Environmental Services. Upon completion we will forward to your office the required documentation in order to satisfactory close out the report. 9/20/13-Zhune visited the site met Lisa R. Scott-Mckenzie (Senior associate Executive Diretor)and Alfred Cegarra (Facility Operations -Safety Director). Lisa said the proyect to upgrade the thank will star in March 2014. 8/23/13-Alfred Segarra sent the following email: Note that the New York Power Authority will be conducting soil testing near the fill port on September 25, 2013 in order to determine if any action is warranted. We will advise you of the test results as soon as they are available. 2/9/16-Russ sent the following email to Leszek. I guess there are two questions/issues: 1.Being that the tank had a hole in it, is there any concern that the tank leaked (should a spill have been called in, should there be any investigation to determine the absence/presence of a spill around the tank)? 2.Has Woodhull done everything that is necessary to address the old spill? If unknown, does this impact the decision to allow this variance (does additional work need to be completed and/or a tank removed in order to address the contamination at the site)? 2/10/16-Russ sent the following email to Lezek The TTT and structural assessment are not in DecDocs. I can get you a copy if you would like to take a look at them. The record is not clear on whether the TTT was done prior to or after the repair of the hole in the tank. The hole is located in the upper area of the tank and as such may not have leaked product if the volume of product in the tank

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

was always below the hole. It is not clear to me whether a spill should have been called in and/or investigated. I will be interested in the feedback from Veronica and Jeff on the spill situation. 2/16/16-Russ sent the following email to Joanna Veronica Zhune is requesting the information concerning the 2012 spill. While we are getting closer to approval, we are not giving the approval yet so it would not be wise to order the steel material for this project yet. 2/17/15-Zhune spoke to Joanna from Wendel Joanna said that I have to speak to Buss Brauksiek in regards to spill #120358. She also said the hospital is responsible to clean the spill. This spill is not incluiding in the project that she is working. 2/23/16-Zhune spoke to Alfres Cigarra. Alfred said he is not involve in this spill anymore the I have to speak to Ricardo Corrales. 2/23/16-Vought-Sent email response to inquiry via DEC Zielinksi via DEC Brauksieck that Russ, Our apologies on Veronica s lack of response to your below email. Unfortunately with a case load of 150 plus projects she is proverbially buried like most in the Region 2 Spills Unit. Veronica and I looked into your query below as to if the reported spill is in close proximity to the site and if Woodhull is completing all the work that is deemed to be necessary. We also noted your concerns in the DEC Remarks of the reported tanks in the sidewalk as well as the sidewalk also having soil contamination. Unfortunately, Woodhull has not submitted any site plan to date so as of yet we cannot answer whether the tanks will need to be removed as part of the soil remediation. Veronica noted she was in communication with Joanna last week and she inquired about the status of the spill and Joanna noted the spill was not part of the project and the project is on hold and the cleanup of the sidewalk spill is the responsibility of the hospital. Joanne noted to Veronica that additional questions regarding the spill should be directed to you. Veronica noted she has also called her contact for the spill, Alfred Cegarra, and left numerous messages since her last note entry in August 2013 but he has not returned her calls. We would like to draft and send out a letter to the responsible party, or parties, requiring delineation of the spill, collection of endpoint samples, and submission of a scaled site plan with all UST and piping locations. As per the PBS Registration, the owner of the tanks is WoodHall Medical & Mental . With your approval, and so that we may be consistent in our efforts, we would like to send out this letter to WoodHall Medical & Mental. We will be sure to copy you on the letter as well. Apologies again for the delay and as always if it is easier to discuss you can call me on my cell phone at 917-577-1728, Thanks. 2/23/16-Russ sent the following email to Jeff. Thanks for your response. I understand the work load situation down there. I agree with sending Woodhull a letter. I have seen the site plan (Leszek also has a copy) but it is not clear exactly where the spill was observed and whether it impacts the area around the tanks. The original letter from Woodhull concerning this tank lining project came in from Ricardo Corrales, Senior Associate Director, Capital Construction & Life Safety Management. His phone number is 718.963-6891. If the other contacts at Woodhull are unresponsive then I suggest contacting Ricardo. 2/25/16-Russ sent the following email to Joanna. I have had email conversation with Veronica and her boss Jeff. The result is the attached email that was sent on Tuesday on which you were copied. I am looking for Woodhull to respond to the email and have a clearer understanding that moving ahead with the spill cleanup and moving ahead on the tank project are not in conflict. At this point, the

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

spill file that you reviewed indicates that the complete cleanup can be accomplished when the tanks are removed. You have indicated that this statement is incorrect but I need confirmation from the facility/Veronica/Jeff that this spill cleanup can occur without disturbing the tanks. 2/25/16-Joanna sent the following email to Russ. Thank you for attaching the email& Never received it, but I do know that yesterday morning, I was told that Veronica had spoken to Ricardo Corrales from the hospital and that the hospital was hiring the services from Empire to follow NYSDEC protocol for clean-up. I have included Ricardo Corrales and Alfred Segarra in this email so they can confirm with you via email and document that this oil spill is nowhere near our construction site. 2/26/16-Joanna sent the following email to Russ Has Ricardo Corrales or Alfred Segarra contacted you in regards to the location of the oil spill? 2/26/16-Ricardo sent the following email to Russ. Please be advised that the oil spill occurred at an abandoned fill port that is nowhere near the construction site in question. We are awaiting a proposal from Empire to remediate the spill which they had left in a contained state several years ago. 2/26/26-Jeff sent the following email to Russ. To date Spills has not received any site plan with tank locations or any delineation data to know how big the spill is and as such we cannot confirm Riccardo s statement below that the oil spill occurred at an abandoned fill port that is nowhere near the construction site in question . We would would be able to answer the question if we had the delineated spill on the same site plan as the tanks in question. 2/26/16-Russ sent the following email to Jeff I appreciate the information. It would be helpful if you would reply to Ricardo s email so that they understand that DEC needs a site plan that includes tank location and the delineation data to demonstrate the accuracy of the statement that the spill is nowhere near the construction site in question. 2/26/16-Zhune sent the following email to Ricardo. We discussed the below with Russ and the additional information we need is a scaled site plan that includes both the tank and piping locations and the completely delineated spill (with sample locations and analyses). We look forward to the information and will review it as quick as possible so as to not affect the schedule for the tank project 2/26/16-Joanna sent the following email to Ricardo. When will this be issued to the NYSDEC? 2/26/16-Carol Castiania from Empire Environmental sent the following email We will be furnishing the proposal to Woodhull Hospital for remediation of the spill at Woodhull Hospital. Michael Giustiniani would like to speak with you to clarify where exactly the samples need to be taken. Can you please call him at (718) 714-6898 to discuss. 2/26/16-Jeff and I spoke with Michael Giustiniani from Empire(copied above) and he will be submitting a site plan with a brief site description in including information on the tank upgrades and proposal for further action on the spill (vz) 3/29/16-Carol from Empire sent the following email We have received the Purchase Order from Woodhull Hospital to proceed with the remediation of Spill #1203508. As per your request, attached please find the following documentation: .Letter from Empire Environmental Services with a brief description of the facility approved work to be performed. . Site Plan indicating the location of the contaminated soil to be remediated, location of previously closed fill box, location of underground storage tanks and location of potential receptors. Please note information regarding the tank upgrades was previously submitted to NYSDEC as requested by Russ Brauksieck. Empire Environmental is submitting the necessary

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

documentation to obtain a DOT permit as required for the removal of the sidewalk flags at the location of the soil contamination. Once the permit has been issued we will commence work at the site. 3/29/16-Zhune sent the folloing email to Carla The Region 2 Spills Unit reviewed your below email and site plan with the information in regards to Spill #1203508. The Department has no objections with the tank upgrade as proposed. Please ensure all tank upgrades are done with the approval of the DEC PBS Program copied above. We look forward to receiving the report with the endpoint sample analyses and a scaled site plan. 4/15/16- Jennifer Perez from Empire Environmental sent the following email We received the analytical report for the end point samples collected for the removal of spill # 1203508. We are working on completing the Spill Closure Report; the only item needed is the drum disposal manifest. We are coordinating the pickup of the 30 x 55 gallon drums with Lincoln Hospital. Attached is the sample table and the analytical report. All samples are under the NYS DEC soil cleanup levels. We would like to back fill this hole asap due to the high populated area. At this time I m requesting your approval to backfill on Monday, April 18th . Please advise if you require a site visit and if we have the okay to backfill the excavated area. In addition please advise if you require any additional information. We will remit the Spill Closure Report as soon as the 30 drums are picked up tentatively scheduled for next Friday. 4/15/16- Zhune reviewed the endpoint analytical results. The results are be below the NYSDEC CP-51 soil cleanup guidance, therefore the spill is closed. "

Remarks: "investigation underway"

All Materials:

Site ID:	466331
Operable Unit ID:	1216333
Operable Unit:	01
Material ID:	2214512
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	TRUCK SADDLE TANK
Address:	760 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0505859 / 2005-08-12
Facility ID:	0505859
Facility Type:	ER
DER Facility ID:	270660
Site ID:	350962
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	2005-08-12
Investigator:	SMSANGES
Referred To:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Reported to Dept:	2005-08-12
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-12
Spill Record Last Update:	2005-08-12
Spiller Name:	DAVID FRANK
Spiller Company:	SPECIALIZED TRANSPORTATIO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	PAUL EIDE
DEC Memo:	"Sangesland spoke to NYC Hazmat officer Paul Eide - He said the spill was all under control and sanitation was coming to sand the area"
Remarks:	"RAN OVER CURB AND PUNCTURED THE TANK: FIRE DEPT IS ON SCENE"

All Materials:

Site ID:	350962
Operable Unit ID:	1108499
Operable Unit:	01
Material ID:	2098440
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WOODHULL HOSPITAL
Address:	760 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0911917 / 2010-02-10
Facility ID:	0911917
Facility Type:	ER
DER Facility ID:	270660
Site ID:	424770
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2010-02-04
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	2010-02-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-10
Spill Record Last Update:	2010-02-10
Spiller Name:	Not reported
Spiller Company:	WOODHULL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ENGINEERING/HOUSE KEEPING
DEC Memo:	"2/9/10 - Raphael Ketani. I received an anonymous call from what sounded like a man. The voice sounded artificially altered. However, the person sounded like a man. He said that he wasn't sure who to speak to regarding a mercury spill in Woodhull Hospital. I asked him who he was. He simply said that he was from the nursing administration. He said that he is concerned for the patients. I asked him how he knew there was a mercury spill. He said that he heard about it from someone at the hospital. I asked him where the spill took place. He said that it was in the boiler room. I asked him what broke that released the mercury. He said that he didn't know. I asked him how he knew it was a mercury spill. He said that he was told it was metal filings, but he doesn't believe them. He said that the staff are covering up the spill. I asked him how large the spill is. He said that he thought it was a small spill, but that it was mercury. He asked for an inspector to come to site and look at the situation. I told him that the DEC doesn't respond to small mercury spills. I told him that usually the Fire Department responds to mercury spills and they would have more information about this if there actually was a spill and they responded. I added that if he is so concerned about the spill, he can call the New York Fire Department. They will come to investigate a mercury spill of any size. He said that he will get back to me. After this, he hung up the phone. 2/10/10 - Raphael Ketani. This mercury spill was called in today. As it is anonymous, and as it is a report from someone who heard about the spill from someone else, and as the caller couldn't give me detailed information yesterday, and as it is allegedly a small spill, I am closing the spill case."
Remarks:	"spill of mercury in a patient care hospital - believed to be in boiler room - stated beads all over floor - unsure of any cleanup being done -"

All Materials:

Site ID:	424770
Operable Unit ID:	1180521
Operable Unit:	01
Material ID:	2174423
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976
Material FA:	Hazardous Material
Quantity:	.00
Units:	L
Recovered:	Not reported
Oxygenate:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

AIRS:

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ATV
Permit Status:	Expired
Issue Date:	08/08/2017
Expiration Date:	Not reported
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	40.700069626
Longitude:	73.942974362

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ATV
Permit Status:	Expired
Issue Date:	06/11/1999
Expiration Date:	06/06/2002
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	40.700069626
Longitude:	73.942974362

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ATV
Permit Status:	Expired
Issue Date:	05/12/2015
Expiration Date:	08/08/2017
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Auth Type Code:	7
Latitude:	40.700069626
Longitude:	73.942974362
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ATV
Permit Status:	Expired
Issue Date:	11/20/2012
Expiration Date:	08/08/2017
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	40.700069626
Longitude:	73.942974362
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ATV
Permit Status:	Expired
Issue Date:	06/15/2007
Expiration Date:	06/04/2012
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	40.700069626
Longitude:	73.942974362
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ATV
Permit Status:	Expired
Issue Date:	01/16/2003
Expiration Date:	06/04/2007
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	40.700069626
Longitude:	73.942974362

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ATV
Permit Status:	Expired
Issue Date:	02/26/2008
Expiration Date:	06/04/2012
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	40.700069626
Longitude:	73.942974362

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	PM25-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.00033885
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Process Id: 002EI
Contaminant Name/cas: PM25-PRI
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.5174535
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: U00001
Process Id: EMGEI
Contaminant Name/cas: PM25-PRI
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.14576614
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: U00001
Process Id: 010FP
Contaminant Name/cas: 50000
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.02
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	129000
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0049
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	PM10-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.00091
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	205992
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0001
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	NOX
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.01175
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	107028
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.09
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	SO2
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.01177499
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	7440417
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	108883
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.41999998
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	7782492
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	191242
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0005
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	120127
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0019
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	VOC
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.00027

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	PM10-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.15547999
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	71432
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.95999997
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	NH3

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.4
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	010FP
Contaminant Name/cas:	CO
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.00125
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	206440
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0079
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7782492
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0033
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	205992
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0002
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	1330207
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.28999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	91203
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.05
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7439965
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.05
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	75070
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.79000002
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	7439976
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0003
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	106990
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.03999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7440439
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.15
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7439921
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.05999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	50000
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	6.90000009
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	VOC
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.182425
Unit:	TON
Auth Type Code:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	NOX
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	2.27519995
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	83329
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0002
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	SO2
Epa Control Code:	Not reported
Contol Eff:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Emissions:	0.04108499
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	NOX
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	13.0112001
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7440473
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.18999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Contaminant Name/cas: 83329
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0015
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: UIC001
Process Id: 002EI
Contaminant Name/cas: 207089
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0002
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: U00001
Process Id: EMGEI
Contaminant Name/cas: CO
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.49011999
Unit: TON
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

DEC Id: 2610400015
Emission Unit Id: U00001
Process Id: EMGEI
Contaminant Name/cas: 207089
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0002
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: UIC001
Process Id: 002EI
Contaminant Name/cas: 7440417
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0016
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: UIC001
Process Id: 002EI
Contaminant Name/cas: 7440020
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.28
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	71432
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.18999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	218019
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0002
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	120127
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0003
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	CO
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	5.7523198
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	56553
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0017
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7439976
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.02999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	206440
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0004
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	91203
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.07999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	50000
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	1.21000003
Unit:	LB
Auth Type Code:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	56553
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0002
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	50328
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0001
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	50328
Epa Control Code:	Not reported
Contol Eff:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Emissions:	0.0002
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	PM10-PRI
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.51745001
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7440484
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.01
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Contaminant Name/cas: 129000
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.0007
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: UIC001
Process Id: 002EI
Contaminant Name/cas: 110543
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 165.710006
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047
DEC Id: 2610400015
Emission Unit Id: U00001
Process Id: EMGEI
Contaminant Name/cas: 85018
Epa Control Code: Not reported
Contol Eff: Not reported
Emissions: 0.02999999
Unit: LB
Auth Type Code: Not reported
Latitude: Not reported
Longitude: Not reported

Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
City: BROOKLYN
Permit Type: Not reported
Permit Status: Not reported
Issue Date: Not reported
Expiration Date: Not reported
County Fips: 36047

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	NH3
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	67.1100006
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	86737
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0004
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	191242
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0002
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	108883
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.31
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	SO2
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.149615
Unit:	TON
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	85018
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0016
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	UIC001
Process Id:	002EI
Contaminant Name/cas:	7440382
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.02
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	86737
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.02999999
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	Not reported
Permit Status:	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
County Fips:	36047
DEC Id:	2610400015
Emission Unit Id:	U00001
Process Id:	EMGEI
Contaminant Name/cas:	218019
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	0.0004
Unit:	LB
Auth Type Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ASF
Permit Status:	Issued
Issue Date:	08/08/2017
Expiration Date:	08/07/2027
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	2
Latitude:	Not reported
Longitude:	Not reported

Name:	NYC-HH - WOODHULL HOSPITAL
Address:	760 BROADWAY
City:	BROOKLYN
Permit Type:	ASF
Permit Status:	Expired
Issue Date:	08/14/2003
Expiration Date:	11/12/2003
County Fips:	Not reported
DEC Id:	2610400015
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	Not reported
Longitude:	Not reported

NY MANIFEST:

Name:	WOODHULL HOSPITAL
Address:	760 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYD981560972
Facility Status:	Not reported
Location Address 1:	760 BROADWAY
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

EPAID:	NYD981560972
Mailing Name:	WOODHULL HOSPITAL
Mailing Contact:	WOODHULL HOSPITAL
Mailing Address 1:	760 BROADWAY
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189638732

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	PAD982661381
Trans2 State ID:	Not reported
Generator Ship Date:	06/26/2018
Trans1 Recv Date:	06/26/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/05/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981560972
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	012006456FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **S106534422**

Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
311 additional NY MANIFEST: record(s) in the EDR Site Report.

AG431 **NYC-HH - WOODHULL HOSPITAL** **RCRA-SQG** **1000189028**
ESE **760 BROADWAY** **NY UST** **NYD981560972**
1/8-1/4 **BROOKLYN, NY 11206** **NY AST**
0.230 mi. **ICIS**
1215 ft. **Site 10 of 13 in cluster AG** **US AIRS**
NJ MANIFEST
Relative:
Higher
Actual:
28 ft.

RCRA-SQG:
Date form received by agency: 01/01/2007
Facility name: WOODHULL HOSPITAL
Facility address: BROADWALL
BROOKLYN, NY 11206
EPA ID: NYD981560972
Contact: AL SEGARRA
Contact address: BROADWALL
BROOKLYN, NY 11206
Contact country: US
Contact telephone: 718-963-8000
Telephone ext.: 5874
Contact email: Not reported
EPA Region: 02
Land type: County
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: HEALTH & HOSPITAL CORP
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NYC HEALTH & HOSPITAL CORP
Owner/operator address: WORTH ST
NEW YORK, NY 10013
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: County
Owner/Operator Type: Operator
Owner/Op start date: 03/13/1980
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): Yes
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WOODHULL HOSPITAL
Classification: Small Quantity Generator

Date form received by agency: 02/25/2004
Site name: WOODHULL HOSPITAL
Classification: Large Quantity Generator

Date form received by agency: 01/01/2001
Site name: WOODHULL MEDICAL & MENTAL HEALTH CTR
Classification: Large Quantity Generator

Date form received by agency: 09/23/1986
Site name: WOODHULL HOSPITAL
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D008
. Waste name: LEAD

. Waste code: F003

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 06/15/2016
Date achieved compliance: 08/16/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 06/15/2016
Date achieved compliance: 06/22/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/15/2016
Date achieved compliance: 07/25/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 06/15/2016
Date achieved compliance: 07/25/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/15/2016
Date achieved compliance: 08/16/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 06/15/2016
Date achieved compliance: 06/15/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Listing - General
Date violation determined: 06/15/2016
Date achieved compliance: 08/16/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 06/15/2016
Date achieved compliance: 07/15/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD IS-Preparedness and Prevention
Date violation determined: 06/15/2016
Date achieved compliance: 08/16/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 06/15/2016
Date achieved compliance: 09/12/2016
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/27/2016
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 07/25/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/12/2016
Evaluation lead agency: State

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 08/16/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/16/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Listing - General
Date achieved compliance: 08/16/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 07/25/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 06/15/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 08/16/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD IS-Preparedness and Prevention
Date achieved compliance: 07/15/2016
Evaluation lead agency: State

Evaluation date: 06/15/2016
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 06/22/2016
Evaluation lead agency: State

Evaluation date: 06/03/2010
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

UST:
Name: WOODHULL MEDICAL & MENTAL HEALTH CENTER
Address: 760 BROADWAY
City,State,Zip: BROOKLYN, NY 11206

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Id/Status:	2-406864 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/15/2022
UTM X:	589415.45533
UTM Y:	4506032.74876
Site Type:	Hospital/Nursing Home/Health Care

Affiliation Records:

Site Id:	19672
Affiliation Type:	Facility Owner
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	DIRECTOR OF E&H
Contact Name:	JAVIER MIRANDA
Address1:	760 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 963-5874
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Site Id:	19672
Affiliation Type:	Mail Contact
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	Not reported
Contact Name:	JOSEPH RICCIO
Address1:	760 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 963-5874
EMail:	JOSEPH.RICCIO@WOODHULLHC.NYCHHC.ORG
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Site Id:	19672
Affiliation Type:	Facility Operator
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	Not reported
Contact Name:	JOSEPH RICCIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-5874
EMail:	Not reported
Fax Number:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Modified By:	ACDANIEL
Date Last Modified:	2018-05-09
Site Id:	19672
Affiliation Type:	Emergency Contact
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	Not reported
Contact Name:	JAVIER MIRANDA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 963-8944
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Tank Info:

Tank Number:	001
Tank ID:	23176
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	06/01/1972
Date Tank Closed:	01/05/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Tank Number:	002
Tank ID:	23177
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	06/01/1972
Date Tank Closed:	01/05/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	003
Tank ID:	23178
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	06/01/1972
Date Tank Closed:	01/05/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	004
Tank ID:	23179
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	27000
Install Date:	06/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	07/26/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TLYE
Last Modified:	08/01/2018

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
J05 - Dispenser - On Site Heating System (Supply/Return)
G04 - Tank Secondary Containment - Double-Walled (Underground)
E04 - Piping Secondary Containment - Double walled UG
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B08 - Tank External Protection - Retrofitted Impressed Current
L00 - Piping Leak Detection - None

Tank Number:	005
Tank ID:	23180
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	27000
Install Date:	06/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 07/26/2018
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TLYE
Last Modified: 08/01/2018

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B08 - Tank External Protection - Retrofitted Impressed Current
G04 - Tank Secondary Containment - Double-Walled (Underground)
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
J05 - Dispenser - On Site Heating System (Supply/Return)

Tank Number: 0D1
Tank ID: 23181
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 15000
Install Date: 06/01/1972
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 07/26/2018
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TLYE
Last Modified: 08/01/2018

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Tank Number:	0G1
Tank ID:	23182
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1998
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	0G2
Tank ID:	55734
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AST:

Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Address:	760 BROADWAY
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-406864
Program Type:	PBS
UTM X:	589415.45533
UTM Y:	4506032.74876
Expiration Date:	10/15/2022
Site Type:	Hospital/Nursing Home/Health Care

Affiliation Records:

Site Id:	19672
Affiliation Type:	Facility Owner
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	DIRECTOR OF E&H
Contact Name:	JAVIER MIRANDA
Address1:	760 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 963-5874
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Site Id:	19672
Affiliation Type:	Mail Contact
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	Not reported
Contact Name:	JOSEPH RICCIO
Address1:	760 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 963-5874
EMail:	JOSEPH.RICCIO@WOODHULLHC.NYCHHC.ORG
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Site Id:	19672

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Affiliation Type:	Facility Operator
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	Not reported
Contact Name:	JOSEPH RICCIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-5874
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Site Id:	19672
Affiliation Type:	Emergency Contact
Company Name:	WOODHULL MEDICAL & MENTAL HEALTH CENTER
Contact Type:	Not reported
Contact Name:	JAVIER MIRANDA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 963-8944
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-09

Tank Info:

Tank Number:	006
Tank Id:	219626
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

H02 - Tank Leak Detection - Interstitial - Manual Monitoring
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
K00 - Spill Prevention - None
L09 - Piping Leak Detection - Exempt Suction Piping
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
D11 - Pipe Type - Flexible Piping

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/24/2005
Capacity Gallons: 4000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DAFRANCI
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 007
Tank Id: 219627
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
D11 - Pipe Type - Flexible Piping
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 06/24/2005
Capacity Gallons: 4000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DAFRANCI
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 008
Tank Id: 219628
Material Code: 0008
Common Name of Substance: Diesel

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/24/2005
Capacity Gallons:	1250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	04/14/2017
Material Name:	diesel
Tank Number:	009
Tank Id:	219629
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/24/2005
Capacity Gallons:	1250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	04/14/2017
Material Name:	diesel
Tank Number:	010
Tank Id:	219630
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/24/2005
Capacity Gallons:	1100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MXLAY
Last Modified:	04/14/2017
Material Name:	diesel
Tank Number:	011
Tank Id:	219631
Material Code:	0008
Common Name of Substance:	Diesel

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
G06 - Tank Secondary Containment - Remote Impounding Area
L09 - Piping Leak Detection - Exempt Suction Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1972
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	diesel
Tank Number:	012
Tank Id:	219632
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

E00 - Piping Secondary Containment - None
G06 - Tank Secondary Containment - Remote Impounding Area
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1972
Capacity Gallons:	275
Tightness Test Method:	NN

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	diesel

ICIS:

Enforcement Action ID:	NY000A0000261040001500315
FRS ID:	110001609590
Action Name:	Not reported
Facility Name:	NYC-HH - WOODHULL HOSPITAL
Facility Address:	760 BROADWAY BROOKLYN, NY 11206
Enforcement Action Type:	Administrative Order
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	8062
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70007
Longitude in Decimal Degrees:	73.9429744
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400015
Facility NAICS Code:	622110
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261040001500308
FRS ID:	110001609590
Action Name:	Not reported
Facility Name:	NYC-HH - WOODHULL HOSPITAL
Facility Address:	760 BROADWAY BROOKLYN, NY 11206
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	8062
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70007
Longitude in Decimal Degrees:	73.9429744
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400015
Facility NAICS Code:	622110
Tribal Land Code:	Not reported

Enforcement Action ID:	02-2008-0820
FRS ID:	110001609590
Action Name:	Coler-Goldwater Hospital and Nursing Facility
Facility Name:	NYC-HH - WOODHULL HOSPITAL
Facility Address:	760 BROADWAY BROOKLYN, NY 11206
Enforcement Action Type:	RCRA 3008A AO For Comp And/Or Penalty
Facility County:	KINGS

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Program System Acronym: RCRAINFO
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 3008A
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.70061
Longitude in Decimal Degrees: -73.94172
Permit Type Desc: Not reported
Program System Acronym: NYD981560972
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: NYC-HH - WOODHULL HOSPITAL
Address: 760 BROADWAY

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

US AIRS (AFS):
Envid: 1000189028
Region Code: 02
County Code: NY047
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
D and B Number: Not reported
Facility Site Name: NYC-HH - WOODHULL HOSPITAL
Primary SIC Code: 8062
NAICS Code: 622110
Default Air Classification Code: MAJ
Facility Type of Ownership Code: Not reported
Air CMS Category Code: TVM
HPV Status: ADDRESSED HPV

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 14:06:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:02:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-02-19 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-06-30 00:00:00
Activity Status Date: 2016-07-09 11:04:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2016-08-24 00:00:00
Activity Status Date: 2016-09-09 07:16:58
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 1999-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2000-12-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2001-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2002-03-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2002-07-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2002-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2003-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-02-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-03-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-05-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2004-07-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2005-01-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2005-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-05-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-05-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2006-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2007-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2007-05-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2007-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2008-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2009-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2009-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2010-07-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2011-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2011-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-01-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-08-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2012-08-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2013-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2013-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-06-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Prevention of Accidental Release/General Duty Clause
Activity Date: 2014-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 14:06:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:02:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-19 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-06-30 00:00:00
Activity Status Date: 2016-07-09 11:04:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-08-24 00:00:00
Activity Status Date: 2016-09-09 07:16:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-03-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-07-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2002-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-02-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-03-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-05-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-07-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-01-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-05-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-05-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2007-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-07-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-01-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-08-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-08-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2014-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-06-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-04 00:00:00
Activity Status Date: 2002-09-04 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-11-08 00:00:00
Activity Status Date: 2000-11-08 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 14:06:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:02:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-02-19 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-06-30 00:00:00
Activity Status Date: 2016-07-09 11:04:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2016-08-24 00:00:00
Activity Status Date: 2016-09-09 07:16:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 1999-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2000-12-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2001-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2002-03-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2002-07-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2002-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2003-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-02-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-03-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-05-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2004-07-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-01-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2005-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-05-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-05-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2006-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-05-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2007-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2008-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2009-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2009-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2010-07-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2011-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2011-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-01-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-08-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2012-08-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2013-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2014-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-06-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Stratospheric Ozone Protection
Activity Date: 2014-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-11-08 00:00:00
Activity Status Date: 2002-09-04 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:10:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 14:06:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:02:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-02-19 00:00:00
Activity Status Date: 2016-06-09 07:01:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-06-30 00:00:00
Activity Status Date: 2016-07-09 11:04:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-08-24 00:00:00
Activity Status Date: 2016-09-09 07:16:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1999-02-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1999-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-12-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2001-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-03-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-07-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2002-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-02-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-03-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-05-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-07-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-01-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-05-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-05-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-05-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2007-07-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-01-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-07-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-03-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-04-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-07-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-01-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-08-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-08-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-07-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Activity Date: 2014-01-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-06-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-07-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-09-04 00:00:00
Activity Status Date: 2002-09-04 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000002610400015
Facility Registry ID: 110001609590
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-11-08 00:00:00
Activity Status Date: 2000-11-08 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

NJ MANIFEST:
EPA Id: NYD981560972

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	7189638520
Emergency Phone:	Not reported
Contact:	JESSE CRAWFORD
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	010559075JJK
EPA ID:	NYD981560972
Date Shipped:	8/28/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Waste:

Manifest Year:	Not reported
Waste Code:	U010 U058
Hand Code:	Not reported
Quantity:	10.00 Pounds

Manifest Number:	004730648JJK
EPA ID:	NYD981560972
Date Shipped:	06/03/2009
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	TXR000050930
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/03/2009
Date Trans2 Transported Waste:	06/04/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/04/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	90 P

Manifest Number:	012175786JJK
EPA ID:	NYD981560972

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Shipped:	12/17/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	80.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	120.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	40.00 Pounds
Manifest Number:	008479579JJK
EPA ID:	NYD981560972

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Shipped:	9/13/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	NJD000692061
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	U058
Hand Code:	H141
Quantity:	40.00 Pounds

Manifest Number:	009334246JJK
EPA ID:	NYD981560972
Date Shipped:	12/6/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	U058
Hand Code:	H141
Quantity:	29.00 Pounds

Manifest Number:	009334401JJK
EPA ID:	NYD981560972
Date Shipped:	10/24/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	U058
Hand Code:	H141
Quantity:	47.00 Pounds

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	14.00 Pounds

Manifest Number:	010982818JJK
EPA ID:	NYD981560972
Date Shipped:	5/21/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	40.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	40.00 Pounds
Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	40.00 Pounds

Manifest Number:	014817687JJK
EPA ID:	NYD981560972
Date Shipped:	11/17/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	014686849JJK
EPA ID:	NYD981560972
Date Shipped:	6/2/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	008479572JJK
EPA ID:	NYD981560972

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Shipped:	6/21/2011
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	70.00 gallons
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H020
Quantity:	15.00 gallons
Manifest Number:	010981658JJK
EPA ID:	NYD981560972
Date Shipped:	1/2/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	U010 U058
Hand Code:	Not reported
Quantity:	60.00 Pounds

Manifest Number:	002699725JJK
EPA ID:	NYD981560972
Date Shipped:	09/05/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	NYD049178296
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/05/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/06/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H06
Quantity:	80 P

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H06
Quantity:	40 P

Manifest Number:	014815606JJK
EPA ID:	NYD981560972
Date Shipped:	7/14/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	014345496JJK
EPA ID:	NYD981560972
Date Shipped:	4/21/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
Manifest Number:	008479842JJK
EPA ID:	NYD981560972
Date Shipped:	8/16/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	NJD000692061
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	U058
Hand Code:	H141
Quantity:	15.00 Pounds

Manifest Number:	010101474JJK
EPA ID:	NYD981560972
Date Shipped:	6/19/2012
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	10.00 gallons
Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	15.00 gallons
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	5.00 gallons
Manifest Number:	014817936JJK
EPA ID:	NYD981560972
Date Shipped:	10/20/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	004716814JJK
EPA ID:	NYD981560972
Date Shipped:	04/13/2009
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	TXR000050930
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/13/2009
Date Trans2 Transported Waste:	04/16/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/16/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	90 P

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	45 P

Manifest Number:	012321692JJK
EPA ID:	NYD981560972
Date Shipped:	10/22/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	80.00 Pounds

Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	40.00 Pounds

Manifest Number:	011607284JJK
EPA ID:	NYD981560972
Date Shipped:	9/10/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

NYC-HH - WOODHULL HOSPITAL (Continued) **1000189028**

Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: Not reported
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: U010 U058
Hand Code: Not reported
Quantity: 40.00 Pounds

AH432 **GEORGE ROYH** **NY UST** **U003127205**
NW **116 UNION AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11204**
0.230 mi.
1217 ft. **Site 2 of 5 in cluster AH**

Relative:
Higher

Actual:
16 ft.

UST:
Name: GEORGE ROYH
Address: 116 UNION AVENUE
City,State,Zip: BROOKLYN, NY 11204
Id/Status: 2-602780 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 588712.96515
UTM Y: 4506363.17807
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 24736
Affiliation Type: Facility Owner
Company Name: UNION PLAZA REALTY CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 401 MARCY AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11204
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 24736
Affiliation Type: Mail Contact
Company Name: UNION PLAZA REALTY CORP.
Contact Type: Not reported
Contact Name: GEORGE ROTH
Address1: 401 MARCY AVENUE

GEORGE ROYH (Continued) **U003127205**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11204
Country Code:	001
Phone:	(718) 384-3377
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24736
Affiliation Type:	Facility Operator
Company Name:	GEORGE ROYH
Contact Type:	Not reported
Contact Name:	GEORGE ROTH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-3377
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24736
Affiliation Type:	Emergency Contact
Company Name:	UNION PLAZA REALTY CORP.
Contact Type:	Not reported
Contact Name:	GEORGE ROTH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-3377
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	51498
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

GEORGE ROYH (Continued) **U003127205**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 51499
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 51500
Tank Status: Closed - Removed
Material Name: Closed - Removed

GEORGE ROYH (Continued) **U003127205**

Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	004
Tank ID:	51501
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

GEORGE ROYH (Continued) **U003127205**

Tank Number:	005
Tank ID:	51502
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	006
Tank ID:	51503
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel

GEORGE ROYH (Continued) **U003127205**

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 51504
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 51505
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

GEORGE ROYH (Continued) **U003127205**

Equipment Records:

H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	009
Tank ID:	51506
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	010
Tank ID:	51507
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

GEORGE ROYH (Continued) **U003127205**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 011
Tank ID: 51508
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 51509
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/1996

GEORGE ROYH (Continued) **U003127205**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 013
Tank ID: 51510
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 014

GEORGE ROYH (Continued) **U003127205**

Tank ID:	51511
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

AA433 **CONSOLIDATED EDISON** **NY MANIFEST** **1009239144**
WNW **MIDDLETON & HARRISON** **N/A**
1/8-1/4 **BROOKLYN, NY 12201**
0.231 mi.
1220 ft. **Site 14 of 14 in cluster AA**

Relative:
Higher

Actual:
16 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MIDDLETON & HARRISON
City,State,Zip:	BROOKLYN, NY 12201
Country:	USA
EPA ID:	NYP004057790
Facility Status:	Not reported
Location Address 1:	MIDDLETON & HARRISON
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	12201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004057790
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CONSOLIDATED EDISON (Continued) **1009239144**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NJA3171757
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	S09041
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2000
Trans1 Recv Date:	06/28/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004057790
Trans1 EPA ID:	NJD982744260
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01000
Units:	P - Pounds
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE434 **ULTIMATE AUTO REPAIR CORP.** **NY AST** **A100178151**
West **45 WALTON STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.231 mi.
1222 ft. **Site 7 of 7 in cluster AE**

Relative:
Lower

Actual:
13 ft.

AST:

Name:	ULTIMATE AUTO REPAIR CORP.
Address:	45 WALTON STREET
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-605910
Program Type:	PBS
UTM X:	588628.11523
UTM Y:	4506129.84186
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	27776
Affiliation Type:	Facility Owner
Company Name:	JOSEPH GOLDBERGER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	45 WALTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 599-1119
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27776
Affiliation Type:	Mail Contact
Company Name:	ULTIMATE AUTO REPAIR CORP.
Contact Type:	Not reported
Contact Name:	JOSEPH GOIDBERGER
Address1:	45 WALTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(718) 599-1119
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27776
Affiliation Type:	Facility Operator
Company Name:	ULTIMATE AUTO REPAIR CORP.
Contact Type:	Not reported
Contact Name:	JOSEPH GOIDBERGER

ULTIMATE AUTO REPAIR CORP. (Continued) **A100178151**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 599-1119
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27776
Affiliation Type:	Emergency Contact
Company Name:	JOSEPH GOLDBERGER
Contact Type:	Not reported
Contact Name:	JOSEPH GOIDBERGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 599-1119
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	01
Tank Id:	60700
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	D00 - Pipe Type - No Piping
	A00 - Tank Internal Protection - None
	G10 - Tank Secondary Containment - Impervious Underlayment
	J00 - Dispenser - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

ULTIMATE AUTO REPAIR CORP. (Continued) **A100178151**

Date Tank Closed:	02/04/2014
Register:	True
Modified By:	LXZIELIN
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

AJ435 **UNITED STATES POSTAL SERVICE/METRO/BUSHW** **NY AST** **S107782454**
East **47 DEBEVOISE STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.233 mi.
1231 ft. **Site 2 of 2 in cluster AJ**

Relative:
Higher

Actual:
24 ft.

AST:

Name:	UNITED STATES POSTAL SERVICE/METRO/BUSHW
Address:	47 DEBEVOISE STREET
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-453137
Program Type:	PBS
UTM X:	589448.42146
UTM Y:	4506199.24697
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	19830
Affiliation Type:	Facility Owner
Company Name:	UNITED STATES POSTAL SERVICE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1050 FORBELL STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11256-9998
Country Code:	001
Phone:	(718) 348-3602
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19830
Affiliation Type:	Mail Contact
Company Name:	UNITED STATES POSTAL SERVICE
Contact Type:	Not reported
Contact Name:	POST MASTER
Address1:	BROOKLYN PROCESSING & DISTRIBUTION CTR.
Address2:	1050 FORBELL STREET
City:	BROOKLYN
State:	NY
Zip Code:	11256-9998
Country Code:	001
Phone:	(718) 348-3602
EMail:	Not reported
Fax Number:	Not reported

UNITED STATES POSTAL SERVICE/METRO/BUSHW (Continued) **S107782454**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19830
Affiliation Type:	Facility Operator
Company Name:	UNITED STATES POSTAL SERVICE/METRO/BUSHW
Contact Type:	Not reported
Contact Name:	MR. MORRIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-5877
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19830
Affiliation Type:	Emergency Contact
Company Name:	UNITED STATES POSTAL SERVICE
Contact Type:	Not reported
Contact Name:	IRA CHAPLAN MFLDM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 348-3593
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	35647
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

UNITED STATES POSTAL SERVICE/METRO/BUSHW (Continued) **S107782454**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/1994
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	49138
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Coated Steel
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	04/01/1994
Capacity Gallons:	330
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1996
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AF436 **CON EDISON SERVICE BOX: 7700** **RCRA NonGen / NLR** **1017778796**
SSE **756 PARK AVE** **NYP004567491**
1/8-1/4 **BROOKLYN, NY 11206**
0.237 mi.
1251 ft. **Site 2 of 3 in cluster AF**

Relative:
Higher

Actual:
30 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/17/2014
Facility name:	CON EDISON SERVICE BOX: 7700
Facility address:	756 PARK AVE BROOKLYN, NY 11206
EPA ID:	NYP004567491
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	06/17/2014
Site name:	CON EDISON
Classification:	Small Quantity Generator

Date form received by agency:	06/17/2014
Site name:	CON EDISON
Classification:	Not a generator, verified

Violation Status: No violations found

AF437 **CON EDISON** **NY MANIFEST** **S117064272**
SSE **756 PARK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.237 mi.
1251 ft. **Site 3 of 3 in cluster AF**

Relative:
Higher

Actual:
30 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	756 PARK AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004567491
Facility Status:	Not reported
Location Address 1:	756 PARK AVE
Code:	BP
Location Address 2:	SB 7700
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004567491
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/2014
Trans1 Recv Date:	06/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004567491
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013255358JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117064272**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AD438 **CON EDISON MANHOLE: 38072** **RCRA NonGen / NLR** **1016971423**
WSW **MARCY AVE & WALLABOUT ST** **NY MANIFEST** **NYP004451639**
1/8-1/4 **BROOKLYN, NY 11206**
0.237 mi.
1251 ft. **Site 2 of 4 in cluster AD**

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/25/2014
Facility name:	CON EDISON MANHOLE: 38072
Facility address:	MARCY AVE & WALLABOUT ST NW COR BROOKLYN, NY 11206
EPA ID:	NYP004451639
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON MANHOLE: 38072 (Continued) **1016971423**

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/25/2014
Site name: CON EDISON MANHOLE: 38072
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: MARCY AVE & WALLABOUT ST
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004451639
Facility Status: Not reported
Location Address 1: N/W/C NORTH WEST COERN OF WALLABOUT ST
Code: BP
Location Address 2: SB38072
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004451639
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported

CON EDISON MANHOLE: 38072 (Continued) **1016971423**

Generator Ship Date:	02/25/2014
Trans1 Recv Date:	02/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004451639
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360101GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AH439 **KNIGHTS COLLISION REPAIR** **NY UST** **U004244778**
NW **120- 150 UNION AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.237 mi.
1253 ft. **Site 3 of 5 in cluster AH**

Relative: UST:
Higher

Name:	KNIGHTS COLLISION REPAIR
Address:	120- 150 UNION AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-608507 / Unregulated/Closed
Program Type:	PBS

Actual:
16 ft.

KNIGHTS COLLISION REPAIR (Continued) **U004244778**

Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588688.54898
UTM Y:	4506387.61651
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	30359
Affiliation Type:	Mail Contact
Company Name:	PAUL MATLI
Contact Type:	Not reported
Contact Name:	PAUL MATLI
Address1:	15 OCEAN AVE
Address2:	2ND FLOOR
City:	BROOKLYN
State:	NY
Zip Code:	11214
Country Code:	001
Phone:	(718) 636-0800
EMail:	PMATLI@HYDROTECHENVIRONMENTAL.COM
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

Site Id:	30359
Affiliation Type:	Facility Operator
Company Name:	KNIGHTS COLLISION REPAIR
Contact Type:	Not reported
Contact Name:	ROBLES REALTY LP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-4447
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

Site Id:	30359
Affiliation Type:	Emergency Contact
Company Name:	120 UNION AVE LLC
Contact Type:	Not reported
Contact Name:	MORAN SHAY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 439-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

KNIGHTS COLLISION REPAIR (Continued) **U004244778**

Site Id:	30359
Affiliation Type:	Facility Owner
Company Name:	120 UNION AVE LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	850 THIRD AVE SUITE 13D
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 439-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

Tank Info:

Tank Number:	001
Tank ID:	65261
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	06/22/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	09/18/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	HDDUPIGN
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	003
Tank ID:	256012
Tank Status:	Closed - Removed

KNIGHTS COLLISION REPAIR (Continued) **U004244778**

Material Name:	Closed - Removed
Capacity Gallons:	400
Install Date:	Not reported
Date Tank Closed:	06/22/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	HDDUPIGN
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number:	004
Tank ID:	256013
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	06/22/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	HDDUPIGN
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground

KNIGHTS COLLISION REPAIR (Continued) **U004244778**

G00 - Tank Secondary Containment - None

AH440 **KNIGHTS COLLISION EXPERTS INC** **RCRA NonGen / NLR** **1000235004**
NW **120 UNION AVE** **FINDS** **NYD012575643**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.237 mi. **NY MANIFEST**
1253 ft. **Site 4 of 5 in cluster AH**

Relative:
Higher

Actual:
16 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	KNIGHTS COLLISION EXPERTS INC
Facility address:	120 UNION AVE BROOKLYN, NY 11206
EPA ID:	NYD012575643
Mailing address:	UNION AVE BROOKLYN, NY 11206
Contact:	Not reported
Contact address:	UNION AVE BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

KNIGHTS COLLISION EXPERTS INC (Continued) **1000235004**

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: KNIGHTS COLLISION EXPERTS INC
Classification: Not a generator, verified

Date form received by agency: 03/30/1995
Site name: KNIGHTS COLLISION EXPERTS INC
Classification: Unverified

Date form received by agency: 06/28/1985
Site name: KNIGHTS COLLISION EXPERTS INC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/20/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110019850375

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans

KNIGHTS COLLISION EXPERTS INC (Continued) **1000235004**

to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000235004
Registry ID:	110019850375
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110019850375

NY MANIFEST:

Name:	KNIGHTS COLLISION EXPERTS INC
Address:	120 UNION AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYD012575643
Facility Status:	Not reported
Location Address 1:	120 UNION AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012575643
Mailing Name:	KNIGHTS COLLISION EXPERTS INC
Mailing Contact:	JOSEPH ROBLES
Mailing Address 1:	120 UNION AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2129634440

KNIGHTS COLLISION EXPERTS INC (Continued) **1000235004**

NY MANIFEST:

Document ID:	NYC3666677
Manifest Status:	K
seq:	Not reported
Year:	1996
Trans1 State ID:	GF2859NY
Trans2 State ID:	Not reported
Generator Ship Date:	01/02/1996
Trans1 Recv Date:	01/02/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/23/1996
Part A Recv Date:	/ /
Part B Recv Date:	02/26/1996
Generator EPA ID:	NYD012575643
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD077840148
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00036
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00112
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

KNIGHTS COLLISION EXPERTS INC (Continued) **1000235004**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AH441 **KNIGHTS COLLISION REPAIR** **NY AST** **A100412850**
NW **120- 150 UNION AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.237 mi.
1253 ft. **Site 5 of 5 in cluster AH**

Relative:
Higher

Actual:
16 ft.

AST:

Name:	KNIGHTS COLLISION REPAIR
Address:	120- 150 UNION AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608507
Program Type:	PBS
UTM X:	588688.54898
UTM Y:	4506387.61651
Expiration Date:	N/A
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	30359
Affiliation Type:	Mail Contact
Company Name:	PAUL MATLI
Contact Type:	Not reported
Contact Name:	PAUL MATLI
Address1:	15 OCEAN AVE
Address2:	2ND FLOOR
City:	BROOKLYN
State:	NY
Zip Code:	11214
Country Code:	001
Phone:	(718) 636-0800
EMail:	PMATLI@HYDROTECHENVIRONMENTAL.COM
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

Site Id:	30359
Affiliation Type:	Facility Operator
Company Name:	KNIGHTS COLLISION REPAIR
Contact Type:	Not reported
Contact Name:	ROBLES REALTY LP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-4447
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

KNIGHTS COLLISION REPAIR (Continued) **A100412850**

Site Id:	30359
Affiliation Type:	Emergency Contact
Company Name:	120 UNION AVE LLC
Contact Type:	Not reported
Contact Name:	MORAN SHAY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 439-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

Site Id:	30359
Affiliation Type:	Facility Owner
Company Name:	120 UNION AVE LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	850 THIRD AVE SUITE 13D
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 439-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-02

Tank Info:

Tank Number:	002
Tank Id:	244580
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

KNIGHTS COLLISION REPAIR (Continued) **A100412850**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2011
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/22/2015
Register:	True
Modified By:	HDDUPIGN
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

AK442 **ENGINE COMPANY 230** **NY AST** **A100175125**
SSW **701 PARK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11205**
0.239 mi.
1264 ft. **Site 1 of 3 in cluster AK**

Relative: **Higher**
Actual: **22 ft.**

AST:

Name:	ENGINE COMPANY 230
Address:	701 PARK AVENUE
City,State,Zip:	BROOKLYN, NY 11205
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-357383
Program Type:	PBS
UTM X:	588946.28347
UTM Y:	4505709.46215
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	17889
Affiliation Type:	Facility Owner
Company Name:	FIRE DEPARTMENT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	9 METROTECH
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-15

Site Id:	17889
Affiliation Type:	Mail Contact
Company Name:	FIRE DEPARTMENT
Contact Type:	Not reported
Contact Name:	DIR. - BLDGS. MAINT. DIV.
Address1:	48-34 35TH STREET

ENGINE COMPANY 230 (Continued) **A100175125**

Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17889
Affiliation Type:	Facility Operator
Company Name:	ENGINE COMPANY 230
Contact Type:	Not reported
Contact Name:	COUNTY OFFICER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 965-8230
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	17889
Affiliation Type:	Emergency Contact
Company Name:	FIRE DEPARTMENT
Contact Type:	Not reported
Contact Name:	EOC/NOTIFICATION DESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-12

Tank Info:

Tank Number:	001
Tank Id:	35051
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None

ENGINE COMPANY 230 (Continued) **A100175125**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2001
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	gasoline

Tank Number:	002
Tank Id:	35052
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

K01 - Spill Prevention - Catch Basin
G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off
H05 - Tank Leak Detection - In-Tank System (ATG)
H99 - Tank Leak Detection - Other
F05 - Pipe External Protection - Jacketed
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	diesel

AL443 **AVALON INDUSTRIES INC** **RCRA NonGen / NLR** **1000290354**
West **95 LORIMER ST** **FINDS** **NYD001233402**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.243 mi.
1284 ft. **Site 1 of 3 in cluster AL**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	AVALON INDUSTRIES INC
Facility address:	95 LORIMER ST BROOKLYN, NY 11206-4893
EPA ID:	NYD001233402
Mailing address:	LORIMER ST BROOKLYN, NY 11206
Contact:	Not reported
Contact address:	LORIMER ST BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MORTON R BERMAN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	MORTON R BERMAN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

AVALON INDUSTRIES INC (Continued) **1000290354**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: AVALON INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: AVALON INDUSTRIES INC
Classification: Not a generator, verified

Date form received by agency: 08/07/1980
Site name: AVALON INDUSTRIES INC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: U122
. Waste name: FORMALDEHYDE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/27/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/19/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004332810

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AVALON INDUSTRIES INC (Continued) **1000290354**

Registry ID: 110060250044

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000290354
Registry ID: 110004332810
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004332810

AG444 **5 STORY WAREHOUSE BLDG** **NY AST** **U004076612**
East **785 FLUSHING AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.243 mi.
1285 ft. **Site 11 of 13 in cluster AG**

Relative: **Higher**
Actual: **27 ft.**

AST:
Name: 5 STORY WAREHOUSE BLDG
Address: 785 FLUSHING AVENUE
City,State,Zip: BROOKLYN, NY 11206
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-130397
Program Type: PBS
UTM X: 589492.94146
UTM Y: 4506059.32851
Expiration Date: N/A
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 4094
Affiliation Type: Facility Owner
Company Name: REVA HOLDING CARE OF LIFEGUARD
Contact Type: Not reported
Contact Name: Not reported
Address1: 114 AVE T
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11223
Country Code: 001
Phone: (212) 563-0800
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-05-14

Site Id: 4094
Affiliation Type: Mail Contact
Company Name: REVA HOLDING CARE OF LIFEGUARD
Contact Type: Not reported

5 STORY WAREHOUSE BLDG (Continued) **U004076612**

Contact Name:	ABE BETESH
Address1:	114 AVENUE T
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11223
Country Code:	001
Phone:	(718) 265-1200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-05-14

Site Id:	4094
Affiliation Type:	Facility Operator
Company Name:	5 STORY WAREHOUSE BLDG
Contact Type:	Not reported
Contact Name:	ABE BETESH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 265-1200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-05-14

Site Id:	4094
Affiliation Type:	Emergency Contact
Company Name:	REVA HOLDING CARE OF LIFEGUARD
Contact Type:	Not reported
Contact Name:	ABE BETESH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 265-1200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-05-14

Tank Info:

Tank Number:	001
Tank Id:	5580
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None

5 STORY WAREHOUSE BLDG (Continued) **U004076612**

D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
H05 - Tank Leak Detection - In-Tank System (ATG)
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1975
Capacity Gallons:	5200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/22/1999
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

AD445 **CON EDISON MANHOLE: 473** **RCRA NonGen / NLR** **1016973503**
WSW **442 MARCY AVE** **NY MANIFEST** **NYP004473062**
1/8-1/4 **BROOKLYN, NY 11206**
0.243 mi.
1285 ft. **Site 3 of 4 in cluster AD**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/20/2014
Facility name:	CON EDISON MANHOLE: 473
Facility address:	442 MARCY AVE BROOKLYN, NY 11206
EPA ID:	NYP004473062
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

CON EDISON MANHOLE: 473 (Continued) **1016973503**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/20/2014
Site name: CON EDISON MANHOLE: 473
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Name: CON EDISON
Address: 442 MARCY AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA
EPA ID: NYP004473062
Facility Status: Not reported
Location Address 1: NORTHWEST CORNER OF MOREY AVE
Code: BP
Location Address 2: SB38072
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004473062
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/20/2014
Trans1 Recv Date: 03/20/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/21/2014
Part A Recv Date: Not reported

CON EDISON MANHOLE: 473 (Continued) **1016973503**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004473062
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002359116GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

446
WNW
1/8-1/4
0.246 mi.
1300 ft.

ANTONIA GONSALIS
118-120 HARRISON AVENUE
BROOKLYN, NY 11206

NY UST **U003418625**
N/A

Relative:
Higher

Actual:
17 ft.

UST:

Name:	ANTONIA GONSALIS
Address:	118-120 HARRISON AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-603840 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588665.47207
UTM Y:	4506339.86757

ANTONIA GONSALIS (Continued) **U003418625**

Site Type: Unknown

Affiliation Records:

Site Id: 25740
Affiliation Type: Facility Owner
Company Name: ANTONIA GONSALIS
Contact Type: Not reported
Contact Name: Not reported
Address1: 118-120 HARRISON AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11206
Country Code: 001
Phone: (718) 963-2538
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 25740
Affiliation Type: Mail Contact
Company Name: ANTONIA GONZALIS
Contact Type: Not reported
Contact Name: MEYER STEIN
Address1: 239 HAVENYER STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 963-2538
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 25740
Affiliation Type: Facility Operator
Company Name: ANTONIA GONSALIS
Contact Type: Not reported
Contact Name: MEYER STEIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 963-2538
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 25740
Affiliation Type: Emergency Contact
Company Name: ANTONIA GONSALIS
Contact Type: Not reported

ANTONIA GONSALIS (Continued) **U003418625**

Contact Name:	MEYER STEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-2538
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	01
Tank ID:	55693
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	02
Tank ID:	55694
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

ANTONIA GONSALIS (Continued) **U003418625**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 03
Tank ID: 55695
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: 11/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 04
Tank ID: 55696
Tank Status: Closed - Removed
Material Name: Closed - Removed

ANTONIA GONSALIS (Continued) **U003418625**

Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

447
NNW
1/8-1/4
0.247 mi.
1303 ft.

Relative:
Higher

Actual:
14 ft.

CON EDISON **NY MANIFEST** **S117537299**
BOERUM & LORIMER ST **N/A**
BROOKLYN, NY

NY MANIFEST:

Name:	CON EDISON
Address:	BOERUM & LORIMER ST
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP004698437
Facility Status:	Not reported
Location Address 1:	BOERUM & LORIMER ST
Code:	BP
Location Address 2:	V 4083
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004698437
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117537299**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/21/2014
Trans1 Recv Date:	11/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004698437
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773518JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AD448 **CON EDISON MANHOLE: 475** **RCRA NonGen / NLR** **1016973498**
WSW **298 WALLABOUT AVE** **NY MANIFEST** **NYP004473013**
1/8-1/4 **BROOKLYN, NY 11206**
0.247 mi.
1306 ft. **Site 4 of 4 in cluster AD**

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/20/2014
Facility name:	CON EDISON MANHOLE: 475
Facility address:	298 WALLABOUT AVE BROOKLYN, NY 11206
EPA ID:	NYP004473013
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/20/2014
Site name:	CON EDISON MANHOLE: 475
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Name:	CON EDISON
Address:	298 WALLABOUT AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004473013
Facility Status:	Not reported
Location Address 1:	W/S OF MARCY AVE 20' W/O WALLABOUT ST
Code:	BP
Location Address 2:	MH # 475
Total Tanks:	Not reported

CON EDISON MANHOLE: 475 (Continued) **1016973498**

Location City:	BROOKLYN
Location State:	NY
Location Zip:	11420
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004473013
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/20/2014
Trans1 Recv Date:	03/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004473013
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002405900GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1

CON EDISON MANHOLE: 475 (Continued) **1016973498**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AM449 **429 MARCY AVENUE** **NY UST** **U004045550**
West **429 MARCY AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.248 mi.
1308 ft. **Site 1 of 3 in cluster AM**

Relative: **Lower**
Actual: **13 ft.**

UST:

Name:	429 MARCY AVENUE
Address:	429 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-609922 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588630.42723
UTM Y:	4506080.12779
Site Type:	Other

Affiliation Records:

Site Id:	343917
Affiliation Type:	Facility Owner
Company Name:	WALTON MARCY HOLDING LLC
Contact Type:	PRESIDENT
Contact Name:	SIMAN DASHINSKY
Address1:	39 HAYWARD STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 246-4762
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-04-20

Site Id:	343917
Affiliation Type:	Mail Contact
Company Name:	HYDRO TECH ENVIRONMENTAL
Contact Type:	Not reported
Contact Name:	MARK ROBBINS
Address1:	2171 JERICHO TURNPIKE
Address2:	SUITE 345

429 MARCY AVENUE (Continued) **U004045550**

City:	COMMACK
State:	NY
Zip Code:	11725
Country Code:	001
Phone:	(631) 462-5866
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-05-12

Site Id:	343917
Affiliation Type:	Facility Operator
Company Name:	429 MARCY AVENUE
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-04-20

Site Id:	343917
Affiliation Type:	Emergency Contact
Company Name:	WALTON MARCY HOLDING LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-04-20

Tank Info:

Tank Number:	001
Tank ID:	196705
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/06/2004
Date Tank Closed:	04/14/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009

429 MARCY AVENUE (Continued) **U004045550**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None

Tank Number: 002
Tank ID: 196706
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/06/2004
Date Tank Closed: 04/14/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination

429 MARCY AVENUE (Continued) **U004045550**

Tank Number:	003
Tank ID:	196707
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/06/2004
Date Tank Closed:	04/14/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Number:	004
Tank ID:	196708
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/06/2004
Date Tank Closed:	04/14/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

429 MARCY AVENUE (Continued) **U004045550**

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	005
Tank ID:	196709
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/06/2004
Date Tank Closed:	04/14/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AN450 **CON EDISON** **NY MANIFEST** **S119078095**
ENE **97 VARET ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.248 mi.
1311 ft. **Site 1 of 3 in cluster AN**

Relative: **Higher**
Actual: **21 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	97 VARET ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004845901

CON EDISON (Continued) **S119078095**

Facility Status:	Not reported
Location Address 1:	OPP 97 VARET ST
Code:	BP
Location Address 2:	SB 9104
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004845901
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/30/2015
Trans1 Recv Date:	09/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004845901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014086219JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S119078095**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AN451 **CON EDISON** **RCRA NonGen / NLR** **1019908437**
ENE **97 VARET ST** **FINDS** **NYP004845901**
1/8-1/4 **BROOKLYN, NY 11206** **ECHO**
0.248 mi.
1311 ft. **Site 2 of 3 in cluster AN**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date form received by agency:	09/30/2015
Facility name:	CON EDISON
Facility address:	97 VARET ST BROOKLYN, NY 11206
EPA ID:	NYP004845901
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

CON EDISON (Continued) **1019908437**

Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/30/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069672580

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019908437
Registry ID: 110069672580
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069672580

AN452 **CON EDISON** **NJ MANIFEST** **S120677352**
ENE **97 VARET ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.248 mi.
1311 ft. **Site 3 of 3 in cluster AN**

Relative:
Higher

Actual:
21 ft.

NJ MANIFEST:
EPA Id: NYP004845901
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 014086219JJK
EPA ID: NYP004845901

CON EDISON (Continued) **S120677352**

Date Shipped:	9/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AG453 **JOYFUL/A & K/GOOD NEIGHBOR CLEANERS** **NY DRYCLEANERS** **S110246975**
East **789 FLUSHING AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.248 mi.
1312 ft. **Site 12 of 13 in cluster AG**

Relative: **Higher**
Actual: **27 ft.**

DRYCLEANERS:

Name:	JOYFUL/A & K/GOOD NEIGHBOR CLEANERS
Address:	789 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Facility ID:	2-6104-01170
Phone Number:	718-302-2932
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	05FEB11
Install Date:	99/00
Drop Shop:	Not reported

JOYFUL/A & K/GOOD NEIGHBOR CLEANERS (Continued) **S110246975**

Shutdown: Y
Alternate Solvent: Not reported
Current Business: Not reported

AG454 **JOYFUL CLEANERS** **RCRA-SQG** **1010566303**
East **789 FLUSHING AVE** **NY MANIFEST** **NYR000148882**
1/8-1/4 **BROOKLYN, NY 11206**
0.248 mi.
1312 ft. **Site 13 of 13 in cluster AG**

Relative:
Higher

Actual:
27 ft.

RCRA-SQG:
Date form received by agency: 08/15/2007
Facility name: JOYFUL CLEANERS
Facility address: 789 FLUSHING AVE
BROOKLYN, NY 11206-4143
EPA ID: NYR000148882
Mailing address: LAWRENCES AVE
BROOKLYN, NY 11230
Contact: MARK KOPLOWITZ
Contact address: LAWRENCES AVE
BROOKLYN, NY 11230
Contact country: US
Contact telephone: 718-288-7977
Contact email: Not reported
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: 1332 ACAME ART CORP
Owner/operator address: LAWRENCE AVE
BROOKLYN, NY 11230
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/15/2007
Owner/Op end date: Not reported

Owner/operator name: JOYFUL CLEANERS
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/15/2007

JOYFUL CLEANERS (Continued) **1010566303**

Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/14/2007
Site name: JOYFUL CLEANERS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

NY MANIFEST:
Name: JOYFUL CLEANERS
Address: 789 FLUSHING AVE
City,State,Zip: BROOKLYN, NY 11206-4143
Country: USA
EPA ID: NYR000148882

JOYFUL CLEANERS (Continued) **1010566303**

Facility Status:	Not reported
Location Address 1:	789 FLUSHING AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000148882
Mailing Name:	JOYFUL CLEANERS
Mailing Contact:	MARK KOPLOWITZ
Mailing Address 1:	12 LAWRENCE AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11230
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182887977

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD986607380
Generator Ship Date:	06/05/2007
Trans1 Recv Date:	06/05/2007
Trans2 Recv Date:	06/13/2007
TSD Site Recv Date:	06/14/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000148882
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	000049660SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

JOYFUL CLEANERS (Continued) **1010566303**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1755
Units:	P - Pounds
Number of Containers:	9
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	D007
Waste Code 1_3:	D008
Waste Code 1_4:	D039
Waste Code 1_5:	D040
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AK455 **CON EDISON - MANHOLE M1082** **NY MANIFEST** **S121968068**
SSW **695 PARK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11206**
0.250 mi.
1318 ft. **Site 2 of 3 in cluster AK**

Relative:
Higher

Actual:
22 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE M1082
Address:	695 PARK AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP005079742
Facility Status:	Not reported
Location Address 1:	695 PARK AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005079742
Mailing Name:	CON EDISON - MANHOLE M1082
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AK456 **CON EDISON - MANHOLE M1082** **RCRA-LQG** **1024891150**
SSW **695 PARK AVE** **NYP005079742**
1/8-1/4 **BROOKLYN, NY 11206**
0.250 mi.
1318 ft. **Site 3 of 3 in cluster AK**

Relative:
Higher

Actual:
22 ft.

RCRA-LQG:

Date form received by agency:	04/10/2018
Facility name:	CON EDISON - MANHOLE M1082
Facility address:	695 PARK AVE BROOKLYN, NY 11206
EPA ID:	NYP005079742
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	ALYSSA SOTTO
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	SOTTOA@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/10/2017
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	212-460-2757
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

CON EDISON - MANHOLE M1082 (Continued) **1024891150**

Owner/Op start date: 05/10/2017
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

AM457 **415-419 MARCY AVENUE** **NY VCP** **S118943585**
West **415-419 MARCY AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.255 mi.
1344 ft. **Site 2 of 3 in cluster AM**

Relative:
Lower

Actual:
13 ft.

VCP NYC:
Project ID: 16CVCP041K
Project Name: 415-419 MARCY AVENUE
Project Address: 415-419 MARCY AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 16CVCP041K
File Name: 2015-10-08.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP041K/2015-10-08.16EHAN044K.415-419_Marcy_Ave.report.Revised_RIR.EBC.v2.pdf

Project ID: 16CVCP041K
File Name: 2015-12-04.RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP041K/2015-12-04.16CVCP041K.16EHAN044K.report.415-419_Marcy_RAWP.EBC_V2.pdf

Project ID: 16CVCP041K
File Name: 2015-12-04.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP041K/2015-12-04.16CVCP041K.16EHAN044K.doc.415-419_Marcy_Ave.FactSheet-1.pdf

415-419 MARCY AVENUE (Continued) **S118943585**

Project ID: 16CVCP041K
File Name: 2015-12-04.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP041K/2015-12-04.16EHAN044K.doc.Translated_Factsheet_1.OER.pdf

Project ID: 16CVCP041K
File Name: 2015-12-04.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP041K/2015-12-04.16EHAN044K.doc.Translated_Community_Protection_Statement.OER.pdf

---

AL458 **FORMER CHARLES PFIZER & CO SITE** **NY ENG CONTROLS** **S112139064**
West **407 MARCY AVENUE** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11206** **NY Spills**
0.260 mi.
1373 ft. **Site 2 of 3 in cluster AL**

Relative: **Lower**
Actual: **13 ft.**

ENG CONTROLS:
Name: FORMER CHARLES PFIZER & CO SITE
Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
HW Code: C224175
Control Code: 15
Control Type: ENG
Date Record Added: 08/08/2013
Date Rec Updated: 04/30/2019
Updated By: CHALLAN
Site Description: Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.
Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-03-04 12:21:00
Record Upd: 2014-12-22 15:32:00
Updated By: JHOCONNE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: c/o The Rabsky Group
Owner Addr2: 505 Flushing Avenue, 1D

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Simon Dushinsky
Owner Company:	Marcy Housing LLC
Owner Address:	505 Flushing Avenue, 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224175
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	M-XYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(GHI)PERYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code:	C224175
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	M-CRESOL(S)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	benzo(g,h,i)perylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2014000421840
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-22 15:50:00
Record Updated:	2014-12-24 12:03:00
Updated By:	IXMUNTEA
Crossref ID:	C224175-04-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-12-22 16:03:00
Record Updated:	2014-12-22 16:03:00
Updated By:	JHOCONNE
Crossref ID:	dummynumber

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-22 15:50:00
Record Updated:	2014-12-22 15:50:00
Updated By:	JHOCONNE
Crossref ID:	1214474
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2013-03-04 13:48:00
Record Updated:	2013-03-04 13:48:00
Updated By:	BXANDERS
Name:	FORMER CHARLES PFIZER & CO SITE
Address:	407 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Site Code:	479327
HW Code:	C224175
Control Code:	13
Control Type:	ENG
Date Record Added:	08/08/2013
Date Rec Updated:	04/30/2019
Updated By:	CHALLAN
Site Description:	Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.
Env Problem:	Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem:	Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-03-04 12:21:00
Record Upd:	2014-12-22 15:32:00
Updated By:	JHOCONNE
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Simon Dushinsky
Owner Company:	Marcy Housing LLC
Owner Address:	c/o The Rabsky Group
Owner Addr2:	505 Flushing Avenue, 1D
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Simon Dushinsky
Owner Company:	Marcy Housing LLC

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Owner Address:	505 Flushing Avenue, 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224175
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	M-XYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(GHI)PERYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	LEAD

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	M-CRESOL(S)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	benzo(g,h,i)perylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2014000421840
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-22 15:50:00
Record Updated:	2014-12-24 12:03:00
Updated By:	IXMUNTEA
Crossref ID:	C224175-04-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-12-22 16:03:00
Record Updated:	2014-12-22 16:03:00
Updated By:	JHOCONNE
Crossref ID:	dummynumber
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-22 15:50:00
Record Updated:	2014-12-22 15:50:00
Updated By:	JHOCONNE
Crossref ID:	1214474

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00
Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

INST CONTROL:
Name: FORMER CHARLES PFIZER & CO SITE
Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
Control Name: Site Management Plan
HW Code: C224175
Control Code: 32
Control Type: INST
Dt record added: 08/08/2013
Dt rec updated: 04/30/2019
Updated By: CHALLAN
Site Code: 479327
Site Description: Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.
Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm),

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-03-04 12:21:00
Record Upd: 2014-12-22 15:32:00
Updated By: JHOCONNE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: c/o The Rabsky Group
Owner Addr2: 505 Flushing Avenue, 1D
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: 505 Flushing Avenue, 1D
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224175
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(GHI)PERYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-CRESOL(S)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(g,h,i)perylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2014000421840
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-24 12:03:00
Updated By: IXMUNTEA
Crossref ID: C224175-04-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-22 16:03:00
Record Updated: 2014-12-22 16:03:00
Updated By: JHOCONNE
Crossref ID: dummynumber
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-22 15:50:00
Updated By: JHOCONNE
Crossref ID: 1214474
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

Name: FORMER CHARLES PFIZER & CO SITE
Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
Control Name: Environmental Easement
HW Code: C224175
Control Code: J
Control Type: INST
Dt record added: 08/08/2013
Dt rec updated: 04/30/2019
Updated By: CHALLAN
Site Code: 479327
Site Description: Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.
Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

(RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-03-04 12:21:00
Record Upd: 2014-12-22 15:32:00
Updated By: JHOCONNE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: c/o The Rabsky Group
Owner Addr2: 505 Flushing Avenue, 1D
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: 505 Flushing Avenue, 1D
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Owner Company: Brooklyn Public Library - Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224175
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(GHI)PERYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type: M-CRESOL(S)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(g,h,i)perylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2014000421840
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-24 12:03:00
Updated By: IXMUNTEA
Crossref ID: C224175-04-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-22 16:03:00
Record Updated: 2014-12-22 16:03:00
Updated By: JHOCONNE
Crossref ID: dummynumber
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-22 15:50:00
Updated By: JHOCONNE
Crossref ID: 1214474
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00
Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

Name: FORMER CHARLES PFIZER & CO SITE

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
Control Name: IC/EC Plan
HW Code: C224175
Control Code: 34
Control Type: INST
Dt record added: 08/08/2013
Dt rec updated: 04/30/2019
Updated By: CHALLAN
Site Code: 479327
Site Description: Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.
Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-03-04 12:21:00
Record Upd: 2014-12-22 15:32:00
Updated By: JHOCONNE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: c/o The Rabsky Group
Owner Addr2: 505 Flushing Avenue, 1D
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: 505 Flushing Avenue, 1D
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Owner Country: United States of America
HW Code: C224175
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Waste Type: M-XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(GHI)PERYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-CRESOL(S)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(g,h,i)perylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2014000421840
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-24 12:03:00
Updated By: IXMUNTEA
Crossref ID: C224175-04-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-22 16:03:00
Record Updated: 2014-12-22 16:03:00
Updated By: JHOCONNE
Crossref ID: dummynumber
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-22 15:50:00
Updated By: JHOCONNE
Crossref ID: 1214474
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00
Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

Name: FORMER CHARLES PFIZER & CO SITE
Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
Control Name: Landuse Restriction

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Control Code: 25
Control Type: INST
Dt record added: 08/08/2013
Dt rec updated: 04/30/2019
Updated By: CHALLAN
Site Code: 479327
Site Description: Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.
Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-03-04 12:21:00
Record Upd: 2014-12-22 15:32:00
Updated By: JHOCONNE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: c/o The Rabsky Group
Owner Addr2: 505 Flushing Avenue, 1D
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: 505 Flushing Avenue, 1D
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224175
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(GHI)PERYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-CRESOL(S)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(g,h,i)perylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2014000421840
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-24 12:03:00
Updated By: IXMUNTEA
Crossref ID: C224175-04-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-22 16:03:00
Record Updated: 2014-12-22 16:03:00
Updated By: JHOCONNE
Crossref ID: dummynumber
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-22 15:50:00
Updated By: JHOCONNE
Crossref ID: 1214474
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00
Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

Name: FORMER CHARLES PFIZER & CO SITE
Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
Control Name: Monitoring Plan
HW Code: C224175
Control Code: 31
Control Type: INST
Dt record added: 08/08/2013

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Dt rec updated: 04/30/2019
Updated By: CHALLAN
Site Code: 479327
Site Description: Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.
Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

	complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.
Health Problem:	Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-03-04 12:21:00
Record Upd:	2014-12-22 15:32:00
Updated By:	JHOCONNE
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Simon Dushinsky
Owner Company:	Marcy Housing LLC
Owner Address:	c/o The Rabsky Group
Owner Addr2:	505 Flushing Avenue, 1D
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Simon Dushinsky
Owner Company:	Marcy Housing LLC
Owner Address:	505 Flushing Avenue, 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224175
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(GHI)PERYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-CRESOL(S)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(g,h,i)perylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2014000421840
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-24 12:03:00
Updated By: IXMUNTEA
Crossref ID: C224175-04-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-22 16:03:00
Record Updated: 2014-12-22 16:03:00
Updated By: JHOCONNE
Crossref ID: dummynumber
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-22 15:50:00
Updated By: JHOCONNE
Crossref ID: 1214474
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00
Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

Name: FORMER CHARLES PFIZER & CO SITE
Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
Control Name: Ground Water Use Restriction
HW Code: C224175
Control Code: 08
Control Type: INST
Dt record added: 08/08/2013
Dt rec updated: 04/30/2019
Updated By: CHALLAN
Site Code: 479327
Site Description: Location: The site is located in an urban area in East Williamsburg,

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.

Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-03-04 12:21:00
Record Upd: 2014-12-22 15:32:00
Updated By: JHOCONNE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: c/o The Rabsky Group
Owner Addr2: 505 Flushing Avenue, 1D
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: 505 Flushing Avenue, 1D
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224175
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(GHI)PERYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-CRESOL(S)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(g,h,i)perylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2014000421840
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-24 12:03:00
Updated By: IXMUNTEA
Crossref ID: C224175-04-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-22 16:03:00
Record Updated: 2014-12-22 16:03:00
Updated By: JHOCONNE
Crossref ID: dummynumber
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-22 15:50:00
Updated By: JHOCONNE
Crossref ID: 1214474
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00
Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

Name: FORMER CHARLES PFIZER & CO SITE
Address: 407 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 479327
Control Name: Soil Management Plan
HW Code: C224175
Control Code: 14
Control Type: INST
Dt record added: 08/08/2013
Dt rec updated: 04/30/2019
Updated By: CHALLAN
Site Code: 479327
Site Description: Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.

Env Problem: Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-03-04 12:21:00
Record Upd: 2014-12-22 15:32:00
Updated By: JHOCONNE
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: c/o The Rabsky Group
Owner Addr2: 505 Flushing Avenue, 1D
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Owner
Sub Type: 06
Owner Name: Simon Dushinsky
Owner Company: Marcy Housing LLC
Owner Address: 505 Flushing Avenue, 1D
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11205
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224175
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-XYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

HW Code: C224175
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: BENZO(GHI)PERYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: M-CRESOL(S)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: 1,1-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(g,h,i)perylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224175
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2014000421840
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-24 12:03:00
Updated By: IXMUNTEA
Crossref ID: C224175-04-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2014-12-22 16:03:00
Record Updated: 2014-12-22 16:03:00
Updated By: JHOCONNE
Crossref ID: dummynumber
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2014-12-22 15:50:00
Record Updated: 2014-12-22 15:50:00
Updated By: JHOCONNE
Crossref ID: 1214474
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-03-04 13:48:00
Record Updated: 2013-03-04 13:48:00
Updated By: BXANDERS

SPILLS:
Name: PHASE 2 RESULTS
Address: 407 MARCY AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1214474 / 2013-07-18
Facility ID: 1214474
Facility Type: ER
DER Facility ID: 433020
Site ID: 477719
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 2013-01-10
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2013-01-10
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other

FORMER CHARLES PFIZER & CO SITE (Continued) **S112139064**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-01-10
Spill Record Last Update:	2013-07-18
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHARLES SOSIK
DEC Memo:	"Cross reference to remediation project no c-224175.(sr)"
Remarks:	"CAller advised received results from a phase 2. Clean up is pending." Not reported

All Materials:

Site ID:	477719
Operable Unit ID:	1227516
Operable Unit:	01
Material ID:	2224904
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AL459 **FORMER CHARLES PFIZER & CO SITE** **NY BROWNFIELDS** **S113402003**
West **407 MARCY AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11206**
0.260 mi.
1373 ft. **Site 3 of 3 in cluster AL**

Relative: **Lower**
Actual: **13 ft.**

BROWNFIELDS:

Name:	FORMER CHARLES PFIZER & CO SITE
Address:	407 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Program:	BCP
Site Code:	479327
Acres:	0.428
HW Code:	C224175
SWIS:	2401
Town:	New York City
Record Added Date:	03/01/2013
Record Updated Date:	07/03/2018
Update By:	JHOCONNE
Site Description:	Location: The site is located in an urban area in East Williamsburg, Brooklyn and occupies Tax Block 2245 Lot 8. Site Features: The site is currently vacant. The site was previously occupied by a vacant one-story brick building with a paved parking lot. The building has been demolished but the foundation slab remains. Current Zoning and Land Use: The site is zoned R7A for residential use, with a C2-2 commercial overlay. The site is surrounded by commercial uses to the

FORMER CHARLES PFIZER & CO SITE (Continued) **S113402003**

south and east, and by residential uses across Marcy Avenue to the west and across Lorimer Avenue to the north. Past Use of the Site: The site was developed prior to 1887 with 12 two-story residential homes. By 1935, the home on the corner of Marcy Ave. and Lorimer St. was replaced with a storefront. The other lots fronting on Lorimer St. contained a commercial building used for truck sales and service. The Charles Pfizer and Co. facility occupied the property from 1965 to 1987. From 1989 to 2007, a warehouse was operated on the site. These uses contributed to the petroleum contamination found at the site. Site Geology and Hydrogeology: Subsurface soils at the Site consist of a urban fill material mixed with bricks, coal ash, and other debris to approximately 5 ft below grade (bg). A native brown to grey silty-clay is present below the fill material to a depth of at least 12 ft bg. Bedrock in this area of Brooklyn is approximately 100 ft bg. Groundwater is present at a depth of approximately 10 ft bg and flows to the west-northwest toward Wallabout Channel.

Env Problem:

Nature and Extent of Contamination: Prior to Remediation Soil: Based on the investigations conducted to date, the primary contaminants of concern detected in soil include SVOCs and metals. The contamination at the site was determined to be in the fill layer and beneath it to a depth of approximately 15 feet below grade over the entire site. Soil in two soil borings was contaminated with petroleum. Numerous SVOC concentrations in soil in three of six soil borings exceeds the Unrestricted Use Soil Cleanup Objective (UUSCOs) as well as the Restricted Residential SCOs (RRSCOs), including: benzo(a)anthracene at a maximum concentration of 630ppm (RRSCO is 1 ppm), benzo(a)pyrene up to 440 ppm (RRSCO is 1 ppm, benzo(b)fluoranthene up to 500 ppm (RRSCO is 1 ppm), benzo(k)fluoranthene up to 130 ppm (RRSCO is 3.9 ppm), chrysene up to 640 ppm (RRSCO is 3.9 ppm), fluoranthene up to 1,200 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene up to 180ppm (RRSCO is 0.5 ppm), phenanthrene up to 1,800 ppm (RRSCO is 100 ppm), and pyrene up to 1,400 ppm (RRSCO is 100 ppm). Metals were detected in two soil samples at concentrations exceeding both the UUSCOs and the RRSCOs, as follows: cadmium up to 7.73 ppm (RRSCO is 2.5 ppm), lead up to 1,060ppm (RRSCO is 400 ppm), and mercury up to 2.78 ppm (RRSCO is 0.81 ppm), and zinc 2,550ppm (RRSCO is 109 ppm). Groundwater: VOCs and SVOCs were the primary contaminants found in groundwater. Cis 1,2 dichloroethene (DCE) was identified at a maximum concentration of 99 ppb (compared to groundwater quality standard of 5 ppb), 1,1,1- trichloroethane (TCA) 140 ppb (compared with groundwater quality standard of 5 ppb), and naphthalene was detected at up to 95 ppb (compared to groundwater quality standard of 10 ppb). The chlorinated solvents detected in groundwater are from a suspected upgradient source. Soil Vapor: In soil vapor, TCA was detected at a concentration of up to 32,000 micrograms per cubic meter. The chlorinated solvents detected in soil vapor are from a suspected upgradient source. Post-Remediation: Remediation at the site is complete. Remaining contamination in soil and groundwater is being managed under a Site Management Plan.

Health Problem:

Direct contact with contaminants in the soil is unlikely because the site is covered entirely by a building. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by this site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of

FORMER CHARLES PFIZER & CO SITE (Continued) **S113402003**

	buildings, is referred to as soil vapor intrusion. Measures are in place to minimize the potential for vapor intrusion in buildings at the site and sampling indicates that soil vapor intrusion is not a concern for off-site buildings.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-03-04 12:21:00
Record Upd:	2014-12-22 15:32:00
Updated By:	JHOCONNE
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Simon Dushinsky
Owner Company:	Marcy Housing LLC
Owner Address:	c/o The Rabsky Group
Owner Addr2:	505 Flushing Avenue, 1D
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Simon Dushinsky
Owner Company:	Marcy Housing LLC
Owner Address:	505 Flushing Avenue, 1D
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224175
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1,1-TRICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175

FORMER CHARLES PFIZER & CO SITE (Continued) **S113402003**

Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACETONE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	M-XYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZ(A)ANTHRACENE

FORMER CHARLES PFIZER & CO SITE (Continued) **S113402003**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	BENZO(GHI)PERYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	M-CRESOL(S)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN

FORMER CHARLES PFIZER & CO SITE (Continued) **S113402003**

Waste Code:	Not reported
HW Code:	C224175
Waste Type:	benzo(g,h,i)perylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224175
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2014000421840
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-22 15:50:00
Record Updated:	2014-12-24 12:03:00
Updated By:	IXMUNTEA
Crossref ID:	C224175-04-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2014-12-22 16:03:00
Record Updated:	2014-12-22 16:03:00
Updated By:	JHOCONNE
Crossref ID:	dummynumber
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2014-12-22 15:50:00
Record Updated:	2014-12-22 15:50:00
Updated By:	JHOCONNE
Crossref ID:	1214474
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2013-03-04 13:48:00
Record Updated:	2013-03-04 13:48:00
Updated By:	BXANDERS

AM460 **CONSTRUCTION SITE** **NY LTANKS** **S106970053**
West **420 MARCY AVE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.263 mi.
1389 ft. **Site 3 of 3 in cluster AM**

Relative: LTANKS:
Lower

Actual:
13 ft.

Name:	CONSTRUCTION SITE
Address:	420 MARCY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0505009 / 2005-11-04
Facility ID:	0505009
Site ID:	349949
Spill Date:	2005-07-26
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	aaobliga
Referred To:	NFA GRANTED
Reported to Dept:	2005-07-26
CID:	444
Water Affected:	Not reported

CONSTRUCTION SITE (Continued) **S106970053**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-07-26
Spill Record Last Update:	2005-11-04
Spiller Name:	SHAGI FREID
Spiller Company:	CONSTRUCTION SITE
Spiller Address:	420 MARCEY AVE
Spiller County:	001
Spiller Contact:	SHAGI FREID
Spiller Phone:	(718) 522-5519
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	296385
DEC Memo:	"7/26/2005 Sangesland spoke to Christopher DeCarlo (cell #201-694-4943) with Flemming Lee Shue Environmental Consulting. Approx. 20 years ago this site was a gasoline station. There is no DEC - PBS or Spill history for the site. Chris DeCarlo works for the new owner of a property which is now under construction. Apparently the former owner dug out the tanks and left a pit. Now that the new owner has started construction, approx 8 ft below the bottom of the pit they found floating gasoline product. They are in the process of removing product and contaminated soil. Since the consultant knew the DEC proceedure and had already started, no contaminated soil letter was sent. 7/26/2005 Sangesland - a second Spill Report came in on this site (#0505029). A vapor complaint from a neighbor with the smell of gasoline (95 degree temp today). Sangesland left a voice mail with Chris DeCarlo at Flemming Shue asking him to confirm that the stock piled material is covered and as much Vapor Abatement as possible has been done. 9/19/05-Reassigned to A. Obligado. (Sun) 9/19/05- Obligado- Reviewed fax from Christopher De Carlo of Fleming Lee Shue consultants dated 9/8/05 requesting case manager be assigned to site. Called De Carlo to give him contact info. DeCarlo stated that they completed excavation of soil and taken clean soil endpoint samples. GW sample from bottom of excavation is 18 ppm MTBE and 3.9 ppm benzene. Asks if they can request closure of spill number. Tell him the NYSDEC needs to see the UST closure report before a judgement can be made. DeCarlo says report is in progress and NYSDEC should receive it shortly. 9/19/05 - Obligado - Follow up phone converstation with De Carlo. Ask him to send DEC foundation and vapor barrier details. Inquire about site status - site construction on hold pending permit for excavation. Ask him not to begin construction until the department reviews designs and UST excavation results. 10/28/05 - Obligado - Received phone call from De Carlo, says he had sent DEC Remedial Action Report and was waiting for DEC response. Told him that haven't seen report yet, and to email pdf of report. 10/31/05 - Obligado - review Remedial Action Report. 5 gasoline USTs removed previously, no records of soil disposal or analyticals. Upon beginning of FLShue's involvement of the site, the USTs had already been removed and an excavation 3 to 4 ft deep was on site. Continued excavation to 9-10 ft bgs. Excavated laterally until no contaminated soil encountered. 354 tons of soil removed from site. Soil results show no VOC exceedences in endpoint samples, only PAH exceedences in one soil sample, SB-2. Ground water sample collected from bottom of

CONSTRUCTION SITE (Continued) **S106970053**

excavation show 3.9 ppb benzene and 18 ppb MTBE. Building construction will include 20 mL high polypropylene vapor barrier. Request NFA based on low concentrations and vapor barrier. Call Chris and leave message. Sent email approving building construction. Need to discuss closure. 11/3/05 - Obligado - Call Chris De Carlo (212) 675-3225, left message "

Remarks: "OWNER OF PROPERTY IS WALMARR LLC REALTY : REMOVING TANKS AND LLEFT A HOLE IN MIDDLE OF PROPERTY AND FOUND CONTAMINATED SOIL; AND FREE PRODUCT: ARE RMOVING SOIL AT THIS TIME;"

All Materials:

Site ID:	349949
Operable Unit ID:	1107537
Operable Unit:	01
Material ID:	2097425
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	UNKNOWN RESIDENCE
Address:	420 MARCY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0505029 / 2005-07-26
Facility ID:	0505029
Facility Type:	ER
DER Facility ID:	296385
Site ID:	349981
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2005-07-26
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2005-07-26
CID:	406
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-26
Spill Record Last Update:	2005-07-26
Spiller Name:	UNKNOWN NAME
Spiller Company:	UNKNOWN RESIDENCE
Spiller Address:	420 MARCY AVE

CONSTRUCTION SITE (Continued) **S106970053**

Spiller Company: 001
Contact Name: JULIO RODRIGUEZ
DEC Memo: "Duplicate spill report - vapor complaint - Cross Ref to #0505009"
Remarks: "Next door to the callers house people are removing soil and tanks from the ground. When they move the material there is a very strong oil and gasoline smell."

All Materials:
Site ID: 349981
Operable Unit ID: 1107566
Operable Unit: 01
Material ID: 2097453
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 349981
Operable Unit ID: 1107566
Operable Unit: 01
Material ID: 2097452
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

---

461 East 1/4-1/2 0.280 mi. 1479 ft.
BUSHWICK -NYCHA
24 HUMBOLDT STREET
BROOKLYN, NY
NY LTANKS S102143036
NY Spills N/A

Relative: Higher
Actual: 26 ft.

LTANKS:
Name: BUSHWICK HOUSES -NYCHA
Address: 24 HUMBOLDT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9505310 / 2005-11-02
Facility ID: 9505310
Site ID: 315418
Spill Date: 1995-07-31
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 1995-07-31
CID: Not reported

BUSHWICK -NYCHA (Continued) **S102143036**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-31
Spill Record Last Update:	2005-11-02
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	254294
DEC Memo:	"11/02/05: This spill transferred from J.Kolleeny to S.Kraszewski. This spill closed to consolidate with open spill #0402157."
Remarks:	"TANK #1 - FAILURE"

All TTF:

Facility ID:	9505310
Spill Number:	9505310
Spill Tank Test:	1544039
Site ID:	315418
Tank Number:	001
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	315418
Operable Unit ID:	1020217
Operable Unit:	01
Material ID:	363300
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BUSHWICK -NYCHA (Continued) **S102143036**

SPILLS:

Name:	BUSHWICK -NYCHA
Address:	24 HUMBOLDT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8908280 / 2013-05-30
Facility ID:	8908280
Facility Type:	ER
DER Facility ID:	254294
Site ID:	138242
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1989-11-20
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1989-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-11-29
Spill Record Last Update:	2013-06-26
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"01/30/06: This spill transferred from J.Kolleeny to S.Kraszewski. This site was previously served by two 23K USTs installed in 1960. They were replaced by two 20K USTs in 2004. They all stored #2 fuel oil. A Phase II report performed in 1993 reveals oil-stained soil in the vacinity of the USTs, the leaks origin is suspected to be the fuel lines since oil seepage has been seen coming through the boiler room wall. Two MWs were installed but neither found any free product or a sheen. Test results show no PAHs, AHs or TPH. However, some GW contamination might exist between the tanks and the boiler room wall, were the leak is most likely to be. Report suggests quarterly monitoring and one additional MW. Monitoring and bailing records on file indicate no free product in any of the MWs. No GW samples taken from any of the wells prior to the Phase II. Seems that only the soil has been impacted and isn't migrating into the GW. - SK 03/22/06: This spill transferred to K.Tang - SK 11/19/07: This spill remains open, but consolidated with 0402157. J.Kann 5/20/09: J.Kann - Investigation work plan received. 5/1/12: J.Kann - work plan approved in an email dated 9/21/09. SIR rcvd 4/2012. Report reviewed. Some product appears to be seeping into the basement based on a photo in the report. Information on the tank closure was requested from NYCHA and submitted on 4/26/2012. SIR includes closure request. File under review. 1/4/12: J.Kann - Work Plan approved in an email dated 9/21/2009. GPR work is scheduled to start on 1/5/12. 4/12/12: J.Kann

BUSHWICK -NYCHA (Continued) **S102143036**

- SIR received in March 27, 2012 5/1/12: J.Kann - reviewed SIR, additional information regarding tank closure requested from NYCHA in an email. Info submitted by NYCHA to DEC on 4/26/12 and is under review. 5/9/12: J.kann - Tank closure report from 2004 received on 4/26/12 shows no VOCs detected in endpoints and minor PAHs in one location of endpoints. In 2004, the excavation was performed to 18 feet (groundwater varies from 8-12 ft bgs on site). The site Investigation Summary report dated March 2012 (installation of 5 borings and 2 new wells, and sampling of an existing well) shows no groundwater impacts and soils below CP-51 with the exception of minor exceedences of PAHs at 10-12 feet in one location. A photo in the report shows some oil seepage in the basement at a depth of approx. 12 ft bgs. A site visit was made on May 3. Staining on the boiler room wall with weathered No. 6 oil was observed at a depth 12-14 feet bgs. Given the number 6 oil tanks were removed in 2004, together with contaminated soils; and the 2012 investigation shows no contamination in borings and wells, it is likely a layer of saturated soils remain immediately adjacent to the foundation wall (the tank excavation required shoring which was place approx. 2-3 feet from the foundation wall (based on site photos and a drawing in the tank closure report. The site was discussed at the May 7 closure meeting. Closure was rejected because of the seepage/staining. An email will be sent to NYCHA indicating this. 5/10/12: J.Kann - email sent to NYCHA and edoced. 5/29/12: J.kann - rcvd a response from NYCHA. 6/13/12: J.kann - sent a response back to NYCHA. The oil seepage issue remains and NYCHA must determine whether there is a feasible way to address it. 8/30/12: J.Kann - received a revised ISR on August 21 and edoced it. 5/30/13: J.Kann - NYCHA sealed the seepage area in the basement and provided a photo. Spoke with Jeff Vought and he confirmed that the spill should be closed and that the revised spill closure letter should be sent. 6/26/13: J.Kann - Spill closure letter sent."

Remarks: "DISCOVERED OIL COMING THROUGH BASEMENT WALL."

All TTF:

Facility ID:	8908280
Spill Number:	8908280
Spill Tank Test:	1536445
Site ID:	138242
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	138242
Operable Unit ID:	933334
Operable Unit:	01
Material ID:	445028

BUSHWICK -NYCHA (Continued) **S102143036**

Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	24 HUMBOLDT ST
Address:	24 HUMBOLDT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9203554 / 1992-12-29
Facility ID:	9203554
Facility Type:	ER
DER Facility ID:	222748
Site ID:	273834
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1992-06-24
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1992-06-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-12-29
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-12
Spill Record Last Update:	1992-12-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OIL FLOWED OUT OF VENT PIPE NOT HAVING A DELIVERY CALLING CONTRACTOR HOUSING PD ON SCENE NO CALL BACK NESS"

All Materials:

Site ID:	273834
Operable Unit ID:	970933
Operable Unit:	01
Material ID:	411347
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G

BUSHWICK -NYCHA (Continued) **S102143036**

Recovered:	.00
Oxygenate:	Not reported
Name:	24 HUMBOLDT ST
Address:	24 HUMBOLDT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9204027 / 1992-07-07
Facility ID:	9204027
Facility Type:	ER
DER Facility ID:	222748
Site ID:	273835
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1992-07-07
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1919-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	1992-07-07
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-07-08
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"SORBENT APPLIED & DISPOSED."

All Materials:

Site ID:	273835
Operable Unit ID:	967824
Operable Unit:	01
Material ID:	567469
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Name:	BUSHWICK HOUSES -NYCHA
Address:	24 HUMBOLDT STREET

BUSHWICK -NYCHA (Continued) **S102143036**

City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0402157 / 2007-11-19
Facility ID:	0402157
Facility Type:	ER
DER Facility ID:	254294
Site ID:	315415
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-05-27
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	2004-05-27
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-27
Spill Record Last Update:	2007-11-19
Spiller Name:	NORMAN ZABUSKI
Spiller Company:	NYCHA BUSHWICK HOUSES
Spiller Address:	24 HUMBOLT STREET
Spiller Company:	001
Contact Name:	NORMAN ZABUSKI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY 11/02/05: This spill transferred from J.Kolleeny to S.Kraszewski 01/13/06: Recieved NYCHA spill report. Gordon Environmental was on site during excavation to perform the site assessment, which is available according to the report. No documentation of investigation report on file. Need to contact NYCHA for the site assessment. - SK 07/07/06: The site summary provided by NYCHA states that a site assessment is available, but doesn't describe what kind of assessment or the date. Recommends that the Department review it. - SK 02/06/07 - J.Kann - site reassigned from S. Kraszewski to J.Kann. 11/19/07: J.Kann - This spill closed and consolidated with 8908280. "
Remarks:	"FOUND SOME CONTAMINATED SOIL WHILE REMOVING TANK: SOIL IS BEING REMOVED BY GORDON ENVIORMENTAL AND WILL BE TESTED AND STOCKPILED ON PLASTIC. "

All Materials:

Site ID:	315415
Operable Unit ID:	883900
Operable Unit:	01
Material ID:	493334
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L

BUSHWICK -NYCHA (Continued) **S102143036**

Recovered:	.00
Oxygenate:	Not reported
Name:	BUSHWICK HOUSES
Address:	24 HUMBOLDT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9010350 / 1994-11-16
Facility ID:	9010350
Facility Type:	ER
DER Facility ID:	254294
Site ID:	315416
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1990-12-24
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-12-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	1994-11-16
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-09
Spill Record Last Update:	1994-11-17
Spiller Name:	Not reported
Spiller Company:	BAYSIDE FUEL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"DRIVER OVERFILLED TANK, SPEEDY DRY WAS APPLIED,WILL PICK UP & DISPOSE."

All TTF:

Facility ID:	9010350
Spill Number:	9010350
Spill Tank Test:	1538085
Site ID:	315416
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

BUSHWICK -NYCHA (Continued) **S102143036**

Last Modified Date: Not reported

All Materials:
Site ID: 315416
Operable Unit ID: 950744
Operable Unit: 01
Material ID: 430510
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 25.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: BUSHWICK HOUSES
Address: 24 HUMBOLDT STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9401533 / 1994-09-06
Facility ID: 9401533
Facility Type: ER
DER Facility ID: 254294
Site ID: 315417
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1994-05-02
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 1994-05-02
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Affected Persons
Cleanup Ceased: 1994-09-06
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1994-05-04
Spill Record Last Update: 2003-11-26
Spiller Name: Not reported
Spiller Company: ALPS MECHANICAL
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "RUPTURED RETURN LINE WHILE EXCAVATING-CONTAINED ON SOIL & BASEMENT BOILER ROOM. CLEAN UP IN PROGRESS. WINSTON CONTRACTING EN ROUTE."

All TTF:
Facility ID: 9401533
Spill Number: 9401533

BUSHWICK -NYCHA (Continued) **S102143036**

Spill Tank Test:	1542666
Site ID:	315417
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	315417
Operable Unit ID:	998756
Operable Unit:	01
Material ID:	385286
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BUSHWICK HYLAN -NYCHA
Address:	24 HUMBOLDT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9102670 / 1994-06-08
Facility ID:	9102670
Facility Type:	ER
DER Facility ID:	254294
Site ID:	207177
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	1991-06-06
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1991-06-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	1994-06-08
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

BUSHWICK -NYCHA (Continued) **S102143036**

Date Entered In Computer:	1991-06-06
Spill Record Last Update:	2006-01-30
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 B'WAY
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"01/30/06: This spill transferred from J.Kolleeny to S.Kraszewski. This site previously served to two 23K USTs installed in 1960. Both were removed and replaced by two 20K tanks in 2004. They all stored #2 fuel oil. "
Remarks:	"20 YDS OF SOIL FUEL LINE RUPTURED IN EXCAVATION BY BACKHOE, BRINGING IN CONTAINER FOR THE SOIL."

All TTF:

Facility ID:	9102670
Spill Number:	9102670
Spill Tank Test:	1538640
Site ID:	207177
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	207177
Operable Unit ID:	953530
Operable Unit:	01
Material ID:	425166
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

462
NW
1/4-1/2
0.281 mi.
1482 ft.

150 UNION AVENUE
150 UNION AVENUE
NEW YORK CITY, NY

NY VCP **S118943448**
N/A

Relative:
Higher

Actual:
17 ft.

VCP NYC:
Project ID: 15CVCP058K
Project Name: 150 UNION AVENUE
Project Address: 150 UNION AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP058K
File Name: 2014-12-24.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP058K/2014-12-24.14EH-A462K.Report.RIR- Final..pdf

Project ID: 15CVCP058K
File Name: 2015-02-06.RAWP_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP058K/2015-02-06.14EH-A462K.Report.RAWP_Final.HTE.pdf

Project ID: 15CVCP058K
File Name: 2015-01-21.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP058K/2015-01-15.15CVCP058K.Factsheet-1.pdf

Project ID: 15CVCP058K
File Name: 2015-01-21.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP058K/2015-01-21.15CVCP058K.Translated_FactSheet-1.pdf

Project ID: 15CVCP058K
File Name: 2015-01-21.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP058K/2014-12-22.15CVCP058K.Translated_CPS.pdf

---

463
WSW
1/4-1/2
0.303 mi.
1601 ft.

CONSTRUCTION SITE
5 WALTON AVE
BROOKLYN, NY

NY LTANKS **S102960158**
N/A

Relative:
Lower

Actual:
11 ft.

LTANKS:
Name: CONSTRUCTION SITE
Address: 5 WALTON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9710662 / 2003-03-07
Facility ID: 9710662
Site ID: 162103
Spill Date: 1997-12-18
Spill Cause: Tank Failure
Spill Source: Unknown
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: WYNE
Referred To: Not reported

CONSTRUCTION SITE (Continued) **S102960158**

Reported to Dept:	1997-12-18
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-12-18
Spill Record Last Update:	2003-03-07
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ROMEO SANTOS
Spiller Phone:	(718) 322-5600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	136819
DEC Memo:	""
Remarks:	"CALLER IS REMOVING TANK FROM GROUNDS AND FOUND CONTAMINATED SOIL"

All Materials:

Site ID:	162103
Operable Unit ID:	1057036
Operable Unit:	01
Material ID:	328949
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AO464 **ENGINE CO. 216/LADD. CO. 108 NYFD -DDC** **NY LTANKS** **S104073416**
NW **187 UNION AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.333 mi.
1759 ft. **Site 1 of 2 in cluster AO**

Relative:
Higher

Actual:
18 ft.

LTANKS:

Name:	ENGINE CO. 216/LADD. CO. 108 FDNY -DDC
Address:	187 UNION AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8607159 / 2005-01-13
Facility ID:	8607159
Site ID:	188778
Spill Date:	1987-02-24
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JAKOLLEE

ENGINE CO. 216/LADD. CO. 108 NYFD -DDC (Continued) **S104073416**

Referred To:	Not reported
Reported to Dept:	1987-02-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-03-04
Spill Record Last Update:	2005-07-07
Spiller Name:	Not reported
Spiller Company:	NYC FIRE / POLICE DEPT.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	141497
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY / / : BURIED ABOVE GROUND TANK LEAKING THROUGH FIRE WALL FROM 90TH PCT. TO FIREHOUSE. ABSORBENT PADS ARE BEINGPUT DOWN. This spill is referred to spill # 9807905 and is closed today as per discussion with Alex. - II (01/13/05). "
Remarks:	"UNDERGROUND TANK LEAKING FROM THE POLICE DEPT. TO THE FIRE DEPT. FOR SEVERAL MONTHS. 90TH PRECINCT - 718-963-5311 ASSIGNED TO DGS MONITORS FOR FURTHER ACTION"

All Materials:

Site ID:	188778
Operable Unit ID:	904921
Operable Unit:	01
Material ID:	559701
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Site ID:	188778
Operable Unit ID:	904921
Operable Unit:	01
Material ID:	559700
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

ENGINE CO. 216/LADD. CO. 108 NYFD -DDC (Continued) **S104073416**

SPILLS:

Name:	ENGINE CO. 216/LADD. CO. 108 NYFD -DDC
Address:	187 UNION AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9807905 / 2013-09-04
Facility ID:	9807905
Facility Type:	ER
DER Facility ID:	141497
Site ID:	167947
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1998-09-28
Investigator:	ADZHITOM
Referred To:	NFA
Reported to Dept:	1998-09-29
CID:	211
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-29
Spill Record Last Update:	2013-09-27
Spiller Name:	CHRIS STEIN
Spiller Company:	ENGINE 216 NYFD
Spiller Address:	187 UNION AV
Spiller Company:	001
Contact Name:	CHRIS STEIN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY Initial site investigation soil data found soil contamination, however, additional soil sampling by URS failed to duplicate those results and only contaminant in groundwater was MTBE, which seemed likely to be coming from upgradient 90th Precinct. In March 2005, J. Kolleeny approved NFA for the soil at site (and monitoring of groundwater combined with 90th Pct. monitoring), but cautioned that if there were indications that on-site soil contamination was impacting groundwater, additional investigation and/or remediation could be required. In November 2004 URS Groundwater Monitoring report for 90th Precinct and Engine Co. 216, MTBE levels in Eng. Co. 216 wells seem persistent and possibly unrelated to 90th Precinct plume. JK spoke with Jane Staten of URS and agreed that if next round of GW sampling still showed high MTBE levels, situation at Eng. Co. 216 would be re-evaluated. Spill transferred from Kolleeny to A. Zhitomirsky on 4/4/05. - JK 8-14-2006 Reviewed monitoring report by Roux dated July 28, 2005 for March through June 2006.MW-3 - 150 PPB mtbe in groundwater.Recommendations: maintainn DPE and Oxygen delivery remediation systems shut down; continue gw monitoring, discontinue SVOCs analyses, evaluate alternative technologies. AZ 04-5-2007 Reviewed Monitoring Reports submitted in November 2006 for July through September 2006 and on March 23, 2007, for October through December 2006. Residual MTBE

ENGINE CO. 216/LADD. CO. 108 NYFD -DDC (Continued) **S104073416**

contamination was detected in four wells with concentrations up to 60 ppb(July 2006). Benzine and naphthalene were encountered in one well. DPE was inactive. ORC injections and ORC socks were discontinued. In October 2006 sampling event MTBE ranged from 16 ppb to 136 ppb. Some increase of MTBE concentrations was observed. ORC socks will be installed in MW 216-MW-01, 216-MW-03 and MW-09. Recommended maintaining shutdown status of DPE system, reducing monitoring and reporting to semi-annual. These recommendations were approved. An e-mail was sent to Brian Morrissey (ROUX). AZ 10-22-2007 Reviewed Monitoring Reports submitted in August 2007 for January through June 2007. Residual MTBE contamination was detected in five wells wells with concentrations up to 85 ppb. ORC socks were reinstalled in three monitoring wells at the NYSDEC request. Roux recommended continuing semi-annual groundwater monitoring program. AZ 7-2-2008 Reviewed Monitoring Reports submitted in April 2008 for July through December 2008. MTBE is the only VOC detected at a concentration greater than its NYSDEC AWQSGV in multiple wells. Roux recommended continuing semi-annual groundwater monitoring program. AZ 2-13-2009 Reviewed Monitoring Reports submitted in October 2009 for January through September 2008. Residual MTBE contamination was detected in four wells of the six wells with concentrations up to 66 ppb. ORC socks were reinstalled in three monitoring wells at the NYSDEC request. MTBE is the only VOC detected at a concentration greater than its NYSDEC AWQSGV in multiple wells. Roux will conduct a site wide groundwater sampling round in preparation for NFA. AZ 11-6-09 An e-mail was sent to Brian Morrisey/Fatemeh Ashkan/ V. Brevdo: I have reviewed a semi-annual report for the above site dated May 22, 2009 add covering the period of June 2008 through March 2009. Roux proposed conducting soil sampling and analyses in areas of residual groundwater contamination (i.e.e 216-MW-02 and MW-08) in order to determine current status of soil impacts. Also, you proposed considering enhanced bioremediation for this site. These proposals are approved and should the work plan should be included in the next monitoring report. AZ 4-25-2011 Reviewed LiRo status report. This spill is associated with four closed in place 550 gallon gasoline USTs. Two soil borings will be installed near these USTs. AZ 11-28-2011 A report dated 9-8-2011 stated that drilling for the borings approved by DEC was scheduled for August 2011. AZ 6-12-2012 Reviewed a status report dated 3-29-2012. ORC socks were placed in contaminated wells. AZ 4-12-2012 Reviewed a status report dated 8-31-2012. Semi-annual sampling is being performed at 12 wells. Downgradient well MW-2 exhibited continued rise in contaminant levels. Left a message for S. Frank. He called back and we discussed the site. He will into it. Maybe LiRo will install a well downgradient of 216-MW-2 AZ 9-3-2013 Reviewed s pill closure report for this spill. This spill is associated with the four closed in-place 550-gallon gasoline USTs located on the Engine Company 216 property. No remediation of soils required based on recent (May 2012) and hsitorical soil analytical data. ORC slurry application was performed in March 2004. Stable dissolved phase groundwater plume with TVOC concentrations less than 100 ppb was recorded uring last two sampling events. The subway and tunnel prevent offsite migration. AZ 9-4-2013 The following e-mail sent to S. Frank/V. Brevdo/F. Ashkan: Dear Steve, I have reviewed Request for Spill Closure dated May 23, 2013. This spill is associated with the four closed in-place 550-gallon gasoline USTs located on the Engine Company 216 property. No remediation of soils required based on recent (May 2012) and

ENGINE CO. 216/LADD. CO. 108 NYFD -DDC (Continued) **S104073416**

historical soil analytical data. ORC slurry application was performed in March 2004. Stable dissolved phase groundwater plume with Total Volatile Organic Contaminant concentrations less than 100 ppb was recorded during last two sampling events. The subway and tunnel prevent offsite migration. URS requested that DEC close spill number 9807905. Based on the documentation provided to date, the New York State Department of Environmental Conservation (the Department) has closed the spill case number 9807905. All wells associated with this project should be closed according to the Department's Groundwater Monitoring Well Decommissioning Procedures. All wells should gaged for the presence of free product before closure. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department's spill case closure, which indicates the corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts must be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations. Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use as the Department's files may not be maintained indefinitely. Sincerely, Alex Zhitomirsky"

Remarks: "CALLER DOING SITE ASSESSMENT AND RESULTS SHOWED CONTAMINATION"

All Materials:

Site ID:	167947
Operable Unit ID:	1065476
Operable Unit:	01
Material ID:	315444
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP465 **COOPER TANK & WELDING CO.** **NY SWF/LF** **S105841714**
ENE **222-26 SIEGAL AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11206**
0.341 mi.
1801 ft. **Site 1 of 3 in cluster AP**

Relative: **Higher**
Actual: **19 ft.**

SWF/LF:

Name:	COOPER TANK & WELDING CO.
Address:	222-26 SIEGAL AVE
City,State,Zip:	BROOKLYN, NY 11206
Flag:	INACTIVE
Region Code:	2
Phone Number:	2124974431
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	SAMUEL COOPER; OWNER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T19]
Active:	No
East Coordinate:	589500
North Coordinate:	4506500
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6104-00103
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AP466 **BORINQUEN PLAZA** **NY LTANKS** **U002034215**
NE **110 HUMBOLDT STREET** **NY UST** **N/A**
1/4-1/2 **BROOKLYN, NY 11206**
0.349 mi.
1843 ft. **Site 2 of 3 in cluster AP**

Relative: **Higher**
Actual: **19 ft.**

LTANKS:

Name:	BORINQUEN PLAZA -NYCHA
Address:	110 HUMBOLDT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9605290 / 2010-11-10
Facility ID:	9605290
Site ID:	86456
Spill Date:	1996-07-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401

BORINQUEN PLAZA (Continued) **U002034215**

Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1996-07-24
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-24
Spill Record Last Update:	2010-11-10
Spiller Name:	DAVE FORTE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	DAVE FORTE
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	79316
DEC Memo:	"12/12/05: This spill transffered from J.Kolleeny to S.Kraszewski. 09/08/06: NYCHA Schedule D list states that quarterly smapling was performed in 2003 and the samples were clean. No such documents on file. No information in the site summaries. - SK 02/08/07: DEC lead changed from S. Kraszewski to J. Kann. J.Kann 02/13/09: J.Kann - Spoke with Gannett Fleming about a work plan being prepared for the site. Groundwater samples will be collected and analyzed for STARS VOCs and SVOCs. 4/28/09: J.Kann - Draft work plan received on 2/25. Comments sent on 3/17. Final Work Plan received on 4/24 and approved on 4/27. 10/06/09: J.Kann - Site visit to observe gw sampling. 1/27/10: J.Kann - ISR submitted on 1/20/10. Spill Closure request. Report needs to be reviewed. 11/10/10: J.Kann - based on review of the SAR and some PAHs remaining in soils at depth, NYCHA was emailed that a Quantitative exposure assessment should be performed on 10/28/10. A revised report was submitted on 11/5/10 and reviewed. Based on the QEA a complete exposure pathway does not exist. NFA. Spill closed. "
Remarks:	"test failed"

All TTF:

Facility ID:	9605290
Spill Number:	9605290
Spill Tank Test:	1544656
Site ID:	86456
Tank Number:	1b
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	-12.80
Gross Fail:	Not reported
Modified By:	Spills

BORINQUEN PLAZA (Continued) **U002034215**

Last Modified Date: Not reported

All Materials:
Site ID: 86456
Operable Unit ID: 1032806
Operable Unit: 01
Material ID: 348039
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

UST:
Name: BORINQUEN PLAZA
Address: 110 HUMBOLDT STREET
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-601867 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589468.29549
UTM Y: 4506547.15849
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 23829
Affiliation Type: Facility Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: FUEL OIL REMEDIATION COORDINATOR
Contact Name: FUEL OIL REMEDIATION COORD.
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: EXROSSAN
Date Last Modified: 2005-09-30

Site Id: 23829
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: LUIS PONCE
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY

BORINQUEN PLAZA (Continued) **U002034215**

Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23829
Affiliation Type:	Facility Operator
Company Name:	BORINQUEN PLAZA
Contact Type:	Not reported
Contact Name:	LUIS PONCE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23829
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICE DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	2005-09-21

Tank Info:

Tank Number:	1
Tank ID:	48182
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	02/01/1975
Date Tank Closed:	03/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

BORINQUEN PLAZA (Continued) **U002034215**

Tightness Test Method: 03
Date Test: 04/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)

467
NE
1/4-1/2
0.350 mi.
1848 ft.

159 BOERUM STREET
159 BOERUM STREET
BROOKYLN, NY 11206

NY BROWNFIELDS **S123658106**
N/A

Relative:
Higher

Actual:
24 ft.

BROWNFIELDS:
Name: 159 BOERUM STREET
Address: 159 BOERUM STREET
City,State,Zip: BROOKYLN, NY 11206
Program: BCP
Site Code: 582502
Acres: 0.25
HW Code: C224291
SWIS: 2401
Town: New York City
Record Added Date: 02/19/2019
Record Updated Date: 04/17/2019
Update By: MJKOMORO
Site Description: Location: The site is located at 159 Boerum Street within an urbanized area of Brooklyn, New York and is identified as Block 3071, Lot 40 on the Kings County Tax Map. The site is located on the city block bound by Johnson Avenue to the north, Humboldt Street to the east, Boerum Street to the south, and Graham Avenue to the west. The site is bound to the north and east by 170 Johnson Avenue (multi-family residential building with vegetative cover); to the south by Boerum Street followed by 160 Boerum Street (multi-family residential building and parking lot); and to the west by 132-138 Graham Avenue (four multifamily residential buildings). Site Features: The about 11,180-square-foot (0.25 acres) site is situated on the south-central part of the tax block and is occupied by an open-air asphalt parking lot surrounded by landscaped areas to the north and south. The site grade slopes from north (elevation1 28.5) to south (elevation 25.8), toward Boerum Street. The topography of the region is characterized by small peaks and valleys, which causes varying changes in the direction and degree of slopes in localized areas. The surrounding area slopes downward gradually to the south-southeast. Current Zoning and Land Use: According to the New York City Planning Commission Zoning Map 13b, the site is located within a residential district (R6). According to the New York City

159 BOERUM STREET (Continued) **S123658106**

Planning Commission, R6 zoning districts are widely mapped in built-up, medium-density areas in Brooklyn, Queens and the Bronx. The character of R6 districts can range from neighborhoods with a diverse mix of building types and heights. The surrounding properties are zoned for residential (R6) uses with commercial overlays (C1/C2) along major thoroughfares. A copy of the zoning map is included in Attachment B. Land use within a half-mile radius includes residential, commercial, industrial, open space and institutional developments. The nearest ecological receptor is the English Kills (tributary to Newtown Creek), located about 0.64 miles northeast of the site. Past Use of the Site: A review of available Sanborn Fire Insurance Maps, historic aerial photographs, and City Directory records indicate the site was developed as early as 1887 with four multi-story buildings used as stores (labeled as tailor shop, synagogue, candy packaging, and warehouse), parking, and residential dwellings until about 1965. The previous mixed commercial/residential buildings were demolished around 1974, and the site was used as an open-air parking lot as early as 1981. Test pits excavated on-site revealed buried solid waste, including glass, organic fibers, fabric, plastic, automobile tires, coal, ceramics, metal, brick and concrete as deep as 7.5 feet bgs, suggesting that undocumented dumping occurred at some point after the buildings were demolished in 1974. Site Geology and Hydrogeology: Based on findings of the previous limited investigation performed in October 2018 the site is underlain by solid waste within a sand and gravel matrix. Solid waste includes random distributions of brick, glass, organic fibers, fabric, plastic, automobile tires, coal, ceramics, metal and concrete from surface grade to about 7.5 feet below grade surface (bgs). Bedrock was not encountered during previous investigations conducted at the site, and is anticipated to be located over 80 feet bgs based on Langan s experience with other projects in this area of Brooklyn. According to the USGS Bedrock and Engineering Geologic Maps of New York County and Parts of Kings and Queens Counties, New York, and parts of Bergen and Hudson Counties, New Jersey, dated 1994, the site is underlain by the Hartland Formation. The Hartland Formation is comprised of 1) quartz-biotite-muscovite schist, 2) gray, fine-grained quartz-muscovite-biotite schist, 3) is white to pinkish-white, gneissic granite, 4) is a dark greenish-black amphibolite, and 5) gray, unevenly foliated gneissic schist. Based on a review of USGS topographic maps, groundwater is inferred to flow east-southeast toward the English Kills (tributary to the Newtown Creek). According to the NYSDEC SHWS database for Top Hat Cleaners, located 200 feet north of the site (152 Graham Avenue), groundwater was encountered between 17.5 to 22.5 feet bgs. During the October 2018 due diligence sampling performed by Langan, groundwater was not encountered; however, groundwater was identified between about 7 to 10 feet at a property located 400 feet southeast of the site during a subsurface investigation performed by Langan.

Env Problem:

Nature and Extent of Contamination: This site has been impacted from contamination in the soil medium. No groundwater or soil vapor sample hasn t been collected. Samples from soil medium was analyzed for volatile organic compounds (VOCs), Semi volatiles (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigation conducted to date, the primary contaminants of concern include: SVOCs, barium, cadmium, lead, mercury, pesticides and PCBs in soil. Metals including barium (maximum concentration of 624 mg/kg), which exceeds the Soil Cleanup Objective (SCO) for

159 BOERUM STREET (Continued) **S123658106**

unrestricted use 350 [mg/kg], cadmium (maximum concentration of 5.98 mg/kg), which exceeds the SCO for unrestricted use 2.5 [mg/kg], mercury (maximum concentration of 0.945 mg/kg), exceeds the SCO for unrestricted use 0.18 [mg/kg], lead (maximum concentration of 900 mg/kg), exceeds the SCO for unrestricted use 63 [mg/kg]. Several SVOCs including benzo(a)anthracene (maximum concentration of 21 mg/kg), benzo(a)pyrene (maximum concentration of 20 mg/kg), benzo(b)fluoranthene (maximum concentration of 26 mg/kg), benzo(k)fluoranthene (maximum concentration of 8.9 mg/kg), chrysene (maximum concentration of 20 mg/kg), dibenzo(a,h)anthracene (maximum concentration of 2.9 mg/kg), and indeno(1,2,3-cd)pyrene (maximum concentration of 12 mg/kg) were detected in soil samples collected from from Test Pit 1 exceeding UU and/or Restricted Use Restricted-Residential (RRU) SCOs. Concentrations of benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, dibenzo(a,h)anthracene, and indeno(1,2,3-cd)pyrene were detected in Test Pit 1 at concentrations exceeding both Commercial and Industrial Use SCOs from about 4 to 7.5 feet bgs. Total PCBs in two samples collected from shallow fill (Test Pit 1) exceeded UU SCOs (maximum concentration of 0.159 mg/kg). Several pesticides including 4,4 -DDD (maximum concentration of 0.151 mg/kg), 4,4 -DDE (maximum concentration of 0.128 mg/kg), 4,4 -DDT (maximum concentration of 0.541 mg/kg), and dieldrin (maximum concentration of 0.0544 mg/kg) exceeded the UU SCOs in all soil samples collected from the two test pits.

Health Problem: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: david schwartz
Owner Company: SPG Boerum LLC
Owner Address: c/o slate property group
Owner Addr2: 38 east 29th street, 9th floor
Owner City,St,Zip: new york, NY 10016
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: n/a
Owner Company: brooklyn public library - bushwick branch
Owner Address: 340 bushwick avenue
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11206
Owner Country: United States of America
Own Op: Applicant/Requestor

159 BOERUM STREET (Continued) **S123658106**

Sub Type:	P03
Owner Name:	DAVID SCHWARTZ
Owner Company:	SPG BOERUM LLC
Owner Address:	C/O SLATE PROPERTY GROUP
Owner Addr2:	38 EAST 29TH STREET, 9TH FLOOR
Owner City,St,Zip:	NEW YORK, NY 10016
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	dealice fuller
Owner Company:	brooklyn community board 1
Owner Address:	435 graham avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	DAVID SCHWARTZ
Owner Company:	SPG BOERUM LLC
Owner Address:	C/O SLATE PROPERTY GROUP
Owner Addr2:	38 EAST 29TH STREET, 9TH FLOOR
Owner City,St,Zip:	NEW YORK, NY 10016
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

---

468 ESE 1/4-1/2 0.351 mi. 1854 ft. **CONWAY/EMPTY BUILDING - TTF** **NY LTANKS** **S113406309**
815 BROADWAY **N/A**
BROOKLYN, NY

Relative: Higher

Actual: 42 ft.

LTANKS:

Name:	CONWAY/EMPTY BUILDING - TTF
Address:	815 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1215990 / 2015-01-20
Facility ID:	1215990
Site ID:	479335
Spill Date:	2013-03-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2013-03-01
CID:	Not reported
Water Affected:	Not reported

CONWAY/EMPTY BUILDING - TTF (Continued) **S113406309**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-03-01
Spill Record Last Update:	2015-01-20
Spiller Name:	Not reported
Spiller Company:	CONWAY/EMPTY BUILDING
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOE YANKO
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	92097
DEC Memo:	"Andy- 631-589-6353. Building will be redeveloped. They will repair and retest and send documentation. 3/27/13 AFrischeisen intern TTF letter sent. 5-6-14 Dupigny - Notes from Sangesland what repair work was done to the tank/ Lines? No work was done will Demo the building 10/30/14-Vought-Received call from Chris Lickman (Ph:718-797-9555) who left Vought numerous messages regarding the above spill. Vought left message for Lickman with Demeo's phone number and email address. 1/20/15 TJD File review. 8K concrete wrapped AST failed tightness test. Tester (ATS) determined the cause of the failure was the fill pipe - failure point was interior (tank room) where the pipe penetrated the concrete wrap. Tank was entirely above ground with no petroleum discharge noted during inspection by tester and author of Phase 2 report (PW Grosser). Tank has subsequently been removed and structure was converted to natural gas heat. Based upon the documentation received there was no petroleum discharge from reported tank test failure. All received documentation has been uploaded to DECDOCS. No further action is required. Spill closed."
Remarks:	"8000 gal ast"

All Materials:

Site ID:	479335
Operable Unit ID:	1229071
Operable Unit:	01
Material ID:	2226826
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AO469 **JOHNSON AVE. & BROADWAY** **NY LTANKS** **S100560449**
NW **JOHNSON AVE AND BROADWAY** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.355 mi.
1877 ft. **Site 2 of 2 in cluster AO**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	JOHNSON AVE. & BROADWAY
Address:	JOHNSON AVE AND BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9305896 / 1993-08-13
Facility ID:	9305896
Site ID:	215550
Spill Date:	1993-08-13
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1993-08-13
SWIS:	2401
Investigator:	GRIFFIN
Referred To:	Not reported
Reported to Dept:	1993-08-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-08-16
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	178521
DEC Memo:	""
Remarks:	"U/G GASOLINE TANK APPEARS TO BE LEAKING - NYC FIRE HAZ/MAT CHECKING FIREMAN RICHARD KELLER"

All Materials:

Site ID:	215550
Operable Unit ID:	984053
Operable Unit:	01
Material ID:	395799
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

470
NW
1/4-1/2
0.356 mi.
1882 ft.

BROOKLYN NORTH 03/03A DOS -DDC
306 RUTLEDGE STREET
BROOKLYN, NY

NY LTANKS
NY Spills

S104621574
N/A

Relative:
Higher

Actual:
23 ft.

LTANKS:

Name:	BROOKLYN NORTH 03/03A DOS -DDC
Address:	306 RUTLEDGE STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001698 / 2008-06-23
Facility ID:	0001698
Site ID:	127996
Spill Date:	2000-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jamaison
Referred To:	HOIST OIL
Reported to Dept:	2000-05-10
CID:	366
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-10
Spill Record Last Update:	2008-06-23
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MOHAMMED AZIZ
Spiller Phone:	(917) -
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	114349
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 10/14/04 The spill was reassigned to Alex. This spill is also referred to spill # 9601941,9200212& 0001698. -II (03/02/05). 3/09/06: This spill transferred from I. Islam to Q. Abidi. 5/31/07 Spill case transferred from K. Tang to J. Maisonave. - JAM 6/23/08 This spill case is closed and consolidated with spill number 9200212. Free phase hoist oil has been evacuated from several wells. An active MPE system is also remediating a gasoline spill at this site. Hoist oil will be added to the list of materials for spill number 9200212. See that spill for more information. - JAM"
Remarks:	"North 3-3a garage. "

All TTF:

Facility ID:	0001698
Spill Number:	0001698
Spill Tank Test:	1525572
Site ID:	127996
Tank Number:	2
Tank Size:	550

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

Material:	1096A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	127996
Operable Unit ID:	823519
Operable Unit:	01
Material ID:	289913
Material Code:	1096A
Material Name:	hoist oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BROOKLYN NORTH 03/03A DOS -DDC
Address:	306 RUTLEDGE STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9601941 / 2005-03-02
Facility ID:	9601941
Site ID:	127997
Spill Date:	1996-05-09
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not reported
Reported to Dept:	1996-05-09
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-09
Spill Record Last Update:	2005-03-02
Spiller Name:	ANTHONY MARINO
Spiller Company:	DEPT OF GENERAL SERVICES
Spiller Address:	MUNICIPAL BLDG-15TH FLOOR
Spiller County:	001
Spiller Contact:	ANTHONY MARINO

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

Spiller Phone:	(212) 669-8286
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	114349
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY TRANSFERRED FROM Y.KRIMGOLD. The spill is closed in consultation with Alex to consolidate with spill # 0001698. The site is currently under remediation by LiRo Engineers. - Il (03/02/05)."
Remarks:	"caller received results from soil tests from around an underground storage tank and the results indicated contamination"

All Materials:

Site ID:	127997
Operable Unit ID:	1029528
Operable Unit:	01
Material ID:	351737
Material Code:	9999
Material Name:	other -
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BROOKLYN NORTH 03/03A DOS -DDC
Address:	306 RUTLEDGE STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8809462 / 2005-03-02
Facility ID:	8809462
Site ID:	132862
Spill Date:	1988-11-02
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not reported
Reported to Dept:	1989-03-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-03-08
Spill Record Last Update:	2005-03-02
Spiller Name:	Not reported
Spiller Company:	DOS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

DEC Region:	2
DER Facility ID:	114349
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMERSKY The spill is closed in consultation with Alex to consolidate with spill # 9200212. The site is under remediation by LiRo Engineers. - II (03/02/05). "
Remarks:	"550 GALLON TANK FAILED A NYCFD AIR PRESSURE TEST, UNDETERMINED LEAK RATE, PUMPED OUT TANK, WILL RETEST."

All TTF:

Facility ID:	8809462
Spill Number:	8809462
Spill Tank Test:	1535230
Site ID:	132862
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	132862
Operable Unit ID:	925527
Operable Unit:	01
Material ID:	454194
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	BROOKLYN NORTH 03/03A DOS -DDC
Address:	306 RUTLEDGE STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9200212 / Not Reported
Facility ID:	9200212
Facility Type:	ER
DER Facility ID:	114349
Site ID:	292895
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1992-04-07

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

Investigator:	adzhitom
Referred To:	PRE-DESIGN INV WP APPRVD
Reported to Dept:	1992-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	5
Date Entered In Computer:	1992-04-08
Spill Record Last Update:	2019-05-29
Spiller Name:	Not reported
Spiller Company:	NYC DOS
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY The spill is referred to spill # 8809462. The site is currently under remediation by LiRo Engineers. - II (03/02/05). 4/28/05- Reviewed the monthly monitoring report-Jan/05. A multi-phase extraction system is in place and is performing well. Both vapor and water effluent are under compliance. A trace (.01 ft)of free product persists at one well only as revealed from monthly monitoring data. Quarterly groundwater sampling results show persistently decreasing trend and are close to under compliance. Soil sampling is done semiannually. Routine site monitoring to continue. 3 monthly electronic files have been installed in the eDoc Folder.- II 6/6/05- Reviewed Feb/05 & Mar/05 monthly monitoring reports. The MPE system monitoring data shows that it is working effectively. Neither of the scheduled Quarterly GW sampling nor Semi-annual soil sampling were done during the monitoring period as they were not due in this period. All monitoring wells have become free from Free Product. Routine monitoring to continue as scheduled.- II 7/22/05- Reviewed the Monthly Monitoring Report prepared by LiRo Engineers dated May 27, 2005. The report presents MPE system performance monitoring data for the month of April, 2004. The system monitoring data indicate that vacuum measurements were not taken at two monitoring wells and six (50%) extraction wells. This lack of readings prevents DEC from properly evaluating the system s effectiveness. Sent the above comment to DDC and LiRo via email. Installed the monthly monitoring reports for Feb., Mar. & Apr./05 in the eDoc Folder. - II 8/23/05- Reviewed the May/05 monitoring report. The report presents MPE system operating data and GW sampling results for the month of May/05. Apprx. 0.3 lbs VOC was collected and the MPE system is functioning effectively.Monthly GW sampling could not be done on wells EW-6 & MW-8 due to deposits lining the inside of the drop tube and well EW-1 & MW-13 for being under water. Over all, the GW contamination has reduced substantially and four of the wells sampled in May/05 still exceed NYSDEC quality criteria for one or more compounds. Routine monitoring will cintinue.- II. 9/19/05- Reviewed the June & July/05 monthly monitoring reports. MPE system is operating effectively. Approx. 2.8 lb VOC was collected during July month which is very high compared to the June month. LiRo did not explain the reason.

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

Quarterly GW sampling was not due during the monitoring period. Routine system monitoring will continue. - II. 10/25/05- Reviewed the August/05 monitoring report. The MPE system collected about 0.5 lb VOC during the month and the last month's spike (2.8 lb) is said to be an anomally. Overall GW contamination at most wells has been significantly reduced. Low level Product has appeared in two wells and they have been sampled for fingerprint analysis. Of the four wells sampled, two wells were non-detect for STARS list compounds. Other two wells showed a very slight increase in TVOC contamination. However, routine monitoring will continue.- II 11/18/05- Reviewed the Sept. & Oct/05 monthly monitoring reports. Product appearance in wells LW-1 & MW-1 have been found to be mineral spirit and hydraulic oil respectively by fingerprint analysis. In Sept. & Oct/05 the MPE system collected 4.2 lbs and 2.4 lbs of VOCs respectively. LiRo states this increase in influent VOC levels during the period due to system cleaning and drop tube adjustments which the contractor Franklin conducted during this period. GW sampling was not due during this two months of monitoring period. LiRo recommends to continue operation of the MPE system with improved induced vacuum. LiRo also recommends installation of passive skimmers in two wells having product. LiRo's recommendation for passive skimmers installation and plan for next round of annual soil sampling four borings) are approved with an additional boring to be located in the vicinity of GPR-13. Filed the monthly reports in the eDoc folder.- II 01/31/06: This spill transferred from Imdad to Q.Abidi. Reviewed November/05 monthly monitoring report. Quarterly groundwater sampling was not performed during this monitoring period. On Dec.6, 2005 Liro pumped out wells LW-1 and MW-1 with a vacuum truck, removing 1,412 gallons of contaminated fluids, of which an estimated 14 gallons was free product. Liro recommends to continue the system operation. No response letter necessary.- QA 02/07/06: Reviewed December/05 Monthly monitoring report. Quarterly groundwater sampling was not performed during the monitoring period. LiRo recommends that the vacuum truck should return to the site to treat wells LW-1 and MW-1. Site is being transferred to Greyhawk. Data show decrease in induced vacuum levels, possibly indicating a line blockage.Liro suggest New CM should evaluate the site and determine whether system should be cleaned, or shut down and only use a vacuum truck on LW-1 and MW-1. Filed the monthly report in the eDoc folder.- QA 08/18/06: Transferred to S.Kraszewski. According to URS Bi-monthly update report Rouc performed GW sampling and gauging on April 5, 2006. VOCs detected range from 6 ppb to 532 ppb. SVOCs were below detection. Monthly gauging on May 5, 2006 revealed 0.22 ft of product in LW-02 and 0.01 ft in LW-01. On June 15, 2006 no free product in LW-02 and 0.01 ft of product in LW-01. An absorbent sock was placed in LW-01. - SK 08/31/06: Reviewed Quarterly O&M and MOnitoring Report for April-June 2006 submitted on July 7, 2006 by Greyhawk/Roux. On April 5, 2006 Roux gauged and monitoring wells EW-1, EW-4, EW-6, EW-9, LW-1 and LW-2. Gauging occured on May 5 and June 15 as well. GW flow direct was determined to be southernly. No free product in April, but 0.01 ft for LW-1 and 0.22 ft for LW-2 in May. In June, LW-1 had 0.01 ft. All six MWs revealed VOCs ranging from 6 ppb to 532 ppb with several TAGM exceedances. No SVOCs detected in GW. Greyhawk plans on contiuing quarterly GW sampling but recommends reducing the gauging and free product removal frequency from monthly to quarterly visits. Low PID readings for influent and effluent air. However, influent air TVOCs reveal 3250 ug/m^3 in April and 877 ug/m^3 in June. Since the

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

system is still effectively removing volatiles Greyhawk recommends contiued operation and maintenance of the MPE system. They will attempt to increase the vacuum in EW-3 and EW-12. SK called Andris Ledins at Greyhawk (718-943-1100.) Left a message to call back. - SK 10/27/06 Spill case transferred from S. Kraszewski to J. Maisonave. - JAM 5/31/07 Reviewed Quarterly Monitoring Report for July through September 2006 submitted by Roux and dated Nov. 10, 2006. Free phase product was detected in wells LW-02 (0.01 foot) and product sheen detected in EW-06 on July 20, 2006. During the previous quarterly monitoring period (April through June 2006), free product was detected in well LW-01 (0.01 ft) and LW-02 (0.22 ft). Groundwater samples were collected from wells on the quarterly schedule (more wells are sampled on an annual schedule at this site) and the highest level of TVOCs was 693ug/L in LW-01. The MPE system continues to run however restricted vacuum readings have been observed in multiple monitoring wells and ventilation wells. 6/11/07 Reviewed Quarterly Monitoring Report for October Through December 2006 submitted by Roux and dated March 15, 2007. Free-phase product was detected in wells LW-02 (0.10 ft) and EW-06/MW-08 (0.15 ft) and product sheen was observed in LW-01 during the October gauging event. Wells EW-06/MW-08 was not gauges in December because of a DOS truck was obstructing and LW-01 and LW-02 had petroleum absorbent socks which were removed. Groundwater samples were collected from wells on the quarterly schedule and the highest level of TVOCs was 261ug/L in LW-01. The MPE system has had an uptime of approximately 80 percent during this monitoring period. However, the system has been hampered by the decreased inlet header vacuum, which resulted in the system s inability to extract groundwater and expose the smear zone. Attached in the appendices were an Enhanced Bioremediation Work Plan and Additional Site Investigation Work Plan. The Enhanced Bioremediation Work Plan proposed injecting a bacteria/enzyme mixture at wells LW-01, LW-02 and MW-16. These wells would be monitored to evaluate the effectiveness of the injection. I requested that EW-07/MW-09 be included in the monitoring program and approved the work plan. The Additional Site Investigation Work Plan proposed the advancement of seven soil borings in locations as shown in Figure 8. I requested that the new borings be advanced as close as possible to the original soil samples collected at the beginning of the site investigation and approved the work plan. Additional recommendations to the O&M Procedures are as follows: 1) Convert MPE system to SVE system 2) Reduce frequency of the quarterly groundwater monitoring program to semi-annual 3) Reduce frequency of gauging from monthly to quarterly 4) Remove SVOCs from the groundwater sampling program 5) Remove wells EW-05, MW-12 and MW-15 from the groundwater sampling program. Recommendations 1, 3, 4, and 5 were approved. Since a new remedy is being implemented at the site groundwater monitoring should continue on a quarterly basis for several more round. The reduction of monitoring frequency from quarterly semi-annual will be reevaluated at a later date. A letter was sent today with these approvals and can be found in edocs. - JAM 3/3/08 Reviewed Quarterly O&M and Monitoring Report for period January through June 2007 submitted by Roux and dated September 18, 2007. MPE system operated at the site and as currently configured the MPE system is not operating efficiently to remediate residual soil and groundwater. Groundwater samples were collected from select wells in January and April 2007 for VOCs and SVOCs. No SVOCs were detected in any wells and TVOCs were observed ranging from ND to 84ug/L. Roux states the MPE system has effectively

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

reduced levels of free product and residual soil and groundwater contamination. During the next monitoring event Roux will conduct quarterly monitoring, implement the approved bioremediation WP and convert the MPE system to an SVE system. - JAM 6/10/08 Spoke to Brian Morrissey at Roux. He said the DOS is terminating their lease and moving from the site. They will maintain liability for the spill. Several tanks on the site will be closed. The In-situ Bioremediation work plan should be implimented soon. The MPE system will also be converted to an SVE system. I have received emails from Envirotrac notifying the DEC that the MPE system has been shut down due to a faulty solenoid valve. The valve will be replaced and the extimated down time is 1 week. - JAM 6/23/08 Spill number 0001698 was closed and consolidated with this spill number. Hoist oil was observed in several wells which has been evacuated or removed by petroleum absorbent sock. I added Hoist Oil to the material list on this spill case. I called Brian Morrissey and let him know that spill number 0001698 was closed and consolidated with this spill. - JAM 7/28/08 Reviewed Quarterly Monitoring Report for period July 2007 through May 2008 submitted by Roux and dated June 24, 2008. The MPE system operated at the site with an uptime of 81 percent. As configured the MPE system is not operating effectively and needs optimization. Free product was detected in 4 of the on-site monitoring wells with a max thickness of 0.38feet in well EW-09/MW-03. Product identified as hydraulic oil or heavy lubricating oil. VOCs were detected in several wells with the max detection during the reporting period of 512ug/L in LW-01 in July 2007. Roux advanced six soil borings as per the approved work plan to a depth ranging between 24 to 31 feet. VOCs were detected in 4 of the six borings with a max of 249400ppb in RXSB-02 from interval 19-21fbs. Roux recommends the following: 1. Continue quarterly groundwater monitoring program. 2. Continue using petroleum absorbent socks in wells LW-01 and LW-02. 3. Conduct a soil investigation (as proposed in Appendix E) near the three UST areas in the south-southwester part of the site. 4. Optimize the MPE system performance. I sent an email today approving these recommendations. A work plan should be submitted in a separate letter for approval that describes the optimization of the current MPE system in more detail. The letter should include a process and instrumentation diagram and a site diagram showing the additional extraction points. The report and email are uploaded to eDocs. - JAM 9/12/08 Received an email from Tom Hug at Envirotrac. The MPE system was shut down because the discharge line has become clogged and the system is shutting down on a high water alarm. As soon as the blockage is cleared the system will be restarted. Estimated downtime is 1 week. - JAM 5/12/10 Received an email from Stephen Frank at LiRo and Fatemah Ashkan at the NYCDDC. LiRo proposed a conceptual remedy, which includes excavation and removal of USTs on-site as well as injecting chemical oxidants to treat smear zone and groundwater contamination. I sent a reply email stating that, The proposed approach is acceptable; however, a remedial action work plan (RAWP) must be submitted to the DEC for approval. The RAWP should include a detailed description of the proposed excavation/tank removal work with figures showing the proposed excavation limits and an end-point soil sampling plan. The RAWP should also include a chemical oxidant injection plan with a detailed description of the chemical oxidant to be used, how the chemical oxidant will be applied and a monitoring plan to evaluate the effectiveness of the remedy. I also notified them that the EPA Underground Injection Control Program needs to be notified and an

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

application must be submitted to perform the chemical oxidant injections. - JAM 6/25/10 Reviewed the Proposed Site Pre-Design Investigation Work Plan for the above referenced site submitted by LiRo Engineers, Inc. (LiRo) dated June 16, 2010. The work plan was prepared for the tanks located on the adjacent property at 314 Rutledge Street and proposes advancing nine soil borings and installing two groundwater monitoring wells. The purpose is to locate the three previously abandoned tanks and delineate soil and groundwater contamination, and to determine the limits of the planned soil excavation and design a chemical oxidation injection program, which constitute the remedial strategy approved by the NYSDEC via email on May 12, 2010. The work plan is uploaded to eDocs. I issued a letter today approving this work plan. A summary report including appropriate diagrams, soil boring logs, well construction logs, and tables summarizing soil and groundwater analytical data should be submitted to the NYSDEC for review. A detailed remedial action plan based on the findings of this investigation should also be included for review and approval. Letter uploaded to eDocs. - JAM 11-10-2010 The spill was transferred from J. Maisonave to Alex Zhitomirsky, as per V. Brevdo/J. Kolleeny. AZ 2-14-2011 Reviewed revised additional soil and geophysical investigation summary report and remedial action work plan dated 10/13/2010 and received from J. Kolleeny on Dec. 20, 2010. The plan proposed an in-situ chemical oxidation system to treat smear zone and phreatic zone at 314 Rutledge St. Also, the plan proposed excavation of the remaining USTs and excavation of the remaining residual soil contamination and injections of a metal solution, hydrogen peroxide, and a biological treatment at 306 Rutledge Street. An e-e-mail was sent to S. Frank, V.Brevdo and F. Ashkan: I have reviewed a Revised Soil and Geophysical Summary Report and Remedial Action Work Plan dated October 13, 2010. The Work Plan is approved. The Responsible Party and Contractors are responsible for the safe execution of the Work Plan. AZ 8-18-2011 The following e-mail was received from S. Frank (LiRo) on 8/18/2011: At the Quarterly meeting we discussed Brooklyn 3/3A. As you know, NYCDOS moved out of the leased site several years ago. There is currently litigation over rent payments and site impacts that have been ongoing between the property owners and NYC. To complicate matters, the former DOS site includes two separate properties (306 Rutledge and 314 Rutledge) that are owned by two different parties. Both parties are separately in litigation with the City. The City is committed to remediating both properties, but in the past, all site contamination was being addressed under a common spill number associated with fuel oil releases on the 306 Rutledge property. We have acquired Sanborn Fire Insurance maps that show that the 314 site had historically been used for dry cleaning and the historical mapping shows solvent tanks in the portion of the site where the contamination was identified as mineral spirits (see attached Sanborn Map). A mineral spirits derivative was historically used for dry cleaning. The City has inquired if it would be possible to open a separate spill number for the mineral spirits release at the 314 Rutledge Street property. At the meeting, Vadim indicated that NYSDEC would review the site information and advise DDC with regard to opening a new spill for mineral spirits at 314 Rutledge Street. I was wondering if you have had an opportunity to discuss this issue with him. AZ 8/22/2011 The following e-mail was sent by S. Frank (LiRo) to Vadim Brevdo and AZ on 8/22/2011: Dear Mr. Brevdo, I am writing to follow-up on our quarterly meeting conversation regarding the former use of 314

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

Rutledge Street for Dry Cleaning and the identification of a mineral spirits release. Mr. Alex Zhitomirsky called me to inquire weather chlorinated dry cleaning hydrocarbon compounds (i.e., tetrachloroethene and/or its breakdown products) were present. LiRo tested for full Target Compound List (TCL) volatile organic compounds during our February 2011 groundwater sampling of wells in the area of concern (314 Rutledge and 306 Rutledge at the common wall with 314 Rutledge) and the results are summarized in the attached table. Based on the February 2011 sampling, there is no evidence that chlorinated compounds are present in groundwater and all samples showed a chemical identification of mineral spirits. Thank you for your attention to this matter and do not hesitate to contact me if your office needs additional information. AZ 10/26/2011 An e-mail with the information regarding the Owner of 314 Rutledge, LLC. Contact info: c/o Abraham Glanzer, 718 855-9100. Mailing address: Edith Kahan and/or Abraham Glanzer, 170 Hewes St, Brooklyn, NY 11211. AZ 10/31/2011 Discussed this site w/V. Brevdo. Contacted S. Frank of LiRo and requested a technical memo which will summarize all information related to a mineral spirits spill. 12-13-2011 Received an email from S. Frank: Dear Alex, I wanted to update you on the status of remedial work at Brooklyn 3/3A. We are installing injection wells for the ISCO work at both properties (314 Rutledge and 306 Rutledge) as well as removing tanks that were formerly closed in place in the building interior at 306 Rutledge. In conjunction with the tank removal work, we are over-excavating contaminated soil to the extent possible. We are hoping to finish the well installation and tank removal work this week. We expect the ISCO injection work will begin within a couple of weeks after the well installations are completed. AZ 2-13-2012 Reviewed and discussed with V. Brevdo a report by LiRo Former DSNY Brooklyn 03/3a Garage Request for spill number for mineral spirits released at 314 Rutledge. The report states that contamination at 314 Rutledge is a different spill and plume from 306 Rutledge. A spill at 306 Rutledge is allegedly caused by mineral spirits. According to the report, this site was a dry cleaning operation between 1947 and 1965. The Sanborn maps indicate the presence of solvent tanks located along eastern wall of 314 Rutledge which is adjacent to the 306 Rutledge Street property. Petroleum based mineral spirits (Stoddard solvent was historically used in dry cleaning operations. Soil and groundwater investigation completed by EBC (contractor working for 314 Rutledge owner) at 314 Rutledge in 2008 indicated petroleum related VOC in soil and groundwater. EBC recommended the DEC Hotline be notified, however, it was not done. Free phase product fingerprint analysis for the sample from MW-18 (located at 314 Rutledge) identified the product as mineral spirits. Routine groundwater sampling completed in February 2011 from 314 Rutledge wells MW-17 and MW-18 indicated petroleum identification as mineral spirits. DSNY records indicate that petroleum fuel storage and fueling operations were never conducted by DSNY at the 314 Rutledge parcel. However, PBS records indicate that there are three 1,500 gal tanks closed and registered by DSNY in 2000. Product stored indicated as gasoline. This discrepancy must be resolved. S. Frank indicated that these tanks were filled with concrete and will be excavated by LiRo. I requested to attempt fingerprinting any remaining product or sludge in the tanks in question. Also, the tanks design should be described. The Sanitation is leasing this site from 1993. LiRo should submit tank inspection results. LiRo should submit any information supporting statement that

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

DSNY did not use 314 Rutledge for fueling or storage. LiRo should include fingerprint analysis of the alleged mineral spirits. The site was discussed with J. Urda. It was decided that V. Brevdo will contact A. Samani and request a conference call with a City lawyer AZ 10-3-2012 LiRo issued a report in August 2011, stating that Empire Environmental conducted the tank removal and remedial soil excavation work at 306 Rutledge from December 2011 to January 2012. The report was uploaded to e-docs. AZ 10-4-2012 According to LiRo's report dated January 8, 2012, tanks 009, 010 and 011 are 1,500-gallon gasoline USTs which were closed in place at 314 Rutledge in 2000. These tanks were registered as gasoline tqanks. However, according to DSNY records, petroleum fuel was not stored and petroleum fuel operations were not conducted at the 314 Rutledge parcel. The results of geophysical investigation did not indicate the presence of USTs beneath the site. In October 2010, free phase product was observed in 314 Rutledge St. well MW-18. Fingerprint analysis identified the product as mineral spirits. Soil and groundwater contamination are present at 314 Rutledge. However, in the report dated August 8, 2012, LiRo stated that they located and removed previously closed in place mineral spirits tanks at 314 Rutledge Street parcel. A report for the 314 Rutledge Street tank removal will be submitted to DEC under separate cover. Discussed the site with V. Brevdo. AZ 1-2-2013 Reviewed LiRo's report dated August 8, 2012. According to the report, Spill#9200212 was opened in in 1992 due to the release of gasoline and hoist oil in the southern portion of the 306 Rutledge parcel of the site. Underground storage tanks (USTs) and aboveground storage tanks (ASTs) used by DSNY for storing gasoline and hoist oil include three 550-gallon USTs (Tanks 012, 013, and 0140, one hoist oil UST and one hoist oil AST). Multi-phase extraction system was made operational in 2002 and shut down in 2008 because of operational issues. The proposed remedial plan included soil/UST excavation to address spill#92002112 in the 306 Rutledge portion of the site. In addition, the plan proposed chemical oxidation to treat mineral spirits contamination supposedly coming from the historic dry cleaning operation at 314 Rutledge. 1-11-2013 A CSL was sent to C/O GLanzer 170 Hewes Street, Brooklyn, NY 11211. Copies were sent to J. Urda/V. Brevdo. AZ 12-5-2013 Reviewed a semi-annual monitoring report through March 2013. According to the report, mineral spirit related impacts from the 314 Rutledge St. parcel, are present in in wells near the common wall with 314 Rutledge and two wells located along Rutledge St. These include wells LW-01, MW-16, IP-22, IP-23, IP-29, MW-22 and MW-23. Total VOC concentrations above the standards ranged from 42 ppb to 3,870 ppb. Contamination fingerprint identification completed previously at IP-22 and MW-22 identified mineral spirits. Residual motor fuel impacts, mainly Benzene and MTBE are present at 306 Rutledge wells, RXMW-01, MW-03/EW-09, MW-01 and RXMW-07, located along Heyward Street. Total VOC concentrations above the standards ranged from 7 ppb to 150 ppb. A trace level (less than 0.03') of residual oil has been detected intermittently at wells RXMW-01 and MW-03/EW-09 located along Heyward Street. The oil was historically identified as a mixture of lube oil and kerosene. AZ 09-16-2014 Reviewed a semi-annual monitoring report for the period of April 2013 through October 2013, dated January 16, 2014. In October 2013 free-phase product was observed in wells EW-09/MW-03, RXMW-01 and MW-22. No groundwater samples were collected from the Site's interior wells since LiRo was unable to gain access from the current site owner to the interior of the 306 Rutledge Street parcel.Residual

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

motor fuel VOC (MTBE) impacts are present in 306 Rutledge street parcel. Residual motor fuel, VOC (MTBE) impacts are present in 306 Rutledge street parcel well RXMW-07, located along Howard Street(29 ppb). Free phase product was noted in wells EW-09/MW-2 and RXMW-01 along Howard Street. Petroleum absorbent socks were placed in wells RW-09/MW-03, RXMW-01 and MW-22 during the October 2013 sampling event. All three wells were gauged again in November 2013 and December 2013 and attempted to collects product samples for TPH petroleum identification. The only well exhibiting free phase product was MW-22. A TPH sample was collected and identified as mineral spirits. AZ 1-22-2015 Reviewed a semi-annual monitoring report for the period of November 2013 through May 2014, dated June 30, 2014. Free phase product was measured in wells FW-09/MW-03, RXMW-01, MW-01 and MW-22 (exteroir 314 Rutledge parcel well) in April 2014, and petroleum absorbent socks were re-installed. TPH samples were collected from EW-09/MW-03, RXMW-09, RXMW-01 and MW-01. The product was generally identified as #2 fuel oil/motor oil mixture or motor oil. The product in MW-01 could not be identified due to low volume of product. On May 13, 2014, LiRO completed EFR on Heyward Street wells (RXMW-01, MW-01, EW-09/MW-03. during the EFR event the only well with measurable free-phase product was RXMW-01. AZ 7-31-2015 Reviewed semi-annual monitoring report for the period of June 2014 to December 2014 and dated 1/29/2015. Free phase product identified as mineral spirits was measured in well MW-22(314 Rutledge Street parcel well).The product thickness ranged from 0.43' to 0.89' thick. Free phase product was measured in well RXMW-01 on Aug. 20, 2014 at 0.13' thick. LiRo performed EFR on September 3, 2014. Absorbent socks were changed on a regular basis during this monitoring period. During the August 2014 gauging event, LiRo noticed that wells RXMW-01 and MW-22 had been tempered with. The petroleum absorbent socks in both wells had been raised and were no longer situated at the groundwater table. LiRo returned to the Site on September 4, 2014 and installed locked j-plugs in the exterior wells. The wells were also tagged. AZ 12-1-2015 Reviewed semi-annual monitoring report for the period of January 2015 to June 2015 and dated 9/01/2015. Free phase product identified as mineral spirits was measured in January 2015 and June 2015. The product was measured in wells MW-16, MW-22, IP-18 and IP-22 during the January 2015 sampling and in wells MW-22, IP-22 and RXMW-01 during the June 2015 sampling. Product thickness ranged from 0.03' to 1.42'. Free -phase product was consistently measured in well MW-22(314 Rutledge Street parcel well). Interior well LW-01 was discovered as being damaged in January 2015. LiRo will utilize nearby well IP-18 as a substitute for sampling and gauging. I left a message for S. Frank requesting continuation of semi-annual monitoring of groundwater monitoring wells at 306 Rutledge Street parcel. AZ 12-15-2015 Reviewed additional groundwater data submitted by LiRo on 12/15. Discussed the site with S. Frank It was decided that LiRo will fingerprint free product from IP-18 and reinstall three monitoring wells MW-2, MW-10 and MW-12 located on Heyward street and near RXMW-01 that contains free product (motor oil). AZ 12-22-2015 On December 22, 2015, a meeting was held among the Department (K. Mintzer, V. Brevdo, Alex Zhitomirsky), owners of the 306 Rutledge Street site and their environmental consultant (Mohamed Ahmed, Tenen Env.) and legal counsel. The current status of the spill cases on both 306 and 314 Rutledge Street properties, path forward towards spill case closure and potential site development were discussed during the meeting. The DER has completed preparation of the case

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

referral form to OGC to enforce cleanup of the 314 Rutledge Street parcel and is preparing Stipulation Agreement and Corrective Action Plan for the owners of the 314 Rutledge Street parcel. AZ 12-23-2016 Reviewed a semi-annual monitoring report dated April 14, 2016. On 12/21/2015 Sheen was encountered at monitoring well RXMW-01. The free-phase product in this well is motor fuel. Petroleum absorbent socks have been used to remove low levels of product. Wells associate with 306 Rutledge Street (spill#9200212) reported low levels total dissolved VOCs: less than 130 ppb. AZ 10-26-2017 Reviewed a semi-annual monitoring report dated April 4, 2017. Measurable FREE-PHASE product was encountered at monitoring well RXMW-01 and MW-01. EFR was performed on two wells on November 2016. Petroleum absorbent socks have been used to remove low levels of product. Wells associated with 306 Rutledge Street (spill#9200212) reported low levels total dissolved VOCs: less than 95 ppb. Only four out of 15 wells of the interior at 306 Rutledge were accessible. AZ 2-22-2018 Reviewed a semi-annual monitoring report dated August 25, 2017. During this monitoring period measurable free-phase product was reported twice in well MW-01 (0.24'and 0.19') EFR was performed on April 10, 2017. Petroleum absorbent socks were changed. Historically, free phase product has been measured in 306 Rutledge Street parcel interior well IP-22, however, the well was covered with debris during this monitoring period. AZ 9-18-2018 Reviewed a semi-annual monitoring report dated March 1, 2018. During this monitoring period free-phase product was not measured in any Heyward Street wells (September and October 2017). However, petroleum absorbent socks were maintained in these wells. LiRo was unable to gain access to the interior wells of 306 Rutledge, therefore, there is no groundwater data for these wells. Numerous interior wells were covered with debris, garbage, storage pallets, etc., and could not be gauged. Well IP-22, which historically contained mineral spirits free-phase product, was covered with debris and could not be gauged. Mineral spirits contamination migrated onto 306 Rutledge Street interior wells in the northeast corner along the common wall with 314 Rutledge Street. AZ 9-27-2018 On September 27, 2018, DEC met with 306 Rutledge representatives. Regional Attorney Patrick Foster (DEC), Vadim Brevdo (DEC), Chris Gorman and Michael Bogin (the owner's counsel), and Mohamed Ahmed (the owner s consultant, Tenen Environmental) were present. The status of the site was discussed. DEC expressed concerns regarding access for the City s consultant, LiRo, to the interior of the site. Mr. Gorman 516-328-2300)promised to assist with this issue; his contact information will be provided to LiRo. The off-site mineral spirits contamination from 314 Rutledge into 306 Rutledge was discussed. The 306 Rutledge owners requested that the 314 Rutledge owners expedite the cleanup of the mineral spirits spill. DEC agreed to contact the 314 Rutledge owners to request that they expedite the cleanup. Mr. Bogin stated that if the City is willing to excavate the remaining petroleum contamination at 306 Rutledge, the 306 Rutledge owners will demolish the existing on-site structures. This proposal will be discussed with the DDC consultant LiRo. AZ 1-29-2019 On January 29, 2019, a meeting was held between the representatives of 306 Rutledge Street property owners, NYCDDC, NYC Law Department, DSNY and NYSDEC (represented by Alex Z, Vadim B. and Regional Attorney) to discuss further course of action for the project. During this meeting 306 Rutledge Street site owner s counsel reiterated their readiness to demolish the building on the property to expedite remediation if the City commits to excavation of the contaminated area to complete

BROOKLYN NORTH 03/03A DOS -DDC (Continued) **S104621574**

remediation. City Law Department expressed concern about the cost of remedial excavation as opposed to product recovery via absorbent socks. The Department stated that it s priority is to have the remedial work completed and spill closed. The NYC Law Department stated that they will hold additional internal discussions on whether City can commit to remedial excavation and get back to 306 Rutledge Street property owner and the Department. 5-29-2019 Reviewed a semi-annual monitoring report dated October 27, 2018. During this monitoring period free-phase product was not measured in any Heyward Street wells (associated with 306 Rutledge Street). However, petroleum absorbent socks were maintained in these wells. A sheen was noticed in RXMW-01 following purging. Petroleum absorbent socks were replaced in wells RXMW-01 and MW-01 on March 1, 2018. Free-phase product was measured in well MW-22 associated with 314 Rutledge Street during this monitoring period. Access to 314 Rutledge wasn't provided during March 2018 sampling event. However, the owner did provide access during the October 2018 sampling event. AZ ‘“"

Remarks: "U.G. TANK INSIDE BLDG, NOT USED FOR 10 YEARS. EXCAV. FOR NEW FLOOR, DISCOVERED CONTAMINATED SOIL. SHOULD BE CHECKED ASAP, PLAN TO POUR NEW FLOOR SOON."

All Materials:

Site ID:	292895
Operable Unit ID:	964234
Operable Unit:	01
Material ID:	2148028
Material Code:	1096A
Material Name:	hoist oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	292895
Operable Unit ID:	964234
Operable Unit:	01
Material ID:	415034
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

471
ENE
1/4-1/2
0.357 mi.
1884 ft.

CON ED
130 MOORE ST
BROOKLYN, NY 11206

NY LTANKS **S105999336**
NY MANIFEST **N/A**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	SPILL NUMBER 0303435
Address:	130 MOORE ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0303435 / 2003-07-02
Facility ID:	0303435
Site ID:	264329
Spill Date:	2003-07-02
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2003-07-02
CID:	233
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-07-02
Spill Record Last Update:	2003-07-02
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	215440
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO "
Remarks:	" veh parked near spill seems to be leaking leaking has stopped speedy dri was applied "

All Materials:

Site ID:	264329
Operable Unit ID:	870541
Operable Unit:	01
Material ID:	504303
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

CON ED (Continued) **S105999336**

NY MANIFEST:

Name:	CON ED
Address:	130 MOORE ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004851693
Facility Status:	Not reported
Location Address 1:	130 MOORE ST
Code:	BP
Location Address 2:	SB 16060
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004851693
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/2015
Trans1 Recv Date:	10/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004851693
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014470959JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON ED (Continued) **S105999336**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

472
WNW
1/4-1/2
0.359 mi.
1894 ft.

UNITED STATES ARMORY
355 MARCY AVENUE
BROOKLYN, NY 11206

NY LTANKS **S103569544**
NY Spills **N/A**

Relative:
Higher

Actual:
18 ft.

LTANKS:

Name:	355 MARCY AVE/NYS ARMORY
Address:	355 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8806820 / 1992-10-07
Facility ID:	8806820
Site ID:	135895
Spill Date:	1988-11-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1992-10-07
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-11-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-11-18
Spill Record Last Update:	2004-01-02
Spiller Name:	Not reported

UNITED STATES ARMORY (Continued) **S103569544**

Spiller Company:	NYS ARMORY
Spiller Address:	355 MARCY AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	116651
DEC Memo:	""
Remarks:	"5K TANK FAILED PETRO TITE WITH A LEAK RATE OF -.626GPH, OGS PROJECT, SYSTEM TEST,WILL TEST ONLY TANK NEXT.5K TANK FAILED ISOLATED PETROTITETEST AT -.605GPH, TANK SHOULD BE PUMPED OUT & REPLACED."

All TTF:

Facility ID:	8806820
Spill Number:	8806820
Spill Tank Test:	1534896
Site ID:	135895
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	135895
Operable Unit ID:	921984
Operable Unit:	01
Material ID:	455162
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	UNITED STATES ARMORY
Address:	355 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Spill Number/Closed Date:	9604202 / 2013-10-10
Facility ID:	9604202
Facility Type:	ER
DER Facility ID:	442306
Site ID:	204041
DEC Region:	2

UNITED STATES ARMORY (Continued) **S103569544**

Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-06-27
Investigator:	RVKETANI
Referred To:	100913 APPRVD REMEDIATION REPORT
Reported to Dept:	1996-06-27
CID:	252
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-27
Spill Record Last Update:	2013-10-15
Spiller Name:	MICHAEL CONICO
Spiller Company:	DIV MILITARY NAVAL AFFAIR
Spiller Address:	330 OLD NISKAYUNA RD
Spiller Company:	001
Contact Name:	SALVATORE MENNELLA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 4/12/04-Vought-Spill transferred from Mulqueen to Vought as per Rommel. 3/24/06 Diaz - Next steps required - review file, track down contacts. Spill transferred back to Region 2 3/10/08 - Austin - Spill assigned to Ahmed for followup - end 10/27/11 - Austin - Transferring this case from Ahmed to Ketani - end 9/23/13 - Raphael Ketani. I spoke to Heidi Unwin (518) 786-4347, Environmental Specialist II, Environmental Compliance Branch regarding the spill. She said that she had been looking through some old records and discovered that the spill had not been closed out. I told her that the DEC had only two letters stating that the investigation and remediation was going to take place. Ms. Unwin stated that she will send the DEC copies of all of the remediation, sampling and disposal information that she has on file. 10/8/13 - Raphael Ketani. Ms. Unwin sent 4 documents regarding the tank removal and soil excavation. These documents were: the Solution Mechanical Corp. 7/11/96 pre-excavation soil endpoint analytical report; the Solution Mechanical Corp. 7/18/96 post-excavation soil endpoint analytical report; the Solution Mechanical Corp. 7/26/96 tank removal and remediation report; and the NYS Division of Military and Naval Affairs 10/2/13 Spill Closure Letter. The pre-excavation soil endpoint samples were analyzed for VOCs and SVOCs. Samples were taken from all four sidewalls and two samples from the bottom. The results were either non-detect or well below the CP-51 unrestricted standards. The post-excavation soil endpoint samples were analyzed for VOCs and SVOCs. Samples were taken from all four sidewalls and two samples from the bottom. Samples were also taken from the soil stockpile and around the stockpile. The results were almost entirely non-detect for the endpoints and non-detect to well below standards for the soil stockpile samples. The tank removal and remediation report had a map showing where the tanks and the pump islands had been. Both 2,000 gal. USTs had contained gasoline, even though one was labeled as containing diesel. The cause of the spill was the

UNITED STATES ARMORY (Continued) **S103569544**

sweating of product from the joints of the fill pipes and the suction lines. The excavation of the soil had started on 6/24/96. The contaminated soil was shipped to a landfill in Albany, NY. Tanks were cleaned and shipped to a scrap metal facility. Manifests were included for the soil and the tanks. The Spill Closure Letter stated that about 63.4 tons of soil had been excavated. 10/10/13 - Raphael Ketani. The spill case was presented to Hassan Hussein, supervisor Unit C, Region 2, Remediation for closure. Mr. Hussein accepted the closure of the spill case. Based upon the information in the case record, the site has been successfully remediated and there are no threats to the public of the environment. Therefore, I am closing the spill case effective today."

Remarks: "upon digging out tanks it was discovered that soil was contaminated from gasoline and possibly diesel fuel-area has been cleaned up"

All Materials:

Site ID:	204041
Operable Unit ID:	1035342
Operable Unit:	01
Material ID:	350492
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ARMY NAT'L GUARD BUILDING
Address:	355 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9514901 / 1996-02-21
Facility ID:	9514901
Facility Type:	ER
DER Facility ID:	116651
Site ID:	135896
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1996-02-21
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1996-02-21
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-21
Spill Record Last Update:	1996-03-27

UNITED STATES ARMORY (Continued) **S103569544**

Spiller Name: WALTER ZAYATZ
Spiller Company: ARMY NAT'L GUARD BUILDING
Spiller Address: 355 MARCY AVENUE
Spiller Company: 001
Contact Name: WALTER ZAYATZ
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks: "one of the guards vehicles leaked fuel."

All Materials:
Site ID: 135896
Operable Unit ID: 1026005
Operable Unit: 01
Material ID: 355021
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 3.00
Units: G
Recovered: .00
Oxygenate: Not reported

AQ473 **SLATTERY STOVE SITE** **SEMS-ARCHIVE** **1000421759**
WSW **171 WALLBOUT ST** **RCRA NonGen / NLR** **NYD001288349**
1/4-1/2 **BROOKLYN, NY 11206** **PRP**
0.359 mi. **ICIS**
1898 ft. **Site 1 of 3 in cluster AQ** **FINDS**
ECHO
Relative: **NY MANIFEST**
Lower

Actual: SEMS Archive:
11 ft. Site ID: 0203594
EPA ID: NYD001288349
Cong District: 12
FIPS Code: 36047
FF: N
NPL: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

SEMS Archive Detail:
Region: 02
Site ID: 0203594
EPA ID: NYD001288349
Site Name: SLATTERY STOVE SITE
NPL: N
FF: N
OU: 00
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 1992-01-31 05:00:00
Finish Date: Not reported
Qual: V
Current Action Lead: EPA Perf

Region: 02
Site ID: 0203594

SLATTERY STOVE SITE (Continued) **1000421759**

EPA ID: NYD001288349
Site Name: SLATTERY STOVE SITE
NPL: N
FF: N
OU: 00
Action Code: RV
Action Name: RMVL
SEQ: 1
Start Date: 1991-12-02 05:00:00
Finish Date: 1992-06-02 04:00:00
Qual: C
Current Action Lead: EPA Perf

Region: 02
Site ID: 0203594
EPA ID: NYD001288349
Site Name: SLATTERY STOVE SITE
NPL: N
FF: N
OU: 00
Action Code: RS
Action Name: RV ASSESS
SEQ: 1
Start Date: 1991-11-01 05:00:00
Finish Date: 1991-11-27 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0203594
EPA ID: NYD001288349
Site Name: SLATTERY STOVE SITE
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 2000-05-05 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: SLATTERY J B & BROS INC
Facility address: 171-187 WALLABOUT ST
BROOKLYN, NY 11206-4906
EPA ID: NYD001288349
Mailing address: WALLABOUT ST
BROOKLYN, NY 11206
Contact: Not reported
Contact address: WALLABOUT ST
BROOKLYN, NY 11206
Contact country: US
Contact telephone: Not reported

SLATTERY STOVE SITE (Continued) **1000421759**

Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: J B SLATTERY & BRO INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: J B SLATTERY & BRO INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SLATTERY J B & BROS INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999

SLATTERY STOVE SITE (Continued) **1000421759**

Site name: SLATTERY J B & BROS INC
Classification: Not a generator, verified

Date form received by agency: 08/06/1980
Site name: SLATTERY J B & BROS INC
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR FROM STEEL FINISHING OPERATIONS OF PLANTS THAT PRODUCE IRON OR STEEL.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/30/1993
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/04/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

PRP:
EPAID: NYD001288349
PRP Name: DATSUN REALTY CORP.
Site ID: Not reported
Facility Name: SLATTERY STOVE SITE
Facility Address: 171 WALLBOUT ST
Facility City: BROOKLYN
Facility State: NY
Facility Zip: 11206
NPL Status: Not on the NPL
NPL Status Short Name: Removal Only Site (No Site Assessment Work Needed)

SLATTERY STOVE SITE (Continued) **1000421759**

PRP Address:	200 W. OLD WILSON BRIDGE
PRP City:	WORTHINGTON
PRP State:	OH
PRP Zip:	43085
Data Type:	SETTLEMENT DATE
Action Date:	1995-09-29 04:00:00
Settlement Code:	CA-1
Settlement:	CON AGMT

ICIS:

Enforcement Action ID:	02-1995-0388
FRS ID:	110004333374
Action Name:	DATSUN REALTY CORP, ET AL
Facility Name:	SLATTERY J B & BROS INC
Facility Address:	171-187 WALLABOUT ST BROOKLYN, NY 112064906
Enforcement Action Type:	CERCLA 122h Agrmt For Cost Recovery
Facility County:	KINGS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	122H
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.700169
Longitude in Decimal Degrees:	-73.953221
Permit Type Desc:	Not reported
Program System Acronym:	8410
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	SLATTERY J B & BROS INC
Address:	171-187 WALLABOUT ST
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	Not reported

Facility Name:	SLATTERY J B & BROS INC
Address:	171-187 WALLABOUT ST
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	Not reported

FINDS:

Registry ID: 110004333374

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SLATTERY STOVE SITE (Continued) **1000421759**

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000421759
Registry ID:	110004333374
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004333374

NY MANIFEST:

Name:	USEPA
Address:	171-187 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY 11206-4906
Country:	USA
EPA ID:	NYD001288349
Facility Status:	Not reported
Location Address 1:	171-191 WALLABOUT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001288349
Mailing Name:	USEPA
Mailing Contact:	PAUL L KAHN
Mailing Address 1:	2890 WOODBRIDGE AVE
Mailing Address 2:	Not reported
Mailing City:	EDISON
Mailing State:	NJ
Mailing Zip:	08837
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9083216617

NY MANIFEST:

Document ID:	NYB4844952
Manifest Status:	C

SLATTERY STOVE SITE (Continued) **1000421759**

seq:	Not reported
Year:	1992
Trans1 State ID:	T977GCNJ
Trans2 State ID:	Not reported
Generator Ship Date:	05/28/1992
Trans1 Recv Date:	05/28/1992
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/02/1992
Part A Recv Date:	06/25/1992
Part B Recv Date:	/ /
Generator EPA ID:	NYD001288349
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00700
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AR474 **BORINQUEN PLAZA** **NY LTANKS** **U002034216**
NE **120 HUMBOLDT STREET** **NY UST** **N/A**
1/4-1/2 **BROOKLYN, NY 11206**
0.363 mi.
1916 ft. **Site 1 of 2 in cluster AR**

Relative: LTANKS:
Higher

Name:	BORINQUEN PLAZA -NYCHA
Address:	120 HUMBOLT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9807939 / 2010-10-28
Facility ID:	9807939
Site ID:	201928
Spill Date:	1998-09-29

Actual:
19 ft.

BORINQUEN PLAZA (Continued) **U002034216**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1998-09-29
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-29
Spill Record Last Update:	2010-10-28
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	167972
DEC Memo:	"12/02/05: This spill transferred from J.Kolleeny to S.Kraszewski. 09/01/06: DEC Lead for this spill changed from unassigned to S. Kraszewski. - J. Kolleeny 02/08/07 : DEC lead changed from S. Kraszewski to J. Kann. J.Kann 02/13/09: J.Kann - Spoke with Ivy Olberding of PW Grosser to discuss Work Plan proposals for this site. Existing groundwater wells will be sampled for STARS VOCs and SVOCs. 4/28/09: J.Kann - Draft work plan received on 2/25. Comments sent on 3/26. Final Work Plan received on 4/24 and approved on 4/27. 10/06/09: J.Kann - Site visit to observe gw sampling. 1/27/10: J.Kann - ISR submitted on 1/20/10. Spill Closure request. Report needs to be reviewed. 10/28/10: J.Kann - Report reviewed. No SVOCs or VOCs detected in soil samples. No SVOCs in groundwater. One upgraident well contained benzene at 6.2 ppb. Tank closed in 2000. NFA."
Remarks:	"WILL ISOLATE AND RE-TEST"

All TTF:

Facility ID:	9807939
Spill Number:	9807939
Spill Tank Test:	1546317
Site ID:	201928
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

BORINQUEN PLAZA (Continued) **U002034216**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 201928
Operable Unit ID: 1069122
Operable Unit: 01
Material ID: 315477
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

UST:
Name: BORINQUEN PLAZA
Address: 120 HUMBOLDT STREET
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-601868 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589484.76971
UTM Y: 4506554.54949
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 23830
Affiliation Type: Facility Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: FUEL OIL REMEDIATION COORDINATOR
Contact Name: FUEL OIL REMEDIATION COORD.
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: EXROSSAN
Date Last Modified: 2005-09-30

Site Id: 23830
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: MR. LUIS PONCE
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY

BORINQUEN PLAZA (Continued) **U002034216**

State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23830
Affiliation Type:	Facility Operator
Company Name:	BORINQUEN PLAZA
Contact Type:	Not reported
Contact Name:	MR. LUIS PONCE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23830
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICE DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	2005-09-21

Tank Info:

Tank Number:	1
Tank ID:	48183
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	02/01/1975
Date Tank Closed:	03/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

BORINQUEN PLAZA (Continued) **U002034216**

Tightness Test Method: 03
Date Test: 01/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AQ475 **242 - 246 WALLABOUT STREET** **NY VCP** **S118943171**
WSW **242 - 246 WALLABOUT STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.368 mi.
1945 ft. **Site 2 of 3 in cluster AQ**

Relative:
Lower

Actual:
11 ft.

VCP NYC:
Project ID: 12CBCP030K
Project Name: 242 - 246 WALLABOUT STREET
Project Address: 242 - 246 WALLABOUT STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 12CBCP030K
File Name: 2011-12-15.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP030K/2011-12-15.12CBCP030K.242-246_Wallabout_Street.RIR.pdf

Project ID: 12CBCP030K
File Name: 2011-12-15.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP030K/2011-12-15.12CBCP030K.242-246_Wallabout_Street.RAWP_Draft.pdf

Project ID: 12CBCP030K
File Name: 2011-12-14.FactSheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP030K/2011-12-14.12CBCP030K.242-246_Wallabout_Street.FactSheet1.pdf

Project ID: 12CBCP030K
File Name: 2012-03-26.FactSheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/12CBCP030K/2012-03-26.12CBCP030K.FactSheet2.pdf

AP476 **CON EDISON** **NY LTANKS** **S102959968**
NE **155 SIEGEL ST** **NY MANIFEST** **N/A**
1/4-1/2 **BROOKLYN, NY 11201**
0.369 mi.
1946 ft. **Site 3 of 3 in cluster AP**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	BORINQUEN PLAZA
Address:	155 SIEGEL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9100258 / 1998-01-12
Facility ID:	9100258
Site ID:	327446
Spill Date:	1991-04-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	1991-04-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-17
Spill Record Last Update:	1998-01-12
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	263580
DEC Memo:	""
Remarks:	"5K UNDERGROUND TANK FAILED A HORNER EZY CHECK WITH A GROSS LEAK,WILL EXCAVATE,ISOLATE & RETEST."

All TTF:

Facility ID:	9100258
Spill Number:	9100258
Spill Tank Test:	1538426
Site ID:	327446
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

CON EDISON (Continued) **S102959968**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 327446
Operable Unit ID: 953801
Operable Unit: 01
Material ID: 426465
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

Name: BORINQUEN HOUSES -NYCHA
Address: 155 SIEGEL STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9711438 / 2010-07-12
Facility ID: 9711438
Site ID: 327447
Spill Date: 1998-01-12
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: jkkann
Referred To: Not reported
Reported to Dept: 1998-01-12
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-01-12
Spill Record Last Update: 2010-07-12
Spiller Name: FRANK OCELLO
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: 250 BROADWAY
Spiller County: 001
Spiller Contact: FRANK OCELLA
Spiller Phone: (212) 306-3233
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 263580
DEC Memo: "11/10/05: This spill transferred form J.Kolleeny to S.Kraszewski. Reviewed ISRP prepared by Gannett Fleming dated February 2003. 03/22/06: This spill transferred to K.Tang - SK 02/13/09: J.Kann - Spill transferred to J.Kann. Spoke with Ivy Olberding of PW Grosser

CON EDISON (Continued) **S102959968**

	to discuss a proposed work plan. Two borings should be advanced with soil samples collected around the groundwater interface. 4 existing monitoring wells will be sampled for analysis of STARS VOCs and SVOCs. 4/28/09: J.Kann - Draft work plan received on 2/25. Comments sent on 3/26. Final Work Plan received on 4/24 and approved on 4/27. 10/06/09: J.Kann - Site visit to observe gw sampling. 1/27/10: J.Kann - ISR submitted on 1/20/10. Spill Closure request. Report needs to be reviewed. 7/12/10: J.Kann - Based on review of the ISR, the spill was closed. Report shows on-site soil samples to have no SVOC or VOCs detected. On-site wells have not been impacted by the UST. One off-site upgradient well did have minor VOCs detected. NFA. "
Remarks:	"houing tested tank, tank failed."

All TTF:

Facility ID:	9711438
Spill Number:	9711438
Spill Tank Test:	1545552
Site ID:	327447
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	327447
Operable Unit ID:	1057928
Operable Unit:	01
Material ID:	326102
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	CON EDISON
Address:	155 SIEGEL ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004641676
Facility Status:	Not reported
Location Address 1:	155 SIEGEL ST
Code:	BP
Location Address 2:	SB44600

CON EDISON (Continued) **S102959968**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004641676
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2014
Trans1 Recv Date:	08/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004641676
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616841GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)

CON EDISON (Continued) **S102959968**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

477
NNE
1/4-1/2
0.371 mi.
1960 ft.

TOP HAT CLEANERS
152 GRAHAM AVE
BROOKLYN, NY 11206

RCRA-VSQG **1004758111**
NY SHWS **NYD986982908**
ICIS
US AIRS
NY MANIFEST

Relative:
Higher

Actual:
27 ft.

RCRA-VSQG:

Date form received by agency:	01/01/2007
Facility name:	TOP HAT CLEANERS
Facility address:	152 GRAHAM AVE BROOKLYN, NY 11206
EPA ID:	NYD986982908
Mailing address:	GRAHAM AVE BROOKLYN, NY 11206
Contact:	REINA DIAZ
Contact address:	GRAHAM AVE BROOKLYN, NY 11206
Contact country:	US
Contact telephone:	718-388-2611
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	REINA DIAZ
Owner/operator address:	37-49 95TH ST JACKSON HEIGHTS, NY 11372
Owner/operator country:	US

TOP HAT CLEANERS (Continued) **1004758111**

Owner/operator telephone: 718-458-5540
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: REINA DIAZ
Owner/operator address: 37-49 95TH ST
JACKSON HEIGHTS, NY 11372
Owner/operator country: US
Owner/operator telephone: 718-458-5540
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: TOP HAT CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/06/1997
Site name: TOP HAT CLEANERS
Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: CORROSIVE WASTE

TOP HAT CLEANERS (Continued) **1004758111**

Violation Status: No violations found

SHWS:
Name: TOP HAT CLEANERS
Address: 152 GRAHAM AVE.
City,State,Zip: BROOKLYN, NY 11206
Program: HW
Site Code: 504341
Classification: P
Region: 2
Acres: 0.057
HW Code: 224208
Record Add: 02/03/2015
Record Upd: 10/03/2017
Updated By: DKHARRIN
Site Description: Location: The Site is located at 152 Graham Avenue in the Borough of Brooklyn, Kings County, NY. The site is located in the East Williamsburg section of Brooklyn, New York. The property is bordered by Graham Avenue on the west, by a three-story mixed commercial/residential building to the north, by a four-story mixed commercial/residential building with a one-story annex and a three-story mixed commercial/residential building to the south, and by a four-story residential building to the east. The three-story building located to the southeast of the site also has a dry cleaner on the first floor. Site Features: The 2,500 square foot (0.057 acre) site parcel is occupied by a three-story building built in 1920. The site parcel also contains an open yard area behind (east of) the structure. The first floor is occupied by a dry cleaner and the upper two floors are occupied by residential apartments. Current Zoning and Land Use: The current site use is a dry cleaner (Top Hat Cleaners) on the first floor with residential apartments on the second and third floors. Past Use of the Site: According to the historical records, a dry cleaner has occupied the 152 Graham Ave location since approximately 1960. A Phase I study at the adjacent property (154 Graham Avenue) identified current and prior occupants of the ground floor retail space (pastry shop, shoe retailer and moving company, among others) which were not likely to be a source for chlorinated VOC impacts beneath the site. The report identifies the dry cleaner at 152 Graham Avenue (Top Hat Cleaners) as the most likely source of the contaminants identified in soil vapor. Site Geology and Hydrogeology: The site elevation is approximately 27 feet above mean sea level. Soil lithology consists of two main types of soils. The first soil type was "fill" material that consisted of fine to medium sand to silt with fine to coarse gravel and traces of brick and other miscellaneous debris. The second type was "natural material" composed of fine to coarse sand to silt with fine to coarse gravel and little clay. Groundwater was encountered between 17.5 feet and 22.5 feet below ground surface. Groundwater flow was determined to be in the north to northwest direction.
Env Problem: Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs). Based upon investigations conducted to date, the primary contaminant of concern is tetrachloroethene (PCE). Soil - Sampling of soil beneath and behind the site structure was limited due to inability to access the area with a drill rig. Sample results from other media indicate that a source area of higher contaminant concentrations may be present beneath the site structure. Two detections of PCE were observed in soil borings advanced during the Site Characterization. PCE was

TOP HAT CLEANERS (Continued) **1004758111**

detected at MW-02 (0.0036 ppm 17 19) and MW-04 (0.0017 ppm 5 6). Both detections are below the NYCRR Part 375 Soil Clean-up Objective of 1.3 ppm for PCE meeting both Unrestricted Use and Protection of Groundwater objectives. Groundwater - PCE was found in groundwater at two of the three boring locations advanced into the water table. Concentrations in contravention of the Class GA Groundwater standard of five (5) ppb were observed at 56 ppb and 10 ppb. Each of these exceedances were located in the public sidewalk immediately off the site parcel. Soil Vapor & Indoor Air A Vapor Intrusion Investigation was performed at the adjacent building to the north (154 Graham Avenue) as part of a real estate transaction. As part of that investigation two sub-slab vapor samples, one basement indoor air sample, and one ambient air sample were collected. At sub-slab location SG2, 43,399 ug/m3 of PCE was detected in soil vapor. (Note that the concentration reported is from a sample that was diluted 600 times. The concentration of PCE in the undiluted sample was 10,171 ug/m3, which exceeded the calibration range of the equipment.) Trichloroethylene (TCE) was detected at 1074 ug/m3 in the diluted sample and at 1504 ug/m3 in the undiluted sub-slab vapor sample. Cis-1,2-dichlorothylene (cis-1,2-DCE) was detected at 2180 ug/m3 in the diluted sample and at 1110 ug/m3 in the undiluted sub-slab vapor sample. Indoor air sampling results identified 44.1 ug/m3 of PCE and 0.43 ug/m3 of TCE in the basement air sample. Special Resources Impacted or Threatened: No special resources were identified on or surrounding the site.

Health Problem: People may contact contaminated soil or groundwater if they dig below the ground surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion on-site. Additional investigation of the potential for soil vapor intrusion to occur off-site is needed.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Applicant/Requestor
Sub Type: NNN
Owner Name: Reina Diaz
Owner Company: RP
Owner Address: 152 Graham Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America

TOP HAT CLEANERS (Continued) **1004758111**

Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Daniel Diaz
Owner Company:	Top Hat Cleaners
Owner Address:	152 Graham Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Belio Urena
Owner Address:	37-49 95th St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Jackson Heights, NY 11372
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	NNN
Owner Name:	Belio Urena
Owner Company:	RP
Owner Address:	152 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

ICIS:

Enforcement Action ID:	NY000A0000261040096200327
FRS ID:	110004480865
Action Name:	TOP HAT CLEANERS 36047R192400327
Facility Name:	TOP HAT CLEANERS
Facility Address:	152 GRAHAM AVE BROOKLYN, NY 112062602
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70676
Longitude in Decimal Degrees:	-73.94311
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400962
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261040096200314

TOP HAT CLEANERS (Continued) **1004758111**

FRS ID:	110004480865
Action Name:	TOP HAT CLEANERS 36047R192400314
Facility Name:	TOP HAT CLEANERS
Facility Address:	152 GRAHAM AVE BROOKLYN, NY 112062602
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70676
Longitude in Decimal Degrees:	-73.94311
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400962
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261040096200304
FRS ID:	110004480865
Action Name:	TOP HAT CLEANERS 36047R192400304
Facility Name:	TOP HAT CLEANERS
Facility Address:	152 GRAHAM AVE BROOKLYN, NY 112062602
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70676
Longitude in Decimal Degrees:	-73.94311
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400962
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1004758111
Region Code:	02
Programmatic ID:	AIR NY0000002610400962
Facility Registry ID:	110004480865
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610400962
Facility Registry ID:	110004480865

TOP HAT CLEANERS (Continued) **1004758111**

Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-17 00:00:00
Activity Status Date: 2002-09-17 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-05-09 00:00:00
Activity Status Date: 2005-05-09 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-08-07 00:00:00
Activity Status Date: 2013-08-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

US AIRS MINOR:
Envid: 1004758111
Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported

TOP HAT CLEANERS (Continued) **1004758111**

HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-17 00:00:00
Activity Status Date: 2002-09-17 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-05-09 00:00:00
Activity Status Date: 2005-05-09 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-08-07 00:00:00
Activity Status Date: 2013-08-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

NY MANIFEST:
Name: TOP HAT CLNRS
Address: 152 GRAHAM AVE
City,State,Zip: BROOKLYN, NY 11206
Country: USA

TOP HAT CLEANERS (Continued) **1004758111**

EPA ID:	NYD986982908
Facility Status:	Not reported
Location Address 1:	152 GRAHAM AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986982908
Mailing Name:	TOP HAT CLNRS
Mailing Contact:	LOU SANCHEZ
Mailing Address 1:	152 GRAHAM AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183382611

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NJD000564906
Trans2 State ID:	MIK814262374
Generator Ship Date:	01/19/2017
Trans1 Recv Date:	01/19/2017
Trans2 Recv Date:	01/27/2017
TSD Site Recv Date:	01/27/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986982908
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	016192468JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

TOP HAT CLEANERS (Continued) **1004758111**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY MANIFEST: record(s) in the EDR Site Report.

AR478 **CONSOLIDATED EDISON** **NY LTANKS** **S108058411**
NE **FRONT OF 130 HUMBOLDT ST ACROS** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11226** **NY MANIFEST**
0.372 mi.
1966 ft. **Site 2 of 2 in cluster AR**

Relative: **Higher**
Actual: **20 ft.**

LTANKS:

Name:	BORINQUEN PLAZA
Address:	130 HUMBOLDT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9905903 / 2004-01-08
Facility ID:	9905903
Site ID:	233389
Spill Date:	1999-08-17
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	1999-08-17
CID:	388
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-17
Spill Record Last Update:	2004-01-08
Spiller Name:	FRANK OCELO
Spiller Company:	NY CITY HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(212) 306-3229

CONSOLIDATED EDISON (Continued) **S108058411**

Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	70105
DEC Memo:	""
Remarks:	"caller reports tested tank and tank failed."

All TTF:

Facility ID:	9905903
Spill Number:	9905903
Spill Tank Test:	1547491
Site ID:	233389
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	233389
Operable Unit ID:	1080347
Operable Unit:	01
Material ID:	302186
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BORINQUEN PLAZA -NYCHA
Address:	130 HUMBOLDT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9402292 / 2004-01-08
Facility ID:	9402292
Site ID:	74795
Spill Date:	1994-05-16
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RXKEATIN
Referred To:	Not reported
Reported to Dept:	1994-05-16
CID:	Not reported
Water Affected:	Not reported

CONSOLIDATED EDISON (Continued) **S108058411**

Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-24
Spill Record Last Update:	2005-03-07
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	70105
DEC Memo:	""
Remarks:	"WILL EMPTY TANK AND INSPECT."

All TTF:

Facility ID:	9402292
Spill Number:	9402292
Spill Tank Test:	1542732
Site ID:	74795
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	74795
Operable Unit ID:	996090
Operable Unit:	01
Material ID:	386032
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	MANHOLE 71383
Address:	130 HUMBOLDT STREET

CONSOLIDATED EDISON (Continued) **S108058411**

City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0604078 / 2006-08-15
Facility ID:	0604078
Facility Type:	ER
DER Facility ID:	70105
Site ID:	366961
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-07-12
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-07-13
CID:	73
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-08-30
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERTS
DEC Memo:	"08/15/06 - See e-docs for Con Ed report detailing cleanup and closure. 201086. see eDocs."
Remarks:	"NO TO ALL 5 QUESTIONS. 1 PINT OIL. REF #201086."

All Materials:

Site ID:	366961
Operable Unit ID:	1124887
Operable Unit:	01
Material ID:	2114394
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	130 HUMBOLDT ST/BKLYN
Address:	130 HUMBOLDT STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8807903 / 1994-11-14
Facility ID:	8807903
Facility Type:	ER
DER Facility ID:	70105
Site ID:	74794

CONSOLIDATED EDISON (Continued) **S108058411**

DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1988-12-28
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1988-12-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Local Agency
Cleanup Ceased:	1994-11-14
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-01-10
Spill Record Last Update:	1994-11-15
Spiller Name:	Not reported
Spiller Company:	ALMAR FUEL OIL COMPANY
Spiller Address:	910 MCDONALD AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"DEC (SIGONA) RESPONDING, PRECINCT #90 CLOSED DOWN STREET, SANITATION PUT DOWN SAND, CONTRACTOR TO CLEAN UP."

All Materials:

Site ID:	74794
Operable Unit ID:	924408
Operable Unit:	01
Material ID:	452678
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	FRONT OF 130 HUMBOLDT ST ACROS
City,State,Zip:	BROOKLYN, NY 11226
Country:	USA
EPA ID:	NYP004143533
Facility Status:	Not reported
Location Address 1:	31-01 20TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY

CONSOLIDATED EDISON (Continued) **S108058411**

Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004143533
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYE1286676
Manifest Status: Not reported
seq: 01
Year: 2006
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/13/2006
Trans1 Recv Date: 07/13/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004143533
Trans1 EPA ID: 18887JU
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 00244
Units: K - Kilograms (2.2 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: L Landfill.

CONSOLIDATED EDISON (Continued) **S108058411**

Specific Gravity: 01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

479
South
1/4-1/2
0.384 mi.
2026 ft.

901 MYRTLE AVENUE **NY VCP** **S118943590**
901 MYRTLE AVENUE **N/A**
NEW YORK CITY, NY

Relative:
Higher

Actual:
35 ft.

VCP NYC:
Project ID: 16CVCP047K
Project Name: 901 MYRTLE AVENUE
Project Address: 901 MYRTLE AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 16CVCP047K
File Name: 2015-12-11.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP047K/2015-10-22.15EHAN579K.doc.RIR.EBC.pdf

Project ID: 16CVCP047K
File Name: 2015-12-11.RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP047K/2015-12-16.15EHAN579K.report.RAWP_edited.EBC.pdf

Project ID: 16CVCP047K
File Name: 2015-12-11.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP047K/2015-12-08.16CVCP047K.15EHAN579K.901-Myrtle_Avenue_Factsheet-1.OER_kd.pdf

Project ID: 16CVCP047K
File Name: 2015-12-11.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP047K/2015-12-09.16CVCP047K.15EHAN579K.901-Myrtle_Avenue_Fact Sheet 1- Translations.OER_kd.pdf

Project ID: 16CVCP047K
File Name: 2015-12-11.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/16CVCP047K/2015-12-09.16CVCP047K.15EHAN579K.901-Myrtle_Avenue_Community Protection Statement.OER_kd (2).pdf

AS480 **NOSTRAND AVE & FLUSHING A** **NY LTANKS** **S100782053**
WSW **NOSTRAND AVE & FLUSHING A** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.393 mi.
2073 ft. **Site 1 of 3 in cluster AS**

Relative:
Lower

Actual:
12 ft.

LTANKS:

Name:	NOSTRAND AVE & FLUSHING A
Address:	NOSTRAND AVE & FLUSHING A
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9309562 / 1993-11-08
Facility ID:	9309562
Site ID:	170265
Spill Date:	1993-11-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial Vehicle
Spill Class:	B2
Cleanup Ceased:	1993-11-08
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1993-11-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-11-09
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	LONDON FOG INDUSTRIES INC
Spiller Address:	ELDERSBURG, MD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143270
DEC Memo:	""
Remarks:	"INDUSTRIAL WASTE WAS NOTIFIED - JOHN RESPONDED. DEC SIGONA RESPONDED AND SPILL LEAKED FROM FUEL LINE AND WEST ONTO ST. IN FRONT OF MARCY HOUSES. TRYREE HIRED TO REMOVE WASTE MATERIAL."

All TTF:

Facility ID:	9309562
Spill Number:	9309562
Spill Tank Test:	1542183
Site ID:	170265
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

NOSTRAND AVE & FLUSHING A (Continued) **S100782053**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	170265
Operable Unit ID:	991116
Operable Unit:	01
Material ID:	392218
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

481
NNE
1/4-1/2
0.399 mi.
2108 ft.

MOST HOLY TRINITY RESIDENCE
157 GRAHAM AVE
BROOKLYN, NY 11211

NY LTANKS **U001839612**
NY UST **N/A**

Relative:
Higher

Actual:
29 ft.

LTANKS:

Name:	CARING COMMUNITIES
Address:	157 GRAHAM AVE
City,State,Zip:	BROOKLYN, NY 11211
Spill Number/Closed Date:	0306650 / 2006-08-25
Facility ID:	0306650
Site ID:	131344
Spill Date:	2003-09-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	2003-09-23
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-23
Spill Record Last Update:	2007-02-14
Spiller Name:	JUAN PEREZ
Spiller Company:	CARING COMMUNITIES
Spiller Address:	157 GRAHAM AVE
Spiller County:	001
Spiller Contact:	JUAN PEREZ

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

Spiller Phone:	(718) 963-3955
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	17030
DEC Memo:	"08/25/06 - Zielinski The drawing has been received and photos indicating filling lines and vent lines. They run in the basement above a concrete floor. Thew case is closed. 8/17/06 - Zielinski Steven Tsevdos called and said that they have only two 257-gallon tanks on the site. The drawing depicting the location of the closed tank and pipe lines would be sent to DEC. 8/17/06 - Zielinski Received soil samples' analyses taken 3 feet below tha tank bottom--no indication of soil contamination (eDOCs). Jim Donelan of Protest faxed a tank test report-- it had been a dry leak. Left a message for Steven Tsevdos, Caring Communities manager, asking for a layout of the failed tank and a number of tanks in service since the subject tank had been closed, and no records of registered tanks at the site. 7/17/06 - Zielinski Sent a letter requesting that within three weeks of receipt of this letter, Caring Communities would submit a report, required by the department's letter of September 24, 2003. This letter provides that the Caring Communities must submit soil sample analyses, an explanation of tank failure, and remowe contaminated soil. 7/13/06 - Zielinski Took photos of at the site. No indication of soil boring. Talked to Mr. Perez- superintendent. Left a note to Mr. Alonso requesting soil sampling results. 7/6/06 - Zielinski Spoke with Gustavo Alonso, the manager of Caring Communites. Asked him to sent all documents related to the spill. That same day, he faxed a DEC letter of 09/24/03 requesting a report and an affidavit; a proposal of work to be done, submitted by Petroleum Tank Cleaners, dated 11/21/03; an affidavit from Mercury Tank & Pump Inc., dated 4/9/04. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHAO 9/24/03 DDO Sawyer sent tank test failure letter to: Juan Perez 157 Graham Ave. Brooklyn, NY 11206 10/3/05: CBN Called Juan Perez and was told that the spill has been taken care of. Requested documentation/report for spill closure. Manager will get back to DEC on that."
Remarks:	"RECOMMEND TO EXCAVATE-ISOLATE- AND RE-TEST"

All TTF:

Facility ID:	0306650
Spill Number:	0306650
Spill Tank Test:	1528699
Site ID:	131344
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

Site ID:	131344
Operable Unit ID:	875397
Operable Unit:	01
Material ID:	503846
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	MOST HOLY TRINITY RESIDENCE
Address:	157 GRAHAM AVE
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-347760 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589301.56731
UTM Y:	4506768.76475
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	17054
Affiliation Type:	Facility Owner
Company Name:	CARING COMMUNITIES ASSOCIATES HDFC
Contact Type:	ASSOCIATE DIRECTOR
Contact Name:	GEORGE STATHOUDAKIS
Address1:	191 JORALEMON STREET, 8TH FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 722-6138
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-03-03

Site Id:	17054
Affiliation Type:	Mail Contact
Company Name:	CARING COMMUNITIES ASSOCIATES HDFC
Contact Type:	Not reported
Contact Name:	GEORGE STATHOUDAKIS
Address1:	191 JORALEMON STREET,
Address2:	8TH FLOOR
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 722-6138

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-03-03

Site Id:	17054
Affiliation Type:	Facility Operator
Company Name:	MOST HOLY TRINITY RESIDENCE
Contact Type:	Not reported
Contact Name:	JUAN PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-3957
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-03-03

Site Id:	17054
Affiliation Type:	Emergency Contact
Company Name:	CARING COMMUNITIES ASSOCIATES HDFC
Contact Type:	Not reported
Contact Name:	JUAN PEREZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 219-4989
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-03-03

Tank Info:

Tank Number:	001
Tank ID:	33195
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	03/25/2004
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	03
Date Test:	10/01/1998
Next Test Date:	Not reported

MOST HOLY TRINITY RESIDENCE (Continued) **U001839612**

Pipe Model: Not reported
Modified By: KXTANG
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

AS482 **535 FLUSHING AVENUE** **NY VCP** **S118943438**
WSW **535 FLUSHING AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.400 mi.
2110 ft. **Site 2 of 3 in cluster AS**

Relative:
Lower

Actual:
12 ft.

VCP NYC:
Project ID: 15CVCP048K
Project Name: 535 FLUSHING AVENUE
Project Address: 535 FLUSHING AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP048K
File Name: 2014-10-25.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2014-10-25.14EHAN422K.report.Revised_RIR_535_Flushing_Ave.pdf

Project ID: 15CVCP048K
File Name: 2015-04-14.Final_RAWP_and_Stip_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/Stip_RAWP.pdf

Project ID: 15CVCP048K
File Name: 2014-11-07.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2014-11-07.14EHAN422K.doc.535_Flushing_Ave.FactSheet-1.pdf

Project ID: 15CVCP048K
File Name: 2014-11-07.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2014-11-07.14EHAN422K.doc.535_Flushing_Ave.Translated_FactSheet-1.pdf

Project ID: 15CVCP048K
File Name: 2014-11-07.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2014-11-07.14EHAN422K.doc.535_Flushing_Avenue.Translated_CPS.pdf

Project ID: 15CVCP048K
File Name: 2015-05-07.Decision_Document

535 FLUSHING AVENUE (Continued) **S118943438**

URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2014-05-13.15CVCP048K.14EHAN422K.notice.535_Flushing_AvenueDecision_Doc_FINAL.OER.pdf

Project ID: 15CVCP048K
File Name: 2015-06-12.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2015-06-12.15CVCP048K.doc.535_Flushing_Avenue.Factsheet-2.pdf

Project ID: 15CVCP048K
File Name: 2015-06-12.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2015-06-12.15CVCP048K.doc.535_Flushing_Avenue.Translated_Factsheet-2.pdf

Project ID: 15CVCP048K
File Name: 2017-06-01.RAR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/RAR.pdf

Project ID: 15CVCP048K
File Name: 2017-12-08.Factsheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2017-12-06.15CVCP048K.535_Flushing_Ave.Fact_Sheet-3.pdf

Project ID: 15CVCP048K
File Name: 2017-12-08.Translated_Factsheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2017-11-30.15CVCP048K.535_Flushing_Ave.Fact Sheet 3 Translated.pdf

Project ID: 15CVCP048K
File Name: 2017-12-11.NOC
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP048K/2017-12-11.15CVCP048K.NoticeOfCompletion.pdf

---

AT483 **209 UNION AVENUE** **NY LTANKS** **S102672924**
NNW **209 UNION AVE - 90TH PCT** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.400 mi.
2114 ft. **Site 1 of 2 in cluster AT**

Relative: **Higher**
Actual: **19 ft.**

LTANKS:

Name:	209 UNION AVENUE
Address:	209 UNION AVE - 90TH PCT
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9502048 / 1995-05-18
Facility ID:	9502048
Site ID:	322916
Spill Date:	1995-05-18
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-05-18
SWIS:	2401
Investigator:	GUTIERREZ

209 UNION AVENUE (Continued) **S102672924**

Referred To:	Not reported
Reported to Dept:	1995-05-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-25
Spill Record Last Update:	1996-01-16
Spiller Name:	Not reported
Spiller Company:	NYCPD
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	260128
DEC Memo:	""
Remarks:	"1983- OVERFILL - TANKS CONTAINING WATER 1987- EMERGENCY GENERATING TANK FAILED TEST."

All Materials:

Site ID:	322916
Operable Unit ID:	1013114
Operable Unit:	01
Material ID:	367117
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AT484 **90 PRECINCT NYPD -DDC** **NY LTANKS** **S102238705**
NNW **209 UNION AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.400 mi.
2114 ft. **Site 2 of 2 in cluster AT**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	90 PRECINCT NYPD -DDC
Address:	209 UNION AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8606252 / 2005-01-10
Facility ID:	8606252
Site ID:	85755
Spill Date:	1987-01-07
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	Not reported

90 PRECINCT NYPD -DDC (Continued) **S102238705**

SWIS:	2401
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1987-01-07
CID:	Not reported
Water Affected:	GROUND WATER
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-02-10
Spill Record Last Update:	2005-07-07
Spiller Name:	Not reported
Spiller Company:	NYC POLICE DEPT.
Spiller Address:	90 TH PRECINCT
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	72843
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY / / : DEC SULLIVAN WILL INVESTIGATE. FIRE DEPT PUT DRY- SORB ON SPILL. This spill is referred to spill # 8607159 and is closed today by II (01/10/05). "
Remarks:	"P.D. DIESEL FEUL TANK ALLEGEDLY LEAKED INTO BASEMENT OF ADJACENT FIRE HOUSE - REASSIGNED TO DGS MONITORS FOR FORMAL INVESTIGATION"

All Materials:

Site ID:	85755
Operable Unit ID:	903055
Operable Unit:	01
Material ID:	475385
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	90 PRECINCT NYPD -DDC
Address:	209 UNION AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0208387 / 2005-04-04
Facility ID:	0208387
Facility Type:	ER
DER Facility ID:	72843
Site ID:	78258
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3

90 PRECINCT NYPD -DDC (Continued) **S102238705**

SWIS:	2401
Spill Date:	2002-11-13
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2002-11-13
CID:	211
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-13
Spill Record Last Update:	2005-04-04
Spiller Name:	WILLIAM KLEIN
Spiller Company:	90TH PRECINCT NYPD
Spiller Address:	211 UNION AV
Spiller Company:	001
Contact Name:	WILLIAM KLEIN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY CALLED WILLIAM KLEIN, (1.32 PM) AT LEAST 4 TIMES. NO RESPONSE FROM ANSWERING MACHINE. DISCUSSED SPILL WITH STEVE, WHO SUGGESTS THAT I TALKED TO JON KOLLEENY. I DISCUSSED WITH JON, WHO WAS WILLING TO TAKE OVER THE INVESTIGATION & MONITOR ANY FURTHER DEVELOPEMENT. - E.R. Franklin Co. excavated some contaminated soil but had to return some soil to the pit to stabilize edge of pit under sidewalk adjacent to precinct. Franklin took end point samples and did some follow-up Geoprobe borings. Found only minor impacts to vadose zone soil, and gasoline-related impacts at water table. Site is being remediated by URS under DDC Consent Order. OK to close this spill; see open spill for this site, no. 9512590. - J. Kolleeny 4/4/05."
Remarks:	"during removal 15000 gal ust sheen on groundwater discovered "

All Materials:

Site ID:	78258
Operable Unit ID:	861374
Operable Unit:	01
Material ID:	515391
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	90 PRECINCT NYPD -DDC
Address:	209 UNION AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9512590 / 2013-09-24
Facility ID:	9512590
Facility Type:	ER

90 PRECINCT NYPD -DDC (Continued) **S102238705**

DER Facility ID:	72843
Site ID:	73529
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1996-01-10
Investigator:	ADZHITOM
Referred To:	NFA
Reported to Dept:	1996-01-10
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-01-10
Spill Record Last Update:	2013-09-24
Spiller Name:	BOB KREUZER
Spiller Company:	NEW YORK CITY PD 90 PRCNT
Spiller Address:	211 UNION AVENUE
Spiller Company:	001
Contact Name:	BOB KREUZER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY URS investigated site, operated dual-phase extraction system to address free product, soil and groundwater contamination. System operation was terminated in 2002 due to diminishing results. To address remaining groundwater contamination they applied ORC. Groundwater monitoring still ongoing. - JK 4/4/05 Spill transferred from Kolleeny to A. Zhitomirsky on 4/4/05. - JK 10/31/2005 Reviewed report dated September 2005. MTBE is at 230 ppb. AZ 8-14-2006 Reviewed monitoring report by Roux dated July 28, 2005 for March through June 2006.MW-3 - 150 PPB mtbe in groundwater.Recommendations: maintainn DPE and Oxygen delivery remediation systems shut down; continue gw monitoring, discontinue SVOCs analyses, evaluate alternative technologies. AZ 04-5-2007 Reviewed Monitoring Reports submitted in November 2006 for July through September 2006 and on March 23, 2007, for October through December 2006. Residual MTBE contamination was detected in four wells with concentrations up to 60 ppb(July 2006). Benzine and naphthalene were encountered in one well. DPE was inactive. ORC injections and ORC socks were discontinued. In October 2006 sampling event MTBE ranged from 16 ppb to 136 ppb. Some increase of MTBE concentrations was observed. ORC socks will be installed in MW 216-MW-01, 216-MW-03 and MW-09. Recommended maintaining shutdown status of DPE system, reducing monitoring and reporting to semi-annual. These recommendations were approved. An e-mail was sent to Brian Morrissey (ROUX): I have reviewed Monitoring Report for October- December 2006 dated March 15, 2007. The report recommended reducing monitoring and reporting frequency to semi-annual. ORC socks should be placed in wells where VOC concentrations exceed NYSDEC Guidance Values. AZ 10-22-2007 Reviewed Monitoring Reports submitted in August 2007 for January through June 2007. Residual MTBE contamination was detected in five wells wells

90 PRECINCT NYPD -DDC (Continued) **S102238705**

with concentrations up to 85 ppb. ORC socks were reinstalled in three monitoring wells at the NYSDEC request. Roux recommended continuing semi-annual groundwater monitoring program. AZ 7-2-2008 Reviewed Monitoring Reports submitted in April 2008 for July through December 2008. Residual MTBE contamination was detected in four wells of the six wells with concentrations up to 56 ppb. ORC socks were reinstalled in three monitoring wells at the NYSDEC request. MTBE is the only VOC detected at a concentration greater than its NYSDEC AWQSGV in multiple wells. Roux recommended continuing semi-annual groundwater monitoring program. AZ 2-13-2009 Reviewed Monitoring Reports submitted in October 2009 for January through September 2008. Residual MTBE contamination was detected in four wells of the six wells with concentrations up to 66 ppb. ORC socks were reinstalled in three monitoring wells at the NYSDEC request. MTBE is the only VOC detected at a concentration greater than its NYSDEC AWQSGV in multiple wells. Roux will conduct a site wide groundwater sampling round in preparation for NFA. AZ 11-6-09 An e-mail was sent to Brian Morrisey/Fatemeh Ashkan/ V. Brevdo: I have reviewed a semi-annual report for the above site dated May 22, 2009 add covering the period of June 2008 through March 2009. Roux proposed conducting soil sampling and analyses in areas of residual groundwater contamination (i.e.e 216-MW-02 and MW-08) in order to determine current status of soil impacts. Also, you proposed considering enhanced bioremediation for this site. These proposals are approved and should the work plan should be included in the next monitoring report. AZ 3-29-2011 Reviewed 4,000 gal gasoline tank closure report.3 bottom samples were collected at depth 13 to 16 bgs. Sidewalls samples could not be collected due to the steel sheeting that was previously installed during the original tank installation. Groundwater sample was collected from approximately 13 ft bgs. No visual evidence of contamination was detected. PID readings 0.6 - 2.1 ppm. The tank was in good condition. 456.4 tons of soil was transported for offsite disposal. No VOCs or SVOCs were detected in the soil samples. Groundwater sample contained VOCs detected above NYSDEC TOGs total VOCS 438 ppb. AZ 4-27-2011 An e-mail was sent to LiRo/DDC/V. Brevdo: I have reviewed the Site Turnover Status Report and Semi-Annual Monitoring Report dated January 24, 2011. I concur with the LiRo's recommendations to install two wells near a former 4,000 gal gasoline UST. Since the groundwater contamination was discovered when this UST was removed, two additional wells are required near this tank (a total of four wells). Well MW-01 could be removed from the monitoring schedule, as per LiRo's recommendation. Additional soil borings are approved. There is a number of USTs, including gasoline tanks, closed in place at this site. I recommend that these tanks be removed, if feasible. AZ 11-27-2011 Reviewed report dated Aug. 29, 2011. The report stated that the latest groundwater results show VOCs were detected above AWQSGVs in four wells. LiRo will ORC socks and continue semi-annual monitoring. AZ 6-11-2012 Additional soil borings SB-01 through SB-04 will be installed. New monitoring wells LMW-01 through LMW-04 will installed in the second quarter of 2012. AZ 4-15-2013 ORC socks are installed in MW-02 and MW-08. AZ 9-24-2013 The following e-mail was sent to S. Frank/V. Brevdo/F. Ashkan: Dear Steve, I have reviewed Request for Spill Closure dated May 23, 2013. This spill is associated with the four closed in-place USTs located on the 90th Precinct property. No remediation of soils required based on recent (May 2012) and historical soil analytical data. ORC slurry application was performed in March 2004. Stable dissolved phase

90 PRECINCT NYPD -DDC (Continued) **S102238705**

groundwater plume with Total Volatile Organic Contaminant concentrations less than 100 ppb was recorded during last two sampling events. The subway and tunnel prevent offsite migration. LiRo requested that DEC close spill number 9512590. Based on the documentation provided to date, the New York State Department of Environmental Conservation (the Department) has closed the spill case number 9512590. All wells associated with this project should be closed according to the Department's Groundwater Monitoring Well Decommissioning Procedures. All wells should gaged for the presence of free product before closure. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department's spill case closure, which indicates that corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts must be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations. Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use as the Department's files may not be maintained indefinitely. Sincerely, Alex Zhitomirsky"

Remarks: "LABORATORY RESULTS SHOW SOIL CONTAMINATION"

All Materials:

Site ID:	73529
Operable Unit ID:	1026919
Operable Unit:	01
Material ID:	2096794
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	73529
Operable Unit ID:	1026919
Operable Unit:	01
Material ID:	356338
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

485
ESE
1/4-1/2
0.401 mi.
2119 ft.

GONZALEZ RESIDENCE
29 BEAVER ST
BROOKLYN, NY

NY LTANKS **S107658820**
N/A

Relative:
Higher

Actual:
47 ft.

LTANKS:

Name:	GONZALEZ RESIDENCE
Address:	29 BEAVER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0514546 / 2006-03-21
Facility ID:	0514546
Site ID:	361288
Spill Date:	2006-03-20
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-03-20
CID:	409
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-03-20
Spill Record Last Update:	2006-03-21
Spiller Name:	THOMAS BUTLER
Spiller Company:	VIJAX OIL CO,
Spiller Address:	222 VARICK ST
Spiller County:	001
Spiller Contact:	MIGUEL GONZALEZ
Spiller Phone:	(718) 788-3031
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	311478
DEC Memo:	"Vijax says it was a minor spill and it was cleaned up. Homeowner did not answer and had no message machine Spill Closed"
Remarks:	"HAS BEEN CLEANED UP."

All Materials:

Site ID:	361288
Operable Unit ID:	1119452
Operable Unit:	01
Material ID:	2108876
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

486
SSE
1/4-1/2
0.402 mi.
2123 ft.

948 MYRTLE AVENUE
948 MYRTLE AVENUE
NEW YORK CITY, NY

NY VCP **S118943520**
N/A

Relative:
Higher

Actual:
45 ft.

VCP NYC:
Project ID: 15CVCP132K
Project Name: 948 MYRTLE AVENUE
Project Address: 948 MYRTLE AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP132K
File Name: 2015-04-24.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP132K/2015-04-24.15EHAN375K.Report.RIR_v2.EBC.pdf

Project ID: 15CVCP132K
File Name: 2015-05-20.RAWP_draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP132K/2015-05-20.15EHAN375K.Report.RAWP_v2.EBC.pdf

Project ID: 15CVCP132K
File Name: 2015-05-21.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP132K/2015-05-21.15CVCP132K.948_Myrtle_Avenue.Factsheet-1.OER.pdf

Project ID: 15CVCP132K
File Name: 2015-05-21.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP132K/2015-05-21.15CVCP132K.948_Myrtle_Avenue.translated_Factsheet-1.OER.pdf

Project ID: 15CVCP132K
File Name: 2015-05-21.Translated_CPSf
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP132K/2015-05-21.15CVCP132K.948_Myrtle_Avenue.translated_CPS.OER.pdf

Project ID: 15CVCP132K
File Name: 2015-06-21.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP132K/2015-06-21.15CVCP132K.948_Myrtle_Avenue.Factsheet-2.OER.pdf

---

AU487
NE
1/4-1/2
0.402 mi.
2123 ft.

BORINQUEN HOUSES
330 BUSHWICK AVENUE
BROOKLYN, NY 11206

NY LTANKS **U002034218**
NY UST **N/A**
NY Spills

Site 1 of 2 in cluster AU

Relative:
Higher

Actual:
18 ft.

LTANKS:
Name: BORINQUEN -NYCHA
Address: 330 BUSHWICK AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9601914 / 2005-12-09
Facility ID: 9601914
Site ID: 63348
Spill Date: 1996-05-08

BORINQUEN HOUSES (Continued) **U002034218**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1996-05-08
CID:	233
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-08
Spill Record Last Update:	2005-12-09
Spiller Name:	FRANK OCELO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	61219
DEC Memo:	"12/09/05: This spill transferred from J.Kolleeny to S.Kraszewski. This spill closed to consolidate with opne spill #9613967."
Remarks:	"TANK FAILED TANK RETEST PLANNED "

All TTF:

Facility ID:	9601914
Spill Number:	9601914
Spill Tank Test:	1544531
Site ID:	63348
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	63348
Operable Unit ID:	1029518
Operable Unit:	01
Material ID:	351709
Material Code:	0001A
Material Name:	#2 fuel oil

BORINQUEN HOUSES (Continued) **U002034218**

Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

UST:
Name: BORINQUEN HOUSES
Address: 330 BUSHWICK AVENUE
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-601870 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589579.77766
UTM Y: 4506565.64952
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 23832
Affiliation Type: Facility Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: FUEL OIL REMEDIATION COORDINATOR
Contact Name: FUEL OIL REMEDIATION COORD.
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: EXROSSAN
Date Last Modified: 2005-09-30

Site Id: 23832
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: MR. LUIS PONCE
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23832

BORINQUEN HOUSES (Continued) **U002034218**

Affiliation Type:	Facility Operator
Company Name:	BORINQUEN HOUSES
Contact Type:	Not reported
Contact Name:	MR. LUIS PONCE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23832
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICE DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	2005-09-21

Tank Info:

Tank Number:	1
Tank ID:	48185
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	02/01/1975
Date Tank Closed:	07/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

Tightness Test Method:	21
Date Test:	10/17/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None

BORINQUEN HOUSES (Continued) **U002034218**

D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

SPILLS:

Name:	BORINQUEN PLAZA -NYCHA
Address:	330 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9613967 / 2010-10-28
Facility ID:	9613967
Facility Type:	ER
DER Facility ID:	61219
Site ID:	142069
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1995-03-14
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1997-02-28
CID:	205
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-28
Spill Record Last Update:	2010-10-28
Spiller Name:	SAME
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY 16TH FLOOR
Spiller Company:	001
Contact Name:	FRANK OCELLO
DEC Memo:	"12/09/05: This spill transferred from J.Kolleeny to S.Kraszewski. 02/08/07 : DEC lead changed from S. Kraszewski to J. Kann. J.Kann 02/13/09: J.Kann - Discussed the site with Ivy Olberding of PW Grosser. A work plan will be prepared which will include the sampling of 9 existing monitoring wells and analysis for STARS VOCs and SVOCs. 4/28/09: J.Kann - Draft work plan received on 2/25. Comments sent on 3/26. Final Work Plan received on 4/24 and approved on 4/27. 10/06/09: J.Kann - Site visit to observe gw sampling. 1/27/10: J.Kann - ISR submitted on 1/20/10. Spill Closure request. Report needs to be reviewed. 10/28/10: J.Kann - No VOCs or SVOCs were detected in soils. One grounwater well (out of nine) contained minor VOC exceedeances (n, Butylbenzene - 11.9 ppb). A quantitative exposure assessment was performed as per DER-10. According to the report, a complete exposure pathway does not exist. NFA."

BORINQUEN HOUSES (Continued) **U002034218**

Remarks: "TRC ENVIRONMENTAL INSTALLING WELLS FOR NYCHA FOUND FREE PRODUCT. ***FAXED FROM REGION"

All Materials:

Site ID:	142069
Operable Unit ID:	1045376
Operable Unit:	01
Material ID:	339072
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

488
South
1/4-1/2
0.403 mi.
2126 ft.

922 MYRTLE AVENUE
922 MYRTLE AVENUE
NEW YORK CITY, NY

NY VCP **S121133153**
N/A

Relative:
Higher

Actual:
41 ft.

VCP NYC:

Project ID:	17CVPC049K
Project Name:	922 MYRTLE AVENUE
Project Address:	922 MYRTLE AVENUE
Borough:	BROOKLYN

VCP NYC:

Project ID:	17CVPC049K
File Name:	2016-12-08.RIR
URL:	Not reported

Project ID:	17CVPC049K
File Name:	2017-01-31.RAWP_draft
URL:	Not reported

Project ID:	17CVPC049K
File Name:	2017-02-28.Factsheet-1
URL:	Not reported

Project ID:	17CVPC049K
File Name:	2017-02-28.Translated_Factsheet-1
URL:	Not reported

Project ID:	17CVPC049K
File Name:	2017-02-28.Translated_CPS
URL:	Not reported

489
SSW
1/4-1/2
0.406 mi.
2143 ft.

FORMER CASCADE LAUNDRY
553 MARCY AVENUE
BROOKLYN, NY 11206

NY ENG CONTROLS **S118628301**
NY INST CONTROL **N/A**
NY BROWNFIELDS

Relative:
Higher

Actual:
28 ft.

ENG CONTROLS:

Name:	FORMER CASCADE LAUNDRY
Address:	553 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Site Code:	495614
HW Code:	C224194
Control Code:	13
Control Type:	ENG
Date Record Added:	12/06/2018
Date Rec Updated:	12/31/2018
Updated By:	JGJONES
Site Description:	Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem:	Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering,

FORMER CASCADE LAUNDRY (Continued) **S118628301**

excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Dell:	Not reported
Record Add:	2014-06-03 07:17:00
Record Upd:	2018-12-14 14:18:00
Updated By:	JGJONES
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Marcy Library
Owner Address:	617 DeKalb Avenue at Nostrand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Michael Kohn
Owner Company:	553 Marcy Avenue Owner LLC
Owner Address:	266 Broadway, Suite 501
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street, Unit 1A
Owner Addr2:	Brooklyn
Owner City,St,Zip:	NY, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Tremaine Wright
Owner Company:	Brooklyn Community Board 3
Owner Address:	1360 Fulton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street
Owner Addr2:	Unit 1A
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224194
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1100223
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2014-06-19 11:32:00
Record Updated:	2014-06-19 11:32:00
Updated By:	BRWOLOSE
Crossref ID:	1601325
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-05-10 15:00:00
Record Updated:	2016-05-10 15:00:00
Updated By:	SXMAHAT
Crossref ID:	C224194-12-14
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-12-06 11:47:00
Record Updated:	2018-12-11 09:31:00
Updated By:	RKCORCOR
Crossref ID:	2017000442656
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-12-06 11:46:00

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

Name: FORMER CASCADE LAUNDRY
Address: 553 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 495614
HW Code: C224194
Control Code: 36
Control Type: ENG
Date Record Added: 12/06/2018
Date Rec Updated: 12/31/2018
Updated By: JGJONES
Site Description: Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the

FORMER CASCADE LAUNDRY (Continued) **S118628301**

depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-06-03 07:17:00

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Record Upd:	2018-12-14 14:18:00
Updated By:	JGJONES
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Marcy Library
Owner Address:	617 DeKalb Avenue at Nostrand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Michael Kohn
Owner Company:	553 Marcy Avenue Owner LLC
Owner Address:	266 Broadway, Suite 501
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street, Unit 1A
Owner Addr2:	Brooklyn
Owner City,St,Zip:	NY, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Tremaine Wright
Owner Company:	Brooklyn Community Board 3
Owner Address:	1360 Fulton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street
Owner Addr2:	Unit 1A
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224194
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	toluene
Waste Quantity:	UNKNOWN

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Code:	Not reported
HW Code:	C224194
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1100223
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2014-06-19 11:32:00
Record Updated:	2014-06-19 11:32:00
Updated By:	BRWOLOSE
Crossref ID:	1601325
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-05-10 15:00:00
Record Updated:	2016-05-10 15:00:00
Updated By:	SXMAHAT
Crossref ID:	C224194-12-14
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-12-06 11:47:00
Record Updated:	2018-12-11 09:31:00
Updated By:	RKCORCOR
Crossref ID:	2017000442656
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-12-06 11:46:00
Record Updated:	2018-12-06 14:00:00
Updated By:	RKCORCOR

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Name:	FORMER CASCADE LAUNDRY
Address:	553 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Site Code:	495614
HW Code:	C224194
Control Code:	15
Control Type:	ENG
Date Record Added:	12/06/2018
Date Rec Updated:	12/31/2018
Updated By:	JGJONES
Site Description:	Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem:	Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the

FORMER CASCADE LAUNDRY (Continued) **S118628301**

soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-06-03 07:17:00
Record Upd:	2018-12-14 14:18:00
Updated By:	JGJONES
Own Op:	Document Repository

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Marcy Library
Owner Address:	617 DeKalb Avenue at Nostrand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Michael Kohn
Owner Company:	553 Marcy Avenue Owner LLC
Owner Address:	266 Broadway, Suite 501
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street, Unit 1A
Owner Addr2:	Brooklyn
Owner City,St,Zip:	NY, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Tremaine Wright
Owner Company:	Brooklyn Community Board 3
Owner Address:	1360 Fulton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street
Owner Addr2:	Unit 1A
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224194
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	1,3,5-trimethylbenzene

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1100223
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-06-19 11:32:00
Record Updated: 2014-06-19 11:32:00
Updated By: BRWOLOSE
Crossref ID: 1601325
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2016-05-10 15:00:00
Record Updated: 2016-05-10 15:00:00
Updated By: SXMAHAT
Crossref ID: C224194-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-12-06 11:47:00
Record Updated: 2018-12-11 09:31:00
Updated By: RKCORCOR
Crossref ID: 2017000442656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-12-06 11:46:00
Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

INST CONTROL:
Name: FORMER CASCADE LAUNDRY

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Address: 553 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 495614
Control Name: Landuse Restriction
HW Code: C224194
Control Code: 25
Control Type: INST
Dt record added: 12/06/2018
Dt rec updated: 12/31/2018
Updated By: JGJONES
Site Code: 495614
Site Description: Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene

FORMER CASCADE LAUNDRY (Continued) **S118628301**

at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-06-03 07:17:00
Record Upd: 2018-12-14 14:18:00
Updated By: JGJONES

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Marcy Library
Owner Address: 617 DeKalb Avenue at Nostrand Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Michael Kohn
Owner Company: 553 Marcy Avenue Owner LLC
Owner Address: 266 Broadway, Suite 501
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street, Unit 1A
Owner Addr2: Brooklyn
Owner City,St,Zip: NY, NY 11206
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Tremaine Wright
Owner Company: Brooklyn Community Board 3
Owner Address: 1360 Fulton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street
Owner Addr2: Unit 1A
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224194
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1100223
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-06-19 11:32:00
Record Updated: 2014-06-19 11:32:00
Updated By: BRWOLOSE
Crossref ID: 1601325
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2016-05-10 15:00:00
Record Updated: 2016-05-10 15:00:00
Updated By: SXMAHAT
Crossref ID: C224194-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-12-06 11:47:00
Record Updated: 2018-12-11 09:31:00
Updated By: RKCORCOR
Crossref ID: 2017000442656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-12-06 11:46:00
Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

Name: FORMER CASCADE LAUNDRY

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Address: 553 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 495614
Control Name: Monitoring Plan
HW Code: C224194
Control Code: 31
Control Type: INST
Dt record added: 12/06/2018
Dt rec updated: 12/31/2018
Updated By: JGJONES
Site Code: 495614
Site Description: Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene

FORMER CASCADE LAUNDRY (Continued) **S118628301**

at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-06-03 07:17:00
Record Upd: 2018-12-14 14:18:00
Updated By: JGJONES

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Marcy Library
Owner Address: 617 DeKalb Avenue at Nostrand Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Michael Kohn
Owner Company: 553 Marcy Avenue Owner LLC
Owner Address: 266 Broadway, Suite 501
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street, Unit 1A
Owner Addr2: Brooklyn
Owner City,St,Zip: NY, NY 11206
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Tremaine Wright
Owner Company: Brooklyn Community Board 3
Owner Address: 1360 Fulton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street
Owner Addr2: Unit 1A
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224194
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1100223
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-06-19 11:32:00
Record Updated: 2014-06-19 11:32:00
Updated By: BRWOLOSE
Crossref ID: 1601325
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2016-05-10 15:00:00
Record Updated: 2016-05-10 15:00:00
Updated By: SXMAHAT
Crossref ID: C224194-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-12-06 11:47:00
Record Updated: 2018-12-11 09:31:00
Updated By: RKCORCOR
Crossref ID: 2017000442656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-12-06 11:46:00
Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

Name: FORMER CASCADE LAUNDRY

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Address: 553 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 495614
Control Name: Ground Water Use Restriction
HW Code: C224194
Control Code: 08
Control Type: INST
Dt record added: 12/06/2018
Dt rec updated: 12/31/2018
Updated By: JGJONES
Site Code: 495614
Site Description: Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene

FORMER CASCADE LAUNDRY (Continued) **S118628301**

at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-06-03 07:17:00
Record Upd: 2018-12-14 14:18:00
Updated By: JGJONES

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Marcy Library
Owner Address: 617 DeKalb Avenue at Nostrand Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Michael Kohn
Owner Company: 553 Marcy Avenue Owner LLC
Owner Address: 266 Broadway, Suite 501
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street, Unit 1A
Owner Addr2: Brooklyn
Owner City,St,Zip: NY, NY 11206
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Tremaine Wright
Owner Company: Brooklyn Community Board 3
Owner Address: 1360 Fulton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street
Owner Addr2: Unit 1A
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224194
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1100223
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-06-19 11:32:00
Record Updated: 2014-06-19 11:32:00
Updated By: BRWOLOSE
Crossref ID: 1601325
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2016-05-10 15:00:00
Record Updated: 2016-05-10 15:00:00
Updated By: SXMAHAT
Crossref ID: C224194-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-12-06 11:47:00
Record Updated: 2018-12-11 09:31:00
Updated By: RKCORCOR
Crossref ID: 2017000442656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-12-06 11:46:00
Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

Name: FORMER CASCADE LAUNDRY

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Address: 553 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 495614
Control Name: Environmental Easement
HW Code: C224194
Control Code: J
Control Type: INST
Dt record added: 12/06/2018
Dt rec updated: 12/31/2018
Updated By: JGJONES
Site Code: 495614
Site Description: Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene

FORMER CASCADE LAUNDRY (Continued) **S118628301**

at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-06-03 07:17:00
Record Upd: 2018-12-14 14:18:00
Updated By: JGJONES

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Marcy Library
Owner Address: 617 DeKalb Avenue at Nostrand Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Michael Kohn
Owner Company: 553 Marcy Avenue Owner LLC
Owner Address: 266 Broadway, Suite 501
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street, Unit 1A
Owner Addr2: Brooklyn
Owner City,St,Zip: NY, NY 11206
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Tremaine Wright
Owner Company: Brooklyn Community Board 3
Owner Address: 1360 Fulton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street
Owner Addr2: Unit 1A
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224194
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1100223
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-06-19 11:32:00
Record Updated: 2014-06-19 11:32:00
Updated By: BRWOLOSE
Crossref ID: 1601325
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2016-05-10 15:00:00
Record Updated: 2016-05-10 15:00:00
Updated By: SXMAHAT
Crossref ID: C224194-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-12-06 11:47:00
Record Updated: 2018-12-11 09:31:00
Updated By: RKCORCOR
Crossref ID: 2017000442656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-12-06 11:46:00
Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

Name: FORMER CASCADE LAUNDRY

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Address: 553 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 495614
Control Name: Building Use Restriction
HW Code: C224194
Control Code: 26
Control Type: INST
Dt record added: 12/06/2018
Dt rec updated: 12/31/2018
Updated By: JGJONES
Site Code: 495614
Site Description: Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene

FORMER CASCADE LAUNDRY (Continued) **S118628301**

at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-06-03 07:17:00
Record Upd: 2018-12-14 14:18:00
Updated By: JGJONES

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Marcy Library
Owner Address: 617 DeKalb Avenue at Nostrand Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Michael Kohn
Owner Company: 553 Marcy Avenue Owner LLC
Owner Address: 266 Broadway, Suite 501
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street, Unit 1A
Owner Addr2: Brooklyn
Owner City,St,Zip: NY, NY 11206
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Tremaine Wright
Owner Company: Brooklyn Community Board 3
Owner Address: 1360 Fulton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street
Owner Addr2: Unit 1A
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224194
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1100223
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-06-19 11:32:00
Record Updated: 2014-06-19 11:32:00
Updated By: BRWOLOSE
Crossref ID: 1601325
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2016-05-10 15:00:00
Record Updated: 2016-05-10 15:00:00
Updated By: SXMAHAT
Crossref ID: C224194-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-12-06 11:47:00
Record Updated: 2018-12-11 09:31:00
Updated By: RKCORCOR
Crossref ID: 2017000442656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-12-06 11:46:00
Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

Name: FORMER CASCADE LAUNDRY

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Address: 553 MARCY AVENUE
City,State,Zip: BROOKLYN, NY 11206
Site Code: 495614
Control Name: Site Management Plan
HW Code: C224194
Control Code: 32
Control Type: INST
Dt record added: 12/06/2018
Dt rec updated: 12/31/2018
Updated By: JGJONES
Site Code: 495614
Site Description: Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene

FORMER CASCADE LAUNDRY (Continued) **S118628301**

at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-06-03 07:17:00
Record Upd: 2018-12-14 14:18:00
Updated By: JGJONES

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Marcy Library
Owner Address: 617 DeKalb Avenue at Nostrand Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Michael Kohn
Owner Company: 553 Marcy Avenue Owner LLC
Owner Address: 266 Broadway, Suite 501
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
Own Op: Owner
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street, Unit 1A
Owner Addr2: Brooklyn
Owner City,St,Zip: NY, NY 11206
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Tremaine Wright
Owner Company: Brooklyn Community Board 3
Owner Address: 1360 Fulton Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11216
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: P03
Owner Name: Isac Deutsch
Owner Company: Cascade 553 LLC
Owner Address: 246 Lynch Street
Owner Addr2: Unit 1A
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
HW Code: C224194
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: methylene chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224194
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1100223
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2014-06-19 11:32:00
Record Updated: 2014-06-19 11:32:00
Updated By: BRWOLOSE
Crossref ID: 1601325
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2016-05-10 15:00:00
Record Updated: 2016-05-10 15:00:00
Updated By: SXMAHAT
Crossref ID: C224194-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-12-06 11:47:00
Record Updated: 2018-12-11 09:31:00
Updated By: RKCORCOR
Crossref ID: 2017000442656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2018-12-06 11:46:00
Record Updated: 2018-12-06 14:00:00
Updated By: RKCORCOR

FORMER CASCADE LAUNDRY (Continued) **S118628301**

BROWNFIELDS:

Name:	FORMER CASCADE LAUNDRY
Address:	553 MARCY AVENUE
City,State,Zip:	BROOKLYN, NY 11206
Program:	BCP
Site Code:	495614
Acres:	2.158
HW Code:	C224194
SWIS:	2401
Town:	New York City
Record Added Date:	06/03/2014
Record Updated Date:	01/02/2019
Update By:	AMSERVIS
Site Description:	Site Location: The site is located in an urban area at 553 Marcy Avenue in Brooklyn, Kings County. It is identified on New York City tax maps as Block 1747, Lot 1. The site is bordered by Stockton Street on the north, Marcy Avenue on the west and Myrtle Avenue on the south. Site Features: The site is about 2.1 acres in size and is currently vacant. The site previously included several attached industrial buildings which were demolished for redevelopment in 2015 and 2016. The remainder of the site is paved parking. Current Zoning and Land Use: Part of the site is zoned as residential with commercial retail businesses on the ground floor (R7D residential with a C2-4 commercial overlay), while the remainder of the site has residential zoning (R6A). The site is currently vacant and the on-site buildings have been demolished. The surrounding area includes multi-family residential buildings, schools, churches and retail stores. The site is located in a Type "A" en-zone. Past Use of the Site: Commercial and residential development at the site began prior to 1887. Cascade Laundry, a commercial laundry, began operating on part of the site prior to 1918 and expanded onto the other parts of the site over the succeeding decades before closing in 2010. Other past uses of the site include various retail stores, an oil paint factory, a carpet cleaning facility, a bakery, an upholstery factory, a furniture manufacturer, and a chemical factory. At some point in their history, Cascade Laundry used tetrachloroethene (PCE) in their operations, as evidenced by PCE-contaminated soil. Petroleum contamination was also detected in the on-site soil, likely from leaking underground storage tanks. The top 4-8 feet of soil beneath the site is historic fill, which contains semi-volatile organic compounds (SVOCs), metals and pesticides. Site Geology and Hydrogeology: Subsurface soils at the site consist of historic fill materials to a depth of about 4 to 8 feet below grade. Silty sand and gravel is present immediately below this layer. The elevation of the property is about 30 feet above mean sea level and the land within the immediate area slopes gradually from southeast to northwest. Groundwater at the site is present at a depth of about 25 feet below grade. The groundwater flow direction is northwest.
Env Problem:	Nature and Extent of Contamination: Remediation at the site is complete. Based on investigations conducted to date, the primary contaminants of concern for the site include volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals. Review of on-site data indicates that the on-site contamination does not impact off-site properties or receptors. Soils - Soil contamination was addressed in the Remedial Action by dewatering, excavation and chemical oxidation. Post remediation, remaining soils to a depth of 15 ft. bgs meet UUSCOs for all parameters due to the

FORMER CASCADE LAUNDRY (Continued) **S118628301**

depth of excavation across the site. All remaining soils at depth meet UUSCOs for all COCs, except for a single detection of Chrysene at 30 ft. bgs beneath Lot 2. Soils pre remediation - The VOCs in the soil included petroleum compounds and chlorinated solvents. During the Remedial Investigation, petroleum compounds exceeding unrestricted use soil cleanup objectives include 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, ethylbenzene, xylene, methylene chloride and naphthalene. For example, 1,2,4-trimethylbenzene, was detected at 38 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective of 3.6 ppm. Tetrachloroethene (PCE), a chlorinated solvent, was found in the soil at 48 ppm, exceeding the unrestricted use soil cleanup objective of 1.3 ppm. SVOCs, metals and pesticides were detected in the subsurface soils. Nearly all of these contaminants were detected near the surface in the historic fill layer, and likely arrived at the site with the deposition of the historic fill material. However, chrysene, an SVOC, was detected beneath the historic fill at 3.1 ppm, exceeding the unrestricted soil cleanup objective of 1 ppm. Lead was detected in the soil at a maximum level of 3,770 ppm, which may classify the soil as hazardous waste. Groundwater - Post Remediation, groundwater beneath the site meets or will meet SCGs for all site-sourced contaminants. The petroleum compounds still being detected in groundwater approximate the ambient water quality standards. Pre Remediation groundwater - The VOCs in the groundwater also consist of petroleum compounds and chlorinated solvents. A viscous petroleum product -- likely fuel oil -- was found in one monitoring well, indicated a layer of free petroleum product floating on the groundwater. PCE was detected in several wells at levels exceeding its New York State groundwater standard; however, the highest PCE concentrations were detected upgradient of any known on-site source area and at the upgradient edge of the site. Several pesticides were detected at concentrations above groundwater standards. Soil Vapor and Sub-Slab Vapor - Post remediation sub-slab samples taken in newly constructed on-site buildings detected PCE at a concentrations as high as 441 micrograms per cubic meter. Pre Remediation Soil Vapor and Sub-Slab Vapor - Several VOCs, including PCE, were detected in soil vapor and sub-slab vapor samples collected on-site, most of which were not detected in the soil and groundwater. However, PCE was detected in the on-site soil and groundwater. PCE and TCE were detected in sub-slab and soil vapor samples at maximum concentrations of 453 micrograms per cubic meter and 25.8 micrograms per cubic meter, respectively. One soil vapor sample had detections of benzene, toluene, ethylbenzene and xylene (BTEX) totaling 1,466 micrograms per cubic meter.

Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-06-03 07:17:00

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Record Upd:	2018-12-14 14:18:00
Updated By:	JGJONES
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Marcy Library
Owner Address:	617 DeKalb Avenue at Nostrand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Michael Kohn
Owner Company:	553 Marcy Avenue Owner LLC
Owner Address:	266 Broadway, Suite 501
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street, Unit 1A
Owner Addr2:	Brooklyn
Owner City,St,Zip:	NY, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Tremaine Wright
Owner Company:	Brooklyn Community Board 3
Owner Address:	1360 Fulton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Isac Deutsch
Owner Company:	Cascade 553 LLC
Owner Address:	246 Lynch Street
Owner Addr2:	Unit 1A
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
HW Code:	C224194
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	toluene
Waste Quantity:	UNKNOWN

FORMER CASCADE LAUNDRY (Continued) **S118628301**

Waste Code:	Not reported
HW Code:	C224194
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224194
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1100223
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2014-06-19 11:32:00
Record Updated:	2014-06-19 11:32:00
Updated By:	BRWOLOSE
Crossref ID:	1601325
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-05-10 15:00:00
Record Updated:	2016-05-10 15:00:00
Updated By:	SXMAHAT
Crossref ID:	C224194-12-14
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-12-06 11:47:00
Record Updated:	2018-12-11 09:31:00
Updated By:	RKCORCOR
Crossref ID:	2017000442656
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2018-12-06 11:46:00
Record Updated:	2018-12-06 14:00:00
Updated By:	RKCORCOR

AQ490 **260 LEE AVENUE** **NY VCP** **S118943531**
WSW **260 LEE AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.407 mi.
2148 ft. **Site 3 of 3 in cluster AQ**

Relative:
Lower

Actual:
12 ft.

VCP NYC:
Project ID: 15CVCP145K
Project Name: 260 LEE AVENUE
Project Address: 260 LEE AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP145K
File Name: 2015-01-29.Phase_I_Screening
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP145K/2015-01-29.15EHAN346K.Doc.PHASE_I_Screening.EBC.pdf

Project ID: 15CVCP145K
File Name: 2015-05-20.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP145K/2015-05-20.15EHAN346K.Report.RIR.OER hz_hm.pdf

Project ID: 15CVCP145K
File Name: 2015-09-17.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP145K/2015-09-17.15CVCP145K.260_Lee_Ave.Report.RAWP_v2.EBC.pdf

Project ID: 15CVCP145K
File Name: 2015-09-17.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP145K/2015-09-19.15CVCP145K.260_Lee_Ave.doc.Factsheet-1.pdf

Project ID: 15CVCP145K
File Name: 2015-09-17.Translated_Factsheet-1
URL: http://www.nyc.gov/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP145K/2015-09-19.15CVCP145K.260_Lee_Ave.doc.Translated_Factsheet-1.pdf

Project ID: 15CVCP145K
File Name: 2015-09-17.Translated_CPS
URL: http://www.nyc.gov/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP145K/2015-09-19.15CVCP145K.260_Lee_Ave.doc.Translated_CPS.pdf

---

AS491 **527 FLUSHING AVENUE** **NY VCP** **S118943225**
WSW **527 FLUSHING AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.414 mi.
2187 ft. **Site 3 of 3 in cluster AS**

Relative:
Lower

Actual:
12 ft.

VCP NYC:
Project ID: 13CVCP087K
Project Name: 527 FLUSHING AVENUE
Project Address: 527 FLUSHING AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 13CVCP087K
File Name: 2012-09-04.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2012-09-04.13CVCP087K.RIR.pdf

527 FLUSHING AVENUE (Continued) **S118943225**

Project ID:	13CVCP087K
File Name:	2012-11-08.RAWP
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2012-11-08.13CVCP087K.527_Flushing_Ave.RAWP_Final.pdf
Project ID:	13CVCP087K
File Name:	2012-09-04.FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2012-09-04.13CVCP087K.FactSheet1.pdf
Project ID:	13CVCP087K
File Name:	2012-09-04.Translated_FactSheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2012-09-05.13CVCP087K.Translated_FactSheet1.pdf
Project ID:	13CVCP087K
File Name:	2012-09-04.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2012-05-09.13CVCP087K.Translated_CPS.pdf
Project ID:	13CVCP087K
File Name:	2013-01-04.FactSheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2013-01-04.13CVCP087K.FactSheet2.pdf
Project ID:	13CVCP087K
File Name:	2012-09-04.Translated_FactSheet-2
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2012-09-04.13CVCP087K.527_Flushing_Ave.Translated.factsheet2.pdf
Project ID:	13CVCP087K
File Name:	2012-12-14.Decision_Document
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/13CVCP087K/2012-12-14.13CVCP087K.Decision_Document.pdf

---

AU492 **BORINQUEN HOUSES** **NY LTANKS** **U002034217**
NE **300 BUSHWICK AVENUE** **NY UST** **N/A**
1/4-1/2 **BROOKLYN, NY 11206**
0.427 mi.
2255 ft. **Site 2 of 2 in cluster AU**

Relative: LTANKS:
Higher

Name:	BORINQUEN PLAZA
Address:	300 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9711478 / 1998-02-02
Facility ID:	9711478
Site ID:	191464
Spill Date:	1998-01-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported

Actual:
19 ft.

BORINQUEN HOUSES (Continued) **U002034217**

Reported to Dept:	1998-01-13
CID:	369
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-01-13
Spill Record Last Update:	1998-02-02
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 360-3233
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	159754
DEC Memo:	""
Remarks:	"tank failed and will be drained and inv is underway"

All TTF:

Facility ID:	9711478
Spill Number:	9711478
Spill Tank Test:	1545555
Site ID:	191464
Tank Number:	001
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	191464
Operable Unit ID:	1057978
Operable Unit:	01
Material ID:	326136
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BORINQUEN HOUSES (Continued) **U002034217**

Name:	BORINQUEN PLAZA
Address:	300 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9010701 / 1998-01-13
Facility ID:	9010701
Site ID:	191530
Spill Date:	1991-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	1991-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-16
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	159754
DEC Memo:	""
Remarks:	"5K TANK FAILED HORNER EZY CHECK,SYSTEM TEST,GROSS LEAK,WILL EXCAVATE, ISOLATE,REPAIR & RETEST,SUSPECT LEAKING STICK LINE."

All TTF:

Facility ID:	9010701
Spill Number:	9010701
Spill Tank Test:	1538135
Site ID:	191530
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

BORINQUEN HOUSES (Continued) **U002034217**

All Materials:

Site ID:	191530
Operable Unit ID:	947842
Operable Unit:	01
Material ID:	430831
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	BORINQUEN PLAZA 1 -NYCHA
Address:	300 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712046 / 2004-02-06
Facility ID:	9712046
Site ID:	191531
Spill Date:	1998-01-28
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1998-01-28
CID:	204
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-01-28
Spill Record Last Update:	2005-03-07
Spiller Name:	SEBASTION LOREFICE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	SEBASTION LOREFICE
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	159754
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY SITE INVESTIGATIONS WERE PERFORMED BY TRC ENVIRONMENTAL IN THE MID 1990s AND BY GANNETT FLEMING IN 2002. VERY MINOR IMPACTS TO SOIL AND GROUNDWATER WERE IDENTIFIED IN THE AREA OF THE FORMER TANK. SEVERAL PAH COMPOUNDS WERE DETECTED IN SOIL AT LEVELS ABOVE TAGM 4046 GUIDELINES, IN THE HUNDREDS OF PPB (HIGHEST WAS CHRYSENE AT 780 UG/KG), AND SEVERAL PAHs WERE DETECTED IN ONE MONITORING WELL, WITH ONLY ONE COMPOUND EXCEEDING ITS GROUNDWATER STANDARD SLIGHTLY

BORINQUEN HOUSES (Continued) **U002034217**

(CHRYSENE AT 1 UG/L). OK TO CLOSE. - JK "
Remarks: "TO BE ISOLATED AND RETESTED"

All TTF:
Facility ID: 9712046
Spill Number: 9712046
Spill Tank Test: 1545581
Site ID: 191531
Tank Number: 001
Tank Size: 5000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 191531
Operable Unit ID: 1054708
Operable Unit: 01
Material ID: 326676
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

UST:
Name: BORINQUEN HOUSES
Address: 300 BUSHWICK AVENUE
City,State,Zip: BROOKLYN, NY 11206
Id/Status: 2-601869 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589622.17610
UTM Y: 4506619.90707
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 23831
Affiliation Type: Facility Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: FUEL OIL REMEDIATION COORDINATOR
Contact Name: FUEL OIL REMEDIATION COORD.
Address1: 23-02 49TH AVENUE

BORINQUEN HOUSES (Continued) **U002034217**

Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	2005-09-30

Site Id:	23831
Affiliation Type:	Mail Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	MR. LUIS PONCE
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23831
Affiliation Type:	Facility Operator
Company Name:	BORINQUEN HOUSES
Contact Type:	Not reported
Contact Name:	MR. LUIS PONCE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23831
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICE DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 707-5725

BORINQUEN HOUSES (Continued) **U002034217**

EMail: Not reported
Fax Number: Not reported
Modified By: EXROSSAN
Date Last Modified: 2005-09-21

Tank Info:

Tank Number: 1
Tank ID: 48184
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: 02/01/1975
Date Tank Closed: 07/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: 03
Date Test: 02/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

---

493 **BEDFORD AUTO SALES** **NY SWF/LF** **S108145701**
SSE **984 MYRTLE AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11206**
0.432 mi.
2281 ft.

Relative:
Higher

Actual:
55 ft.

SWF/LF:
Name: BEDFORD AUTO SALES
Address: 984 MYRTLE AVE
City,State,Zip: BROOKLYN, NY 11206
Flag: ACTIVE
Region Code: 2
Phone Number: 7188552725
Owner Name: Frank Waters
Owner Type: Private
Owner Address: 105 Nostrand Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Email: biker202222@yahoo.com
Owner Phone: 7188552725

BEDFORD AUTO SALES (Continued) **S108145701**

Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7043667]
Active:	Yes
East Coordinate:	589414
North Coordinate:	4505539
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AV494 **BORDEN CHEMICAL** **NY HSWDS** **S108146439**
SW **56 NOSTRAND AVE.** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.439 mi.
2317 ft. **Site 1 of 4 in cluster AV**

Relative: **Higher**

Actual: **14 ft.**

HSWDS:

Facility ID:	Not reported
Region:	2
Facility Status:	Unknown
Owner Type:	Puplic
Owner:	Borden Chemical
Owner Address:	56 Nostrand Avenue
Owner Phone:	(212)834-5662
Operator Type:	Same
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	None
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	None
RCRA Permitted:	Unknown
Site Code:	Leaking tanks, drums, lagoons, other containers
Owner City State:	Brooklyn
Operator City State:	Not reported
Quadrange:	Brooklyn
Latitude:	40 41 51 N
Longitude:	73 57 24 W
Acres:	0.00
Operator Date:	Unknown
Close Date:	Unknown
Completed:	Unknown
Active:	Not reported
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No

BORDEN CHEMICAL (Continued) **S108146439**

Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	None
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AV495 **BORDEN CHEMICAL ADHESIVES & CHEM** **SEMS-ARCHIVE** **1000186343**
SW **56 NOSTRAND AVE** **RCRA NonGen / NLR** **NYD012497335**
1/4-1/2 **BROOKLYN, NY 11205** **FINDS**
0.439 mi. **ECHO**
2317 ft. **Site 2 of 4 in cluster AV**

Relative: Higher

Actual: 14 ft.

SEMS Archive:

Site ID:	0201493
EPA ID:	NYD012497335
Cong District:	28
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201493
EPA ID:	NYD012497335
Site Name:	BORDEN CHEMICAL ADHESIVES & CHEM
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1980-10-01 04:00:00
Finish Date:	1980-11-01 05:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201493
EPA ID:	NYD012497335
Site Name:	BORDEN CHEMICAL ADHESIVES & CHEM
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1980-11-01 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0201493
EPA ID:	NYD012497335
Site Name:	BORDEN CHEMICAL ADHESIVES & CHEM
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1980-05-01 04:00:00
Finish Date:	1980-05-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

BORDEN CHEMICAL ADHESIVES & CHEM (Continued) **1000186343**

Region:	02
Site ID:	0201493
EPA ID:	NYD012497335
Site Name:	BORDEN CHEMICAL ADHESIVES & CHEM
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1980-10-01 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	BORDEN CHEMICAL ADHESIVES & CHEMICALS
Facility address:	56 NOSTRAND AVE BROOKLYN, NY 11205-1624
EPA ID:	NYD012497335
Mailing address:	E BROAD ST COLUMBUS, NY 43215
Contact:	Not reported
Contact address:	E BROAD ST COLUMBUS, NY 43215
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BORDEN INC
Owner/operator address:	180 EAST BROAD ST OPERCITY, OH 99999
Owner/operator country:	US
Owner/operator telephone:	212-834-5662
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	BORDEN INC
Owner/operator address:	180 E BROAD ST COLUMBUS, OH 43215
Owner/operator country:	US
Owner/operator telephone:	212-834-5662
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

BORDEN CHEMICAL ADHESIVES & CHEM (Continued) **1000186343**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: BORDEN CHEMICAL ADHESIVES & CHEMICALS
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: BORDEN CHEMICAL ADHESIVES & CHEMICALS
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Site name: BORDEN CHEMICAL ADHESIVES & CHEMICALS
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: BORDEN CHEMICAL ADHESIVES & CHEMICALS
Classification: Small Quantity Generator

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: U001
. Waste name: ACETALDEHYDE (I) (OR) ETHANAL (I)

BORDEN CHEMICAL ADHESIVES & CHEM (Continued) **1000186343**

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U043
. Waste name: ETHENE, CHLORO- (OR) VINYL CHLORIDE

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U088
. Waste name: 1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U156
. Waste name: CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)

. Waste code: U188
. Waste name: PHENOL

. Waste code: U202
. Waste name: 1,2-BENZISOTHIAZOL-3(2H)-ONE, 1,1-DIOXIDE, & SALTS

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U226
. Waste name: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110004344451

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000186343

BORDEN CHEMICAL ADHESIVES & CHEM (Continued) **1000186343**

Registry ID: 110004344451
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004344451

496
WSW
1/4-1/2
0.448 mi.
2363 ft.

CLOSED-LACKOF RECENT INFO **NY LTANKS** **S106703218**
204 WALLABOUT ST **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
12 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	204 WALLABOUT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8801005 / 2003-03-05
Facility ID:	8801005
Site ID:	324576
Spill Date:	1988-05-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1988-05-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-05-05
Spill Record Last Update:	2004-03-25
Spiller Name:	Not reported
Spiller Company:	NEW ERA KNITTING MILLS
Spiller Address:	204 WALLABOUT
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	261444
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/05/2003- Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"2500 GALLON TANK FAILED WITH A LEAK RATE OF -.197GPH, INITIAL SYSTEM PETRO TITE TEST.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID:	8801005
Spill Number:	8801005
Spill Tank Test:	1533813
Site ID:	324576
Tank Number:	Not reported
Tank Size:	0

CLOSED-LACKOF RECENT INFO (Continued) **S106703218**

Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	324576
Operable Unit ID:	918001
Operable Unit:	01
Material ID:	460161
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

497
WSW
1/4-1/2
0.452 mi.
2388 ft.

30 WARSOFF PLACE/BKLYN **NY LTANKS** **S100144944**
30 WARSOFF PLACE **N/A**
NEW YORK CITY, NY

Relative:
Higher

Actual:
14 ft.

LTANKS:

Name:	30 WARSOFF PLACE/BKLYN
Address:	30 WARSOFF PLACE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8708592 / 1992-09-30
Facility ID:	8708592
Site ID:	228023
Spill Date:	1988-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1992-09-30
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

30 WARSOFF PLACE/BKLYN (Continued) **S100144944**

Date Entered In Computer:	1988-01-25
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	RELIABLE SAMPLE CARD COMP
Spiller Address:	30 WARSOFF PLACE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	188084
DEC Memo:	""
Remarks:	"10K TANK FAILED WITH A LEAK RATE OF -.122GPH, WILL EXCAVATE, ISOLATE AND RETEST."

All TTF:

Facility ID:	8708592
Spill Number:	8708592
Spill Tank Test:	1532946
Site ID:	228023
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	228023
Operable Unit ID:	913266
Operable Unit:	01
Material ID:	463971
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AV498 **MARCY HOUSES -NYCHA** **NY LTANKS** **S105054636**
SW **603 PARK AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.474 mi.
2502 ft. **Site 3 of 4 in cluster AV**

Relative:
Higher

Actual:
17 ft.

LTANKS:

Name:	MARCY HOUSES -NYCHA
Address:	603 PARK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0100526 / 2003-12-09
Facility ID:	0100526
Site ID:	274620
Spill Date:	2001-04-13
Spill Cause:	Tank Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2001-04-13
CID:	199
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2001-04-13
Spill Record Last Update:	2005-12-09
Spiller Name:	LUIS PONCE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	23-02 49TH AVENUE
Spiller County:	001
Spiller Contact:	MOHAMMID ARIF
Spiller Phone:	(718) 566-8960
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	178748
DEC Memo:	""
Remarks:	"WHILE REMOVING OLD TANKD (3) THERE WAS EVIDENCE FOUND OF OLD TANKS AND LEAKS IN THE CURRENT TANKS - CONTAMINATED SOIL FOUND / ALL SOIL WILL BE EXCAVATED AND SEPERATED TILL SAMPLES CAN BE TAKEN"

All Materials:

Site ID:	274620
Operable Unit ID:	837414
Operable Unit:	01
Material ID:	536231
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

MARCY HOUSES -NYCHA (Continued) **S105054636**

Site ID:	274620
Operable Unit ID:	837414
Operable Unit:	01
Material ID:	536230
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV499 **MARCY HOUSES -NYCHA** **NY LTANKS** **S101102893**
SW **603 PARK AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.474 mi.
2502 ft. **Site 4 of 4 in cluster AV**

Relative: LTANKS:
Higher

Actual: Name:	MARCY HOUSES -NYCHA
17 ft. Address:	603 PARK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9607616 / 2005-12-09
Facility ID:	9607616
Site ID:	215887
Spill Date:	1996-09-17
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1996-09-17
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-09-17
Spill Record Last Update:	2005-12-09
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY 16TH FLOOR
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	178748
DEC Memo:	"12/09/05: This spill transferred from J.Kolleeny to S.Kraszewski. This spill closed to consolidate with open spill #9614725."
Remarks:	"diesel generator fuel tank failed"

MARCY HOUSES -NYCHA (Continued) **S101102893**

All TTF:

Facility ID:	9607616
Spill Number:	9607616
Spill Tank Test:	1544761
Site ID:	215887
Tank Number:	001
Tank Size:	2000
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	215887
Operable Unit ID:	1038782
Operable Unit:	01
Material ID:	346875
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MARCY HOUSES -NYCHA
Address:	603 PARK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9611167 / 2007-12-11
Facility ID:	9611167
Site ID:	215888
Spill Date:	1996-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	CONSOLIDATED WITH 9315457
Reported to Dept:	1996-12-10
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

MARCY HOUSES -NYCHA (Continued) **S101102893**

Remediation Phase:	0
Date Entered In Computer:	1996-12-10
Spill Record Last Update:	2007-12-11
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	178748
DEC Memo:	"12/09/05: This spill transferred from J.Kolleeny to S.Kraszewski. 07/28/06: See comments for spill #9614725. - SK 02/08/07 : DEC lead changed from S. Kraszewski to J. Kann. J.Kann"
Remarks:	"ISOLATE PIPING FROM TANK AND THEY WILL RE-TEST"

All TTF:

Facility ID:	9611167
Spill Number:	9611167
Spill Tank Test:	1544924
Site ID:	215888
Tank Number:	3
Tank Size:	2000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Name:	MARCY HOUSES -NYCHA
Address:	603 PARK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9614725 / 2007-12-11
Facility ID:	9614725
Site ID:	215889
Spill Date:	1997-03-21
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	CONSOLIDATED WITH 9315457
Reported to Dept:	1997-03-21
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

MARCY HOUSES -NYCHA (Continued) **S101102893**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-21
Spill Record Last Update:	2007-12-11
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	178748
DEC Memo:	"12/09/05: This spill transferred from J.Kolleeny to S.Kraszewski. 07/28/06: NYCHA update summary states that two 35K USTs installed in 1982 and stored #4 and #6 oil were closed-removed in 2001. A 2K Diesel tank installe din 1982 was closed-removed in 2001. In 1999, a 20K UST was installed. In 1996, a 4K AST was installed. Both were disconnected in 2001. In 2001, two 25 USTs that store #2 oil and one 2K diesel tank were installed and are currently in service. No recovery system and no MWs on site. NYCHA recommends that DEC review the available site assessment. - SK 12/11/07: Closed and consolidated with spill 9315457. Reassigned to J.Kann -J.Kann"
Remarks:	"tank failed test "

All TTF:

Facility ID:	9614725
Spill Number:	9614725
Spill Tank Test:	1545038
Site ID:	215889
Tank Number:	1
Tank Size:	35000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Name:	MARCY HOUSES -NYCHA
Address:	603 PARK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9315457 / 2016-01-20
Facility ID:	9315457
Site ID:	274622
Spill Date:	1992-07-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann

MARCY HOUSES -NYCHA (Continued) **S101102893**

Referred To:	Not reported
Reported to Dept:	1994-03-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-05
Spill Record Last Update:	2016-01-20
Spiller Name:	Not reported
Spiller Company:	NYCHA - JOE MONTELLA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	178748
DEC Memo:	"12/09/05: This spill transferred from J.Kolleeny to S.Kraszewski. 03/23/06: This spill transferred to K.Tang - SK 12/11/07: J.Kann. This spill transferred to J.Kann. Consolidated with 9611167 (closed) and 9614725 (closed). Spill 9611167 indicates 07/28/06: NYCHA update summary states that two 35K USTs installed in 1982 and stored #4 and #6 oil were closed-removed in 2001. A 2K Diesel tank installe din 1982 was closed-removed in 2001. In 1999, a 20K UST was installed. In 1996, a 4K AST was installed. Both were disconnected in 2001. In 2001, two 25 USTs that store #2 oil and one 2K diesel tank were installed and are currently in service. No recovery system and no MWs on site. NYCHA recommends that DEC review the available site assessment. 3/10/11: J.Kann - Investigative work plan submitted on 3/3/11. 5/29/12: J.kann - priority p0 assigned to the site 3/31/15: J.Kann - email sent to NYCHA on March 11 asking if they have any information regarding the tank closure (endpoints). NYCHA did not find additional information, therefore the IWP was approved today. 10/5/15: J.Kann - received notice that field work will be occurring today and tomorrow at Marcy Houses. 1/20/16: J.Kann - SIR for the site was received on 12/7/16. 7 borings were advanced and 4 monitoring wells installed. No stained soils or odors noted in borings. 7 soils samples and 4 groundwater samples were collected for VOC and SVOC analysis. No VOCs or SVOCs were detected. Spill closed. 1/20/16 - J.kann - DecDoced site file correspondences from 1996-present under this spill number."
Remarks:	"LEAK RATE OF 0.08 GPH REPORTED AS PASSED BY TESTER."

All TTF:

Facility ID:	9315457
Spill Number:	9315457
Spill Tank Test:	1542561
Site ID:	274622
Tank Number:	001
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

MARCY HOUSES -NYCHA (Continued) **S101102893**

Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported
Facility ID:	9315457
Spill Number:	9315457
Spill Tank Test:	1542562
Site ID:	274622
Tank Number:	002
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	274622
Operable Unit ID:	997511
Operable Unit:	01
Material ID:	387209
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

---

500 SW 1/4-1/2 0.483 mi. 2548 ft. **COMMERCIAL BUILDING** **NY LTANKS** **S108467904**
544 PARK AVE **N/A**
BROOKLYN, NY

Relative: Higher
Actual: 18 ft.

LTANKS:

Name:	COMMERCIAL BUILDING
Address:	544 PARK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0613501 / 2008-07-01
Facility ID:	0613501
Site ID:	378545
Spill Date:	2007-03-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

COMMERCIAL BUILDING (Continued) **S108467904**

Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-03-15
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-03-15
Spill Record Last Update:	2008-07-01
Spiller Name:	MATT
Spiller Company:	COMMERCIAL BUILDING
Spiller Address:	544 PARK AVE
Spiller County:	001
Spiller Contact:	MATT
Spiller Phone:	(631) 234-4273
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	328078
DEC Memo:	"3/27/07 bf: Spoke with Matt of Associated Environmental (631)234-4273. Expoxy patch from previous repair at top of tank was problem. Tank is AST. They plan on having the tank cleaned out, inspected, remove epoxy, and weld a steel patch to tank. Then tank will be tightness tested. They plan on starting work next week. One problem is getting a tanker to be dedicated to the building while the repairs are made. Petroleum Tank Cleaners will be doing repairs and testing in conjunction with Associated. Sent ttf letter to: David Rochlitz 544 Park Avenue Brooklyn, NY 11205 7/13/07 On 7/12/07, received call from Antionette Ollivierre of American Environmental Associates and Solutions (718)209-0653. She requested a call back. Called her back today. I faxed her a copy of the ttf letter dated 3/27/07. fax:(718)622-5807. bf 9/20/07 Received call from Aron Weinstein tesla Environmental 732-904-4618. Called him back at 2:45 PM. He will send email letting me know where project stands. Tank is encased in concrete and there may be structural concerns regarding the building. A Phase II was done on the property and eight borings were done. I told him I need to see those. I asked him why the tank failed and he could not answer except that the Horner EZ 3 should not be allowed. He was on a cell phone and was hard to hear. bf 11/13/07 On 11/8/07, received call from Donna of ABC Tank. Ph.(718)272-2800 Fax.(718)272-3147. She requested any paperwork regarding the spill. I sent her the ttf letter and the spill report. Called her back, but she is not in until Thursday. bf 3/4/08 Site inspected on 2/29/08. NOV issued. Received call to day from John of Gianco (contractor doing tank test/repair). I faxed ttf letter to him. Fax: (631)952-5975. bf 4/2/08 Signed order hand-delivered with check for $1100 panalty. bf 4/30/08 Received faxed letter on 4/9/08 from John Sinatra of Gianco, dated 4/8/08, to Robert Hoffman. Tank passed pressure test over the weekend holding 7 pounds of air. No contamination was found on, near, or surrounding the tank. It is his belief that the tank can be out online as a backup. 6/19/08 Called

COMMERCIAL BUILDING (Continued) **S108467904**

Robert Hoffman requesting tank test report. He faxed letter to close spill, not report. Sent tt return letter to him since document is not a tank test report. bf 7/1/08 Received passing test report on 6/30/08. NFA. bf"

Remarks: "CONTACT IS FROM COMPANY THAT HIRED CALLER TO PERFORM TANK TEST: MATT FROM ASSOCIATED ENVIRONMENTAL"

All TTF:

Facility ID:	0613501
Spill Number:	0613501
Spill Tank Test:	1550709
Site ID:	378545
Tank Number:	001
Tank Size:	13000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	378545
Operable Unit ID:	1136045
Operable Unit:	01
Material ID:	2125975
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

501 **802-806 MYRTLE AVENUE** **NY VCP** **S118943422**
SSW **802-806 MYRTLE AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.483 mi.
2549 ft.

Relative:
Higher

Actual:
28 ft.

VCP NYC:

Project ID:	15CVCP029K
Project Name:	802-806 MYRTLE AVENUE
Project Address:	802-806 MYRTLE AVENUE
Borough:	BROOKLYN

VCP NYC:

Project ID:	15CVCP029K
File Name:	2014-11-18.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP029K/2014-09-22.15EHAN140K.report.RIR.EBC.pdf

802-806 MYRTLE AVENUE (Continued) **S118943422**

Project ID: 15CVCP029K
File Name: 2014-11-18.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP029K/2014-10-23.15EHAN140K.report.RAWP_revised.EBC.pdf

Project ID: 15CVCP029K
File Name: 2014-11-18.Factsheet_1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP029K/2014-10-23.15CVCP029K.doc.802-806_Myrtle_Avenue_Factsheet-1.OER.pdf

Project ID: 15CVCP029K
File Name: 2014-11-18.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP029K/2014-10-23.15CVCP029K.doc.802-806_Myrtle_Avenue_Translated_FactSheet-1.OER.pdf

Project ID: 15CVCP029K
File Name: 2014-11-18.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP029K/2014-10-23.15CVCP029K.doc.802-806_Myrtle_Avenue_Translated_CPS.OER_rx.pdf

---

502 SSW 1/4-1/2 0.491 mi. 2593 ft.

74 VERNON AVENUE
74 VERNON AVENUE
NEW YORK CITY, NY

NY VCP **S118943476**
N/A

Relative: Higher

Actual: 34 ft.

VCP NYC:
Project ID: 15CVCP087K
Project Name: 74 VERNON AVENUE
Project Address: 74 VERNON AVENUE
Borough: BROOKLYN

VCP NYC:
Project ID: 15CVCP087K
File Name: 2015-01-23.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP087K/2014-12-29.15EH-A149K.RIR_draft.EBC.pdf

Project ID: 15CVCP087K
File Name: 2015-01-30.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP087K/2015-02-18.15EHA149K.PDF.RAWP. EBC KS.pdf

Project ID: 15CVCP087K
File Name: 2015-01-30.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP087K/2015-02-27.15EH-A149K.doc.74-Vernon_Factsheet-1.pdf

Project ID: 15CVCP087K
File Name: 2015-01-30.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP087K/2015-03-02.15EH-A149K.doc.translation_FS1.OER.pdf

Project ID: 15CVCP087K

74 VERNON AVENUE (Continued) **S118943476**

File Name: 2015-01-30.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/15CVCP087K/2015-03-02.15EH-A149K.doc.translation_FS1.OER.pdf

---

503 ESE 1/4-1/2 0.492 mi. 2596 ft. **SUMNER HOUSES -NYCHA**
10 LEWIS AVE
BROOKLYN, NY

NY LTANKS S101658425
NY Spills N/A

Relative: Higher
Actual: 70 ft.

LTANKS:

Name:	SUMNER HOUSES -NYCHA
Address:	10 LEWIS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9505160 / 2003-10-30
Facility ID:	9505160
Site ID:	180721
Spill Date:	1995-07-27
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1995-07-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-28
Spill Record Last Update:	2005-11-29
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	172229
DEC Memo:	""
Remarks:	"TANK #1 - FAILURE"

All TTF:

Facility ID:	9505160
Spill Number:	9505160
Spill Tank Test:	1544031
Site ID:	180721
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported

SUMNER HOUSES -NYCHA (Continued) **S101658425**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	180721
Operable Unit ID:	1016156
Operable Unit:	01
Material ID:	363156
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SUMNER HOUSES -NYCHA
Address:	10 LEWIS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9505222 / 2015-12-16
Facility ID:	9505222
Site ID:	180722
Spill Date:	1995-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	CONSOLIDATED WITH 9904132
Reported to Dept:	1995-07-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-07-28
Spill Record Last Update:	2015-12-16
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

SUMNER HOUSES -NYCHA (Continued) **S101658425**

DEC Region: 2
DER Facility ID: 172229
DEC Memo: "12/19/05: This spill transferred from J.Kolleeny to S.Kraszewski. 03/23/06: This spill transferred to K.Tang - SK 12/30/09: J.Kann - site reassigned to J.kann and consolidated with 9904132 5/25/12: J.kann - assigned priority P0 to site as part of monthly report exercise, little information is readily available. 12/16/15: J.Kann - Site Assessment Report (submittal cover page dated March 13, 2000) was reviewed. 8 endpoint soil samples were collected as a part of the tank removal process back in 1999. No VOCs exceeded Table 3 of CP-51. 7 of the 8 soil samples were below Table 3 CP-51 guidance for SVOCs. At one location, NW-3, some minor SVOCs were detected above CP-51, however they were minimal and isolated to one location. An excavation was performed on site as a part of tank removal and a total of 656 tons of contaminated soil were removed from the site. In addition 3 borings were advanced around the tank that was closed in place. Each of the three samples collected for analysis in these three borings (at a depth of 20 ft) were below CP-51 Table 3 for SVOCs and VOCs. Spill therefore closed. Report DECdoced."
Remarks: "TANK #2 - FAILURE"

All TTF:
Facility ID: 9505222
Spill Number: 9505222
Spill Tank Test: 1544033
Site ID: 180722
Tank Number: 002
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 180722
Operable Unit ID: 1016192
Operable Unit: 01
Material ID: 363215
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: SUMNER HOUSES

SUMNER HOUSES -NYCHA (Continued) **S101658425**

Address:	10 LEWIS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8909504 / 1992-12-08
Facility ID:	8909504
Facility Type:	ER
DER Facility ID:	172229
Site ID:	207567
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1990-01-02
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	1992-12-08
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-01-16
Spill Record Last Update:	2004-05-14
Spiller Name:	Not reported
Spiller Company:	MYSTIC OIL CO
Spiller Address:	GEORGE ALVERA
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"VENDORS SPILLED FUEL OIL ON THE SIDEWALK - BROKEN HOSE. APPLIED SPEEDI-DRY, MATERIAL WAS PLACED IN GALVANIZED CANS. CONTRACTOR WILL DISPOSE OF CONTAMINATED MATERIAL & CLEAN."

All TTF:

Facility ID:	8909504
Spill Number:	8909504
Spill Tank Test:	1536630
Site ID:	207567
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

SUMNER HOUSES -NYCHA (Continued) **S101658425**

Site ID:	207567
Operable Unit ID:	936673
Operable Unit:	01
Material ID:	442667
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SUMNER HOUSES -NYCHA
Address:	10 LEWIS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9904132 / 2009-12-30
Facility ID:	9904132
Facility Type:	ER
DER Facility ID:	172229
Site ID:	207568
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1999-07-08
Investigator:	jkkann
Referred To:	CONSOLIDATED WITH 9505222
Reported to Dept:	1999-07-08
CID:	252
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-08
Spill Record Last Update:	2015-12-16
Spiller Name:	EDWARD MALONE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller Company:	001
Contact Name:	RAY VALEZ
DEC Memo:	"11/29/05: This spill transferred from J.Kolleeny to S.Kraszewski. 02/02/06: This spill transferred from S.Kraszewski to Q.Abidi. 04/04/04: This spill transferred from Q. Abidi to Koon Tang 12/30/09: J.Kann - site reasssigned to J.Kann and consolidated with 9505222 12/16/15: J.Kann - Site Assessment Report (submittal cover page dated March 13, 2000) was reviewed. 8 endpoint soil samples were collected as a part of the tank removal process back in 1999. No VOCs exceeded Table 3 of CP-51. 7 of the 8 soil samples were below Table 3 CP-51 guidance for SVOCs. At one location, NW-3, some minor SVOCs were detected above CP-51, however they were minimal and isolated to one

SUMNER HOUSES -NYCHA (Continued) **S101658425**

location. The excavation was done to the extent feasible and a total of 656 tons of contaminated soil were removed from the site. In addition 3 borings were advanced around the tank that was closed in place. Each of the three samples collected for analysis in these three borings (at a depth of 20 ft) were below CP-51 for SVOCs and VOCs. Spill therefore closed. Report DECdoced."

Remarks: "UPON REMOVAL OF 20,000 FUEL OIL TANK SOIL CONTAMINATION WAS DISCOVERED-NYC HOUSING AUTH ON SITE FOR CLEANUP."

All Materials:

Site ID:	207568
Operable Unit ID:	1083071
Operable Unit:	01
Material ID:	304025
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

504 East 1/4-1/2 0.492 mi. 2597 ft. **BROOKLYN SCRAP METAL CO.** **SEMS-ARCHIVE** **1018149162**
171 COOK ST. **LEAD SMELTERS** **NYN000206621**
BROOKLYN, NY 11206

Relative: Higher

Actual: 25 ft.

SEMS Archive:

Site ID:	0206621
EPA ID:	NYN000206621
Cong District:	Not reported
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0206621
EPA ID:	NYN000206621
Site Name:	BROOKLYN SCRAP METAL CO.
NPL:	N
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	2015-01-12 05:00:00
Finish Date:	2015-01-12 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206621
EPA ID:	NYN000206621
Site Name:	BROOKLYN SCRAP METAL CO.

BROOKLYN SCRAP METAL CO. (Continued) **1018149162**

NPL: N
FF: N
OU: 00
Action Code: HX
Action Name: PRE-CERC
SEQ: 1
Start Date: 2012-10-18 04:00:00
Finish Date: 2012-10-18 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0206621
EPA ID: NYN000206621
Site Name: BROOKLYN SCRAP METAL CO.
NPL: N
FF: N
OU: 00
Action Code: HX
Action Name: PRE-CERC
SEQ: 2
Start Date: 2014-05-02 05:00:00
Finish Date: 2014-05-08 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Lead Smelter Sites:
Site ID: 206621
Facility Region Id: 2
Latitude: Not reported
Longitude: Not reported
CoC Ind: Not reported
Contaminant Name: Not reported
FF Ind: N
NAI: N
Non-Primary Site-Sub Type: Not reported
NPL: Not on the NPL
Primary Site-Sub Type: Metal fabrication/finishing/coating and allied industries (Manufacturing/Processing/Maintenance)
Special Initiative: Unrecognized Smelter per 2001 Report

AW505 **FORMER TECHTRONICS SITE B** **NY SHWS** **S121933852**
WSW **480 FLUSHING AVENUE** **NY BROWNFIELDS** **N/A**
1/4-1/2 **BROOKLYN, NY 11205**
0.497 mi.
2625 ft. **Site 1 of 4 in cluster AW**

Relative:
Higher

Actual:
14 ft.

SHWS:
Name: FORMER TECHTRONICS SITE B
Address: 480 FLUSHING AVENUE
City,State,Zip: BROOKLYN, NY 11205
Program: HW
Site Code: 548235
Classification: P
Region: 2
Acres: 0.102

FORMER TECHTRONICS SITE B (Continued) **S121933852**

HW Code: 224259
Record Add: 05/08/2017
Record Upd: 03/01/2018
Updated By: SXDEWES
Site Description: Location: The 0.1 acre site is located on the west side of Walworth Street in Brooklyn between Flushing Avenue and Park Avenue. The site is bounded to the south and west by single story commercial buildings, to the north by Flushing Avenue and to the east by Walworth Street. Site No. 224239: Former Techtronics Ecological Corp. is located immediately south of the property. Site Features: Currently, the site consists of a one-story building used as a storage facility and food store. Current Zoning/Use(s): The site is located in an M1-2 (light manufacturing) zoning district. The surrounding area consists of a mix of light manufacturing, commercial and residential uses. Historical Use(s): The southern portion of the site was utilized in the past by a paint and lacquer manufacturing company (Techtronics Ecological Corporation) from 1962 to 1990. The former Techtronics operation encompassed the property to the south (8 Walworth Street, Block 1716 Lot 33) as well as the southern portion of this site (Block 1716 Lot 30). During the period from 1981 to 1990, the site was a large quantity generator of hazardous waste under EPA ID no. NYD000824334. Wastes formerly generated at the site include ignitable waste, corrosive waste, spent halogenated solvents (i.e. tetrachloroethene), spent non-halogenated solvents (i.e. xylene) and lead. Myer Auto Center operated at the site as a vehicle repair shop from approximately 2005 - 2015. Waste oil was stored on-site under NYSDEC Petroleum Bulk Storage (PBS) ID 2-605797. Site Geology and Hydrogeology: Fill material was identified to a depth of five to seven feet below grade, and native soil thereafter. Groundwater was found at approximately 10 feet below grade. Regional groundwater flow direction in the vicinity of the site is to the west towards the East River.
Env Problem: The environmental assessment will be updated when information becomes available.
Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Not reported
Sub Type: Not reported
Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported

FORMER TECHTRONICS SITE B (Continued) **S121933852**

HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

BROWNFIELDS:

Name:	480 FLUSHING
Address:	480 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11205
Program:	BCP
Site Code:	578363
Acres:	0.102
HW Code:	C224259
SWIS:	2401
Town:	New York City
Record Added Date:	10/16/2018
Record Updated Date:	05/08/2019
Update By:	SXDEWES
Site Description:	Location The site (a.k.a. Former Techtronics B, Site No. 224259). is in the Bedford Stuyvesant section of Brooklyn in the City of New York and is comprised of a single tax parcel totaling 4,450 square feet (0.102 acre). The site is rectangular in shape with 50 feet of frontage on Flushing Avenue and 89.25 feet of frontage on Walworth Street. The north side of the property is bordered by Flushing Avenue, and the east side is bordered by Walworth Street. The west and south property lines are bordered by two NYSBCP sites; the 11 Spencer site to the east and the 8 Walworth site to the south. Site Features The site is currently vacant with no structures present. An 8-foot-high construction fence borders the property on the north and west sites to prevent unauthorized access. The property was most recently used as an auto repair shop. Current Zoning and Land Use The property is currently zoned M1-2. M1 districts are often buffers between M2 or M3 districts and adjacent residential or commercial districts. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale service and storage facilities. Nearly all industrial uses are allowed in M1 districts if they meet the stringent M1 performance standards. Offices, hotels and most retail uses are also permitted. Certain community facilities, such as hospitals, are allowed in M1 districts only by special permit, but houses of worship are allowed as-of-right. The site is currently vacant with no structures present and is not being used. Surrounding land use includes commercial and mixed-use (retail / residential) properties along the north side of Flushing Avenue, commercial / office use to the west, commercial (warehouses) properties to the south and to the east. The area surrounding the property is highly urbanized and predominantly consists of older industrial / commercial buildings with mixed use (retail / residential) buildings along main corridors such as Bedford Avenue, Flushing Avenue and Park Avenue. There are ten schools located within 1,200 feet of the site including Bnei Shimon Yisroel of Sopron approximately 150 feet to the east. There were no nursing homes or

FORMER TECHTRONICS SITE B (Continued) **S121933852**

hospitals identified within 1,000 feet of the site. Past Use of the Site The environmental history of the subject property was previously investigated through the review of Federal and State Environmental databases, Environmental Sanborn Fire Insurance maps, NYC Department of Building records and the NYC Department of Finance databases. According to the review of these sources the property was developed sometime prior to 1887 with two 2-story residences in the southern portion of the Lot with the northern portion vacant. A 1-story building was constructed on the northern portion which is shown as broom manufacturers supply till 1950. A new 1 story building is present in the southern portion of the site in 1965 and identified as paint mixing . The northern building is shown as storage or warehouse. Both buildings remain unchanged till 2016 when the north building was demolished. The south building was demolished in 2018. The property was known to be most recently used by an auto repair shop and a fish market. A site characterization of the site was completed under the project name Former Techtronics B (Site No. 224259). After the site characterization the site entered the brownfield program as 480 Flushing. Site Geology and Hydrogeology Subsurface soils at the site consist of historic fill materials to a depth of approximately 1 foot below grade followed by native silty-sand and clay. According to the USGS topographic map for the area (Brooklyn Quadrangle), the elevation of the property is approximately 16 feet above mean sea level. The topography within the immediate area slopes gradually from south to north. Groundwater was reported to be present under confined or semi-confined conditions at approximately 14 ft below grade. Groundwater flow was estimated to be northwest. The site is not located within a designated flood zone area.

Env Problem:

Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), some metals, and polychlorinated biphenyls (PCBs) as part of a site characterization. Soil Vapor samples were collected and analyzed for VOCs. Based upon the limited investigation conducted to date, the primary contaminants of concern are chlorinated solvents, Tetrachloroethene (PCE), trichloroethene (TCE), and 1,2-dichlorethene (1,2-DCE), in addition to a suite of SVOCs present in soil. Surface Soil PCE [maximum concentration 16 parts per million (ppm), standard 1.3 unrestricted use soil cleanup objective (UUSCO)], Benzo(a)anthracene (5.5 ppm max, standard 1 UUSCO), Benzo(a)pyrene (4.7 ppm, standard 1 UUSCO), Benzo(b)fluoranthene (8.5 ppm, standard 1 UUSCO), Indo(1,2,3-cd)pyrene (4.5 ppm, standard 0.5 UUSCO). Subsurface Soil PCE [maximum concentration 99 parts per million (ppm), standard 1.3 unrestricted use soil cleanup objective (UUSCO)], Benzo(a)anthracene (260 ppm max, standard 1 UUSCO), Benzo(a)pyrene (230 ppm, standard 1 UUSCO), Benzo(b)fluoranthene (280 ppm, standard 1 UUSCO), Benzo(k)Fluoranthene (100 ppm, standard 0.8 UUSCO), Phenanthrene (800 ppm, standard 1 UUSCO), Dibenzo(a,h)anthracene (37 ppm, standard 0.33 UUSCO), Indo(1,2,3-cd)pyrene (140 ppm, standard 0.5 UUSCO). Brick and coal fragments were observed in shallow soil at some of the soil borings collected, suggesting the presence of urban fill. Groundwater - PCE [maximum concentration 2,400 parts per billion (ppb), standard 5 ppb], TCE (350 ppb max, 5 ppb standard), and 1,2-dichlorethene (340 ppb max, 5 ppb standard). Elevated metal concentrations were detected in groundwater throughout the site. Iron (8840 ppb max, standard 300 ppb), Manganese (6621 ppb max, standard 300 ppb), and Sodium (66100 ppb max, standard 2000 ppb). Soil Vapor The site is currently

FORMER TECHTRONICS SITE B (Continued) **S121933852**

	undeveloped. Three soil vapor samples were collected on-site with elevated concentrations of chlorinated VOCs. Max concentrations of PCE are 40.6 micrograms per cubic meter (ug/m3), TCE 1470 ug/m3 and vinyl chloride 7.77 ug/m3.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-02-07 10:47:00
Record Upd:	2019-02-07 10:47:00
Updated By:	GWBURKE
Own Op:	Owner
Sub Type:	P03
Owner Name:	Shimon Schwartz
Owner Company:	480 Flushing LLC
Owner Address:	17 Keap Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library-Marcy Branch
Owner Address:	617 DeKalb Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P02
Owner Name:	Shimon Schwartz
Owner Company:	480 Flushing LLC
Owner Address:	17 Keap Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 3
Owner Address:	1360 Fulton Street
Owner Addr2:	Rm. 202
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
HW Code:	C224259
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224259
Waste Type:	tetrachloroethene (PCE)

FORMER TECHTRONICS SITE B (Continued) **S121933852**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224239
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2019-03-12 14:20:00
Record Updated:	2019-03-12 14:20:00
Updated By:	AGFISCHE
Crossref ID:	224259
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2019-03-12 14:19:00
Record Updated:	2019-03-12 14:19:00
Updated By:	AGFISCHE

---

506 East 1/4-1/2 0.497 mi. 2625 ft.

1-37 FORREST STREET
1-37 FORREST STREET
NEW YORK CITY, NY

NY VCP **S118943360**
N/A

Relative: Higher

Actual: 50 ft.

VCP NYC:

Project ID:	14CVCP225K
Project Name:	1-37 FORREST STREET
Project Address:	1-37 FORREST STREET
Borough:	BROOKLYN

VCP NYC:

Project ID:	14CVCP225K
File Name:	2015-03-09.RIR
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/2015-03-09.14EHAN365K.report.RIR_v2.EBC.pdf

Project ID:	14CVCP225K
File Name:	2015-03-18.RAWP_Draft
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/2015-03-18.14EHAN365K.report.Revised_RAWP_v2.EBC.pdf

Project ID:	14CVCP225K
File Name:	2015-03-18.Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/2015-03-18.14EHAN365K.doc.FS-1.pdf

Project ID:	14CVCP225K
File Name:	2015-03-18.Translated_Factsheet-1
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/FS1-Translation.pdf

Project ID:	14CVCP225K
File Name:	2015-03-18.Translated_CPS
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/CPS translation.pdf

Project ID:	14CVCP225K
File Name:	2015-05-22.Decision_Document
URL:	http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/2015-05-22.14EHAN365K.notice.Final_Decision_Doc.OER.pdf

1-37 FORREST STREET (Continued) **S118943360**

Project ID: 14CVCP225K
File Name: 2015-06-11.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/2015-06-11.14CVCP225K.doc.1-37_Forrest_Street.FactSheet-2.pdf

Project ID: 14CVCP225K
File Name: 2015-06-11.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP225K/2015-06-11.14CVCP225K.doc.1-37_Forrest_Street.Translated_FactSheet-2.pdf

---

507 NE 1/4-1/2 0.498 mi. 2628 ft.

83 BUSHWICK PLACE
83 BUSHWICK PLACE
NEW YORK CITY, NY

NY VCP **S118943357**
N/A

Relative: Higher

Actual: 23 ft.

VCP NYC:
Project ID: 14CVCP221K
Project Name: 83 BUSHWICK PLACE
Project Address: 83 BUSHWICK PLACE
Borough: BROOKLYN

VCP NYC:
Project ID: 14CVCP221K
File Name: 2014-01-21.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-01-21.14CVCP221K.RIR.pdf

Project ID: 14CVCP221K
File Name: 2014-01-21.RAWP
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-01-21.14CVCP221K.RAWP.pdf

Project ID: 14CVCP221K
File Name: 2014-02-04.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-02-04.14CVCP221K.83_Bushwick.Factsheet-1.pdf

Project ID: 14CVCP221K
File Name: 2014-01-21.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-01-21.14CVCP221K.Translated_Factsheet-1.pdf

Project ID: 14CVCP221K
File Name: 2014-01-21.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-01-21.14CVCP221K.CPS.pdf

Project ID: 14CVCP221K
File Name: 2014-02-27.Stip_List
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-02-27.14CVCP221K..83_Bushwick.StipList.pdf

Project ID: 14CVCP221K
File Name: 2014-04-02.Decision_Document

83 BUSHWICK PLACE (Continued) **S118943357**

URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-04-02.14CVCP221K.Decision_Document.pdf

Project ID: 14CVCP221K
File Name: 2014-10-30.Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-10-28.14CVCP221K.83_Bushwick_Place.Factsheet-2.pdf

Project ID: 14CVCP221K
File Name: 2014-10-30.Translated_Factsheet-2
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2014-10-28.14CVCP221K.doc.83_Bushwick_Place.Translated_FactSheet-2.pdf

Project ID: 14CVCP221K
File Name: 2016-08-15.RAR_Final
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2016_04_01.14RHAZ180K.RAR_Final.pdf

Project ID: 14CVCP221K
File Name: 2016-08-15.Notice_Of_Completion
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2016-08-08.14CVCP221K.83_Bushwick_Place.doc.Notice_Of_Completion.pdf

Project ID: 14CVCP221K
File Name: 2016-08-15.Factsheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2016-08-08.14CVCP221K.83_Bushwick_Place.doc.Factsheet-3.pdf

Project ID: 14CVCP221K
File Name: 2016-08-15.Translated_Factsheet-3
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/14CVCP221K/2016-08-09.14CVCP221K.doc.Translated_Factsheet-3.pdf

---

508 East 1/4-1/2 0.499 mi. 2633 ft.

11-23 MONTIETH STREET
11-23 MONTIETH STREET
NEW YORK CITY, NY

NY VCP **S121133137**
N/A

Relative: Higher

Actual: 37 ft.

VCP NYC:
Project ID: 17CVCP057K
Project Name: 11-23 MONTIETH STREET
Project Address: 11-23 MONTIETH STREET
Borough: BROOKLYN

VCP NYC:
Project ID: 17CVCP057K
File Name: 2016-09-14.RIR
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP057K/2016-09-14.16TMP0410K.RIR Phase II Report.Rev1_RIR v2 PDF_ALC Environmental.pdf

Project ID: 17CVCP057K
File Name: 2017-03-01.RAWP_Draft
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/1

11-23 MONTIETH STREET (Continued) **S121133137**

7CVCP057K/2017-03-01.16TMP0410K.RAPRAWP.Rev1_RAWP v2 ALC Environmental.pdf

Project ID: 17CVCP057K
File Name: 2017-07-14.Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP057K/2017-07-13.17CVCP057K.doc.11-23 Montieth Street.Factsheet_1.pdf

Project ID: 17CVCP057K
File Name: 2017-07-14.Translated_Factsheet-1
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP057K/2017-07-13.17CVCP057K.doc.11-23 Montieth Street.Translated_Factsheet-1.pdf

Project ID: 17CVCP057K
File Name: 2017-07-14.Translated_CPS
URL: http://www.nyc.gov/html/oer/downloads/pdf/repository/NYCBCP_Brooklyn/17CVCP057K/2017-07-14.16TMP0410K.11-23_Montieth_St.Translated_CPS.OER.pdf

---

509 ESE 1/4-1/2 0.499 mi. 2637 ft. **WEST BUSHWICK HOUSING** **NY LTANKS** **S104790729**
86-88 BEAVER ST **N/A**
BROOKLYN, NY

Relative: Higher
Actual: 61 ft.

LTANKS:

Name:	WEST BUSHWICK HOUSING
Address:	86-88 BEAVER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0008389 / 2004-06-09
Facility ID:	0008389
Site ID:	143808
Spill Date:	2000-10-18
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-10-18
CID:	270
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-18
Spill Record Last Update:	2004-06-09
Spiller Name:	WALTER ROBERTS
Spiller Company:	BUSHWICK HOUSING
Spiller Address:	86-88 BEAVER ST
Spiller County:	001

WEST BUSHWICK HOUSING (Continued) **S104790729**

Spiller Contact:	WALTER ROBERTS
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	122613
DEC Memo:	""
Remarks:	"contaminated soil discovered from samples taken"

All Materials:

Site ID:	143808
Operable Unit ID:	830849
Operable Unit:	01
Material ID:	545898
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AW510 **FORMER TECHTRONICS ECOLOGICAL CORP.** **NY SHWS** **S120706231**
WSW **8 WALWORTH STREET** **N/A**
1/2-1 **BROOKLYN, NY 11205**
0.505 mi.
2666 ft. **Site 2 of 4 in cluster AW**

Relative:
Higher

Actual:
15 ft.

SHWS:

Name:	FORMER TECHTRONICS ECOLOGICAL CORP.
Address:	8 WALWORTH STREET
City,State,Zip:	BROOKLYN, NY 11205
Program:	HW
Site Code:	529340
Classification:	N
Region:	2
Acres:	0.09
HW Code:	224239
Record Add:	06/23/2016
Record Upd:	03/29/2018
Updated By:	BXANDERS

Site Description: Location: The site is located on the west side of Walworth Street in Brooklyn between Flushing Avenue and Park Avenue. The site is bounded to the north, south and west by single story commercial buildings, and to the east by Walworth Street. Site Features: Currently, the site has one-story used as a synagogue and a shipping facility. Current Zoning/Use(s): The site is located in an M1-2 (light manufacturing) zoning district. The surrounding area consists of a mix of light manufacturing, commercial and residential uses. Historical Use(s): The site was utilized in the past by a paint and lacquer manufacturing company (Techtronics Ecological Corporation) from 1962 to the 1990s. During the period from 1981 to 1993 the site was a large quantity generator of hazardous waste under EPA ID no. NYD000824334. Wastes formerly generated at the site include ignitable waste, corrosive waste, spent halogenated solvents (i.e. tetrachloroethene), spent non-halogenated solvents (i.e. xylene) and lead. Site Geology and Hydrogeology: Fill material was identified to

FORMER TECHTRONICS ECOLOGICAL CORP. (Continued) **S120706231**

	a depth of five to seven feet below grade, and native soil thereafter. Groundwater was found at 10 feet below grade. Regional groundwater flow direction in the vicinity of the site is to the west towards the East River.
Env Problem:	Nature and Extent of Contamination: The chlorinated solvent compounds tetracholoethylene (PCE) and its breakdown products trichloroethene (TCE) and cis-1,2-dichloroethene (cis-1,2-DCE), as well as other volatile organic compounds (VOCs) were detected in soil and groundwater samples during investigation in December 2007. Soil Chlorinated solvents were detected in one soil sample collected from above the water table at concentrations exceeding unrestricted use soil cleanup objectives: PCE (4.3 parts per million, or ppm) and TCE (0.87 ppm). Groundwater Chlorinated solvents were detected in all four groundwater samples collected at the site: PCE ranges from 17 to 30,845 parts per billion, or ppb; TCE ranges from 31 to 48,675 ppb; and cis-1,2-DCE ranges from 7 to 164,000 ppb. Non-chlorinated VOCs were detected in one groundwater sample (MW-2): toluene (75,488 ppb), ethylbenzene (4,393 ppb) and xylene (17,405 ppb). Significant Threat: A significant threat determination will be made following completion of a site characterization.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Fishel Miller
Owner Company:	TOLDOS YEHUDAH, LLC
Owner Address:	182 Nostrand Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AW511 **TOLDOS YEHUDAH LLC** **CORRACTS** **1000244308**
WSW **8 WALWORTH ST** **RCRA-LQG** **NYD000824334**
1/2-1 **BROOKLYN, NY 11205** **NY BROWNFIELDS**
0.505 mi. **NY MANIFEST**
2666 ft. **Site 3 of 4 in cluster AW**

Relative:
Higher

Actual:
15 ft.

CORRACTS:

EPA ID:	NYD000824334
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19940802
Action:	CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority
NAICS Code(s):	813110 Religious Organizations
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	NYD000824334
EPA Region:	02
Area Name:	SITEWIDE
Actual Date:	19851122
Action:	CA050 - RFA Completed
NAICS Code(s):	813110 Religious Organizations
Original schedule date:	Not reported
Schedule end date:	Not reported

RCRA-LQG:

Date form received by agency:	08/22/2018
Facility name:	TOLDOS YEHUDAH LLC
Facility address:	8 WALWORTH ST BROOKLYN, NY 11205
EPA ID:	NYD000824334
Mailing address:	LEE AVE #323 BROOKLYN, NY 11211
Contact:	PHILLIP MILLER
Contact address:	FLUSHING AVE BROOKLYN, NY 11205
Contact country:	US
Contact telephone:	718-484-0061
Contact email:	REALTY9099@GMAIL.COM
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Owner/Operator Summary:

Owner/operator name:	TOLDOS YEHUDA LLC
Owner/operator address:	WALWORTH ST NEW YORK, NY 11205
Owner/operator country:	US
Owner/operator telephone:	718-484-0061
Owner/operator email:	REALTY9099@GMAIL.COM
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/17/2012
Owner/Op end date:	Not reported

Owner/operator name:	TOLDOS YEHUDA LLC
Owner/operator address:	WALWORTH ST NEW YORK, NY 11205
Owner/operator country:	US
Owner/operator telephone:	718-484-0061
Owner/operator email:	REALTY9099@GMAIL.COM
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/17/2012
Owner/Op end date:	Not reported

Owner/operator name:	TECHTRONICS ECOLOGICAL CORP
Owner/operator address:	501 FLUSHING AVE OPERCITY, NY 99999
Owner/operator country:	Not reported
Owner/operator telephone:	212-624-5240
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	TWELVE WALWORTH STREET CORP
Owner/operator address:	501 FLUSHING AVE BROOKLYN, NY 11205
Owner/operator country:	Not reported
Owner/operator telephone:	212-624-5240
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2007
Site name: TECHTRONICS ECOLOGICAL CORP
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: TECHTRONICS ECOLOGICAL CORP
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: TECHTRONICS ECOLOGICAL CORP
Classification: Not a generator, verified

Date form received by agency: 11/19/1980
Site name: TECHTRONICS ECOLOGICAL CORP
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: TECHTRONICS ECOLOGICAL CORP
Classification: Large Quantity Generator

Hazardous Waste Summary:

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE

TOLDOS YEHUDAH LLC (Continued) **1000244308**

USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Corrective Action Summary:
Event date: 11/22/1985
Event: RFA COMPLETED

Event date: 08/02/1994
Event: CA PRIORITIZATION-MEDIUM CA PRIORITY

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 12/13/1988
Date achieved compliance: 06/06/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/01/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 03/30/1988
Date achieved compliance: 04/30/1988
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 01/15/1987
Date achieved compliance: 01/17/1987
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/15/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 08/28/1986
Date achieved compliance: 04/30/1988
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/11/1986
Date achieved compliance: 04/30/1988
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/11/1986
Date achieved compliance: 08/28/1986
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 09/16/1985
Date achieved compliance: 07/16/1986
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 04/24/1986
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 875
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 09/16/1985
Date achieved compliance: 07/16/1986
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/16/1985
Date achieved compliance: 01/17/1987
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 05/16/1985
Date achieved compliance: 07/16/1986
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 02/21/1985
Date achieved compliance: 06/06/1990
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 05/01/1984
Date achieved compliance: 06/08/1984
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/11/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 03/31/1984
Date achieved compliance: 10/04/1985
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/20/1985
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Permits - Application
Date violation determined: 03/09/1984
Date achieved compliance: 11/21/1984
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/20/1984
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 12/13/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/06/1990
Evaluation lead agency: State

Evaluation date: 03/30/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 04/30/1988
Evaluation lead agency: EPA

Evaluation date: 05/27/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/13/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/13/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

Evaluation date: 01/15/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 01/17/1987
Evaluation lead agency: State

Evaluation date: 01/06/1987
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/28/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Permits - Application
Date achieved compliance: 04/30/1988
Evaluation lead agency: State

Evaluation date: 08/28/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA-Initiated Oversight/Observation/Training Actions

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Evaluation date: 03/11/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/28/1986
Evaluation lead agency: EPA

Evaluation date: 03/11/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/30/1988
Evaluation lead agency: State

Evaluation date: 09/16/1985
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - Manifest
Date achieved compliance: 07/16/1986
Evaluation lead agency: State

Evaluation date: 05/16/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 01/17/1987
Evaluation lead agency: EPA

Evaluation date: 05/16/1985
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 07/16/1986
Evaluation lead agency: EPA

Evaluation date: 02/21/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/06/1990
Evaluation lead agency: EPA

Evaluation date: 02/21/1985
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/01/1984
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 06/08/1984
Evaluation lead agency: EPA

Evaluation date: 03/31/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 10/04/1985
Evaluation lead agency: State

Evaluation date: 03/09/1984
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Permits - Application

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Date achieved compliance: 11/21/1984
Evaluation lead agency: State

BROWNFIELDS:

Name:	8 WALWORTH
Address:	8 WALWORTH STREET
City,State,Zip:	BROOKLYN, NY 11205
Program:	BCP
Site Code:	552969
Acres:	0.089
HW Code:	C224239
SWIS:	2401
Town:	New York City
Record Added Date:	06/21/2017
Record Updated Date:	05/09/2018
Update By:	SXDEWES
Site Description:	Location The Site is located in the Bedford Stuyvesant section of Kings County and is comprised of a single tax parcel totaling 3,910 square feet (0.089 acres). The Site is located in the City of New York and Borough of Brooklyn. The Site is rectangular shaped with 78 feet of frontage along Walworth Street. The north, south and west sides of the property are bordered by warehouses and commercial / industrial buildings. Site Features The Site is improved with a 3,910 sf, 1- story masonry building constructed in 1982 (estimate). The building is divided into two sections each with its own access to the outside; the north section which was recently used as warehouse space and the south section which was used by an orthodox congregation for a prayer room. Current Zoning and Land Use Compliance with Current Zoning The property is currently zoned M1-2. M1 districts are often buffers between M2 or M3 districts and adjacent residential or commercial districts. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale service and storage facilities. Nearly all industrial uses are allowed in M1 districts if they meet the stringent M1 performance standards. Offices, hotels and most retail uses are also permitted. Certain community facilities, such as hospitals, are allowed in M1 districts only by special permit, but houses of worship are allowed as-of-right. The proposed project, which includes an office building, is compatible with the surrounding land use and will be in compliance with the current zoning. Compliance with Land Use Plans On May 9, 2001, the City Council approved the Flushing - Bedford rezoning action (CEQR No. 00DCP015K) covering 15 blocks in the Flushing Avenue and Bedford Avenue area of Community Districts 1 and 3 in the Bedford Stuyvesant neighborhood of Brooklyn. According to the Notice of Completion of The Final Environmental Impact Statement issued on March 16, 2001 by the NYC Planning Commission: "The Flushing Bedford area, although zoned for manufacturing uses, contains a mix of residential uses, vacant land, open uses, auto-related uses, and commercial and industrial buildings. The rezoning area has experienced a significant decline in industrial activity over the last four decades resulting in an increase in auto related uses, junk yards and vacant land. Study findings indicate that over the last two decades, there has been a substantial growth in the residential population in the surrounding areas, resulting in a housing shortfall and increasing demand for new dwelling 'units. Since the mid 1980's there has been a marked increase in residential development, especially in the area north of Flushing Avenue." "Although the existing manufacturing zoning does not permit as-of-right

TOLDOS YEHUDAH LLC (Continued) **1000244308**

residential development, in recent years there has been new residential development in the area north of Flushing Avenue pursuant to zoning variances granted by the Board of Standards, and Appeals (BSA). In 1996 and 1998, two rezoning applications were approved changing the designation of a three block area immediately north of the rezoning area from manufacturing to residential. The presence of vacant and underutilized land, coupled with the increasing demand for housing in the adjacent communities, presents an opportunity for new residential development in this part of Brooklyn." The objectives of the rezoning were to: -provide opportunities for new residential development on vacant and under- utilized parcels; -bring existing non-conforming residential uses into conformance, and would allow for their enlargement; -allow for the continued presence and expansion of commercial and manufacturing uses; -permit the introduction of new commercial and manufacturing uses; and, -allow the residential re-use of underutilized and vacant land. In general, the action would provide the land use controls necessary for appropriate residentialdevelopment and the continued presence of viable manufacturing uses. The proposed project will be in full compliance with the current land use plans as identified in the Flushing Bedford Rezoning Action (CEQR No. 00DCP015K) adopted by the City on May 9, 2001. Past Use of the Site The historic use of the Site includes a storefront building, garage and residence from sometime prior to 1887 to sometime before to sometime before 1965 when a two-story residence remained on the south side of the Site and a single-story warehouse used for chemical drum storage was present on the north side of the Site. By 1977, the two-story residence was no longer present and the singlestory chemical drum storage warehouse remained on the north side of the Site. By 1982 the Site was redeveloped with a single-story paint mixing warehouse. The Site and adjacent properties have remained generally unchanged through the current day. Site Geography and Geology The geologic setting of Long Island is well documented and consists of crystalline bedrock overlain by layers of unconsolidated deposits. According to geologic maps of the area created by the United States Geologic Survey (USGS), the bedrock in this area of Brooklyn is an igneous intrusive classified as the Ravenswood grano-diorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays, deposited by glacial-fluvial activity. Non-native fill materials consisting of dredge spoils, rubble and / or other materials have historically been used to reinforce and extend shoreline areas and to raise and improve the drainage of low lying areas. Subsurface soils at the Site consist of historic fill materials to a depth of approximately 4 to 6 feet below grade. Silty sand and gravel is present immediately below this layer. According to the USGS topographic map for the area (Brooklyn Quadrangle), the elevation of the property is approximately 20 feet above mean sea level. The topography within the immediate area slopes gradually from south to north. No portion of the Site is located within a designated flood zone area. The nearest moderate risk flood zone is located 800 feet to the northwest and the nearest high risk flood zone is located 950 feet to the northwest.

Env Problem: Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.

Health Problem: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised

TOLDOS YEHUDAH LLC (Continued) **1000244308**

	as additional information becomes available.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-10-20 12:52:00
Record Upd:	2017-10-20 12:52:00
Updated By:	GWBURKE
Own Op:	Owner
Sub Type:	P02
Owner Name:	Fischel Miller
Owner Company:	Taldos Yehudah, LLC
Owner Address:	209 Harrison Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P02
Owner Name:	Fischel Miller
Owner Company:	Toldos Yehudah, LLC
Owner Address:	209 Harrison Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 3
Owner Address:	1360 Fulton Street, Room 202
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

TOLDOS YEHUDAH LLC (Continued) **1000244308**

NY MANIFEST:

Name:	TECHTRONICS ECOLOGICAL
Address:	8 WALWORTH ST
City,State,Zip:	NEW YORK, NY 11205
Country:	USA
EPA ID:	NYD000824334
Facility Status:	Not reported
Location Address 1:	501 FLUSHING AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11205
Location Zip 4:	1610

NY MANIFEST:

EPAID:	NYD000824334
Mailing Name:	TECHTRONICS ECOLOGICAL
Mailing Contact:	CARL LING-GENERAL MANAGER
Mailing Address 1:	501 FLUSHING AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11205
Mailing Zip 4:	1610
Mailing Country:	USA
Mailing Phone:	7185223838

NY MANIFEST:

Document ID:	NYB4212414
Manifest Status:	C
seq:	Not reported
Year:	1993
Trans1 State ID:	PD1011
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/1993
Trans1 Recv Date:	05/06/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/07/1993
Part A Recv Date:	05/20/1993
Part B Recv Date:	05/25/1993
Generator EPA ID:	NYD000824334
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

TOLDOS YEHUDAH LLC (Continued) **1000244308**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	02400
Units:	P - Pounds
Number of Containers:	008
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00793
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	013
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AW512 **SPENCER STREET GW** **NY SHWS** **S121102086**
WSW **INTERSECTION OF SPENCER STREET AND FLUSHING AVENUE** **N/A**
1/2-1 **BROOKLYN, NY 11205**
0.530 mi.
2796 ft. **Site 4 of 4 in cluster AW**

Relative: **Lower**
Actual: **13 ft.**

SHWS:

Name:	SPENCER STREET GW
Address:	INTERSECTION OF SPENCER STREET AND FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11205
Program:	HW
Site Code:	537811
Classification:	P
Region:	2
Acres:	Not reported
HW Code:	224251
Record Add:	12/27/2016

SPENCER STREET GW (Continued) **S121102086**

Record Upd:	08/01/2017
Updated By:	SXDEWES
Site Description:	At this time, no other site-specific information is available. The project was generated based on information collected on the public sidewalk of Spencer Street between Flushing Avenue and Park Avenue. More information will be provided as it becomes available.
Env Problem:	To date, only one groundwater sample has been collected as part of the environmental investigation. A site characterization will be conducted in 2017. Groundwater: The site is contaminated with chlorinated volatile organic compounds (VOCs). Tetrachloroethene (PCE) was detected at 120,000 parts per billion or ppb (compared to a groundwater standard of 5 ppb), trichloroethene was detected at 38,000 ppb (compared to a groundwater standard of 5 ppb) and 1,1,1-trichloroethane was detected at 86,000 ppb (compared to a groundwater standard of 5 ppb). Soil, groundwater and soil vapor samples will be collected as part of the site characterization.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AX513 **K - SKILLMAN ST. STATION** **NY SHWS** **S109321184**
WSW **7 SKILLMAN STREET** **NY BROWNFIELDS** **N/A**
1/2-1 **BROOKLYN, NY 11205**
0.627 mi.
3309 ft. **Site 1 of 2 in cluster AX**

Relative:
Higher

Actual:
19 ft.

SHWS:
Name: K - SKILLMAN ST. STATION
Address: 7 SKILLMAN STREET
City,State,Zip: BROOKLYN, NY 11205
Program: HW
Site Code: 379003
Classification: A
Region: 2
Acres: 0.54
HW Code: 224068
Record Add: 03/27/2007
Record Upd: 04/26/2018
Updated By: GWHEITZM
Site Description: Location: The Skillman Street Holder Station is located in an urban area, at 7 Skillman Street, Brooklyn, NY. Site Features: The 7 Skillman Street parcel is completely covered by a two-story building. This building is used as a banquet/catering hall. Current Zoning/Use: The property is currently in active use as a banquet hall, and is zoned for mixed use, which includes residential, commercial, and light industrial uses. The surrounding parcels are currently used for a combination of commercial and residential purposes. The nearest residential building is approximately 150 feet to the southwest. Past Use of the Site: Two manufactured gas storage holders were constructed at the site between 1887 and 1904. These holders were operated solely as gas distribution holders, and no gas production facilities were present. At some point prior to 1935, gas storage operations ceased and the holders were demolished. The site remained under the ownership of the Brooklyn Union Gas Company until sometime prior to 1947. Upon being sold the property was used for automobile parking and storage. By 1950, the site was used as an automobile repair facility which remained until at least 1993. In 2003, the existing building was developed into a catering hall, which is presently in operation. Site Geology and Hydrogeology: The site is underlain by fill material, alluvial sands, glacial outwash and bedrock at depth. Groundwater is typically found at approximately 7 to 16 feet below ground surface (bgs), and flows generally to the west-northwest.
Env Problem: Based upon investigations conducted to date, the primary contaminants of concern are the volatile organic compounds (VOCs) benzene, toluene, ethylbenzene and xylene (together known as BTEX), and styrene; polycyclic aromatic hydrocarbons (PAHs); and metals. Soil- The subsurface soil exceedances for on-site VOCs (BTEX) were slightly above unrestricted soil cleanup objectives (USCOs), though no samples exceed the restricted residential SCOs. However sampling of soil beneath the site was limited due to the inability to access much of the property with a drill rig, and a source area of higher contaminant concentrations may be present beneath the buildings. Adjacent to the site, in a sample collected beneath Skillman Street at a depth of approximately 27 feet where evidence of coal tar was observed, the concentration of toluene was 160 ppm, ethylbenzene was 220 ppm, and xylenes were 840 ppm in subsurface soil. Styrene was also detected at this location at a concentration of 400 ppm. There were no detections of chlorinated solvents or total cyanide in soil

K - SKILLMAN ST. STATION (Continued) **S109321184**

above unrestricted SCOs either on or off-site. The PAH exceedances above unrestricted SCOs consisted of benzo(b)fluoranthene, benz(a)anthracene, benzo(a)pyrene, chrysene, indeno(1,2,3-cd)pyrene, and naphthalene. Adjacent to the site the concentration of naphthalene was 1000 ppm (at 27 feet below ground surface). The only inorganics to exceed unrestricted SCOs were lead and mercury, although neither exceeded the restricted residential SCOs in soil. Groundwater - Samples collected from monitoring wells located both on-site (temporary sampling points) and off-site exceeded groundwater quality standards (GWQS) for benzene, toluene, ethylbenzene, xylenes (BTEX) compounds, naphthalene, chlorinated VOCs, cyanide, and metals. On-site, benzene ranged from 13 to 5,600 ppb (GWQS of 1 ppb), toluene at 20,000 ppb (GWQS of 5 ppb), ethylbenzene at 12,000 ppb (GWQS of 5 ppb), xylenes at 9,400 ppb (GWQS of 5 ppb), isopropyl benzene at 420 ppb (GWQS of 5 ppb), styrene at 82 ppb (GWQS of 5 ppb), cis-1,2-dichloroethene at 9.2 ppb (GWQS of 5 ppb), naphthalene at 5,600 ppb (GWQS of 10 ppb), total cyanide at 240 ppb (GWQS of 200 ppb), chromium at 380 ppb (GWQS of 50 ppb), and lead at 280 ppb (GWQS of 25 ppb). Elevated BTEX and napthalene also indicate the possible presence of MGP-related contaminants in the subsurface beneath the building. Off-site, detections of benzene range from 100 ppb to 410 ppb; toluene from 79 ppb to 1,100 ppb; ethylbenzene from 32 ppb to 930 ppb; xylenes from 100 ppb to 3,900 ppb; tetrachloroethene (PCE) from 5.6 to 9,400 ppb; trichloroethene (TCE) from 140 to 1,900 ppb; vinyl chloride from 200 to 380 ppb; cis-1,2-dichloroethene from 600 ppb to 8,000 ppb; isopropyl benzene from 64 ppb to 420 ppb; styrene from 82 ppb to 1,800 ppb; and naphthalene from 62 ppb to 5,600 ppb. There were also eight inorganic compounds that exceeded the groundwater standards in both on-site and off-site wells. These compounds were copper, iron, magnesium, manganese, nickel, selenium, sodium, and thallium, all of which are not associated with the former MGP operations. Soil Vapor - Soil vapor samples collected from the site contained elevated levels of both MGP-related and non-MGP-related compounds. The MGP-related detections included benzene at 35 ug/m3; toluene at 96 ug/m3; ethylbenzene at 12 ug/m3; xylenes at 40 ug/m3; 1,2,4-trimethylbenzene at 12 ug/m3; and nonane at 8.4 ug/m3. The non-MGP constituents included PCE at 12,000 ug/m3, TCE at 1,200 ug/m3, and cis-1,2-dichloroethene at 1,500 ug/m3. Indoor Air - The contaminants present in soil vapor at elevated levels were detected at much lower concentrations in indoor air. The highest concentration of the BTEX compounds was toluene at 6.3 ug/m3. PCE was detected at a concentration of 0.66 ug/m3; TCE at 0.21 ug/m3; and ethanol at 450 ug/m3. The ethanol concentrations in indoor air were approximately an order of magnitude larger than the soil vapor concentrations, indicating the source to be within the building. No indoor air guidance values were exceeded for any compound. The owners of the affected property have been notified where mitigation or monitoring of impacts to indoor air is required. An Interim Site Management Plan (ISMP) is in place that governs soil disturbance and the required groundwater monitoring.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered with buildings and pavement. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move in to the soil vapor (air spaces within the soil), which in turn may move into overlying

K - SKILLMAN ST. STATION (Continued) **S109321184**

buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Mitigation has been recommended to address the potential for people to inhale contaminants in indoor air of the onsite building due to soil vapor intrusion. Environmental sampling indicates that soil vapor intrusion is a concern for off-site buildings which are occupied.

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-03-06 13:37:00
Record Upd:	2013-09-20 14:17:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	C05
Owner Name:	HENRY BUTLER
Owner Company:	BROOKLYN COMMUNITY BOARD 3
Owner Address:	1360 FULTON STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11216
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library
Owner Address:	Williamsburg Branch
Owner Addr2:	240 Division at Marcy Street
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	224068
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	STYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068

K - SKILLMAN ST. STATION (Continued) **S109321184**

Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	Isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224068
Waste Type:	BENZO(A)ANTHRACENE

K - SKILLMAN ST. STATION (Continued) **S109321184**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: 1,2-DICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: trans-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224068
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224156
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2011-11-17 09:19:00
Record Updated: 2011-11-17 09:19:00
Updated By: BXANDERS

BROWNFIELDS:
Name: K - SKILLMAN ST. STATION
Address: SKILLMAN ST. FLUSHING & BEDFORD AVES.,& PARK ST
City,State,Zip: BROOKLYN, NY 11205
Program: BCP
Site Code: 57409
Acres: 0.7
HW Code: C224068
SWIS: 2401
Town: New York City
Record Added Date: 05/19/2004
Record Updated Date: 12/07/2009
Update By: MOBARRIE
Site Description: See Site 224068
Env Problem: Not reported
Health Problem: Not reported

K - SKILLMAN ST. STATION (Continued) **S109321184**

Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AX514 **SKILLMAN STATION** **EDR MGP** **1008407900**
WSW **SKILLMAN ST. FLUSHING AND BEDFORD AVES., AND PARK ST** **N/A**
1/2-1 **BROOKLYN, NY 11205**
0.628 mi.
3318 ft. **Site 2 of 2 in cluster AX**

Relative: Manufactured Gas Plants:
Higher No additional information available

Actual:
18 ft.

---

515 **NASSAU GAS** **EDR MGP** **1008407895**
WSW **SKILLMAN AVE** **N/A**
1/2-1 **BROOKLYN, NY 11205**
0.645 mi.
3408 ft.

Relative: Manufactured Gas Plants:
Higher No additional information available

Actual:
25 ft.

516
WSW
1/2-1
0.680 mi.
3592 ft.

KOLLMORGAN OPTICAL
NO CITY, NY

FUDS **1024899324**
N/A

Relative:
Higher

Actual:
16 ft.

FUDS:

EPA Region:	2
Installation ID:	NY29799F890500
Congressional District Number:	7
Facility Name:	KOLLMORGAN OPTICAL
FUDS Number:	C02NY1020
City:	NO CITY
State:	NY
County:	Not reported
Telephone:	978-318-8238
USACE Division:	North Atlantic Division (NAD)
USACE District:	New England District (NAE)
Status:	Properties without projects
Current Owner:	Private Sector
X Coord:	-73.958888889709797
Y Coord:	40.6986111101155
Latitude:	40.698611110000002
Longitude:	-73.958888889999997

517
ENE
1/2-1
0.728 mi.
3845 ft.

2 INGRAHAM STREET
2 INGRAHAM ST
EAST WILLIAMSBURG, NY 11206

NY SHWS **S110487597**
NY VCP **N/A**
NY BROWNFIELDS

Relative:
Higher

Actual:
19 ft.

SHWS:

Name:	FORMER JAYER PLATING
Address:	2 INGRAHAM ST
City,State,Zip:	EAST WILLIAMSBURG, NY 11206
Program:	HW
Site Code:	57074
Classification:	N
Region:	2
Acres:	0.5
HW Code:	224036
Record Add:	02/21/2002
Record Upd:	02/28/2018
Updated By:	JEBROWN

Site Description: Site being handled under BCP - C224036 Location: The Former Jayer Plating site is located at 2 Ingraham Street in the East Williamsburg Area of Brooklyn, New York. Site Features: The site is a 0.5 acre warehouse and is bordered on the south by Harrison Place, on the north by Ingraham Street, on the west by Bogart Street, and on the east by Morgan Avenue. The site is affected by an easement for the New York City Water Tunnel No. 3. Current Zoning and Land Use: The current zoning of the property is M1-2 (light manufacturing), and it is currently vacant. The surrounding land use is mainly manufacturing (M-1 and M-2) with residential (R-6) farther east and west of the site. The businesses in the immediate area include warehouses, auto scrap yards, masonry materials sales, waste management and trucking. The neighborhood surrounding the site includes some residential units interspersed with commercial properties. A New York City Transit Authority subway line is located beneath Harrison Place, and there are rail yards nearby which are connected to the Long Island Railroad

2 INGRAHAM STREET (Continued) **S110487597**

Bushwick Branch. Past Use of the Site: Prior 1946 the Site was used as an orphanage. In 1948, the site was occupied by an umbrella manufacturing plant and a metal plating company between 1946 and early 1990's. After the 1990's, the site has been used as a warehouse without major changes. The site structure has been unoccupied since April 2016. Site Geology and Hydrogeology: The site is underlain by 0 to 8 feet of fill. The fill consists predominantly of silty sands with gravel, bricks, rock fragments, concrete, and coal cinders. Native soils beneath the fill layer consist of medium to fine sand and silt and continues with slight variations up to 35 feet below ground surface (bgs). Clay was encountered at several boring locations at depths greater than 6 feet bgs. The depth to groundwater is approximately 15 feet below grade. The regional groundwater flow direction is roughly south to north, towards the English Kills.

Env Problem:	This site is now in the BCP as 2 Ingraham Street site (C224036). Project was reclassed to N.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	C05
Owner Name:	Gerald A. Esposito
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	01
Owner Name:	Joe Brunner
Owner Company:	Bogart Holdings LLC
Owner Address:	390 Berry Street, Suite 200
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Loren Williams
Owner Company:	Brooklyn Public Library, Central Branch
Owner Address:	10 Grand Army Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported

2 INGRAHAM STREET (Continued) **S110487597**

Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

VCP:
Name: 2 INGRAHAM STREET
Address: 2 INGRAHAM STREET
City,State,Zip: BROOKLYN, NY 11206
Program Type: VCP
Site Code: 56868
HW Code: V00184
Site Class: N
SWIS: 2401
Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 06/16/2009
Updated By: IXMUNTEA
Site Description: 2 Ingraham Street, site represents the Block 3084, Lot 1, in the Williamsburg Area of Brooklyn, NY 11206. The site is a 0.5 acre warehouse. The property is bordered by Ingraham Street to the north, by Marrisson Place to the south, by Bogart Street to the west and by Morgan Avenue to the east. The current use of the site is commercial. Before 1998, the building was used for cloth manufacturing and one of its section was used as a plating factory (Former Jayer Plating Co.). In spring 1998, the warehouse was vacant. The neighbourhood was mixed industrial, residential, and commercial. In the western section of the warehouse, where the plating factory has operated a deep corroded dry drain was noticed. In this area the concrete floor was also broken and corroded, perhaps due to waste bath residues of the metal plating processes on the floor. The VCP investigation was not compleated and the Volunteer Cleanup Agreement negotiations have been closed . See project C224036
Env Problem: Not reported
Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Applicant/Requestor
Sub Type: ZZZ
Owner Name: CARL SAVRYN
Owner Company: Milhan Realty Corporation
Owner Address: 2 INGRAHAM ST.
Owner Addr2: Not reported

2 INGRAHAM STREET (Continued) **S110487597**

Owner City,St,Zip:	BROOKLYN, NY 11206
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BROWNFIELDS:

Name:	2 INGRAHAM STREET
Address:	2 INGRAHAM ST
City,State,Zip:	EAST WILLIAMSBURG, NY 11206
Program:	BCP
Site Code:	435675
Acres:	1.8
HW Code:	C224036
SWIS:	2401
Town:	New York City
Record Added Date:	06/04/2010
Record Updated Date:	01/14/2019
Update By:	GWBURKE
Site Description:	Location: The 2 Ingraham Street site is located at 2 Ingraham Street in the East Williamsburg Area of Brooklyn, New York. Site Features: The site is a 0.5 acre warehouse and is bordered on the south by Harrison Place, on the north by Ingraham Street, on the west by Bogart Street, and on the east by Morgan Avenue. The site is affected by an easement for the New York City Water Tunnel No. 3. Current Zoning and Land Use: The current zoning of the property is M1-2 (light manufacturing), and it is currently vacant. The surrounding land use is mainly manufacturing (M-1 and M-2) with residential (R-6) farther east and west of the site. The businesses in the immediate area include warehouses, auto scrap yards, masonry materials sales, waste management and trucking. The neighborhood surrounding the site includes some residential units interspersed with commercial properties. A New York City Transit Authority subway line is located beneath Harrison Place, and there are rail yards nearby which are connected to the Long Island Railroad Bushwick Branch. Past Use of the Site: Prior 1946 the Site was used as an orphanage. In 1948, the site was occupied by an umbrella manufacturing plant and a metal plating company between 1946 and early 1990's. After the 1990's, the site has been used as a warehouse without major changes. The site structure has been unoccupied since April 2016. Site Geology and Hydrogeology: The site is underlain by 0 to 8 feet of fill. The fill consists predominantly of silty sands with gravel, bricks, rock fragments, concrete, and coal cinders. Native soils beneath the fill layer consist of medium to fine sand and silt and continues with slight variations up to 35 feet below ground surface (bgs). Clay was encountered at several boring locations at depths greater than 6 feet bgs. The depth to groundwater is approximately 15 feet below grade. The regional groundwater flow direction is roughly south to north, towards the English Kills.
Env Problem:	Nature and Extent of Contamination: Soil and groundwater were

2 INGRAHAM STREET (Continued) **S110487597**

analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. The primary contaminants of concern at the site include metals, SVOCs, and VOCs. Environmental investigation in the area revealed concentrations of metals, SVOCs, and VOCs exceeding Standards, Criteria, and Guidance values (SCGs) in the soil and/or groundwater. Soil: Based upon investigations to date, sub-surface soils are contaminated with metals, SVOCS, and VOCs. Results from soils sampling reported metals (chromium, lead, mercury, and nickel), SVOCs (polyaromatic hydrocarbons or PAHs), and VOCs(tetrachloroethene or PCE). The PAHs contamination in soils is likely related to the presence of historic fill. Maximum detections vs. applicable unrestricted use or protection of groundwater soil cleanup objectives (UUSCO/PGWSCO) are as follows: chromium at 8,400 ppm vs. 19 ppm, lead at 607 ppm vs. 63 ppm, mercury at 1,790 ppm vs. 0.73 ppm, nickel at 3,720 ppm vs. 130 ppm, several PAHs including benzo(a)pyrene at 16 ppm vs. 1 ppm, and PCE at 1.9 ppm vs. 0.47 ppm. Mercury and nickel (up to 18.2 ppm, and 433 ppm, respectively) were detected off-site at soil boring SSB7N. Lead (up to 106 ppm) was detected off-site at soil boring SB8. Groundwater: Groundwater sampling indicates metals and VOCs contamination above Class GA groundwater standards. Some metals were found in relative low levels in groundwater and are likely related to the presence of historic fill. Maximum groundwater detections vs. standards are as follows: chromium at 110,000 parts per billion (ppb) vs. 50 ppb, lead at 461 ppb vs. 25 ppb, and nickel at 90,900 ppb vs. 100 ppb. PCE (up to 17 ppb) and mercury (up to 3.3 ppb) were detected in off-site downgradient groundwater at MW-7. Chromium, lead, and nickel (up to 10,800 ppb, 802 ppb, and 8,690 ppb, respectively) were detected off-site in down-gradient groundwater at MW-8. Trichloroethene up to 140 ppb was detected off-site in groundwater at MW-6. Soil Vapor: Elevated levels of VOCs were detected in sub-slab soil vapor. The maximum concentrations of PCE and 1,1,1-Trichloroethane in sub-slab soil vapor were detected in the northwestern/northeastern portion of the site at the respective concentrations of 827 micrograms per cubic meter (ug/m3) and 1,220 ug/m3. In addition, soil vapor intrusion (SVI) levels for methylene chloride (e.g., 42 ug/m3 [below the slab] and 20.5 ug/m3 [indoor air]) require additional assessment, investigation or mitigation in accordance with NYSDOH SVI matrices. Therefore, additional sampling is needed to determine whether actions are needed to address soil vapor intrusion on- and off-site. Significant Threat: Recent public events held at the site and past unapproved activities are likely to increase the risk of direct contact with the contamination visually observed on the surface of the slab and/or slab areas with broken concrete in which the upper soils likely contain hazardous waste levels of contamination. Contravention of SCOs for metals pose a significant threat to human health due to accessibility. Also, metals contamination in soil at the source area exceeds respective industrial and/or protection of groundwater SCOs. This has resulted in contamination of shallow groundwater at levels several orders of magnitude above standards, creating a significant threat to the environment.

Health Problem: Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. People may come into contact with contaminants in soils if they dig below the surface or contact exposed soil. Volatile organic compounds

2 INGRAHAM STREET (Continued) **S110487597**

in soil vapor (air spaces within the soil) may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern. The potential exists for the inhalation of site contaminants due to soil vapor intrusion in the event the site is re-occupied and for any future buildings developed on the site. Additional evaluation is needed to determine whether actions are needed to address soil vapor intrusion off-site.

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-09-20 13:57:00
Record Upd:	2016-09-28 14:18:00
Updated By:	JXPEREZM
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Loren Williams
Owner Company:	Brooklyn Public Library, Central Branch
Owner Address:	10 Grand Army Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	06
Owner Name:	Joe Brunner
Owner Company:	Bogart Holdings LLC
Owner Address:	390 Berry Street, Suite 200
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Joseph Brunner
Owner Company:	Bogart Holdings LLC
Owner Address:	390 Berry Street, Suite 200
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Gerald A. Esposito
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported

2 INGRAHAM STREET (Continued) **S110487597**

Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	224036
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2018-02-28 08:41:00
Record Updated:	2018-02-28 08:41:00
Updated By:	JEBROWN
Crossref ID:	V00184
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2018-02-28 08:39:00
Record Updated:	2018-02-28 08:39:00
Updated By:	JEBROWN
Crossref ID:	9830001
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-03-30 11:11:00
Record Updated:	2016-03-30 11:11:00
Updated By:	JXPEREZM

Name:	2 INGRAHAM STREET - OFF-SITE
Address:	2 INGRAHAM ST
City,State,Zip:	EAST WILLIAMSBURG, NY 11206
Program:	BCP
Site Code:	567066
Acres:	Not reported
HW Code:	C224036A
SWIS:	2401
Town:	New York City
Record Added Date:	02/22/2018
Record Updated Date:	03/25/2019
Update By:	GWBURKE
Site Description:	This project (2 Ingraham Street Off-Site, C224036A) was created to investigate for potential off-site impacts from the 2 Ingraham Street BCP Site (C224036). Location: This site is the off-site component to the 2 Ingraham Street Site located at 2 Ingraham Street in the East Williamsburg Area of Brooklyn, New York. Site Features: The BCP site is a 0.5 acre warehouse and is bordered on the south by Harrison Place, on the north by Ingraham Street, on the west by Bogart Street, and on the east by Morgan Avenue. The BCP site is affected by an easement for the New York City Water Tunnel No. 3. Current Zoning and Land Use: The current zoning of the BCP site is M1-2 (light manufacturing), and it is currently vacant. The surrounding land use is mainly manufacturing (M-1 and M-2) with residential (R-6) farther east and west of the site. The businesses in the immediate area include warehouses, auto scrap yards, masonry materials sales, waste management and trucking. The neighborhood surrounding the site includes some residential units interspersed with commercial properties. A New York City Transit Authority subway line is located beneath Harrison Place, and there are rail yards nearby which are connected to the Long Island Railroad Bushwick Branch. Past Use of the Site: Prior 1946 the BCP site was used as an orphanage. In 1948, the BCP site was occupied by an umbrella manufacturing plant and a metal plating company between 1946 and early 1990's. After the 1990's, the BCP site has been used as a warehouse without major changes. The site structure has been unoccupied since April 2016.

2 INGRAHAM STREET (Continued) **S110487597**

	Site Geology and Hydrogeology: The BCP site is underlain by 0 to 8 feet of fill. The fill consists predominantly of silty sands with gravel, bricks, rock fragments, concrete, and coal cinders. Native soils beneath the fill layer consist of medium to fine sand and silt and continues with slight variations up to 35 feet below ground surface (bgs). Clay was encountered at several boring locations at depths greater than 6 feet bgs. The depth to groundwater is approximately 15 feet below grade. The regional groundwater flow direction is roughly south to north, towards the English Kills.
Env Problem:	Nature and Extent of Contamination: The primary contaminants of concern off-site include metals, and volatile organic compounds (VOCs). Previous environmental investigation in the area revealed concentrations of metals and VOCs exceeding Standards, Criteria, and Guidance values in the soil and/or groundwater. Based upon investigations to date, shallow soils (up to 5 feet below ground surface) are contaminated with metals. Data results from soils sampling reported metals (lead, mercury and nickel). Maximum detections vs. applicable unrestricted use or protection of groundwater cleanup objectives are as follows: lead at 106 parts per million (ppm) vs. 63 ppm, mercury at 18.2 ppm vs. 0.73 ppm, and nickel at 433 ppm vs. 130 ppm. Groundwater sampling indicates metals and VOCs contamination above Class GA groundwater standards. Some metals were found in relative low levels in groundwater and are likely related to the presence of historic fill. Maximum groundwater detections vs. standards are as follows: tetrachloroethene at 17 parts per billion (ppb) vs. 5 ppb, trichloroethene at 140 ppb vs. 5 ppb, chromium at 10,800 ppb vs. 50 ppb, and nickel at 8,690 ppb vs. 100 ppb.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-03-07 12:41:00
Record Upd:	2018-03-07 12:41:00
Updated By:	JXPEREZM
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	C224036A
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	nickel

2 INGRAHAM STREET (Continued) **S110487597**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

518
WSW
1/2-1
0.767 mi.
4049 ft.

RUTLEDGE STATION **EDR MGP** **1008407898**
RUTLEDGE ST. WYTHE AND KENT AVE AND WALLABOUT AND HEYARD ST **N/A**
BROOKLYN, NY 11205

Relative:
Higher

Actual:
14 ft.

Manufactured Gas Plants:
No additional information available

519
NE
1/2-1
0.798 mi.
4216 ft.

SCHOLES ST. STATION **EDR MGP** **1008407899**
SCHOLES ST 7 BOGART STS. MESSEROLE AND MORGAN AVE. **N/A**
BROOKLYN, NY 11206

Relative:
Higher

Actual:
17 ft.

Manufactured Gas Plants:
No additional information available

520
West
1/2-1
0.851 mi.
4492 ft.

KEAP ST. STATION
KEAP ST. WYTHE AVE. HOOPER ST. AND KENT AVE
BROOKLYN, NY 11211

EDR MGP **1008407893**
N/A

Relative:
Higher

Actual:
15 ft.

Manufactured Gas Plants:
No additional information available

521
NNW
1/2-1
0.928 mi.
4901 ft.

BQE/ANSBACHER COLOR & DYE FACTORY
MEEKER AVENUE
BROOKLYN, NY

NY SHWS **S106780917**
N/A

Relative:
Higher

Actual:
15 ft.

SHWS:
Name: BQE/ANSBACHER COLOR & DYE FACTORY
Address: MEEKER AVENUE
City,State,Zip: BROOKLYN, NY
Program: HW
Site Code: 55913
Classification: Does not present a significant threat to the public health or the environment - action may be deferred.
Region: 2
Acres: 0.6
HW Code: 224016
Record Add: 11/18/1999
Record Upd: 08/31/2017
Updated By: JXGRECO
Site Description: Location: The site is located in the Williamsburg section of Brooklyn. The site is bounded by Havemeyer Street to the northwest, North 6th Street to the southwest, Macri Triangle park to the southeast, and North 8th Street to the northeast. Site Features: The site is completely covered with buildings in the northwest section; and covered with asphalt, concrete, and open park space in the southeast section. The site is bisected by an elevated portion of I-278 (the Brooklyn-Queens Expressway (BQE)) adjacent to the park. Current Zoning and Land Use(s): The site is zoned for residential, manufacturing, and commercial uses. The residential area is in the northwest section of the site. The manufacturing building along Meeker Avenue is unoccupied. Past Use of the Site: According to Sanborn maps, the former Ansbacher Color and Dye Factory (Ansbacher) occupied multiple buildings along North 6th Street, North 7th Street, and Metropolitan Avenue from ~1887 to ~1945. The assumed use of the facility was to manufacture paints and/or pigments for commercial and industrial use. In the early 1950's, the buildings in the southeastern section of the site were torn down to make room for the construction of the BQE. It is believed that during this construction, waste material and debris from the former Ansbacher plant may have been used as fill material in the project area. A Phase II - type investigation was conducted by the New York State Department of Transportation (NYSDOT) in 1988. The investigation found hazardous levels of arsenic and lead in the soil and elevated levels of arsenic, lead and cyanide in the groundwater. During the reconstruction of the BQE in the early 1990s, the NYSDOT completed an IRM (soil removal) within the project's right-of way. The remaining contaminated soil is located beneath asphalt and concrete. A Preliminary Site Assessment was completed by the New York State

BQE/ANSBACHER COLOR & DYE FACTORY (Continued) **S106780917**

Department of Environmental Conservation (NYSDEC) during the summer of 1999 to evaluate the areas outside the BQE footprint. The sampling results indicate that the subsurface soils within the footprint of the former Ansbacher Plant contain elevated levels of arsenic, lead, and mercury. The groundwater in this area is also contaminated with these metals, but the contaminated groundwater has not migrated significantly beyond the footprint of the former factory. In 2015, the NYSDEC initiated an investigation on the perimeter of the site to identify the origin of chlorinated solvents found in groundwater beneath the sidewalk as part of routine sampling. Site Geology and Hydrogeology: The site is underlain by fine to medium sands; with limited quantities of coarse sand, gravel, and silt throughout the site at varying intervals. Groundwater is approximately 9.5 - 12.5' below grade. Flow direction in shallow groundwater is toward the west-southwest, while deeper groundwater appears to flow towards the east. (This may be due to the presence of the L train subway tunnel underneath North 7th Street.)

Env Problem: Nature and Extent of Contamination: - Soil Sampling was completed in multiple stages from 1988 to 1999. The primary contaminants of concern in soil at this site are arsenic, lead, and mercury. Arsenic has been found at concentrations up to 7,500 ppm, well above the cleanup objective for commercial use (16 ppm). This soil failed for EP Toxicity (48 mg/l, 5.0 mg/l criteria), indicating the soil is hazardous. Lead has been found at concentrations up to 10,600 ppm, well above the cleanup objective for commercial use (1,000 ppm). This soil failed for EP Toxicity (20.3 mg/l, 5.0 mg/l criteria), indicating the soil is hazardous. Mercury was also found at concentrations up to 294 ppm, well above the cleanup objective for commercial use (2.8 ppm). These concentrations were all found in the vicinity of the Arsenate Of Lead building in the southeast area of the site, which is now located in the footprint of the BQE. - Groundwater Sampling has been completed in multiple stages from 1988 to 2015. The primary contaminants of concern in groundwater are arsenic, lead, and mercury. Arsenic has been found at concentrations up to 15,500 ppb, well above the Class GA standard of 25 ppb. Lead has been found at concentrations up to 431 ppb, above the Class GA standard of 25 ppb. Mercury has been found at concentrations up to 75 ppb, well above the Class GA standard of 0.7 ppb. These concentrations were all found in the vicinity of the Arsenate Of Lead building in the southeast area of the site, which is now located in the footprint of the BQE. In 2015, groundwater in the northwest portion of the site was also found to contain tetrachloroethene (PCE) up to 1,900 ppb, trichloroethene (TCE) up to 120 ppb, and cis-1,2-dichloroethene (DCE) up to 320 ppb. PCE, TCE, and DCE all have a Class GA standard of 5 ppb. Significant Threat: The site does not constitute a significant threat to human health or the environment as the contaminated soil is covered by existing layers of asphalt and concrete, and the contaminated groundwater has not migrated significantly beyond the footprint of the former factory.

Health Problem: Residual arsenic and lead contamination remain under the BQE and is covered with several layers of concrete and asphalt, thereby preventing direct contact. Contaminated soil also underlies several on-site buildings formerly used by Ansbacher. Groundwater in the area is not used, since public water is available. Off-site sampling of surface soils from residential yards adjacent to the site indicated the presence of metals (particularly arsenic and lead) at concentrations above the range of concentrations typically

BQE/ANSBACHER COLOR & DYE FACTORY (Continued) **S106780917**

encountered in urban neighborhoods. However, the exact source of the metals in the soils could not be determined from the data collected. The NYSDOH gave the residents advice on how to minimize their exposure to these surface soil contaminants.

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	unknown
Disp Term:	unknown
Lat/Long:	40:42:52:0 / 73:57:12:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2016-03-16 14:25:00
Updated By:	DKHARRIN
Own Op:	Owner
Sub Type:	05
Owner Name:	Not reported
Owner Company:	285 North 6th LLC
Owner Address:	125 Park Avenue
Owner Addr2:	Apt. 11th Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	05
Owner Name:	Not reported
Owner Company:	297 North 7th LLC
Owner Address:	110A Broadway #110
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	NYC Parks and Recreation (General)
Owner Address:	Arsenal West
Owner Addr2:	16 West 61st Street
Owner City,St,Zip:	New York, NY 10023-7604
Owner Country:	United States of America
HW Code:	224016
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224016
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224016
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported

BQE/ANSBACHER COLOR & DYE FACTORY (Continued) **S106780917**

Updated By: Not reported

Count: 11 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S113916585	DAVIDSON PIPE SUPPLY COMPANY	3RD AVE & 37TH STREET		NY SHWS
BROOKLYN	S113916751	INGRAHAM STREET SIDEWALK GW	INGRAHAM STREET	11237	NY SHWS
BROOKLYN	S113917078	NORTH OF CORNISH KNIT GOODS	JOHNSON AVE	11206	NY SHWS
BROOKLYN	S113916586	KENT TERMINAL	KENT AVE. BETWEEN 5TH-11TH ST.	11211	NY SHWS, NY VCP
BROOKLYN	S121102044	MCCARREN COMFORT STSTION	LORIMER ST		NY LTANKS
BROOKLYN	S113916666	MORGAN OIL TERMINAL	224038 MORGAN OIL TERMINAL		NY SHWS
BROOKLYN	S113922150	RUTLEDGE STATION	RUTLEDGE ST, WYTHE&,KENTAVE&WA	11206	NY VCP
BROOKLYN	S110487592	K - SCHOLES ST. STATION	SCHOLES ST 7 BOGART STS, MESSE	11206	NY SHWS, NY BROWNFIELDS
BROOKLYN	S113922100	SCHOLES ST. STATION	SCHOLES ST 7 BOGART STS, MESSE	11206	NY VCP
BROOKLYN	S113922101	SKILLMAN STATION	SKILLMAN ST. FLUSHING & BEDFOR	11205	NY VCP
BROOKLYN	S117535331	BASEMENT	925 UNION ST		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: N/A
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/03/2019
Date Data Arrived at EDR: 04/05/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 10/04/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/13/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 6

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/07/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 08/19/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/20/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 08/19/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/20/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/09/2019
Date Data Arrived at EDR: 09/09/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 14

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 09/09/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/13/2019
Date Data Arrived at EDR: 05/15/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 07/02/2019
Date Data Arrived at EDR: 07/02/2019
Date Made Active in Reports: 09/06/2019
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 09/30/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/12/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/13/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 09/24/2018
Date Data Arrived at EDR: 03/12/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 50
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/23/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/10/2018
Date Data Arrived at EDR: 03/08/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 54
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 02/19/2019
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/01/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 08/12/2019
Date Data Arrived at EDR: 08/13/2019
Date Made Active in Reports: 08/29/2019
Number of Days to Update: 16
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 08/26/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 06/24/2019
Date Data Arrived at EDR: 06/26/2019
Date Made Active in Reports: 09/05/2019
Number of Days to Update: 71

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/25/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 06/24/2019
Date Data Arrived at EDR: 06/26/2019
Date Made Active in Reports: 09/05/2019
Number of Days to Update: 71

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/25/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 06/24/2019
Date Data Arrived at EDR: 06/26/2019
Date Made Active in Reports: 09/05/2019
Number of Days to Update: 71

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/25/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 06/24/2019
Date Data Arrived at EDR: 06/26/2019
Date Made Active in Reports: 09/05/2019
Number of Days to Update: 71

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/25/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 08/05/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 11/07/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/01/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/03/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 09/24/2018
Date Data Arrived at EDR: 03/12/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 50

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/23/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 10/12/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/05/2019
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 03/07/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 55

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/10/2018
Date Data Arrived at EDR: 03/08/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 54

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 06/24/2019
Date Data Arrived at EDR: 06/26/2019
Date Made Active in Reports: 09/05/2019
Number of Days to Update: 71

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 09/25/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 02/13/2019
Date Data Arrived at EDR: 03/22/2019
Date Made Active in Reports: 06/14/2019
Number of Days to Update: 84

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 12/30/2019
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 12/30/2019
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 05/13/2019
Date Data Arrived at EDR: 05/15/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/13/2019
Date Data Arrived at EDR: 05/15/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/19/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 05/13/2019
Date Data Arrived at EDR: 05/15/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 12/14/2018
Date Data Arrived at EDR: 12/19/2018
Date Made Active in Reports: 02/13/2019
Number of Days to Update: 56

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 09/12/2019
Next Scheduled EDR Contact: 12/30/2019
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 05/13/2019
Date Data Arrived at EDR: 05/15/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 05/13/2019
Date Data Arrived at EDR: 05/15/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/03/2019
Date Data Arrived at EDR: 06/04/2019
Date Made Active in Reports: 08/26/2019
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/19/2019
Next Scheduled EDR Contact: 12/30/2019
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 09/06/2019
Next Scheduled EDR Contact: 12/23/2019
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 07/02/2019
Date Data Arrived at EDR: 07/02/2019
Date Made Active in Reports: 09/06/2019
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 09/30/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/19/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 08/02/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 06/11/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/13/2019
Date Data Arrived at EDR: 05/15/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 06/11/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 08/09/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

SUFFOLK CO TANKS: Storage Tank Database
Facilities that have no tank information

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 05/02/2019
Date Data Arrived at EDR: 05/02/2019
Date Made Active in Reports: 06/19/2019
Number of Days to Update: 48

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 08/02/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 07/30/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/24/2019
Date Data Arrived at EDR: 06/26/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 89

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 09/24/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 08/12/2019
Date Data Arrived at EDR: 08/13/2019
Date Made Active in Reports: 08/29/2019
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/13/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/25/2019
Date Data Arrived at EDR: 03/27/2019
Date Made Active in Reports: 04/17/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/15/2019
Date Data Arrived at EDR: 05/21/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 79

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/23/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/09/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/07/2019
Next Scheduled EDR Contact: 01/20/2020
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/16/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/24/2019
Date Data Arrived at EDR: 06/26/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 89

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 09/24/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 08/05/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/09/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/19/2019
Next Scheduled EDR Contact: 12/30/2019
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/23/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 09/30/2018
Date Data Arrived at EDR: 04/24/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 106

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/26/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/25/2019
Date Data Arrived at EDR: 05/02/2019
Date Made Active in Reports: 05/23/2019
Number of Days to Update: 21

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/22/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 09/05/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 18

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/20/2019
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 34

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/12/2019
Next Scheduled EDR Contact: 10/21/2019
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 10/07/2019
Next Scheduled EDR Contact: 01/20/2020
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 06/20/2019
Date Data Arrived at EDR: 06/20/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 49

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 09/04/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 09/06/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 09/03/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/09/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 10/01/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 04/01/2019
Date Data Arrived at EDR: 04/30/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 100
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/31/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2019
Date Data Arrived at EDR: 07/16/2019
Date Made Active in Reports: 10/02/2019
Number of Days to Update: 78
Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 01/20/2020
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218
Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 01/06/2020
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546
Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/06/2019
Next Scheduled EDR Contact: 01/19/2020
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3
Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/30/2019
Next Scheduled EDR Contact: 11/18/2019
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23
Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 07/19/2019
Date Data Arrived at EDR: 07/30/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 35
Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/03/2019
Date Data Arrived at EDR: 05/29/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 71

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/27/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/30/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/30/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/27/2019
Date Data Arrived at EDR: 03/28/2019
Date Made Active in Reports: 05/01/2019
Number of Days to Update: 34

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/10/2019
Next Scheduled EDR Contact: 12/23/2019
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/03/2019
Date Data Arrived at EDR: 06/05/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 90

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 09/04/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 01/17/2019
Date Made Active in Reports: 04/01/2019
Number of Days to Update: 74

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/10/2019
Next Scheduled EDR Contact: 01/27/2020
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/21/2019
Next Scheduled EDR Contact: 12/09/2019
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 07/06/2019
Date Data Arrived at EDR: 07/09/2019
Date Made Active in Reports: 10/02/2019
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 10/08/2019
Next Scheduled EDR Contact: 01/20/2020
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/20/2019
Date Data Arrived at EDR: 05/21/2019
Date Made Active in Reports: 08/08/2019
Number of Days to Update: 79

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/20/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Quarterly

AIRS: Air Emissions Data
Point source emissions inventory data.

Date of Government Version: 05/06/2019
Date Data Arrived at EDR: 05/07/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 37

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/22/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 04/02/2019
Date Data Arrived at EDR: 04/04/2019
Date Made Active in Reports: 06/19/2019
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 09/27/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 11/05/2018
Date Data Arrived at EDR: 03/12/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 93

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 09/06/2019
Next Scheduled EDR Contact: 12/23/2019
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 02/28/2019
Date Data Arrived at EDR: 03/26/2019
Date Made Active in Reports: 06/18/2019
Number of Days to Update: 84

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/16/2019
Next Scheduled EDR Contact: 12/30/2019
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/02/2019
Date Made Active in Reports: 09/06/2019
Number of Days to Update: 66

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 09/27/2019
Next Scheduled EDR Contact: 01/13/2020
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 03/01/2019
Date Data Arrived at EDR: 03/19/2019
Date Made Active in Reports: 06/18/2019
Number of Days to Update: 91

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 09/06/2019
Next Scheduled EDR Contact: 12/23/2019
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 05/01/2019
Date Made Active in Reports: 06/21/2019
Number of Days to Update: 51

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/29/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 04/22/2019
Date Data Arrived at EDR: 04/24/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 61

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/19/2019
Next Scheduled EDR Contact: 11/04/2019
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 12/01/2018
Date Data Arrived at EDR: 02/13/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 120

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/16/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 06/03/2019
Date Data Arrived at EDR: 06/05/2019
Date Made Active in Reports: 06/18/2019
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 09/04/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 07/09/2019
Date Data Arrived at EDR: 07/17/2019
Date Made Active in Reports: 09/06/2019
Number of Days to Update: 51

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/17/2019
Next Scheduled EDR Contact: 10/28/2019
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List
The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List
The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 08/29/2019
Number of Days to Update: 77

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/26/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/13/2019
Date Made Active in Reports: 08/29/2019
Number of Days to Update: 77

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/26/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/30/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/30/2019
Next Scheduled EDR Contact: 12/16/2019
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: No Update Planned

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/25/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 05/10/2019
Date Data Arrived at EDR: 05/17/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 27

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/26/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 05/10/2019
Date Data Arrived at EDR: 05/17/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 27

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/26/2019
Next Scheduled EDR Contact: 11/11/2019
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/14/2019
Date Data Arrived at EDR: 05/14/2019
Date Made Active in Reports: 08/05/2019
Number of Days to Update: 83

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/07/2019
Next Scheduled EDR Contact: 11/25/2019
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/02/2019
Next Scheduled EDR Contact: 01/20/2020
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/09/2019
Next Scheduled EDR Contact: 12/07/2020
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/16/2019
Next Scheduled EDR Contact: 12/02/2019
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 07/15/2019
Date Data Arrived at EDR: 07/16/2019
Date Made Active in Reports: 10/04/2019
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/10/2019
Next Scheduled EDR Contact: 01/27/2020
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/06/2019
Next Scheduled EDR Contact: 12/23/2019
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

BROOKLYN TRIANGLE SITE C
90-100 GERRY ST,84-100 THROOP AVE,59-69 BARTLETT ST
BROOKLYN, NY 11206

TARGET PROPERTY COORDINATES

Latitude (North):	40.70174 - 40° 42' 6.26''
Longitude (West):	73.946241 - 73° 56' 46.47''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589024.2
UTM Y (Meters):	4505971.0
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5940597 BROOKLYN, NY
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 14 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970204F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970208F	FEMA FIRM Flood data
3604970064B	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000829033	0 - 1/8 Mile East
A2	USGS40000828973	1/8 - 1/4 Mile SW
A3	USGS40000828976	1/8 - 1/4 Mile SW
A4	USGS40000828975	1/8 - 1/4 Mile SW
A5	USGS40000828974	1/8 - 1/4 Mile SW
A6	USGS40000828958	1/8 - 1/4 Mile SW
A7	USGS40000828960	1/8 - 1/4 Mile SW
A8	USGS40000828959	1/8 - 1/4 Mile SW
A9	USGS40000828977	1/8 - 1/4 Mile WSW
10	USGS40000828916	1/8 - 1/4 Mile SSE
A11	USGS40000834988	1/8 - 1/4 Mile WSW
A12	USGS40000834987	1/8 - 1/4 Mile WSW
13	USGS40000828917	1/8 - 1/4 Mile SSW
A14	USGS40000828938	1/8 - 1/4 Mile SW
B15	USGS40000828918	1/8 - 1/4 Mile SW
B16	USGS40000828940	1/8 - 1/4 Mile WSW
B17	USGS40000828939	1/8 - 1/4 Mile WSW
C18	USGS40000829064	1/4 - 1/2 Mile WNW
D19	USGS40000829004	1/4 - 1/2 Mile West
C20	USGS40000829065	1/4 - 1/2 Mile West
D21	USGS40000828978	1/4 - 1/2 Mile WSW
E22	USGS40000829242	1/4 - 1/2 Mile NNE
E23	USGS40000829262	1/4 - 1/2 Mile NNE
F24	USGS40000828830	1/4 - 1/2 Mile SW
25	USGS40000829320	1/2 - 1 Mile North
26	USGS40000829203	1/2 - 1 Mile NW
F27	USGS40000828809	1/2 - 1 Mile SW
28	USGS40000829291	1/2 - 1 Mile NNE
F29	USGS40000828816	1/2 - 1 Mile SW
G30	USGS40000829002	1/2 - 1 Mile East
G31	USGS40000829003	1/2 - 1 Mile East
H32	USGS40000829261	1/2 - 1 Mile NE
H33	USGS40000829273	1/2 - 1 Mile NE
34	USGS40000828836	1/2 - 1 Mile ESE
35	USGS40000829263	1/2 - 1 Mile NW
I36	USGS40000829032	1/2 - 1 Mile East
I37	USGS40000829031	1/2 - 1 Mile East
J38	USGS40000829234	1/2 - 1 Mile NE
39	USGS40000828715	1/2 - 1 Mile South
J40	USGS40000829233	1/2 - 1 Mile ENE
41	USGS40000828770	1/2 - 1 Mile SW
K42	USGS40000829386	1/2 - 1 Mile NNE
I43	USGS40000829001	1/2 - 1 Mile East
I44	USGS40000829052	1/2 - 1 Mile East
K45	USGS40000829385	1/2 - 1 Mile NNE
46	USGS40000829139	1/2 - 1 Mile WNW
47	USGS40000829232	1/2 - 1 Mile ENE
48	USGS40000829373	1/2 - 1 Mile NNW
49	USGS40000829248	1/2 - 1 Mile WNW
50	USGS40000829063	1/2 - 1 Mile East
51	USGS40000828781	1/2 - 1 Mile SE
52	USGS40000829091	1/2 - 1 Mile West

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
53	USGS40000829019	1/2 - 1 Mile West
L54	USGS40000828957	1/2 - 1 Mile East
55	USGS40000828808	1/2 - 1 Mile ESE
L56	USGS40000829000	1/2 - 1 Mile East
57	USGS40000829116	1/2 - 1 Mile ENE
58	USGS40000829247	1/2 - 1 Mile ENE
59	USGS40000829364	1/2 - 1 Mile NE
M60	USGS40000829478	1/2 - 1 Mile NNW
61	USGS40000829042	1/2 - 1 Mile West
M62	USGS40000829485	1/2 - 1 Mile NNW
63	USGS40000828626	1/2 - 1 Mile SSE
64	USGS40000829528	1/2 - 1 Mile NNE
65	USGS40000828675	1/2 - 1 Mile SW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
66	NY0007257	1/2 - 1 Mile NNW

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG90000035966	1/2 - 1 Mile NW

PHYSICAL SETTING SOURCE MAP - 5823513.9s



County Boundary
Major Roads
Contour Lines
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

0 1/4 1/2 1 Miles

Groundwater Flow Direction
Indeterminate Groundwater Flow at Location
Groundwater Flow Varies at Location
Closest Hydrogeological Data
Oil, gas or related wells

N

SITE NAME:	Brooklyn Triangle Site C	CLIENT:	Env. Business Consultants
ADDRESS:	90-100 Gerry St,84-100 Throop Ave,59-69 Bartlett St Brooklyn NY 11206	CONTACT:	Keith W Butler
LAT/LONG:	40.70174 / 73.946241	INQUIRY #:	5823513.9s
		DATE:	October 11, 2019 9:09 am

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
East
0 - 1/8 Mile
Higher

FED USGS **USGS40000829033**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3483. 1	Type:	Well
Description:	Throop Ave and Bartleet St, Tompkins Park North		
HUC:	02030201	Drainage Area:	Not Reported
Drainage Area Units:	Not Reported	Contrib Drainage Area:	Not Reported
Contrib Drainage Area Unts:	Not Reported		
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	20001018	Well Depth:	45.6
Well Depth Units:	ft	Well Hole Depth:	45.6
Well Hole Depth Units:	ft		

A2
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828973**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 64. 5	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	165	Well Hole Depth Units:	ft

A3
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828976**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1275. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	175	Well Hole Depth Units:	ft

A4
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828975**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1274. 1	Type:	Well

Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	165	Well Hole Depth Units:	ft

A5
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828974**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 64. 6	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	174	Well Hole Depth Units:	ft

A6
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828958**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 64. 2	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	168	Well Hole Depth Units:	ft

A7
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828960**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1629. 1	Type:	Well
Description:	5602	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	170	Well Depth Units:	ft
Well Hole Depth:	170	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A8
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828959**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1160. 1	Type:	Well
Description:	5601	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	155	Well Hole Depth Units:	ft

A9
WSW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828977**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1600. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	157	Well Hole Depth Units:	ft

10
SSE
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000828916**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1237. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	63
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	239	Level reading date:	1953-08-03
Feet below surface:	Not Reported	Feet to sea level:	-10.35
Note:	Not Reported		
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-10.82	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-11.47	Note:	Not Reported

Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-11.52	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-11.87	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-12.15	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-12.29	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-12.99	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-13.71	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-14.87	Note:	Not Reported
Level reading date:	1952-09-22	Feet below surface:	Not Reported
Feet to sea level:	-15.30	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-15.59	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-16.80	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-17.04	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-18.25	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-18.88	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-19.61	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-20.09	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-21.08	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-21.42	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-22.33	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-23.38	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-23.62	Note:	Not Reported

Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-23.39	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-23.32	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-23.62	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-24.12	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-24.82	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-25.18	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-25.57	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-26.38	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-26.71	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-26.92	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-26.62	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-26.17	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-25.86	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-25.84	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-25.94	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-25.80	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-26.39	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-27.13	Note:	Not Reported

Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-27.37	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-27.27	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-27.25	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-27.38	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-27.83	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-28.15	Note:	Not Reported
Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-28.60	Note:	Not Reported
Level reading date:	1949-04-05	Feet below surface:	Not Reported
Feet to sea level:	-29.10	Note:	Not Reported
Level reading date:	1949-02-21	Feet below surface:	Not Reported
Feet to sea level:	-29.95	Note:	Not Reported
Level reading date:	1949-01-27	Feet below surface:	Not Reported
Feet to sea level:	-30.24	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-29.76	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-30.23	Note:	Not Reported
Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-31.37	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-31.73	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-31.53	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-32.56	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-33.01	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-32.78	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-32.95	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-32.58	Note:	Not Reported
Level reading date:	1948-03-02	Feet below surface:	Not Reported
Feet to sea level:	-32.65	Note:	Not Reported

Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-33.11	Note:	Not Reported
Level reading date:	1948-01-08	Feet below surface:	Not Reported
Feet to sea level:	-33.79	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-34.56	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-34.98	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-34.93	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-35.61	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-35.59	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-35.47	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-35.23	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-35.68	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-35.57	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-35.09	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-36.02	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-35.92	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-35.87	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-35.75	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-35.88	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-35.87	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-35.86	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-35.81	Note:	Not Reported
Level reading date:	1947-05-27	Feet below surface:	Not Reported
Feet to sea level:	-36.12	Note:	Not Reported

Level reading date:	1947-05-07	Feet below surface:	Not Reported
Feet to sea level:	-36.42	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-36.47	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-36.15	Note:	Not Reported
Level reading date:	1947-01-24	Feet below surface:	Not Reported
Feet to sea level:	-36.53	Note:	Not Reported
Level reading date:	1946-12-27	Feet below surface:	Not Reported
Feet to sea level:	-36.30	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-36.44	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-35.92	Note:	Not Reported
Level reading date:	1946-09-26	Feet below surface:	Not Reported
Feet to sea level:	-36.04	Note:	Not Reported
Level reading date:	1946-08-30	Feet below surface:	Not Reported
Feet to sea level:	-35.71	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-35.18	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-34.64	Note:	Not Reported
Level reading date:	1946-06-10	Feet below surface:	Not Reported
Feet to sea level:	-34.27	Note:	Not Reported
Level reading date:	1946-05-10	Feet below surface:	Not Reported
Feet to sea level:	-34.09	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-33.87	Note:	Not Reported
Level reading date:	1946-03-18	Feet below surface:	Not Reported
Feet to sea level:	-33.72	Note:	Not Reported
Level reading date:	1946-02-14	Feet below surface:	Not Reported
Feet to sea level:	-33.90	Note:	Not Reported
Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-33.92	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-34.54	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-34.68	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-34.43	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-34.11	Note:	Not Reported

Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-34.02	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-34.19	Note:	Not Reported
Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-33.83	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-33.56	Note:	Not Reported
Level reading date:	1945-04-04	Feet below surface:	Not Reported
Feet to sea level:	-33.57	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-33.30	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-33.68	Note:	Not Reported
Level reading date:	1944-12-06	Feet below surface:	Not Reported
Feet to sea level:	-34.61	Note:	Not Reported
Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-34.33	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-34.30	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-34.36	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-34.68	Note:	Not Reported
Level reading date:	1944-07-05	Feet below surface:	Not Reported
Feet to sea level:	-34.58	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-34.44	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-34.01	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-33.85	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-33.58	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-33.61	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-33.66	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-33.71	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-33.82	Note:	Not Reported

Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-33.47	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-34.45	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-34.03	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-33.96	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-34.06	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-34.01	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-34.26	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-34.15	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-33.69	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-34.07	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-34.36	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-34.30	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-34.28	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-34.27	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-34.32	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-34.16	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-34.06	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-34.02	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-33.91	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-33.76	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-33.89	Note:	Not Reported

Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-33.78	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-33.67	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-33.71	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-33.71	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-33.72	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-33.53	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-33.37	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-33.21	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-33.04	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-33.59	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-33.73	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-33.69	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-33.83	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-33.98	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-34.08	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-34.11	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-34.16	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-34.12	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-34.16	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-34.18	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-34.16	Note:	Not Reported

Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-34.18	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-34.13	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-34.25	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-34.34	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-34.28	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-34.30	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-34.36	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-34.09	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-34.13	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-34.18	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-34.39	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-34.35	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-33.62	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-34.51	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-34.14	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-34.38	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-34.15	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-34.03	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-33.96	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-34.26	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-34.27	Note:	Not Reported

Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-34.29	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-34.55	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-34.36	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-34.17	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-34.31	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-34.20	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-34.30	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-34.17	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-33.81	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-33.98	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-34.06	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-33.79	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-33.78	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-33.66	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-33.65	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-33.27	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-33.50	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-33.40	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-33.15	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-33.25	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-33.19	Note:	Not Reported

Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-33.28	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-33.13	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-33.08	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-33.15	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-32.72	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-33.08	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-32.90	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-32.71	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-32.81	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-33.01	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-32.87	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-32.64	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-32.83	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-32.68	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-31.56	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-32.67	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-32.67	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-32.24	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-32.64	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-32.46	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-32.41	Note:	Not Reported

Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-32.10	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-32.81	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-32.29	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-32.44	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-32.90	Note:	Not Reported

A11
WSW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000834988**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3123. 2	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	168
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

A12
WSW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000834987**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3123. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	179	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

13
SSW
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000828917**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2286. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported

Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	190	Well Hole Depth Units:	ft

A14
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828938**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2434. 1	Type:	Well
Description:	5901	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	196	Well Hole Depth Units:	ft

B15
SW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828918**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3133. 1	Type:	Well
Description:	Not Reported	HUC:	02030101
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	190
Well Depth Units:	ft	Well Hole Depth:	202
Well Hole Depth Units:	ft		

B16
WSW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828940**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1344. 1	Type:	Well
Description:	0102	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	171	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B17
WSW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000828939**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1305. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	166	Well Hole Depth Units:	ft

C18
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829064**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 29. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	78	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	66	Level reading date:	1939-03-24
Feet below surface:	Not Reported	Feet to sea level:	-24.57
Note:	Not Reported		

Level reading date:	1939-03-12	Feet below surface:	Not Reported
Feet to sea level:	-24.72	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-24.62	Note:	Not Reported
Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-24.59	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-24.54	Note:	Not Reported
Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-24.50	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-24.54	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-24.80	Note:	Not Reported

Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-24.78	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-24.68	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-24.70	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-24.94	Note:	Not Reported
Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-25.00	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-24.97	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1938-11-11	Feet below surface:	Not Reported
Feet to sea level:	-24.69	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-24.77	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-24.67	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-25.10	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-24.94	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-24.96	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-24.93	Note:	Not Reported

Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-24.83	Note:	Not Reported
Level reading date:	1938-07-22	Feet below surface:	Not Reported
Feet to sea level:	-24.84	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-24.79	Note:	Not Reported
Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-24.61	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1938-06-11	Feet below surface:	Not Reported
Feet to sea level:	-24.41	Note:	Not Reported
Level reading date:	1938-06-04	Feet below surface:	Not Reported
Feet to sea level:	-24.43	Note:	Not Reported
Level reading date:	1938-05-28	Feet below surface:	Not Reported
Feet to sea level:	-24.40	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-24.46	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-24.34	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-24.37	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-24.43	Note:	Not Reported
Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-24.47	Note:	Not Reported
Level reading date:	1938-04-09	Feet below surface:	Not Reported
Feet to sea level:	-23.90	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-24.07	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-24.32	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-24.18	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-24.09	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-24.48	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-24.59	Note:	Not Reported

Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-24.44	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-24.73	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-24.82	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-24.65	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-24.78	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-24.75	Note:	Not Reported
Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-24.90	Note:	Not Reported
Level reading date:	1937-12-04	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1937-11-27	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1937-11-20	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1937-11-13	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1937-11-08	Feet below surface:	Not Reported
Feet to sea level:	-24.81	Note:	Not Reported

D19
West
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000829004**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 33. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	176	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C20
West
1/4 - 1/2 Mile
Higher | **FED USGS** | **USGS40000829065**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 65. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	59
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	468	Level reading date:	1968-11-06
Feet below surface:	Not Reported	Feet to sea level:	0.65
Note:	Not Reported		

Level reading date:	1967-10-20	Feet below surface:	Not Reported
Feet to sea level:	0.51	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	5.43	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	-0.40	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1965-09-14	Feet below surface:	Not Reported
Feet to sea level:	-0.71	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	6.73	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	-1.63	Note:	Not Reported
Level reading date:	1964-04-23	Feet below surface:	Not Reported
Feet to sea level:	-0.90	Note:	Not Reported
Level reading date:	1963-10-19	Feet below surface:	Not Reported
Feet to sea level:	-1.07	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	-0.68	Note:	Not Reported
Level reading date:	1962-11-09	Feet below surface:	Not Reported
Feet to sea level:	-0.71	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.70	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	-1.75	Note:	Not Reported

Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	-2.95	Note:	Not Reported
Level reading date:	1961-06-29	Feet below surface:	Not Reported
Feet to sea level:	-3.94	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1960-07-05	Feet below surface:	Not Reported
Feet to sea level:	-3.44	Note:	Not Reported
Level reading date:	1960-03-30	Feet below surface:	Not Reported
Feet to sea level:	-3.13	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	-2.56	Note:	Not Reported
Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	-3.82	Note:	Not Reported
Level reading date:	1959-07-16	Feet below surface:	Not Reported
Feet to sea level:	-3.40	Note:	Not Reported
Level reading date:	1959-03-18	Feet below surface:	Not Reported
Feet to sea level:	-2.75	Note:	Not Reported
Level reading date:	1958-01-10	Feet below surface:	Not Reported
Feet to sea level:	-4.35	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	-4.66	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	-4.47	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	-4.08	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	-3.97	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	-3.93	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	-3.90	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	-3.73	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	-3.44	Note:	Not Reported
Level reading date:	1956-07-03	Feet below surface:	Not Reported
Feet to sea level:	-3.89	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	-3.79	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	-3.39	Note:	Not Reported

Level reading date:	1956-03-05	Feet below surface:	Not Reported
Feet to sea level:	-3.44	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	-3.93	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	-4.25	Note:	Not Reported
Level reading date:	1955-11-15	Feet below surface:	Not Reported
Feet to sea level:	-4.60	Note:	Not Reported
Level reading date:	1955-10-07	Feet below surface:	Not Reported
Feet to sea level:	-5.48	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	-5.49	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	-5.20	Note:	Not Reported
Level reading date:	1955-05-25	Feet below surface:	Not Reported
Feet to sea level:	-5.22	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	-5.09	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	-5.63	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	-5.60	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	-5.77	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	-6.03	Note:	Not Reported
Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	-6.27	Note:	Not Reported
Level reading date:	1954-10-28	Feet below surface:	Not Reported
Feet to sea level:	-6.53	Note:	Not Reported
Level reading date:	1954-10-05	Feet below surface:	Not Reported
Feet to sea level:	-6.63	Note:	Not Reported
Level reading date:	1954-08-25	Feet below surface:	Not Reported
Feet to sea level:	-6.82	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	-6.99	Note:	Not Reported
Level reading date:	1954-06-29	Feet below surface:	Not Reported
Feet to sea level:	-6.85	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	-6.78	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	-6.56	Note:	Not Reported

Level reading date:	1954-03-30	Feet below surface:	Not Reported
Feet to sea level:	-6.57	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	-6.36	Note:	Not Reported
Level reading date:	1954-01-28	Feet below surface:	Not Reported
Feet to sea level:	-6.33	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-6.26	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-6.25	Note:	Not Reported
Level reading date:	1953-10-28	Feet below surface:	Not Reported
Feet to sea level:	-6.58	Note:	Not Reported
Level reading date:	1953-10-02	Feet below surface:	Not Reported
Feet to sea level:	-6.93	Note:	Not Reported
Level reading date:	1953-08-28	Feet below surface:	Not Reported
Feet to sea level:	-6.51	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	-7.14	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-7.58	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-7.81	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-9.00	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-9.57	Note:	Not Reported
Level reading date:	1952-12-18	Feet below surface:	Not Reported
Feet to sea level:	-10.41	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-11.24	Note:	Not Reported
Level reading date:	1952-09-22	Feet below surface:	Not Reported
Feet to sea level:	-11.98	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-12.18	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-12.75	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-12.99	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-13.34	Note:	Not Reported

Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-13.64	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-14.18	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-14.88	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-14.67	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-15.96	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-16.21	Note:	Not Reported
Level reading date:	1951-11-02	Feet below surface:	Not Reported
Feet to sea level:	-16.49	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-17.06	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-17.20	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-17.23	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-17.32	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-17.51	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-17.80	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-18.22	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-18.55	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-18.96	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-18.95	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-19.20	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-19.43	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-19.27	Note:	Not Reported

Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-19.13	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-19.19	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-18.95	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-19.09	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-19.03	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-19.20	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-19.43	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-19.61	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-19.89	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-19.90	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-20.13	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-20.33	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-20.50	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-20.78	Note:	Not Reported
Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-21.18	Note:	Not Reported
Level reading date:	1949-04-05	Feet below surface:	Not Reported
Feet to sea level:	-21.42	Note:	Not Reported
Level reading date:	1949-02-21	Feet below surface:	Not Reported
Feet to sea level:	-22.00	Note:	Not Reported
Level reading date:	1949-01-27	Feet below surface:	Not Reported
Feet to sea level:	-22.17	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-22.46	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-22.77	Note:	Not Reported

Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-22.89	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-23.16	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-23.18	Note:	Not Reported
Level reading date:	1948-07-23	Feet below surface:	Not Reported
Feet to sea level:	-23.50	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-23.67	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-23.92	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-24.29	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-24.62	Note:	Not Reported
Level reading date:	1948-03-02	Feet below surface:	Not Reported
Feet to sea level:	-24.74	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-24.96	Note:	Not Reported
Level reading date:	1948-01-07	Feet below surface:	Not Reported
Feet to sea level:	-25.10	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-25.52	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-25.75	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-25.83	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-25.80	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-25.73	Note:	Not Reported

Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-25.90	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-25.93	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-25.70	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-25.76	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-25.73	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-25.65	Note:	Not Reported
Level reading date:	1947-05-27	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1947-05-07	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-25.70	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-25.47	Note:	Not Reported
Level reading date:	1947-01-24	Feet below surface:	Not Reported
Feet to sea level:	-25.32	Note:	Not Reported
Level reading date:	1946-12-27	Feet below surface:	Not Reported
Feet to sea level:	-25.40	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-25.26	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-25.27	Note:	Not Reported
Level reading date:	1946-09-26	Feet below surface:	Not Reported
Feet to sea level:	-25.19	Note:	Not Reported
Level reading date:	1946-08-30	Feet below surface:	Not Reported
Feet to sea level:	-25.13	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-24.90	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-24.69	Note:	Not Reported
Level reading date:	1946-06-10	Feet below surface:	Not Reported
Feet to sea level:	-24.57	Note:	Not Reported

Level reading date:	1946-05-10	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-24.62	Note:	Not Reported
Level reading date:	1946-03-18	Feet below surface:	Not Reported
Feet to sea level:	-24.66	Note:	Not Reported
Level reading date:	1946-02-15	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-25.12	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-25.27	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-25.40	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-25.27	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-25.19	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-25.10	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-25.01	Note:	Not Reported
Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-24.81	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-24.78	Note:	Not Reported
Level reading date:	1945-04-04	Feet below surface:	Not Reported
Feet to sea level:	-24.87	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-24.74	Note:	Not Reported
Level reading date:	1945-02-06	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-25.06	Note:	Not Reported
Level reading date:	1944-12-06	Feet below surface:	Not Reported
Feet to sea level:	-25.06	Note:	Not Reported
Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-25.12	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-25.19	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-25.23	Note:	Not Reported

Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-25.14	Note:	Not Reported
Level reading date:	1944-07-01	Feet below surface:	Not Reported
Feet to sea level:	-24.97	Note:	Not Reported
Level reading date:	1944-06-03	Feet below surface:	Not Reported
Feet to sea level:	-24.70	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-24.81	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-24.56	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-24.66	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-24.80	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-25.11	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-25.40	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-25.48	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-25.44	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-25.61	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-25.68	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-25.88	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-25.73	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-25.91	Note:	Not Reported

Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-26.15	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-26.01	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-26.14	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-26.03	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-26.07	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-26.02	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-25.92	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-26.02	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-25.89	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-25.94	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-25.91	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-25.90	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-25.80	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-25.77	Note:	Not Reported
Level reading date:	1942-09-04	Feet below surface:	Not Reported
Feet to sea level:	-25.79	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-25.52	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported

Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-25.73	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-25.93	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-25.99	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-26.02	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-26.13	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-26.14	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-26.17	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-26.25	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-26.33	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-26.40	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-26.37	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-26.46	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-26.49	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-26.54	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-26.51	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-26.73	Note:	Not Reported

Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-26.60	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-26.57	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-26.58	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-26.47	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-26.61	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-26.72	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-26.85	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-26.65	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-26.85	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-26.75	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-26.90	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-26.85	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-26.97	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-27.04	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-26.97	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-27.04	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-27.11	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-26.98	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-27.03	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-27.03	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-27.04	Note:	Not Reported

Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-26.89	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-26.99	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-26.95	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-26.95	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-26.80	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-26.85	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-26.80	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-26.72	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-26.66	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-26.74	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-26.65	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-26.60	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-26.61	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-26.60	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-26.59	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-26.58	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-26.58	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-26.46	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-26.47	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported

Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-26.46	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-26.37	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-26.37	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-26.24	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-26.25	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-26.31	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-26.26	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-25.99	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-26.16	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-26.21	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-26.15	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-26.17	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-26.29	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-26.22	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-26.25	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-26.20	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-26.03	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-26.13	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-26.21	Note:	Not Reported

Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-26.32	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-26.16	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-26.23	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-26.17	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-26.16	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-26.23	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-26.06	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-26.13	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-26.13	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-26.06	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-26.09	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-26.01	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-25.90	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-25.92	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-25.81	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-25.76	Note:	Not Reported
Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-25.50	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-25.75	Note:	Not Reported
Level reading date:	1940-07-27	Feet below surface:	Not Reported
Feet to sea level:	-25.74	Note:	Not Reported

Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-25.68	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-25.52	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-25.65	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-25.56	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-25.57	Note:	Not Reported
Level reading date:	1940-05-29	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-25.55	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-25.52	Note:	Not Reported
Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-25.46	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-25.41	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-25.38	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-25.61	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-25.67	Note:	Not Reported

Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-25.61	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-25.59	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-25.68	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-25.70	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-25.73	Note:	Not Reported
Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-25.68	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-25.57	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-25.91	Note:	Not Reported
Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-25.76	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-25.84	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-25.67	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-25.75	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-25.70	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-25.81	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-25.99	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-25.79	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-25.89	Note:	Not Reported

Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-25.94	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1939-09-15	Feet below surface:	Not Reported
Feet to sea level:	-26.30	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-26.63	Note:	Not Reported
Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-27.89	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-28.34	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-28.25	Note:	Not Reported
Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-28.20	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-28.12	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-28.02	Note:	Not Reported
Level reading date:	1939-07-21	Feet below surface:	Not Reported
Feet to sea level:	-27.94	Note:	Not Reported
Level reading date:	1939-07-14	Feet below surface:	Not Reported
Feet to sea level:	-27.67	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-27.59	Note:	Not Reported
Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-27.30	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-27.00	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-26.52	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-25.65	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-24.41	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-24.46	Note:	Not Reported
Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-24.42	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-24.51	Note:	Not Reported

Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-24.44	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-24.49	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1939-04-15	Feet below surface:	Not Reported
Feet to sea level:	-24.35	Note:	Not Reported
Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-24.41	Note:	Not Reported
Level reading date:	1939-03-24	Feet below surface:	Not Reported
Feet to sea level:	-24.40	Note:	Not Reported
Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-24.51	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-24.49	Note:	Not Reported
Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-24.49	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-24.36	Note:	Not Reported
Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-24.45	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-24.43	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-24.44	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-24.64	Note:	Not Reported
Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-24.68	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-24.65	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-24.55	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-24.81	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-24.78	Note:	Not Reported

Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-24.91	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1938-11-11	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-24.70	Note:	Not Reported
Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-24.75	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-24.45	Note:	Not Reported
Level reading date:	1938-09-23	Feet below surface:	Not Reported
Feet to sea level:	-24.66	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-24.93	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-24.84	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-24.81	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-24.81	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-24.78	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported
Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-24.64	Note:	Not Reported
Level reading date:	1938-07-22	Feet below surface:	Not Reported
Feet to sea level:	-24.70	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-24.64	Note:	Not Reported

Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-24.59	Note:	Not Reported
Level reading date:	1938-06-28	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1938-06-21	Feet below surface:	Not Reported
Feet to sea level:	-24.46	Note:	Not Reported
Level reading date:	1938-06-14	Feet below surface:	Not Reported
Feet to sea level:	-24.51	Note:	Not Reported
Level reading date:	1938-06-07	Feet below surface:	Not Reported
Feet to sea level:	-24.36	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-24.44	Note:	Not Reported
Level reading date:	1938-05-14	Feet below surface:	Not Reported
Feet to sea level:	-24.42	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-24.40	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-24.39	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-24.48	Note:	Not Reported
Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1938-04-09	Feet below surface:	Not Reported
Feet to sea level:	-24.01	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-24.39	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-24.23	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-24.41	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-24.31	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-24.20	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-24.48	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-24.61	Note:	Not Reported

Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-24.74	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-24.66	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-24.71	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-24.48	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-24.66	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-24.65	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1937-12-04	Feet below surface:	Not Reported
Feet to sea level:	-24.84	Note:	Not Reported
Level reading date:	1937-11-27	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1937-11-20	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1937-11-13	Feet below surface:	Not Reported
Feet to sea level:	-25.12	Note:	Not Reported
Level reading date:	1937-11-08	Feet below surface:	Not Reported
Feet to sea level:	-24.94	Note:	Not Reported

D21
WSW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000828978**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2069. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	177	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E22
NNE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829242**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 637. 1	Type:	Well
Description:	4101	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	212	Well Hole Depth Units:	ft

E23
NNE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829262**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2533. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	92	Well Hole Depth Units:	ft

F24
SW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000828830**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 30. 1	Type:	Well
Description:	NEW: K 30. 2 197809	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	56
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	218	Level reading date:	1978-04-04
Feet below surface:	Not Reported	Feet to sea level:	5.70
Note:	Not Reported		

Level reading date:	1977-01-05	Feet below surface:	Not Reported
Feet to sea level:	4.35	Note:	Not Reported

Level reading date:	1976-07-09	Feet below surface:	Not Reported
Feet to sea level:	5.78	Note:	Not Reported

Level reading date:	1976-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.52	Note:	Not Reported
Level reading date:	1976-03-23	Feet below surface:	Not Reported
Feet to sea level:	4.54	Note:	Not Reported
Level reading date:	1975-12-16	Feet below surface:	Not Reported
Feet to sea level:	4.78	Note:	Not Reported
Level reading date:	1975-10-07	Feet below surface:	Not Reported
Feet to sea level:	4.69	Note:	Not Reported
Level reading date:	1975-06-30	Feet below surface:	Not Reported
Feet to sea level:	4.29	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	4.05	Note:	Not Reported
Level reading date:	1974-12-19	Feet below surface:	Not Reported
Feet to sea level:	4.81	Note:	Not Reported
Level reading date:	1974-09-25	Feet below surface:	Not Reported
Feet to sea level:	4.74	Note:	Not Reported
Level reading date:	1974-09-04	Feet below surface:	Not Reported
Feet to sea level:	4.52	Note:	Not Reported
Level reading date:	1974-06-26	Feet below surface:	Not Reported
Feet to sea level:	4.51	Note:	Not Reported
Level reading date:	1974-03-19	Feet below surface:	Not Reported
Feet to sea level:	4.20	Note:	Not Reported
Level reading date:	1974-01-09	Feet below surface:	Not Reported
Feet to sea level:	1.59	Note:	Not Reported
Level reading date:	1973-10-02	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1973-07-09	Feet below surface:	Not Reported
Feet to sea level:	2.58	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	2.15	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	2.99	Note:	Not Reported
Level reading date:	1972-09-29	Feet below surface:	Not Reported
Feet to sea level:	3.09	Note:	Not Reported
Level reading date:	1972-07-17	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1972-07-11	Feet below surface:	Not Reported
Feet to sea level:	2.63	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	3.87	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	3.30	Note:	Not Reported

Level reading date:	1971-09-23	Feet below surface:	Not Reported
Feet to sea level:	3.25	Note:	Not Reported
Level reading date:	1971-07-28	Feet below surface:	Not Reported
Feet to sea level:	3.57	Note:	Not Reported
Level reading date:	1971-05-05	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1971-03-16	Feet below surface:	Not Reported
Feet to sea level:	2.75	Note:	Not Reported
Level reading date:	1971-02-09	Feet below surface:	Not Reported
Feet to sea level:	2.69	Note:	Not Reported
Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	2.89	Note:	Not Reported
Level reading date:	1970-05-08	Feet below surface:	Not Reported
Feet to sea level:	3.03	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	2.84	Note:	Not Reported
Level reading date:	1970-02-06	Feet below surface:	Not Reported
Feet to sea level:	2.30	Note:	Not Reported
Level reading date:	1969-11-10	Feet below surface:	Not Reported
Feet to sea level:	2.38	Note:	Not Reported
Level reading date:	1969-09-11	Feet below surface:	Not Reported
Feet to sea level:	2.88	Note:	Not Reported
Level reading date:	1969-09-05	Feet below surface:	Not Reported
Feet to sea level:	2.24	Note:	Not Reported
Level reading date:	1969-08-04	Feet below surface:	Not Reported
Feet to sea level:	2.24	Note:	Not Reported
Level reading date:	1969-07-02	Feet below surface:	Not Reported
Feet to sea level:	1.55	Note:	Not Reported
Level reading date:	1969-05-28	Feet below surface:	Not Reported
Feet to sea level:	1.40	Note:	Not Reported
Level reading date:	1969-04-22	Feet below surface:	Not Reported
Feet to sea level:	1.42	Note:	Not Reported
Level reading date:	1969-04-01	Feet below surface:	Not Reported
Feet to sea level:	1.42	Note:	Not Reported
Level reading date:	1969-02-20	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1969-01-29	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1969-01-08	Feet below surface:	Not Reported
Feet to sea level:	0.97	Note:	Not Reported
Level reading date:	1968-12-03	Feet below surface:	Not Reported
Feet to sea level:	0.73	Note:	Not Reported

Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	0.80	Note:	Not Reported
Level reading date:	1968-09-30	Feet below surface:	Not Reported
Feet to sea level:	0.97	Note:	Not Reported
Level reading date:	1968-08-28	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1968-07-29	Feet below surface:	Not Reported
Feet to sea level:	1.11	Note:	Not Reported
Level reading date:	1968-06-26	Feet below surface:	Not Reported
Feet to sea level:	1.06	Note:	Not Reported
Level reading date:	1968-05-28	Feet below surface:	Not Reported
Feet to sea level:	0.97	Note:	Not Reported
Level reading date:	1968-04-22	Feet below surface:	Not Reported
Feet to sea level:	0.97	Note:	Not Reported
Level reading date:	1968-03-27	Feet below surface:	Not Reported
Feet to sea level:	0.82	Note:	Not Reported
Level reading date:	1968-02-29	Feet below surface:	Not Reported
Feet to sea level:	0.68	Note:	Not Reported
Level reading date:	1968-02-05	Feet below surface:	Not Reported
Feet to sea level:	0.73	Note:	Not Reported
Level reading date:	1968-01-03	Feet below surface:	Not Reported
Feet to sea level:	0.63	Note:	Not Reported
Level reading date:	1967-11-29	Feet below surface:	Not Reported
Feet to sea level:	0.49	Note:	Not Reported
Level reading date:	1967-10-20	Feet below surface:	Not Reported
Feet to sea level:	0.65	Note:	Not Reported
Level reading date:	1967-09-26	Feet below surface:	Not Reported
Feet to sea level:	0.75	Note:	Not Reported
Level reading date:	1967-09-07	Feet below surface:	Not Reported
Feet to sea level:	0.81	Note:	Not Reported
Level reading date:	1967-07-28	Feet below surface:	Not Reported
Feet to sea level:	0.31	Note:	Not Reported
Level reading date:	1967-07-06	Feet below surface:	Not Reported
Feet to sea level:	0.30	Note:	Not Reported
Level reading date:	1967-05-31	Feet below surface:	Not Reported
Feet to sea level:	0.40	Note:	Not Reported
Level reading date:	1967-05-04	Feet below surface:	Not Reported
Feet to sea level:	0.31	Note:	Not Reported
Level reading date:	1967-03-28	Feet below surface:	Not Reported
Feet to sea level:	0.33	Note:	Not Reported
Level reading date:	1967-02-24	Feet below surface:	Not Reported
Feet to sea level:	0.09	Note:	Not Reported

Level reading date:	1967-01-31	Feet below surface:	Not Reported
Feet to sea level:	0.02	Note:	Not Reported
Level reading date:	1966-12-23	Feet below surface:	Not Reported
Feet to sea level:	-0.43	Note:	Not Reported
Level reading date:	1966-12-01	Feet below surface:	Not Reported
Feet to sea level:	-0.39	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	-0.65	Note:	Not Reported
Level reading date:	1966-09-30	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1966-08-29	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1966-07-29	Feet below surface:	Not Reported
Feet to sea level:	-0.45	Note:	Not Reported
Level reading date:	1966-06-27	Feet below surface:	Not Reported
Feet to sea level:	-0.30	Note:	Not Reported
Level reading date:	1966-05-26	Feet below surface:	Not Reported
Feet to sea level:	-0.33	Note:	Not Reported
Level reading date:	1966-05-02	Feet below surface:	Not Reported
Feet to sea level:	-0.33	Note:	Not Reported
Level reading date:	1966-03-30	Feet below surface:	Not Reported
Feet to sea level:	-0.31	Note:	Not Reported
Level reading date:	1966-03-02	Feet below surface:	Not Reported
Feet to sea level:	-0.31	Note:	Not Reported
Level reading date:	1966-01-28	Feet below surface:	Not Reported
Feet to sea level:	-0.36	Note:	Not Reported
Level reading date:	1965-12-30	Feet below surface:	Not Reported
Feet to sea level:	-0.50	Note:	Not Reported
Level reading date:	1965-12-02	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	-0.85	Note:	Not Reported
Level reading date:	1965-10-07	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1965-09-02	Feet below surface:	Not Reported
Feet to sea level:	-0.61	Note:	Not Reported
Level reading date:	1965-07-23	Feet below surface:	Not Reported
Feet to sea level:	-0.49	Note:	Not Reported
Level reading date:	1965-06-24	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1965-05-24	Feet below surface:	Not Reported
Feet to sea level:	-0.43	Note:	Not Reported

Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	-0.45	Note:	Not Reported
Level reading date:	1965-03-25	Feet below surface:	Not Reported
Feet to sea level:	-0.42	Note:	Not Reported
Level reading date:	1965-02-24	Feet below surface:	Not Reported
Feet to sea level:	-0.42	Note:	Not Reported
Level reading date:	1965-01-29	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1964-12-31	Feet below surface:	Not Reported
Feet to sea level:	-0.65	Note:	Not Reported
Level reading date:	1964-11-25	Feet below surface:	Not Reported
Feet to sea level:	-0.80	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	-0.72	Note:	Not Reported
Level reading date:	1964-10-01	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1964-09-02	Feet below surface:	Not Reported
Feet to sea level:	-0.32	Note:	Not Reported
Level reading date:	1964-07-27	Feet below surface:	Not Reported
Feet to sea level:	-0.27	Note:	Not Reported
Level reading date:	1964-07-06	Feet below surface:	Not Reported
Feet to sea level:	-0.39	Note:	Not Reported
Level reading date:	1964-05-28	Feet below surface:	Not Reported
Feet to sea level:	-0.47	Note:	Not Reported
Level reading date:	1964-04-23	Feet below surface:	Not Reported
Feet to sea level:	-0.49	Note:	Not Reported
Level reading date:	1964-03-30	Feet below surface:	Not Reported
Feet to sea level:	-0.46	Note:	Not Reported
Level reading date:	1964-02-28	Feet below surface:	Not Reported
Feet to sea level:	-0.55	Note:	Not Reported
Level reading date:	1964-01-28	Feet below surface:	Not Reported
Feet to sea level:	-0.95	Note:	Not Reported
Level reading date:	1963-12-31	Feet below surface:	Not Reported
Feet to sea level:	-1.08	Note:	Not Reported
Level reading date:	1963-12-05	Feet below surface:	Not Reported
Feet to sea level:	-1.05	Note:	Not Reported
Level reading date:	1963-10-26	Feet below surface:	Not Reported
Feet to sea level:	-0.88	Note:	Not Reported
Level reading date:	1963-09-30	Feet below surface:	Not Reported
Feet to sea level:	-0.68	Note:	Not Reported
Level reading date:	1963-09-03	Feet below surface:	Not Reported
Feet to sea level:	-0.58	Note:	Not Reported

Level reading date:	1963-07-30	Feet below surface:	Not Reported
Feet to sea level:	-0.49	Note:	Not Reported
Level reading date:	1963-07-02	Feet below surface:	Not Reported
Feet to sea level:	-0.45	Note:	Not Reported
Level reading date:	1963-06-03	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1963-03-29	Feet below surface:	Not Reported
Feet to sea level:	-0.38	Note:	Not Reported
Level reading date:	1963-02-28	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1963-01-31	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1963-01-03	Feet below surface:	Not Reported
Feet to sea level:	-0.60	Note:	Not Reported
Level reading date:	1962-12-04	Feet below surface:	Not Reported
Feet to sea level:	-0.51	Note:	Not Reported
Level reading date:	1962-10-31	Feet below surface:	Not Reported
Feet to sea level:	-0.37	Note:	Not Reported
Level reading date:	1962-10-03	Feet below surface:	Not Reported
Feet to sea level:	-0.27	Note:	Not Reported
Level reading date:	1962-08-31	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1962-07-30	Feet below surface:	Not Reported
Feet to sea level:	-0.07	Note:	Not Reported
Level reading date:	1962-07-02	Feet below surface:	Not Reported
Feet to sea level:	-0.13	Note:	Not Reported
Level reading date:	1962-05-29	Feet below surface:	Not Reported
Feet to sea level:	-0.05	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.28	Note:	Not Reported
Level reading date:	1962-03-27	Feet below surface:	Not Reported
Feet to sea level:	-0.32	Note:	Not Reported
Level reading date:	1962-03-05	Feet below surface:	Not Reported
Feet to sea level:	-0.43	Note:	Not Reported
Level reading date:	1962-01-31	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1961-12-20	Feet below surface:	Not Reported
Feet to sea level:	-0.82	Note:	Not Reported
Level reading date:	1961-11-28	Feet below surface:	Not Reported
Feet to sea level:	-0.88	Note:	Not Reported

Level reading date:	1961-10-31	Feet below surface:	Not Reported
Feet to sea level:	-0.92	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	-0.76	Note:	Not Reported
Level reading date:	1961-08-30	Feet below surface:	Not Reported
Feet to sea level:	-0.92	Note:	Not Reported
Level reading date:	1961-08-11	Feet below surface:	Not Reported
Feet to sea level:	-1.36	Note:	Not Reported
Level reading date:	1961-06-20	Feet below surface:	Not Reported
Feet to sea level:	-1.64	Note:	Not Reported
Level reading date:	1961-05-31	Feet below surface:	Not Reported
Feet to sea level:	-1.81	Note:	Not Reported
Level reading date:	1961-04-26	Feet below surface:	Not Reported
Feet to sea level:	-1.84	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	-2.17	Note:	Not Reported
Level reading date:	1961-03-01	Feet below surface:	Not Reported
Feet to sea level:	-2.49	Note:	Not Reported
Level reading date:	1961-01-30	Feet below surface:	Not Reported
Feet to sea level:	-2.59	Note:	Not Reported
Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	-2.68	Note:	Not Reported
Level reading date:	1960-12-06	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1960-11-02	Feet below surface:	Not Reported
Feet to sea level:	-2.53	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.48	Note:	Not Reported
Level reading date:	1960-08-30	Feet below surface:	Not Reported
Feet to sea level:	-2.48	Note:	Not Reported
Level reading date:	1960-08-02	Feet below surface:	Not Reported
Feet to sea level:	-2.53	Note:	Not Reported
Level reading date:	1960-06-30	Feet below surface:	Not Reported
Feet to sea level:	-2.40	Note:	Not Reported
Level reading date:	1960-06-02	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1960-05-04	Feet below surface:	Not Reported
Feet to sea level:	-2.47	Note:	Not Reported
Level reading date:	1960-03-29	Feet below surface:	Not Reported
Feet to sea level:	-2.60	Note:	Not Reported
Level reading date:	1960-03-08	Feet below surface:	Not Reported
Feet to sea level:	-2.65	Note:	Not Reported

Level reading date:	1960-01-27	Feet below surface:	Not Reported
Feet to sea level:	-2.79	Note:	Not Reported
Level reading date:	1960-01-05	Feet below surface:	Not Reported
Feet to sea level:	-2.94	Note:	Not Reported
Level reading date:	1959-12-01	Feet below surface:	Not Reported
Feet to sea level:	-3.22	Note:	Not Reported
Level reading date:	1959-11-02	Feet below surface:	Not Reported
Feet to sea level:	-3.44	Note:	Not Reported
Level reading date:	1959-10-06	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1959-09-03	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1959-08-04	Feet below surface:	Not Reported
Feet to sea level:	-2.92	Note:	Not Reported
Level reading date:	1959-07-02	Feet below surface:	Not Reported
Feet to sea level:	-2.68	Note:	Not Reported
Level reading date:	1959-06-02	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1959-05-06	Feet below surface:	Not Reported
Feet to sea level:	-2.23	Note:	Not Reported
Level reading date:	1959-04-03	Feet below surface:	Not Reported
Feet to sea level:	-2.21	Note:	Not Reported
Level reading date:	1959-03-02	Feet below surface:	Not Reported
Feet to sea level:	-2.39	Note:	Not Reported
Level reading date:	1959-01-29	Feet below surface:	Not Reported
Feet to sea level:	-2.39	Note:	Not Reported
Level reading date:	1959-01-07	Feet below surface:	Not Reported
Feet to sea level:	-2.52	Note:	Not Reported
Level reading date:	1958-12-09	Feet below surface:	Not Reported
Feet to sea level:	-2.56	Note:	Not Reported
Level reading date:	1958-10-30	Feet below surface:	Not Reported
Feet to sea level:	-2.62	Note:	Not Reported
Level reading date:	1958-10-07	Feet below surface:	Not Reported
Feet to sea level:	-2.86	Note:	Not Reported
Level reading date:	1958-08-28	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1958-07-29	Feet below surface:	Not Reported
Feet to sea level:	-2.68	Note:	Not Reported
Level reading date:	1958-06-30	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported
Level reading date:	1958-05-29	Feet below surface:	Not Reported
Feet to sea level:	-2.68	Note:	Not Reported

Level reading date:	1958-05-01	Feet below surface:	Not Reported
Feet to sea level:	-3.12	Note:	Not Reported
Level reading date:	1958-04-02	Feet below surface:	Not Reported
Feet to sea level:	-3.35	Note:	Not Reported
Level reading date:	1958-03-03	Feet below surface:	Not Reported
Feet to sea level:	-3.73	Note:	Not Reported
Level reading date:	1958-01-28	Feet below surface:	Not Reported
Feet to sea level:	-3.59	Note:	Not Reported
Level reading date:	1957-12-31	Feet below surface:	Not Reported
Feet to sea level:	-3.68	Note:	Not Reported
Level reading date:	1957-11-22	Feet below surface:	Not Reported
Feet to sea level:	-3.83	Note:	Not Reported
Level reading date:	1957-10-30	Feet below surface:	Not Reported
Feet to sea level:	-3.88	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	-3.64	Note:	Not Reported
Level reading date:	1957-08-27	Feet below surface:	Not Reported
Feet to sea level:	-3.62	Note:	Not Reported
Level reading date:	1957-07-24	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	-3.43	Note:	Not Reported
Level reading date:	1957-05-28	Feet below surface:	Not Reported
Feet to sea level:	-3.35	Note:	Not Reported
Level reading date:	1957-04-24	Feet below surface:	Not Reported
Feet to sea level:	-3.38	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	-3.53	Note:	Not Reported
Level reading date:	1957-02-27	Feet below surface:	Not Reported
Feet to sea level:	-3.46	Note:	Not Reported
Level reading date:	1957-01-25	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	-3.80	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	-3.70	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	-3.75	Note:	Not Reported
Level reading date:	1956-09-26	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1956-09-04	Feet below surface:	Not Reported
Feet to sea level:	-3.40	Note:	Not Reported

Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	-3.31	Note:	Not Reported
Level reading date:	1956-07-03	Feet below surface:	Not Reported
Feet to sea level:	-3.56	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	-3.48	Note:	Not Reported
Level reading date:	1956-05-02	Feet below surface:	Not Reported
Feet to sea level:	-3.66	Note:	Not Reported
Level reading date:	1956-03-29	Feet below surface:	Not Reported
Feet to sea level:	-4.01	Note:	Not Reported
Level reading date:	1956-03-05	Feet below surface:	Not Reported
Feet to sea level:	-4.16	Note:	Not Reported
Level reading date:	1956-02-03	Feet below surface:	Not Reported
Feet to sea level:	-4.35	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	-4.69	Note:	Not Reported
Level reading date:	1955-12-02	Feet below surface:	Not Reported
Feet to sea level:	-4.87	Note:	Not Reported
Level reading date:	1955-11-04	Feet below surface:	Not Reported
Feet to sea level:	-5.17	Note:	Not Reported
Level reading date:	1955-10-07	Feet below surface:	Not Reported
Feet to sea level:	-5.95	Note:	Not Reported
Level reading date:	1955-09-06	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	-6.05	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	-4.99	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	-4.71	Note:	Not Reported
Level reading date:	1955-05-25	Feet below surface:	Not Reported
Feet to sea level:	-4.70	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	-4.71	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	-4.85	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	-5.21	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	-5.60	Note:	Not Reported

Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	-5.74	Note:	Not Reported
Level reading date:	1954-10-28	Feet below surface:	Not Reported
Feet to sea level:	-5.96	Note:	Not Reported
Level reading date:	1954-10-05	Feet below surface:	Not Reported
Feet to sea level:	-5.85	Note:	Not Reported
Level reading date:	1954-08-25	Feet below surface:	Not Reported
Feet to sea level:	-6.16	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	-6.24	Note:	Not Reported

25
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000829320**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 715. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	120	Well Hole Depth Units:	ft

26
NW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829203**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 717. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	202	Well Hole Depth Units:	ft

F27
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828809**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2040. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported

Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

28
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829291**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 426. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	140	Well Hole Depth Units:	ft

F29
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828816**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 30. 2	Type:	Well
Description:	OLD: K 30. 1	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	18
Well Depth Units:	ft	Well Hole Depth:	18
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	28	Level reading date:	1985-04-03
Feet below surface:	Not Reported	Feet to sea level:	3.78
Note:	Not Reported		
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	4.16	Note:	Not Reported
Level reading date:	1984-10-05	Feet below surface:	Not Reported
Feet to sea level:	5.26	Note:	Not Reported
Level reading date:	1984-06-27	Feet below surface:	Not Reported
Feet to sea level:	5.96	Note:	Not Reported
Level reading date:	1984-03-16	Feet below surface:	Not Reported
Feet to sea level:	5.65	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	5.27	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	4.82	Note:	Not Reported

Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	5.56	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	5.36	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	4.84	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	4.86	Note:	Not Reported
Level reading date:	1982-06-01	Feet below surface:	Not Reported
Feet to sea level:	4.66	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	4.74	Note:	Not Reported
Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	5.10	Note:	Not Reported
Level reading date:	1981-06-24	Feet below surface:	Not Reported
Feet to sea level:	4.47	Note:	Not Reported
Level reading date:	1981-03-20	Feet below surface:	Not Reported
Feet to sea level:	4.84	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	5.40	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	7.38	Note:	Not Reported
Level reading date:	1980-06-19	Feet below surface:	Not Reported
Feet to sea level:	5.06	Note:	Not Reported
Level reading date:	1980-03-13	Feet below surface:	Not Reported
Feet to sea level:	5.13	Note:	Not Reported
Level reading date:	1979-12-18	Feet below surface:	Not Reported
Feet to sea level:	5.43	Note:	Not Reported
Level reading date:	1979-09-17	Feet below surface:	Not Reported
Feet to sea level:	5.86	Note:	Not Reported
Level reading date:	1979-06-28	Feet below surface:	Not Reported
Feet to sea level:	5.89	Note:	Not Reported
Level reading date:	1978-12-22	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	1978-11-01	Feet below surface:	Not Reported
Feet to sea level:	5.48	Note:	Not Reported
Level reading date:	1978-10-26	Feet below surface:	Not Reported
Feet to sea level:	5.96	Note:	Not Reported
Level reading date:	1978-10-02	Feet below surface:	Not Reported
Feet to sea level:	6.54	Note:	Not Reported
Level reading date:	1978-09-27	Feet below surface:	Not Reported
Feet to sea level:	5.72	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G30
East
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000829002**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2136. 1	Type:	Well
Description:	1001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	112	Well Hole Depth Units:	ft

G31
East
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000829003**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 236. 1	Type:	Well
Description:	1008	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	130	Well Depth Units:	ft
Well Hole Depth:	130	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	52	Level reading date:	1954-12-17
Feet below surface:	Not Reported	Feet to sea level:	-8.30
Note:	Not Reported		

Level reading date:	1954-06-29	Feet below surface:	Not Reported
Feet to sea level:	-9.31	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	-8.45	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	-10.08	Note:	Not Reported
Level reading date:	1954-03-30	Feet below surface:	Not Reported
Feet to sea level:	-9.85	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	-9.49	Note:	Not Reported
Level reading date:	1954-01-28	Feet below surface:	Not Reported
Feet to sea level:	-10.11	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-10.76	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-10.78	Note:	Not Reported

Level reading date:	1953-10-28	Feet below surface:	Not Reported
Feet to sea level:	-10.03	Note:	Not Reported
Level reading date:	1953-10-02	Feet below surface:	Not Reported
Feet to sea level:	-11.58	Note:	Not Reported
Level reading date:	1953-08-28	Feet below surface:	Not Reported
Feet to sea level:	-11.23	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	-11.25	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-10.48	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-10.59	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-11.85	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-12.38	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-12.18	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-12.68	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-12.74	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-12.60	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	-16.95	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-16.73	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-17.79	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-17.05	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-19.03	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-19.20	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-20.10	Note:	Not Reported

Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-20.88	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-22.55	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-22.59	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-25.95	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-25.47	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-26.24	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-26.53	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-26.63	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-26.78	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-27.90	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-28.49	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-28.00	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-27.98	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-29.66	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-29.53	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-29.04	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-27.59	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-26.28	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-28.80	Note:	Not Reported

Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-28.80	Note:	Not Reported

H32
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829261**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 37. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	130	Well Hole Depth Units:	ft

H33
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829273**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1490. 1	Type:	Well
Description:	2301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	135	Well Hole Depth Units:	ft

34
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828836**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 255. 1	Type:	Well
Description:	1301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	123	Well Depth Units:	ft
Well Hole Depth:	123	Well Hole Depth Units:	ft

35
NW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829263**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 670. 1	Type:	Well

Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	165	Well Hole Depth Units:	ft

I36
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000829032**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1273. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	275	Well Hole Depth Units:	ft

I37
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000829031**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1153. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	103
Well Hole Depth Units:	ft		

J38
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829234**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1130. 1	Type:	Well
Description:	1301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	89	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

39
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000828715**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 249. 1	Type:	Well
Description:	4301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	175	Well Depth Units:	ft
Well Hole Depth:	175	Well Hole Depth Units:	ft

J40
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829233**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 955. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	72	Well Hole Depth Units:	ft

41
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828770**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 95. 1	Type:	Well
Description:	1701	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

K42
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829386**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 724. 1	Type:	Well
Description:	Not Reported	HUC:	02030201

Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	137	Well Hole Depth Units:	ft

I43
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000829001**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1336. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	163	Well Hole Depth Units:	ft

I44
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000829052**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 36. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	115
Well Hole Depth Units:	ft		

K45
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829385**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1283. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	240	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

46
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829139**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 666. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	214	Well Hole Depth Units:	ft

47
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829232**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 893. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	118	Well Hole Depth Units:	ft

48
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829373**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 672. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	170	Well Hole Depth Units:	ft

49
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829248**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 67. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	475	Level reading date:	1975-10-07
Feet below surface:	Not Reported	Feet to sea level:	13.99
Note:	Not Reported		

Level reading date:	1975-06-30	Feet below surface:	Not Reported
Feet to sea level:	14.09	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	15.35	Note:	Not Reported
Level reading date:	1974-12-19	Feet below surface:	Not Reported
Feet to sea level:	9.86	Note:	Not Reported
Level reading date:	1974-09-04	Feet below surface:	Not Reported
Feet to sea level:	9.70	Note:	Not Reported
Level reading date:	1974-06-26	Feet below surface:	Not Reported
Feet to sea level:	9.64	Note:	Not Reported
Level reading date:	1974-03-19	Feet below surface:	Not Reported
Feet to sea level:	9.89	Note:	Not Reported
Level reading date:	1974-01-09	Feet below surface:	Not Reported
Feet to sea level:	8.60	Note:	Not Reported
Level reading date:	1973-10-02	Feet below surface:	Not Reported
Feet to sea level:	10.47	Note:	Not Reported
Level reading date:	1973-09-25	Feet below surface:	Not Reported
Feet to sea level:	11.70	Note:	Not Reported
Level reading date:	1973-07-09	Feet below surface:	Not Reported
Feet to sea level:	4.20	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	4.51	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.38	Note:	Not Reported
Level reading date:	1972-10-02	Feet below surface:	Not Reported
Feet to sea level:	5.00	Note:	Not Reported
Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	4.90	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	4.71	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	4.63	Note:	Not Reported
Level reading date:	1971-09-23	Feet below surface:	Not Reported
Feet to sea level:	4.81	Note:	Not Reported

Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	6.91	Note:	Not Reported
Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	7.01	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	4.41	Note:	Not Reported
Level reading date:	1969-11-12	Feet below surface:	Not Reported
Feet to sea level:	4.06	Note:	Not Reported
Level reading date:	1969-09-03	Feet below surface:	Not Reported
Feet to sea level:	3.48	Note:	Not Reported
Level reading date:	1969-04-22	Feet below surface:	Not Reported
Feet to sea level:	3.00	Note:	Not Reported
Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	2.61	Note:	Not Reported
Level reading date:	1968-04-22	Feet below surface:	Not Reported
Feet to sea level:	2.52	Note:	Not Reported
Level reading date:	1967-10-20	Feet below surface:	Not Reported
Feet to sea level:	2.07	Note:	Not Reported
Level reading date:	1967-03-28	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	1.29	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	1.12	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	1.02	Note:	Not Reported
Level reading date:	1965-09-14	Feet below surface:	Not Reported
Feet to sea level:	0.85	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	0.89	Note:	Not Reported
Level reading date:	1964-10-02	Feet below surface:	Not Reported
Feet to sea level:	1.10	Note:	Not Reported
Level reading date:	1964-04-23	Feet below surface:	Not Reported
Feet to sea level:	1.15	Note:	Not Reported
Level reading date:	1963-10-19	Feet below surface:	Not Reported
Feet to sea level:	0.89	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.18	Note:	Not Reported
Level reading date:	1962-11-23	Feet below surface:	Not Reported
Feet to sea level:	1.03	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.25	Note:	Not Reported

Level reading date:	1961-12-28	Feet below surface:	Not Reported
Feet to sea level:	-0.96	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	-2.51	Note:	Not Reported
Level reading date:	1961-06-28	Feet below surface:	Not Reported
Feet to sea level:	-4.80	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	-6.02	Note:	Not Reported
Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	-5.64	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	-3.96	Note:	Not Reported
Level reading date:	1960-07-05	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1960-03-31	Feet below surface:	Not Reported
Feet to sea level:	-0.96	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	-1.24	Note:	Not Reported
Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	-1.05	Note:	Not Reported
Level reading date:	1959-07-16	Feet below surface:	Not Reported
Feet to sea level:	-1.34	Note:	Not Reported
Level reading date:	1959-03-18	Feet below surface:	Not Reported
Feet to sea level:	-1.14	Note:	Not Reported
Level reading date:	1958-04-16	Feet below surface:	Not Reported
Feet to sea level:	-2.07	Note:	Not Reported
Level reading date:	1958-01-10	Feet below surface:	Not Reported
Feet to sea level:	-2.02	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	-2.67	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	-1.90	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	-1.57	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	-1.52	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	-1.45	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	-1.15	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	-0.67	Note:	Not Reported

Level reading date:	1956-07-03	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.35	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	-0.44	Note:	Not Reported
Level reading date:	1956-03-05	Feet below surface:	Not Reported
Feet to sea level:	-1.05	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	-1.17	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	-1.36	Note:	Not Reported
Level reading date:	1955-11-15	Feet below surface:	Not Reported
Feet to sea level:	-1.89	Note:	Not Reported
Level reading date:	1955-10-07	Feet below surface:	Not Reported
Feet to sea level:	-2.36	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	-3.01	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	-3.37	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	-3.46	Note:	Not Reported
Level reading date:	1955-05-25	Feet below surface:	Not Reported
Feet to sea level:	-3.49	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	-3.64	Note:	Not Reported
Level reading date:	1955-03-28	Feet below surface:	Not Reported
Feet to sea level:	-3.89	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	-4.20	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	-4.29	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	-4.60	Note:	Not Reported
Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	-4.73	Note:	Not Reported
Level reading date:	1954-08-25	Feet below surface:	Not Reported
Feet to sea level:	-5.63	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1954-06-29	Feet below surface:	Not Reported
Feet to sea level:	-5.50	Note:	Not Reported

Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	-5.26	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	-5.10	Note:	Not Reported
Level reading date:	1954-03-30	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	-4.83	Note:	Not Reported
Level reading date:	1954-01-28	Feet below surface:	Not Reported
Feet to sea level:	-4.82	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-4.80	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-4.80	Note:	Not Reported
Level reading date:	1953-10-28	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1953-10-02	Feet below surface:	Not Reported
Feet to sea level:	-5.39	Note:	Not Reported
Level reading date:	1953-08-28	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	-6.07	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-6.31	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-6.51	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-6.88	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-8.10	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	-8.77	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-8.99	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-9.45	Note:	Not Reported
Level reading date:	1952-09-22	Feet below surface:	Not Reported
Feet to sea level:	-10.08	Note:	Not Reported

Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-10.52	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-10.92	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-11.04	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-11.28	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-11.60	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-12.02	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-12.48	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-12.74	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-13.14	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-13.42	Note:	Not Reported
Level reading date:	1951-11-02	Feet below surface:	Not Reported
Feet to sea level:	-13.69	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-14.15	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-14.33	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-14.38	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-14.42	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-14.38	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-14.49	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-14.80	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-14.94	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-15.10	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-15.31	Note:	Not Reported

Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-15.40	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-15.55	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-15.80	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-16.10	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-16.05	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-15.88	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-15.58	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-15.63	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-15.65	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-15.70	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-15.80	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-16.00	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-16.15	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-16.29	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-16.54	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-16.98	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-17.06	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-17.15	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-16.97	Note:	Not Reported
Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-17.18	Note:	Not Reported
Level reading date:	1949-04-05	Feet below surface:	Not Reported
Feet to sea level:	-17.32	Note:	Not Reported

Level reading date:	1949-02-21	Feet below surface:	Not Reported
Feet to sea level:	-17.65	Note:	Not Reported
Level reading date:	1949-01-27	Feet below surface:	Not Reported
Feet to sea level:	-17.82	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-18.04	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-18.25	Note:	Not Reported
Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-18.32	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-18.80	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-18.97	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-19.32	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-19.22	Note:	Not Reported
Level reading date:	1948-06-01	Feet below surface:	Not Reported
Feet to sea level:	-19.32	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-19.68	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-20.05	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-20.13	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-20.14	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-20.30	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-20.34	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-20.41	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-20.48	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-20.91	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-20.84	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-20.80	Note:	Not Reported

Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-20.80	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-20.80	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-20.68	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-20.57	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-20.53	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-20.50	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-20.47	Note:	Not Reported
Level reading date:	1947-05-27	Feet below surface:	Not Reported
Feet to sea level:	-20.30	Note:	Not Reported
Level reading date:	1947-05-07	Feet below surface:	Not Reported
Feet to sea level:	-20.17	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-20.10	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-20.00	Note:	Not Reported
Level reading date:	1947-01-24	Feet below surface:	Not Reported
Feet to sea level:	-19.86	Note:	Not Reported
Level reading date:	1946-12-27	Feet below surface:	Not Reported
Feet to sea level:	-19.83	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-19.75	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-19.90	Note:	Not Reported
Level reading date:	1946-09-26	Feet below surface:	Not Reported
Feet to sea level:	-20.14	Note:	Not Reported
Level reading date:	1946-09-16	Feet below surface:	Not Reported
Feet to sea level:	-20.10	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-19.90	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-19.69	Note:	Not Reported
Level reading date:	1946-06-10	Feet below surface:	Not Reported
Feet to sea level:	-19.50	Note:	Not Reported
Level reading date:	1946-05-10	Feet below surface:	Not Reported
Feet to sea level:	-19.42	Note:	Not Reported

Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-19.44	Note:	Not Reported
Level reading date:	1946-03-18	Feet below surface:	Not Reported
Feet to sea level:	-19.46	Note:	Not Reported
Level reading date:	1946-02-15	Feet below surface:	Not Reported
Feet to sea level:	-19.58	Note:	Not Reported
Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-19.55	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-19.64	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-19.64	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-19.70	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-19.84	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-19.73	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-19.53	Note:	Not Reported
Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-19.17	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-19.30	Note:	Not Reported
Level reading date:	1945-04-04	Feet below surface:	Not Reported
Feet to sea level:	-19.40	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-19.35	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-19.38	Note:	Not Reported
Level reading date:	1944-12-06	Feet below surface:	Not Reported
Feet to sea level:	-19.77	Note:	Not Reported
Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-19.29	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-19.39	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-19.57	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-19.52	Note:	Not Reported
Level reading date:	1944-07-05	Feet below surface:	Not Reported
Feet to sea level:	-19.24	Note:	Not Reported

Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-19.17	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-19.16	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-19.01	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-18.94	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-18.87	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-18.97	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-18.99	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-18.98	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-19.12	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-19.18	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-19.22	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-19.19	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-19.20	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-19.25	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-19.28	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-19.27	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-19.27	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-19.30	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-19.26	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-19.15	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-19.15	Note:	Not Reported

Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-19.14	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-19.13	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-19.11	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-19.13	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-19.13	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-19.15	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-19.16	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-19.16	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-19.17	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-19.18	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-19.18	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-19.19	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-19.22	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-19.25	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-19.39	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-19.31	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-19.34	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-19.38	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-19.42	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-19.48	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-19.55	Note:	Not Reported

Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-19.62	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-19.71	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-19.80	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-19.88	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-19.93	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-19.95	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-19.99	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-20.04	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-20.08	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-20.11	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-20.14	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-20.15	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-20.16	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-20.21	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-20.24	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-20.24	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-20.26	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-20.30	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-20.30	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-20.35	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-20.37	Note:	Not Reported

Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-20.46	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-20.49	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-20.52	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-20.55	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-20.59	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-20.61	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-20.63	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-20.66	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-20.69	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-20.71	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-20.75	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-20.74	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-20.73	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-20.73	Note:	Not Reported

Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-20.73	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-20.71	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-20.69	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-20.69	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-20.67	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-20.67	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-20.64	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-20.62	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-20.60	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-20.58	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-20.56	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-20.54	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-20.52	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-20.50	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-20.49	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-20.48	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-20.45	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-20.45	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-20.45	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-20.41	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-20.41	Note:	Not Reported

Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-20.38	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-20.37	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-20.35	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-20.35	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-20.33	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-20.31	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-20.31	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-20.31	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-20.32	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-20.35	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-20.30	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-20.30	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-20.29	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-20.28	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-20.28	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-20.28	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-20.26	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-20.27	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-20.25	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-20.25	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-20.22	Note:	Not Reported

Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-20.21	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-20.21	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-20.22	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-20.22	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-20.21	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-20.20	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-20.19	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-20.19	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-20.14	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-20.13	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-20.10	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-20.07	Note:	Not Reported
Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-20.05	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-20.03	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-20.02	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-19.99	Note:	Not Reported
Level reading date:	1940-07-27	Feet below surface:	Not Reported
Feet to sea level:	-19.99	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-19.98	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-19.97	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-19.96	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-19.91	Note:	Not Reported

Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-19.92	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-19.91	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-19.88	Note:	Not Reported
Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-19.91	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-19.90	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-19.87	Note:	Not Reported
Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-19.85	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-19.87	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-19.84	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-19.80	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-19.82	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-19.78	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-19.81	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-19.80	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-19.79	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-19.78	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-19.73	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-19.69	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-19.72	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-19.74	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-19.73	Note:	Not Reported

Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-19.71	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-19.71	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-19.71	Note:	Not Reported
Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-19.72	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-19.72	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-19.74	Note:	Not Reported
Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-19.70	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-19.67	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-19.66	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-19.67	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-19.65	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-19.66	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-19.67	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-19.63	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-19.62	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-19.54	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-19.63	Note:	Not Reported
Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-19.57	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-19.63	Note:	Not Reported
Level reading date:	1939-09-16	Feet below surface:	Not Reported
Feet to sea level:	-19.47	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-19.43	Note:	Not Reported

Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-19.34	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-19.29	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-19.23	Note:	Not Reported
Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-19.10	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-19.08	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-19.13	Note:	Not Reported
Level reading date:	1939-07-21	Feet below surface:	Not Reported
Feet to sea level:	-19.00	Note:	Not Reported
Level reading date:	1939-07-14	Feet below surface:	Not Reported
Feet to sea level:	-18.86	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-18.85	Note:	Not Reported
Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-18.63	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-18.61	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-18.63	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-18.63	Note:	Not Reported
Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-18.62	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported
Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-18.63	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-18.64	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-18.64	Note:	Not Reported
Level reading date:	1939-04-08	Feet below surface:	Not Reported
Feet to sea level:	-18.63	Note:	Not Reported

Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-18.73	Note:	Not Reported
Level reading date:	1939-03-24	Feet below surface:	Not Reported
Feet to sea level:	-18.73	Note:	Not Reported
Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-18.73	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-18.73	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-18.75	Note:	Not Reported
Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-18.70	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-18.72	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-18.78	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-18.82	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-18.85	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-18.90	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-18.90	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-18.90	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-18.89	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-18.93	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-18.89	Note:	Not Reported
Level reading date:	1938-11-11	Feet below surface:	Not Reported
Feet to sea level:	-18.90	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-18.89	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-18.88	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-18.85	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-18.86	Note:	Not Reported

Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-18.86	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-18.85	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-18.91	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-18.87	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-18.90	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-18.83	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-18.83	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-18.78	Note:	Not Reported
Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-18.76	Note:	Not Reported
Level reading date:	1938-07-22	Feet below surface:	Not Reported
Feet to sea level:	-18.75	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-18.71	Note:	Not Reported
Level reading date:	1938-06-25	Feet below surface:	Not Reported
Feet to sea level:	-18.69	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-18.57	Note:	Not Reported
Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-18.55	Note:	Not Reported
Level reading date:	1938-04-09	Feet below surface:	Not Reported
Feet to sea level:	-18.51	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-18.51	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-18.49	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-18.55	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-18.58	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-18.60	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported

Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-18.64	Note:	Not Reported
Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-18.67	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported
Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-18.66	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-18.64	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-18.67	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-18.66	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-18.68	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-18.66	Note:	Not Reported
Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-18.56	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-18.63	Note:	Not Reported
Level reading date:	1937-12-04	Feet below surface:	Not Reported
Feet to sea level:	-18.62	Note:	Not Reported
Level reading date:	1937-11-27	Feet below surface:	Not Reported
Feet to sea level:	-18.61	Note:	Not Reported
Level reading date:	1937-11-20	Feet below surface:	Not Reported
Feet to sea level:	-18.56	Note:	Not Reported
Level reading date:	1937-11-13	Feet below surface:	Not Reported
Feet to sea level:	-18.60	Note:	Not Reported
Level reading date:	1937-11-08	Feet below surface:	Not Reported
Feet to sea level:	-18.60	Note:	Not Reported

50
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000829063**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 87. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	160	Well Depth Units:	ft

Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	184	Level reading date:	1941-05-31
Feet below surface:	Not Reported	Feet to sea level:	-9.41
Note:	Not Reported		

Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-9.39	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-9.36	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-9.36	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-9.32	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-9.30	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-9.25	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-9.25	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-9.23	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-9.23	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported

Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-9.26	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-9.25	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-9.20	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-9.19	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-9.16	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-9.10	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-9.05	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-9.03	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-8.92	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-8.91	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-8.88	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-8.74	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-8.51	Note:	Not Reported

Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-8.55	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-8.44	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-8.50	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-8.34	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-8.86	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-8.70	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-8.72	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-7.98	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-8.45	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-8.10	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported
Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-7.83	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-7.79	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-7.78	Note:	Not Reported
Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-7.77	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-7.75	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-7.73	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-7.60	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported

Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-7.68	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-8.44	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-8.47	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-8.37	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-8.43	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-8.51	Note:	Not Reported
Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-8.73	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-8.58	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-8.73	Note:	Not Reported
Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-8.77	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-8.56	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-8.70	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-8.92	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-9.02	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-8.91	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-8.93	Note:	Not Reported

Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-8.92	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-8.87	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-7.99	Note:	Not Reported
Level reading date:	1939-09-16	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-7.87	Note:	Not Reported
Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-7.82	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-7.76	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-7.70	Note:	Not Reported
Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-7.63	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-7.60	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-7.53	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-7.33	Note:	Not Reported
Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-7.33	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-7.33	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-7.36	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-7.39	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-7.41	Note:	Not Reported

Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-7.45	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-7.48	Note:	Not Reported
Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-7.48	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-7.48	Note:	Not Reported
Level reading date:	1939-04-15	Feet below surface:	Not Reported
Feet to sea level:	-7.50	Note:	Not Reported
Level reading date:	1939-04-08	Feet below surface:	Not Reported
Feet to sea level:	-7.52	Note:	Not Reported
Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-7.61	Note:	Not Reported
Level reading date:	1939-03-24	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-7.63	Note:	Not Reported
Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-7.70	Note:	Not Reported
Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-7.79	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-7.85	Note:	Not Reported
Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-7.86	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-7.89	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-7.93	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-7.95	Note:	Not Reported

Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-8.00	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-8.03	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-8.07	Note:	Not Reported
Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-8.17	Note:	Not Reported
Level reading date:	1938-11-11	Feet below surface:	Not Reported
Feet to sea level:	-8.16	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-8.21	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-8.22	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-8.24	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-8.29	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1938-09-23	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-8.38	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-8.34	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-8.28	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-8.22	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-8.18	Note:	Not Reported

Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1938-07-22	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-8.00	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-7.96	Note:	Not Reported
Level reading date:	1938-06-25	Feet below surface:	Not Reported
Feet to sea level:	-7.93	Note:	Not Reported
Level reading date:	1938-06-18	Feet below surface:	Not Reported
Feet to sea level:	-7.86	Note:	Not Reported
Level reading date:	1938-06-11	Feet below surface:	Not Reported
Feet to sea level:	-7.83	Note:	Not Reported
Level reading date:	1938-06-04	Feet below surface:	Not Reported
Feet to sea level:	-7.82	Note:	Not Reported
Level reading date:	1938-05-28	Feet below surface:	Not Reported
Feet to sea level:	-7.77	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-7.76	Note:	Not Reported
Level reading date:	1938-05-14	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-7.68	Note:	Not Reported
Level reading date:	1938-04-09	Feet below surface:	Not Reported
Feet to sea level:	-7.66	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-7.67	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-7.67	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported

Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-7.73	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-7.76	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-7.79	Note:	Not Reported
Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-7.83	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-7.84	Note:	Not Reported
Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-7.89	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-7.93	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-7.99	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-8.02	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-8.04	Note:	Not Reported
Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-8.06	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1937-12-04	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1937-11-27	Feet below surface:	Not Reported
Feet to sea level:	-8.18	Note:	Not Reported
Level reading date:	1937-11-20	Feet below surface:	Not Reported
Feet to sea level:	-8.23	Note:	Not Reported
Level reading date:	1937-11-13	Feet below surface:	Not Reported
Feet to sea level:	-8.23	Note:	Not Reported
Level reading date:	1937-11-08	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported

51
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828781**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 92. 1	Type:	Well

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	185
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	439	Level reading date:	1960-01-11
Feet below surface:	Not Reported	Feet to sea level:	0.40
Note:	Not Reported		

Level reading date:	1959-10-08	Feet below surface:	Not Reported
Feet to sea level:	0.51	Note:	Not Reported
Level reading date:	1959-07-21	Feet below surface:	Not Reported
Feet to sea level:	0.73	Note:	Not Reported
Level reading date:	1958-01-10	Feet below surface:	Not Reported
Feet to sea level:	-0.15	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	-0.30	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	0.15	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	0.53	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	0.36	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	0.37	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	0.05	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	0.05	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	-0.13	Note:	Not Reported
Level reading date:	1956-07-11	Feet below surface:	Not Reported
Feet to sea level:	-0.01	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	0.02	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	-0.05	Note:	Not Reported
Level reading date:	1956-03-05	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	-0.47	Note:	Not Reported

Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	-1.34	Note:	Not Reported
Level reading date:	1955-11-15	Feet below surface:	Not Reported
Feet to sea level:	-1.12	Note:	Not Reported
Level reading date:	1955-10-07	Feet below surface:	Not Reported
Feet to sea level:	-1.27	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	-1.69	Note:	Not Reported
Level reading date:	1955-07-28	Feet below surface:	Not Reported
Feet to sea level:	-1.62	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	-1.56	Note:	Not Reported
Level reading date:	1955-05-25	Feet below surface:	Not Reported
Feet to sea level:	-1.15	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	-1.24	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	-1.44	Note:	Not Reported
Level reading date:	1955-02-25	Feet below surface:	Not Reported
Feet to sea level:	-1.43	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	-1.68	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	-1.99	Note:	Not Reported
Level reading date:	1954-06-29	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	-2.24	Note:	Not Reported
Level reading date:	1954-03-30	Feet below surface:	Not Reported
Feet to sea level:	-2.38	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	-2.51	Note:	Not Reported
Level reading date:	1954-01-28	Feet below surface:	Not Reported
Feet to sea level:	-2.78	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-3.30	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-3.43	Note:	Not Reported
Level reading date:	1953-10-28	Feet below surface:	Not Reported
Feet to sea level:	-3.86	Note:	Not Reported
Level reading date:	1953-10-01	Feet below surface:	Not Reported
Feet to sea level:	-4.17	Note:	Not Reported

Level reading date:	1953-08-28	Feet below surface:	Not Reported
Feet to sea level:	-4.06	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	-4.40	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-4.45	Note:	Not Reported
Level reading date:	1953-05-22	Feet below surface:	Not Reported
Feet to sea level:	-4.41	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-4.64	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-5.29	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-5.68	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-6.12	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-6.98	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-7.35	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-8.23	Note:	Not Reported
Level reading date:	1952-09-22	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-9.25	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-9.64	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-9.99	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-10.33	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-10.64	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-10.95	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-11.37	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-11.64	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-11.99	Note:	Not Reported

Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-12.18	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-12.27	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-12.46	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-12.59	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-12.54	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-12.60	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-12.34	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-12.13	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-12.56	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-12.75	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-13.05	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-13.40	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-13.61	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-13.99	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-14.20	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-14.05	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-13.93	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-13.71	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-13.39	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-13.29	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-13.43	Note:	Not Reported

Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-13.63	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-14.01	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-14.45	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-14.89	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-15.35	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-15.52	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-15.78	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-16.00	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-16.23	Note:	Not Reported
Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-16.48	Note:	Not Reported
Level reading date:	1949-04-05	Feet below surface:	Not Reported
Feet to sea level:	-16.79	Note:	Not Reported
Level reading date:	1949-02-21	Feet below surface:	Not Reported
Feet to sea level:	-17.52	Note:	Not Reported
Level reading date:	1949-01-27	Feet below surface:	Not Reported
Feet to sea level:	-18.15	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-18.68	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-18.80	Note:	Not Reported
Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-19.04	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-19.30	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-19.58	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-19.83	Note:	Not Reported
Level reading date:	1948-07-01	Feet below surface:	Not Reported
Feet to sea level:	-19.90	Note:	Not Reported

Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-19.95	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-20.19	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-20.17	Note:	Not Reported
Level reading date:	1948-03-02	Feet below surface:	Not Reported
Feet to sea level:	-20.33	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-20.77	Note:	Not Reported
Level reading date:	1948-01-07	Feet below surface:	Not Reported
Feet to sea level:	-21.16	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-21.55	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-21.73	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-21.85	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-22.23	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-22.47	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-22.57	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-22.65	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-22.75	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-22.81	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-22.83	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-22.81	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-22.82	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-22.77	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-22.71	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-22.70	Note:	Not Reported

Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-22.69	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-22.71	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-22.69	Note:	Not Reported
Level reading date:	1947-05-27	Feet below surface:	Not Reported
Feet to sea level:	-22.67	Note:	Not Reported
Level reading date:	1947-05-07	Feet below surface:	Not Reported
Feet to sea level:	-22.66	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-22.61	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-22.57	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-22.51	Note:	Not Reported
Level reading date:	1946-12-27	Feet below surface:	Not Reported
Feet to sea level:	-22.43	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-22.34	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-22.60	Note:	Not Reported
Level reading date:	1946-09-26	Feet below surface:	Not Reported
Feet to sea level:	-22.22	Note:	Not Reported
Level reading date:	1946-08-30	Feet below surface:	Not Reported
Feet to sea level:	-21.95	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-22.04	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-21.95	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-21.85	Note:	Not Reported
Level reading date:	1946-05-10	Feet below surface:	Not Reported
Feet to sea level:	-21.78	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-21.67	Note:	Not Reported
Level reading date:	1946-03-18	Feet below surface:	Not Reported
Feet to sea level:	-21.50	Note:	Not Reported
Level reading date:	1946-02-15	Feet below surface:	Not Reported
Feet to sea level:	-21.41	Note:	Not Reported
Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-21.55	Note:	Not Reported

Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-21.91	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-22.12	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-22.38	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-22.38	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-22.28	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-22.04	Note:	Not Reported
Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-21.84	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-21.65	Note:	Not Reported
Level reading date:	1945-04-04	Feet below surface:	Not Reported
Feet to sea level:	-21.54	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-21.26	Note:	Not Reported
Level reading date:	1945-02-06	Feet below surface:	Not Reported
Feet to sea level:	-21.62	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-22.09	Note:	Not Reported
Level reading date:	1944-12-06	Feet below surface:	Not Reported
Feet to sea level:	-22.17	Note:	Not Reported
Level reading date:	1944-10-27	Feet below surface:	Not Reported
Feet to sea level:	-22.68	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-22.98	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-22.98	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-22.84	Note:	Not Reported
Level reading date:	1944-07-05	Feet below surface:	Not Reported
Feet to sea level:	-22.64	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-22.29	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-22.12	Note:	Not Reported
Level reading date:	1944-04-01	Feet below surface:	Not Reported
Feet to sea level:	-21.71	Note:	Not Reported

Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-22.94	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-22.89	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-22.93	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-22.90	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-22.82	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-21.70	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-21.68	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-21.65	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-21.61	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-21.72	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-21.88	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-22.08	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-22.20	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-22.41	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-22.48	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-22.52	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-22.56	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-22.64	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-22.68	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-22.75	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-22.81	Note:	Not Reported

Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-22.90	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-22.98	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-23.10	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-23.19	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-23.30	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-23.41	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-23.40	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-23.35	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-23.34	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-23.31	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-23.29	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-23.25	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-23.20	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-23.15	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-23.04	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-22.98	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-22.86	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-22.78	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-22.53	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-22.38	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-22.24	Note:	Not Reported

Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-22.10	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-22.04	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-22.03	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-22.06	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-22.08	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-22.10	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-22.12	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-22.15	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-22.18	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-22.23	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-22.25	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-22.25	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-22.30	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-22.36	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-22.39	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-22.41	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-22.45	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-22.49	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-22.54	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-22.61	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-22.67	Note:	Not Reported

Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-22.71	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-22.81	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-22.85	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-22.93	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-22.99	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-23.08	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-23.17	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-23.27	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-23.36	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-23.48	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-23.59	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-23.72	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-23.85	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-24.00	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-24.08	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-24.04	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-23.97	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-23.90	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-23.80	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-23.72	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-23.62	Note:	Not Reported

Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-23.52	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-23.41	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-23.29	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-23.15	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-23.02	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-22.86	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-22.73	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-22.54	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-22.35	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-22.17	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-22.03	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-21.89	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-21.76	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-21.61	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-21.45	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-21.29	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-21.31	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-21.34	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-21.38	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-21.41	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-21.45	Note:	Not Reported

Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-21.50	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-21.56	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-21.61	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-21.68	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-21.73	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-21.80	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-21.88	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-21.93	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-22.01	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-22.07	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-22.15	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-22.22	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-22.32	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-22.41	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-22.53	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-22.63	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-22.76	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-22.89	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-23.01	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-23.17	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-23.33	Note:	Not Reported

Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-23.49	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-23.66	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-23.81	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-23.97	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-23.98	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-23.92	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-23.97	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-23.95	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-23.83	Note:	Not Reported
Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-23.84	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-23.79	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-23.73	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-23.64	Note:	Not Reported
Level reading date:	1940-07-27	Feet below surface:	Not Reported
Feet to sea level:	-23.61	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-23.64	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-23.40	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-23.38	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-23.20	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-23.23	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-23.12	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-23.01	Note:	Not Reported

Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-22.85	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-22.84	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-22.83	Note:	Not Reported
Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-22.86	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-22.81	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-22.83	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-22.81	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-22.84	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-22.85	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-22.84	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-22.85	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-22.89	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-22.92	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-22.92	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-22.93	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-23.02	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-22.96	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-23.00	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-23.01	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-23.01	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-23.04	Note:	Not Reported

Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-23.05	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-23.06	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-23.07	Note:	Not Reported
Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-23.14	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-23.21	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-23.40	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-23.61	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-23.82	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-24.00	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-24.16	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-24.21	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-24.25	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-24.33	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-24.38	Note:	Not Reported
Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-24.46	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-24.35	Note:	Not Reported
Level reading date:	1939-09-16	Feet below surface:	Not Reported
Feet to sea level:	-24.21	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-24.35	Note:	Not Reported
Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-24.32	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-24.29	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-24.25	Note:	Not Reported

Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-24.24	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-24.20	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-23.81	Note:	Not Reported
Level reading date:	1939-07-21	Feet below surface:	Not Reported
Feet to sea level:	-24.05	Note:	Not Reported
Level reading date:	1939-07-14	Feet below surface:	Not Reported
Feet to sea level:	-23.99	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-23.94	Note:	Not Reported
Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-23.85	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-23.82	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-23.79	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-23.73	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-23.64	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-23.54	Note:	Not Reported
Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-23.47	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-23.41	Note:	Not Reported
Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-23.30	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-23.35	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-23.40	Note:	Not Reported
Level reading date:	1939-04-15	Feet below surface:	Not Reported
Feet to sea level:	-23.37	Note:	Not Reported
Level reading date:	1939-04-08	Feet below surface:	Not Reported
Feet to sea level:	-23.52	Note:	Not Reported
Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-23.66	Note:	Not Reported
Level reading date:	1939-03-24	Feet below surface:	Not Reported
Feet to sea level:	-23.73	Note:	Not Reported

Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-23.77	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-23.68	Note:	Not Reported
Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-23.74	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-23.80	Note:	Not Reported
Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-23.84	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-23.89	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-23.93	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-24.04	Note:	Not Reported
Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-24.06	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-24.12	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-24.21	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-24.28	Note:	Not Reported
Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-24.35	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-24.42	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-24.53	Note:	Not Reported
Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-24.53	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-24.57	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-24.69	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-24.73	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-24.80	Note:	Not Reported

Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-24.99	Note:	Not Reported
Level reading date:	1938-09-23	Feet below surface:	Not Reported
Feet to sea level:	-25.15	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-25.23	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-25.28	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-25.25	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-25.15	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-25.04	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-24.92	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-24.71	Note:	Not Reported
Level reading date:	1938-07-22	Feet below surface:	Not Reported
Feet to sea level:	-24.61	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-24.51	Note:	Not Reported
Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-24.15	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-24.21	Note:	Not Reported
Level reading date:	1938-06-25	Feet below surface:	Not Reported
Feet to sea level:	-24.06	Note:	Not Reported
Level reading date:	1938-06-18	Feet below surface:	Not Reported
Feet to sea level:	-23.71	Note:	Not Reported
Level reading date:	1938-06-11	Feet below surface:	Not Reported
Feet to sea level:	-23.73	Note:	Not Reported
Level reading date:	1938-06-04	Feet below surface:	Not Reported
Feet to sea level:	-23.70	Note:	Not Reported
Level reading date:	1938-05-28	Feet below surface:	Not Reported
Feet to sea level:	-23.80	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-23.79	Note:	Not Reported

Level reading date:	1938-05-14	Feet below surface:	Not Reported
Feet to sea level:	-23.81	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-23.84	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-23.92	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-23.94	Note:	Not Reported
Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-24.00	Note:	Not Reported
Level reading date:	1938-04-09	Feet below surface:	Not Reported
Feet to sea level:	-24.04	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-24.13	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-24.23	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-24.28	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-24.40	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-26.59	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-26.67	Note:	Not Reported
Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-28.05	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-28.37	Note:	Not Reported
Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-29.07	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-29.20	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-28.78	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-29.34	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-29.31	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-29.24	Note:	Not Reported

Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-29.62	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-29.69	Note:	Not Reported

52
West
1/2 - 1 Mile
Higher

FED USGS **USGS40000829091**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 687. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	200	Well Hole Depth Units:	ft

53
West
1/2 - 1 Mile
Higher

FED USGS **USGS40000829019**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1662. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	147	Well Hole Depth Units:	ft

L54
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000828957**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 887. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	125	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

55
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828808**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 952. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	122	Well Hole Depth Units:	ft

L56
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000829000**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1031. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

57
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829116**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 894. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	282	Well Hole Depth Units:	ft

58
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829247**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3111. 1	Type:	Well
Description:	0001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	95
Well Hole Depth Units:	ft		

59
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829364**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 889. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	74
Well Depth Units:	ft	Well Hole Depth:	74
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	265	Level reading date:	1985-10-01
Feet below surface:	Not Reported	Feet to sea level:	3.53
Note:	Not Reported		

Level reading date:	1985-05-21	Feet below surface:	Not Reported
Feet to sea level:	4.48	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	4.95	Note:	Not Reported
Level reading date:	1984-10-05	Feet below surface:	Not Reported
Feet to sea level:	5.16	Note:	Not Reported
Level reading date:	1984-06-27	Feet below surface:	Not Reported
Feet to sea level:	5.47	Note:	Not Reported
Level reading date:	1984-03-15	Feet below surface:	Not Reported
Feet to sea level:	5.13	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	1983-09-29	Feet below surface:	Not Reported
Feet to sea level:	4.96	Note:	Not Reported
Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	4.59	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	3.69	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	3.86	Note:	Not Reported

Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1982-04-02	Feet below surface:	Not Reported
Feet to sea level:	4.19	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	4.01	Note:	Not Reported
Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	4.10	Note:	Not Reported
Level reading date:	1981-06-24	Feet below surface:	Not Reported
Feet to sea level:	4.28	Note:	Not Reported
Level reading date:	1981-03-18	Feet below surface:	Not Reported
Feet to sea level:	5.36	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	5.06	Note:	Not Reported
Level reading date:	1980-06-24	Feet below surface:	Not Reported
Feet to sea level:	5.14	Note:	Not Reported
Level reading date:	1980-03-13	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported
Level reading date:	1979-12-18	Feet below surface:	Not Reported
Feet to sea level:	4.92	Note:	Not Reported
Level reading date:	1979-09-17	Feet below surface:	Not Reported
Feet to sea level:	4.57	Note:	Not Reported
Level reading date:	1979-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.07	Note:	Not Reported
Level reading date:	1979-03-26	Feet below surface:	Not Reported
Feet to sea level:	5.46	Note:	Not Reported
Level reading date:	1978-12-22	Feet below surface:	Not Reported
Feet to sea level:	5.11	Note:	Not Reported
Level reading date:	1978-10-02	Feet below surface:	Not Reported
Feet to sea level:	5.94	Note:	Not Reported
Level reading date:	1978-06-23	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported
Level reading date:	1978-04-04	Feet below surface:	Not Reported
Feet to sea level:	4.06	Note:	Not Reported
Level reading date:	1978-01-03	Feet below surface:	Not Reported
Feet to sea level:	4.29	Note:	Not Reported
Level reading date:	1977-09-22	Feet below surface:	Not Reported
Feet to sea level:	3.81	Note:	Not Reported
Level reading date:	1977-07-07	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported

Level reading date:	1977-03-29	Feet below surface:	Not Reported
Feet to sea level:	2.60	Note:	Not Reported
Level reading date:	1976-12-22	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1976-09-23	Feet below surface:	Not Reported
Feet to sea level:	3.25	Note:	Not Reported
Level reading date:	1976-07-09	Feet below surface:	Not Reported
Feet to sea level:	3.97	Note:	Not Reported
Level reading date:	1976-06-28	Feet below surface:	Not Reported
Feet to sea level:	3.21	Note:	Not Reported
Level reading date:	1976-03-23	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1975-12-16	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported
Level reading date:	1975-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.10	Note:	Not Reported
Level reading date:	1975-06-30	Feet below surface:	Not Reported
Feet to sea level:	2.80	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	2.67	Note:	Not Reported
Level reading date:	1974-12-19	Feet below surface:	Not Reported
Feet to sea level:	1.99	Note:	Not Reported
Level reading date:	1974-09-04	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1974-06-26	Feet below surface:	Not Reported
Feet to sea level:	2.58	Note:	Not Reported
Level reading date:	1974-03-19	Feet below surface:	Not Reported
Feet to sea level:	2.36	Note:	Not Reported
Level reading date:	1974-01-09	Feet below surface:	Not Reported
Feet to sea level:	2.26	Note:	Not Reported
Level reading date:	1973-09-24	Feet below surface:	Not Reported
Feet to sea level:	1.86	Note:	Not Reported
Level reading date:	1973-07-02	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	0.97	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported
Level reading date:	1972-10-02	Feet below surface:	Not Reported
Feet to sea level:	1.57	Note:	Not Reported
Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	1.94	Note:	Not Reported

Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	0.27	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	0.44	Note:	Not Reported
Level reading date:	1971-09-27	Feet below surface:	Not Reported
Feet to sea level:	0.57	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	1.08	Note:	Not Reported
Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	1.02	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported
Level reading date:	1969-11-12	Feet below surface:	Not Reported
Feet to sea level:	0.49	Note:	Not Reported
Level reading date:	1969-09-05	Feet below surface:	Not Reported
Feet to sea level:	0.24	Note:	Not Reported
Level reading date:	1969-04-23	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	-3.34	Note:	Not Reported
Level reading date:	1968-04-22	Feet below surface:	Not Reported
Feet to sea level:	0.46	Note:	Not Reported
Level reading date:	1967-10-20	Feet below surface:	Not Reported
Feet to sea level:	-0.01	Note:	Not Reported
Level reading date:	1967-03-28	Feet below surface:	Not Reported
Feet to sea level:	-0.64	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	-2.53	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	-0.64	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	-1.85	Note:	Not Reported
Level reading date:	1965-09-14	Feet below surface:	Not Reported
Feet to sea level:	-2.21	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	-1.79	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.19	Note:	Not Reported
Level reading date:	1963-11-05	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	-0.13	Note:	Not Reported

Level reading date:	1962-12-04	Feet below surface:	Not Reported
Feet to sea level:	-0.88	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1961-12-28	Feet below surface:	Not Reported
Feet to sea level:	-1.92	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	-3.06	Note:	Not Reported
Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	-3.44	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	-4.38	Note:	Not Reported
Level reading date:	1960-07-05	Feet below surface:	Not Reported
Feet to sea level:	-4.23	Note:	Not Reported
Level reading date:	1960-03-31	Feet below surface:	Not Reported
Feet to sea level:	-4.56	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	-4.97	Note:	Not Reported
Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1959-07-17	Feet below surface:	Not Reported
Feet to sea level:	-4.44	Note:	Not Reported
Level reading date:	1959-03-18	Feet below surface:	Not Reported
Feet to sea level:	-4.96	Note:	Not Reported
Level reading date:	1958-01-10	Feet below surface:	Not Reported
Feet to sea level:	-4.06	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	-4.44	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	-3.58	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	-3.09	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	-3.01	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	-3.06	Note:	Not Reported

Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	-3.00	Note:	Not Reported
Level reading date:	1956-07-11	Feet below surface:	Not Reported
Feet to sea level:	-2.95	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	-3.26	Note:	Not Reported
Level reading date:	1956-03-05	Feet below surface:	Not Reported
Feet to sea level:	-3.53	Note:	Not Reported
Level reading date:	1956-02-03	Feet below surface:	Not Reported
Feet to sea level:	-3.69	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	-3.74	Note:	Not Reported
Level reading date:	1955-11-15	Feet below surface:	Not Reported
Feet to sea level:	-4.04	Note:	Not Reported
Level reading date:	1955-10-07	Feet below surface:	Not Reported
Feet to sea level:	-4.61	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	-4.74	Note:	Not Reported
Level reading date:	1955-07-27	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	-4.43	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	-4.91	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	-5.07	Note:	Not Reported
Level reading date:	1955-02-25	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	-5.34	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	-5.61	Note:	Not Reported
Level reading date:	1954-06-29	Feet below surface:	Not Reported
Feet to sea level:	-6.25	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	-6.72	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	-6.79	Note:	Not Reported
Level reading date:	1954-03-30	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported

Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	-7.02	Note:	Not Reported
Level reading date:	1954-01-28	Feet below surface:	Not Reported
Feet to sea level:	-7.19	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-7.15	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1953-10-02	Feet below surface:	Not Reported
Feet to sea level:	-7.61	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	-7.45	Note:	Not Reported
Level reading date:	1953-06-23	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-9.10	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-9.37	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-10.14	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-10.54	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-11.13	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-12.22	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	-12.62	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-13.11	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-13.84	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-14.33	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-15.09	Note:	Not Reported

Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-15.88	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-16.33	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-16.98	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-17.37	Note:	Not Reported
Level reading date:	1951-11-02	Feet below surface:	Not Reported
Feet to sea level:	-17.86	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-18.29	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-18.53	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-18.97	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-19.39	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-19.79	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-20.22	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-20.97	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-21.64	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-22.36	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-24.01	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-24.78	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-24.48	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported

Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-24.97	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-24.90	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-25.44	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-25.76	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-25.59	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-25.62	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-25.89	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-26.02	Note:	Not Reported
Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-26.14	Note:	Not Reported
Level reading date:	1949-04-05	Feet below surface:	Not Reported
Feet to sea level:	-26.39	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-27.08	Note:	Not Reported
Level reading date:	1949-01-27	Feet below surface:	Not Reported
Feet to sea level:	-27.47	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-27.87	Note:	Not Reported
Level reading date:	1948-12-14	Feet below surface:	Not Reported
Feet to sea level:	-28.03	Note:	Not Reported
Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-28.60	Note:	Not Reported
Level reading date:	1948-10-06	Feet below surface:	Not Reported
Feet to sea level:	-28.94	Note:	Not Reported

Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-29.46	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-30.22	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-30.77	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-31.35	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-32.12	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-32.84	Note:	Not Reported
Level reading date:	1948-03-02	Feet below surface:	Not Reported
Feet to sea level:	-33.43	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-34.37	Note:	Not Reported
Level reading date:	1948-01-07	Feet below surface:	Not Reported
Feet to sea level:	-35.55	Note:	Not Reported
Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-35.93	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-36.76	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-36.87	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-37.15	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-37.22	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-37.17	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-37.13	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-37.00	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-36.56	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-36.15	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-35.58	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-35.29	Note:	Not Reported

Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-35.21	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-35.95	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-36.46	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-36.32	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-36.69	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-37.12	Note:	Not Reported
Level reading date:	1947-06-20	Feet below surface:	Not Reported
Feet to sea level:	-37.16	Note:	Not Reported
Level reading date:	1947-06-13	Feet below surface:	Not Reported
Feet to sea level:	-37.06	Note:	Not Reported
Level reading date:	1947-06-06	Feet below surface:	Not Reported
Feet to sea level:	-36.95	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-36.78	Note:	Not Reported
Level reading date:	1947-05-23	Feet below surface:	Not Reported
Feet to sea level:	-36.63	Note:	Not Reported
Level reading date:	1947-05-17	Feet below surface:	Not Reported
Feet to sea level:	-36.47	Note:	Not Reported
Level reading date:	1947-05-16	Feet below surface:	Not Reported
Feet to sea level:	-36.41	Note:	Not Reported
Level reading date:	1947-05-10	Feet below surface:	Not Reported
Feet to sea level:	-35.93	Note:	Not Reported
Level reading date:	1947-05-03	Feet below surface:	Not Reported
Feet to sea level:	-35.89	Note:	Not Reported
Level reading date:	1947-04-26	Feet below surface:	Not Reported
Feet to sea level:	-35.43	Note:	Not Reported
Level reading date:	1947-04-19	Feet below surface:	Not Reported
Feet to sea level:	-35.17	Note:	Not Reported
Level reading date:	1947-04-18	Feet below surface:	Not Reported
Feet to sea level:	-35.09	Note:	Not Reported
Level reading date:	1947-03-29	Feet below surface:	Not Reported
Feet to sea level:	-33.64	Note:	Not Reported
Level reading date:	1947-03-22	Feet below surface:	Not Reported
Feet to sea level:	-33.32	Note:	Not Reported
Level reading date:	1947-03-08	Feet below surface:	Not Reported
Feet to sea level:	-34.08	Note:	Not Reported

Level reading date:	1947-03-01	Feet below surface:	Not Reported
Feet to sea level:	-35.65	Note:	Not Reported
Level reading date:	1947-02-22	Feet below surface:	Not Reported
Feet to sea level:	-36.06	Note:	Not Reported
Level reading date:	1947-02-15	Feet below surface:	Not Reported
Feet to sea level:	-36.93	Note:	Not Reported
Level reading date:	1947-02-08	Feet below surface:	Not Reported
Feet to sea level:	-37.58	Note:	Not Reported
Level reading date:	1947-02-01	Feet below surface:	Not Reported
Feet to sea level:	-38.31	Note:	Not Reported
Level reading date:	1947-01-25	Feet below surface:	Not Reported
Feet to sea level:	-39.01	Note:	Not Reported
Level reading date:	1947-01-18	Feet below surface:	Not Reported
Feet to sea level:	-37.73	Note:	Not Reported
Level reading date:	1947-01-10	Feet below surface:	Not Reported
Feet to sea level:	-37.61	Note:	Not Reported
Level reading date:	1946-10-19	Feet below surface:	Not Reported
Feet to sea level:	-31.90	Note:	Not Reported
Level reading date:	1946-10-12	Feet below surface:	Not Reported
Feet to sea level:	-27.83	Note:	Not Reported
Level reading date:	1946-10-05	Feet below surface:	Not Reported
Feet to sea level:	-20.51	Note:	Not Reported
Level reading date:	1946-09-23	Feet below surface:	Not Reported
Feet to sea level:	-36.25	Note:	Not Reported
Level reading date:	1946-09-16	Feet below surface:	Not Reported
Feet to sea level:	-37.75	Note:	Not Reported
Level reading date:	1946-08-30	Feet below surface:	Not Reported
Feet to sea level:	-38.35	Note:	Not Reported
Level reading date:	1946-08-19	Feet below surface:	Not Reported
Feet to sea level:	-38.17	Note:	Not Reported
Level reading date:	1946-07-30	Feet below surface:	Not Reported
Feet to sea level:	-37.69	Note:	Not Reported
Level reading date:	1946-07-08	Feet below surface:	Not Reported
Feet to sea level:	-37.25	Note:	Not Reported
Level reading date:	1946-06-10	Feet below surface:	Not Reported
Feet to sea level:	-36.63	Note:	Not Reported
Level reading date:	1946-05-27	Feet below surface:	Not Reported
Feet to sea level:	-36.17	Note:	Not Reported
Level reading date:	1946-05-20	Feet below surface:	Not Reported
Feet to sea level:	-35.97	Note:	Not Reported
Level reading date:	1946-05-13	Feet below surface:	Not Reported
Feet to sea level:	-35.55	Note:	Not Reported

Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-35.32	Note:	Not Reported
Level reading date:	1946-04-29	Feet below surface:	Not Reported
Feet to sea level:	-35.07	Note:	Not Reported
Level reading date:	1946-04-22	Feet below surface:	Not Reported
Feet to sea level:	-35.31	Note:	Not Reported
Level reading date:	1946-04-15	Feet below surface:	Not Reported
Feet to sea level:	-35.44	Note:	Not Reported
Level reading date:	1946-04-08	Feet below surface:	Not Reported
Feet to sea level:	-35.56	Note:	Not Reported
Level reading date:	1946-04-01	Feet below surface:	Not Reported
Feet to sea level:	-35.67	Note:	Not Reported
Level reading date:	1946-03-25	Feet below surface:	Not Reported
Feet to sea level:	-35.66	Note:	Not Reported
Level reading date:	1946-03-18	Feet below surface:	Not Reported
Feet to sea level:	-35.80	Note:	Not Reported
Level reading date:	1946-03-11	Feet below surface:	Not Reported
Feet to sea level:	-35.79	Note:	Not Reported
Level reading date:	1946-03-04	Feet below surface:	Not Reported
Feet to sea level:	-35.75	Note:	Not Reported
Level reading date:	1946-02-25	Feet below surface:	Not Reported
Feet to sea level:	-35.66	Note:	Not Reported
Level reading date:	1946-02-18	Feet below surface:	Not Reported
Feet to sea level:	-35.67	Note:	Not Reported
Level reading date:	1946-02-11	Feet below surface:	Not Reported
Feet to sea level:	-35.61	Note:	Not Reported
Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-35.07	Note:	Not Reported
Level reading date:	1945-12-03	Feet below surface:	Not Reported
Feet to sea level:	-34.78	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-34.30	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-33.23	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-32.54	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-30.12	Note:	Not Reported
Level reading date:	1945-07-23	Feet below surface:	Not Reported
Feet to sea level:	-30.27	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-30.41	Note:	Not Reported

Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-30.46	Note:	Not Reported

M60
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829478**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 898. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	46	Well Depth Units:	ft
Well Hole Depth:	74	Well Hole Depth Units:	ft

61
West
1/2 - 1 Mile
Higher

FED USGS **USGS40000829042**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 664. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	179	Well Hole Depth Units:	ft

M62
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829485**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 673. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	196	Well Hole Depth Units:	ft

63
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828626**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3482. 1	Type:	Well

Description:	N/E CORNER OF GREENE AVE AND MARCY AVENUE		
HUC:	02030201	Drainage Area:	Not Reported
Drainage Area Units:	Not Reported	Contrib Drainage Area:	Not Reported
Contrib Drainage Area Unts:	Not Reported		
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	20010717	Well Depth:	70
Well Depth Units:	ft	Well Hole Depth:	70
Well Hole Depth Units:	ft		

64
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829528**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 678. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	221	Well Hole Depth Units:	ft

65
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828675**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 256. 1	Type:	Well
Description:	2501	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	174	Well Depth Units:	ft
Well Hole Depth:	206	Well Hole Depth Units:	ft

66
NNW
1/2 - 1 Mile
Higher

FRDS PWS **NY0007257**

PWS ID:	NY0007257	PWS type:	System Owner/Responsible Party
PWS name:	ROSENBERG MAYER	PWS address:	C/O MAYER ROSENBURG
PWS address:	570 BEDFORD AVE	PWS city:	BROOKLYN
PWS state:	NY	PWS zip:	11211
PWS ID:	NY0007257	Activity status:	Active
Date system activated:	Not Reported	Date system deactivated:	Not Reported
Retail population:	00000100	System name:	MANSFIELD BUNG COLONY
System address:	Not Reported	System address:	GALE ROAD, BOX 123
System city:	MONGAUP VALLEY	System state:	NY
System zip:	12762		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

County FIPS:	052	City served:	BETHEL (T)
Latitude:	404251	Longitude:	0735714

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
NW
1/2 - 1 Mile

OIL_GAS **NYOG90000035966**

API Well #:	31061236030000	Well Name:	MPP - 5
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Type:	Stratigraphic
Well Status:	Plugged and Abandoned	Permit Date:	0
Drill Date:	0	Completion Date:	0
Plug Date:	0	Field Name:	Not Applicable
Formation:	Not Applicable	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	550
True Depth:	645	Measured Length:	645

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX E

PRIOR REPORTS/MISCELLANEOUS

Soil Map—Kings County, New York
(Broadway Triangle Site C, Brooklyn, NY)

Map Scale: 1:1,050 if printed on A landscape (11" x 8.5") sheet.

N

Meters
0 15 30 60 90

Feet
0 50 100 200 300

Map projection: Web Mercator Corner coordinates: WGS84 Edge tics: UTM Zone 18N WGS84

MAP LEGEND

Area of Interest (AOI)
- Area of Interest (AOI)

Soils
- Soil Map Unit Polygons
- Soil Map Unit Lines
- Soil Map Unit Points

Special Point Features
- Blowout
- Borrow Pit
- Clay Spot
- Closed Depression
- Gravel Pit
- Gravelly Spot
- Landfill
- Lava Flow
- Marsh or swamp
- Mine or Quarry
- Miscellaneous Water
- Perennial Water
- Rock Outcrop
- Saline Spot
- Sandy Spot
- Severely Eroded Spot
- Sinkhole
- Slide or Slip
- Sodic Spot
- Spoil Area
- Stony Spot
- Very Stony Spot
- Wet Spot
- Other
- Special Line Features

Water Features
- Streams and Canals

Transportation
- Rails
- Interstate Highways
- US Routes
- Major Roads
- Local Roads

Background
- Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:12,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Kings County, New York
Survey Area Data: Version 9, Sep 16, 2019

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Jul 23, 2014—Aug 15, 2014

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
UGAl	Urban land-Greenbelt complex, 0 to 3 percent slopes, low impervious surface	0.5	13.1%
UtA	Urban land, till substratum, 0 to 3 percent slopes	3.5	86.9%
Totals for Area of Interest		**4.0**	**100.0%**

U.S. Fish and Wildlife Service
National Wetlands Inventory

Broadway Triangle Site C, Brooklyn, NY

November 5, 2019

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

National Flood Hazard Layer FIRMette

FEMA

40°42'18.73"N

73°57'4.67"W



73°56'27.21"W

40°41'51.45"N

0 250 500 1,000 1,500 2,000 Feet

1:6,000

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 Cross Sections with 1% Annual Chance
- 17.5 Water Surface Elevation
- Coastal Transect
- Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 11/5/2019 at 4:47:05 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.