February 6, 2023

David Linehan
Franklin Avenue Property Owner LLC
49 West 23rd Street, 4th Floor
New York, NY 10010

Re: Phase I Environmental Site Assessment for
970 Franklin Avenue
Brooklyn, New York 11225

Dear Mr. Linehan:

Per your authorization, ALC Environmental has completed a Phase I Environmental Site Assessment (ESA) of the property located at 970 Franklin Avenue Brooklyn, NY 11225. The objective of this assessment was to evaluate the past and current environmental conditions at the site and to identify any potential areas of environmental concern or recognized environmental conditions that could affect the environmental integrity of the property. This Phase I ESA was performed in general conformance with the scope and limitations of the ASTM International (ASTM) Practice E1527-21.

The Phase I ESA identified recognized environmental conditions (RECs) associated with the subject property. In addition, *de minimis* conditions were identified. Details were provided in the report. Please call 212-675-5544 or e-mail (tania.castro@alcenvironmental.com) if you have any questions regarding this report.

Respectfully submitted,

Tania Castro
Real Estate Due Diligence, Division Manager
ALC Environmental

PHASE I ENVIRONMENTAL SITE ASSESSMENT

970 Franklin Avenue
Brooklyn, NY 11225
Block 1192, Lots 63 & 66

Prepared by

ALC Environmental
39 West 29th Street, 8th Floor
New York, NY 10001

Prepared for

Franklin Ave Property Owner LLC
49 West 23rd Street, 4th Floor
New York, NY 10010

February 6, 2023

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY 1-1
1.1 SUMMARY OF FINDINGS 1-3
2.0 INTRODUCTION 2-1
2.1 PURPOSE 2-1
2.2 DETAILED SCOPE-OF-SERVICES 2-1
2.3 SIGNIFICANT ASSUMPTIONS 2-2
2.4 LIMITATIONS AND EXCEPTIONS 2-2
2.5 SPECIAL TERMS AND CONDITIONS 2-2
2.6 USER RELIANCE 2-2
3.0 SITE DESCRIPTION 3-1
3.1 LOCATION AND LEGAL DESCRIPTION 3-1
3.2 SITE AND VICINITY GENERAL CHARACTERISTICS 3-1
3.3 FORMER USE OF THE PROPERTY 3-1
3.4 CURRENT USE OF THE PROPERTY 3-2
3.5 DESCRIPTIONS OF STRUCTURES, ROADS, OTHER IMPROVEMENTS ON THE SITE 3-2
3.6 CURRENT USES OF THE ADJOINING PROPERTIES 3-3
4.0 USER PROVIDED INFORMATION 4-1
4.1 TITLE RECORDS 4-1
4.3 SPECIALIZED KNOWLEDGE 4-1
4.4 COMMONLY KNOWN OR REASONABLY ASCERTAINABLE INFORMATION (40 CFR 312.30) 4-1
4.5 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES 4-1
4.6 OWNER, PROPERTY MANAGER, AND OCCUPANT INFORMATION 4-1
4.7 REASON FOR PERFORMING THE PHASE I 4-2
4.8 DEGREE OF OBVIOUSNESS (40 CFR 312.31) 4-2
4.9 PREVIOUS REPORTS 4-2
5.0 RECORDS REVIEW 5-1
5.1 STANDARD ENVIRONMENTAL RECORD SOURCES 5-1
5.1.1 FEDERAL RECORDS 5-2
5.1.2 STATE RECORDS 5-3
5.1.3 EDR PROPERTY RECORDS 5-8
5.2 ADDITIONAL ENVIRONMENTAL RECORD SOURCES 5-9
5.3 PHYSICAL SETTING SOURCE 5-10
5.4 HISTORICAL USE INFORMATION ON THE PROPERTY AND ADJOINING PROPERTIES 5-10
5.4.1 AERIAL PHOTOGRAPHS 5-11
5.4.2 HISTORICAL SANBORN MAPS 5-12
5.4.3 CITY DIRECTORIES 5-16
5.4.4 TOPOGRAPHIC MAPS 5-20
6.0 SITE RECONNAISSANCE 6-1
6.1 METHODOLOGY AND LIMITING CONDITIONS 6-1
6.2 GENERAL SITE SETTING 6-1
6.3 EXTERIOR AND INTERIOR OBSERVATIONS 6-1
6.3.1 LEAD 6-1
6.3.2 ASBESTOS 6-2
6.3.3 NON-ASBESTOS HAZARDOUS MATERIALS 6-3
6.3.4 UNDERGROUND/ABOVEGROUND STORAGE TANKS 6-3

6.3.5 Non-Hazardous Solid Waste 6-4
6.3.6 Hazardous Waste 6-4
6.3.7 Vapor Encroachment 6-4
6.3.8 PCB-Containing Equipment 6-5
6.3.9 Storm Water and Waste Water 6-6
6.3.10 Wetlands 6-6
6.3.11 Floodplains 6-6
6.3.12 Radon 6-6
6.3.13 Air Emissions 6-6
6.3.14 Stressed Vegetation 6-6
6.3.15 Heating/Cooling 6-7
6.3.16 Stains or Corrosion 6-7
6.3.17 Drains and Sumps 6-7
6.3.18 Mold 6-7
7.0 Interviews 7-1
7.1 Interview with Owner 7-1
7.2 Interview with Site Manager 7-1
7.3 Interviews with Occupants 7-1
7.4 Interviews with Local Government Officials 7-1
7.4 Interviews with others 7-1
8.0 Findings 8-1
9.0 Conclusions and Recommendations 9-1
9.1 Conclusions 9-1
9.2 Recommendations 9-1
10.0 Deviations 10-1
11.0 Additional Services 11-1
12.0 References 12-1
13.0 Signature of Environmental Professional 13-1
14.0 Qualifications of Environmental Professional 14-1

15.0 Appendices
15.1 Figures
15.2 Site Photographs
15.3 Historical Research Documentation
15.4 Regulatory Records Documentation
15.5 Supporting Documentation
15.6 Contractual Conditions Between the User And the Environmental Professional
15.7 Qualifications of the Environmental Professional

1.0 EXECUTIVE SUMMARY

ALC Environmental (ALC) was contracted by Franklin Ave Property Owner LLC, the Client, to conduct a Phase I Environmental Site Assessment (ESA) of the property located at 970 Franklin Avenue, Brooklyn, NY 11225. The property consists of two adjoining lots (collectively denoted as the **"Subject Property"**) comprising two single-story buildings and a grassed area. Below is a description of the subject lots:

Address	Block	Lot	Area	Description
962 Franklin Avenue	1192	63	0.3 acres	One vacant single-story warehouse building.
972 Franklin Avenue	1192	66	1.34 acres	One vacant single-story office building and a large grassed area.

The Subject Property is approximately 245 feet north of Sullivan Place, between Franklin Avenue to the east and Washington Avenue to the west.

The objective of this assessment was to evaluate past and current environmental conditions at the Subject Property and to identify any potential areas of environmental concern or recognized environmental conditions that could affect the environmental integrity of the property. This Phase I ESA was performed in general conformance with the scope and limitations of the ASTM International Practice E1527-21.

On January 24, 2023, ALC's Field Technician Virxhinia Daci conducted a site reconnaissance at the Subject Property. The information included in this report was gathered from state and municipal offices and officials, former environmental data, site interviews, the environmental database search, and from the site inspection.

The Subject Property is in the Crown Heights section of the NYC Borough of Brooklyn. The general vicinity of the property consists of vacant light industrial buildings, an institutional building known as P.S. 375 Jackie Robinson School, multi-family apartment buildings, and railroad tracks to the immediate west. Below is a summary of the Phase I ESA findings:

	Acceptable	Corrective Action	Further Investigation	Reference Section
USER PROVIDED INFORMATION				
Environmental Cleanup Liens	✓			**4.2**
Activity & Land Use Limitations (AULs)	✓			**4.3**
Specialized Knowledge or Experience	✓			**4.3**
Relationship of Purchase Price to Fair Market Value	✓			**4.0**
Commonly Known or Reasonable Ascertainable Information	✓			**4.0**

	Acceptable	Corrective Action	Further Investigation	Reference Section
USER PROVIDED INFORMATION				
Degree of Obviousness	✓			4.0
RECORDS REVIEW				
Standard Environmental Record	✓			7.0
Physical Setting Records	✓			
HISTORICAL USE INFORMATION				
Subject Property	✓			5.3
Adjoining Properties	✓			5.3
Surrounding Areas	✓			5.3
GENERAL SITE SETTING				
Current Use(s) of the Subject Property	✓			3.3
Current Use(s) of Adjoining Properties	✓			3.5
Current or Past Use of the Surrounding Area	✓			5.3
Surficial & Subsurface Physical Conditions	✓			6.0
INTERIOR & EXTERIOR OBSERVATIONS				
Lead-Based Paint	✓			6.3.1
Asbestos Containing Materials		✓		6.3.2
Hazardous Substance & Petroleum Products	✓			6.3.3
Storage Tanks			✓	6.3.4
Solid Waste		✓		6.3.5
Odors	✓			6.3.6
Hazardous Waste	✓			6.3.6
Vapor Encroachment	✓			6.3.7
Polychlorinated Biphenyls (PCBs)	✓			6.3.8
Wastewater	✓			6.3.9
Wetlands	✓			6.3.10
Flood Maps	✓			6.3.11

	Acceptable	Corrective Action	Further Investigation	Reference Section
INTERIOR & EXTERIOR OBSERVATIONS				
Radon	✓			**6.3.12**
Air Emissions	✓			**6.3.13**
Stressed Vegetation	✓			**6.3.14**
Stains or Corrosion	✓			**6.3.16**
Heating/Cooling	✓			**6.3.15**
Stains or Corrosion	✓			**6.3.16**
Drains & Sumps	✓			**6.3.17**
Mold	✓			**6.3.18**

1.1 SUMMARY OF FINDINGS

RECOGNIZED ENVIRONMENTAL CONDITIONS

A recognized environmental condition (REC) is defined as the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property 1) due to a release of any hazardous substances or petroleum products; 2) under conditions indicative of a release to the environment; or 3) under conditions that pose a material threat of a future release to the environment. The following was identified during the course of this assessment:

- According to the historical sources reviewed (Fire Insurance maps and city directories), Lot 63 (962 Franklin Avenue) has historically been used for manufacturing purposes. Former identified occupants of the existing single-story warehouse building include a spring manufacturer depicted in the 1951 Fire Insurance (Sanborn map), a metal products manufacturer depicted in the 1963 Sanborn map, and a chemical manufacturer depicted between 1978 and 2007. Per the 1969 Certificate of Occupancy reviewed, the referenced chemical manufacturer produced toiletries such as hair spray, lacquers, rinses, and shampoo. In addition, Arcade Laundry Co. and Star Napkin & Towel Supply Co. were listed in the 1928 city directory. Lot 66 was occupied by Rubel Ice Corp. in the late 1920s and 1930s. All structures associated with Rubel Ice Corp. were demolished before 1951.

  Per the historical Sanborn maps and city directories reviewed, the northern adjoining property (124 Montgomery Street) was occupied by a manufacturer of mattresses and cotton Felts (Burton Dixie Corp.) from as early as 1932 until at least 1951. An additional manufacturing company (Leake Manufacturer Corp.) was listed in the 1960 city directories, and EJK Corp. Aircraft & Machine Division was listed between at least 1965 and 1985. This site was subsequently occupied by M. S. Golombeck Inc.- Spice Importers until at least 2017.

  ALC reviewed a Phase I ESA and Phase II Site Investigation Report prepared by The Elm Group, Inc. (Elm). The report details subsurface investigations conducted at the Subject Property and adjoining northern property on March 21 and 22, 2017. Groundwater was not

encountered during the investigation. The analytical results of the soil samples collected revealed the presence of polycyclic aromatic hydrocarbons (PAHs) and metals (including barium, copper, mercury, zinc, cadmium, and lead) at levels exceeding the New York State Department of Environmental Conservation (NYSDEC) Unrestricted Residential and Restricted Residential Soil Cleanup Objectives (SCOs). However, ELM stated that the contaminants identified did not appear to be related to the former uses of the Subject Property and adjoining northern property but rather a result of non-indigenous fill brought into the Subject Property and adjoining northern property as part of grading/development activities. No fuel oil compounds, volatile organic compounds (VOCs), or semi volatile organic compounds (SVOCs) were identified in the soil samples collected and analyzed.

- No underground or aboveground storage tanks were observed at the Subject Property during the site inspection. However, ALC noted a fuel oil fill port and vent pipe on the northern façade of the small office building in Lot 66, near the northeast corner of the building. Due to unsafe conditions, ALC was not able to inspect the interior of the building. It is unknown if the building has a basement level and whether or not the tank associated with the referenced fill port and vent pipe is still present. Based on the fact that there are no registered tanks associated with the Subject Property, ALC presumes that this potential tank has a capacity of less than 1,100 gallons and therefore was not required to be registered with the NYSDEC. The possible presence of a fuel oil tank inside the building in Lot 66 is considered a REC.

HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITION

An historical recognized environmental condition (HREC) is defined as an environmental condition which in the past would have been considered a *recognized environmental condition*, but which may or may not be considered a *recognized environmental condition* currently. The final decision rests with the environmental professional and will be influenced by the current impact of the historical recognized environmental condition on the property.

- No HRECs associated with the Subject Property were identified during the course of this assessment.

CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITION

Controlled recognized environmental conditions (CRECs) refer to sites that have achieved regulatory closure, where no further remediation is required but residual contamination still exists and the site is subject to some sort of control or use restrictions.

- No CRECs associated with the Subject Property were identified during the course of this assessment.

HISTORICAL REVIEW

- Lot 63

  According to the historical and municipal records reviewed, the subject lot was previously improved with a single-story building constructed sometime between 1888 and 1908, and was previously utilized as the bottling department and barrel storage for Consumers Park Brewery. The lot was redeveloped in the late 1930s with the existing single-story building, which was initially used for spring manufacturing and was subsequently occupied by a manufacturer of metal products. The referenced metal products manufacturer vacated the building prior to 1965. Between at least 1969 and 2007, the subject building was occupied by

a chemical manufacturing company identified in the city directories as Lustray Labs Inc. According to the 1969 Certificate of Occupancy obtained from the NYC Department of Buildings, the referenced chemical manufacturer produced toiletries such as hair spray, lacquers, rinses, and shampoo. The building was subsequently part of M.S. Golombeck- a spice manufacturing and storage facility that operated at the adjacent northern property. Additional tenants listed in the city directories include Arcade Laundry Co. and Star Napkin & Towel Supply Co. in 1928, Stewart & Co. and Doran B.H. Inc. in the early 1960s, Select Beauty Brands Inc. between 1965 and 1970, and Quality Metal Fabricators Inc. in 1985. No other prior uses were identified.

- Lot 66
  According to the historical and municipal records reviewed, the subject lot was previously improved with a four-story building constructed before 1908. The referenced building was occupied by the Rubel Corp. - Ice Division. All structures associated with Rubel Ice Corp. were demolished before 1951, and the subject lot was converted into tennis courts with an associated small office along the southern border of the lot. By 1963, the tennis courts were no longer present, but the small office building is still present. Per the city directories reviewed, Stones Accountants occupied the small office building in 1976. No other prior uses were identified.

ENVIRONMENTAL DATABASE FINDINGS

- The Subject Property was not listed in any of the databases searched by Environmental Data Resources, Inc. (EDR).

STORAGE TANKS/PIPELINES

- No underground or aboveground storage tanks were observed at the Subject Property during the site inspection. However, ALC noted a fuel oil fill port and vent pipe on the northern façade of the small office building in Lot 66, near the northeast corner of the building. The referenced fill port and vent pipe was discussed in the RECs section above.

ASBESTOS CONTAINING MATERIALS

- On July 28, 2017, ALC conducted asbestos testing at 972 Franklin Avenue (Lot 66). The roof membrane and parapet flashing tar of the single-story office building in Lot 66 tested positive for asbestos. A copy of the chain of custody and laboratory results is included in Appendix 15.5.

- Suspect asbestos-containing materials in the form of roofing materials and sheetrock walls and ceilings are present at the existing warehouse building in Lot 63. Access to the roof was not provided and therefore the condition of the roof is unknown. Damaged sheetrock walls and ceilings were observed throughout the warehouse, particularly in the restroom.

LEAD-BASED PAINT

- Commercial buildings are not targeted for the identification of lead-based paint (LBP) and therefore LBP was not addressed.

MOLD

- No visible mold growth was observed at the subject warehouse building during the site visit. The interior of the small office in Lot 66 was not inspected due to unsafe conditions.

VAPOR ENCROACHMENT

- Vapor Encroachment Conditions (VECs) that could not be ruled out were not identified for the Subject Property or surroundings sites within the distances specified by ASTM E2600-10. The EDR Vapor Encroachment Screen report is included in Appendix 15.5.

2.0 INTRODUCTION

The following sections discuss the purpose, scope of services, limitations, and exceptions of assessment, and the information sources and methodology used in the preparation of this report.

2.1 PURPOSE

The purpose of a Phase I ESA is to evaluate a particular property for contamination that might have arisen from past property uses and assess whether any of these uses might have resulted in property contamination.

2.2 DETAILED SCOPE-OF-SERVICES

The purpose of this study was to evaluate past and existing environmental conditions at the Subject Property, including the storage, release, or disposal of hazardous substances on the property. In accordance with the ASTM Standard E1527-21, ALC has conducted the following scope of services:

- Interviews with ownership, operators and occupants;
- Reviews of historical sources of information;
- Reviews of federal, state, and local government records;
- Visual inspections of the facility and adjoining properties;
- Commonly known or reasonably ascertainable information;
- Degree of obviousness of the presence or likely presence of contamination at the property and the ability to detect the contamination;
- Assessments of any specialized knowledge related to environmental concerns at the Subject Property;
- Review of geologic and hydrogeologic literature pertaining to the site vicinity. The purpose of this review was to gain a basic understanding of subsurface conditions at the site;
- Evaluation of any potential sources of off-site contamination within a reasonable distance which may have impacted the site;
- Evaluation of past treatment, recycling, or disposal of hazardous materials on the site. An environmental records search of local, state, and federal environmental files was conducted. A copy of the records search conducted by Environmental Data Resources, Inc. (EDR) is included in Appendix 15.4 of this report;
- An assessment of the relationship of the purchase price to the fair market value of the property, if the property was not contaminated; and
- Recommendations for further study or work at the subject site will be made should potential problem areas be uncovered that could negatively impact property value. The client will be made aware of these conditions as soon as possible if they should arise.

2.3 *Significant Assumptions*

This study is intended to reduce, but not eliminate, uncertainty regarding the potential for recognized environmental conditions in connection with the Subject Property, within reasonable limits of time and cost. It is assumed that the user has provided ALC with any specialized knowledge or experience that is material to recognized environmental conditions in connection with the property, including the reason why the property may have a significantly lower purchase price than comparable properties, if applicable. In general, groundwater flow direction has been determined based on topography in the vicinity of the Subject Property (i.e. the assumption that shallow groundwater flow will follow topography) or on other available resources. No site-specific field measurements of groundwater flow direction (e.g. installation of groundwater monitoring wells) have been performed.

Based on this interpretation, ALC has reviewed regulatory agency information for sites that are located in a presumed up-gradient direction, which based on proximity and knowledge of potential contaminant fate and transport, may present a potential to impact the Subject Property.

2.4 *Limitations and Exceptions*

This assessment meets the requirements of the ASTM Standard E1527-21. The following limitations should be noted:

- Results of this investigation are valid as of the dates on which the investigation was performed;
- A visual inspection for the identification of suspect asbestos containing materials and mold growth was performed only in readily accessible areas of the subject buildings. No samples were collected as part of this assessment; and
- The report has been prepared in accordance with generally accepted environmental methodologies referred to in ASTM E1527-21, and contains all of the limitations inherent in these methodologies. No other warranties, expressed or implied, are made as to the professional services provided under the terms of our contract and included in this report.

2.5 *Special Terms and Conditions*

There are no special terms and conditions for this assessment. ALC's standard terms and conditions are described in Appendix 15.6.

2.6 *User Reliance*

This Phase I ESA report ("the Report") has been prepared for the benefit of and addressed to Franklin Ave Property Owner LLC and such other persons as may be designated by Franklin Ave Property Owner LLC, and their respective successors and assigns, employees and affiliates, and counsel and consultants. The report speaks only as of its date in the absence of a specific written update of the Report.

3.0 SITE DESCRIPTION

This section discusses the site location and description, site vicinity characteristics, description of structures, roads, and other improvements, physical setting, and current uses of the site and adjacent sites.

3.1 LOCATION AND LEGAL DESCRIPTION

Legal Description: Two units of land located in the State of New York, within Kings County, and known as 962 Franklin Avenue and 972 Franklin Avenue. The Subject Property is identified by the NYC Department of Finance as Block 1192 and Lots 63 and 66. A site map is included in Appendix 15.1.

Per the NYC Department of Buildings, the Subject Property is alternatively identified as:

- Lot 63
  962-964 Franklin Avenue, Brooklyn, NY 11225

- Lot 63
  968-994 Franklin Avenue, Brooklyn, NY 11225

3.2 SITE AND VICINITY GENERAL CHARACTERISTICS

Per the NYC Department of City Planning, the Subject Property is zoned R6A: Residential. The general vicinity of the property consists of vacant light industrial buildings, an institutional building known as P.S. 375 Jackie Robinson School, multi-family apartment buildings, and railroad tracks to the immediate west. No heavy manufacturing was observed in immediate proximity to the Subject Property.

3.3 FORMER USE OF THE PROPERTY

Lot 63
According to the historical and municipal records reviewed, the subject lot was previously improved with a single-story building constructed sometime between 1888 and 1908 and was previously utilized as the bottling department and barrel storage for Consumers Park Brewery. The lot was redeveloped in the late 1930s with the existing single-story building, which was initially used for spring manufacturing and was subsequently occupied by a manufacturer of metal products. The referenced metal products manufacturer vacated the building before 1965. Between at least 1969 and 2007, the subject building was occupied by a chemical manufacturing company identified in the city directories as Lustray Labs Inc. According to the 1969 Certificate of Occupancy obtained from the NYC Department of Buildings, the referenced chemical manufacturer produced toiletries such as hair spray, lacquers, rinses, and shampoo. The building was subsequently part of M.S. Golombeck- a spice manufacturing and storage facility that operated at the adjacent northern property. Additional tenants listed in the city directories include Arcade Laundry Co. and Star Napkin & Towel Supply Co. in 1928, Stewart & Co. and Doran B.H. Inc. in the early 1960s, Select Beauty Brands Inc. between 1965 and 1970, and Quality Metal Fabricators Inc. in 1985. No other prior uses were identified.

Lot 66

According to the historical and municipal records reviewed, the subject lot was previously improved with a four-story building constructed before 1908. The referenced building was occupied by the Rubel Corp. - Ice Division. All structures associated with Rubel Ice Corp. were demolished before 1951, and the subject lot was converted into tennis courts with an associated small office along the south border of the lot. By 1963, the tennis courts were no longer present, but the small office building is still present. Per the city directories reviewed, Stones Accountants occupied the small office building in 1976. No other prior uses were identified.

3.4 CURRENT USE OF THE PROPERTY

The Subject Property is currently vacant and is planned to be redeveloped as a multi-family residential building.

3.5 DESCRIPTIONS OF STRUCTURES, ROADS, OTHER IMPROVEMENTS ON THE SITE

The Subject Property consists of two adjoining lots, as described below:

- **Lot 63**

  The subject lot is improved with a slab-on-grade single-story warehouse building, located on a rectangular-shaped parcel of land is approximately 0.3 acres in size. The subject building occupies the entire footprint of the lot.

  The subject building is approximately 12,968 square feet in area and contains a boiler room, restroom, and storage areas. Primary access/egress into the building is via an entrance on Franklin Avenue.

  Per the historical Sanborn maps and municipal records reviewed, the subject building was constructed in the late 1930s. The structural improvements consist of a slab-on-grade foundation with masonry walls and a flat roof. The interior finishes consist of wood framing, exposed brick walls, sheetrock walls and ceilings, and concrete flooring.

  No central heating, ventilation, and air conditioning (HVAC) systems were observed inside the warehouse building. However, ALC observed an inactive natural gas-fired boiler and inactive water heater inside the subject building, as well as a furnace. Per information obtained from a previous Phase I ESA, the referenced boiler previously supplied hot water to the steel chamber located in one of the adjacent northern buildings (Lot 46). Portions of the warehouse appear to have been heated by space heaters.

- **Lot 66**

  The subject lot consists of an irregular-shaped parcel of land that is approximately 1.34 acres in size. The majority of Lot 66 consists of grassed land. A small single-story office building is present on the southern border of the lot. Access to the interior of the building was not provided due to structurally unsafe conditions.

  According to the historical Sanborn maps reviewed, the onsite office building was constructed sometime between 1932 and 1951. The structural improvements consist of masonry walls and a flat roof.

At present, no utilities provided to the Subject Property. However, electricity is provided to the Subject Property area by Consolidated Edison. Domestic water is supplied by the municipal authority and overseen by the Department of Environmental Protection (DEP). Sanitary sewer services are tied into the municipal sewer system. No water wells or septic systems were observed on or in the immediate vicinity of the Subject Property.

3.6 CURRENT USES OF THE ADJOINING PROPERTIES

During the onsite reconnaissance, observations were made of the adjoining properties to identify recognized environmental conditions that have the potential to impact the Subject Property. The following is a list of adjoining properties and a summary of the observations made:

Direction	Name/Descriptions	Address	Topography
North	One vacant industrial split-level five-story building	124 Montgomery Street	The topography of the parcel to the north is up-gradient and at a slightly higher elevation than the Subject Property.
East	Franklin Avenue	-	The topography of the parcel to the east is cross-gradient and at approximately the same elevation as the Subject Property.
	A 4-story institutional building occupied by P.S. 375-Jackie Robinson School	945 Franklin Avenue	
South	Two 6-story multi-family apartment buildings	1015 and 1035 Washington Avenue	The topography of the parcels to the south is down-gradient and at a slightly lower elevation than the Subject Property.
West	Railroad tracks	-	The topography of the parcel to the west is cross-gradient and at approximately the same elevation as the Subject Property.
	One 4-story multi-family apartment building	975 Washington Avenue	
	One vacant lot	995 Washington Avenue	

The current adjoining property uses do not appear to pose an environmental risk to the Subject Property.

4.0 USER PROVIDED INFORMATION

The following information is based upon information provided by the client. The type of information provided can include title records, environmental liens, specialized knowledge, reasons for performing the Phase I ESA, and prior environmental reports.

4.1 TITLE RECORDS

Below is a summary of the records obtained from the NYC Department of Finance (a copy of the most recent deed is provided in Appendix 15.5):

Name of Property Owner	Year Purchased
Lots 63 and 66	
Franklin Ave Property Owner LLC	2017
Lot 63	
The City of New York	1986
HPG Associates, Inc.	1983
Allboro Utility Corp.	1981
Lot 63	
HPG Associates, Inc.	1983
M.J.G Realty Corp.	-

4.2 ENVIRONMENTAL LIENS OR ACTIVITY AND USE LIMITATIONS

The Client did not report the existence of any environmental liens or use limitations for the Subject Property.

4.3 SPECIALIZED KNOWLEDGE

The user of this ESA report is not aware of any activity and use limitations (AULs), such as engineering controls, land use restrictions or institutional controls that are in place at the Subject Property and/or have been filed or recorded in a registry under local, tribal, state, or federal law.

4.4 COMMONLY KNOWN OR REASONABLY ASCERTAINABLE INFORMATION (40 CFR 312.30)

The Client did not report any particular concerns related to environmental issues at the Subject Property.

4.5 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES

No property valuation reduction relating to environmental concerns was reported by the Client.

4.6 OWNER, PROPERTY MANAGER, AND OCCUPANT INFORMATION

During the site reconnaissance, ALC was accompanied by Mr. David Linehan, Developer Manager with The Continuum Company, LLC, who has been associated with the Subject Property for approximately 1.5 years. Per Mr. Linehan, the existing warehouse building in Lot 63 was part of a spice manufacturing and storage facility on the adjoining northern property. The Subject Property is planned to be redeveloped with a 14-story multi-family apartment building.

No areas of concern were reported by Mr. Linehan.

4.7 REASON FOR PERFORMING THE PHASE I

This Phase I ESA is being performed as a part of the due diligence process for the Subject Property. The preparation of the report was requested by the Client.

4.8 DEGREE OF OBVIOUSNESS (40 CFR 312.31)

The user of this Phase I ESA did not report any obvious indicators that point to the presence or likely presence of contamination at the Subject Property.

4.9 PREVIOUS REPORTS

During the preparation of this report ALC reviewed the following previous reports:

1. **Phase I ESA and Phase II Site Investigation (SIR) report for 130 Montgomery Street, Brooklyn, NY 11225 (Block 1192, Lots 41, 46, 43, and 66), prepared by The Elm Group, Inc. (ELM)**

    - At the time of the assessment, the referenced lots consisted of several multi-story buildings including an office building, a former boiler building, a spice warehouse, and spice packaging areas.

    - The Phase I ESA identified ten recognized environmental conditions (RECs) associated with the referenced lots. Based on the findings of the Phase I ESA, on March 21 and 22, 2017, ELM performed a Phase II Site Investigation at the Subject Property and adjacent northern properties to address the identified RECs. Below is a summary of the RECs identified and soil sampling conducted:

      AOC B-2- Kerosene Tanks
      Three 100-gallon kerosene aboveground storage tanks (ASTs) were observed in the boiler room of the two-story building located adjacent to the office building in Lot 46, identified by ELM as Building 2. No staining was observed on or in the immediate vicinity of the ASTs, however, the floor of the boiler room consisted of a dirt floor, and therefore the ASTs were considered a REC.

      One soil boring (SB-23) was advanced adjacent to the ASTs, to a depth of 8 feet below grade surface (bgs). No visual evidence of impacts was observed and no elevated photoionization (PID) readings were recorded. Groundwater was not encountered at this location. One soil sample was collected at a depth of 4.5 feet bgs and analyzed for VOCs, SVOCs, metals, pesticides, and polychlorinated biphenyls (PCBs). No compounds were detected above the NYSDEC Soil Cleanup Objectives (SCOs) for Unrestricted Use. Based on the analytical results, ELM concluded that no further investigation was recommended regarding this REC.

      AOC B-3-Bunkered Oil AST Associated with the Boiler
      As per the report, the office area and one of the fumigation booths of one of the onsite

buildings was heated via an oil-fired boiler located in the former brewery boiler room (Lot 46). Fuel oil was stored in a bunkered concrete-encased AST located beneath a concrete walkway within the former boiler room. ELM was not able to determine whether the bottom of the bunker consisted of concrete or soil. The AST was considered a REC.

One soil boring (SB-22) was advanced adjacent to the AST, to a depth of 12 feet bgs. No visual evidence of impacts was observed and PID readings ranged from 0.1 parts per million (ppm) to 12.7 ppm. Groundwater was not encountered at this location. One soil sample was collected at a depth of 5 feet bgs and analyzed for the NYSDEC Fuel Oil List. No compounds were detected above the NYSDEC SCOs for Unrestricted Use, except for chrysene, which was detected at 1.1 milligrams per kilogram (mg/kg), marginally above the NYSDEC SCOs of 1 mg/kg. The report stated that chrysene was detected in soil samples collected throughout the site. Based on the identified concentrations, the report concluded that the presence of chrysene was not indicative of a release but rather a result of fill material brought into the property for grading/development activities.

OC C-2: Historic Transformer House
Based on a review of historic 1932 and 1951 Sanborn maps, a former transformer house was present in Lot 46, on the northern border of the lot. No indication of the former transformer house was observed during ELM's December 29, 2016 inspection and no pertinent information was provided by the property owner (Mr. Golombeck). The former transformer house was considered a REC.

Two soil borings (SB-5 and SB-13) were advanced in the footprint of the former transformer house, to a depth of 8 feet bgs. No visual evidence of impacts was observed and PID readings ranged from 1.2 ppm to 12.1 ppm. Groundwater was not encountered at this location. Two soil samples were collected at a depth of 0.5 feet bgs at SB-5, and from 2 feet bgs at SB-13. The samples were analyzed for PCBs. Additionally, the sample collected at SB-13 was analyzed for VOCs and metals. No compounds were detected above the NYSDEC SCOs for Unrestricted Use, except for lead, mercury, and nickel, which were marginally above their respective NYSDEC SCOs. The report stated that these compounds were detected in soil samples collected throughout the property. Therefore, based on the identified concentrations, the report concluded that the presence of mercury, lead, and nickel was a result of fill material brought into the property for grading/development activities.

AOC D: Floor Drains in Basement
A total of seven drains were observed within the basements of the onsite 4 and 5-story buildings (Lot 46). Per the information provided by the property owner, the drains were no longer in use and had since been sealed with concrete. ELM was not able to determine whether or not the drains discharged into the municipal system. Based on the fact that Lot 46 were utilized for industrial purposes from as early as the 1900s, the presence of drains was considered a REC.

Seven soil borings (one next to each floor drain) were advanced to a depth of 4 feet bgs and labeled SB-14 - SB-16 and SB-18 - SB-21. No visual evidence of impacts was observed and PID readings ranged from 0 ppm to 14.3 ppm. Groundwater was not encountered at

this location. Soil samples were collected at depths ranging from 0.5 to 3 feet bgs and were analyzed for PCBs, VOCs, and TAL metals. Several Polycyclic Aromatic Hydrocarbons (PAHs), including benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, chrysene, dibenzo(a,h)anthracene, and indeno(1,2,3-CD)pyrene, were detected above the NYSDEC SCO for unrestricted and restricted use in soil boring SB-18. Nickel was detected above the NYSDEC SCO for unrestricted use in soil boring SB-15; and copper, lead, mercury, nickel, and zinc were all detected above the NYSDEC SCO for unrestricted use, except for mercury which also exceeded the SCO for restricted use.

The report concluded that the compounds identified were a result of fill material brought into the property for grading/development activities.

AOC E-2: Dry Well in Basement
A possible dry well was identified in the basement of one of the buildings located within Lot 46. A metal plate was covering the dry well, which hindered a thorough inspection of the well. ELM was not able to obtain any information pertaining to the potential dry well or its historical uses. The potential dry well was considered a REC.

One soil boring (SB-17) was advanced adjacent to the dry well, to a depth of 8 bgs. No visual evidence of impacts was observed and PID readings ranged from 4 ppm to 9.4 ppm. Groundwater was not encountered at this location. One soil sample was collected at a depth of 6 feet bgs and analyzed for VOCs, TAL metals, and PCBs. No compounds were detected above the NYSDEC SCOs, except for mercury and nickel. Mercury was detected above the NYSDEC SCOs Unrestricted and Restricted Uses, and Nickel was detected above the Unrestricted Use. The report stated that these two compounds were detected in soil samples collected throughout the property and therefore, based on the identified concentrations, the presence of mercury and nickel was a result of fill material brought into the property for grading/development activities.

AOC H-3: Historic Boiler Room Associated with the Former Brewery Operations
Per the historical Sanborn maps reviewed and information provided by the property owner, a larger boiler room associated with the former onsite brewery operations was formerly located in one of the buildings located in Lot 46. Mr. Golombeck stated that several large tanks previously located in the boiler room were removed when the property was converted into a spice factory. Three 100-gallon kerosene ASTs were observed in the boiler room. No staining was observed on or in the immediate vicinity of the ASTs, however, the floor of the boiler room consisted of a dirt floor, which presented the potential for a discharge of hazardous materials to the subsurface. At the time of the site visit, the boiler room was used for storage of construction materials and small chemical containers including paints, greases, and sealants. The boiler room was considered a REC.

Two soil borings (SB-23 and SB-24) were advanced in the former boiler room adjacent to the kerosene ASTs and empty drum storage area, to a depth of 8 feet bgs. No visual evidence of impacts was observed and no elevated PID readings were recorded. Groundwater was not encountered at this location. One soil sample was collected at a depth of 4.5 feet bgs in SB-23. The sample was analyzed for the NYSDEC Fuel Oil List. No compounds were detected above the NYSDEC SCOs for Unrestricted Use. Based on the

analytical results, ELM concluded that no further investigation was recommended regarding the former boiler room.

AOC H-4: Historic Boiler Room Associated with the Former Ice Manufacturing Operations
Per the 1932 Sanborn maps reviewed, a boiler room associated with the former operations of Rubel Corporation was present in Lot 66. No specific information regarding this boiler room was located and there were no indications of this former boiler during Elm's site visit in 2016. The former boiler room was considered a REC.

Two soil borings (SB-1 and SB-2) were advanced in the footprint of the former boiler room, along the eastern property boundary, to a depth of 4 feet bgs. No visual evidence of impacts was observed and PID readings ranged from 0.5 ppm to 8.8 ppm. Groundwater was not encountered at this location. One soil sample was collected from SB-2, at a depth of 1-foot bgs. The sample was analyzed for the NYSDEC Fuel Oil List. No compounds were detected above the NYSDEC SCOs for Unrestricted Use. Based on the analytical results, ELM concluded that no further investigation was recommended regarding the former boiler in Lot 66.

AOC K: Historic Coal Shed and Storage Area
A former coal shed and storage area was identified on the 1908 Sanborn map. The referenced coal shed and storage area was formerly located in Lot 46, immediately north of the former brewery boiler room. No indications of this former area were identified during ELM's December 2016 site visit. The former coal shed and storage area was considered a REC.

Four soil borings (SB-8 and SB-11) were advanced in the footprint of the former coal shed and storage area to a depth of 8 feet bgs. No visual evidence of impacts was observed and no elevated PID readings were recorded. Groundwater was not encountered at this location. One soil sample was collected from SB-9 at a depth of 1.5 feet bgs. Several PAHs, including benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, chrysene, dibenzo(a,h)anthracene, and indeno(1,2,3-CD)pyrene, were detected above the NYSDEC SCO for Unrestricted and Restricted Uses. In addition, several metals including barium, copper, mercury, and zinc were detected above the NYSDEC SCO for Unrestricted Use, and cadmium and lead were detected above the NYSDEC SCO for Restricted Use.

The report concluded that the compounds identified were a result of fill material brought into the property for historic grading/development activities.

AOC L: Former Engine Room/Machine Shop
A former engine room/machine shop was identified on the 1932 and 1951 Sanborn maps. The engine room/machine shop was formerly located in the spice storage area at the time of Elm´s assessment, adjacent to the office building (Lot 46). No indications of this former engine room/machine shop were identified during ELM's December 2016 site visit. The former engine room/machine shop was considered a REC.

Two soil borings (SB-6 and SB-7) were advanced along the northern exterior wall of the

former engine room/machine shop to a depth of 12 feet bgs. No visual evidence of impacts was observed and PID readings ranged from 0 ppm to 10.8 ppm. Groundwater was not encountered at this location. One soil sample was collected from each soil boring at a depth of 1-foot bgs. The samples were analyzed for TAL metals. Lead, nickel, and zinc were detected above the NYSDEC SCO for Unrestricted Use, and mercury was detected above Unrestricted and Restricted Use in SB-6. Lead, mercury, and zinc exceeded the NYSDEC SCO for Unrestricted Use in SB-7.

The report concluded that the compounds identified were a result of fill material brought into the property for historic grading/development activities.

AOC O: Brick Smoke Stack
A brick smoke stack was observed adjacent to the former brewery boiler room during ELM's December 2016 site visit (Lot 46). According to Mr. Golombeck, the smoke stack had been out of use for many years. No staining or evidence of a release was identified on or in the immediate vicinity of the smoke stack. However, no information was available regarding the use or age of the smoke stack. The former smoke stack was considered a REC.

One soil boring (SB-9) was advanced adjacent to the smoke stack to a depth of 8 feet bgs. No visual evidence of impacts was observed and no elevated PID readings were recorded. Groundwater was not encountered at this location. One soil sample was collected at a depth of 1.5 feet bgs and analyzed for PAHs and TAL metals. Several PAHs, including benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, chrysene, dibenzo(a,h)anthracene, and indeno(1,2,3-CD)pyrene, were detected above the NYSDEC SCO for Unrestricted and Restricted Uses. In addition, several metals including barium, copper, mercury, and zinc were detected above the NYSDEC SCO for Unrestricted Use, and cadmium and lead were detected above the NYSDEC SCO for Restricted Use.

The report concluded that the compounds identified were a result of fill material brought into the property for grading/development activities.

AOC P- Historic Fill
The report stated that several compounds were detected in samples collected throughout the subject lots at concentrations exceeding the NYSDEC Unrestricted Residential and Restricted Residential SCOs. The exceedances were limited to PAHs and metals, which according to ELM, did not appear to be related to an operational release at the subject lots, but were likely the result of non-indigenous fill brought in as part of grading/development activities.

ELM stated that based on the location of the subject lots and the fact that groundwater was not encountered in the deepest soil borings installed to 12 feet bgs, there was a limited risk of impacts to groundwater from the detected metals and PAHs. VOCs were not detected in any of the soil samples collected and therefore vapor intrusion was not a concern. Based on the facts mentioned above, EML concluded that the only exposure pathway was through direct contact with onsite soils. ELM stated that this pathway could be addressed through soil removal and regrading activities as part of future development

of the subject lots, or through the implementation of engineering and institutional controls.

2. **Phase I ESA report for 130 Montgomery Street, Brooklyn, NY 11225 (Block 1192, Lots 41, 46, 43, and 66), prepared by ALC Environmental, dated September 12, 2017**

- Lot 63 (962 Franklin Avenue) was described as a 0.3-acre rectangular-shaped parcel improved with a single-story warehouse building. At the time of the assessment, the referenced building was used for storage and was connected to the adjacent four-story building in Lot 46.

- Lot 66 (972 Franklin Avenue) was described as a 1.34-acre irregular-shaped parcel of land comprising a small single-story structure located in the southeast section of the lot. The remainder of the parcel consisted of a vacant, grassed land.

- The following RECs were identified:
  - The report stated that the Subject Property and adjacent Lots 41 and 46 were used for industrial/manufacturing purposes from as early as the 1900s. Former identified tenants included Consumers Park Brewery, Rubel Corp. Ice Division, Burton Dixie Corp. - Manufacturers of Mattresses and Cotton Felts, a spring manufacturing facility, metal products manufacturing, and a chemical manufacturing facility. Per the Phase I ESA and Phase II Site Investigation Report prepared by ELM, dated 2017, soil contaminants were identified at the Subject Property and adjacent Lots 41 and 46 at concentrations exceeding the NYSDEC Unrestricted Residential and Restricted SCOs. The exceedances were limited to PAHs including benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, chrysene, dibenzo(a,h)anthracene, and indeno(1,2,3-CD)pyrene, and metals (lead, mercury, cadmium, nickel, barium, copper, and zinc). VOCs were not detected in any of the soil samples collected and therefore, ELM concluded that vapor intrusion was not a concern at the Subject Property and adjacent northern lots.

    Based on the concentrations of contaminants detected and areas impacted, ELM determined that the contaminants identified did not appear to be related to an operational release at the Subject Property but rather a result of non-indigenous fill brought into the Subject Property as part of former grading/development activities.

- On July 28, 2017, ALC conducted asbestos surveys at the Subject Property. The roof membrane (asphalt roll) and flashing tar of the single-story building in Lot 66 tested positive for asbestos.

- No underground or aboveground fuel oil storage tanks were observed at the Subject Property.

- On July 29 and August 2, 2017, ALC conducted testing of window caulking material found in the onsite buildings for the presence of PCBs. A total of 13 samples were collected and submitted for laboratory analysis. None of the samples collected yielded results above the

regulatory standard of 50 ppm for PCBs in window caulking.

5.0 RECORDS REVIEW

5.1 STANDARD ENVIRONMENTAL RECORD SOURCES

ALC conducted a review of the regulatory status of the Subject Property and surrounding properties within a 1-mile radius as it pertains to regulated activities involving the use of hazardous chemicals; the generation of hazardous waste; the treatment, storage, or disposal of hazardous waste; or the release of regulated substances. ALC utilized EDR to conduct the appropriate searches of federal and state sites identified within the radii specified by ASTM 1527-13.

- **The Subject Property was not listed in any of the databases searched by EDR.**

The following is a summary of the databases reviewed for this assessment. The regulatory database report is provided in Appendix 15.4:

Database	Search Radius	Site Listed	Adjacent	0-1/8 miles	1/8-¼ miles	¼-½ miles	½-1 miles
Federal Databases							
NPL	1 mile	No	0	0	0	0	0
ROD	1 mile	No	0	0	0	0	0
Delisted NPL	½ mile	No	0	0	0	0	
SEMS	½ mile	No	0	0	0	0	
CORRACTS	1 mile	No	0	0	0	0	0
RCRA LQG	¼ mile	No	0	0	5		
RCRA SQG	¼ mile	No	0	0	2		
RCRA VSQG	¼ mile	No	1	0	3		
RCRA NonGen/NLR	¼ mile	No	2	18	34		
ERNS	Site	No					
FINDS	Site	No					
State Databases							
UST	¼ mile	No	0	5	27		
AST	¼ mile	No	2	7	46		
CBS AST	¼ mile	No	0	0	1		
LTANKS	½ mile	No	0	1	14	29	
NY SHWS	1 mile	No	0	0	0	0	0
ENG CONTROLS	½ mile	No	0	0	0	1	
INST CONTROLS	½ mile	No	0	0	0	1	
NY Spills	⅛ mile	No	3	15			
NY E Designation	⅛ mile	No	0	12			
NY VCP	½ mile	No	0	0	2	0	
BROWNFIELDS	½ mile	No	0	1	0	2	
SWF/LF	½ mile	No	0	1	2	2	
SWRCY	½ mile	No	0	0	0	1	
DRYCLEANERS	¼ mile	No	0	1	3		

Database	Search Radius	Site Listed	Adjacent	0-1/8 miles	1/8-¼ miles	¼-½ miles	½-1 miles
State Databases							
NY MANIFEST	¼ mile	No	3	21	46		
NJ MANIFEST	¼ mile	No	0	7	9		
PA MANIFEST	¼ mile	No	0	0	3		
EDR Property Records							
MGP	1 mile	No	0	0	0	0	2
Hist Cleaners	⅛ mile	No	0	1			
EDR Hits Auto	⅛ mile	No	0	1			

5.1.1 FEDERAL RECORDS

National Priority List (NPL)
The NPL is the Environmental Protection Agency's (EPA) database of some of the most serious uncontrolled or abandoned hazardous waste sites identified for potential remedial action under the Superfund Program. These sites may constitute an immediate threat to human health and the environment. Due to the amount of public attention focused on NPL sites, they pose a significant risk of stigmatizing surrounding properties and potentially impacting property values.

- The search did not identify any NPL sites within a 1.0-mile radius of the Subject Property.

Superfund Enterprise Management System (SEMS)
SEMS is a compilation of hazardous wastes sites, potentially hazardous wastes sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly known as the Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS), renamed to SEMS by the EPA in 2015. In addition, SEMS lists sites that are either proposed to or on the NPL, or sites that are in the screening and assessment phase for possible inclusion on the NPL.

- No SEMS sites were identified within a 0.5 mile radius of the Subject Property.

Resource Conservation and Recovery Act (RCRA)
The RCRA database is compiled by the EPA and contains notification, permitting, compliance, and corrective action data on facilities that generate, transport, store, treat, and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Facilities that receive hazardous waste from generators and other facilities for treatment, storage, or disposal of waste are known as TSDF's.

- The adjacent eastern property, identified as Intermediate School 320K at 46 Mckeever Place, was listed in the RCRA-VSQG (Very Small Quantity Generators) database. Listed wastes associated with this site include ignitable and corrosive wastes. There are reported violations associated with this site. The areas of violation are described as "Listing-General" and "Universal Waste-Small Quantity Handlers". Written Informal enforcement actions were issued and compliance was issued on all violations.
- Consolidated Edison Manhole 47218 located in front of 975 Washington Avenue (adjacent to the west), was listed in the RCRA-NonGen/NLR (Non-Generators/No Longer Regulated) database. There are no reported violations. In addition, RCRA-NonGen/NLR sites do not presently generate any hazardous waste.

- Consolidated Edison Manhole 26211 located at 1003 Franklin Avenue (adjacent to the east), was listed in the RCRA-NonGen/NLR database. There are no reported violations. In addition, RCRA-NonGen/NLR sites do not presently generate any hazardous waste.
- None of the remaining adjacent properties were identified as RCRA facilities, however the search identified five RCRA-LQG (Large Quantity Generators), two RCRA-SQG (Small Quantity Generators), three RCRA-VSQG (Very Small Quantity Generators), and 52 additional RCRA-NonGen/NLR facilities within a 0.25-mile radius of the Subject Property. There is a violation associated with one of the RCRA-NonGen/NLR sites (Brooklyn Botanic Gardens-1000 Washington Avenue). The area of violation is described as "Used Oil-Generators". Per the site status, the action was satisfied. Based on the compliance achieved, no further action is warranted.
- There are no reported violations associated with any of the listed sites located within a 0.125-mile radius of the Subject Property. No further action or investigation is recommended.

CORRACTS
CORRACTS is a list of handlers with RCRA Corrective Action Activity.

- The search did not identify any CORRACTS site within a 1-mile radius of the Subject Property.

5.1.2 STATE RECORDS

Underground Storage Tanks (UST)
The UST database is compiled by the NYSDEC, and contains an inventory of facilities with petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

- The search did not identify any registered USTs associated with the adjacent properties. No further action or investigation is recommended.

Aboveground Storage Tanks (AST)
The AST database is compiled by the NYSDEC and contains an inventory of registered aboveground storage tanks. The AST database lists facilities with aboveground petroleum storage capacities in excess of 1,100-gallons and less than 400,000 gallons.

- One of the adjacent southern properties, known as 1015 Washington Avenue, was listed regarding an active 5,000-gallon No. 2 fuel oil AST reportedly installed on April 1, 1942. The tank is properly registered with the NYSDEC under Petroleum Bulk Storage (PBS) No. 2-605904 and the tank registration expires in May 2021. There are no reported releases associated with this tank. Based on the lack of reported releases and the fact that the tank is located aboveground and visually acceptable, no further action or investigation is warranted regarding this listing.
- The remaining adjacent property to the south, known as 1035 Washington Avenue, was listed on the AST database regarding an active 5,000-gallon No. 4 fuel oil AST reportedly installed on December 31, 1932. The tank is properly registered with the NYSDEC under PBS No. 2-205222, and the tank registration expires in July 2023. There are no reported releases associated with this tank. Based on the lack of reported releases and the fact that the tank is located aboveground and visually acceptable, no further action or investigation is warranted regarding this listing.

- One of the adjacent western properties, known as 975 Washington Avenue, was listed regarding an active 3,000-gallon No. 2 fuel oil AST reportedly installed on July 1, 1950. The tank is properly registered with the NYSDEC under PBS No. 2-148148, and the tank registration expires in 2026. There are no reported releases associated with this tank. Based on the lack of reported releases and the fact that the tank is located aboveground and visually acceptable, no further action or investigation is warranted regarding this listing.
- The search did not identify any registered ASTs associated with the adjacent properties. No further action or investigation is recommended.

Chemical Bulk Storage (CBS)
These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

- The search identified one NY CBS site within a 0.25-mile radius of the Subject Property. The listed site, located at Central Laundry Corp.- 46 Crown Street, is approximately 0.1-mile away and up-gradient from the Subject Property. Online records indicate that the former building at this location has been razed and that the site is currently a vacant lot. Based on the distance, no significant impacts to the Subject Property are anticipated from this site.

Leaking Storage Tanks (LTANKS)
The LTANKS database is compiled by the NYSDEC and contains an inventory of leaking aboveground or underground tanks reported since April 1, 1986. The causes of the incidents are tank test failures, tank failure, or overfill.

- None of the adjacent properties were listed, however the search identified 44 NY LTANKS sites within a 0.5-mile radius of the Subject Property. Further review indicates that all 44 listed sites have been granted a 'case closed' status. The regulatory agency awards a 'case closed' status only when contamination, if any, has been investigated and/or remediated in accordance with currently accepted regulatory standards.
- The listed NY LTANKS sites are located over 400 feet away. Based on a combination of factors such as information reviewed, topographic relations, distances, and regulatory closure, no impacts to the Subject Property are anticipated from the listed NY LTANKS sites.

Spills Information Database (NY Spills)
The NY Spills database contains data regarding chemical and petroleum spill incidents reported to the NYSDEC. It includes spills that took place from April 1, 1986, to the present.

- There are two listings associated with the adjacent eastern property, identified as Intermediate School 320K at 46 Mckeever Place, as described below:
    - The first incident was reported on May 25, 1993, due to equipment failure (Spill No. 9302528). Per the database, approximately 2 gallons of No. 6 fuel oil spilled due to faulty plumbing. Cleanup was completed by a custodian and this spill case was closed by the NYSDEC on May 25, 1993. Based on the small amount of product released, no impacts to the Subject Property are anticipated from this incident.
    - The second incident was reported on reported on May 18, 2021 due to equipment failure (Spill No. 2101518). Per the database, there was a temporary boiler with a 10,000-gallon AST in the Street. One of the valves was leaking, causing approximately 3 gallons of No.

2 fuel oil to spill. The valve was repaired and the leak was cleaned. No drains were impacted. This spill case was closed by the NYSDEC on September 13, 2021 . Based on the small amount of product released, no impacts to the Subject Property are anticipated from this incident.

- One of the western adjacent properties, known as 975 Washington Avenue, was listed twice in the NY Spills as described below:
  - The first incident pertains to abandoned drums at this location, reported on November 27, 2000 (Spill No. 0009713). Per the database, approximately 10 gallons of waste oil/used oil spilled from a drum, however no drums were observed during a site visit conducted by a NYSDEC representative on May 15, 2001. Therefore, this spill case was closed. It appears that this spill incident was reported twice (please refer to Spill No. 0009733 below).
  - The second incident also pertains to abandoned drums and was also reported on November 27, 2000 (Spill No. 0009733). Per the database, a caller reported finding an approximately 20-gallon drum at this location. However, at the time it did not appear that the drum was leaking. No drums were observed during a site visit conducted by a NYSDEC representative on May 27, 2003 and therefore this spill case was closed. Based on the information reviewed, no significant impacts to the Subject Property are anticipated from this listing.
- One of the southern adjacent properties, known as 1035 Washington Avenue, was listed regarding an incident reported on May 11, 2017 (Spill No. 1701355). Per the database, NYC Tank Testing (NYCTT) was contacted after oil was observed in an open excavation at this location. The spill was believed to be from a historical overfill. The defective fill line was identified and replaced. Petroleum contamination from an unknown source was found at this site during excavation. NYCTT excavated all contaminated concrete and soil along the old line until all contamination had been removed. A total of one hundred and seven fifty-five 55-gallon drums of contaminated soil were removed and properly disposed of. Between July 25 and 26, 2017 NYCTT began collecting post-excavation soil samples. A total of five (5) composite samples were collected to a depth of 7 to 8 feet below grade surface (bgs) and submitted for analysis. The sampling was biased toward any possible staining or residual product. The analytical results of the soil sampling conducted revealed that VOCs and SVOCs were not detected or below the NYSDEC CP-51 standards. Therefore, this spill case was closed by the NYSDEC on September 25, 2017. Based on the remedial work completed, the analytical results of the soil sampling conducted, and the fact that this site is located down-gradient from the Subject Property, no further action or investigation is warranted.
- None of the remaining adjacent properties were listed, however the search identified 16 additional NY Spills sites within a 0.125-mile radius of the Subject Property. Further review indicates that all 16 listed sites have been granted a 'case closed' status.
- The nearest listed site is located at 955 Washington Avenue, approximately 187 feet to the northwest and up-gradient from the Subject Property. This spill incident was reported on May 22, 1996. Per the database, a hydraulic hose break on a contractor´s truck caused hydraulic oil to spill into a gutter. The spill was contained and prevented from going into the sewer. Cleanup was conducted by the spiller. This spill case was closed by the NYSDEC on May 23, 1996. Based on the nature of the spill, no impacts to the Subject Property are anticipated from this incident.

- The next listed site was identified as Manhole 4709 at Franklin Avenue neat Sullivan Place, approximately 199 feet to the south and down-gradient from the Subject Property. This incident was reported on December 15, 2005 (Spill No. 0510798). Per the database, one pint of unknown oil was found on 200 gallons of water inside the manhole. No sewers, waterways, or private property were affected. Cleanup was completed by Consolidated Edison and this spill case was closed by the NYSDEC on January 10, 2008. Based on the fact that no waterways or private property were impacted, no impacts to the Subject Property are anticipated from this incident.
- The next spill incident was reported at Franklin Street and Sullivan Place, approximately 200 feet to the south and down-gradient from the Subject Property. This incident was reported on January 6, 1997 due to equipment failure associated with Consolidated Edison (Spill No. 9612030). Per the database, approximately one gallon of cable oil spilled when the cable was cut. Cleanup was completed by Consolidated Edison and this spill case was closed by the NYSDEC on January 10, 2008. Based on the fact that no waterways or private property were impacted, no impacts to the Subject Property are anticipated from this incident.
- The next spill incident is associated with Manhole M4785 at Washington Avenue and Sullivan Place, approximately 289 feet to the south-southwest and down-gradient from the Subject Property. This incident was reported on October 4, 2005 due to equipment failure associated with Consolidated Edison (Spill No. 0508015). Per the database, approximately 2 quarts of unknown oil were found inside the manhole. The source of the spill is unknown. No sewers, waterways, or private property were affected. Cleanup was completed by Consolidated Edison and this spill case was closed by the NYSDEC on January 10, 2008. This spill case was closed by the NYSDEC on December 1, 2005. Based on the fact that no waterways or private property were impacted and small amount of product released, no impacts to the Subject Property are anticipated from this incident.
- The remaining listed NY Spills sites are located over 350 feet away. Based on the regulatory closure, information reviewed, and distance, no impacts to the Subject Property are anticipated from the remaining listed sites.

State Hazardous Waste Sites (SHWS)
The SHWS program, also referred to as the State Superfund Program, is the cleanup program for inactive hazardous waste and now includes hazardous substances sites. These sites may or may not already be listed on the federal CERCLIS list.

- None of the adjacent properties were listed, however, the search identified six SHWS listings within a 1-mile radius of the Subject Property. The listed sites are located approximately 0.25 to 0.7 miles away and either cross or down-gradient from the Subject Property. Based on the respective distances and topography, no impacts to the Subject Property are anticipated from the listed sites.

Engineering Controls (ENG CONTROLS) and Institutional Controls (INST CONTROL)
Environmental Remediation sites that have engineering and institutional controls in place.

- None of the adjacent properties were listed, however, the search identified one ENG CONTROLS and INST CONTROL site within a 0.5-mile radius of the Subject Property. The listed site, identified as 1519-1535 Bedford Avenue, is approximately 0.46 mile away. Based on the distance, and engineering and institutional controls in place, no impacts to the Subject

Property are anticipated from the listed site.

NY BROWNFIELDS

A Brownfields site is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

- None of the adjacent properties were listed in the NY Brownfields database, however, the search identified three NY Brownfields sites within a 0.5-mile radius of the Subject Property.
- The nearest listed site, identified as Con Edison Manhole 64993 at 73 Empire Boulevard, is approximately 450 feet to the southeast and down-gradient of the Subject Property. Per the database, the site was historically occupied by automotive repair facilities and a Laundromat. Information submitted with the BCP application regarding the environmental conditions at the site are currently under review and will be revised as additional information becomes available. However, soil vapor impacts from this site are not anticipated since the site is located over the critical distance of 100 feet for down-gradient sites, as specified by ASTM International Practice 2600-10. As such, no further action or investigation is warranted in regards to this listing.
- The remaining listed sites are located approximately 0.34 and 0.46 miles away. Based on the respective distances, no impacts to the Subject Property are anticipated from the listed sites.

Voluntary Cleanup Program (VCP)

New York established its VCP to address the environmental, legal, and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance the private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites. The search did not identify any dry cleaning facilities within the study radius.

- None of the adjacent properties were listed, however, the search identified 2 NY VCP sites within a 0.5-mile radius of the Subject Property. The listed sites (54 Crown Street and 931 Carroll Street) are located approximately 0.12 to 0.2 miles away. Based on the respective distances, no impacts to the Subject Property are anticipated from the listed NY VCP sites.

E Designation Site Listing (E DESIGNATION)

The E (Environmental) designation ensures that sampling and remediation take place on the subject properties, in order to avoid any significant impacts related to hazardous materials at these locations. Prior to issuance of a permit by the Department of Buildings, the Property Owners are required to conduct a testing and sampling protocol and remediation where appropriate. The (E) designation also includes a mandatory construction-related health and safety plan, which must be approved by NYCDEP.

- The search identified one NY E-Designation site within a 0.125-mile radius of the Subject Property. The listed site, known as 135 Montgomery Street (Block 1190, Lot 50), is approximately 389 feet to the north and up-gradient from the Subject Property. This site was assigned the following E-Designations in 2018, in support of a request to rezone portions of the lot: Air Quality- HVAC fuel limited to natural gas, Exhaust stack location limitations, and Hazardous Materials* Phase I and Phase II Testing Protocol. The referenced E Designations point to potential subsurface contamination and indoor air impacts at the assigned sites.

However, based on the distance and the presence of a road and buildings in between this site and the Subject Property, no significant impacts to the Subject Property are anticipated from this site.

Solid Waste Facilities/ Landfill Sites in New York State (SWF/LF)
SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

- The search did not identify any NY SWF/LF sites within a 0.5-mile radius of the Subject Property.

DRYCLEANERS
A listing of registered dry cleaning facilities.

- None of the adjacent properties were listed, however four NY DRYCLEANERS were identified within a 0.25-mile radius of the Subject Property. The nearest listed site, identified as Garden Cleaners at 96 Montgomery Street, is approximately 334 feet to the northwest and up-gradient from the Subject Property. Per the records, this facility began operating in 1994. The last inspection was completed on November 19, 2003. The records indicate that the facility has closed. There are no reported releases or violations.
- The remaining listed sites are located approximately 0.127 to 0.231 miles away. The records indicate that one of the facilities (46 Crown Street) has closed. There are no reported releases or violations associated with the listed sites.

Facility and Manifest data (NY, NJ & PA MANIFEST)
The manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

- A Consolidated Edison site at 1003 Franklin Avenue (adjacent to the east) was listed in the NY MANIFEST database. The listing pertains to 150 gallons of lead waste (waste code D008) removed from this site in 2014. There are no reported violations.
- Consolidated Edison Manhole 47218 located in front of 975 Washington Avenue (adjacent to the west), was listed in the NY MANIFEST database. There are no reported violations.
- Consolidated Edison Service Box 47218 at 995 Washington Avenue (adjacent to the west) was listed in the NY MANIFEST database. There are no reported violations.
- The search did not identify any additional MANIFEST sites associated with the remaining adjacent properties. Based on the nature of the MANIFEST database, which is not necessarily indicative of an environmental concern but rather the types of activities occurring, the listed NY, NJ, and PA MANIFEST sites are not considered to represent an environmental concern.

5.1.3 EDR Property Records

Manufactured Gas Plants (MGP)
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as

fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

- None of the adjacent properties were listed, however, the search identified two MGP facilities within a 1.0-mile radius of the Subject Property. The two listed sites (Flatbush Station A and B) are approximately 0.8 and 0.85 miles away and down-gradient from the Subject Property. Given the respective distances and down-gradient locations, no impacts to the Subject Property are anticipated from the listed sites.

US Historical Auto Stations (EDR Hist Auto)
A listing of potential gas station/filling station/service station sites that were compiled by EDR through a search of national business directories. This database falls within a category of information EDR classifies as "High Risk Historical Records".

- The search identified one EDR Hist Auto site within a 0.125-mile radius of the Subject Property. The listed site, known as 100 Empire Boulevard, is approximately 0.14 mile to the southeast and down-gradient of the Subject Property. Per the database, automotive repair shops were present at this location between 1982 and 1997. However, soil vapor impacts from this site are not anticipated since the site is located over the critical distance of 100 feet for down-gradient sites, as specified by ASTM International Practice 2600-10. As such, no further action or investigation is warranted regarding this listing.

Historical Cleaners (EDR Hist Cleaner)
EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry, etc.

- The search identified one EDR Hist Cleaners within a 0.125-mile radius of the Subject Property. The listed site, identified as Garden Cleaners at 96 Montgomery Street, is approximately 334 feet to the northwest and up-gradient from the Subject Property. The records indicate that Garden Cleaning operated at this site between 1986 and 1996. This site was cross-listed in the NY DRYCLEANERS database. The records indicate that this facility was last inspected on November 19, 2003 and that the facility has been closed. There are no reported releases or violations. Based on the distance, and the presence of buildings and a road in between this site and the Subject Property, no significant impacts to the Subject Property are anticipated from this site.

5.2 ADDITIONAL ENVIRONMENTAL RECORD SOURCES

1. ALC reviewed online records maintained by the NYSDEC for information concerning the Subject Property. The records reviewed did not identify any information pertaining to the Subject Property on the state databases related to spill incidents or site remediation.

2. NYC Department of Buildings (DOB) records were reviewed to determine whether there were any violations or other conditions that would pose an environmental risk to the Subject Property. The following pertinent records were located:

   Lot 63

   - A demolition permit issued in 1939.
   - A Certificate of Occupancy issued in July 1969 describes the existing single-story building as a manufacturer of toiletries (hair spray, lacquers, rinses, and shampoo).
   - A demolition permit submitted on April 25, 2018.
   - No boiler records were located.

   Lot 66

   - A demolition permit submitted on April 25, 2018.

   Copies of the documents reviewed were provided in Appendix 15.5.

3. ALC reviewed the New York City Department of Environmental Protection Citywide Planning for Zoning and E-designation site list. The Subject Property is not listed as having any E-designations. A zoning map is provided in Appendix 15.1.

4. ALC reviewed online records maintained by the NYC Office of Environmental Remediation-Searchable Property Environmental E-Database (SPEED). No Voluntary Cleanup Program/Brownfields or hazardous waste sites were identified in the vicinity of the Subject Property.

5.3 PHYSICAL SETTING SOURCE

ALC reviewed the USGS Brooklyn, NY 15 Minute Series topographic map dated 1897 through 1900, and USGS Brooklyn, NY 7.5 Minute Series topographic map dated 1947 through 2019, to determine physical setting information associated with the Subject Property. Representative copies of the topographic maps reviewed are included in Appendix 15.3.

5.4 HISTORICAL USE INFORMATION ON THE PROPERTY AND ADJOINING PROPERTIES

Historical use information is based on a review of the following:

- Historical aerial photographs (1924, 1951, 1954, 1961, 1966, 1974, 1976, 1980, 1984, 1994, 2006, 2011, 2015, and 2019).
- Sanborn maps (1908, 1932, 1951, 1963, 1965, 1978, 1979, 1980, 1982, 1987, 1988, 1989, 1991, 1992, 1993, 1994, 1995, 2001, 2002, 2003, 2004, 2005, 2006, and 2007).
- Topographic maps (1897, 1898, 1900, 1947, 1956, 1966, 1979, 1997, 2013, 2016 and 2019).
- City directories (1928, 1934, 1940, 1945, 1949, 1960, 1965, 1970, 1973, 1976, 1980, 1985, 1992, 1994, 1997, 1999, 2000, 2004, 2005, 2009, 2014, and 2017).

The historical data is provided in Appendix 15.3.

5.4.1 AERIAL PHOTOGRAPHS

1924

- **Subject Property:** Lot 63 is improved with an apparent industrial building. Several commercial/industrial structures are depicted in Lot 66.
- **Offsite:** Apparent industrial buildings are depicted to the north. Franklin Avenue is depicted to the immediate east, followed by a few small residential and commercial buildings, and vacant lots. Apparent residential buildings fronting Franklin Avenue and vacant lots are depicted to the south. Railroad tracks are depicted to the immediate west, followed by vacant land.

1951-1954

- **Subject Property:** Lot 63 is improved with the existing industrial building. Lot 66 consists of a vacant lot, with the exception of a small commercial building on the southernmost border of the lot.
- **Offsite:** Apparent industrial buildings are depicted to the north. Franklin Avenue is depicted to the immediate east, followed by a few small residential and commercial buildings, a relatively large industrial building, and vacant lots. Multi-family apartment buildings are depicted to the south. Railroad tracks are depicted to the immediate west, followed by a multi-family apartment building and a vacant lot.

1961

- **Subject Property:** Lot 63 is improved with the existing industrial building. Lot 66 appears to be used for parking. Several vehicles are depicted on the lot. A small commercial building is depicted on the southernmost border of the lot.
- **Offsite:** Apparent industrial buildings are depicted to the north. Franklin Avenue is depicted to the immediate east, followed by a few small residential and commercial buildings, a relatively large industrial building, and vacant lots. Multi-family apartment buildings are depicted to the south. Railroad tracks are depicted to the immediate west, followed by a multi-family apartment building and a vacant lot.

1966

- **Subject Property:** No changes are depicted relative to the 1961 aerial photograph.
- **Offsite:** Apparent industrial buildings are depicted to the north. Franklin Avenue is depicted to the immediate east, followed by a vacant lot. Multi-family apartment buildings are depicted to the south. Railroad tracks are depicted to the immediate west, followed by a multi-family apartment building and a vacant lot.

1974-1976

- **Subject Property:** No changes are depicted relative to the 1961 aerial photograph.
- **Offsite:** Apparent industrial buildings are depicted to the north. Franklin Avenue is depicted to the immediate east, followed by the existing intermediate school. Multi-family apartment buildings are depicted to the south. Railroad tracks are depicted to the immediate west, followed by a multi-family apartment building and a vacant lot.

1980-2019

- **Subject Property:** Lot 63 is improved with the existing industrial building. Lot 66 consists of a vacant lot with the exception of a small commercial building depicted on the southernmost border of the lot.
- **Offsite:** Apparent industrial buildings are depicted to the north. Franklin Avenue is depicted to the immediate east, followed by the existing intermediate school. Multi-family apartment buildings are depicted to the south. Railroad tracks are depicted to the immediate west, followed by a multi-family apartment building and a vacant lot.

The adjoining northern and eastern properties appear to have been used for commercial/industrial uses. The uses of the adjoining properties are further discussed in the Historical Sanborn Maps and City Directory sections below.

5.4.2 HISTORICAL SANBORN MAPS

Subject Property

Year	Description
Lot 63	
1888	The subject lot is improved with a small single-story dwelling.
1908	The subject lot is improved with a single-story building labeled as ´Bottling Department´, with an attached single-story structure labeled as ´Barrel Storage´. The structures are part of the Consumers Park Brewery to the north.
1932	The subject lot is improved with a split-level single and two-story building noted to be vacant.
1951	The subject lot has been redeveloped with the existing single-story manufacturing building. The building is occupied by a spring manufacturer.
1963	The existing building is now occupied by a metal products manufacturer.
1965	The existing building is now vacant.
1978-2007	The existing building is now occupied by a chemical manufacturing facility.
Lot 66	
1888	The subject lot consists of a vacant lot.
1908	The subject lot is improved with a 4-story building. Per the map annotations, the building was to be occupied by the Flatbush Hygienic Ice Co., however, admittance was refused. Washington Place traverses the central portion of the lot.
1932	The subject lot is improved with a 4-story building occupied by Rubel Ice Corp. The building contains ice storage rooms, freezing tanks, a boiler room, and a machine room. The southwest border of the lot consists of a 2-story ice storage building with an office on the first floor.

Year	Description
Lot 66	
1951	The previous structures associated with the Rubel Ice Corp. have been razed. The property now consists of tennis courts with a small office building on the southern-most border of the lot.
1963-1994	The property consists of a large vacant lot, except for the previously mentioned small single-story office along the southern border of the lot.
1995-2007	The subject lot is used as an outdoor parking lot. The small office along the southern border of the lot is still depicted.

Lot 63 has historically been used for manufacturing purposes. Former identified occupants of the existing single-story building include a spring manufacturer, a metal products manufacturer, and a chemical manufacturer. Per the 1969 Certificate of Occupancy reviewed, the referenced chemical company manufactured toiletries such as hair spray, lacquers, rinses, and shampoo. In the 1930s, Lot 66 was occupied by Rubel Ice Corp. ALC reviewed a Phase I ESA and Phase II Site Investigation Report prepared by The Elm Group, Inc. The report details subsurface investigations conducted at the Subject Property in 2017. The analytical results of the soil samples collected revealed the presence of PAHs and metals exceeding the NYSDEC Unrestricted Residential and Restricted Residential SCOs. However, according to ELM, the soil contaminants identified did not appear to be related to the former uses of the Subject Property but rather a result of non-indigenous fill brought into the Subject Property as part of grading/development activities. No VOCs or SVOCs were identified. The presence of PAHs and metal contaminants in onsite soils is considered a REC.

Adjacent Properties

Year	Description
North – 124 Montgomery Street	
1888	The property consists of small scattered single-story dwellings.
1908	The property is improved with a 5-story building occupied by Consumers Park Brewery.
1932-1951	The property is improved with a large industrial building occupied by Burton Dixie Corp.- Manufacturers of Mattresses & Cotton Felts.
1963-2007	The previously mentioned building is now occupied by M. S. Golombeck Inc.- Spice Importers.
East – 945 Franklin Avenue	
1888	Franklin Avenue is depicted to the immediate east, followed by a 3-story residential building with a ground-level retail store occupied by a "painting and storage" facility; small outbuildings associated with a dwelling; and ten vacant lots.

Year	Description
East – 945 Franklin Avenue	
1908	Franklin Avenue is depicted to the immediate east, followed by two 2-story dwellings; a single-story building occupied by a carpenter; a single-story dwelling; and six vacant lots.
1932	Franklin Avenue is depicted to the immediate east, followed by two 2-story dwellings; a single-story building occupied by a sheet metal works; a single-story building occupied by a print works facility; a large commercial garage with one gasoline tank on the western portion of the building; and four vacant lots.
1951	Franklin Avenue is depicted to the immediate east, followed by a single-story building occupied by a sheet metal works; two 2-story dwellings; a single-story building occupied by a print works facility; and four vacant lots. The previously mentioned garage is now depicted as a wholesale grocer. The gasoline tank is still depicted.
1963	Franklin Avenue is depicted to the immediate east, followed by a single-story building occupied by a sheet metal works; two 2-story dwellings; a single-story building noted to be vacant; and four vacant lots. The previously mentioned wholesale grocer is now depicted as a used car dealer. The gasoline tank is no longer still depicted.
1965	Franklin Avenue is depicted to the immediate east, followed by a single-story building noted to be vacant; two 2-story dwellings; a single-story building used for storage; a used car dealership facility; and four vacant lots.
1978-2007	Franklin Avenue is depicted to the immediate east, followed by the existing 4-story school known as Jackie Robinson School Intermediate School- No. 320. Per the map annotations, the school was constructed in 1968.
South– 1015 Washington Avenue	
1888	The property consists of a road (Henrietta Shannon Lane) and vacant land.
1908	Washington Place traverses the central portion of the lot. South of Washington Place is a single-story hotel named Park Brewery Hotel. North of Washington Place is a vacant lot.
1932-2007	The property is improved with a large 6-story multi-family apartment building.

Year	Description
South– 1035 Washington Avenue	
1888	The property is improved with a row of four 2-story dwellings fronting Franklin Avenue; a 2-story structure labeled as ´Wagon Factory´ fronting Washington Avenue; and a structure on the southwest-most section of the lot labeled as ´stand pipe´.
1908	The property is improved with a single-story wagon shed; three contiguous 2-story dwellings fronting Franklin Avenue; a 2-story building labeled as ´bottling´ fronting Franklin Avenue; a stable; a water tower on the southwest corner of the lot; and a 4-story brewery identified as ´Park Brewery´ fronting Washington Avenue.
1932	The property is improved with a row of four 2-story dwellings fronting Franklin Avenue. The remaining portions of the lot are vacant.
1951-1965	The property is improved with a large 6-story multi-family apartment building named Parkview Apartments. The building features ground-level retail units along Franklin Avenue and Sullivan Place.
1978-1988	The property is improved with a large 6-story multi-family apartment building named Parkview Apartments.
1989-2007	The property is improved with a large 6-story multi-family apartment building named Parkview Apartments, with one ground-level commercial unit.
South– 975 Washington Avenue	
1888	Railroad tracks are depicted to the immediate west, followed by vacant land.
1908	The Brooklyn Rapid Transit tracks are depicted to the immediate west, followed by a 2-story hotel named Consumers Park Hotel.
1932-2007	Railroad tracks are depicted to the immediate west, followed by a 4-story multi-family apartment building.
South– 995 Washington Avenue	
1888	Railroad tracks are depicted to the immediate west, followed by vacant land.
1908	The Brooklyn Rapid Transit tracks are depicted to the immediate west, followed by a vacant lot.
1932-2007	Railroad tracks are depicted to the immediate west, followed by a vacant lot.

North- 124 Montgomery Street
Per the Sanborn maps reviewed, from as early as 1932 until at least 1951, the northern adjacent property was occupied by a manufacturer of mattresses and cotton Felts (Burton Dixie Corp.).

This site wad subsequently occupied by M. S. Golombeck Inc.- Spice Importers until at least 2017. The historical uses of the adjoining northern property are further discussed in the City Directories section below.

East- 945 Franklin Avenue
The Sanborn maps revealed several former uses of environmental concern associated with the adjacent eastern site, as detailed below:

- A painting and storage facility in 1888
- A commercial garage with a gasoline tank in 1932
- Sheet metal works and print works facilities between 1932 and 1951
- A sheet metal works and print works facilities between 1932 and 1963

However, a subsurface investigation completed by Elm in 2017, which included the collection of two soil samples on the border of Lot 66, did not identify any fuel compounds, VOCs, or SVOCs at the Subject Property. The eastern adjacent site was redeveloped in 1968 with the existing public school. Based on the site redevelopment and analytical results of the soil samples collected at the Subject Property, no further action or investigation is warranted regarding the historical uses of the adjacent eastern property.

West
Railroad tracks were depicted to the immediate west, however per ALC´s observations during the site visit, the railroad tracks are located at a lower elevation than the Subject Property surrounding properties. Therefore, no significant impacts to the Subject Property are anticipated from the adjacent railroad tracks.

No additional areas of concern were identified from the Sanborn maps reviewed.

5.4.3 CITY DIRECTORIES

City directories can be useful in providing the names of businesses that have operated at a particular site. Historical city directories were obtained from EDR. Below is a summary of the findings:

Subject Property

Year	Uses
962-964 Franklin Avenue (Lot 63)	
1985	• Quality Metal Fabricators Inc.
1973	• Lustray Labs Inc. • Healox Company Inc.
1965 and 1970	• Select Beauty Brands Inc. • Lustray Labs Inc.
1960	• Stewart & Co. • Doran B.H. Inc.
1928	• Arcade Laundry Co. • Star Napkin & Towel Supply Co.

Year	Uses
968-994 Franklin Avenue (Lot 66)	
1976	• Stones Accountants
1934	• Rubel Ice Corp.
1928	• Rubel Coal & Ice Corp. • Flatbush Geia Ice Co.

Per the Sanborn maps and city directories reviewed, Lot 63 appears to have been used for manufacturing purposes from as early as 1951. In addition, Arcade Laundry Co. and Star Napkin & Towel Supply Co. were listed in 1928. Lot 66 was occupied by Rubel Ice Corp. in the late 1920s and 1930s. A 2017 subsurface investigation conducted by The Elm Group, Inc. at the Subject Property and adjacent northern property, revealed the presence of PAHs and metals exceeding the NYSDEC Unrestricted Residential and Restricted Residential SCOs in onsite soils. However, according to ELM, the contaminants identified did not appear to be related to the former uses of the Subject Property but rather a result of non-indigenous fill brought into the Subject Property as part of grading/development activities. No VOCs or SVOCs were identified. The presence of PAHs and metal contaminants in onsite soils is considered a REC.

Adjacent Properties

Year	Uses
934-960 Franklin Avenue/124 Montgomery Street (North)	
2014, and 2017	• Morris Golombeck Spices Inc.
2005 and 2009	• Morris Golombeck Spices Inc. • HPG Associates Inc.
1992, 1994, 1997, and 1999	• Morris Golombeck Spices Inc.
1985	• Morris Golombeck Spices Inc. • EJK Corp. Aircraft & Machine Division • Edward Keifer Cut Glass
1980	• Edward Keifer Cut Glass
1976	• Morris Golombeck Spices Inc. • Edward Keifer Cut Glass
1965, 1970 and 1973	• Morris Golombeck Spices Inc. • EJK Corp. Aircraft & Machine Division • Edward Keifer Cut Glass
1960	• Morris Golombeck Spices Inc. • Edward Keifer Cut Glass • Leake Manufacturer Corp.
969-991 Franklin Avenue (East)	
2014 and 2017	• Brooklyn Plumbing Company
2004	• Newman Hirschfield bank
1976	• Retail Credit Co.
1965	• Residential listing (975 Franklin Avenue) • Retail Credit Co. • Garden City Office

Year	Uses
969-991 Franklin Avenue (East)	
1965	• Follman L.D. Used Clothing (985 Franklin Avenue)
1970 and 1973	• Retail Credit Co. • Garden City Office
1960	• Residential listings (975 & 991 Franklin Avenue) • Elliot Thermographers Corp. (979 Franklin Avenue)
1949	• Residential listing (975 & 991 Franklin Avenue) • Brenner Alvino & Brenner Inc. Conveyers (973 Franklin Avenue) • Fyn Paint & Lacquer Co.- Office & Warehouse (979 Franklin Avenue) • Spinner Max Grocer (985 Franklin Avenue)
1945	• Residential listing (975 Franklin Avenue) • Fyn Paint & Lacquer Co.- Office & Warehouse (979 Franklin Avenue)
1940	• Residential listing (991 Franklin Avenue) • Brenner Bros- Cornices and Roofers (973 Franklin Avenue • Fyn Paint & Lacquer Works Inc.- Office (979 Franklin Avenue) • Ballfield Garage (983 Franklin Avenue)
1934	• Residential listings • Brenner Bros- Cornices and Roofers (971 Franklin Avenue) • Nitrosol Co. Inc. (979 Franklin Avenue) • Ballfield Garage (983 Franklin Avenue)
1928	• Residential listings (979 & 991 Franklin Avenue) • Ballfield Garage (983 Franklin Avenue)
1035 Washington Avenue (West)	
2014 and 2017	• Residential listings
2009	• Residential listings • Flying Rock Productions
2005	• Residential listings • Johnson, Sophie & Shellman
2004	• Residential listings • Artist Rites Enterprises Inc.
2000	• Residential listings
1999	• Mrs. Blacks School

Year	Uses
1035 Washington Avenue (West)	
1992, 1994 and 1997	• Residential listings • Mrs. Blacks School • Johnson, Sophie & Shellman
1985	• Residential listings • Mrs. Blacks School
1976 and 1980	• Residential listings
1965, 1970 and 1973	• Residential listings • Dental office
1960	• Residential listings • Dental office • Community Art Center Inc.
1949	• Residential listings • Dental office • Sandor Gluck Dance Studios
1945	• Residential listings • Dental office • Klahrs Miss School for Little Folk
1940	• Residential listings • Dental office • Klahrs Miss School for Little Folk • Y & Z Gasoline Services Stations Inc.
975-991 Washington Avenue (West)	
2014 and 2017	• Residential listings
2009	• Residential listings • Cedar Heart Pictures LLC • Lockitup Locksmiths
1928, 1940, 1945, 1949, 1960, 1965, 1970, 1973, 1976, 1980, 1985, 1992, 1997, 1994, 2000, 2004, and 2005	• Residential listings

North- 124 Montgomery Street

Per the Sanborn maps and city directories reviewed, from as early as 1932 until at least 1951, the northern adjacent property was occupied by a manufacturer of mattresses and cotton Felts (Burton Dixie Corp.). An additional manufacturing company (Leake Manufacturer Corp.) was listed in the city directories in 1960, and EJK Corp. Aircraft & Machine Division was listed between 1965 and 1985. This site was subsequently occupied by M. S. Golombeck Inc.- Spice Importers until at least 2017. A 2017 subsurface investigation conducted by The Elm Group, Inc. at the Subject Property and adjacent northern property revealed the presence of PAHs and metals exceeding the NYSDEC Unrestricted Residential and Restricted Residential SCOs in onsite soils. However, according to ELM, the contaminants identified did not appear to be related to the former uses of the Subject Property but rather a result of non-indigenous fill brought into the Subject Property and adjoining northern property as part of grading/development activities. No VOCs or SVOCs were identified. The presence of PAHs and metal contaminants in onsite soils is considered a REC.

East- 945 Franklin Avenue

Per the Sanborn maps and city directories reviewed, a commercial garage identified as Ballfield Garage was present at the adjacent eastern property between at least 1928 and 1940. A gasoline tank was depicted in this garage. In addition, Nitrosol Co. Inc. was listed in 1934. However, a subsurface investigation completed by Elm in 2017, which included the collection of two soil samples on the border of Lot 66, did not identify any fuel compounds, VOCs, or SVOCs at the Subject Property. This site was redeveloped in 1968 with the existing public school. Based on the site redevelopment and analytical results of the soil samples collected at the Subject Property, no further action or investigation is warranted regarding the former historical uses of the adjacent eastern property.

West- 1035 Washington Avenue

Y & Z Gasoline Service Stations Inc. was listed at this location in 1940. This site is improved with a large six-story multi-family apartment building constructed in 1942 (per the Certificate of Occupancy). Based on the site redeveloped and the current uses of this property, no further action or investigation is warranted.

No additional areas of concern were identified from the remaining historical uses of the adjacent properties.

5.4.4 TOPOGRAPHIC MAPS

Historical topographic maps can be useful in determining the nature of historic land use and the presence of historical structures at a particular site. The following topographic maps were reviewed:

- **1897-1900**: The Subject Property and adjacent northern property are located in a white-shaded area, which is indicative of undeveloped areas. Two small structures are depicted to the east (across Franklin Avenue) and south, and railroad tracks are depicted to the immediate west.
- **1947**: The Subject Property and adjacent properties are located within an area that is shaded black, which is indicative of built-up, developed areas. Railroad tracks are depicted to the immediate west
- **1956:** The Subject Property and the surrounding areas are located in a pink-shaded area, indicating that the Subject Property is within a densely populated area where only landmark structures are delineated. Railroad tracks are depicted to the immediate west.
- **1967-1995:** The Subject Property and the surrounding areas are located in a pink-shaded area, indicating the Subject Property is within a densely populated area where only landmark structures are delineated. A vacant lot is depicted to the east and railroad tracks are depicted to the immediate west.
- **2013-2019:** The Subject Property is located in a gray-shaded area, indicating the Subject Property is within a built-up area where individual structures are not delineated. Railroad tracks are depicted to the immediate west.

6.0 SITE RECONNAISSANCE

The objective of the site reconnaissance is to obtain information indicating the likelihood of identifying recognized environmental conditions in connection with the property.

6.1 METHODOLOGY AND LIMITING CONDITIONS

This Phase I ESA was performed in general conformance with the scope and limitations of ASTM International (ASTM) Practice E1527-21. All areas of the Subject Property were accessible during the site inspection, except for the small office building on the southern border of Lot 66 due to unsafe conditions.

6.2 GENERAL SITE SETTING

The Subject Property is located on the U.S.G.S. Brooklyn, NY 7.5' Quadrangle topographic map. The general site topographic gradient within a 1,000-foot radius of the Subject Property is in the south direction. Topographic conditions of the site vicinity are shown in Appendix 15.3. The Subject Property is approximately 90 feet above mean sea level. The nearest body of water is Prospect Lake, located approximately 0.59 mile to the southwest of the Subject Property.

The soils under and in the vicinity of the site are classified by the U.S. Department of Agriculture (USDA) as Urban Land. Urban land is noted to be comprised of surfaces covered by asphalt, concrete, buildings, or other impervious surfaces. Soils and foundation materials are highly variable. Urban structures and works cover so much of this land type that identification of the soils is not practical. Most areas have been smoothed and the original soil material has been disturbed, filled over, or otherwise destroyed prior to construction.

The Subject Property area is located within the Atlantic Coastal Plain physiographic province. The basic foundation of New York City is a sequence of Proterozoic Z to lower Paleozoic crystalline rocks. The Coastal Plain surface beneath Brooklyn and Queens is covered by unconsolidated Cretaceous sediments (gravel, sand and clay) of predominately terrestrial origin.

While groundwater in the vicinity of the Subject Property typically flows in a southern direction, local variations are possible due to intervening subsurface structures that could alter groundwater flow patterns. Groundwater at the Subject Property is not used as a source of drinking water.

6.3 EXTERIOR AND INTERIOR OBSERVATIONS

The periphery of the Subject Property, as well as the periphery of the onsite structures, was inspected to identify recognized environmental conditions in connection with the Subject Property. ALC visually inspected the interior of the single-story warehouse building in Lot 63. No access was provided to the interior of the small office building in Lot 66 due to unsafe conditions. No recognized environmental conditions were observed in the visually accessible areas of the Subject Property. The following conditions were observed:

6.3.1 LEAD

Commercial buildings are not targeted for the identification of lead-based paint (LBP) and

therefore LBP was not addressed.

The scope of this study did not include water testing for the identification of lead. However, the Subject Property is supplied with public water which is routinely monitored by the NYCDEP. As such, impacts associated with lead in water are not anticipated.

6.3.2 ASBESTOS

Since the onsite buildings were built prior to 1979, there is a possibility that the original construction materials contained asbestos. According to the EPA and included in the publication EPA560/5-85-025 "Guidance for Controlling Asbestos Containing Materials (ACM) in Buildings", asbestos containing materials are found in three forms: (1) Sprayed or troweled on ceilings and walls and structural steel; (2) in insulation around hot and cold piping, ducts, boilers, and tanks; and (3) in a non-friable state in products such as ceiling and floor tiles, wallboards and outside materials such as shingles and roofing materials. In general, ACM in a friable state (the first two categories) is of greatest concern because they are able to release asbestos fibers with only minimal disturbance.

We have used the 4-category system as defined by Asbestos Hazardous Emergency Response Act (AHERA) to designate the different conditions of asbestos notes throughout the areas of the site.

1. **Good Condition**
   Materials with no visible damage or deterioration to very limited damage or deterioration.

2. **Fair Condition**
   i. A few water stains or less than one tenth of insulation with missing jackets.
   ii. Crushed, heavily gouged, or punctured insulation, on at least one tenth of pipe runs/risers, boiler, tank duct, etc., if the damage is evenly distributed (one quarter if the damage is localized).

3. **Poor Condition**
   Material with one or more of the following characteristics:
   i. Missing jackets on at least one tenth of the piping equipment.
   ii. Crushed, heavily gouged or punctured insulation on at least one tenth of pipe runs/risers, boiler, tank duct, etc., if the damage is evenly distributed (one quarter if the damage is localized).

4. **Significantly Damaged**
   Thermal systems insulation on pipes, boilers, tanks, ducts, and other thermal system insulation equipment where the insulation has lost its structural integrity, or its covering, in whole or in parts, is crushed, water-stained, gouged, punctured, missing, or not intact such that is not able to contain fibers. Damage may be further illustrated by occasional punctures, gouges, or other signs of physical injury to ACM; occasional water damage on the protective coverings/jackets; or exposed ACM ends or joints. Asbestos debris, originating from the ACM in question may also indicate damage.

Findings:

I. On July 28, 2017, ALC conducted testing of suspect asbestos containing materials at 972 Franklin Avenue (Lot 66). The bulk samples were analyzed by Metro Analytical laboratories (ELAP #12003), located at 255 West 36th Street, Suite 101, New York, NY 10018. ALC chains of custody and laboratory analysis report are included in Appendix 15.5.

By definition, building materials containing greater than 1% asbestos are classified as Asbestos Containing Materials (ACM). Following is a summary of the findings:

Location	Material	Asbestos % & Type
Lot 66- 972 Franklin Avenue		
Roof	Roof membrane- asphalt roll	3.2 % Chrysotile
Roof parapet	Flashing tar	2.4 % Chrysotile

- Prior to any renovation/remodeling or repair work, the referenced roofing materials should be abated by a certified asbestos abatement contractor per all applicable local, state, and federal regulations.

II. In addition, the following suspect ACM was observed at the Subject Property:

Location	Material	Condition
Lot 63- 962 Franklin Avenue		
Roof	Roof membrane and flashing	-
Throughout	Sheetrock walls and ceilings	Significantly Damaged

- Access to the roof was not provided; therefore, the condition of the roof at 962 Franklin Avenue is unknown. Prior to any renovation/remodeling or repair work that will affect the above-referenced materials, asbestos testing should be conducted. If determined to contain asbestos via laboratory analysis, the referenced materials should be abated by a certified asbestos abatement contractor per all applicable local, state, and federal regulations.

This inspection was conducted solely to identify suspect ACM in accessible areas of the Subject Property. Additional asbestos-containing materials/quantities may be present in concealed areas of the building, or areas not visually inspected during this assessment. Any suspect asbestos-containing materials encountered during future construction activities should be tested or assumed to be ACM and treated as such.

6.3.3 NON-ASBESTOS HAZARDOUS MATERIALS

No hazardous materials were observed at the Subject Property during the site visit.

6.3.4 UNDERGROUND/ABOVEGROUND STORAGE TANKS

No underground or aboveground storage tanks were observed at the Subject Property during the site visit, however, ALC noted a fuel oil fill port and vent pipe on the northern façade of the small office building in Lot 66, near the northeast corner of the building. Due to unsafe conditions, ALC was not able to inspect the interior of the building. It is unknown if the building has a basement

level and whether or not the tank associated with the referenced fuel oil and vent pipe is still present. Based on the fact that the tank was not listed in any of the regulatory databases reviewed, ALC assumes that the tank is less than has a capacity of less than 1,100 gallons and therefore was not required to be registered with the NYSDEC. The potential presence of a fuel oil tank inside the building in Lot 66 is considered a REC.

6.3.5 NON-HAZARDOUS SOLID WASTE

Solid waste is not currently generated at the Subject Property. However, building materials debris (mainly damaged sheetrock walls and ceilings) were observed inside the warehouse building in Lot 63. The referenced building materials may be contaminated with asbestos and therefore should be properly disposed of per all applicable regulations.

There was no evidence that the Subject Property may have been used for dumping or landfilling.

6.3.6 HAZARDOUS WASTE

The Subject Property is vacant, and therefore hazardous waste is not generated. However, one discarded 8-ounce can of multi-purpose oil and two 4-ounce plastic bottles containing lubricant were observed inside the warehouse building in Lot 63. No evidence of spillage was observed; however, the referenced waste should be properly disposed of per applicable local regulations.

- **ODORS**
  No strong, pungent, or noxious odors were noted at the Subject Property at the time of the site visit.

- **POOLS OF LIQUID**
  No pools or sumps containing liquids likely to be hazardous substances or petroleum products were visually observed at the Subject Property at the time of the site visit.

- **DRUMS**
  No waste drums were observed at the Subject Property at the time of the site visit.

- **UNIDENTIFIED SUBSTANCE CONTAINERS**
  No open or damaged containers containing unidentified substances suspected of being hazardous substances or petroleum products were observed on the Subject Property.

6.3.7 VAPOR ENCROACHMENT

A Tier 1 Vapor Encroachment Screening for the Subject Property was performed, in accordance with the ASTM International Practice 2600-10. ALC utilized EDR to conduct the appropriate searches of federal and state sites identified within the area of concern (AOC) specified by ASTM 2600-10. The appropriate minimum search distances surrounding the Subject Property are as follows:

Standard Environmental Record Sources	Chemicals of Concern (miles)	Petroleum Hydrocarbon Chemicals of Concern (miles)
Registered storage tanks	Target property only	Target property only

Standard Environmental Record Sources	Chemicals of Concern (miles)	Petroleum Hydrocarbon Chemicals of Concern (miles)
Emergency Response Notification System (ERNS)	Target property only	Target property only
Federal and state institutional and engineering Controls list	Target property only	Target property only
Federal RCRA Generators	Target property only	Target property only
Federal NPL	1/3	1/10
State- and tribal-equivalent NPL	1/3	1/10
Federal SEMS	1/3	1/10
State- and tribal-equivalent SEMS	1/3	1/10
Federal RCRA CORRACTS facilities	1/3	1/10
State and tribal landfill and/or solid waste disposal sites	1/3	1/10
State and tribal voluntary cleanup sites (VCP)	1/3	1/10
State and tribal Brownfield sites	1/3	1/10

Minimum search distances when groundwater flow direction can be estimated:		
Up-gradient	**Cross-gradient**	**Down-gradient**
- 1/3 mile for chemicals of concern sources - 1/10 mile for petroleum hydrocarbon sources	- 100 feet for chemicals of concern sources/petroleum hydrocarbon *Light Non-Aqueous Phase Liquid (LNAPL) sources plus plume width consideration.* - 30 feet for dissolved petroleum hydrocarbon sources *plus plume width consideration.*	- 100 feet for chemicals of concern sources/petroleum hydrocarbon *LNAPL sources.* - 30 feet for dissolved petroleum hydrocarbon sources. LNAPL sources.

Findings:

- VECs that could not be ruled out were not identified for the Subject Property or surroundings sites within the above-specified distances. A VEC is defined by ASTM E2600-10 as "the presence or likely presence of chemicals of concern (COC) vapors in the sub-surface of the target property caused by the release of vapors from contaminated soil or groundwater either on or near the target property". The EDR Vapor Encroachment Screen report is included in Appendix H. No further action or investigation is warranted.

6.3.8 PCB-CONTAINING EQUIPMENT

Observation of electrical equipment or electrical components containing dielectric fluid with potential PCB levels excessing 50 ppm was conducted as part of this assessment. No suspect PCB-containing equipment fluid was observed at the Subject Property.

6.3.9 *STORM WATER AND WASTE WATER*

The Subject Property is connected to a municipal-owned and maintained sewer system. Stormwater is drained from the Subject Property primarily by sheet flow action across paved surfaces and into catch basins located along the adjacent streets or permeates the soil in Lot 66. No unusual ponding of storm waters was observed.

Industrial effluent is not known to have been generated at the Subject Property and, in any event, would not have been permitted to be discharged to the sewer system without the requisite Municipal Utility Authority (MUA) permits. Sanitary effluent discharges to the municipal sewer system generated at the Subject Property originate from the domestic bathroom facilities.

6.3.10 *WETLANDS*

A review of the National Wetlands Inventory published by USGS indicated that there are no recognized wetlands on or in the immediate vicinity of the Subject Property. A copy of the wetlands map is provided in Appendix 15.1.

6.3.11 *FLOODPLAINS*

As per the FEMA flood map reviewed (FEMA FIRM Panel No. 3604970212F), the Subject Property is located in Flood Zone X- defined as areas of minimal flood hazard, typically above the 500-year flood level. A copy of the FEMA flood map is provided in Appendix 15.1.

6.3.12 *RADON*

Radon is a colorless, odorless gas produced by the radioactive decay of certain elements. The most common sources of radon are igneous and metamorphic rocks containing uranium (such as pitchblende), granite, shale, or phosphate, as well as soils or sediments derived from these parent materials. Radon may also be found in soils contaminated with certain industrial wastes (such as uranium or phosphate mine tailings) or in earth-derived building products which include industrial wastes that contain phosphate slag. In areas where the potential for radon accumulation is high, special ventilation systems may offset potential health hazards.

Review of the EPA Map of Radon Zones places the Subject Property in Zone 3, where average predicted radon levels are less than 2.0 pCi/L (picocuries/liter). The USEPA recommended action level is 4.0 pCi/L. Based on the low predicted radon levels, adverse environmental impacts related to radon gas migration are not anticipated at the Subject Property.

6.3.13 *AIR EMISSIONS*

No potential sources of permitted air emissions were observed at the Subject Property during the site reconnaissance.

6.3.14 *STRESSED VEGETATION*

This inspection did not reveal any visual indication of environmental contamination immediately adjacent to the Subject Property nor within the boundaries of the Subject Property.

6.3.15 HEATING/COOLING

No central HVAC systems were observed inside the warehouse building. However, ALC observed an inactive natural gas-fired boiler and inactive water heater inside the subject building, as well as a furnace. Per information obtained from a previous Phase I ESA, the referenced boiler previously supplied hot water to the steel chamber located in one of the adjacent northern buildings (Lot 46). Portions of the warehouse appear to have been heated by space heaters.

6.3.16 STAINS OR CORROSION

No areas of stained soil or pavement were visually observed at the Subject Property at the time of the site visit.

6.3.17 DRAINS AND SUMPS

Floor drains within the onsite buildings discharge to the municipal sewer systems. No sump pumps were observed inside the warehouse building (Lot 63).

6.3.18 MOLD

No visible mold growth was observed at the subject warehouse building during the site visit. The interior of the small office in Lot 66 was not inspected due to unsafe conditions.

7.0 INTERVIEWS

7.1 INTERVIEW WITH OWNER

The building Owner was not available for interview at the time of the site visit.

7.2 INTERVIEW WITH SITE MANAGER

A Site Manager was not available for interview at the time of the site visit.

7.3 INTERVIEWS WITH OCCUPANTS

At present the building is unoccupied and therefore no occupants were interviewed at the time of the site visit.

7.4 INTERVIEWS WITH LOCAL GOVERNMENT OFFICIALS

A Freedom of Information Act (FOIL) request for information associated with the Subject Property was submitted to the NYSDEC. No records were located for the Subject Property.

7.5 INTERVIEW WITH OTHERS

During the site reconnaissance, ALC was accompanied by Mr. David Linehan, Developer Manager with The Continuum Company, LLC, who has been associated with the Subject Property for approximately 1.5 years. In addition, Mr. Linehan completed a standard environmental questionnaire (see Appendix 15.5). Per Mr. Linehan, the existing warehouse building (Lot 63) was part of a spice manufacturing and storage facility on the adjoining northern property. The Subject Property is planned to be developed with a 14-story multi-family apartment building. No areas of concern were reported by Mr. Linehan.

8.0 FINDINGS

The Consultant identified the following recognized environmental conditions (RECs) associated with the Subject Property:

- According to the historical sources reviewed (Sanborn maps and city directories), Lot 63 (962 Franklin Avenue) has historically been used for manufacturing purposes. Former identified occupants of the existing single-story warehouse building include a spring manufacturer depicted in the 1951 Sanborn map, a metal products manufacturer depicted in the 1963 Sanborn map, and a chemical manufacturer depicted between 1978 and 2007. Per the 1969 Certificate of Occupancy reviewed, the referenced chemical manufacturer produced toiletries such as hair spray, lacquers, rinses, and shampoo. In addition, Arcade Laundry Co. and Star Napkin & Towel Supply Co. were listed in the 1928 city directory. Lot 66 was occupied by Rubel Ice Corp. in the late 1920s and 1930s. All structures associated with the referenced ice company were demolished before 1951.

  Per the historical Sanborn maps and city directories reviewed, the northern adjacent property (124 Montgomery Street) was occupied by a manufacturer of mattresses and cotton Felts (Burton Dixie Corp.) from as early as 1932 until at least 1951. An additional manufacturing company (Leake Manufacturer Corp.) was listed in the city directories in 1960, and EJK Corp. Aircraft & Machine Division was listed between at least 1965 and 1985. This site was subsequently occupied by M. S. Golombeck Inc.- Spice Importers until at least 2017.

  ALC reviewed a Phase I ESA and Phase II Site Investigation Report prepared by The Elm Group, Inc. (Elm). The report details subsurface investigations conducted at the Subject Property and adjoining northern property on March 21 and 22, 2017. Groundwater was not encountered during the investigation. The analytical results of the soil samples collected revealed the presence of PAHs and metals (including barium, copper, mercury, zinc, cadmium, and lead) at levels exceeding the NYSDEC Unrestricted Residential and Restricted Residential Soil Cleanup Objectives. However, ELM stated that the contaminants identified did not appear to be related to the former uses of the Subject Property and adjacent northern property but rather a result of non-indigenous fill brought into the Subject Property and adjoining northern property as part of grading/development activities. No fuel oil compounds, VOCs, or SVOCs were identified in the soil samples collected and analyzed.

- No underground or aboveground storage tanks were observed at the Subject Property during the site inspection. However, ALC noted a fuel oil fill port and vent pipe on the northern façade of the small office building in Lot 66, near the northeast corner of the building. Due to unsafe conditions, ALC was not able to inspect the interior of the building. It is unknown if the building has a basement level and whether or not the tank associated with the referenced fill port and vent pipe is still present. Based on the fact that there are no registered tanks associated with the Subject Property, ALC presumes that this potential tank has a capacity of less than 1,100 gallons and therefore was not required to be registered with the NYSDEC. The possible presence of a fuel oil tank inside the building in Lot 66 is considered a REC.

In addition, the following noteworthy conditions, including de minimis conditions were

observed:

- On July 28, 2017, ALC conducted testing of suspect asbestos containing materials at 972 Franklin Avenue (Lot 66). The roof membrane and parapet flashing tar of the single-story office building in Lot 66 tested positive for asbestos.

- Suspect asbestos-containing materials in the form of roofing materials and sheetrock walls and ceilings are present at the existing warehouse building in Lot 63. No access was provided to the roof and therefore the condition of the roof could not be assessed. Damaged sheetrock walls and ceilings were observed throughout the warehouse, particularly in the restroom.

- Building materials debris (mainly damaged sheetrock walls and ceilings) were observed inside the warehouse building in Lot 63. The referenced building materials may be contaminated with asbestos and therefore should be properly disposed of, per all applicable regulations.

- VECs that could not be ruled out were not identified for the Subject Property or surroundings sites within the distances specified by ASTM E2600-10. The EDR Vapor Encroachment Screen report is included in Appendix 15.5.

No additional conditions were observed at the site that could potentially present a significant environmental concern or recognized environmental condition.

9.0 CONCLUSIONS AND RECOMMENDATIONS

Based on a review of background data, regulatory agency records, aerial photographs, and observations made during the site reconnaissance, the following conclusions and recommendations are presented regarding the Subject Property. The scope of this study did not include subsurface exploration, sampling or analytical laboratory testing.

9.1 CONCLUSIONS

- The Subject Property is not identified as being evaluated by the State of New York or the federal government for remedial action under SEMS or any other environmental regulations.

- There were two hundred and sixty-eight (268) sites listed on the regulatory database search within a 1-mile radius of the Subject Property. Based on available information, estimated flow direction of groundwater, and the nature of the database listings, it is unlikely that the Subject Property has been impacted by unauthorized releases of hazardous materials at this time, though it is impossible to entirely rule out the potential for contamination.

- Asbestos-containing materials were identified at the single-story small office building in Lot 66 (972 Franklin Avenue).

- ALC performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-21 of the property located at 970 Franklin Avenue, Brooklyn, NY 11225. Any exceptions to, or deletions from, this practice are described in Section 2.0 of this report. This assessment revealed evidence of recognized environmental conditions (RECs) in connection with the Subject Property.

9.2 RECOMMENDATIONS

- Regarding the presence of PAHs and metal contaminants in onsite soils associated with the historical uses of the Subject Property and adjoining northern property, since the exposure pathway is through direct contact with onsite soils, contaminated soil can be excavated and disposed of offsite during the planned site redeveloped activities. ALC recommends that a Soil Management Plan be developed and implemented during the planned construction activities to ensure the proper removal of impacted soils and minimize exposure to contaminants.

- Regarding the fuel oil fill port and vent pipe observed on the northern façade of the small office building in Lot 66, once access to the interior of the building is feasible, further visual investigation is needed to determine whether or not the tank associated with the fuel oil and vent pipe is still present, and to assess the condition of said tank.

- Regarding the asbestos-containing roofing materials at the single-story office building in Lot 66, prior to any renovation/remodeling or repair work, the referenced roofing materials should be abated by a certified asbestos abatement contractor as per all applicable local, state, and federal regulations.

- Suspect asbestos-containing materials in the form of roofing materials and sheetrock walls and ceilings are present at the existing warehouse building in Lot 63. Prior to any renovation or repair work that will affect the above-referenced materials, asbestos testing should be conducted. If determined to contain asbestos, the referenced materials should be abated by a certified asbestos abatement contractor per all applicable local, state, and federal regulations.

- Regarding the building materials debris (mainly damaged sheetrock walls and ceilings) observed inside the warehouse building in Lot 63, the referenced building materials may be contaminated with asbestos and therefore should be properly disposed of, per all applicable regulations.

ALC has no additional recommendations for further study at the Subject Property at this time, other than the recommendations provided above.

10.0 DEVIATIONS

ALC did not interview the prior property owner as part of this assessment. Beyond the aforementioned exceptions, there were no deletions or deviations from ASTM E1527-21. The client did not impose any constraints that required deviation from the standard practice, and there were no conditions at the site that limited the scope of work.

Data Gaps: No data gaps were encountered during the preparation of this report.

11.0 ADDITIONAL SERVICES

ALC did not provide any additional services to the Client as part of this Phase I ESA.

12.0 REFERENCES

Environmental Data Resources (EDR) with Geocheck: 972 Franklin Avenue, Brooklyn, NY 11225, dated January 23, 2023.

EDR Aerial Photo Decade Package, dated January 23, 2023

EDR Certified Sanborn Map Report, dated January 23, 2023

EDR City Directory, dated January 23, 2023

EDR Historical Topographic Map Report, dated January 23, 2023

National Wetlands Inventory
http://www.fws.gov/wetlands/data/Mapper.html

USEPA Map of Radon Zones.
http://www.epa.gov/radon/zonemap.html

NYC Oasis
www.oasisnyc.net

Department of Buildings
http://www.nyc.gov/html/dob/html/bis/bis.shtml

NYSDEC Environmental Site Database Search
http://www.dec.ny.gov/chemical/8437.html

NYC Department of Finance
http://www.nyc.gov/html/dof/html/jump/acris.shtml

NYS Searchable Property Environmental E-Database (SPEED)
https://gis.nyc.gov/moer/speed/

13.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONAL

This Phase I ESA was performed in general conformance with the scope and limitations of ASTM International Practice E1527-13. Ms. Tania Castro of ALC Environmental, a qualified Environmental Professional, performed this Phase I ESA.

Surveyed by: Virxhinia Daci, Field Technician
Real Estate Due Diligence
ALC Environmental

Written by: Tania Castro, Division Manager
Real Estate Due Diligence
ALC Environmental

14.0 QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONAL

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental professional as defined in §312.10 of 40 CFR 312 and I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Surveyed by: Virxhinia Daci, Field Technician
Real Estate Due Diligence
ALC Environmental

Written by: Tania Castro, Division Manager
Real Estate Due Diligence
ALC Environmental

15.0 APPENDICES

15.1 Figures

15.2 Site Photographs

15.3 Historical Research Documentation

15.4 Regulatory Records Documentation

15.5 Supporting Documentation

15.6 Contractual Conditions between User and Environmental Professional

15.7 Qualifications of the Environmental Professional

APPENDIX 15.1
FIGURES



ALC Environmental

970 Franklin Avenue, Brooklyn, NY 11225
Google Maps

Appendix 15.1
Site Vicinity Map

ALC Environmental

970 Franklin Avenue, Brooklyn, NY 11225
Google Earth

N

Appendix 15.1
Site Vicinity Map



ALC Environmental

970 Franklin Avenue, Brooklyn, NY 11225
Google Earth

N

Appendix 15.1
Site Vicinity Map



ALC Environmental

970 Franklin Avenue, Brooklyn, NY 11225
NYC SPEED

Appendix 15.1
NYC SPEED


Advanced
Map Type
CROWN ST
MONTGOMERY ST
WASHINGTON AV
FRANKLIN AV
Jackie Robinson Playground
MC KEEVER PL
BEDFORD AV
P.S. 375
SULLIVAN PL
EAST DR
EMPIRE BLVD
OCEAN AV
STERLING ST
New York
feet
200
Total Results: 1 - Tax Lot (PLUTO)
Export
Map It
Layer Control
View Historical Data
Right-click on a layer name for more information.
Vacant Property Database (VPD)
NYS Brownfield Opportunity Areas (BOA)
Governmental Environmental Databases
NYC E-Designation Sites (E)
NYS Brownfield and Voluntary Cleanup Program Sites (BCP/VCP)
NYS Hazardous Waste Sites (HW)
NYS Open Petroleum Spill Locations
NYS Chemical Bulk Storage Sites (CBS)
NYS Petroleum Bulk Storage Sites (PBS)
NYS Major Oil Storage Facilities (MOSF)
NYS Resource Conservation & Recovery Act Facilities (RCRA)
NYS Solid Waste Facilities (SW)
US National Priority List Sites (NPL)
US National Priority List Sites (NPL-Area)
Economic and Incentive Zones
Political Districts & City Facilities
Shoreline
Transportation



ALC Environmental

970 Franklin Avenue, Brooklyn, NY 11225 NYC
Department of Planning- Map 16d

Appendix 15.1
Zoning Map

National Flood Hazard Layer FIRMette

FEMA

73°57'56"W 40°40'7"N



73°57'19"W 40°39'39"N

0 250 500 1,000 1,500 2,000 Feet

1:6,000

Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 / 17.5 Cross Sections with 1% Annual Chance / Water Surface Elevation
- Coastal Transect
- Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 2/2/2023 at 3:50 AM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

U.S. Fish and Wildlife Service

National Wetlands Inventory

970 Franklin Avenue



February 2, 2023

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

APPENDIX 15.2

SITE PHOTOGRAPHS

The subject property viewed from the southern elevation

The subject property viewed from the northern elevation

The subject property viewed from the east elevation

Western border of the subject property, viewed from the southern border

Lot 63- single-story warehouse building at 962 Franklin Avenue, viewed from Franklin Avenue

Lot 63- western portion of the warehouse building

Lot 63- eastern portion of the warehouse building

Lot 63- interior view of the warehouse building

Lot 63- inactive natural gas-fired boiler in the northeast portion of the warehouse building

Lot 63- inactive water heater outside the restroom

63- closer view of the furnace

Lot 63- restroom

Lot 63- typical natural gas space heaters throughout the warehouse

Lot 66- office building along the southern border of the lot

Lot 66- western portion of the building

Lot 66- interior of the office building, viewed from the window

Lot 66- fuel oil fill port and vent pipe

Adjacent northern property- 124 Montgomery Street

Adjacent school to the east- P.S. 375- Jackie Robinson School

Adjoining southern properties

Adjacent railroad tracks to the west

APPENDIX 15.3

HISTORICAL RESEARCH DOCUMENTATION

962 & 972

972 Franklin Avenue

Brooklyn, NY 11225

Inquiry Number: 7231046.8

January 23, 2023

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

01/23/23

Site Name:

962 & 972
972 Franklin Avenue
Brooklyn, NY 11225
EDR Inquiry # 7231046.8

Client Name:

The ALC Group, LLC T/A ALC
39 West Street
New York, NY 10001
Contact: Tania Castro

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 04, 1994	USGS/DOQQ
1984	1"=500'	Flight Date: March 26, 1984	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1976	1"=500'	Flight Date: October 29, 1976	USGS
1974	1"=500'	Flight Date: October 19, 1974	NOAA
1966	1"=500'	Flight Date: February 23, 1966	USGS
1961	1"=500'	Flight Date: April 12, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: February 23, 1954	USGS
1951	1"=500'	Flight Date: April 21, 1951	EDR Proprietary Aerial Viewpoint
1924	1"=500'	Flight Date: July 01, 1924	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 7231046.8
YEAR: 2019
= 500'
N
EDR

INQUIRY #: 7231046.8
YEAR: 2015
= 500'
N
EDR

INQUIRY #: 7231046.8

YEAR: 2011

= 500'

N

EDR

INQUIRY #: 7231046.8
YEAR: 2006
= 500'
N
EDR


INQUIRY #: 7231046.8
YEAR: 1994
= 500'
N
EDR

INQUIRY #: 7231046.8

YEAR: 1984

= 500'

N

EDR

INQUIRY #: 7231046.8
YEAR: 1980
= 500'
N
EDR

INQUIRY #: 7231046.8

YEAR: 1976

= 500'

N

EDR

INQUIRY #: 7231046.8

YEAR: 1974

= 500'

N

EDR

INQUIRY #: 7231046.8

YEAR: 1966

= 500'

N

EDR

INQUIRY #: 7231046.8

YEAR: 1961

= 500'

N

EDR

INQUIRY #: 7231046.8

YEAR: 1954

= 500'

N

EDR

INQUIRY #: 7231046.8

YEAR: 1951

= 500'

N

EDR

INQUIRY #: 7231046.8

YEAR: 1924

= 500'

N

EDR

962 & 972

972 Franklin Avenue

Brooklyn, NY 11225

Inquiry Number: 7231046.3

January 23, 2023

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

01/23/23

Site Name:

962 & 972
972 Franklin Avenue
Brooklyn, NY 11225
EDR Inquiry # 7231046.3

Client Name:

The ALC Group, LLC T/A ALC
39 West Street
New York, NY 10001
Contact: Tania Castro

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by The ALC Group, LLC T/A ALC were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 7346-48F6-8BB9

PO # NA

Project NA

Maps Provided:

2007	1994	1980	1888
2006	1993	1979	
2005	1992	1978	
2004	1991	1965	
2003	1989	1963	
2002	1988	1951	
2001	1987	1932	
1995	1982	1908	

Sanborn® Library search results

Certification #: 7346-48F6-8BB9

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

The ALC Group, LLC T/A ALC (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets


Volume 7, Sheet 51
2007


Volume 7, Sheet 52
2007


Volume 7, Sheet 64
2007

Volume 7, Sheet 63
2007

2006 Source Sheets

Volume 7, Sheet 63
2006


Volume 7, Sheet 64
2006


Volume 7, Sheet 52
2006


Volume 7, Sheet 51
2006

2005 Source Sheets


Volume 7, Sheet 51
2005


Volume 7, Sheet 52
2005


Volume 7, Sheet 64
2005

Volume 7, Sheet 63
2005

2004 Source Sheets

Volume 7, Sheet 63
2004


Volume 7, Sheet 64
2004


Volume 7, Sheet 52
2004

Volume 7, Sheet 51
2004

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets


Volume 7, Sheet 51
2003


Volume 7, Sheet 52
2003

Volume 7, Sheet 63
2003


Volume 7, Sheet 64
2003

2002 Source Sheets

Volume 7, Sheet 63
2002


Volume 7, Sheet 52
2002

Volume 7, Sheet 51
2002


Volume 7, Sheet 64
2002

2001 Source Sheets

Volume 7, Sheet 63
2001

Volume 7, Sheet 51
2001


Volume 7, Sheet 52
2001


Volume 7, Sheet 64
2001

1995 Source Sheets


Volume 7, Sheet 52
1995


Volume 7, Sheet 51
1995


Volume 7, Sheet 64
1995

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets


Volume 7, Sheet 64
1994

Volume 7, Sheet 63
1994

Volume 7, Sheet 51
1994


Volume 7, Sheet 52
1994

1993 Source Sheets


Volume 7, Sheet 52
1993


Volume 7, Sheet 51
1993

Volume 7, Sheet 63
1993


Volume 7, Sheet 64
1993

1992 Source Sheets

Volume 7, Sheet 63
1992


Volume 7, Sheet 64
1992


Volume 7, Sheet 51
1992


Volume 7, Sheet 52
1992

1991 Source Sheets


Volume 7, Sheet 52
1991

Volume 7, Sheet 51
1991


Volume 7, Sheet 64
1991

Volume 7, Sheet 63
1991

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1989 Source Sheets

Volume 7, Sheet 63
1989


Volume 7, Sheet 64
1989

Volume 7, Sheet 51
1989


Volume 7, Sheet 52
1989

1988 Source Sheets


Volume 7, Sheet 51
1988


Volume 7, Sheet 64
1988


Volume 7, Sheet 52
1988


Volume 7, Sheet 63
1988

1987 Source Sheets


Volume 7, Sheet 64
1987


Volume 7, Sheet 52
1987


Volume 7, Sheet 51
1987

Volume 7, Sheet 63
1987

1982 Source Sheets

Volume 7, Sheet 63
1982


Volume 7, Sheet 51
1982


Volume 7, Sheet 52
1982


Volume 7, Sheet 64
1982

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1980 Source Sheets

Volume 7, Sheet 52
1980

Volume 7, Sheet 63
1980


Volume 7, Sheet 64
1980

Volume 7, Sheet 51
1980

1979 Source Sheets


Volume 7, Sheet 51
1979


Volume 7, Sheet 63
1979


Volume 7, Sheet 64
1979


Volume 7, Sheet 52
1979

1978 Source Sheets


Volume 7, Sheet 64
1978

Volume 7, Sheet 63
1978

Volume 7, Sheet 51
1978

Volume 7, Sheet 52
1978

1965 Source Sheets


Volume 7, Sheet 52
1965


Volume 7, Sheet 51
1965


Volume 7, Sheet 64
1965

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1963 Source Sheets



Volume 7, Sheet 64
1963



Volume 7, Sheet 51
1963



Volume 7, Sheet 52
1963



Volume 7, Sheet 63
1963

1951 Source Sheets

Volume 7, Sheet 63
1951

Volume 7, Sheet 52
1951



Volume 7, Sheet 51
1951



Volume 7, Sheet 64
1951

1932 Source Sheets



Volume 7, Sheet 64
1932

Volume 7, Sheet 51
1932



Volume 7, Sheet 52
1932

1908 Source Sheets



Volume 7, Sheet 60
1908



Volume 7, Sheet 59
1908



Volume 7, Sheet 74
1908

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1888 Source Sheets



Volume 7, Sheet a
1888

Volume 7, Sheet a
1888



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 63
Volume 7, Sheet 64
Volume 7, Sheet 52
Volume 7, Sheet 51

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7346-48F6-8BB9

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 51
Volume 7, Sheet 52
Volume 7, Sheet 64
Volume 7, Sheet 63

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 63
Volume 7, Sheet 64
Volume 7, Sheet 52
Volume 7, Sheet 51

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 51
Volume 7, Sheet 52
Volume 7, Sheet 64
Volume 7, Sheet 63

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 64
Volume 7, Sheet 63
Volume 7, Sheet 52
Volume 7, Sheet 51

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7346-48F6-8BB9

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 64
Volume 7, Sheet 51
Volume 7, Sheet 52
Volume 7, Sheet 63

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 64
Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 63

N

Certified Sanborn® Map

1995



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7346-48F6-8BB9

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #:	7346-48F6-8BB9
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 64
Volume 7, Sheet 51
Volume 7, Sheet 52

N

Certified Sanborn® Map

1994



Certification #7346-48F6-8BB9

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #:	7346-48F6-8BB9
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 63
Volume 7, Sheet 64

N



Certification #7346-48F6-8BB9

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #:	7346-48F6-8BB9
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 64
Volume 7, Sheet 63
Volume 7, Sheet 51
Volume 7, Sheet 52

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 64
Volume 7, Sheet 63

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 63
Volume 7, Sheet 64
Volume 7, Sheet 51
Volume 7, Sheet 52

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 64
Volume 7, Sheet 63

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 63
Volume 7, Sheet 52
Volume 7, Sheet 64
Volume 7, Sheet 51

0 Feet 150 300 600

N



Certification #7346-48F6-8BB9

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 63
Volume 7, Sheet 51
Volume 7, Sheet 52
Volume 7, Sheet 64

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 64
Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 63

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7346-48F6-8BB9

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 51
Volume 7, Sheet 64
Volume 7, Sheet 63
Volume 7, Sheet 52

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #:	7346-48F6-8BB9
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 52
Volume 7, Sheet 64
Volume 7, Sheet 63
Volume 7, Sheet 51

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #:	7346-48F6-8BB9
Copyright	1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 63
Volume 7, Sheet 64

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 64
Volume 7, Sheet 51
Volume 7, Sheet 52

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7346-48F6-8BB9

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #:	7346-48F6-8BB9
Copyright	1963

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 63
Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 64

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #7346-48F6-8BB9

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet 64
Volume 7, Sheet 51
Volume 7, Sheet 52
Volume 7, Sheet 63

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #:	7346-48F6-8BB9
Copyright	1932

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 52
Volume 7, Sheet 51
Volume 7, Sheet 64

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1908

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 7, Sheet 74
Volume 7, Sheet 59
Volume 7, Sheet 60

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	962 & 972
Address:	972 Franklin Avenue
City, ST, ZIP:	Brooklyn, NY 11225
Client:	The ALC Group, LLC T/A ALC
EDR Inquiry:	7231046.3
Order Date:	01/23/2023
Certification #	7346-48F6-8BB9
Copyright	1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 7, Sheet a
Volume 7, Sheet a

N

962 & 972

972 Franklin Avenue

Brooklyn, NY 11225

Inquiry Number: 7231046.4

January 23, 2023

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

01/23/23

Site Name:

962 & 972
972 Franklin Avenue
Brooklyn, NY 11225
EDR Inquiry # 7231046.4

Client Name:

The ALC Group, LLC T/A ALC
39 West Street
New York, NY 10001
Contact: Tania Castro

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by The ALC Group, LLC T/A ALC were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA

Project: NA

Coordinates:

Latitude:	40.665112 40° 39' 54" North
Longitude:	-73.960462 -73° 57' 38" West
UTM Zone:	Zone 18 North
UTM X Meters:	587868.48
UTM Y Meters:	4502101.86
Elevation:	91.77' above sea level

Maps Provided:

2019	1900
2016	1898
2013	1897
1995	
1979	
1967	
1956	
1947	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets



Brooklyn
2019
7.5-minute, 24000

2016 Source Sheets



Brooklyn
2016
7.5-minute, 24000

2013 Source Sheets



Brooklyn
2013
7.5-minute, 24000

1995 Source Sheets



Brooklyn
1995
7.5-minute, 24000
Aerial Photo Revised 1977

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979 Source Sheets



Brooklyn
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1967 Source Sheets

Brooklyn
1967
7.5-minute, 24000
Aerial Photo Revised 1966

1956 Source Sheets



Brooklyn
1956
7.5-minute, 24000

1947 Source Sheets

Brooklyn
1947
7.5-minute, 24000
Aerial Photo Revised 1940

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets

Brooklyn
1900
15-minute, 62500

1898 Source Sheets

Brooklyn
1898
15-minute, 62500

1897 Source Sheets

Brooklyn
1897
15-minute, 62500

Historical Topo Map

2019

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2019, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2016, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2013, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

Historical Topo Map

1995



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1995, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1979, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

Historical Topo Map

1967



This report includes information from the following map sheet(s).

NW N NE
W E
SW S SE

TP, Brooklyn, 1967, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

Historical Topo Map

1956

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1956, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1947, 7.5-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

Historical Topo Map

1900

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1900, 15-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1898, 15-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1897, 15-minute

SITE NAME: 962 & 972
ADDRESS: 972 Franklin Avenue
Brooklyn, NY 11225
CLIENT: The ALC Group, LLC T/A ALC

N

962 & 972
972 Franklin Avenue
Brooklyn, NY 11225

Inquiry Number: 7231046.5
January 23, 2023

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through 2017. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2017	Cole Information Services	-	X	X	-
2014	Cole Information Services	-	X	X	-
2009	Cole Information Services	-	X	X	-
2005	Hill-Donnelly Corporation	-	X	X	-
2004	Cole Information Services	-	X	X	-
2000	Cole Information Services	-	X	X	-
1999	Cole Information Services	-	X	X	-
1997	NYNEX	-	X	X	-
1994	Cole Information Services	-	X	X	-
1992	NYNEX Informantion Resource Co.	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1985	NYNEX Information Resources Company	-	X	X	-
1980	New York Telephone	-	X	X	-
1976	New York Telephone	-	X	X	-
1973	New York Telephone	-	X	X	-
1970	New York Telephone	-	X	X	-
1965	New York Telephone	-	X	X	-
1960	New York Telephone	-	X	X	-
	New York Telephone Company	-	X	X	-
1949	New York Telephone Company	-	X	X	-
1945	New York Telephone	-	X	X	-
1940	New York Telephone	-	X	X	-
1934	R. L. Polk & Co.	-	X	X	-
1928	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
962 Franklin Avenue	Client Entered	X
124 Montgomery Street	Client Entered	X
945 Franklin Avenue	Client Entered	X
1035 Washington Avenue	Client Entered	X
975 Washington Avenue	Client Entered	X

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

972 Franklin Avenue
Brooklyn, NY 11225

FINDINGS DETAIL

Target Property research detail.

FRANKLIN AVE

962 FRANKLIN AVE

Year	*Uses*	*Source*
1928	ARCADE LAUNDRY CO	New York Telephone
	STAR NAPKIN & TOWEL SUPPLY CO	New York Telephone

Franklin Avenue

962 Franklin Avenue

Year	*Uses*	*Source*
1928	ARCADE LAUNDRY CO	New York Telephone
	STAR NAPKIN & TOWEL SUPPLY CO	New York Telephone

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

FRAKLIN AVE

960 FRAKLIN AVE

Year	Uses	Source
1985	GOLOMBECK MORRIS J INC SPICES	NYNEX Information Resources Company

FRANKIIN AVE

991 FRANKIIN AVE

Year	Uses	Source
1934	WALSH JOHN J H	R. L. Polk & Co.

FRANKLIN AVE

959 FRANKLIN AVE

Year	Uses	Source
1960	RYAN LORETTA J MISS	New York Telephone
	Ryan Loretta J Miss	New York Telephone Company
1949	Risko John	New York Telephone Company
1934	MCFADDEN SARAH MGR R	R. L. Polk & Co.
	MCFADDEN SAML R	R. L. Polk & Co.
1928	BURKE B F R	New York Telephone

960 FRANKLIN AVE

Year	Uses	Source
2017	MORRIS J GOLOMBECK INC	Cole Information Services
2014	MORRIS J GOLOMBECK INCORPORATED	Cole Information Services
2009	HPG ASSOCIATES INC	Cole Information Services
	MORRIS J GOLOMBECK INC	Cole Information Services
2005	Morris J Golombeck Inc	Hill-Donnelly Corporation
2004	HPG ASSOCS INC	Cole Information Services
	MORRIS J GOLOMBECK INC	Cole Information Services
	SHALOM GOLOMBECK	Cole Information Services

FINDINGS

Year	Uses	Source
1999	GOLOMBECK MORRIS J INCORPORATED	Cole Information Services
1997	Golombeck Morris J Inc spices	NYNEX
1994	GOLOMBECK MORRIS J INC, SPICES	Cole Information Services
1992	GOLOMBECK MORRIS J INC SPICES	NYNEX Informantion Resource Co.
1976	GOLOMBECK MORRIS J INC SPICES	New York Telephone
1973	Golombeck Morris J Inc sp ces	New York Telephone
1970	Golombeck Morris J Inc spices	New York Telephone
1965	Golombeck Morris J Inc spices	New York Telephone
1960	GOLOMBECK MORRIS J INC SPICES	New York Telephone
	Golombeck Morris J Inc spices	New York Telephone Company
1949	Sisal Pad & Spring Unit Co	New York Telephone Company
	Burton Dixie Corp bedding mfrs	New York Telephone Company
1945	Burton Dixie Corp bedding mfrs	New York Telephone
	Sisal Pad & Spring Unit Co	New York Telephone
1940	Sisal Pad & Spring Unit Co	New York Telephone
1934	BURTENSHAW DIXIE CORP GEO S KNOTT GENL MGR BEDDING MFR	R. L. Polk & Co.
	BURTON OLIVER M CO INC MFRS COTTON FELT	R. L. Polk & Co.
	ROBINSON RODERS CO INC MFRD BEDDING	R. L. Polk & Co.
1928	BURTON-DIXIE CORP BEDDING MFRS	New York Telephone
	BURTON OLIVER M CO COTTON FELT MFRS	New York Telephone
	ROBINSON-RODERS CO BEDDING MFRS	New York Telephone

963 FRANKLIN AVE

Year	Uses	Source
1934	KLEBER SYLVESTER STUDENT R	R. L. Polk & Co.
	DERBY MARY R	R. L. Polk & Co.
	DERBY LORRETIA AGT R	R. L. Polk & Co.
	DERBY JULIA H	R. L. Polk & Co.

964 FRANKLIN AVE

Year	Uses	Source
1985	QUALITY METAL FABRICATORS INC	NYNEX Information Resources Company

FINDINGS

Year	Uses	Source
1973	Lustray Labs Inc	New York Telephone
	Healox Company Inc	New York Telephone
1970	Select Beauty Brands Inc	New York Telephone
	Lustray Labs Inc	New York Telephone
1965	Select Beauty Brands Inc	New York Telephone
	Lustray Labs Inc	New York Telephone
1960	STEWART & CO	New York Telephone
	DORAN B H INC	New York Telephone
	Stew art & Co	New York Telephone Company
	Doran B H Inc	New York Telephone Company

965 FRANKLIN AVE

Year	Uses	Source
1960	MUELLER PAUL H	New York Telephone
	Mueller Paul H	New York Telephone Company
1949	Mueller Paul H	New York Telephone Company
1945	Mueller Paul H	New York Telephone
1940	Mueller Paul H	New York Telephone
1934	MUELLER PAUL R	R. L. Polk & Co.
	MUELLER PAUL H SEC LYON WOVEN LABEL CO INC H	R. L. Polk & Co.
1928	MUELLER PAUL H R	New York Telephone

969 FRANKLIN AVE

Year	Uses	Source
1934	BAILEY JOHN J CHAUF H	R. L. Polk & Co.
	BRITTON HARRY AUTO MECH H	R. L. Polk & Co.

971 FRANKLIN AVE

Year	Uses	Source
1934	BRENNER BROS CORNICES AND ROOFERS	R. L. Polk & Co.

973 FRANKLIN AVE

Year	Uses	Source
1976	RETAIL CREDIT CO	New York Telephone

FINDINGS

Year	Uses	Source
1976	RETAIL CREDIT CO	New York Telephone
1973	Grdn Cty Sales	New York Telephone
	Retail Credit Co	New York Telephone
	Grdn Cty Office	New York Telephone
	Retail Credit Co	New York Telephone
1970	Retail Credit Co	New York Telephone
	Grdn Cty Office	New York Telephone
1965	Grdn Cty Sales	New York Telephone
	Retail Credit Co Brentwd Office	New York Telephone
	Retail Credit Co Brentwd Office	New York Telephone
	Grdn Cty Office	New York Telephone
1949	Brenner Alvino & Brenner Inc conveyrs	New York Telephone Company
1945	Brenner Bros cornices roofg	New York Telephone
1940	Brenner Bros cornices roofg	New York Telephone

975 FRANKLIN AVE

Year	Uses	Source
2004	BANK NEWMAN HIRSCHFIELD & BANK	Cole Information Services
1965	Weintraub Louis	New York Telephone
1960	WEINTRAUB LOUIS	New York Telephone
	LEWIS JAS J	New York Telephone
	HOYT JACK	New York Telephone
	Weintraub Louis	New York Telephone Company
	Lewis Jas J	New York Telephone Company
	Hoyt Jack	New York Telephone Company
1949	De Fillippo Nancy G	New York Telephone Company
1945	De Fillippo Nancy	New York Telephone
1934	WALKER HENRY M LAB H	R. L. Polk & Co.
	DEFILLIPO JOHN R	R. L. Polk & Co.
	DEFILLIPO MICHL LAB H	R. L. Polk & Co.
	RASO ANTHONY ICE DLR H	R. L. Polk & Co.
	VOTTA PATSY CHAUF H	R. L. Polk & Co.

FINDINGS

979 FRANKLIN AVE

Year	*Uses*	*Source*
1960	Elliot Thermographers Corp	New York Telephone Company
	ELLIOT THERMOGRAPHERS CORP	New York Telephone
1949	Fatory	New York Telephone Company
	Fyn Paint & Lacquer Co ofc w arehse	New York Telephone Company
1945	Plant & w arehouse	New York Telephone
	Fyn Paint & Lacquer Co Ofc	New York Telephone
1940	Plant w rehse	New York Telephone
	Fyn Paint & Lacquer Wks Inc ofc	New York Telephone
1934	NITROSOL CO INC LESTER KOROS PRES JACOB C SWIMMER SEC-TREAS LACQUERS AND T	R. L. Polk & Co.
1928	LONDONER CHAS	New York Telephone

980 FRANKLIN AVE

Year	*Uses*	*Source*
1934	DECICCO ANTHONY EMP RUBEL ICE CORP	R. L. Polk & Co.
1928	RUBEL COAL & ICE CORP	New York Telephone
	FLATBUSH HYGEIA ICE CO	New York Telephone

983 FRANKLIN AVE

Year	*Uses*	*Source*
1940	Ballfield Garage	New York Telephone
1934	LEVINE LOUIS WTCHMN BALT FIELD GARAGE	R. L. Polk & Co.
1928	EBBATS FIELD GARAGE	New York Telephone

985 FRANKLIN AVE

Year	*Uses*	*Source*
2017	BROOKLYN PLUMBING COMPANY	Cole Information Services
2014	BROOKLYN PLUMBING COMPANY	Cole Information Services
1965	Follman L D used clthg	New York Telephone
1960	FOLLMAN L D USED CLTHG	New York Telephone
	Follman L D used clthg	New York Telephone Company
1949	Spinner Max grocr	New York Telephone Company

FINDINGS

991 FRANKLIN AVE

Year	*Uses*	*Source*
1960	CASELLA C	New York Telephone
	Casella C	New York Telephone Company
1949	Cassidy Stephen F	New York Telephone Company
	Cooke Wm J	New York Telephone Company
1940	Cassidy Stephen	New York Telephone
	Carney Theresa	New York Telephone
1934	WALSH ALF A POLICE R	R. L. Polk & Co.
	WALSH AGNES B TEL OPR R	R. L. Polk & Co.
1928	WALSH ALFRED A R	New York Telephone

968A FRANKLIN AVE

Year	*Uses*	*Source*
1976	STONES S ACCOUNTANTS	New York Telephone

Franklin Avenue

945 Franklin Avenue

Year	*Uses*	*Source*
1965	Alvarez Angelina	New York Telephone
	Left Field Tavern	New York Telephone
	Simmons Frances Mrs	New York Telephone
1960	Simmons Frances Mrs	New York Telephone Company
	Zaher John	New York Telephone Company
	SIMMONS FRANCES MRS	New York Telephone
	ZAHER JOHN	New York Telephone
1949	Left Field Bar & Grill Corp	New York Telephone Company
	Radcliffe Arthur Mrs	New York Telephone Company
1945	Montgomery Bar & Grill Inc	New York Telephone
1940	Montgomery Restrnt	New York Telephone
1934	HERMAN WAITER H	R. L. Polk & Co.
	WRAY MAY CLK H	R. L. Polk & Co.
1928	EYRICH H CAFE	New York Telephone

FINDINGS

Montgomery Street

124 Montgomery Street

Year	Uses	Source
1985	EJK CORP AIRCRAFT & MACH DIV	NYNEX Information Resources Company
	EJK CORP AIRCRAFT & MACH DIV	NYNEX Information Resources Company
	KIEFER EDW J CUT GLAS	NYNEX Information Resources Company
1980	KIEFER EDW J CUT GLAS	New York Telephone
1976	KIEFER EDW J CUT GLGS	New York Telephone
	E J K CORP	New York Telephone
	E J K CORP	New York Telephone
1973	E J K CORP	New York Telephone
	Aircraft & Mach Div	New York Telephone
	Glasw r Div	New York Telephone
	E J K CORP	New York Telephone
1970	EJK CORP	New York Telephone
	Aircraft & Mach Div	New York Telephone
	EJK CORP	New York Telephone
	Glasw r Div	New York Telephone
	Kiefer Edw J cut glas	New York Telephone
1965	EJK CORP	New York Telephone
	Aircraft & Wach Div	New York Telephone
	EJK CORP	New York Telephone
	Glasw r Div	New York Telephone
	Kiefer Edw J cut glass	New York Telephone
1960	KIEFER EDW J CUT GLASS	New York Telephone
	LEAKE MFG CORP	New York Telephone
	Kiefer Edw J cut glass	New York Telephone Company
	Leake Mfg Corp	New York Telephone Company

WASHINGTON AVE

975 WASHINGTON AVE

Year	Uses	Source
2017	INGHAM HODGE	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	JEROME HERNANDEZ	Cole Information Services
	CLAYTON ALFRED	Cole Information Services
	KAREN BULL	Cole Information Services
	WAYNE COLLYMORE	Cole Information Services
	IDAHOSA IGHODARO	Cole Information Services
	ALENA PEPOVA	Cole Information Services
	JOSSETH PERRY	Cole Information Services
	JENNIFER SOTO	Cole Information Services
	CURTIS HARRIS	Cole Information Services
	TANYA WORKMAN	Cole Information Services
	ROSA COLBERT	Cole Information Services
	SAJATO JARRETT	Cole Information Services
	KAREN LANARRE	Cole Information Services
	JULIO APONTE	Cole Information Services
	PAMELA FRASER	Cole Information Services
	THOMAS HANSARD	Cole Information Services
	HERBERT HORN	Cole Information Services
	PIERRE JANVIER	Cole Information Services
	NYCOLE KINNS	Cole Information Services
	NATOYA LAWRENCE	Cole Information Services
	OLIVIER HELLIET	Cole Information Services
	LISA WOODS	Cole Information Services
2014	WAYNE COLLYMORE	Cole Information Services
	DIANA CLARKE	Cole Information Services
	JOSSETH PERRY	Cole Information Services
	IDAHOSA IGHODARO	Cole Information Services
	RICHETTE ROBILLARD	Cole Information Services
	JENNIFER SOTO	Cole Information Services
	JOSE FIGUEREO	Cole Information Services
	PREMA KELLEY	Cole Information Services
	JEFFREY WHEET	Cole Information Services
	TANYA WORKMAN	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2014	KRISTIN BARTLETT	Cole Information Services
	ROSA COLBERT-KASEM	Cole Information Services
	JULIO APONTE	Cole Information Services
	KAREN LANARRE	Cole Information Services
	PAMELA FRASER	Cole Information Services
	EUNICE GOMES	Cole Information Services
	NATOYA LAWRENCE	Cole Information Services
	VANESSA LAWRENCE	Cole Information Services
	ERIC SLATON	Cole Information Services
	JAIME STEIN	Cole Information Services
	PIERRE JANVIER	Cole Information Services
	OLIVIER HELLIET	Cole Information Services
	JEROME HERNANDEZ	Cole Information Services
	VINCENT NEMORIN	Cole Information Services
	CLAYTON ALFRED	Cole Information Services
	KAREN BULL	Cole Information Services
	MICHAEL HODGE	Cole Information Services
2009	VANESSA SIMON	Cole Information Services
	KAREN BULL	Cole Information Services
	MILTON MELO	Cole Information Services
	VINCENT NEMORIN	Cole Information Services
	OLIVIER HELLIET	Cole Information Services
	PIERRE JANVIER	Cole Information Services
	NATOYA LAWRENCE	Cole Information Services
	JULIO APONTE	Cole Information Services
	SARAH FIGUEREO	Cole Information Services
	ELAINE CLARKE	Cole Information Services
	ROSA COLBERT	Cole Information Services
	HUGHSTON ORR	Cole Information Services
	SHELLY QUILES	Cole Information Services
	JULIA CLAVIJO	Cole Information Services
	PHYLLIS MURCHISON	Cole Information Services

FINDINGS

Year	Uses	Source
2009	MENELAS NICOLARAKIS	Cole Information Services
	JOSSETH PERRY	Cole Information Services
	GAIL ROBINSON	Cole Information Services
	MICHAEL HODGE	Cole Information Services
	CEDAR HEART PICTURES LLC	Cole Information Services
	LOCKITUP LOCKSMITHS	Cole Information Services
	JEVON CANNON	Cole Information Services
2004	GAIL ROBINSON	Cole Information Services
	FRANKLIN THOMAS	Cole Information Services
	MENELAS NICOLARAKIS	Cole Information Services
	E QUILES	Cole Information Services
	CHERYLANN HERNANDEZ	Cole Information Services
	LISA GILL	Cole Information Services
	HUGHSTON ORR	Cole Information Services
	SADIE BRUER	Cole Information Services
	ELAINE CLARKE	Cole Information Services
	ELAINE BLUNT	Cole Information Services
	SARAH FIGUEREO	Cole Information Services
	JULIO APONTE	Cole Information Services
	ERNESTINE PLASS	Cole Information Services
	PIERRE JANVIER	Cole Information Services
	ORVILLE BROWN	Cole Information Services
	ANTHONIA MESMAIN	Cole Information Services
	CHARLANDY CHARLESCAR	Cole Information Services
	VINCENT NEMORIN	Cole Information Services
	EGLAND HODGE	Cole Information Services
	PAUL PORTO	Cole Information Services
	GLORIA ABITOL	Cole Information Services
	MONALISA COLON	Cole Information Services
	CAROL GLEN	Cole Information Services
	LISA WOODS	Cole Information Services
	VANESSA SIMON	Cole Information Services

FINDINGS

Year	Uses	Source
1994	HODGE, ERROL	Cole Information Services
	MERILUS, JOSEPH	Cole Information Services
	ARAPIOANNOU, JOSE	Cole Information Services
	ORR, HUGHSTON	Cole Information Services
	CARLTON, BENNIE	Cole Information Services
	CLARKE, E	Cole Information Services
	FENTON, C	Cole Information Services
	PENA, EMILIO	Cole Information Services
	CORRY, RONALD	Cole Information Services
	GILL, LISA	Cole Information Services
	DAVIDSON, LORNA	Cole Information Services
	TOMPKINS, LUTHER	Cole Information Services
	SERRANO, ISHMAEL	Cole Information Services
	MELO, JOSE	Cole Information Services
	CARTER, LORRAINE	Cole Information Services
	RICHARDSON, ANA	Cole Information Services
	HARPER, WINNIE	Cole Information Services

1035 WASHINGTON AVE

Year	Uses	Source
2017	RACHEL BLATT	Cole Information Services
	PHILIP TABAK	Cole Information Services
	MARIE DILLON	Cole Information Services
	MELVIN DOCTOR	Cole Information Services
	IRWIN WARWELL	Cole Information Services
	ISABEL GARCIA	Cole Information Services
	LINCOLN HEROD	Cole Information Services
	YVES JEUDY	Cole Information Services
	SOPHIE JOHNSON	Cole Information Services
	LAURA NEMESI	Cole Information Services
	ESLYN PRICE	Cole Information Services
	JOSHUA BROOME	Cole Information Services
	SCADI ETIENNE	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	CHERICE LANDERS	Cole Information Services
	JANET MASON	Cole Information Services
	LAUREN MOORE	Cole Information Services
	JENNIFER SMALL	Cole Information Services
	CARROLL BRATHWAITE	Cole Information Services
	HILLARY WEISS	Cole Information Services
	EMILY EARLE	Cole Information Services
	ANDREW ELVY	Cole Information Services
	KEVIN GATHERER	Cole Information Services
	SHERRI JEFFERSON	Cole Information Services
	AISHA RICHARDSON	Cole Information Services
	JANET SCHUMACHER	Cole Information Services
	ROCHELLE TORRES	Cole Information Services
	SHIRLEY CALEB	Cole Information Services
	SARAH CONSORO	Cole Information Services
	KIRK DOUGLAS	Cole Information Services
	MAR DURANDISSE	Cole Information Services
	MILTON WEBSTER	Cole Information Services
	MOHAMED KHAN	Cole Information Services
	BENJAMIN ROSS	Cole Information Services
	CARL WALKER	Cole Information Services
	KIMBERLY FOOTE	Cole Information Services
	VICTOR MARSHALL	Cole Information Services
	CHARLES MCCANNA	Cole Information Services
	MYRIE MCHUGH	Cole Information Services
	STEPHANIE SAISSELIN	Cole Information Services
	CHAZ TODD	Cole Information Services
	AUBREY TOONE	Cole Information Services
	WHITNEY MONTGOMERY	Cole Information Services
	BENITA SCOTT	Cole Information Services
	EMILY ALBARILLO	Cole Information Services
	STEPHANIE CHARLTON	Cole Information Services

FINDINGS

Year	Uses	Source
2017	JIWE DILLARD	Cole Information Services
	ERIC WEISS	Cole Information Services
	DOROTHEA FOGGIE	Cole Information Services
	ANDREA HICKEY	Cole Information Services
	JOEL MANGAN	Cole Information Services
	MAGGY BELIZAIRE	Cole Information Services
	CONROY ALLISON	Cole Information Services
	L ANDERSON	Cole Information Services
	DAVID CUTILLI	Cole Information Services
	CHEYENNA WEBER	Cole Information Services
	PERLINE WESTON	Cole Information Services
	CAMARA FLOWERS	Cole Information Services
	BRIDGETTE MCLEOD	Cole Information Services
	IAN MORGAN	Cole Information Services
	JANICE CLARKE	Cole Information Services
2014	LINCOLN HEROD	Cole Information Services
	YVES JEUDY	Cole Information Services
	LAURA NEMESI	Cole Information Services
	PADRAIG ODONOGHUE	Cole Information Services
	ESLYN PRICE	Cole Information Services
	IRWIN WARWELL	Cole Information Services
	CARROLL BRATHWAITE	Cole Information Services
	MILTON CHARLTON	Cole Information Services
	SULAIMAN KHAN	Cole Information Services
	ROSE KWARTENG	Cole Information Services
	CHERICE LANDERS	Cole Information Services
	JOSEPH MELENDEZ	Cole Information Services
	JANET MASON	Cole Information Services
	BRIAN PALMER	Cole Information Services
	JENNIFER SMALL	Cole Information Services
	KAMEKE SWEENEY	Cole Information Services
	DON TODD	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2014	WINSTON WESTON	Cole Information Services
	SARAH CONSORO	Cole Information Services
	JAVELINE COMPERE	Cole Information Services
	MAR DURANDISSE	Cole Information Services
	KIRK DOUGLAS	Cole Information Services
	KEVIN GATHERER	Cole Information Services
	LESLIE HENRY	Cole Information Services
	NESHANI JANI	Cole Information Services
	SHERRI JEFFERSON	Cole Information Services
	CHANDRA MOORE	Cole Information Services
	JANET SCHUMACHER	Cole Information Services
	BRIEANNE WALTMAN	Cole Information Services
	BOLAJI AGBOOLA	Cole Information Services
	WESTBROOK JOHNSON	Cole Information Services
	BENJAMIN ROSS	Cole Information Services
	SUESTER RICHARDSON	Cole Information Services
	TINESHIA STEWART	Cole Information Services
	MILTON WEBSTER	Cole Information Services
	CHARLES WEST	Cole Information Services
	FABRICE AVRIL	Cole Information Services
	PAULINE BARTON	Cole Information Services
	CRYSTAL BONNETTE	Cole Information Services
	PIERRE DILLARD	Cole Information Services
	KIMBERLY FOOTE	Cole Information Services
	VICTOR MARSHALL	Cole Information Services
	JASON RAUCEO	Cole Information Services
	AUBREY TOONE	Cole Information Services
	CARL WALKER	Cole Information Services
	JESSICA WHITTET	Cole Information Services
	HENRIETTA LOUISSAINT	Cole Information Services
	INGA KNETS	Cole Information Services
	VIVIANE PAPILLON	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2014	A PINEDA	Cole Information Services
	BENITA SCOTT	Cole Information Services
	CONROY ALLISON	Cole Information Services
	L ANDERSON	Cole Information Services
	DOROTHEA FOGGIE	Cole Information Services
	CARAN HARTSFIELD	Cole Information Services
	HALL LATIMORE	Cole Information Services
	VASSEL MCHUGH	Cole Information Services
	MARGENETT MOORE	Cole Information Services
	JENNIFER NEKHLYUDOV	Cole Information Services
	RACHEL BLATT	Cole Information Services
	JANICE CLARKE	Cole Information Services
	MARIE DILLON	Cole Information Services
	CAMARA FLOWERS	Cole Information Services
	BRANDON NEUBAUBER	Cole Information Services
	AMY POUEYMIROU	Cole Information Services
	FRANS ALBARILLO	Cole Information Services
	AMANDA BRANDES	Cole Information Services
	NIGEL GITTENS	Cole Information Services
2009	JOYE FRIDIA	Cole Information Services
	ROSE KWARTENG	Cole Information Services
	JANET MASON	Cole Information Services
	JOSEPH MELENDEZ	Cole Information Services
	MICHAEL MENSAH	Cole Information Services
	MARIE VERNEUS	Cole Information Services
	SHANIA JOHNSON	Cole Information Services
	KAMEKE SWEENEY	Cole Information Services
	REELDEAL DEALS USA	Cole Information Services
	FLYING ROCK PRODUCTIONS	Cole Information Services
	CAROL HAUGE	Cole Information Services
	LORETTA DOCTOR	Cole Information Services
	KIRK DOUGLAS	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2009	MARIE DURANDISSE	Cole Information Services
	LESLIE HENRY	Cole Information Services
	NICOLE NAVITSKY	Cole Information Services
	JEANNIE GALLEGO	Cole Information Services
	GAUNTLETT PRICE	Cole Information Services
	ENA AUSTIN	Cole Information Services
	TOMMIE MCHELON	Cole Information Services
	SHIRLEY CALEB	Cole Information Services
	JAVELINE COMPERE	Cole Information Services
	SARAH CONSORO	Cole Information Services
	SHERRI JEFFERSON	Cole Information Services
	JANET SCHUMACHER	Cole Information Services
	JACQUES DILLARD	Cole Information Services
	LESTER DURRANT	Cole Information Services
	MOHAMED KHAN	Cole Information Services
	MILTON WEBSTER	Cole Information Services
	BOLAJI AGBOOLA	Cole Information Services
	SUESTER RICHARDSON	Cole Information Services
	ROBERT RISINGER	Cole Information Services
	BILAL DERICI	Cole Information Services
	NOAH SANDERS	Cole Information Services
	KAVERI NAIR	Cole Information Services
	AUBREY TOONE	Cole Information Services
	PAULINE BARTON	Cole Information Services
	KEVIN KEATING	Cole Information Services
	CARL WALKER	Cole Information Services
	JEAN WAUGH	Cole Information Services
	JASON RAUCEO	Cole Information Services
	SEITH MANN	Cole Information Services
	A PINEDA	Cole Information Services
	VIVIANE PAPILLON	Cole Information Services
	TRUSTY FRANCIS	Cole Information Services

FINDINGS

Year	Uses	Source
2009	CLAYTON KING	Cole Information Services
	HENRIETTA LOUISSAINT	Cole Information Services
	DEBRA HARRY	Cole Information Services
	L ANDERSON	Cole Information Services
	JESSICA SINETAR	Cole Information Services
	SHEILA GITTENS	Cole Information Services
	AMY POUEYMIROU	Cole Information Services
	DORETHA FOGGIE	Cole Information Services
	PERLINE WESTON	Cole Information Services
	IAN MORGAN	Cole Information Services
	JANICE CLARKE	Cole Information Services
	JOSEPH HEROD	Cole Information Services
	ANGEL PABON	Cole Information Services
	GEORGIA FLOWERS	Cole Information Services
	KARIN BRUCE	Cole Information Services
	IRWIN WARWELL	Cole Information Services
	MARY MCINTYRE	Cole Information Services
	SUSAN REID	Cole Information Services
	MARIE RIOS	Cole Information Services
	LISSETTE CHENG	Cole Information Services
	YVES JEUDY	Cole Information Services
	SOPHIE JOHNSON	Cole Information Services
	GYAAME NANA	Cole Information Services
	DOMINIQUE TYSON	Cole Information Services
	NTIH GYAAME	Cole Information Services
	RALPH GATHERER	Cole Information Services
	LINCOLN PHILLIPS	Cole Information Services
2004	CATHERINE ELLIS	Cole Information Services
	L ANDERSON	Cole Information Services
	ANDREEN MCWILLIAMS	Cole Information Services
	CELESTIN COMPERE	Cole Information Services
	SHELLMAN JOHNSON	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	ALTONIESE STEWART	Cole Information Services
	AMY POUEYMIROU	Cole Information Services
	LAVONDA ELAM	Cole Information Services
	CHRISTINE ALLISON	Cole Information Services
	MARGARET MCRAE	Cole Information Services
	IAN MORGAN	Cole Information Services
	JANICE CLARKE	Cole Information Services
	RANA LEWIS	Cole Information Services
	ADRIAN YOUNG	Cole Information Services
	ANGEL PABON	Cole Information Services
	GEORGIA FLOWERS	Cole Information Services
	HASAN BAKR	Cole Information Services
	KARIN BRUCE	Cole Information Services
	MARIE RIOS	Cole Information Services
	MARY MCINTYRE	Cole Information Services
	LISSETTE CHENG	Cole Information Services
	TRAVIS CARROLL	Cole Information Services
	YVES JEUDY	Cole Information Services
	LORI DURDEN	Cole Information Services
	SHARON HARRIS	Cole Information Services
	DON TODD	Cole Information Services
	ABDO THABIT	Cole Information Services
	RALPH GATHERER	Cole Information Services
	LINCOLN PHILLIPS	Cole Information Services
	DOMINIQUE TYSON	Cole Information Services
	JOYE FRIDIA	Cole Information Services
	DENNIS BOSTON	Cole Information Services
	WINSTON WESTON	Cole Information Services
	CARROLL BRATHWAITE	Cole Information Services
	ROSE KWARTENG	Cole Information Services
	JOSEPH MELENDEZ	Cole Information Services
	MICHAEL MENSAH	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	TOMMIE MCHELLON	Cole Information Services
	ALLEN DENCH	Cole Information Services
	B DERICI	Cole Information Services
	BARBARA HARLEY	Cole Information Services
	G HUGH	Cole Information Services
	LESLIE HENRY	Cole Information Services
	KHARI FREEMAN	Cole Information Services
	GAUNTLETT PRICE	Cole Information Services
	SESSI ABOH	Cole Information Services
	MOHAMED ALBADANI	Cole Information Services
	ENA AUSTIN	Cole Information Services
	JAVELINE COMPERE	Cole Information Services
	JANET SCHUMACHER	Cole Information Services
	LESTER DURRANT	Cole Information Services
	NICOLE CORNILLON	Cole Information Services
	MONICA HENDERSON	Cole Information Services
	JAMES GRAHAM	Cole Information Services
	MILTON WEBSTER	Cole Information Services
	MOHAMED KHAN	Cole Information Services
	DINA KAGAN	Cole Information Services
	J RUTH	Cole Information Services
	ANNMARIE MIDGETTE	Cole Information Services
	BRADEN CHATTMAN	Cole Information Services
	ANNA SWEENEY	Cole Information Services
	GEORLINE DAVIS	Cole Information Services
	HENRY DELACOUDRAY	Cole Information Services
	AUBREY TOONE	Cole Information Services
	PAULINE BARTON	Cole Information Services
	CARL WALKER	Cole Information Services
	CLYDE WILLIAMS	Cole Information Services
	SHANIA MCLEOD	Cole Information Services
	MARTIN OFORI	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	D CRANDALL	Cole Information Services
	SEITH MANN	Cole Information Services
	JENNY DORE	Cole Information Services
	HILLARY HERMAN	Cole Information Services
	A PINEDA	Cole Information Services
	TRUSTY FRANCIS	Cole Information Services
	GELENI FONTAINE	Cole Information Services
	MICHAEL BOSWORTH	Cole Information Services
	CLAYTON KING	Cole Information Services
	HARUN ABUBAKAR	Cole Information Services
	WAI CHU	Cole Information Services
	DEBRA HARRY	Cole Information Services
	KEVIN BOSEMAN	Cole Information Services
	ARTIST RITES ENTERPRISES INC	Cole Information Services
1999	MRS BLACKS SCHOOL	Cole Information Services
1994	ALEXANDER, G	Cole Information Services
	MRS BLACK'S SCHOOL	Cole Information Services
	ISIDORE, JANE	Cole Information Services
	WALKER, CARL & ELEANOR	Cole Information Services
	LETT, A	Cole Information Services
	JOHNSON, SOPHIE & SHELLMAN	Cole Information Services
	JONES, BERNADETTE	Cole Information Services
	BREWESTER, CLEVELAND	Cole Information Services
	ALEXANDER, BETTY	Cole Information Services
	BARTON, PAULINE	Cole Information Services
	PEMBERTON, CAMELLA	Cole Information Services
	FLOWERS, G M	Cole Information Services
	DELACOUDRAY, HENRY L	Cole Information Services
	WEBSTER, MILTON	Cole Information Services
	DEFOR, MERABO	Cole Information Services
	DURDEN, C	Cole Information Services
	KING, WANDA	Cole Information Services

FINDINGS

Year	Uses	Source
1994	WESTON, WINSTON	Cole Information Services
	LAROCHELLE, GARY	Cole Information Services
	BROWN, SHARAN	Cole Information Services
	GOSHAY, I	Cole Information Services
	WESTON, PHONZETTA	Cole Information Services
	PABON, DASSILYN	Cole Information Services
	BERNARD, SYLVIA ELAINE	Cole Information Services
	HARLEY, B	Cole Information Services
	TOONE, C	Cole Information Services
	MCHELLON, TOMMIE	Cole Information Services
	ALLISON, CONROY H	Cole Information Services
	KHAN, SULAIMAN	Cole Information Services
	BLANCHARD, LORVANA	Cole Information Services
	PRESCOD, BERNARD	Cole Information Services
	THABET, ANWAR	Cole Information Services
	THOMAS, LATISHA	Cole Information Services
	REID, M	Cole Information Services
	ALBEN, BEATRICE	Cole Information Services
	JOHNSON, DEIDRE	Cole Information Services
	SMITH, T SHEKERE	Cole Information Services
	DOGUE, GISELLE	Cole Information Services
	DAVIS, GEORLINE	Cole Information Services
	REID, SUSAN	Cole Information Services
	GARIBALDI, S	Cole Information Services
	STEWART, ALTONESE	Cole Information Services
	FORDE, M	Cole Information Services

Washington Avenue

975 Washington Avenue

Year	Uses	Source
2005	Multi Unit Address	Hill-Donnelly Corporation
	Aponte Julio	Hill-Donnelly Corporation

FINDINGS

Year	Uses	Source
2005	Number10 h Chambers Javler	Hill-Donnelly Corporation
	Number2 F h Clarke E	Hill-Donnelly Corporation
	Number1 Flguereo Jose A 0 V	Hill-Donnelly Corporation
	Number3 E 8 Glen Carol	Hill-Donnelly Corporation
	Number2 C h Hodge B	Hill-Donnelly Corporation
	Hodge Michael	Hill-Donnelly Corporation
	Number1 E h Janvier Pierre	Hill-Donnelly Corporation
	Law rence Natoya s	Hill-Donnelly Corporation
	Number3 H h Mel N Milton	Hill-Donnelly Corporation
	Number4 A h Nicolarakis Menelas	Hill-Donnelly Corporation
	Number3 C H Orr Hughston	Hill-Donnelly Corporation
	Ortiz Madeline	Hill-Donnelly Corporation
	h Quiles Shelly	Hill-Donnelly Corporation
	Number4 K h Robinson Gall	Hill-Donnelly Corporation
2000	APARTMENTS	Cole Information Services
	3D BENNIE CARLTON	Cole Information Services
	2F E CLARKE	Cole Information Services
	2J MONALISA COLON	Cole Information Services
	1I GILBERT DOUGLAS	Cole Information Services
	LISA GILL	Cole Information Services
	CAROL GLEN	Cole Information Services
	4H C HERNANDEZ	Cole Information Services
	LEONEL HEVIA	Cole Information Services
	2I ERROL HODGE	Cole Information Services
	EYHANA HOLLINGTON	Cole Information Services
	S JACK ALVAREZ	Cole Information Services
	T JOBITY	Cole Information Services
	ANTHONIA MESMAIN	Cole Information Services
	M NICOLARAKIS	Cole Information Services
	HUGHSTON ORR	Cole Information Services
	1C FERNANDO ORITZ	Cole Information Services
	3H EMILIO PENA	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2000	2K ERNESTINE PLASS	Cole Information Services
	PAUL PORTO	Cole Information Services
	AUSTIN RAMSEY	Cole Information Services
	1G ROBERT TROWELL	Cole Information Services
	1D JUDITH WAIWELL	Cole Information Services
1997	BLUNT Elaine	NYNEX
	CLARKE E	NYNEX
	COLON Monalisa	NYNEX
	CORRY Ronald	NYNEX
	DOUGLAS Gilbert	NYNEX
	ENOCH Toneylle	NYNEX
	FENTON C	NYNEX
	GILL Lisa	NYNEX
	HERNANDEZ C	NYNEX
	HODGE Errol	NYNEX
	HOSPEDALES Brett	NYNEX
	MERILUS Joseph	NYNEX
	NICOLARAKIS Menelas	NYNEX
	ORR Hughston	NYNEX
	ORTIZ Fernando	NYNEX
	PASTRANA Yolanda	NYNEX
	PENA Emillo	NYNEX
1992	SERRANO ISHMAEL	NYNEX Informantion Resource Co.
	ALLEYNE MERNA	NYNEX Informantion Resource Co.
	ARAPIOANNOU JOSE	NYNEX Informantion Resource Co.
	BARTHOLOMEW D	NYNEX Informantion Resource Co.
	CARLO JOSE	NYNEX Informantion Resource Co.
	CARLTON BENNIE	NYNEX Informantion Resource Co.
	CLARKE E	NYNEX Informantion Resource Co.
	CORRY RONALD	NYNEX Informantion Resource Co.
	FENTON C	NYNEX Informantion Resource Co.
	GILL LISA	NYNEX Informantion Resource Co.

FINDINGS

Year	Uses	Source
1992	JOYNER C	NYNEX Informantion Resource Co.
	MELO JOSE	NYNEX Informantion Resource Co.
	MELO ORQULDIA	NYNEX Informantion Resource Co.
	MERILUS JOSEPH	NYNEX Informantion Resource Co.
	ORR HUGHSTON	NYNEX Informantion Resource Co.
	PENA EMILIO	NYNEX Informantion Resource Co.
	RODRIGUEZ EDUVIGIS	NYNEX Informantion Resource Co.
	TAYLOR WARREN	NYNEX Informantion Resource Co.
1985	MARRAST FRANCIS T	NYNEX Information Resources Company
	BELGARDE GEORGINA	NYNEX Information Resources Company
	CORRY RONALD	NYNEX Information Resources Company
	HAMILTON R	NYNEX Information Resources Company
	KENNEDY E	NYNEX Information Resources Company
	MERILUS JOSEPH	NYNEX Information Resources Company
	ORR HUGHSTON	NYNEX Information Resources Company
	PETERS W	NYNEX Information Resources Company
	ROBINSON G	NYNEX Information Resources Company
	ROWLEY J	NYNEX Information Resources Company
	RUDYK E	NYNEX Information Resources Company
	VELEZ MYRNA	NYNEX Information Resources Company
	VOLTAIRE E	NYNEX Information Resources Company
	WILLIAMS GREGORY	NYNEX Information Resources Company
1980	MARRAST TREVOR F	New York Telephone
	ORR HUGHSTON	New York Telephone
	ROBERTS RICK	New York Telephone
	STIGALL Y	New York Telephone
	ROBBINS JOHN	New York Telephone
1976	RABINOWITZ JEFFREY	New York Telephone
	ABOUELAZM AHMED	New York Telephone
	AKSOY SALT ZIYA	New York Telephone
	ALGOOD CARL	New York Telephone
	APDIROGLU FIRDES	New York Telephone

FINDINGS

Year	Uses	Source
1976	ASRETLI EMINE	New York Telephone
	BALLARD DONNA	New York Telephone
	BLACKWELL MAMIE	New York Telephone
	BRANKER E	New York Telephone
	DENIZE SOLANGES	New York Telephone
	HACIOGLU RAUF	New York Telephone
	JOHNSON REGINALD	New York Telephone
	JURGELEIT W D	New York Telephone
	LAM HUNG K	New York Telephone
	MURPHY S	New York Telephone
	ORR HUGHSTON	New York Telephone
	THOMPSON WALLACE	New York Telephone
	TUNAIL IIKER AHMET	New York Telephone
1973	Andrean P G	New York Telephone
	Asretli Emine	New York Telephone
	Barous John	New York Telephone
	Branker Ernesta	New York Telephone
	Bursh Maxine Mrs	New York Telephone
	Clements C S	New York Telephone
	Hacioglu Rauf	New York Telephone
	Hooten Douglas	New York Telephone
	Iglesias Carmen Mrs	New York Telephone
	Kondo Chuzo	New York Telephone
	Lam Hung K	New York Telephone
	Lippman F	New York Telephone
	Lorber Betty M	New York Telephone
	Okamura Frank M	New York Telephone
	Oztan Sedat	New York Telephone
	Rabinow itz Jeffrey	New York Telephone
	Reitman Peter M	New York Telephone
	Seider R	New York Telephone
	Sperato Raymond	New York Telephone

FINDINGS

Year	Uses	Source
1973	Steinfeld Carlos	New York Telephone
	Tunail Itker Ahmet	New York Telephone
	Weinberg Saml M	New York Telephone
1970	Abrahams Wm T	New York Telephone
	Barous John	New York Telephone
	Bursh Maxine Mrs	New York Telephone
	Ellis Allan L	New York Telephone
	Ergun Turgay	New York Telephone
	Hopping Bethia M	New York Telephone
	Inal Selahattin	New York Telephone
	Jackson J R	New York Telephone
	Kanter R Balsam	New York Telephone
	Kessler M	New York Telephone
	Kleiman K	New York Telephone
	Knight M	New York Telephone
	Kramer Ruth F	New York Telephone
	Lippman F	New York Telephone
	Lorber Betty M	New York Telephone
	Muratore Shinji	New York Telephone
	Novatt Fay	New York Telephone
	Okamutra Frank M	New York Telephone
	Oztan Sedat	New York Telephone
	Reitman Vicki	New York Telephone
	Rodriguez I	New York Telephone
	Scott W A	New York Telephone
	Seider R	New York Telephone
	Simmons V M	New York Telephone
	Steinfeld Carlos	New York Telephone
	Tunail Ilker Ahmet	New York Telephone
	Villa Patricia	New York Telephone
	Weinberg Saml M	New York Telephone
	Wenger M	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1965	Asretll Haybullah	New York Telephone
	Bursh Maxine Mrs	New York Telephone
	Ellis Allan L	New York Telephone
	Geller H	New York Telephone
	Hedderson Betty	New York Telephone
	Hirsch Mae	New York Telephone
	Hopping Bethia M	New York Telephone
	Kanter R Balsam	New York Telephone
	Kramer Ruth F	New York Telephone
	Lippman F	New York Telephone
	Mc Fadden Jerry R	New York Telephone
	Nahem Jos	New York Telephone
	Novatt Fay	New York Telephone
	Okamura Frank M	New York Telephone
	Rose Harry	New York Telephone
	Rosen Harry	New York Telephone
	Schwartz S	New York Telephone
	Seider R	New York Telephone
	Shore Max L	New York Telephone
	Sissman Mac	New York Telephone
	Stevens Jules P	New York Telephone
	Tardo Janet	New York Telephone
	Trouse A	New York Telephone
	Voulgarelis Nikos	New York Telephone
	Weinberg Saml M	New York Telephone
1960	Alexander S	New York Telephone Company
	Antanovsky Bertha Mrs	New York Telephone Company
	Balin Harry	New York Telephone Company
	Baron Irving	New York Telephone Company
	Berl W	New York Telephone Company
	Birnholz Regina	New York Telephone Company
	Burtoff Morris	New York Telephone Company

FINDINGS

Year	*Uses*	*Source*
1960	Chassen Edw	New York Telephone Company
	Cohen H	New York Telephone Company
	Corrigan Wm M Jr	New York Telephone Company
	Geller Helen Miss	New York Telephone Company
	Geller Saml	New York Telephone Company
	Hedderson Betty	New York Telephone Company
	Hertz Arthur	New York Telephone Company
	Hirsch Mae	New York Telephone Company
	Hockstein A	New York Telephone Company
	Kanter Rose	New York Telephone Company
	Kramer Ruth F	New York Telephone Company
	Lerner Elias	New York Telephone Company
	Lippman Freda	New York Telephone Company
	Mandel Max	New York Telephone Company
	Mc Groarty John	New York Telephone Company
	Meehan Joan Mrs	New York Telephone Company
	Meehan John	New York Telephone Company
	Mermelstein Max	New York Telephone Company
	Mocrey Robt	New York Telephone Company
	Mullaney John V	New York Telephone Company
	Novatt Fay	New York Telephone Company
	Parisi Arthur C	New York Telephone Company
	Rosen Harry	New York Telephone Company
	Seider R	New York Telephone Company
	Shore Max L	New York Telephone Company
	Sissman Max	New York Telephone Company
	Sokoloff Nathan	New York Telephone Company
	Studin Dorothy	New York Telephone Company
	Tenner Terry	New York Telephone Company
	Trouse A	New York Telephone Company
	Turner Max	New York Telephone Company
	WEINBERG SAML M	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1949	Belser U	New York Telephone Company
	Birnholz F R Miss	New York Telephone Company
	Bukzin Jack	New York Telephone Company
	Burns Geo R	New York Telephone Company
	Burtoff Morris	New York Telephone Company
	Chassen Edw	New York Telephone Company
	Cohen Mildred Pearl	New York Telephone Company
	Dobrovir Rose Mrs	New York Telephone Company
	Fishman Molly Mrs	New York Telephone Company
	Freedenberg Morris	New York Telephone Company
	Galaton Martin	New York Telephone Company
	Gans Geo	New York Telephone Company
	Gomberg Belle	New York Telephone Company
	Goodstein Frank	New York Telephone Company
	Herman Tillie	New York Telephone Company
	Jaffe Michl	New York Telephone Company
	Kanter Rose	New York Telephone Company
	Kaplan Hy	New York Telephone Company
	Koenig John H Mrs	New York Telephone Company
	Kraham Chas C	New York Telephone Company
	Lang E M	New York Telephone Company
	Lapper Mitzi Mrs	New York Telephone Company
	Levine Lee Mrs	New York Telephone Company
	Mc Dermott Geo C	New York Telephone Company
	Merrifield Richd N	New York Telephone Company
	Novatt Fay	New York Telephone Company
	Palmer Morris	New York Telephone Company
	Plocker A	New York Telephone Company
	Roof Molly	New York Telephone Company
	Rubinstein Martin	New York Telephone Company
	Sackheim Abram F	New York Telephone Company
	Shore Max L	New York Telephone Company

FINDINGS

Year	Uses	Source
1949	Silverman Louis	New York Telephone Company
	Stevens Jules P	New York Telephone Company
	Thorn Ben	New York Telephone Company
1945	Chaikin Benny	New York Telephone
	Cohen Marvin M	New York Telephone
	Cohen Mildred Pearl	New York Telephone
	Fishman Molly Mrs	New York Telephone
	Gomberg Belle	New York Telephone
	Hirshan M	New York Telephone
	King Leona nrse	New York Telephone
	Lang E M	New York Telephone
	Maxon Sylvia	New York Telephone
	Novatt Fay	New York Telephone
	Pasternack Abraham	New York Telephone
	Plocker A	New York Telephone
	Sackheim Abram F	New York Telephone
	Schwartz Rose T	New York Telephone
	Shapiro Lee	New York Telephone
	Silverman Louis	New York Telephone
	Singer David	New York Telephone
	Watkins Jeanette K	New York Telephone
1940	Birnholz F R Miss	New York Telephone
	Cohen Mildred Pearl	New York Telephone
	Dinney Sadie	New York Telephone
	Gomberg Belle	New York Telephone
	Goodman A	New York Telephone
	Hirshan M	New York Telephone
	Holtzberg Milton	New York Telephone
	Kaplan C	New York Telephone
	King Leona nrse	New York Telephone
	Maxon Susan	New York Telephone
	Mosco James	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1940	Novatt S	New York Telephone
	Prussack B J	New York Telephone
	Roof Irving	New York Telephone
	Schwartz Rose T	New York Telephone
	Seid Claire	New York Telephone
	Stone Leo F	New York Telephone
	Suib David	New York Telephone
	Zatushna Rose nrse	New York Telephone
1928	BAKER GEO P R	New York Telephone
	BIDWELL J P R	New York Telephone
	BLACK NANCY MRS R	New York Telephone
	BRIGGS LEONARD S R	New York Telephone
	BRUMBERG FRANK R	New York Telephone
	BUCKOWITZ P M R	New York Telephone
	CAMPBELL ANDREW H R	New York Telephone
	CIANO FRANK R	New York Telephone
	DAVIDSON LILLIAN R	New York Telephone
	HAMBERGER D R	New York Telephone
	HENRY GERALD B R	New York Telephone
	HOTCHKISS GROSVENOR R	New York Telephone
	HOUSE F MISS R	New York Telephone
	HOUSE ROSE MISS R	New York Telephone
	HOWELLS EDMUND H R	New York Telephone
	LANDSMAN GEO M R	New York Telephone
	MEANY MARIE MRS R	New York Telephone
	MERKLINGER ROBT J R	New York Telephone
	MILLS DONALD C R	New York Telephone
	RAIS FLORENCE MISS R	New York Telephone
	RIZZO AL R	New York Telephone
	STEINBERG JOS R	New York Telephone
	STEINBERGER ANNA R	New York Telephone
	STEINBERGER SAMIL R	New York Telephone

FINDINGS

Year	Uses	Source
1928	ZEIDEN HARRY R	New York Telephone
	ZENDER F A R	New York Telephone

1035 Washington Avenue

Year	Uses	Source
2005	Multi Unit Address	Hill-Donnelly Corporation
	NumberGR 2 Agboola Bolaji	Hill-Donnelly Corporation
	Anderson L	Hill-Donnelly Corporation
	Bakr Hasan	Hill-Donnelly Corporation
	Number5 F h Barton Pauline	Hill-Donnelly Corporation
	h Bosw orth Michael	Hill-Donnelly Corporation
	Number5 T Bruce Karin	Hill-Donnelly Corporation
	Number3 F h Clarke Janice	Hill-Donnelly Corporation
	Number2 N Compere Ericque	Hill-Donnelly Corporation
	Compere Javletine	Hill-Donnelly Corporation
	Consoro Sarah	Hill-Donnelly Corporation
	Number4 N a Crandall D	Hill-Donnelly Corporation
	Number6 K h Davis Tyrone	Hill-Donnelly Corporation
	Number1 R Davison William	Hill-Donnelly Corporation
	Number2 T Delacoudray Henry L	Hill-Donnelly Corporation
	Number1 N Derici B	Hill-Donnelly Corporation
	Number2 K Douglas Kirk v	Hill-Donnelly Corporation
	Number5 A h Durandisse M	Hill-Donnelly Corporation
	Number6D h Flow ers G M	Hill-Donnelly Corporation
	Number40 h Franis Trusty	Hill-Donnelly Corporation
	Freeman Khari	Hill-Donnelly Corporation
	Number4 B h Gatherer Emily	Hill-Donnelly Corporation
	Number68 h Grange Colette	Hill-Donnelly Corporation
	Number5 H h Inniss Beverley	Hill-Donnelly Corporation
	Number1 F Jeudy Yves	Hill-Donnelly Corporation
	Johnson Shellman	Hill-Donnelly Corporation
	Number58 Johnson Sophie & Shellman	Hill-Donnelly Corporation
	Number3D h Khan Sulaiman A	Hill-Donnelly Corporation

FINDINGS

Year	*Uses*	*Source*
2005	Number6 S h King Cayton S Jr	Hill-Donnelly Corporation
	Number3 T h Kw arteng Rose	Hill-Donnelly Corporation
	Loulssaint Henrietta	Hill-Donnelly Corporation
	Number4D Mann Seith	Hill-Donnelly Corporation
	h Mc Intyre M B L	Hill-Donnelly Corporation
	h Mchellon Tommie	Hill-Donnelly Corporation
	h Meliendez Joseph	Hill-Donnelly Corporation
	Mensah Michael	Hill-Donnelly Corporation
	Number4 F Morgan Ian	Hill-Donnelly Corporation
	Mrs Blacks School	Hill-Donnelly Corporation
	Ofrib Martin	Hill-Donnelly Corporation
	Number10D h Pabon D	Hill-Donnelly Corporation
	Number2 R Phillips Lincoln	Hill-Donnelly Corporation
	Pineda A	Hill-Donnelly Corporation
	Number6 M Poueymirou Amy	Hill-Donnelly Corporation
	Number5 Eh Price E G	Hill-Donnelly Corporation
	Reid Maria	Hill-Donnelly Corporation
	Reid Young Michelle	Hill-Donnelly Corporation
	Number2 B h Rios Marie	Hill-Donnelly Corporation
	Ruth J	Hill-Donnelly Corporation
	Number3 L h Schumacher	Hill-Donnelly Corporation
	Senhouse Sheila Number 18 h Stew art Altonlese v 71a	Hill-Donnelly Corporation
	Toone C	Hill-Donnelly Corporation
	Number3 K h Toone Carolyn	Hill-Donnelly Corporation
	Number2 C h Tyson DomInique	Hill-Donnelly Corporation
	Vemreus Marie Immacula 0v os	Hill-Donnelly Corporation
	Number1 h Walker Carl & Eleanor	Hill-Donnelly Corporation
	Number2 A h Webster Milton AV	Hill-Donnelly Corporation
	Number6 L H Weston Winston	Hill-Donnelly Corporation
	Weston Winston	Hill-Donnelly Corporation
	Weston Winston	Hill-Donnelly Corporation
2000	S ABOH	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2000	BETTY ALEXANDER	Cole Information Services
	CHRISTINE ALLISON	Cole Information Services
	CONROY H ALLISON	Cole Information Services
	PAULINE BARTON	Cole Information Services
	RONALD BLACKMAN	Cole Information Services
	AMEULD BLOUCHARD	Cole Information Services
	MICHAEL BOSWORTH	Cole Information Services
	CARROLL BRATHWATE	Cole Information Services
	LEEORA BROWN	Cole Information Services
	W CHISHOLM	Cole Information Services
	JAVELINE COMPERE	Cole Information Services
	GEORLINE DAVIS	Cole Information Services
	H L DELACOUDRAY	Cole Information Services
	ALLEN DENCH	Cole Information Services
	B DERICI	Cole Information Services
	C DURDEN	Cole Information Services
	LESTER DURRANT	Cole Information Services
	G M FLOWERS	Cole Information Services
	COBIE FOSTER	Cole Information Services
	C FRIED JENKINS	Cole Information Services
	EMILY GATHERER	Cole Information Services
	I GOSHAY	Cole Information Services
	JAMES GREHAM	Cole Information Services
	LESLIE HENY	Cole Information Services
	RICHARD T HIMES	Cole Information Services
	JANE ISIDORE	Cole Information Services
	YVES JEUDY	Cole Information Services
	SHELLMAN JOHNSON	Cole Information Services
	SOPHIE JOHNSON	Cole Information Services
	SUFAIMAN KHAN	Cole Information Services
	A LE VAILLANT	Cole Information Services
	DERRICK LEWIS	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2000	TOMMIE MC HELLON	Cole Information Services
	M B MCINTYRE	Cole Information Services
	SHANIA MCLEOD	Cole Information Services
	JOSEPH MELENDEZ	Cole Information Services
	MICHAEL MENSAH	Cole Information Services
	CYBELE MERRICK	Cole Information Services
	ROSE MINTA ADDO	Cole Information Services
	CARNE OLSHAN	Cole Information Services
	D PABON	Cole Information Services
	LINCOLN PHILLIPS	Cole Information Services
	DOURRHO PIERRE	Cole Information Services
	E G PRICE	Cole Information Services
	M REID	Cole Information Services
	SUSAN REID	Cole Information Services
	MANE RIOS	Cole Information Services
	L SAUNDERSON	Cole Information Services
	ALTONIESE STEWART	Cole Information Services
	OZBIL TEZCAN	Cole Information Services
	ABDO S THABIT	Cole Information Services
	AUBREY TOONE	Cole Information Services
	C TOONE	Cole Information Services
	CAROLYN TOONE	Cole Information Services
	CARL WALKER	Cole Information Services
	I WALTER	Cole Information Services
	MILTON WEBSTER	Cole Information Services
	WINSTON WESTON	Cole Information Services
	WINSTON WESTON	Cole Information Services
	MRS BLACKS SCHOOL	Cole Information Services
1997	Mrs Blacks School	NYNEX
	ALEXANDER Betty	NYNEX
	ALEXANDER G	NYNEX
	ALLISON Conroy H	NYNEX

FINDINGS

Year	*Uses*	*Source*
1997	ANDRE Edith	NYNEX
	BARTON Pauline	NYNEX
	BERNARD Sylvia Elaine	NYNEX
	BLANCHARD Lorvana	NYNEX
	BREWESTER Cleveland	NYNEX
	COMPERE Javeline	NYNEX
	CONTENT Hugues	NYNEX
	DAVIS Georline	NYNEX
	DEAN P	NYNEX
	DURDEN C	NYNEX
	FORDE M	NYNEX
	GARIBALDI S	NYNEX
	GOSHAY I	NYNEX
	GRANGE Stacey	NYNEX
	HARLEY B	NYNEX
	HENRY Leslie	NYNEX
	HENRY Leslie	NYNEX
	JOHNSON Charles	NYNEX
	JOHNSON Deidre	NYNEX
	JOHNSON Sophie & Shelman	NYNEX
	JONES Bernadette	NYNEX
	KHAN Sulaiman	NYNEX
	KING Wands	NYNEX
	LAROCHELLE Gary	NYNEX
	MCHELLON Tommie	NYNEX
	REID	NYNEX
	REID Susan	NYNEX
	SAMEDY Woodley	NYNEX
	SAUNDERSON L	NYNEX
	SMITH D	NYNEX
	THABIT Abdo S	NYNEX
	THOMAS Latisha	NYNEX

FINDINGS

Year	*Uses*	*Source*
1997	TOONE Aubrey	NYNEX
	TOONE C	NYNEX
	TOONE Carolyn	NYNEX
	TORCHON Guirlande	NYNEX
	WALKER Carl & Eleanor	NYNEX
	WEBSTER Milton	NYNEX
	WESTON Phonzetta	NYNEX
	WESTON Winston	NYNEX
1992	ALBEN B	NYNEX Informantion Resource Co.
	ALEXANDER BETTY	NYNEX Informantion Resource Co.
	ALEXANDER G	NYNEX Informantion Resource Co.
	ALLISON CONROY H	NYNEX Informantion Resource Co.
	ANTOINE MARISE	NYNEX Informantion Resource Co.
	BARNES S	NYNEX Informantion Resource Co.
	BARTON PAULINE	NYNEX Informantion Resource Co.
	BEKOFSKY M	NYNEX Informantion Resource Co.
	BERNARD SYLVIA ELAINE	NYNEX Informantion Resource Co.
	BLANCHARD LORNA	NYNEX Informantion Resource Co.
	BRUTUS MARIE H	NYNEX Informantion Resource Co.
	CHARLES WILFRED	NYNEX Informantion Resource Co.
	COBHAM MARIE	NYNEX Informantion Resource Co.
	DELACOUDRAY HENRY L	NYNEX Informantion Resource Co.
	DEL ROSARIO A	NYNEX Informantion Resource Co.
	DOGUE GISELLE	NYNEX Informantion Resource Co.
	DURANDISSE M	NYNEX Informantion Resource Co.
	DURDEN C	NYNEX Informantion Resource Co.
	ETIENNE MARIE	NYNEX Informantion Resource Co.
	FLOWERS G M	NYNEX Informantion Resource Co.
	FORD K	NYNEX Informantion Resource Co.
	FRIDIA J	NYNEX Informantion Resource Co.
	GILES LANTHE	NYNEX Informantion Resource Co.
	HARLEY B	NYNEX Informantion Resource Co.

FINDINGS

Year	*Uses*	*Source*
1992	HARLEY B	NYNEX Informantion Resource Co.
	ISIDORE JANE	NYNEX Informantion Resource Co.
	JOHNSON SOPHIE & SHELLMAN	NYNEX Informantion Resource Co.
	JONES BERNADETTE	NYNEX Informantion Resource Co.
	KHAN SULAIMAN	NYNEX Informantion Resource Co.
	MCCLENDON JACKIE	NYNEX Informantion Resource Co.
	MRS BLACKS SCHOOL	NYNEX Informantion Resource Co.
	PABON DASILYN	NYNEX Informantion Resource Co.
	PERRY D	NYNEX Informantion Resource Co.
	PERRY ERIKA	NYNEX Informantion Resource Co.
	PINEDA ALICIA	NYNEX Informantion Resource Co.
	PRINGLE J	NYNEX Informantion Resource Co.
	SAMAD JEAN	NYNEX Informantion Resource Co.
	TOONE C	NYNEX Informantion Resource Co.
	WALKER CARL & ELEANOR	NYNEX Informantion Resource Co.
	WEBSTER MILTON	NYNEX Informantion Resource Co.
	WESTON PHONZETTA	NYNEX Informantion Resource Co.
	WESTON WINSTON	NYNEX Informantion Resource Co.
1985	ALLISON CONROY H	NYNEX Information Resources Company
	ATLAS G	NYNEX Information Resources Company
	BARNES S	NYNEX Information Resources Company
	BARTON PAULINE	NYNEX Information Resources Company
	BEKOFSKY M	NYNEX Information Resources Company
	BOSTIC A L	NYNEX Information Resources Company
	BRICE R L	NYNEX Information Resources Company
	CURRY GABRIEL	NYNEX Information Resources Company
	DEMONIC SHEILAH	NYNEX Information Resources Company
	DURDEN L	NYNEX Information Resources Company
	DUPREE B	NYNEX Information Resources Company
	FORD K	NYNEX Information Resources Company
	GRANDCHAMPS GARY	NYNEX Information Resources Company
	GROSS L L	NYNEX Information Resources Company

FINDINGS

Year	Uses	Source
1985	HARLEY B	NYNEX Information Resources Company
	HERNANDEZ MOISES	NYNEX Information Resources Company
	HYLTON SEE ALSO HILTON HYLTON A	NYNEX Information Resources Company
	IKEAGU F	NYNEX Information Resources Company
	ISIDORE JANE	NYNEX Information Resources Company
	JEAN HENRY	NYNEX Information Resources Company
	KHAN SULAIMAN	NYNEX Information Resources Company
	LAROCHELLE G	NYNEX Information Resources Company
	LAVENTURE EMANUEL	NYNEX Information Resources Company
	MORRISON A	NYNEX Information Resources Company
	MRS BLACK S SCHOOL	NYNEX Information Resources Company
	PHILLIPS TYRONE	NYNEX Information Resources Company
	PINNOCK P	NYNEX Information Resources Company
	PRINGLE J	NYNEX Information Resources Company
	ROBINSON AVON	NYNEX Information Resources Company
	SCOTT L	NYNEX Information Resources Company
	TONDREAU L	NYNEX Information Resources Company
	TOONE C	NYNEX Information Resources Company
	WALKER CARL & ELEANOR	NYNEX Information Resources Company
	WAUGH JEAN BEVERLY	NYNEX Information Resources Company
	WESTON PHONZETTA	NYNEX Information Resources Company
	DEIACOUDRAY HENRY L	NYNEX Information Resources Company
	SANDERS WILLIAM E	NYNEX Information Resources Company
1980	ATLAS G	New York Telephone
	FINDLAY NORVILLA	New York Telephone
	GOLDSTEIN J S	New York Telephone
	KHAN-HUTSON B	New York Telephone
	KHAN ROBIE	New York Telephone
	PINNOCK P	New York Telephone
	WALKER CARL & ELEANOR	New York Telephone
	WILLIAMS M	New York Telephone
1976	FEINBERG IRVING	New York Telephone

FINDINGS

Year	Uses	Source
1976	ANTHONY EVANDA	New York Telephone
	ATLAS G	New York Telephone
	BRICE R L	New York Telephone
	BRILL SOL	New York Telephone
	BRODERSON ESTHER A	New York Telephone
	BRUCKNER EDWARD	New York Telephone
	CLEVELAND C H	New York Telephone
	COLEMAN V	New York Telephone
	DECADY MANASSE	New York Telephone
	DURDEN L	New York Telephone
	EVANS ROBERT	New York Telephone
	FINDLAY NORVILLA	New York Telephone
	FORBES R	New York Telephone
	FRIQUE P	New York Telephone
	GILLIAM W M	New York Telephone
	GOLDFARB N A	New York Telephone
	GOLDSTEIN E J	New York Telephone
	GOLDSTEIN J S	New York Telephone
	HINDS GWENETH A	New York Telephone
	HOBEL A	New York Telephone
	HYLTON A	New York Telephone
	ISIDORE JANE	New York Telephone
	JOE CLIVE C	New York Telephone
	MCGILL M	New York Telephone
	PATTERSON G	New York Telephone
	PINNOCK P	New York Telephone
	RODRIGUEZ D	New York Telephone
	ROWSON A	New York Telephone
	SANDERS WILLIAM E	New York Telephone
	SCHULER GLORIA	New York Telephone
	SCOTT L	New York Telephone
	SHAPIRO JOSEPH	New York Telephone

FINDINGS

Year	Uses	Source
1976	SHULER JAMES	New York Telephone
	SORRELL LUCY MRS	New York Telephone
	WADDELL B	New York Telephone
	WALKER ELEANORE	New York Telephone
	WESTON PHONZETTA	New York Telephone
	WILLIAMS M	New York Telephone
	WILSON S	New York Telephone
1973	Alper Nat	New York Telephone
	Appell Stanton	New York Telephone
	Atlas G	New York Telephone
	Babior Martin	New York Telephone
	Bekofsky Mollie Mrs	New York Telephone
	Brice R L	New York Telephone
	Brodeson Esther Av	New York Telephone
	Buzen Rose	New York Telephone
	Clapp G H	New York Telephone
	Davies H M Mrs	New York Telephone
	Decady Manasse	New York Telephone
	Diskin Philip	New York Telephone
	Ellenport Harry	New York Telephone
	Evans Robert	New York Telephone
	Feinberg Irving	New York Telephone
	Frater E	New York Telephone
	Fratkin William	New York Telephone
	Frederick G	New York Telephone
	Friday Jerry	New York Telephone
	Gilbert Philip J	New York Telephone
	Gilliam W M	New York Telephone
	Goldberg David	New York Telephone
	Goldfarb N A DDS	New York Telephone
	Goldman Rose	New York Telephone
	Goldstein Maurice	New York Telephone

FINDINGS

Year	Uses	Source
1973	Gordon Leo	New York Telephone
	Grashow Edward	New York Telephone
	Grashow Jas B	New York Telephone
	Gross L L	New York Telephone
	Gross Rose Mrs	New York Telephone
	Harris Sand	New York Telephone
	Hinds Gweneth A	New York Telephone
	Hobel A	New York Telephone
	Hunt Ruth	New York Telephone
	Isidore Jane	New York Telephone
	Janpole Max L	New York Telephone
	Katz Bee Mrs	New York Telephone
	Katz Ida S	New York Telephone
	Komow Irene	New York Telephone
	Kramer Martin	New York Telephone
	Kurtin Edith A	New York Telephone
	Lanch Dan	New York Telephone
	Lefkowitz D	New York Telephone
	Lipski Joel	New York Telephone
	Maslow Max	New York Telephone
	Megann Johna G	New York Telephone
	Morais Michele	New York Telephone
	Pavey Mollie	New York Telephone
	Perlman Bill	New York Telephone
	Perlman William	New York Telephone
	Pinnock P	New York Telephone
	Rappaport Jos	New York Telephone
	Rice A	New York Telephone
	Rose Lester	New York Telephone
	Roseman Ellen K	New York Telephone
	Roseman Gertrude	New York Telephone
	Sanders William E	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1973	Sandler Hannah Mis	New York Telephone
	Scher B	New York Telephone
	Scott L	New York Telephone
	Seldow itz Benj	New York Telephone
	Sellinger Harry	New York Telephone
	Serota Aaron	New York Telephone
	Serota Robt	New York Telephone
	Shanman Jay	New York Telephone
	Shapiro Jos Iw yr	New York Telephone
	Residence	New York Telephone
	Simmons Herbert L	New York Telephone
	Sosnoff Miriam	New York Telephone
	Tirsch Jacob	New York Telephone
	Unger S	New York Telephone
	Uager S	New York Telephone
	Weinstein M	New York Telephone
	Weiss Steve	New York Telephone
	Wilson S	New York Telephone
	Wolff David	New York Telephone
	Yormark Jos	New York Telephone
1970	Aaron Irving P DDS	New York Telephone
	Res	New York Telephone
	Alper Nat	New York Telephone
	Appell Stanton	New York Telephone
	Aronow itz Herman	New York Telephone
	Atlas Gertrude Mrs	New York Telephone
	Babior Martin	New York Telephone
	Bekofsky Mollie Mrs	New York Telephone
	Braun Felix E	New York Telephone
	Brill Sol	New York Telephone
	Buzen Rose	New York Telephone
	Cooper Jos	New York Telephone

FINDINGS

Year	Uses	Source
1970	Davies H M Mrs	New York Telephone
	Ellenport Harry	New York Telephone
	Flaum Nathan H	New York Telephone
	Fratkin William	New York Telephone
	Gilbert Philip J	New York Telephone
	Goldberg David	New York Telephone
	Goldman Rose	New York Telephone
	Goldstein E J	New York Telephone
	Goldstein Maurice	New York Telephone
	Gordon Leo	New York Telephone
	Grashow Edward	New York Telephone
	Grashow Jas B	New York Telephone
	Grill Nathan	New York Telephone
	Gross L L	New York Telephone
	Gross Rose Mrs	New York Telephone
	Guy M	New York Telephone
	Harris Saml	New York Telephone
	Heller E H	New York Telephone
	Hobel A	New York Telephone
	Hoffer Arnold	New York Telephone
	Hollander Louis	New York Telephone
	Jones Roosevelt	New York Telephone
	Katz Bee Mrs	New York Telephone
	Katz Ida S	New York Telephone
	Katz Molly S	New York Telephone
	Kellman Issie	New York Telephone
	Kellman Saml	New York Telephone
	Komow Irene	New York Telephone
	Kurtin Edith A	New York Telephone
	Kurtz L	New York Telephone
	Latch Dan	New York Telephone
	Lescht Seymour	New York Telephone

FINDINGS

Year	Uses	Source
1970	Levine Alvin J	New York Telephone
	Levy Harry	New York Telephone
	Lieberman Rose	New York Telephone
	Lucey Jas A	New York Telephone
	Malament Albert	New York Telephone
	Mannix Jas	New York Telephone
	Megann John G	New York Telephone
	Nusbacher Stephen	New York Telephone
	OConnor Chas E	New York Telephone
	Pavey Mollie	New York Telephone
	Price Joanna	New York Telephone
	Rao Jas G Jr	New York Telephone
	Rappaport Jos	New York Telephone
	Rose Lester	New York Telephone
	Roseman Ellen K	New York Telephone
	Roseman Gertrude	New York Telephone
	Samuels H	New York Telephone
	Sandler Hannah Mrs	New York Telephone
	Scher Beatrice	New York Telephone
	Schleyer Theodore	New York Telephone
	Seldowitz Benj	New York Telephone
	Sellinger Harry	New York Telephone
	Senyk George	New York Telephone
	Serota Aaron	New York Telephone
	Serota Robt	New York Telephone
	Shanman Jay	New York Telephone
	Residence	New York Telephone
	Shapiro Jos lwyr	New York Telephone
	Simmons Herbert L	New York Telephone
	Small Max	New York Telephone
	Sommer Leo	New York Telephone
	Sosnoff Benj	New York Telephone

FINDINGS

Year	Uses	Source
1970	Sosnoff Miriam	New York Telephone
	Thoreau H D	New York Telephone
	Tirsch Jacob	New York Telephone
	Unger S	New York Telephone
	Weinstein M	New York Telephone
	Wolff David	New York Telephone
	Yampolsky Harry	New York Telephone
	Yormark Jos	New York Telephone
1965	Aaron Irving P DDS	New York Telephone
	Res	New York Telephone
	Alper Nat	New York Telephone
	Ames Ruth Mrs	New York Telephone
	Appell Stanton	New York Telephone
	Aronow itz Herman	New York Telephone
	Babior Martin	New York Telephone
	Beckerman L	New York Telephone
	Bekofsky Mollie Mrs	New York Telephone
	Bernhard Matthew E	New York Telephone
	Braun Felix E	New York Telephone
	Braverman Helen T Mrs	New York Telephone
	Buzen Rose	New York Telephone
	Cohen Bernard	New York Telephone
	Cohen David	New York Telephone
	Corigliano Rose	New York Telephone
	Davies H M Mrs	New York Telephone
	Duffy Robt	New York Telephone
	Flaum Nathan H	New York Telephone
	Fratkin Wm guitr instr	New York Telephone
	Fromberg Melvin	New York Telephone
	Goldfarb N A DDS	New York Telephone
	Goldman Mina	New York Telephone
	Goldman Rose	New York Telephone

FINDINGS

Year	Uses	Source
1965	Goldstein Maurice	New York Telephone
	Gordon Leo	New York Telephone
	Gould Bob	New York Telephone
	Gross A	New York Telephone
	Gross Rose Mrs	New York Telephone
	Guy M	New York Telephone
	Harris Saml	New York Telephone
	Hobel Anne	New York Telephone
	Hollander Louis	New York Telephone
	Kaplan Natalie	New York Telephone
	Kashdan Bernard	New York Telephone
	Katz Bee Mrs	New York Telephone
	Katz Ida S	New York Telephone
	Katz Molly S	New York Telephone
	Kellman Ira	New York Telephone
	Kellman Saml	New York Telephone
	Koeppel Robt R	New York Telephone
	Komow Irene	New York Telephone
	Kuflik Aaron Mrs	New York Telephone
	Kuflik Wm E MD	New York Telephone
	Kurtin Edith A	New York Telephone
	Kurtz	New York Telephone
	Laurie Jas A Mrs	New York Telephone
	Lescht Seymour	New York Telephone
	Levine Alvin J	New York Telephone
	Levy Harry	New York Telephone
	Lubarsky Harvey	New York Telephone
	Marks Wm	New York Telephone
	Megann John G	New York Telephone
	Mitlin Jos	New York Telephone
	Pavey Mollie	New York Telephone
	Price Joanna	New York Telephone

FINDINGS

Year	Uses	Source
1965	Rader Jill	New York Telephone
	Rader Pauline	New York Telephone
	Rao Jas G Jr	New York Telephone
	Rappaport Jos	New York Telephone
	Rose Chas J	New York Telephone
	Rose Rube	New York Telephone
	Roseman Ellen K	New York Telephone
	Roseman Gertrude	New York Telephone
	Ross Marion	New York Telephone
	Rothberg Ruth	New York Telephone
	Samuels H	New York Telephone
	Sandler Hannah Mrs	New York Telephone
	Scher Beatrice	New York Telephone
	Schiff Bernard	New York Telephone
	Serota Aaron	New York Telephone
	Serota Robt	New York Telephone
	Sesansky A B	New York Telephone
	Sfart Pavel	New York Telephone
	Residence	New York Telephone
	Shapiro Jos Iw yr	New York Telephone
	Silverman Crystal	New York Telephone
	Silverman Larry W	New York Telephone
	Silverman Sol	New York Telephone
	Simmons Herbert L	New York Telephone
	Small Max	New York Telephone
	Sommer Leo	New York Telephone
	Stadin Harry A	New York Telephone
	Sternberg Saml	New York Telephone
	Sternfeld G	New York Telephone
	Tepper Eva	New York Telephone
	Unger S	New York Telephone
	Wachman Seymour	New York Telephone

FINDINGS

Year	Uses	Source
1965	W Williams Moving & Storage Inc	New York Telephone
	Weinrauch David	New York Telephone
	Weinstein M	New York Telephone
	Wolff David	New York Telephone
	Yormark Jos	New York Telephone
1960	Ames Ruth Mrs	New York Telephone Company
	Appell Stanton	New York Telephone Company
	Aronowitz Herman	New York Telephone Company
	Atlas Louis	New York Telephone Company
	Babior Martin	New York Telephone Company
	Bernhard Matthew E	New York Telephone Company
	Braverman Helen T Mrs	New York Telephone Company
	Buzen Rose	New York Telephone Company
	Cohen David	New York Telephone Company
	Community Art Cntr Inc	New York Telephone Company
	Corigliano Rose	New York Telephone Company
	Dombroff Saml	New York Telephone Company
	Duffy Robt	New York Telephone Company
	Flaum Nathan H	New York Telephone Company
	Fratkin Wm	New York Telephone Company
	Fromberg Melvin	New York Telephone Company
	Goldfarb N A DDS	New York Telephone Company
	Goldman Mina	New York Telephone Company
	Goldman Rose	New York Telephone Company
	Goldstein Maurice	New York Telephone Company
	Gordon Leo	New York Telephone Company
	Gross A	New York Telephone Company
	Gross Rose Mrs	New York Telephone Company
	Grossman Simon	New York Telephone Company
	Guy M	New York Telephone Company
	Hamburg Edith L Mrs	New York Telephone Company
	Harris Saml	New York Telephone Company

FINDINGS

Year	*Uses*	*Source*
1960	Havsy Jos	New York Telephone Company
	Hobel Anne	New York Telephone Company
	Hoffman Henriette M	New York Telephone Company
	Hollander Louis	New York Telephone Company
	Kashdan Bernard	New York Telephone Company
	Katz Bee Mrs	New York Telephone Company
	Katz Molly S	New York Telephone Company
	Kellman Ira	New York Telephone Company
	Kellman Saml	New York Telephone Company
	Komow Irene	New York Telephone Company
	Kurtin Edith A	New York Telephone Company
	Kurtz L	New York Telephone Company
	Laurie Jas A Mrs	New York Telephone Company
	Levine Alvin J	New York Telephone Company
	Levinson Kale	New York Telephone Company
	Lubarsky Harvey	New York Telephone Company
	Marks Wm	New York Telephone Company
	Megann John G	New York Telephone Company
	Miller David	New York Telephone Company
	Mitlin Jos	New York Telephone Company
	Nemeroff Morris	New York Telephone Company
	Pavey Mollie	New York Telephone Company
	Polsky Robt I	New York Telephone Company
	Popkin A D	New York Telephone Company
	Rader Isidar	New York Telephone Company
	Rader Pauline	New York Telephone Company
	Rao Jos G Jr	New York Telephone Company
	Rappaport Jos	New York Telephone Company
	Rose Chas J	New York Telephone Company
	Rose Rube	New York Telephone Company
	Roseman Gertrude	New York Telephone Company
	Rosenberg Harry P	New York Telephone Company

FINDINGS

Year	*Uses*	*Source*
1960	Ross Marion	New York Telephone Company
	Rothberg Ruth	New York Telephone Company
	Samuels A J	New York Telephone Company
	Sandler Hannah Mrs	New York Telephone Company
	Sandor Gluck	New York Telephone Company
	Schaeffer Beatrice Mrs	New York Telephone Company
	Scher Beatrice	New York Telephone Company
	Schiff Bernard	New York Telephone Company
	Serota Robt	New York Telephone Company
	Sesaesky A B	New York Telephone Company
	Residence	New York Telephone Company
	Shapiro Jos lw yr	New York Telephone Company
	Silberman Paul	New York Telephone Company
	Silverman Larry W	New York Telephone Company
	Silverman Rose A	New York Telephone Company
	Silverman Sol	New York Telephone Company
	Simmons Herbert L	New York Telephone Company
	Small Max	New York Telephone Company
	Sommer Leo	New York Telephone Company
	Stadin Harry A	New York Telephone Company
	Starobin Clara	New York Telephone Company
	Sternberg Saml	New York Telephone Company
	Tirsch Jacob	New York Telephone Company
	Wachman Seymour	New York Telephone Company
	Weinrauch David	New York Telephone Company
	Weinstein M	New York Telephone Company
	Weisman David R	New York Telephone Company
	Wolff David	New York Telephone Company
	Yablon J Mrs	New York Telephone Company
	Yormark Jos	New York Telephone Company
	BLUM RUBIN	New York Telephone
	BREIER ALBERT J	New York Telephone

FINDINGS

Year	Uses	Source
1960	FEINBERG IRVING	New York Telephone
	JANPOLE MAX L	New York Telephone
	KAYE ALBERT E DDS	New York Telephone
	LEFKOWITZ D	New York Telephone
1949	Arm Ed W	New York Telephone Company
	Aronow itz Herman	New York Telephone Company
	Atlas Louis	New York Telephone Company
	Blum Rubin	New York Telephone Company
	Braverman Allen	New York Telephone Company
	Breier Albert J	New York Telephone Company
	Buzen Jacob	New York Telephone Company
	Cohen David	New York Telephone Company
	Cooper Isaac	New York Telephone Company
	Davis Bert A	New York Telephone Company
	Dombroff S	New York Telephone Company
	Dw orkin H	New York Telephone Company
	Fader Carl	New York Telephone Company
	Feinberg Irving	New York Telephone Company
	Finkelstein Irving	New York Telephone Company
	Flamberg H	New York Telephone Company
	Friedman Saul B	New York Telephone Company
	Goldfarb Louis	New York Telephone Company
	Goldfarb N A DDS	New York Telephone Company
	Goldman Isidore	New York Telephone Company
	Goldman Rose	New York Telephone Company
	Goldstein M	New York Telephone Company
	Goodman Drane	New York Telephone Company
	Gross Rose Mrs	New York Telephone Company
	Grossman Simon	New York Telephone Company
	Guy M	New York Telephone Company
	Harris Saml	New York Telephone Company
	Hass Morris	New York Telephone Company

FINDINGS

Year	Uses	Source
1949	Havsy Jos	New York Telephone Company
	Hirsch Lillian Mrs	New York Telephone Company
	Hobel Anne	New York Telephone Company
	Hoffman Henriette M	New York Telephone Company
	Janpole Max L	New York Telephone Company
	Kaplan Jack	New York Telephone Company
	Karp Murray C	New York Telephone Company
	Katz Annie Mrs	New York Telephone Company
	Katz David DDS	New York Telephone Company
	Kaye Albert E DDS	New York Telephone Company
	Kaye Albert E DDS	New York Telephone Company
	Kimler Geo J	New York Telephone Company
	Komow Irene	New York Telephone Company
	Krams J	New York Telephone Company
	Kreisberg Maurice J	New York Telephone Company
	Kurtin Morris M	New York Telephone Company
	Kurtz L	New York Telephone Company
	Laski Marks	New York Telephone Company
	Lefkowitz D	New York Telephone Company
	Levinson Martin K	New York Telephone Company
	Lubarsky Harvey	New York Telephone Company
	Miller David	New York Telephone Company
	Nemeroff Morris	New York Telephone Company
	Odell Geo M	New York Telephone Company
	Pavey Mollie	New York Telephone Company
	Popkin Anna D	New York Telephone Company
	Posner Wm	New York Telephone Company
	Rader Pauline	New York Telephone Company
	Radzwiller B Mrs	New York Telephone Company
	Rappaport Jos	New York Telephone Company
	Residence	New York Telephone Company
	Robin Benj B	New York Telephone Company

FINDINGS

Year	Uses	Source
1949	Robinson Anne	New York Telephone Company
	Robinson Wm I	New York Telephone Company
	Rose Benj	New York Telephone Company
	Rose Rube	New York Telephone Company
	Rosswig L M	New York Telephone Company
	Rosten Norman	New York Telephone Company
	Rpsten Sidney	New York Telephone Company
	Salomon Gilbert H	New York Telephone Company
	Sandler J M	New York Telephone Company
	Sandor Gluck dance studios	New York Telephone Company
	Saresky Saml	New York Telephone Company
	Schaeffer Beatrice Mrs	New York Telephone Company
	Schiff Bernard	New York Telephone Company
	Schwarz Betty Mrs	New York Telephone Company
	Sesansky A B	New York Telephone Company
	Sesansky Rose Mrs	New York Telephone Company
	Shacter Taube Mrs	New York Telephone Company
	Residence	New York Telephone Company
	Shapiro Albert lwyr	New York Telephone Company
	Residence	New York Telephone Company
	Shapiro Jos lwyr	New York Telephone Company
	Silverman Sol	New York Telephone Company
	Simmons Herbert L	New York Telephone Company
	Slater Z	New York Telephone Company
	Starobin Morris	New York Telephone Company
	Stern Edw	New York Telephone Company
	Sternberg Saml	New York Telephone Company
	Sternfeld C Mrs	New York Telephone Company
	Suda John	New York Telephone Company
	Tepper Bennett J	New York Telephone Company
1945	Aronowitz Herman	New York Telephone
	Aronson Nathan	New York Telephone

FINDINGS

Year	Uses	Source
1945	Atlas Louis	New York Telephone
	Cooper Isaac	New York Telephone
	Dombroff S	New York Telephone
	Dworkin H	New York Telephone
	Epstein Miriam	New York Telephone
	Finkelstein Irving	New York Telephone
	Friedman Beatrice	New York Telephone
	Goldfarb Louis	New York Telephone
	Goldfarb N A Dr	New York Telephone
	Goldman Isidore	New York Telephone
	Goldman Rose	New York Telephone
	Goldstein M	New York Telephone
	Goodman Diane	New York Telephone
	Gross Maurice W	New York Telephone
	Grossman Simon	New York Telephone
	Guy M	New York Telephone
	Havsy Jos	New York Telephone
	Hobel Anne	New York Telephone
	Hoffman Henriette M	New York Telephone
	Hollander Louis	New York Telephone
	Kaplan Jack	New York Telephone
	Karp Murray C	New York Telephone
	Katz Annie Mrs	New York Telephone
	Katz David DDS	New York Telephone
	Kellman Saml	New York Telephone
	Kenin Kate	New York Telephone
	Komow Irene	New York Telephone
	Krams J	New York Telephone
	Kreisberg Dorothy Miss	New York Telephone
	Kurtin Morris M	New York Telephone
	Kurtz L	New York Telephone
	Lefkowitz Jos	New York Telephone

FINDINGS

Year	Uses	Source
1945	Lesser Lawrence	New York Telephone
	Mogelesky Walter	New York Telephone
	Nemeroff Morris	New York Telephone
	Odell Geo M	New York Telephone
	Popkin Edw	New York Telephone
	Radzwiller J	New York Telephone
	Rappaport Jos	New York Telephone
	Robinson Wm I	New York Telephone
	Rose Rube	New York Telephone
	Rothberg Paul	New York Telephone
	Salomon Gilbert H	New York Telephone
	Sandler J M	New York Telephone
	Sandor Gluck	New York Telephone
	Schaeffer Beatrie Mrs	New York Telephone
	Schiff Bernard	New York Telephone
	Schwarz Betty Mrs	New York Telephone
	Sesansky A B	New York Telephone
	Shacter Taube Mrs	New York Telephone
	Residence	New York Telephone
	Shapiro Albert lwyr	New York Telephone
	Shapiro Jos lwyr	New York Telephone
	Residence	New York Telephone
	Silverman P M	New York Telephone
	Silverman Sol	New York Telephone
	Simmons Herbert L	New York Telephone
	Spritzer Helene	New York Telephone
	Starobin Morris	New York Telephone
	Steinberg Anne R	New York Telephone
	Steinberg Leon	New York Telephone
	Stern Edw	New York Telephone
	Stern Mildred	New York Telephone
	Sternberg Saml	New York Telephone

FINDINGS

Year	Uses	Source
1945	Weinrauch David	New York Telephone
	Wolff David	New York Telephone
	Woolf I J	New York Telephone
	Yablon J Mrs	New York Telephone
	Zinn Saml	New York Telephone
1940	Albert Murray M MD	New York Telephone
	Arm Edw	New York Telephone
	Aronow itz Herman	New York Telephone
	Barb Estelle B	New York Telephone
	Berkow itz Chas B	New York Telephone
	Blum J dntst	New York Telephone
	Res	New York Telephone
	Boorstein Nathan	New York Telephone
	Bronow itz Chas	New York Telephone
	Buzen Jacob	New York Telephone
	Cohen Rebecca I	New York Telephone
	Cutler Irving	New York Telephone
	Dombroff S	New York Telephone
	Dubin Jos G	New York Telephone
	Dumay R Miss	New York Telephone
	Dw orkin H	New York Telephone
	Ehrlich Jack	New York Telephone
	Fassy S	New York Telephone
	Garmize Maurice	New York Telephone
	Goldfarb Louis	New York Telephone
	Goldman Isidore	New York Telephone
	Goldstein M	New York Telephone
	Gross Maurice W	New York Telephone
	Grossman Israel	New York Telephone
	Grossman S	New York Telephone
	Gutmaker Harold	New York Telephone
	Harris Saml	New York Telephone

FINDINGS

Year	Uses	Source
1940	Isaacs Sidney M	New York Telephone
	Jarnevi Verna	New York Telephone
	Katz David DDS	New York Telephone
	Kellman Saml	New York Telephone
	Kenin Abel MD	New York Telephone
	Klahrs Miss School for Little Folk	New York Telephone
	Komow Irene	New York Telephone
	Kurtin Morris M	New York Telephone
	Kurtz L	New York Telephone
	Margolin Mack	New York Telephone
	Meyer Richd A	New York Telephone
	Moses Chas	New York Telephone
	Odell Geo M	New York Telephone
	Popkin Edw	New York Telephone
	Ragozin Harry	New York Telephone
	Robiczek Law rence M	New York Telephone
	Robinson Wm I	New York Telephone
	Rogozin Harry	New York Telephone
	Sandler J M	New York Telephone
	Schiff Bernard	New York Telephone
	Schw ab I K	New York Telephone
	Sesansky Rose Mrs	New York Telephone
	Shacter Jos	New York Telephone
	Shapiro Albert lw yr	New York Telephone
	Res	New York Telephone
	Siegel Geo	New York Telephone
	Simmons Herbert L	New York Telephone
	Simon Martin	New York Telephone
	Spritzer Helene	New York Telephone
	Starobin Morris	New York Telephone
	Steinberg Anne R	New York Telephone
	Steinberg Leon	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1940	Strammer Lillian	New York Telephone
	Waiser Irma Mrs	New York Telephone
	Wolff David	New York Telephone
	Woolf I J	New York Telephone
	Y & Z Gasoline Svce Stas Inc	New York Telephone
	Yablon J Mrs	New York Telephone
	Zinn Saml	New York Telephone
	Zuck A Mrs	New York Telephone
	Zucker Harry atty	New York Telephone
	Res	New York Telephone

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
1035 WASHINGTON AVE	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1035 Washington Avenue	2017, 2014, 2009, 2004, 1999, 1994, 1934, 1928
124 Montgomery Street	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1949, 1945, 1940, 1934, 1928
945 Franklin Avenue	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970
959 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1945, 1940
960 FRAKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
960 FRANKLIN AVE	2017, 2014, 2009, 2004, 2000, 1999, 1994, 1985, 1980
960 FRANKLIN AVE	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
963 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
964 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1980, 1976, 1949, 1945, 1940, 1934, 1928
965 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965
968A FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
969 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
971 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
973 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1960, 1934, 1928
975 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1940, 1928
975 FRANKLIN AVE	2017, 2014, 2009, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
975 WASHINGTON AVE	2005, 2000, 1999, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
975 Washington Avenue	2017, 2014, 2009, 2004, 1999, 1994, 1934
979 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965

FINDINGS

Address Researched	Address Not Identified in Research Source
980 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940
983 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945
985 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1945, 1940, 1934, 1928
985 FRANKLIN AVE	2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
991 FRANKIIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
991 FRANKLIN AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1945

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
972 Franklin Avenue	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934

APPENDIX 15.4

REGULATORY RECORDS DOCUMENTATION

962 & 972
972 Franklin Avenue
Brooklyn, NY 11225

Inquiry Number: 7231046.2s
January 23, 2023

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	956
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

972 FRANKLIN AVENUE
BROOKLYN, NY 11225

COORDINATES

Latitude (North):	40.6651120 - 40ˆ 39' 54.40''
Longitude (West):	73.9604620 - 73ˆ 57' 37.66''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	587870.8
UTM Y (Meters):	4501890.5
Elevation:	90 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	WASHINGTON REALTY LL	1015 WASHINGTON AVEN	NY AST	Lower	60, 0.011, SW
A2	CON EDISON - SERVICE	995 WASHINGTON AVE	NY MANIFEST	Higher	65, 0.012, WNW
B3	975 WASHINGTON AVENU	975 WASHINGTON AVENU	NY AST	Higher	99, 0.019, NW
B4	CON ED - MH 47218	F/O 975 WASHINGTON A	RCRA NonGen / NLR, NY MANIFEST	Higher	99, 0.019, NW
B5	975 WASHINGTON AVE	975 WASHINGTON AVE	NY Spills	Higher	99, 0.019, NW
A6	BROOKLYN BOTANIC GAR	1000 WASHINGTON AVEN	NY UST, NY AST	Higher	138, 0.026, West
A7	BROOKLYN BOTANIC GAR	1000 WASHINGTON AVE	RCRA NonGen / NLR, FINDS, ECHO, NJ MANIFEST, NY...	Higher	138, 0.026, West
C8	CON EDISON	1003 FRANKLIN AVE	NY MANIFEST	Lower	139, 0.026, SSE
C9	CON EDISON MANHOLE:	1003 FRANKLIN AVE	RCRA NonGen / NLR	Lower	139, 0.026, SSE
A10	BROOKLYN BOTANICAL G	1008 WASHINGTON AVE	NY Spills	Higher	158, 0.030, West
A11	SOIL	1035 WASHINGTON AVE	NY Spills, NY LEAD	Lower	163, 0.031, SSW
A12	1035 WASHINGTON AVEN	1035 WASHINGTON AVEN	NY AST	Lower	163, 0.031, SSW
B13	955 WASHINGTON AVE	955 WASHINGTON AVE	NY Spills	Higher	189, 0.036, NW
C14	MANHOLE 4709	FRANKLIN AVE NEAR SU	NY Spills	Lower	199, 0.038, South
C15	CON ED - TM 356	SULLIVAN PL & FRANKL	RCRA NonGen / NLR, NY MANIFEST	Lower	200, 0.038, South
C16	CON EDISON	SULLIVAN PL & FRANKL	NJ MANIFEST	Lower	200, 0.038, South
C17	CON EDISON	SULLIVAN PL & FRANKL	RCRA NonGen / NLR, FINDS, ECHO	Lower	200, 0.038, South
C18	FRANKLIN ST & SULLIV	FRANKLIN ST & SULLIV	NY Spills	Lower	200, 0.038, South
C19	CON ED	SULLIVAN PL & FRANKL	NY MANIFEST	Lower	200, 0.038, South
B20	961 REALTY LLC	961 WASHINGTON AVENU	NY UST	Higher	204, 0.039, NNW
C21	CON EDISON	998 FRANKLIN AVE	NY MANIFEST	Lower	246, 0.047, South
C22	VICTOR LOGAN COLLISI	62 SULLIVAN PL	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	274, 0.052, SSE
D23	CON EDISON SERVICE B	48 MCKEEVER PL SB 28	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	280, 0.053, East
D24	I.S. 320 - BROOKLYN	46 MCKEEVER PLACE	NY AST	Lower	280, 0.053, East
D25	NYC BD OF ED - IS 32	46 MCKEEVER PL	RCRA-VSQG, NY Spills, NY LEAD, NY MANIFEST	Lower	280, 0.053, East
C26	MAZE AUTO REPAIR INC	66 SULLIVAN PLACE	NY AST	Lower	283, 0.054, SE
C27	CON ED	1028 FRANKLIN AVE	NY MANIFEST	Lower	289, 0.055, South
C28	CON EDISON	1028 FRANKLIN AVE	NJ MANIFEST	Lower	289, 0.055, South
C29	CON EDISON	1028 FRANKLIN AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	289, 0.055, South
E30	CON EDISON	SULLIVAN PL & WASHIN	RCRA NonGen / NLR, FINDS, ECHO	Lower	289, 0.055, SSW
E31	MANHOLE # M4785	WASHINGTON AVE AND S	NY Spills	Lower	289, 0.055, SSW
E32	CON EDISON	SULLIVAN PL & WASHIN	RCRA NonGen / NLR	Lower	289, 0.055, SSW
E33	CON EDISON	WASHINGTON AVE & SUL	NJ MANIFEST	Lower	289, 0.055, SSW
E34	CON ED	SULLIVAN PL & WASHIN	NY MANIFEST	Lower	289, 0.055, SSW
E35	CON EDISON	SULLIVAN PL & WASHIN	NJ MANIFEST	Lower	289, 0.055, SSW
E36	SPILL NUMBER 9812071	SULLIVAN PL & WASHIN	NY Spills	Lower	289, 0.055, SSW
E37	CON ED	WASHINGTON AVE & SUL	NY MANIFEST	Lower	289, 0.055, SSW
D38	CON EDISON SERVICE B	47 MCKEEVER PL SB 28	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	319, 0.060, East
B39	941 WASHINGTON AVENU	941 WASHINGTON AVENU	NY AST	Higher	321, 0.061, NNW

MAPPED SITES SUMMARY

Target Property Address:
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
B40	CON EDISON	104 MONTGOMERY ST	NY MANIFEST	Higher	324, 0.061, NNW
F41	GARDEN CLEANERS	96 MONTGOMERY STREET	NY DRYCLEANERS	Higher	344, 0.065, NNW
F42	GARDEN CLEANING	96 MONTGOMERY ST	EDR Hist Cleaner	Higher	344, 0.065, NNW
F43	GARDEN CLEANERS	96 MONTGOMERY ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	344, 0.065, NNW
F44	MANHOLE 1135	MONTGOMERY ST/WASHIN	NY Spills	Higher	365, 0.069, NNW
45	GOLOMBECKS METHYL BR	MONTGOMERY AV & FRAN	NY Spills	Higher	377, 0.071, NNE
F46	LOT 50,TAXBLOCK 1190	135 MONTGOMERY STREE	NY E DESIGNATION	Higher	439, 0.083, North
F47	EXCAVATION SITE	109 MONTGOMERY ST	NY Spills	Higher	457, 0.087, NNW
F48	109 MONTGOMERY OWNER	109 MONTGOMERY STREE	NY UST	Higher	457, 0.087, NNW
F49	CON EDISON - MANHOLE	WASHINGTON AVE AND M	RCRA NonGen / NLR, NY MANIFEST	Higher	467, 0.088, NNW
F50	MANHOLE #4787	WASHINGTON AVE AND M	NY Spills	Higher	467, 0.088, NNW
F51	NEW YORK TELEPHONE	MONTGOMERY & WASHING	RCRA NonGen / NLR, NY MANIFEST	Higher	467, 0.088, NNW
G52	CON EDISON MANHOLE:	73 EMPIRE BLVD	NY BROWNFIELDS, NY Spills, RCRA NonGen / NLR,...	Lower	490, 0.093, SSE
H53	MANHOLE # 23430	EMPIRE BL & FRANKLIN	NY Spills	Lower	498, 0.094, South
E54	GASETERIA FRANKLIN	43 EMPIRE BOULEVARD	NY UST	Lower	509, 0.096, SSW
E55	GASETERIA OIL CORP	43 EMPIRE BLVD	NY LTANKS	Lower	509, 0.096, SSW
H56	CON EDISON MANHOLE:	EMPIRE BLVD & WASHIN	RCRA NonGen / NLR, NY MANIFEST	Lower	528, 0.100, SSW
H57	CON EDISON	WASHINGTON AVE & EMP	RCRA NonGen / NLR, NY MANIFEST	Lower	528, 0.100, SSW
H58	STREET	EMPIRE BLVD/ WASHING	NY Spills	Lower	532, 0.101, SSW
H59	MANHOLE # 4761	EMPIRE BLVD./E WASHI	NY Spills	Lower	532, 0.101, SSW
H60	MANHOLE 58808	WASHINGTON AVE/EMPIR	NY Spills	Lower	532, 0.101, SSW
H61	CON EDISON	1035 FRANKLIN AVE	NY MANIFEST	Lower	551, 0.104, South
G62	CON EDISON	99 EMPIRE BLVD	NJ MANIFEST	Lower	556, 0.105, SE
G63	CON EDISON	99 EMPIRE BLVD	RCRA NonGen / NLR	Lower	556, 0.105, SE
G64	CON EDISON	99 EMPIRE BLVD	NY MANIFEST	Lower	556, 0.105, SE
F65	921 WASHINGTON AVE.	921 WASHINGTON AVE.	NY AST	Higher	557, 0.105, NNW
H66	BROOKLYN FIRE COMM C	35 EMPIRE BOULEVARD	NY UST	Lower	562, 0.106, SSW
H67	BROOKLYN FIRE COMM C	35 EMPIRE BOULEVARD	NY AST	Lower	562, 0.106, SSW
H68	MID-COUNTY MOTORS	44 EMPIRE BLVD	RCRA NonGen / NLR, FINDS, ECHO	Lower	579, 0.110, SSW
G69	CON EDISON MANHOLE:	103 EMPIRE BLVD	NJ MANIFEST	Lower	597, 0.113, SE
G70	CON EDISON MANHOLE:	103 EMPIRE BLVD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	597, 0.113, SE
G71	FALCON AUTOMOTIVE IN	100 EMPIRE BLVD	EDR Hist Auto	Lower	651, 0.123, SE
I72	SEA CREST LINEN/CENT	46 CROWN STREET	NY DRYCLEANERS	Higher	668, 0.127, NNE
I73	54 CROWN STREET	46 CROWN STREET	NY VCP	Higher	668, 0.127, NNE
I74	CENTRAL LAUNDRY CORP	46 CROWN STREET	NY LTANKS, NY CBS, NY AST, NY Spills	Higher	668, 0.127, NNE
I75	SEACREST LINEN SUPPL	46 CROWN STREET	NY UST	Higher	668, 0.127, NNE
I76	CENTRAL LAUNDRY CORP	46 CROWN ST.	NY CBS AST	Higher	668, 0.127, NNE
G77	104-110 EMPIRE BLVD	104-110 EMPIRE BLVD	NY AST	Lower	674, 0.128, SE
G78	SAFEGUARD SELF-STORA	115 EMPIRE BLVD.	NY UST	Lower	698, 0.132, SE

MAPPED SITES SUMMARY

Target Property Address:
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G79	EMPIRE VALLEY LLC	110 EMPIRE BOULEVARD	NY AST	Lower	705, 0.134, SE
J80	915 WASHINGTON AVE	915 WASHINGTON AVENU	NY UST	Higher	705, 0.134, NNW
81	CON EDISON	35 STERLING ST	NY MANIFEST	Lower	707, 0.134, SSE
I82	CON ED - VS 5973	CROWN ST & FRANKLIN	RCRA NonGen / NLR, NY MANIFEST	Higher	708, 0.134, NNE
H83	CON EDISON - MANHOLE	WASHINGTON AVE & FRA	RCRA NonGen / NLR, NY MANIFEST	Lower	725, 0.137, South
K84	TANK TEST	49 CROWN ST	NY LTANKS	Higher	727, 0.138, North
K85	TIVOLI TOWERS & TIVO	49 CROWN STREET	NY UST	Higher	727, 0.138, North
L86	CON EDISON	475 FLATBUSH AVE SB2	NJ MANIFEST	Lower	738, 0.140, SSW
L87	CON EDISON	475 FLATBUSH AVE SB2	RCRA NonGen / NLR	Lower	738, 0.140, SSW
L88	CON EDISON	475 FLATBUSH AVE SB2	RCRA NonGen / NLR, FINDS, ECHO	Lower	738, 0.140, SSW
L89	CON EDISON	475 FLATBUSH AVE SB2	NY MANIFEST	Lower	738, 0.140, SSW
L90	CON EDISON	475 FLATBUSH AVE SB2	NY MANIFEST	Lower	738, 0.140, SSW
L91	CON EDISON	475 FLATBUSH AVE SB2	NJ MANIFEST	Lower	738, 0.140, SSW
M92	LEFFERTS HOMESTEAD	440 FLATBUSH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	739, 0.140, SW
J93	35 CROWN STREET HDFC	35 CROWN STREET	NY AST	Higher	742, 0.141, North
J94	12 CROWN STREET	12 CROWN STREET	NY AST	Higher	744, 0.141, NNW
N95	EBBETS FIELD APARTME	1720 BEDFORD AVENUE	NY UST, NY AST	Lower	748, 0.142, East
L96	CON EDISON - MANHOLE	2-26 EMPIRE BLVD	NY MANIFEST	Lower	791, 0.150, SW
O97	CON EDISON	FLATBUSH AVE & EMPIR	NY MANIFEST	Lower	791, 0.150, SW
O98	CON EDISON - MANHOLE	NEC FLATBUSH AVE / O	RCRA-LQG, NY MANIFEST	Lower	791, 0.150, SW
O99	PROSPECT PARK - PARA	FLATBUSH AND OCEAN A	NY LTANKS	Lower	791, 0.150, SW
O100	CON EDISON - MANHOLE	NEC FLATBUSHA VE / E	RCRA-LQG	Lower	791, 0.150, SW
O101	CON EDISON - MANHOLE	OCEAN AVE & FLATBUSH	NJ MANIFEST	Lower	791, 0.150, SW
J102	15 CROWN STREET LLC	15 CROWN STREET	NY AST	Higher	793, 0.150, NNW
L103	CONSOLIDATED EDISON	SE STERLING PL & WAS	RCRA NonGen / NLR	Lower	799, 0.151, South
L104	CON ED-MH4514	WASHINGTON AVE & STE	NY MANIFEST	Lower	799, 0.151, South
L105	CON EDISON - MANHOLE	WASHINGTON AVE AND S	RCRA NonGen / NLR, NY MANIFEST	Lower	799, 0.151, South
L106	WAREHOUSE/PHAT ALBER	495 FLATBUSH AVE	NY LTANKS	Lower	806, 0.153, SSW
M107	TTF PROSPECT PARK ZO	450 FLATBUSH AVE	NY LTANKS	Higher	815, 0.154, SW
J108	CON EDISON MANHOLE:	WASHINGTON AVE & CRO	RCRA NonGen / NLR, NY MANIFEST	Higher	828, 0.157, NNW
J109	CONSOLIDATED EDISON	WASHINGTON & CROWN S	NY MANIFEST	Higher	830, 0.157, NNW
P110	FIRESTONE COMPLETE A	1730 BEDFORD AVENUE	NY AST	Lower	832, 0.158, ESE
L111	NYCT - FLATBUSH EMPI	479 FLATBUSH AVE	RCRA-LQG	Lower	834, 0.158, SSW
L112	NYCT - FLATBUSH EMPI	479 FLATBUSH AVE	NY MANIFEST	Lower	834, 0.158, SSW
L113	PHAT ALBERT WAREHOUS	495 FLATBUSH AVE	NY UST	Lower	865, 0.164, SSW
N114	CONGRESS CLEANERS	1685 BEDFORD AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	869, 0.165, East
P115	SHELL OIL CO	136 EMPIRE BLVD	RCRA NonGen / NLR, NY MANIFEST	Lower	871, 0.165, SE
P116	MOTIVA ENTERPRISES,	136 EMPIRE BOULEVARD	NY UST	Lower	871, 0.165, SE
P117	SHELL	136 EMPIRE BLVD	NY LTANKS, NY Spills	Lower	871, 0.165, SE

MAPPED SITES SUMMARY

Target Property Address:
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P118	MOTIVA ENTERPRISES,	136 EMPIRE BOULEVARD	NY AST	Lower	871, 0.165, SE
L119	PROSPECT PARK SUBWAY	478 FLATBUSH AVENUE	NY UST	Lower	889, 0.168, SSW
L120	CON EDISON SERVICE B	480 FLATBUSH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	890, 0.169, SSW
L121	CON ED	FO 480 FLATBUSH AVE	NY MANIFEST	Lower	890, 0.169, SSW
P122	KFC	1715 BEDFORD AVENUE	NY UST	Lower	891, 0.169, ESE
P123	K F C NATIONAL MANAG	1715 BEDFORD AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	891, 0.169, ESE
Q124	CON EDISON	MONTGOMERY ST & BEDF	RCRA NonGen / NLR	Higher	893, 0.169, ENE
Q125	CON EDISON	MONTGOMERY ST & BEDF	NJ MANIFEST	Higher	893, 0.169, ENE
Q126	CON EDISON	MONTGOMERY ST & BEDF	NY MANIFEST	Higher	893, 0.169, ENE
N127	RITE AID #03978	1679 BEDFORD AVE	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	896, 0.170, East
J128	901 WASHINGTON AVE	901 WASHINGTON AVENU	NY AST	Higher	903, 0.171, NNW
P129	BEDOSULL AUTO REPAIR	1727 BEDFORD AVE	NY UST	Lower	917, 0.174, ESE
P130	BRIDGESTONE FIRESTON	1750 BEDFORD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	925, 0.175, SE
R131	NYC SANITATION	115 CROWN ST - BK-E-	RCRA NonGen / NLR, ICIS, FINDS, ECHO	Higher	928, 0.176, NE
R132	BROOKLYN EAST 09 DOS	115 CROWN STREET	NY LTANKS, NY Spills	Higher	928, 0.176, NE
R133	MEDGAR EVERS COLLEGE	115 CROWN STREET	NY UST, NY AST	Higher	928, 0.176, NE
134	PROSPECT PARK ZOO	450 FLATBUSH AVENUE	NY UST	Lower	936, 0.177, West
P135	CON-ED - MH4802	BEDFORD AVE AND EMPI	RCRA NonGen / NLR	Lower	939, 0.178, ESE
Q136	MONTGOMERY REALTY, L	236 MONTGOMERY STREE	NY AST	Higher	958, 0.181, East
Q137	MEDGAR EVERS COLLEGE	1650 BEDFORD AVENUE	NY LTANKS, NY UST	Higher	962, 0.182, ENE
S138	CON EDISON SERVICE B	960 CARROLL ST	RCRA NonGen / NLR, NY MANIFEST	Higher	992, 0.188, NNE
S139	NYCTA - CHEMICAL LAB	960 CARROLL ST	NY LTANKS, RCRA NonGen / NLR, FINDS, ECHO	Higher	992, 0.188, NNE
S140	TRANSIT DISTRICT 32	960 CARROLL STREET	NY AST	Higher	992, 0.188, NNE
S141	TRANSIT DISTRICT 32	960 CARROLL STREET	NY UST	Higher	992, 0.188, NNE
T142	25 LEFFERTS, LLC	25 LEFFERTS AVENUE	NY AST	Lower	998, 0.189, South
P143	EBBETTS FIELD EXXON	155 EMPIRE BLVD	RCRA-VSQG, ICIS, US AIRS, NY MANIFEST	Lower	1001, 0.190, ESE
P144	EBBET'S FIELD (CLOSE	155 EMPIRE BLVD	NY UST	Lower	1001, 0.190, ESE
U145	934 CARROLL STREET	934 CARROLL STREET	NY AST	Higher	1022, 0.194, North
U146	932 CARROLL STREET	932 CARROLL STREET	NY AST	Higher	1024, 0.194, North
V147	MEDGAR EVERS COLLEGE	1638 BEDFORD AVENUE	NY AST	Higher	1029, 0.195, ENE
V148	MEDGAR EVERS COLLEGE	1638 BEDFORD AVE	RCRA-SQG, NY MANIFEST	Higher	1029, 0.195, ENE
V149	MEDGAR EVERS COLLEGE	1638 BEDFORD AVENUE	NY UST	Higher	1029, 0.195, ENE
Q150	CON EDISON	1653 BEDFORD AV	NY MANIFEST	Higher	1035, 0.196, ENE
Q151	CON EDISON SERVICE B	1653 BEDFORD AVE	RCRA NonGen / NLR	Higher	1035, 0.196, ENE
S152	CON EDISON SERVICE B	FRANKLIN AVE & CARRO	RCRA NonGen / NLR, NY MANIFEST	Higher	1037, 0.196, NNE
Q153	250 REALTY ASSOCIATE	250 MONTGOMERY STREE	NY AST	Higher	1041, 0.197, East
W154	CON EDISON SB73433	15 OCEAN AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1052, 0.199, SSW
W155	CON EDISON - SERVICE	15 OCEAN AVE	RCRA-LQG	Lower	1052, 0.199, SSW
W156	CON EDISON - SERVICE	15 OCEAN AVE	NY MANIFEST	Lower	1052, 0.199, SSW

MAPPED SITES SUMMARY

Target Property Address:
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
W157	P.T. STATES INC.	15 OCEAN AVENUE	NY UST	Lower	1052, 0.199, SSW
W158	CON EDISON - MANHOLE	15 OCEAN AVE	RCRA-LQG, NY MANIFEST	Lower	1052, 0.199, SSW
Q159	1645 BEDFORD CLEANER	1645 BEDFORD AVE	NY DRYCLEANERS	Higher	1055, 0.200, ENE
Q160	1645 BEDFORD INC	1645 BEDFORD AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1055, 0.200, ENE
U161	916 CARROLL STREET	916 CARROLL STREET	NY AST	Higher	1067, 0.202, North
V162	CON EDISON - CROWN &	CROWN & BEDFORD ST	PA MANIFEST	Higher	1074, 0.203, ENE
V163	CON EDISON	BEDFORD AVE & CROWN	RCRA NonGen / NLR, NY MANIFEST	Higher	1074, 0.203, ENE
V164	CON EDISON SERVICE B	CROWN ST & BEDFORD A	RCRA NonGen / NLR, NY MANIFEST	Higher	1074, 0.203, ENE
V165	CON EDISON VAULT SUB	CROWN ST & BEDFORD A	RCRA NonGen / NLR, NY MANIFEST	Higher	1074, 0.203, ENE
V166	MEDGAR EVERS COLLEGE	1637 BEDFORD AVE.	NY AST	Higher	1075, 0.204, ENE
S167	CITY OF N.Y. DEPT. O	888 FRANKLIN AVE	NY AST	Higher	1083, 0.205, NNE
S168	951 CARROLL ST	951 CARROLL ST	NY AST	Higher	1106, 0.209, NNE
169	1767 BEDFORD AVE	1767 BEDFORD AVE	NY AST	Lower	1109, 0.210, SE
T170	50 LEFFERTS TENANTS	50 LEFFERTS AVENUE	NY AST	Lower	1114, 0.211, South
T171	50 REALTY CO	50 LEFFERTS AVENUE	NY AST	Lower	1114, 0.211, South
S172	959 CARROLL ASSOCIAT	959 CARROLL STREET	NY AST	Higher	1119, 0.212, NNE
X173	CON EDISON	FLATBUSH AVE & LEFFE	NJ MANIFEST	Lower	1120, 0.212, SSW
X174	CON EDISON	FLATBUSH AVE & LEFFE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1120, 0.212, SSW
X175	CON EDISON	FLATBUSH AVE & LEFFE	NY MANIFEST	Lower	1120, 0.212, SSW
R176	1030 CARROLL STREET	1030 CARROLL STREET	NY AST	Higher	1134, 0.215, NE
W177	J & L PROPERTIES	39 OCEAN AVENUE	NY AST	Lower	1135, 0.215, SSW
U178	931 CARROLL STREET	931 CARROLL STREET	NY VCP	Higher	1137, 0.215, NNE
U179	SEACREST LINEN	931 CARROLL ST	NY LTANKS, NY E DESIGNATION	Higher	1137, 0.215, NNE
U180	931 CARROLL STREET	931 CARROLL STREET	NY AST	Higher	1137, 0.215, NNE
U181	931 CARROLL STREET	931 CARROLL STREET	NY UST	Higher	1137, 0.215, NNE
S182	TAG REALTY INC.	969 CARROLL STREET	NY AST	Higher	1140, 0.216, NNE
X183	CON EDISON	514 FLATBUSH AVE	NY MANIFEST	Lower	1141, 0.216, SSW
X184	CON EDISON	514 FLATBUSH AVE	NJ MANIFEST	Lower	1141, 0.216, SSW
X185	CON EDISON	514 FLATBUSH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1141, 0.216, SSW
Y186	881 WASHINGTON AVE	881 WASHINGTON AVENU	NY AST	Higher	1146, 0.217, NNW
V187	MEDGAR EVERS COLLEGE	123 CROWN STREET	NY UST	Higher	1147, 0.217, ENE
V188	VACANT LOT	123 CROWN ST	NY LTANKS	Higher	1147, 0.217, ENE
X189	CON EDISON	504 FLATBUSH AVE	PA MANIFEST	Lower	1148, 0.217, SSW
T190	CON EDISON - SERVICE	1120 WASHINGTON AVE	NY MANIFEST	Lower	1154, 0.219, South
T191	CON EDISON SERVICE B	1120 WASHINGTON AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1154, 0.219, South
Z192	CON EDISON	989 CARROLL ST	NY MANIFEST	Higher	1158, 0.219, NE
T193	CON EDISON SERVICE B	1123 WASHINGTON AVE	RCRA NonGen / NLR	Lower	1159, 0.220, South
T194	CON EDISON	1123 WASHINGTON AVE	NY MANIFEST	Lower	1159, 0.220, South
Y195	CLARA BARTON HIGH SC	925 CARROLL ST	NY LTANKS	Higher	1176, 0.223, North

MAPPED SITES SUMMARY

Target Property Address:
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Z196	991 CARROLL STREET	991 CARROLL STREET	NY UST, NY AST	Higher	1177, 0.223, NE
W197	45 OCEAN LLC	45 OCEAN AVENUE	NY AST	Lower	1182, 0.224, SSW
S198	883 FRANKLIN LLC, C/	883 FRANKLIN AVENUE	NY AST	Higher	1188, 0.225, NNE
X199	BP SERVICE STATION #	513 FLATBUSH AVENUE	NY UST	Lower	1199, 0.227, South
X200	BP PRODUCTS NORTH AM	513 FLATBUSH AVE	NJ MANIFEST	Lower	1199, 0.227, South
X201	BP PRODUCTS NORTH AM	513 FLATBUSH AVE	RCRA-SQG, NY MANIFEST	Lower	1199, 0.227, South
X202	CON EDISON	510 FLAT BUSH AV	NY MANIFEST	Lower	1200, 0.227, SSW
AA203	1040 CARROLL ST HDFC	1040 CARROLL STREET	NY AST	Higher	1207, 0.229, NE
S204	GARDEN CLEANERS	879 FRANKLYN AVE	RCRA-VSQG, ICIS, US AIRS, NY MANIFEST	Higher	1220, 0.231, NNE
S205	NEW GARDEN CLEANER	879 FRANKLIN AVE	NY DRYCLEANERS	Higher	1220, 0.231, NNE
AB206	CON EDISON	990 PRESIDENT ST & F	NJ MANIFEST	Higher	1229, 0.233, NNE
AB207	CON EDISON	990 PRESIDENT ST & F	NJ MANIFEST	Higher	1229, 0.233, NNE
AB208	CON EDISON	990 PRESIDENT ST & F	RCRA NonGen / NLR	Higher	1229, 0.233, NNE
V209	150 CROWN STREET	150 CROWN STREET	NY AST	Higher	1233, 0.234, ENE
AC210	100 LEFFERTS AVE	100 LEFFERTS AVENUE	NY AST	Lower	1246, 0.236, SSE
AC211	100 LEFFERTS AVE	100 LEFFERTS AVENUE	NY UST	Lower	1246, 0.236, SSE
W212	J & L PROPERTIES	55 OCEAN AVENUE	NY AST	Lower	1248, 0.236, SSW
W213	57-65 OCEAN AVE	57-65 OCEAN AVENUE	NY UST	Lower	1270, 0.241, SSW
X214	CON EDISON SERVICE B	526 FLATBUSH AVE FRO	RCRA NonGen / NLR, NY MANIFEST	Lower	1271, 0.241, South
AD215	MARINE EQUITIES 101,	101 LINCOLN ROAD	NY UST	Lower	1273, 0.241, South
AD216	101 LINCOLN ROAD	101 LINCOLN ROAD	NY AST	Lower	1273, 0.241, South
AD217	105 REALTY CO	105 LINCOLN ROAD	NY AST	Lower	1291, 0.245, SSE
AD218	M & B LINCOLN REALTY	57-73 LINCOLN ROAD	NY AST	Lower	1298, 0.246, South
AD219	M & B LINCOLN REALTY	57-73 LINCOLN ROAD	NY UST	Lower	1298, 0.246, South
AB220	FRANKLIN PRESIDENT A	1000 PRESIDENT ST	NY AST	Higher	1303, 0.247, NNE
AE221	STRAUSS AUTO 122	183-207 EMPIRE BOULE	NY AST	Lower	1305, 0.247, ESE
AE222	STRAUSS AUTO 122	183-207 EMPIRE BOULE	NY UST	Lower	1305, 0.247, ESE
AE223	R & S STRAUSS	183-207 EMPIRE BLVD	RCRA NonGen / NLR	Lower	1305, 0.247, ESE
AE224	R & S STRAUSS	183-207 EMPIRE BLVD	RCRA NonGen / NLR, FINDS, ECHO	Lower	1305, 0.247, ESE
AF225	1010 REALTY LLC	1010 PRESIDENT STREE	NY AST	Higher	1308, 0.248, NNE
AD226	MERIDIAN PROPERTIES	101 LINCOLN BLVD	NY LTANKS	Lower	1311, 0.248, SSE
AG227	APT BUILDING - TTF	65 OCEAN AVE	NY LTANKS, NY LEAD	Lower	1312, 0.248, SSW
AG228	MOZAK REALTY CORP	65 OCEAN AVENUE	NY UST	Lower	1312, 0.248, SSW
AC229	LEFFERTS GARDENS, LL	115 LINCOLN ROAD	NY AST	Lower	1315, 0.249, SSE
AC230	CON EDISON - LINCOLN	115 LINCOLN ROAD	PA MANIFEST	Lower	1315, 0.249, SSE
AA231	CONSOLIDATED EDISON	BEDFORD AVE & CARROL	NY MANIFEST	Higher	1315, 0.249, NE
AF232	CON EDISON	1016 PRESIDENT ST	NY MANIFEST	Higher	1320, 0.250, NNE
AF233	CON EDISON SERVICE B	1016 PRESIDENT ST	RCRA NonGen / NLR, FINDS	Higher	1320, 0.250, NNE
AB234	990 PRESIDENT PARTNE	990 PRESIDENT STREET	NY AST	Higher	1320, 0.250, NNE

MAPPED SITES SUMMARY

Target Property Address:
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AB235	CON EDISON	990 PRESIDENT ST & F	NY Spills, NY MANIFEST	Higher	1320, 0.250, NNE
AD236		64 LINCOLN ROAD	NY LTANKS, NY LEAD	Lower	1409, 0.267, South
237	CLARA BARTON HIGH SC	CLASSON AVE AT PRESI	NY LTANKS	Higher	1469, 0.278, North
238	MONTOUTE RESIDENCE	304 MONTGOMERY ST	NY LTANKS	Higher	1483, 0.281, East
239	BOARD OF EDUCATION	901 CLASSON AVE	NY LTANKS, NY Spills	Higher	1509, 0.286, NNW
240	RESIDENCE	150 LEFFERTS AVE	NY LTANKS	Lower	1530, 0.290, SE
AH241	POLLOCK FILM INC	1579 BEDFORD AVE-LOA	NY LTANKS, RCRA NonGen / NLR, NY MANIFEST	Higher	1573, 0.298, NE
AH242	BEDFORD UNION ARMORY	1555 BEDFORD AVENUE	NY BROWNFIELDS, NY E DESIGNATION	Higher	1790, 0.339, NE
243	TTF	215 STERLING STREET	NY LTANKS	Lower	1792, 0.339, ESE
244	APARTMENT BUILDING	334 MONTGOMERY STREE	NY LTANKS, NY LEAD	Higher	1837, 0.348, East
AI245	GOODY DRY CLEANERS	812 A FRANKILN AVE	NY LTANKS	Higher	1865, 0.353, NNE
AI246	348 EASTERN PARKWAY	348 EASTERN PARKWAY	NY LTANKS, NY Spills	Higher	1902, 0.360, NNE
247	EXXONMOBIL	1550 BEDFORD AVENUE	NY LTANKS, NY Spills	Higher	1914, 0.363, NE
248	590 FLATBUSH AVE.	590 FLATBUSH AVE	NY LTANKS, NY AST, NY LEAD	Lower	2026, 0.384, South
249	240 CROWN ST CORPORA	240 CROWN ST	NY LTANKS, NY LEAD	Higher	2050, 0.388, East
250	APRT BUILDINGS	362 EASTERN PARK WAY	NY LTANKS	Higher	2052, 0.389, NNE
251	SPILL NUMBER 0313756	197 MAPLE STREET	NY LTANKS	Lower	2180, 0.413, SE
252	1880 BEDFORD AVE	1880 BEDFORD AVE	NY LTANKS	Lower	2187, 0.414, SSE
253	263-321 EASTERN PKWY	263-321 EASTERN PARK	NY LTANKS	Higher	2195, 0.416, North
254	271 SULLIVAN PLACE	271 SULLIVAN PLACE	NY LTANKS, NY AST, NY LEAD	Lower	2215, 0.420, East
255	426 EASTERN PARKWAY	426 EASTERN PARKWAY	NY LTANKS, NY UST, NY LEAD	Higher	2238, 0.424, NE
AJ256	SOIL	200 EASTERN PARKWAY	NY LTANKS, NY Spills	Higher	2249, 0.426, NNW
257	PVT DWELLING	552 LINCOLN PLACE	NY LTANKS, NY Spills	Higher	2300, 0.436, NNE
258		250 CROWN STREET	NY LTANKS, NY LEAD	Higher	2319, 0.439, East
AJ259	APPARTMENT	201 EASTERN PKWY	NY LTANKS, NY Spills, NY LEAD	Higher	2367, 0.448, North
AK260	1519 BEDFORD AVE	1519 BEDFORD AVE	NY LTANKS	Higher	2456, 0.465, NE
AK261	1525 BEDFORD AVENUE	1519-1535 BEDFORD AV	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Higher	2456, 0.465, NE
262	1150 CARROLL STREET	1150 CARROLL STREET	NY LTANKS	Higher	2479, 0.470, ENE
263	SAUTIN RESIDENCE	181 FENIMORE ST	NY LTANKS	Lower	2497, 0.473, SSE
AL264	18 ST. CHARLES PL/BK	18 ST. CHARLES PLACE	NY LTANKS	Higher	2550, 0.483, NNE
AL265	BENT RESIDENCE	16 ST CHARLES PL	NY LTANKS	Higher	2569, 0.487, NNE
266	LAKE VIEW HOUSES - T	217 OCEAN AVE	NY LTANKS	Lower	2594, 0.491, South
267	FLATBUSH STATION A A	NOSTRAND AVE. WINTHR	EDR MGP	Lower	4326, 0.819, SE
268	FLATBUSH STATION B	NOSTRAND. CLARKSON.	EDR MGP	Lower	4486, 0.850, SE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state- and tribal hazardous waste facilities

NY SHWS ---------- Inactive Hazardous Waste Disposal Sites in New York State

EXECUTIVE SUMMARY

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF ---------- Facility Register

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF UST ---------- Major Oil Storage Facilities Database
NY MOSF ---------- Major Oil Storage Facility Site Listing
NY MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land
NY TANKS ---------- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---------- Registered Waste Tire Storage & Facility List
NY SWRCY ---------- Registered Recycling Facility List
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---------- Delisted Registry Sites
US CDL ---------- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---------- Historical Petroleum Bulk Storage Database

NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
UXO ---- Unexploded Ordnance Sites
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
PFAS NPL ---- Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES ---- Federal Sites PFAS Information
PFAS TSCA ---- PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST ---- PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR ---- PFAS Contamination Site Location Listing
PFAS WQP ---- Ambient Environmental Sampling for PFAS

PFAS NPDES ---- Clean Water Act Discharge Monitoring Information
PFAS ECHO ---- Facilities in Industries that May Be Handling PFAS Listing
PFAS ECHO FIRE TRAINING Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT --- All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC ---- Aqueous Foam Related Incidents Listing
NY PFAS ---- PFAS Contamination Site Location Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY SPDES ---- State Pollutant Discharge Elimination System
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells
NY COOLING TOWERS ---- Registered Cooling Towers
MINES MRDS ---- Mineral Resources Data System

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 11/21/2022 has revealed that there are 5 RCRA-LQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE	***NEC FLATBUSH AVE / O***	***SW 1/8 - 1/4 (0.150 mi.)***	***O98***	***274***

EPA ID:: NYP004334413				
CON EDISON - MANHOLE EPA ID:: NYP004334355	NEC FLATBUSHA VE / E	SW 1/8 - 1/4 (0.150 mi.)	O100	279
NYCT - FLATBUSH EMPI EPA ID:: NYR000163733	479 FLATBUSH AVE	SSW 1/8 - 1/4 (0.158 mi.)	L111	304
CON EDISON - SERVICE EPA ID:: NYP005105242	15 OCEAN AVE	SSW 1/8 - 1/4 (0.199 mi.)	W155	576
CON EDISON - MANHOLE EPA ID:: NYP004404190	***15 OCEAN AVE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***W158***	***589***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 11/21/2022 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MEDGAR EVERS COLLEGE EPA ID:: NYR000177618	***1638 BEDFORD AVE***	***ENE 1/8 - 1/4 (0.195 mi.)***	***V148***	***548***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BP PRODUCTS NORTH AM EPA ID:: NYD987002870	***513 FLATBUSH AVE***	***S 1/8 - 1/4 (0.227 mi.)***	***X201***	***714***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 11/21/2022 has revealed that there are 4 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GARDEN CLEANERS EPA ID:: NYR000041517	***879 FRANKLYN AVE***	***NNE 1/8 - 1/4 (0.231 mi.)***	***S204***	***724***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYC BD OF ED - IS 32 EPA ID:: NYR000106377	***46 MCKEEVER PL***	***E 0 - 1/8 (0.053 mi.)***	***D25***	***94***
RITE AID #03978 EPA ID:: NYR000024356	***1679 BEDFORD AVE***	***E 1/8 - 1/4 (0.170 mi.)***	***N127***	***370***
EBBETTS FIELD EXXON	***155 EMPIRE BLVD***	***ESE 1/8 - 1/4 (0.190 mi.)***	***P143***	***475***

EPA ID:: NYD987026903

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 08/08/2022 has revealed that there are 44 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTRAL LAUNDRY CORP	***46 CROWN STREET***	***NNE 1/8 - 1/4 (0.127 mi.)***	***I74***	***217***
Spill Number/Closed Date: 1406415 / 2015-01-29				
Spill Number/Closed Date: 9903240 / 1999-08-10				
Site ID: 499883				
Site ID: 108983				
Spill Date: 2014-09-16				
Spill Date: 1999-06-21				
TANK TEST	49 CROWN ST	N 1/8 - 1/4 (0.138 mi.)	K84	244
Spill Number/Closed Date: 1505659 / 2015-10-09				
Site ID: 513042				
Spill Date: 2015-08-25				
TTF PROSPECT PARK ZO	450 FLATBUSH AVE	SW 1/8 - 1/4 (0.154 mi.)	M107	295
Spill Number/Closed Date: 0404814 / 2006-03-01				
Spill Number/Closed Date: 1004617 / 2011-03-23				
Site ID: 132092				
Site ID: 437896				
Spill Date: 2004-08-03				
Spill Date: 2010-07-23				
BROOKLYN EAST 09 DOS	***115 CROWN STREET***	***NE 1/8 - 1/4 (0.176 mi.)***	***R132***	***399***
Spill Number/Closed Date: 9614782 / 2005-02-23				
Spill Number/Closed Date: 0001495 / 2005-05-09				
Spill Number/Closed Date: 0001496 / 2005-02-23				
Spill Number/Closed Date: 0001497 / 2005-02-23				
Site ID: 117169				
Site ID: 314854				
Site ID: 314855				
Site ID: 314856				
Spill Date: 1997-03-24				
Spill Date: 2000-05-04				
MEDGAR EVERS COLLEGE	***1650 BEDFORD AVENUE***	***ENE 1/8 - 1/4 (0.182 mi.)***	***Q137***	***448***
Spill Number/Closed Date: 0706994 / 2009-12-29				
Spill Number/Closed Date: 0313372 / 2008-07-09				
Spill Number/Closed Date: 9913846 / 2005-03-14				
Site ID: 387611				
Site ID: 302810				
Site ID: 302811				
Spill Date: 2007-09-24				
Spill Date: 2004-03-05				

Spill Date: 2000-03-08

NYCTA - CHEMICAL LAB ***960 CARROLL ST*** ***NNE 1/8 - 1/4 (0.188 mi.)*** ***S139*** ***460***
Spill Number/Closed Date: 9100192 / 2001-11-30
Site ID: 181513
Spill Date: 1991-04-03

SEACREST LINEN ***931 CARROLL ST*** ***NNE 1/8 - 1/4 (0.215 mi.)*** ***U179*** ***638***
Spill Number/Closed Date: 0003909 / 2005-07-14
Site ID: 147612
Spill Date: 2000-06-29

VACANT LOT 123 CROWN ST ENE 1/8 - 1/4 (0.217 mi.) V188 660
Spill Number/Closed Date: 0603818 / 2006-07-28
Site ID: 366641
Spill Date: 2006-07-06

CLARA BARTON HIGH SC 925 CARROLL ST N 1/8 - 1/4 (0.223 mi.) Y195 672
Spill Number/Closed Date: 0012946 / 2004-06-09
Site ID: 115013
Spill Date: 2001-03-09

CLARA BARTON HIGH SC CLASSON AVE AT PRESI N 1/4 - 1/2 (0.278 mi.) 237 812
Spill Number/Closed Date: 9712737 / 2003-03-03
Site ID: 74434
Spill Date: 1998-02-13

MONTOUTE RESIDENCE 304 MONTGOMERY ST E 1/4 - 1/2 (0.281 mi.) 238 813
Spill Number/Closed Date: 0010821 / 2003-12-11
Site ID: 182019
Spill Date: 2000-12-29

BOARD OF EDUCATION ***901 CLASSON AVE*** ***NNW 1/4 - 1/2 (0.286 mi.)*** ***239*** ***814***
Spill Number/Closed Date: 9712739 / 1999-07-21
Site ID: 175550
Spill Date: 1998-02-13

POLLOCK FILM INC ***1579 BEDFORD AVE-LOA*** ***NE 1/4 - 1/2 (0.298 mi.)*** ***AH241*** ***817***
Spill Number/Closed Date: 9109496 / 2003-03-07
Site ID: 158643
Spill Date: 1991-12-05

APARTMENT BUILDING ***334 MONTGOMERY STREE*** ***E 1/4 - 1/2 (0.348 mi.)*** ***244*** ***830***
Spill Number/Closed Date: 0702097 / 2007-08-30
Spill Number/Closed Date: 9808644 / 2011-05-04
Site ID: 381746
Site ID: 330440
Spill Date: 2007-05-21
Spill Date: 1998-10-12

GOODY DRY CLEANERS 812 A FRANKILN AVE NNE 1/4 - 1/2 (0.353 mi.) AI245 838
Spill Number/Closed Date: 0601854 / 2006-11-08
Site ID: 364203
Spill Date: 2006-05-19

348 EASTERN PARKWAY ***348 EASTERN PARKWAY*** ***NNE 1/4 - 1/2 (0.360 mi.)*** ***AI246*** ***842***
Spill Number/Closed Date: 0211889 / 2003-11-12
Site ID: 232005
Spill Date: 2003-03-03

EXXONMOBIL ***1550 BEDFORD AVENUE*** ***NE 1/4 - 1/2 (0.363 mi.)*** ***247*** ***844***
Spill Number/Closed Date: 8706242 / 2019-07-30
Spill Number/Closed Date: 9813767 / 2003-10-02

Site ID: 170296
Site ID: 78584
Spill Date: 1987-10-23
Spill Date: 1999-02-11

240 CROWN ST CORPORA ***240 CROWN ST*** ***E 1/4 - 1/2 (0.388 mi.)*** ***249*** ***871***
Spill Number/Closed Date: 9813545 / 2003-04-14
Site ID: 125137
Spill Date: 1999-02-05

APRT BUILDINGS 362 EASTERN PARK WAY NNE 1/4 - 1/2 (0.389 mi.) 250 874
Spill Number/Closed Date: 0311838 / 2006-01-05
Site ID: 81207
Spill Date: 2004-01-21

263-321 EASTERN PKWY 263-321 EASTERN PARK N 1/4 - 1/2 (0.416 mi.) 253 878
Spill Number/Closed Date: 8903427 / 1989-10-01
Site ID: 149233
Spill Date: 1989-07-05

426 EASTERN PARKWAY ***426 EASTERN PARKWAY*** ***NE 1/4 - 1/2 (0.424 mi.)*** ***255*** ***884***
Spill Number/Closed Date: 0708102 / 2007-11-13
Site ID: 388939
Spill Date: 2007-10-24

SOIL ***200 EASTERN PARKWAY*** ***NNW 1/4 - 1/2 (0.426 mi.)*** ***AJ256*** ***890***
Spill Number/Closed Date: 0212402 / 2007-05-23
Site ID: 284900
Spill Date: 2003-03-17

PVT DWELLING ***552 LINCOLN PLACE*** ***NNE 1/4 - 1/2 (0.436 mi.)*** ***257*** ***894***
Spill Number/Closed Date: 0906646 / 2013-04-17
Site ID: 418995
Spill Date: 2009-09-10

Not reported ***250 CROWN STREET*** ***E 1/4 - 1/2 (0.439 mi.)*** ***258*** ***896***
Spill Number/Closed Date: 0410100 / 2006-03-01
Site ID: 335090
Spill Date: 2004-12-10

APPARTMENT ***201 EASTERN PKWY*** ***N 1/4 - 1/2 (0.448 mi.)*** ***AJ259*** ***906***
Spill Number/Closed Date: 1904836 / 2020-07-09
Site ID: 592841
Spill Date: 2019-08-06

1519 BEDFORD AVE 1519 BEDFORD AVE NE 1/4 - 1/2 (0.465 mi.) AK260 915
Spill Number/Closed Date: 9109883 / 2003-02-27
Site ID: 306124
Spill Date: 1991-12-16

1150 CARROLL STREET 1150 CARROLL STREET ENE 1/4 - 1/2 (0.470 mi.) 262 945
Spill Number/Closed Date: 0706996 / 2010-02-05
Spill Number/Closed Date: 0313371 / 2008-07-11
Spill Number/Closed Date: 9703262 / 2005-07-20
Site ID: 387613
Site ID: 73622
Site ID: 73623
Spill Date: 2007-09-24
Spill Date: 2004-03-05
Spill Date: 1997-06-16

18 ST. CHARLES PL/BK 18 ST. CHARLES PLACE NNE 1/4 - 1/2 (0.483 mi.) AL264 952

Spill Number/Closed Date: 9102191 / 1995-06-20
Site ID: 310623
Spill Date: 1991-05-23

BENT RESIDENCE — 16 ST CHARLES PL — NNE 1/4 - 1/2 (0.487 mi.) — AL265 — 953
Spill Number/Closed Date: 9708264 / 1997-11-13
Site ID: 279943
Spill Date: 1997-10-14

Lower Elevation	Address	Direction / Distance	Map ID	Page
GASETERIA OIL CORP	43 EMPIRE BLVD	SSW 0 - 1/8 (0.096 mi.)	E55	179
Spill Number/Closed Date: 9404188 / 2001-03-21				
Site ID: 175030				
Spill Date: 1994-06-23				
PROSPECT PARK - PARA	FLATBUSH AND OCEAN A	SW 1/8 - 1/4 (0.150 mi.)	O99	278
Spill Number/Closed Date: 0011106 / 2005-05-06				
Site ID: 228332				
Spill Date: 2001-01-11				
WAREHOUSE/PHAT ALBER	495 FLATBUSH AVE	SSW 1/8 - 1/4 (0.153 mi.)	L106	293
Spill Number/Closed Date: 0200458 / 2011-06-08				
Site ID: 284946				
Spill Date: 2002-04-12				
SHELL	***136 EMPIRE BLVD***	***SE 1/8 - 1/4 (0.165 mi.)***	***P117***	***332***
Spill Number/Closed Date: 8708602 / 1989-03-23				
Spill Number/Closed Date: 8903486 / 1989-07-07				
Spill Number/Closed Date: 9300390 / 1993-04-15				
Spill Number/Closed Date: 9601908 / 2012-12-21				
Site ID: 235594				
Site ID: 235595				
Site ID: 235596				
Site ID: 235597				
Spill Date: 1988-01-07				
Spill Date: 1989-07-07				
Spill Date: 1993-04-08				
Spill Date: 1996-05-08				
MERIDIAN PROPERTIES	101 LINCOLN BLVD	SSE 1/8 - 1/4 (0.248 mi.)	AD226	785
Spill Number/Closed Date: 0605577 / 2009-10-26				
Site ID: 368723				
Spill Date: 2006-08-05				
APT BUILDING - TTF	***65 OCEAN AVE***	***SSW 1/8 - 1/4 (0.248 mi.)***	***AG227***	***787***
Spill Number/Closed Date: 1209277 / 2016-09-08				
Site ID: 472341				
Spill Date: 2012-11-05				
Not reported	***64 LINCOLN ROAD***	***S 1/4 - 1/2 (0.267 mi.)***	***AD236***	***805***
Spill Number/Closed Date: 0708149 / 2010-06-10				
Site ID: 388993				
Spill Date: 2007-10-25				
RESIDENCE	150 LEFFERTS AVE	SE 1/4 - 1/2 (0.290 mi.)	240	816
Spill Number/Closed Date: 9812318 / 1999-09-08				
Site ID: 227574				
Spill Date: 1999-01-05				
TTF	215 STERLING STREET	ESE 1/4 - 1/2 (0.339 mi.)	243	828

Spill Number/Closed Date: 9802380 / 2015-06-02
Site ID: 177768
Spill Date: 1998-05-22

590 FLATBUSH AVE.	***590 FLATBUSH AVE***	***S 1/4 - 1/2 (0.384 mi.)***	***248***	***867***
Spill Number/Closed Date: 9213769 / 1993-03-16 Site ID: 311459 Spill Date: 1993-03-05				
SPILL NUMBER 0313756	197 MAPLE STREET	SE 1/4 - 1/2 (0.413 mi.)	251	875
Spill Number/Closed Date: 0313756 / 2004-04-20 Site ID: 160338 Spill Date: 2004-03-16				
1880 BEDFORD AVE	1880 BEDFORD AVE	SSE 1/4 - 1/2 (0.414 mi.)	252	877
Spill Number/Closed Date: 9211937 / 1993-01-19 Site ID: 192657 Spill Date: 1993-01-19				
271 SULLIVAN PLACE	***271 SULLIVAN PLACE***	***E 1/4 - 1/2 (0.420 mi.)***	***254***	***879***
Spill Number/Closed Date: 9415727 / 1995-03-04 Site ID: 199271 Spill Date: 1995-03-04				
SAUTIN RESIDENCE	181 FENIMORE ST	SSE 1/4 - 1/2 (0.473 mi.)	263	950
Spill Number/Closed Date: 1402553 / 2014-07-11 Site ID: 495881 Spill Date: 2014-06-09				
LAKE VIEW HOUSES - T	217 OCEAN AVE	S 1/4 - 1/2 (0.491 mi.)	266	954
Spill Number/Closed Date: 0900014 / 2009-07-14 Site ID: 411923 Spill Date: 2009-04-01				

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 32 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BROOKLYN BOTANIC GAR	***1000 WASHINGTON AVEN***	***W 0 - 1/8 (0.026 mi.)***	***A6***	***18***
Database: UST, Date of Government Version: 09/19/2022				
961 REALTY LLC	961 WASHINGTON AVENU	NNW 0 - 1/8 (0.039 mi.)	B20	78
Database: UST, Date of Government Version: 09/19/2022				
109 MONTGOMERY OWNER	109 MONTGOMERY STREE	NNW 0 - 1/8 (0.087 mi.)	F48	148
Database: UST, Date of Government Version: 09/19/2022				
SEACREST LINEN SUPPL	46 CROWN STREET	NNE 1/8 - 1/4 (0.127 mi.)	I75	222
Database: UST, Date of Government Version: 09/19/2022				
915 WASHINGTON AVE	915 WASHINGTON AVENU	NNW 1/8 - 1/4 (0.134 mi.)	J80	233
Database: UST, Date of Government Version: 09/19/2022				
TIVOLI TOWERS & TIVO	49 CROWN STREET	N 1/8 - 1/4 (0.138 mi.)	K85	245
Database: UST, Date of Government Version: 09/19/2022				

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MEDGAR EVERS COLLEGE	***115 CROWN STREET***	***NE 1/8 - 1/4 (0.176 mi.)***	***R133***	***410***
Database: UST, Date of Government Version: 09/19/2022				
MEDGAR EVERS COLLEGE	***1650 BEDFORD AVENUE***	***ENE 1/8 - 1/4 (0.182 mi.)***	***Q137***	***448***
Database: UST, Date of Government Version: 09/19/2022				
TRANSIT DISTRICT 32	960 CARROLL STREET	NNE 1/8 - 1/4 (0.188 mi.)	S141	470
Database: UST, Date of Government Version: 09/19/2022				
MEDGAR EVERS COLLEGE	1638 BEDFORD AVENUE	ENE 1/8 - 1/4 (0.195 mi.)	V149	559
Database: UST, Date of Government Version: 09/19/2022				
931 CARROLL STREET	931 CARROLL STREET	NNE 1/8 - 1/4 (0.215 mi.)	U181	643
Database: UST, Date of Government Version: 09/19/2022				
MEDGAR EVERS COLLEGE	123 CROWN STREET	ENE 1/8 - 1/4 (0.217 mi.)	V187	657
Database: UST, Date of Government Version: 09/19/2022				
991 CARROLL STREET	***991 CARROLL STREET***	***NE 1/8 - 1/4 (0.223 mi.)***	***Z196***	***673***
Database: UST, Date of Government Version: 09/19/2022				

Lower Elevation	Address	Direction / Distance	Map ID	Page
GASETERIA FRANKLIN	43 EMPIRE BOULEVARD	SSW 0 - 1/8 (0.096 mi.)	E54	168
Database: UST, Date of Government Version: 09/19/2022				
BROOKLYN FIRE COMM C	35 EMPIRE BOULEVARD	SSW 0 - 1/8 (0.106 mi.)	H66	200
Database: UST, Date of Government Version: 09/19/2022				
SAFEGUARD SELF-STORA	115 EMPIRE BLVD.	SE 1/8 - 1/4 (0.132 mi.)	G78	228
Database: UST, Date of Government Version: 09/19/2022				
EBBETS FIELD APARTME	***1720 BEDFORD AVENUE***	***E 1/8 - 1/4 (0.142 mi.)***	***N95***	***267***
Database: UST, Date of Government Version: 09/19/2022				
PHAT ALBERT WAREHOUS	495 FLATBUSH AVE	SSW 1/8 - 1/4 (0.164 mi.)	L113	309
Database: UST, Date of Government Version: 09/19/2022				
MOTIVA ENTERPRISES,	136 EMPIRE BOULEVARD	SE 1/8 - 1/4 (0.165 mi.)	P116	320
Database: UST, Date of Government Version: 09/19/2022				
PROSPECT PARK SUBWAY	478 FLATBUSH AVENUE	SSW 1/8 - 1/4 (0.168 mi.)	L119	346
Database: UST, Date of Government Version: 09/19/2022				
KFC	1715 BEDFORD AVENUE	ESE 1/8 - 1/4 (0.169 mi.)	P122	354
Database: UST, Date of Government Version: 09/19/2022				
BEDOSULL AUTO REPAIR	1727 BEDFORD AVE	ESE 1/8 - 1/4 (0.174 mi.)	P129	382
Database: UST, Date of Government Version: 09/19/2022				
PROSPECT PARK ZOO	450 FLATBUSH AVENUE	W 1/8 - 1/4 (0.177 mi.)	134	440
Database: UST, Date of Government Version: 09/19/2022				
EBBET'S FIELD (CLOSE	155 EMPIRE BLVD	ESE 1/8 - 1/4 (0.190 mi.)	P144	482
Database: UST, Date of Government Version: 09/19/2022				
P.T. STATES INC.	15 OCEAN AVENUE	SSW 1/8 - 1/4 (0.199 mi.)	W157	579
Database: UST, Date of Government Version: 09/19/2022				
BP SERVICE STATION #	513 FLATBUSH AVENUE	S 1/8 - 1/4 (0.227 mi.)	X199	681
Database: UST, Date of Government Version: 09/19/2022				
100 LEFFERTS AVE	100 LEFFERTS AVENUE	SSE 1/8 - 1/4 (0.236 mi.)	AC211	747
Database: UST, Date of Government Version: 09/19/2022				
57-65 OCEAN AVE	57-65 OCEAN AVENUE	SSW 1/8 - 1/4 (0.241 mi.)	W213	752
Database: UST, Date of Government Version: 09/19/2022				

Lower Elevation	Address	Direction / Distance	Map ID	Page
MARINE EQUITIES 101, Database: UST, Date of Government Version: 09/19/2022	101 LINCOLN ROAD	S 1/8 - 1/4 (0.241 mi.)	AD215	757
M & B LINCOLN REALTY Database: UST, Date of Government Version: 09/19/2022	57-73 LINCOLN ROAD	S 1/8 - 1/4 (0.246 mi.)	AD219	766
STRAUSS AUTO 122 Database: UST, Date of Government Version: 09/19/2022	183-207 EMPIRE BOULE	ESE 1/8 - 1/4 (0.247 mi.)	AE222	773
MOZAK REALTY CORP Database: UST, Date of Government Version: 09/19/2022	65 OCEAN AVENUE	SSW 1/8 - 1/4 (0.248 mi.)	AG228	789

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 09/19/2022 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTRAL LAUNDRY CORP Facility Status: Unregulated/Closed CBS Number: 2-000158	***46 CROWN STREET***	***NNE 1/8 - 1/4 (0.127 mi.)***	***I74***	***217***

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 55 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
975 WASHINGTON AVENU Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-148148	975 WASHINGTON AVENU	NW 0 - 1/8 (0.019 mi.)	B3	10
BROOKLYN BOTANIC GAR Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-600229	***1000 WASHINGTON AVEN***	***W 0 - 1/8 (0.026 mi.)***	***A6***	***18***
941 WASHINGTON AVENU Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-312045	941 WASHINGTON AVENU	NNW 0 - 1/8 (0.061 mi.)	B39	134
921 WASHINGTON AVE. Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-252239	921 WASHINGTON AVE.	NNW 0 - 1/8 (0.105 mi.)	F65	198
CENTRAL LAUNDRY CORP Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-000158	***46 CROWN STREET***	***NNE 1/8 - 1/4 (0.127 mi.)***	***I74***	***217***
35 CROWN STREET HDFC Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-347825	35 CROWN STREET	N 1/8 - 1/4 (0.141 mi.)	J93	262
12 CROWN STREET Database: AST, Date of Government Version: 09/19/2022	12 CROWN STREET	NNW 1/8 - 1/4 (0.141 mi.)	J94	264

Facility Id: 2-273716				
15 CROWN STREET LLC Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-252220	15 CROWN STREET	NNW 1/8 - 1/4 (0.150 mi.)	J102	283
901 WASHINGTON AVE Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-311464	901 WASHINGTON AVENU	NNW 1/8 - 1/4 (0.171 mi.)	J128	380
MEDGAR EVERS COLLEGE Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-456020	***115 CROWN STREET***	***NE 1/8 - 1/4 (0.176 mi.)***	***R133***	***410***
MONTGOMERY REALTY, L Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-602875	236 MONTGOMERY STREE	E 1/8 - 1/4 (0.181 mi.)	Q136	446
TRANSIT DISTRICT 32 Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-190365	960 CARROLL STREET	NNE 1/8 - 1/4 (0.188 mi.)	S140	468
934 CARROLL STREET Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-608595	934 CARROLL STREET	N 1/8 - 1/4 (0.194 mi.)	U145	541
932 CARROLL STREET Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-054720	932 CARROLL STREET	N 1/8 - 1/4 (0.194 mi.)	U146	543
MEDGAR EVERS COLLEGE Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-611359	1638 BEDFORD AVENUE	ENE 1/8 - 1/4 (0.195 mi.)	V147	546
250 REALTY ASSOCIATE Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-259454	250 MONTGOMERY STREE	E 1/8 - 1/4 (0.197 mi.)	Q153	570
916 CARROLL STREET Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-054712	916 CARROLL STREET	N 1/8 - 1/4 (0.202 mi.)	U161	598
MEDGAR EVERS COLLEGE Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-612221	1637 BEDFORD AVE.	ENE 1/8 - 1/4 (0.204 mi.)	V166	612
CITY OF N.Y. DEPT. O Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-601142	888 FRANKLIN AVE	NNE 1/8 - 1/4 (0.205 mi.)	S167	615
951 CARROLL ST Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-234273	951 CARROLL ST	NNE 1/8 - 1/4 (0.209 mi.)	S168	617
959 CARROLL ASSOCIAT Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-208108	959 CARROLL STREET	NNE 1/8 - 1/4 (0.212 mi.)	S172	626
1030 CARROLL STREET Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-214183	1030 CARROLL STREET	NE 1/8 - 1/4 (0.215 mi.)	R176	633
931 CARROLL STREET Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-215929	931 CARROLL STREET	NNE 1/8 - 1/4 (0.215 mi.)	U180	641
TAG REALTY INC. Database: AST, Date of Government Version: 09/19/2022	969 CARROLL STREET	NNE 1/8 - 1/4 (0.216 mi.)	S182	646

Facility Id: 2-285412

881 WASHINGTON AVE — 881 WASHINGTON AVENU — NNW 1/8 - 1/4 (0.217 mi.) — Y186 — 654
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-216208

991 CARROLL STREET — 991 CARROLL STREET — NE 1/8 - 1/4 (0.223 mi.) — Z196 — 673
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-187267

883 FRANKLIN LLC, C/ — 883 FRANKLIN AVENUE — NNE 1/8 - 1/4 (0.225 mi.) — S198 — 679
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-091669

1040 CARROLL ST HDFC — 1040 CARROLL STREET — NE 1/8 - 1/4 (0.229 mi.) — AA203 — 722
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-608664

150 CROWN STREET — 150 CROWN STREET — ENE 1/8 - 1/4 (0.234 mi.) — V209 — 743
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-609096

FRANKLIN PRESIDENT A — 1000 PRESIDENT ST — NNE 1/8 - 1/4 (0.247 mi.) — AB220 — 768
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-154016

1010 REALTY LLC — 1010 PRESIDENT STREE — NNE 1/8 - 1/4 (0.248 mi.) — AF225 — 783
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-467030

990 PRESIDENT PARTNE — 990 PRESIDENT STREET — NNE 1/8 - 1/4 (0.250 mi.) — AB234 — 799
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-196746

Lower Elevation	Address	Direction / Distance	Map ID	Page

WASHINGTON REALTY LL — 1015 WASHINGTON AVEN — SW 0 - 1/8 (0.011 mi.) — A1 — 8
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-605904

1035 WASHINGTON AVEN — 1035 WASHINGTON AVEN — SSW 0 - 1/8 (0.031 mi.) — A12 — 64
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-205222

I.S. 320 - BROOKLYN — 46 MCKEEVER PLACE — E 0 - 1/8 (0.053 mi.) — D24 — 90
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-355690

MAZE AUTO REPAIR INC — 66 SULLIVAN PLACE — SE 0 - 1/8 (0.054 mi.) — C26 — 109
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-610606

BROOKLYN FIRE COMM C — 35 EMPIRE BOULEVARD — SSW 0 - 1/8 (0.106 mi.) — H67 — 203
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-357219

104-110 EMPIRE BLVD — 104-110 EMPIRE BLVD — SE 1/8 - 1/4 (0.128 mi.) — G77 — 226
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-272086

EMPIRE VALLEY LLC — 110 EMPIRE BOULEVARD — SE 1/8 - 1/4 (0.134 mi.) — G79 — 231
Database: AST, Date of Government Version: 09/19/2022
Facility Id: 2-600775

EBBETS FIELD APARTME — 1720 BEDFORD AVENUE — E 1/8 - 1/4 (0.142 mi.) — N95 — 267
Database: AST, Date of Government Version: 09/19/2022

Facility Id: 2-152064				
FIRESTONE COMPLETE A Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-607835	1730 BEDFORD AVENUE	ESE 1/8 - 1/4 (0.158 mi.)	P110	302
MOTIVA ENTERPRISES, Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-190926	136 EMPIRE BOULEVARD	SE 1/8 - 1/4 (0.165 mi.)	P118	344
25 LEFFERTS, LLC Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-065021	25 LEFFERTS AVENUE	S 1/8 - 1/4 (0.189 mi.)	T142	473
1767 BEDFORD AVE Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-373885	1767 BEDFORD AVE	SE 1/8 - 1/4 (0.210 mi.)	169	619
50 LEFFERTS TENANTS Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-603774	50 LEFFERTS AVENUE	S 1/8 - 1/4 (0.211 mi.)	T170	622
50 REALTY CO Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-359009	50 LEFFERTS AVENUE	S 1/8 - 1/4 (0.211 mi.)	T171	624
J & L PROPERTIES Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-219711	39 OCEAN AVENUE	SSW 1/8 - 1/4 (0.215 mi.)	W177	636
45 OCEAN LLC Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-219738	45 OCEAN AVENUE	SSW 1/8 - 1/4 (0.224 mi.)	W197	677
100 LEFFERTS AVE Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-206636	100 LEFFERTS AVENUE	SSE 1/8 - 1/4 (0.236 mi.)	AC210	745
J & L PROPERTIES Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-219746	55 OCEAN AVENUE	SSW 1/8 - 1/4 (0.236 mi.)	W212	749
101 LINCOLN ROAD Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-237310	101 LINCOLN ROAD	S 1/8 - 1/4 (0.241 mi.)	AD216	760
105 REALTY CO Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-155543	105 LINCOLN ROAD	SSE 1/8 - 1/4 (0.245 mi.)	AD217	762
M & B LINCOLN REALTY Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-603914	57-73 LINCOLN ROAD	S 1/8 - 1/4 (0.246 mi.)	AD218	764
STRAUSS AUTO 122 Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-603867	183-207 EMPIRE BOULE	ESE 1/8 - 1/4 (0.247 mi.)	AE221	770
LEFFERTS GARDENS, LL Database: AST, Date of Government Version: 09/19/2022 Facility Id: 2-187119	115 LINCOLN ROAD	SSE 1/8 - 1/4 (0.249 mi.)	AC229	791

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTRAL LAUNDRY CORP Facility Status: 2 Facility Status: 1 CBS Number: 2-000158	46 CROWN ST.	NNE 1/8 - 1/4 (0.127 mi.)	I76	224

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 08/08/2022 has revealed that there is 1 NY ENG CONTROLS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
1525 BEDFORD AVENUE Site Code: 503333	***1519-1535 BEDFORD AV***	***NE 1/4 - 1/2 (0.465 mi.)***	***AK261***	***916***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 08/08/2022 has revealed that there is 1 NY INST CONTROL site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
1525 BEDFORD AVENUE Site Code: 503333	***1519-1535 BEDFORD AV***	***NE 1/4 - 1/2 (0.465 mi.)***	***AK261***	***916***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 2 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
54 CROWN STREET Database: VCP NYC, Date of Government Version: 09/05/2022	46 CROWN STREET	NNE 1/8 - 1/4 (0.127 mi.)	I73	216
931 CARROLL STREET Database: VCP NYC, Date of Government Version: 09/05/2022	931 CARROLL STREET	NNE 1/8 - 1/4 (0.215 mi.)	U178	638

EXECUTIVE SUMMARY

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 08/08/2022 has revealed that there are 3 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BEDFORD UNION ARMORY Site Code: 540934	***1555 BEDFORD AVENUE***	***NE 1/4 - 1/2 (0.339 mi.)***	***AH242***	***823***
1525 BEDFORD AVENUE Site Code: 503333	***1519-1535 BEDFORD AV***	***NE 1/4 - 1/2 (0.465 mi.)***	***AK261***	***916***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: Site Code: 628295	***73 EMPIRE BLVD***	***SSE 0 - 1/8 (0.093 mi.)***	***G52***	***159***

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 08/08/2022 has revealed that there are 18 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
975 WASHINGTON AVE Spill Number/Closed Date: 0009713 / 2001-05-15 Spill Number/Closed Date: 0009723 / 2003-05-27 Site ID: 191217 Site ID: 191218 Spill Date: 2000-11-27	975 WASHINGTON AVE	NW 0 - 1/8 (0.019 mi.)	B5	16
BROOKLYN BOTANICAL G Spill Number/Closed Date: 9712821 / 1999-02-03 Site ID: 191118 Spill Date: 1998-02-06	1008 WASHINGTON AVE	W 0 - 1/8 (0.030 mi.)	A10	56
955 WASHINGTON AVE Spill Number/Closed Date: 9602523 / 1996-05-23 Site ID: 63761 Spill Date: 1996-05-22	955 WASHINGTON AVE	NW 0 - 1/8 (0.036 mi.)	B13	66
MANHOLE 1135 Spill Number/Closed Date: 0008062 / 2002-04-05 Site ID: 279728 Spill Date: 2000-10-10	MONTGOMERY ST/WASHIN	NNW 0 - 1/8 (0.069 mi.)	F44	143
GOLOMBECKS METHYL BR	MONTGOMERY AV & FRAN	NNE 0 - 1/8 (0.071 mi.)	45	144

Spill Number/Closed Date: 8602323 / 1986-07-09
Site ID: 156377
Spill Date: 1986-07-09

EXCAVATION SITE — 109 MONTGOMERY ST — NNW 0 - 1/8 (0.087 mi.) — F47 — 145
Spill Number/Closed Date: 1801903 / 2018-12-20
Site ID: 570453
Spill Date: 2018-05-18

MANHOLE #4787 — WASHINGTON AVE AND M — NNW 0 - 1/8 (0.088 mi.) — F50 — 155
Spill Number/Closed Date: 0508060 / 2005-12-01
Site ID: 353580
Spill Date: 2005-10-05

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOIL	***1035 WASHINGTON AVE***	***SSW 0 - 1/8 (0.031 mi.)***	***A11***	***57***
Spill Number/Closed Date: 1701355 / 2017-09-25 Site ID: 548401 Spill Date: 2017-05-11				
MANHOLE 4709	FRANKLIN AVE NEAR SU	S 0 - 1/8 (0.038 mi.)	C14	67
Spill Number/Closed Date: 0510798 / 2008-01-10 Site ID: 356839 Spill Date: 2005-12-15				
FRANKLIN ST & SULLIV	FRANKLIN ST & SULLIV	S 0 - 1/8 (0.038 mi.)	C18	76
Spill Number/Closed Date: 9612030 / 2008-03-20 Site ID: 328376 Spill Date: 1997-01-06				
NYC BD OF ED - IS 32	***46 MCKEEVER PL***	***E 0 - 1/8 (0.053 mi.)***	***D25***	***94***
Spill Number/Closed Date: 2101518 / 2021-09-13 Spill Number/Closed Date: 9302528 / 1993-05-25 Site ID: 619234 Site ID: 133241 Spill Date: 2021-05-18 Spill Date: 1993-05-25				
MANHOLE # M4785	WASHINGTON AVE AND S	SSW 0 - 1/8 (0.055 mi.)	E31	119
Spill Number/Closed Date: 0508015 / 2005-12-01 Site ID: 353528 Spill Date: 2005-10-02				
SPILL NUMBER 9812071	SULLIVAN PL & WASHIN	SSW 0 - 1/8 (0.055 mi.)	E36	127
Spill Number/Closed Date: 9812071 / 2003-02-20 Site ID: 212176 Spill Date: 1998-12-28				
CON EDISON MANHOLE:	***73 EMPIRE BLVD***	***SSE 0 - 1/8 (0.093 mi.)***	***G52***	***159***
Spill Number/Closed Date: 2102064 / 2021-06-22 Site ID: 619801 Spill Date: 2021-06-04				
MANHOLE # 23430	EMPIRE BL & FRANKLIN	S 0 - 1/8 (0.094 mi.)	H53	167
Spill Number/Closed Date: 9909194 / 2002-02-22 Site ID: 232206 Spill Date: 1999-10-28				
STREET	EMPIRE BLVD/ WASHING	SSW 0 - 1/8 (0.101 mi.)	H58	188
Spill Number/Closed Date: 0801500 / 2008-05-08				

Site ID: 397438 Spill Date: 2008-05-07				
MANHOLE # 4761 Spill Number/Closed Date: 0409712 / 2005-01-07 Site ID: 334511 Spill Date: 2004-11-30	EMPIRE BLVD./E WASHI	SSW 0 - 1/8 (0.101 mi.)	H59	189
MANHOLE 58808 Spill Number/Closed Date: 0502779 / 2006-01-09 Site ID: 347212 Spill Date: 2005-06-08	WASHINGTON AVE/EMPIR	SSW 0 - 1/8 (0.101 mi.)	H60	190

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 11/21/2022 has revealed that there are 54 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON ED - MH 47218 EPA ID:: NYP004011938	***F/O 975 WASHINGTON A***	***NW 0 - 1/8 (0.019 mi.)***	***B4***	***13***
BROOKLYN BOTANIC GAR EPA ID:: NYR000176255	***1000 WASHINGTON AVE***	***W 0 - 1/8 (0.026 mi.)***	***A7***	***25***
GARDEN CLEANERS EPA ID:: NYD982529182	***96 MONTGOMERY ST***	***NNW 0 - 1/8 (0.065 mi.)***	***F43***	***138***
CON EDISON - MANHOLE EPA ID:: NYP004136974	***WASHINGTON AVE AND M***	***NNW 0 - 1/8 (0.088 mi.)***	***F49***	***150***
NEW YORK TELEPHONE EPA ID:: NYP000908467	***MONTGOMERY & WASHING***	***NNW 0 - 1/8 (0.088 mi.)***	***F51***	***156***
CON ED - VS 5973 EPA ID:: NYP000930602	***CROWN ST & FRANKLIN***	***NNE 1/8 - 1/4 (0.134 mi.)***	***I82***	***237***
CON EDISON MANHOLE: EPA ID:: NYP004414306	***WASHINGTON AVE & CRO***	***NNW 1/8 - 1/4 (0.157 mi.)***	***J108***	***298***
CON EDISON EPA ID:: NYP004773784	MONTGOMERY ST & BEDF	ENE 1/8 - 1/4 (0.169 mi.)	Q124	365
NYC SANITATION EPA ID:: NYD982529679	***115 CROWN ST - BK-E-***	***NE 1/8 - 1/4 (0.176 mi.)***	***R131***	***395***
CON EDISON SERVICE B EPA ID:: NYP004415204	***960 CARROLL ST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***S138***	***456***
NYCTA - CHEMICAL LAB EPA ID:: NYD980653885	***960 CARROLL ST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***S139***	***460***
CON EDISON SERVICE B EPA ID:: NYP004543781	1653 BEDFORD AVE	ENE 1/8 - 1/4 (0.196 mi.)	Q151	564
CON EDISON SERVICE B	***FRANKLIN AVE & CARRO***	***NNE 1/8 - 1/4 (0.196 mi.)***	***S152***	***566***

EPA ID:: NYP004439162				
1645 BEDFORD INC EPA ID:: NYD980778724	***1645 BEDFORD AVE***	***ENE 1/8 - 1/4 (0.200 mi.)***	***Q160***	***594***
CON EDISON EPA ID:: NYP004182192	***BEDFORD AVE & CROWN***	***ENE 1/8 - 1/4 (0.203 mi.)***	***V163***	***601***
CON EDISON SERVICE B EPA ID:: NYP004437919	***CROWN ST & BEDFORD A***	***ENE 1/8 - 1/4 (0.203 mi.)***	***V164***	***605***
CON EDISON VAULT SUB EPA ID:: NYP004437901	***CROWN ST & BEDFORD A***	***ENE 1/8 - 1/4 (0.203 mi.)***	***V165***	***609***
CON EDISON EPA ID:: NYP004805388	990 PRESIDENT ST & F	NNE 1/8 - 1/4 (0.233 mi.)	AB208	741
CON EDISON SERVICE B EPA ID:: NYP004492963	***1016 PRESIDENT ST***	***NNE 1/8 - 1/4 (0.250 mi.)***	***AF233***	***796***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID:: NYP004558987	1003 FRANKLIN AVE	SSE 0 - 1/8 (0.026 mi.)	C9	53
CON ED - TM 356 EPA ID:: NYP004003554	***SULLIVAN PL & FRANKL***	***S 0 - 1/8 (0.038 mi.)***	***C15***	***69***
CON EDISON EPA ID:: NYP004759767	***SULLIVAN PL & FRANKL***	***S 0 - 1/8 (0.038 mi.)***	***C17***	***73***
VICTOR LOGAN COLLISI EPA ID:: NYD981184864	***62 SULLIVAN PL***	***SSE 0 - 1/8 (0.052 mi.)***	***C22***	***82***
CON EDISON SERVICE B EPA ID:: NYP004288981	***48 MCKEEVER PL SB 28***	***E 0 - 1/8 (0.053 mi.)***	***D23***	***86***
CON EDISON EPA ID:: NYP004759775	***1028 FRANKLIN AVE***	***S 0 - 1/8 (0.055 mi.)***	***C29***	***114***
CON EDISON EPA ID:: NYP004759858	***SULLIVAN PL & WASHIN***	***SSW 0 - 1/8 (0.055 mi.)***	***E30***	***116***
CON EDISON EPA ID:: NYP004759866	SULLIVAN PL & WASHIN	SSW 0 - 1/8 (0.055 mi.)	E32	121
CON EDISON SERVICE B EPA ID:: NYP004288825	***47 MCKEEVER PL SB 28***	***E 0 - 1/8 (0.060 mi.)***	***D38***	***130***
CON EDISON MANHOLE: EPA ID:: NYP004271730	***73 EMPIRE BLVD***	***SSE 0 - 1/8 (0.093 mi.)***	***G52***	***159***
CON EDISON MANHOLE: EPA ID:: NYP004293122	***EMPIRE BLVD & WASHIN***	***SSW 0 - 1/8 (0.100 mi.)***	***H56***	***180***
CON EDISON EPA ID:: NYP004182184	***WASHINGTON AVE & EMP***	***SSW 0 - 1/8 (0.100 mi.)***	***H57***	***184***
CON EDISON EPA ID:: NYP004779005	99 EMPIRE BLVD	SE 0 - 1/8 (0.105 mi.)	G63	194
MID-COUNTY MOTORS EPA ID:: NYD093760627	***44 EMPIRE BLVD***	***SSW 0 - 1/8 (0.110 mi.)***	***H68***	***206***
CON EDISON MANHOLE: EPA ID:: NYP004279402	***103 EMPIRE BLVD***	***SE 0 - 1/8 (0.113 mi.)***	***G70***	***212***
CON EDISON - MANHOLE	***WASHINGTON AVE & FRA***	***S 1/8 - 1/4 (0.137 mi.)***	***H83***	***240***

EPA ID:: NYP004136164				
CON EDISON EPA ID:: NYP004733796	475 FLATBUSH AVE SB2	SSW 1/8 - 1/4 (0.140 mi.)	L87	249
CON EDISON EPA ID:: NYP004733788	***475 FLATBUSH AVE SB2***	***SSW 1/8 - 1/4 (0.140 mi.)***	***L88***	***251***
LEFFERTS HOMESTEAD EPA ID:: NY0000204420	***440 FLATBUSH AVE***	***SW 1/8 - 1/4 (0.140 mi.)***	***M92***	***258***
CONSOLIDATED EDISON EPA ID:: NYP004034666	SE STERLING PL & WAS	S 1/8 - 1/4 (0.151 mi.)	L103	286
CON EDISON - MANHOLE EPA ID:: NYP004136230	***WASHINGTON AVE AND S***	***S 1/8 - 1/4 (0.151 mi.)***	***L105***	***289***
CONGRESS CLEANERS EPA ID:: NYD982793747	***1685 BEDFORD AVE***	***E 1/8 - 1/4 (0.165 mi.)***	***N114***	***312***
SHELL OIL CO EPA ID:: NYD987008141	***136 EMPIRE BLVD***	***SE 1/8 - 1/4 (0.165 mi.)***	***P115***	***316***
CON EDISON SERVICE B EPA ID:: NYP004335873	***480 FLATBUSH AVE***	***SSW 1/8 - 1/4 (0.169 mi.)***	***L120***	***348***
K F C NATIONAL MANAG EPA ID:: NYR000102558	***1715 BEDFORD AVE***	***ESE 1/8 - 1/4 (0.169 mi.)***	***P123***	***361***
BRIDGESTONE FIRESTON EPA ID:: NYD987008711	***1750 BEDFORD AVE***	***SE 1/8 - 1/4 (0.175 mi.)***	***P130***	***391***
CON-ED - MH4802 EPA ID:: NYP004043725	BEDFORD AVE AND EMPI	ESE 1/8 - 1/4 (0.178 mi.)	P135	443
CON EDISON SB73433 EPA ID:: NYP004395257	***15 OCEAN AVE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***W154***	***572***
CON EDISON EPA ID:: NYP004726949	***FLATBUSH AVE & LEFFE***	***SSW 1/8 - 1/4 (0.212 mi.)***	***X174***	***629***
CON EDISON EPA ID:: NYP004726998	***514 FLATBUSH AVE***	***SSW 1/8 - 1/4 (0.216 mi.)***	***X185***	***652***
CON EDISON SERVICE B EPA ID:: NYP004395265	***1120 WASHINGTON AVE***	***S 1/8 - 1/4 (0.219 mi.)***	***T191***	***663***
CON EDISON SERVICE B EPA ID:: NYP004568382	1123 WASHINGTON AVE	S 1/8 - 1/4 (0.220 mi.)	T193	668
CON EDISON SERVICE B EPA ID:: NYP004409173	***526 FLATBUSH AVE FRO***	***S 1/8 - 1/4 (0.241 mi.)***	***X214***	***754***
R & S STRAUSS EPA ID:: NY0000027433	183-207 EMPIRE BLVD	ESE 1/8 - 1/4 (0.247 mi.)	AE223	775
R & S STRAUSS EPA ID:: NYD987037009	***183-207 EMPIRE BLVD***	***ESE 1/8 - 1/4 (0.247 mi.)***	***AE224***	***779***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 08/30/2022 has revealed that there are 4 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GARDEN CLEANERS	96 MONTGOMERY STREET	NNW 0 - 1/8 (0.065 mi.)	F41	137

Facility Id: 2-6104-00816				
SEA CREST LINEN/CENT Facility Id: 2-6104-00778	46 CROWN STREET	NNE 1/8 - 1/4 (0.127 mi.)	I72	216
1645 BEDFORD CLEANER Facility Id: 2-6104-01048	1645 BEDFORD AVE	ENE 1/8 - 1/4 (0.200 mi.)	Q159	593
NEW GARDEN CLEANER Facility Id: 2-6104-01321	879 FRANKLIN AVE	NNE 1/8 - 1/4 (0.231 mi.)	S205	731

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 09/21/2022 has revealed that there is 1 NY E DESIGNATION site within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 50,TAXBLOCK 1190	135 MONTGOMERY STREE	N 0 - 1/8 (0.083 mi.)	F46	145

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 70 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - SERVICE EPA ID: NYP004913180	995 WASHINGTON AVE	WNW 0 - 1/8 (0.012 mi.)	A2	10
CON ED - MH 47218 EPA ID: NYP004011938	***F/O 975 WASHINGTON A***	***NW 0 - 1/8 (0.019 mi.)***	***B4***	***13***
BROOKLYN BOTANIC GAR EPA ID: NYR000176255	***1000 WASHINGTON AVE***	***W 0 - 1/8 (0.026 mi.)***	***A7***	***25***
CON EDISON EPA ID: NYP004688040	104 MONTGOMERY ST	NNW 0 - 1/8 (0.061 mi.)	B40	136
GARDEN CLEANERS EPA ID: NYD982529182	***96 MONTGOMERY ST***	***NNW 0 - 1/8 (0.065 mi.)***	***F43***	***138***
CON EDISON - MANHOLE EPA ID: NYP004136974	***WASHINGTON AVE AND M***	***NNW 0 - 1/8 (0.088 mi.)***	***F49***	***150***
NEW YORK TELEPHONE EPA ID: NYP000908467	***MONTGOMERY & WASHING***	***NNW 0 - 1/8 (0.088 mi.)***	***F51***	***156***
CON ED - VS 5973 EPA ID: NYP000930602	***CROWN ST & FRANKLIN***	***NNE 1/8 - 1/4 (0.134 mi.)***	***I82***	***237***
CON EDISON MANHOLE: EPA ID: NYP004414306	***WASHINGTON AVE & CRO***	***NNW 1/8 - 1/4 (0.157 mi.)***	***J108***	***298***
CONSOLIDATED EDISON EPA ID: NYP004136461	WASHINGTON & CROWN S	NNW 1/8 - 1/4 (0.157 mi.)	J109	301
CON EDISON EPA ID: NYP004773784	MONTGOMERY ST & BEDF	ENE 1/8 - 1/4 (0.169 mi.)	Q126	369
CON EDISON SERVICE B	***960 CARROLL ST***	***NNE 1/8 - 1/4 (0.188 mi.)***	***S138***	***456***

EPA ID: NYP004415204 EPA ID: NYD980653885				
MEDGAR EVERS COLLEGE EPA ID: NYR000177618	***1638 BEDFORD AVE***	***ENE 1/8 - 1/4 (0.195 mi.)***	***V148***	***548***
CON EDISON EPA ID: NYP004658175 EPA ID: NYP004632493 EPA ID: NYP004543781	1653 BEDFORD AV	ENE 1/8 - 1/4 (0.196 mi.)	Q150	561
CON EDISON SERVICE B EPA ID: NYP004439162	***FRANKLIN AVE & CARRO***	***NNE 1/8 - 1/4 (0.196 mi.)***	***S152***	***566***
1645 BEDFORD INC EPA ID: NYD980778724	***1645 BEDFORD AVE***	***ENE 1/8 - 1/4 (0.200 mi.)***	***Q160***	***594***
CON EDISON EPA ID: NYP004182192	***BEDFORD AVE & CROWN***	***ENE 1/8 - 1/4 (0.203 mi.)***	***V163***	***601***
CON EDISON SERVICE B EPA ID: NYP004437919	***CROWN ST & BEDFORD A***	***ENE 1/8 - 1/4 (0.203 mi.)***	***V164***	***605***
CON EDISON VAULT SUB EPA ID: NYP004437901	***CROWN ST & BEDFORD A***	***ENE 1/8 - 1/4 (0.203 mi.)***	***V165***	***609***
CON EDISON EPA ID: NYP004662615	989 CARROLL ST	NE 1/8 - 1/4 (0.219 mi.)	Z192	666
GARDEN CLEANERS EPA ID: NYR000041517	***879 FRANKLYN AVE***	***NNE 1/8 - 1/4 (0.231 mi.)***	***S204***	***724***
CONSOLIDATED EDISON EPA ID: NYP004113213	BEDFORD AVE & CARROL	NE 1/8 - 1/4 (0.249 mi.)	AA231	794
CON EDISON EPA ID: NYP004492963	1016 PRESIDENT ST	NNE 1/8 - 1/4 (0.250 mi.)	AF232	795
CON EDISON EPA ID: NYP004805388 EPA ID: NYP004805396	***990 PRESIDENT ST & F***	***NNE 1/8 - 1/4 (0.250 mi.)***	***AB235***	***801***

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CON EDISON EPA ID: NYP004558987	1003 FRANKLIN AVE	SSE 0 - 1/8 (0.026 mi.)	C8	52
CON ED - TM 356 EPA ID: NYP004003554	***SULLIVAN PL & FRANKL***	***S 0 - 1/8 (0.038 mi.)***	***C15***	***69***
CON ED EPA ID: NYP004759767	SULLIVAN PL & FRANKL	S 0 - 1/8 (0.038 mi.)	C19	77
CON EDISON EPA ID: NYP004654778	998 FRANKLIN AVE	S 0 - 1/8 (0.047 mi.)	C21	80
VICTOR LOGAN COLLISI EPA ID: NYD981184864	***62 SULLIVAN PL***	***SSE 0 - 1/8 (0.052 mi.)***	***C22***	***82***
CON EDISON SERVICE B EPA ID: NYP004288981	***48 MCKEEVER PL SB 28***	***E 0 - 1/8 (0.053 mi.)***	***D23***	***86***
NYC BD OF ED - IS 32 EPA ID: NYR000106377	***46 MCKEEVER PL***	***E 0 - 1/8 (0.053 mi.)***	***D25***	***94***
CON ED EPA ID: NYP004759775	1028 FRANKLIN AVE	S 0 - 1/8 (0.055 mi.)	C27	111
CON ED	SULLIVAN PL & WASHIN	SSW 0 - 1/8 (0.055 mi.)	E34	124

EPA ID: NYP004759866				
CON ED EPA ID: NYP004759858	WASHINGTON AVE & SUL	SSW 0 - 1/8 (0.055 mi.)	E37	128
CON EDISON SERVICE B EPA ID: NYP004288825	***47 MCKEEVER PL SB 28***	***E 0 - 1/8 (0.060 mi.)***	***D38***	***130***
CON EDISON MANHOLE: EPA ID: NYP004271730	***73 EMPIRE BLVD***	***SSE 0 - 1/8 (0.093 mi.)***	***G52***	***159***
CON EDISON MANHOLE: EPA ID: NYP004293122	***EMPIRE BLVD & WASHIN***	***SSW 0 - 1/8 (0.100 mi.)***	***H56***	***180***
CON EDISON EPA ID: NYP004182184	***WASHINGTON AVE & EMP***	***SSW 0 - 1/8 (0.100 mi.)***	***H57***	***184***
CON EDISON EPA ID: NYP004595153	1035 FRANKLIN AVE	S 0 - 1/8 (0.104 mi.)	H61	191
CON EDISON EPA ID: NYP004779005	99 EMPIRE BLVD	SE 0 - 1/8 (0.105 mi.)	G64	196
CON EDISON MANHOLE: EPA ID: NYP004279402	***103 EMPIRE BLVD***	***SE 0 - 1/8 (0.113 mi.)***	***G70***	***212***
CON EDISON EPA ID: NYP004405700	35 STERLING ST	SSE 1/8 - 1/4 (0.134 mi.)	81	235
CON EDISON - MANHOLE EPA ID: NYP004136164	***WASHINGTON AVE & FRA***	***S 1/8 - 1/4 (0.137 mi.)***	***H83***	***240***
CON EDISON EPA ID: NYP004733796	475 FLATBUSH AVE SB2	SSW 1/8 - 1/4 (0.140 mi.)	L89	254
CON EDISON EPA ID: NYP004733788	475 FLATBUSH AVE SB2	SSW 1/8 - 1/4 (0.140 mi.)	L90	255
LEFFERTS HOMESTEAD EPA ID: NY0000204420	***440 FLATBUSH AVE***	***SW 1/8 - 1/4 (0.140 mi.)***	***M92***	***258***
CON EDISON - MANHOLE EPA ID: NYP004935332	2-26 EMPIRE BLVD	SW 1/8 - 1/4 (0.150 mi.)	L96	271
CON EDISON EPA ID: NYP004334355	FLATBUSH AVE & EMPIR	SW 1/8 - 1/4 (0.150 mi.)	O97	272
CON EDISON - MANHOLE EPA ID: NYP004334413	***NEC FLATBUSH AVE / O***	***SW 1/8 - 1/4 (0.150 mi.)***	***O98***	***274***
CON ED-MH4514 EPA ID: NYZ004019030	WASHINGTON AVE & STE	S 1/8 - 1/4 (0.151 mi.)	L104	288
CON EDISON - MANHOLE EPA ID: NYP004136230	***WASHINGTON AVE AND S***	***S 1/8 - 1/4 (0.151 mi.)***	***L105***	***289***
NYCT - FLATBUSH EMPI EPA ID: NYR000163733	479 FLATBUSH AVE	SSW 1/8 - 1/4 (0.158 mi.)	L112	307
CONGRESS CLEANERS EPA ID: NYD982793747	***1685 BEDFORD AVE***	***E 1/8 - 1/4 (0.165 mi.)***	***N114***	***312***
SHELL OIL CO EPA ID: NYD987008141	***136 EMPIRE BLVD***	***SE 1/8 - 1/4 (0.165 mi.)***	***P115***	***316***
CON EDISON SERVICE B EPA ID: NYP004335873	***480 FLATBUSH AVE***	***SSW 1/8 - 1/4 (0.169 mi.)***	***L120***	***348***
CON ED	FO 480 FLATBUSH AVE	SSW 1/8 - 1/4 (0.169 mi.)	L121	352

EPA ID: NYP004424966				
K F C NATIONAL MANAG EPA ID: NYR000102558	***1715 BEDFORD AVE***	***ESE 1/8 - 1/4 (0.169 mi.)***	***P123***	***361***
RITE AID #03978 EPA ID: NYR000024356	***1679 BEDFORD AVE***	***E 1/8 - 1/4 (0.170 mi.)***	***N127***	***370***
EBBETTS FIELD EXXON EPA ID: NYD987026903	***155 EMPIRE BLVD***	***ESE 1/8 - 1/4 (0.190 mi.)***	***P143***	***475***
CON EDISON SB73433 EPA ID: NYP004395257	***15 OCEAN AVE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***W154***	***572***
CON EDISON - SERVICE EPA ID: NYP005105242	15 OCEAN AVE	SSW 1/8 - 1/4 (0.199 mi.)	W156	579
CON EDISON - MANHOLE EPA ID: NYP004404190	***15 OCEAN AVE***	***SSW 1/8 - 1/4 (0.199 mi.)***	***W158***	***589***
CON EDISON EPA ID: NYP004726949	FLATBUSH AVE & LEFFE	SSW 1/8 - 1/4 (0.212 mi.)	X175	632
CON EDISON EPA ID: NYP004726998	514 FLATBUSH AVE	SSW 1/8 - 1/4 (0.216 mi.)	X183	648
CON EDISON - SERVICE EPA ID: NYP004934640	1120 WASHINGTON AVE	S 1/8 - 1/4 (0.219 mi.)	T190	662
CON EDISON SERVICE B EPA ID: NYP004395265	***1120 WASHINGTON AVE***	***S 1/8 - 1/4 (0.219 mi.)***	***T191***	***663***
CON EDISON EPA ID: NYP004568382	1123 WASHINGTON AVE	S 1/8 - 1/4 (0.220 mi.)	T194	670
BP PRODUCTS NORTH AM EPA ID: NYD987002870	***513 FLATBUSH AVE***	***S 1/8 - 1/4 (0.227 mi.)***	***X201***	***714***
CON EDISON EPA ID: NYP004590709	510 FLAT BUSH AV	SSW 1/8 - 1/4 (0.227 mi.)	X202	720
CON EDISON SERVICE B EPA ID: NYP004409173	***526 FLATBUSH AVE FRO***	***S 1/8 - 1/4 (0.241 mi.)***	***X214***	***754***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 3 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - CROWN & Generator EPA Id: NYP005051891	CROWN & BEDFORD ST	ENE 1/8 - 1/4 (0.203 mi.)	V162	601

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON Generator EPA Id: NYP005187988	504 FLATBUSH AVE	SSW 1/8 - 1/4 (0.217 mi.)	X189	661
CON EDISON - LINCOLN Generator EPA Id: NYP005033105	115 LINCOLN ROAD	SSE 1/8 - 1/4 (0.249 mi.)	AC230	793

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 16 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BROOKLYN BOTANIC GAR EPA Id: NYR000176255	***1000 WASHINGTON AVE***	***W 0 - 1/8 (0.026 mi.)***	***A7***	***25***
CON EDISON EPA Id: NYP004773784	MONTGOMERY ST & BEDF	ENE 1/8 - 1/4 (0.169 mi.)	Q125	368
CON EDISON EPA Id: NYP004805396	990 PRESIDENT ST & F	NNE 1/8 - 1/4 (0.233 mi.)	AB206	738
CON EDISON EPA Id: NYP004805388	990 PRESIDENT ST & F	NNE 1/8 - 1/4 (0.233 mi.)	AB207	739

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004759767	SULLIVAN PL & FRANKL	S 0 - 1/8 (0.038 mi.)	C16	72
CON EDISON EPA Id: NYP004759775	1028 FRANKLIN AVE	S 0 - 1/8 (0.055 mi.)	C28	113
CON EDISON EPA Id: NYP004759858	WASHINGTON AVE & SUL	SSW 0 - 1/8 (0.055 mi.)	E33	123
CON EDISON EPA Id: NYP004759866	SULLIVAN PL & WASHIN	SSW 0 - 1/8 (0.055 mi.)	E35	126
CON EDISON EPA Id: NYP004779005	99 EMPIRE BLVD	SE 0 - 1/8 (0.105 mi.)	G62	193
CON EDISON MANHOLE: EPA Id: NYP004279402	103 EMPIRE BLVD	SE 0 - 1/8 (0.113 mi.)	G69	210
CON EDISON EPA Id: NYP004733788	475 FLATBUSH AVE SB2	SSW 1/8 - 1/4 (0.140 mi.)	L86	248
CON EDISON EPA Id: NYP004733796	475 FLATBUSH AVE SB2	SSW 1/8 - 1/4 (0.140 mi.)	L91	257
CON EDISON - MANHOLE EPA Id: NYP004770160	OCEAN AVE & FLATBUSH	SW 1/8 - 1/4 (0.150 mi.)	O101	282
CON EDISON EPA Id: NYP004726949	FLATBUSH AVE & LEFFE	SSW 1/8 - 1/4 (0.212 mi.)	X173	628
CON EDISON EPA Id: NYP004726998	514 FLATBUSH AVE	SSW 1/8 - 1/4 (0.216 mi.)	X184	650
BP PRODUCTS NORTH AM EPA Id: NYD987002870	513 FLATBUSH AVE	S 1/8 - 1/4 (0.227 mi.)	X200	713

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EXECUTIVE SUMMARY

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 2 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FLATBUSH STATION A A	NOSTRAND AVE. WINTHR	SE 1/2 - 1 (0.819 mi.)	267	955
FLATBUSH STATION B	NOSTRAND. CLARKSON.	SE 1/2 - 1 (0.850 mi.)	268	955

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there is 1 EDR Hist Auto site within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FALCON AUTOMOTIVE IN	100 EMPIRE BLVD	SE 0 - 1/8 (0.123 mi.)	G71	216

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GARDEN CLEANING	96 MONTGOMERY ST	NNW 0 - 1/8 (0.065 mi.)	F42	138

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 8 records.

Site Name	Database(s)
DAVIDSON PIPE SUPPLY COMPANY	NY SHWS
CATON PLACE GW	NY SHWS
GOLDEN TOUCH CLEANERS	NY DRYCLEANERS
FLATBUSH STATION B	NY VCP, NY BROWNFIELDS
VICTORY CONTRACTING CO; I	NY SWF/LF
MARINE PARK	NY SWF/LF
BROOKLYN MODEL CITY - DEKALB AVE/W	NY SWF/LF
BASEMENT	NY LTANKS

OVERVIEW MAP - 7231046.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 962 & 972	CLIENT: The ALC Group, LLC T/A ALC
ADDRESS: 972 Franklin Avenue Brooklyn NY 11225	CONTACT: Tania Castro INQUIRY #: 7231046.2s
LAT/LONG: 40.665112 / 73.960462	DATE: January 23, 2023 10:42 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7231046.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 962 & 972	CLIENT: The ALC Group, LLC T/A ALC
ADDRESS: 972 Franklin Avenue Brooklyn NY 11225	CONTACT: Tania Castro
LAT/LONG: 40.665112 / 73.960462	INQUIRY #: 7231046.2s DATE: January 23, 2023 10:43 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	5	NR	NR	NR	5
RCRA-SQG	0.250		0	2	NR	NR	NR	2
RCRA-VSQG	0.250		1	3	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	0	0	0	NR	0
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	0	0	NR	NR	0
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		1	14	29	NR	NR	44
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		5	27	NR	NR	NR	32
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY MOSF	0.500		0	0	0	NR	NR	0
NY AST	0.250		9	46	NR	NR	NR	55
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	1	NR	NR	1
NY INST CONTROL	0.500		0	0	1	NR	NR	1
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		0	2	0	NR	NR	2
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		1	0	2	NR	NR	3
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		18	NR	NR	NR	NR	18
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		20	34	NR	NR	NR	54
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	0	NR	NR	NR	0
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		1	3	NR	NR	NR	4
NY E DESIGNATION	0.125		1	NR	NR	NR	NR	1
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250		24	46	NR	NR	NR	70
PA MANIFEST	0.250		0	3	NR	NR	NR	3
NJ MANIFEST	0.250		7	9	NR	NR	NR	16
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	2	NR	2
EDR Hist Auto	0.125		1	NR	NR	NR	NR	1
EDR Hist Cleaner	0.125		1	NR	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		0	90	196	33	2	0	321

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
SW
< 1/8
0.011 mi.
60 ft.

WASHINGTON REALTY LLC
1015 WASHINGTON AVENUE
BROOKLYN, NY 11225

Site 1 of 7 in cluster A

NY AST **A100178148**
N/A

Relative:
Lower

Actual:
89 ft.

AST:

Name:	WASHINGTON REALTY LLC
Address:	1015 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605904
Program Type:	PBS
UTM X:	587817.72501
UTM Y:	4502057.13576
Expiration Date:	05/24/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	27770
Affiliation Type:	Facility Owner
Company Name:	WASHINGTON REALTY LLC
Contact Type:	AGENT
Contact Name:	ARTHUR W
Address1:	166 MONTAGUE STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 875-1522
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-09-12

Site Id:	27770
Affiliation Type:	Mail Contact
Company Name:	UNITED MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	PROPERTY MANAGER
Address1:	166 MONTAGUE STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 875-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27770
Affiliation Type:	Facility Operator
Company Name:	WASHINGTON REALTY LLC
Contact Type:	Not reported
Contact Name:	ATIF

WASHINGTON REALTY LLC (Continued) **A100178148**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 287-0035
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	27770
Affiliation Type:	Emergency Contact
Company Name:	WASHINGTON REALTY LLC
Contact Type:	Not reported
Contact Name:	ATIF
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 287-0035
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	01
Tank Id:	60694
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/1942
Capacity Gallons:	5000
Tightness Test Method:	NN

WASHINGTON REALTY LLC (Continued) **A100178148**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

A2 **CON EDISON - SERVICE BOX M47218** **NY MANIFEST** **S120958110**
WNW **995 WASHINGTON AVE** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.012 mi.
65 ft. **Site 2 of 7 in cluster A**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX M47218
Address:	995 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004913180
Facility Status:	Not reported
Location Address 1:	995 WASHINGTON AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004913180
Mailing Name:	CON EDISON - SERVICE BOX M47218
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

B3 **975 WASHINGTON AVENUE** **NY AST** **U003385560**
NW **975 WASHINGTON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.019 mi.
99 ft. **Site 1 of 7 in cluster B**

Relative:
Higher

Actual:
92 ft.

AST:

Name:	975 WASHINGTON AVENUE
Address:	975 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active

975 WASHINGTON AVENUE (Continued) **U003385560**

Facility Id: 2-148148
Program Type: PBS
UTM X: 587799.92477
UTM Y: 4502166.97907
Expiration Date: 12/19/2026
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 4397
Affiliation Type: Facility Operator
Company Name: 975 WASHINGTON AVENUE
Contact Type: Not reported
Contact Name: APPROVED OIL
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 238-1050
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-06-02

Site Id: 4397
Affiliation Type: Emergency Contact
Company Name: 975 WASHINGTON PROPERTY LLC
Contact Type: Not reported
Contact Name: STEVEN FEWINTZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 865-8410
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-10-12

Site Id: 4397
Affiliation Type: Mail Contact
Company Name: 975 WASHINGTON PROPERTY LLC
Contact Type: AUTHORIZED REP
Contact Name: ISRAEL WEINBERGER
Address1: 85 DELANCY ST
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10002
Country Code: 001
Phone: (212) 777-2060
EMail: CUSTOMERSERVICE@COLTOWN.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-06-02

975 WASHINGTON AVENUE (Continued) **U003385560**

Site Id:	4397
Affiliation Type:	Facility Owner
Company Name:	975 WASHINGTON PROPERTY LLC
Contact Type:	AUTHORIZED REP
Contact Name:	JONATHAN WEINBERGER
Address1:	85 DELANCY ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10002
Country Code:	001
Phone:	(212) 777-2060
EMail:	CUSTOMERSERVICE@COLTOWN.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-10-12

Tank Info:

Tank Number:	001
Tank Id:	8025
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	L09 - Piping Leak Detection - Exempt Suction Piping
	H99 - Tank Leak Detection - Other
	B99 - Tank External Protection - Other
	G04 - Tank Secondary Containment - Double-Walled (Underground)
	C01 - Pipe Location - Aboveground
	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/01/1950
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

B4 **CON ED - MH 47218** **RCRA NonGen / NLR** **1007206556**
NW **F/O 975 WASHINGTON AVE** **NY MANIFEST** **NYP004011938**
< 1/8 **BROOKLYN, NY 11225**
0.019 mi.
99 ft. **Site 2 of 7 in cluster B**

Relative: **Higher**
Actual: **92 ft.**

RCRA Listings:

Date Form Received by Agency:		19980228
Handler Name:	CON ED - MH 47218	
Handler Address:		F/O 975 WASHINGTON AVE
Handler City,State,Zip:		BROOKLYN, NY 11225-0000
EPA ID:		NYP004011938
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC
Contact City,State,Zip:		NEW YORK, NY 10003-0000
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON ED - MH 47218 (Continued) **1007206556**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980226
Handler Name: CON ED - MH 47218	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980227
Handler Name: CON ED - MH 47218	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON ED - MH 47218 (Continued) **1007206556**

Electronic Manifest Broker: Not reported

Receive Date: 19980228
Handler Name: CON ED - MH 47218
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: F/O 975 WASHINGTON AVE
City,State,Zip: BROOKLYN, NY 11225-0000
Country: USA
EPA ID: NYP004011938
Facility Status: Not reported
Location Address 1: 47218 - 975 WASHINGTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004011938
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON ED - MH 47218 (Continued) **1007206556**

Mailing Phone: 2124602808

B5 **975 WASHINGTON AVE** **NY Spills** **S104880672**
NW **975 WASHINGTON AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.019 mi.
99 ft. **Site 3 of 7 in cluster B**

Relative:
Higher

Actual:
92 ft.

SPILLS:

Name:	OPPISITE
Address:	975 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0009713 / 2001-05-15
Facility ID:	0009713
Facility Type:	ER
DER Facility ID:	159496
Site ID:	191217
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	2401
Spill Date:	2000-11-27
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2000-11-27
CID:	257
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-27
Spill Record Last Update:	2001-05-15
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	OPERATOR 110
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 5/15/2001 TJD No drum found"
Remarks:	"drum leaking "

All Materials:

Site ID:	191217
Operable Unit ID:	831964
Operable Unit:	01
Material ID:	543652
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G

975 WASHINGTON AVE (Continued) **S104880672**

Recovered:	.00
Oxygenate:	Not reported
Name:	975 WASHINGTON AVE
Address:	975 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0009723 / 2003-05-27
Facility ID:	0009723
Facility Type:	ER
DER Facility ID:	159496
Site ID:	191218
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C1
SWIS:	2401
Spill Date:	2000-11-27
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2000-11-27
CID:	389
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-27
Spill Record Last Update:	2003-05-27
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 5/27/03 TJD No spill. Drum removed."
Remarks:	"CALLER REPORTING A FOUND OIL DRUM APPROX 20 GAL DRUM DOESN'T APPEAR TO BE A SPILL BUT NOT CONFIRMED AT THIS TIME. NO CALLBACK NECESSARY"

All Materials:

Site ID:	191218
Operable Unit ID:	831968
Operable Unit:	01
Material ID:	543661
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A6
West
< 1/8
0.026 mi.
138 ft.

BROOKLYN BOTANIC GARDEN
1000 WASHINGTON AVENUE
BROOKLYN, NY 11238

Site 3 of 7 in cluster A

NY UST **U004062140**
NY AST **N/A**

Relative:
Higher

Actual:
92 ft.

UST:

Name:	BROOKLYN BOTANIC GARDEN
Address:	1000 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11238
Id/Status:	2-600229 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/23/2026
UTM X:	587737.15154
UTM Y:	4502375.04109
Site Type:	Other

Affiliation Records:

Site Id:	22212
Affiliation Type:	Emergency Contact
Company Name:	BROOKLYN BOTANIC GARDENS
Contact Type:	Not reported
Contact Name:	SAL GJURKAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 623-7028
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2022-05-10

Site Id:	22212
Affiliation Type:	Mail Contact
Company Name:	BROOKLYN BOTANIC GARDEN
Contact Type:	Not reported
Contact Name:	TRACEY FAIRELAND / SAL GJURKAJ
Address1:	1000 WASHINGTON AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 623-7277
EMail:	TFAIRLAND@BBG.ORG
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-05-13

Site Id:	22212
Affiliation Type:	Facility Owner
Company Name:	BROOKLYN BOTANIC GARDEN
Contact Type:	VP PLANNING
Contact Name:	TRACEY FAIRELAND
Address1:	1000 WASHINGTON AVENUE

BROOKLYN BOTANIC GARDEN (Continued) **U004062140**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 623-7277
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-12-07

Site Id:	22212
Affiliation Type:	Facility Operator
Company Name:	BROOKLYN BOTANIC GARDEN
Contact Type:	Not reported
Contact Name:	TRACEY FAIRELAND
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 623-7281
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-12-07

Tank Info:

Tank Number:	001
Tank ID:	41640
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000
Install Date:	08/01/1987
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	05/13/2022

Equipment Records:

D99 - Pipe Type - Other
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F05 - Pipe External Protection - Jacketed

BROOKLYN BOTANIC GARDEN (Continued) **U004062140**

K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG

Tank Number:	002
Tank ID:	41641
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000
Install Date:	08/01/1987
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	05/13/2022

Equipment Records:

F05 - Pipe External Protection - Jacketed
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D99 - Pipe Type - Other
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number:	005
Tank ID:	47726
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	11627
Install Date:	08/01/1987
Date Tank Closed:	05/20/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	03/30/2009

BROOKLYN BOTANIC GARDEN (Continued) **U004062140**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser

AST:
Name: BROOKLYN BOTANIC GARDEN
Address: 1000 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11238
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-600229
Program Type: PBS
UTM X: 587737.15154
UTM Y: 4502375.04109
Expiration Date: 07/23/2026
Site Type: Other

Affiliation Records:
Site Id: 22212
Affiliation Type: Emergency Contact
Company Name: BROOKLYN BOTANIC GARDENS
Contact Type: Not reported
Contact Name: SAL GJURKAJ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 623-7028
EMail: Not reported
Fax Number: Not reported
Modified By: MXLAY
Date Last Modified: 2022-05-10

Site Id: 22212
Affiliation Type: Mail Contact
Company Name: BROOKLYN BOTANIC GARDEN
Contact Type: Not reported
Contact Name: TRACEY FAIRELAND / SAL GJURKAJ
Address1: 1000 WASHINGTON AVENUE
Address2: Not reported
City: BROOKLYN

BROOKLYN BOTANIC GARDEN (Continued) **U004062140**

State: NY
Zip Code: 11225
Country Code: 001
Phone: (718) 623-7277
EMail: TFAIRLAND@BBG.ORG
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2022-05-13

Site Id: 22212
Affiliation Type: Facility Owner
Company Name: BROOKLYN BOTANIC GARDEN
Contact Type: VP PLANNING
Contact Name: TRACEY FAIRELAND
Address1: 1000 WASHINGTON AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11225
Country Code: 001
Phone: (718) 623-7277
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-12-07

Site Id: 22212
Affiliation Type: Facility Operator
Company Name: BROOKLYN BOTANIC GARDEN
Contact Type: Not reported
Contact Name: TRACEY FAIRELAND
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 623-7281
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-12-07

Tank Info:

Tank Number: 003
Tank Id: 41642
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

I99 - Overfill - Other
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

BROOKLYN BOTANIC GARDEN (Continued) **U004062140**

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A01 - Tank Internal Protection - Epoxy Liner
B04 - Tank External Protection - Fiberglass
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	08/01/1987
Capacity Gallons:	1000
Tightness Test Method:	21
Date Test:	02/14/2003
Next Test Date:	Not reported
Date Tank Closed:	05/20/2014
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel
Tank Number:	004
Tank Id:	47725
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J00 - Dispenser - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H03 - Tank Leak Detection - Vapor Well

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	08/01/1987
Capacity Gallons:	500
Tightness Test Method:	21
Date Test:	02/27/2003
Next Test Date:	Not reported
Date Tank Closed:	08/01/2013
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

BROOKLYN BOTANIC GARDEN (Continued) **U004062140**

Tank Number: 006
Tank Id: 249545

Equipment Records:

J05 - Dispenser - On Site Heating System (Supply/Return)
K99 - Spill Prevention - Other
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1989
Capacity Gallons: 75
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DAFRANCI
Last Modified: 05/13/2022
Material Name: Diesel (E-Gen)

Tank Number: 007
Tank Id: 252200

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/09/2014
Capacity Gallons: 275
Tightness Test Method: -

BROOKLYN BOTANIC GARDEN (Continued) **U004062140**

Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DAFRANCI
Last Modified: 05/13/2022
Material Name: Diesel (E-Gen)

Tank Number: 008
Tank Id: 252201

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/05/2014
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: DAFRANCI
Last Modified: 05/13/2022
Material Name: Diesel (E-Gen)

A7 **BROOKLYN BOTANIC GARDENS** **RCRA NonGen / NLR** **1015747068**
West **1000 WASHINGTON AVE** **FINDS** **NYR000176255**
< 1/8 **BROOKLYN, NY 11225** **ECHO**
0.026 mi. **NJ MANIFEST**
138 ft. **Site 4 of 7 in cluster A** **NY MANIFEST**

Relative: Higher
Actual: 92 ft.

RCRA Listings:
Date Form Received by Agency: 20120531
Handler Name: BROOKLYN BOTANIC GARDEN
Handler Address: 1000 WASHINGTON AVE
Handler City,State,Zip: BROOKLYN, NY 11225
EPA ID: NYR000176255
Contact Name: SCOT MEDBURY
Contact Address: WASHINGTON AVE
Contact City,State,Zip: BROOKLYN, NY 11225
Contact Telephone: 718-623-7269

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Contact Fax:		718-857-2430
Contact Email:		PRESIDENTSOFFICE@BBG.ORG
Contact Title:		PRESIDENT
EPA Region:		02
Land Type:		Other
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		WASHINGTON AVE
Mailing City,State,Zip:		BROOKLYN, NY 11225
Owner Name:	THE CITY OF NEW YORK	
Owner Type:		Private
Operator Name:	BROOKLYN BOTANIC GARDEN	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Groundwater Controls Indicator: N/A
Operating TSDF Universe: Not reported
Full Enforcement Universe: Not reported
Significant Non-Complier Universe: No
Unaddressed Significant Non-Complier Universe: No
Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20150414
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2011

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: THE CITY OF NEW YORK
Legal Status: Private
Date Became Current: 18970101
Date Ended Current: Not reported
Owner/Operator Address: 31 CHAMBERS ST - 2ND FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10007
Owner/Operator Telephone: 212-513-9300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE CITY OF NEW YORK
Legal Status: Private
Date Became Current: 18970101
Date Ended Current: Not reported
Owner/Operator Address: 31 CHAMBERS ST - 2ND FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10007
Owner/Operator Telephone: 212-513-9300
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BROOKLYN BOTANIC GARDEN
Legal Status: Private
Date Became Current: 19100101
Date Ended Current: Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NEW YORK
Legal Status: Municipal
Date Became Current: 19770101
Date Ended Current: Not reported
Owner/Operator Address: 31 CHAMBERS ST
Owner/Operator City,State,Zip: NEW YORK, NY 10007
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BROOKLYN BOTANIC GARDEN INC
Legal Status: Private
Date Became Current: 19770101
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BROOKLYN BOTANIC GARDEN
Legal Status: Private
Date Became Current: 19100101
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20120216
Handler Name: BROOKLYN BOTANIC GARDEN INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Receive Date: 20120531
Handler Name: BROOKLYN BOTANIC GARDEN
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100629
Handler Name: BROOKLYN BOTANIC GARDEN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 71213
NAICS Description: ZOOS AND BOTANICAL GARDENS

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20120814
Actual Return to Compliance Date: 20130219
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20120918
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20130219
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20120814
Actual Return to Compliance Date: 20130219
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20120918
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20130219
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Used Oil - Generators
Date Violation was Determined:	20120814
Actual Return to Compliance Date:	20130219
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20120918
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20130219
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20120814
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20130219
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20120814
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20130219
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20130219
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: FOLLOW-UP INSPECTION
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20120814
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20130219
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110055616445

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1015747068
Registry ID:	110055616445
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055616445
Name:	BROOKLYN BOTANIC GARDENS
Address:	1000 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY 11225

NJ MANIFEST:

EPA Id:	NYR000176255
Mail Address:	WASHINGTON AVE
Mail City/State/Zip:	BROOKLYN, NY 11225
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	SCOT MEDBURY

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007469842JJK
EPA ID:	NYR000176255
Date Shipped:	07/27/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/27/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/27/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	56780 P

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Manifest Number:	007469814JJK
EPA ID:	NYR000176255
Date Shipped:	07/26/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/26/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/26/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	54020 P

Manifest Number:	007469802JJK
EPA ID:	NYR000176255
Date Shipped:	07/26/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/26/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/26/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	55760 P

Manifest Number:	007469791JJK
EPA ID:	NYR000176255
Date Shipped:	07/23/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/23/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/23/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	61060 P

Manifest Number:	007469803JJK
EPA ID:	NYR000176255
Date Shipped:	07/26/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/26/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/26/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	59040 P

Manifest Number:	007469782JJK
EPA ID:	NYR000176255
Date Shipped:	07/23/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/23/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/23/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	59200 P

Manifest Number:	007469843JJK
EPA ID:	NYR000176255
Date Shipped:	07/27/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/27/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/27/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	54360 P

Manifest Number:	007469865JJK
EPA ID:	NYR000176255

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Date Shipped:	07/28/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/28/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	49400 P

Manifest Number:	007469855JJK
EPA ID:	NYR000176255
Date Shipped:	07/28/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/28/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	54660 P

Manifest Number:	007469790JJK
EPA ID:	NYR000176255
Date Shipped:	07/23/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/23/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/23/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	58200 P

Manifest Number:	007469862JJK
EPA ID:	NYR000176255
Date Shipped:	07/28/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/28/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	47680 P

Manifest Number:	007469809JJK
EPA ID:	NYR000176255
Date Shipped:	07/26/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/26/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/26/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	49200 P

Manifest Number:	007469864JJK
EPA ID:	NYR000176255
Date Shipped:	07/28/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/28/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	48760 P

Manifest Number:	007469840JJK
EPA ID:	NYR000176255
Date Shipped:	07/26/2010
TSDF EPA ID:	NJD991291105

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/26/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/26/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	46000 P

Manifest Number:	007469863JJK
EPA ID:	NYR000176255
Date Shipped:	07/28/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Date Trans1 Transported Waste:	07/28/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/28/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	58500 P

Manifest Number:	007469807JJK
EPA ID:	NYR000176255
Date Shipped:	07/25/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/25/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Date TSDF Received Waste:	07/26/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	53660 P

Manifest Number:	007469844JJK
EPA ID:	NYR000176255
Date Shipped:	07/27/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/27/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/27/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	58060 P

Manifest Number:	007469853JJK
EPA ID:	NYR000176255
Date Shipped:	07/27/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/27/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/27/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Hand Code:	H111
Quantity:	51980 P
Manifest Number:	007469789JJK
EPA ID:	NYR000176255
Date Shipped:	07/23/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/23/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/23/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	59960 P
Manifest Number:	007469788JJK
EPA ID:	NYR000176255
Date Shipped:	07/23/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/23/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/23/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN, NY 11225
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	57960 P

NY MANIFEST:

Name:	BROOKLYN BOTANIC GARDEN
Address:	1000 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYR000176255
Facility Status:	Not reported
Location Address 1:	1000 WASHINGTON AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000176255
Mailing Name: BROOKLYN BOTANIC GARDEN
Mailing Contact: BROOKLYN BOTANIC GARDEN
Mailing Address 1: 1000 WASHINGTON AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJR000029967
Trans2 State ID: Not reported
Generator Ship Date: 07/28/2010
Trans1 Recv Date: 07/28/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/28/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000176255
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 007469855JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 54660
Units: P - Pounds
Number of Containers: 1
Container Type: DT - Dump trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

BROOKLYN BOTANIC GARDENS (Continued) **1015747068**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C8 **CON EDISON** **NY MANIFEST** **S117063473**
SSE **1003 FRANKLIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.026 mi.
139 ft. **Site 1 of 14 in cluster C**

Relative:
Lower

Actual:
83 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	1003 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004558987
Facility Status:	Not reported
Location Address 1:	FO 1003 FRANKLYN AVE
Code:	BP
Location Address 2:	MH 26241
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004558987
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/10/2014
Trans1 Recv Date:	06/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004558987
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117063473**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245982JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C9 **CON EDISON MANHOLE: 26241** **RCRA NonGen / NLR** **1017777986**
SSE **1003 FRANKLIN AVE** **NYP004558987**
< 1/8 **BROOKLYN, NY 11225**
0.026 mi.
139 ft. **Site 2 of 14 in cluster C**

Relative: **Lower**
Actual: **83 ft.**

RCRA Listings:

Date Form Received by Agency:	20140710
Handler Name:	CON EDISON MANHOLE: 26241
Handler Address:	1003 FRANKLIN AVE
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYP004558987
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON MANHOLE: 26241 (Continued) **1017777986**

Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No

CON EDISON MANHOLE: 26241 (Continued) **1017777986**

Financial Assurance Required: Not reported
Handler Date of Last Change: 20150211
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20140610
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140610
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140710
Handler Name: CON EDISON MANHOLE: 26241
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON MANHOLE: 26241 (Continued) **1017777986**

Evaluation Action Summary:
Evaluations: No Evaluations Found

A10
West
< 1/8
0.030 mi.
158 ft.

BROOKLYN BOTANICAL GARDEN **NY Spills** **S103036044**
1008 WASHINGTON AVE **N/A**
BROOKLYN, NY

Site 5 of 7 in cluster A

Relative:
Higher

Actual:
92 ft.

SPILLS:

Name:	BROOKLYN BOTANICAL GARDEN
Address:	1008 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712821 / 1999-02-03
Facility ID:	9712821
Facility Type:	ER
DER Facility ID:	159415
Site ID:	191118
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1998-02-06
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1998-02-17
CID:	312
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-17
Spill Record Last Update:	2005-02-03
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY DURING TANK UPGRADE/PIPING CLOSURE IN PLACE, CONTAM. SOIL FOUND. WARREN & PANZER EXCAVATED & REMOVED 57 TONS, DID SITE INVESTIGATION, FOUND MINOR RESIDUAL CONTAM. DEPTH TO GROUNDWATER IS 80+ FEET, JK APPROVED NO FURTHER ACTION."
Remarks:	"SOIL SAMPLES ABOVE STARS AMOUNTS - GATE #1008 AREA"

All Materials:

Site ID:	191118
Operable Unit ID:	1055672
Operable Unit:	01
Material ID:	327411
Material Code:	0066A
Material Name:	unknown petroleum

BROOKLYN BOTANICAL GARDEN (Continued) **S103036044**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A11 **SOIL** **NY Spills** **S120702733**
SSW **1035 WASHINGTON AVE** **NY LEAD** **N/A**
< 1/8 **BROOKLYN, NY**
0.031 mi.
163 ft. **Site 6 of 7 in cluster A**

Relative: SPILLS:
Lower

Actual:
88 ft.

Name:	SOIL
Address:	1035 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1701355 / 2017-09-25
Facility ID:	1701355
Facility Type:	ER
DER Facility ID:	502045
Site ID:	548401
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2017-05-11
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2017-05-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-05-11
Spill Record Last Update:	2018-10-30
Spiller Name:	WEXLER
Spiller Company:	UNKNOWN
Spiller Address:	1035 WASHINGTON AVE
Spiller Company:	999
Contact Name:	WEXLER
DEC Memo:	"5/11/17- DEC Piper spoke with Abe from NYC Tank Testing. As per conversation, ABe was contacted after building observed oil in open excavation. The spill was believed to be from a historical overfill. Abe will over excavated and collect endpoint samples. CSL sent to Arthur Weiner 1035 Washington Avenue Realty, LLC 166 Montague Street Brooklyn, NY 11201 9/25/17-New York City tank Testing, In. Emailed the report. As per the report the defective fill line was replaced. NYCTT proceed by excavating all contaminated concrete and soil along the old line until all contamination was removed. The final dimensions of the excavation 22’ 8 long and up to 5’ 8 wide with a

SOIL (Continued) **S120702733**

depth of 8’ below grade. A total of one hundred and seven fifty-five 55-gallon drums of contaminated soil were removed and properly disposed of by able Environmental services, Inc as petroleum contaminated soil. On July 25, 2017 NYCTT began collecting post excavation soil samples. Sample #1 is a composite floor sample that was collected from the area of the excavation closest to the building, which is on the eastern side of the old fill line, to a depth of seven feet (7’). On July 26, 2017, sample #2 was collected from from the floor at the center of the lower area of the excavation in the area of the old fill line, to a depth of 8’. Sample #3 is a composite sample which was collected from the perimeter of the lower excavation in the area of the old fill line to a depth of 8’. Sample #4 was collected from the floor at the center of the upper excavation along the old fill line to a depth of 7’ below grade. Sample #5 is a composite sample which was collected from the perimeters of the upper excavation along the old fill line. Enclosed are photos and a diagram of the site, which further details the excavation and sampling locations. The sampling was biased towards any possible staining or residual product. The soil analytical indicated VOCs and SVOCs not detected or below the NYSDEC CP-51 standards. Spill Closed. "

Remarks: "Clean up is pending found material in soil sampling"

All Materials:

Site ID:	548401
Operable Unit ID:	1296548
Operable Unit:	01
Material ID:	2302596
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NYC LEAD:

Name:	Not reported
Address:	1035 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	13933460
Building ID:	388518
Registration ID:	304949
Apartment:	5A
Story:	5
Class:	Most Serious
Inspection Date:	12/09/2020
Approved Date:	12/10/2020
Original Certify By Date:	01/09/2021
Original Correct By Date:	01/04/2021
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	7031381
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD -

SOIL (Continued) **S120702733**

PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM SOUTH AT WEST WALL IN THE FOYER LOCATED AT APT 5A, 5th STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date: 12/11/2020
Current Status ID: 21
Current Status: NOT COMPLIED WITH
Current Status Date: 10/05/2021

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 13886988
Building ID: 388518
Registration ID: 304949
Apartment: 6M
Story: 6
Class: Most Serious
Inspection Date: 10/28/2020
Approved Date: 11/10/2020
Original Certify By Date: 12/11/2020
Original Correct By Date: 12/06/2020
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7004024
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE 1st BATHROOM FROM EAST LOCATED AT APT 6M, 6th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date: 11/12/2020
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 01/07/2021

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 13886989
Building ID: 388518
Registration ID: 304949
Apartment: 6M
Story: 6
Class: Most Serious
Inspection Date: 10/28/2020
Approved Date: 11/10/2020
Original Certify By Date: 12/11/2020
Original Correct By Date: 12/06/2020
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7004024
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE

SOIL (Continued) **S120702733**

USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL IN THE PRIVATE HALLWAY LOCATED AT APT 6M, 6th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date: 11/12/2020
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 01/07/2021

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11190785
Building ID: 388518
Registration ID: 304949
Apartment: 3D
Story: 3
Class: Most Serious
Inspection Date: 04/08/2016
Approved Date: 04/08/2016
Original Certify By Date: 05/14/2016
Original Correct By Date: 05/09/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 617
NOV ID: 5405554
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL, EAST WALL IN THE 1st ROOM FROM EAST LOCATED AT APT 3D, 3rd STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date: 04/11/2016
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 02/21/2017

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11287868
Building ID: 388518
Registration ID: 304949
Apartment: 3D
Story: 3
Class: Most Serious
Inspection Date: 06/18/2016
Approved Date: 06/24/2016
Original Certify By Date: 07/30/2016
Original Correct By Date: 07/25/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 5459632
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, 3rd

SOIL (Continued) **S120702733**

WINDOW FRAME FROM WEST AT NORTH WALL IN THE 2nd ROOM FROM EAST AT NORTH LOCATED AT APT 3D, 3rd STORY, 1st APARTMENT FROM WEST AT NORTH

NOV Issued Date: 06/27/2016
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 02/21/2017

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11287869
Building ID: 388518
Registration ID: 304949
Apartment: 3D
Story: 3
Class: Most Serious
Inspection Date: 06/18/2016
Approved Date: 06/24/2016
Original Certify By Date: 07/30/2016
Original Correct By Date: 07/25/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 5459632
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) EAST WALL, 1st WINDOW FRAME FROM WEST AT NORTH WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL, 2nd WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 4th ROOM FROM EAST AT NORTH LOCATED AT APT 3D, 3rd STORY, 1st APARTMENT FROM WEST AT NORTH

NOV Issued Date: 06/27/2016
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 02/21/2017

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11291301
Building ID: 388518
Registration ID: 304949
Apartment: 3D
Story: 3
Class: Most Serious
Inspection Date: 06/18/2016
Approved Date: 06/28/2016
Original Certify By Date: 08/01/2016
Original Correct By Date: 07/27/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 5461798
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE

SOIL (Continued) **S120702733**

USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, 4th WINDOW FRAME FROM WEST AT NORTH WALL IN THE 1st ROOM FROM EAST AT NORTH LOCATED AT APT 3D, 3rd STORY, 1st APARTMENT FROM WEST AT NORTH

NOV Issued Date: 06/29/2016
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 02/21/2017

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 14635869
Building ID: 388518
Registration ID: 304949
Apartment: 6M
Story: 6
Class: Most Serious
Inspection Date: 10/12/2021
Approved Date: 10/18/2021
Original Certify By Date: 11/17/2021
Original Correct By Date: 11/12/2021
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7518262
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE BATHROOM LOCATED AT APT 6M, 6th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date: 10/19/2021
Current Status ID: 2
Current Status: NOV SENT OUT
Current Status Date: 10/19/2021

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 14635870
Building ID: 388518
Registration ID: 304949
Apartment: 6M
Story: 6
Class: Most Serious
Inspection Date: 10/12/2021
Approved Date: 10/18/2021
Original Certify By Date: 11/17/2021
Original Correct By Date: 11/12/2021
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7518262
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) EAST WALL IN THE

SOIL (Continued) **S120702733**

PRIVATE HALLWAY LOCATED AT APT 6M, 6th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date: 10/19/2021
Current Status ID: 2
Current Status: NOV SENT OUT
Current Status Date: 10/19/2021

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 14635871
Building ID: 388518
Registration ID: 304949
Apartment: 6M
Story: 6
Class: Most Serious
Inspection Date: 10/12/2021
Approved Date: 10/18/2021
Original Certify By Date: 11/17/2021
Original Correct By Date: 11/12/2021
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7518262
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL IN THE KITCHEN LOCATED AT APT 6M, 6th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date: 10/19/2021
Current Status ID: 2
Current Status: NOV SENT OUT
Current Status Date: 10/19/2021

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 14635872
Building ID: 388518
Registration ID: 304949
Apartment: 6M
Story: 6
Class: Most Serious
Inspection Date: 10/12/2021
Approved Date: 10/18/2021
Original Certify By Date: 11/17/2021
Original Correct By Date: 11/12/2021
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7518262
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE 1st ROOM FROM EAST AT NORTH LOCATED AT APT 6M, 6th STORY, 2nd

SOIL (Continued) **S120702733**

APARTMENT FROM NORTH AT EAST
NOV Issued Date: 10/19/2021
Current Status ID: 2
Current Status: NOV SENT OUT
Current Status Date: 10/19/2021

Name: Not reported
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 13886990
Building ID: 388518
Registration ID: 304949
Apartment: 6M
Story: 6
Class: Most Serious
Inspection Date: 10/28/2020
Approved Date: 11/10/2020
Original Certify By Date: 12/11/2020
Original Correct By Date: 12/06/2020
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7004024
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE 1st ROOM FROM EAST AT SOUTH LOCATED AT APT 6M, 6th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date: 11/12/2020
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 01/07/2021

A12 **1035 WASHINGTON AVENUE REALTY, LLC.** **NY AST** **U003389647**
SSW **1035 WASHINGTON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.031 mi.
163 ft. **Site 7 of 7 in cluster A**

Relative: **Lower**
Actual: **88 ft.**

AST:
Name: 1035 WASHINGTON AVENUE REALTY, LLC.
Address: 1035 WASHINGTON AVENUE
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-205222
Program Type: PBS
UTM X: 587822.23443
UTM Y: 4502024.76002
Expiration Date: 07/06/2023
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 7174
Affiliation Type: Facility Owner
Company Name: 1035 WASHINGTON REALTY, LLC

1035 WASHINGTON AVENUE REALTY, LLC. (Continued) **U003389647**

Contact Type:	AGENT
Contact Name:	ARTHUR WIENER
Address1:	166 MONTAGUE STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 875-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-08-14

Site Id:	7174
Affiliation Type:	Mail Contact
Company Name:	1035 WASHINGTON REALTY, LLC
Contact Type:	AGENT
Contact Name:	ARTHUR WIENER
Address1:	166 MONTAGUE STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 875-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-08-14

Site Id:	7174
Affiliation Type:	Facility Operator
Company Name:	1035 WASHINGTON AVENUE REALTY, LLC.
Contact Type:	Not reported
Contact Name:	BILAL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 693-9607
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7174
Affiliation Type:	Emergency Contact
Company Name:	1035 WASHINGTON REALTY, LLC
Contact Type:	Not reported
Contact Name:	A. WIENER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

1035 WASHINGTON AVENUE REALTY, LLC. (Continued) **U003389647**

Zip Code:	Not reported
Country Code:	001
Phone:	(718) 875-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	17098
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/31/1932
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

B13 **955 WASHINGTON AVE** **NY Spills** **S102240044**
NW **955 WASHINGTON AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.036 mi.
189 ft. **Site 4 of 7 in cluster B**

Relative:
Higher

Actual:
96 ft.

SPILLS:

Name:	955 WASHINGTON AVE
Address:	955 WASHINGTON AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9602523 / 1996-05-23
Facility ID:	9602523
Facility Type:	ER
DER Facility ID:	61542
Site ID:	63761

955 WASHINGTON AVE (Continued) **S102240044**

DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3101
Spill Date:	1996-05-22
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1996-05-22
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-22
Spill Record Last Update:	1996-06-27
Spiller Name:	Not reported
Spiller Company:	RITE-WAY DEMOLITION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD CLEANED UP BY SPILLER "
Remarks:	"contractor's truck seemed to have a hydraulic hose break causing spill into the gutter. spill is blocked off from going into the seweer. caller notified the epa already.****** updated spiller info ****"

All Materials:

Site ID:	63761
Operable Unit ID:	1033971
Operable Unit:	01
Material ID:	352340
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C14 **MANHOLE 4709** **NY Spills** **S107521229**
South **FRANKLIN AVE NEAR SULLIVAN PLACE** **N/A**
< 1/8 **BROOKLYN, NY**
0.038 mi.
199 ft. **Site 3 of 14 in cluster C**

Relative: SPILLS:
Lower

Name:	MANHOLE 4709
Address:	FRANKLIN AVE NEAR SULLIVAN PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0510798 / 2008-01-10

Actual:
82 ft.

MANHOLE 4709 (Continued) **S107521229**

Facility ID:	0510798
Facility Type:	ER
DER Facility ID:	306892
Site ID:	356839
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-12-15
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-12-15
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-15
Spill Record Last Update:	2008-01-10
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	FRANKLIN AVE/SULLIVAN
Spiller Company:	999
Contact Name:	ERT DESK’
DEC Memo:	"01/10/08 - See eDocs for Con Ed report detailing cleanup and closure. 162254. 12/15/05 - 1238hrs - Peter Franzi #28930 Field Operator FOD reports while working on FDR 4B10 found 1 pt unknown oil on 200 gallons water in M4790. No fire/smoke involved. No sewers or waterways affected. No private property affected. Sample taken marked E priority - chain of custody # DD18923. No parking Tues & Fri 830am to 10am. States structure has been dfaulted # 05240 fdr # unknown at this time. Env. stop tag # 48930 placed. Clean up pending safe access and sample results. cn#19661 "
Remarks:	"CONED # 162254: CLEAN UP PENDING LAB RESULTS: ON 200 GALLONS OF WATER: NO TO 5 QUESTIONS"

All Materials:

Site ID:	356839
Operable Unit ID:	1114133
Operable Unit:	01
Material ID:	2104213
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C15 **CON ED - TM 356** **RCRA NonGen / NLR** **1007206099**
South **SULLIVAN PL & FRANKLIN AVE** **NY MANIFEST** **NYP004003554**
< 1/8 **BROOKLYN, NY 11225**
0.038 mi.
200 ft. **Site 4 of 14 in cluster C**

Relative: **Lower**

Actual: **82 ft.**

RCRA Listings:

Date Form Received by Agency:		19980228
Handler Name:	CON ED - TM 356	
Handler Address:		SULLIVAN PL & FRANKLIN AVE
Handler City,State,Zip:		BROOKLYN, NY 11225-0000
EPA ID:		NYP004003554
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC
Contact City,State,Zip:		NEW YORK, NY 10003-0000
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON ED - TM 356 (Continued) **1007206099**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - TM 356	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - TM 356	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON ED - TM 356 (Continued) **1007206099**

Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED - TM 356
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON CO
Address: SULLIVAN PL & FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225-0000
Country: USA
EPA ID: NYP004003554
Facility Status: Not reported
Location Address 1: FRANKLIN AVENUE V 356
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: Not reported
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004003554
Mailing Name: CONSOLIDATED EDISON CO
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON ED - TM 356 (Continued) **1007206099**

Mailing Phone: 2124602808

C16 **CON EDISON** **NJ MANIFEST** **S120669752**
South **SULLIVAN PL & FRANKLIN AVE NE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.038 mi.
200 ft. **Site 5 of 14 in cluster C**

Relative: **Lower**

Actual: **82 ft.**

NJ MANIFEST:

EPA Id:	NYP004759767
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619098GBF
EPA ID:	NYP004759767
Date Shipped:	3/29/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON (Continued) **S120669752**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C17 **CON EDISON** **RCRA NonGen / NLR** **1018281046**
South **SULLIVAN PL & FRANKLIN AVE NE** **FINDS** **NYP004759767**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.038 mi.
200 ft. **Site 6 of 14 in cluster C**

Relative: **Lower**

Actual: **82 ft.**

RCRA Listings:

Date Form Received by Agency:		20150329
Handler Name:	CON EDISON	
Handler Address:		SULLIVAN PL & FRANKLIN AVE NE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004759767
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

CON EDISON (Continued) **1018281046**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON (Continued) **1018281046**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067686640

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281046
Registry ID:	110067686640
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067686640
Name:	CON EDISON
Address:	SULLIVAN PL & FRANKLIN AVE NE
City,State,Zip:	BROOKLYN, NY 11215

C18 **FRANKLIN ST & SULLIVAN PL** **NY Spills** **S102446835**
South **FRANKLIN ST & SULLIVAN PL** **N/A**
< 1/8 **BROOKLYN, NY**
0.038 mi.
200 ft. **Site 7 of 14 in cluster C**

Relative: **Lower**

Actual: **82 ft.**

SPILLS:

Name:	FRANKLIN ST & SULLIVAN PL
Address:	FRANKLIN ST & SULLIVAN PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9612030 / 2008-03-20
Facility ID:	9612030
Facility Type:	ER
DER Facility ID:	264286
Site ID:	328376
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-01-06
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1997-01-06
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-06
Spill Record Last Update:	2008-03-20
Spiller Name:	TIM SOILCH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	RICHARD ROACH
DEC Memo:	"03/20/08 - See eDocs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks:	"THE CABLE HAD BEEN CUT SPILLING THE OIL - CLEAN UP IN PROGRESS"

All Materials:

Site ID:	328376
Operable Unit ID:	1039899
Operable Unit:	01
Material ID:	340684
Material Code:	0020B
Material Name:	cable oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C19 **CON ED** **NY MANIFEST** **S118088412**
South **SULLIVAN PL & FRANKLIN AVE NE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.038 mi.
200 ft. **Site 8 of 14 in cluster C**

Relative:
Lower

Actual:
82 ft.

NY MANIFEST:

Name:	CON ED
Address:	SULLIVAN PL & FRANKLIN AVE NE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004759767
Facility Status:	Not reported
Location Address 1:	N/E COR FRANKLIN AVE & SULLIVAN PL
Code:	BP
Location Address 2:	MH 4789
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759767
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	04/07/2015
TSD Site Recv Date:	04/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759767
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619098GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118088412**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B20 **961 REALTY LLC** **NY UST** **U004332695**
NNW **961 WASHINGTON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11235**
0.039 mi.
204 ft. **Site 5 of 7 in cluster B**

Relative: **Higher**
Actual: **97 ft.**

UST:

Name:	961 REALTY LLC
Address:	961 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11235
Id/Status:	2-276359 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/12/2026
UTM X:	587794.89698
UTM Y:	4502197.57697
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	11894
Affiliation Type:	Facility Operator
Company Name:	961 REALTY LLC
Contact Type:	Not reported
Contact Name:	DELROY CLEGHORN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 235-5811

961 REALTY LLC (Continued) **U004332695**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-28

Site Id:	11894
Affiliation Type:	Emergency Contact
Company Name:	961 REALTY LLC
Contact Type:	Not reported
Contact Name:	EDWARD SUAZO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 235-6994
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-28

Site Id:	11894
Affiliation Type:	Mail Contact
Company Name:	961 REALTY LLC
Contact Type:	MEMBER
Contact Name:	MEIR BOUSKILA
Address1:	P.O. BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116
Country Code:	001
Phone:	(212) 564-2111
EMail:	CHRISTINA@PINNACLENY.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-11-17

Site Id:	11894
Affiliation Type:	Facility Owner
Company Name:	961 REALTY LLC
Contact Type:	AGENT
Contact Name:	ISAK RADONCIC
Address1:	P.O. BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116
Country Code:	001
Phone:	(212) 564-2111
EMail:	CHRISTINA@PINNACLENY.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-11-18

961 REALTY LLC (Continued) **U004332695**

Tank Info:

Tank Number:	001
Tank ID:	13975
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	04/01/1926
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	10/11/2016
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

C21 **CON EDISON** **NY MANIFEST** **S117317993**
South **998 FRANKLIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11221**
0.047 mi.
246 ft. **Site 9 of 14 in cluster C**

Relative: **Lower**

Actual: **82 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	998 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11221
Country:	USA
EPA ID:	NYP004654778
Facility Status:	Not reported
Location Address 1:	998 FRANKLIN AVE
Code:	BP
Location Address 2:	STRUCTURE # 26243
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11221
Location Zip 4:	Not reported

CON EDISON (Continued) **S117317993**

NY MANIFEST:

EPAID:	NYP004654778
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/11/2014
Trans1 Recv Date:	09/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004654778
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617221GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117317993**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C22 **VICTOR LOGAN COLLISION CORP** **RCRA NonGen / NLR** **1000417748**
SSE **62 SULLIVAN PL** **FINDS** **NYD981184864**
< 1/8 **BROOKLYN, NY 11225** **ECHO**
0.052 mi. **NY MANIFEST**
274 ft. **Site 10 of 14 in cluster C**

Relative: **Lower**
Actual: **79 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	VICTOR LOGAN COLLISION CORP	
Handler Address:		62 SULLIVAN PL
Handler City,State,Zip:		BROOKLYN, NY 11225-2505
EPA ID:		NYD981184864
Contact Name:		Not reported
Contact Address:		SULLIVAN PL
Contact City,State,Zip:		BROOKLYN, NY 11225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		SULLIVAN PL
Mailing City,State,Zip:		BROOKLYN, NY 11225
Owner Name:	VICTOR LOGAN SR	
Owner Type:		Private
Operator Name:	VICTOR LOGAN SR	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

VICTOR LOGAN COLLISION CORP (Continued) **1000417748**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: VICTOR LOGAN SR	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

VICTOR LOGAN COLLISION CORP (Continued) **1000417748**

Owner/Operator Indicator: Owner
Owner/Operator Name: VICTOR LOGAN SR
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: VICTOR LOGAN SR
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: VICTOR LOGAN COLLISION CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: VICTOR LOGAN COLLISION CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: VICTOR LOGAN COLLISION CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

VICTOR LOGAN COLLISION CORP (Continued) **1000417748**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19860226
Handler Name:	VICTOR LOGAN COLLISION CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004402815

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000417748
Registry ID:	110004402815
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004402815
Name:	VICTOR LOGAN COLLISION CORP
Address:	62 SULLIVAN PL
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:
Name: VICTOR LOGAN COLLISION CORP

VICTOR LOGAN COLLISION CORP (Continued) **1000417748**

Address:	62 SULLIVAN PL
City,State,Zip:	BROOKLYN, NY 11225-2505
Country:	USA
EPA ID:	NYD981184864
Facility Status:	Not reported
Location Address 1:	62 SULLIVAN PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981184864
Mailing Name:	VICTOR LOGAN COLLISION CORP
Mailing Contact:	VICTOR LOGAN COLLISION CORP
Mailing Address 1:	62 SULLIVAN PLACE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7186930757

D23 **CON EDISON SERVICE BOX: 28591** **RCRA NonGen / NLR** **1016150227**
East **48 MCKEEVER PL SB 28591** **FINDS** **NYP004288981**
< 1/8 **BROOKLYN, NY 11225** **ECHO**
0.053 mi. **NY MANIFEST**
280 ft. **Site 1 of 4 in cluster D**

Relative: **Lower**

Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	28591
Handler Address:		48 MCKEEVER PL SB 28591
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004288981
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003

CON EDISON SERVICE BOX: 28591 (Continued) **1016150227**

Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20180208
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No

CON EDISON SERVICE BOX: 28591 (Continued) **1016150227**

Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20130213
Handler Name: CON EDISON SERVICE BOX: 28591
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170728
Handler Name: CON EDISON SERVICE BOX: 28591
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055433767

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON SERVICE BOX: 28591 (Continued) **1016150227**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016150227
Registry ID:	110055433767
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055433767
Name:	CON EDISON SERVICE BOX: 28591
Address:	48 MCKEEVER PL SB 28591
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	CON EDISON
Address:	48 MCKEEVER PL SB 28591
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004288981
Facility Status:	Not reported
Location Address 1:	OPP 48 MCKEEVER PL
Code:	BP
Location Address 2:	SERV BOX 43185
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004288981
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/13/2013
Trans1 Recv Date:	02/13/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004288981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON SERVICE BOX: 28591 (Continued) **1016150227**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840436JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D24 **I.S. 320 - BROOKLYN K320** **NY AST** **U003394305**
East **46 MCKEEVER PLACE** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.053 mi.
280 ft. **Site 2 of 4 in cluster D**

Relative:
Lower

Actual:
86 ft.

AST:

Name:	I.S. 320 - BROOKLYN K320
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-355690
Program Type:	PBS
UTM X:	587971.22632
UTM Y:	4502071.38708
Expiration Date:	06/28/2023
Site Type:	School

Affiliation Records:

Site Id:	17737
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION

I.S. 320 - BROOKLYN K320 (Continued) **U003394305**

Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-03

Site Id:	17737
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Site Id:	17737
Affiliation Type:	Facility Operator
Company Name:	I.S. 320 - BROOKLYN K320
Contact Type:	Not reported
Contact Name:	SALVATORE CALDERONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 893-6655
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-09-12

Site Id:	17737
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY

I.S. 320 - BROOKLYN K320 (Continued) **U003394305**

Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-25

Tank Info:

Tank Number:	001
Tank Id:	34719
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/24/1968
Capacity Gallons:	10000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/05/2018
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34720
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating

I.S. 320 - BROOKLYN K320 (Continued) **U003394305**

K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/24/1968
Capacity Gallons:	10000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/05/2018
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)
Tank Number:	003
Tank Id:	274769

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/14/2017
Capacity Gallons:	10000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

D25 **NYC BD OF ED - IS 320K** **RCRA-VSQG** **1005444316**
East **46 MCKEEVER PL** **NY Spills** **NYR000106377**
< 1/8 **BROOKLYN, NY 11225** **NY LEAD**
0.053 mi. **NY MANIFEST**
280 ft. **Site 3 of 4 in cluster D**

Relative: **Lower**
Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	NYC BD OF ED - IS 320K	
Handler Address:		46 MCKEEVER PL
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYR000106377
Contact Name:		BERNARD ORLAN
Contact Address:		QUEENS PLZ N
Contact City,State,Zip:		LONG ISLAND CITY, NY 11101
Contact Telephone:		718-391-6475
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Municipal
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		QUEENS PLZ N
Mailing City,State,Zip:		LONG ISLAND CITY, NY 11101
Owner Name:	NYC BOARD OF EDUCATION	
Owner Type:		Municipal
Operator Name:	NYC BOARD OF EDUCATION	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

NYC BD OF ED - IS 320K (Continued) **1005444316**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC BOARD OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2811 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-391-6475
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC BOARD OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	20010101

NYC BD OF ED - IS 320K (Continued) **1005444316**

Date Ended Current: Not reported
Owner/Operator Address: 2811 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6475
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 2811 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6475
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - IS 320K
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - IS 320K
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020517
Handler Name: NYC BD OF ED - IS 320K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

NYC BD OF ED - IS 320K (Continued) **1005444316**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20150316
Actual Return to Compliance Date: 20150916
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150416
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYCMK
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20150316
Actual Return to Compliance Date: 20150916
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150416
Enforcement Responsible Agency: State

NYC BD OF ED - IS 320K (Continued) **1005444316**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYCMK
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20150316
Actual Return to Compliance Date: 20150506
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150416
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYCMK
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

NYC BD OF ED - IS 320K (Continued) **1005444316**

SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20150316
Actual Return to Compliance Date: 20150916
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150416
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYCMK
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20150316
Actual Return to Compliance Date: 20150916
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150416
Enforcement Responsible Agency: State

NYC BD OF ED - IS 320K (Continued) **1005444316**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYCMK
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20150316
Actual Return to Compliance Date: 20150909
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150416
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYCMK
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

NYC BD OF ED - IS 320K (Continued) **1005444316**

SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150506
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported

NYC BD OF ED - IS 320K (Continued) **1005444316**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150909
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SPILLS:

Name:	SCHOOL
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2101518 / 2021-09-13
Facility ID:	2101518
Facility Type:	ER
DER Facility ID:	566842
Site ID:	619234
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2021-05-18
Investigator:	AAOBLIGA
Referred To:	Not reported
Reported to Dept:	2021-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

NYC BD OF ED - IS 320K (Continued) **1005444316**

Remediation Phase:	0
Date Entered In Computer:	2021-05-19
Spill Record Last Update:	2021-09-13
Spiller Name:	Not reported
Spiller Company:	NYC SCHOOL CONSTRUCTION AUTHORITY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JENNA RAUP
DEC Memo:	"5/19/21 - Obligado - Desk Duty - There was a temporary boiler with a 10,000 gallon AST in the street. Once of the valves was leaking. It was a slow leak that they noticed yesterday morning. Easco went yesterday to clean and they will do more today. The repair of the valve has been completed. Jenn of NYCSCA will send me email with pictures documenting the work. According to Jenn no drains were impacted."
Remarks:	"Clean-up pending."

All Materials:

Site ID:	619234
Operable Unit ID:	1366410
Operable Unit:	01
Material ID:	2379041
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	46 MCKEEVER PLACE
Address:	46 MCKEEVER PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9302528 / 1993-05-25
Facility ID:	9302528
Facility Type:	ER
DER Facility ID:	114686
Site ID:	133241
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1993-05-25
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1993-05-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Vessel
Spill Notifier:	Other
Cleanup Ceased:	1993-05-25
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

NYC BD OF ED - IS 320K (Continued) **1005444316**

Date Entered In Computer:	1993-05-25
Spill Record Last Update:	1993-07-19
Spiller Name:	Not reported
Spiller Company:	PUB. SCHOOL 320.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG. "
Remarks:	"FUEL LEAKED DUE TO FAULTY PLUMBING- DRIVER WASN'T NOTIFIED OF PROBLEM UNTIL OFTER SPILL OCCURRED. DRIVER CUSTODIAN CLEANED SPILL-NYC DEP TO BE NOTIFIED."

All Materials:

Site ID:	133241
Operable Unit ID:	980857
Operable Unit:	01
Material ID:	399650
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LEAD 2:

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	103
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	106
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	108

NYC BD OF ED - IS 320K (Continued) **1005444316**

Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	114
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	116
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	118
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	120
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	126
Deteriorated Paint:	NO
Presence of LBP:	NA

NYC BD OF ED - IS 320K (Continued) **1005444316**

Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: 128
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: 135
Deteriorated Paint: YES
Presence of LBP: NO
Stabilization Required: NO
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: 214B
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: 224/226
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: 229
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

NYC BD OF ED - IS 320K (Continued) **1005444316**

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: 231
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: AUD
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: C-15
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: C-17
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 375 - BROOKLYN
Address: 46 MCKEEVER PLACE
City,State,Zip: BROOKLYN, NY
Geographical District: 17
Building Code: K320
Room: cafe
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

NY MANIFEST:
Name: NYC BOARD OF EDUCATION

NYC BD OF ED - IS 320K (Continued) **1005444316**

Address:	46 MCKEEVER PL
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYR000106377
Facility Status:	Not reported
Location Address 1:	46 MCKEEVER PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000106377
Mailing Name:	NYC BOARD OF EDUCATION
Mailing Contact:	N/S
Mailing Address 1:	46 MCKEEVER PL
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189414514

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD986938645
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/2014
Trans1 Recv Date:	12/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000106377
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAC300017498
TSDF ID 2:	Not reported
Manifest Tracking Number:	002581461GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141

NYC BD OF ED - IS 320K (Continued) **1005444316**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	31
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C26 **MAZE AUTO REPAIR INC.** **NY AST** **A100304628**
SE **66 SULLIVAN PLACE** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.054 mi.
283 ft. **Site 11 of 14 in cluster C**

Relative:
Lower

Actual:
79 ft.

AST:

Name:	MAZE AUTO REPAIR INC.
Address:	66 SULLIVAN PLACE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610606
Program Type:	PBS
UTM X:	588020.07070
UTM Y:	4501999.53547
Expiration Date:	07/06/2022
Site Type:	Other

Affiliation Records:

Site Id:	383960
Affiliation Type:	Facility Owner
Company Name:	DAVE BALCOMB
Contact Type:	PRESIDENT/OWNER
Contact Name:	DAVE BALCOMBE
Address1:	66 SULLIVAN PLACE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 221-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-09-13

MAZE AUTO REPAIR INC. (Continued) **A100304628**

Site Id:	383960
Affiliation Type:	Mail Contact
Company Name:	MAZE AUTO REPAIR INC.
Contact Type:	Not reported
Contact Name:	DAVE BALCOMB
Address1:	66 SULLIVAN PLACE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 221-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-07-06

Site Id:	383960
Affiliation Type:	Facility Operator
Company Name:	MAZE AUTO REPAIR INC.
Contact Type:	Not reported
Contact Name:	DAVE BALCOMB
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 221-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-07-06

Site Id:	383960
Affiliation Type:	Emergency Contact
Company Name:	DAVE BALCOMB
Contact Type:	Not reported
Contact Name:	DAVE BALCOMB
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 221-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-07-06

Tank Info:

Tank Number:	001
Tank Id:	218174
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

MAZE AUTO REPAIR INC. (Continued) **A100304628**

Equipment Records:

D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I01 - Overfill - Float Vent Valve
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/20/2004
Capacity Gallons:	200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

C27 **CON ED** **NY MANIFEST** **S118088413**
South **1028 FRANKLIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11210**
0.055 mi.
289 ft. **Site 12 of 14 in cluster C**

Relative: **Lower**
Actual: **81 ft.**

NY MANIFEST:

Name:	CON ED
Address:	1028 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11210
Country:	USA
EPA ID:	NYP004759775
Facility Status:	Not reported
Location Address 1:	OPP 1028 FRANKLIN AVE
Code:	BP
Location Address 2:	MH 26244
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759775
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported

CON ED (Continued) **S118088413**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	04/07/2015
TSD Site Recv Date:	04/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759775
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619099GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C28 **CON EDISON** **NJ MANIFEST** **S120669753**
South **1028 FRANKLIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11210**
0.055 mi.
289 ft. **Site 13 of 14 in cluster C**

Relative:
Lower

Actual:
81 ft.

NJ MANIFEST:

EPA Id:	NYP004759775
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619099GBF
EPA ID:	NYP004759775
Date Shipped:	3/29/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120669753**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C29 **CON EDISON** **RCRA NonGen / NLR** **1018281047**
South **1028 FRANKLIN AVE** **FINDS** **NYP004759775**
< 1/8 **BROOKLYN, NY 11210** **ECHO**
0.055 mi.
289 ft. **Site 14 of 14 in cluster C**

Relative: **Lower**
Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:		20150329
Handler Name:	CON EDISON	
Handler Address:		1028 FRANKLIN AVE
Handler City,State,Zip:		BROOKLYN, NY 11210
EPA ID:		NYP004759775
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1018281047**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150329
Handler Name: CON EDISON	

CON EDISON (Continued) **1018281047**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067686659

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281047
Registry ID:	110067686659
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067686659
Name:	CON EDISON
Address:	1028 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11210

E30 **CON EDISON** **RCRA NonGen / NLR** **1018281055**
SSW **SULLIVAN PL & WASHINGTON AVE** **FINDS** **NYP004759858**
< 1/8 **BROOKLYN, NY 11215** **ECHO**
0.055 mi.
289 ft. **Site 1 of 10 in cluster E**

Relative: **Lower**
Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:	20150329
Handler Name:	CON EDISON
Handler Address:	WASHINGTON AVE & SULLIVAN PL
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004759858

CON EDISON (Continued) **1018281055**

Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No

CON EDISON (Continued) **1018281055**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON (Continued) **1018281055**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067686739

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018281055
Registry ID:	110067686739
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067686739
Name:	CON EDISON
Address:	SULLIVAN PL & WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY 11215

E31 **MANHOLE # M4785** **NY Spills** **S107409409**
SSW **WASHINGTON AVE AND SULLIVAN PLACE** **N/A**
< 1/8 **BROOKLYN, NY**
0.055 mi.
289 ft. **Site 2 of 10 in cluster E**

Relative:
Lower

Actual:
81 ft.

SPILLS:

Name:	MANHOLE # M4785
Address:	WASHINGTON AVE AND SULLIVAN PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0508015 / 2005-12-01
Facility ID:	0508015
Facility Type:	ER
DER Facility ID:	300869
Site ID:	353528
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-10-02
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-10-04
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

MANHOLE # M4785 (Continued) **S107409409**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-04
Spill Record Last Update:	2005-12-01
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	ERT DESK'
DEC Memo:	"161330. 10-2-2005 04:00 HRS R. LAROCCO #76043 FOD REPORTS FINDING APPROX 2 QTS OF UNKNOWN OIL ON CONCRETE IN M4785. THIS WAS FOUND WHILE ATTEMPTING TO CHECK FOR ENDS ON DEAD FDR 25811 ON ACCT# C3244. THERE WAS NO SMOKE, FIRE, OR INJURIES RELATED TO THE SPILL, NOR WERE ANY SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. THE SOURCE AND CAUSE OF THE SPILL IS UNKNOWN. THERE DID NOT APPEAR TO BE ANY SUMPS, DRAINS, OR SEWER CONNECTIONS IN THE STRUCTURE. ENV STOP TAG# 31434 WAS PLACED AND ONE LIQUID SAMPLE TAKEN ON E PRIORITY FOR PCB ANALYSIS ON CHAIN OF CUSTODY#DD03521. THE SAMPLE WILL BE TAKEN TO CHEM LAB BY MR LAROCCO, AND CLEANUP IS PENDING LAB RESULTS. J ANDERSON UPDATE 02-OCT-2005 12:43 HRS. LSN-05-10310-001 MATRIX : OIL GRAB 68 PPM C.HOGAN 07511 10/02/2005 17:00 HRS. -- BROOKLYN ENV OPS SUPERVISOR B. BAMONTE ON LOCATION AND REPORTS UNABLE TO CLEAN STRUCTURE AS THIS TIME DUE TO FIVE CARS THAT WOULD NEED TO BE MOVED, INCLUDING TWO WITH OUT-OF-STATE LICENSE PLATES. HE WILL SCHEDULE CLEANUP FOR MORNING OF TUE. 10/04/2005, WHEN PARKING RESTRICTIONS ARE IN EFFECT. INCIDENT TO REMAIN ON 72-HOUR DEMINIMIS. -- W.W. Update - 10/3/05 1330hrs. A. Walker OS reports there is still a car on hole with out of town plates. No access at this time. cn#19661 Order >50 tanker for 7am 10/4/05 as per B. Bamonte. cn#19661 update 10-4-05 1016hrs. flush operations supv e. williams requesting no. 9, however will see if u.g. crew on location will assist him. borchrdingc UPDATE 10-4-05 1044HRS. FLUSH OPERATIONS SUPERVISOR E. WILLIAMS UNABLE TO COORDINATE W/ UNDERGROUND ON LEAKING JOINT. REQUESTING NO. 9 . REFERRED TO BROOKLYN FLUSH DISPATCHER, TO ARRANGE MEET W/FLUSH TRUCK ON LOCATION. BORCHERDINGC UPDATE OCT 04-05 1715HRS. FLUSH OPERATIONS MECHANIC D. WILLIAMS, EMPLOYEE NO 82580 REPORTS AN OPEN DRAIN IN STRUCTURE. SUPV. ON LOCATION. TO BE TAKEN OFF THE ENVIRONMENTAL 72HR CLOCK. BORCHERDINGC Closed. 12-01-05. see eDocs. GB "
Remarks:	"2 quarts of material spilled onto concrete in the manhole. clean up is complete. ConEd#161330 No to the after hours questions."

All Materials:

Site ID:	353528
Operable Unit ID:	1110986
Operable Unit:	01
Material ID:	2101025
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E32 **CON EDISON** **RCRA NonGen / NLR** **1018281056**
SSW **SULLIVAN PL & WASHINGTON AVE** **NYP004759866**
< 1/8 **BROOKLYN, NY 11215**
0.055 mi.
289 ft. **Site 3 of 10 in cluster E**

Relative: **Lower**
Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:		20150329
Handler Name:	CON EDISON	
Handler Address:		SULLIVAN PL & WASHINGTON AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004759866
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018281056**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150329
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018281056**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E33 **CON EDISON** **NJ MANIFEST** **S120669761**
SSW **WASHINGTON AVE & SULLIVAN PL** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.055 mi.
289 ft. **Site 4 of 10 in cluster E**

Relative:
Lower

Actual:
81 ft.

NJ MANIFEST:

EPA Id:	NYP004759858
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619096GBF
EPA ID:	NYP004759858
Date Shipped:	3/29/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120669761**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

E34 **CON ED** **NY MANIFEST** **S118088422**
SSW **SULLIVAN PL & WASHINGTON AVE** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.055 mi.
289 ft. **Site 5 of 10 in cluster E**

Relative: **Lower**
Actual: **81 ft.**

NY MANIFEST:

Name:	CON ED
Address:	SULLIVAN PL & WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004759866
Facility Status:	Not reported
Location Address 1:	N/S SULLIVAN PL 95’ E WASHINGTON AVE
Code:	BP
Location Address 2:	SB 42064
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759866
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON ED (Continued) **S118088422**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	04/07/2015
TSD Site Recv Date:	04/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759866
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619100GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E35
SSW
< 1/8
0.055 mi.
289 ft.

CON EDISON
SULLIVAN PL & WASHINGTON AVE
BROOKLYN, NY 11215

Site 6 of 10 in cluster E

NJ MANIFEST **S120669762**
N/A

Relative:
Lower

Actual:
81 ft.

NJ MANIFEST:

EPA Id:	NYP004759866
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619100GBF
EPA ID:	NYP004759866
Date Shipped:	3/29/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120669762**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

E36 **SPILL NUMBER 9812071** **NY Spills** **S104648382**
SSW **SULLIVAN PL & WASHINGTON** **N/A**
< 1/8 **BROOKLYN, NY**
0.055 mi.
289 ft. **Site 7 of 10 in cluster E**

Relative: SPILLS:
Lower

Actual:
81 ft.

Name:	SPILL NUMBER 9812071
Address:	SULLIVAN PL & WASHINGTON
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9812071 / 2003-02-20
Facility ID:	9812071
Facility Type:	ER
DER Facility ID:	175831
Site ID:	212176
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-12-28
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1998-12-28
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-28
Spill Record Last Update:	2003-02-24
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mmis 122140 28-DEC-1998 1115HRS HOBART 84060 O/S UNDERGROUND REPORTS FOUND 3 GALLONS UNKNOWN OIL ON 1GAL OF WATER IN MH4783 SAMPLE TAKEN AND TAG #11646 HUNG. NO SEWERS OR WATERWAYS AFFECTED IT IS CONTAINED. 4 TO 6 HR TURNAROUND. FOUND WHILE DOING INSPECTION.CIG NOTIFIED JR78448 UPDATE:28-DEC-1998 1629HRS LAB RESULTS BACK 137 PPM LAB SEQUENCE #98-14342 JR78448 UPDATE: 12/28/98-17:30HRS-EPA#NYP004034146-TANKER ORDERED FOR A.M 12/29/98 BY D. HERBST. WILL VERIFY TANKER READY IN A.M 12/29/98 JAP-56037 UPDATE - 12/29/98 2135 HRS - HOWELL, FLUSH SUPERVISOR ADVISED CLEAN UP

SPILL NUMBER 9812071 (Continued) **S104648382**

COMPLETE AS OF 2115HRS. THEY DOUBLED WASHED STRUCTURE WITH SLIX. FLUSH OPERATOR WAS D. BANKHEAD #64999. STOP TAG WAS REMOVED. WHILE CLEANING FOUND A 3 DRAIN IN STRUCTURE WHICH WAS INACTIVE. NOTHING FLOWED THROUGH. THIS DRAIN WAS CLEANED AND SEALED. ****NOTE EARLIER IN THE DAY UG HAD REMOVED 5 LINEAR FEET OF ARC PROOFING FROM THIS SITE WHICH WAS DRUMMED AND LABELED. TOTAL OF 3 DRUMS OF SOLID DEBRIS IS BEING PICKED UP BY TANKER TODAY. MEN ON LOCATION WAITING PICK UP.====C. NEVILLE 19661========== UPDATE 12/30/98 0100HRS - BARRELS WERE PICKED UP FROM SITE ---JOB COMPLETED---C NEVILLE 19661========== 50 - 499 PPM CLEANUP PAPERWORK RETAINED WITH ENV. OPS. INCIDENT IS CLOSED."

Remarks: "MANHOLE #4783. THREE GALLONS OF UNKNOWN OIL ON ONE GALLON OF WATER. CONTAINED WITHIN THE MANHOLE. SAMPLES TAKNE. CLEAN UP PENDING TEST RESULTS. CON EDISON REFERENCE NUMBER 122140."

All Materials:

Site ID:	212176
Operable Unit ID:	1072707
Operable Unit:	01
Material ID:	312351
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

E37 **CON ED** **NY MANIFEST** **S118088421**
SSW **WASHINGTON AVE & SULLIVAN PL** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.055 mi.
289 ft. **Site 8 of 10 in cluster E**

Relative: **Lower**
Actual: **81 ft.**

NY MANIFEST:

Name:	CON ED
Address:	WASHINGTON AVE & SULLIVAN PL
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004759858
Facility Status:	Not reported
Location Address 1:	EAST INT. SULLIVAN PL & WASHINGTON AVE
Code:	BP
Location Address 2:	MH 4783
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004759858
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported

CON ED (Continued) **S118088421**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/29/2015
Trans1 Recv Date:	03/29/2015
Trans2 Recv Date:	04/07/2015
TSD Site Recv Date:	04/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004759858
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619096GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D38 **CON EDISON SERVICE BOX: 28592** **RCRA NonGen / NLR** **1016150211**
East **47 MCKEEVER PL SB 28592** **FINDS** **NYP004288825**
< 1/8 **BROOKLYN, NY 11225** **ECHO**
0.060 mi. **NY MANIFEST**
319 ft. **Site 4 of 4 in cluster D**

Relative: **Lower**
Actual: **85 ft.**

RCRA Listings:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON SERVICE BOX:	28592
Handler Address:		47 MCKEEVER PL SB 28592
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004288825
Contact Name:		JUAN RODRIGUEZ
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		347-865-5931
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		OPERATING SUPERVISOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 28592 (Continued) **1016150211**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20180208
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130213
Handler Name: CON EDISON SERVICE BOX:	28592
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON SERVICE BOX:	28592
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON SERVICE BOX: 28592 (Continued) **1016150211**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055431527

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016150211
Registry ID:	110055431527
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055431527
Name:	CON EDISON SERVICE BOX: 28592
Address:	47 MCKEEVER PL SB 28592
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	CON EDISON
Address:	47 MCKEEVER PL SB 28592
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004288825
Facility Status:	Not reported
Location Address 1:	OPP 47 MCKEEVER PL
Code:	BP
Location Address 2:	SERV BOX 28592
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004288825
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON SERVICE BOX: 28592 (Continued) **1016150211**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/13/2013
Trans1 Recv Date:	02/13/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004288825
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010840360JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B39 **941 WASHINGTON AVENUE LLC** **NY AST** **U003390126**
NNW **941 WASHINGTON AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.061 mi.
321 ft. **Site 6 of 7 in cluster B**

Relative:
Higher

Actual:
102 ft.

AST:

Name:	941 WASHINGTON AVENUE LLC
Address:	941 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-312045
Program Type:	PBS
UTM X:	587786.26408
UTM Y:	4502250.46561
Expiration Date:	02/28/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14325
Affiliation Type:	Facility Owner
Company Name:	941 WASHINGTON AVENUE LLC
Contact Type:	AGENT
Contact Name:	RYAN VILLARRUEL
Address1:	120 WEST 31ST STREET, 6TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 947-0007
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Site Id:	14325
Affiliation Type:	Facility Operator
Company Name:	941 WASHINGTON AVENUE LLC
Contact Type:	Not reported
Contact Name:	RYAN VILLARRUEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 315-0872
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Site Id:	14325
Affiliation Type:	Mail Contact
Company Name:	941 WASHINGTON AVENUE LLC
Contact Type:	Not reported
Contact Name:	RYAN VILLARRUEL

941 WASHINGTON AVENUE LLC (Continued) **U003390126**

Address1:	C/O SAFEGUARD REALTY MANAGEMENT INC.
Address2:	120 WEST 31ST STREET, 6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(646) 448-0826
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Site Id:	14325
Affiliation Type:	Emergency Contact
Company Name:	941 WASHINGTON AVENUE LLC
Contact Type:	Not reported
Contact Name:	BENNY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 315-0872
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Tank Info:

Tank Number:	001
Tank Id:	18396
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K00 - Spill Prevention - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1961
Capacity Gallons:	5000

941 WASHINGTON AVENUE LLC (Continued) **U003390126**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

B40 **CON EDISON** **NY MANIFEST** **S117536339**
NNW **104 MONTGOMERY ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.061 mi.
324 ft. **Site 7 of 7 in cluster B**

Relative:
Higher

Actual:
101 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	104 MONTGOMERY ST
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP004688040
Facility Status:	Not reported
Location Address 1:	104 MONTGOMERY ST
Code:	BP
Location Address 2:	STRUCTURE 30666
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004688040
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2014
Trans1 Recv Date:	10/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004688040

CON EDISON (Continued) **S117536339**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416883GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F41 **GARDEN CLEANERS** **NY DRYCLEANERS** **S110246668**
NNW **96 MONTGOMERY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.065 mi.
344 ft. **Site 1 of 11 in cluster F**

Relative: **Higher**

Actual: **102 ft.**

DRYCLEANERS:

Name:	GARDEN CLEANERS
Address:	96 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Facility ID:	2-6104-00816
Phone Number:	NOT LISTED
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	2003-11-19 00:00:00
Install Date:	94/03
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

F42 **GARDEN CLEANING** **EDR Hist Cleaner** **1018429970**
NNW **96 MONTGOMERY ST** **N/A**
< 1/8 **NEW YORK - BROOKLYN, NY 11225**
0.065 mi.
344 ft. **Site 2 of 11 in cluster F**

Relative: EDR Hist Cleaner
Higher

Actual: **102 ft.**

Year:	Name:	Type:
1986	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1987	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1988	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1989	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1990	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1991	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1992	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1993	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1994	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1995	GARDEN CLEANING	Garment Pressing And Cleaners' Agents
1996	GARDEN CLEANING	Garment Pressing And Cleaners' Agents

F43 **GARDEN CLEANERS** **RCRA NonGen / NLR** **1000186370**
NNW **96 MONTGOMERY ST** **FINDS** **NYD982529182**
< 1/8 **BROOKLYN, NY 11225** **ECHO**
0.065 mi. **NY MANIFEST**
344 ft. **Site 3 of 11 in cluster F**

Relative: RCRA Listings:
Higher

Actual: **102 ft.**

Date Form Received by Agency:		20070101
Handler Name:	GARDEN CLEANERS	
Handler Address:		96 MONTGOMERY ST
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYD982529182
Contact Name:		Not reported
Contact Address:		MONTGOMERY ST
Contact City,State,Zip:		BROOKLYN, NY 11225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		MONTGOMERY ST
Mailing City,State,Zip:		BROOKLYN, NY 11225
Owner Name:	GARDEN CLEANERS	
Owner Type:		Private
Operator Name:	GARDEN CLEANERS	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No

GARDEN CLEANERS (Continued) **1000186370**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001

GARDEN CLEANERS (Continued) **1000186370**

Waste Description: IGNITABLE WASTE

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: GARDEN CLEANERS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: GARDEN CLEANERS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: GARDEN CLEANERS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950426
Handler Name: GARDEN CLEANERS	

GARDEN CLEANERS (Continued) **1000186370**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: GARDEN CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: GARDEN CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19880216
Handler Name: GARDEN CLEANERS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

GARDEN CLEANERS (Continued) **1000186370**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004421144

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000186370
Registry ID:	110004421144
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004421144
Name:	GARDEN CLEANERS
Address:	96 MONTGOMERY ST
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	GARDEN CLNRS
Address:	96 MONTGOMERY ST
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYD982529182
Facility Status:	Not reported
Location Address 1:	86 MONTGOMERY ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982529182
Mailing Name:	GARDEN CLNRS
Mailing Contact:	GARDEN CLNRS
Mailing Address 1:	86 MONTGOMERY STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11225
Mailing Zip 4:	Not reported

GARDEN CLEANERS (Continued) **1000186370**

Mailing Country: USA
Mailing Phone: 7180000000

F44
NNW
< 1/8
0.069 mi.
365 ft.

MANHOLE 1135
MONTGOMERY ST/WASHINGTON
BROOKLYN, NY

Site 4 of 11 in cluster F

NY Spills **S104790428**
N/A

Relative:
Higher

Actual:
104 ft.

SPILLS:

Name:	MANHOLE 1135
Address:	MONTGOMERY ST/WASHINGTON
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0008062 / 2002-04-05
Facility ID:	0008062
Facility Type:	ER
DER Facility ID:	227153
Site ID:	279728
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-10-10
Investigator:	OKWUOHA
Referred To:	Not reported
Reported to Dept:	2000-10-10
CID:	382
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-10
Spill Record Last Update:	2002-04-05
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	BRIAN JOYCE
DEC Memo:	""
Remarks:	"oil on 200 gals of water contained in manhole. leak from transformer. clean up in progress. con ed 133-858"

All Materials:

Site ID:	279728
Operable Unit ID:	830520
Operable Unit:	01
Material ID:	545583
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00

MANHOLE 1135 (Continued) **S104790428**

Units: G
Recovered: .00
Oxygenate: Not reported

45
NNE
< 1/8
0.071 mi.
377 ft.

GOLOMBECKS METHYL BROMIDE **NY Spills** **S102671103**
MONTGOMERY AV & FRANKLIN **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
98 ft.

SPILLS:
Name: GOLOMBECKS METHYL BROMIDE
Address: MONTGOMERY AV & FRANKLIN
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8602323 / 1986-07-09
Facility ID: 8602323
Facility Type: ER
DER Facility ID: 132357
Site ID: 156377
DEC Region: 2
Spill Cause: Other
Spill Class: Not reported
SWIS: 2401
Spill Date: 1986-07-09
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 1986-07-09
CID: Not reported
Water Affected: NONE
Spill Source: Commercial Vehicle
Spill Notifier: Local Agency
Cleanup Ceased: 1986-07-09
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1986-07-09
Spill Record Last Update: 2002-02-26
Spiller Name: Not reported
Spiller Company: MORRIS GOLOMBECK,INC
Spiller Address: 960 FRANKLIN ST
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was "
Remarks: "GOLOMBECK FUMIGATED TRILER W/HOT PEPERS OUT ON STREET-FUMIGANT WAS METHYL BROMIDE(98%) NYCDOT PD DISCOVERED TRAILER AND CALLED EMER. RESPONS"

All Materials:
Site ID: 156377
Operable Unit ID: 899715
Operable Unit: 01
Material ID: 478776
Material Code: 0096A
Material Name: methyl bromide
Case No.: 00074839

GOLOMBECKS METHYL BROMIDE (Continued) **S102671103**

Material FA:	Hazardous Material
Quantity:	6.00
Units:	L
Recovered:	6.00
Oxygenate:	Not reported

F46 **LOT 50,TAXBLOCK 1190** **NY E DESIGNATION** **S123676950**
North **135 MONTGOMERY STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.083 mi.
439 ft. **Site 5 of 11 in cluster F**

Relative: **Higher**
Actual: **93 ft.**

E DESIGNATION:

Name:	LOT 50,TAXBLOCK 1190
Address:	135 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	50
Tax Block:	1190
Borough Code:	Not reported
E-No:	E-405
Effective Date:	12/20/2018
Satisfaction Date:	Not reported
Ceqr Number:	17DCP067K
Ulurp Number:	180347ZMK, 180348ZRK180347ZMK, 180348ZRK
Zoning Map No:	16d
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

F47 **EXCAVATION SITE** **NY Spills** **S122478841**
NNW **109 MONTGOMERY ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.087 mi.
457 ft. **Site 6 of 11 in cluster F**

Relative: **Higher**
Actual: **104 ft.**

SPILLS:

Name:	EXCAVATION SITE
Address:	109 MONTGOMERY ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1801903 / 2018-12-20
Facility ID:	1801903
Facility Type:	ER
DER Facility ID:	523669
Site ID:	570453
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2018-05-18

EXCAVATION SITE (Continued) **S122478841**

Investigator:	HSSEKHON
Referred To:	Not reported
Reported to Dept:	2018-05-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-05-18
Spill Record Last Update:	2018-12-20
Spiller Name:	FRANK GOLDING
Spiller Company:	UNKNOWN
Spiller Address:	109 MONTGOMERY ST
Spiller Company:	999
Contact Name:	FRANK GOLDING
DEC Memo:	"05/21/18-Hiralkumar Patel. alternate address: 109-111 Montgomerty Street no PBS or other spills found. as per NYCDOB records, a permit application was approved on 06/12/2015 for construction of a new 12-story residential building. 10:16 AM:- spoke with Mr. Norets, project manager for site's redevelopment. he mentioned that Frank Galdun from GCI Env. will handle environmental issues at the site and letter should be sent to the attention of Aaron Lemma. 109 Montgomery Owner LLC. **property owner** c/o LIVWRK 55 Prospect Street, 4th Floor Brooklyn NY, 11201 Attn.: Aaron Lemma PH. (212) 531-4100 Ext. 102 (212) 205-1432 email: aaron@livwrk.com Val Norets Top Rock Development & Construction PH. (212) 205-1433 (917) 406-0844 (C) email: valn@toprock-ny.com 10:25 AM:- received call from Frank. he mentioned that a multi-story apartment building with a basement is being built at the site. entire site will be excavated down to a depth of 18 ft bg for foundation. 2/3rd of the site has been excavated to proposed foundation depth. during further excavation, crew noted some gasoline odors in soil. Frank conducted subsurface investigation via few borings and collected soil samples. only one sampled showed minor detection of VOCs, but bottom samples from all borings were non-detect. property owner has conducted Phase I and Phase II reports prior to beginning the project. asked Frank to submit all reports for review. 10:37 AM:- received email from Frank including copy of subsurface investigation report. 11:05 AM:- received email from Frank including links to Phase I (two reports dated 08/11/14 and 03/04/15) and Phase II (dated 06/26/15) reports. as per Sanborn maps, two gasoline tanks were located in the southwestern corner of the site from at least 1932 until sometime prior to 1965, and municipal records indicate that a gas tank and pump were installed at the property in 1966. also an oil storage structure was present on the northern portion of the site dating to circa 1908. summary of Phase II report dated 06/26/15: - total of eight (8) soil borings (AEI-SB1 through AEI-SB8) were installed - boring AEI-SB1 was installed, near the suspect oil storage structure, to depth of 6 ft bg where refusal encountered. no PID readings or odors noted - boring AEI-SB2 was installed, near center of building, to depth of 12 ft bg. only PID reading (of 20 ppm) recorded at the end of boring - boring AEI-SB3 was installed, near center of

EXCAVATION SITE (Continued) **S122478841**

building, to depth of 12 ft bg. more than 10 ppm recorded on PID below 9 ft depth, with max. of 64.6 ppm at 10 ft bg - boring AEI-SB4 was installed, in southeast corner of the property, to depth of 12 ft bg. strong petroleum odors and high PID readings (100.6 to 188.7 ppm; highest at end of boring) were recorded below 10 ft depth ---------- - boring AEI-SB5 was installed, to the west of the former USTs, to depth of 7 ft bg where refusal encountered. no PID readings or odors noted - boring AEI-SB6 was installed, to the east of the former USTs, to depth of 7.5 ft bg were refusal encountered. no PID readings or odors noted - boring AEI-SB7 was installed, in former auto repair area, to depth of 9 ft bg. less than 1 ppm recorded on PID except at 1 ft bg (17.7 ppm) and 5 ft bg (6.9 ppm) - boring AEI-SB8 was installed, in former auto repair area, to depth of 8 ft bg where refusal encountered. no PID readings or odors noted - groundwater was not encountered in the borings - sediment encountered in each of the boring generally consisted of red brown sandy silty with some sub-rounded gravel - one soil sample was collected at the end of each soil boring - found contamination in sample from boring AEI-SB4 soil analyticals: ----------AEI-SB4 11.5-12 ft Toluene----------680 Ethylbenzene----------4,600 Xylene----------16,000 1,2,4-Trimethylbenzene---21,000 1,3,5-Trimethylbenzene----7,100 summary of subsurface investigation report dated 05/18/18: - site elevation is approx. 100-110 ft above mean sea level - as per USGS maps, depth to water at the site is estimated to be 89 ft bg ---------- - at least 2/3rd of the site has already been excavated for redevelopment and its southern section remains largely untouched - seven (7) soil borings (B1 through B7) were installed at the southern section of the site, to a depth of 20 ft bg except boring B3 which was installed to a depth of 12 ft bg due to refusal - gasoline odors were detected in several of the borings - total of twelve (12) soil samples were collected: two from borings B1, B2, B4, B5 and B6; and one from borings B3 and B7 soil analyticals: ----------B1 13 ft Ethylbenzene----------2,300 Xylene----------6,900 1,2,4-Trimethylbenzene----12,000 1,3,5-Trimethylbenzene-----8,400 Naphthalene----------3,600 12:08 PM:- spoke with Frank. informed him that based on review of available information, the Department requires collection/analysis of endpoint samples after removal of petroleum contaminated soil. suggested him to submit endpoint sample results for review prior to foundation pouring. Frank mentioned that vapor barrier will be installed beneath the new building. 12:57 PM:- sent letter to Mr. Lemma requiring endpoint sampling and submission of site redevelopment plan (including vapor mitigation details). asked him to submit report by the end of 06/29/18. letter emailed to Mr. Lemma, Mr. Norets, Frank and DEC DeMeo. case assigned to DEC DeMeo. 5/24/18 TJD Spill reassigned to DEC (Sekon). 10/23/18 - Sekhon Closure report submitted. Discussed with DEC Kumar. DECDOCs 12/18 Sekhon Foundation construction and assembly of the building superstructure is complete. vapor barrier has been installed under the basement floor. Basement floor thickness is six inches thick at minimum and consists of poured concrete. Basement perimeter/foundation poured concrete foundation walls are one-foot thick and impermeable waterproofing has been applied to the exterior sides of all foundation walls. As indicated in closure report, a single post-excavation soil sample was reported by the laboratory to contain four gasoline-related volatile organic compounds at levels that slightly to moderately exceed applicable

EXCAVATION SITE (Continued) **S122478841**

limits. The multiple additional; post-excavation soil samples are reported to contain no VOC exceedances. Further, prior subsurface studies conducted by GCI before site development and submitted to NYSDEC also show that only a low number of VOC exceedances were present in one of these historical collected samples. Depth to the water table in the area of the Site is roughly 80 feet. No water-bearing deposits were encountered during foundation excavation work or by the impacted soil removal activities. Submitted documents reviewed. Disscussed with DEC Kumar. Based on submitted document case closed. "

Remarks: "historical spill clean up pending investigation"

All Materials:

Site ID:	570453
Operable Unit ID:	1318293
Operable Unit:	01
Material ID:	2326229
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

F48 **109 MONTGOMERY OWNER LLC** **NY UST** **U004289069**
NNW **109 MONTGOMERY STREET** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.087 mi.
457 ft. **Site 7 of 11 in cluster F**

Relative:
Higher

Actual:
104 ft.

UST:

Name:	109 MONTGOMERY OWNER LLC
Address:	109 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-612905 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	571454
Affiliation Type:	Facility Owner
Company Name:	109 MONTGOMERY OWNER LLC
Contact Type:	PARTNER
Contact Name:	AARON LEMMA
Address1:	2329 NOSTRAND AVENUE, THIRD FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11210
Country Code:	001
Phone:	(908) 419-4336

109 MONTGOMERY OWNER LLC (Continued) **U004289069**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2018-06-13

Site Id:	571454
Affiliation Type:	Mail Contact
Company Name:	109 MONTGOMERY OWNER LLC
Contact Type:	Not reported
Contact Name:	AARON LEMMA
Address1:	2329 NOSTRAND AVENUE, THIRD FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11210
Country Code:	001
Phone:	(908) 409-4336
EMail:	AARON@LIVWRK.COM
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2018-06-13

Site Id:	571454
Affiliation Type:	Facility Operator
Company Name:	109 MONTGOMERY OWNER LLC
Contact Type:	Not reported
Contact Name:	CHESKEL WERZBERGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 263-0066
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2018-06-13

Tank Info:

Tank Number:	001
Tank ID:	276215
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	06/08/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

109 MONTGOMERY OWNER LLC (Continued) **U004289069**

Equipment Records:

L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	276216
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	06/08/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

F49 **CON EDISON - MANHOLE 4787** **RCRA NonGen / NLR** **1010326005**
NNW **WASHINGTON AVE AND MONTGONERY** **NY MANIFEST** **NYP004136974**
< 1/8 **BROOKLYN, NY 11213**
0.088 mi.
467 ft. **Site 8 of 11 in cluster F**

Relative: **Higher**
Actual: **108 ft.**

RCRA Listings:

Date Form Received by Agency:	20060223
Handler Name:	CON EDISON - MANHOLE 4787
Handler Address:	WASHINGTON AVE AND MONTGONERY
Handler City,State,Zip:	BROOKLYN, NY 11213
EPA ID:	NYP004136974

CON EDISON - MANHOLE 4787 (Continued) **1010326005**

Contact Name:	FRANKLIN MURRAY
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No

CON EDISON - MANHOLE 4787 (Continued) **1010326005**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.	
Legal Status:	Private
Date Became Current:	20051005
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.	
Legal Status:	Private
Date Became Current:	20051005
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator: Operator

CON EDISON - MANHOLE 4787 (Continued) **1010326005**

Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20051005
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20051005
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060222
Handler Name: CON EDISON - MANHOLE 4787
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060223
Handler Name: CON EDISON - MANHOLE 4787
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - MANHOLE 4787
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

CON EDISON - MANHOLE 4787 (Continued) **1010326005**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: WASHINGTON AVE AND MONTGONERY
City,State,Zip: BROOKLYN, NY 11213
Country: USA
EPA ID: NYP004136974
Facility Status: Not reported
Location Address 1: MONTGOMERY & WASHINGTON MH4787
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004136974
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

F50 **MANHOLE #4787** **NY Spills** **S107409430**
NNW **WASHINGTON AVE AND MONTGOMERY AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.088 mi.
467 ft. **Site 9 of 11 in cluster F**

Relative: **Higher**

Actual: **108 ft.**

SPILLS:

Name:	MANHOLE #4787
Address:	WASHINGTON AVE AND MONTGOMERY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0508060 / 2005-12-01
Facility ID:	0508060
Facility Type:	ER
DER Facility ID:	300925
Site ID:	353580
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-10-05
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-10-05
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-05
Spill Record Last Update:	2005-12-01
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON MANHOLE #4787
Spiller Address:	WASHINGTON/MONTGOMERY AVE
Spiller Company:	999
Contact Name:	ERT DESK’
DEC Memo:	"161394. 10/5/05 - 1650hrs - Robert Esponda # 86029 Mech A Env. Ops reports while on location with UG to verify a d-fault he found 1 oz dielectric fluid leaked from tubing elbow onto feeder soaking arcproofing in MH4787. Structure has been dfaulted by UG dfault # 05242 fdr # unknown at this time. No fire/smoke involved. No sewers or waterways affected. No private property affected. Substance owned by Coned. Sample cannot be taken until structure made safe. Env. stop tag # 46411 placed. Access anytime, structure in int. Clean up pending sampling, test results and safe access. cn#19661 Closed. 12-1-05. see eDocs. GB "
Remarks:	"Amount 1 ounce, con ed #161394"

All Materials:

Site ID:	353580
Operable Unit ID:	1111037
Operable Unit:	01
Material ID:	2101078
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported

MANHOLE #4787 (Continued) **S107409430**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F51 **NEW YORK TELEPHONE** **RCRA NonGen / NLR** **1007205070**
NNW **MONTGOMERY & WASHINGTON** **NY MANIFEST** **NYP000908467**
< 1/8 **BROOKLYN, NY 11225**
0.088 mi.
467 ft. **Site 10 of 11 in cluster F**

Relative: **Higher**

Actual: **108 ft.**

RCRA Listings:

Date Form Received by Agency:		19940327
Handler Name:	NEW YORK TELEPHONE	
Handler Address:		MONTGOMERY & WASHINGTON
Handler City,State,Zip:		BROOKLYN, NY 11225-0000
EPA ID:		NYP000908467
Contact Name:		JOHN QUATRALE
Contact Address:		1095 AVENUE OF THE AMERICAS
Contact City,State,Zip:		NEW YORK, NY 10036-0000
Contact Telephone:		212-395-2436 x9999
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		1095 AVENUE OF THE AMERICAS
Mailing City,State,Zip:		NEW YORK, NY 10036-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

NEW YORK TELEPHONE (Continued) **1007205070**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19940326
Handler Name: NEW YORK TELEPHONE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19940327
Handler Name: NEW YORK TELEPHONE	
Federal Waste Generator Description:	Not a generator, verified

NEW YORK TELEPHONE (Continued) **1007205070**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940325
Handler Name: NEW YORK TELEPHONE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 5133
NAICS Description: TELECOMMUNICATIONS

NAICS Code: 51331
NAICS Description: WIRED TELECOMMUNICATIONS CARRIERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: NYNEX
Address: MONTGOMERY & WASHINGTON
City,State,Zip: BROOKLYN, NY 11225-0000
Country: USA
EPA ID: NYP000908467
Facility Status: Not reported
Location Address 1: MONTGOMERY & WASHINGTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000908467
Mailing Name: NYNEX

NEW YORK TELEPHONE (Continued) **1007205070**

Mailing Contact:	BENNY J STUMBO
Mailing Address 1:	1095 AVE OF AMER
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10036
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123956040

G52 **CON EDISON MANHOLE: 64993** **NY BROWNFIELDS** **1016148594**
SSE **73 EMPIRE BLVD** **NY Spills** **NYP004271730**
< 1/8 **BROOKLYN, NY 11225** **RCRA NonGen / NLR**
0.093 mi. **FINDS**
490 ft. **Site 1 of 10 in cluster G** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
73 ft.

BROWNFIELDS:

Name:	73 - 99 EMPIRE BOULEVARD
Address:	73 - 99 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11225
Program:	BCP
Site Code:	628295
Acres:	0.860
HW Code:	C224343
SWIS:	2401
Town:	New York City
Record Added Date:	11/09/2021
Record Updated Date:	01/04/2022
Update By:	LSZINOMA
Site Description:	"Location: The site is located in an urban area with a mix of commercial and residential buildings. The property is identified with the following addresses: 73 to 99 Empire Boulevard, 95 to 103 McKeever Place, and 46 to 62 Sullivan Place in Brooklyn, Kings County, New York (the site). The site is identified as Block 1306, Lot 28 on the Tax Map of Kings County. The site formerly consisted of three tax lots identified as Block 1306, Lots 28, 32, and 35. The site is located on the northern side of Empire Boulevard, the southern side of Sullivan Place, and the eastern side of McKeever Place. The approximate site area is 40,000 square feet (0.86 acres). Site Features The site is improved with two, one-story commercial buildings with partial cellars. The larger building (29,000 square feet) is vacant, and the smaller building (8,000 square feet) is occupied by a laundromat. The site buildings encompass approximately 37,000 square feet. The site buildings are constructed of concrete block and brick with a concrete, brick, and metal-lined window fa ade. Exterior areas include concrete-paved sidewalks and asphalt paved parking areas. Current Zoning and Land Use A portion of the site is currently active. Based on a review of the New York City Department of City Planning Zoning and Land Use (ZoLa) mapping program, the site is zoned C8-2, R6, and C1-3. The C8 (commercial) zoning is described as areas bridging commercial and manufacturing uses and provide for automotive and other heavy commercial services that often require large amounts of land. R6 (residential) zoning is described as mid-rise, eight- to ten-story buildings to much taller buildings set back from the street on large zoning lots. The C1 (commercial) zoning is described as commercial overlays that serve

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

local retail needs within residential districts. The neighboring properties are currently used for a combination of commercial and residential uses. The site is undergoing a rezoning process whereby the applicant intends to change the zoning from C8-2 (commercial), R6 (residential), and C1-3 (commercial) to c4-4D with an R8A residential equivalent prior to redevelopment. Past Use of the Site According to a Draft Phase I Environmental Site Assessment (ESA) prepared by VERTEX, dated December 23, 2021 (copy attached), the building on Lot 28 was constructed in 1925 and was initially occupied by Mack Truck Auto Service. The operations included the use of a gasoline tank, located on the southern portion of the property and a forge, located on the northeastern portion of the property. Mack Truck Auto Service operated at former Lot 28 until the late 1930s. Former Lot 28 was occupied by a garage in the mid-1940s and then occupied by an auto, truck and equipment manufacturer and auto parts and service station from the early 1950s through the early 2000s. A laundromat/laundry occupied the building from the early 2000s through 2014. The building has remained vacant since 2014. Former Lot 32 was developed with a store and an apartment prior to 1932. The structures were demolished sometime between 1932 and 1951. The parcel has remained an undeveloped/paved parking lot through present day. The building on former Lot 35 was constructed in 1930 and was originally occupied by the parts department of Mack Truck Auto Service. From the late 1930s to the early 1960s, the building was occupied by Tire Sales & Service. From the early 1960s to the late 1980s, the building was occupied by an auto and truck manufacturer. From the late 1980s through the early 1990s, the site was listed as Family Services. The building was vacant from 1994 through 2014. World Laundry has occupied the building on former Lot 35 since 2014. Site Geology and Hydrogeology Based upon the findings of the Phase II LSI (VERTEX, December 23, 2020/revised October 2021), soils encountered at the site generally consist of brown silty sand with gravel. Limited areas of historic fill were identified throughout the site. The historic fill layer generally consists of varying amounts of sands, gravels, and silts with concrete, brick, and wood in some areas. Bedrock and groundwater were not encountered to a depth of 63 feet bgs. Based on review of local topography and the location of the closest water body in relation to the site, groundwater is assumed to flow to the southeast. "

Env Problem: "Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."

Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

Own Op:	1
Sub Type:	P03
Owner Name:	Michael Berfield
Owner Company:	Empire Boulevard Holdings LLC
Owner Address:	150 E 58th St
Owner Addr2:	15th FL
Owner City,St,Zip:	New York, NY 10155
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Flatbush Branch
Owner Address:	22 Linden Blvd at Flatbush Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11226
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Michael Berfield
Owner Company:	Empire Boulevard Holdings LLC
Owner Address:	150 E 58th St
Owner Addr2:	15th FL
Owner City,St,Zip:	New York, NY 10155
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	NYC Brooklyn Community Board 9
Owner Address:	890 Nostrand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11225
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	COMMERCIAL
Address:	73 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2102064 / 2021-06-22
Facility ID:	2102064
Facility Type:	ER
DER Facility ID:	567360
Site ID:	619801
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2021-06-04

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2021-06-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-06-04
Spill Record Last Update:	2021-06-22
Spiller Name:	MADYLYN KULAS
Spiller Company:	UNKNOWN
Spiller Address:	73-99 EMPIRE BLVD
Spiller Company:	999
Contact Name:	MADYLYN KULAS
DEC Memo:	"06/04/21-Hiralkumar Patel. 3:40 PM:- spoke with Madalyn. she mentioned that some SVOCs found during sampling. asked her to submit lab data and sample location site sketch for review. Madalyn Kulas The Vertex Companies, Inc. Ph. (908) 448-2627 (908) 578-2186 email: mkulas@vertexeng.com 06/07/21-Hiralkumar Patel. received email from Madalyn (at 6:36 PM on 06/04/21) including a sample location site map and sample results. soil and soil-vapor samples were collected. no VOC contamination was noted in soil samples. some SVOC compounds noted in multiple soil samples. some VOCs were detected in soil-vapor samples. 9:48 AM:- sent email to Madalyn and asked her to provide some details about site's historical use, current condition and future planned use. 06/16/21-Hiralkumar Patel. 10:36 AM:- sent email to Madalyn and asked her to provide some details about site's historical use, current condition and future planned use. 06/22/21-Hiralkumar Patel. received email from Madalyn (at 4:02 PM on 06/21/21) including site background, current condition and future use. she also mentioned that they have submitted a brownfield pre-application form to DEC Jane on 06/21/21 and the pre-application meeting is tentatively scheduled for late June 2021. - site background: the building on Lot 28 was constructed in 1925 and was initially occupied by Mack Truck Auto Service, which included use of a forge. Mack Truck Auto Service operated at Lot 28 until the late 1930s. lot 28 was occupied by a garage in the mid-1940s and then occupied by an auto, truck and equipment manufacturer and auto parts and service station from the early 1950s through the early 2000s. a laundromat occupied the building from the early 2000s through 2014. the building has remained vacant since 2014. lot 32 was developed with a store and an apartment prior to 1932. the structures were demolished sometime between 1932 and 1951. the parcel has remained an undeveloped/paved parking lot through present day. the building on Lot 35 was constructed in 1930 and was originally occupied by the parts department of Mack Truck Auto Service. from the late 1930s to the early 1960s, the building was occupied by Tire Sales & Service. from the early 1960s to the late 1980s, the building was occupied by an auto and truck manufacturer. from the late 1980s through the early 1990s, the site was listed as Family Services. the building was vacant from 1994 through 2014. World Laundry has occupied the

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

building since 2014. on June 14, 2021, an Application for Apportionments or Mergers was submitted to the NYCDOF to merge Lots 28, 32 and 35 into Lot 28. the lot merger is tentative. - current condition: the site building on Lot 28 is currently vacant and was most recently occupied by World Laundry, a retail laundromat. the site building on Lot 35 is currently occupied by World Laundry, which still operates as a retail laundromat. World Laundry has occupied the building on Lot 35 since approximately 2014. World Laundry offers dry-cleaning services; however, it is only a drop shop and dry-cleaning is not performed onsite. Lot 32 is a small asphalt-paved parking lot. - proposed future use: the proposed development would consist of a 13-story, 368,100 gsf mixed-use building to be built on the development site. the proposed development would contain 65,828 sf of commercial/ retail uses on the first and second floors and 208,616 sf of residential uses on floors 3-13. below grade, 31,175 sf of retail use would be provided in the cellar level and a sub-cellar would contain 188 required parking spaces via a combination of single space stalls and two-tiered stackers. as per email from Madalyn, three lots #28, 32 and 35 on block # 1306 are involved in the project. alternate addresses: lot # 28 - 56 to 58 Sullivan Place, 95 to 103 McKeever Place, 73 to 97 Empire Blvd lot # 32 - 46 to 54 Sullivan Place, 79 McKeever Place lot # 35 - 60 to 62 Sullivan Place, 99 to 101 Empire Blvd no PBS or other spills found for all three lots. case closed based on review of all available information. 12:49 PM:- sent email to Madalyn and informed her about case closure. email copied to DEC Jane and Joseph Dultz (jdultz@vertexeng.com)."

Remarks: "CLEANUP PENDING."

All Materials:

Site ID:	619801
Operable Unit ID:	1366981
Operable Unit:	01
Material ID:	2379687
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20170728
Handler Name:	CON EDISON MANHOLE: 64993
Handler Address:	73 EMPIRE BLVD
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYP004271730
Contact Name:	BENJAMIN WARE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4515
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

Unaddressed Significant Non-Complier Universe: No
Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20171027
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20121002
Handler Name: CON EDISON MANHOLE: 64993
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170728
Handler Name: CON EDISON MANHOLE: 64993
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055422797

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016148594
Registry ID:	110055422797
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055422797
Name:	CON EDISON MANHOLE: 64993
Address:	73 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	CON EDISON
Address:	73 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004271730
Facility Status:	Not reported
Location Address 1:	EMPIRE BLVD & FRANKLIN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004271730
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported

CON EDISON MANHOLE: 64993 (Continued) **1016148594**

Generator Ship Date:	10/02/2012
Trans1 Recv Date:	10/02/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/04/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004271730
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	004806633FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	B007
Waste Code 1_6:	Not reported

H53 **MANHOLE # 23430** **NY Spills** **S104283512**
South **EMPIRE BL & FRANKLIN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.094 mi.
498 ft. **Site 1 of 11 in cluster H**

Relative: SPILLS:
Lower

Name:	MANHOLE # 23430
Address:	EMPIRE BL & FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9909194 / 2002-02-22
Facility ID:	9909194
Facility Type:	ER
DER Facility ID:	191366
Site ID:	232206

Actual:
77 ft.

MANHOLE # 23430 (Continued) **S104283512**

DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-10-28
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1999-10-28
CID:	390
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-28
Spill Record Last Update:	2002-02-22
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	STEPHEN CRIBBIN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks:	"1 gal unk sheen on 1 gal of water and mud mixture in a manhole - sample taken clean up pending lab results con ed # 128704"

All Materials:

Site ID:	232206
Operable Unit ID:	1087871
Operable Unit:	01
Material ID:	298282
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E54 **GASETERIA FRANKLIN** **NY UST** **U001833060**
SSW **43 EMPIRE BOULEVARD** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.096 mi.
509 ft. **Site 9 of 10 in cluster E**

Relative: UST:
Lower

Actual:
78 ft.

Name:	GASETERIA FRANKLIN
Address:	43 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-191760 / Unregulated/Closed
Program Type:	PBS
Region:	STATE

GASETERIA FRANKLIN (Continued) **U001833060**

DEC Region: 2
Expiration Date: N/A
UTM X: 587844.47832
UTM Y: 4501925.64606
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 5995
Affiliation Type: Mail Contact
Company Name: GASETERIA OIL CORP.
Contact Type: Not reported
Contact Name: ADAM GOOD
Address1: 364 MASPETH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 782-4200
EMail: EDABO@LARGAVISTA.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-06-23

Site Id: 5995
Affiliation Type: Emergency Contact
Company Name: MALU PROPERTIES
Contact Type: Not reported
Contact Name: ROBERTO PORCELLI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 294-3511
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-04-23

Site Id: 5995
Affiliation Type: Facility Owner
Company Name: MALU PROPERTIES
Contact Type: Not reported
Contact Name: Not reported
Address1: 364 MASPETH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 782-4200
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-04-23

GASETERIA FRANKLIN (Continued) **U001833060**

Site Id:	5995
Affiliation Type:	Facility Operator
Company Name:	GASETERIA FRANKLIN
Contact Type:	Not reported
Contact Name:	GASETERIA OIL CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 693-8053
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-04-23

Tank Info:

Tank Number:	001
Tank ID:	7697
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	05/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	002
Tank ID:	7708
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972

GASETERIA FRANKLIN (Continued) **U001833060**

Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 003
Tank ID: 7698
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1972
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

GASETERIA FRANKLIN (Continued) **U001833060**

Tank Number:	004
Tank ID:	7699
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	05/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number:	005
Tank ID:	7700
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	05/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None

GASETERIA FRANKLIN (Continued) **U001833060**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	006
Tank ID:	7701
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	05/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	007
Tank ID:	7702
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	05/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

GASETERIA FRANKLIN (Continued) **U001833060**

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	008
Tank ID:	7703
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	05/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	009
Tank ID:	7704
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1972
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

GASETERIA FRANKLIN (Continued) **U001833060**

Tightness Test Method: 03
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 010
Tank ID: 7705
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1972
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 011
Tank ID: 7706
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1972
Date Tank Closed: 07/01/1994

GASETERIA FRANKLIN (Continued) **U001833060**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 012
Tank ID: 7707
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1972
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 1

GASETERIA FRANKLIN (Continued) **U001833060**

Tank ID:	48343
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	07/01/1994
Date Tank Closed:	04/14/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
L08 - Piping Leak Detection - Tank Top Sump
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
B05 - Tank External Protection - Jacketed
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
F99 - Pipe External Protection - Other

Tank Number:	2
Tank ID:	48344
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	07/01/1994
Date Tank Closed:	04/14/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K01 - Spill Prevention - Catch Basin

GASETERIA FRANKLIN (Continued) **U001833060**

I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
L08 - Piping Leak Detection - Tank Top Sump
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
B05 - Tank External Protection - Jacketed
F99 - Pipe External Protection - Other

Tank Number:	3
Tank ID:	48345
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	07/01/1994
Date Tank Closed:	04/14/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
L08 - Piping Leak Detection - Tank Top Sump
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
B05 - Tank External Protection - Jacketed
F99 - Pipe External Protection - Other

Tank Number:	4
Tank ID:	48346
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	07/01/1994

GASETERIA FRANKLIN (Continued) **U001833060**

Date Tank Closed:	04/14/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
L08 - Piping Leak Detection - Tank Top Sump
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
B05 - Tank External Protection - Jacketed
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
F99 - Pipe External Protection - Other

E55 **GASETERIA OIL CORP** **NY LTANKS** **1001756895**
SSW **43 EMPIRE BLVD** **N/A**
< 1/8 **BROOKLYN, NY**
0.096 mi.
509 ft. **Site 10 of 10 in cluster E**

Relative: **Lower**
Actual: **78 ft.**

LTANKS:

Name:	GASETERIA OIL CORP
Address:	43 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9404188 / 2001-03-21
Facility ID:	9404188
Site ID:	175030
Spill Date:	1994-06-23
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C2
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	1994-06-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

GASETERIA OIL CORP (Continued) **1001756895**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-07-27
Spill Record Last Update:	2001-03-21
Spiller Name:	Not reported
Spiller Company:	GASETERIA SVCE STATION
Spiller Address:	43 EMPIRE BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	147159
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 03/21/01 Phase II performed by Berninger five geoprobes around new tanks, old tanks and new dispensers to 22' Nothing detected by PID or by lab analysis above MDL's. Close. "
Remarks:	"GASETERIA PULLING TANKS AT STATION. OVERFILL AT REMOTE FILL ABANDONED TANK AT SITE. GASETERIA DID NOT NOTIFY STATE. (WILSON)"

All Materials:

Site ID:	175030
Operable Unit ID:	1001085
Operable Unit:	01
Material ID:	380808
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

H56 **CON EDISON MANHOLE: 4761** **RCRA NonGen / NLR** **1016450288**
SSW **EMPIRE BLVD & WASHINGTON AVE N** **NY MANIFEST** **NYP004293122**
< 1/8 **BROOKLYN, NY 11201**
0.100 mi.
528 ft. **Site 2 of 11 in cluster H**

Relative: **Lower**
Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:	20130413
Handler Name:	CON EDISON MANHOLE: 4761
Handler Address:	EMPIRE BLVD & WASHINGTON AVE N
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004293122
Contact Name:	DENNIS HUACON
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON MANHOLE: 4761 (Continued) **1016450288**

Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		Not reported
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No

CON EDISON MANHOLE: 4761 (Continued) **1016450288**

Financial Assurance Required: Not reported
Handler Date of Last Change: 20130910
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20130313
Handler Name: CON EDISON MANHOLE: 4761
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130413
Handler Name: CON EDISON MANHOLE: 4761
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: EMPIRE BLVD & WASHINGTON AVE N
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004293122
Facility Status: Not reported

CON EDISON MANHOLE: 4761 (Continued) **1016450288**

Location Address 1:	NEC EMPIRE BLVD
Code:	BP
Location Address 2:	WASHINGTON AVE
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004293122
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/2012
Trans1 Recv Date:	08/17/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/17/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004293122
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000895550GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON MANHOLE: 4761 (Continued) **1016450288**

Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H57 **CON EDISON** **RCRA NonGen / NLR** **1014396038**
SSW **WASHINGTON AVE & EMPIRE BLVD** **NY MANIFEST** **NYP004182184**
< 1/8 **BROOKLYN, NY 11201**
0.100 mi.
528 ft. **Site 3 of 11 in cluster H**

Relative: **Lower**
Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		WASHINGTON AVE & EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11201
EPA ID:		NYP004182184
Contact Name:		STEVEN MARTIS
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-416-5423
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No

CON EDISON (Continued) **1014396038**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160609
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090625
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON (Continued) **1014396038**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160601
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON - MH58807
Address: WASHINGTON AVE & EMPIRE BLVD
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004182184
Facility Status: Not reported
Location Address 1: WASHINGTON AVE & SULLIVAN PLACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004182184
Mailing Name: CONSOLIDATED EDISON - MH58807
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

CON EDISON (Continued) **1014396038**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/26/2009
Trans1 Recv Date:	06/26/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004182184
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433330FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	350
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	B002
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H58 **STREET** **NY Spills** **S109062621**
SSW **EMPIRE BLVD/ WASHINGTON A** **N/A**
< 1/8 **BROOKLYN, NY**
0.101 mi.
532 ft. **Site 4 of 11 in cluster H**

Relative:
Lower

Actual:
78 ft.

SPILLS:

Name:	STREET
Address:	EMPIRE BLVD/ WASHINGTON A
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0801500 / 2008-05-08
Facility ID:	0801500
Facility Type:	ER
DER Facility ID:	346853
Site ID:	397438
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-05-07
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2008-05-07
CID:	404
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-07
Spill Record Last Update:	2008-05-08
Spiller Name:	CHRISTINA RYSZEWSKI
Spiller Company:	NYS TRANSIT
Spiller Address:	2 BROADWAY
Spiller Company:	001
Contact Name:	CHRISTINA RYSZEWSKI
DEC Memo:	"NYS Transit cleaned up as much as they could."
Remarks:	"some went into the sewer; believes it was only 1 to 2 gallons in sewer; everything else was cleaned up;"

All Materials:

Site ID:	397438
Operable Unit ID:	1154400
Operable Unit:	01
Material ID:	2145195
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H59 **MANHOLE # 4761** **NY Spills** **S106735821**
SSW **EMPIRE BLVD./E WASHINGTON** **N/A**
< 1/8 **BROOKLYN, NY**
0.101 mi.
532 ft. **Site 5 of 11 in cluster H**

Relative: **Lower**

Actual: **78 ft.**

SPILLS:

Name:	MANHOLE # 4761
Address:	EMPIRE BLVD./E WASHINGTON
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0409712 / 2005-01-07
Facility ID:	0409712
Facility Type:	ER
DER Facility ID:	269718
Site ID:	334511
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-11-30
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2004-12-01
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-01
Spill Record Last Update:	2005-01-07
Spiller Name:	ERT DESK
Spiller Company:	MANHOLE # 4761
Spiller Address:	EMPIRE BLVD./E WASHINGTON
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"30-NOV-2004 DAVE LICHTENSTEIN,EMPLOYEE NO. 08078, IN MH4761,LOCATED ON THE N/S OF EMPIRE BLVD, 15' E/ E/C, OF WASHINGTON AVENUE, REPORTS FINDING APPX 1 GAL OF DIELECTRIC FLUID, ON DEBRIS IN THE STRUCTURE, FROM A LEAKING CAPPED FEEDER, 4B10. NO FIRE OR SMOKE INVOLVED, NO INJURIES RELATED TO THE SPILL, NO SEWERS, WATERWAYS OR PRIVATE PROPERTY INVOLVED, SPILL APPEARS TO BE CONTAINED TO THE STRUCTURE. HE IS UNABLE TO VERIFY ANY SUMPS OR SUBSTANTIAL CRACKS IN THE STRUCTURE AT THIS TIME. ENVIRONMENTAL TAG NO. 44592 WAS PLACED IN THE STRUCTURE AND SAMPLE TAKEN FOR PCB'S. THIS WILL BE TAKEN VIA COURIER TO THE LAB ON CC NO. DD09305. NO 9 WILL BE NOTIFIED TO IDENTIFY AND MAKE THE REPAIRS. QC ID: 02-200411260853 - PCBs < 1 ppm UPDATE 01-DEC-2004 10:40 HRS. ENVIR. OPER O.S. E.WILLIAMS REPORTS: DUE TO MANPOWER PROBLEMS INCIDENT# 156415 WILL NOT BE MEETING THE 24hr CLOCK AND WILL BE RECLASSIFIED AS SPILL DIELECTRIC FLUID. UPDATE 05-DEC-2004 20:00 ENVIR. OPER. MECH-A S.ADEDAPO EMP# 16544 REPORTS: DBL. WASHED STRUCTURE WITH BIO-GEN 760. NO SUMP IN STRUCTURE, ENVIR. TAG# 44592 REMOVED. CLEANUP COMPLETE 100%. **UPDATE 06-DEC-2004 INCIDENTAL, AS PER CC SUPV D. HEARNS, FLUSH OPERATIONS SUPV G. WILLIAMS REPORTS, NO. 9 WAS ON LOCATION PRIOR TO THE CLEAN UP AND CAPPED THE CABLE."

MANHOLE # 4761 (Continued) **S106735821**

Remarks: "leaked from a feeder: no to 5 questions: 24 hour clock off due to lack of manpower: coned # 156415"

All Materials:

Site ID:	334511
Operable Unit ID:	1096645
Operable Unit:	01
Material ID:	576561
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H60 **MANHOLE 58808** **NY Spills** **S106968536**
SSW **WASHINGTON AVE/EMPIRE BOU** **N/A**
< 1/8 **BROOKLYN, NY**
0.101 mi.
532 ft. **Site 6 of 11 in cluster H**

Relative: **Lower**

Actual: **78 ft.**

SPILLS:

Name:	MANHOLE 58808
Address:	WASHINGTON AVE/EMPIRE BOU
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0502779 / 2006-01-09
Facility ID:	0502779
Facility Type:	ER
DER Facility ID:	293516
Site ID:	347212
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-06-08
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2005-06-08
CID:	409
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-08
Spill Record Last Update:	2006-01-09
Spiller Name:	ERT DESK MIKE DAUGHTERY
Spiller Company:	MANHOLE 58808
Spiller Address:	WASHINGTON AVE/EMPIRE BOU
Spiller Company:	001
Contact Name:	ERT DESK MIKE DAUGHTERY

MANHOLE 58808 (Continued) **S106968536**

DEC Memo: "e2mis no 159021 K. NIXON REPORTS FINDING APPROX 1 PT OF AN UNKNOWN OIL ON APPROX 1 GAL OF WATER IN MH58808. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. CANNOT VERIFY THE EXISTENCE OF ANY SEWER CONNECTIONS, SUMPS OR DRAINS. THERE IS A 3c STRT JT WITH TUBING NOT CONNECTED TO ANYTHING IN THE STRUCTURE. TAG # 35413 PLACED IN STRUCTURE. PCB SAMPLE TAKEN. CLEANUP PENDING LAB RESULT. "

Remarks: "1 pint and clean up is pending lab results. con ed#159021. d fault in the hose."

All Materials:

Site ID:	347212
Operable Unit ID:	1104952
Operable Unit:	01
Material ID:	1262277
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H61 **CON EDISON** **NY MANIFEST** **S117066815**
South **1035 FRANKLIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.104 mi.
551 ft. **Site 7 of 11 in cluster H**

Relative: **Lower**

Actual: **76 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	1035 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004595153
Facility Status:	Not reported
Location Address 1:	1035 FRANKLIN AVE
Code:	BP
Location Address 2:	SB26243
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004595153
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117066815**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/2014
Trans1 Recv Date:	07/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004595153
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614925GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G62
SE
< 1/8
0.105 mi.
556 ft.

CON EDISON
99 EMPIRE BLVD
BROOKLYN, NY 11225

Site 2 of 10 in cluster G

NJ MANIFEST **S120671458**
N/A

Relative:
Lower

Actual:
71 ft.

NJ MANIFEST:

EPA Id:	NYP004779005
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624253GBF
EPA ID:	NYP004779005
Date Shipped:	5/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120671458**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

G63 **CON EDISON** **RCRA NonGen / NLR** **1019902890**
SE **99 EMPIRE BLVD** **NYP004779005**
< 1/8 **BROOKLYN, NY 11225**
0.105 mi.
556 ft. **Site 3 of 10 in cluster G**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:		20150505
Handler Name:	CON EDISON	
Handler Address:		99 EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004779005
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1019902890**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150505
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150505
Handler Name: CON EDISON	

CON EDISON (Continued) **1019902890**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

G64 **CON EDISON** **NY MANIFEST** **S119075104**
SE **99 EMPIRE BLVD** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.105 mi.
556 ft. **Site 4 of 10 in cluster G**

Relative: **Lower**

Actual: **71 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	99 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004779005
Facility Status:	Not reported
Location Address 1:	FO 99 EMPIRE BLVD
Code:	BP
Location Address 2:	STRUCTURE 23435
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004779005
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S119075104**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	05/05/2015
Trans1 Recv Date:	05/05/2015
Trans2 Recv Date:	05/14/2015
TSD Site Recv Date:	05/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004779005
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624253GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F65 **921 WASHINGTON AVE.** **NY AST** **U003387413**
NNW **921 WASHINGTON AVE.** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.105 mi.
557 ft. **Site 11 of 11 in cluster F**

Relative:
Higher

Actual:
109 ft.

AST:

Name:	921 WASHINGTON AVE.
Address:	921 WASHINGTON AVE.
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-252239
Program Type:	PBS
UTM X:	587780.20730
UTM Y:	4502291.11847
Expiration Date:	02/28/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10156
Affiliation Type:	Facility Owner
Company Name:	921 WASHINGTON AVENUE LLC
Contact Type:	AGENT
Contact Name:	RYAN VILLARRUEL
Address1:	120 WEST 31ST STREET, 6TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 947-0007
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Site Id:	10156
Affiliation Type:	Facility Operator
Company Name:	921 WASHINGTON AVE.
Contact Type:	Not reported
Contact Name:	RYAN VILLARRUEL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 854-5880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Site Id:	10156
Affiliation Type:	Mail Contact
Company Name:	921 WASHINGTON AVENUE LLC
Contact Type:	Not reported
Contact Name:	RYAN VILLARRUEL

921 WASHINGTON AVE. (Continued) **U003387413**

Address1:	C/O SAFEGUARD REALTY MANAGEMENT INC.
Address2:	120 WEST 31ST STREET, 6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(646) 448-0826
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Site Id:	10156
Affiliation Type:	Emergency Contact
Company Name:	921 WASHINGTON AVENUE LLC
Contact Type:	Not reported
Contact Name:	BENNY KODRA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 315-0872
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-11-21

Tank Info:

Tank Number:	001
Tank Id:	11829
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1935
Capacity Gallons:	4500

921 WASHINGTON AVE. (Continued) **U003387413**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

H66 **BROOKLYN FIRE COMM CENTRAL OFFICE** **NY UST** **U001840020**
SSW **35 EMPIRE BOULEVARD** **N/A**
< 1/8 **BROOKLYN, NY 11238**
0.106 mi.
562 ft. **Site 8 of 11 in cluster H**

Relative:
Lower

Actual:
79 ft.

UST:

Name:	BROOKLYN FIRE COMM CENTRAL OFFICE
Address:	35 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11238
Id/Status:	2-357219 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/28/2023
UTM X:	587792.06580
UTM Y:	4501919.42477
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	17873
Affiliation Type:	Mail Contact
Company Name:	BUILDINGS MAINTENANCE DIVISION
Contact Type:	Not reported
Contact Name:	JOSEPH M. MASTROPIETRO, ASST. COMMISSIONER
Address1:	FIRE DEPARTMENT
Address2:	48-34 35TH STREET
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6510
EMail:	MASTROJ@FDNY.NYC.GOV
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-09-26

Site Id:	17873
Affiliation Type:	Emergency Contact
Company Name:	FIRE DEPARTMENT
Contact Type:	Not reported
Contact Name:	EOC/NOTIFICATION DESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 999-2094

BROOKLYN FIRE COMM CENTRAL OFFICE (Continued) **U001840020**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-07-25

Site Id:	17873
Affiliation Type:	Facility Operator
Company Name:	BROOKLYN FIRE COMM CENTRAL OFFICE
Contact Type:	Not reported
Contact Name:	VINCENT FIORE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 965-8266
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-15

Site Id:	17873
Affiliation Type:	Facility Owner
Company Name:	FIRE DEPARTMENT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	9 METROTECH
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-15

Tank Info:

Tank Number:	001
Tank ID:	35019
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5500
Install Date:	12/01/1922
Date Tank Closed:	06/01/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

BROOKLYN FIRE COMM CENTRAL OFFICE (Continued) **U001840020**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 35020
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1500
Install Date: 12/01/1980
Date Tank Closed: 06/01/2001
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 60893
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 6000
Install Date: 06/01/2001
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel

BROOKLYN FIRE COMM CENTRAL OFFICE (Continued) **U001840020**

Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	21
Date Test:	03/21/2007
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
H05 - Tank Leak Detection - In-Tank System (ATG)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser

H67 **BROOKLYN FIRE COMM CENTRAL OFFICE** **NY AST** **A100380367**
SSW **35 EMPIRE BOULEVARD** **N/A**
< 1/8 **BROOKLYN, NY 11238**
0.106 mi.
562 ft. **Site 9 of 11 in cluster H**

Relative:
Lower

Actual:
79 ft.

AST:

Name:	BROOKLYN FIRE COMM CENTRAL OFFICE
Address:	35 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11238
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-357219
Program Type:	PBS
UTM X:	587792.06580
UTM Y:	4501919.42477
Expiration Date:	06/28/2023
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	17873
Affiliation Type:	Mail Contact
Company Name:	BUILDINGS MAINTENANCE DIVISION
Contact Type:	Not reported
Contact Name:	JOSEPH M. MASTROPIETRO, ASST. COMMISSIONER
Address1:	FIRE DEPARTMENT
Address2:	48-34 35TH STREET
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6510

BROOKLYN FIRE COMM CENTRAL OFFICE (Continued) **A100380367**

EMail: MASTROJ@FDNY.NYC.GOV
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-09-26

Site Id: 17873
Affiliation Type: Emergency Contact
Company Name: FIRE DEPARTMENT
Contact Type: Not reported
Contact Name: EOC/NOTIFICATION DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-07-25

Site Id: 17873
Affiliation Type: Facility Operator
Company Name: BROOKLYN FIRE COMM CENTRAL OFFICE
Contact Type: Not reported
Contact Name: VINCENT FIORE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-8266
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2016-09-15

Site Id: 17873
Affiliation Type: Facility Owner
Company Name: FIRE DEPARTMENT
Contact Type: Not reported
Contact Name: Not reported
Address1: 9 METROTECH
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201-3857
Country Code: 001
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2016-09-15

BROOKLYN FIRE COMM CENTRAL OFFICE (Continued) **A100380367**

Tank Info:

Tank Number:	003A
Tank Id:	248713

Equipment Records:

E99 - Piping Secondary Containment - Other
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A01 - Tank Internal Protection - Epoxy Liner
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/08/2013
Capacity Gallons:	120
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	003B
Tank Id:	248714

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

BROOKLYN FIRE COMM CENTRAL OFFICE (Continued) **A100380367**

Pipe Model:	Not reported
Install Date:	05/08/2013
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	003C
Tank Id:	248715

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
C03 - Pipe Location - Aboveground/Underground Combination

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/08/2013
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

H68 **MID-COUNTY MOTORS** **RCRA NonGen / NLR** **1000138707**
SSW **44 EMPIRE BLVD** **FINDS** **NYD093760627**
< 1/8 **BROOKLYN, NY 11225** **ECHO**
0.110 mi.
579 ft. **Site 10 of 11 in cluster H**

Relative: **Lower**
Actual: **79 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	MID-COUNTY MOTORS	
Handler Address:		44 EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYD093760627

MID-COUNTY MOTORS (Continued) **1000138707**

Contact Name:		ROBERT SABO
Contact Address:		EMPIRE BLVD
Contact City,State,Zip:		BROOKLYN, NY 11225
Contact Telephone:		718-941-9800
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		EMPIRE BLVD
Mailing City,State,Zip:		BROOKLYN, NY 11225
Owner Name:	STEVE MALISE	
Owner Type:		Private
Operator Name:	STEVE MALISE	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No

MID-COUNTY MOTORS (Continued) **1000138707**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	X001
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: STEVE MALISE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: STEVE MALISE	
Legal Status:	Private
Date Became Current:	Not reported

MID-COUNTY MOTORS (Continued) **1000138707**

Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: STEVE MALISE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: MID-COUNTY MOTORS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: MID-COUNTY MOTORS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19860711
Handler Name: MID-COUNTY MOTORS	
Federal Waste Generator Description:	Not reported
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

MID-COUNTY MOTORS (Continued) **1000138707**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004374971

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000138707
Registry ID: 110004374971
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004374971
Name: MID-COUNTY MOTORS
Address: 44 EMPIRE BLVD
City,State,Zip: BROOKLYN, NY 11225

G69 **CON EDISON MANHOLE: 23435** **NJ MANIFEST** **S117987071**
SE **103 EMPIRE BLVD** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.113 mi.
597 ft. **Site 5 of 10 in cluster G**

Relative: **Lower**
Actual: **71 ft.**

NJ MANIFEST:
EPA Id: NYP004279402
Mail Address: IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: MICHAEL STAMPFEL
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported

CON EDISON MANHOLE: 23435 (Continued) **S117987071**

TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001674700GBF
EPA ID:	NYP004279402
Date Shipped:	12/3/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	200.00 gallons

G70 **CON EDISON MANHOLE: 23435** **RCRA NonGen / NLR** **1016149277**
SE **103 EMPIRE BLVD** **FINDS** **NYP004279402**
< 1/8 **BROOKLYN, NY 11225** **ECHO**
0.113 mi. **NY MANIFEST**
597 ft. **Site 6 of 10 in cluster G**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:		20170728
Handler Name:	CON EDISON MANHOLE: 23435	
Handler Address:		103 EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004279402
Contact Name:		MICHAEL STAMPFEL
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-666-4550
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SPECIALIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON MANHOLE: 23435 (Continued) **1016149277**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20171127
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20121203
Handler Name: CON EDISON MANHOLE: 23435	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170728
Handler Name: CON EDISON MANHOLE: 23435	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON MANHOLE: 23435 (Continued) **1016149277**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055468603

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016149277
Registry ID:	110055468603
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055468603
Name:	CON EDISON MANHOLE: 23435
Address:	103 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	CON EDISON
Address:	103 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004279402
Facility Status:	Not reported
Location Address 1:	103 EMPIRE BLVD
Code:	BP
Location Address 2:	MH #23435
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004279402
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON

CON EDISON MANHOLE: 23435 (Continued) **1016149277**

Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/2012
Trans1 Recv Date:	12/03/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004279402
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	001674700GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G71 **FALCON AUTOMOTIVE INC** **EDR Hist Auto** **1021721031**
SE **100 EMPIRE BLVD** **N/A**
< 1/8 **BROOKLYN, NY 11225**
0.123 mi.
651 ft. **Site 7 of 10 in cluster G**

Relative: EDR Hist Auto
Lower

Actual: **69 ft.**

Year:	Name:	Type:
1982	TORQUE TRANSMISSION CO	Automotive Repair Shops, NEC
1983	TORQUE TRANSMISSION CO	Automotive Repair Shops, NEC
1985	FALCON AUTOMOTIVE INC	Automotive Repair Shops, NEC
1986	FALCON AUTOMOTIVE INC	Automotive Repair Shops, NEC
1987	FALCON AUTOMOTIVE INC	Automotive Repair Shops, NEC
1988	FALCON AUTOMOTIVE INC	Automotive Repair Shops, NEC
1989	FALCON AUTOMOTIVE INC	Automotive Transmission Repair Shops
1990	FALCON AUTOMOTIVE INC	Automotive Transmission Repair Shops
1994	HOUSE OF KINGS TRANSMISSION	Automotive Transmission Repair Shops
1995	HOUSE OF KINGS TRANSMISSION	Automotive Transmission Repair Shops
1996	HOUSE OF KINGS TRANSMISSION	Automotive Transmission Repair Shops
1997	HOUSE OF KINGS TRANSMISSION	Automotive Transmission Repair Shops

---

I72 **SEA CREST LINEN/CENTRAL LAUNDRY SERVICE** **NY DRYCLEANERS** **S110247883**
NNE **46 CROWN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.127 mi.
668 ft. **Site 1 of 6 in cluster I**

Relative: DRYCLEANERS:
Higher

Actual: **105 ft.**

Name:	SEA CREST LINEN/CENTRAL LAUNDRY SERVICE
Address:	46 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Facility ID:	2-6104-00778
Phone Number:	718-287-4800
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	2003-11-19 00:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

I73 **54 CROWN STREET** **NY VCP** **S125317144**
NNE **46 CROWN STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.127 mi.
668 ft. **Site 2 of 6 in cluster I**

Relative: VCP NYC:
Higher

Actual: **105 ft.**

Project ID:	19TMP1132K,19EH-A295K,20CVCP031K
Name:	54 CROWN STREET
Address:	46 CROWN STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0119000293011901E+29

54 CROWN STREET (Continued) **S125317144**

OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.667294
Longitude:	-73.960028
Postcode:	9
Community Board:	35
Council District:	213
Census Tract:	3330786
BIN:	3011900029
NTA:	Crown Heights South

I74 **CENTRAL LAUNDRY CORP.-SEACREST DIV.** **NY LTANKS** **S103941438**
NNE **46 CROWN STREET** **NY CBS** **N/A**
1/8-1/4 **BROOKLYN, NY 11225** **NY AST**
0.127 mi. **NY Spills**
668 ft. **Site 3 of 6 in cluster I**

Relative: **Higher**
Actual: **105 ft.**

LTANKS:

Name:	TANK TEST FAILURE AT COMMERCIAL BUILDING
Address:	46 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1406415 / 2015-01-29
Facility ID:	1406415
Site ID:	499883
Spill Date:	2014-09-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2014-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-09-16
Spill Record Last Update:	2015-02-06
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	RAY KAHN
Spiller Phone:	(212) 330-7501
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	95767
DEC Memo:	"11-09-2014-DEC Piper spoke with Ray Kahn, tank is rbeing removed today. Cont soil is present and will be overexcavated. Once done, endpoints will be taken. Report to follow. 1/29/15- DECPiper received tank removal/ closure report. Based on excavation removal and endpoints, this spill is closed. See Dec Docs for Report."
Remarks:	"reccommend removal"

CENTRAL LAUNDRY CORP.-SEACREST DIV. (Continued) **S103941438**

All Materials:

Site ID:	499883
Operable Unit ID:	1249290
Operable Unit:	01
Material ID:	2250854
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	SEA CREST LINEN
Address:	46 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9903240 / 1999-08-10
Facility ID:	9903240
Site ID:	108983
Spill Date:	1999-06-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1999-06-21
CID:	365
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-21
Spill Record Last Update:	2003-11-20
Spiller Name:	T WILLIAMS
Spiller Company:	SEA CREST LINEN
Spiller Address:	46 CROWN ST
Spiller County:	001
Spiller Contact:	T WILLIAMS
Spiller Phone:	(718) 287-4800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	95767
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND JUNE 24, 1999 PROTEST WAS AT SITE AND RE-TESTED THE TANK ALONE AND THE LINES ALONE.... BOTH PAST THE TEST.... HOWEVER, PROTEST DISCOVERED SOIL CONTAMINATION NEAR THE OIL FILL PORT. THEY DUG AROUND THAT AREA AND REMOVED 2 CUBIC YARDS OF CONTAMINATION. THE CONTAMINATION SEEMS TO BE BETWEEN THE SIDE OF THE BURIED TANK AND THE BUILDING FOUNDATION WALL. SANGESLAND TOLD PROTEST TO EXCAVATE AS MUCH CONTAMINATION AS POSSIBLE (MAINTAINING BUILDING STRUCTUAL INTEGRITY)

CENTRAL LAUNDRY CORP.-SEACREST DIV. (Continued) **S103941438**

AND TAKE END POINT SAMPLES. IF THE CONTAMINATION GETS WORSE OR DOESN'T END PROTEST WILL CALL BACK. 8/10/99 RECEIVED A REPORT FROM PROTEST SHOWING SYSTEM NOW PASSES HORNER EZY 3 TIGHTNESS TEST. 49.84 TONS OF CONTAMINATED SOIL WERE REMOVED (MANIFESTED TO CLEAN WATERS OF AMERICA 603-798-4700) 2 END POINT SAMPLES WERE TAKEN FROM THE EXCAVATION. SOME SLIGHT HITS, VERY MINOR. SPILL CLOSED 8/10/99 "

Remarks: "horner ez 3 - underground tank"

All TTF:

Facility ID:	9903240
Spill Number:	9903240
Spill Tank Test:	1547284
Site ID:	108983
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	108983
Operable Unit ID:	1082164
Operable Unit:	01
Material ID:	303168
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CBS:

Name:	CENTRAL LAUNDRY CORP.-SEACREST DIV.
Address:	46 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
CBS Number:	2-000158
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	587897.10291
UTMY:	4502342.23434

AST:

Name:	CENTRAL LAUNDRY CORP.-SEACREST DIV.

CENTRAL LAUNDRY CORP.-SEACREST DIV. (Continued) **S103941438**

Address:	46 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000158
Program Type:	CBS
UTM X:	587897.10291
UTM Y:	4502342.23434
Expiration Date:	N/A
Site Type:	Other

Tank Info:

Tank Number:	00001
Tank Id:	188041
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1985
Capacity Gallons:	288
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	00002
Tank Id:	188042
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1980
Capacity Gallons:	352
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

SPILLS:

Name:	CP VI CROWN HEIGHTS LLC
Address:	46 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1903555 / Not Reported
Facility ID:	1903555

CENTRAL LAUNDRY CORP.-SEACREST DIV. (Continued) **S103941438**

Facility Type:	ER
DER Facility ID:	95767
Site ID:	591519
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2019-07-08
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-07-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2019-07-08
Spill Record Last Update:	2019-07-10
Spiller Name:	MATTHEW FELDMAN
Spiller Company:	CP VI CROWN HEIGHTS LLC
Spiller Address:	46 CROWN ST
Spiller Company:	999
Contact Name:	AMANDA FORSBURG
DEC Memo:	"7/8/19 - Sekhon Historic impacts confirmed in lab results for E - designated site. Case transferred to DEC Rick Lin for follow up. Company: CP VI Crown Heights LLC Contact Person: Matt Feldman Email: mfeldman@carmelpartners.com Phone: 212.202.5783 "
Remarks:	"historic impacts confirmed in lab results"

All Materials:

Site ID:	591519
Operable Unit ID:	1339136
Operable Unit:	01
Material ID:	2348671
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

I75 NNE 1/8-1/4 0.127 mi. 668 ft. **SEACREST LINEN SUPPLY CO.**
46 CROWN STREET
BROOKLYN, NY 11225
Site 4 of 6 in cluster I

NY UST **U003031011**
N/A

Relative: Higher

Actual: 105 ft.

UST:

Name:	SEACREST LINEN SUPPLY CO.
Address:	46 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-511528 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	587864.77011
UTM Y:	4502336.37129
Site Type:	Other

Affiliation Records:

Site Id:	21952
Affiliation Type:	Facility Operator
Company Name:	SEACREST LINEN SUPPLY CO.
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-11

Site Id:	21952
Affiliation Type:	Emergency Contact
Company Name:	CORNELL CROWN LLC
Contact Type:	Not reported
Contact Name:	SHLOIMY REICHMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 496-7126
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-11

Site Id:	21952
Affiliation Type:	Mail Contact
Company Name:	CORNELL CROWN LLC
Contact Type:	Not reported
Contact Name:	SHLOIMY REICHMAN
Address1:	75 HUNTINGTON STREET

SEACREST LINEN SUPPLY CO. (Continued) **U003031011**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 496-7126
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-11

Site Id:	21952
Affiliation Type:	Facility Owner
Company Name:	CORNELL CROWN LLC
Contact Type:	MEMBER
Contact Name:	SHIFRA HAGER
Address1:	75 HUNTINGTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 496-7126
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-11

Tank Info:

Tank Number:	001
Tank ID:	39849
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	12/01/1973
Date Tank Closed:	11/09/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	06/07/2010
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

SEACREST LINEN SUPPLY CO. (Continued) **U003031011**

K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

I76 **CENTRAL LAUNDRY CORP.-SEACREST DIV.** **NY CBS AST** **S102639246**
NNE **46 CROWN ST.** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.127 mi.
668 ft. **Site 5 of 6 in cluster I**

Relative:
Higher

Actual:
105 ft.

CBS AST:

CBS Number:	2-000158
ICS Number:	2-700592
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	I
Telephone:	(718) 539-5867
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	08/01/1991
Total Capacity of All Active Tanks(gal):	0
Operator:	JOSE VELIZ
Emergency Contact:	JOSE VELIZ
Emergency Phone:	(718) 539-5867
Owner Name:	IRVING OLAN
Owner Address:	271-7D GRAND CENTRAL PKWY.
Owner City,St,Zip:	FLORAL PARK, NY 11005
Owner Telephone:	(718) 229-0424
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	CENTRAL LAUNDRY CORP
Mail Contact Addr:	46 CROWN STREET
Mail Contact Addr2:	Not reported
Mail Contact Contact:	DANNY GREENBERG
Mail Contact City,St,Zip:	BROOKLYN, NY 11225
Mail Phone:	(718) 229-0424
Tank Id:	00002
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	0
Install Date:	06/80
Tank Closed:	00/00
Capacity (Gal):	352
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	08/01/1989
Certified Date:	08/01/1989

CENTRAL LAUNDRY CORP.-SEACREST DIV. (Continued) **S102639246**

Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/14/92
Is It There:	False
Delinquent:	False
Date Expired:	08/01/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/14/1992

Tank Id:	00001
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	0
Install Date:	01/85
Tank Closed:	00/00
Capacity (Gal):	288
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	08/01/1989
Certified Date:	08/01/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101

CENTRAL LAUNDRY CORP.-SEACREST DIV. (Continued) **S102639246**

Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/14/92
Is It There:	False
Delinquent:	False
Date Expired:	08/01/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/14/1992

G77 **104-110 EMPIRE BLVD** **NY AST** **U003392251**
SE **104-110 EMPIRE BLVD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.128 mi.
674 ft. **Site 8 of 10 in cluster G**

Relative:
Lower

Actual:
69 ft.

AST:

Name:	104-110 EMPIRE BLVD
Address:	104-110 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-272086
Program Type:	PBS
UTM X:	588052.46896
UTM Y:	4501871.30047
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	11511
Affiliation Type:	Facility Owner
Company Name:	MAGNA REALTY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1408 CONEY ISLAND AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11230
Country Code:	001
Phone:	(718) 859-3101
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	11511
Affiliation Type:	Mail Contact
Company Name:	MAGNA REALTY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1408 CONEY ISLAND AVE
Address2:	Not reported
City:	BROOKLYN

104-110 EMPIRE BLVD (Continued) **U003392251**

State: NY
Zip Code: 11230
Country Code: 001
Phone: (718) 859-3101
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 11511
Affiliation Type: Facility Operator
Company Name: 104-110 EMPIRE BLVD
Contact Type: Not reported
Contact Name: DOMETRIAN RODRIGUEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 284-3256
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 11511
Affiliation Type: Emergency Contact
Company Name: MAGNA REALTY
Contact Type: Not reported
Contact Name: VICTOR SILBER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 859-3103
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 24198
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None

104-110 EMPIRE BLVD (Continued) **U003392251**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/1995
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	gasoline

G78 **SAFEGUARD SELF-STORAGE** **NY UST** **U004107531**
SE **115 EMPIRE BLVD.** **N/A**
1/8-1/4 **NEW YORK, NY 11111**
0.132 mi.
698 ft. **Site 9 of 10 in cluster G**

Relative: **Lower**
Actual: **69 ft.**

UST:

Name:	SAFEGUARD SELF-STORAGE
Address:	115 EMPIRE BLVD.
City,State,Zip:	NEW YORK, NY 11111
Id/Status:	2-610542 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588051.92130
UTM Y:	4501925.66317
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	380152
Affiliation Type:	Facility Owner
Company Name:	SAFEGUARD STORAGE PROPERTIES
Contact Type:	SUP OF DEVELOPMENT
Contact Name:	JIM GOONAN
Address1:	105 MAXESS RD. SUITE 125
Address2:	Not reported
City:	MELVILLE
State:	NY
Zip Code:	11747
Country Code:	001
Phone:	(631) 539-0205
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-04-19

Site Id:	380152

SAFEGUARD SELF-STORAGE (Continued) **U004107531**

Affiliation Type:	Mail Contact
Company Name:	ISLANDWIDE SITE DEVELOPMENT
Contact Type:	Not reported
Contact Name:	CHRISTOPHER CAVOTO
Address1:	209 SOUTH FEHR WAY
Address2:	Not reported
City:	BAYSHORE
State:	NY
Zip Code:	11706
Country Code:	001
Phone:	(631) 242-7440
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-04-19

Site Id:	380152
Affiliation Type:	Facility Operator
Company Name:	SAFEGUARD SELF-STORAGE
Contact Type:	Not reported
Contact Name:	SAFEGUARD SELF-STORAGE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(631) 831-3196
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-04-19

Site Id:	380152
Affiliation Type:	Emergency Contact
Company Name:	SAFEGUARD STORAGE PROPERTIES
Contact Type:	Not reported
Contact Name:	CHRIS DAVOTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(631) 539-0205
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-04-19

Tank Info:

Tank Number:	1
Tank ID:	216871
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1032

SAFEGUARD SELF-STORAGE (Continued) **U004107531**

Install Date:	Not reported
Date Tank Closed:	04/18/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	2
Tank ID:	216872
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	04/18/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	3
Tank ID:	216873
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	570
Install Date:	Not reported
Date Tank Closed:	04/18/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

SAFEGUARD SELF-STORAGE (Continued) **U004107531**

Tank Number:	4
Tank ID:	216874
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	570
Install Date:	Not reported
Date Tank Closed:	04/18/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

G79 **EMPIRE VALLEY LLC** **NY AST** **U003395747**
SE **110 EMPIRE BOULEVARD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.134 mi.
705 ft. **Site 10 of 10 in cluster G**

Relative:
Lower

Actual:
69 ft.

AST:

Name:	EMPIRE VALLEY LLC
Address:	110 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-600775
Program Type:	PBS
UTM X:	588036.50122
UTM Y:	4501902.03581
Expiration Date:	02/28/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	22752
Affiliation Type:	Facility Operator
Company Name:	EMPIRE VALLEY LLC
Contact Type:	Not reported
Contact Name:	ISAAC POLLAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 680-5393
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-05-29

EMPIRE VALLEY LLC (Continued) **U003395747**

Site Id:	22752
Affiliation Type:	Emergency Contact
Company Name:	EMPIRE VALLEY LLC
Contact Type:	Not reported
Contact Name:	ISAAC POLLAK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 680-5393
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-05-29

Site Id:	22752
Affiliation Type:	Facility Owner
Company Name:	EMPIRE VALLEY LLC
Contact Type:	MEMBER
Contact Name:	ISAAC POLLAK
Address1:	93 MONTROSE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(347) 680-5393
EMail:	CP0193@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2022-05-12

Site Id:	22752
Affiliation Type:	Mail Contact
Company Name:	EMPIRE VALLEY LLC
Contact Type:	MEMBER
Contact Name:	ISAAC POLLAK
Address1:	93 MONTROSE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(347) 680-5393
EMail:	CP0193@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2022-05-12

Tank Info:

Tank Number:	001
Tank Id:	43711
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

EMPIRE VALLEY LLC (Continued) **U003395747**

Equipment Records:

	L09 - Piping Leak Detection - Exempt Suction Piping
	H00 - Tank Leak Detection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1995
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

J80 **915 WASHINGTON AVE** **NY UST** **U004332696**
NNW **915 WASHINGTON AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.134 mi.
705 ft. **Site 1 of 7 in cluster J**

Relative: Higher
Actual: 115 ft.

UST:

Name:	915 WASHINGTON AVE
Address:	915 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-290408 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/12/2026
UTM X:	587768.39822
UTM Y:	4502363.15796
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	13121
Affiliation Type:	Facility Operator
Company Name:	915 WASHINGTON AVE
Contact Type:	Not reported
Contact Name:	RON DE SILVA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

915 WASHINGTON AVE (Continued) **U004332696**

Phone:	(646) 235-6077
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-28

Site Id:	13121
Affiliation Type:	Emergency Contact
Company Name:	915 REALTY LLC
Contact Type:	Not reported
Contact Name:	EDWARD SUAZO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 238-6994
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-28

Site Id:	13121
Affiliation Type:	Mail Contact
Company Name:	915 REALTY LLC
Contact Type:	MEMBER
Contact Name:	MEIR BOUSKILA
Address1:	P.O. BOX 1919
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116
Country Code:	001
Phone:	(212) 564-2111
EMail:	CHRISTINA@PINNACLENY.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-11-17

Site Id:	13121
Affiliation Type:	Facility Owner
Company Name:	915 REALTY LLC
Contact Type:	AGENT
Contact Name:	ISAK RADONCIC
Address1:	P.O. BOX 1919
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116
Country Code:	001
Phone:	(212) 564-2111
EMail:	CHRISTINA@PINNACLENY.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-11-18

915 WASHINGTON AVE (Continued) **U004332696**

Tank Info:

Tank Number:	001
Tank ID:	18972
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	03/18/1956
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
B01 - Tank External Protection - Painted/Asphalt Coating
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None

81
SSE
1/8-1/4
0.134 mi.
707 ft.

CON EDISON **NY MANIFEST** **S116044176**
35 STERLING ST **N/A**
BROOKLYN, NY 11225

Relative:
Lower

Actual:
74 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	35 STERLING ST
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004405700
Facility Status:	Not reported
Location Address 1:	35 STERLING ST
Code:	BP
Location Address 2:	SB48081
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

CON EDISON (Continued) **S116044176**

NY MANIFEST:

EPAID:	NYP004405700
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/13/2013
Trans1 Recv Date:	12/13/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004405700
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300439GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S116044176**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I82 **CON ED - VS 5973** **RCRA NonGen / NLR** **1007205399**
NNE **CROWN ST & FRANKLIN AVE** **NY MANIFEST** **NYP000930602**
1/8-1/4 **BROOKLYN, NY 11235**
0.134 mi.
708 ft. **Site 6 of 6 in cluster I**

Relative: **Higher**

Actual: **106 ft.**

RCRA Listings:

Date Form Received by Agency:		19980228
Handler Name:	CON ED - VS 5973	
Handler Address:		CROWN ST & FRANKLIN AVE
Handler City,State,Zip:		BROOKLYN, NY 11235-0000
EPA ID:		NYP000930602
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC
Contact City,State,Zip:		NEW YORK, NY 10003-0000
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON ED - VS 5973 (Continued) **1007205399**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - VS 5973	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - VS 5973	
Federal Waste Generator Description:	Not a generator, verified

CON ED - VS 5973 (Continued) **1007205399**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED - VS 5973
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON CO
Address: CROWN ST & FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11235-0000
Country: USA
EPA ID: NYP000930602
Facility Status: Not reported
Location Address 1: VS2988-FOOTHILL AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000930602
Mailing Name: CONSOLIDATED EDISON CO

CON ED - VS 5973 (Continued) **1007205399**

Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

H83 **CON EDISON - MANHOLE 63407** **RCRA NonGen / NLR** **1010325953**
South **WASHINGTON AVE & FRANKLIN AVE** **NY MANIFEST** **NYP004136164**
1/8-1/4 **BROOKLYN, NY 11204**
0.137 mi.
725 ft. **Site 11 of 11 in cluster H**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20060223
Handler Name:	CON EDISON - MANHOLE 63407
Handler Address:	WASHINGTON AVE & FRANKLIN AVE
Handler City,State,Zip:	BROOKLYN, NY 11204
EPA ID:	NYP004136164
Contact Name:	FRANKLIN MURRAY
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

Actual:
77 ft.

CON EDISON - MANHOLE 63407 (Continued) **1010325953**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private

CON EDISON - MANHOLE 63407 (Continued) **1010325953**

Date Became Current: 20050513
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050513
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050513
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050513
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060222
Handler Name: CON EDISON - MANHOLE 63407
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

CON EDISON - MANHOLE 63407 (Continued) **1010325953**

Electronic Manifest Broker: Not reported

Receive Date: 20060223
Handler Name: CON EDISON - MANHOLE 63407
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - MANHOLE 63407
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: WASHINGTON AVE & FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11204
Country: USA
EPA ID: NYP004136164
Facility Status: Not reported
Location Address 1: WASHINGTON AVE MH63407
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

CON EDISON - MANHOLE 63407 (Continued) **1010325953**

NY MANIFEST:

EPAID:	NYP004136164
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

K84 **TANK TEST** **NY LTANKS** **S118263465**
North **49 CROWN ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.138 mi.
727 ft. **Site 1 of 2 in cluster K**

Relative: **Higher**

Actual: **100 ft.**

LTANKS:

Name:	TANK TEST
Address:	49 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1505659 / 2015-10-09
Facility ID:	1505659
Site ID:	513042
Spill Date:	2015-08-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2015-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-08-26
Spill Record Last Update:	2015-10-09
Spiller Name:	ERIK DEITZ
Spiller Company:	WCC
Spiller Address:	49 CROWN ST
Spiller County:	999
Spiller Contact:	ERIK DEITZ
Spiller Phone:	8455649555
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	467580
DEC Memo:	"09/01/15-Hiralkumar Patel. alternate address: 43-65 Crown Street, 900 Franklin Ave no other spills found. PBS #: 2-032956. as per PBS

TANK TEST (Continued) **S118263465**

record, the site has one (1) 20,000 gal #2 oil UST, in-service, installed in Nov. 1973. 3:08 PM:- spoke with Erik. he mentioned that a dry leak was found due to a loose connection of fill line on top of the tank. 3:15 PM:- spoke with Ms. Vazquez. she mentioned that there is no product level drop in the tank. they have hired a contractor who will fix and retest the tank system by 09/04/15. asked her to submit report by the end of 09/04/15. Tivoli Towers Housing Co. Inc. **property owner** c/o Stellar Management 156 William Street, 10th Floor New York, NY 10038 Attn.: Katina Vazquez Ph. (212) 843-3783 email: kvazquez@stellarmanagement.com 3:22 PM:- sent email to Ms. Vazquez and asked her to submit result of system retest by the end of 09/04/15. 09/16/15-Hiralkumar Patel. 10:22 AM:- spoke with Ms. Vazquez. she mentioned that the loose fill line connection was fixed earlier and they are conducting system retest today. she will submit result once available. 10:23 AM:- sent email to Ms. Vazquez. 1:58 PM:- received call from Eric from tank testing company. he mentioned that the tank system passed the retest. 10/09/15-Hiralkumar Patel. 3:27 PM:- sent email to Ms. Vazquez and asked her to submit report immediately. 3:39 PM:- received email from Ms. Vazquez including closure report. as per the report, tank system failed the test due to damaged coupling in the fill line. there was no petroleum impacted soil noted during tank repair activities. tank system was tested tight on 06/16/15. case closed. 3:54 PM:- sent email to Ms. Vazquez informing about case closure."

Remarks: "Loose fill stick line"

All Materials:

Site ID:	513042
Operable Unit ID:	1262274
Operable Unit:	01
Material ID:	2265794
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

K85 **TIVOLI TOWERS & TIVOLI BI LLC** **NY UST** **U000407643**
North **49 CROWN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.138 mi.
727 ft. **Site 2 of 2 in cluster K**

Relative:
Higher

Actual:
100 ft.

UST:

Name:	TIVOLI TOWERS & TIVOLI BI LLC
Address:	49 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-032956 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/28/2025
UTM X:	587880.44043
UTM Y:	4502365.20678

TIVOLI TOWERS & TIVOLI BI LLC (Continued) **U000407643**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 257
Affiliation Type: Facility Owner
Company Name: TIVOLI BI LLC
Contact Type: COMPLIANCE ADMINISTRATOR
Contact Name: KATINA V VAZQUEZ
Address1: 156 WILLIAM STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 406-0030
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-12-17

Site Id: 257
Affiliation Type: Mail Contact
Company Name: STELLAR MANAGEMENT
Contact Type: Not reported
Contact Name: KATINA V VAZQUEZ
Address1: 156 WILLIAM STREET
Address2: 10TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10038
Country Code: 001
Phone: (212) 843-3783
EMail: KVAZQUEZ@STELLARMANAGEMENT.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-09-06

Site Id: 257
Affiliation Type: Facility Operator
Company Name: TIVOLI TOWERS & TIVOLI BI LLC
Contact Type: Not reported
Contact Name: ABDUL WALI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 895-3048
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-09-24

Site Id: 257
Affiliation Type: Emergency Contact
Company Name: TIVOLI TOWERS & TIVOLI BI LLC
Contact Type: Not reported

TIVOLI TOWERS & TIVOLI BI LLC (Continued) **U000407643**

Contact Name:	NITI JAKUPAJ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(973) 418-3783
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-02-01

Tank Info:

Tank Number:	001
Tank ID:	27142
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	20000
Install Date:	11/01/1973
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	04/15/2021
Next Test Date:	04/15/2022
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

L86
SSW
1/8-1/4
0.140 mi.
738 ft.

CON EDISON
475 FLATBUSH AVE SB26697
BROOKLYN, NY 11225

Site 1 of 17 in cluster L

NJ MANIFEST **S120667460**
N/A

Relative:
Lower

Actual:
80 ft.

NJ MANIFEST:

EPA Id:	NYP004733788
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002620696GBF
EPA ID:	NYP004733788
Date Shipped:	2/18/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667460**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L87 **CON EDISON** **RCRA NonGen / NLR** **1018278600**
SSW **475 FLATBUSH AVE SB26702** **NYP004733796**
1/8-1/4 **BROOKLYN, NY 11225**
0.140 mi.
738 ft. **Site 2 of 17 in cluster L**

Relative: **Lower**
Actual: **80 ft.**

RCRA Listings:

Date Form Received by Agency:		20150218
Handler Name:	CON EDISON	
Handler Address:		475 FLATBUSH AVE SB26702
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004733796
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON (Continued) **1018278600**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150218
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150218
Handler Name: CON EDISON	

CON EDISON (Continued) **1018278600**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

L88 **CON EDISON** **RCRA NonGen / NLR** **1018278599**
SSW **475 FLATBUSH AVE SB26702** **FINDS** **NYP004733788**
1/8-1/4 **BROOKLYN, NY 11225** **ECHO**
0.140 mi.
738 ft. **Site 3 of 17 in cluster L**

Relative: **Lower**
Actual: **80 ft.**

RCRA Listings:

Date Form Received by Agency:		20150218
Handler Name:	CON EDISON	
Handler Address:		475 FLATBUSH AVE SB26697
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004733788
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No

CON EDISON (Continued) **1018278599**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1018278599**

Historic Generators:
Receive Date: 20150218
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150218
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067707949

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278599
Registry ID: 110067707949

CON EDISON (Continued) **1018278599**

DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067707949
Name:	CON EDISON
Address:	475 FLATBUSH AVE SB26702
City,State,Zip:	BROOKLYN, NY 11225

L89 **CON EDISON** **NY MANIFEST** **S117740220**
SSW **475 FLATBUSH AVE SB26702** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.140 mi.
738 ft. **Site 4 of 17 in cluster L**

Relative:
Lower

Actual:
80 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	475 FLATBUSH AVE SB26702
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004733796
Facility Status:	Not reported
Location Address 1:	OPP 475 FLATBUSH AVE
Code:	BP
Location Address 2:	SB 26702
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004733796
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/18/2015
Trans1 Recv Date:	02/18/2015
Trans2 Recv Date:	02/24/2015
TSD Site Recv Date:	02/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004733796
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117740220**

Manifest Tracking Number:	002620697GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L90 **CON EDISON** **NY MANIFEST** **S117740219**
SSW **475 FLATBUSH AVE SB26697** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.140 mi.
738 ft. **Site 5 of 17 in cluster L**

Relative:
Lower

Actual:
80 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	475 FLATBUSH AVE SB26697
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004733788
Facility Status:	Not reported
Location Address 1:	475 FLATBUSH AVE
Code:	BP
Location Address 2:	SB 26697
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004733788
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING

CON EDISON (Continued) **S117740219**

Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/18/2015
Trans1 Recv Date:	02/18/2015
Trans2 Recv Date:	02/24/2015
TSD Site Recv Date:	02/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004733788
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620696GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L91
SSW
1/8-1/4
0.140 mi.
738 ft.

CON EDISON
475 FLATBUSH AVE SB26702
BROOKLYN, NY 11225

Site 6 of 17 in cluster L

NJ MANIFEST **S120667461**
N/A

Relative:
Lower

Actual:
80 ft.

NJ MANIFEST:

EPA Id:	NYP004733796
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002620697GBF
EPA ID:	NYP004733796
Date Shipped:	2/18/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120667461**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

M92 **LEFFERTS HOMESTEAD** **RCRA NonGen / NLR** **1000889993**
SW **440 FLATBUSH AVE** **FINDS** **NY0000204420**
1/8-1/4 **BROOKLYN, NY 11225** **ECHO**
0.140 mi. **NY MANIFEST**
739 ft. **Site 1 of 2 in cluster M**

Relative: **Lower**
Actual: **89 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	LEFFERTS HOMESTEAD	
Handler Address:		440 FLATBUSH AVE
Handler City,State,Zip:		BROOKLYN, NY 11225-3707
EPA ID:		NY0000204420
Contact Name:		Not reported
Contact Address:		PROSPECT PARK W
Contact City,State,Zip:		BROOKLYN, NY 11215
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		PROSPECT PARK W
Mailing City,State,Zip:		BROOKLYN, NY 11215
Owner Name:	NYC PARKS RECREATION - PROSPECT PARK	
Owner Type:		Private
Operator Name:	NYC PARKS RECREATION - PROSPECT PARK	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

LEFFERTS HOMESTEAD (Continued) **1000889993**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC PARKS RECREATION - PROSPECT PARK
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	95 PROSPECT PARK W
Owner/Operator City,State,Zip:	BROOKLYN, NY 11215

LEFFERTS HOMESTEAD (Continued) **1000889993**

Owner/Operator Telephone: 718-965-6505
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC PARKS RECREATION - PROSPECT PARK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 95 PROSPECT PARK W
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-965-6505
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC PARKS RECREATION - PROSPECT PARK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 95 PROSPECT PARK W
Owner/Operator City,State,Zip: BROOKLYN, NY 11215
Owner/Operator Telephone: 718-965-6505
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: LEFFERTS HOMESTEAD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: LEFFERTS HOMESTEAD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101

LEFFERTS HOMESTEAD (Continued) **1000889993**

Handler Name: LEFFERTS HOMESTEAD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940412
Handler Name: LEFFERTS HOMESTEAD
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004313920

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000889993
Registry ID: 110004313920
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004313920
Name: LEFFERTS HOMESTEAD

LEFFERTS HOMESTEAD (Continued) **1000889993**

Address: 440 FLATBUSH AVE
City,State,Zip: BROOKLYN, NY 11225

NY MANIFEST:
Name: LEFFERTS HOMESTEAD
Address: 440 FLATBUSH AVE
City,State,Zip: BROOKLYN, NY 11225-3707
Country: USA
EPA ID: NY0000204420
Facility Status: Not reported
Location Address 1: 440 FLATBUSH AVE PROSPECT PARK
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000204420
Mailing Name: LEFFERTS HOMESTEAD
Mailing Contact: V SHAFFER
Mailing Address 1: 440 FLATBUSH AVE PROSPECT PARK
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7188945656

J93 **35 CROWN STREET HDFC** **NY AST** **U003393938**
North **35 CROWN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.141 mi.
742 ft. **Site 2 of 7 in cluster J**

Relative:
Higher

Actual:
114 ft.

AST:
Name: 35 CROWN STREET HDFC
Address: 35 CROWN STREET
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-347825
Program Type: PBS
UTM X: 587853.71982
UTM Y: 4502372.01254
Expiration Date: 04/05/2023
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 17060
Affiliation Type: Facility Operator
Company Name: 35 CROWN STREET HDFC
Contact Type: Not reported

35 CROWN STREET HDFC (Continued) **U003393938**

Contact Name:	MIKE ALLISANI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 783-5503
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-04-02

Site Id:	17060
Affiliation Type:	Emergency Contact
Company Name:	35 CROWN STREET HDFC
Contact Type:	Not reported
Contact Name:	MIKE ALLISANI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 600-7206
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-04-02

Site Id:	17060
Affiliation Type:	Mail Contact
Company Name:	A MICHAEL TYLER REALTY CORP
Contact Type:	Not reported
Contact Name:	MIKE ALLISANI/MARITA JOSEPH
Address1:	821 W JERICHO TURNPIKE, SUITE 113
Address2:	Not reported
City:	SMITHTOWN
State:	NY
Zip Code:	11787
Country Code:	001
Phone:	(877) 641-5900
EMail:	MARITAJ@AMTREALTY.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-04-02

Site Id:	17060
Affiliation Type:	Facility Owner
Company Name:	35 CROWN STREET HDFC
Contact Type:	AGENT
Contact Name:	MARITA JOSEPH
Address1:	35 CROWN ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225

35 CROWN STREET HDFC (Continued) **U003393938**

Country Code:	001
Phone:	(718) 788-7900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2018-04-02

Tank Info:

Tank Number:	001
Tank Id:	33206
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/15/1975
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

J94 **12 CROWN STREET** **NY AST** **U003386007**
NNW **12 CROWN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.141 mi.
744 ft. **Site 3 of 7 in cluster J**

Relative:
Higher

Actual:
116 ft.

AST:

Name:	12 CROWN STREET
Address:	12 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active

12 CROWN STREET (Continued) **U003386007**

Facility Id: 2-273716
Program Type: PBS
UTM X: 587850.01664
UTM Y: 4502346.52633
Expiration Date: 05/17/2024
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 11658
Affiliation Type: Emergency Contact
Company Name: 12 REALTY ASSOCIATES LLC
Contact Type: Not reported
Contact Name: EDWARD SUAZO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 235-6994
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2016-10-28

Site Id: 11658
Affiliation Type: Mail Contact
Company Name: 12 REALTY ASSOCIATES LLC
Contact Type: OFFICER
Contact Name: MEIR BOUSKILA
Address1: P.O. BOX 1919
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10116
Country Code: 001
Phone: (212) 564-2111
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-12-31

Site Id: 11658
Affiliation Type: Facility Owner
Company Name: THE 12 CROWN CONDOMINIUM
Contact Type: AGENT
Contact Name: ISAK RADONCIK
Address1: 1 PENN PLAZA SUITE 4000
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10116
Country Code: 001
Phone: (212) 564-2111
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-01-26

12 CROWN STREET (Continued) **U003386007**

Site Id:	11658
Affiliation Type:	Facility Operator
Company Name:	12 CROWN STREET
Contact Type:	Not reported
Contact Name:	RODERICK HARRIGAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 235-5466
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-26

Tank Info:

Tank Number:	001
Tank Id:	8991
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	I04 - Overfill - Product Level Gauge (A/G)
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1994
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

N95 **EBBETS FIELD APARTMENTS** **NY UST** **1000550104**
East **1720 BEDFORD AVENUE** **NY AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.142 mi.
748 ft. **Site 1 of 3 in cluster N**

Relative:
Lower

Actual:
85 ft.

UST:

Name:	EBBETS FIELD APTS
Address:	1720 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-152072 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588096.21316
UTM Y:	4502101.63782
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	4737
Affiliation Type:	Emergency Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	JOEL ZEU DRILIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 756-2425
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kxtang
Date Last Modified:	2004-03-23

Site Id:	4737
Affiliation Type:	Facility Operator
Company Name:	EBBETS FIELD APTS
Contact Type:	Not reported
Contact Name:	FIELDBRIDGE ASSOCIATES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 756-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kxtang
Date Last Modified:	2004-03-23

Site Id:	4737
Affiliation Type:	Mail Contact
Company Name:	FIELDBRIDGE ASSOCIATES, LLC
Contact Type:	MANAGING AGENT
Contact Name:	DAVID SCHMELCZER
Address1:	1720 BEDFORD AVE.

EBBETS FIELD APARTMENTS (Continued) **1000550104**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 314-0574
EMail:	DAVID@FIELDBRIDGELLC.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-02-04

Site Id:	4737
Affiliation Type:	Facility Owner
Company Name:	FIELDBRIDGE ASSOCIATES
Contact Type:	MANAGER
Contact Name:	BOWMAN BAIM
Address1:	1720 BEDFORD AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 756-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-02-04

Tank Info:

Tank Number:	001
Tank ID:	178311
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	30000
Install Date:	01/01/1962
Date Tank Closed:	12/13/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

EBBETS FIELD APARTMENTS (Continued) **1000550104**

F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J05 - Dispenser - On Site Heating System (Supply/Return)

Tank Number: 002
Tank ID: 8767
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 30000
Install Date: 12/01/1962
Date Tank Closed: 12/13/2018
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J05 - Dispenser - On Site Heating System (Supply/Return)

AST:
Name: EBBETS FIELD APARTMENTS
Address: 1720 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Inactive
Facility Id: 2-152064
Program Type: PBS
UTM X: 588140.76650
UTM Y: 4502148.73590
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 4736

EBBETS FIELD APARTMENTS (Continued) **1000550104**

Affiliation Type:	Facility Owner
Company Name:	NEW FIELD HOUSING CO INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1720 BEDFORD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 756-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4736
Affiliation Type:	Mail Contact
Company Name:	COASTAL COMBUSTION CORP
Contact Type:	Not reported
Contact Name:	MIKE LACERTOSA
Address1:	314 JERICHO TPKE
Address2:	Not reported
City:	FLORAL PARK
State:	NY
Zip Code:	11001
Country Code:	001
Phone:	(212) 475-4263
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4736
Affiliation Type:	Facility Operator
Company Name:	EBBETS FIELD APARTMENTS
Contact Type:	Not reported
Contact Name:	ARCO MNGT CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 756-2400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4736
Affiliation Type:	Emergency Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	JOEL ZEU DRILIN
Address1:	Not reported
Address2:	Not reported

EBBETS FIELD APARTMENTS (Continued) **1000550104**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 756-2425
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kxtang
Date Last Modified:	2004-03-23

Tank Info:

Tank Number:	001
Tank Id:	8766
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
G07 - Tank Secondary Containment - Excavation Liner

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	12/01/1962
Capacity Gallons:	30000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/18/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

L96 **CON EDISON - MANHOLE 23416** **NY MANIFEST** **S120958411**
SW **2-26 EMPIRE BLVD** **N/A**
1/8-1/4 **BROOKYN, NY 11225**
0.150 mi.
791 ft. **Site 7 of 17 in cluster L**

Relative: **Lower**
Actual: **86 ft.**

NY MANIFEST:

Name:	CON EDISON - MANHOLE 23416
Address:	2-26 EMPIRE BLVD
City,State,Zip:	BROOKYN, NY 11225
Country:	USA
EPA ID:	NYP004935332
Facility Status:	Not reported
Location Address 1:	2-26 EMPIRE BLVD

CON EDISON - MANHOLE 23416 (Continued) **S120958411**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004935332
Mailing Name: CON EDISON - MANHOLE 23416
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

O97 **CON EDISON** **NY MANIFEST** **S119073699**
SW **FLATBUSH AVE & EMPIRE BLVD NE** **N/A**
1/8-1/4 **BROOKLYN, NY 11226**
0.150 mi.
791 ft. **Site 1 of 5 in cluster O**

Relative:
Lower

Actual:
86 ft.

NY MANIFEST:
Name: CON EDISON
Address: FLATBUSH AVE & EMPIRE BLVD NE
City,State,Zip: BROOKLYN, NY 11226
Country: USA
EPA ID: NYP004334355
Facility Status: Not reported
Location Address 1: NEC FLATBUSHA VE / EMPIRE BLVR
Code: BP
Location Address 2: D
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11226
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004334355
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

CON EDISON (Continued) **S119073699**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/2013
Trans1 Recv Date:	07/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004334355
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002018168GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O98 **CON EDISON - MANHOLE 4762** **RCRA-LQG** **1016961017**
SW **NEC FLATBUSH AVE / OCEAN AVE** **NY MANIFEST** **NYP004334413**
1/8-1/4 **BROOKLYN, NY 11226**
0.150 mi.
791 ft. **Site 2 of 5 in cluster O**

Relative: **Lower**
Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 4762
Handler Address:	NEC FLATBUSH AVE / OCEAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11226
EPA ID:	NYP004334413
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	401-765-1500
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON - MANHOLE 4762 (Continued) **1016961017**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130724
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private

CON EDISON - MANHOLE 4762 (Continued) **1016961017**

Date Became Current:	20130724
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - MANHOLE 4762
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130724
Handler Name:	CON EDISON MANHOLE: 4762
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130824
Handler Name:	CON EDISON MANHOLE: 4762
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON - MANHOLE 4762 (Continued) **1016961017**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	FLATBUSH AVE & OCEAN AVE NE
City,State,Zip:	BROOKLYN, NY 11226
Country:	USA
EPA ID:	NYP004334413
Facility Status:	Not reported
Location Address 1:	NEC FLATBUSH AVE / OCEAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11226
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004334413
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/24/2013
Trans1 Recv Date:	07/24/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004334413
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002018108GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

CON EDISON - MANHOLE 4762 (Continued) **1016961017**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O99 **PROSPECT PARK - PARADE** **NY LTANKS** **S104950800**
SW **FLATBUSH AND OCEAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.150 mi.
791 ft. **Site 3 of 5 in cluster O**

Relative: LTANKS:
Lower

Name:	PROSPECT PARK - PARADE
Address:	FLATBUSH AND OCEAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0011106 / 2005-05-06
Facility ID:	0011106
Site ID:	228332
Spill Date:	2001-01-11
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-01-11
CID:	207
Water Affected:	Not reported
Spill Notifier:	Police Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-11

Actual:
86 ft.

PROSPECT PARK - PARADE (Continued) **S104950800**

Spill Record Last Update:	2006-07-05
Spiller Name:	Not reported
Spiller Company:	RAPID OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ART DECESARIO
Spiller Phone:	(718) 389-9286
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	188333
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks:	"CONTACT # FOR REP ON SITE 917 337-4693 CLEANUP CREW CONTACTED AND RESPONDING"

All Materials:

Site ID:	228332
Operable Unit ID:	833162
Operable Unit:	01
Material ID:	541428
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O100 **CON EDISON - MANHOLE 26693** **RCRA-LQG** **1016961013**
SW **NEC FLATBUSHA VE / EMPIRE BLVR** **NYP004334355**
1/8-1/4 **BROOKLYN, NY 11226**
0.150 mi.
791 ft. **Site 4 of 5 in cluster O**

Relative: **Lower**

Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 26693
Handler Address:	NEC FLATBUSHA VE / EMPIRE BLVR
Handler City,State,Zip:	BROOKLYN, NY 11226
EPA ID:	NYP004334355
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	401-765-1500
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2

CON EDISON - MANHOLE 26693 (Continued) **1016961013**

Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON - MANHOLE 26693 (Continued) **1016961013**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130724
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20130724
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - MANHOLE 26693
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130724
Handler Name: CON EDISON MANHOLE: 26693

CON EDISON - MANHOLE 26693 (Continued) **1016961013**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130824
Handler Name:	CON EDISON MANHOLE: 26693
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

O101 **CON EDISON - MANHOLE 36914** **NJ MANIFEST** **S120670675**
SW **OCEAN AVE & FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.150 mi.
791 ft. **Site 5 of 5 in cluster O**

Relative: NJ MANIFEST:
Lower

Actual: EPA Id:	NYP004770160
86 ft. Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported

CON EDISON - MANHOLE 36914 (Continued) **S120670675**

Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014085040JJK
EPA ID:	NYP004770160
Date Shipped:	4/17/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J102 **15 CROWN STREET LLC** **NY AST** **U003387412**
NNW **15 CROWN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.150 mi.
793 ft. **Site 4 of 7 in cluster J**

Relative:
Higher

Actual:
118 ft.

AST:

Name:	15 CROWN STREET LLC
Address:	15 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE

15 CROWN STREET LLC (Continued) **U003387412**

DEC Region: 2
Site Status: Active
Facility Id: 2-252220
Program Type: PBS
UTM X: 587818.57240
UTM Y: 4502381.23766
Expiration Date: 02/02/2026
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 10155
Affiliation Type: Facility Operator
Company Name: 15 CROWN STREET
Contact Type: Not reported
Contact Name: KENYATTA CLARKE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 201-1835
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-06-23

Site Id: 10155
Affiliation Type: Emergency Contact
Company Name: BCB 15 CROWN STREET LLC
Contact Type: Not reported
Contact Name: KENYATTA CLARKE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 756-2252
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-01-04

Site Id: 10155
Affiliation Type: Facility Owner
Company Name: 15 CROWN STREET LLC
Contact Type: VP PROPERTY MANAGEMENT
Contact Name: TARRIN WYNTER
Address1: 111 GREAT NECK ROAD, SUITE 408
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11201
Country Code: 001
Phone: (516) 504-2210
EMail: Not reported
Fax Number: Not reported

15 CROWN STREET LLC (Continued) **U003387412**

Modified By:	JSMACRI
Date Last Modified:	2021-01-04
Site Id:	10155
Affiliation Type:	Mail Contact
Company Name:	STERLING EQUITIES
Contact Type:	Not reported
Contact Name:	TARRIN WYNTER
Address1:	111 GREAT NECK ROAD
Address2:	SUITE 408
City:	GREAT NECK
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(516) 504-2210
EMail:	TARRIN@STERL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-01-13

Tank Info:

Tank Number:	001
Tank Id:	11828
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K00 - Spill Prevention - None
	I04 - Overfill - Product Level Gauge (A/G)
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1935
Capacity Gallons:	4500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

L103 **CONSOLIDATED EDISON INC - MH4514** **RCRA NonGen / NLR** **1027473468**
South **SE STERLING PL & WASHINGTON AVE** **NYP004034666**
1/8-1/4 **BROOKLYN, NY 11225**
0.151 mi.
799 ft. **Site 8 of 17 in cluster L**

Relative: **Lower**
Actual: **76 ft.**

RCRA Listings:

Date Form Received by Agency:		20010103
Handler Name:	CONSOLIDATED EDISON INC - MH4514	
Handler Address:		SE STERLING PL & WASHINGTON AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004034666
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		IRVING PL ROOM 300
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL ROOM 300
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CONSOLIDATED EDISON INC - MH4514 (Continued) **1027473468**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20220829
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20010102
Handler Name: MH4514	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010103
Handler Name: CONSOLIDATED EDISON INC - MH4514	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No

CONSOLIDATED EDISON INC - MH4514 (Continued) **1027473468**

Electronic Manifest Broker: No

Receive Date: 20010101
Handler Name: MH4514
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

L104 **CON ED-MH4514** **NY MANIFEST** **S109064667**
South **WASHINGTON AVE & STERLING PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.151 mi.
799 ft. **Site 9 of 17 in cluster L**

Relative: **Lower**
Actual: **76 ft.**

NY MANIFEST:
Name: CON ED-MH4514
Address: WASHINGTON AVE & STERLING PL
City,State,Zip: BROOKLYN, NY 11225
Country: USA
EPA ID: NYZ004019030
Facility Status: Not reported
Location Address 1: WASHINGTON AVE & STERLING PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: 0000

NY MANIFEST:
EPAID: NYZ004019030
Mailing Name: CON ED-MH4514
Mailing Contact: Not reported
Mailing Address 1: Not reported
Mailing Address 2: Not reported

CON ED-MH4514 (Continued) **S109064667**

Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

L105 **CON EDISON - MANHOLE 58809** **RCRA NonGen / NLR** **1010325961**
South **WASHINGTON AVE AND STERLING ST** **NY MANIFEST** **NYP004136230**
1/8-1/4 **BROOKLYN, NY 11201**
0.151 mi.
799 ft. **Site 10 of 17 in cluster L**

Relative: **Lower**
Actual: **76 ft.**

RCRA Listings:

Date Form Received by Agency:	20060223
Handler Name:	CON EDISON - MANHOLE 58809
Handler Address:	WASHINGTON AVE AND STERLING ST
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004136230
Contact Name:	FRANKLIN MURRAY
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported

CON EDISON - MANHOLE 58809 (Continued) **1010325961**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050512
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE

CON EDISON - MANHOLE 58809 (Continued) **1010325961**

Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050512
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050512
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050512
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060222
Handler Name: CON EDISON - MANHOLE 58809
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060223

CON EDISON - MANHOLE 58809 (Continued) **1010325961**

Handler Name: CON EDISON - MANHOLE 58809
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - MANHOLE 58809
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: WASHINGTON AVE AND STERLING ST
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004136230
Facility Status: Not reported
Location Address 1: WASHINGTON & STERLING MH58809
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004136230
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY

CON EDISON - MANHOLE 58809 (Continued) **1010325961**

Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

L106 **WAREHOUSE/PHAT ALBERTS** **NY LTANKS** **S105995627**
SSW **495 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.153 mi.
806 ft. **Site 11 of 17 in cluster L**

Relative: LTANKS:
Lower

Actual:
83 ft.

Name:	WAREHOUSE/PHAT ALBERTS
Address:	495 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0200458 / 2011-06-08
Facility ID:	0200458
Site ID:	284946
Spill Date:	2002-04-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2002-04-12
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-12
Spill Record Last Update:	2011-06-08
Spiller Name:	MATT BOECKEL /
Spiller Company:	WAREHOUSE
Spiller Address:	495 FLAT BUSH RD
Spiller County:	001
Spiller Contact:	T J OCONNOR
Spiller Phone:	(516) 678-5115
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	231072
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 11/14/2002 TIPPLE 10,000 GAL #2 FO TANK IN BASEMENT EXCAVATION AND RETEST TO FOLLOW. POSSIBLY 2 ADDITIONAL ABANDON TANKS FOUND DURING MAGNETIC SURVEY OF THE SITE. A SITE MEETING HAS BEEN SET FOR MONDAY NOV.25 TO ASSESS THE SITE. REGISTRATION OF THE 2 NEWLY DISCOVERED UNITS WILL FOLLOW ONCE THE INVESTIGATION REVFEALS THEIR TRUE IDENTITY. 12/03/2002 site visit suggests further investigation

WAREHOUSE/PHAT ALBERTS (Continued) **S105995627**

Remarks:	of two abandon tanks necessary in order to determine if contamination exists, The 10,000 gal tank/piping must be separated and retested. Matt Boeckel 516-984-0191 7/13/03 Tipple spoke with Matt Boeckel// 2 abandon tanks encased in conc. tight to foundation wall and column footings, after numerous attempts two successful samples were taken / contractor to take two additional samples from the sand from within the tanks// if petroleum/sand mixture found in the tanks they will be cleaned and tanks will be refilled with clean material. the 10,000 gal tank to be abandon in place/ 2 bottom and 4 sidewall samples to be taken. Transferred to CO (MJSCIBEL) 03/29/06 Recommended next: Contact Boeckel, determine if work was completed. 6/29/06 - Mike - Spoke with GCI environmental said project is not complete due to owner stopping at some point. Will be forwarding report asap. 3/30/07 - Austin - Trasferred to Patel for further review - end 05/28/08 Steve Gordon from American Site Restoration@(631)833-0022 called to say they will be doing investigation around the tank,Work Plan will be sent to DEC for approval.(sr) 09/16/09 Performed site visit this morning. The site is a huge two story commercial building.I spoke with owner's rep Marva Sobers over the phone.She said she would look into the file for any tank closure report.TTF was sent to (via facsimile also at (718)486-7545) 495 Flatbush Avenue LLC 774 Broadway Brooklyn, NY 11206 Attn: Marva Sobers (sr) 09/21/10 left messege for Charles Sosik to follow up on the case. He has been retained to perform the soil sampling around the tank.(sr) 06/08/11 Non cooperative owner.No reply received from the owner.Spill was reported in 2002.No indication of subsurface contamination. Case closed.(sr)"
Remarks:	"RECOMMEND TANK ONLY TEST."

All TTF:

Facility ID:	0200458
Spill Number:	0200458
Spill Tank Test:	1527038
Site ID:	284946
Tank Number:	Not reported
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	284946
Operable Unit ID:	851451
Operable Unit:	01
Material ID:	521899
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

WAREHOUSE/PHAT ALBERTS (Continued) **S105995627**

Units: G
Recovered: .00
Oxygenate: Not reported

M107 **TTF PROSPECT PARK ZOO** **NY LTANKS** **S106719446**
SW **450 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.154 mi.
815 ft. **Site 2 of 2 in cluster M**

Relative: **Higher**
Actual: **90 ft.**

LTANKS:

Name:	PROSPECT ZOO
Address:	450 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0404814 / 2006-03-01
Facility ID:	0404814
Site ID:	132092
Spill Date:	2004-08-03
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SXSCHARF
Referred To:	Not reported
Reported to Dept:	2004-08-03
CID:	444
Water Affected:	AND STORM DRAIN
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-03
Spill Record Last Update:	2006-03-28
Spiller Name:	BRENDA BURBACH
Spiller Company:	PROSPECT ZOO
Spiller Address:	450 FLATBUSH AVE
Spiller County:	001
Spiller Contact:	BRENDA BURBACH
Spiller Phone:	(718) 220-7153
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	113778
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 8/3/04 Sangesland spoke to Brenda Barbach (718-399-7310) the new environmental compliance officer for the Prospect Zoo. She identified two longterm problem areas: 1) An area where a waste oil drum stood near a floor/sewer drain and had a long term drip problem. Short term fix is an absobsion pad in the drain, also the drum was moved. Long term fix- A new drum storage area will be designed to prevent drips from impacting the ground or sewer. 2) The containment wall around the oil fill port was in poor condition resulting in repeated minor over fills being poured onto the ground right around the fill line. This area will be dug out, and rebuilt to prevent any minor spills from going into the ground. Followup should include a

TTF PROSPECT PARK ZOO (Continued) **S106719446**

site visit and/or a report with photos showing that these two areas have been taken care of. Prosepect Zoo submitted documentation that spill(s) were addressed and spill was closed 3/1/06. S. Scharf Brenda Burbach (718)399-7340. Bronx number (718)220-7153. bburbach@wcs.org"

Remarks: "LOOKS LIKE ITS GOING INTO STORM DRAIN A BOOM HAS BEEN PLACED DOWN: FURTHER INVESTIGATING"

All Materials:

Site ID:	132092
Operable Unit ID:	887788
Operable Unit:	01
Material ID:	488792
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Site ID:	132092
Operable Unit ID:	887788
Operable Unit:	01
Material ID:	488793
Material Code:	0056A
Material Name:	paint thinners
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	TTF PROSPECT PARK ZOO
Address:	450 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1004617 / 2011-03-23
Facility ID:	1004617
Site ID:	437896
Spill Date:	2010-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	BKFALVEY
Referred To:	Not reported
Reported to Dept:	2010-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

TTF PROSPECT PARK ZOO (Continued) **S106719446**

Date Entered In Computer:	2010-07-23
Spill Record Last Update:	2011-03-23
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BRENDA BURBACK
Spiller Phone:	(201) 213-3775
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	392945
DEC Memo:	"10/21/2010 Sangesland spoke to Michael Alletto of Harbor Environmental Corp (516-650-7412) He said that the tank initially failed a system test, then later it failed a tank only test. Harbor pumped out the tank, cleaned it and then took soil samples through the side walls (bottom was into cement). Samples were sent out for lab tests on 10/20/2010 and will be back soon. A temp tank was set up. If the results come back clean, Harbor will request that the tank be abandoned in place. TTF Letter sent to: Michael Alletto Harbor Environmental Corp. PO Box 467 Locust Valley, NY 11560 Fax: 516-609-9802 3/2/11 bf: Sent the following e-mail to brenda Burbach of Bronx Zoo: Brenda, I have yet to receive documentation in response to the 10/21/10 letter for the tank test failure of Tank 002. Please have your consultant respond to this letter. A copy is attached. Brian 3/23/11 Received the following e-mail from Michael Alletto: Hi Brian, 1. The UST is located adjacent to the buildings foundation wall. The underground fuel oil supply (FOS) and fuel oil return (FOR) piping are located within the UST excavation, therefore, no soil samples were collected beneath the piping. 2. A Site/Sampling Plan Figure will be submitted along with the Petroleum Bulk Storage (PBS) Application to the NYSDEC following the completion of the UST Closure Activities once we receive your approval. Should you require additional information, or have any questions, please do not hesitate to contact my office at 212.888.1984 ext. 11 or cellular telephone at 516.650.7412. Best regards, Michael Michael Alletto, President Harbor Environmental Corporation 747 Third Avenue, Third Floor New York, New York 10017 P 212.888.1984 ext. 11 F 212.888.1994 M 516.650.7412 E malletto@harborenvironmental.com ----------end of e-mail---------- NFA. bf "
Remarks:	"removal - all work pending"

All Materials:

Site ID:	437896
Operable Unit ID:	1188559
Operable Unit:	01
Material ID:	2183493
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

J108 **CON EDISON MANHOLE: 58804** **RCRA NonGen / NLR** **1016967832**
NNW **WASHINGTON AVE & CROWN ST** **NY MANIFEST** **NYP004414306**
1/8-1/4 **BROOKLYN, NY 11225**
0.157 mi.
828 ft. **Site 5 of 7 in cluster J**

Relative: **Higher**
Actual: **119 ft.**

RCRA Listings:

Date Form Received by Agency:		20140208
Handler Name:	CON EDISON MANHOLE: 58804	
Handler Address:		WASHINGTON AVE & CROWN ST
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004414306
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON MANHOLE: 58804 (Continued) **1016967832**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140108
Handler Name: CON EDISON MANHOLE: 58804	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140208
Handler Name: CON EDISON MANHOLE: 58804	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 58804 (Continued) **1016967832**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: WASHINGTON AVE & CROWN ST
City,State,Zip: BROOKLYN, NY 11225
Country: USA
EPA ID: NYP004414306
Facility Status: Not reported
Location Address 1: W/INT WASHINGTON AVE AND CROWN
Code: BP
Location Address 2: ST
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004414306
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 01/08/2014
Trans1 Recv Date: 01/08/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/08/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004414306

CON EDISON MANHOLE: 58804 (Continued) **1016967832**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328473GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J109 **CONSOLIDATED EDISON** **NY MANIFEST** **1009244013**
NNW **WASHINGTON & CROWN ST MH4788** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.157 mi.
830 ft. **Site 6 of 7 in cluster J**

Relative: **Higher**

Actual: **119 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	WASHINGTON & CROWN ST MH4788
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004136461
Facility Status:	Not reported
Location Address 1:	WASHINGTON & CROWN ST MH4788
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

CONSOLIDATED EDISON (Continued) **1009244013**

NY MANIFEST:

EPAID:	NYP004136461
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

P110 **FIRESTONE COMPLETE AUTO CARE #000930** **NY AST** **A100293344**
ESE **1730 BEDFORD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.158 mi.
832 ft. **Site 1 of 12 in cluster P**

Relative:
Lower

Actual:
72 ft.

AST:

Name:	FIRESTONE COMPLETE AUTO CARE #000930
Address:	1730 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607835
Program Type:	PBS
UTM X:	588131.61537
UTM Y:	4502012.83938
Expiration Date:	06/14/2022
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	29687
Affiliation Type:	Facility Operator
Company Name:	FIRESTONE COMPLETE AUTO CARE #000930
Contact Type:	Not reported
Contact Name:	ANGEL MORALES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 284-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-03-20

Site Id:	29687
Affiliation Type:	Emergency Contact
Company Name:	BRIDGESTONE RETAIL OPERATIONS, LLC
Contact Type:	Not reported
Contact Name:	ANGEL MORALES (STORE MANAGER)
Address1:	Not reported

FIRESTONE COMPLETE AUTO CARE #000930 (Continued) **A100293344**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 284-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-03-20

Site Id:	29687
Affiliation Type:	Facility Owner
Company Name:	BRIDGESTONE RETAIL OPERATIONS, LLC
Contact Type:	ENVIRONMENTAL MANAGER
Contact Name:	DEBRA HAMLIN
Address1:	123 PARTRIDGE RUN, ATTN: LISA STERNLICT
Address2:	Not reported
City:	SCHENECTADY
State:	NY
Zip Code:	12309
Country Code:	001
Phone:	(518) 370-5454
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-03-20

Site Id:	29687
Affiliation Type:	Mail Contact
Company Name:	BRIDGESTONE RETAIL OPERATIONS, LLC
Contact Type:	Not reported
Contact Name:	DEBRA HAMLIN
Address1:	200 4TH AVENUE SOUTH
Address2:	ATTN: ENVIRONMENTAL DEPT.--BSRO
City:	NASHVILLE
State:	TN
Zip Code:	37201
Country Code:	001
Phone:	(615) 937-9379
EMail:	ENVGEN@BFRC.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-03-20

Tank Info:

Tank Number:	1
Tank Id:	63615
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None

FIRESTONE COMPLETE AUTO CARE #000930 (Continued) **A100293344**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1990
Capacity Gallons:	235
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

L111 **NYCT - FLATBUSH EMPIRE SUBSTATION** **RCRA-LQG** **1012186512**
SSW **479 FLATBUSH AVE** **NYR000163733**
1/8-1/4 **BROOKLYN, NY 11225**
0.158 mi.
834 ft. **Site 12 of 17 in cluster L**

Relative: **Lower**
Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:	20200218
Handler Name:	NYCT - FLATBUSH EMPIRE SUBSTATION
Handler Address:	479 FLATBUSH AVE
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYR000163733
Contact Name:	DANIEL YU
Contact Address:	BROADWAY
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-5777
Contact Fax:	Not reported
Contact Email:	ENVIRONMENTALPROTECTIONNYCT@NYCT.COM
Contact Title:	LEAD SPECIALIST
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2019
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BROADWAY
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	NEW YORK CITY TRANSIT

NYCT - FLATBUSH EMPIRE SUBSTATION (Continued) **1012186512**

Owner Type:	State
Operator Name:	NEW YORK CITY TRANSIT
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20201230
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

NYCT - FLATBUSH EMPIRE SUBSTATION (Continued) **1012186512**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2019

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19320101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-5777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19631201
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19631201
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19320101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-5777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

NYCT - FLATBUSH EMPIRE SUBSTATION (Continued) **1012186512**

Historic Generators:

Receive Date:	20200218
Handler Name:	NYCT - FLATBUSH EMPIRE SUBSTATION
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20090311
Handler Name:	NYCT - FLATBUSH EMPIRE SUBSTATION
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

L112 **NYCT - FLATBUSH EMPIRE SUBSTATION** **NY MANIFEST** **S118954197**
SSW **479 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.158 mi.
834 ft. **Site 13 of 17 in cluster L**

Relative: NY MANIFEST:
Lower

Actual: Name:	NYCT - FLATBUSH EMPIRE SUBSTATION
78 ft. Address:	479 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYR000163733
Facility Status:	Not reported
Location Address 1:	479 FLATBUSH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN

NYCT - FLATBUSH EMPIRE SUBSTATION (Continued) **S118954197**

Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000163733
Mailing Name:	NYCT - FLATBUSH EMPIRE SUBSTATION
Mailing Contact:	NYCT-OSS (CPM)
Mailing Address 1:	2 BROADWAY ROOM A27.64
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462525777

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR986628162
Trans2 State ID:	Not reported
Generator Ship Date:	11/22/2016
Trans1 Recv Date:	11/22/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/22/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000163733
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	009401713FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	8
Container Type:	DM - Metal drums, barrels

NYCT - FLATBUSH EMPIRE SUBSTATION (Continued) **S118954197**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L113 **PHAT ALBERT WAREHOUSE** **NY UST** **U004077595**
SSW **495 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.164 mi.
865 ft. **Site 14 of 17 in cluster L**

Relative:
Lower

Actual:
81 ft.

UST:

Name:	PHAT ALBERT WAREHOUSE
Address:	495 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-274372 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	587779.47494
UTM Y:	4501779.06544
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	11719
Affiliation Type:	Facility Operator
Company Name:	PHAT ALBERT WAREHOUSE
Contact Type:	Not reported
Contact Name:	ALBERT SROUR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 417-7511
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-11-09

Site Id:	11719
Affiliation Type:	Emergency Contact
Company Name:	495 FLATBUSH AVE, LLC
Contact Type:	Not reported
Contact Name:	ALBERT SROUR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

PHAT ALBERT WAREHOUSE (Continued) **U004077595**

Phone:	(201) 574-2989
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-11-09

Site Id:	11719
Affiliation Type:	Mail Contact
Company Name:	495 FLATBUSH AVE, LLC
Contact Type:	MGR
Contact Name:	KEVIN BRUSSEE
Address1:	774 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(917) 417-7511
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-11-09

Site Id:	11719
Affiliation Type:	Facility Owner
Company Name:	495 FLATBUSH AVE, LLC
Contact Type:	MGR
Contact Name:	KEVIN BRUSSEE
Address1:	774 BROADWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11206
Country Code:	001
Phone:	(917) 417-7511
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-11-09

Tank Info:

Tank Number:	001
Tank ID:	9234
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	04/24/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-
Date Test:	Not reported

PHAT ALBERT WAREHOUSE (Continued) **U004077595**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 9235
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 06/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H03 - Tank Leak Detection - Vapor Well

Tank Number: 003
Tank ID: 283306
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1080
Install Date: Not reported
Date Tank Closed: 04/24/2008
Registered: True

PHAT ALBERT WAREHOUSE (Continued) **U004077595**

Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

N114 **CONGRESS CLEANERS** **RCRA NonGen / NLR** **1000236609**
East **1685 BEDFORD AVE** **FINDS** **NYD982793747**
1/8-1/4 **BROOKLYN, NY 11225** **ECHO**
0.165 mi. **NY MANIFEST**
869 ft. **Site 2 of 3 in cluster N**

Relative: **Lower**
Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	CONGRESS CLEANERS	
Handler Address:		1685 BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11225-2601
EPA ID:		NYD982793747
Contact Name:		Not reported
Contact Address:		BEDFORD AVE
Contact City,State,Zip:		BROOKLYN, NY 11205
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BEDFORD AVE
Mailing City,State,Zip:		BROOKLYN, NY 11205
Owner Name:	GREHER, HENRY	
Owner Type:		Private
Operator Name:	GREHER, HENRY	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

CONGRESS CLEANERS (Continued) **1000236609**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND

CONGRESS CLEANERS (Continued) **1000236609**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: GREHER, HENRY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: GREHER, HENRY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: GREHER, HENRY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: CONGRESS CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: CONGRESS CLEANERS	

CONGRESS CLEANERS (Continued) **1000236609**

Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CONGRESS CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19890809
Handler Name: CONGRESS CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004434327

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CONGRESS CLEANERS (Continued) **1000236609**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000236609
Registry ID:	110004434327
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004434327
Name:	CONGRESS CLEANERS
Address:	1685 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	CONGRESS CLEANERS CORP
Address:	1685 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225-2601
Country:	USA
EPA ID:	NYD982793747
Facility Status:	Not reported
Location Address 1:	1085 BEDFORD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11228
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982793747
Mailing Name:	CONGRESS CLEANERS CORP
Mailing Contact:	CONGRESS CLEANERS CORP
Mailing Address 1:	1085 BEDFORD
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11228
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7162543131

P115 **SHELL OIL CO** **RCRA NonGen / NLR** **1000694486**
SE **136 EMPIRE BLVD** **NY MANIFEST** **NYD987008141**
1/8-1/4 **BROOKLYN, NY 11225**
0.165 mi.
871 ft. **Site 2 of 12 in cluster P**

Relative: **Lower**

Actual: **69 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	SHELL OIL CO	
Handler Address:		136 EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11225-3316
EPA ID:		NYD987008141
Contact Name:		Not reported

SHELL OIL CO (Continued) **1000694486**

Contact Address:		JERICHO PLZ
Contact City,State,Zip:		JERICHO, NY 11753
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		JERICHO PLZ
Mailing City,State,Zip:		JERICHO, NY 11753
Owner Name:	LEMBURG FOUNDATION	
Owner Type:		Private
Operator Name:	LEMBURG FOUNDATION	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking

SHELL OIL CO (Continued) **1000694486**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LEMBURG FOUNDATION	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: LEMBURG FOUNDATION	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: LEMBURG FOUNDATION	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED

SHELL OIL CO (Continued) **1000694486**

Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: SHELL OIL CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SHELL OIL CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SHELL OIL CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920713
Handler Name: SHELL OIL CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

SHELL OIL CO (Continued) **1000694486**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	SHELL OIL CO
Address:	136 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225-3316
Country:	USA
EPA ID:	NYD987008141
Facility Status:	Not reported
Location Address 1:	136 EMPIRE BOULEVARD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987008141
Mailing Name:	SHELL OIL CO
Mailing Contact:	NORA CORTEZ
Mailing Address 1:	12700 NORTHBOROUGH DR MFT240G
Mailing Address 2:	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77067
Mailing Zip 4:	2508
Mailing Country:	USA
Mailing Phone:	2818742224

P116 **MOTIVA ENTERPRISES, LLC #138603** **NY UST** **U004062632**
SE **136 EMPIRE BOULEVARD** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.165 mi.
871 ft. **Site 3 of 12 in cluster P**

Relative:
Lower

Actual:
69 ft.

UST:

Name:	MOTIVA ENTERPRISES, LLC #138603
Address:	136 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11201
Id/Status:	2-190926 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Expiration Date: N/A
UTM X: 588135.73950
UTM Y: 4501881.89324
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 5921
Affiliation Type: Emergency Contact
Company Name: MOTIVA ENTERPRISES, LLC
Contact Type: Not reported
Contact Name: ENVIRONMENTAL HELP DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (800) 997-7725
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-06-21

Site Id: 5921
Affiliation Type: Facility Operator
Company Name: MOTIVA ENTERPRISES, LLC #138603
Contact Type: Not reported
Contact Name: SITE MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 284-6025
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-08-19

Site Id: 5921
Affiliation Type: Facility Owner
Company Name: MOTIVA ENTERPRISES, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: ONE SHELL PLAZA, 910 LOUISIANA ST
Address2: Not reported
City: HOUSTON
State: TX
Zip Code: 77002
Country Code: 001
Phone: (713) 277-8000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2012-07-12

Site Id: 5921

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Affiliation Type:	Mail Contact
Company Name:	MOTIVA ENTERPRISES LLC
Contact Type:	Not reported
Contact Name:	ROBERT RULE
Address1:	% GILBARCO VEEDER-ROOT
Address2:	3139 VILLAGE DRIVE
City:	WAYNESBORO
State:	VA
Zip Code:	22980
Country Code:	001
Phone:	(540) 943-8468
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-07-12

Tank Info:

Tank Number:	001
Tank ID:	7255
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1971
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	02/01/1988
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Number:	002
Tank ID:	7256
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1977
Date Tank Closed:	07/09/2008

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 07/23/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
D11 - Pipe Type - Flexible Piping
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
A01 - Tank Internal Protection - Epoxy Liner
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F05 - Pipe External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground

Tank Number: 003
Tank ID: 7257
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1977
Date Tank Closed: 07/09/2008
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 07/23/2003
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
A01 - Tank Internal Protection - Epoxy Liner
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
F05 - Pipe External Protection - Jacketed
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D11 - Pipe Type - Flexible Piping

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 004
Tank ID: 7258
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 005
Tank ID: 7259
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 11/30/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	006
Tank ID:	54720
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	12000
Install Date:	06/01/1998
Date Tank Closed:	07/10/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	07/23/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
F05 - Pipe External Protection - Jacketed
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	008
Tank ID:	58717
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	12000
Install Date:	09/01/2000
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
D08 - Pipe Type - Equivalent Technology
B04 - Tank External Protection - Fiberglass
F05 - Pipe External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 101
Tank ID: 218844
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/20/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 102
Tank ID: 218845
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/20/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	103
Tank ID:	218846
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	104
Tank ID:	218847
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	105
Tank ID:	218848
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 106
Tank ID: 218849
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/20/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 107
Tank ID: 218850
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/20/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 108
Tank ID: 218851
Tank Status: Closed - Removed
Material Name: Closed - Removed

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/20/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 109
Tank ID: 218852
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/20/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 110
Tank ID: 218853
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/20/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Tank Number:	111
Tank ID:	218854
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	112
Tank ID:	218855
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	113
Tank ID:	218856
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	114
Tank ID:	218857
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	115
Tank ID:	218858
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	07/20/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	116
Tank ID:	244746
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	07/09/2012
Registered:	True
Tank Location:	Underground

MOTIVA ENTERPRISES, LLC #138603 (Continued) **U004062632**

Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

P117 **SHELL** **NY LTANKS S100495017**
SE **136 EMPIRE BLVD** **NY Spills N/A**
1/8-1/4 **BROOKLYN, NY**
0.165 mi.
871 ft. **Site 4 of 12 in cluster P**

Relative: LTANKS:
Lower

Name:	SHELL
Address:	136 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8708602 / 1989-03-23
Facility ID:	8708602
Site ID:	235594
Spill Date:	1988-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1989-03-23
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1988-01-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-25
Spill Record Last Update:	2004-05-25
Spiller Name:	Not reported

Actual:
69 ft.

SHELL (Continued) **S100495017**

Spiller Company: SHELL OIL
Spiller Address: 136 EMPIRE BLVD
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 194054
DEC Memo: ""
Remarks: "(3) 4K TKS FAILED PETRO-TITE. L R = UNREADABLE. 1ST 2 WERE SUPER NO LEAD AND 3RD TANK HAD REGULAR NO LEAD."

All TTF:
Facility ID: 8708602
Spill Number: 8708602
Spill Tank Test: 1532951
Site ID: 235594
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 235594
Operable Unit ID: 913278
Operable Unit: 01
Material ID: 463979
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

Name: SHELL
Address: 136 EMPIRE BLVD
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8903486 / 1989-07-07
Facility ID: 8903486
Site ID: 235595
Spill Date: 1989-07-07
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Not reported
Cleanup Ceased: 1989-07-07

SHELL (Continued) **S100495017**

SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1989-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-07-11
Spill Record Last Update:	2004-01-09
Spiller Name:	Not reported
Spiller Company:	SHELL OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	194054
DEC Memo:	""
Remarks:	"FIRE DEPT ON SCENE, WILL BE CLEANED UP BY SHELL."

All Materials:

Site ID:	235595
Operable Unit ID:	930980
Operable Unit:	01
Material ID:	447574
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

Name:	SHELL
Address:	136 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9300390 / 1993-04-15
Facility ID:	9300390
Site ID:	235596
Spill Date:	1993-04-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C2
Cleanup Ceased:	1993-04-15
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1993-04-08
CID:	Not reported
Water Affected:	Not reported

SHELL (Continued) **S100495017**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-04-09
Spill Record Last Update:	2004-01-09
Spiller Name:	Not reported
Spiller Company:	SHELL OIL CO
Spiller Address:	1 JERICHO PLAZA
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	194054
DEC Memo:	""
Remarks:	"SUCTION LINE FAILED-NO ACTION YET DETERMINED"

All TTF:

Facility ID:	9300390
Spill Number:	9300390
Spill Tank Test:	1541385
Site ID:	235596
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235596
Operable Unit ID:	979078
Operable Unit:	01
Material ID:	401151
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	SHELL GAS STATION
Address:	136 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY

SHELL (Continued) **S100495017**

Spill Number/Closed Date:	9601908 / 2012-12-21
Facility ID:	9601908
Site ID:	235597
Spill Date:	1996-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	2005-05-02
SWIS:	2401
Investigator:	aaobliga
Referred To:	NFA
Reported to Dept:	1996-05-08
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-05-08
Spill Record Last Update:	2014-06-11
Spiller Name:	Not reported
Spiller Company:	SHELL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	BROOK TERLE
Spiller Phone:	(516) 365-2489
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	194054
DEC Memo:	"3/23/2000 Envirotrac called to say: Shell is planning on pulling tanks and did geoprobing to characterize the waste fill material. Near the despenser islands contamination was found. Tanks should be pulled in April 2000 A request for closure was previously submitted on this site, but DEC has not yet acted on the closure, so this new contamination was not called in as a new spill, but rather added to the previous spill. 1/5/04 Reassigned from Mulqueen/Sangesland to Foley. Received update report from NES, dated 12/30/03. DTW 57-58'bgs. Six monitoring wells have been installed. Three were installed May 2003. Total product recovery to date 17.75gal. Apartment building downgradient. Groundwater sampling from 9/10/03 identified highest BTEX at 30036ppb in MW-2 (upgradient of former 550s) and highest MTBE at 876ppb in MW-3 (downgradient of former USTs). A sensitive receptor survey will be completed. NES also recommends a slug test. 3/22/04 Update report received(NES, 3/16/04). LNAPL not detected since 4/03. Last sampling event on 12/8/03 showed highest BTEX conc in MW-1 at 5014ppb. MW-2, historically a hot well, was not sampled. Concentrations appear to be dropping. 5/18/04 Received update report(NES, 5/13/04). BTEX range from 1ppb(MW-4) to 16,964ppb(MW-1). MTBE ranges from greater than Activities conducted 4/30/07 through 5/7/07: greater than - Hand cleared and located electric, water, and sewer lines crossing greater than the western portion of the property. greater than - Removed ten 550-gallon steel abandoned USTs. All USTs are greater than abandoned with concrete and are located within a concrete vault. The greater than 10 tanks have been emptied, cleaned, crushed, and removed from the greater than

SHELL (Continued) **S100495017**

site. greater than - Removed 3/4 of the concrete vault/bottom slab; all concrete has greater than been removed from the site. greater than - Collected the south wall sidewall samples for laboratory analysis. greater than greater than greater than UST Removal activities remaining: greater than - Remove 2 remaining 550's greater than - Remove 4,000-gallon abandoned UST greater than - Remove remaining 1/4 of concrete vault/bottom slab greater than - Collect North, East, West and Bottom endpoint samples greater than - Conduct limited over-excavation in vicinity of abandoned USTs greater than - Backfill excavation 9/17/07 - Obligado - Review project schedule as per RAP: Jul 07 - UST Removal Sep 07 - UST Removal Report Dec 07 - Reinstallation of Monitoring Wells Mar 08 - Pilot Test May 08 - Pilot Test Report Review Quarterly Monitorin Reports: 1Q07 Monitoring Report - March 07 - Guaged and sampled wells, drilled borings and obtained soil samples for waste disposal. Ground water results show BTEX from ND to 36620 ug/L (MW1) and MTBE from ND to 1050 ug/L (MW3). Ground water flow is to the south. No LNAPL detected. Proposes UST removal in May 07 and continued monitoring. 2Q07 Monitoring Report - April 2007 - 13 USTs removed and 613.9 tons of petroleum impactred soils. 8 wells guaged and sampled, BTEX from ND to 19953 ug/L (MW3), MTBE ND to 280 ug/L (MW3). GW flow to south. Proposes continured monitoring, preparation of an Tank excavation report. 10/4/07 - Obligado - Portfolio meeting with Rob Rule of Shell, Heather Cloud of GES, Eric Harvey of GES, and myself. This project is ahead of schedule. The USTs were removed. They actually found a waste oil UST beneath the old tankfield, encased in concreate, and the UST was filled with fuel. The fuel was vacuumed and disposed of. A tank excavation report was submitted on 9/24/07. They will do a pilot test for AS/SVE. All the AS/SVE wells have already been installed. They will not do a pump tests because a pump test was already performed and they did not get signifant drawdown. If AS/SVE pilot is unfavorable, then they can use the AS wells as injection wells. 613 tons of contaminated soil were removed. 11/20/07 - Obligado - Review Tank Excavation Report, dated September 24, 2007. Tanks were removed between April and May 2007. 13 abandoned 550 gallon gasoline USTs, 1 abandoned 4000 gallon UST of unknown contents, and 1 previously unknown steel UST containing waste oil was encountered and removed. The 550 gallon USTs had no signs of leakage. A hole was discovered in the 4000 galon gasoline UST. 1288 gallons of waste oil was removed from the discovered UST and properly disposed of. 613 tons of petroleum contaminated soil was removed and transported to soil safe. Excavation reached depths of 17 ft bgs. Soil analytical results were above SCOs at 14 of 16 soil sampling locations. Total VOCs ranged from 593 ug/L to 1,202,307 ug/L. SVOCs were below SCOs at all locations. Proposed Plans: In March 2008, GES will conduct a pilot test. By May of 2008 they will submit a remedial system design. 11/20/07 - Obligado - Review 3Q07 monitoring report. Between May and June 2007 10 SVE wells were installed on site and 7 air sparge wells. All wels were resurveyed on July 12, 2007. The wells were guaged and sampled on August 110, 2007. No LNAPL was detected. Depth to GW between 52.72 and 56.21 ft bgs. BTEX from ND to 19,726 ug/L (MW1). MTBE from ND to 188 ug/L. Next report will be submitted January 2008. 5/7/08 - Obligado - Review 4Q07 report. BTEX from ND to 26,621 ug/L (MW1), MTBE from ND to 133 ug/L (MW1). LNAPL not detected. Proposes pilot test and ground water sampling in March 2008. Review 1Q08 update report. In March, ground water sampled and SVE/AS pilot test peformed. BTEX range is from ND to 34,462 ug/L (MW1). MTBE range is

SHELL (Continued) **S100495017**

from ND to 124 ug/L (MW1). No LNApl. Proposes continued monitoring and submitting SVE/AS pilot test report in May 2008. 6/23/08 - Obligado - Reviewed AS/SVE pilot test report. The report had some descrepencies. According to the report, VOC readings from SVE effluent increased 52% when AS was activated, however, PID readings increase only from 480 to 510 ppm, whic is not a 52 % increase. Additionally, some of the best fit lines on the Radius of Influence graphs were questionable. I was also concerned that the deep SVE wells were screened from 15 to 50 ft bgs, and this large screened interval will not allow SVE to target deep impacts. I called Heather Cloud to discuss these issues. As for the deep well issue, she said she would use packers to isolate the deep interval, and she wasn't concerned about short circuiting through the sand pack. She would look into the graphs and the % increase. 9/16/09- Obligado - meeting with Shell, GES, DEC. Shell will install vapor points along property boundary. Install delineation well on ajacent property if possible. 1/14/09 - Obligado - Review UST Closure report. 1 8000 gallon and 2 4000 gallon gasoline USTs removed. Approximately 19.08 tons of petroleum impacted soils were removed and transported to Soil Safe, Inc. (Soil Safe) of Logan Township, New Jersey for disposal. Endpoint samples had to exceedences for MTBE (645 ppb and 1020 ppb) in B1 and B2 bottom samples. All other VOCs below SCOs. 3/23/09 - Obligado - Reviewed revised implementation schedule. Sent approval for Feasibity Report. 6/5/09 - Obligado - Reviewed Remedial Design Documents and OM&M plan. Effluent samples will be collected weekly during 45 days start up period, then quarterly after that, and effluent will be monitored biweekly with a PID. Groundwater will be sampled quarterly. System will consist of 10 vapor extraction lines and 7 sparge lines. 7 additional schedule 80 injection lines will also be installed for future use if necessary. SVE and AS system will be interlocked. System will have # of safety devises including vacuum and pressure relief valves, high level flost swithces, and temp/pressure indicators, and emergency shut off switch. System will consist of 2 separate SVE blowers. Each blower will discharge through 2 activated carbon canisters and discharge to a 20 ft stack. System will be inclosed in a shed surrounded by bollards. Emailed approval letter. 11/9/09 - Obligado - Meeting with Shell and GES. Discussed the results of the vapor sampling. Perc was found in soil vapor. They will test ground water for perc as well as system effluent. DEC will look into effluent requirements for PERC. 12/19/09 - Obligado - Emailed Heather to inquire about the system start up. She replied the system started on 12/18/09. I asked her to sample effluent for total VOCs, in addition to BTEX, MTBE, and TPH. She said the system effluent was running through 6 carbon canisters and the effluent was ND on the PID. She agreed to sampled for total VOCS. 3/4/10 - Obligado - I received the revised report. Total VOCs were less than the 0.5lbs per hour limit for total VOCs. 4/20/10 - Obligado - Meeting with Shell,GES, DEC. They will submit a report summarizing vapor sampling, gw sampling for Perc, as well as a source investigation for the perc. 8/5/10 - Obligado - I reviewed the quarterly report. VOCs in ground water decreased this quarter since system start up. According to the report, a total of 3100 lbs of hydrocarbons have been recovered to date. Recommends continued system operation and gw sampling. 3/7/2011 - Obligado - Review 4Q10 report - During 4rth quarter they peformed routine OMM and ground water sampling. Maximum BTEX is 3,102 ug/l. Influent and effluent vapor sampling were ND. They removed the carbon treatment. To date an

SHELL (Continued) **S100495017**

estimated total of 3798 lbs of hydrocarbon has been been removed. 12/6/11 - Obligado - Conference call between Shell, DEC, and Developer/purchaser 111 Stephen LLC. DEC approves removal of system shed on the condition that AS/SVE system piping is maintained. Conference call email summary in edocs. 6/27/12 - Obligado - Email from Sarah Burke: Spill number 12-02788 was called in due to the below activities: Development activities are occurring at 136 Empire Boulevard in Brooklyn, NY. The developer is currently excavating for the building to be constructed on-site and during excavation impacted soil was encountered in the area of the former dispenser islands. The impacted soil (approximately 550 tons) was segregated and stockpiled. It is anticipated that this soil will be removed from the site tomorrow on Thursday, June 27. The soil will be disposed of at a permitted facility. Post-excavation samples were collected following the excavation activities. The results will be forwarded to the NYSDEC after receipt. 6/27/12 - Obligado - I emailed Sarah Burke to confirm that building will have vapor barrier and passive SSDS system. Rob responded that they will contact developer to make sure that the passive vent piping is installed. 6/27/12 - Obligado - I emailed all parties including developer and attorney for developer reiterating that vapor barrier and SSDS pipes must be installed. 6/29/12 - Obligado - I reviewed PBS records and noticed one 550 gallon abandoned waste oil tank is still present on site in the footprint of the proposed building. I emailed Rob Rule and cc to developer to confirm that the waste oil tank will be removed by Shell. 7/11/12 - Obligado - I sent email to developer requesting confirmation that SSDS pipes and vapor barrier will be installed beneath the building and requested plans/specs. 7/19/12 - Obligado - Met on-site with developer and URS. Based on recent endpoint samples, requested additional excavation in area where elevated benzene concentrations were detected, SW2 and SW3. They will do additional excavation. The the developer provided SSDS and vapor barrier plans. According to the developer, steel is being fabricated and will begin installation of frame in several weeks. INformed parties DEC would investigating adjacent property for PCE issues. 7/20/12 - Obligado - Inspected adjacent warehouse with Hassan Hussein, Raphael Ketani, Sarah Carlson. No evidence of PCE storage/disposal. According to the owner, he owned the business for 30 years and did not perform carpet cleaning. 7/23/12 - Obligado - Requested URS/Shell to do PCE soil vapor investigation in footprint of former garage. 9/12/12 - Obligado - Received Closure Report. The report documents elevated PCE concentrations in soil vapor (~12000 ug/m3 PCE at one location). I forwarded the results to NYSDOH. 9/13/12 - Obligado - Emailed developer/Shell, notified them it is not advisable to pour the floor slab yet as based on results DOH/DEC may request additional investigation/remediation. 9/14/12 - Obligado - Response from DOH. DOH requests additional vapor investigation. DOH recommends full VI investigation of adjacent apartment building to the south. DOH recommends an active SSDS system. I forwarded comments to RPs and also required a soil investigation in the building footprint to determine if there was a source for PCE in the soil. Prior to full VI investigation they will do additional soil vapor sampling at the property boundary to confirm. I requested an investigation Plan. 9/21/12 - Obligado - Approved the Investigation plan. 10/18/12 - Obligado - Received Closure Report. I forwarded the report to DOH due to PCE vapor issues. 12/17/12- Obligado - I had email correspondence with DOH, inquiring if they still recommended off-site vapor

SHELL (Continued) **S100495017**

investigation at neighboring property and DOH confirmed VI investigation still warranted at the apartment building. I also inquired as to whether they were concerned about the petroleum vapor in soil, or just chlorinated solvents. DOH confirmed that they were not concerned with the petroleum as the contamination has been substantially removed and they were only concerned with the chlorinated solvent vapors. They also recommended the SSDS system be active. 12/18/12 - Obligado - DER Section C Staff met to discuss a closure request for Spill No.9601908. After discussion, the spill closure request was approved based on: 1) All sources of petroleum removed from site 2) 3,800 lbs of hydrocarbon removed via AS/SVE system 3) Total BTEX concentrations in groundwater reduced from 46,010 ug/L in 2003 to 1,215.5 ug/L in 2012 (97% reduction) 4) The AS/SVE system achieved asymptotic recovery 5) In addition to AS/SVE, approximately 2,040 tons of petroleum impacted soil has been excavated to date, and limited residual soil contamination remains above CP-51 Soil Clean-up Guidance. 6) Petroleum contamination has been remediated to the extent feasible, and residual groundwater impacts are expected to improve over time. 7) The NYSDOH is not concerned about low level petroleum compounds in soil vapor 8) The NYSDOH is concerned about high levels of PCE in soil vapor which appears to be coming from off-site 9) The off-site PCE vapor source and potential vapor intrusion impacts to adjacent properties should be investigated and addressed as a P-site and transferred to Section A. 12/20/12 - Obligado - I forwarded this project to the Hazaradous Waste Section as a P-Site due to PERC Vapors. 4/8/13 - Obligado - Monitoring well decommissioning report submitted to the Departmetn. All well sdecommissioned in accordance with CP-43 on April 5, 2013. 3/21/14 - According to email from central office dated 9/30/13, they did a desktop study but did not identify a clear source of the PCE and other CVOCs that has been detected in the soil vapor at 136 Empire Blvd. As per DEC Schick : No site number assigned and no further work needed due to no obvious source. I sent an email to Jim DiMartinis cc to Mr. Koptiev, notifying him that no off-site source was positively identified, but re-iterating to him that DOH had reviously recommended that the SSDS system should be active to prevent vapor intrusion. I also asked him to provide information about the building occupants and use. 4/2/14 - Obilgado - I emailed BRidget Callahan notifying her of the current site status, that a commercial building was constructed on an old gas station with PCE and TCE in soil vapor which was suspected to be coming from an off-site source. The developer installed a vapor barrier and passive SSDS but was reluctant to install a blower and activate the system, and that the commericial building was complete and occupied. Aslo, since the source is from an unknown off-site there is currently no confirmed RP to do the off-site investigation of the adjacent apartment building recommended by DOH. I requested her guidance on the issue. 6/6/14 - Obligado - I called Michael Hughes to follow up on the issue. He will speak with Bridget and call me back on Monday. 6/9/14-Vought-DEC Obligado received call from Callahan who requested a teleconference to discuss the possible listing of the site as a significant threat due to soil vapor. Vought and Obligado spoke with RHWRE who noted that she spoke wih Cozzy regardings Obligado’s prior P-Site request and the request was denied a significant threat determination cannot be made based on soil vapor. RHWRE then held teleconference with Vought, Obligado and Cozzy and Cozzy again noted that we cannot make a significant threat determination based on soil

SHELL (Continued) **S100495017**

vapor and that NYSDOH should send a letter to the owner with any requirements. Vought requested that RWHRE and/or Cozzy participate in call and they declined and Vought suggested that an email be sent to all parties which was also declined. RHWRE requested that Vought and Obligado convey the infor regarding lack of significant threat determination to NYSDOH Callahan and Demmings. RHWRE also noted that if NYSDOH had any further concerns than they should call DEC Cozzy. 6/11/14-Vought-Spoke with RSE regarding the above 6/9 entry and RSE noted that Spills could not participate in teleconference and convey and possibly defend decisions made by another remedial section. Vought spoke with NYSDOH Callahan and informed her of discussion with RSE as well as discussion with RWHRE and DEC Cozzy on 6/9. NYSDOH Callahan will inform NYSDOH Demings of same and he will contact DEC Cozzy if he has any further concerns. This spill to remain closed as no further concerns with respect to petroleum contamination as per Vought."

Remarks: ""

All TTF:

Facility ID:	9601908
Spill Number:	9601908
Spill Tank Test:	1544530
Site ID:	235597
Tank Number:	s1
Tank Size:	4000
Material:	1213A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	14
Test Method 2:	VacuTest
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235597
Operable Unit ID:	1033457
Operable Unit:	01
Material ID:	351703
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	235597
Operable Unit ID:	1033457
Operable Unit:	01
Material ID:	579372
Material Code:	0001A
Material Name:	#2 fuel oil

SHELL (Continued) **S100495017**

Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: True

Site ID: 235597
Operable Unit ID: 1033457
Operable Unit: 01
Material ID: 2106655
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

SPILLS:
Name: FORMERLY SHELL STATION
Address: 136 EMPIRE BLVD
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1202788 / 2012-06-29
Facility ID: 1202788
Facility Type: ER
DER Facility ID: 194054
Site ID: 465565
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2012-06-21
Investigator: AAOBLIGA
Referred To: CLOSED AND CONSOLIDATED WITH 9601908
Reported to Dept: 2012-06-21
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-06-21
Spill Record Last Update: 2012-06-29
Spiller Name: CHRISTOPHER GAULE
Spiller Company: FORMERLY SHELL STATION
Spiller Address: 136 EMPIRE BLVD
Spiller Company: 999
Contact Name: CHRISTOPHER GAULE
DEC Memo: "6-29-12 - Obligado - Closed and consolidated with existing spill number 96-01908."

SHELL (Continued) **S100495017**

Remarks: "visual observations confirm loss, Former spill 9601908"

All Materials:

Site ID:	465565
Operable Unit ID:	1215586
Operable Unit:	01
Material ID:	2213718
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	EMPIRE AUTO REPAIR
Address:	136 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1110770 / 2011-12-06
Facility ID:	1110770
Facility Type:	ER
DER Facility ID:	194054
Site ID:	458620
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-12-05
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2011-12-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-12-05
Spill Record Last Update:	2012-01-09
Spiller Name:	Not reported
Spiller Company:	SHELL GAS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SARA BURKE
DEC Memo:	"Old gas station. DEC Andre Obligado is working a longterm gasoline spill at this site. This new spill relates a hydraulic spill from one of the lifts in the garage which must have leaked. When the lifts were dug out, the area looked clean but the samples later came back with some SVOC hits. Consultant will go back, dig additional soil, take new end point samples, take photos and will send in a report to close the case out. 12/06/11-Hiralkumar Patel. 1:21 PM:- spoke with Ms. Burke at URS and asked her to submit lab data for review. she

SHELL (Continued) **S100495017**

mentioned that soil samples were collected at 5 ft depth and groundwater is at 50 ft bg. 1:30 PM:- received email from Ms. Burke including sample results. SVOC compounds found in all samples. 1:43 PM:- sent email to Ms. Burke and asked to submit site map with sample locations, sample depth and type of soil. 2:32 PM:- received email from Ms. Burke including site map. she mentioned that sidewall samples were collected at 5 ft bg and bottom soil samples were collected at 8 ft bg. each excavation was 2 ft by 2 ft and was 8 ft deep. the soil type was a medium sand. as per map, four excavations were made. found SVOC compounds in all soil samples at almost same level except samples SWN-3, SWE-2 and SWS-4 where slightly higher SVOCs found. based on submitted information, case closed. 01/06/12-Hiralkumar Patel. 4:42 PM:- received email from Ms. Burke including hydraulic lift removal report."

Remarks: "clean up pending"

All Materials:

Site ID:	458620
Operable Unit ID:	1208741
Operable Unit:	01
Material ID:	2206070
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

P118 **MOTIVA ENTERPRISES, LLC #138603** **NY AST** **A100168825**
SE **136 EMPIRE BOULEVARD** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.165 mi.
871 ft. **Site 5 of 12 in cluster P**

Relative: **Lower**
Actual: **69 ft.**

AST:

Name:	MOTIVA ENTERPRISES, LLC #138603
Address:	136 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11201
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-190926
Program Type:	PBS
UTM X:	588135.73950
UTM Y:	4501881.89324
Expiration Date:	N/A
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	5921
Affiliation Type:	Emergency Contact
Company Name:	MOTIVA ENTERPRISES, LLC
Contact Type:	Not reported
Contact Name:	ENVIRONMENTAL HELP DESK
Address1:	Not reported
Address2:	Not reported

MOTIVA ENTERPRISES, LLC #138603 (Continued) **A100168825**

City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (800) 997-7725
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-06-21

Site Id: 5921
Affiliation Type: Facility Operator
Company Name: MOTIVA ENTERPRISES, LLC #138603
Contact Type: Not reported
Contact Name: SITE MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 284-6025
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2008-08-19

Site Id: 5921
Affiliation Type: Facility Owner
Company Name: MOTIVA ENTERPRISES, LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: ONE SHELL PLAZA, 910 LOUISIANA ST
Address2: Not reported
City: HOUSTON
State: TX
Zip Code: 77002
Country Code: 001
Phone: (713) 277-8000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2012-07-12

Site Id: 5921
Affiliation Type: Mail Contact
Company Name: MOTIVA ENTERPRISES LLC
Contact Type: Not reported
Contact Name: ROBERT RULE
Address1: % GILBARCO VEEDER-ROOT
Address2: 3139 VILLAGE DRIVE
City: WAYNESBORO
State: VA
Zip Code: 22980
Country Code: 001
Phone: (540) 943-8468
EMail: Not reported

MOTIVA ENTERPRISES, LLC #138603 (Continued) **A100168825**

Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-07-12

Tank Info:

Tank Number:	007
Tank Id:	54721
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/14/2008
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/15/2011
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

L119 **PROSPECT PARK SUBWAY STATION** **NY UST** **U004363262**
SSW **478 FLATBUSH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.168 mi.
889 ft. **Site 15 of 17 in cluster L**

Relative: UST:
Lower

Actual: Name:	PROSPECT PARK SUBWAY STATION
82 ft. Address:	478 FLATBUSH AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-613334 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported

PROSPECT PARK SUBWAY STATION (Continued) **U004363262**

UTM Y: Not reported
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 636259
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY TRANSIT AUTHORITY
Contact Type: DIRECTOR, ENVIRONMENTAL PROTECTION & INDUSTRIAL HY
Contact Name: DOREEN BOATSWAIN
Address1: 2 BROADWAY, 27TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10004
Country Code: 001
Phone: (646) 252-5777
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2022-05-12

Site Id: 636259
Affiliation Type: Mail Contact
Company Name: NEW YORK CITY TRANSIT AUTHORITY
Contact Type: Not reported
Contact Name: FRANK ROBINSON / ALEXANDER GERAGHTY
Address1: 478 FLATBUSH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11225
Country Code: 001
Phone: (718) 243-3019
EMail: FRANK.ROBINSON2@NYCT.COM
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2022-05-12

Site Id: 636259
Affiliation Type: Facility Operator
Company Name: PROSPECT PARK SUBWAY STATION
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2022-05-11

Site Id: 636259
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY TRANSIT AUTHORITY

PROSPECT PARK SUBWAY STATION (Continued) **U004363262**

Contact Type:	Not reported
Contact Name:	FRANK ROBINSON / ALEXANDER GERAGHTY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 243-3019
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2022-05-11

Tank Info:

Tank Number:	UT-1
Tank ID:	295097
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LXZIELIN
Last Modified:	05/11/2022

Equipment Records:

E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

L120 **CON EDISON SERVICE BOX: 66621** **RCRA NonGen / NLR** **1016961110**
SSW **480 FLATBUSH AVE** **NY MANIFEST** **NYP004335873**
1/8-1/4 **BROOKLYN, NY 11225**
0.169 mi.
890 ft. **Site 16 of 17 in cluster L**

Relative: **Lower**
Actual: **82 ft.**

RCRA Listings:

Date Form Received by Agency:	20140224
Handler Name:	CON EDISON SERVICE BOX: 66621
Handler Address:	480 FLATBUSH AVE
Handler City,State,Zip:	BROOKLYN, NY 11225

CON EDISON SERVICE BOX: 66621 (Continued) **1016961110**

EPA ID:		NYP004335873
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No

CON EDISON SERVICE BOX: 66621 (Continued) **1016961110**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140124
Handler Name: CON EDISON SERVICE BOX:	66621
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140224
Handler Name: CON EDISON SERVICE BOX:	66621
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 66621 (Continued) **1016961110**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 480 FLATBUSH AVE
City,State,Zip: BROOKLYN, NY 11225
Country: USA
EPA ID: NYP004335873
Facility Status: Not reported
Location Address 1: 480 FLAT BUSH AVE
Code: BP
Location Address 2: SERVICE BOX # 66621
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004335873
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/26/2013
Trans1 Recv Date: 07/26/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004335873
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002085736GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX: 66621 (Continued) **1016961110**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L121 **CON ED** **NY MANIFEST** **S116291438**
SSW **FO 480 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.169 mi.
890 ft. **Site 17 of 17 in cluster L**

Relative:
Lower

Actual:
82 ft.

NY MANIFEST:

Name:	CON ED
Address:	FO 480 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004424966
Facility Status:	Not reported
Location Address 1:	FO 480 FLATBUSH AVE
Code:	BP
Location Address 2:	SB 66621
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004424966
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON ED (Continued) **S116291438**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/2014
Trans1 Recv Date:	01/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004424966
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329068GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P122 **KFC** **NY UST** **U003800465**
ESE **1715 BEDFORD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.169 mi.
891 ft. **Site 6 of 12 in cluster P**

Relative:
Lower

Actual:
75 ft.

UST:

Name:	KFC
Address:	1715 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-606994 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588179.98385
UTM Y:	4502015.58680
Site Type:	Other

Affiliation Records:

Site Id:	28849
Affiliation Type:	Facility Owner
Company Name:	TRICON
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	17091 VON KARMON, MD 700
Address2:	Not reported
City:	IRVINE
State:	CA
Zip Code:	90614
Country Code:	001
Phone:	(949) 863-3934
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	28849
Affiliation Type:	Mail Contact
Company Name:	TRICON
Contact Type:	Not reported
Contact Name:	MS. JULIE REESE
Address1:	17091 VON KARMON, MD 700
Address2:	Not reported
City:	IRVINE
State:	CA
Zip Code:	90614
Country Code:	001
Phone:	(949) 863-3934
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	28849
Affiliation Type:	Facility Operator
Company Name:	KFC
Contact Type:	Not reported
Contact Name:	UNKNOWN
Address1:	Not reported

KFC (Continued) **U003800465**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(949) 863-3934
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	28849
Affiliation Type:	Emergency Contact
Company Name:	TRICON
Contact Type:	Not reported
Contact Name:	JULIE REESE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(949) 863-3934
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	62145
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	09/01/1901
Date Tank Closed:	09/01/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Concrete
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

KFC (Continued) **U003800465**

I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 10
Tank ID: 62155
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
C02 - Pipe Location - Underground/On-ground

Tank Number: 11
Tank ID: 62426
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/20/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 2642
Common Name of Substance: Used Oil (Heating, On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

KFC (Continued) **U003800465**

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
C02 - Pipe Location - Underground/On-ground

Tank Number: 2
Tank ID: 62146
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
D00 - Pipe Type - No Piping

Tank Number: 3
Tank ID: 62147
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

KFC (Continued) **U003800465**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 4
Tank ID: 62148
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
C02 - Pipe Location - Underground/On-ground

Tank Number: 5
Tank ID: 62150
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground

KFC (Continued) **U003800465**

Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
D00 - Pipe Type - No Piping

Tank Number: 6
Tank ID: 62151
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J00 - Dispenser - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

Tank Number: 7
Tank ID: 62152
Tank Status: Closed - Removed

KFC (Continued) **U003800465**

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J00 - Dispenser - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
D00 - Pipe Type - No Piping

Tank Number: 8
Tank ID: 62153
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground

KFC (Continued) **U003800465**

D00 - Pipe Type - No Piping

Tank Number: 9
Tank ID: 62154
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 09/01/2001
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

P123 **K F C NATIONAL MANAGEMENT CO** **RCRA NonGen / NLR** **1004762995**
ESE **1715 BEDFORD AVE** **FINDS** **NYR000102558**
1/8-1/4 **BROOKLYN, NY 12225** **ECHO**
0.169 mi. **NY MANIFEST**
891 ft. **Site 7 of 12 in cluster P**

Relative: RCRA Listings:
Lower
Actual: Date Form Received by Agency: 20070101
75 ft. Handler Name: K F C NATIONAL MANAGEMENT CO
Handler Address: 1715 BEDFORD AVE
Handler City,State,Zip: BROOKLYN, NY 12225
EPA ID: NYR000102558
Contact Name: JULIE REESE
Contact Address: BEDFORD AVE
Contact City,State,Zip: BROOKLYN, NY 12225
Contact Telephone: 949-863-3934
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported

K F C NATIONAL MANAGEMENT CO (Continued) **1004762995**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BEDFORD AVE
Mailing City,State,Zip:	BROOKLYN, NY 12225
Owner Name:	KFC NATIONAL MANAGEMENT CO
Owner Type:	Private
Operator Name:	KFC NATIONAL MANAGEMENT CO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

K F C NATIONAL MANAGEMENT CO (Continued) **1004762995**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KFC NATIONAL MANAGEMENT CO
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	17091 VAN KARMAN - MD 700
Owner/Operator City,State,Zip:	IRVINE, CA 92614
Owner/Operator Telephone:	949-863-3934
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KFC NATIONAL MANAGEMENT CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	17091 VAN KARMAN - MD 700
Owner/Operator City,State,Zip:	IRVINE, CA 92614
Owner/Operator Telephone:	949-863-3934
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KFC NATIONAL MANAGEMENT CO
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	17091 VAN KARMAN - MD 700
Owner/Operator City,State,Zip:	IRVINE, CA 92614
Owner/Operator Telephone:	949-863-3934
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101

K F C NATIONAL MANAGEMENT CO (Continued) **1004762995**

Handler Name: K F C NATIONAL MANAGEMENT CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: K F C NATIONAL MANAGEMENT CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20011206
Handler Name: K F C NATIONAL MANAGEMENT CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110012260258

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

K F C NATIONAL MANAGEMENT CO (Continued) **1004762995**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762995
Registry ID:	110012260258
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012260258
Name:	K F C NATIONAL MANAGEMENT CO
Address:	1715 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	KFC NATIONAL MANAGEMENT CO
Address:	1715 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 12225
Country:	USA
EPA ID:	NYR000102558
Facility Status:	Not reported
Location Address 1:	1715 BEDFORD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000102558
Mailing Name:	KFC NATIONAL MANAGEMENT CO
Mailing Contact:	GENE GUIDO
Mailing Address 1:	17091 VAN KARMAN
Mailing Address 2:	Not reported
Mailing City:	IRVINE
Mailing State:	CA
Mailing Zip:	92614
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6312493100

Q124 **CON EDISON** **RCRA NonGen / NLR** **1019902440**
ENE **MONTGOMERY ST & BEDFORD AVE** **NYP004773784**
1/8-1/4 **BROOKLYN, NY 11215**
0.169 mi.
893 ft. **Site 1 of 10 in cluster Q**

Relative: **Higher**

Actual: **94 ft.**

RCRA Listings:

Date Form Received by Agency:		20150424
Handler Name:	CON EDISON	
Handler Address:		MONTGOMERY ST & BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004773784

CON EDISON (Continued) **1019902440**

Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No

CON EDISON (Continued) **1019902440**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON (Continued) **1019902440**

Evaluation Action Summary:
Evaluations: No Evaluations Found

Q125 **CON EDISON** **NJ MANIFEST** **S120670989**
ENE **MONTGOMERY ST & BEDFORD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.169 mi.
893 ft. **Site 2 of 10 in cluster Q**

Relative:
Higher

Actual:
94 ft.

NJ MANIFEST:

EPA Id:	NYP004773784
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619116GBF
EPA ID:	NYP004773784
Date Shipped:	4/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON (Continued) **S120670989**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q126 **CON EDISON** **NY MANIFEST** **S119074776**
ENE **MONTGOMERY ST & BEDFORD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.169 mi.
893 ft. **Site 3 of 10 in cluster Q**

Relative: **Higher**

Actual: **94 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	MONTGOMERY ST & BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004773784
Facility Status:	Not reported
Location Address 1:	SS MONTGOMERY ST 298' W/O BEDFORD
Code:	BP
Location Address 2:	MH 30669
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004773784
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2015
Trans1 Recv Date:	04/24/2015

CON EDISON (Continued) **S119074776**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004773784
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619116GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N127 **RITE AID #03978** **RCRA-VSQG** **1001113445**
East **1679 BEDFORD AVE** **FINDS** **NYR000024356**
1/8-1/4 **BROOKLYN, NY 11225** **ECHO**
0.170 mi. **NY MANIFEST**
896 ft. **Site 3 of 3 in cluster N**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:		20190417
Handler Name:	RITE AID #03978	
Handler Address:		1679 BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYR000024356
Contact Name:		JOSEPH A CHEST
Contact Address:		HUNTER LN
Contact City,State,Zip:		CAMP HILL, PA 17011
Contact Telephone:		717-975-8643
Contact Fax:		717-972-3989

Actual:
88 ft.

RITE AID #03978 (Continued) **1001113445**

Contact Email:		EHS@RITEAID.COM
Contact Title:		MANAGER ENVIRONMENTAL HEALTH SERVICES
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		HUNTER LN
Mailing City,State,Zip:		CAMP HILL, PA 17011
Owner Name:	1679 LLC	
Owner Type:		Private
Operator Name:	RITE AID OF NEW YORK INC	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A

RITE AID #03978 (Continued) **1001113445**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200227
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D011
Waste Description:	SILVER
Waste Code:	D013
Waste Description:	LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)
Waste Code:	D016
Waste Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D022
Waste Description:	CHLOROFORM
Waste Code:	D024
Waste Description:	M-CRESOL
Waste Code:	D026
Waste Description:	CRESOL

RITE AID #03978 (Continued) **1001113445**

Waste Code:	D027
Waste Description:	1,4-DICHLOROBENZENE
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	P001
Waste Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Waste Code:	P075
Waste Description:	NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS
Waste Code:	U002
Waste Description:	2-PROPANONE (I) (OR) ACETONE (I)
Waste Code:	U035
Waste Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL
Waste Code:	U044
Waste Description:	CHLOROFORM (OR) METHANE, TRICHLORO-
Waste Code:	U058
Waste Description:	2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE
Waste Code:	U072
Waste Description:	BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE
Waste Code:	U122
Waste Description:	FORMALDEHYDE
Waste Code:	U129
Waste Description:	CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE
Waste Code:	U154
Waste Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Waste Code:	U165
Waste Description:	NAPHTHALENE
Waste Code:	U188
Waste Description:	PHENOL
Waste Code:	U201
Waste Description:	1,3-BENZENEDIOL (OR) RESORCINOL
Waste Code:	U205
Waste Description:	SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)
Waste Code:	U211
Waste Description:	CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-
Waste Code:	U240

RITE AID #03978 (Continued) **1001113445**

Waste Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MONAJ REALTY CORP C-O P ZAHAKOS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1 CROSS ISLAND PKWY SUITE 231
Owner/Operator City,State,Zip: ROSEDALE, NY 11422
Owner/Operator Telephone: 718-276-7676
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF NEW YORK INC
Legal Status: Private
Date Became Current: 19961111
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 1679 LLC
Legal Status: Private
Date Became Current: 19960412
Date Ended Current: Not reported
Owner/Operator Address: 124-19 METROPOLITAN AVE
Owner/Operator City,State,Zip: KEW GARDENS, NY 11415
Owner/Operator Telephone: 718-441-7100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: RITE AID CORP
Legal Status: Private
Date Became Current: 19961111
Date Ended Current: Not reported
Owner/Operator Address: 30 HUNTER LANE
Owner/Operator City,State,Zip: CAMP HILL, PA 17011
Owner/Operator Telephone: 717-761-2633
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID CORP

RITE AID #03978 (Continued) **1001113445**

Legal Status:	Private
Date Became Current:	19961111
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MONAJ REALTY CORP C-O P ZAHAKOS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CROSS ISLAND PKWY SUITE 231
Owner/Operator City,State,Zip:	ROSEDALE, NY 11422
Owner/Operator Telephone:	718-276-7676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MONAJ REALTY CORP C-O P ZAHAKOS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1 CROSS ISLAND PKWY SUITE 231
Owner/Operator City,State,Zip:	ROSEDALE, NY 11422
Owner/Operator Telephone:	718-276-7676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: 1679 LLC	
Legal Status:	Private
Date Became Current:	19960412
Date Ended Current:	Not reported
Owner/Operator Address:	124-19 METROPOLITAN AVE
Owner/Operator City,State,Zip:	KEW GARDENS, NY 11415
Owner/Operator Telephone:	718-441-7100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: RITE AID OF NEW YORK INC	
Legal Status:	Private
Date Became Current:	19961111
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LN
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	717-972-3989
Owner/Operator Email:	EHS@RITEAID.COM

RITE AID #03978 (Continued) **1001113445**

Historic Generators:

Receive Date:	19990708
Handler Name: MONAJ REALTY CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: MONAJ REALTY CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: MONAJ REALTY CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19960523
Handler Name: MONAJ REALTY CORP	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20111104
Handler Name: RITE AID #3978	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY

RITE AID #03978 (Continued) **1001113445**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150914
Handler Name: RITE AID #03978	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20190417
Handler Name: RITE AID #03978	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	44611
NAICS Description:	PHARMACIES AND DRUG STORES

NAICS Code:	446110
NAICS Description:	PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violation:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	19970826
Actual Return to Compliance Date:	19971015
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19971001
Enforcement Identifier:	000
Date of Enforcement Action:	19970826
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NY

RITE AID #03978 (Continued) **1001113445**

Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19970301
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19971015
Scheduled Compliance Date:	19971001
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004525292

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

RITE AID #03978 (Continued) **1001113445**

Envid:	1001113445
Registry ID:	110004525292
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004525292
Name:	RITE AID #03978
Address:	1679 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225

NY MANIFEST:

Name:	RITE AID #3978
Address:	1679 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11223
Country:	USA
EPA ID:	NYR000024356
Facility Status:	Not reported
Location Address 1:	1679 BEDFORD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000024356
Mailing Name:	RITE AID #3978
Mailing Contact:	PETER ZAHAKOS
Mailing Address 1:	1 CROSS ISLAND PKW SUITE 231
Mailing Address 2:	Not reported
Mailing City:	ROSEDALE
Mailing State:	NY
Mailing Zip:	11422
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182767676

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	12/23/2014
Trans1 Recv Date:	12/23/2014
Trans2 Recv Date:	12/29/2014
TSD Site Recv Date:	12/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000024356
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	007387160FLE
Import Indicator:	N
Export Indicator:	N

RITE AID #03978 (Continued) **1001113445**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	7
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J128 **901 WASHINGTON AVE** **NY AST** **A100175103**
NNW **901 WASHINGTON AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.171 mi.
903 ft. **Site 7 of 7 in cluster J**

Relative:
Higher

Actual:
121 ft.

AST:

Name:	901 WASHINGTON AVE
Address:	901 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-311464
Program Type:	PBS
UTM X:	587758.12802
UTM Y:	4502426.98452
Expiration Date:	03/03/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14278
Affiliation Type:	Emergency Contact
Company Name:	901 BKLYN REALTY LLC C/O BROOKLYN EQUITIES II LLC
Contact Type:	Not reported
Contact Name:	KEVIN PADGETT
Address1:	Not reported
Address2:	Not reported
City:	Not reported

901 WASHINGTON AVE (Continued) **A100175103**

State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 689-7543
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-04-22

Site Id: 14278
Affiliation Type: Facility Owner
Company Name: 901 BKLYN REALTY LLC C/O BROOKLYN EQUITIES 11 LLC
Contact Type: V.P
Contact Name: KEVIN PADGETT
Address1: 45 MAIN STREET
Address2: SUITE 846
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (347) 689-7543
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2019-12-17

Site Id: 14278
Affiliation Type: Mail Contact
Company Name: 901 BKLYN REALTY LLC C/O BROOKLYN EQUITIES 11 LLC
Contact Type: V.P
Contact Name: KEVIN PADGETT
Address1: 45 MAIN STREET
Address2: SUITE 846
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (347) 689-7543
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2019-12-17

Site Id: 14278
Affiliation Type: Facility Operator
Company Name: 901 WASHINGTON AVE
Contact Type: Not reported
Contact Name: GERMAN FIQUEROA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 508-7349
EMail: Not reported
Fax Number: Not reported

901 WASHINGTON AVE (Continued) **A100175103**

Modified By: JSMACRI
Date Last Modified: 2019-12-17

Tank Info:

Tank Number: 001
Tank Id: 24413
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/04/1963
Capacity Gallons: 7000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

P129 **BEDOSULL AUTO REPAIR** **NY UST** **U004046114**
ESE **1727 BEDFORD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.174 mi.
917 ft. **Site 8 of 12 in cluster P**

Relative: **Lower**
Actual: **74 ft.**

UST:
Name: BEDOSULL AUTO REPAIR
Address: 1727 BEDFORD AVE
City,State,Zip: BROOKLYN, NY 11225
Id/Status: 2-610211 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 588156.81391
UTM Y: 4501996.82917
Site Type: Retail Gasoline Sales

Affiliation Records:

BEDOSULL AUTO REPAIR (Continued) **U004046114**

Site Id:	364106
Affiliation Type:	Facility Owner
Company Name:	ALBERT CHANG
Contact Type:	OWNER
Contact Name:	ALBERT CHANG
Address1:	239 HAWTHORN ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 953-0050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-06-09

Site Id:	364106
Affiliation Type:	Mail Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	ALBERT CHANG
Address1:	239 HAWTHORNE STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 953-0050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-06-09

Site Id:	364106
Affiliation Type:	Facility Operator
Company Name:	BEDOSULL AUTO REPAIR
Contact Type:	Not reported
Contact Name:	ALBERT CHANG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 953-0050
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-05-18

Site Id:	364106
Affiliation Type:	Emergency Contact
Company Name:	ALBERT CHANG
Contact Type:	Not reported
Contact Name:	ALBERT CHANG
Address1:	Not reported

BEDOSULL AUTO REPAIR (Continued) **U004046114**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 953-0500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-05-18

Tank Info:

Tank Number:	01
Tank ID:	211817
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/27/1977
Date Tank Closed:	06/19/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
J00 - Dispenser - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B02 - Tank External Protection - Original Sacrificial Anode

Tank Number:	02
Tank ID:	211818
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/27/1977
Date Tank Closed:	06/19/2006
Registered:	True

BEDOSULL AUTO REPAIR (Continued) **U004046114**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L00 - Piping Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B02 - Tank External Protection - Original Sacrificial Anode

Tank Number: 03
Tank ID: 211819
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/27/1977
Date Tank Closed: 06/19/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
J00 - Dispenser - None
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

BEDOSULL AUTO REPAIR (Continued) **U004046114**

B02 - Tank External Protection - Original Sacrificial Anode
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 04
Tank ID: 211820
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/27/1977
Date Tank Closed: 06/19/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
J00 - Dispenser - None
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None

Tank Number: 05
Tank ID: 211821
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/27/1977
Date Tank Closed: 06/19/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

BEDOSULL AUTO REPAIR (Continued) **U004046114**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L00 - Piping Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
J00 - Dispenser - None
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B02 - Tank External Protection - Original Sacrificial Anode

Tank Number: 06
Tank ID: 211822
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/27/1977
Date Tank Closed: 06/19/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J00 - Dispenser - None
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None

Tank Number: 07
Tank ID: 211823

BEDOSULL AUTO REPAIR (Continued) **U004046114**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/27/1977
Date Tank Closed:	06/19/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J00 - Dispenser - None
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
B02 - Tank External Protection - Original Sacrificial Anode
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number:	08
Tank ID:	211824
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/27/1977
Date Tank Closed:	06/19/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L00 - Piping Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
J00 - Dispenser - None

BEDOSULL AUTO REPAIR (Continued) **U004046114**

F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B02 - Tank External Protection - Original Sacrificial Anode

Tank Number:	09
Tank ID:	211825
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/27/1977
Date Tank Closed:	06/19/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B02 - Tank External Protection - Original Sacrificial Anode
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None

Tank Number:	10
Tank ID:	211826
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/27/1977
Date Tank Closed:	06/19/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

BEDOSULL AUTO REPAIR (Continued) **U004046114**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B02 - Tank External Protection - Original Sacrificial Anode
J00 - Dispenser - None

Tank Number: 11
Tank ID: 211828
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/27/1977
Date Tank Closed: 06/19/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B02 - Tank External Protection - Original Sacrificial Anode
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C03 - Pipe Location - Aboveground/Underground Combination

BEDOSULL AUTO REPAIR (Continued) **U004046114**

F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None

P130 **BRIDGESTONE FIRESTONE** **RCRA NonGen / NLR** **1000789410**
SE **1750 BEDFORD AVE** **FINDS** **NYD987008711**
1/8-1/4 **BROOKLYN, NY 11225** **ECHO**
0.175 mi.
925 ft. **Site 9 of 12 in cluster P**

Relative: **Lower**

Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	BRIDGESTONE FIRESTONE	
Handler Address:		1750 BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11225-3327
EPA ID:		NYD987008711
Contact Name:		Not reported
Contact Address:		RTE 9 SUITE 411
Contact City,State,Zip:		WOODBRIDGE, NY 07095
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		RTE 9 SUITE 411
Mailing City,State,Zip:		WOODBRIDGE, NY 07095
Owner Name:	BRIDGESTONE FIRESTONE	
Owner Type:		Private
Operator Name:	BRIDGESTONE FIRESTONE	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No

BRIDGESTONE FIRESTONE (Continued) **1000789410**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: BRIDGESTONE FIRESTONE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	900 RTE 9 SUITE 411
Owner/Operator City,State,Zip:	WOODBRIDGE, NJ 07095
Owner/Operator Telephone:	908-855-1900
Owner/Operator Telephone Ext:	Not reported

BRIDGESTONE FIRESTONE (Continued) **1000789410**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BRIDGESTONE FIRESTONE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 900 RTE 9 SUITE 411
Owner/Operator City,State,Zip: WOODBRIDGE, NJ 07095
Owner/Operator Telephone: 908-855-1900
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BRIDGESTONE FIRESTONE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 900 RTE 9 SUITE 411
Owner/Operator City,State,Zip: WOODBRIDGE, NJ 07095
Owner/Operator Telephone: 908-855-1900
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: BRIDGESTONE FIRESTONE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: BRIDGESTONE FIRESTONE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BRIDGESTONE FIRESTONE
Federal Waste Generator Description: Not a generator, verified

BRIDGESTONE FIRESTONE (Continued) **1000789410**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920714
Handler Name: BRIDGESTONE FIRESTONE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004492576

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000789410
Registry ID: 110004492576
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004492576
Name: BRIDGESTONE FIRESTONE
Address: 1750 BEDFORD AVE
City,State,Zip: BROOKLYN, NY 11225

R131 **NYC SANITATION** **RCRA NonGen / NLR** **1000140988**
NE **115 CROWN ST - BK-E-9** **ICIS** **NYD982529679**
1/8-1/4 **BROOKLYN, NY 11225** **FINDS**
0.176 mi. **ECHO**
928 ft. **Site 1 of 4 in cluster R**

Relative: **Higher**
Actual: **108 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	NYC SANITATION	
Handler Address:		115 CROWN ST - BK-E-9
Handler City,State,Zip:		BROOKLYN, NY 11225-2003
EPA ID:		NYD982529679
Contact Name:		Not reported
Contact Address:		58TH ST - ROOM 404
Contact City,State,Zip:		WOODSIDE, NY 11377
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		58TH ST - ROOM 404
Mailing City,State,Zip:		WOODSIDE, NY 11377
Owner Name:	MR USDAN	
Owner Type:		Private
Operator Name:	MR USDAN	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

NYC SANITATION (Continued) **1000140988**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MR USDAN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MR USDAN	
Legal Status:	Private
Date Became Current:	Not reported

NYC SANITATION (Continued) **1000140988**

Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MR USDAN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: NYC SANITATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: NYC SANITATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: NYC SANITATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

NYC SANITATION (Continued) **1000140988**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19880202
Handler Name: NYC SANITATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: 02-1991-0160
FRS ID: 110004421297
Action Name: NYC, REFUELING FACILITIES
Facility Name: NYC SANITATION
Facility Address: 115 CROWN ST - BK-E-9
BROOKLYN, NY 112252003
Enforcement Action Type: Pre-Referral Negotiation
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Judicial
EA Type Code: PRN
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.666726
Longitude in Decimal Degrees: -73.957304
Permit Type Desc: Not reported
Program System Acronym: 31397
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: NYC SANITATION
Address: 115 CROWN ST - BK-E-9
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

NYC SANITATION (Continued) **1000140988**

Facility Name: NYC SANITATION
Address: 115 CROWN ST - BK-E-9
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

FINDS:
Registry ID: 110004421297

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000140988
Registry ID: 110004421297
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004421297
Name: NYC SANITATION
Address: 115 CROWN ST - BK-E-9
City,State,Zip: BROOKLYN, NY 11225

R132
NE
1/8-1/4
0.176 mi.
928 ft.

BROOKLYN EAST 09 DOS -DDC
115 CROWN STREET
BROOKLYN, NY

Site 2 of 4 in cluster R

NY LTANKS **S104621550**
NY Spills **N/A**

Relative: Higher

Actual: 108 ft.

LTANKS:
Name: BROOKLYN EAST 09 DOS -DDC
Address: 115 CROWN STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9614782 / 2005-02-23
Facility ID: 9614782
Site ID: 117169

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

Spill Date:	1997-03-24
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not reported
Reported to Dept:	1997-03-24
CID:	205
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-03-24
Spill Record Last Update:	2005-02-23
Spiller Name:	WILLIAM FENNELL
Spiller Company:	DEPT OF SANITATION
Spiller Address:	301 WEST 215TH ST
Spiller County:	001
Spiller Contact:	TONY MARINO
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	101929
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY The spill is closed in consultation with Alex to consolidate with spill # 9702991. -II (02/23/05). "
Remarks:	"SOIL SAMPLES SHOWED CONTAMINATION OF BOTH GASOLINE & DIESEL"

All Materials:

Site ID:	117169
Operable Unit ID:	1042444
Operable Unit:	01
Material ID:	339883
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	117169
Operable Unit ID:	1042444
Operable Unit:	01
Material ID:	339884
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

Oxygenate: Not reported

Name: BROOKLYN EAST 09 DOS -DDC
Address: 115 CROWN STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0001495 / 2005-05-09
Facility ID: 0001495
Site ID: 314854
Spill Date: 2000-05-04
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: AIIslam
Referred To: Not reported
Reported to Dept: 2000-05-05
CID: 390
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-05-05
Spill Record Last Update: 2005-05-09
Spiller Name: JOHN LEDDY
Spiller Company: NYC DEPT OF SANITATION.
Spiller Address: 115 CROWN ST
Spiller County: 001
Spiller Contact: JOHN LEDDY
Spiller Phone: (631) 321-4670
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 101929
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY This spill is also referred to spill #s 0001496 and 0001497. - II (01/23/05). 5/9/05- The site is under active remediation by LiRo Engineers through installation of SVE system in place for soil contamination. Most recent monitoring results of influent air show that soil VOC contamination has been removed. Close-out soil borings are underway. The site has another open spill (# 9702991) from motor oil. As such this spill is closed to consolidate with that spill. -II. "
Remarks: "TANK FAILED TEST, NO PRODUCT SPILLAGE C/R - NEXT 2 SPILLS FROM SAME LOCATION"

All TTF:
Facility ID: 0001495
Spill Number: 0001495
Spill Tank Test: 1525560
Site ID: 314854
Tank Number: 1
Tank Size: 550
Material: 0015A
EPA UST: Not reported

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	314854
Operable Unit ID:	823090
Operable Unit:	01
Material ID:	289715
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001496 / 2005-02-23
Facility ID:	0001496
Site ID:	314855
Spill Date:	2000-05-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not reported
Reported to Dept:	2000-05-05
CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-05
Spill Record Last Update:	2005-02-23
Spiller Name:	JOHN LEDDY
Spiller Company:	NYC DEPT OF SANITATION.
Spiller Address:	115 CROWN ST
Spiller County:	001
Spiller Contact:	JOHN LEDDY
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

DEC Region: 2
DER Facility ID: 101929
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY The spill is closed in consultation with Alex to consolidate with spill # 0001495. This spill is also referred to spill #s 0001497 and 0001495. -II (02/23/05). "
Remarks: "TANK FAILED TEST - NO PRODUCT SPILLAGE C/R - PREVIOUS AND NEXT SPILL FROM SAME LOCATION"

All TTF:
Facility ID: 0001496
Spill Number: 0001496
Spill Tank Test: 1525561
Site ID: 314855
Tank Number: 2
Tank Size: 550
Material: 1096A
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 314855
Operable Unit ID: 823091
Operable Unit: 01
Material ID: 289716
Material Code: 1096A
Material Name: hoist oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: BROOKLYN EAST 09 DOS -DDC
Address: 115 CROWN STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0001497 / 2005-02-23
Facility ID: 0001497
Site ID: 314856
Spill Date: 2000-05-04
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: AIIslam
Referred To: Not reported

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

Reported to Dept:	2000-05-05
CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-05
Spill Record Last Update:	2005-02-23
Spiller Name:	JOHN LEDDY
Spiller Company:	NYC DEPT OF SANITATION.
Spiller Address:	115 CROWN ST
Spiller County:	001
Spiller Contact:	JOHN LEDDY
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	101929
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY I spoke with Afsar and told her that tanks must be taken out of service or repaired immeadiately. Afsar Taherzadeh told me that tanks will be taken out of service May 15, 2000. The spill is closed in consultation with Alex to consolidate with spill # 0001495. - II (02/23/05) "
Remarks:	"TANK FAILED TEST - NO PRODUCT SPILLAGE C/R - PREVIOUS 2 SPILLS AT SAME LOCATION"

All TTF:

Facility ID:	0001497
Spill Number:	0001497
Spill Tank Test:	1525562
Site ID:	314856
Tank Number:	3
Tank Size:	550
Material:	1096A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	314856
Operable Unit ID:	823092
Operable Unit:	01
Material ID:	289717
Material Code:	1096A
Material Name:	hoist oil
Case No.:	Not reported
Material FA:	Petroleum

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702991 / 2009-06-08
Facility ID:	9702991
Facility Type:	ER
DER Facility ID:	101929
Site ID:	314857
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1997-06-10
Investigator:	jamaison
Referred To:	NFA
Reported to Dept:	1997-06-10
CID:	370
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-06-10
Spill Record Last Update:	2009-06-08
Spiller Name:	Not reported
Spiller Company:	NYC SANITATION GARAGE
Spiller Address:	50 KENT AV
Spiller Company:	001
Contact Name:	ABOVE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY TRANSFERRED TO I. ISLAM This spill is also referred to spill # 9614782. -II (02/23/05). 6/6/05- The soil only contamination at the site is being treated by operating SVE system at the site by LiRo Engineers. GW is at 80'bgs. Reviewed the quarterly monitoring report Jan/05-Mar/05. The SVE system is remediating soil effectively. Confirmation soil borings and soil samplings are required to be done during the next quarter to consider closing out of the spill. - II 6/15/05- LiRo's email request for five close-out soil boring locations is approved via email with a modification to relocate SBR-24 further north.- II 5/23/05- Finally, close-out soil sampling plan (for 6 locations-SBR-20 to SBR-25)is approved.Soil boring to be started in the 1st week of July/05. STV Inc on behalf of Dormitory Authority of State of NY (DASNY)submitted a plan to develop the site for the construction of Dormitory building and parking lot of the Edgar Evers College. A decision on this is dependent upon the close-out soil sampling results.- II 9/13/05- Reviewed the

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

Apr.-July/05 quarterly monitoring report.And, had a meeting with Peter Burger of STV. In principle, it's agreed that existing SVE sytem on eastern area can be dismantled to allow foundation excavation for the proposed Dormitory Bldg., and shallow depth contaminated soil will be removed. The western side SVE system will continue until such time that parking area dev. works on the area starts. It's anticipated that it will require about 6 months to 1 year to start working in parking area. Sudden spike of TVOC (20,900 ug/m^3)in SVE influent air in the month of June is a concern. LiRo has been asked to provide with the latest data on this.- II 10/24/05- Reviewed the August-Sept/05 monitoring report. The Sept./05 system influent air VOC concentration (4,740ug/m^3) suggests that the system may be collecting slightly more VOCs than it had been collecting prior to June 2005 and the amount of increase is said to be attributable to natural causes such as changes in soil moisture conditions. The reason for SVE system influent air spike in June 2005 is not clear. Based on PID readings, no unusual event occurred to cause the sudden increase, and it is said that the spike might be as a result of cross-contamination or lab. error. Spoke to Peter Burger of STV Inc. who is the consultant for DASNY to construct the dormitory bldg at the site. He indicated that the dismantling of the existing bldg. in eastern area would take place in this winter to start foundation excavation in next year April/May. It has been agreed that the SVE system in the eastern area may be shut down and the proposed excavation for the dormitory bldg construction should address any shallow residual contamination in the eastern portion of the site. On the other hand, SVE system at the western portion may continue until such time that the proposed parking area dev starts in next year summer. The dev. of parking area is considered to be protective of human health and environment, and any remaining residual contamination at deeper depth (at 25'-35') will be addressed through natural attenuation. A letter was issued to this effect addessed to NYCDDC and cc'd to DASNY, STV and LiRo. Filed the report in the eDoc.- II 03/29/06: This spill transferred from I.Islam to S.Kraszewski - SK 03/31/06: Sent Email to Steve Frank at LiRo asking for new contact information. Ed Looney , PM GREYHAWK North America, L.L.C. 260 Crossways Park Drive Woodbury, NY 11797 * phone: 516.921.1900 * fax: 516.921.5649 * email: elooney@greyhawk.com DOS is no longer at the site. Greyhawk started site visits in January, but was locked out for the first 9 days. Turns out that DASNY has started the process of taking down the building; it is slated for demolition. Ed has professed his disagreement and proposes that Turner Contructions go no further until the system can be analyzed by his guys. He will keep me breast of any future activities. - SK 04/21/06: Spoke with Peter Burger, from STV about the Brooklyn East 9 site for NYCDDC. DASNY wants to build a dormitory on the site. Peter is requesting to shut-down the SVE in order to begin construction and excavation activities on-site. Based on the most recent SVE system monitoring data, he believes that little residual soil contamination remains. GW is said to be a 90 fbg, too deep to be impacted. Peter will be stopping by on Monday at 1:00PM to discuss what plan of action should be taken. - SK 04/24/06: Met with Pete Burger from STV, accompanied by J.Kolleeny. Pete explained the situation with the site and what plans are in place to address the existing SVE system and residual soil contamination. Since Imdad's October 2005 letter giving the go-ahead to shutdown the system, STV has been hired by DASNY to work with Greyhawk and DDC to reclaim the site and build an academic

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

building. The buildings footprint will cover most of the environmental conditions limit area expected to be impacted by the contamination. Two areas of concern are identified: residual contamination in subsurface soil ranging from 20' - 40' below ground as determined by soil borings. STV plans to keep the system running until mid-May, then proposes to shutdown and dismatle it. One area of concern will be addressed by excavation activities for the structure, since it is relatively shallow. Pete has told us that they will excavate until screening and soil tests confirm that no contamination remains. The second area will be left alone and natural attenuation will take its course. Continuous monitoring activities will be conducted during excavation for the entire site. All on-site USTs and ASTs will be removed and disposed of properly. The building will have a passive ventalation system installed throughout the structure and based on a month long post-construction air monitoring event it will be determined whether an active system will be necessary. As mentioned, Imdad has already given the word to allow these activites to begin. John mentioned that since DDC is the RP and Greyhawk is the contractor responsible we would require a requested letter from Greyhawk to shutdown the system rather than STV requesting it. SK will be sending out an Email to Ed Looney asking for them to submit a letter to request terminattion of SVE system activities. - SK 05/01/06: Fatemeh Ashkan called asking for the documents STV submitted and to inquire about the Wednesday meeting. I told her that I would PDF the documents and send her an Email. Jon and I will discuss about attending the meeting. - SK 06/12/06: Received SVE Shutdown Request dated April 9, 2006 (typo: date should be June 9, 2006)prepared and submitted by Greyhawk on behalf of NYCDDC. The letter formaly requests the termination and removal of the SVE system on-site.The Department approves this request, letter sent out. - SK 10/27/06 Spill case transferred from S. Kraszewski to J. Maisonave. - JAM 01/09/07 Met with P. Burger at SVT to discuss the remediation plan/site redevelopment. The site is behind schedule. Excavation/tank removal is slated for the week of Jan. 15 and the site-wide excavation is slated for Jan. 22. - JAM 01/18/07 Sent email to P. Burger and NYCDDC letting him know that a PBS application form for information correction must be submitted to change the status of the tanks from Closed in Place to Closed-Removed. - JAM 2/27/06 Met with Peter Burger of STV to go over the tank closure report. STV wrote two reports, one for this site address at 115 Crown St and one for address 123 Crown St. All active ASTs and USTs were removed from the site and closure soil sampling showed very little petroleum impacts. The entire site will be excavated as soon as a DASNY finishes negotiating with the disposal facilities. - JAM 3/15/07. Recieved a call from P. Burger of SVT. Four 550-gallon USTs were discovered while excavating the site for construction of the new academic building. The tanks were abandoned-in-place by an unknown party. All the tanks will be removed and end-point samples will be taken. - JAM 3/19/07 The four tanks were removed. No visible soil impacts were observed and soil sampling will be done across the entire site. 4/23/07 Received a call from P. Burger. Three additional tanks were discovered under the basement floor of the previous facility. The tanks were abondoned-in-place and filled with sand. The tanks were encased in concrete and the surrounding soil was visibly contaminated. All the tanks will be removed along with any contaminated soil. Soils will be screen with PID while being excavated. When PID readings are zero, end-point samples will be

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

taken. - JAM 6/1/07 Visited the site at 1:30pm. Closure sampling has begun throughout the entire site. A total of 29 samples will be taken to characterize soil at grade. 16 samples were taken and analyzed so far and all are below TAGM numbers. P. Burger of STV asked me to come look at the area where 4 USTs were removed (1 4,000-gal and 3 550-gal). Surrounding soil was screened with a PID and determined to be contaminated. This is the area above Residual Area 2. Since the construction trailors are adhacent to the contaminated soil, they believe excavation has reached its limit without undermining the construction trailors. Mr. Burger said they plan to excavate as much soil as possible and take endpoint samples (2 from both the north and south walls, 3 from both the east and west walls, and 4 bottom, total 14). If there is still contamination based on laboratory endpoint samples then they will come back to remediate after the trailors are removed. - JAM 10/29/07 Spoke to P. Burger today. He will prepare a Remedial Summary Report. - JAM 6/19/08 PBS numbers 115 Crown Street - 2-456020 123 Crown Street - 2-610277 Met with P. Burger from STV yesterday to go over the closure report. All tanks on-site and contaminated soils to a depth of 20' were removed. Residual soil contamination remains at the interval from 20' to 40', which is beneath a new asphalt parking lot next to the academic building. DASNY is reviewing the closure report and when they complete their review, STV will submit the report to Greyhawk/Roux and the NYSDEC. Spill number 9011356, which was open at this site for a fuel oil spill, was closed today and consolidated with spill number 9702991. Since all tanks, associated piping and shallow contaminated soil have been removed, the tank associated with spill number 9011356 no longer exists on the site. - JAM 6/5/09 Reviewed the Closure Assessment Report for 115 Crown St. and 123 Crown St submitted by STV, on behalf of DASNY, to Roux and forwarded to the DEC by Roux. The report summarizes all remedial activities performed on-site prior to constructing a new academic building for Medgar Evers College. Soil contamination from petroleum releases (gasoline and diesel) occurred at this former DOS garage and was being remediated with a SVE system, which was initiated in July 2001. The new academic building encompasses two addresses: 115 Crown St. (former DOS garage) and 123 Crown St. (former auto service shop). The groundwater table, located at 90 ft below ground surface, was not impacted. The SVE system operated until August 2006 when it was shut down (with DEC approval) prior to excavation activities. All USTs and ASTs were removed from both sites and contaminated soils were excavated down to 20-25 ft below grade prior to construction of the new building. End-point soil samples were collected after the tank removals. Some contaminated soil was encountered after excavating the USTs, however, further soil excavation occurred later for the building foundation. End-point soil samples were collected in a grid pattern from the excavation of the building footprint. No VOCs were detected above regulatory criteria in any samples from the building excavation. However, there were some minor SVOC and metals exceeding criteria. The concentrations for metals were shown to be less than background levels. Deeper known soil contamination (greater than 20 feet) was left in place, which the DEC agreed to in correspondence on October 25, 2005 because this soil contamination is not affecting the deep water table and poses no threat to human health. The building was constructed with a vapor barrier and a passive sub-slab venting system. STV recommends that this site be considered for closure. On January 19, 2009, Roux submitted a letter with STV s Closure Assessment Report attached,

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

requesting that spill number 9702991 be closed. Based on the available information, this site poses no threat to human health or the environment. On June 8, 2009, DEC issued a No Further Action letter. All 3 STV Reports and Roux's Request for Spill Closure Report as well as the NFA letter are uploaded to eDocs. - JAM"

Remarks: "CALLER IS IN PROCESS OF DOING TANK ABANDONMENT FOUND CONTAMINATED SOIL ON TOP OF TANK SOIL WAS EXCAVATED AND REMOVED"

All Materials:

Site ID:	314857
Operable Unit ID:	1045721
Operable Unit:	01
Material ID:	335904
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9011356 / 2008-06-19
Facility ID:	9011356
Facility Type:	ER
DER Facility ID:	101929
Site ID:	117168
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1991-01-28
Investigator:	jamaison
Referred To:	Not reported
Reported to Dept:	1991-01-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-02-08
Spill Record Last Update:	2008-06-19
Spiller Name:	C/O MIDWOOD MGNT CO
Spiller Company:	NATHAINEL USDAIN
Spiller Address:	60 EAST 42ND STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY 01/28/91: DEC INSPECTED SITE,FOUND THICK #4 F.O.

BROOKLYN EAST 09 DOS -DDC (Continued) **S104621550**

ACCUMULATING AROUND THE FILL PIPE, NYCDOS TO EMPTY OUT TANK,SET UP TEMPORARY TANK FOR HEATING, EXCAVATE AREA ALONG FILLPIPE TO LOCATE LEAK & VAC OUT OIL. 10/27/06 Spill case transferred from S. Kraszewski to J. Maisonave. - JAM 6/19/08 This spill case has been tracked under spill number 9702991. The environmental consultant, STV, was hired on behalf of DASNY to oversee the construction of a new academic building for Medgar Evers College. All USTs and ASTs on-site have already been removed and contaminated soils were excavated for the foundation of the new building. This spill case is closed. Refer to spill 9702991. - JAM"

Remarks: "NYCDOS LEASED PROPERTY,WHILE DOING EXCAVATION ON SITE TO REPLACE EXISTING TANK,TO BE CLOSED ON SITE, OIL WAS DISCOVERED IN EXCAVATION, NYCDOS CLAIMS SPILL COULD BE FROM PIPE LEAK."

All Materials:

Site ID:	117168
Operable Unit ID:	951436
Operable Unit:	01
Material ID:	427904
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R133 **MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE)** **NY UST U004062138**
NE **115 CROWN STREET** **NY AST N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.176 mi.
928 ft. **Site 3 of 4 in cluster R**

Relative:
Higher

Actual:
108 ft.

UST:

Name:	MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE)
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-456020 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588175.22582
UTM Y:	4502249.75112
Site Type:	Other

Affiliation Records:

Site Id:	20086
Affiliation Type:	Facility Owner
Company Name:	DORMITORY AUTHORITY-STATE OF NEW YORK
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	515 BROADWAY
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12207

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Country Code:	001
Phone:	(518) 257-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-08-02

Site Id:	20086
Affiliation Type:	Mail Contact
Company Name:	DORMITORY AUTHORITY-STATE OF NEW YORK
Contact Type:	Not reported
Contact Name:	EUGENE LEUNG, R.A.
Address1:	OFFICE OF ENVIRONMENTAL AFFAIRS
Address2:	ONE PENN PLAZA, 52ND FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10119
Country Code:	001
Phone:	(212) 273-5109
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-06-20

Site Id:	20086
Affiliation Type:	Facility Operator
Company Name:	MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE)
Contact Type:	Not reported
Contact Name:	EUGENE LEUNG, R.A.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 467-0340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-08-02

Site Id:	20086
Affiliation Type:	Emergency Contact
Company Name:	DORMITORY AUTHORITY-STATE OF NEW YORK
Contact Type:	Not reported
Contact Name:	ROBERT THELIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 727-8103
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-08-02

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tank Info:

Tank Number:	001
Tank ID:	36437
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	36438
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 36439
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: 004
Tank ID: 173634
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004-A
Tank ID: 173646
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 36441
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0013
Common Name of Substance: Lube Oil

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G07 - Tank Secondary Containment - Excavation Liner
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 36442
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 36443
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 12/01/2000

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 008
Tank ID: 36444
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: 10/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 010

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tank ID: 36446
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1080
Install Date: 01/01/1991
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 011VR4
Tank ID: 64393
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/2000
Date Tank Closed: 07/15/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 012
Tank ID: 53494
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1080
Install Date: Not reported
Date Tank Closed: 04/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 1
Tank ID: 59323
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 01/01/2001
Date Tank Closed: 07/15/2006
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
L09 - Piping Leak Detection - Exempt Suction Piping
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number:	2
Tank ID:	59324
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	01/01/2001
Date Tank Closed:	07/15/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
F05 - Pipe External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	3
Tank ID:	59325
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	01/01/2001
Date Tank Closed:	07/15/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0022

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
L09 - Piping Leak Detection - Exempt Suction Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number: 4
Tank ID: 36447
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 2000
Install Date: 01/01/1991
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
D02 - Pipe Type - Galvanized Steel
I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: U001

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tank ID: 218657
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 01/18/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: U002
Tank ID: 218658
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 01/18/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number: U003
Tank ID: 218659
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 01/18/2007
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
B04 - Tank External Protection - Fiberglass
I04 - Overfill - Product Level Gauge (A/G)
F05 - Pipe External Protection - Jacketed
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number: U004
Tank ID: 218660
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 01/18/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
F02 - Pipe External Protection - Original Sacrificial Anode
G04 - Tank Secondary Containment - Double-Walled (Underground)
I04 - Overfill - Product Level Gauge (A/G)
B02 - Tank External Protection - Original Sacrificial Anode
H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number: U005
Tank ID: 218661
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/19/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: U006

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tank ID: 218662
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 05/29/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: U007
Tank ID: 218663
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/19/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	U008
Tank ID:	218664
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	04/17/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number:	U009
Tank ID:	218665
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/29/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: U010
Tank ID: 218666
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/25/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: U011
Tank ID: 218667
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Install Date: Not reported
Date Tank Closed: 04/25/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: U012
Tank ID: 218668
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/25/2004
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: U013
Tank ID: 218669
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/25/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: U014
Tank ID: 218670
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/19/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	U015
Tank ID:	218671
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/19/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	U016
Tank ID:	218672
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/19/2007
Registered:	True
Tank Location:	Underground

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: U017
Tank ID: 218673
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/29/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tank Number:	U018
Tank ID:	218674
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/29/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
F02 - Pipe External Protection - Original Sacrificial Anode
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	U019
Tank ID:	218675
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	06/06/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	U020
Tank ID:	218676
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	03/19/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F02 - Pipe External Protection - Original Sacrificial Anode
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Number:	VR1
Tank ID:	64395
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1000
Install Date:	12/01/2001
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J03 - Dispenser - Gravity
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F00 - Pipe External Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Number: VR2
Tank ID: 64396
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 12/01/2001
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J03 - Dispenser - Gravity
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
F00 - Pipe External Protection - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: VR3
Tank ID: 64394
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 12/01/2001
Date Tank Closed: Not reported
Registered: True

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F00 - Pipe External Protection - None
J03 - Dispenser - Gravity
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

AST:
Name: MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE)
Address: 115 CROWN STREET
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-456020
Program Type: PBS
UTM X: 588175.22582
UTM Y: 4502249.75112
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 20086
Affiliation Type: Facility Owner
Company Name: DORMITORY AUTHORITY-STATE OF NEW YORK
Contact Type: Not reported
Contact Name: Not reported
Address1: 515 BROADWAY
Address2: Not reported
City: ALBANY
State: NY
Zip Code: 12207
Country Code: 001
Phone: (518) 257-3000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-08-02

Site Id: 20086
Affiliation Type: Mail Contact
Company Name: DORMITORY AUTHORITY-STATE OF NEW YORK

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Contact Type:	Not reported
Contact Name:	EUGENE LEUNG, R.A.
Address1:	OFFICE OF ENVIRONMENTAL AFFAIRS
Address2:	ONE PENN PLAZA, 52ND FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10119
Country Code:	001
Phone:	(212) 273-5109
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-06-20

Site Id:	20086
Affiliation Type:	Facility Operator
Company Name:	MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE)
Contact Type:	Not reported
Contact Name:	EUGENE LEUNG, R.A.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 467-0340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-08-02

Site Id:	20086
Affiliation Type:	Emergency Contact
Company Name:	DORMITORY AUTHORITY-STATE OF NEW YORK
Contact Type:	Not reported
Contact Name:	ROBERT THELIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 727-8103
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-08-02

Tank Info:

Tank Number:	5
Tank Id:	36445
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/15/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	6
Tank Id:	212321
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/15/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	A001
Tank Id:	218652
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/29/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	A002
Tank Id:	218653
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/29/2007
Register:	True

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

Tank Number: A003
Tank Id: 218654
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/29/2007
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

Tank Number: A004
Tank Id: 218655
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None

MEDGAR EVERS COLLEGE (AKA BROOKLYN 9 GARAGE) (Continued) **U004062138**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/29/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	A005
Tank Id:	218656
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/29/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

134
West
1/8-1/4
0.177 mi.
936 ft.

PROSPECT PARK ZOO
450 FLATBUSH AVENUE
BROOKLYN, NY 11225

NY UST **U001841853**
N/A

Relative:
Lower

Actual:
83 ft.

UST:

Name:	PROSPECT PARK ZOO
Address:	450 FLATBUSH AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-601280 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	12/19/2026
UTM X:	587548.72480
UTM Y:	4502065.38850
Site Type:	Other

Affiliation Records:

Site Id:	23247
Affiliation Type:	Facility Owner
Company Name:	NYC DEPT. OF PARKS & RECREATION
Contact Type:	OPERATIONS MAINTENANCE DEPT MGR
Contact Name:	MARK LEWANDOWSKI
Address1:	2 BOROUGH OF OPERATIONS
Address2:	Not reported
City:	RANDALLS ISLAND
State:	NY
Zip Code:	10035
Country Code:	001
Phone:	(212) 410-8916
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-11-30

Site Id:	23247
Affiliation Type:	Mail Contact
Company Name:	PROSPECT PARK ZOO
Contact Type:	Not reported
Contact Name:	LARRY SANTEE
Address1:	450 FLATBUSH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 399-7340
EMail:	PPZMAINTENANCE@WCS.ORG
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-11-09

Site Id:	23247
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPT. OF PARKS & RECREATION
Contact Type:	Not reported
Contact Name:	LARRY SANTEE
Address1:	Not reported

PROSPECT PARK ZOO (Continued) **U001841853**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 579-7518
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-11-09

Site Id:	23247
Affiliation Type:	Facility Operator
Company Name:	PROSPECT PARK ZOO
Contact Type:	Not reported
Contact Name:	WILDLIFE CONSERVATION SOCIETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 399-7340
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-11-09

Tank Info:

Tank Number:	001
Tank ID:	45185
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	04/25/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	01/12/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None

PROSPECT PARK ZOO (Continued) **U001841853**

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	207333
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1000
Install Date:	01/01/1986
Date Tank Closed:	04/06/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	003
Tank ID:	222975
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	02/29/2008
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	0
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	08/18/2011

PROSPECT PARK ZOO (Continued) **U001841853**

Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
B09 - Tank External Protection - Urethane
G04 - Tank Secondary Containment - Double-Walled (Underground)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

---

P135 **CON-ED - MH4802** **RCRA NonGen / NLR** **1027222043**
ESE **BEDFORD AVE AND EMPIRE BLVD** **NYP004043725**
1/8-1/4 **BROOKLYN, NY 11213**
0.178 mi.
939 ft. **Site 10 of 12 in cluster P**

Relative: **Lower**

Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:		20010103
Handler Name:	CON-ED - MH4802	
Handler Address:		BEDFORD AVE AND EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11213
EPA ID:		NYP004043725
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		IRVING PL RM 300
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL RM 300
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No

CON-ED - MH4802 (Continued) **1027222043**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20220324
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20010102
Handler Name:	MH4802

CON-ED - MH4802 (Continued) **1027222043**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010103
Handler Name: CON-ED - MH4802	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20010101
Handler Name: MH4802	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code:	22111
NAICS Description:	ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

Q136 **MONTGOMERY REALTY, LLC** **NY AST** **U003396871**
East **236 MONTGOMERY STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.181 mi.
958 ft. **Site 4 of 10 in cluster Q**

Relative:
Higher

Actual:
91 ft.

AST:

Name:	MONTGOMERY REALTY, LLC
Address:	236 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602875
Program Type:	PBS
UTM X:	588195.37654
UTM Y:	4502160.34566
Expiration Date:	12/27/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24830
Affiliation Type:	Facility Owner
Company Name:	MONTGOMERY REALTY LCC C/O MILBROOK PROPERTIES
Contact Type:	VP
Contact Name:	JEFFREY KATZ
Address1:	42 BAYVIEW AVENUE
Address2:	Not reported
City:	MANHASSET
State:	NY
Zip Code:	11030
Country Code:	001
Phone:	(516) 869-1240
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-12-28

Site Id:	24830
Affiliation Type:	Mail Contact
Company Name:	MONTGOMERY REALTY, LLC
Contact Type:	Not reported
Contact Name:	J. KATZ
Address1:	C/O MILBROOK PROPERTIES, LTD.
Address2:	42 BAYVIEW AVENUE
City:	MANHASSET
State:	NY
Zip Code:	11030
Country Code:	001
Phone:	(516) 869-1240
EMail:	JKATZ@MILBROOKPROPERTIES.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-12-28

Site Id:	24830
Affiliation Type:	Facility Operator
Company Name:	MONTGOMERY REALTY, LLC
Contact Type:	Not reported
Contact Name:	DARCO LIZARNA

MONTGOMERY REALTY, LLC (Continued) **U003396871**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 576-0419
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-03-03

Site Id:	24830
Affiliation Type:	Emergency Contact
Company Name:	MONTGOMERY REALTY LCC C/O MILBROOK PROPERTIES
Contact Type:	Not reported
Contact Name:	CHARLES HIRSCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 869-1240
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	51947
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground
	I04 - Overfill - Product Level Gauge (A/G)
	F06 - Pipe External Protection - Wrapped
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	B00 - Tank External Protection - None
	D02 - Pipe Type - Galvanized Steel
	A00 - Tank Internal Protection - None
	K00 - Spill Prevention - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/27/1927
Capacity Gallons:	3000

MONTGOMERY REALTY, LLC (Continued) **U003396871**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Q137 **MEDGAR EVERS COLLEGE (CUNY)** **NY LTANKS** **U001329958**
ENE **1650 BEDFORD AVENUE** **NY UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.182 mi.
962 ft. **Site 5 of 10 in cluster Q**

Relative:
Higher

Actual:
99 ft.

LTANKS:

Name:	MEDGAR EVERS COLLEGE
Address:	1650 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0706994 / 2009-12-29
Facility ID:	0706994
Site ID:	387611
Spill Date:	2007-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-09-24
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-24
Spill Record Last Update:	2009-12-29
Spiller Name:	Not reported
Spiller Company:	MEDGAR EVERS COLLEGE
Spiller Address:	1650 BEDFORD AVE
Spiller County:	001
Spiller Contact:	WILLIAM KLEIN
Spiller Phone:	(718) 762-5200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244651
DEC Memo:	"10/1/07 bf: Called Frank Tumminello of Medgar Evers College (718)270-6099. He said that he was aware of tank failure and CUNY will be bringing in contractor soon but, he was unsure of the date. I confirmed address and told him about ttf letter. I told him the registration expired and will include application in letter. he does not hyandle the registration, but would forward to right party. Sent letter to: Frank Tumminello Medgar Evers College 1150 Carroll St. Brooklyn, NY 11225 10/3/07 Received message from Esther Hundley,

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

Safety Officer of CUNY. She received letters (also for spill 0706996, a ttf, which happened at Medgar Evers College the same day). telephone: (212)541-0430. Tank repair and retesting will be handled by Woodard and cohen. There was no spill, but tanks are not tight. Will forward info to me as she gets it. bf 10/9/07 Received call from Michael Vanderheijenden of Woodard and Curran He said that he is the consultant for Medgar Evers and they wish to receive all correspondence. I faxed him information correction applications for this site and the one at Carroll St. PBS #s: 2-456926 and 2-601243. Fax: (914)448-0147. bf 11/1/07 letter from Woodward & Curran. Both tanks failed because of piping. Tank to be isolated anbd perform another tightness test. if tanks are tight, will replace supply and return lines with DW FRP pipe. Also, will install 2 five gallon spill buckets. bf 7/8/08 Received closure report from Mark Randazzo of O'Brien & Gere on 6/26/08. 12/29/09 Report states that the tank failure was due to one vent line. Inspection of soils during sampling did not indicate visual or olefactory evidence of petroleum. Samples taken around the tanks and from the tank bottoms. No compounds above Part 375-6 requirements. Checked rrequirements under SPOTS and none found to be above soil cleranup objectives. Report states that MEK was found at 130 ug/kg which is above above DEC requirement in 375-6 for unrestricted use, but beklow DEC requirement ofor commercial use (500 ug/kg). NFA. bf"

Remarks: "ESTERBROOK EASY THREE USED FOR TESTING TANKS; SEEMS TO BE A TANK TOP LEAK;"

All TTF:

Facility ID:	0706994
Spill Number:	0706994
Spill Tank Test:	1764134
Site ID:	387611
Tank Number:	1
Tank Size:	6000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

Facility ID:	0706994
Spill Number:	0706994
Spill Tank Test:	1764135
Site ID:	387611
Tank Number:	2
Tank Size:	6000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	387611
Operable Unit ID:	1144811
Operable Unit:	01
Material ID:	2135122
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	1650 BEDFORD AVE
Address:	1650 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225
Spill Number/Closed Date:	0313372 / 2008-07-09
Facility ID:	0313372
Site ID:	302810
Spill Date:	2004-03-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	BKFALVEY
Referred To:	Not reported
Reported to Dept:	2004-03-05
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-05
Spill Record Last Update:	2008-07-09
Spiller Name:	DAN SHEGRY
Spiller Company:	1650 BEDFORD AVE
Spiller Address:	1650 BEDFORD AVE
Spiller County:	001
Spiller Contact:	DAN SHEGRY
Spiller Phone:	(718) 270-4906
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	23137
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO sent TTF letter See also spill # 9913846 (ttf at same facility) 9/15/05: CBN Left a message for the owner to call back, but still

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

	hasn't received any call. 7/9/08 This spill to be administratively closed. Refer to Spill 0706994. Tanks to be closed - report received for tank closure on 6/26/08. bf"
Remarks:	"tank test failed.petroleum tank cleaners is contracted to cut the line from the tank and perform tank only test"

All TTF:

Facility ID:	0313372
Spill Number:	0313372
Spill Tank Test:	1529025
Site ID:	302810
Tank Number:	2
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	302810
Operable Unit ID:	878598
Operable Unit:	01
Material ID:	498524
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	MEDGAR EVANS COLLEGE
Address:	1650 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9913846 / 2005-03-14
Facility ID:	9913846
Site ID:	302811
Spill Date:	2000-03-08
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2000-03-08
CID:	371
Water Affected:	Not reported

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-03-08
Spill Record Last Update:	2005-03-14
Spiller Name:	GINA CONSTANTINI(CONTRACT
Spiller Company:	MEDGAR EVANS COLLEGE
Spiller Address:	1650 BEDFORD AVE
Spiller County:	001
Spiller Contact:	GINA CONSTANTINI(CONTRACT
Spiller Phone:	(516) 249-3150
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244651
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 5/18/04 - AUSTIN - TRANSFERRED FROM TOMASELLO FOR REASSIGNMENT - END 3/14/05 - Spill closed and consolidated with spill # 0313372 -end"
Remarks:	"CONTRACTOR NOTIFIED (GINA AT TYREE) - "

All TTF:

Facility ID:	9913846
Spill Number:	9913846
Spill Tank Test:	1548112
Site ID:	302811
Tank Number:	Not reported
Tank Size:	6000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	302811
Operable Unit ID:	1088379
Operable Unit:	01
Material ID:	292134
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

UST:

Name:	MEDGAR EVERS COLLEGE (CUNY)
Address:	1650 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-601243 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588160.58295
UTM Y:	4502213.67169
Site Type:	School

Affiliation Records:

Site Id:	23212
Affiliation Type:	Facility Owner
Company Name:	CITY UNIVERSITY OF NEW YORK ATT: HOWARD APSAN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	535 EAST 80TH ST, 3RD FL
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10075
Country Code:	001
Phone:	(212) 541-0430
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-04-29

Site Id:	23212
Affiliation Type:	Mail Contact
Company Name:	CAMPUS FACILITIES OFFICER
Contact Type:	Not reported
Contact Name:	FRANK TUMINELLO
Address1:	MEDGAR EVERS COLLEGE
Address2:	1650 BEDFORD AVENUE
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 270-6099
EMail:	FRANKT@MEC.CUNY.EDU
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-04-29

Site Id:	23212
Affiliation Type:	Facility Operator
Company Name:	MEDGAR EVERS COLLEGE (CUNY)
Contact Type:	Not reported
Contact Name:	FRANK TUMMINELLO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

Zip Code:	Not reported
Country Code:	001
Phone:	(718) 270-6099
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-04-29

Site Id:	23212
Affiliation Type:	Emergency Contact
Company Name:	CITY UNIVERSITY OF NEW YORK ATT: HOWARD APSAN
Contact Type:	Not reported
Contact Name:	ESTHER HUNDLEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 541-0430
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-04-29

Tank Info:

Tank Number:	001
Tank ID:	54602
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	03/10/1986
Date Tank Closed:	03/26/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
B03 - Tank External Protection - Original Impressed Current
E00 - Piping Secondary Containment - None

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

H00 - Tank Leak Detection - None
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None

Tank Number:	001A
Tank ID:	45089
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H05 - Tank Leak Detection - In-Tank System (ATG)
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
G01 - Tank Secondary Containment - Diking (Aboveground)

Tank Number:	002
Tank ID:	54601
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	03/10/1986
Date Tank Closed:	03/26/2009
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination

MEDGAR EVERS COLLEGE (CUNY) (Continued) **U001329958**

G00 - Tank Secondary Containment - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I05 - Overfill - Vent Whistle
B03 - Tank External Protection - Original Impressed Current
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
J03 - Dispenser - Gravity

S138 **CON EDISON SERVICE BOX: 22682** **RCRA NonGen / NLR** **1016967921**
NNE **960 CARROLL ST** **NY MANIFEST** **NYP004415204**
1/8-1/4 **BROOKLYN, NY 11225**
0.188 mi.
992 ft. **Site 1 of 12 in cluster S**

Relative: **Higher**
Actual: **113 ft.**

RCRA Listings:

Date Form Received by Agency:		20140209
Handler Name:	CON EDISON SERVICE BOX:	22682
Handler Address:		960 CARROLL ST
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004415204
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

CON EDISON SERVICE BOX: 22682 (Continued) **1016967921**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140109
Handler Name: CON EDISON SERVICE BOX:	22682
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 22682 (Continued) **1016967921**

Receive Date:	20140209
Handler Name: CON EDISON SERVICE BOX:	22682
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	960 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004415204
Facility Status:	Not reported
Location Address 1:	960 CARROLL ST
Code:	BP
Location Address 2:	SB23682
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004415204
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON SERVICE BOX: 22682 (Continued) **1016967921**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/09/2014
Trans1 Recv Date:	01/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/10/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004415204
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328424GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	NYCTA CHEMICAL LAB
Address:	960 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11225-1802
Country:	USA
EPA ID:	NYD980653885
Facility Status:	Not reported
Location Address 1:	960 CARROLL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 22682 (Continued) **1016967921**

Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD980653885
Mailing Name: NYCTA CHEMICAL LAB
Mailing Contact: FRANCES GAGOFALLOU
Mailing Address 1: 370 JAY ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11201
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123304904

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

S139 **NYCTA - CHEMICAL LABORATORY** **NY LTANKS** **1000299187**
NNE **960 CARROLL ST** **RCRA NonGen / NLR** **NYD980653885**
1/8-1/4 **BROOKLYN, NY 11225** **FINDS**
0.188 mi. **ECHO**
992 ft. **Site 2 of 12 in cluster S**

Relative: **Higher**
Actual: **113 ft.**

LTANKS:
Name: CHEMICAL LAB- NYCT
Address: 960 CARROLL STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9100192 / 2001-11-30
Facility ID: 9100192
Site ID: 181513
Spill Date: 1991-04-03
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1991-04-03
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1991-04-17
Spill Record Last Update: 2005-03-21
Spiller Name: Not reported
Spiller Company: NYCTA
Spiller Address: Not reported
Spiller County: 001

NYCTA - CHEMICAL LABORATORY (Continued) **1000299187**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	152215
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 11/16/94: REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 11/16/94. transfered from Hale to Tibbe on 12/27/00. tank replaced. closure investigation pending. 11/30/01 NO CONTAMINATION FOUND DURING INVESTIGATION. SEE FILE."
Remarks:	"5K TANK FAILED PETRO TITE WITH A LEAK RATE OF -.939GPH."

All TTF:

Facility ID:	9100192
Spill Number:	9100192
Spill Tank Test:	1538416
Site ID:	181513
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	181513
Operable Unit ID:	953734
Operable Unit:	01
Material ID:	426403
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	NYCTA - CHEMICAL LABORATORY
Handler Address:	960 CARROLL ST
Handler City,State,Zip:	BROOKLYN, NY 11225-1802
EPA ID:	NYD980653885
Contact Name:	Not reported
Contact Address:	CARROLL ST
Contact City,State,Zip:	BROOKLYN, NY 11225
Contact Telephone:	Not reported
Contact Fax:	Not reported

NYCTA - CHEMICAL LABORATORY (Continued) **1000299187**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	CARROLL ST
Mailing City,State,Zip:	BROOKLYN, NY 11225
Owner Name:	NEW YORK CITY TRANSIT AUTHORITY
Owner Type:	Private
Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

NYCTA - CHEMICAL LABORATORY (Continued) **1000299187**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F004
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS

NYCTA - CHEMICAL LABORATORY (Continued) **1000299187**

CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name:	NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

NYCTA - CHEMICAL LABORATORY (Continued) **1000299187**

Receive Date: 20060101
Handler Name: NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19821215
Handler Name: NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920316
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940330
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No

NYCTA - CHEMICAL LABORATORY (Continued) **1000299187**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960320
Handler Name: NYCT/CHEMICAL LABORATORY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 485999
NAICS Description: ALL OTHER TRANSIT AND GROUND PASSENGER TRANSPORTATION

NAICS Code: 561599
NAICS Description: ALL OTHER TRAVEL ARRANGEMENT AND RESERVATION SERVICES

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19891212
Actual Return to Compliance Date: 19900405
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19900409
Enforcement Identifier: 001
Date of Enforcement Action: 19900108
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported

NYCTA - CHEMICAL LABORATORY (Continued) **1000299187**

SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19891212
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19900405
Scheduled Compliance Date:	19900409
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110000808886

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000299187
Registry ID:	110000808886
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000808886
Name:	NYCTA - CHEMICAL LABORATORY
Address:	960 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11225

S140 **TRANSIT DISTRICT 32** **NY AST** **A100293535**
NNE **960 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.188 mi.
992 ft. **Site 3 of 12 in cluster S**

Relative:
Higher

Actual:
113 ft.

AST:

Name:	TRANSIT DISTRICT 32
Address:	960 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-190365
Program Type:	PBS
UTM X:	587947.70690
UTM Y:	4502426.52341
Expiration Date:	06/05/2027
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	5871
Affiliation Type:	Facility Operator
Company Name:	CHEMICAL LABORATORY
Contact Type:	Not reported
Contact Name:	NYC TRANSIT AUTHORITY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 243-4581
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5871
Affiliation Type:	Emergency Contact
Company Name:	NYC POLICE DEPARTMENT
Contact Type:	Not reported
Contact Name:	JOSEPHINE BROWN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 243-3481
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-07-29

Site Id:	5871
Affiliation Type:	Mail Contact
Company Name:	BUILDING MAINTENANCE SECTION
Contact Type:	Not reported
Contact Name:	COMMANDING OFFICER

TRANSIT DISTRICT 32 (Continued) **A100293535**

Address1:	59-06 BROOKLYN QUEENS EXPRESSWAY
Address2:	Not reported
City:	WOODSIDE
State:	NY
Zip Code:	11377
Country Code:	001
Phone:	(718) 476-7576
EMail:	FLOYD.MITCHELL@NYPD.ORG
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-23

Site Id:	5871
Affiliation Type:	Facility Owner
Company Name:	NYC POLICE DEPARTMENT
Contact Type:	SUPERVISOR
Contact Name:	FLOYD MITCHELL
Address1:	ONE POLICE PLAZA, ROOM 800
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 374-7650
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-02-16

Tank Info:

Tank Number:	0002
Tank Id:	67421
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I03 - Overfill - Automatic Shut-Off
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	C01 - Pipe Location - Aboveground
	L00 - Piping Leak Detection - None
	F06 - Pipe External Protection - Wrapped
	G04 - Tank Secondary Containment - Double-Walled (Underground)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/01/2002
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported

TRANSIT DISTRICT 32 (Continued) **A100293535**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

S141 **TRANSIT DISTRICT 32** **NY UST** **U004062278**
NNE **960 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.188 mi.
992 ft. **Site 4 of 12 in cluster S**

Relative:
Higher

Actual:
113 ft.

UST:

Name:	TRANSIT DISTRICT 32
Address:	960 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-190365 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/05/2027
UTM X:	587947.70690
UTM Y:	4502426.52341
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	5871
Affiliation Type:	Facility Operator
Company Name:	CHEMICAL LABORATORY
Contact Type:	Not reported
Contact Name:	NYC TRANSIT AUTHORITY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 243-4581
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5871
Affiliation Type:	Emergency Contact
Company Name:	NYC POLICE DEPARTMENT
Contact Type:	Not reported
Contact Name:	JOSEPHINE BROWN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 243-3481
EMail:	Not reported
Fax Number:	Not reported

TRANSIT DISTRICT 32 (Continued) **U004062278**

Modified By:	ACDANIEL
Date Last Modified:	2021-07-29
Site Id:	5871
Affiliation Type:	Mail Contact
Company Name:	BUILDING MAINTENANCE SECTION
Contact Type:	Not reported
Contact Name:	COMMANDING OFFICER
Address1:	59-06 BROOKLYN QUEENS EXPRESSWAY
Address2:	Not reported
City:	WOODSIDE
State:	NY
Zip Code:	11377
Country Code:	001
Phone:	(718) 476-7576
EMail:	FLOYD.MITCHELL@NYPD.ORG
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-23
Site Id:	5871
Affiliation Type:	Facility Owner
Company Name:	NYC POLICE DEPARTMENT
Contact Type:	SUPERVISOR
Contact Name:	FLOYD MITCHELL
Address1:	ONE POLICE PLAZA, ROOM 800
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 374-7650
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-02-16

Tank Info:

Tank Number:	0001
Tank ID:	58476
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	6000
Install Date:	12/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI

TRANSIT DISTRICT 32 (Continued) **U004062278**

Last Modified: 05/09/2022

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 001
Tank ID: 6807
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

T142 **25 LEFFERTS, LLC** **NY AST** **A100445482**
South **25 LEFFERTS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.189 mi.
998 ft. **Site 1 of 7 in cluster T**

Relative:
Lower

Actual:
74 ft.

AST:

Name:	25 LEFFERTS, LLC
Address:	25 LEFFERTS AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-065021
Program Type:	PBS
UTM X:	587875.48639
UTM Y:	4501754.55842
Expiration Date:	01/14/2027
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	1397
Affiliation Type:	Facility Operator
Company Name:	25 LEFFERTS, LLC
Contact Type:	Not reported
Contact Name:	DOMINIC LABORDE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 658-1300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-12-21

Site Id:	1397
Affiliation Type:	Emergency Contact
Company Name:	25 LEFFERTS, LLC
Contact Type:	Not reported
Contact Name:	NEAL ALIMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 658-1300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-03-20

Site Id:	1397
Affiliation Type:	Facility Owner
Company Name:	25 LEFFERTS, LLC
Contact Type:	AGENT
Contact Name:	NEAL ALIMAN

25 LEFFERTS, LLC (Continued) **A100445482**

Address1:	141-50 85TH ROAD
Address2:	Not reported
City:	BRIARWOOD
State:	NY
Zip Code:	11435
Country Code:	001
Phone:	(718) 658-1300
EMail:	NEALA@METROPROP.NET
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-12-21

Site Id:	1397
Affiliation Type:	Mail Contact
Company Name:	25 LEFFERTS, LLC
Contact Type:	AGENT
Contact Name:	NEAL ALIMAN
Address1:	141-50 85TH ROAD
Address2:	Not reported
City:	BRIARWOOD
State:	NY
Zip Code:	11435
Country Code:	001
Phone:	(718) 658-1300
EMail:	NEALA@METROPROP.NET
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-12-21

Tank Info:

Tank Number:	001
Tank Id:	2747
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
J05 - Dispenser - On Site Heating System (Supply/Return)
G00 - Tank Secondary Containment - None

Tank Location:	Partially buried tank (tank with 10% or more below ground).... Tank is less than 90% above grade, partially buried.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/31/1925
Capacity Gallons:	5000

25 LEFFERTS, LLC (Continued) **A100445482**

Tightness Test Method:	34
Date Test:	08/17/2022
Next Test Date:	08/17/2023
Date Tank Closed:	Not reported
Register:	True
Modified By:	KRRAMIRE
Last Modified:	09/02/2022
Material Name:	#2 fuel oil (on-site consumption)

P143 **EBBETTS FIELD EXXON 31910** **RCRA-VSQG 1004758846**
ESE **155 EMPIRE BLVD** **ICIS NYD987026903**
1/8-1/4 **BROOKLYN, NY 11225** **US AIRS**
0.190 mi. **NY MANIFEST**
1001 ft. **Site 11 of 12 in cluster P**

Relative: **Lower**
Actual: **69 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	EXXON DIV OF CFI #70217	
Handler Address:		155 EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYD987026903
Contact Name:		MAUREEN JERNSTEDT
Contact Address:		DEDHAM ST
Contact City,State,Zip:		CANTON, MA 02021
Contact Telephone:		800-225-9702 3378
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		DEDHAM ST
Mailing City,State,Zip:		CANTON, MA 02021
Owner Name:	CUMBERLAND FARMS	
Owner Type:		Private
Operator Name:	NO NAME FOUND	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

EBBETTS FIELD EXXON 31910 (Continued) **1004758846**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D018
Waste Description: BENZENE

EBBETTS FIELD EXXON 31910 (Continued) **1004758846**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: SECKIN MGMT INC.	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CUMBERLAND FARMS INC	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TOSCO	
Legal Status:	Private
Date Became Current:	20000301
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085
Owner/Operator Telephone:	602-728-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CUMBERLAND FARMS	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	777 DEDHAM ST
Owner/Operator City,State,Zip:	CANTON, MA 02021
Owner/Operator Telephone:	Not reported

EBBETTS FIELD EXXON 31910 (Continued) **1004758846**

Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CUMBERLAND FARMS INC	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CUMBERLAND FARMS	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	777 DEDHAM ST
Owner/Operator City,State,Zip:	CANTON, MA 02021
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: TOSCO	
Legal Status:	Private
Date Became Current:	20000301
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085
Owner/Operator Telephone:	602-728-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: EXXON DIV OF CFI #70217	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY

EBBETTS FIELD EXXON 31910 (Continued) **1004758846**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: EXXON DIV OF CFI #70217	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19930201
Handler Name: TOSCO #34645	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010808
Handler Name: TOSCO #34645	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20041001
Handler Name: EXXON DIV OF CFI #70217	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

EBBETTS FIELD EXXON 31910 (Continued) **1004758846**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20040810
Handler Name: EXXON #70217	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	44711
NAICS Description:	GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

ICIS:

Enforcement Action ID:	NY000A0000261040021600008
FRS ID:	110004500255
Action Name:	EBBETTS FIELD EXXON 31910 360470089500008
Facility Name:	EBBETTS FIELD EXXON 31910
Facility Address:	155 EMPIRE BLVD BROOKLYN, NY 11225
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	5541
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.663547
Longitude in Decimal Degrees:	-73.956985
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400216
Facility NAICS Code:	999999
Tribal Land Code:	Not reported

US AIRS (AFS):

Region Code:	02
County Code:	NY047
Programmatic ID:	AIR NY0000002610400216
Facility Registry ID:	110004500255

EBBETTS FIELD EXXON 31910 (Continued) **1004758846**

D and B Number: Not reported
Facility Site Name: EBBETTS FIELD EXXON 31910
Primary SIC Code: 5541
NAICS Code: 999999
Default Air Classification Code: SMI
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002610400216
Facility Registry ID: 110004500255
Air Operating Status Code: OPR
Default Air Classification Code: SMI

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-07-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1996-11-27 00:00:00
Activity Status Date: 1996-11-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Air Program: Federally-Enforceable State Operating Permit - Non Title V
Activity Date: 1995-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1995-05-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1994-11-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-04-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

EBBETTS FIELD EXXON 31910 (Continued) **1004758846**

NY MANIFEST:

Name:	EXXON CO USA 31910
Address:	155 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYD987026903
Facility Status:	Not reported
Location Address 1:	155 EMPIRE BOULEVARD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987026903
Mailing Name:	EXXON CO USA 31910
Mailing Contact:	ALDA S POOL
Mailing Address 1:	PO BOX 4415
Mailing Address 2:	Not reported
Mailing City:	HOUSTON
Mailing State:	TX
Mailing Zip:	77210
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7136567709

P144 **EBBET'S FIELD (CLOSED) #1910** **NY UST** **U000400374**
ESE **155 EMPIRE BLVD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.190 mi.
1001 ft. **Site 12 of 12 in cluster P**

Relative:
Lower

Actual:
69 ft.

UST:

Name:	CUMBERLAND FARMS #70217
Address:	155 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-601523 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588173.91444
UTM Y:	4501955.24632
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	23485
Affiliation Type:	Facility Operator
Company Name:	CUMBERLAND FARMS #70217
Contact Type:	Not reported
Contact Name:	JESSICA PFEIFER
Address1:	Not reported
Address2:	Not reported
City:	Not reported

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-07-09

Site Id:	23485
Affiliation Type:	Emergency Contact
Company Name:	155 EMPIRE HOLDINGS LLC % LSC DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	STEVE OSBORNE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(847) 409-7939
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-07-09

Site Id:	23485
Affiliation Type:	Facility Owner
Company Name:	155 EMPIRE HOLDINGS LLC % LSC DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	777 LAKE ZURICH RD
Address2:	Not reported
City:	BURLINGTON
State:	IL
Zip Code:	60010
Country Code:	001
Phone:	(847) 382-0578
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-07-09

Site Id:	23485
Affiliation Type:	Mail Contact
Company Name:	CUMBERLAND FARMS INC
Contact Type:	Not reported
Contact Name:	ANGELA PIMENTAL
Address1:	100 CROSSING BOULEVARD
Address2:	Not reported
City:	FRAMINGHAM
State:	MA
Zip Code:	01702
Country Code:	001
Phone:	(800) 225-9702
EMail:	AIMENTAL@CUMBERLANDGULF.COM
Fax Number:	Not reported

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Modified By: NRLOMBAR
Date Last Modified: 2015-07-09

Tank Info:

Tank Number: 001
Tank ID: 40518
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 001
Tank ID: 45891
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	001
Tank ID:	46640
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	ZZ
Date Test:	02/01/1993
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	002
Tank ID:	40519
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 45892
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number:	002
Tank ID:	46641
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	ZZ
Date Test:	02/01/1993
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	003
Tank ID:	46642
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	ZZ
Date Test:	02/01/1993
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	003
Tank ID:	45893
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	003
Tank ID:	40520
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 45894
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number: 004
Tank ID: 46643
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 01/10/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 004
Tank ID: 40521
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 40522
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 45895
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 005
Tank ID: 46644
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 01/10/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 006
Tank ID: 252862

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/23/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	006
Tank ID:	40523
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number:	007
Tank ID:	252863
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/24/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	007
Tank ID:	40524
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	008
Tank ID:	252864
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/27/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number:	008
Tank ID:	40525
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	009
Tank ID:	40526
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 009
Tank ID: 252865
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/27/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 010
Tank ID: 40527
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 010
Tank ID: 252866

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/27/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	011
Tank ID:	252867
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/12/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	011
Tank ID:	40528
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	012
Tank ID:	252868
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/19/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	012
Tank ID:	40529
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number: 013
Tank ID: 40530
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 014
Tank ID: 40531
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	13
Tank ID:	255987
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	04/24/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	14
Tank ID:	255988
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	600
Install Date:	Not reported
Date Tank Closed:	04/24/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number: 15
Tank ID: 255989
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 600
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 16
Tank ID: 255990
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 600
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 17
Tank ID: 255991
Tank Status: Closed - Removed
Material Name: Closed - Removed

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	04/24/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None

Affiliation Records:

Site Id:	11296
Affiliation Type:	Facility Operator
Company Name:	EBBETS FIELD (CLOSED) #1910
Contact Type:	Not reported
Contact Name:	EBBETS FIELD (CLOSED)
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 462-0109
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	11296
Affiliation Type:	Facility Owner
Company Name:	EXXON COMPANY U.S.A.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4550 DACOMA ST
Address2:	Not reported
City:	HOUSTON
State:	TX
Zip Code:	77092
Country Code:	001
Phone:	(800) 992-3647
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2004-12-15

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Site Id:	11296
Affiliation Type:	Mail Contact
Company Name:	EXXON COMPANY U.S.A.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4550 DACOMA ST
Address2:	Not reported
City:	HOUSTON
State:	TX
Zip Code:	77092
Country Code:	001
Phone:	(800) 992-3647
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2004-12-15

Site Id:	11296
Affiliation Type:	Emergency Contact
Company Name:	EXXON COMPANY, USA
Contact Type:	Not reported
Contact Name:	EXXON COMPANY U.S.A.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(800) 992-3647
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	40518
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	001
Tank ID:	45891
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	001
Tank ID:	46640
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 002
Tank ID: 40519
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 45892

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	002
Tank ID:	46641
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	ZZ
Date Test:	02/01/1993
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	003
Tank ID:	46642
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	ZZ
Date Test:	02/01/1993
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	003
Tank ID:	45893
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 003
Tank ID: 40520
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 45894

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	004
Tank ID:	46643
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	ZZ
Date Test:	02/01/1993
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 004
Tank ID: 40521
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 40522
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 45895
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 005
Tank ID: 46644
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 01/10/2014

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 006
Tank ID: 252862
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/23/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 006
Tank ID: 40523
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 007
Tank ID: 252863
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/24/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 007
Tank ID: 40524
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 252864
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/27/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 008
Tank ID: 40525
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	009
Tank ID:	40526
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number:	009
Tank ID:	252865
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/27/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Tank Number:	010
Tank ID:	40527

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	010
Tank ID:	252866
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/27/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	011
Tank ID:	252867
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/12/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 011
Tank ID: 40528
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 252868
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/19/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number:	012
Tank ID:	40529
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number:	013
Tank ID:	40530
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 014
Tank ID: 40531
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 13
Tank ID: 255987
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 14
Tank ID: 255988
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 600
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 15
Tank ID: 255989
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 600
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

G00 - Tank Secondary Containment - None

Tank Number: 16
Tank ID: 255990
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 600
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 17
Tank ID: 255991
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None

Affiliation Records:
Site Id: 23362

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Affiliation Type:	Facility Owner
Company Name:	EXXON CO, USA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4550 DACOMA ST.
Address2:	Not reported
City:	HOUSTON
State:	TX
Zip Code:	77092
Country Code:	001
Phone:	(800) 992-3647
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23362
Affiliation Type:	Mail Contact
Company Name:	EXXON CO, USA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4550 DACOMA ST.
Address2:	Not reported
City:	HOUSTON
State:	TX
Zip Code:	77092
Country Code:	001
Phone:	(800) 992-3647
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23362
Affiliation Type:	Facility Operator
Company Name:	EBBETTS FIELD EXXON #31910
Contact Type:	Not reported
Contact Name:	WINSLOW JOHNSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 693-8085
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23362
Affiliation Type:	Emergency Contact
Company Name:	EXXON CO, USA
Contact Type:	Not reported
Contact Name:	WINSLOW JOHNSON
Address1:	Not reported
Address2:	Not reported

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 693-8085
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	40518
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	001
Tank ID:	45891
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 001
Tank ID: 46640
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 01/10/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L09 - Piping Leak Detection - Exempt Suction Piping
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number:	002
Tank ID:	40519
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	45892
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 002
Tank ID: 46641
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 01/10/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 003
Tank ID: 46642
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 01/10/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 003
Tank ID: 45893
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: 02/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Number:	003
Tank ID:	40520
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	45894
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1992
Date Tank Closed:	02/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
I01 - Overfill - Float Vent Valve

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	004
Tank ID:	46643
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1992
Date Tank Closed:	01/10/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	ZZ
Date Test:	02/01/1993
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	004
Tank ID:	40521
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 40522
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 45895
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1992
Date Tank Closed: 02/01/1995

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 005
Tank ID: 46644
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1992
Date Tank Closed: 01/10/2014
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: ZZ
Date Test: 02/01/1993
Next Test Date: Not reported
Pipe Model: D
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	006
Tank ID:	252862
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/23/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	006
Tank ID:	40523
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number:	007
Tank ID:	252863

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/24/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	007
Tank ID:	40524
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	008
Tank ID:	252864
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/27/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 008
Tank ID: 40525
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 009
Tank ID: 40526
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 009
Tank ID: 252865
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/27/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 010
Tank ID: 40527
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	010
Tank ID:	252866
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	01/27/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	011
Tank ID:	252867
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/12/2014
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	011
Tank ID:	40528
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1961
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	NN
Date Test:	Not reported

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 252868
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 02/19/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 012
Tank ID: 40529
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 013
Tank ID: 40530
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 014
Tank ID: 40531
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1961
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 13
Tank ID: 255987
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 14
Tank ID: 255988
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 600
Install Date: Not reported
Date Tank Closed: 04/24/2015
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	15
Tank ID:	255989
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	600
Install Date:	Not reported
Date Tank Closed:	04/24/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	16
Tank ID:	255990
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	600
Install Date:	Not reported
Date Tank Closed:	04/24/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

EBBET'S FIELD (CLOSED) #1910 (Continued) **U000400374**

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	17
Tank ID:	255991
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	04/24/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C00 - Pipe Location - No Piping
B00 - Tank External Protection - None
G00 - Tank Secondary Containment - None

U145 **934 CARROLL STREET** **NY AST** **A100292881**
North **934 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.194 mi.
1022 ft. **Site 1 of 7 in cluster U**

Relative:
Higher

Actual:
121 ft.

AST:

Name:	934 CARROLL STREET
Address:	934 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608595
Program Type:	PBS
UTM X:	587873.23157
UTM Y:	4502446.17515
Expiration Date:	03/14/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30447
Affiliation Type:	Facility Owner
Company Name:	934 CARROLL LLC
Contact Type:	MEMBER
Contact Name:	GETZ OBSTFEID
Address1:	48 LIBERTY AVE

934 CARROLL STREET (Continued) **A100292881**

Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10805
Country Code:	001
Phone:	(914) 235-7865
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-18

Site Id:	30447
Affiliation Type:	Mail Contact
Company Name:	934 CARROLL LLC
Contact Type:	Not reported
Contact Name:	GETZ OBSTFEID
Address1:	48 LIBERTY AVENUE
Address2:	Not reported
City:	NEW ROCHELLE
State:	NY
Zip Code:	10805
Country Code:	001
Phone:	(914) 235-7865
EMail:	GETZ.CDI@VERIZON.NET
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-18

Site Id:	30447
Affiliation Type:	Facility Operator
Company Name:	934 CARROLL STREET
Contact Type:	Not reported
Contact Name:	AL SEAGERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 287-7536
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30447
Affiliation Type:	Emergency Contact
Company Name:	934 CARROLL LLC
Contact Type:	Not reported
Contact Name:	AL SEAGERS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 319-7285

934 CARROLL STREET (Continued) **A100292881**

EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2018-01-18

Tank Info:

Tank Number: 01
Tank Id: 65362
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1980
Capacity Gallons: 4000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

U146 **932 CARROLL STREET** **NY AST** **A100300588**
North **932 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.194 mi.
1024 ft. **Site 2 of 7 in cluster U**

Relative:
Higher

Actual:
122 ft.

AST:
Name: 932 CARROLL STREET
Address: 932 CARROLL STREET
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-054720
Program Type: PBS
UTM X: 587843.72943

932 CARROLL STREET (Continued) **A100300588**

UTM Y: 4502453.48284
Expiration Date: 06/26/2023
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 773
Affiliation Type: Facility Operator
Company Name: 932 CARROLL STREET
Contact Type: Not reported
Contact Name: OMAR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 261-0752
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2013-07-29

Site Id: 773
Affiliation Type: Emergency Contact
Company Name: 932 CARROLL LLC
Contact Type: Not reported
Contact Name: MARC BARHORIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 210-7142
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2013-07-29

Site Id: 773
Affiliation Type: Mail Contact
Company Name: 932 CARROLL LLC
Contact Type: MEMBER
Contact Name: MEIR BOUSKILA
Address1: PO BOX 1920
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10116-1920
Country Code: 001
Phone: (212) 564-2111
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2013-07-29

Site Id: 773
Affiliation Type: Facility Owner

932 CARROLL STREET (Continued) **A100300588**

Company Name:	932 CARROLL LLC
Contact Type:	AGENT
Contact Name:	ISAK RADONCIC
Address1:	PO BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116-1920
Country Code:	001
Phone:	(212) 564-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-08

Tank Info:

Tank Number:	001
Tank Id:	1694
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/30/2005
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	226316
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

932 CARROLL STREET (Continued) **A100300588**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/2005
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

V147 **MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1** **NY AST** **A100407906**
ENE **1638 BEDFORD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.195 mi.
1029 ft. **Site 1 of 11 in cluster V**

Relative:
Higher

Actual:
103 ft.

AST:

Name:	MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1
Address:	1638 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611359
Program Type:	PBS
UTM X:	588185.83869
UTM Y:	4502293.87460
Expiration Date:	03/30/2024
Site Type:	School

Affiliation Records:

Site Id:	435410
Affiliation Type:	Facility Operator
Company Name:	MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1
Contact Type:	Not reported
Contact Name:	MEDGAR EVERS - CAMPUS FACILITIES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1 (Continued) **A100407906**

Country Code:	001
Phone:	(718) 270-4842
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2015-03-25

Site Id:	435410
Affiliation Type:	Facility Owner
Company Name:	CITY UNIVERSITY OF NEW YORK
Contact Type:	ASST. VP, FACILITIES MGT
Contact Name:	THOMAS CHING
Address1:	205 EAST 42ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(646) 361-5481
EMail:	TCHING@MEC.CUNY.EDU
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2022-03-16

Site Id:	435410
Affiliation Type:	Mail Contact
Company Name:	MEDGAR EVERS COLLEGE
Contact Type:	ASST. VP, FACILITIES MGT
Contact Name:	THOMAS CHING
Address1:	1638 BEDFORD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 270-6238
EMail:	TCHING@MEC.CUNY.EDU
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-02-28

Site Id:	435410
Affiliation Type:	Emergency Contact
Company Name:	CITY UNIVERSITY OF NEW YORK
Contact Type:	Not reported
Contact Name:	THOMAS CHING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 361-5481
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-02-28

MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1 (Continued) **A100407906**

Tank Info:

Tank Number:	002
Tank Id:	255016

Equipment Records:

J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/31/2010
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

V148 **MEDGAR EVERS COLLEGE - CUNY** **RCRA-SQG** **1014399672**
ENE **1638 BEDFORD AVE** **NY MANIFEST** **NYR000177618**
1/8-1/4 **BROOKLYN, NY 11225**
0.195 mi.
1029 ft. **Site 2 of 11 in cluster V**

Relative: **Higher**
Actual: **103 ft.**

RCRA Listings:

Date Form Received by Agency:	20100901
Handler Name:	MEDGAR EVERS COLLEGE - CUNY
Handler Address:	1638 BEDFORD AVE
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYR000177618
Contact Name:	MOHAMED A BANGURA
Contact Address:	CARROLL ST ROOM C-224
Contact City,State,Zip:	BROOKLYN, NY 11225
Contact Telephone:	718-270-6216
Contact Fax:	917-270-6197
Contact Email:	MBANGURA@MEC.CUNY.EDU
Contact Title:	ENVIRONMENTAL HEALTH AND SAFETY OFFICER
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Small Quantity Generator

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		CARROLL ST ROOM C-224
Mailing City,State,Zip:		BROOKLYN, NY 11225
Owner Name:	CITY UNIVERSITY OF NEW YORK	
Owner Type:		State
Operator Name:	MEDGAR EVERS COLLEGE	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20150414
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D003
Waste Description: REACTIVE WASTE

Waste Code: D004
Waste Description: ARSENIC

Waste Code: D005
Waste Description: BARIUM

Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D018
Waste Description: BENZENE

Waste Code: D019
Waste Description: CARBON TETRACHLORIDE

Waste Code: D021
Waste Description: CHLOROBENZENE

Waste Code: D022
Waste Description: CHLOROFORM

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Waste Code: D023
Waste Description: O-CRESOL

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: D025
Waste Description: P-CRESOL

Waste Code: D026
Waste Description: CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D028
Waste Description: 1,2-DICHLOROETHANE

Waste Code: D029
Waste Description: 1,1-DICHLOROETHYLENE

Waste Code: D030
Waste Description: 2,4-DINITROTOLUENE

Waste Code: D034
Waste Description: HEXACHLOROETHANE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D036
Waste Description: NITROBENZENE

Waste Code: D038
Waste Description: PYRIDINE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F004
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: P005
Waste Description: 2-PROPEN-1-OL (OR) ALLYL ALCOHOL

Waste Code: P023
Waste Description: ACETALDEHYDE, CHLORO- (OR) CHLOROACETALDEHYDE

Waste Code: P024
Waste Description: BENZENAMINE, 4-CHLORO- (OR) P-CHLORANILINE

Waste Code: P077
Waste Description: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

Waste Code: U001
Waste Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U003
Waste Description: ACETONITRILE (I,T)

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Waste Code: U004
Waste Description: ACETOPHENONE (OR) ETHANONE, 1-PHENYL-

Waste Code: U012
Waste Description: ANILINE (I,T) (OR) BENZENAMINE (I,T)

Waste Code: U015
Waste Description: AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)

Waste Code: U019
Waste Description: BENZENE (I,T)

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U037
Waste Description: BENZENE, CHLORO- (OR) CHLOROBENZENE

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U056
Waste Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Waste Code: U057
Waste Description: CYCLOHEXANONE (I)

Waste Code: U076
Waste Description: ETHANE, 1,1-DICHLORO- (OR) ETHYLIDENE DICHLORIDE

Waste Code: U080
Waste Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Waste Code: U092
Waste Description: DIMETHYLAMINE (I) (OR) METHANAMINE, N-METHYL- (I)

Waste Code: U108
Waste Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Waste Code: U112
Waste Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U115
Waste Description: ETHYLENE OXIDE (I,T) (OR) OXIRANE (I,T)

Waste Code: U117
Waste Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Waste Code: U119
Waste Description: ETHYL METHANESULFONATE (OR) METHANESULFONIC ACID, ETHYL ESTER

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U123
Waste Description: FORMIC ACID (C,T)

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Waste Code: U138
Waste Description: METHANE, IODO- (OR) METHYL IODIDE

Waste Code: U140
Waste Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Waste Code: U144
Waste Description: ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE

Waste Code: U147
Waste Description: 2,5-FURANDIONE (OR) MALEIC ANHYDRIDE

Waste Code: U151
Waste Description: MERCURY

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U159
Waste Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U161
Waste Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U169
Waste Description: BENZENE, NITRO- (OR) NITROBENZENE (I,T)

Waste Code: U188
Waste Description: PHENOL

Waste Code: U196
Waste Description: PYRIDINE

Waste Code: U211
Waste Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Waste Code: U213
Waste Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U225
Waste Description: BROMOFORM (OR) METHANE, TRIBROMO-

Waste Code: U228
Waste Description: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Waste Code: U239
Waste Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Waste Code: U404
Waste Description: U404

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CITY UNIVERSITY OF NEW YORK
Legal Status: State
Date Became Current: 20100823
Date Ended Current: Not reported
Owner/Operator Address: 535 E 80TH ST
Owner/Operator City,State,Zip: NEW YORK, NY 10075
Owner/Operator Telephone: 212-794-5735
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MEDGAR EVERS COLLEGE
Legal Status: State
Date Became Current: 20100823
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100901
Handler Name: MEDGAR EVERS COLLEGE - CUNY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61131
NAICS Description: COLLEGES, UNIVERSITIES, AND PROFESSIONAL SCHOOLS

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20170928
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170928
Enforcement Responsible Agency: EPA

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: R2STP
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20170928
Actual Return to Compliance Date: 20170928
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170928
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: R2STP
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20170928
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20170928
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20170928
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	MEDGAR EVERS COLLEGE - CUNY
Address:	1638 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYR000177618
Facility Status:	Not reported
Location Address 1:	1638 BEDFORD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000177618
Mailing Name:	MEDGAR EVERS COLLEGE - CUNY
Mailing Contact:	MOHAMED BANGURA
Mailing Address 1:	1150 CARROLL STREET

MEDGAR EVERS COLLEGE - CUNY (Continued) **1014399672**

Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182706455

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	12/22/2011
Trans1 Recv Date:	12/22/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/28/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177618
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	004160360FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D008
Waste Code 1_3:	D002
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V149 **MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1** **NY UST** **U004154645**
ENE **1638 BEDFORD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.195 mi.
1029 ft. **Site 3 of 11 in cluster V**

Relative:
Higher

Actual:
103 ft.

UST:

Name:	MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1
Address:	1638 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-611359 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/30/2024
UTM X:	588185.83869
UTM Y:	4502293.87460
Site Type:	School

Affiliation Records:

Site Id:	435410
Affiliation Type:	Facility Operator
Company Name:	MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1
Contact Type:	Not reported
Contact Name:	MEDGAR EVERS - CAMPUS FACILITIES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 270-4842
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2015-03-25

Site Id:	435410
Affiliation Type:	Facility Owner
Company Name:	CITY UNIVERSITY OF NEW YORK
Contact Type:	ASST. VP, FACILITIES MGT
Contact Name:	THOMAS CHING
Address1:	205 EAST 42ND STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(646) 361-5481
EMail:	TCHING@MEC.CUNY.EDU
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2022-03-16

Site Id:	435410
Affiliation Type:	Mail Contact
Company Name:	MEDGAR EVERS COLLEGE
Contact Type:	ASST. VP, FACILITIES MGT
Contact Name:	THOMAS CHING
Address1:	1638 BEDFORD AVENUE

MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1 (Continued) **U004154645**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 270-6238
EMail:	TCHING@MEC.CUNY.EDU
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-02-28

Site Id:	435410
Affiliation Type:	Emergency Contact
Company Name:	CITY UNIVERSITY OF NEW YORK
Contact Type:	Not reported
Contact Name:	THOMAS CHING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 361-5481
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-02-28

Tank Info:

Tank Number:	001
Tank ID:	234615
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	25000
Install Date:	03/20/2009
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L02 - Piping Leak Detection - Interstitial - Manual Monitoring
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
E04 - Piping Secondary Containment - Double walled UG

MEDGAR EVERS COLLEGE - ACADEMIC BUILDING 1 (Continued) **U004154645**

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)

Q150 **CON EDISON** **NY MANIFEST** **S117062050**
ENE **1653 BEDFORD AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.196 mi.
1035 ft. **Site 6 of 10 in cluster Q**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	1653 BEDFORD AV
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004658175
Facility Status:	Not reported
Location Address 1:	1653 BEDFORD AV
Code:	BP
Location Address 2:	SB23835
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004658175
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2014
Trans1 Recv Date:	09/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004658175
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117062050**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617282GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	1653 BEDFORD AV
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004632493
Facility Status:	Not reported
Location Address 1:	1653 BEDFORD AV
Code:	BP
Location Address 2:	SB23838
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004632493
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117062050**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/2014
Trans1 Recv Date:	08/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004632493
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616326GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q151
ENE
1/8-1/4
0.196 mi.
1035 ft.

CON EDISON SERVICE BOX: 23835
1653 BEDFORD AVE
BROOKLYN, NY 11210

Site 7 of 10 in cluster Q

RCRA NonGen / NLR

1017776518
NYP004543781

Relative:
Higher

Actual:
99 ft.

RCRA Listings:

Date Form Received by Agency:		20140627
Handler Name:	CON EDISON SERVICE BOX:	23835
Handler Address:		1653 BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11210
EPA ID:		NYP004543781
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 23835 (Continued) **1017776518**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140527
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140527
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 23835 (Continued) **1017776518**

Electronic Manifest Broker: Not reported

Receive Date: 20140627
Handler Name: CON EDISON SERVICE BOX: 23835
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

S152 **CON EDISON SERVICE BOX: 26235** **RCRA NonGen / NLR** **1016970215**
NNE **FRANKLIN AVE & CARROLL ST** **NY MANIFEST** **NYP004439162**
1/8-1/4 **BROOKLYN, NY 11225**
0.196 mi.
1037 ft. **Site 5 of 12 in cluster S**

Relative: **Higher**
Actual: **115 ft.**

RCRA Listings:
Date Form Received by Agency: 20140310
Handler Name: CON EDISON SERVICE BOX: 26235
Handler Address: FRANKLIN AVE & CARROLL ST
Handler City,State,Zip: BROOKLYN, NY 11225
EPA ID: NYP004439162
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: IRVING PL, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported

CON EDISON SERVICE BOX: 26235 (Continued) **1016970215**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 26235 (Continued) **1016970215**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20140210
Handler Name: CON EDISON SERVICE BOX:	26235
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140310
Handler Name: CON EDISON SERVICE BOX:	26235
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	FRANKLIN AVE & CARROLL ST
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004439162
Facility Status:	Not reported
Location Address 1:	F/O 907 FRANKLIN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

CON EDISON SERVICE BOX: 26235 (Continued) **1016970215**

NY MANIFEST:

EPAID:	NYP004439162
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/10/2014
Trans1 Recv Date:	02/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004439162
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697970JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON SERVICE BOX: 26235 (Continued) **1016970215**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Q153 **250 REALTY ASSOCIATES INC.** **NY AST** **U003200534**
East **250 MONTGOMERY STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.197 mi.
1041 ft. **Site 8 of 10 in cluster Q**

Relative:
Higher

Actual:
92 ft.

AST:
Name: 250 REALTY ASSOCIATES INC.
Address: 250 MONTGOMERY STREET
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-259454
Program Type: PBS
UTM X: 588228.63939
UTM Y: 4502158.46108
Expiration Date: 08/17/2027
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 10786
Affiliation Type: Mail Contact
Company Name: 250 REALTY ASSOCIATES, INC.
Contact Type: Not reported
Contact Name: YITZCHAK SHWARTZ
Address1: P.O. BOX 190772
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11219
Country Code: 001
Phone: (718) 972-9188
EMail: YLSCHWARTZ2@GMAIL.COM
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-10-16

Site Id: 10786
Affiliation Type: Facility Operator
Company Name: 250 REALTY ASSOCIATES INC.
Contact Type: Not reported
Contact Name: NAZMI HASANI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 610-2737
EMail: Not reported

250 REALTY ASSOCIATES INC. (Continued) **U003200534**

Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-16

Site Id:	10786
Affiliation Type:	Emergency Contact
Company Name:	250 REALTY ASSOCIATES INC.
Contact Type:	Not reported
Contact Name:	YITZCHAK SHWARTZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 972-9188
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-16

Site Id:	10786
Affiliation Type:	Facility Owner
Company Name:	250 REALTY ASSOCIATES INC.
Contact Type:	OFFICER
Contact Name:	YITZCHAR SHWARTZ
Address1:	P.O. BOX 190772
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 972-9188
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-07-25

Tank Info:

Tank Number:	001
Tank Id:	18115
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

250 REALTY ASSOCIATES INC. (Continued) **U003200534**

	K00 - Spill Prevention - None
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/27/1941
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

W154 **CON EDISON SB73433** **RCRA NonGen / NLR** **1016966679**
SSW **15 OCEAN AVE** **NY MANIFEST** **NYP004395257**
1/8-1/4 **BROOKLYN, NY 11225**
0.199 mi.
1052 ft. **Site 1 of 9 in cluster W**

Relative: **Lower**

Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:		20220125
Handler Name:	CON EDISON SB73433	
Handler Address:		15 OCEAN AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004395257
Contact Name:		THOMAS TEELING
Contact Address:		IRVING PL, 15TH FL NE
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

CON EDISON SB73433 (Continued) **1016966679**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20220125
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20220125
Handler Name: CON EDISON SB73433	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON SB73433 (Continued) **1016966679**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20131120
Handler Name: CON EDISON SB 73433
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20170705
Handler Name: CON EDISON SB 73433
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20131220
Handler Name: CON EDISON SERVICE BOX: 73433
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CON EDISON SB73433 (Continued) **1016966679**

NY MANIFEST:

Name:	CON EDISON
Address:	15 OCEAN AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004395257
Facility Status:	Not reported
Location Address 1:	15 OLEA AVE
Code:	BP
Location Address 2:	SERVICE BOX # 15433
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004395257
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	11/20/2013
Trans1 Recv Date:	11/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/21/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004395257
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299208GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SB73433 (Continued) **1016966679**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W155 **CON EDISON - SERVICE BOX M4766** **RCRA-LQG** **1024891384**
SSW **15 OCEAN AVE** **NYP005105242**
1/8-1/4 **BROOKLYN, NY 11225**
0.199 mi.
1052 ft. **Site 2 of 9 in cluster W**

Relative: **Lower**

Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	CON EDISON - SERVICE BOX M4766
Handler Address:	15 OCEAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYP005105242
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON - SERVICE BOX M4766 (Continued) **1024891384**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

CON EDISON - SERVICE BOX M4766 (Continued) **1024891384**

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170630
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170630
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX M4766
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:

CON EDISON - SERVICE BOX M4766 (Continued) **1024891384**

Evaluations: No Evaluations Found

W156 **CON EDISON - SERVICE BOX M4766** **NY MANIFEST** **S121968308**
SSW **15 OCEAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.199 mi.
1052 ft. **Site 3 of 9 in cluster W**

Relative:
Lower

Actual:
78 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX M4766
Address:	15 OCEAN AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP005105242
Facility Status:	Not reported
Location Address 1:	15 OCEAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005105242
Mailing Name:	CON EDISON - SERVICE BOX M4766
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

W157 **P.T. STATES INC.** **NY UST** **U001839571**
SSW **15 OCEAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.199 mi.
1052 ft. **Site 4 of 9 in cluster W**

Relative:
Lower

Actual:
78 ft.

UST:

Name:	P.T. STATES INC.
Address:	15 OCEAN AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-402796 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	587688.54919
UTM Y:	4501804.95505
Site Type:	Unknown

P.T. STATES INC. (Continued) **U001839571**

Affiliation Records:

Site Id:	19308
Affiliation Type:	Facility Owner
Company Name:	P.T. STATES INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	315 SEACOST TERRACE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 769-9412
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19308
Affiliation Type:	Mail Contact
Company Name:	P.T. ESTATES, INC.
Contact Type:	Not reported
Contact Name:	B. FEINSTEIN
Address1:	35 OCEAN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 769-9412
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19308
Affiliation Type:	Facility Operator
Company Name:	P.T. STATES INC.
Contact Type:	Not reported
Contact Name:	KINGS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 451-0427
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19308
Affiliation Type:	Emergency Contact
Company Name:	P.T. STATES INC.
Contact Type:	Not reported
Contact Name:	B. FONSTEIN

P.T. STATES INC. (Continued) **U001839571**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 769-9412
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	33026
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	33027
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009

P.T. STATES INC. (Continued) **U001839571**

Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 33028
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1954
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 33029
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550

P.T. STATES INC. (Continued) **U001839571**

Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	005
Tank ID:	33030
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0012
Common Name of Substance:	Kerosene [#1 Fuel Oil] (On-Site Consumption)
Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

P.T. STATES INC. (Continued) **U001839571**

Tank Number:	006
Tank ID:	33031
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	007
Tank ID:	33032
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None

P.T. STATES INC. (Continued) **U001839571**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 33033
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1954
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 009
Tank ID: 33034
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1954
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

P.T. STATES INC. (Continued) **U001839571**

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	010
Tank ID:	33035
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	03
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number:	011
Tank ID:	33036
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1954
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

P.T. STATES INC. (Continued) **U001839571**

Tightness Test Method: 03
Date Test: 11/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 33037
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1954
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 11/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 013
Tank ID: 33038
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1954
Date Tank Closed: 12/01/1999

P.T. STATES INC. (Continued) **U001839571**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 014
Tank ID: 33039
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 550
Install Date: 10/01/1954
Date Tank Closed: 08/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

W158 **CON EDISON - MANHOLE 4766** **RCRA-LQG** **1016967086**
SSW **15 OCEAN AVE** **NY MANIFEST** **NYP004404190**
1/8-1/4 **BROOKLYN, NY 11225**
0.199 mi.
1052 ft. **Site 5 of 9 in cluster W**

Relative: **Lower**

Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 4766
Handler Address:	15 OCEAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYP004404190
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON - MANHOLE 4766 (Continued) **1016967086**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20131211
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private

CON EDISON - MANHOLE 4766 (Continued) **1016967086**

Date Became Current:	20131211
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - MANHOLE 4766
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	15 OCEAN AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004404190
Facility Status:	Not reported
Location Address 1:	15 OCEAN AVE
Code:	BP
Location Address 2:	SB4766
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004404190
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE

CON EDISON - MANHOLE 4766 (Continued) **1016967086**

Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2013
Trans1 Recv Date:	12/11/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004404190
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300422GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q159 **1645 BEDFORD CLEANERS** **NY DRYCLEANERS** **S110245780**
ENE **1645 BEDFORD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.200 mi.
1055 ft. **Site 9 of 10 in cluster Q**

Relative:
Higher

Actual:
101 ft.

DRYCLEANERS:

Name:	1645 BEDFORD CLEANERS
Address:	1645 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Facility ID:	2-6104-01048
Phone Number:	7184678995
Region:	Not reported
Registration Effective Date:	2002-04-04 10:47:19
Inspection Date:	2000-06-23 11:30:00
Install Date:	Not reported
Expiration Date:	12/12/2002
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	1645 BEDFORD CLEANERS
Address:	1645 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Facility ID:	2-6104-01048
Phone Number:	7184678995
Region:	Not reported
Registration Effective Date:	2002-04-04 10:47:19
Inspection Date:	2001-06-14 08:45:00
Install Date:	Not reported
Expiration Date:	12/12/2002
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	1645 BEDFORD CLEANERS
Address:	1645 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Facility ID:	2-6104-01048
Phone Number:	7184678995
Region:	Not reported
Registration Effective Date:	2002-04-04 10:47:19
Inspection Date:	2002-06-13 11:15:00
Install Date:	Not reported
Expiration Date:	12/12/2002
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Q160 **1645 BEDFORD INC** **RCRA NonGen / NLR** **1000273902**
ENE **1645 BEDFORD AVE** **NY MANIFEST** **NYD980778724**
1/8-1/4 **BROOKLYN, NY 11225**
0.200 mi.
1055 ft. **Site 10 of 10 in cluster Q**

Relative: **Higher**

Actual: **101 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	1645 BEDFORD INC	
Handler Address:		1645 BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYD980778724
Contact Name:		Not reported
Contact Address:		BEDFORD AVE
Contact City,State,Zip:		BROOKLYN, NY 11225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BEDFORD AVE
Mailing City,State,Zip:		BROOKLYN, NY 11225
Owner Name:	SEUNG IL KIM	
Owner Type:		Private
Operator Name:	SEUNG IL KIM	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

1645 BEDFORD INC (Continued) **1000273902**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	NONE
Waste Description:	Not Defined

1645 BEDFORD INC (Continued) **1000273902**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SEUNG IL KIM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: SEUNG IL KIM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: SEUNG IL KIM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950405
Handler Name: 1645 BEDFORD INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: 1645 BEDFORD INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

1645 BEDFORD INC (Continued) **1000273902**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: 1645 BEDFORD INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19841012
Handler Name: 1645 BEDFORD INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	1645 BEDFORD INCORPORATED
Address:	1645 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYD980778724
Facility Status:	Not reported
Location Address 1:	1645 BEDFORD AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

1645 BEDFORD INC (Continued) **1000273902**

Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD980778724
Mailing Name: 1645 BEDFORD INCORPORATED
Mailing Contact: HAM JUNG GYU
Mailing Address 1: 1645 BEDFORD AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124678995

U161 **916 CARROLL STREET** **NY AST** **A100298597**
North **916 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.202 mi.
1067 ft. **Site 3 of 7 in cluster U**

Relative:
Higher

Actual:
125 ft.

AST:
Name: 916 CARROLL STREET
Address: 916 CARROLL STREET
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-054712
Program Type: PBS
UTM X: 587814.31783
UTM Y: 4502461.21015
Expiration Date: 06/26/2023
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 772
Affiliation Type: Facility Operator
Company Name: 916 CARROLL STREET
Contact Type: Not reported
Contact Name: OMAR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 261-0752
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2013-07-29

Site Id: 772
Affiliation Type: Emergency Contact

916 CARROLL STREET (Continued) **A100298597**

Company Name:	916 CARROLL ST LLC
Contact Type:	Not reported
Contact Name:	MARC BARHORIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 261-0752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-08

Site Id:	772
Affiliation Type:	Mail Contact
Company Name:	916 CARROLL ST LLC
Contact Type:	MEMBER
Contact Name:	MEIR BOUSKILA
Address1:	PO BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116-1920
Country Code:	001
Phone:	(212) 564-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-08

Site Id:	772
Affiliation Type:	Facility Owner
Company Name:	916 CARROLL ST LLC
Contact Type:	AGENT
Contact Name:	ISAK RADONCIC
Address1:	PO BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10116-1920
Country Code:	001
Phone:	(212) 564-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-08

Tank Info:

Tank Number:	001
Tank Id:	1693
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

916 CARROLL STREET (Continued) **A100298597**

Equipment Records:

G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Coated Steel
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	01/30/2005
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	01
Tank Id:	213374
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Fiberglass Coated Steel
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/30/2005
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

916 CARROLL STREET (Continued) **A100298597**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

V162 **CON EDISON - CROWN & BEDFORD STREET** **PA MANIFEST** **S123093177**
ENE **CROWN & BEDFORD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.203 mi.
1074 ft. **Site 4 of 11 in cluster V**

Relative: **Higher**
Actual: **105 ft.**

Manifest Details:

Year:	2017
Manifest Number:	009794895FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYP005051891
Generator Date:	03/24/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	1500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

V163 **CON EDISON** **RCRA NonGen / NLR** **1014396039**
ENE **BEDFORD AVE & CROWN ST** **NY MANIFEST** **NYP004182192**
1/8-1/4 **BROOKLYN, NY 11201**
0.203 mi.
1074 ft. **Site 5 of 11 in cluster V**

Relative: **Higher**
Actual: **105 ft.**

RCRA Listings:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		BEDFORD AVE & CROWN ST
Handler City,State,Zip:		BROOKLYN, NY 11201
EPA ID:		NYP004182192
Contact Name:		STEVEN MARTIS
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		917-416-5423
Contact Fax:		Not reported

CON EDISON (Continued) **1014396039**

Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A

CON EDISON (Continued) **1014396039**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160609
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090625
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1014396039**

NY MANIFEST:

Name:	CONSOLIDATED EDISON - MH 4795
Address:	BEDFORD AVE & CROWN ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004182192
Facility Status:	Not reported
Location Address 1:	BEDFORD & CROWN
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004182192
Mailing Name:	CONSOLIDATED EDISON - MH 4795
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/26/2009
Trans1 Recv Date:	06/26/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004182192
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001440072FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **1014396039**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	450
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	5
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	B002
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V164 **CON EDISON SERVICE BOX: 7338** **RCRA NonGen / NLR** **1016970092**
ENE **CROWN ST & BEDFORD AVE** **NY MANIFEST** **NYP004437919**
1/8-1/4 **BROOKLYN, NY 11225**
0.203 mi.
1074 ft. **Site 6 of 11 in cluster V**

Relative: **Higher**

Actual: **105 ft.**

RCRA Listings:

Date Form Received by Agency:		20140308
Handler Name:	CON EDISON SERVICE BOX:	7338
Handler Address:		CROWN ST & BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004437919
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No

CON EDISON SERVICE BOX: 7338 (Continued) **1016970092**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:
Receive Date: 20140208

CON EDISON SERVICE BOX: 7338 (Continued) **1016970092**

Handler Name: CON EDISON SERVICE BOX: 7338
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140308
Handler Name: CON EDISON SERVICE BOX: 7338
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: CROWN ST & BEDFORD AVE
City,State,Zip: BROOKLYN, NY 11225
Country: USA
EPA ID: NYP004437919
Facility Status: Not reported
Location Address 1: CROWN ST 200 W/O BEDFORD AVE
Code: BP
Location Address 2: SB2338
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004437919
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE

CON EDISON SERVICE BOX: 7338 (Continued) **1016970092**

Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2014
Trans1 Recv Date:	02/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004437919
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002301053GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V165 **CON EDISON VAULT SUBMERSIBLE: 7524** **RCRA NonGen / NLR** **1016970091**
ENE **CROWN ST & BEDFORD AVE** **NY MANIFEST** **NYP004437901**
1/8-1/4 **BROOKLYN, NY 11225**
0.203 mi.
1074 ft. **Site 7 of 11 in cluster V**

Relative: **Higher**
Actual: **105 ft.**

RCRA Listings:

Date Form Received by Agency:		20140308
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 7524	
Handler Address:		CROWN ST & BEDFORD AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004437901
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON VAULT SUBMERSIBLE: 7524 (Continued) **1016970091**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140208
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 7524
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140308
Handler Name:	CON EDISON VAULT SUBMERSIBLE: 7524
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON VAULT SUBMERSIBLE: 7524 (Continued) **1016970091**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	CROWN ST & BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004437901
Facility Status:	Not reported
Location Address 1:	S/S CROWN ST 163 W/O BEDFORD A
Code:	BP
Location Address 2:	VE
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004437901
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2014
Trans1 Recv Date:	02/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004437901

CON EDISON VAULT SUBMERSIBLE: 7524 (Continued) **1016970091**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002301052GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V166 **MEDGAR EVERS COLLEGE S-BLDG** **NY AST** **A100393061**
ENE **1637 BEDFORD AVE.** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.204 mi.
1075 ft. **Site 8 of 11 in cluster V**

Relative:
Higher

Actual:
103 ft.

AST:

Name:	MEDGAR EVERS COLLEGE S-BLDG
Address:	1637 BEDFORD AVE.
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-612221
Program Type:	PBS
UTM X:	588204.31159
UTM Y:	4502270.71208
Expiration Date:	N/A
Site Type:	School

Affiliation Records:

Site Id:	493947

MEDGAR EVERS COLLEGE S-BLDG (Continued) **A100393061**

Affiliation Type:	Facility Owner
Company Name:	CITY UNIV OF NY
Contact Type:	FAC
Contact Name:	LINDA CORCORAN
Address1:	205 EAST 42ND ST
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(646) 664-2855
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-04-21

Site Id:	493947
Affiliation Type:	Mail Contact
Company Name:	MEDGAR EVERS COLLEGE S-BLDG
Contact Type:	Not reported
Contact Name:	MOHAMED A. BANGURA
Address1:	1650 BEDFORD AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 270-6216
EMail:	MBANGURA@MEC.CUNY.EDU
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-04-21

Site Id:	493947
Affiliation Type:	Facility Operator
Company Name:	MEDGAR EVERS COLLEGE S-BLDG
Contact Type:	Not reported
Contact Name:	MEDGAR EVERS COLLEGE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 270-4842
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-04-21

Site Id:	493947
Affiliation Type:	Emergency Contact
Company Name:	CITY UNIV OF NY
Contact Type:	Not reported
Contact Name:	MOHAMEDA A. BANGURA
Address1:	Not reported
Address2:	Not reported

MEDGAR EVERS COLLEGE S-BLDG (Continued) **A100393061**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 270-6216
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-04-21

Tank Info:

Tank Number:	003
Tank Id:	251741

Equipment Records:

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/30/2006
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	004
Tank Id:	251742

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

MEDGAR EVERS COLLEGE S-BLDG (Continued) **A100393061**

E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/30/2006
Capacity Gallons:	100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

S167 **CITY OF N.Y. DEPT. OF H.P.D.** **NY AST** **U003396017**
NNE **888 FRANKLIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.205 mi.
1083 ft. **Site 6 of 12 in cluster S**

Relative: **Higher**
Actual: **117 ft.**

AST:

Name:	CITY OF N.Y. DEPT. OF H.P.D.
Address:	888 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-601142
Program Type:	PBS
UTM X:	587985.92380
UTM Y:	4502444.62786
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	23112
Affiliation Type:	Mail Contact
Company Name:	CITY OF N.Y. DEPT. OF H.P.D.,TECH.SERVICES
Contact Type:	Not reported
Contact Name:	IVAN SCHWARTZ
Address1:	75 MAIDEN LANE
Address2:	4TH FLOOR -RM 427
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 806-8037
EMail:	Not reported
Fax Number:	Not reported

CITY OF N.Y. DEPT. OF H.P.D. (Continued) **U003396017**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	23112
Affiliation Type:	Facility Operator
Company Name:	CITY OF N.Y. DEPT. OF H.P.D.
Contact Type:	Not reported
Contact Name:	NORMAN FEIG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 827-1972
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	23112
Affiliation Type:	Emergency Contact
Company Name:	CITY OF N.Y. DEPT. OF H.P.D.
Contact Type:	Not reported
Contact Name:	MIKE RIVERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 827-1982
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	23112
Affiliation Type:	Facility Owner
Company Name:	CITY OF N.Y. DEPT. OF H.P.D.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	75 MAIDEN LANE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 806-8306
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-09-26

Tank Info:

Tank Number:	1

CITY OF N.Y. DEPT. OF H.P.D. (Continued) **U003396017**

Tank Id: 44840
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/2000
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

S168 **951 CARROLL ST** **NY AST** **U003387774**
NNE **951 CARROLL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.209 mi.
1106 ft. **Site 7 of 12 in cluster S**

Relative: **Higher**
Actual: **116 ft.**

AST:
Name: 951 CARROLL ST
Address: 951 CARROLL ST
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-234273
Program Type: PBS
UTM X: 588018.21573
UTM Y: 4502433.67452
Expiration Date: 03/31/2024
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 8569
Affiliation Type: Mail Contact
Company Name: BLOG EQUITY MGMT
Contact Type: Not reported
Contact Name: MICHAEL VINOCAR
Address1: 1261 BROADWAY

951 CARROLL ST (Continued) **U003387774**

Address2:	SUITE 812
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 489-5060
EMail:	MVINOCUR@BEMNY.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8569
Affiliation Type:	Facility Operator
Company Name:	951 CARROLL ST
Contact Type:	Not reported
Contact Name:	MICHAEL PANCHAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 573-0210
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2014-07-21

Site Id:	8569
Affiliation Type:	Emergency Contact
Company Name:	CARROLL STREET ASSOC, LLC
Contact Type:	Not reported
Contact Name:	MICHAEL VINOCAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 573-0210
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Site Id:	8569
Affiliation Type:	Facility Owner
Company Name:	CARROLL STREET ASSOC, LLC
Contact Type:	AGENT
Contact Name:	MICHAEL VINOCAR
Address1:	1261 BROADWAY, SUITE 812
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10001
Country Code:	001
Phone:	(212) 489-5060

951 CARROLL ST (Continued) **U003387774**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-01-04

Tank Info:

Tank Number:	001
Tank Id:	12546
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1995
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

169
SE
1/8-1/4
0.210 mi.
1109 ft.

1767 BEDFORD AVE **NY AST** **U003391410**
1767 BEDFORD AVE **N/A**
BROOKLYN, NY 11225

Relative:
Lower

Actual:
67 ft.

AST:

Name:	1767 BEDFORD AVE
Address:	1767 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-373885
Program Type:	PBS
UTM X:	588164.87038

1767 BEDFORD AVE (Continued) **U003391410**

UTM Y: 4501868.08958
Expiration Date: 11/25/2023
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 18789
Affiliation Type: Mail Contact
Company Name: YJ BEDFORD LLC
Contact Type: Not reported
Contact Name: D. RAKOWER
Address1: PO BOX D1800
Address2: Not reported
City: POMONA
State: NY
Zip Code: 10970
Country Code: 001
Phone: (845) 354-9236 104
EMail: Not reported
Fax Number: Not reported
Modified By: JAAVERSA
Date Last Modified: 2016-09-22

Site Id: 18789
Affiliation Type: Facility Operator
Company Name: MARC NELSON ASSOCIATES LLC
Contact Type: Not reported
Contact Name: FIDELFIA MACIAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 636-3491
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2016-08-22

Site Id: 18789
Affiliation Type: Emergency Contact
Company Name: YJ BEDOFRD LLC
Contact Type: Not reported
Contact Name: FIDELFIA MACIAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 636-3491
EMail: Not reported
Fax Number: Not reported
Modified By: JAAVERSA
Date Last Modified: 2016-09-21

Site Id: 18789
Affiliation Type: Facility Owner

1767 BEDFORD AVE (Continued) **U003391410**

Company Name:	YJ BEDFORD LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	D. RAKOWER
Address1:	PO BOX D1800
Address2:	Not reported
City:	POMONA
State:	NY
Zip Code:	10970
Country Code:	001
Phone:	(845) 354-9236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-08-14

Tank Info:

Tank Number:	001
Tank Id:	21420
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	F06 - Pipe External Protection - Wrapped
	J02 - Dispenser - Suction Dispenser
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	C00 - Pipe Location - No Piping
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/13/1918
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

T170 **50 LEFFERTS TENANTS CORP.** **NY AST** **A100521179**
South **50 LEFFERTS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.211 mi.
1114 ft. **Site 2 of 7 in cluster T**

Relative:
Lower

Actual:
73 ft.

AST:

Name:	50 LEFFERTS TENANTS CORP.
Address:	50 LEFFERTS AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-603774
Program Type:	PBS
UTM X:	587964.11615
UTM Y:	4501722.79307
Expiration Date:	11/25/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	25677
Affiliation Type:	Mail Contact
Company Name:	C/O 50 LEFFERTS TENANTS CORP.
Contact Type:	Not reported
Contact Name:	FSR - COMPLIANCE DEPT.
Address1:	622 THIRD AVENUE
Address2:	14TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10017
Country Code:	001
Phone:	(212) 634-8900
EMail:	COMPLIANCE.NY@FSRESIDENTIAL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-12-27

Site Id:	25677
Affiliation Type:	Facility Operator
Company Name:	50 LEFFERTS TENANTS CORP.
Contact Type:	Not reported
Contact Name:	HARLIN LASCELL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 606-5186
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-01-28

Site Id:	25677
Affiliation Type:	Emergency Contact
Company Name:	50 LEFFERTS TENANTS CORP.
Contact Type:	Not reported
Contact Name:	RANDY SULZER

50 LEFFERTS TENANTS CORP. (Continued) **A100521179**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 634-8900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-12-27

Site Id:	25677
Affiliation Type:	Facility Owner
Company Name:	50 LEFFERTS TENANTS CORP.
Contact Type:	DIRECTOR OF COMPLIANCE
Contact Name:	STEPHANIE CARDELLO
Address1:	50 LEFFERTS AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(212) 634-8900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-08-09

Tank Info:

Tank Number:	001
Tank Id:	55528
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	E00 - Piping Secondary Containment - None
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	D00 - Pipe Type - No Piping
	J00 - Dispenser - None
	G00 - Tank Secondary Containment - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1939
Capacity Gallons:	5000
Tightness Test Method:	-

50 LEFFERTS TENANTS CORP. (Continued) **A100521179**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

T171 **50 REALTY CO** **NY AST** **A100520849**
South **50 LEFFERTS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.211 mi.
1114 ft. **Site 3 of 7 in cluster T**

Relative:
Lower

Actual:
73 ft.

AST:

Name:	50 REALTY CO
Address:	50 LEFFERTS AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-359009
Program Type:	PBS
UTM X:	587964.24724
UTM Y:	4501721.91426
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	18031
Affiliation Type:	Facility Owner
Company Name:	50 REALTY C/OJ KEMPLER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1526 - 54 ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 851-1940
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	18031
Affiliation Type:	Mail Contact
Company Name:	50 REALTY C/OJ KEMPLER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1526 - 54 ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 851-1940

50 REALTY CO (Continued) **A100520849**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 18031
Affiliation Type: Facility Operator
Company Name: 50 REALTY CO
Contact Type: Not reported
Contact Name: POSOTIVE HEATING
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 851-1940
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 18031
Affiliation Type: Emergency Contact
Company Name: 50 REALTY C/OJ KEMPLER
Contact Type: Not reported
Contact Name: TITO VEGA/SUPT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 826-1453
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 20397
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)

50 REALTY CO (Continued) **A100520849**

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	12/01/1944
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/29/2003
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

S172 **959 CARROLL ASSOCIATES** **NY AST** **U004076993**
NNE **959 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.212 mi.
1119 ft. **Site 8 of 12 in cluster S**

Relative: **Higher**

Actual: **116 ft.**

AST:

Name:	959 CARROLL ASSOCIATES
Address:	959 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-208108
Program Type:	PBS
UTM X:	588046.70563
UTM Y:	4502426.06243
Expiration Date:	09/19/2027
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	7419
Affiliation Type:	Mail Contact
Company Name:	959 CARROLL ASSOCIATES
Contact Type:	Not reported
Contact Name:	SUPER/FACILITY MANAGER
Address1:	P.O. BOX 190155
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219-0155
Country Code:	001
Phone:	(718) 871-7909
EMail:	JMCMANAGE@AOL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-13

Site Id:	7419
Affiliation Type:	Facility Operator
Company Name:	959 CARROLL ASSOCIATES
Contact Type:	Not reported

959 CARROLL ASSOCIATES (Continued) **U004076993**

Contact Name:	EFRAIM NEVICS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 871-7909
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7419
Affiliation Type:	Emergency Contact
Company Name:	DAVID JAKOB
Contact Type:	Not reported
Contact Name:	JOSH JACOBS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 871-7909
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	7419
Affiliation Type:	Facility Owner
Company Name:	959 CARROLL ASSOCIATES LLC
Contact Type:	MANAGING AGENT
Contact Name:	JOSH JACOBS
Address1:	P.O. BOX 190155
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 871-7909
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-13

Tank Info:

Tank Number:	001
Tank Id:	9663
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None

959 CARROLL ASSOCIATES (Continued) **U004076993**

K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1938
Capacity Gallons:	7000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	09/13/2022
Material Name:	#2 fuel oil (on-site consumption)

X173 **CON EDISON** **NJ MANIFEST** **S120666857**
SSW **FLATBUSH AVE & LEFFERTS AVE SE** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.212 mi.
1120 ft. **Site 1 of 12 in cluster X**

Relative: **Lower**
Actual: **72 ft.**

NJ MANIFEST:

EPA Id:	NYP004726949
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	012773542JJK
EPA ID:	NYP004726949
Date Shipped:	2/6/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported

CON EDISON (Continued) **S120666857**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

X174 **CON EDISON** **RCRA NonGen / NLR** **1018277947**
SSW **FLATBUSH AVE & LEFFERTS AVE SE** **FINDS** **NYP004726949**
1/8-1/4 **BROOKLYN, NY 11217** **ECHO**
0.212 mi.
1120 ft. **Site 2 of 12 in cluster X**

Relative: RCRA Listings:
Lower

Actual: Date Form Received by Agency:		20150206
72 ft. Handler Name:	CON EDISON	
Handler Address:		FLATBUSH AVE & LEFFERTS AVE SE
Handler City,State,Zip:		BROOKLYN, NY 11217
EPA ID:		NYP004726949
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private

CON EDISON (Continued) **1018277947**

Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No

CON EDISON (Continued) **1018277947**

Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20160502
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150206
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150206
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067696513

Click Here for FRS Facility Detail Report:

CON EDISON (Continued) **1018277947**

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277947
Registry ID:	110067696513
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067696513
Name:	CON EDISON
Address:	FLATBUSH AVE & LEFFERTS AVE SE
City,State,Zip:	BROOKLYN, NY 11217

X175 **CON EDISON** **NY MANIFEST** **S117739569**
SSW **FLATBUSH AVE & LEFFERTS AVE SE** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.212 mi.
1120 ft. **Site 3 of 12 in cluster X**

Relative: **Lower**

Actual: **72 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FLATBUSH AVE & LEFFERTS AVE SE
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004726949
Facility Status:	Not reported
Location Address 1:	SEC FLATBUSH AVE & LEFFERS AV
Code:	BP
Location Address 2:	SB265705
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004726949
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CON EDISON (Continued) **S117739569**

Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/06/2015
Trans1 Recv Date:	02/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004726949
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773542JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R176 **1030 CARROLL STREET** **NY AST** **U003386393**
NE **1030 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.215 mi.
1134 ft. **Site 4 of 4 in cluster R**

Relative: AST:
Higher

Name:	1030 CARROLL STREET
Address:	1030 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2

Actual:
115 ft.

1030 CARROLL STREET (Continued) **U003386393**

Site Status: Active
Facility Id: 2-214183
Program Type: PBS
UTM X: 588154.81415
UTM Y: 4502372.24242
Expiration Date: 07/24/2023
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 7940
Affiliation Type: Mail Contact
Company Name: LINEAGE VENTURES LLC
Contact Type: Not reported
Contact Name: BEN HERSKOWITZ
Address1: 1 STATE STREET
Address2: 32ND FLOOR
City: NEW YORK
State: NY
Zip Code: 10004
Country Code: 001
Phone: (212) 320-2400
EMail: ALANAR@LINEAGEPROPERTIES.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2019-03-28

Site Id: 7940
Affiliation Type: Facility Owner
Company Name: 1030 CARROLL HOLDINGS LLC
Contact Type: OWNER
Contact Name: DANIEL TINNENY
Address1: 266 BROADWAY, SUITE 403
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (212) 320-2400
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2019-03-22

Site Id: 7940
Affiliation Type: Facility Operator
Company Name: 1030 CARROLL STREET
Contact Type: Not reported
Contact Name: GAZI SEJDIU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 841-7302
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI

1030 CARROLL STREET (Continued) **U003386393**

Date Last Modified: 2019-03-22

Site Id: 7940
Affiliation Type: Emergency Contact
Company Name: 1030 CARROLL HOLDINGS LLC
Contact Type: Not reported
Contact Name: GAZI SEJDIU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 841-7302
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2019-03-22

Tank Info:

Tank Number: 001
Tank Id: 9856
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
J07 - Dispenser - Loading Rack/Transfer Pump
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 11/03/1926
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

W177 **J & L PROPERTIES** **NY AST** **U003392226**
SSW **39 OCEAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.215 mi.
1135 ft. **Site 6 of 9 in cluster W**

Relative:
Lower

Actual:
76 ft.

AST:

Name:	J & L PROPERTIES
Address:	39 OCEAN AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-219711
Program Type:	PBS
UTM X:	587667.17763
UTM Y:	4501763.37231
Expiration Date:	01/07/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8434
Affiliation Type:	Emergency Contact
Company Name:	J & L PROPERTIES
Contact Type:	Not reported
Contact Name:	J&L PROPERTIES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 972-0726
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-22

Site Id:	8434
Affiliation Type:	Facility Owner
Company Name:	J & L PROPERTIES
Contact Type:	MANAGING AGENT
Contact Name:	ISAAC HEIMOVITS
Address1:	1522 41ST STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11218
Country Code:	001
Phone:	(718) 972-0726
EMail:	IMKMANAGEMENTLLC@GMAIL.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-22

Site Id:	8434
Affiliation Type:	Mail Contact
Company Name:	J & L PROPERTIES
Contact Type:	MANAGING AGENT
Contact Name:	ISAAC HEIMOVITS

J & L PROPERTIES (Continued) **U003392226**

Address1:	1522 41ST STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11218
Country Code:	001
Phone:	(718) 972-0726
EMail:	IMKMANAGEMENTLLC@GMAIL.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-22

Site Id:	8434
Affiliation Type:	Facility Operator
Company Name:	J & L PROPERTIES
Contact Type:	Not reported
Contact Name:	RAMON CSSPEDER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 479-6162
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-11-14

Tank Info:

Tank Number:	001
Tank Id:	24139
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H04 - Tank Leak Detection - Groundwater Well
	E00 - Piping Secondary Containment - None
	I02 - Overfill - High Level Alarm
	I04 - Overfill - Product Level Gauge (A/G)
	J00 - Dispenser - None
	C01 - Pipe Location - Aboveground
	G02 - Tank Secondary Containment - Vault (w/access)
	K00 - Spill Prevention - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	L00 - Piping Leak Detection - None
	F99 - Pipe External Protection - Other
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1920

J & L PROPERTIES (Continued) **U003392226**

Capacity Gallons:	3500
Tightness Test Method:	34
Date Test:	01/11/2021
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

U178 **931 CARROLL STREET** **NY VCP** **S125317246**
NNE **931 CARROLL STREET** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.215 mi.
1137 ft. **Site 4 of 7 in cluster U**

Relative: **Higher**
Actual: **117 ft.**

VCP NYC:

Project ID:	19TMP1475K,19EH-A320K,19CVCP064K
Name:	931 CARROLL STREET
Address:	931 CARROLL STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3011880058
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Approved Remedial Plan
Latitude:	40.668183
Longitude:	-73.959685
Postcode:	9
Community Board:	35
Council District:	213
Census Tract:	3029709
BIN:	3011880058
NTA:	Crown Heights South

U179 **SEACREST LINEN** **NY LTANKS** **S104621873**
NNE **931 CARROLL ST** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.215 mi.
1137 ft. **Site 5 of 7 in cluster U**

Relative: **Higher**
Actual: **117 ft.**

LTANKS:

Name:	SEACREST LINEN
Address:	931 CARROLL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0003909 / 2005-07-14
Facility ID:	0003909
Site ID:	147612
Spill Date:	2000-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JXGRECO
Referred To:	Not reported
Reported to Dept:	2000-06-29

SEACREST LINEN (Continued) **S104621873**

CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-06-29
Spill Record Last Update:	2005-07-14
Spiller Name:	DANIEL GREENBERG
Spiller Company:	SEACREST LINEN
Spiller Address:	931 CARROLL ST
Spiller County:	001
Spiller Contact:	DANIEL GREENBERG
Spiller Phone:	(718) 287-4800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	125661
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/9/03 TJD Transferred Demeo >>> Rommel. June, 2005: Spill transferred to Greco as part of Spill Closure Initiative. The facility contact, Mr. Daniel Greenberg, was called on 6/16/05. Mr. Greenberg claims that all remedial work is complete and that the DEC was involved in the project. Unfortunately, the project file contains only the Spill Report and the second tank test report (i.e., the one that Mr. Greenberg claims was done following tank repair and soils remediation). Mr. Greenberg is attempting to find the engineer's report on the remediation. 06/20/05 JDG July 14: Pro Test (the firm that did the tank testing)contacted me on 7/13/05 and explained that Mr. Greenberg had confused this site with another site he had been involved in (i.e., 9903240, located at a different Sea Crest Linen site at 46 Crown St.). The 46 Crown St. site did require remediation and was ultimately closed by the DEC. Pro Test went on to say that the 931 Carroll St. site had two tanks that failed tightness testing, however, they were determined to not have leaked (i.e., it was a vent line breach, only). This was determined during an excavation and tank upgrade performed following the first tightness failure. The tanks have been upgraded and have passed tightness testing. Sice there was no reported release to the environment and the tanks now have been upgraded and pass testing, the spill was closed. JDG 7/14/05"
Remarks:	"both tanks failed test - no product spilage"

All TTF:

Facility ID:	0003909
Spill Number:	0003909
Spill Tank Test:	1525736
Site ID:	147612
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00

SEACREST LINEN (Continued) **S104621873**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 147612
Operable Unit ID: 825133
Operable Unit: 01
Material ID: 548661
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 147612
Operable Unit ID: 825133
Operable Unit: 01
Material ID: 548662
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

E DESIGNATION:
Name: LOT 58,TAXBLOCK 1188
Address: 931 CARROLL STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 58
Tax Block: 1188
Borough Code: Not reported
E-No: E-405
Effective Date: 12/20/2018
Satisfaction Date: Not reported
Ceqr Number: 17DCP067K
Ulurp Number: 180347ZMK, 180348ZRK180347ZMK, 180348ZRK
Zoning Map No: 16d

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Exhaust stack location limitations
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

U180 **931 CARROLL STREET** **NY AST** **A100295976**
NNE **931 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.215 mi.
1137 ft. **Site 6 of 7 in cluster U**

Relative:
Higher

Actual:
117 ft.

AST:

Name:	931 CARROLL STREET
Address:	931 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-215929
Program Type:	PBS
UTM X:	587937.63416
UTM Y:	4502454.78284
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8094
Affiliation Type:	Mail Contact
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	OWNER'S REP
Contact Name:	HARRY EINHOM
Address1:	100A BROADWAY, SUITE 110
Address2:	Not reported
City:	BROOKYLN
State:	NY
Zip Code:	11249
Country Code:	001
Phone:	(646) 488-0093
EMail:	PAUL@STREKTE.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-05-29

Site Id:	8094
Affiliation Type:	Facility Owner
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	OWNER'S REP
Contact Name:	HARRY EINHOM
Address1:	100A BROADWAY, SUITE 110
Address2:	Not reported
City:	BROOKYLN
State:	NY
Zip Code:	11249
Country Code:	001
Phone:	(646) 488-0093
EMail:	PAUL@STREKTE.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-05-29

Site Id:	8094
Affiliation Type:	Facility Operator
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	Not reported
Contact Name:	PAUL STREKTE

931 CARROLL STREET (Continued) **A100295976**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 488-0093
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-05-29

Site Id:	8094
Affiliation Type:	Emergency Contact
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	Not reported
Contact Name:	PAUL JENSEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 488-0093
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-04-05

Tank Info:

Tank Number:	3
Tank Id:	67447
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

	G00 - Tank Secondary Containment - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D00 - Pipe Type - No Piping
	J00 - Dispenser - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

931 CARROLL STREET (Continued) **A100295976**

Date Tank Closed:	08/22/2010
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil
Tank Number:	4
Tank Id:	67448
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/22/2010
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

U181 **931 CARROLL STREET** **NY UST** **U004064327**
NNE **931 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.215 mi.
1137 ft. **Site 7 of 7 in cluster U**

Relative: **Higher**
Actual: **117 ft.**

UST:

Name:	931 CARROLL STREET
Address:	931 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-215929 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	587937.63416
UTM Y:	4502454.78284
Site Type:	Apartment Building/Office Building

931 CARROLL STREET (Continued) **U004064327**

Affiliation Records:

Site Id:	8094
Affiliation Type:	Mail Contact
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	OWNER'S REP
Contact Name:	HARRY EINHOM
Address1:	100A BROADWAY, SUITE 110
Address2:	Not reported
City:	BROOKYLN
State:	NY
Zip Code:	11249
Country Code:	001
Phone:	(646) 488-0093
EMail:	PAUL@STREKTE.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-05-29

Site Id:	8094
Affiliation Type:	Facility Owner
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	OWNER'S REP
Contact Name:	HARRY EINHOM
Address1:	100A BROADWAY, SUITE 110
Address2:	Not reported
City:	BROOKYLN
State:	NY
Zip Code:	11249
Country Code:	001
Phone:	(646) 488-0093
EMail:	PAUL@STREKTE.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-05-29

Site Id:	8094
Affiliation Type:	Facility Operator
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	Not reported
Contact Name:	PAUL STREKTE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 488-0093
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-05-29

Site Id:	8094
Affiliation Type:	Emergency Contact
Company Name:	CARROLL DEVELOPMENT PLAZA LLC
Contact Type:	Not reported
Contact Name:	PAUL JENSEN

931 CARROLL STREET (Continued) **U004064327**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 488-0093
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-04-05

Tank Info:

Tank Number:	001
Tank ID:	22325
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1984
Date Tank Closed:	10/07/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	00
Date Test:	09/16/2014
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
L09 - Piping Leak Detection - Exempt Suction Piping
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
E04 - Piping Secondary Containment - Double walled UG
B08 - Tank External Protection - Retrofitted Impressed Current
F08 - Pipe External Protection - Retrofitted Impressed Current
J04 - Dispenser - On Site Heating System (Suction)

Tank Number:	002
Tank ID:	22326
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1984
Date Tank Closed:	01/19/2006
Registered:	True

931 CARROLL STREET (Continued) **U004064327**

Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	12/13/2000
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

S182 **TAG REALTY INC.** **NY AST** **A100175094**
NNE **969 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.216 mi.
1140 ft. **Site 9 of 12 in cluster S**

Relative: **Higher**

Actual: **117 ft.**

AST:

Name:	TAG REALTY INC.
Address:	969 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-285412
Program Type:	PBS
UTM X:	588093.84258
UTM Y:	4502377.45881
Expiration Date:	01/16/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	12688
Affiliation Type:	Facility Owner
Company Name:	TAG REALTY INC.
Contact Type:	SECRETARY
Contact Name:	ARON WIZNITZER
Address1:	5318 NEW UTRECHT AVENUE, 2ND FLOOR
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 694-2541
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY

TAG REALTY INC. (Continued) **A100175094**

Date Last Modified: 2016-07-28

Site Id: 12688
Affiliation Type: Mail Contact
Company Name: TAG REALTY INC.
Contact Type: Not reported
Contact Name: ARON WIZNITZER
Address1: 5318 NEW UTRECHT AVENUE
Address2: 2ND FLOOR
City: BROOKLYN
State: NY
Zip Code: 11219
Country Code: 001
Phone: (718) 694-2541
EMail: ARON@WMREALTYNY.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-01-04

Site Id: 12688
Affiliation Type: Facility Operator
Company Name: TAG REALTY INC.
Contact Type: Not reported
Contact Name: CARLOS RAMOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 219-6009
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-12-06

Site Id: 12688
Affiliation Type: Emergency Contact
Company Name: TAG REALTY INC.
Contact Type: Not reported
Contact Name: CARLOS RAMOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 219-6009
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-12-06

Tank Info:

Tank Number: 01
Tank Id: 17570

TAG REALTY INC. (Continued) **A100175094**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/19/1925
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

X183 **CON EDISON** **NY MANIFEST** **S117739574**
SSW **514 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.216 mi.
1141 ft. **Site 4 of 12 in cluster X**

Relative: **Lower**
Actual: **71 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 514 FLATBUSH AVE
City,State,Zip: BROOKLYN, NY 11215
Country: USA
EPA ID: NYP004726998
Facility Status: Not reported
Location Address 1: 514 FLATBUSH AV
Code: BP
Location Address 2: SB26712
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004726998
Mailing Name: CON EDISON
Mailing Contact: CON EDISON

CON EDISON (Continued) **S117739574**

Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/06/2015
Trans1 Recv Date:	02/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004726998
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002621005GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X184 **CON EDISON** **NJ MANIFEST** **S120666861**
SSW **514 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.216 mi.
1141 ft. **Site 5 of 12 in cluster X**

Relative: **Lower**

Actual: **71 ft.**

NJ MANIFEST:

EPA Id:	NYP004726998
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002626028GBF
EPA ID:	NYP004726998
Date Shipped:	2/9/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120666861**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported
Manifest Number:	002621005GBF
EPA ID:	NYP004726998
Date Shipped:	2/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

X185 **CON EDISON** **RCRA NonGen / NLR** **1018277952**
SSW **514 FLATBUSH AVE** **FINDS** **NYP004726998**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.216 mi.
1141 ft. **Site 6 of 12 in cluster X**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:		20150206
Handler Name:	CON EDISON	
Handler Address:		514 FLATBUSH AVE
Handler City,State,Zip:		BROOKLYN, NY 11215
EPA ID:		NYP004726998
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1018277952**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150206
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150206
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018277952**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067696568

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277952
Registry ID:	110067696568
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067696568
Name:	CON EDISON
Address:	514 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY 11215

Y186 **881 WASHINGTON AVE** **NY AST** **U003391824**
NNW **881 WASHINGTON AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.217 mi.
1146 ft. **Site 1 of 2 in cluster Y**

Relative:
Higher

Actual:
128 ft.

AST:

Name:	881 WASHINGTON AVE
Address:	881 WASHINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-216208
Program Type:	PBS
UTM X:	587753.63481
UTM Y:	4502455.87773
Expiration Date:	10/15/2027
Site Type:	Apartment Building/Office Building

Affiliation Records:

881 WASHINGTON AVE (Continued) **U003391824**

Site Id:	8119
Affiliation Type:	Emergency Contact
Company Name:	881 REALTY LLC
Contact Type:	Not reported
Contact Name:	STEVEN FOX
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 941-1300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-10

Site Id:	8119
Affiliation Type:	Facility Operator
Company Name:	881 WASHINGTON AVE
Contact Type:	Not reported
Contact Name:	BERT DUNCAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 622-6089
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-09

Site Id:	8119
Affiliation Type:	Facility Owner
Company Name:	881 REALTY LLC
Contact Type:	MANAGING AGENT
Contact Name:	STEVEN FOX
Address1:	PO BOX 660010
Address2:	Not reported
City:	FRESH MEADOWS
State:	NY
Zip Code:	11366
Country Code:	001
Phone:	(718) 941-1300
EMail:	MANAGEMENT@JLMREALTYCORP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-09-05

Site Id:	8119
Affiliation Type:	Mail Contact
Company Name:	JLM REALTY CORP.
Contact Type:	Not reported
Contact Name:	STEVEN FOX
Address1:	P.O. BOX 660010

881 WASHINGTON AVE (Continued) **U003391824**

Address2:	Not reported
City:	FRESH MEADOWS
State:	NY
Zip Code:	11366
Country Code:	001
Phone:	(718) 941-1300
EMail:	MANAGEMENT@JLMREALTYCORP.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-09-11

Tank Info:

Tank Number:	001
Tank Id:	22353
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K00 - Spill Prevention - None
	I04 - Overfill - Product Level Gauge (A/G)
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1926
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

V187 **MEDGAR EVERS COLLEGE** **NY UST** **U004063525**
ENE **123 CROWN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.217 mi.
1147 ft. **Site 9 of 11 in cluster V**

Relative:
Higher

Actual:
107 ft.

UST:

Name:	MEDGAR EVERS COLLEGE
Address:	123 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-610277 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588159.42957
UTM Y:	4502285.34391
Site Type:	School

Affiliation Records:

Site Id:	366893
Affiliation Type:	Facility Owner
Company Name:	DORMITORY AUTHORITY - NYS
Contact Type:	PROJECT MANAGER
Contact Name:	EUGENE LEUNG, R.A.
Address1:	515 BROADWAY
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12207
Country Code:	001
Phone:	(718) 774-2897
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-07-12

Site Id:	366893
Affiliation Type:	Mail Contact
Company Name:	DORMITORY AUTHORITY - NYS
Contact Type:	Not reported
Contact Name:	EUGENE LEUNG, R.A.
Address1:	OFFICE OF ENVIRONMENTAL AFFAIRS
Address2:	ONE PENN PLAZA, 52ND FL
City:	NEW YORK
State:	NY
Zip Code:	10119
Country Code:	001
Phone:	(212) 273-5109
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-07-12

Site Id:	366893
Affiliation Type:	Facility Operator
Company Name:	MEDGAR EVERS COLLEGE
Contact Type:	Not reported
Contact Name:	EUGENE LEUNG
Address1:	Not reported

MEDGAR EVERS COLLEGE (Continued) **U004063525**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 774-2897
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-07-12

Site Id:	366893
Affiliation Type:	Emergency Contact
Company Name:	DORMITORY AUTHORITY - NYS
Contact Type:	Not reported
Contact Name:	EUGENE LEUNG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 879-1574
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-07-12

Tank Info:

Tank Number:	1
Tank ID:	212631
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	07/06/2006
Date Tank Closed:	07/06/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground

MEDGAR EVERS COLLEGE (Continued) **U004063525**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
D10 - Pipe Type - Copper

Tank Number: 2
Tank ID: 212632
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 07/06/2006
Date Tank Closed: 07/06/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 3
Tank ID: 212633
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: 07/06/2006
Date Tank Closed: 07/06/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None

MEDGAR EVERS COLLEGE (Continued) **U004063525**

I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

V188 **VACANT LOT** **NY LTANKS** **S108059433**
ENE **123 CROWN ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.217 mi.
1147 ft. **Site 10 of 11 in cluster V**

Relative: **Higher**
Actual: **107 ft.**

LTANKS:

Name:	VACANT LOT
Address:	123 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0603818 / 2006-07-28
Facility ID:	0603818
Site ID:	366641
Spill Date:	2006-07-06
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-07-06
CID:	406
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2006-07-06
Spill Record Last Update:	2006-08-01
Spiller Name:	MICHAEL COSTACHE
Spiller Company:	DORMOITORY AUTHORITY
Spiller Address:	123 CROWN ST.
Spiller County:	001
Spiller Contact:	PETER BERGER
Spiller Phone:	(646) 602-5850
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	316688
DEC Memo:	"07/07/06-Hiralkumar Patel. Left message for Mr. Burger. Received call from Mr. Burger. he took soil samples from UST excavation pit and from hydraulic lift area. he will get lab result probably by July 20, 2006. tank was on concrete pad and Mr. Burger hasn't noticed any oil stains on pad. he took side wall samples from excavation pit. he found highest 89 ppm reading in excavation pit samples. 07/28/06-Hiralkumar Patel. received message from Mr. Burger. spoke with Mr. Burger and asked to email lab analyticals. received lab analyticals in email. sample shows very little SVOC contamination. based on available information, case closed."

VACANT LOT (Continued) **S108059433**

Remarks: "Caller removed a UST from the location. Soil samples have not been completed yet. No staining observed, Found low PID readings and noticeable gasoline odor at the location. Tank has been out of service for estimated 30yrs. Unknown if groundwater was affected. Caller will be contacting us once the lab results have come in. *** Caller had removed some hydraulic lifts from the site also and found staining around those. *** No further potential for a spill."

All Materials:

Site ID:	366641
Operable Unit ID:	1124575
Operable Unit:	01
Material ID:	2114073
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	366641
Operable Unit ID:	1124575
Operable Unit:	01
Material ID:	2114072
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

X189 **CON EDISON** **PA MANIFEST** **S125059334**
SSW **504 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 12225**
0.217 mi.
1148 ft. **Site 7 of 12 in cluster X**

Relative: **Lower**

Actual: **69 ft.**

Manifest Details:

Year:	2018
Manifest Number:	011096749FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYP005187988
Generator Date:	02/20/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA

CON EDISON (Continued) **S125059334**

Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

T190 **CON EDISON - SERVICE BOX 47222** **NY MANIFEST** **S120958397**
South **1120 WASHINGTON AVE** **N/A**
1/8-1/4 **BROOLYN, NY 11235**
0.219 mi.
1154 ft. **Site 4 of 7 in cluster T**

Relative:
Lower

Actual:
73 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 47222
Address:	1120 WASHINGTON AVE
City,State,Zip:	BROOLYN, NY 11235
Country:	USA
EPA ID:	NYP004934640
Facility Status:	Not reported
Location Address 1:	1120 WASHINGTON AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOLYN
Location State:	NY
Location Zip:	11235
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004934640
Mailing Name:	CON EDISON - SERVICE BOX 47222
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

T191 **CON EDISON SERVICE BOX: 47222** **RCRA NonGen / NLR** **1016966680**
South **1120 WASHINGTON AVE** **NY MANIFEST** **NYP004395265**
1/8-1/4 **BROOKLYN, NY 11225**
0.219 mi.
1154 ft. **Site 5 of 7 in cluster T**

Relative: **Lower**

Actual: **73 ft.**

RCRA Listings:

Date Form Received by Agency:		20131220
Handler Name:	CON EDISON SERVICE BOX:	47222
Handler Address:		1120 WASHINGTON AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004395265
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON SERVICE BOX: 47222 (Continued) **1016966680**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131120
Handler Name: CON EDISON SERVICE BOX:	47222
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131220
Handler Name: CON EDISON SERVICE BOX:	47222
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 47222 (Continued) **1016966680**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 1120 WASHINGTON AVE
City,State,Zip: BROOKLYN, NY 11225
Country: USA
EPA ID: NYP004395265
Facility Status: Not reported
Location Address 1: 1120 WASHINGTON AVE
Code: BP
Location Address 2: SB 47222
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004395265
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/20/2013
Trans1 Recv Date: 11/20/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/21/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004395265

CON EDISON SERVICE BOX: 47222 (Continued) **1016966680**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299207GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z192 **CON EDISON** **NY MANIFEST** **S117535503**
NE **989 CARROLL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.219 mi.
1158 ft. **Site 1 of 2 in cluster Z**

Relative: **Higher**

Actual: **118 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	989 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004662615
Facility Status:	Not reported
Location Address 1:	989 CARROLL ST
Code:	BP
Location Address 2:	SB22684
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

CON EDISON (Continued) **S117535503**

NY MANIFEST:

EPAID:	NYP004662615
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	09/22/2014
Trans1 Recv Date:	09/22/2014
Trans2 Recv Date:	09/30/2014
TSD Site Recv Date:	09/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004662615
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617539GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117535503**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T193 **CON EDISON SERVICE BOX: 47233** **RCRA NonGen / NLR** **1017778881**
South **1123 WASHINGTON AVE** **NYP004568382**
1/8-1/4 **BROOKLYN, NY 11225**
0.220 mi.
1159 ft. **Site 6 of 7 in cluster T**

Relative: **Lower**

Actual: **72 ft.**

RCRA Listings:

Date Form Received by Agency:		20140718
Handler Name:	CON EDISON SERVICE BOX:	47233
Handler Address:		1123 WASHINGTON AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004568382
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON SERVICE BOX: 47233 (Continued) **1017778881**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140618
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140618
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 47233 (Continued) **1017778881**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140718
Handler Name: CON EDISON SERVICE BOX:	47233
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T194 **CON EDISON** **NY MANIFEST** **S117064358**
South **1123 WASHINGTON AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.220 mi.
1159 ft. **Site 7 of 7 in cluster T**

Relative: **Lower**

Actual: **72 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	1123 WASHINGTON AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004568382
Facility Status:	Not reported
Location Address 1:	1123 WASHINGTON AVE
Code:	BP
Location Address 2:	STRUCTURE 47233
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:
EPAID: NYP004568382

CON EDISON (Continued) **S117064358**

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/18/2014
Trans1 Recv Date:	06/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004568382
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502581GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117064358**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Y195 **CLARA BARTON HIGH SCHOOL** **NY LTANKS** **S118953450**
North **925 CARROLL ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.223 mi.
1176 ft. **Site 2 of 2 in cluster Y**

Relative:
Higher

Actual:
129 ft.

LTANKS:

Name:	CLARA BARTON HIGH SCHOOL
Address:	925 CARROLL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012946 / 2004-06-09
Facility ID:	0012946
Site ID:	115013
Spill Date:	2001-03-09
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2001-03-09
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-09
Spill Record Last Update:	2004-10-14
Spiller Name:	JEFF BRADY
Spiller Company:	NYC SCHOOL DISTRICT
Spiller Address:	901 CLASSON AVE
Spiller County:	001
Spiller Contact:	JEFF BRADY
Spiller Phone:	(718) 243-1843
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	267502
DEC Memo:	"10/14/2004 Case was closed out in June 2004 under the address of 901 Classon Ave, Brooklyn. School Construction Authority requested the address be changed to 925 Carroll St. This change was made. "
Remarks:	"DURING ROUTINE CLEANING OF TANK AT ABOVE LOCATION A HOLE HAS BEEN DISCOVERED. TANK TO BE DRAINED AND FURTHER EVALUATION TO BE DONE. TANK IS A 20,000 GALLON UNDERGROUND UNIT."

All Materials:

Site ID:	115013
Operable Unit ID:	834878
Operable Unit:	01
Material ID:	539665
Material Code:	0003A

CLARA BARTON HIGH SCHOOL (Continued) **S118953450**

Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Z196 **991 CARROLL STREET** **NY UST U004076541**
NE **991 CARROLL STREET** **NY AST N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.223 mi.
1177 ft. **Site 2 of 2 in cluster Z**

Relative:
Higher

Actual:
118 ft.

UST:

Name:	991 CARROLL STREET
Address:	991 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-187267 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/26/2023
UTM X:	588110.23595
UTM Y:	4502409.21682
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5597
Affiliation Type:	Facility Operator
Company Name:	991 CARROLL STREET
Contact Type:	Not reported
Contact Name:	AMOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 529-0504
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-01-02

Site Id:	5597
Affiliation Type:	Emergency Contact
Company Name:	991 CARROLL LLC
Contact Type:	Not reported
Contact Name:	ED L JESJANIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 418-0363 3021

991 CARROLL STREET (Continued) **U004076541**

EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2014-01-02

Site Id: 5597
Affiliation Type: Mail Contact
Company Name: 991 CARROLL ST LLC
Contact Type: Not reported
Contact Name: MEIR BOUSKILA
Address1: PO BOX 1920
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10119
Country Code: 001
Phone: (212) 564-2111
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2014-01-02

Site Id: 5597
Affiliation Type: Facility Owner
Company Name: 991 CARROLL LLC
Contact Type: AGENT
Contact Name: ISAK RADONCIC
Address1: PO BOX 1920
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10119
Country Code: 001
Phone: (212) 564-2111
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2018-05-08

Tank Info:

Tank Number: 01
Tank ID: 23490
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: 03/24/2006
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 05/20/2005
Next Test Date: Not reported

991 CARROLL STREET (Continued) **U004076541**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)

AST:

Name: 991 CARROLL STREET
Address: 991 CARROLL STREET
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-187267
Program Type: PBS
UTM X: 588110.23595
UTM Y: 4502409.21682
Expiration Date: 06/26/2023
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 5597
Affiliation Type: Facility Operator
Company Name: 991 CARROLL STREET
Contact Type: Not reported
Contact Name: AMOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 529-0504
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2014-01-02

Site Id: 5597
Affiliation Type: Emergency Contact
Company Name: 991 CARROLL LLC
Contact Type: Not reported
Contact Name: ED L JESJANIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported

991 CARROLL STREET (Continued) **U004076541**

Country Code:	999
Phone:	(917) 418-0363 3021
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-01-02

Site Id:	5597
Affiliation Type:	Mail Contact
Company Name:	991 CARROLL ST LLC
Contact Type:	Not reported
Contact Name:	MEIR BOUSKILA
Address1:	PO BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10119
Country Code:	001
Phone:	(212) 564-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-01-02

Site Id:	5597
Affiliation Type:	Facility Owner
Company Name:	991 CARROLL LLC
Contact Type:	AGENT
Contact Name:	ISAK RADONCIC
Address1:	PO BOX 1920
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10119
Country Code:	001
Phone:	(212) 564-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-05-08

Tank Info:

Tank Number:	02
Tank Id:	211579
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None

991 CARROLL STREET (Continued) **U004076541**

F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Galvanized Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/24/2006
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

W197 **45 OCEAN LLC** **NY AST** **A100157511**
SSW **45 OCEAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.224 mi.
1182 ft. **Site 7 of 9 in cluster W**

Relative: **Lower**
Actual: **76 ft.**

AST:

Name:	45 OCEAN LLC
Address:	45 OCEAN AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-219738
Program Type:	PBS
UTM X:	587670.28009
UTM Y:	4501745.02091
Expiration Date:	01/07/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8435
Affiliation Type:	Facility Operator
Company Name:	45 OCEAN LLC
Contact Type:	Not reported
Contact Name:	RAMON CESPEDER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 479-6162
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL

45 OCEAN LLC (Continued) **A100157511**

Date Last Modified: 2021-07-08

Site Id: 8435
Affiliation Type: Emergency Contact
Company Name: IMK MANAGEMENT LLC
Contact Type: Not reported
Contact Name: ISAAC HEIMOVITS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 972-4460
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2021-07-08

Site Id: 8435
Affiliation Type: Facility Owner
Company Name: 45 OCEAN LLC
Contact Type: MANAGING AGENT
Contact Name: ISAAC HEIMOVITS
Address1: 1522 41ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11218
Country Code: 001
Phone: (718) 972-0141
EMail: IMKMANAGEMENTLLC@GMAIL.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2021-07-08

Site Id: 8435
Affiliation Type: Mail Contact
Company Name: IMK MANAGEMENT LLC
Contact Type: MANAGING AGENT
Contact Name: ISAAC HEIMOVITS
Address1: 1522 41ST STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11218
Country Code: 001
Phone: (718) 972-4460
EMail: IMKMANAGEMENTLLC@GMAIL.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2021-07-08

Tank Info:

Tank Number: 002
Tank Id: 24140

45 OCEAN LLC (Continued) **A100157511**

Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
C00 - Pipe Location - No Piping
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1920
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

S198 **883 FRANKLIN LLC, C/O CHESNUT HOLDINGS** **NY AST** **U003387092**
NNE **883 FRANKLIN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.225 mi.
1188 ft. **Site 10 of 12 in cluster S**

Relative: **Higher**
Actual: **117 ft.**

AST:

Name:	883 FRANKLIN LLC, C/O CHESNUT HOLDINGS
Address:	883 FRANKLIN AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-091669
Program Type:	PBS
UTM X:	588017.49972
UTM Y:	4502467.20085
Expiration Date:	05/04/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2314
Affiliation Type:	Emergency Contact
Company Name:	883 FRANKLIN LLC, C/O CHESNUT HOLDINGS OF NY INC
Contact Type:	Not reported

883 FRANKLIN LLC, C/O CHESNUT HOLDINGS (Continued) **U003387092**

Contact Name:	SEFIK GUNES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 543-8200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-07-05

Site Id:	2314
Affiliation Type:	Facility Owner
Company Name:	883 FRANKLIN LLC
Contact Type:	DIRECTOR OF FIELD OPERATIONS
Contact Name:	SEFIK GUNES
Address1:	5676 RIVERDALE AVENUE, SUITE 307
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10471
Country Code:	001
Phone:	(718) 543-8200
EMail:	MGARGLY@CHESNUTHOLDINGS.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-03-10

Site Id:	2314
Affiliation Type:	Facility Operator
Company Name:	883 FRANKLIN LLC, C/O CHESNUT HOLDINGS
Contact Type:	Not reported
Contact Name:	ROHAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 543-8200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-03-11

Site Id:	2314
Affiliation Type:	Mail Contact
Company Name:	883 FRANKLIN LLC, C/O CHESNUT HOLDINGS OF NY INC
Contact Type:	DIRECTOR OF FIELD OPERATIONS
Contact Name:	SEFIK GUNES
Address1:	5676 RIVERDALE AVENUE, SUITE 307
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10471

883 FRANKLIN LLC, C/O CHESNUT HOLDINGS (Continued) **U003387092**

Country Code:	001
Phone:	(718) 543-8200
EMail:	MGARGLY@CHESNUTHOLDINGS.COM
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-07-05

Tank Info:

Tank Number:	01
Tank Id:	11253
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/06/1975
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

X199 **BP SERVICE STATION #35046** **NY UST** **U001838951**
South **513 FLATBUSH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.227 mi.
1199 ft. **Site 8 of 12 in cluster X**

Relative: **Lower**
Actual: **72 ft.**

UST:

Name:	BP SERVICE STATION # 35046
Address:	513 FLATBUSH AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-480835 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2

BP SERVICE STATION #35046 (Continued) **U001838951**

Expiration Date: 11/16/2024
UTM X: 587797.88016
UTM Y: 4501722.08056
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 21473
Affiliation Type: Facility Operator
Company Name: BP SERVICE STATION # 35046
Contact Type: Not reported
Contact Name: XUBING CHEN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 284-8349
EMail: Not reported
Fax Number: Not reported
Modified By: MXLAY
Date Last Modified: 2016-08-18

Site Id: 21473
Affiliation Type: Emergency Contact
Company Name: 513 FLATBUSH REALTY CORP
Contact Type: Not reported
Contact Name: JOHN MAHONEY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (973) 392-6150
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-17

Site Id: 21473
Affiliation Type: Mail Contact
Company Name: BP PRODUCTS NORTH AMERICA INC.
Contact Type: RETAIL COMPLIANCE COORDINATOR
Contact Name: JESSICA VISLOCKY
Address1: PO BOX 6038
Address2: Not reported
City: ARTESIA
State: CA
Zip Code: 90702
Country Code: 001
Phone: (718) 781-2693
EMail: JESSICA.VISLOCKY@BP.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2020-07-23

Site Id: 21473

BP SERVICE STATION #35046 (Continued) **U001838951**

Affiliation Type:	Facility Owner
Company Name:	513 FLATBUSH REALTY CORP
Contact Type:	RETAIL COMPLIANCE COORDINATOR
Contact Name:	JOHN MAHONEY
Address1:	2449 EAST 74TH ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11234
Country Code:	001
Phone:	(732) 864-0778
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-17

Tank Info:

Tank Number:	001
Tank ID:	27925
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1986
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	27926
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1986
Date Tank Closed:	10/01/1992

BP SERVICE STATION #35046 (Continued) **U001838951**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 003
Tank ID: 27927
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1986
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
H99 - Tank Leak Detection - Other
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank ID:	27928
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1986
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
I00 - Overfill - None
F02 - Pipe External Protection - Original Sacrificial Anode
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	005
Tank ID:	39092
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	09/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B02 - Tank External Protection - Original Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)

BP SERVICE STATION #35046 (Continued) **U001838951**

F02 - Pipe External Protection - Original Sacrificial Anode
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	005
Tank ID:	27929
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	08/01/1979
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
F07 - Pipe External Protection - Retrofitted Sacrificial Anode

Tank Number:	006
Tank ID:	43550
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

BP SERVICE STATION #35046 (Continued) **U001838951**

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	007
Tank ID:	43551
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I00 - Overfill - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	008
Tank ID:	43552
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported

BP SERVICE STATION #35046 (Continued) **U001838951**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 009
Tank ID: 43553
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1976
Date Tank Closed: 05/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 01
Tank ID: 39088
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/23/2016
Registered: True
Tank Location: Underground

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 10/25/2015
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 010
Tank ID: 43554
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1976
Date Tank Closed: 05/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank Number:	011
Tank ID:	43555
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	012
Tank ID:	43556
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

BP SERVICE STATION #35046 (Continued) **U001838951**

A00 - Tank Internal Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	013
Tank ID:	43557
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	014
Tank ID:	43558
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

BP SERVICE STATION #35046 (Continued) **U001838951**

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	015
Tank ID:	43559
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	016
Tank ID:	43560
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

BP SERVICE STATION #35046 (Continued) **U001838951**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 017
Tank ID: 43561
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1976
Date Tank Closed: 05/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 02
Tank ID: 39089
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/23/2016

BP SERVICE STATION #35046 (Continued) **U001838951**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	10/08/2014
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None

Tank Number:	03
Tank ID:	39090
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1986
Date Tank Closed:	11/23/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	10/08/2014
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron

BP SERVICE STATION #35046 (Continued) **U001838951**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 04
Tank ID: 39091
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/23/2016
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 06/25/2015
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None

Tank Number: 05
Tank ID: 267059
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 12000
Install Date: 01/05/2017
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Tightness Test Method: -
Date Test: Not reported

BP SERVICE STATION #35046 (Continued) **U001838951**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass

Tank Number: 06
Tank ID: 267061
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 01/05/2017
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank Number:	07
Tank ID:	268349
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	250
Install Date:	Not reported
Date Tank Closed:	12/21/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Affiliation Records:

Site Id:	16286
Affiliation Type:	Facility Operator
Company Name:	BP SERVICE STATION #35046
Contact Type:	Not reported
Contact Name:	XUBING CHEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-05-18

Site Id:	16286
Affiliation Type:	Emergency Contact
Company Name:	513 FLATBUSH REALTY CORP.
Contact Type:	Not reported
Contact Name:	JOHN MAHONEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported

BP SERVICE STATION #35046 (Continued) **U001838951**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(973) 392-6150
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-17

Site Id:	16286
Affiliation Type:	Mail Contact
Company Name:	BP PRODUCTS NORTH AMERICA, INC.
Contact Type:	RETAIL COMPLIANCE COORDINATOR
Contact Name:	JOHN MAHONEY
Address1:	P.O. BOX 6038
Address2:	Not reported
City:	ARTESIA
State:	CA
Zip Code:	90702
Country Code:	001
Phone:	(973) 392-6150
EMail:	JOHN.MAHONEY@BP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-17

Site Id:	16286
Affiliation Type:	Facility Owner
Company Name:	513 FLATBUSH REALTY CORP.
Contact Type:	RETAIL COMPLIANCE COORDINATOR
Contact Name:	JOHN MAHONEY
Address1:	2449 EAST 74TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11234
Country Code:	001
Phone:	(718) 444-3990
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-17

Tank Info:

Tank Number:	001
Tank ID:	27925
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	12/01/1986
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

BP SERVICE STATION #35046 (Continued) **U001838951**

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 27926
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1986
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 003
Tank ID: 27927
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1986
Date Tank Closed: 10/01/1992

BP SERVICE STATION #35046 (Continued) **U001838951**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
H99 - Tank Leak Detection - Other
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 27928
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 12/01/1986
Date Tank Closed: 10/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
I00 - Overfill - None
F02 - Pipe External Protection - Original Sacrificial Anode
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 005

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank ID:	39092
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	09/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B02 - Tank External Protection - Original Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
F02 - Pipe External Protection - Original Sacrificial Anode
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	005
Tank ID:	27929
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	08/01/1979
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None

BP SERVICE STATION #35046 (Continued) **U001838951**

C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
F07 - Pipe External Protection - Retrofitted Sacrificial Anode

Tank Number: 006
Tank ID: 43550
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1976
Date Tank Closed: 05/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 43551
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1976
Date Tank Closed: 05/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

BP SERVICE STATION #35046 (Continued) **U001838951**

I00 - Overfill - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 43552
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1976
Date Tank Closed: 05/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 009
Tank ID: 43553
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1976
Date Tank Closed: 05/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported

BP SERVICE STATION #35046 (Continued) **U001838951**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 01
Tank ID: 39088
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/23/2016
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 10/25/2015
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 010
Tank ID: 43554
Tank Status: Closed - Removed
Material Name: Closed - Removed

BP SERVICE STATION #35046 (Continued) **U001838951**

Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

Tank Number:	011
Tank ID:	43555
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank Number:	012
Tank ID:	43556
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	013
Tank ID:	43557
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None

BP SERVICE STATION #35046 (Continued) **U001838951**

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	014
Tank ID:	43558
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	015
Tank ID:	43559
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

BP SERVICE STATION #35046 (Continued) **U001838951**

Equipment Records:

H99 - Tank Leak Detection - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	016
Tank ID:	43560
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
H99 - Tank Leak Detection - Other
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	017
Tank ID:	43561
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1976
Date Tank Closed:	05/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

BP SERVICE STATION #35046 (Continued) **U001838951**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 02
Tank ID: 39089
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1986
Date Tank Closed: 11/23/2016
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 10/08/2014
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None

Tank Number: 03
Tank ID: 39090

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1986
Date Tank Closed:	11/23/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	10/08/2014
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	04
Tank ID:	39091
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1986
Date Tank Closed:	11/23/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	06/25/2015
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
I02 - Overfill - High Level Alarm

BP SERVICE STATION #35046 (Continued) **U001838951**

K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None

Tank Number:	05
Tank ID:	267059
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	01/05/2017
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass

Tank Number:	06
Tank ID:	267061
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	01/05/2017
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

BP SERVICE STATION #35046 (Continued) **U001838951**

Tank Type: Equivalent technology
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 07
Tank ID: 268349
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 250
Install Date: Not reported
Date Tank Closed: 12/21/2016
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

X200 **BP PRODUCTS NORTH AMERICA INC - BP 35046** **NJ MANIFEST** **S120665570**
South **513 FLATBUSH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.227 mi.
1199 ft. **Site 9 of 12 in cluster X**

Relative:
Lower

Actual:
72 ft.

NJ MANIFEST:

EPA Id:	NYD987002870
Mail Address:	PO BOX 6038
Mail City/State/Zip:	RANCHO SANTA MARGARITA, CA 92688
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	MARK OKAMOTO
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	012238155JJK
EPA ID:	NYD987002870
Date Shipped:	10/21/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

BP PRODUCTS NORTH AMERICA INC - BP 35046 (Continued) **S120665570**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	RANCHO SANTA MARGARITA, CA 92688
Reason Load Was Rejected:	Not reported

X201 **BP PRODUCTS NORTH AMERICA INC - BP 35046** **RCRA-SQG** **1004572220**
South **513 FLATBUSH AVE** **NY MANIFEST** **NYD987002870**
1/8-1/4 **BROOKLYN, NY 11225**
0.227 mi.
1199 ft. **Site 10 of 12 in cluster X**

Relative: **Lower**
Actual: **72 ft.**

RCRA Listings:

Date Form Received by Agency:	20141106
Handler Name:	BP PRODUCTS NORTH AMERICA INC - BP 35046
Handler Address:	513 FLATBUSH AVE
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYD987002870
Contact Name:	MARK OKAMOTO
Contact Address:	PO BOX 6038
Contact City,State,Zip:	ARTESIA, CA 90702
Contact Telephone:	732-743-0901
Contact Fax:	732-743-0834
Contact Email:	MARK.OKAMOTO@BP.COM
Contact Title:	ENVIRONMENTAL COMPLIANCE SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	PO BOX 6038
Mailing City,State,Zip:	RANCHO SANTA MARGARITA, CA 92688
Owner Name:	BP PRODUCTS NORTH AMERICA INC
Owner Type:	Private
Operator Name:	BP PRODUCTS NORTH AMERICA INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported

BP PRODUCTS NORTH AMERICA INC - BP 35046 (Continued) **1004572220**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20141204
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOHAMMAD ASHRAF	
Legal Status:	Private
Date Became Current:	20061130

BP PRODUCTS NORTH AMERICA INC - BP 35046 (Continued) **1004572220**

Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	513 FLATBUSH REALTY CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	6201 AVE U
Owner/Operator City,State,Zip:	BROOKLYN, NY 11234
Owner/Operator Telephone:	718-856-9385
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BP NORTH AMERICA INC
Legal Status:	Private
Date Became Current:	19930910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BP PRODUCTS NORTH AMERICA INC
Legal Status:	Private
Date Became Current:	19701113
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 6038
Owner/Operator City,State,Zip:	ARTESIA, CA 90702
Owner/Operator Telephone:	732-743-0834
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BP NORTH AMERICA INC
Legal Status:	Private
Date Became Current:	19930910
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 3011
Owner/Operator City,State,Zip:	NAPERVILLE, IL 60566
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

BP PRODUCTS NORTH AMERICA INC - BP 35046 (Continued) **1004572220**

Owner/Operator Name: GAD GASOLINE INC
Legal Status: Private
Date Became Current: 20090915
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BP PRODUCTS NORTH AMERICA INC
Legal Status: Private
Date Became Current: 19701113
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: LESBOS SERVICE CENTER INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080414
Handler Name: YASMIN ENTERPRISE INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920511
Handler Name: LESBOS SERVICE CENTER INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

BP PRODUCTS NORTH AMERICA INC - BP 35046 (Continued) **1004572220**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080415
Handler Name: YASMIN ENTERPRISE INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091008
Handler Name: GAD GASOLINE INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141106
Handler Name: BP PRODUCTS NORTH AMERICA INC - BP 35046
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44711
NAICS Description: GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

BP PRODUCTS NORTH AMERICA INC - BP 35046 (Continued) **1004572220**

NY MANIFEST:

Name:	BP PRODUCTS NORTH AMERICA INC - BP 35046
Address:	513 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYD987002870
Facility Status:	Not reported
Location Address 1:	513 FLATBUSH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11225
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987002870
Mailing Name:	BP PRODUCTS NORTH AMERICA INC - BP 35046
Mailing Contact:	BP PRODUCTS NORTH AMERICA INC - BP 35046
Mailing Address 1:	PO BOX 80249
Mailing Address 2:	Not reported
Mailing City:	RANCHO SANTA MARGARITA
Mailing State:	CA
Mailing Zip:	92688
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9494605200

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR000023036
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2014
Trans1 Recv Date:	12/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987002870
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	012238062JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

BP PRODUCTS NORTH AMERICA INC - BP 35046 (Continued) **1004572220**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	168
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X202 **CON EDISON** **NY MANIFEST** **S117066420**
SSW **510 FLAT BUSH AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.227 mi.
1200 ft. **Site 11 of 12 in cluster X**

Relative:
Lower

Actual:
69 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	510 FLAT BUSH AV
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004590709
Facility Status:	Not reported
Location Address 1:	510 FLAT BUSH AV
Code:	BP
Location Address 2:	SB26712
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004590709
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117066420**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2014
Trans1 Recv Date:	07/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004590709
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504147GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA203 **1040 CARROLL ST HDFC CORP** **NY AST** **A100291238**
NE **1040 CARROLL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.229 mi.
1207 ft. **Site 1 of 2 in cluster AA**

Relative:
Higher

Actual:
115 ft.

AST:

Name:	1040 CARROLL ST HDFC CORP
Address:	1040 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608664
Program Type:	PBS
UTM X:	588192.91590
UTM Y:	4502362.27667
Expiration Date:	03/26/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30516
Affiliation Type:	Facility Operator
Company Name:	1040 CARROLL ST HDFC
Contact Type:	Not reported
Contact Name:	RICHARD REYES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 360-6185
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-10-09

Site Id:	30516
Affiliation Type:	Emergency Contact
Company Name:	1040 CARROLL ST HDFC C/O MANAS PROPERTY GROUP
Contact Type:	Not reported
Contact Name:	TOMMY MAMOUNAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 609-8348
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-10-09

Site Id:	30516
Affiliation Type:	Mail Contact
Company Name:	MANAS PROPERTY GROUP
Contact Type:	Not reported
Contact Name:	TOMMY MAMOUNAS

1040 CARROLL ST HDFC CORP (Continued) **A100291238**

Address1:	509 B 39TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(347) 294-0152
EMail:	OFFICE@MANASNY.COM
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-10-09

Site Id:	30516
Affiliation Type:	Facility Owner
Company Name:	1040 CARROLL ST HDFC C/O MANAS PROPERTY GROUP
Contact Type:	PROPERTY MANAGER
Contact Name:	TOMMY MAMOUNAS
Address1:	509 B 39TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(347) 294-0152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-10-09

Tank Info:

Tank Number:	001
Tank Id:	65467
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
D02 - Pipe Type - Galvanized Steel
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B00 - Tank External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
A02 - Tank Internal Protection - Rubber Liner

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1984
Capacity Gallons:	5000

1040 CARROLL ST HDFC CORP (Continued) **A100291238**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

S204 **GARDEN CLEANERS** **RCRA-VSQG** **1001202892**
NNE **879 FRANKLYN AVE** **ICIS** **NYR000041517**
1/8-1/4 **BROOKLYN, NY 11225** **US AIRS**
0.231 mi. **NY MANIFEST**
1220 ft. **Site 11 of 12 in cluster S**

Relative: **Higher**
Actual: **118 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	GARDEN CLEANERS	
Handler Address:		879 FRANKLYN AVE
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYR000041517
Contact Name:		Not reported
Contact Address:		FRANKLYN AVE
Contact City,State,Zip:		BROOKLYN, NY 11225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		FRANKLYN AVE
Mailing City,State,Zip:		BROOKLYN, NY 11225
Owner Name:	NERYS R BAEZ	
Owner Type:		Private
Operator Name:	NERYS R BAEZ	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

GARDEN CLEANERS (Continued) **1001202892**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

GARDEN CLEANERS (Continued) **1001202892**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NERYS R BAEZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111-50 CORONA
Owner/Operator City,State,Zip:	QUEENS, NY 11368
Owner/Operator Telephone:	718-760-4413
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NERYS R BAEZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111-50 CORONA
Owner/Operator City,State,Zip:	QUEENS, NY 11368
Owner/Operator Telephone:	718-760-4413
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NERYS R BAEZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	111-50 CORONA
Owner/Operator City,State,Zip:	QUEENS, NY 11368
Owner/Operator Telephone:	718-760-4413
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990714
Handler Name: GARDEN CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: GARDEN CLEANERS	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

GARDEN CLEANERS (Continued) **1001202892**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GARDEN CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970624
Handler Name: GARDEN CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: NY000A0000261040132100311
FRS ID: 110004535343
Action Name: NEW GARDEN CLEANER 36047R292200311
Facility Name: NEW GARDEN CLEANER
Facility Address: 879 FRANKLIN AVE
BROOKLYN, NY 112251304
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal

GARDEN CLEANERS (Continued) **1001202892**

EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.668657
Longitude in Decimal Degrees:	-73.958673
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610401321
Facility NAICS Code:	812320
Tribal Land Code:	Not reported
Enforcement Action ID:	NY000A0000261040132100305
FRS ID:	110004535343
Action Name:	NEW GARDEN CLEANER 36047R292200305
Facility Name:	NEW GARDEN CLEANER
Facility Address:	879 FRANKLIN AVE
	BROOKLYN, NY 112251304
Enforcement Action Type:	Administrative Order
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.668657
Longitude in Decimal Degrees:	-73.958673
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610401321
Facility NAICS Code:	812320
Tribal Land Code:	Not reported
Enforcement Action ID:	NY000A0000261040132100301
FRS ID:	110004535343
Action Name:	NEW GARDEN CLEANER 36047R292200301
Facility Name:	NEW GARDEN CLEANER
Facility Address:	879 FRANKLIN AVE
	BROOKLYN, NY 112251304
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.668657
Longitude in Decimal Degrees:	-73.958673
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610401321
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1001202892
Region Code:	02
Programmatic ID:	AIR NY0000002610401321
Facility Registry ID:	110004535343
D and B Number:	Not reported

GARDEN CLEANERS (Continued) **1001202892**

Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610401321
Facility Registry ID: 110004535343
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-08-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401321
Facility Registry ID: 110004535343
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-12-01 00:00:00
Activity Status Date: 2003-12-01 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002610401321
Facility Registry ID: 110004535343
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-08-28 00:00:00
Activity Status Date: 2003-08-28 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610401321
Facility Registry ID: 110004535343
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-05-12 00:00:00
Activity Status Date: 2005-05-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610401321

GARDEN CLEANERS (Continued) **1001202892**

Facility Registry ID: 110004535343
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-08-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401321
Facility Registry ID: 110004535343
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-12-01 00:00:00
Activity Status Date: 2003-12-01 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002610401321
Facility Registry ID: 110004535343
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-08-28 00:00:00
Activity Status Date: 2003-08-28 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

NY MANIFEST:
Name: GARDEN CLEANERS
Address: 879 FRANKLYN AVE
City,State,Zip: BROOKLYN, NY 11225
Country: USA
EPA ID: NYR000041517
Facility Status: Not reported
Location Address 1: 879 FRANKLYN AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11225
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000041517
Mailing Name: GARDEN CLEANERS
Mailing Contact: NERYS BAEZ
Mailing Address 1: 879 FRANKLYN AVE
Mailing Address 2: Not reported

GARDEN CLEANERS (Continued) **1001202892**

Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187740827

S205 **NEW GARDEN CLEANER** **NY DRYCLEANERS** **S110247427**
NNE **879 FRANKLIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.231 mi.
1220 ft. **Site 12 of 12 in cluster S**

Relative:
Higher

Actual:
118 ft.

DRYCLEANERS:

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2003-12-17 07:10:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2003-12-17 07:10:00
Install Date:	Not reported
Expiration Date:	09/08/2017
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2015-12-17 12:00:00
Install Date:	Not reported
Expiration Date:	09/08/2017
Removal Date:	Not reported

NEW GARDEN CLEANER (Continued) **S110247427**

Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2015-12-17 12:00:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2014-12-11 08:15:00
Install Date:	Not reported
Expiration Date:	09/08/2017
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2014-12-11 08:15:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321

NEW GARDEN CLEANER (Continued) **S110247427**

Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2006-02-28 11:07:39
Inspection Date: 2013-12-12 09:30:00
Install Date: Not reported
Expiration Date: 09/08/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2003-12-08 14:15:29
Inspection Date: 2013-12-12 09:30:00
Install Date: Not reported
Expiration Date: 02/01/2006
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2006-02-28 11:07:39
Inspection Date: 2012-12-12 09:40:00
Install Date: Not reported
Expiration Date: 09/08/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2003-12-08 14:15:29
Inspection Date: 2012-12-12 09:40:00
Install Date: Not reported
Expiration Date: 02/01/2006
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported

NEW GARDEN CLEANER (Continued) **S110247427**

Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2006-02-28 11:07:39
Inspection Date: 2011-12-15 10:00:00
Install Date: Not reported
Expiration Date: 09/08/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2003-12-08 14:15:29
Inspection Date: 2011-12-15 10:00:00
Install Date: Not reported
Expiration Date: 02/01/2006
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2006-02-28 11:07:39
Inspection Date: 2010-12-14 11:00:00
Install Date: Not reported
Expiration Date: 09/08/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported

NEW GARDEN CLEANER (Continued) **S110247427**

Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2004-12-20 14:00:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2004-12-20 14:00:00
Install Date:	Not reported
Expiration Date:	09/08/2017
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2005-12-12 09:00:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2005-12-12 09:00:00
Install Date:	Not reported
Expiration Date:	09/08/2017
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

NEW GARDEN CLEANER (Continued) **S110247427**

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2006-12-06 13:00:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2006-12-06 13:00:00
Install Date:	Not reported
Expiration Date:	09/08/2017
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2007-12-05 10:10:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2007-12-05 10:10:00
Install Date:	Not reported

NEW GARDEN CLEANER (Continued) **S110247427**

Expiration Date: 09/08/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2003-12-08 14:15:29
Inspection Date: 2008-12-08 09:15:00
Install Date: Not reported
Expiration Date: 02/01/2006
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2006-02-28 11:07:39
Inspection Date: 2008-12-08 09:15:00
Install Date: Not reported
Expiration Date: 09/08/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE
City,State,Zip: BROOKLYN, NY 11225 1304
Facility ID: 2-6104-01321
Phone Number: 7187740827
Region: Not reported
Registration Effective Date: 2003-12-08 14:15:29
Inspection Date: 2009-12-09 08:15:00
Install Date: Not reported
Expiration Date: 02/01/2006
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: NEW GARDEN CLEANER
Address: 879 FRANKLIN AVE

NEW GARDEN CLEANER (Continued) **S110247427**

City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2009-12-09 08:15:00
Install Date:	Not reported
Expiration Date:	09/08/2017
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2010-12-14 11:00:00
Install Date:	Not reported
Expiration Date:	02/01/2006
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

AB206 **CON EDISON** **NJ MANIFEST** **S120673762**
NNE **990 PRESIDENT ST & FRANKLIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11226**
0.233 mi.
1229 ft. **Site 1 of 6 in cluster AB**

Relative:
Higher

Actual:
116 ft.

NJ MANIFEST:

EPA Id:	NYP004805396
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619934GBF
EPA ID:	NYP004805396
Date Shipped:	7/10/2015

CON EDISON (Continued) **S120673762**

TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AB207 **CON EDISON** **NJ MANIFEST** **S120673761**
NNE **990 PRESIDENT ST & FRANKLIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11226**
0.233 mi.
1229 ft. **Site 2 of 6 in cluster AB**

Relative: **Higher**
Actual: **116 ft.**

NJ MANIFEST:

EPA Id:	NYP004805388
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported

CON EDISON (Continued) **S120673761**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619935GBF
EPA ID:	NYP004805388
Date Shipped:	7/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AB208 **CON EDISON** **RCRA NonGen / NLR** **1019905060**
NNE **990 PRESIDENT ST & FRANKLIN AVE** **NYP004805388**
1/8-1/4 **BROOKLYN, NY 11226**
0.233 mi.
1229 ft. **Site 3 of 6 in cluster AB**

Relative: **Higher**
Actual: **116 ft.**

RCRA Listings:

Date Form Received by Agency:		20150710
Handler Name:	CON EDISON	
Handler Address:		990 PRESIDENT ST & FRANKLIN AVE
Handler City,State,Zip:		BROOKLYN, NY 11226
EPA ID:		NYP004805388
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019905060**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150710
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150710
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019905060**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

V209 **150 CROWN STREET** **NY AST** **A100291510**
ENE **150 CROWN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.234 mi.
1233 ft. **Site 11 of 11 in cluster V**

Relative:
Higher

Actual:
104 ft.

AST:
Name: 150 CROWN STREET
Address: 150 CROWN STREET
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609096
Program Type: PBS
UTM X: 588263.72099
UTM Y: 4502255.63287
Expiration Date: 07/10/2023
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 30942
Affiliation Type: Facility Owner
Company Name: CROWN REALTY LLC
Contact Type: AGENT
Contact Name: MEIR BOUSKILA
Address1: 166 MONTAGUE STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 875-1552
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2019-08-14

Site Id: 30942
Affiliation Type: Mail Contact
Company Name: CROWN REALTY LLC
Contact Type: AGENT
Contact Name: MEIR BOUSKILA
Address1: 166 MONTAGUE STREET
Address2: Not reported

150 CROWN STREET (Continued) **A100291510**

City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 875-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2019-08-14

Site Id:	30942
Affiliation Type:	Facility Operator
Company Name:	150 CROWN STREET
Contact Type:	Not reported
Contact Name:	LOUIS MENJIVAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 948-1098
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30942
Affiliation Type:	Emergency Contact
Company Name:	CROWN REALTY LLC
Contact Type:	Not reported
Contact Name:	ARTHUR WIENER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 875-1552
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-09-03

Tank Info:

Tank Number:	01
Tank Id:	66376
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None

150 CROWN STREET (Continued) **A100291510**

F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/31/1930
Capacity Gallons:	7000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AC210 **100 LEFFERTS AVE** **NY AST** **A100291207**
SSE **100 LEFFERTS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.236 mi.
1246 ft. **Site 1 of 4 in cluster AC**

Relative: **Lower**
Actual: **69 ft.**

AST:

Name:	100 LEFFERTS AVE
Address:	100 LEFFERTS AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-206636
Program Type:	PBS
UTM X:	588086.70011
UTM Y:	4501733.21949
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	7292
Affiliation Type:	Facility Owner
Company Name:	DGB REALTY ASSOCIATES
Contact Type:	PARTNER, AGENT
Contact Name:	SOL KENIGSBERG
Address1:	1860 FLATBUSH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11210
Country Code:	001
Phone:	(718) 943-3201
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR

100 LEFFERTS AVE (Continued) **A100291207**

Date Last Modified: 2005-11-22

Site Id: 7292
Affiliation Type: Mail Contact
Company Name: DGB REALTY ASSOCIATES
Contact Type: PARTNER, AGENT
Contact Name: SOL KENIGSBERG
Address1: 1860 FLATBUSH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11210
Country Code: 001
Phone: (718) 943-3201
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-11-22

Site Id: 7292
Affiliation Type: Facility Operator
Company Name: 100 LEFFERTS AVE
Contact Type: Not reported
Contact Name: DGB REALTY ASSOCATES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 943-3200
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-11-22

Site Id: 7292
Affiliation Type: Emergency Contact
Company Name: DGB REALTY ASSOCIATES
Contact Type: Not reported
Contact Name: POSITIVE HEATING
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 629-4000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-11-22

Tank Info:

Tank Number: 002
Tank Id: 208992

100 LEFFERTS AVE (Continued) **A100291207**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/29/2005
Capacity Gallons: 1080
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

AC211 **100 LEFFERTS AVE** **NY UST** **U004076964**
SSE **100 LEFFERTS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.236 mi.
1246 ft. **Site 2 of 4 in cluster AC**

Relative: **Lower**
Actual: **69 ft.**

UST:
Name: 100 LEFFERTS AVE
Address: 100 LEFFERTS AVENUE
City,State,Zip: BROOKLYN, NY 11225
Id/Status: 2-206636 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 588086.70011
UTM Y: 4501733.21949
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 7292
Affiliation Type: Facility Owner
Company Name: DGB REALTY ASSOCIATES
Contact Type: PARTNER, AGENT
Contact Name: SOL KENIGSBERG
Address1: 1860 FLATBUSH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY

100 LEFFERTS AVE (Continued) **U004076964**

Zip Code:	11210
Country Code:	001
Phone:	(718) 943-3201
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-11-22

Site Id:	7292
Affiliation Type:	Mail Contact
Company Name:	DGB REALTY ASSOCIATES
Contact Type:	PARTNER, AGENT
Contact Name:	SOL KENIGSBERG
Address1:	1860 FLATBUSH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11210
Country Code:	001
Phone:	(718) 943-3201
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-11-22

Site Id:	7292
Affiliation Type:	Facility Operator
Company Name:	100 LEFFERTS AVE
Contact Type:	Not reported
Contact Name:	DGB REALTY ASSOCATES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 943-3200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-11-22

Site Id:	7292
Affiliation Type:	Emergency Contact
Company Name:	DGB REALTY ASSOCIATES
Contact Type:	Not reported
Contact Name:	POSITIVE HEATING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 629-4000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR

100 LEFFERTS AVE (Continued) **U004076964**

Date Last Modified: 2005-11-22

Tank Info:

Tank Number:	001
Tank ID:	9540
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	09/08/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	03/24/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination

W212 **J & L PROPERTIES** **NY AST** **U003392228**
SSW **55 OCEAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.236 mi.
1248 ft. **Site 8 of 9 in cluster W**

Relative: **Lower**
Actual: **76 ft.**

AST:

Name:	J & L PROPERTIES
Address:	55 OCEAN AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-219746
Program Type:	PBS
UTM X:	587672.73243
UTM Y:	4501727.21273
Expiration Date:	01/07/2023
Site Type:	Apartment Building/Office Building

J & L PROPERTIES (Continued) **U003392228**

Affiliation Records:

Site Id:	8436
Affiliation Type:	Facility Operator
Company Name:	J & L PROPERTIES
Contact Type:	Not reported
Contact Name:	RAMON CESPEDER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 972-0726
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-08-05

Site Id:	8436
Affiliation Type:	Emergency Contact
Company Name:	55 OCEAN, LLC
Contact Type:	Not reported
Contact Name:	ISAAC HEIMOVITS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 972-4460
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-08-05

Site Id:	8436
Affiliation Type:	Facility Owner
Company Name:	55 OCEAN, LLC
Contact Type:	MANAGING AGENT
Contact Name:	ISAAC HEIMOVITS
Address1:	1522 41ST STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11218
Country Code:	001
Phone:	(718) 972-0726
EMail:	IMKMANAGEMENTLLC@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-08-05

Site Id:	8436
Affiliation Type:	Mail Contact
Company Name:	IMKMANAGEMENT, LLC
Contact Type:	MANAGING AGENT
Contact Name:	ISAAC HEIMOVITS

J & L PROPERTIES (Continued) **U003392228**

Address1:	1522 41ST STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11218
Country Code:	001
Phone:	(718) 972-4460
EMail:	IMKMANAGEMENTLLC@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-08-05

Tank Info:

Tank Number:	001
Tank Id:	24141
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A99 - Tank Internal Protection - Other
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
C00 - Pipe Location - No Piping
H04 - Tank Leak Detection - Groundwater Well
D01 - Pipe Type - Steel/Carbon Steel/Iron
B99 - Tank External Protection - Other
J02 - Dispenser - Suction Dispenser
F99 - Pipe External Protection - Other

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1920
Capacity Gallons:	5000
Tightness Test Method:	34
Date Test:	01/11/2021
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

W213 **57-65 OCEAN AVE** **NY UST** **U004272263**
SSW **57-65 OCEAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.241 mi.
1270 ft. **Site 9 of 9 in cluster W**

Relative:
Lower

Actual:
76 ft.

UST:

Name:	57-65 OCEAN AVE
Address:	57-65 OCEAN AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-345431 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	05/18/2027
UTM X:	587664.32909
UTM Y:	4501717.63796
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	16849
Affiliation Type:	Mail Contact
Company Name:	A&E REAL ESTATE MANAGEMENT
Contact Type:	Not reported
Contact Name:	BRIAN GARLAND
Address1:	5 BRYANT PARK 31ST FLOOR
Address2:	6TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 721-5500
EMail:	BRIAN.GARLAND@AE-RE.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-18

Site Id:	16849
Affiliation Type:	Facility Operator
Company Name:	57-65 OCEAN AVE
Contact Type:	Not reported
Contact Name:	ALFRED CLARKE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 721-5500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-18

Site Id:	16849
Affiliation Type:	Emergency Contact
Company Name:	57-65 OCEAN AVENUE, LLC
Contact Type:	Not reported
Contact Name:	ALFRED CLARKE
Address1:	Not reported

57-65 OCEAN AVE (Continued) **U004272263**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 436-6683
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-18

Site Id:	16849
Affiliation Type:	Facility Owner
Company Name:	57-65 OCEAN AVENUE, LLC
Contact Type:	PROPERTY MANAGER
Contact Name:	BRIAN GARLAND
Address1:	5 BRYANT PARK 31ST FLOOR
Address2:	Not reported
City:	MANHATTAN
State:	NY
Zip Code:	10018
Country Code:	001
Phone:	(212) 721-5500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-05-18

Tank Info:

Tank Number:	001
Tank ID:	32779
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	01/01/2001
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	09/22/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

57-65 OCEAN AVE (Continued) **U004272263**

K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground

X214 **CON EDISON SERVICE BOX: 26713** **RCRA NonGen / NLR** **1016967299**
South **526 FLATBUSH AVE FRONT OF** **NY MANIFEST** **NYP004409173**
1/8-1/4 **BROOKLYN, NY 11225**
0.241 mi.
1271 ft. **Site 12 of 12 in cluster X**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:		20140119
Handler Name:	CON EDISON SERVICE BOX:	26713
Handler Address:		526 FLATBUSH AVE FRONT OF
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004409173
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

CON EDISON SERVICE BOX: 26713 (Continued) **1016967299**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131219
Handler Name: CON EDISON SERVICE BOX:	26713
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140119
Handler Name: CON EDISON SERVICE BOX:	26713
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 26713 (Continued) **1016967299**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	526 FLATBUSH AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004409173
Facility Status:	Not reported
Location Address 1:	526 FLATBUSH AVE
Code:	BP
Location Address 2:	SB 26713
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004409173
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON SERVICE BOX: 26713 (Continued) **1016967299**

Trans2 State ID:	Not reported
Generator Ship Date:	12/15/2013
Trans1 Recv Date:	12/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004409173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300756GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AD215 **MARINE EQUITIES 101, LLC** **NY UST** **U004138355**
South **101 LINCOLN ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.241 mi.
1273 ft. **Site 1 of 7 in cluster AD**

Relative: **Lower**
Actual: **72 ft.**

UST:

Name:	MARINE EQUITIES 101, LLC
Address:	101 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-603773 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2

MARINE EQUITIES 101, LLC (Continued) **U004138355**

Expiration Date: 08/10/2026
UTM X: 587924.45910
UTM Y: 4501658.79372
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 25676
Affiliation Type: Emergency Contact
Company Name: MARINE EQUITIES 101, LLC
Contact Type: Not reported
Contact Name: JAMES DEMETRIADES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 837-6904
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2016-07-27

Site Id: 25676
Affiliation Type: Mail Contact
Company Name: MARINE EQUITIES 101, LLC
Contact Type: Not reported
Contact Name: JAMES DEMETRIADES
Address1: P.O. BOX 423
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11209
Country Code: 001
Phone: (718) 439-1800
EMail: MARIA@MENDIANPROPERTIESLLC.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2016-07-27

Site Id: 25676
Affiliation Type: Facility Owner
Company Name: MARINE EQUITIES 101, LLC
Contact Type: MANAGING AGENT
Contact Name: MICHAEL NIAMONITAKIS
Address1: PO BOX 423
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11209
Country Code: 001
Phone: (718) 439-1800
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-06-18

Site Id: 25676

MARINE EQUITIES 101, LLC (Continued) **U004138355**

Affiliation Type:	Facility Operator
Company Name:	MARINE EQUITIES 101, LLC
Contact Type:	Not reported
Contact Name:	MICHAEL OQUENDO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 688-2161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-06-18

Tank Info:

Tank Number:	001
Tank ID:	55527
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	5000
Install Date:	04/11/1965
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	10/02/2017
Next Test Date:	10/02/2018
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J00 - Dispenser - None
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

AD216 **101 LINCOLN ROAD** **NY AST** **U003389696**
South **101 LINCOLN ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.241 mi.
1273 ft. **Site 2 of 7 in cluster AD**

Relative:
Lower

Actual:
72 ft.

AST:

Name:	101 LINCOLN ROAD
Address:	101 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-237310
Program Type:	PBS
UTM X:	588008.44485
UTM Y:	4501617.99096
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8838
Affiliation Type:	Facility Owner
Company Name:	FEDERAL HOME LOAN MORTGAGE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	17-22 WHITESTONE EXPRESSWAY
Address2:	Not reported
City:	WHITESTON
State:	NY
Zip Code:	11357
Country Code:	001
Phone:	(718) 352-3100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8838
Affiliation Type:	Mail Contact
Company Name:	FEDERAL HOME LOAN MORTGAGE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	17-22 WHITESTONE EXPRESSWAY
Address2:	Not reported
City:	WHITESTON
State:	NY
Zip Code:	11357
Country Code:	001
Phone:	(718) 352-3100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8838
Affiliation Type:	Facility Operator
Company Name:	101 LINCOLN ROAD
Contact Type:	Not reported
Contact Name:	GUSTAVO TERPIA

101 LINCOLN ROAD (Continued) **U003389696**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 940-2842
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8838
Affiliation Type:	Emergency Contact
Company Name:	FEDERAL HOME LOAN MORTGAGE
Contact Type:	Not reported
Contact Name:	RODNEY STEVENS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 925-9483
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	17265
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A01 - Tank Internal Protection - Epoxy Liner
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	C01 - Pipe Location - Aboveground
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	12/01/1945
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

101 LINCOLN ROAD (Continued) **U003389696**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AD217 **105 REALTY CO** **NY AST** **U003393479**
SSE **105 LINCOLN ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.245 mi.
1291 ft. **Site 3 of 7 in cluster AD**

Relative: **Lower**
Actual: **71 ft.**

AST:

Name:	105 REALTY CO
Address:	105 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-155543
Program Type:	PBS
UTM X:	587996.33399
UTM Y:	4501674.40463
Expiration Date:	01/07/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5045
Affiliation Type:	Facility Owner
Company Name:	105 REALTY CO
Contact Type:	AGENT
Contact Name:	DAVID HOCH
Address1:	1529 56TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 851-9384
EMail:	EMBASSY14@VERIZON.NET
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-11-14

Site Id:	5045
Affiliation Type:	Mail Contact
Company Name:	105 REALTY CO
Contact Type:	AGENT
Contact Name:	DAVID HOCH
Address1:	1529 56TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 851-9384
EMail:	EMBASSY14@VERIZON.NET
Fax Number:	Not reported
Modified By:	MFLEONAR

105 REALTY CO (Continued) **U003393479**

Date Last Modified: 2017-11-14

Site Id: 5045
Affiliation Type: Facility Operator
Company Name: 105 REALTY CO
Contact Type: Not reported
Contact Name: COLLINS BRUNO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 856-1445
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5045
Affiliation Type: Emergency Contact
Company Name: 105 REALTY CO
Contact Type: Not reported
Contact Name: DAVID HOCH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 851-9384
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-11-14

Tank Info:

Tank Number: 001
Tank Id: 28328
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H99 - Tank Leak Detection - Other
E02 - Piping Secondary Containment - Vault (with Access)
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
A01 - Tank Internal Protection - Epoxy Liner
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
F05 - Pipe External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser

105 REALTY CO (Continued) **U003393479**

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/1979
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AD218 **M & B LINCOLN REALTY CORP.** **NY AST** **A100294896**
South **57-73 LINCOLN ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.246 mi.
1298 ft. **Site 4 of 7 in cluster AD**

Relative:
Lower

Actual:
71 ft.

AST:

Name:	M & B LINCOLN REALTY CORP.
Address:	57-73 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-603914
Program Type:	PBS
UTM X:	587863.15454
UTM Y:	4501646.94106
Expiration Date:	01/27/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	25808
Affiliation Type:	Mail Contact
Company Name:	M & B LINCOLN REALTY CORP.
Contact Type:	Not reported
Contact Name:	ARON WIZNITZER
Address1:	5318 NEW UTRECHT AVE
Address2:	FLOOR 2
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 694-2541
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-10-08

Site Id:	25808
Affiliation Type:	Facility Operator
Company Name:	M & B LINCOLN REALTY CORP.
Contact Type:	Not reported

M & B LINCOLN REALTY CORP. (Continued) **A100294896**

Contact Name:	CRUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 287-7923
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKyer
Date Last Modified:	2004-03-17

Site Id:	25808
Affiliation Type:	Emergency Contact
Company Name:	M & B LINCOLN REALTY CORP.
Contact Type:	Not reported
Contact Name:	A. WIZNITZER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 694-2541
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-05-31

Site Id:	25808
Affiliation Type:	Facility Owner
Company Name:	M & B LINCOLN REALTY CORP.
Contact Type:	OFFICER
Contact Name:	ARON WIZNITZER
Address1:	5318 NEW UTRECHT AVE, FLOOR 2
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 694-2541
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-10-08

Tank Info:

Tank Number:	002
Tank Id:	206583
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None

M & B LINCOLN REALTY CORP. (Continued) **A100294896**

K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle
G02 - Tank Secondary Containment - Vault (w/access)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
H99 - Tank Leak Detection - Other
J05 - Dispenser - On Site Heating System (Supply/Return)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	C
Install Date:	03/24/2005
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AD219 **M & B LINCOLN REALTY CORP.** **NY UST** **U004078222**
South **57-73 LINCOLN ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.246 mi.
1298 ft. **Site 5 of 7 in cluster AD**

Relative:
Lower

Actual:
71 ft.

UST:

Name:	M & B LINCOLN REALTY CORP.
Address:	57-73 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-603914 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/27/2024
UTM X:	587863.15454
UTM Y:	4501646.94106
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	25808
Affiliation Type:	Mail Contact
Company Name:	M & B LINCOLN REALTY CORP.
Contact Type:	Not reported
Contact Name:	ARON WIZNITZER
Address1:	5318 NEW UTRECHT AVE
Address2:	FLOOR 2
City:	BROOKLYN

M & B LINCOLN REALTY CORP. (Continued) **U004078222**

State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 694-2541
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2019-10-08

Site Id: 25808
Affiliation Type: Facility Operator
Company Name: M & B LINCOLN REALTY CORP.
Contact Type: Not reported
Contact Name: CRUZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 287-7923
EMail: Not reported
Fax Number: Not reported
Modified By: KAKyer
Date Last Modified: 2004-03-17

Site Id: 25808
Affiliation Type: Emergency Contact
Company Name: M & B LINCOLN REALTY CORP.
Contact Type: Not reported
Contact Name: A. WIZNITZER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 694-2541
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-05-31

Site Id: 25808
Affiliation Type: Facility Owner
Company Name: M & B LINCOLN REALTY CORP.
Contact Type: OFFICER
Contact Name: ARON WIZNITZER
Address1: 5318 NEW UTRECHT AVE, FLOOR 2
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 694-2541
EMail: Not reported
Fax Number: Not reported

M & B LINCOLN REALTY CORP. (Continued) **U004078222**

Modified By: JSMACRI
Date Last Modified: 2019-10-08

Tank Info:

Tank Number: 001
Tank ID: 55986
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: 03/23/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

AB220 **FRANKLIN PRESIDENT ASSOC** **NY AST** **U003385642**
NNE **1000 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.247 mi.
1303 ft. **Site 4 of 6 in cluster AB**

Relative:
Higher

Actual:
122 ft.

AST:
Name: FRANKLIN PRESIDENT ASSOC
Address: 1000 PRESIDENT ST
City,State,Zip: BROOKLYN, NY 11225
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-154016
Program Type: PBS
UTM X: 587922.22511
UTM Y: 4502524.26413
Expiration Date: N/A
Site Type: Unknown

Affiliation Records:
Site Id: 4910

FRANKLIN PRESIDENT ASSOC (Continued) **U003385642**

Affiliation Type:	Facility Operator
Company Name:	FRANKLIN PRESIDENT ASSOC
Contact Type:	Not reported
Contact Name:	C JONES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 778-1280
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4910
Affiliation Type:	Facility Owner
Company Name:	N FRANKEL
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	32 COURT ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 855-0740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4910
Affiliation Type:	Mail Contact
Company Name:	N FRANKEL
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	32 COURT ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201
Country Code:	001
Phone:	(718) 855-0740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4910
Affiliation Type:	Emergency Contact
Company Name:	N FRANKEL
Contact Type:	Not reported
Contact Name:	WM L HIGGINS
Address1:	Not reported
Address2:	Not reported

FRANKLIN PRESIDENT ASSOC (Continued) **U003385642**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 287-5500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	40109
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AE221 **STRAUSS AUTO 122** **NY AST** **A100343922**
ESE **183-207 EMPIRE BOULEVARD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.247 mi.
1305 ft. **Site 1 of 4 in cluster AE**

Relative:
Lower

Actual:
71 ft.

AST:

Name:	STRAUSS AUTO 122
Address:	183-207 EMPIRE BOULEVARD
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-603867
Program Type:	PBS

STRAUSS AUTO 122 (Continued) **A100343922**

UTM X: 588242.26179
UTM Y: 4501944.17438
Expiration Date: 08/19/2014
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 25766
Affiliation Type: Emergency Contact
Company Name: STRAUSS DISCOUNT AUTO
Contact Type: Not reported
Contact Name: GREG SCHULTZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (732) 390-9000 5213
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-06-22

Site Id: 25766
Affiliation Type: Mail Contact
Company Name: STRAUSS DISCOUNT AUTO
Contact Type: Not reported
Contact Name: GREG SCHULTZ
Address1: 9A BRICK PLANT ROAD
Address2: Not reported
City: SOUTH RIVER
State: NJ
Zip Code: 08882
Country Code: 001
Phone: (732) 390-9000
EMail: GSCHULTZ@STRAUSSAUTO.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-08-19

Site Id: 25766
Affiliation Type: Facility Owner
Company Name: STRAUSS AUTO
Contact Type: Not reported
Contact Name: Not reported
Address1: 9A BRICK PLANT RD
Address2: Not reported
City: SOUTH RIVER
State: NJ
Zip Code: 08882
Country Code: 001
Phone: (732) 390-9000
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-05-12

Site Id: 25766

STRAUSS AUTO 122 (Continued) **A100343922**

Affiliation Type:	Facility Operator
Company Name:	STRAUSS DISCOUNT AUTO 122
Contact Type:	Not reported
Contact Name:	STORE MGR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 940-3431
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-08-19

Tank Info:

Tank Number:	122-1B
Tank Id:	230217
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

	J02 - Dispenser - Suction Dispenser E00 - Piping Secondary Containment - None C01 - Pipe Location - Aboveground D10 - Pipe Type - Copper I04 - Overfill - Product Level Gauge (A/G) F00 - Pipe External Protection - None A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground) H01 - Tank Leak Detection - Interstitial - Electronic Monitoring K01 - Spill Prevention - Catch Basin L00 - Piping Leak Detection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/13/2002
Capacity Gallons:	350
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil

Tank Number:	122-1W
Tank Id:	234312

STRAUSS AUTO 122 (Continued) **A100343922**

Material Code: 0015
Common Name of Substance: Motor Oil

Equipment Records:
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 04/01/2002
Capacity Gallons: 245
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: motor oil

AE222 **STRAUSS AUTO 122** **NY UST** **U003418637**
ESE **183-207 EMPIRE BOULEVARD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.247 mi.
1305 ft. **Site 2 of 4 in cluster AE**

Relative: **Lower**
Actual: **71 ft.**

UST:
Name: STRAUSS AUTO 122
Address: 183-207 EMPIRE BOULEVARD
City,State,Zip: BROOKLYN, NY 11225
Id/Status: 2-603867 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 08/19/2014
UTM X: 588242.26179
UTM Y: 4501944.17438
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 25766
Affiliation Type: Emergency Contact
Company Name: STRAUSS DISCOUNT AUTO
Contact Type: Not reported
Contact Name: GREG SCHULTZ

STRAUSS AUTO 122 (Continued) **U003418637**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(732) 390-9000 5213
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-06-22

Site Id:	25766
Affiliation Type:	Mail Contact
Company Name:	STRAUSS DISCOUNT AUTO
Contact Type:	Not reported
Contact Name:	GREG SCHULTZ
Address1:	9A BRICK PLANT ROAD
Address2:	Not reported
City:	SOUTH RIVER
State:	NJ
Zip Code:	08882
Country Code:	001
Phone:	(732) 390-9000
EMail:	GSCHULTZ@STRAUSSAUTO.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-08-19

Site Id:	25766
Affiliation Type:	Facility Owner
Company Name:	STRAUSS AUTO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	9A BRICK PLANT RD
Address2:	Not reported
City:	SOUTH RIVER
State:	NJ
Zip Code:	08882
Country Code:	001
Phone:	(732) 390-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-05-12

Site Id:	25766
Affiliation Type:	Facility Operator
Company Name:	STRAUSS DISCOUNT AUTO 122
Contact Type:	Not reported
Contact Name:	STORE MGR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

STRAUSS AUTO 122 (Continued) **U003418637**

Phone:	(718) 940-3431
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-08-19

Tank Info:

Tank Number:	001
Tank ID:	55809
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	550
Install Date:	05/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG
B02 - Tank External Protection - Original Sacrificial Anode
J03 - Dispenser - Gravity
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass

AE223 **R & S STRAUSS** **RCRA NonGen / NLR** **1000871306**
ESE **183-207 EMPIRE BLVD** **NY0000027433**
1/8-1/4 **BROOKLYN, NY 11225**
0.247 mi.
1305 ft. **Site 3 of 4 in cluster AE**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:	R & S STRAUSS	
Handler Address:		183-207 EMPIRE BLVD
Handler City,State,Zip:		BROOKLYN, NY 11225-3402
EPA ID:		NY0000027433
Contact Name:		Not reported
Contact Address:		BRICK PLANT RD
Contact City,State,Zip:		SOUTH RIVER, NY 08882

R & S STRAUSS (Continued) **1000871306**

Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BRICK PLANT RD
Mailing City,State,Zip:	SOUTH RIVER, NY 08882
Owner Name:	WATER BERCOVIK C/O STATEWIDE WINDOW
Owner Type:	Private
Operator Name:	WATER BERCOVIK C/O STATEWIDE WINDOW
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

R & S STRAUSS (Continued) **1000871306**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	X001
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WATER BERCOVIK C/O STATEWIDE WINDOW
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	400 RTE 59
Owner/Operator City,State,Zip:	MONSEY, NY 10952
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	WATER BERCOVIK C/O STATEWIDE WINDOW
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	400 RTE 59
Owner/Operator City,State,Zip:	MONSEY, NY 10952
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	WATER BERCOVIK C/O STATEWIDE WINDOW

R & S STRAUSS (Continued) **1000871306**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	400 RTE 59
Owner/Operator City,State,Zip:	MONSEY, NY 10952
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: R & S STRAUSS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: R & S STRAUSS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: R & S STRAUSS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19930728
Handler Name: R & S STRAUSS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

R & S STRAUSS (Continued) **1000871306**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AE224 **R & S STRAUSS** **RCRA NonGen / NLR** **1000872487**
ESE **183-207 EMPIRE BLVD** **FINDS** **NYD987037009**
1/8-1/4 **BROOKLYN, NY 11225** **ECHO**
0.247 mi.
1305 ft. **Site 4 of 4 in cluster AE**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:
Date Form Received by Agency: 20070101
Handler Name: R & S STRAUSS
Handler Address: 183 EMPIRE BLVD
Handler City,State,Zip: BROOKLYN, NY 11225-3402
EPA ID: NYD987037009
Contact Name: Not reported
Contact Address: EMPIRE BLVD
Contact City,State,Zip: BROOKLYN, NY 11225
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: EMPIRE BLVD
Mailing City,State,Zip: BROOKLYN, NY 11225
Owner Name: R & S STRAUSS ASSOCIATES
Owner Type: Private
Operator Name: R & S STRAUSS ASSOCIATES
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No

R & S STRAUSS (Continued) **1000872487**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

R & S STRAUSS (Continued) **1000872487**

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: R & S STRAUSS ASSOCIATES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9A BRICK PLANT RD
Owner/Operator City,State,Zip: SOUTH RIVER, NJ 08882
Owner/Operator Telephone: 201-686-8200
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: R & S STRAUSS ASSOCIATES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9A BRICK PLANT RD
Owner/Operator City,State,Zip: SOUTH RIVER, NJ 08882
Owner/Operator Telephone: 201-686-8200
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: R & S STRAUSS ASSOCIATES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9A BRICK PLANT RD
Owner/Operator City,State,Zip: SOUTH RIVER, NJ 08882
Owner/Operator Telephone: 201-686-8200
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: R & S STRAUSS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: R & S STRAUSS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No

R & S STRAUSS (Continued) **1000872487**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: R & S STRAUSS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930708
Handler Name: R & S STRAUSS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004506473

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

R & S STRAUSS (Continued) **1000872487**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000872487
Registry ID:	110004506473
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004506473
Name:	R & S STRAUSS
Address:	183-207 EMPIRE BLVD
City,State,Zip:	BROOKLYN, NY 11225

AF225 **1010 REALTY LLC** **NY AST** **U003394658**
NNE **1010 PRESIDENT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.248 mi.
1308 ft. **Site 1 of 3 in cluster AF**

Relative:
Higher

Actual:
120 ft.

AST:

Name:	1010 REALTY LLC
Address:	1010 PRESIDENT STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-467030
Program Type:	PBS
UTM X:	588044.78812
UTM Y:	4502503.62373
Expiration Date:	02/15/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	20296
Affiliation Type:	Facility Owner
Company Name:	1010 REALTY LLC
Contact Type:	MEMBER
Contact Name:	WOLF SICHERMAN
Address1:	1451 52ND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 851-4441
EMail:	SICHERMANMGMT@AOL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-12-07

Site Id:	20296
Affiliation Type:	Mail Contact
Company Name:	1010 REALTY LLC
Contact Type:	Not reported
Contact Name:	WOLF SICHERMAN
Address1:	1451 52ND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY

1010 REALTY LLC (Continued) **U003394658**

Zip Code:	11219
Country Code:	001
Phone:	(718) 851-4441
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-12-16

Site Id:	20296
Affiliation Type:	Facility Operator
Company Name:	1010 REALTY LLC
Contact Type:	Not reported
Contact Name:	ORLANDO FUNEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 807-1951
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-12-16

Site Id:	20296
Affiliation Type:	Emergency Contact
Company Name:	1010 REALTY LLC
Contact Type:	Not reported
Contact Name:	WOLF SICHERMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 851-4441
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	36973
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None

1010 REALTY LLC (Continued) **U003394658**

D01 - Pipe Type - Steel/Carbon Steel/Iron
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AD226 **MERIDIAN PROPERTIES** **NY LTANKS** **S108131237**
SSE **101 LINCOLN BLVD** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.248 mi.
1311 ft. **Site 6 of 7 in cluster AD**

Relative: **Lower**
Actual: **71 ft.**

LTANKS:

Name:	MERIDIAN PROPERTIES
Address:	101 LINCOLN BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0605577 / 2009-10-26
Facility ID:	0605577
Site ID:	368723
Spill Date:	2006-08-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	BKFALVEY
Referred To:	Not reported
Reported to Dept:	2006-08-14
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-14
Spill Record Last Update:	2009-10-26
Spiller Name:	MARIA GALANTE
Spiller Company:	MERIDIAN PROPERTIES
Spiller Address:	101 LINCOLN BLVD.
Spiller County:	001
Spiller Contact:	MARIA GALANTE
Spiller Phone:	(631) 321-4670

MERIDIAN PROPERTIES (Continued) **S108131237**

Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 318619
DEC Memo: "8/31/06 - ttf letter sent. bf 10/2/06 received response to ttf letter. Spill Report names Meridian Equities as spill location name. Letter is from Marine Equities 101, LLC, P.O. Box 411, Brooklyn. (718)439-1800. bf 10/4/06 called Marine Equities 101, LLC and requested they send a letter from 3rd party w/all info in #4 of 8/31/06 letter. Will do so, if any problems, will call me back. bf 10/5/06 Marine (Mike) called and left message to call back. bf 10/6/06 called Marine back to speak with Mike. Not in left message wtih secretary. bf 10/23/06 tank test received. tank passed. bf 10/30/06 spoke to Mike Niamonitakis (718)439-1800. I told him that tank test is not enough and he needs to have a letter sent explaining what happened and what was done to clean up. bf 11/17/06 received message from John Leddy of Pro Test. He will send a letter regarding the spill. He also said that no borings were done because they only work they did was what they were authorized to do and borings were not authorized. bf 11/21/06 Received message from M. Niamonitakis asking if I received a letter from Pro test. I called him back and left message with secretary that I did not receive it. bf 4/27/09 PBS inspection 4/24/09. NOV mailed today to: Michael Niamonitakis Meridian Equities 310 85th St. Brooklyn, NY 11209 AAdministrative settlement conference scheduled for 5/28/09. bf 5/20/09 Received fax from M. Niamonitakis. Letter from Pro Test states piping was cause of spill. Pipie under floor inside the building failed. This pipe was never removed nor were samples taken to determine extent of contamination. Called M. Niamonitakis and explained what's needed to be done to close the spill. Rescheduled settlement conference to 6/23/09 at 2:30 PM. bf 6/25/09 Called mr. Niamonitakis on 6/23/09. He said that he did not receive message for rescgheduled conference. Conference now scheduled for 7/7/09. Fax sent to him stating this. Received message and fax from John Leddy of Pro Test. Message requested that I call him back. Fax was sent requesting call. 2006 letter was included. Called him back and explained that the indoor portion of the piope failed and, to move forward, it needs to be determined whther there was a leak or not. bf 10/26/09 received letter from Robert Urban of Pro Test on 10/19/09. Letter was dated 8/18/09 and was received in Region 1 on 10/15/09. On 8/5-6/09, Pro test removed the piping under the floor and took 4 samples. Contaminants below the MDL except for two semi-volatiles detected: fluoranthene (170 ug/l) and phenanthrene (430 ug/l). NFA. bf"
Remarks: "DRY LEAK IN TANK, TANK HAS BEEN REPAIRED AND HAS PASSED TEST: DISCONNECTED REMOTE FILL LINE FROM TANK, RE-TESTED AND TANK PASSED: 8/08/2006"

All TTF:
Facility ID: 0605577
Spill Number: 0605577
Spill Tank Test: 1550196
Site ID: 368723
Tank Number: 001
Tank Size: 5000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported

MERIDIAN PROPERTIES (Continued) **S108131237**

Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	368723
Operable Unit ID:	1126589
Operable Unit:	01
Material ID:	2116129
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AG227 **APT BUILDING - TTF** **NY LTANKS** **U001839504**
SSW **65 OCEAN AVE** **NY LEAD** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.248 mi.
1312 ft. **Site 1 of 2 in cluster AG**

Relative:
Lower

Actual:
75 ft.

LTANKS:

Name:	APT BUILDING - TTF
Address:	65 OCEAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1209277 / 2016-09-08
Facility ID:	1209277
Site ID:	472341
Spill Date:	2012-11-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2012-11-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-05
Spill Record Last Update:	2016-09-08
Spiller Name:	CHRISTOPHER STEELE
Spiller Company:	PROPERTY OWNER
Spiller Address:	65 OCEAN AVE

APT BUILDING - TTF (Continued) **U001839504**

Spiller County:	999
Spiller Contact:	ADAM FISHER
Spiller Phone:	9142603061
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	426599
DEC Memo:	"4/19/13 - Austin - Recieved call from an individual at Castle Realty, who wanted to know how to follow up on this spill. She indicated that she received correspondence from a third party contractor not hired by her company, indicating that DEC fines would be imposed if this matter was not resolved (note to DeMeo: please follow up on this ands get a copy of this letter to see who is threatening DEC penalties). Spill assigned to DEC DeMeo, who was listed as Runner for the date this spil came into DEC - end 9/8/16 TJD File review. PTC is no longer in business, however, as part of operations shutdown DEC DeMeo requested information regarding open spills called into hotline by PTC without any further documentation provided. In 8/11/16 letter report regarding this site, PTC provided the passing test report associated with 5K gallon UST installed in 2001. Report states that it is unknown to PTC who called the failing tank test report into hotline - review of records indicate Christopher Steele of PTC made the initial report. As per report, PTC plugged gauge line and tank passed tightness test. Notifier's remarks indicate PBS #2-258024 has been administratively closed - review of records indicate that there were duplicate PBS registrations for this site. The active PBS registration is 2-345431. Based upon the documentation available the reported spill was associated with a dry leak discovered during a failed tank test. A passing test was conducted at this site approximately 1 month after initial report. No further action is required. All documentation has been uploaded to DECDOCS. Spill closed."
Remarks:	"PBS info stated administrative closed. Failed Tank Test, dry leak. Tank has apx 3000g in it now."

All Materials:

Site ID:	472341
Operable Unit ID:	1222200
Operable Unit:	01
Material ID:	2220889
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NYC LEAD:

Name:	Not reported
Address:	65 OCEAN AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	13525395
Building ID:	347767
Registration ID:	306056
Apartment:	6A

APT BUILDING - TTF (Continued) **U001839504**

Story:	6
Class:	Most Serious
Inspection Date:	12/27/2019
Approved Date:	12/31/2019
Original Certify By Date:	02/04/2020
Original Correct By Date:	01/30/2020
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6779488
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM SOUTH AT WEST WALL IN THE BATHROOM LOCATED AT APT 6A, 6th STORY, 3rd APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	01/02/2020
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	01/02/2020

AG228 **MOZAK REALTY CORP** **NY UST** **U004272240**
SSW **65 OCEAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11224**
0.248 mi.
1312 ft. **Site 2 of 2 in cluster AG**

Relative:
Lower

Actual:
75 ft.

UST:

Name:	MOZAK REALTY CORP
Address:	65 OCEAN AVENUE
City,State,Zip:	BROOKLYN, NY 11224
Id/Status:	2-258024 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	587689.61143
UTM Y:	4501697.94098
Site Type:	Unknown

Affiliation Records:

Site Id:	10668
Affiliation Type:	Facility Owner
Company Name:	WILLIAM D RUBIN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	205 SEABREEZE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11224
Country Code:	001
Phone:	(718) 996-5473
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

MOZAK REALTY CORP (Continued) **U004272240**

Site Id:	10668
Affiliation Type:	Mail Contact
Company Name:	WILLIAM D RUBIN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	205 SEABREEZE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11224
Country Code:	001
Phone:	(718) 996-5473
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	10668
Affiliation Type:	Facility Operator
Company Name:	MOZAK REALTY CORP
Contact Type:	Not reported
Contact Name:	MOKHTAR ZAKHARY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 996-5474
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	10668
Affiliation Type:	Emergency Contact
Company Name:	WILLIAM D RUBIN
Contact Type:	Not reported
Contact Name:	COLUMBIA UTILITIES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 851-6655
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	13255
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use

MOZAK REALTY CORP (Continued) **U004272240**

Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	03/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
G07 - Tank Secondary Containment - Excavation Liner
J02 - Dispenser - Suction Dispenser

AC229 **LEFFERTS GARDENS, LLC** **NY AST** **A100291314**
SSE **115 LINCOLN ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.249 mi.
1315 ft. **Site 3 of 4 in cluster AC**

Relative: **Lower**

Actual: **71 ft.**

AST:

Name:	LEFFERTS GARDENS, LLC
Address:	115 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-187119
Program Type:	PBS
UTM X:	588027.89342
UTM Y:	4501678.64273
Expiration Date:	09/28/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	5583
Affiliation Type:	Emergency Contact
Company Name:	LEFFERTS GARDENS, LLC
Contact Type:	Not reported
Contact Name:	MIKE TAKIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

LEFFERTS GARDENS, LLC (Continued) **A100291314**

Phone: (718) 439-1800
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 2006-12-04

Site Id: 5583
Affiliation Type: Facility Operator
Company Name: LEFFERTS GARDENS, LLC
Contact Type: Not reported
Contact Name: FRANK CHARLES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 297-2793
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-08-03

Site Id: 5583
Affiliation Type: Mail Contact
Company Name: LEFFERTS GARDENS, LLC
Contact Type: MANAGING MEMBER
Contact Name: MICHAEL NIAMONITAKIS
Address1: P.O. BOX 423
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11209
Country Code: 001
Phone: (718) 439-1800
EMail: MARIA@MERIDIANPROPERTIESLLC.COM
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-07-24

Site Id: 5583
Affiliation Type: Facility Owner
Company Name: LEFFERTS GARDENS, LLC
Contact Type: MANAGING MEMBER
Contact Name: MICHAEL NIAMONITAKIS
Address1: P.O. BOX 423
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11209
Country Code: 001
Phone: (718) 439-1800
EMail: MARIA@MERIDIANPROPERTIESLLC.COM
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-07-24

LEFFERTS GARDENS, LLC (Continued) **A100291314**

Tank Info:

Tank Number:	001
Tank Id:	23478
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1939
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AC230 **CON EDISON - LINCOLN ROAD** **PA MANIFEST** **S123093077**
SSE **115 LINCOLN ROAD** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.249 mi.
1315 ft. **Site 4 of 4 in cluster AC**

Relative:
Lower

Actual:
71 ft.

Manifest Details:

Year:	2017
Manifest Number:	009797549FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYP005033105
Generator Date:	02/14/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield

CON EDISON - LINCOLN ROAD (Continued) **S123093077**

TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AA231 **CONSOLIDATED EDISON** **NY MANIFEST** **1009242379**
NE **BEDFORD AVE & CARROLL ST 4794** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.249 mi.
1315 ft. **Site 2 of 2 in cluster AA**

Relative:
Higher

Actual:
117 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	BEDFORD AVE & CARROLL ST 4794
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004113213
Facility Status:	Not reported
Location Address 1:	BEDFORD AVE & CARROLL ST 4794
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004113213
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

AF232 **CON EDISON** **NY MANIFEST** **S116550871**
NNE **1016 PRESIDENT ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.250 mi.
1320 ft. **Site 2 of 3 in cluster AF**

Relative:
Higher

Actual:
122 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	1016 PRESIDENT ST
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYP004492963
Facility Status:	Not reported
Location Address 1:	1016 PRESIDENT ST
Code:	BP
Location Address 2:	SB 31712
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11213
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004492963
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/08/2014
Trans1 Recv Date:	04/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004492963
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406362GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116550871**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF233 **CON EDISON SERVICE BOX: 31712** **RCRA NonGen / NLR** **1017772340**
NNE **1016 PRESIDENT ST** **FINDS** **NYP004492963**
1/8-1/4 **BROOKLYN, NY 11225**
0.250 mi.
1320 ft. **Site 3 of 3 in cluster AF**

Relative: **Higher**
Actual: **122 ft.**

RCRA Listings:

Date Form Received by Agency:		20140508
Handler Name:	CON EDISON SERVICE BOX:	31712
Handler Address:		1016 PRESIDENT ST
Handler City,State,Zip:		BROOKLYN, NY 11225
EPA ID:		NYP004492963
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported

CON EDISON SERVICE BOX: 31712 (Continued) **1017772340**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 31712 (Continued) **1017772340**

Historic Generators:

Receive Date:		20140408
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140408
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140508
Handler Name:	CON EDISON SERVICE BOX:	31712
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		NY
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063771930

Click Here for FRS Facility Detail Report:

CON EDISON SERVICE BOX: 31712 (Continued) **1017772340**

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AB234 **990 PRESIDENT PARTNERS LLC** **NY AST** **A100175061**
NNE **990 PRESIDENT STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11225**
0.250 mi.
1320 ft. **Site 5 of 6 in cluster AB**

Relative:
Higher

Actual:
121 ft.

AST:

Name:	990 PRESIDENT PARTNERS LLC
Address:	990 PRESIDENT STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-196746
Program Type:	PBS
UTM X:	587962.33039
UTM Y:	4502527.36540
Expiration Date:	03/16/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	6430
Affiliation Type:	Facility Operator
Company Name:	990 PRESIDENT ST
Contact Type:	Not reported
Contact Name:	RAYFIELD HARRISON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(862) 242-4003
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-06-08

Site Id:	6430
Affiliation Type:	Facility Owner
Company Name:	990 PRESIDENT PARTNERS LLC
Contact Type:	MANAGER
Contact Name:	JONATHAN SAMET
Address1:	1360 EAST 14 STREET, ROOM 101
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11230

990 PRESIDENT PARTNERS LLC (Continued) **A100175061**

Country Code:	001
Phone:	(718) 972-1800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-03-27

Site Id:	6430
Affiliation Type:	Emergency Contact
Company Name:	990 PRESIDENT PARTNERS LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-03-27

Site Id:	6430
Affiliation Type:	Mail Contact
Company Name:	990 PRESIDENT PARTNERS LLC
Contact Type:	Not reported
Contact Name:	JONATHAN SAMET
Address1:	1360 EAST 14 STREET
Address2:	APT 101
City:	BROOKLYN
State:	NY
Zip Code:	11230
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-03-27

Tank Info:

Tank Number:	001
Tank Id:	27994
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
I04 - Overfill - Product Level Gauge (A/G)

990 PRESIDENT PARTNERS LLC (Continued) **A100175061**

C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
B05 - Tank External Protection - Jacketed

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1938
Capacity Gallons:	5000
Tightness Test Method:	34
Date Test:	01/15/2019
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AB235 **CON EDISON** **NY Spills** **S106866998**
NNE **990 PRESIDENT ST & FRANKLIN AV** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11226**
0.250 mi.
1320 ft. **Site 6 of 6 in cluster AB**

Relative:
Higher

Actual:
121 ft.

SPILLS:

Name:	SERVICE BOX 51711
Address:	990 PRESIDENT ST/FRANKLIN
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0412759 / 2005-06-22
Facility ID:	0412759
Facility Type:	ER
DER Facility ID:	273682
Site ID:	338344
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-03-05
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-03-06
CID:	74
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-06
Spill Record Last Update:	2005-06-22
Spiller Name:	Not reported
Spiller Company:	UNKNOWN

CON EDISON (Continued) **S106866998**

Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT DESK
DEC Memo: "157480. 05-MAR-2005 09:49 HRS. I&A DEPT.MECH-A D.BRINDISI EMP# 85877 : FOUND APPROX. 2 QTS OF UNKNOWN OIL ON APPROX. 30 GAL'S OF WATER. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. THE SPILL APPEARS TO BE CONTAINED. THERE IS NO FIRE INVOLVEMENT. NO SMOKE INVOLVEMENT. THERE WERE NO INJURIES RELATED TO THIS INCIDENT. THERE ARE NO INCLEMENT WEATHER CONDITIONS OR HAZARD THAT CONTRIBUTED TO THIS SPILL. NO PRIVATE PROPERTY AFFECTED. OWNER OF SUBSTANCES IS UNKNOWN. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENIVIR. TAG# 26012 PLACED. 1 LIQ. SAMPLE TAKEN FROM SPILL & MARKED PRIORITY E . 24 HR DEMINIMIS CHAIN OF CUSTODY# AA-16142. SAMPLE TO BE TAKEN TO ASTORIA CHEM. LAB N/P C.HOGAN 07511. Aroclor 1242 < 1.0 ppm EPA 608/8082 Aroclor 1254 < 1.0 ppm EPA 608/8082 Aroclor 1248 < 1.0 ppm EPA 608/8082 Aroclor 1260 < 1.0 ppm EPA 608/8082
========== UPDATE 3/6/05 00:45 HRS NO ACCESS DUE TO CAR ON STRUCTURE, INCIDENT TO BE TAKEN OFF CLOCK AS PER ENV SUPV B. BROWN. 15-MAR-2005 11:45 HRS. ENVIR. OPER. MECH-A R.VEGA EMP# 04005 REPORTS: DBL. WASHED STRUCTURE WITH BIO-GEN 760. REMOVED ALL DEBRIS WITH VACTOR. NO SUMP IN STRUCTURE, ENVIR. TAG# 26092 REMOVED. CLEANUP COMPLETE 100%"
Remarks: "2 quarts of unknown oil on 30 gallons of water. Cleanup pending removal of car over service box. Ref. 157480"

All Materials:
Site ID: 338344
Operable Unit ID: 1100293
Operable Unit: 01
Material ID: 580572
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Name: CON EDISON
Address: 990 PRESIDENT ST & FRANKLIN AV
City,State,Zip: BROOKLYN, NY 11226
Country: USA
EPA ID: NYP004805388
Facility Status: Not reported
Location Address 1: 990 PRESIDENT ST
Code: BP
Location Address 2: SB 51711
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

CON EDISON (Continued) **S106866998**

NY MANIFEST:

EPAID:	NYP004805388
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2015
Trans1 Recv Date:	07/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004805388
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619935GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S106866998**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Name: CON EDISON
Address: 990 PRESIDENT ST & FRANKLIN AV
City,State,Zip: BROOKLYN, NY 11226
Country: USA
EPA ID: NYP004805396
Facility Status: Not reported
Location Address 1: 993 PRESIDENT ST
Code: BP
Location Address 2: SB 31708
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004805396
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/10/2015
Trans1 Recv Date: 07/10/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/13/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004805396
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002619934GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N

CON EDISON (Continued) **S106866998**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AD236 **NY LTANKS** **S108957767**
South **64 LINCOLN ROAD** **NY LEAD** **N/A**
1/4-1/2 **BROOKLYN, NY 11225**
0.267 mi.
1409 ft. **Site 7 of 7 in cluster AD**

Relative: **Lower**

Actual: **69 ft.**

LTANKS:

Name:	PRIVATE HOME
Address:	64 LINCOLN RD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0708149 / 2010-06-10
Facility ID:	0708149
Site ID:	388993
Spill Date:	2007-10-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-10-25
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

(Continued) **S108957767**

Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-25
Spill Record Last Update:	2010-06-10
Spiller Name:	NEW YORK CITY MANAGMENT
Spiller Company:	PRIVATE HOME
Spiller Address:	64 LINCOLN RD
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	112
DEC Region:	2
DER Facility ID:	338551
DEC Memo:	"10/31/07 bf: Called 64 Lincoln LLC at 718-871-3400. They no longer manage the property and do not know who the new management company is. According to deed, owner is : Lincoln Five Realty LLC c/o Praedium Group LLC 825 Third Avenue New york, NY 10022 No phone number found in internet search for this company. Sent ttf to the above address. bf 5/22/2008 Sangesland found a new address for the property owner and sent a TTF 2nd notice letter. 5/27/08 received message from Bob of New York City Management (212)689-8833 ext. 8722. Tank was replaced. bf 5/28/08 Called Bob of NYC Management and left message to call me regarding the closure report for the spill and the need to update the registration certificate. bf. 4/19/10 bf: sent 2nd ttf to: Robert Jenny Lincoln Five Realty c/o NYC Management 381 Park Avenue South New York, NY 10016 6/9/10 Received call from Joe Ostrowski of Rite-Way tank on 6/4/10 and today. returned his call. Vent line failed and no release. He will get a letter to me confirming the same. bf 6/10/10 Received letter by fax from Joe Ostrowski. Tank failed because of vent. No contamination found. NFA. bf"
Remarks:	""

All TTF:

Facility ID:	0708149
Spill Number:	0708149
Spill Tank Test:	1815700
Site ID:	388993
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	99
Source:	03
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	388993
Operable Unit ID:	1146146
Operable Unit:	01

(Continued) **S108957767**

Material ID: 2136509
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

NYC LEAD:
Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11743136
Building ID: 326988
Registration ID: 301329
Apartment: 3J
Story: 3
Class: Most Serious
Inspection Date: 04/17/2017
Approved Date: 04/19/2017
Original Certify By Date: 05/23/2017
Original Correct By Date: 05/18/2017
New Certify By Date: 06/06/2017
New Correct By Date: 06/01/2017
Certified Date: 06/03/2017
Order Number: 617
NOV ID: 5732085
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) EAST WALL IN THE 2nd ROOM FROM EAST AT NORTH LOCATED AT APT 3J, 3rd STORY, 5th APARTMENT FROM WEST AT NORTH
NOV Issued Date: 04/20/2017
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 06/15/2017

Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11812922
Building ID: 326988
Registration ID: 301329
Apartment: 4E
Story: 4
Class: Most Serious
Inspection Date: 06/01/2017
Approved Date: 06/05/2017
Original Certify By Date: 07/09/2017
Original Correct By Date: 07/04/2017
New Certify By Date: 07/23/2017
New Correct By Date: 07/18/2017
Certified Date: 07/15/2017
Order Number: 617

(Continued) **S108957767**

NOV ID: 5768055
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, SOUTH WALL, EAST WALL, WEST WALL, 1st WINDOW FRAME FROM NORTH AT EAST WALL IN THE 1st ROOM FROM EAST LOCATED AT APT 4E, 4th STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date: 06/06/2017
Current Status ID: 22
Current Status: FIRST NO ACCESS TO RE- INSPECT VIOLATION
Current Status Date: 08/10/2017

Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11284306
Building ID: 326988
Registration ID: 301329
Apartment: 3J
Story: 3
Class: Most Serious
Inspection Date: 06/20/2016
Approved Date: 06/22/2016
Original Certify By Date: 07/26/2016
Original Correct By Date: 07/21/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: 07/22/2016
Order Number: 617
NOV ID: 5457890
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL IN THE 2nd ROOM FROM EAST AT NORTH LOCATED AT APT 3J, 3rd STORY, 5th APARTMENT FROM WEST AT NORTH
NOV Issued Date: 06/23/2016
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 07/28/2016

Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11284307
Building ID: 326988
Registration ID: 301329
Apartment: 3J
Story: 3
Class: Most Serious
Inspection Date: 06/20/2016
Approved Date: 06/22/2016
Original Certify By Date: 07/26/2016
Original Correct By Date: 07/21/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: 07/22/2016
Order Number: 616

(Continued) **S108957767**

NOV ID:	5457897
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DUMB WAITER FROM WEST AT NORTH WALL IN THE KITCHEN LOCATED AT APT 3J, 3rd STORY, 5th APARTMENT FROM WEST AT NORTH
NOV Issued Date:	06/23/2016
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	07/28/2016
Name:	Not reported
Address:	64 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11284308
Building ID:	326988
Registration ID:	301329
Apartment:	3J
Story:	3
Class:	Most Serious
Inspection Date:	06/20/2016
Approved Date:	06/22/2016
Original Certify By Date:	07/26/2016
Original Correct By Date:	07/21/2016
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	07/22/2016
Order Number:	617
NOV ID:	5457897
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, SOUTH WALL IN THE PRIVATE HALLWAY LOCATED AT APT 3J, 3rd STORY, 5th APARTMENT FROM WEST AT NORTH
NOV Issued Date:	06/23/2016
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	07/28/2016
Name:	Not reported
Address:	64 LINCOLN ROAD
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11284309
Building ID:	326988
Registration ID:	301329
Apartment:	3J
Story:	3
Class:	Most Serious
Inspection Date:	06/20/2016
Approved Date:	06/22/2016
Original Certify By Date:	07/26/2016
Original Correct By Date:	07/21/2016
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	07/22/2016
Order Number:	617
NOV ID:	5457897

(Continued) **S108957767**

NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) EAST WALL, WEST WALL IN THE FOYER LOCATED AT APT 3J, 3rd STORY, 5th APARTMENT FROM WEST AT NORTH
NOV Issued Date: 06/23/2016
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 07/28/2016

Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11812923
Building ID: 326988
Registration ID: 301329
Apartment: 4E
Story: 4
Class: Most Serious
Inspection Date: 06/01/2017
Approved Date: 06/05/2017
Original Certify By Date: 07/09/2017
Original Correct By Date: 07/04/2017
New Certify By Date: 07/23/2017
New Correct By Date: 07/18/2017
Certified Date: 07/15/2017
Order Number: 617
NOV ID: 5768058
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM NORTH AT EAST WALL DOOR FRAME, 1st DOOR FRAME FROM NORTH AT EAST WALL, NORTH WALL, SOUTH WALL, EAST WALL, WEST WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 3rd ROOM FROM EAST LOCATED AT APT 4E, 4th STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date: 06/06/2017
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 12/06/2017

Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11812924
Building ID: 326988
Registration ID: 301329
Apartment: 4E
Story: 4
Class: Most Serious
Inspection Date: 06/01/2017
Approved Date: 06/05/2017
Original Certify By Date: 07/09/2017
Original Correct By Date: 07/04/2017
New Certify By Date: 07/23/2017
New Correct By Date: 07/18/2017
Certified Date: 07/15/2017
Order Number: 617

(Continued) **S108957767**

NOV ID: 5768058
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL IN THE PRIVATE HALLWAY LOCATED AT APT 4E, 4th STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date: 06/06/2017
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 12/06/2017

Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11812926
Building ID: 326988
Registration ID: 301329
Apartment: 4E
Story: 4
Class: Most Serious
Inspection Date: 06/01/2017
Approved Date: 06/05/2017
Original Certify By Date: 07/09/2017
Original Correct By Date: 07/04/2017
New Certify By Date: 07/23/2017
New Correct By Date: 07/18/2017
Certified Date: 07/15/2017
Order Number: 617
NOV ID: 5768058
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL IN THE 1st ROOM FROM NORTH AT WEST LOCATED AT APT 4E, 4th STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date: 06/06/2017
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 12/06/2017

Name: Not reported
Address: 64 LINCOLN ROAD
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11812927
Building ID: 326988
Registration ID: 301329
Apartment: 4E
Story: 4
Class: Most Serious
Inspection Date: 06/01/2017
Approved Date: 06/05/2017
Original Certify By Date: 07/09/2017
Original Correct By Date: 07/04/2017
New Certify By Date: 07/23/2017
New Correct By Date: 07/18/2017
Certified Date: 07/15/2017
Order Number: 617
NOV ID: 5768058

(Continued) **S108957767**

NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM WEST AT NORTH WALL IN THE FOYER LOCATED AT APT 4E, 4th STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date: 06/06/2017
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 12/06/2017

---

237 North 1/4-1/2 0.278 mi. 1469 ft.

CLARA BARTON HIGH SCHOOL
CLASSON AVE AT PRESIDENT
BROOKLYN, NY

NY LTANKS **S102960526** **N/A**

Relative: Higher

Actual: 139 ft.

LTANKS:

Name:	CLARA BARTON HIGH SCHOOL
Address:	CLASSON AVE AT PRESIDENT
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712737 / 2003-03-03
Facility ID:	9712737
Site ID:	74434
Spill Date:	1998-02-13
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1998-02-13
CID:	322
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-13
Spill Record Last Update:	2003-03-03
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	HOWARD LEVY
Spiller Phone:	(718) 595-6700
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	69836
DEC Memo:	""
Remarks:	"tank at school overfilled - spill ran into street unk if any sewers are effected "

All Materials:

Site ID:	74434
Operable Unit ID:	1055600

CLARA BARTON HIGH SCHOOL (Continued) **S102960526**

Operable Unit:	01
Material ID:	569448
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

238 **MONTOUTE RESIDENCE** **NY LTANKS** **S104877530**
East **304 MONTGOMERY ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.281 mi.
1483 ft.

Relative: **Higher**

Actual: **93 ft.**

LTANKS:

Name:	MONTOUTE RESIDENCE
Address:	304 MONTGOMERY ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0010821 / 2003-12-11
Facility ID:	0010821
Site ID:	182019
Spill Date:	2000-12-29
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2000-12-29
CID:	390
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-29
Spill Record Last Update:	2003-12-11
Spiller Name:	RAY
Spiller Company:	PETRO OIL
Spiller Address:	48 HARVARD PARK DRIVE
Spiller County:	001
Spiller Contact:	VALERIE MONTOUTE
Spiller Phone:	(718) 282-4012
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	152604
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/11/03 TJD Tank overfilled. Most of product entered drain discharging to NYC sewer. DEP notified. Remained of product cleaned using absorbents. No further action required. Spill closed."
Remarks:	"driver overfilled tank - spilled to ground clean up will be done

MONTOUTE RESIDENCE (Continued) **S104877530**

tomorrow - unk how much entered sewer total delivered was 27 gallons"

All Materials:

Site ID:	182019
Operable Unit ID:	832848
Operable Unit:	01
Material ID:	544707
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

239
NNW
1/4-1/2
0.286 mi.
1509 ft.

BOARD OF EDUCATION **NY LTANKS** **S104621283**
901 CLASSON AVE **NY Spills** **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
141 ft.

LTANKS:

Name:	NYC PUBLIC SCHOOL
Address:	901 CLASSON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712739 / 1999-07-21
Facility ID:	9712739
Site ID:	175550
Spill Date:	1998-02-13
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1998-02-14
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-14
Spill Record Last Update:	2000-05-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MIKE BURKE
Spiller Phone:	(718) 855-3376
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	100236

BOARD OF EDUCATION (Continued) **S104621283**

DEC Memo: ""
Remarks: "CALLERS COMPANY HIRED TO CLEAN UP THE ABOVE SPILL - CALLER THOUGHT THE SCHOOL DISTRICT CALLED THE SPILL IN"

All Materials:
Site ID: 175550
Operable Unit ID: 1058955
Operable Unit: 01
Material ID: 327330
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 200.00
Units: G
Recovered: 200.00
Oxygenate: Not reported

SPILLS:
Name: BOARD OF EDUCATION
Address: 901 CLASSON AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0012493 / 2003-06-02
Facility ID: 0012493
Facility Type: ER
DER Facility ID: 100236
Site ID: 115012
DEC Region: 2
Spill Cause: Human Error
Spill Class: B3
SWIS: 2401
Spill Date: 2001-02-21
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2001-02-22
CID: 398
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-02-22
Spill Record Last Update: 2003-06-02
Spiller Name: Not reported
Spiller Company: BOARD OF EDUCATION
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ANTHONY LARA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO SAME AS 0012491. "
Remarks: "TRANSFERRING FUL FROM TANK 1 TO TANK 2. ENROUTE TO CLEAN UP PRODUCT. 917-335-0369 CELL FROM CALLER. WISHES A CALL BACK."

BOARD OF EDUCATION (Continued) **S104621283**

All Materials:

Site ID:	115012
Operable Unit ID:	834391
Operable Unit:	01
Material ID:	542757
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

240 SE 1/4-1/2 0.290 mi. 1530 ft.

RESIDENCE
150 LEFFERTS AVE
BROOKLYN, NY

NY LTANKS **S103559044**
N/A

Relative: Lower

Actual: 65 ft.

LTANKS:

Name:	RESIDENCE
Address:	150 LEFFERTS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9812318 / 1999-09-08
Facility ID:	9812318
Site ID:	227574
Spill Date:	1999-01-05
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1999-01-05
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-05
Spill Record Last Update:	1999-09-08
Spiller Name:	JOHN GOODWIN
Spiller Company:	MYSTIC TRANSPORT
Spiller Address:	1901 STEINWAY ST
Spiller County:	001
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	187821
DEC Memo:	""

RESIDENCE (Continued) **S103559044**

Remarks: "SPILL CREW IS ON SITE FOR CLEANUP."

All Materials:
Site ID: 227574
Operable Unit ID: 1072914
Operable Unit: 01
Material ID: 312597
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

AH241 **POLLOCK FILM INC** **NY LTANKS** **1001489074**
NE **1579 BEDFORD AVE-LOADING AREA** **RCRA NonGen / NLR** **NYR000070946**
1/4-1/2 **BROOKLYN, NY 11225** **NY MANIFEST**
0.298 mi.
1573 ft. **Site 1 of 2 in cluster AH**

Relative:
Higher

Actual:
126 ft.

LTANKS:
Name: 1579 BEDFORD AV/NYS/NAVAL
Address: 1579 BEDFORD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9109496 / 2003-03-07
Facility ID: 9109496
Site ID: 158643
Spill Date: 1991-12-05
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1991-12-06
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1991-12-11
Spill Record Last Update: 2003-03-07
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 134045

POLLOCK FILM INC (Continued) **1001489074**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 6/24/98 TRANSCRIBING NOTES FROM K.S.TANG FROM 12/6/91, 11:30 AM: CALL RICH, LEFT MESSAGE TO CALL BACK BET 3-4. TOLD HIM TO DISPOSE OF SOIL PROPERLY, SUBMIT POST-EXCAVATION SOIL SAMPLING RESULTS AND BILL OF LADING FOR THE SOIL. ALSO, SUBMIT THE PBS FORM. 03/07/2003-AUSTIN/ckc As per directive to close out spills with no recent history, close out."
Remarks: "2K TANKPULL; STOCKPILE, TEST, PICKUP & DISPOSE."

All Materials:
Site ID: 158643
Operable Unit ID: 963347
Operable Unit: 01
Material ID: 418110
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

RCRA Listings:
Date Form Received by Agency: 20070101
Handler Name: POLLOCK FILM INC
Handler Address: 1579 BEDFORD AVE-LOADING AREA
Handler City,State,Zip: BROOKLYN, NY 11225-1306
EPA ID: NYR000070946
Contact Name: THOMAS NOUSIAS
Contact Address: GREENWICH ST #7C
Contact City,State,Zip: NEW YORK, NY 10014
Contact Telephone: 212-604-0360
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: State
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: GREENWICH ST #7C
Mailing City,State,Zip: NEW YORK, NY 10014
Owner Name: DIVISION OF MILITARY & NAVAL AFFAIRS
Owner Type: State
Operator Name: DIVISION OF MILITARY & NAVAL AFFAIRS
Operator Type: State
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No

POLLOCK FILM INC (Continued) **1001489074**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

POLLOCK FILM INC (Continued) **1001489074**

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: DIVISION OF MILITARY & NAVAL AFFAIRS
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 330 OLD NISKAYUNA RD
Owner/Operator City,State,Zip: LATHAM, NY 12110
Owner/Operator Telephone: 518-786-4495
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DIVISION OF MILITARY & NAVAL AFFAIRS
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 330 OLD NISKAYUNA RD
Owner/Operator City,State,Zip: LATHAM, NY 12110
Owner/Operator Telephone: 518-786-4495
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DIVISION OF MILITARY & NAVAL AFFAIRS
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 330 OLD NISKAYUNA RD
Owner/Operator City,State,Zip: LATHAM, NY 12110
Owner/Operator Telephone: 518-786-4495
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: POLLOCK FILM INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: POLLOCK FILM INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No

POLLOCK FILM INC (Continued) **1001489074**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19990422
Handler Name: POLLOCK FILM INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type: Not reported	
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number: Not reported	
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported

POLLOCK FILM INC (Continued) **1001489074**

SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20110311
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	POLLOCK FILMS INC
Address:	1579 BEDFORD AVE-LOADING AREA
City,State,Zip:	BROOKLYN, NY 11225-1306
Country:	USA
EPA ID:	NYR000070946
Facility Status:	Not reported
Location Address 1:	1579 BEDFORD AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000070946
Mailing Name:	POLLOCK FILMS INC
Mailing Contact:	N/S
Mailing Address 1:	609 GREENWICH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10014
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189537441

AH242 **BEDFORD UNION ARMORY** **NY BROWNFIELDS** **S120706204**
NE **1555 BEDFORD AVENUE** **NY E DESIGNATION** **N/A**
1/4-1/2 **BROOKLYN, NY 11225**
0.339 mi.
1790 ft. **Site 2 of 2 in cluster AH**

Relative:
Higher

Actual:
133 ft.

BROWNFIELDS:

Name:	BEDFORD UNION ARMORY
Address:	1555 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Program:	BCP
Site Code:	540934
Acres:	2.805
HW Code:	C224252
SWIS:	2401
Town:	New York City
Record Added Date:	02/07/2017
Record Updated Date:	06/07/2021
Update By:	JHOCONNE
Site Description:	"Location: The site is located at 1555 Bedford Avenue in an urban area of the Crown Heights neighborhood of Brooklyn. It is identified on New York City tax maps as Block 1274, Lot 1. The site is bordered by Union Street to the north, multistory residential and mixed-use buildings followed by Rogers Avenue to the east, President Street to the south, and Bedford Avenue to the west. Site Features: The site is approximately 2.80 acres in size and is currently developed with a vacant three-story building, which contains a single story open drill hall; the head house, which previously contained sleeping quarters, showers, artillery ranges, stables, and kitchen and laundry areas; and the parking facility, which previously contained a vehicle maintenance shop and a battery charging room. The footprint of the building covers the entire site. Current Zoning and Land Use: The site is located in a R6 residential zone, and is currently vacant. The adjoining parcels are used for residential purposes, with the surrounding area generally consisting of residential, commercial, and institutional (schools and churches) use. Past Uses of the Site: The site was undeveloped before 1903. The original armory structure was built in 1903 with an expansion into the eastern portion of the parcel in the 1930s, which was converted to a parking facility in the 1960s. From about 1904 until 2013 the site was used as a military armory, including storage and maintenance of military vehicles and equipment, vehicle refueling, and artillery ranges located in the basement. Portions of the building had also been used for various film productions between 1991 and 2012. Site Geology and Hydrogeology: The site elevation is about 130 feet above sea level. The site is located in a developed area of Brooklyn that is generally covered with paved roads, walkways and buildings. The building is generally underlain by fill material used for construction and development since the 1800s. The subsurface strata beneath the site consists of historic fill material generally characterized by loose medium-to-coarse brown sand with varying amounts of silt, gravel, ash, and metal extending to depths of about 1 to 21 feet below grade surface (bgs). The historic fill material is underlain by native soil generally consisting of fine-to-coarse reddish brown sands with varying amounts of gravel and clay. Bedrock is anticipated to be at a depth of greater than 150 feet. Groundwater is present at a depth of approximately 130 feet below grade (about elevation 9.5 feet) and flows towards the northwest. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the

BEDFORD UNION ARMORY (Continued) **S120706204**

	primary contaminants of concern were volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) and metals including lead, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo[k]fluoranthene, chrysene, indeno(1,2,3-CD)pyrene, and tetrachloroethene (PCE). Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination remaining in soil and groundwater is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to prevent people from coming in contact with any residual contamination on the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-03-17 10:16:00
Record Upd:	2020-10-28 16:45:00
Updated By:	GWHEITZM
Own Op:	6
Sub Type:	P03
Owner Name:	Brandon Baron/John Valladales
Owner Company:	Bedford Courts LLC
Owner Address:	150 Myrtle Avenue, Suite 2
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bedford Branch
Owner Address:	496 Franklin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	1
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	City of New York
Owner Address:	One Centre Street, 17th Floor South
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10007
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 9
Owner Address:	890 Nostrand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11225
Owner Country:	United States of America
Own Op:	1
Sub Type:	E

BEDFORD UNION ARMORY (Continued) **S120706204**

Owner Name:	LEE WARSHAVSKY
Owner Company:	BEDFORD COURTS LOCAL DEVELOPMENT CORPORATION
Owner Address:	247 West 37th Street, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	BRandon Baron
Owner Company:	Bedford Courts I LLC
Owner Address:	150 Myrtle Avenue, Suite 2
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Brandon Baron
Owner Company:	Bedford Courts III LLC
Owner Address:	150 Myrtle Avenue, Suite 2
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Brandon Baron
Owner Company:	BEDFORD COURTS I LLC
Owner Address:	150 Myrtle Avenue, Suite 2
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Brandon Baron
Owner Company:	Bedford Courts III LIHTC LLC
Owner Address:	150 Myrtle Avenue, Suite 2
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Lee Warshavsky
Owner Company:	Bedford Courts III Housing Development Fund Corporation
Owner Address:	247 West 37th Street, 4th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	new york, NY 10018
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Lee Warshavsky
Owner Company:	Bedford Courts Local Development Corporation
Owner Address:	247 West 37th Street, 4th floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New york, NY 10018
Owner Country:	United States of America
HW Code:	C224252
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN

BEDFORD UNION ARMORY (Continued) **S120706204**

Waste Code:	Not reported
HW Code:	C224252
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	chloroform
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	carbon tetrachloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224252
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	9109496
Cross Ref Type Code:	03
Cross Ref Type:	ERP Site ID
Record Added Date:	2017-02-09 14:17:00
Record Updated:	2017-02-09 14:17:00
Updated By:	IXMUNTEA
Crossref ID:	8706242
Cross Ref Type Code:	03
Cross Ref Type:	ERP Site ID
Record Added Date:	2017-02-09 10:08:00
Record Updated:	2017-02-09 10:08:00
Updated By:	IXMUNTEA

BEDFORD UNION ARMORY (Continued) **S120706204**

Crossref ID:	NYR000070946
Cross Ref Type Code:	08
Cross Ref Type:	EPA Case No.
Record Added Date:	2017-02-09 10:03:00
Record Updated:	2017-02-09 10:03:00
Updated By:	IXMUNTEA
Crossref ID:	NYD981077829
Cross Ref Type Code:	08
Cross Ref Type:	EPA Case No.
Record Added Date:	2017-02-09 10:02:00
Record Updated:	2017-02-09 10:02:00
Updated By:	IXMUNTEA
Crossref ID:	NY6210090027
Cross Ref Type Code:	08
Cross Ref Type:	EPA Case No.
Record Added Date:	2017-02-09 10:03:00
Record Updated:	2017-02-09 10:03:00
Updated By:	IXMUNTEA
Crossref ID:	2-391980
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-02-09 14:24:00
Record Updated:	2017-02-09 14:24:00
Updated By:	IXMUNTEA
Crossref ID:	9109496
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2017-02-09 14:17:00
Record Updated:	2020-12-11 09:22:00
Updated By:	JHOCONNE
Crossref ID:	NY6210090027
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2017-02-09 10:03:00
Record Updated:	2020-12-11 09:22:00
Updated By:	JHOCONNE
Crossref ID:	NYD981077829
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2017-02-09 10:02:00
Record Updated:	2020-12-11 09:22:00
Updated By:	JHOCONNE
Crossref ID:	NYR000070946
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2017-02-09 10:03:00
Record Updated:	2020-12-11 09:22:00
Updated By:	JHOCONNE
Crossref ID:	C224252-06-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-01 22:17:00
Record Updated:	2020-10-01 22:17:00
Updated By:	MXMAGLOI
Crossref ID:	2020000300598
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier

BEDFORD UNION ARMORY (Continued) **S120706204**

Record Added Date: 2020-11-03 11:15:00
Record Updated: 2020-11-03 11:15:00
Updated By: GWHEITZM

E DESIGNATION:
Name: LOT 1,TAXBLOCK 1274
Address: 1555 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 1
Tax Block: 1274
Borough Code: Not reported
E-No: E-428
Effective Date: 11/30/2017
Satisfaction Date: Not reported
Ceqr Number: 16DME005K
Ulurp Number: 170416ZMK, 170417ZRK, 170418ZSK, 170419ZSK170416ZMK, 170417ZRK, 170418ZSK, 170419ZSK
Zoning Map No: 17b

Description: Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

---

243 **TTF** **NY LTANKS** **S104619530**
ESE **215 STERLING STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11225**
0.339 mi.
1792 ft.

Relative: **Lower**
Actual: **67 ft.**

LTANKS:
Name: TTF
Address: 215 STERLING STREET
City,State,Zip: BROOKLYN, NY 11225
Spill Number/Closed Date: 9802380 / 2015-06-02
Facility ID: 9802380
Site ID: 177768
Spill Date: 1998-05-22
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SXMAHAT
Referred To: Not reported
Reported to Dept: 1998-05-23
CID: 266
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False

TTF (Continued) **S104619530**

Remediation Phase:	0
Date Entered In Computer:	1998-05-23
Spill Record Last Update:	2015-10-28
Spiller Name:	Not reported
Spiller Company:	HAYES NIXON
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	19091
DEC Memo:	"3/16/06-Nathan- Conatacted Hayes Nixon, 718-756-5796, he indicates the tank has been repaired but has nothing but payment stub. PBS, 2-400572, info indicates continued testing of tank is not required and the tank is above ground. Next step confirm that tank is above ground and determine if it needs testing. Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 5/18/04 - AUSTIN - TRANSFERRED FROM TOMASELLO FOR REASSIGNMENT - END 8/17/12 Spill re-assigned to T. Demeo as per RSE. bf Mahat: 10/07/13 A call was received from Mr. Ebiniza (Peach Environmental). He is working for property owner to remediate the site. He wanted to know if there was any spill back in 1998 when the tank failed TT. His intension was to find out the previous situation and current situation to make the property contamination free. Also, the tank doesn t have weep holes and it is covered with concrete. Yet the tank is registered as above ground tank. As of today, DEC requires a TT result and the confirmation letter saying that there is no contamination. Mr. Ebiniza Peach Environmental 732.326.1010 * 424 Mahat: 10/18/13 A phone call was made to Mr. Ebiniza about the TT report. He mention that property owner decide to move along the process without him. A letter for TT sent out to the property owner. (The same copy that Tim sent them in 2012) This spill case is transferred to Mahat as per Demeo. 10/22/13-Vought-Received call from Derek Bestreich (Ph:718-475-4368) and he is working with property owners representative. Owner noted he replaced gaskets and he did keep a copy of the receipts due to age of spill. Derek requesting call back for next steps. He was thinking of converting site to gas but was not sure of timeframe as heating season was approaching. Vought noted that a possible solution to spill closure was tightness testing of the new UST system to account for this spill number as well as comply with PBS Requirements of regular tightness testing. Derek noted that the tank currently had oil in it and Vought noted that there was no passing test results to ensure that this oil was not leaking into floor (especially considering the lack of weepholes). Derek will return call to Santosh with update on next step. 3/17/14 :Mahat A voice message was left for Mr. Bestreich to call back to touch base about the case. 10/22/2013 : Mahat Left a message to Mr. Derek to call DEC back. DEC Requires: 1)tightness testing of tank system 2)rereg istration of tank as UST as in grave and no weepholes. 6/1/15: Mahat e/c: DEC Mahat received an email from David (RiteWay) for spill closure report inclusing a passing TT result. Both has been uploaded on D2 for reference. Based on the spill closure report and passing TT result, the Department does not warrant nay further investigation. Hence, the spill case will be closed on DEC Spill Database. "
Remarks:	"APARTMENT BUILDING. DEFINATE PROBLEM IN MANHOLE COVER. CUSTOMER

TTF (Continued) **S104619530**

NOTIFIED OF RESULTS."

All TTF:

Facility ID:	9802380
Spill Number:	9802380
Spill Tank Test:	1545929
Site ID:	177768
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	177768
Operable Unit ID:	1062917
Operable Unit:	01
Material ID:	320711
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

244 East 1/4-1/2 0.348 mi. 1837 ft.

APARTMENT BUILDING
334 MONTGOMERY STREET
BROOKLYN, NY

NY LTANKS **S104619743**
NY LEAD **N/A**

Relative: Higher

Actual: 91 ft.

LTANKS:

Name:	PRIVATE HOME
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0702097 / 2007-08-30
Facility ID:	0702097
Site ID:	381746
Spill Date:	2007-05-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-05-21

APARTMENT BUILDING (Continued) **S104619743**

CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-05-21
Spill Record Last Update:	2007-08-30
Spiller Name:	MARLIN JOSEPH
Spiller Company:	PRIVATE HOME
Spiller Address:	334 MONTGOMERY STREET
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	112
DEC Region:	2
DER Facility ID:	331145
DEC Memo:	"5/29/07 bf: sent ttf letter to: Carmen Torres, Secretary 334 LLC 57 5th Ave. Brooklyn, NY 11217 8/29/07 On 7/27/07, received letter from Michael Savino of Statewide Oil & Heating Co. Letter requests closing of spill. letter refers to all attached documentation , but only includes tightness terst results one a failure and one passing. Called Mr. Savino (718)858-9000. Left message with secretary. Mr. Savino called me back and we discussed cause of failure. He told me that the gauge line on top of the tank was cracked and no release of petroleum was observed. He told me he would fax letter regarding what was repaired and contamination. bf 8/30/07 Received fax confirming yesterday's conversation with Mr. Savino. NFA. bf"
Remarks:	"ABOVE LIQUID LEAK"

All TTF:

Facility ID:	0702097
Spill Number:	0702097
Spill Tank Test:	1550851
Site ID:	381746
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	381746
Operable Unit ID:	1139181
Operable Unit:	01
Material ID:	2129192
Material Code:	0001A

APARTMENT BUILDING (Continued) **S104619743**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	APARTMENT BUILDING
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9808644 / 2011-05-04
Facility ID:	9808644
Site ID:	330440
Spill Date:	1998-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	1998-10-12
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-12
Spill Record Last Update:	2011-05-04
Spiller Name:	LOUIS LAMARCHE
Spiller Company:	APARTMENT BUILDING
Spiller Address:	57 5TH AVE
Spiller County:	999
Spiller Contact:	LOUIS LAMARCHE
Spiller Phone:	(718) 857-0635
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	331145
DEC Memo:	"3/17/06 - Nathan - 718-857-0635, LeMarche Realty Corp, also has PBS 2291137. Next Step, Contact owner determine nature of spill. Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 2/16/00 ORIGINALLY ASSIGNED TO MULQUEEN. 01/26/04 Reassigned from Rommel to Austin 02/17/04: Reassigned from AUSTIN to KRIMGOLD. 10/29/10 - Austin - Reassigned from N. Putnam in Albany to Ketani in Region 2 - end 11/5/10 - Raphael Ketani. The spill took place on 10/12/98 and consisted of a tank test failure. The origin of the failure was unknown. The site is block and lot 1305 and 9. The site address is 334 Montgomery Street, Brooklyn. A deed dated 8/16/02 in ACRIS lists the owner as 334 LLC, 57 5th Avenue, Brooklyn, 11217. The seller, Louis Lamarche, is listed at the same address. The PBS is #2-291137. It lists a 5,000 gal. UST as in service with #2 oil. The owner is listed as 334 LLC, 57 5th Avenue, Brooklyn, 11217. The site

APARTMENT BUILDING (Continued) **S104619743**

phone is (718) 857-1260. The phone number under the mailing address is Louis Lamarche at (718) 857-0635. The operator is Ms. Johnson at (718) 774-2326. There are no other Spill cases, no paper file and no E-docs. I called up the (718) 857-1260 number and spoke to an operator. She took down my information and told me that someone will get back to me on monday, 11/8/10. 11/8/10 - Raphael Ketani. Carmen Torrez of Aimsley Realty ((718) 857-0635; the management company for the building) called to let me know that a passing tank test report was sent to the Albany DER office in 2003. I asked her whether the tank that is present now is the same tank that was tested in 1998 and failed. She said that, as far as she knew, we've only ever had one tank. She asked how I knew that there had been a spill in 1998. I told her that the TTF suggests the potential of a spill. So, by law, the tester has to call in the failure to the DEC Spills Hotline. She asked whether I could send her any documentation showing that there had been a spill. I told her that the DEC didn't have any other documentation except the spill report stating that there had been a TTF. She asked what should happen next. I told her to look through her company's records and see whether there are any documents from 1998 regarding the TTF. I told her that if there are none, then she should contact the testing company, Protest, and see whether they have any records. If they don't, then a soil investigation will need to take place. She said that she understood and that she will look into the matter. 1/26/11 - Raphael Ketani. I tried to contact Ms. Torrez (718) 857-0635, but I could only leave a message. The message stated that the DEC has not received any information regarding the spill, or that an investigation is taking place, and that the DEC is very concerned that there has been no action. 1/28/11 - Raphael Ketani. I spoke to Ms. Torrez. I asked her whether she had found the documentation regarding the tank test failure report. She said that she hadn't. I told her that since the DEC has no documentation regarding the potential spill, then we have to consider that there still may have been a spill. Ms. Torrez said that there never was a spill and that some people were supposed to call her back regarding the tank test. She asked for more time to try and find the documentation. I told her that we had last talked on 11/8/10 and so over two months had passed. I told her that the DEC couldn't give her more time. She said that she had been out for a month. I asked her whether Aimsley Realty had assigned the task of looking for the documentation to someone in her absence. She said No. I told her the DEC is sending a tank test failure letter. I sent the letter out today with a deadline of February 28, 2011. 2/28/11 - Raphael Ketani. As no contact has been forthcoming from the owners or Ms. Torrez regarding the investigation of the potential release and as there has been no response in any fashion to the TTF letter, I sent a followup letter. The followup letter had a deadline of March 23 for the submission of the investigation report. 3/23/11 - Raphael Ketani. As there has been no response from Ms. Torrez, I sent a STIP package. I set a deadline of April 20 for submission of the signed STIP. 4/20/11 - Raphael Ketani. The signed STIP was never received. Therefore, I submitted a case initiation form to Randall Austin, Chief of the Spills Unit, for his signature. 4/24/11 - Raphael Ketani. Mr. Austin returned the Case Initiation form unsigned. He told me to investigate whether the tank had ever been tested and repaired. 5/4/11 - Raphael Ketani. I spoke to Brian Falvey of the PBS Unit regarding the 5,000 gal. UST at the site. He looked up the e-docs attached to the PBS file. There was a tank test failure from 5/21/07. It was a ullage

APARTMENT BUILDING (Continued) **S104619743**

failure. Petroleum Tank Cleaners (718) 624-4842 did the repair, though it was not specified what exactly had been wrong. The tank was retested on 5/30/07 and passed. Previous to this, the tank had been tested on 6/25/02 and had passed. However, the PBS files and the e-docs in the PBS database did not have any earlier testing documentation. Later, I spoke to Mark Salamack of Petroleum Tank Cleaners. He said that PTC didn't have any records that went back to 1998 (most companies purge records over 7 years old). He said that the TTF that had happened on 5/21/07 was due to an open line. There was an extra line that had been left attached to the tank. Mr. Salamack believed that an old line had been replaced, but someone had left the intact end of this old line. He recommended that I call State Wide Oil (718) 858-9000 to see whether someone there remembered the job back in 1998. I spoke to Michael Savino of State Wide Oil. He said that he remembered the tank. He said that the spill reported in 1998 as a TTF was due to a gauge problem and not a leaking tank or pipe. He said that he remembered that PTC had taken care of the problem. Based upon the passing tank tests in 2002 and 2007 and my conversation with Mr. Savino today, I have determined that there was no release of oil to the environment. Therefore, there is no threat to the public or the environment. As such, I have closed the spill case. "

Remarks: "TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER ADVISED OF PROBLEM. NO CALL BACK REQUESTED."

All TTF:

Facility ID:	9808644
Spill Number:	9808644
Spill Tank Test:	1546377
Site ID:	330440
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	False
UST:	False
Cause:	03
Source:	00
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	RVKETANI
Last Modified Date:	Not reported

All Materials:

Site ID:	330440
Operable Unit ID:	1069817
Operable Unit:	01
Material ID:	316137
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

APARTMENT BUILDING (Continued) **S104619743**

NYC LEAD:

Name:	Not reported
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11926880
Building ID:	339808
Registration ID:	341401
Apartment:	7D
Story:	4
Class:	Most Serious
Inspection Date:	08/01/2017
Approved Date:	08/14/2017
Original Certify By Date:	09/16/2017
Original Correct By Date:	09/11/2017
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	5825701
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) EAST WALL IN THE 1st ROOM FROM NORTH AT EAST LOCATED AT APT 7D, 4th STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	08/14/2017
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	08/14/2017

Name:	Not reported
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11990288
Building ID:	339808
Registration ID:	341401
Apartment:	C7
Story:	3
Class:	Most Serious
Inspection Date:	09/21/2017
Approved Date:	09/25/2017
Original Certify By Date:	10/28/2017
Original Correct By Date:	10/23/2017
New Certify By Date:	11/11/2017
New Correct By Date:	11/06/2017
Certified Date:	11/09/2017
Order Number:	617
NOV ID:	5857268
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE BATHROOM LOCATED AT APT C7, 3rd STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	09/25/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/24/2017

APARTMENT BUILDING (Continued) **S104619743**

Name:	Not reported
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11990289
Building ID:	339808
Registration ID:	341401
Apartment:	C7
Story:	3
Class:	Most Serious
Inspection Date:	09/21/2017
Approved Date:	09/25/2017
Original Certify By Date:	10/28/2017
Original Correct By Date:	10/23/2017
New Certify By Date:	11/11/2017
New Correct By Date:	11/06/2017
Certified Date:	11/09/2017
Order Number:	617
NOV ID:	5857268
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE FOYER LOCATED AT APT C7, 3rd STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	09/25/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/24/2017

Name:	Not reported
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11990290
Building ID:	339808
Registration ID:	341401
Apartment:	C7
Story:	3
Class:	Most Serious
Inspection Date:	09/21/2017
Approved Date:	09/25/2017
Original Certify By Date:	10/28/2017
Original Correct By Date:	10/23/2017
New Certify By Date:	11/11/2017
New Correct By Date:	11/06/2017
Certified Date:	11/09/2017
Order Number:	617
NOV ID:	5857268
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, EAST WALL, WEST WALL IN THE 1st ROOM FROM NORTH AT EAST LOCATED AT APT C7, 3rd STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	09/25/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/24/2017

APARTMENT BUILDING (Continued) **S104619743**

Name:	Not reported
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11990291
Building ID:	339808
Registration ID:	341401
Apartment:	C7
Story:	3
Class:	Most Serious
Inspection Date:	09/21/2017
Approved Date:	09/25/2017
Original Certify By Date:	10/28/2017
Original Correct By Date:	10/23/2017
New Certify By Date:	11/11/2017
New Correct By Date:	11/06/2017
Certified Date:	11/09/2017
Order Number:	617
NOV ID:	5857268
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL IN THE 2nd PRIVATE HALLWAY LOCATED AT APT C7, 3rd STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	09/25/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/24/2017

Name:	Not reported
Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11990292
Building ID:	339808
Registration ID:	341401
Apartment:	C7
Story:	3
Class:	Most Serious
Inspection Date:	09/21/2017
Approved Date:	09/25/2017
Original Certify By Date:	10/28/2017
Original Correct By Date:	10/23/2017
New Certify By Date:	11/11/2017
New Correct By Date:	11/06/2017
Certified Date:	11/09/2017
Order Number:	617
NOV ID:	5857268
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL, WEST WALL IN THE 4th ROOM FROM NORTH AT WEST LOCATED AT APT C7, 3rd STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	09/25/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/24/2017

Name:	Not reported

APARTMENT BUILDING (Continued) **S104619743**

Address:	334 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11990293
Building ID:	339808
Registration ID:	341401
Apartment:	C7
Story:	3
Class:	Most Serious
Inspection Date:	09/21/2017
Approved Date:	09/25/2017
Original Certify By Date:	10/28/2017
Original Correct By Date:	10/23/2017
New Certify By Date:	11/11/2017
New Correct By Date:	11/06/2017
Certified Date:	11/09/2017
Order Number:	617
NOV ID:	5857268
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL IN THE 4th ROOM FROM NORTH AT EAST LOCATED AT APT C7, 3rd STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	09/25/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/24/2017

AI245 **GOODY DRY CLEANERS** **NY LTANKS** **S107789427**
NNE **812 A FRANKILN AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11225**
0.353 mi.
1865 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
136 ft.

LTANKS:

Name:	GOODY DRY CLEANERS
Address:	812 A FRANKILN AVE
City,State,Zip:	BROOKLYN, NY 11225
Spill Number/Closed Date:	0601854 / 2006-11-08
Facility ID:	0601854
Site ID:	364203
Spill Date:	2006-05-19
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2006-05-19
CID:	409
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-19

GOODY DRY CLEANERS (Continued) **S107789427**

Spill Record Last Update:	2006-11-08
Spiller Name:	UNKNOWN NAME
Spiller Company:	GOODY DRY CLEANERS
Spiller Address:	812 A FRANKILN AVE
Spiller County:	001
Spiller Contact:	UNKNOWN NAME
Spiller Phone:	(718) 467-6620
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	314418
DEC Memo:	"5/19/06 - Raphael Ketani. I called up Joe Ostrowski cell (646) 772-6313 of PTC (718) 624-4842 to find out the status of the cleanup. He said his guys were at the site and they reported back that there was only a small puddle of oil, despite the burst tank. They told him that there was nothing in the burst tank. Mr. Ostrowski said that, from what his crew was saying, there was less than 10 gals. of oil on the floor. He said his guys are cleaning up with Speedi Dri. He told them to look around and see where the oil went. He also said that there are no drains, only 2 small cracks, and a wet rug. Mr. Ostrowski said that the rug is dry underneath and that there is nothing else to be seen. I asked him to do some soil borings monday, 5/22. He said he will do it. 5/22/06 - Raphael Ketani. I arrived at the site after the soil borings had been taken. I met Marlon of PTC (718) 624-4842. He showed me the 2 samples he had collected below the concrete floor. They both had strong oil odors. One sample had been taken at the left end of the tank and one sample had been taken from in front of the middle of the tank. The room where the tank was had a floor with only 2 fine cracks. However, it was apparent that the oil had flowed across the floor and away from the tank. Vapor concentrations were 3000 ppb in the room. I checked the temporary tank, suction line, and boiler in the other room and everything looked alright, though the suction line looked a little oxidized over its length. I spoke to Sung Soo Kim, the manager for Goody Cleaners (718) 467-6620. He said the superintendant is near and that the management company is MRM Management. Mr. Kim said that the oil company came friday, 5/19, and filled up his tank, but the oil overflowed out the vent pipe (I looked at the vent pipe and the oil spill had been cleaned up). He said that later that day he smelled oil and found the oil dripping out the bottom of the tank through small holes in the bottom. Mr. Kim told me that Blue Diamond Oil had hired PTC. I told him to contact them and have them pay for the cleanup. I told Mr. Kim that, at the very least, the oil tank will have to be replaced, the floor will have to be broken up and the contaminated soil removed, and maybe bioremediation used to clean up the soil that can't be taken out (there are 5 large columns near the oil tank which support the floor above). He said he will call them. 6/15/06 - Raphael Ketani. I called Mr. Kim. He said that he received a bill for the soil sampling done by PTC, but nothing else. I asked him whether MRM Management was involved. He said he didn't know, but gave me their number (516) 869-1240. Next, I called Mr. Ostrowski of PTC and I asked him what the analytical results for the soil samples were. He said he didn't know, but that he would call me back later with an answer. Lastly, I called up MRM Management. I got Millbrook Properties (of which MRM is a subsidiary) and the owner of the site, Charles Hirsch. He is at 42 Bayview Avenue, Manhassett, NY, 11030. I asked Mr. Hirsch whether he was aware of the oil spill. He said this is the first he heard of it. I told him that, as the owner of the

GOODY DRY CLEANERS (Continued) **S107789427**

property, he is responsible for the oil spill. I told him I needed the information that PTC had regarding the soil sampling and whether additional work needed to be performed. He said he will look into the situation and get back to me. I will send a contaminated soil letter to Mr. Hirsch. 6/19/06 - Raphael Ketani. Mr. Kim called me to say that PTC (718) 624-4842 had lost the original soil samples and that they came today to take 3 more samples. They told Mr. Kim that it will take 2 to 3 weeks until they get the results back. 7/14/06 - Raphael Ketani. I left messages for Mr. Kim (718) 467-6620 and Mr. Hirsch. I spoke to Mr. Ostrowski and he said he just got the analytical results for the soil samples. He said there are hot spots. However, he can't release the documents as Mr. Kim hasn't paid his company for the work that was done. 7/18/06 - Raphael Ketani. I tried to call Mr. Kim, but could only leave a message. I also left a message for Mr. Hirsch. Mr. Kim called me back later and said that he just sent PTC a check for the balance of the work. He said that once he gets the report, then he will send me a copy. I told him that I was told by PTC that one boring indicated that there was contamination below the concrete floor and that the soil will have to be dug up. He said he was aware of this. 7/19/06 - Raphael Ketani. Mr. Hirsch left a message and said that they are working on getting the bill for PTC paid so that the information can be released. 8/8/06 - Raphael Ketani. I tried calling Mr. Kim, but could only leave a message. I called Mr. Ostrowski of PTC and he said that the soil samples came back hot - so there is soil to dig out, they have been paid - so they can release a report to me, and they sent a remediation plan to MRM Management. I called up MRM (516) 869-1240 and got Mr. Katz, who works with Mr. Hirsch. Mr. Katz said that he was aware of the dirty soil samples and that he paid PTC. He went on to say that PTC never sent him a plan of action. I told him the soil has to get removed very soon as this has been dragging on too long. He said he was aware of this and will try a different company if PTC doesn't act soon. I said that would be fine. 8/9/06 - Raphael Ketani. I received an e-mail from John Jeun (718) 279-9001 with an attachment of 5 soil analytical results. The samples were N, S, E, W, and C. Samples N had hits, but below TAGM. Samples S and E had an exceedence for 1,3,5-trimethylbenzene. Samples W and C had many exceedences of TAGM. I e-mailed Mr. Jeun back and told him in a letter that the soil needed to be removed. I sent the following letter: Dear Mr. Jeun: I have reviewed the analytical results that you provided me from South Mall Analytical Labs, Inc. There is significant contamination under the basement floor at Goody Dry Cleaners and the soil needs to be removed. Samples C and W were particularly contaminated. Samples E and S also show exceedences for 1,3,5-trimethylbenzene. The New York State Department of Environmental Conservation is ordering Goody Dry Cleaners and Millbrook Properties to immediately begin removal of all contaminated soil. The Department holds Millbrook Properties and Goody Dry Cleaners, the Responsible Parties, liable for addressing any on and off site contamination associated with this spill. Under Section 192 of the Navigation Law, any person who discharges petroleum and fails to promptly clean up such prohibiited discharge may be subject to a penalty of up to $25,000 per day per violation and possibly to legal action. If you have any questions regarding this matter, you may reach me at (718) 482-4634 between 8:30AM to 4:30PM. Thank you, Raphael Ketani Engineering Geologist II I left a message for Mr. Hirsch that I had received the analytical results from Mr. Jeun (pronounced Jon). John Kurth (917) 412-4946 of ALC

GOODY DRY CLEANERS (Continued) **S107789427**

Environmental called and left a voice mail. He said he is the consultant for Goody Dry Cleaners. I tried to reach him, but could only leave a voice mail. At 3:40PM Mr. Kurth called me back. He said he was hired by Millbrook Properties and had received the analytical results. I told him that there is significant contamination on site. I added that the soil has to be removed, clean end point samples taken, and the tank and piping removed and replaced. I told him to send me a report with manifests for the soil, analytical results, and other pertinent cleanup documentation. He said he will have this done. He added that he didn't know who Mr. Jeun was or who hired him. 8/14/06 - Raphael Ketani. Today, I received the following e-mail from John Jeun: Hi Mr. Katani, We are appreciated your concerned opinion and reminding our duty/obligation for this subject. Currently, we are in contact with two potential companies in coordination with our landlord, Milbrook Properties, Ltd., to perform soil removal and soil sampling at the above captioned site. We already received one proposal and waiting the second one. We will pick one most capable company and conduct the earliest possible time. We will keep you posted for its progress. Have any question for this regards, please advice. John Jeun 8/22/06 - Raphael Ketani. I tried calling Mr. Kurtz, but could only leave a voice mail. 9/6/06 - Raphael Ketani. I spoke to Mr. John Kurtz of ALC Environmental (917) 412-4946. He said they were going to start digging out the contaminated soil today. He said that Safety Clean will take away the drums of soil. 11/7/06 - Raphael Ketani. I tried to call Mr. Kurtz, but could only leave a voice mail. Mr. Kurtz called me back. He said that back in mid-October he had e-mailed me the final investigation and cleanup report. I told him I never received it. He told me the e-mail address he had used to try and send me the report and it was wrong. He told me he will resend it. 11/8/06 - Raphael Ketani. Today I received the October 5, 2006 Soil Removal and Sampling Report for the site from ALC Environmental. Less than 1 drum of soil was removed from the site. They dug two soil borings and took 2 soil end point samples. With the exception of very low levels (below TAGM RSCO) of bis(2-ethylhexyl)phthalate, acetone, and tetrachloroethylene, there were no hits. The report states the total volume of oil lost must have been about 1 gal. and that the oil contamination is limited to surface staining. Based upon the October 5, 2006 Soil Removal and Sampling Report, I am closing the spill case. "

Remarks: "CLEAN UP IN PROCESS."

All Materials:

Site ID:	364203
Operable Unit ID:	1122237
Operable Unit:	01
Material ID:	2111709
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI246 **348 EASTERN PARKWAY** **NY LTANKS** **S106014829**
NNE **348 EASTERN PARKWAY** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.360 mi.
1902 ft. **Site 2 of 2 in cluster AI**

Relative:
Higher

Actual:
138 ft.

LTANKS:

Name:	348 EASTERN PARKWAY
Address:	348 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0211889 / 2003-11-12
Facility ID:	0211889
Site ID:	232005
Spill Date:	2003-03-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2003-03-03
CID:	281
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-03
Spill Record Last Update:	2003-11-12
Spiller Name:	SAME
Spiller Company:	MADISON FUEL OIL
Spiller Address:	2125 MILL AVE
Spiller County:	001
Spiller Contact:	WILLIAM FALKENMEYER
Spiller Phone:	(718) 444-3400
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	176580
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE DEC Sigona called Ms. Ramirez 718-756-7859 at Molly Realty on 3/3/2003, confirmed spill is being cleaned up. DEC Sigona also called Madison Oil Bill Falkenmeyer and confirmed Trade Winds is doing the cleanup and there is no spill in the basement. Assigned to DEC Tipple for follow-up inspection. 3/20/03 spoke with Steve Braun, manifests to follow, cleanup completed. 6/6/03 Jim 516-779-7819 schedule site vsit asap 11/12/03 all documentation arrived//nfa"
Remarks:	"TANK OVERFILL AT ABOVE LOCATION. CREW ENROUTE FOR CLEANUP AND ALL MATERIAL IS EXPECTED TO BE RECOVERED."

All Materials:

Site ID:	232005
Operable Unit ID:	862893
Operable Unit:	01
Material ID:	511672
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

348 EASTERN PARKWAY (Continued) **S106014829**

Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	348 EASTERN PARKWAY
Address:	348 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0330012 / 2003-11-12
Facility ID:	0330012
Facility Type:	ER
DER Facility ID:	176580
Site ID:	213135
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2003-06-09
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2003-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-09
Spill Record Last Update:	2003-11-12
Spiller Name:	STEVE FOX
Spiller Company:	348 EASTERN PARKWAY
Spiller Address:	348 EASTERN PARKWAY
Spiller Company:	001
Contact Name:	STEVE FOX
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 6/9/03 SURFACE SPILL # 02-11889 HAS BEEN CLEANED BY TRADEWINDS AND WILL BE CLOSED WHEN THE MANIFESTS ARRIVE. THE SUBSURFACE SPILL WHICH THIS SPILL NUMBER REPRESENTS APPEARS TO HAVE BEEN CAUSED BY YEARS OF A REMOTE FILL LEAKING. THE CARDBOARD HANGING ABOVE THE FUEL OIL TANK INDICATES THAT SOMEONE ASSOCIATED WITH THIS BUILDING HAS KNOWN ABOUT THIS SPILL FOR A WHILE. 8/28/03 TIPPLE AWAITING DISPOSAL MANIFESTS. see spill 0330012"
Remarks:	"WHILE PERFORMING A SITE VISIT CONCERNING A SURFACE SPILL, FUEL OIL WAS NOTICED INFILTRATING TANK ROOM THROUGH VAULT WALL. CARDBOARD HAD BEEN HUNG FROM THE CIELING TO COVER SOMETHING. THE CARDBOARD WAS SATURATED IN THE AREA THE REMOTE FILL CAME THROUGH THE WALL. "

All Materials:

Site ID:	213135
Operable Unit ID:	881430

348 EASTERN PARKWAY (Continued) **S106014829**

Operable Unit:	01
Material ID:	496512
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

247
NE
1/4-1/2
0.363 mi.
1914 ft.

EXXONMOBIL
1550 BEDFORD AVENUE
BROOKLYN, NY

NY LTANKS **S103824118**
NY Spills **N/A**

Relative:
Higher

Actual:
139 ft.

LTANKS:

Name:	CFI STATION - EXXONMOBIL
Address:	1550 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8706242 / 2019-07-30
Facility ID:	8706242
Site ID:	170296
Spill Date:	1987-10-23
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	1993-08-11
SWIS:	2401
Investigator:	AXDORONO
Referred To:	CASE CLOSED
Reported to Dept:	1987-10-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-02
Spill Record Last Update:	2019-07-30
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143297
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 02/10/2004. This spill investigation site has been consolidated under Spill No. 8706242. 08/11/93: REMOVED TWO ABANDONED SUCTION LINES RETESTED AND PASSED ON 11/16/87. 2/5/04 Current PBS owner Cumberland

EXXONMOBIL (Continued) **S103824118**

Farms. 6/14/05: This spill case transferred from Rommel to J. Kolleeny. - JK 03/05/07: Spoke with Bill Simmons about this site, he said GSC had submitted an investigation plan to DEC in 2003 that did not get a response. I looked for plan in file but could not find it. Sent email to Bill Simmons asking for copy of GSC plan, and asking if I should review and respond to that plan, or if ECS will prepare an up-to-date plan for my review. - J. Kolleeny 04/23/07: Received hard copy and e-copy of On-Site Subsurface Investigation Work Plan by ECS, dated 4/16/07 (in eDocs). Will review. - J. Kolleeny 05/08/07: Received On-site Subsurface Investigation Work Plan dated 4/16/07, on 4/23/07, prepared by ECS (in eDocs). Plan calls for five soil borings, with up to 3 to be finished as wells if perched water is encountered; borings will be advanced to 42 feet, if last interval is contaminated, will continue until 10 feet of clean soil observed. However, no boring is planned beneath former gasoline UST area Excavation Event #3, where greatest residual soil contamination was found in past investigations, as this area is beneath canopy among active dispensers. Discussed plan with Bill Simmons of ECS on 4/25/07, and agreed that they would either get a geoprobe under the canopy to advance a boring through former tank pit, or they would do angled-drilling from just south of canopy to reach soil beneath former tank pit, and if contamination is found exceeding 30 feet, they will come back later and install a well as close as possible, down to regional water table (suspected at about 120 ft. bg). I also suggested relocating one boring to be near active fill ports where high PID readings (up to 639 ppm) were found during spill bucket installation work. Bill said he would submit a revised work plan to reflect these changes. On 5/7/07, received On-site Subsurface Investigation Work Plan Addendum dated 4/30/07 by ECS (in eDocs), which incorporated changes we had discussed. I emailed and mailed an approval letter to Chris Johnson of Cumberland Farms (cc'd Bill Simmons) on 5/8/07 (in eDocs). - J. Kolleeny 08/07/2007: This spill case was transferred to A. Doronova. -AD 10/03/2007: Received On-Site Subsurface Investigation Report. Will review. AD 11/01/2007: Reviewed the investigation report. During the period June-August 2007, ECS performed six soil borings with three of them completed as groundwater monitoring wells. A total of 15 soil samples and two groundwater samples (well MW-3 was dry) were collected and analyzed for VOCs and SVOCs. Soil analytical data indicate that significant concentrations of BTEX and MTBE remain in the area of the former USTs. Total BTEX in that area ranges from 203,528 ppb(MW-3)to 289,557 ppb(B-4). Groundwater analytical results show some elevated concentrations of BTEX and MTBE. 53.7 ppb for MW-1 and 49 ppb for MW-2. Based on the data consultant proposes installation of two additional soil borings and one monitoring well down to the regional aquifer, to determine if soil contamination impacting the regional groundwater and better delineate boundaries of contamination. Will prepare a letter. AD 11/06/2007: Wrote a letter, addressed to C. Johnson (cc: J. Kolleeny and B. Simmons). Approved additional subsurface investigation with the following modification: If impacts to the regional aquifer are confirmed during this investigation, further groundwater delineation will be necessary via installation of at least two additional wells. AD 03/13/2008: Received an email from Bill Simmons of ECS with a request to issue a sidewalk permission letter for off-site boring/well installation. Sent requested letter the same day. AD 04/30/2008: Received a message from B. Simmons. They were performing investigation work at the site and encountered

EXXONMOBIL (Continued) **S103824118**

refusal at 102 feet bgs with no groundwater appearance during a monitoring well installation. They got a permission to discontinue the well installation, to summarize investigation data, and to submit a report with conclusion and recommendations for further actions. AD 07/18/2008: Received a Subsurface Investigation Report Addendum. Will review. AD 09/2008: Reviewed the report. It states that the scope of work during the March 28, 2008 investigation included the advancement of two soil borings (SB-6 and SB-7), followed by collection of four soil samples. In April 29, 2008 ECS made an attempt to install one deep monitoring well into regional groundwater aquifer, but it was unsuccessful due to refusal encountered at 102.5 fbg. No groundwater was encountered at this depth and the boring was abondoned. The results for the soil samples collected indicated elevated levels of VOCs in sample from SB-7 at the depth of 19-20'. Groundwater analytical data from July 9, 2008 indicated some elevated levels of BTEX in well MW-1 (43 ppb), MW-2 was ND. MW-3 was dry. ECS concludes that there is presence of historical petroleum-impacted soils in the vicinity of the former UST grave, located beneath the canopy to at least 22fbg interval. Groundwater samples collected from the perched water table on the southwestern portion of the site have been impacted with low levels of VOCs. Based on the geology of the site that consists of a dense till layer from approximately 35-75 fbg, sand and gravel - from 75-80 fbg, a clay layer from 80-90 fbg and a very dense rock layer from 90-102 fbg, ECS believes that no further attempts to reach regional GW is necessary. Based on the soil impact identified less than 30 fbg during 2007-2008 soil investigation, it is not likely that the release migrated into regional aquifer. AD 07/22/2011: Received a Groundwater Update Report and Remedial Action Plan. Will Review. To request pdf copy of the report. AD 08/09/2011: Reviewed the report. It states that groundwater samples were collected from the two site wells MW-1 and MW-2 on February 15, 2010; from MW-1 and MW-2 on April 14, 2011; and only from well MW-1 on July 7, 2011 due to LNAPL encountered in well MW-2. During these three sampling events TVOCs in MW-1 ranged from 32.5ppb to 145.7ppb to 88.3ppb respectively. TVOCs in well MW-2 renged from 24.8ppb to 18.5ppb. Depth to water in well MW-2 in six gauging events performed since 2007, ranged from 15.8 fbg in July 2011 to 22.17 fbg in July 2008 and February 2010. Thickness of the LNAPL ranged from 0.13' on July 7, 2011 to 0.08' on July 13, 2011 after re-gauging the well. Based on the recent occurrence of weathered LNAPL in the vicinity of the former 1,000-gallon fuel oil UST, that was removed in August 1992, ECS proposes performing a bi-monthly gauging and hand bailing program of well MW-2 for a quarter to determine LNAPL recharge rate and evaluate data for appropriate remedial actions. New address: Christopher Johnson Project Manager Cumberland Gulf Group of Companies Business Support Campus 100 Crossing Blvd Framingham, MA 01702 AD 08/12/2011: Issued and sent an approval letter to Chris Johnson of CFI. DL pdf copy of the letter to eDocs. AD 04/25/2012: Called and left a message to B. Simmons of ECS with a request for site status update. AD 05/01/2012: Received hard copy of a Groundwater Update Report and RAP Status Report, dated April 24, 2012. No PDF copy was submitted. To request its submission. Will review. AD 05/02/2012: Sent an e-mail to B. Simmons with a request for pdf copy of the report submission. AD 05/03/2012: Received ecopy of the report via e-mail. DL the report to eDocs. AD 05/29/2012: Reviewed the report. It states that ECS collected groundwater samples from on-site monitoring well MW-1 on November 10, 2011 and February

EXXONMOBIL (Continued) **S103824118**

6, 2012 and from well MW-2 on February 6, 2012, and the samples were analyzed for VOCs. The samples collected from wells MW-1 and MW-2 on February 15, 2012 were also submitted for SVOC due to the presence of LNAPL discovered in well MW-2. Well MW-1: - July 2008 groundwater data collected from well MW-1, indicates the highest concentrations of total BTEX were detected at 43.07 ug/L. The highest concentrations of other VOCs were detected at 32 ug/L; - The November 10, 2011 data indicated concentrations of total BTEX at 10.44 ug/L, and TVOCs at 94.55 ug/L; - The February 6, 2012 data indicated concentrations of TBTEX at 20.92 ug/L and TVOCs at 116.55 ug/L. Analysis for SVOC concentrations indicated six various SVOCs below their respective TOGS GWQS. According to the most recent GW data, slight increase in TVOCs in well MW-1 is noted. Well MW-2: - July 2008 groundwater data collected from well MW-2, indicated only concentrations of MtBE at 33.3 ug/L in the initial July 2007 sampling event, and at 35.7 ug/L in the October 31, 2007 sampling events above the TOGS GWQS. No other VOC concentrations exceeded the TOGS GWQS; - on November 10, 2011 no samples were collected from well MW-2 due to the presence of approximately 0.10 feet of LNAPL. - on February 16, 2012 gauging of well MW-2 indicated no LNAPL so the groundwater was sampled. Results indicated only a concentration of MtBE at 20.9 ug/L above the TOGS GWQS of 10 ug/L. No other VOC concentrations were detected above the minimum laboratory reporting limits. Analysis for SVOCs indicated no concentrations above the minimum laboratory RDLs LNAPL Evaluation Status in Well MW-2 August 2011 through March 2012: Gauging of well MW-2 in August and September 2011 indicated no LNAPL in well MW-2 when depth to groundwater ranged from approximately 14.88-15.54' bsg. Gauging on November 10, 2011 indicated an approximate 0.10 thickness when groundwater was at approximately 15.37' bsg. No LNAPL was able to be recovered via hand bailing due to the viscous and weathered nature of the LNAPL. On November 23, 2011, LNAPL was present at an approximate 0.06 thickness when groundwater was at approximately 15.48' bsg. Since the hand bailing program was determined to be unsuccessful in recovering the small thickness of LNAPL, ECS installed two 1-inch diameter LNAPL sorbent socks in well MW-2 on November 23, 2011. Gauging of well MW-2 in December 2011 and in January, February and March 2012 indicated no LNAPL. Depth to water in well MW-2 as measured from approximate surface grade of the well on July 7, 2011 was at 15.92' bsg, increased to a historic high elevation of 14.88' bsg on September 19, 2011, and since has continued to decrease to 17.39' bsg on February 6, 2012, to 20.33' bsg on February 21, 2012, to a historic low elevation of 22.54' bsg on March 26, 2012. This data indicates an approximate 7.66 foot groundwater elevation fluctuation decrease between September 2011 and March 2012. Evaluation of this groundwater elevation data indicates that LNAPL has only been present when the groundwater elevation was between approximately 15-16' bsg. Based on this information, ECS recommends leaving the LNAPL sorbent socks in well MW-2 and continued monthly gauging of well MW-2. ECS will continue to perform quarterly groundwater monitoring that will consist of depth to groundwater gauging, field analysis for groundwater geochemical parameters (i.e. dissolved oxygen, redox potential, specific conductivity, temperature, and pH levels), and the collection of groundwater samples from wells MW-1 and MW-2 if LNAPL is not present, for the presence of VOCs and SVOCs. A semi-annual Groundwater Update and a RAP Status Report summarizing the quarterly monitoring and proposed RAP activities will be submitted. AD 04/02/2013: Received the

EXXONMOBIL (Continued) **S103824118**

following email from B. Simmons: Hi Ainura, Please find attached an electronic pdf copy of the report for Spill No. 8706242 for the Cumberland Farms, Inc. Facility # 70219, at 1550 Bedford Avenue, Brooklyn NY. A hard copy and a CD will be put in the mail. Thank you. Bill William Simmons Senior Project Manager/Geologis DL the report to eDocs. Will review. AD 05/09/2013: Reviewed the report. It states that ECS personnel collected groundwater samples from on-site monitoring well MW-1 on May 1, 2012 and from wells MW-1 and MW-2 on August 16 and November 29, 2012. Well MW-1 - Historical groundwater data collected from well MW-1 (installed in July 2007) indicates the highest concentrations of total benzene, toluene, ethylbenzene and total xylenes (total BTEX) were detected at 43.07 ug/L in July 2008 with the concentrations of benzene at 18.6 ug/L and total xylenes at 19.8 ug/L above the TOGS GWQS. The highest concentrations of total other various gasoline-related VOCs were detected at 32 ug/L in the July 2008 sampling event (the first time these additional gasoline-related VOCs were first analyzed for). - The May 1, 2012 data indicated concentrations of benzene at 6.49 ug/L, total xylenes at 10.4 ug/L, MtBE at 25.5 ug/L, and five other various VOCs totaling 90.2 ug/L, with three above the TOGS GWQS. Analysis for SVOCs indicated five various SVOCs totaling 48.5 ug/L with only the concentration of acenaphthen at 21.6 ug/L above the TOGS GWQS of 20 ug/L. - The August 16, 2012 data indicated concentrations of benzene at 1.4 ug/L, total xylenes at 10.3 ug/L, MtBE at 43.6 ug/L, and five other various VOCs totaling 98.6 ug/L, with three above the TOGS GWQS (Table 1). Analysis for SVOCs indicated six various SVOCs totaling 66.95 ug/L with only the concentration of acenaphthen at 22.1 ug/L above the TOGS GWQS of 20 ug/L. - The November 29, 2012 data indicated concentrations of benzene at 1.4 ug/L, total xylenes at 11 ug/L, and four other various VOCs totaling 41.5 ug/L, with two above the TOGS GWQS. Analysis for SVOCs indicated five various SVOCs totaling 28.3 ug/L with no concentration above the TOGS GWQS of 20 ug/L. A comparison of this data to the historical data indicates overall relatively stable total VOCs during the period 2007 through 2012 and SVOCs during the period February 2012 through November 2012. Well MW-2 - Historical groundwater data collected from well MW-2 (installed in July 2007) indicated only concentrations of MtBE at 33.3 ug/L in the initial July 2007 sampling event, and at 35.7 ug/L in the October 31, 2007 sampling events above the TOGS GWQS. No other VOC concentrations exceeded the TOGS GWQS. o No samples were collected on May 1, 2012 since no water was present in the well to approximately 24.1 feet below grade (fbg). o The August 16, 2012 data indicated only an MtBE concentration at 18.5 ug/L above the TOGS GWQS, and no other VOCs above the minimum RDLs. Analysis for SVOCs indicated no concentrations above the minimum laboratory RDLs. o The November 29, 2012 data indicated only an MtBE concentration at 11 ug/L above the TOGS GWQS, and no other VOCs above the minimum laboratory RDLs. Analysis for SVOCs indicated no concentrations above the minimum laboratory RDLs. A comparison of this data to the historical data indicates overall relatively stable levels of MtBE during the period 2007 through 2012 and the continued absence of SVOCs during the period February 2012 through November 2012. Based on the intermittent presence of LNAPL in well MW-2 last observed in November 2011 when ECS installed LNAPL sorbent socks, and the observed fluctuating groundwater table (presumed to be perched) in the area of well MW-2 on the southwestern portion of the Site, ECS proposes leaving the LNAPL sorbent socks in well MW-2 and replacing

EXXONMOBIL (Continued) **S103824118**

them as necessary. ECS will continue to perform quarterly groundwater monitoring that will consist of depth to groundwater and/or LNAPL gauging, field analysis for groundwater geochemical parameters (i.e. dissolved oxygen, redox potential, specific conductivity, temperature, and pH levels), and the collection of groundwater samples from monitoring wells MW-1 and MW-2 if LNAPL is not present, for the presence of VOCs according to NYSDEC STARS List per USEPA Method 8260 for gasoline-related compounds, and from well MW-1 only for SVOCs according to USEPA Method 8270. The data will continue to be documented in semi-annual Groundwater Update and a RAP Status Reports. AD 11/01/2013: Received Semi-Annual Groundwater Monitoring Report for the period January - June 2013. DL the report to eDocs. Will review. AD 12/06/2013: Reviewed the report. It states that ECS personnel collected groundwater samples from on-site monitoring wells MW-1 and MW-2 on February 15 and May 29, 2013 for analysis of VOCs. The samples collected from well MW-1 were also analyzed for SVOCs according to USEPA Method 8270C. Well MW-1: Historical groundwater data collected from well MW-1 (installed in July 2007) indicated the highest concentrations of total BTEX detected at 43.07 ug/L in July 2008. The highest concentrations of total other VOCs were detected at 32 ug/L in the July 2008. - The February 15, 2013 data indicated concentrations of benzene at 3.3 ug/L, total xylenes at 8.3 ug/L, MtBE at 17.7 ug/L, and five other various VOCs totaling 39.3 ug/L, with three above the TOGS GWQS. Analysis for SVOCs indicated six various SVOCs totaling 47.4 ug/L with no concentrations exceeding their respective TOGS GWQS. - The May 29, 2013 data indicated concentrations of benzene at 3.4 ug/L, total xylenes at 7.0 ug/L, MtBE at 34 ug/L, and five other various VOCs totaling 56.5 ug/L, with three above the TOGS GWQS. Analysis for SVOCs indicated ten various SVOCs totaling 86.7 ug/L with five above the TOGS GWQS. A comparison of the current 2013 data to historical data indicates relatively stable total VOCs during the period 2007 through 2013 and SVOCs during the period February 2012 through May 2013. Well MW-2: Historical groundwater data collected from well MW-2 (installed in July 2007) indicated only concentrations of MtBE at 33.3 ug/L in the initial July 2007 sampling event, and at 35.7 ug/L in the October 31, 2007 sampling events above the TOGS GWQS. No other VOC concentrations exceeded the TOGS GWQS. - The February 15, 2013 data indicated only an MtBE concentration at 4.6 ug/L below the TOGS GWQS (Table 1), and no other VOCs above the minimum laboratory RDLs. - The May 29, 2013 data indicated only an MtBE concentration at 16.5 ug/L above the TOGS GWQS (Table 1), and no other VOCs above the minimum laboratory RDLs. A comparison of this data to the historical data indicates continued low level concentrations of MtBE during the period 2007 through 2013. No SVOCs were indicated during the period February 2012 through November 2012. LNAPL has not been measured in well MW-2 since the sorbent socks were installed in November 2011. The sorbent socks were replaced in June 2012 and May 2013. Based on the intermittent presence of LNAPL in well MW-2 last observed in November 2011, ECS proposes leaving the LNAPL sorbent socks in well MW-2 and replacing them as necessary. ECS will continue to perform quarterly groundwater monitoring that will consist of depth to groundwater and/or LNAPL gauging, field analysis for groundwater geochemical parameters (i.e. dissolved oxygen, redox potential, specific conductivity, temperature, and pH levels), and the collection of groundwater samples from monitoring wells MW-1 and MW-2 if LNAPL is not present, for the presence of VOCs according to NYSDEC STARS List per USEPA

EXXONMOBIL (Continued) **S103824118**

Method 8260 for gasoline-related compounds, and from well MW-1 only for SVOCs according to USEPA Method 8270. Based on the data, the spill case should be evaluated for closure. Spoke with B. Simmons regarding this spill. Suggested to analyze the historical data and evaluate the case for closure if applicable. AD 01/16/2014: Received a phone call from W. Simmons of ECS. He informed me that CFI selling the property and is planning to remove all USTs with associated piping. Requested to send me a summary e-mail and to notify DEC on soil sampling date. AD 01/17/2014: Received the following e-mail from B. Simmons: Hi Ainura, As discussed, this is notice to inform you that Cumberland Farms Inc. will be removing the entire underground storage tank system including all 5 double-wall steel fiberglass coated gasoline USTs, the 6 dispenser island pumps, and all product and vent lines. The USTs are scheduled to begin to be removed on Tuesday January 21, 2014 and they should all be out of the ground on Wednesday January 22. ECS will be on-site during the entire construction process to document all work and will also collect soil samples for field screening, collect end-point soil samples for lab analysis, and to oversee the excavation of all accessible contaminated soil for off-site disposal. A UST Closure Summary Report will be submitted that will document all data and work. Please let me know if you plan to be on-site at any point in time and I will keep you updated on the schedules. Thank you! Bill 01/20/2013: Received the following e-mail from B. Simmons: Hi Ainura, Status Update: All the USTs should be out of the ground on Tuesday January 21 by end of the day. Please let me know if you plan to be on-site at any point in time and I will keep you updated. Thank you! Bill AD 01/22/2014: Received the following update from ECS: Hi Ainura, Status Update: All the USTs have been removed and all were in good condition. Post-excavation soil samples collected from around the entire perimeter from the sidewalls only at 8-10 indicated a maximum field screening concentration of 6.7 ppm. These will all be submitted for lab analysis. Once the bottom concrete tank pad is removed in the next few days, we will evaluate soil quality in the bottom samples. Then we will excavate if necessary, and then commence impacted soil excavation on the other areas of the Site where there is known impact. Please let me know if you plan to be on-site at any point in time and I will keep you updated. Thank you. Bill AD 02/26/2014: Received Semi-Annual Groundwater Monitoring Report for the period July - December 2013. DL the report to eDocs. Will review. AD 03/27/2014: Reviewed the report. It states that ECS personnel collected groundwater samples from on-site monitoring wells MW-1 and MW-2 on August 26, 2013, and from well MW-1 on November 12, 2013. GW results: Well MW-1: Historical groundwater data collected from well MW-1 (installed in July 2007) indicated the highest concentrations of total BTEX detected at 43.07 ug/L in July 2008. The highest concentrations of total other VOCs were detected at 32 ug/L in the July 2008. - The August 26, 2013 data indicated concentrations of benzene at 1.12 ug/L, total xylenes at 8.374ug/L, MtBE at 32 ug/L, and five other various VOCs totaling 56 ug/L, with three above the TOGS GWQS. Analysis for SVOCs indicated two various SVOCs totaling 5.4 ug/L with no concentrations exceeding their respective TOGS GWQS. The GW analytical results for thihs well indicate slight increase in TVOCs levels comparing to the data from the previous sampling period. - The November 12, 2013 data indicated concentrations of benzene at 1.28 ug/L, total xylenes at 8.6 ug/L, MtBE at 24.9 ug/L, and five other various VOCs totaling 51.2 ug/L, with three compounds above the

EXXONMOBIL (Continued) **S103824118**

TOGS GWQS. Analysis for SVOCs indicated six various SVOCs totaling 66ug/L with five above the TOGS GWQS. A comparison of the current 2013 data to historical data indicates relatively stable total VOCs during the period 2007 through 2013 and SVOCs during the period February 2012 through May 2013. Well MW-2: Historical groundwater data collected from well MW-2 (installed in July 2007) indicated only concentrations of MtBE at 33.3 ug/L in the initial July 2007 sampling event, and at 35.7 ug/L in the October 31, 2007 sampling events above the TOGS GWQS. No other VOC concentrations exceeded the TOGS GWQS. - The August 26, 2013 data indicated only an MtBE concentration at 18.8 ug/L which is above the TOGS GWQS, and no other VOCs above the minimum laboratory RDLs. - The well was dry on November 12, 2013 and no samples were collected. A comparison of this data to the historical data indicates continued low level concentrations of MtBE during the period 2007 through 2013. No SVOCs were indicated during the period February 2012 through November 2012. The report also states that CFI sold the property in December 2013, and commenced removal of the entire UST system in January 2014. During the construction activities, areas of the Site where petroleum-impacted soil has been documented and/or is discovered, will be excavated to the extents feasible for off-site recyling/disposal. ECS will submit a UST Closure Summary Report that will document all of the UST system removal activities, and include the results of post-excavation soil samples and an evaluation of the data with recommendations for additional monitoring and/or remedial actions, if necessary, in order to obtain closure of Spill# 8706242. AD 04/30/2014: Received a UST Closure Summary Report. DL to eDocs. Will review. AD 05/20/2014: Reviewed the report. It states that during the period from January 21 through March 6, 2014, CFI contracted with Tyree Service Corp. (Tyree) of Brookfield, Connecticut, to remove the entire UST system that consisted of the following: five (5) 4,000-gallon double-wall fiberglass gasoline USTs; all associated piping; vent lines; product dispensers; dispenser islands; a concrete tank pad mat; and canopy footings. In addition, four (4) abandoned USTs discovered during petroleum-impacted soil excavation were also removed. Subsurface materials encountered during excavation activities consisted of a range of fill material from just below surface grade to approximately 8 feet below grade (fbg) that was comprised of medium to coarse sand with areas of brick, concrete, glass and metal pieces. Material from approximately 8 to 20 fbg consisted of silty-clay with coarse sand and cobbles. Groundwater was not encountered at the maximum excavation depth of 20 fbg. End-point soil sampling: A total of fifty-three (53) post-excavation samples collected from varying depths along the sidewalls limits and base areas of the final excavation. Analyticsl results indicated that twenty-three (23) of these samples indicated one or more VOCs above their respective NYSDEC CP-51 Supplemental Soil Cleanup Objectives (SSCOs). The results also indicated five samples with concentrations below the SSCOs and twenty-five samples with no VOC concentrations detected above the laboratory minimum reporting detection limits. All excavated areas were either backfilled with native soil that was segregated as clean during excavation activities or with certified virgin blasted quarry rock stone supplied by New York Sand & Stone, LLC, of Brooklyn, New York. During February 18 through March 6, 2014, a total of 2,049.98 tons of petroleum-impacted soil generated from the on-site excavations were transported off-site to Clean Earth of Carteret, New Jersey, for recycling. On March 3, 2014 Tyree evacuated

EXXONMOBIL (Continued) **S103824118**

approximately 600 gallons of water from the excavation area of the broken water line in the southwestern portion of the Site. Conclusions and recommendations: According to the consultant, evaluation of fifty-three post-excavation end-point soil samples collected from the lateral and vertical limits of the completed excavation areas indicated twenty-three samples with one or more VOCs above the NYSDEC SSCOs. The results also indicated five samples with various VOC concentrations below the NYSDEC SSCOs. Further excavation of the remaining impacted areas were not feasible due to the presence of the sidewalk along Bedford Avenue on eastern boundary of the Site, the presence of a live underground electrical line north of the former northeastern dispenser island excavation area, and a retaining wall along the southwestern boundary of the Site. Further excavation greater than 18-20 fbg in the former UST excavation area on the southern and southeastern portion of the Site was not feasible due to the excavator reach capacity and the risk of collapse to the sidewalls adjacent to the sidewalk. The proposed future development plans for the Site includes new construction of a storage building. When Site development plans do evolve, CFI and the new Site owner will develop an environmental monitoring and management plan for the excavation and off-site recycling/disposal of any impacted soil encountered. ECS will notify the NYSDEC of the construction schedule when available. Once the soil excavation for Site development is complete, ECS will prepare a UST Closure Addendum Report that will summarize the additional post-excavation soil quality data, with recommendations for additional remedial actions, if necessary, in order to obtain closure of Spill No. 87-06242. AD 07/09/2014: Received the following e-mail from B. Simmons: Hi Ainura, Please find the attached Remedial Action Plan Report for the former Cumberland Farms, Inc. property located at 1550 Bedford Ave., Brooklyn, NY Spill# 87-06242, as a follow-up to the UST Closure Summary Report dated April 30, 2014 also submitted to your attention. Please let me know if you also require a hard copy and/or a copy on a CD. Thank you. Bill Will review. AD 08/13/2014: Reviewed the report. It states that the purpose of the RAP is to satisfy the necessary remediation requirements of the NYSDEC and obtain closure of Spill No. 87-06242. The April 2014 UST Closure Report submitted to the NYSDEC summarized the activities performed during the period January 21 through March 6, 2014 associated with the removal of the entire UST system and four abandoned USTs and the excavation and off-site disposal of approximately 2,050 tons of petroleum-impacted soil, and provided an evaluation of post-excavation soil samples. Evaluation of fifty-three (53) post-excavation end-point soil samples collected from the completed excavation areas indicated twenty-three (23) samples with one (1) or more volatile organic compounds (VOCs) above the NYSDEC CP-51 SSCOs. The results also indicated five (5) samples with various VOC concentrations below the SSCOs and twenty-five (25) samples with no VOCs detected above the laboratory minimum reporting detection limits. Further soil excavation of the remaining impacted areas were not feasible due to the presence of the sidewalk along Bedford Avenue on eastern boundary of the Site, the presence of a live underground electrical line north of the former northeastern dispenser island excavation area, and a retaining wall along the southwestern boundary of the Site. Excavation greater than 18-20 fbg in the former UST excavation area on the southern and southeastern portion of the Site was not feasible due to the excavator reach capacity and the risk of collapse to the sidewalls adjacent to the sidewalk. The proposed

EXXONMOBIL (Continued) **S103824118**

future development plans for the Site includes new construction of a storage building. When Site development plans do evolve, CFI and the new Site owner will develop an environmental monitoring and management plan for the excavation and off-site recycling/disposal of any impacted soil encountered. ECS will notify the NYSDEC of the construction schedule when available. Once the soil excavation for Site development is complete, ECS will prepare a UST Closure Addendum & RAP Report that will summarize the additional post-excavation soil quality data, with recommendations for additional remedial actions, if necessary, in order to obtain closure of Spill No. 87-06242. AD 05/2015: called and left a message to Bill. AD 08/2016: called and spoke with B. Simmons. According to Mr. Simmons, no construction work was done at the site yet. AD 02/22/2017: Called and spoke with Bill. He said that his technician goes and checks on the site every few weeks. The building was demolished, but no excavation started yet. The new site owner, according to the contract, should contact AST upon start of the re-development of the property, so AST could oversee remediation activities. Bill will update DEC. AD 04/24/2018: Received a message from Bill. He informed that the redevelopment started at the site. Called and spoke with Bill. He said that 4 550-gallon USTs filled with water were discovered on the site. The new owner is planning to build a hotel. ECS will oversee the remediation of the site during redevelopment. Mr. Simmons will submit a summary e-mail for a site status update. AD 04/25/2018: Received the following e-mail from Bill Simmons: Good Afternoon Ainura, As we discussed, here is a summary of some facts on the redevelopment work on this Site. " The property is being developed as a hotel. " Work has commenced involving shoring installations along the sidewalks and minor grading excavations. " The northern-half of the Site is being excavated to 20 for the planned basement of the new building. " The southern-half of the Site is being excavated to 12 . " A vapor barrier will be installed. " OER is not involved as this is not an e-Designation site. " As we find contaminated soil we load it off-site to Clean Earth of Carteret NJ for recycling. " We will collect post-excavation end-point samples for field screening and lab analysis. " See attached Site Plans that depict the hotel footprint and planned areas of excavation between 12 and 20 and the Site Plan presented in the 2014 UST Closure Summary Report with post-ex sample locations. As per the April 30, 2014 UST Closure Summary Report and the RAP dated July 9, 2014, remaining petroleum-impacted soil above CP-51 SSCO s was present in various depths (greater than 18 -20) in certain portions of the Site. At that time, the property was to be developed as a warehouse now it will be a hotel. Per the RAP, contaminated soil would be excavated for off-site recycling and end-point samples would be collected and summarized in a report with recommendations for additional remedial actions if necessary to obtain closure of Spill No. 87-06242. For discussion: " Soil data is provided in the September 2007 SIR, the September 17, 2008 SIR Addendum, and the April 30, 2014 UST Closure Summary Report. " Soil quality at certain deeper depths are present above CP-51 SSCO s in the following locations: o Former Gasoline USTs (removed January 2014) on southern portion of Site (See Site Plan with corresponding Table on the right side with sample locations and PID readings and ID s, and separate VOC 8260 STARS lab summary table). Soil was removed from 18 -20 . Post-Ex samples No. s 17, 18, 19, 20, 21, 22, and 23 indicated elevated total VOCs with Total BTEX ranging from 7,066 ug/Kg to 746,100 ug/Kg. o Former Southeastern Dispenser, northeast of

EXXONMOBIL (Continued) **S103824118**

former USTs Sample #31 - soil at 18 had PID of 2,100 ppm with Total BTEX of 1,368,000 ug/Kg. o Former well Boring MW-3 located between former Gas USTs and Southeastern Dispenser Island has soil from 20 -22 with 424 ppm and Total BTEX of 203,528 ug/Kg. o Former Northeastern Dispenser Island samples 44, 45, 46 and 47 10 -12 and 16 PID readings ranging from 524 ppm to 1,138 ppm Total BTEX ranging from 32,320 ug/Kg to 315,480 ug/Kg. Most of this soil will be able to be excavated likely to 20 . For these above locations specifically on the southern portion of the Site where soil is only planned to be excavated to 12 for redevelopment, it is likely that contaminated soil in certain areas greater than 18 -20 will not be able to be excavated. A vapor barrier will be installed during the development. Please let us know your comments so we can discuss further and perform what is necessary to achieve Spill No. closure. Thank you, Bill William A. Simmons - SENIOR PROJECT MANAGER / GEOLOGIST - ATC Group Services LLC +1 413 519 0769 mobile - +1 413 789 3530 AD 06/13/2018: Received the following e-mail from Mr. Simmons: Good Morning Ainura, I would like to provide you an update on the site construction progress and request comments from you and/or have a discussion: " Site Photos attached taken June 12, 2018. " A total of approximately greater than 3,600 tons of impacted soil has gone off-site for recycling/disposal so far during April 23-June 8, 2018. " Construction Development crew is still excavating the site final grade in areas and we are field screening, segregating soil, and collecting post-ex (end-point) base samples once they complete those areas. " Week of June 4 we submitted a group of 13 samples collected at 25 feet below sidewalk grade (the deepest we will excavate anywhere) in the eastern and northeastern-central portions of the Site (beneath the former mid-eastern and northeastern dispenser islands areas removed in 2014). The field screening of these 13 post-excavation samples collected at 25 ranged from 6.0 ppm to 618 ppm. The field screening of soil above this depth from 20 -24 before it was excavated ranged greater than 2,000 ppm. Deeper excavation greater than 25 could not be safely advanced due to risk of sidewalk sidewall shoring undermining and integrity collapse (the excavation got within 7 of the sidewalk wall). " We also collected samples at 21 from the northern and northeastern portions on June 11 and all field screened at 0 ppm. " A vapor barrier will be installed by the contractor. " As previously indicated, it is likely that impacted soil above standards will remain at deeper depths beyond excavation capabilities. All the data will be documented in a report with the purpose of obtaining Spill No. 87-06242 Closure. " Everyone is inquiring whether the NYSDEC has any comment on this work progress, and whether this current 2018 site impacted soil excavation work (3,600+tons), the 2014 impacted soil excavation and disposal of 2,050 tons, vapor barrier installation, along with all the previous historical subsurface data collected from investigations documented in previous reports will be adequate enough to close out Spill No. 87-06242. " The concrete footings and slabs will be poured very soon. Please let me know. Thank you, Bill William A. Simmons - SENIOR PROJECT MANAGER / GEOLOGIST - ATC Group Services LLC +1 413 519 0769 mobile - +1 413 789 3530 main number Called and spoke with Mr. Simmons regarding progress at the site. Asked if the basement is planned for the hotel building and for what it will be used. Bill will find out info on that. Mentioned that based on the labdata, a SSDS might be required for the building. Requested to submit a site plan with locations of the collected soil samples. The update will be

EXXONMOBIL (Continued) **S103824118**

submitted to DEC after soil results will be received by the consultant from the lab. AD 06/27/2019: Received the following e-mail from Mr. Simmons: Good Afternoon, I hope all is well. Please find attached the Remedial Action & Spill No. 8706242 Closure Request for the former Cumberland Farms, Inc. Gasoline Station Facility located at 1550 Bedford Avenue, Brooklyn, New York. Please let me know if you received this report and also if you require it be sent via mail in a different format. Thank you, Bill William A. Simmons - SENIOR PROJECT MANAGER / GEOLOGIST - ATC Group Services LLC +1 413 519 0769 mobile - +1 413 504 1908 direct number Will review. AD 07/19/2019: Reviewed the Remedial Action Report & Spill Closure Request. It states that the site development occurred in 2018 that including construction of a hotel building, and the work that occurred during this development provides a basis for closure. As indicated in a RAP submitted to the NYSDEC dated July 9, 2014, and as concluded in the UST Closure Report, when future Site development commences, CFI and the new Site owner will develop an environmental monitoring and management plan for the excavation and off-site recycling/disposal of any impacted soil encountered. A RAP Report would be prepared that would summarize the additional post-excavation soil quality data, with recommendations for additional remedial actions, if necessary, in order to obtain closure of Spill No. 87-06242. During the period April 23 through October 29, 2018, site development occurred that involved soil excavation across the entire property footprint at depths ranging from a minimum of 12 fbg to a maximum of 25 fbg, all of which was removed from the site for construction of a hotel building. Prior to development, the former one-story building was removed. During the construction activities, shoring was installed along the entire property perimeter (approximate footprint of 192 by 100) that extended up to approximately 2 feet into the sidewalks to the east along Bedford Avenue and to the south along Union Street as the soil excavations advanced vertically. The excavation did not encroach into the sidewalk to the north along Eastern Parkway. During development, ATC was on-site when soil was exposed and excavated in order to field screen the soil and segregate it. Soil was screened with PID with results reported in ppm with a range from 0.1 ppm to 15,000 ppm. Soil that indicated TOV concentrations greater than 10 ppm were considered petroleum impacted and were segregated for off-site disposal. A total of 7,505.82 tons of petroleum-impacted soil was generated for off-site recycling. Approximately 13,500 tons of clean soil generated from the Site was managed by the contractor for off-site disposal. During the development, four (4) abandoned single-wall steel USTs discovered to be full of water on the northeastern portion of the Site were removed. Due to the extensive soil excavation, numerous soil samples were collected for field screening analysis. As indicated in the April 2014 UST Closure Summary Report, of the 53 post-excavation soil samples identified as ID s # s 1-47, 23 were above NYSDEC CP-51 SSCO s at that time. After the 2018 excavations were completed, only four (4) of these original samples ID # s 24, 32, 36 and 39, all of which were not above standards are still considered post-excavation as the areas where these samples were collected were not excavated. All post-excavation soil samples collected during April through October 2018, were analyzed for VOCs according to the NYSDEC Spills Technology and Remediation Series (STARS) List per United States Environmental Protection Agency (USEPA) Method 8260B for gasoline-related compounds. Laboratory certificates of analysis are included as

EXXONMOBIL (Continued) **S103824118**

Attachment VI. ABANDONED USTS REMOVAL APRIL 2018 On April 18, 2018, 4 abandoned single-wall steel USTs were discovered on the northeastern portion of the Site. The tops of the tanks were at approximately 6 fbg and all of these tanks were full of water. On April 19, 2019, Lorco Petroleum Services (Lorco) of New Jersey evacuated approximately 1,343 gallons of water from the tanks. On April 24, 2018, Lorco cleaned the tanks and generated approximately 241 gallons of waste. The tanks were subsequently disposed of as scrap metal by the contractor. The base of the tanks were set at approximately 10-11 fbg. Soil surrounding the tanks indicated TOV concentrations ranging up to 169 ppm. All soil in this portion of the Site were subsequently excavated to a depth of 21 fbg. Soil Data: Evaluation of the sixty (60) post-excavation soil samples collected during the 2014 and 2018 excavations indicates three (3) areas of the site where soil remains above the SSCOs for various VOCs beyond the final depths of the completed excavations. - Eastern-central portion of the Site: Post-excavation sample # s 60, 61, 63, 65, 66, 67 and 68 were all collected at the final depth of 25 fbg with TOV concentrations that ranged from 254-618 ppm. These samples were all collected in the area of the former northeastern-most and eastern-central dispenser islands that were removed in February 2014, and also immediately north of a former tank grave that consisted of six (6) 550-gallon USTs, four (4) of which were removed in September 1992 and two (2) that were removed in February 2014. Total BTEX in these samples ranged from 731 ug/Kg to 169,458 ug/Kg. Total other various VOCs in these samples ranged from 7,973 ug/Kg 188,090 ug/Kg. - Western-Southwestern portion of the Site: Post-excavation sample # s 96 and 97 were collected at the final depths of 10 fbg and 15 fbg, respectively, with TOVs of 5.0 ppm and 3.0 ppm, and 837 ppm, respectively. These samples were collected in the area of the two (2) abandoned waste oil USTs that were removed on March 4, 2014. Samples #96 and #97 were collected along the western sidewalls of the 20 fbg final excavation depth of the former USTs, and the data indicated only benzene concentrations above the SSCOs of 429 ug/Kg and 106 ug/Kg, respectively, and no total other various VOCs. - South-southeastern portion of the Site: Post-excavation sample # s 109 and 113 were collected at the final depths of 24 fbg and 25 fbg, respectively, with TOVs of 1,284 ppm and 233 ppm, respectively. Sample #109 was collected in the area of the former gasoline USTs removed in February 2014 and sample #113 was collected to the south of these former USTs (Figure 3). Sample #109 indicated only total xylenes at 1,170 ug/Kg which is above the SSCO, and total various other VOCs of 7,190 ug/K, none of which were above their respective SSCOs. Sample #113 indicated total BTEX of 156,484 ug/Kg and total other various VOCs of 101,828 ug/Kg. - Of the sixty (60) post-excavation samples, forty-seven (47) indicated no VOCs above the laboratory minimum reporting detection limits (RDLs), and two (2) had low level VOCs below their respective SSCOs. Waste Management Summary: The following is a summary of the waste management for the Site generated in 2014. During February 18 through March 6, 2014, a total of 2,049.98 tons of petroleum-impacted soil generated from the on-site excavations were transported off-site to Clean Earth of Carteret, New Jersey, for recycling. On March 4, 2014 Lorco Petroleum Services (Lorco) of New Jersey, evacuated approximately 1,025 gallons of water from two (2) abandoned tanks and an abandoned drywell. The following is a summary of the waste management for the Site generated in 2018: On April 19, 2018, Lorco evacuated approximately 1,343 gallons of water from the abandoned

EXXONMOBIL (Continued) **S103824118**

550-gallon USTs discovered on the northeastern portion of the Site. On April 24, 2018, Lorco cleaned the tanks and generated approximately 241 gallons of waste fluids. The tanks were disposed of as scrap metal by the construction contractor. During the period April 23 through October 29, 2018, 7,505.82 tons of petroleum-impacted soil generated from the on-site excavations were transported off-site to Clean Earth for recycling. The extensive soil excavations that occurred in 2014 and 2018, generated a total of 9,555.80 tons of petroleum-impacted soil that was disposed of off-site for recycling. An additional approximately 13,500 tons of Site soil was removed from the Site during development by the construction contractor. The final excavations that occurred during development in 2018 ranged from a minimum of 12 fbg to 25 fbg. Vapor barrier: In November 2018, a 20-Mil. vapor barrier was installed below the concrete slab for the entire building. Based on the data presented in this report, ATC does not recommend any additional response or remedial actions at the Site, and requests closure of Spill No. 87-06242. AD 07/30/2019: Discussed the closure request with J. Kolleeny of DER. The following remediation was performed at the site: - In 2014, entire UST system that consisted of the following: five (5) 4,000-gallon double-wall fiberglass gasoline USTs; all associated piping; vent lines; product dispensers; dispenser islands; a concrete tank pad mat; and canopy footings was removed off-site. In addition, four (4) abandoned USTs discovered during petroleum-impacted soil excavation were also removed. A total of 2,049.98 tons of petroleum-impacted soil generated from the on-site excavations were transported off-site to Clean Earth of Carteret, New Jersey, for recycling. - In 2018, a total of 7,505.82 tons of petroleum-impacted soil was generated for off-site recycling. Approximately 13,500 tons of clean soil generated from the Site was managed by the contractor for off-site disposal. During the development, four (4) abandoned single-wall steel USTs discovered to be full of water on the northeastern portion of the Site were removed. - The extensive soil excavations that occurred in 2014 and 2018, generated a total of 9,555.80 tons of petroleum-impacted soil that was disposed of off-site for recycling. An additional approximately 13,500 tons of Site soil was removed from the Site during development by the construction contractor. The final excavations that occurred during development in 2018 ranged from a minimum of 12 fbg to 25 fbg. - Vapor barrier was installed under entire building. - Soil Data: Evaluation of the sixty (60) post-excavation soil samples collected during the 2014 and 2018 excavations indicates that only two post-excavation soil samples collected at depth of 25’ bgs showed BTEX around 150,000 ppb mostly Xylenes and Trimethylbenzene. - Groundwater Data: The depth to regional GW is more than 115’ bds. Attempts to install deep well were unsuccessful. Two site wells MW-1 and MW-2 installed at the site were perched GW wells at 16’ bgs and they never indicated significant levels of TVOCs. The latest data from these wells on 2013 indicated concentrations of benzene at 1.28 ug/L, total xylenes at 8.6 ug/L, MtBE at 24.9 ug/L, and five other various VOCs totaling 51.2 ug/L, with three compounds above the TOGS GWQS in well MW-1, and only MtBE at 18.8 ug/L in MW-2; Based on the extensive site cleanup and most recent soil and groundwater data, it was decided to approve the spill closure request. AD "

Remarks: "4K TANK FAILED WITH A LEAK RATE OF -.131 G/HR. WILL EXCAVATE, AND INVESTIGATE. CONTACT: SUSAN WAINWRIGHT (1-800-992-3647 EXT 5164)"

EXXONMOBIL (Continued) **S103824118**

All TTF:

Facility ID:	8706242
Spill Number:	8706242
Spill Tank Test:	1532021
Site ID:	170296
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	170296
Operable Unit ID:	912278
Operable Unit:	01
Material ID:	465262
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	1550 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9813767 / 2003-10-02
Facility ID:	9813767
Site ID:	78584
Spill Date:	1999-02-11
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1999-02-11
CID:	297
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True

EXXONMOBIL (Continued) **S103824118**

Remediation Phase:	0
Date Entered In Computer:	1999-02-11
Spill Record Last Update:	2005-06-13
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD FAIRFAX
Spiller County:	001
Spiller Contact:	JASON LAVEGLIA
Spiller Phone:	(516) 876-4671
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143297
DEC Memo:	""
Remarks:	"A 4000 GALLON DOUBLE WALL TANK HAS A LEAK IN THE PRIMARY WALL AND EXXON HAS HIRED THE ABOVE COMPANY TO PUMP OUT THE TANK AND RELINE THE INTERIOR WALL OF THE TANK - THERE IS NO CONTAMINATION TO THE GROUND OR SOIL - ALL FUEL CONTAINED IN THE SECONDARY WALL"

All Materials:

Site ID:	78584
Operable Unit ID:	1071306
Operable Unit:	01
Material ID:	310474
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CUMBERLAND FARMS #70219
Address:	1550 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1112318 / 2012-01-26
Facility ID:	1112318
Facility Type:	ER
DER Facility ID:	346746
Site ID:	460252
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2012-01-24
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2012-01-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

EXXONMOBIL (Continued) **S103824118**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-01-24
Spill Record Last Update:	2012-01-26
Spiller Name:	CUMBERLAND FARMS
Spiller Company:	CUMBERLAND FARMS
Spiller Address:	1550 BEDFORD AVE
Spiller Company:	999
Contact Name:	CUMBERLAND FARMS
DEC Memo:	"water in containment - Tyree cleaned it."
Remarks:	"Water in containment area of tank for regular unleaded. Cleanup (Tyree) will be responding to remove water."

All Materials:

Site ID:	460252
Operable Unit ID:	1210342
Operable Unit:	01
Material ID:	2207973
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	1550 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8600769 / 1986-05-01
Facility ID:	8600769
Facility Type:	ER
DER Facility ID:	143297
Site ID:	155458
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1986-05-01
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1986-05-01
CID:	Not reported
Water Affected:	STORM SEWER
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1986-05-01
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-05-28
Spill Record Last Update:	2003-10-02
Spiller Name:	MELISSA MELISSA

EXXONMOBIL (Continued) **S103824118**

Spiller Company: EXXONMOBIL
Spiller Address: 3225 GALLOWS ROAD
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "P.D. & F.D. ON SCENE & FLUSHED TO SEWER"

All Materials:
Site ID: 155458
Operable Unit ID: 897099
Operable Unit: 01
Material ID: 480905
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: EXXONMOBIL
Address: 1550 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0306906 / 2003-10-02
Facility ID: 0306906
Facility Type: ER
DER Facility ID: 143297
Site ID: 193821
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 2003-09-30
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 2003-09-30
CID: 216
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 2003-09-30
Spill Record Last Update: 2003-10-02
Spiller Name: MELISSA WINSOR
Spiller Company: EXXONMOBIL
Spiller Address: 3225 GALLOWS ROAD
Spiller Company: 001
Contact Name: ANDY BOWMAN
DEC Memo: ""
Remarks: "Gas filter leaked has been replaced went into soil at pump 7 and 8 "

EXXONMOBIL (Continued) **S103824118**

All Materials:

Site ID:	193821
Operable Unit ID:	875652
Operable Unit:	01
Material ID:	500522
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	EXXON #7172204
Address:	1550 BEDFORD AV
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0711513 / 2008-02-21
Facility ID:	0711513
Facility Type:	ER
DER Facility ID:	342620
Site ID:	393010
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-01-31
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2008-01-31
CID:	77
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-01
Spill Record Last Update:	2008-02-21
Spiller Name:	Not reported
Spiller Company:	EXXON #7172204
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ART
DEC Memo:	"2/7/08 TTF letter faxed to Cjohnson@cumberlandfarms.com. Spoke to Chris Johnson. Will eget back to me with more info. bf 2/8/08 Sent ttf by mail and fax to: Chris Johnson Cumberland Farms, Inc. 777 Dedham St. Canton, MA 02021 (7810575-9536 Received email from C. Johnson requesting fax of letter. bf 2/21/08 received letter from William A. Simmons of ECS stating the submersible pump was malfunctioning whioch caused the failure. No free product observedin the containment sump. Head was replaced and line tested tight (results attached). NFA. bf"

EXXONMOBIL (Continued) **S103824118**

Remarks: "Caller states doing line test -did not pass. no evidence of spill. Product line is shut down until repairs made and line passes."

All Materials:
Site ID: 393010
Operable Unit ID: 1149986
Operable Unit: 01
Material ID: 2140548
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

Name: CUMBERLAND # 70219
Address: 1550 BEDFORD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0801404 / 2008-05-19
Facility ID: 0801404
Facility Type: ER
DER Facility ID: 346746
Site ID: 397316
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2008-05-05
Investigator: HRAHMED
Referred To: Not reported
Reported to Dept: 2008-05-05
CID: 408
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-05-05
Spill Record Last Update: 2008-05-19
Spiller Name: MELLISSA GLIDDEN
Spiller Company: CUMBERLAND # 70219
Spiller Address: 1550 BEDFORD AVE
Spiller Company: 001
Contact Name: MELLISSA GLIDDEN
DEC Memo: "05/19/08-Hasan Ahmed-Tyree pumped out 15 gallons of gasoline-water mix from the sump. See eDoc for Bill of Lading from Tyree. This case is closed."
Remarks: "WATER IN SUMP; WEATHER RELATED; TYREE WILL HANDLE;"

All Materials:
Site ID: 397316

EXXONMOBIL (Continued) **S103824118**

Operable Unit ID: 1154288
Operable Unit: 01
Material ID: 2145078
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

Name: CUMBERLAND FARMS 70219
Address: 1550 BEDFORD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1214570 / 2013-01-29
Facility ID: 1214570
Facility Type: ER
DER Facility ID: 346746
Site ID: 477816
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2013-01-14
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 2013-01-14
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-01-14
Spill Record Last Update: 2013-01-29
Spiller Name: BRETT VIGNALA
Spiller Company: CUMBERLAND FARMS
Spiller Address: 1550 BEDFORD AVE
Spiller Company: 999
Contact Name: BRETT VIGNALA
DEC Memo: "minor spill (1 cup) contained within a sump. "
Remarks: "1 cup lost to containment sump, c/u and repair pending"

All Materials:
Site ID: 477816
Operable Unit ID: 1227614
Operable Unit: 01
Material ID: 2225040
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum

EXXONMOBIL (Continued) **S103824118**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	1550 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9012713 / 1991-03-12
Facility ID:	9012713
Facility Type:	ER
DER Facility ID:	143297
Site ID:	170297
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1991-03-11
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1991-03-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1991-03-12
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1991-03-13
Spill Record Last Update:	2003-10-02
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SPILL CONTAINED ON PAVEMENT,CONTRACTOR TO REPAIR,VEHICLE PULLED AWAY WITH HOSE IN TANK."

All Materials:

Site ID:	170297
Operable Unit ID:	952484
Operable Unit:	01
Material ID:	429181
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

EXXONMOBIL (Continued) **S103824118**

Name:	EXXONMOBIL
Address:	1550 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9206907 / 2003-10-02
Facility ID:	9206907
Facility Type:	ER
DER Facility ID:	143297
Site ID:	170298
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B1
SWIS:	2401
Spill Date:	1992-09-15
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1992-09-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-09-15
Spill Record Last Update:	2003-10-02
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	170298
Operable Unit ID:	970686
Operable Unit:	01
Material ID:	407593
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

248
South
1/4-1/2
0.384 mi.
2026 ft.

590 FLATBUSH AVE.
590 FLATBUSH AVE
BROOKLYN, NY

NY LTANKS
NY AST
NY LEAD

U001838087
N/A

Relative:
Lower

Actual:
61 ft.

LTANKS:

Name:	590 FLATBUSH AVE.
Address:	590 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9213769 / 1993-03-16
Facility ID:	9213769
Site ID:	311459
Spill Date:	1993-03-05
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1993-03-16
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1993-03-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-03-30
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	MYSTIC AD TRANSPORT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	251284
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"MYSTIC FILLED TANK. SPILL CAME OUT VENT. OIL IS CONTAINED. PETROLEUM TANK TO CLEAN. CLEANED UP TOMORROW."

All Materials:

Site ID:	311459
Operable Unit ID:	977873
Operable Unit:	01
Material ID:	403529
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

590 FLATBUSH AVE. (Continued) **U001838087**

AST:

Name:	FLATBUSH PATIO LLC
Address:	590 FLATBUSH AVE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-309648
Program Type:	PBS
UTM X:	587849.81913
UTM Y:	4501428.18366
Expiration Date:	09/26/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	14124
Affiliation Type:	Facility Operator
Company Name:	FLATBUSH PATIO LLC
Contact Type:	Not reported
Contact Name:	JOHN FORRESTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 469-7700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-04-12

Site Id:	14124
Affiliation Type:	Facility Owner
Company Name:	FLATBUSH PATIO LLC
Contact Type:	MGR
Contact Name:	BENJAMIN BAUM
Address1:	PO BOX 250136
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 469-7700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2016-10-11

Site Id:	14124
Affiliation Type:	Mail Contact
Company Name:	FLATBUSH PATIO LLC
Contact Type:	MGR
Contact Name:	BENJAMIN BAUM
Address1:	PO BOX 250136
Address2:	Not reported
City:	BROOKLYN

590 FLATBUSH AVE. (Continued) **U001838087**

State: NY
Zip Code: 11225
Country Code: 001
Phone: (718) 469-7700
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2016-10-11

Site Id: 14124
Affiliation Type: Emergency Contact
Company Name: FLATBUSH PATIO LLC
Contact Type: Not reported
Contact Name: JOHN FORRESTER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 469-9600
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2011-01-25

Tank Info:

Tank Number: 002
Tank Id: 46671
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1995
Capacity Gallons: 5850
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True

590 FLATBUSH AVE. (Continued) **U001838087**

Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

NYC LEAD:
Name: Not reported
Address: 590 FLATBUSH AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 12147336
Building ID: 292821
Registration ID: 373327
Apartment: 17L
Story: 16
Class: Most Serious
Inspection Date: 12/14/2017
Approved Date: 12/14/2017
Original Certify By Date: 01/17/2018
Original Correct By Date: 01/12/2018
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 5962311
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING, NORTH WALL, SOUTH WALL, EAST WALL, WEST WALL IN THE BATHROOM LOCATED AT APT 17L, 16th STORY, 3rd APARTMENT FROM WEST AT NORTH
NOV Issued Date: 12/15/2017
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 12/22/2017

Name: Not reported
Address: 590 FLATBUSH AVENUE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11252407
Building ID: 292821
Registration ID: 373327
Apartment: 14T
Story: 14
Class: Most Serious
Inspection Date: 05/25/2016
Approved Date: 05/27/2016
Original Certify By Date: 07/03/2016
Original Correct By Date: 06/28/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 5440068
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st WINDOW FRAME FROM EAST AT SOUTH WALL IN THE 1st ROOM FROM EAST AT SOUTH LOCATED AT APT 14T, 14th STORY, 4th APARTMENT FROM EAST AT SOUTH
NOV Issued Date: 05/31/2016

590 FLATBUSH AVE. (Continued) **U001838087**

Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	06/18/2016
Name:	Not reported
Address:	590 FLATBUSH AVENUE
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11252408
Building ID:	292821
Registration ID:	373327
Apartment:	14T
Story:	14
Class:	Most Serious
Inspection Date:	05/25/2016
Approved Date:	05/27/2016
Original Certify By Date:	07/03/2016
Original Correct By Date:	06/28/2016
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	5440068
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st WINDOW FRAME FROM EAST AT SOUTH WALL IN THE 2nd ROOM FROM EAST LOCATED AT APT 14T, 14th STORY, 4th APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	05/31/2016
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	06/18/2016

---

249 **240 CROWN ST CORPORATION** **NY LTANKS** **S103824088**
East **240 CROWN ST** **NY LEAD** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.388 mi.
2050 ft.

Relative: **Higher**

Actual: **104 ft.**

LTANKS:

Name:	240 CROWN ST CORPORATION
Address:	240 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9813545 / 2003-04-14
Facility ID:	9813545
Site ID:	125137
Spill Date:	1999-02-05
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1999-02-05
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

240 CROWN ST CORPORATION (Continued) **S103824088**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-05
Spill Record Last Update:	2003-04-14
Spiller Name:	MIKE BLUTH
Spiller Company:	240 CROWN ST CORPORATION
Spiller Address:	240 CROWN ST
Spiller County:	001
Spiller Contact:	MIKE BLUTH
Spiller Phone:	(718) 851-4829
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	108272
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 9/3/02 - R. AUSTIN - SPOKE WITH ALEX AVERSON OF COSMO ENVIR. - RECEIVED REPORT PREVIOUSLY THAT SHOWED THAT SOIL IN COURTYARD WAS REMOVED DOWN TO SUPPOSED CLAY LAYER. WATER PERCHED ON THIS LAYER. CLEAN SOIL BACKFILLED INTO HOLE. COURTYARD IS SURROUNDED ON THREE SIDES BY BUILDING. AFTER DOING SOME ADDIDTIONAL DIGGING, AVERSON THEN PLACED A SUMP INTO BACK END OF SITE, AND RECOVERED WATER, NO PRODUCT. HE ALSO PLACED TWO WELLS BY THE COURTYARD OPENING. ACCORDING TO AVERSON, NO PRODUCT WAS FOUND IN THOSE WELLS. I REQUESTED THAT HE TAKE DISSOLVED PHASE SAMPLES ROM THE TWO WELLS AND SUMP (SEPARTATE SAMPLES FOR 8270 AND 8041), AND SUBMIT THE RESLTS TO ME. HE INDICATED THAT HE WOULD DO SO. - @ 4/14/2003 Austin forwarded the case to Sangesland for review. Alex Avracen of Cosmos Environmental forwarded groundwater sample results (8021/8270) from this site. Results show Non Detect for everything. Based on the excavation work done at this site and the Non Detect results from the groundwater sampling, this spill is closed. Spill Closed "
Remarks:	"SAMPLE RESULTS SHOWING CONTAMINATED SOIL - TANK REMOVAL SCHEDULED FOR 2/8/99 - ENDPOINT ANALYSIS RESULTS TO FOLLOW TO SPILL DIVISION"

All Materials:

Site ID:	125137
Operable Unit ID:	1073981
Operable Unit:	01
Material ID:	566412
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LEAD:

Name:	Not reported
Address:	240 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	12974229
Building ID:	228366
Registration ID:	320386

240 CROWN ST CORPORATION (Continued) **S103824088**

Apartment:	6D
Story:	6
Class:	Most Serious
Inspection Date:	03/20/2019
Approved Date:	03/22/2019
Original Certify By Date:	04/27/2019
Original Correct By Date:	04/22/2019
New Certify By Date:	05/11/2019
New Correct By Date:	05/06/2019
Certified Date:	05/09/2019
Order Number:	617
NOV ID:	6430215
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE 3rd ROOM FROM EAST LOCATED AT APT 6D, 6th STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	03/25/2019
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	05/17/2019

Name:	Not reported
Address:	240 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	12974230
Building ID:	228366
Registration ID:	320386
Apartment:	6D
Story:	6
Class:	Most Serious
Inspection Date:	03/20/2019
Approved Date:	03/22/2019
Original Certify By Date:	04/27/2019
Original Correct By Date:	04/22/2019
New Certify By Date:	05/11/2019
New Correct By Date:	05/06/2019
Certified Date:	05/09/2019
Order Number:	617
NOV ID:	6430215
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL IN THE 1st ROOM FROM EAST AT NORTH LOCATED AT APT 6D, 6th STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	03/25/2019
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	05/17/2019

250
NNE
1/4-1/2
0.389 mi.
2052 ft.

APRT BUILDINGS
362 EASTERN PARK WAY
BROOKLYN, NY

NY LTANKS **S106124015**
N/A

Relative:
Higher

Actual:
141 ft.

LTANKS:

Name:	APRT BUILDINGS
Address:	362 EASTERN PARK WAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0311838 / 2006-01-05
Facility ID:	0311838
Site ID:	81207
Spill Date:	2004-01-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2004-01-21
CID:	402
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-21
Spill Record Last Update:	2006-01-06
Spiller Name:	HENRY BEO
Spiller Company:	APRT BUILDINGS
Spiller Address:	362 EASTERN PARK WAY
Spiller County:	001
Spiller Contact:	HENRY BEO
Spiller Phone:	(718) 221-5295
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	75153
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER sent TTF letter 12/16/05- DEC Piper- Previous owner to inform new owner to contact DEC. The tank is 1080 gallons, Peter Samet 718.604.8484 will send info on abandonment. 12/23/05- DEC Piper Subsurface investigation warranted due to tank test failure and abandonment 1 1/2 + yrs apart. 1/5/06- DEC Piper reviewed info sent. Sufficient documentation received to close spill. <1100 gal tank. Legally abandoned by ABC tank."
Remarks:	""

All TTF:

Facility ID:	0311838
Spill Number:	0311838
Spill Tank Test:	1528930
Site ID:	81207
Tank Number:	1
Tank Size:	1
Material:	0001
EPA UST:	Not reported

APRT BUILDINGS (Continued) **S106124015**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	81207
Operable Unit ID:	879437
Operable Unit:	01
Material ID:	497081
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

251
SE
1/4-1/2
0.413 mi.
2180 ft.

SPILL NUMBER 0313756 **NY LTANKS** **S106385611**
197 MAPLE STREET **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
62 ft.

LTANKS:

Name:	SPILL NUMBER 0313756
Address:	197 MAPLE STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0313756 / 2004-04-20
Facility ID:	0313756
Site ID:	160338
Spill Date:	2004-03-16
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2004-04-20

SPILL NUMBER 0313756 (Continued) **S106385611**

Spiller Name:	VINNIE S.
Spiller Company:	APPROVED OIL CO.
Spiller Address:	6751 5TH AVE
Spiller County:	001
Spiller Contact:	SABRINA
Spiller Phone:	(718) 282-9070
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	135409
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 3/16/2004 Sangesland spoke to Mrs. Phailtos (homeowner). Approved Oil made a miss delivery to her house. Spill into her basement. New ceramic floor and sheetrock wall impacts. Sangesland called oil company, Oil Insurance Comp. and eventually Tristate Enviornmental. Site visit scheduled on site for 3/17 3PM with Krimgold and Lisa from Tristate. 3/17/04. J.Krimgold at site. Initial spill containment was done by FDNY Haz Mat Unit. FDNY applied absorbent and called Approved Oil (as a suspected spiller) to perform a cleanup. On 3/16/04 around 6:00 am Approved Oil Co. attempted oil delivery to this address instead of 195 Maple Street. The house is on gas and doesn't have an oil tank. However, the fill port was not properly closed and fill line opened to the basement. About 10-15 gallons spilled in the basement and oil covered about 2/3 of basement floor (based on a stain observation). Approved Oil did not reported a spill to DEC. Bulk of oil was removed with absorbent, but strong oil smell is still present. Also, observed oil stains on the part of a baseboard and floor ceramic tiles throughout basement. Tri-State will remove contaminated baseboard and if necessary part of a drywall. They also will powerwash basement tile floor and examine and if necessary clean sewer access vault. Additional info: Insurance carrier for Approved Oil - City Underwriter (Vinnie Franco @ 516-358-3509) Consultant for City Underwriter - Action Environmental (Gil Roland @ 704-394-6913). Contractor - Tri-State Env. (Lisa @ 914-589-8418). YK. 4/5/04. J.Krimgold called Gil Rolland and requested info regarding cleanup. According to Mr. Roland cleanup has been completed. He suggested that a letter from Action Env. will be submitted to DEC on 4/9/04. Also left a massege for Sabrina Philson to confirm the cleanup. 4/20/04. J.Krimgold reviewed a letter report submitted by Action Env. dated April 12, 2004. Cleanup has been completed by Tri-State. Non-Haz. Manifest enclosed. NFA."
Remarks:	"CALLER STATES SHE DOES NOT HAVE AN OIL TANK AND OIL; CO. MISTAKLEN DELIVERED OIL TOP HER INSTEAD OF HER NIEGHBOR BUT CAUGHT IT QUICKLY AND FIRE CO AN\\D OIL CO. CLEANED IT UP. wants someone to come and see if the clean up job was done right because she casn still smell the odors"

All Materials:

Site ID:	160338
Operable Unit ID:	879042
Operable Unit:	01
Material ID:	495347
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00

SPILL NUMBER 0313756 (Continued) **S106385611**

Oxygenate: Not reported

252
SSE
1/4-1/2
0.414 mi.
2187 ft.

1880 BEDFORD AVE
1880 BEDFORD AVE
BROOKLYN, NY

NY LTANKS **S118953753**
N/A

Relative:
Lower

Actual:
64 ft.

LTANKS:

Name:	1880 BEDFORD AVE
Address:	1880 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9211937 / 1993-01-19
Facility ID:	9211937
Site ID:	192657
Spill Date:	1993-01-19
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1993-01-19
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1993-01-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-28
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	160640
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"CONTAINED ON CONCRETE FLOOR IN BASEMENT -CLEANUP IN PROGRESS,CALLED BORO FUEL OIL AND CONFIRMED CLEANUP ONLY A SLIGHT LEAK FROM THE FITTING OF THE TANK 12-275 GALS HAS BEEN REPAIRED"

All Materials:

Site ID:	192657
Operable Unit ID:	978842
Operable Unit:	01
Material ID:	405321
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

1880 BEDFORD AVE (Continued) **S118953753**

Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

253
North
1/4-1/2
0.416 mi.
2195 ft.

263-321 EASTERN PKWY/BKLY **NY LTANKS** **S106703339**
263-321 EASTERN PARKWAY **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
141 ft.

LTANKS:

Name:	263-321 EASTERN PKWY/BKLY
Address:	263-321 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8903427 / 1989-10-01
Facility ID:	8903427
Site ID:	149233
Spill Date:	1989-07-05
Spill Cause:	Tank Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1989-07-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-07-06
Spill Record Last Update:	2004-08-23
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	126971
DEC Memo:	""
Remarks:	"CONSTRUCTION COMPANY DOING WORK IN AREA DAMAGED FILL PIPE, WATER GOT INTO TANK CAUSING AN APPARENT OVERFLOW INTO BASEMENT & ONTO STREET."

All TTF:

Facility ID:	8903427
Spill Number:	8903427
Spill Tank Test:	1535680
Site ID:	149233
Tank Number:	Not reported

263-321 EASTERN PKWY/BKLY (Continued) **S106703339**

Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	149233
Operable Unit ID:	928840
Operable Unit:	01
Material ID:	447522
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2500.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

254 **271 SULLIVAN PLACE** **NY LTANKS** **U003386994**
East **271 SULLIVAN PLACE** **NY AST** **N/A**
1/4-1/2 **BROOKLYN, NY** **NY LEAD**
0.420 mi.
2215 ft.

Relative:
Lower

Actual:
86 ft.

LTANKS:

Name:	271 SULLIVAN PLACE
Address:	271 SULLIVAN PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9415727 / 1995-03-04
Facility ID:	9415727
Site ID:	199271
Spill Date:	1995-03-04
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	1995-03-04
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1995-03-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False

271 SULLIVAN PLACE (Continued) **U003386994**

Remediation Phase:	0
Date Entered In Computer:	1995-04-12
Spill Record Last Update:	1995-04-21
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU OIL
Spiller Address:	740 JAMAICA AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	165859
DEC Memo:	""
Remarks:	"CLEANED UP THE SPILL WITH SPEEDY DRY."

All Materials:

Site ID:	199271
Operable Unit ID:	1009175
Operable Unit:	01
Material ID:	370900
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

AST:

Name:	271 SULLIVAN PLACE REALTY LLC
Address:	271 SULLIVAN PLACE
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-235350
Program Type:	PBS
UTM X:	588576.80544
UTM Y:	4502069.13950
Expiration Date:	02/01/2022
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8666
Affiliation Type:	Mail Contact
Company Name:	KENSINGTON REALTY MANAGEMENT LLC
Contact Type:	Not reported
Contact Name:	JOSEPH ESSES
Address1:	190 KENSINGTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11235
Country Code:	001
Phone:	(646) 306-8536
EMail:	JMESSES@GMAIL.COM

271 SULLIVAN PLACE (Continued) **U003386994**

Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-08-15

Site Id:	8666
Affiliation Type:	Facility Operator
Company Name:	271 SULLIVAN PLACE REALTY LLC
Contact Type:	Not reported
Contact Name:	NONE LISTED
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	NONE LISTED
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-08-15

Site Id:	8666
Affiliation Type:	Emergency Contact
Company Name:	SULLIVAN CROWN LLC
Contact Type:	Not reported
Contact Name:	FRANKLIN HERNANDEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 488-4389
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-03-16

Site Id:	8666
Affiliation Type:	Facility Owner
Company Name:	SULLIVAN CROWN LLC
Contact Type:	MANAGING AGENT
Contact Name:	JOSEPH ESSES
Address1:	458 AVENUE T
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11223
Country Code:	001
Phone:	(718) 375-0002
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-08-15

Tank Info:

271 SULLIVAN PLACE (Continued) **U003386994**

Tank Number: 001
Tank Id: 11052
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/07/2005
Capacity Gallons: 3000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

NYC LEAD:
Name: Not reported
Address: 271 SULLIVAN PLACE
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 11233232
Building ID: 379130
Registration ID: 327113
Apartment: 1D
Story: 1
Class: Most Serious
Inspection Date: 05/07/2016
Approved Date: 05/12/2016
Original Certify By Date: 06/15/2016
Original Correct By Date: 06/10/2016
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 617
NOV ID: 5428924
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, SOUTH WALL, EAST WALL IN THE 1st ROOM FROM EAST LOCATED AT APT 1D, 1st STORY, 1st APARTMENT FROM WEST AT NORTH

271 SULLIVAN PLACE (Continued) **U003386994**

NOV Issued Date:	05/13/2016
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	06/23/2017
Name:	Not reported
Address:	271 SULLIVAN PLACE
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11233233
Building ID:	379130
Registration ID:	327113
Apartment:	1D
Story:	1
Class:	Most Serious
Inspection Date:	05/07/2016
Approved Date:	05/12/2016
Original Certify By Date:	06/15/2016
Original Correct By Date:	06/10/2016
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	5428924
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE 3rd ROOM FROM EAST LOCATED AT APT 1D, 1st STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date:	05/13/2016
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	06/23/2017
Name:	Not reported
Address:	271 SULLIVAN PLACE
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	11691222
Building ID:	379130
Registration ID:	327113
Apartment:	1D
Story:	1
Class:	Most Serious
Inspection Date:	03/10/2017
Approved Date:	03/14/2017
Original Certify By Date:	04/17/2017
Original Correct By Date:	04/12/2017
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	5705008
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE 4th KITCHEN FROM EAST LOCATED AT APT 1D, 1st STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	03/15/2017

271 SULLIVAN PLACE (Continued) **U003386994**

Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 06/23/2017

255
NE
1/4-1/2
0.424 mi.
2238 ft.

426 EASTERN PARKWAY
426 EASTERN PARKWAY
BROOKLYN, NY 11225

NY LTANKS **U000404805**
NY UST **N/A**
NY LEAD

Relative:
Higher

Actual:
141 ft.

LTANKS:

Name:	APRT
Address:	426 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0708102 / 2007-11-13
Facility ID:	0708102
Site ID:	388939
Spill Date:	2007-10-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-10-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-24
Spill Record Last Update:	2007-11-13
Spiller Name:	STEVE FOX
Spiller Company:	APRT
Spiller Address:	426 EASTERN PARKWAY
Spiller County:	001
Spiller Contact:	STEVE FOX
Spiller Phone:	(718) 941-1300
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	338501
DEC Memo:	"10/29/07 bf: Called Steven Fox at (718)941-1300 and left kmessage. Sent ttf letter to: Steven Fox 426 Realty LLC 1110 Flatbush Avenue Brooklyn, NY 11226 10/30/07 Spoke with S. Fox yesterday. He said the technician did not seal the second fill line and therefore could not get a vacuum on the tank. Technician was unaware of the second fill line. Tanknolgy will return tomorrow to retest. I confimed S. Fox's address and told him I will be sending a letter and testing contractor will have to respond. bf 11/1/07 Received message from Camilla of Tanknology (413)572-1900. She told me that the tank was retseted and passed. As Mr. Fox tolfd me yesterday, there was a remote fill that was not found during first test. I told her I need a ttf response and a copy of the passing tank test. She will get it out to me today. bf 11/13/07 Received letter and passing tank test report

426 EASTERN PARKWAY (Continued) **U000404805**

	from Geoff Brock of Tanknology. Letter explains that a vehicle was parked over a remote fill which cqause the ullage ingress. NFA. bf"
Remarks:	"ULIDGE ABOVE PRODUCT: ISOLATE AND RETEST"

All TTF:

Facility ID:	0708102
Spill Number:	0708102
Spill Tank Test:	1815691
Site ID:	388939
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	99
Source:	99
Test Method:	14
Test Method 2:	VacuTest
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	388939
Operable Unit ID:	1146092
Operable Unit:	01
Material ID:	2136455
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	426 EASTERN PARKWAY
Address:	426 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11225
Id/Status:	2-399140 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/15/2023
UTM X:	588388.70788
UTM Y:	4502615.41846
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	18995
Affiliation Type:	Facility Operator
Company Name:	426 EASTERN PARKWAY
Contact Type:	Not reported
Contact Name:	TREVOR

426 EASTERN PARKWAY (Continued) **U000404805**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 522-5111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-08-09

Site Id:	18995
Affiliation Type:	Emergency Contact
Company Name:	CITADEL ESTATES
Contact Type:	Not reported
Contact Name:	ZOHAR SIRI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 522-5111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2011-08-09

Site Id:	18995
Affiliation Type:	Facility Owner
Company Name:	CITADEL ESTATES LLC
Contact Type:	MANAGER
Contact Name:	SIRIZOHAR SIRI
Address1:	PO BOX 24688
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11202
Country Code:	001
Phone:	(718) 522-5111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-06-04

Site Id:	18995
Affiliation Type:	Mail Contact
Company Name:	CITADEL ESTATES
Contact Type:	Not reported
Contact Name:	ZO SIRI
Address1:	PO BOX 24688
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11202
Country Code:	001

426 EASTERN PARKWAY (Continued) **U000404805**

Phone:	(718) 522-5111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-10-05

Tank Info:

Tank Number:	001
Tank ID:	21597
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	01/01/1930
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	04/02/2022
Next Test Date:	04/02/2023
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

NYC LEAD:

Name:	Not reported
Address:	426 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	12686998
Building ID:	287823
Registration ID:	311419
Apartment:	2E
Story:	2
Class:	Most Serious
Inspection Date:	10/19/2018
Approved Date:	10/20/2018
Original Certify By Date:	11/24/2018
Original Correct By Date:	11/19/2018
New Certify By Date:	12/22/2018

426 EASTERN PARKWAY (Continued) **U000404805**

New Correct By Date: 12/17/2018
Certified Date: 12/21/2018
Order Number: 617
NOV ID: 6262420
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 2nd DOOR FROM SOUTH AT WEST WALL IN THE 4th ROOM FROM NORTH LOCATED AT APT 2E, 2nd STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date: 10/22/2018
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 12/26/2018

Name: Not reported
Address: 426 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 15242616
Building ID: 287823
Registration ID: 311419
Apartment: 1D
Story: 1
Class: Most Serious
Inspection Date: 06/28/2022
Approved Date: 06/28/2022
Original Certify By Date: 07/28/2022
Original Correct By Date: 07/23/2022
New Certify By Date: 08/11/2022
New Correct By Date: 08/06/2022
Certified Date: Not reported
Order Number: 617
NOV ID: 7956154
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) EAST WALL IN THE FOYER LOCATED AT APT 1D, 1st STORY, 2nd APARTMENT FROM NORTH AT EAST , SECTION ''EAST''
NOV Issued Date: 06/29/2022
Current Status ID: 28
Current Status: INVALID CERTIFICATION
Current Status Date: 07/27/2022

Name: Not reported
Address: 426 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 15242617
Building ID: 287823
Registration ID: 311419
Apartment: 1D
Story: 1
Class: Most Serious
Inspection Date: 06/28/2022
Approved Date: 06/28/2022
Original Certify By Date: 07/28/2022
Original Correct By Date: 07/23/2022
New Certify By Date: 08/11/2022
New Correct By Date: 08/06/2022

426 EASTERN PARKWAY (Continued) **U000404805**

Certified Date: Not reported
Order Number: 617
NOV ID: 7956154
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM NORTH AT EAST WALL DOOR FRAME, 2nd CLOSET FROM NORTH AT EAST WALL DOOR FRAME, 1st DOOR FRAME FROM EAST AT SOUTH WALL IN THE PRIVATE HALLWAY LOCATED AT APT 1D, 1st STORY, 2nd APARTMENT FROM NORTH AT EAST , SECTION ''EAST''
NOV Issued Date: 06/29/2022
Current Status ID: 28
Current Status: INVALID CERTIFICATION
Current Status Date: 07/27/2022

Name: Not reported
Address: 426 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 15242618
Building ID: 287823
Registration ID: 311419
Apartment: 1D
Story: 1
Class: Most Serious
Inspection Date: 06/28/2022
Approved Date: 06/28/2022
Original Certify By Date: 07/28/2022
Original Correct By Date: 07/23/2022
New Certify By Date: 08/11/2022
New Correct By Date: 08/06/2022
Certified Date: Not reported
Order Number: 617
NOV ID: 7956154
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FROM EAST AT SOUTH WALL, 1st DOOR FRAME FROM EAST AT SOUTH WALL IN THE BATHROOM LOCATED AT APT 1D, 1st STORY, 2nd APARTMENT FROM NORTH AT EAST , SECTION ''EAST''
NOV Issued Date: 06/29/2022
Current Status ID: 28
Current Status: INVALID CERTIFICATION
Current Status Date: 07/27/2022

Name: Not reported
Address: 426 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11225
Violation ID: 15435537
Building ID: 287823
Registration ID: 311419
Apartment: 5D
Story: 5
Class: Most Serious
Inspection Date: 10/15/2022
Approved Date: 10/16/2022
Original Certify By Date: 11/15/2022
Original Correct By Date: 11/10/2022

426 EASTERN PARKWAY (Continued) **U000404805**

New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	8073942
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DUMB WAITER FROM SOUTH AT WEST WALL IN THE KITCHEN LOCATED AT APT 5D, 5th STORY, 5th APARTMENT FROM WEST AT NORTH
NOV Issued Date:	10/17/2022
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	10/17/2022

AJ256 **SOIL** **NY LTANKS S105998410**
NNW **200 EASTERN PARKWAY** **NY Spills N/A**
1/4-1/2 **BROOKLYN, NY 11238**
0.426 mi.
2249 ft. **Site 1 of 2 in cluster AJ**

Relative: **Higher**

Actual: **153 ft.**

LTANKS:

Name:	BROOKLYN MUSEUM
Address:	200 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0212402 / 2007-05-23
Facility ID:	0212402
Site ID:	284900
Spill Date:	2003-03-17
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2003-03-17
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-17
Spill Record Last Update:	2007-05-23
Spiller Name:	NORMAN
Spiller Company:	BROOKLYN MUSEUM
Spiller Address:	200 EASTERN PARKWAY
Spiller County:	001
Spiller Contact:	NORMAN
Spiller Phone:	(718) 501-6456
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	231027
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 3/17/2003 Zhao/DO: TTF letter sent. 1/7/04-Vought-Spill

SOIL (Continued) **S105998410**

transferred from Vought to Austin. 01/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 12/16/05- DEC Piper spoke w/ Alexenader, Chief Engineer for the Museum, Norman no longer works there. Alex will sent info via fax. 2/16/06- DEC Piper left message for Alex requesting info, callback. 5/8/06- DEC Piper left message for Alex requesting info, callback. 4/30/07- DEC Piper left message for Alex requesting info, callback. 5/3/07- DEC Piper spoke w/. Alex. Alex stated failure was due to an error by contractor. He will submit documentation or have tester contact DEC. 5/21/07- PAssing test results reseived for MAy 20, 2003. Spill closed."

Remarks: "no comments"

All TTF:

Facility ID:	0212402
Spill Number:	0212402
Spill Tank Test:	1528101
Site ID:	284900
Tank Number:	1
Tank Size:	20000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	284900
Operable Unit ID:	865865
Operable Unit:	01
Material ID:	512138
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SOIL
Address:	200 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11238
Spill Number/Closed Date:	0901162 / 2009-05-18
Facility ID:	0901162
Facility Type:	ER
DER Facility ID:	22825
Site ID:	413132
DEC Region:	2
Spill Cause:	Equipment Failure

SOIL (Continued) **S105998410**

Spill Class:	C4
SWIS:	2401
Spill Date:	2009-04-28
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2009-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-28
Spill Record Last Update:	2009-05-18
Spiller Name:	Not reported
Spiller Company:	FUEL OIL TANK REMOVAL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SAME AS ABOVE
DEC Memo:	"** PBS-2-600929** 05/01/09 CSL was sent to (as per PBS record) Brooklyn Museum 200 Eastern Parkway Brooklyn, NY 11238 Attn: Alexander Serkov (sr) 05/12/09 Spoke with Frantz Vincent,facility representative as per PBS.CSL was faxed @(718)501-6132 to Planning Dept as Frantz suggested.(sr) ** Rec'd call from Ann Webster@(718)501-6206.She indicated that things are moving ahead.Tank is being replaced followed by removal of contamination.** 05/18/09 Rec'd closure report. One 2,500 gallon UST was removed followed by end point analyticals from tank bottom and sidewalls. Results showed VOC/SVOCs were within TAGM limit except some svocs exceedances.PID reading was 00.00 as per the report.No contaminated soil was removed as soil contamination was not above the regulatory limit.I told Ann Webster that PBS record will have to be updated as tank was removed and a new tank will be installed.Tank excavation will be backfilled in few days.Excavation was 15x20 and approx 12 feet deep.Ground water was not encountered.Report in edocs.Case closed.(sr)"
Remarks:	"tank removal from the brooklyn museum of art. Paul Hatcher received the spill results back today which showed that the soil was contaminated."

All Materials:

Site ID:	413132
Operable Unit ID:	1169579
Operable Unit:	01
Material ID:	2161237
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SOIL (Continued) **S105998410**

Name:	BROOKLYN MUSUEM
Address:	200 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0210130 / 2008-02-14
Facility ID:	0210130
Facility Type:	ER
DER Facility ID:	231027
Site ID:	284899
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-01-06
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2003-01-07
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-07
Spill Record Last Update:	2008-02-14
Spiller Name:	ROBERT PAIGE
Spiller Company:	BROOKLYN MUSUEM
Spiller Address:	200 EASTERN PARKWAY
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"01/24/2006 Kuldeep has called1-914-804-5436 and left message to call back. return to Region 2- Kuldeep Gupta. Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO CALLED ROBERT PAIGE, WHO CONFIRMED THE PRESENCE OF THE DIRTY-DIRT HE AGREED THAT THE DIRTY-DIRT LETTER SHOULD BE SENT TO HIM. SO, LETTER WAS PREPARED AND SENT 1/8/03. E.R. 1/24/03 - AUSTIN, DDO - RECD. CALL FROM DEAN PEARCE OF TESTWELL LABS (914-804-5436 - CELL) - PROVIDED STATUS REPORT THAT EXCAVATION OF CONTAM. SOILS WAS OCCURRING TODAY AT THIS LOCATION - HARD COPY OF THIS UPDATE CONVEYED TO DEMEO. 2/26/03 TJD Report summarizing remedial activities performed sent by Testwell laboratories. SVOC contamination above TAGM identified. DeMeo left message for Dean Pierce (Testwell) to discuss results. DECP iper - I received passing tightness test from owner. Minor SVOC exceedances. This spill is closed."
Remarks:	"soil samples set out for testing came back and show contamination unk cause or sorce construction work is underway at the sight"

All Materials:

Site ID:	284899
Operable Unit ID:	863340
Operable Unit:	01
Material ID:	562923
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported

SOIL (Continued) **S105998410**

Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

257
NNE
1/4-1/2
0.436 mi.
2300 ft.

PVT DWELLING
552 LINCOLN PLACE
BROOKLYN, NY

NY LTANKS **S104650159**
NY Spills **N/A**

Relative:
Higher

Actual:
129 ft.

LTANKS:
Name: PVT DWELLING
Address: 552 LINCOLN PLACE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0906646 / 2013-04-17
Facility ID: 0906646
Site ID: 418995
Spill Date: 2009-09-10
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 2009-09-10
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2009-09-10
Spill Record Last Update: 2013-04-17
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: MARLIN JOESEPH
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 368119
DEC Memo: "09/10/09 Sharif spoke with Marlin Joseph.He indicated that the leak is at air vent,going into the building.No spill of oil.PTC will perform isolation test and will be able to identify any other problem on the tank system.(sr) 9-22-2011- ttf letter sent 4/17/13- DEC Piper reviewed csae. TTF was a n air leak. No spill of petroleum. Case closed."
Remarks: "bad pipes...no loss of product"

All Materials:
Site ID: 418995

PVT DWELLING (Continued) **S104650159**

Operable Unit ID: 1175147
Operable Unit: 01
Material ID: 2167693
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Name: SPILL NUMBER 9911924
Address: 552 LINCOLN PL
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9911924 / 2000-02-22
Facility ID: 9911924
Facility Type: ER
DER Facility ID: 151611
Site ID: 180759
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2000-01-14
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 2000-01-14
CID: 211
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-01-14
Spill Record Last Update: 2000-02-22
Spiller Name: SAMPSON RES
Spiller Company: Not reported
Spiller Address: 552 LINCOLN PL
Spiller Company: 001
Contact Name: SAMPSON RES
DEC Memo: ""
Remarks: "no vent alarm on system / causing spill - spill contained - clean up crew enroute"

All Materials:
Site ID: 180759
Operable Unit ID: 1090628
Operable Unit: 01
Material ID: 297359
Material Code: 0001A

PVT DWELLING (Continued) **S104650159**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

258
East
1/4-1/2
0.439 mi.
2319 ft.

250 CROWN STREET
BROOKLYN, NY 11225

NY LTANKS **S106737544**
NY LEAD **N/A**

Relative:
Higher

Actual:
104 ft.

LTANKS:

Name:	250 CROWN STREET
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0410100 / 2006-03-01
Facility ID:	0410100
Site ID:	335090
Spill Date:	2004-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SXSCHARF
Referred To:	Not reported
Reported to Dept:	2004-12-10
CID:	409
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-13
Spill Record Last Update:	2006-03-01
Spiller Name:	POPACK
Spiller Company:	Not reported
Spiller Address:	250 CROWN STREET
Spiller County:	001
Spiller Contact:	POPACK
Spiller Phone:	(718) 953-3379
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	270310
DEC Memo:	"ttf ltr sent 1/14/2005 10/20/05-Spoke to Bernie at Tank test. He will get back to me on the repair.- S. Scharf 12/05- received a fax from New york City Tank testing Inc. -Abraham Wachsler- Tank was tested after repairs and passed test. Close Spill. -S. Scharf"
Remarks:	""

All TTF:

Facility ID:	0410100

(Continued) **S106737544**

Spill Number:	0410100
Spill Tank Test:	1548399
Site ID:	335090
Tank Number:	Not reported
Tank Size:	7000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

NYC LEAD:

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	13767750
Building ID:	228367
Registration ID:	309785
Apartment:	2II
Story:	2
Class:	Most Serious
Inspection Date:	08/15/2020
Approved Date:	08/16/2020
Original Certify By Date:	09/15/2020
Original Correct By Date:	09/10/2020
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6931540
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM EAST AT SOUTH WALL DOOR FRAME IN THE 3rd ROOM FROM NORTH LOCATED AT APT 2II, 2nd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	08/17/2020
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/19/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	13767748
Building ID:	228367
Registration ID:	309785
Apartment:	2II
Story:	2
Class:	Most Serious

(Continued) **S106737544**

Inspection Date:	08/15/2020
Approved Date:	08/16/2020
Original Certify By Date:	09/15/2020
Original Correct By Date:	09/10/2020
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6931540
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM NORTH AT EAST WALL IN THE FOYER LOCATED AT APT 2II, 2nd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	08/17/2020
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/19/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	13767749
Building ID:	228367
Registration ID:	309785
Apartment:	2II
Story:	2
Class:	Most Serious
Inspection Date:	08/15/2020
Approved Date:	08/16/2020
Original Certify By Date:	09/15/2020
Original Correct By Date:	09/10/2020
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6931540
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM WEST AT NORTH WALL IN THE KITCHEN LOCATED AT APT 2II, 2nd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	08/17/2020
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/19/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708736
Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021

(Continued) **S106737544**

Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) BASEBOARD AT NORTH WALL, 1st DOOR FRAME FROM EAST AT SOUTH WALL, 1st DOOR FRAME FROM NORTH AT EAST WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL, 2nd WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 2nd ROOM FROM NORTH AT WEST LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708737
Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM EAST AT SOUTH WALL, 1st DOOR FRAME FROM NORTH AT EAST WALL, 2nd WALL CABINET FROM WEST AT NORTH WALL, 1st WALL CABINET FROM SOUTH AT WEST WALL IN THE KITCHEN LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14092178
Building ID:	228367
Registration ID:	309785

(Continued) **S106737544**

Apartment:	2H
Story:	2
Class:	Most Serious
Inspection Date:	03/19/2021
Approved Date:	03/26/2021
Original Certify By Date:	04/27/2021
Original Correct By Date:	04/22/2021
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	7133574
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE KITCHEN LOCATED AT APT 2H, 2nd STORY, 3rd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	03/29/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/19/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14092177
Building ID:	228367
Registration ID:	309785
Apartment:	2H
Story:	2
Class:	Most Serious
Inspection Date:	03/19/2021
Approved Date:	03/26/2021
Original Certify By Date:	04/27/2021
Original Correct By Date:	04/22/2021
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	7133574
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE BATHROOM LOCATED AT APT 2H, 2nd STORY, 3rd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	03/29/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/19/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708732
Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5

(Continued) **S106737544**

Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) BASEBOARD AT SOUTH WALL, 1st CLOSET FROM NORTH AT EAST WALL DOOR FRAME, 1st DOOR FRAME FROM NORTH AT EAST WALL IN THE FOYER LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022
Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708740
Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM SOUTH AT WEST WALL IN THE 4th BATHROOM FROM NORTH AT CENTER LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022
Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	12031787
Building ID:	228367
Registration ID:	309785
Apartment:	1H

(Continued) **S106737544**

Story:	1
Class:	Most Serious
Inspection Date:	10/22/2017
Approved Date:	10/23/2017
Original Certify By Date:	11/25/2017
Original Correct By Date:	11/20/2017
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	5878595
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL, EAST WALL IN THE KITCHEN LOCATED AT APT 1H, 1st STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	10/23/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	04/05/2022
Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708735
Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM EAST AT SOUTH WALL, 1st RADIATOR FROM SOUTH AT WEST WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL, 2nd WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 3rd ROOM FROM NORTH AT WEST LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022
Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	15105037
Building ID:	228367
Registration ID:	309785

(Continued) **S106737544**

Apartment:	I2
Story:	2
Class:	Most Serious
Inspection Date:	04/06/2022
Approved Date:	04/09/2022
Original Certify By Date:	05/10/2022
Original Correct By Date:	05/05/2022
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	04/29/2022
Order Number:	616
NOV ID:	7871058
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE 1st ROOM FROM NORTH LOCATED AT APT I2, 2nd STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''270'', 1st FROM SOUTH AT WEST
NOV Issued Date:	04/11/2022
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	05/11/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	13767751
Building ID:	228367
Registration ID:	309785
Apartment:	2II
Story:	2
Class:	Most Serious
Inspection Date:	08/15/2020
Approved Date:	08/16/2020
Original Certify By Date:	09/15/2020
Original Correct By Date:	09/10/2020
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6931540
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM NORTH AT EAST WALL IN THE BATHROOM LOCATED AT APT 2II, 2nd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	08/17/2020
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/19/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708741
Building ID:	228367
Registration ID:	309785
Apartment:	5F

(Continued) **S106737544**

Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM SOUTH AT WEST WALL IN THE 3rd BATHROOM FROM NORTH AT EAST LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708734
Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM NORTH AT EAST WALL DOOR FRAME, 1st DOOR FRAME FROM NORTH AT EAST WALL, 1st WINDOW FRAME FROM EAST AT SOUTH WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 4th ROOM FROM NORTH AT WEST LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708738

(Continued) **S106737544**

Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) BASEBOARD AT EAST WALL, 2nd CLOSET FROM SOUTH AT WEST WALL DOOR FRAME, 1st DOOR FRAME FROM WEST AT NORTH WALL, 1st RADIATOR FROM EAST AT SOUTH WALL, 1st WINDOW FRAME FROM EAST AT SOUTH WALL IN THE 4th ROOM FROM NORTH AT EAST LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	14708739
Building ID:	228367
Registration ID:	309785
Apartment:	5F
Story:	5
Class:	Most Serious
Inspection Date:	11/22/2021
Approved Date:	12/01/2021
Original Certify By Date:	12/31/2021
Original Correct By Date:	12/26/2021
New Certify By Date:	01/14/2022
New Correct By Date:	01/09/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7564320
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM EAST AT SOUTH WALL DOOR FRAME, 2nd CLOSET FROM EAST AT SOUTH WALL DOOR FRAME, 1st DOOR FRAME FROM EAST AT SOUTH WALL, 1st WINDOW FRAME FROM NORTH AT EAST WALL IN THE 2nd ROOM FROM NORTH AT EAST LOCATED AT APT 5F, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	12/02/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/13/2022

(Continued) **S106737544**

Name:	Not reported
Address:	250 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Violation ID:	13767747
Building ID:	228367
Registration ID:	309785
Apartment:	2II
Story:	2
Class:	Most Serious
Inspection Date:	08/15/2020
Approved Date:	08/16/2020
Original Certify By Date:	09/15/2020
Original Correct By Date:	09/10/2020
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6931540
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM EAST AT SOUTH WALL DOOR FRAME, 1st DOOR FRAME FROM EAST AT SOUTH WALL IN THE 1st ROOM FROM NORTH LOCATED AT APT 2II, 2nd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	08/17/2020
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	01/19/2022

AJ259 **APPARTMENT** **NY LTANKS** **U003384086**
North **201 EASTERN PKWY** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY** **NY LEAD**
0.448 mi.
2367 ft. **Site 2 of 2 in cluster AJ**

Relative: **Higher**
Actual: **150 ft.**

LTANKS:

Name:	APPARTMENT
Address:	201 EASTERN PKWY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1904836 / 2020-07-09
Facility ID:	1904836
Site ID:	592841
Spill Date:	2019-08-06
Spill Cause:	Tank Test Failure
Spill Source:	Unknown
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-08-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

APPARTMENT (Continued) **U003384086**

Remediation Phase:	0
Date Entered In Computer:	2019-08-07
Spill Record Last Update:	2020-07-09
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ABRAHAM WATHSLER
Spiller Phone:	(718) 731-7011
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	101039
DEC Memo:	"8/7/2019 - Feng - Duty Desk. Spoke to Abraham Wathsler of NYC Tank Testing. Last night, the tank was test failed. The test show the system is leaking, but does not know where it leak, it could be the tank or the line or anywhere. There is 20 inches (or 2,200 gallons) inside the tank. It is underground, no sign of any spill. He recommended the owner to empty the product and clean the tank. He thought the tank is too old to worth for the repair. He haven't heard back from the owner. The building has a gas system also. Spoke to Peter Weinber of the building management. He was notified one hour ago by the tester. Building management is contacting to see which company can do the job. Since they don't know where in the system leak, and there is 2,200 gallons oil inside the tank, they'd better empty out the tank immediately in case it is a wet leak, then do the necessary repair or replacement of the tank system. He said maybe empty out the tank, then abandon it. Tank Tester: Abraham Wathsler NYC Tank Testing 646-321-2876 Management of the Building: Peter Weinberg 201 Parkway company LLC 284 Eastern Parkway Apt 1I Brooklyn, NY 11225 718-230-8500 Plaza@PlazaManagementInc.com PBS 2-082112 (1) 20,000-gallon #2 oil UST, installed in 1939. Discussed with Rick Lin and he might conduct site inspection. Spill is assigned to Rick Lin. 8/8/2019 - Sent TTF Letter to Peter Weinberg of 201 Parkway Company LLC. 7/9/2020-Lin-Building is running on gas and is going to close out the tank. Samples taken underneath the bank and the supply and return lines came back clean. According to the owner they have been using natural gas only for many years and they only had a delivery in 2017 because the boiler needed to be repaired on the natural gas side. Once the repair was made, they switched back to natural gas a week last. Received 2017 oil delivery bill. Last passing tank test was in 2018 and last delivery was in 2017. Case close. "
Remarks:	"tank test failure"

All Materials:

Site ID:	592841
Operable Unit ID:	1340439
Operable Unit:	01
Material ID:	2350144
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

APPARTMENT (Continued) **U003384086**

SPILLS:

Name:	MANHOLE #4511
Address:	201 EASTERN PKWY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0010842 / 2001-05-30
Facility ID:	0010842
Facility Type:	ER
DER Facility ID:	101039
Site ID:	116073
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2001-01-02
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2001-01-02
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-02
Spill Record Last Update:	2003-02-05
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	PETE MCGUIRE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL DEC INSPECTOR'S NOTES CON ED E2MIS REPORT 1-02-01 2gals. of an unknown oil on 2 1/2 gals. of standing water in MH4511. Liquid sample taken & tag placed. No oil filled equipment visible. lab Seq#01-00005 <1.00ppm Aroclor 1254;Solid sample 1-13-01 2005hrs. Cleanup reported completed and tag removed. 1-15-01 0940hrs. Cleanup completed by double washing structure with slix. Liquids were removed using diapers and couglant. No sump in structure. No leaking company equipment. Incident is closed."
Remarks:	"CON ED SPILL #134951 / SAMPLES TAKEN CLEANUP PENDING RESULTS - THERE IS NO ACTIVE LEAK AND IT IS CONTAINED TO TEH MANHOLE "

All Materials:

Site ID:	116073
Operable Unit ID:	832124
Operable Unit:	01
Material ID:	544727
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G

APPARTMENT (Continued) **U003384086**

Recovered: .00
Oxygenate: Not reported

NYC LEAD:
Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 15272732
Building ID: 287756
Registration ID: 310980
Apartment: 3K
Story: 3
Class: Most Serious
Inspection Date: 07/15/2022
Approved Date: 07/16/2022
Original Certify By Date: 08/16/2022
Original Correct By Date: 08/11/2022
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 617
NOV ID: 7975105
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM EAST AT SOUTH WALL, EAST WALL IN THE BATHROOM LOCATED AT APT 3K, 3rd STORY, 3rd APARTMENT FROM WEST AT NORTH
NOV Issued Date: 07/18/2022
Current Status ID: 7
Current Status: CERTIFICATION POSTPONMENT DENIED
Current Status Date: 08/04/2022

Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 15272733
Building ID: 287756
Registration ID: 310980
Apartment: 3K
Story: 3
Class: Most Serious
Inspection Date: 07/15/2022
Approved Date: 07/16/2022
Original Certify By Date: 08/16/2022
Original Correct By Date: 08/11/2022
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 617
NOV ID: 7975105
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM EAST AT SOUTH WALL DOOR FRAME IN THE PRIVATE HALLWAY LOCATED AT APT 3K, 3rd STORY, 3rd APARTMENT FROM WEST

APPARTMENT (Continued) **U003384086**

AT NORTH
NOV Issued Date: 07/18/2022
Current Status ID: 7
Current Status: CERTIFICATION POSTPONMENT DENIED
Current Status Date: 08/04/2022

Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 15272734
Building ID: 287756
Registration ID: 310980
Apartment: 3K
Story: 3
Class: Most Serious
Inspection Date: 07/15/2022
Approved Date: 07/16/2022
Original Certify By Date: 08/16/2022
Original Correct By Date: 08/11/2022
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 617
NOV ID: 7975105
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM NORTH AT EAST WALL, 1st DOOR FRAME FROM SOUTH AT WEST WALL IN THE 3rd ROOM FROM EAST LOCATED AT APT 3K, 3rd STORY, 3rd APARTMENT FROM WEST AT NORTH
NOV Issued Date: 07/18/2022
Current Status ID: 7
Current Status: CERTIFICATION POSTPONMENT DENIED
Current Status Date: 08/04/2022

Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 15272735
Building ID: 287756
Registration ID: 310980
Apartment: 3K
Story: 3
Class: Most Serious
Inspection Date: 07/15/2022
Approved Date: 07/16/2022
Original Certify By Date: 08/16/2022
Original Correct By Date: 08/11/2022
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 617
NOV ID: 7975105
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, 1st WINDOW FRAME FROM WEST AT NORTH WALL IN

APPARTMENT (Continued) **U003384086**

THE 1st ROOM FROM EAST LOCATED AT APT 3K, 3rd STORY, 3rd APARTMENT FROM WEST AT NORTH
NOV Issued Date: 07/18/2022
Current Status ID: 7
Current Status: CERTIFICATION POSTPONMENT DENIED
Current Status Date: 08/04/2022

Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 14942840
Building ID: 287756
Registration ID: 310980
Apartment: 5R
Story: 5
Class: Most Serious
Inspection Date: 02/25/2022
Approved Date: 02/26/2022
Original Certify By Date: 03/29/2022
Original Correct By Date: 03/24/2022
New Certify By Date: 04/12/2022
New Correct By Date: 04/07/2022
Certified Date: Not reported
Order Number: 617
NOV ID: 7737888
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FROM EAST AT SOUTH WALL, 1st DOOR FRAME FROM SOUTH AT WEST WALL, 1st WINDOW FRAME FROM WEST AT NORTH WALL IN THE KITCHEN LOCATED AT APT 5R, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''WEST''
NOV Issued Date: 02/28/2022
Current Status ID: 6
Current Status: CERTIFICATION POSTPONMENT GRANTED
Current Status Date: 03/22/2022

Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 14942830
Building ID: 287756
Registration ID: 310980
Apartment: 5R
Story: 5
Class: Most Serious
Inspection Date: 02/25/2022
Approved Date: 02/26/2022
Original Certify By Date: 03/29/2022
Original Correct By Date: 03/24/2022
New Certify By Date: 04/12/2022
New Correct By Date: 04/07/2022
Certified Date: Not reported
Order Number: 617
NOV ID: 7737888
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON

APPARTMENT (Continued) **U003384086**

A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM NORTH AT EAST WALL IN THE FOYER LOCATED AT APT 5R, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''WEST''

NOV Issued Date: 02/28/2022
Current Status ID: 6
Current Status: CERTIFICATION POSTPONMENT GRANTED
Current Status Date: 03/22/2022

Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 14942833
Building ID: 287756
Registration ID: 310980
Apartment: 5R
Story: 5
Class: Most Serious
Inspection Date: 02/25/2022
Approved Date: 02/26/2022
Original Certify By Date: 03/29/2022
Original Correct By Date: 03/24/2022
New Certify By Date: 04/12/2022
New Correct By Date: 04/07/2022
Certified Date: Not reported
Order Number: 617
NOV ID: 7737888
NOV Description: SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) BASEBOARD AT NORTH WALL, BASEBOARD AT WEST WALL, 1st CLOSET FROM EAST AT SOUTH WALL DOOR FRAME, 1st DOOR FRAME FROM NORTH AT EAST WALL, 1st RADIATOR FROM WEST AT NORTH WALL, 1st WINDOW FRAME FROM WEST AT NORTH WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 3rd ROOM FROM EAST AT NORTH LOCATED AT APT 5R, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''WEST''
NOV Issued Date: 02/28/2022
Current Status ID: 6
Current Status: CERTIFICATION POSTPONMENT GRANTED
Current Status Date: 03/22/2022

Name: Not reported
Address: 201 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11238
Violation ID: 12848608
Building ID: 287756
Registration ID: 310980
Apartment: 5L
Story: 5
Class: Most Serious
Inspection Date: 01/09/2019
Approved Date: 01/10/2019
Original Certify By Date: 02/13/2019
Original Correct By Date: 02/08/2019
New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported

APPARTMENT (Continued) **U003384086**

Order Number:	616
NOV ID:	6360299
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, EAST WALL IN THE 1st ROOM FROM EAST LOCATED AT APT 5L, 5th STORY, 2nd APARTMENT FROM WEST AT NORTH
NOV Issued Date:	01/11/2019
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	01/25/2019
Name:	Not reported
Address:	201 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11238
Violation ID:	14942832
Building ID:	287756
Registration ID:	310980
Apartment:	5R
Story:	5
Class:	Most Serious
Inspection Date:	02/25/2022
Approved Date:	02/26/2022
Original Certify By Date:	03/29/2022
Original Correct By Date:	03/24/2022
New Certify By Date:	04/12/2022
New Correct By Date:	04/07/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7737888
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM NORTH AT EAST WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 3rd ROOM FROM EAST AT SOUTH LOCATED AT APT 5R, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''WEST''
NOV Issued Date:	02/28/2022
Current Status ID:	6
Current Status:	CERTIFICATION POSTPONMENT GRANTED
Current Status Date:	03/22/2022
Name:	Not reported
Address:	201 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11238
Violation ID:	14942835
Building ID:	287756
Registration ID:	310980
Apartment:	5R
Story:	5
Class:	Most Serious
Inspection Date:	02/25/2022
Approved Date:	02/26/2022
Original Certify By Date:	03/29/2022
Original Correct By Date:	03/24/2022
New Certify By Date:	04/12/2022
New Correct By Date:	04/07/2022
Certified Date:	Not reported

APPARTMENT (Continued) **U003384086**

Order Number:	617
NOV ID:	7737888
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) BASEBOARD AT WEST WALL IN THE PRIVATE HALLWAY LOCATED AT APT 5R, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''WEST''
NOV Issued Date:	02/28/2022
Current Status ID:	6
Current Status:	CERTIFICATION POSTPONMENT GRANTED
Current Status Date:	03/22/2022
Name:	Not reported
Address:	201 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11238
Violation ID:	14942837
Building ID:	287756
Registration ID:	310980
Apartment:	5R
Story:	5
Class:	Most Serious
Inspection Date:	02/25/2022
Approved Date:	02/26/2022
Original Certify By Date:	03/29/2022
Original Correct By Date:	03/24/2022
New Certify By Date:	04/12/2022
New Correct By Date:	04/07/2022
Certified Date:	Not reported
Order Number:	617
NOV ID:	7737888
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM SOUTH AT WEST WALL IN THE BATHROOM LOCATED AT APT 5R, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''WEST''
NOV Issued Date:	02/28/2022
Current Status ID:	6
Current Status:	CERTIFICATION POSTPONMENT GRANTED
Current Status Date:	03/22/2022
Name:	Not reported
Address:	201 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11238
Violation ID:	14942838
Building ID:	287756
Registration ID:	310980
Apartment:	5R
Story:	5
Class:	Most Serious
Inspection Date:	02/25/2022
Approved Date:	02/26/2022
Original Certify By Date:	03/29/2022
Original Correct By Date:	03/24/2022
New Certify By Date:	04/12/2022
New Correct By Date:	04/07/2022
Certified Date:	Not reported

APPARTMENT (Continued) **U003384086**

Order Number:	617
NOV ID:	7737888
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) BASEBOARD AT NORTH WALL, 1st RADIATOR FROM NORTH AT EAST WALL IN THE 2nd ROOM FROM EAST AT SOUTH LOCATED AT APT 5R, 5th STORY, 1st APARTMENT FROM SOUTH AT WEST , SECTION ''WEST''
NOV Issued Date:	02/28/2022
Current Status ID:	6
Current Status:	CERTIFICATION POSTPONMENT GRANTED
Current Status Date:	03/22/2022

AK260 **1519 BEDFORD AVE** **NY LTANKS** **S106703591**
NE **1519 BEDFORD AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.465 mi.
2456 ft. **Site 1 of 2 in cluster AK**

Relative: **Higher**

Actual: **136 ft.**

LTANKS:

Name:	1519 BEDFORD AVE
Address:	1519 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9109883 / 2003-02-27
Facility ID:	9109883
Site ID:	306124
Spill Date:	1991-12-16
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1991-12-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-01-31
Spill Record Last Update:	2003-06-17
Spiller Name:	Not reported
Spiller Company:	NYS DIV OF NAVY & MILITAR
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	247270
DEC Memo:	""
Remarks:	"2X500 GAL TANKS HAVE LEAKED - EXCAVATED THE TANKS AND DRUMMED THE SOILON SITE."

1519 BEDFORD AVE (Continued) **S106703591**

All Materials:

Site ID:	306124
Operable Unit ID:	959904
Operable Unit:	01
Material ID:	418462
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK261 **1525 BEDFORD AVENUE** **NY ENG CONTROLS** **S117535351**
NE **1519-1535 BEDFORD AVENUE** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11216** **NY BROWNFIELDS**
0.465 mi.
2456 ft. **Site 2 of 2 in cluster AK**

Relative: **Higher**
Actual: **136 ft.**

ENG CONTROLS:

Name:	1525 BEDFORD AVENUE
Address:	1519-1535 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11216
Site Code:	503333
HW Code:	C224206
Control Code:	13
Control Type:	ENG
Date Record Added:	12/06/2017
Date Rec Updated:	11/30/2020
Updated By:	LSZINOMA
Site Description:	"Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile

1525 BEDFORD AVENUE (Continued) **S117535351**

	organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-01-09 14:32:00
Record Upd:	2018-01-03 12:28:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Alicia Pritchard
Owner Company:	Brooklyn Public Library - Bedford Library
Owner Address:	496 Franklin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michelle George
Owner Company:	Brooklyn Community Board 8
Owner Address:	1291 St. Marks Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11213
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Avenue, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Ave, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
HW Code:	C224206
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206

1525 BEDFORD AVENUE (Continued) **S117535351**

Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224206-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-26 08:50:00
Updated By:	RPMUSTIC
Crossref ID:	2017050101237001
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-12-20 10:17:00
Updated By:	RPMUSTIC
Crossref ID:	2-337579
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-10-16 09:29:00
Record Updated:	2017-10-16 09:29:00
Updated By:	JAAVERSA
Crossref ID:	C224206-12-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-07 14:39:00
Updated By:	RPMUSTIC
Crossref ID:	2017050101237001
Cross Ref Type Code:	31
Cross Ref Type:	Environmental Easement No.
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-11-10 14:38:00
Updated By:	RPMUSTIC

Name:	1525 BEDFORD AVENUE
Address:	1519-1535 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11216
Site Code:	503333
HW Code:	C224206
Control Code:	15
Control Type:	ENG
Date Record Added:	12/06/2017
Date Rec Updated:	11/30/2020
Updated By:	LSZINOMA
Site Description:	"Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site

1525 BEDFORD AVENUE (Continued) **S117535351**

	Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-01-09 14:32:00
Record Upd:	2018-01-03 12:28:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Alicia Pritchard
Owner Company:	Brooklyn Public Library - Bedford Library
Owner Address:	496 Franklin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michelle George
Owner Company:	Brooklyn Community Board 8
Owner Address:	1291 St. Marks Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11213
Owner Country:	United States of America
Own Op:	1

1525 BEDFORD AVENUE (Continued) **S117535351**

Sub Type:	E
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Avenue, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Ave, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
HW Code:	C224206
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224206-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-26 08:50:00
Updated By:	RPMUSTIC
Crossref ID:	2017050101237001
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-12-20 10:17:00
Updated By:	RPMUSTIC
Crossref ID:	2-337579
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-10-16 09:29:00
Record Updated:	2017-10-16 09:29:00
Updated By:	JAAVERSA
Crossref ID:	C224206-12-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-07 14:39:00
Updated By:	RPMUSTIC
Crossref ID:	2017050101237001
Cross Ref Type Code:	31

1525 BEDFORD AVENUE (Continued) **S117535351**

Cross Ref Type:	Environmental Easement No.
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-11-10 14:38:00
Updated By:	RPMUSTIC
Name:	1525 BEDFORD AVENUE
Address:	1519-1535 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11216
Site Code:	503333
HW Code:	C224206
Control Code:	35
Control Type:	ENG
Date Record Added:	12/06/2017
Date Rec Updated:	11/30/2020
Updated By:	LSZINOMA
Site Description:	"Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported

1525 BEDFORD AVENUE (Continued) **S117535351**

Record Add:	2015-01-09 14:32:00
Record Upd:	2018-01-03 12:28:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Alicia Pritchard
Owner Company:	Brooklyn Public Library - Bedford Library
Owner Address:	496 Franklin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michelle George
Owner Company:	Brooklyn Community Board 8
Owner Address:	1291 St. Marks Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11213
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Avenue, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Ave, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
HW Code:	C224206
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224206-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-26 08:50:00
Updated By:	RPMUSTIC

1525 BEDFORD AVENUE (Continued) **S117535351**

Crossref ID:	2017050101237001
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-12-20 10:17:00
Updated By:	RPMUSTIC
Crossref ID:	2-337579
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-10-16 09:29:00
Record Updated:	2017-10-16 09:29:00
Updated By:	JAAVERSA
Crossref ID:	C224206-12-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-07 14:39:00
Updated By:	RPMUSTIC
Crossref ID:	2017050101237001
Cross Ref Type Code:	31
Cross Ref Type:	Environmental Easement No.
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-11-10 14:38:00
Updated By:	RPMUSTIC

INST CONTROL:

Name:	1525 BEDFORD AVENUE
Address:	1519-1535 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11216
Site Code:	503333
Control Name:	Building Use Restriction
HW Code:	C224206
Control Code:	26
Control Type:	INST
Dt record added:	12/06/2017
Dt rec updated:	11/30/2020
Updated By:	LSZINOMA
Site Code:	503333
Site Description:	"Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was

1525 BEDFORD AVENUE (Continued) **S117535351**

encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-01-09 14:32:00
Record Upd: 2018-01-03 12:28:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Alicia Pritchard
Owner Company: Brooklyn Public Library - Bedford Library
Owner Address: 496 Franklin Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Michelle George
Owner Company: Brooklyn Community Board 8
Owner Address: 1291 St. Marks Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11213
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Avenue, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Ave, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022

1525 BEDFORD AVENUE (Continued) **S117535351**

Owner Country: United States of America
HW Code: C224206
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA
Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

Name: 1525 BEDFORD AVENUE
Address: 1519-1535 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY 11216
Site Code: 503333
Control Name: IC/EC Plan
HW Code: C224206
Control Code: 34
Control Type: INST
Dt record added: 12/06/2017

1525 BEDFORD AVENUE (Continued) **S117535351**

Dt rec updated:	11/30/2020
Updated By:	LSZINOMA
Site Code:	503333
Site Description:	"Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-01-09 14:32:00
Record Upd:	2018-01-03 12:28:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Alicia Pritchard
Owner Company:	Brooklyn Public Library - Bedford Library
Owner Address:	496 Franklin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository

1525 BEDFORD AVENUE (Continued) **S117535351**

Sub Type: NNN
Owner Name: Michelle George
Owner Company: Brooklyn Community Board 8
Owner Address: 1291 St. Marks Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11213
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Avenue, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Ave, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
HW Code: C224206
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA

1525 BEDFORD AVENUE (Continued) **S117535351**

Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

Name: 1525 BEDFORD AVENUE
Address: 1519-1535 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY 11216
Site Code: 503333
Control Name: Site Management Plan
HW Code: C224206
Control Code: 32
Control Type: INST
Dt record added: 12/06/2017
Dt rec updated: 11/30/2020
Updated By: LSZINOMA
Site Code: 503333
Site Description: "Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination

1525 BEDFORD AVENUE (Continued) **S117535351**

remaining at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-01-09 14:32:00
Record Upd: 2018-01-03 12:28:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Alicia Pritchard
Owner Company: Brooklyn Public Library - Bedford Library
Owner Address: 496 Franklin Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Michelle George
Owner Company: Brooklyn Community Board 8
Owner Address: 1291 St. Marks Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11213
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Avenue, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Ave, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
HW Code: C224206
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

1525 BEDFORD AVENUE (Continued) **S117535351**

HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA
Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

Name: 1525 BEDFORD AVENUE
Address: 1519-1535 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY 11216
Site Code: 503333
Control Name: Environmental Easement
HW Code: C224206
Control Code: J
Control Type: INST
Dt record added: 12/06/2017
Dt rec updated: 11/30/2020
Updated By: LSZINOMA
Site Code: 503333
Site Description: "Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash.

1525 BEDFORD AVENUE (Continued) **S117535351**

Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-01-09 14:32:00
Record Upd: 2018-01-03 12:28:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Alicia Pritchard
Owner Company: Brooklyn Public Library - Bedford Library
Owner Address: 496 Franklin Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Michelle George
Owner Company: Brooklyn Community Board 8
Owner Address: 1291 St. Marks Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11213
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Avenue, Suite 13D
Owner Addr2: Not reported

1525 BEDFORD AVENUE (Continued) **S117535351**

Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Ave, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
HW Code: C224206
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA
Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

1525 BEDFORD AVENUE (Continued) **S117535351**

Name:	1525 BEDFORD AVENUE
Address:	1519-1535 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11216
Site Code:	503333
Control Name:	Monitoring Plan
HW Code:	C224206
Control Code:	31
Control Type:	INST
Dt record added:	12/06/2017
Dt rec updated:	11/30/2020
Updated By:	LSZINOMA
Site Code:	503333
Site Description:	"Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-01-09 14:32:00
Record Upd:	2018-01-03 12:28:00
Updated By:	JXGRECO

1525 BEDFORD AVENUE (Continued) **S117535351**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Alicia Pritchard
Owner Company: Brooklyn Public Library - Bedford Library
Owner Address: 496 Franklin Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Michelle George
Owner Company: Brooklyn Community Board 8
Owner Address: 1291 St. Marks Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11213
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Avenue, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Ave, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
HW Code: C224206
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier

1525 BEDFORD AVENUE (Continued) **S117535351**

Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA
Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

Name: 1525 BEDFORD AVENUE
Address: 1519-1535 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY 11216
Site Code: 503333
Control Name: Landuse Restriction
HW Code: C224206
Control Code: 25
Control Type: INST
Dt record added: 12/06/2017
Dt rec updated: 11/30/2020
Updated By: LSZINOMA
Site Code: 503333
Site Description: "Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."

1525 BEDFORD AVENUE (Continued) **S117535351**

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-01-09 14:32:00
Record Upd:	2018-01-03 12:28:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Alicia Pritchard
Owner Company:	Brooklyn Public Library - Bedford Library
Owner Address:	496 Franklin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michelle George
Owner Company:	Brooklyn Community Board 8
Owner Address:	1291 St. Marks Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11213
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Avenue, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Ave, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
HW Code:	C224206
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN

1525 BEDFORD AVENUE (Continued) **S117535351**

Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA
Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

Name: 1525 BEDFORD AVENUE
Address: 1519-1535 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY 11216
Site Code: 503333
Control Name: Ground Water Use Restriction
HW Code: C224206
Control Code: 08
Control Type: INST
Dt record added: 12/06/2017
Dt rec updated: 11/30/2020
Updated By: LSZINOMA
Site Code: 503333
Site Description: "Location: The 1525 Bedford Avenue site is located in an urban area

1525 BEDFORD AVENUE (Continued) **S117535351**

in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-01-09 14:32:00
Record Upd: 2018-01-03 12:28:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Alicia Pritchard
Owner Company: Brooklyn Public Library - Bedford Library
Owner Address: 496 Franklin Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Michelle George
Owner Company: Brooklyn Community Board 8
Owner Address: 1291 St. Marks Avenue

1525 BEDFORD AVENUE (Continued) **S117535351**

Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11213
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Avenue, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Ave, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
HW Code: C224206
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA
Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00

1525 BEDFORD AVENUE (Continued) **S117535351**

Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

Name: 1525 BEDFORD AVENUE
Address: 1519-1535 BEDFORD AVENUE
City,State,Zip: BROOKLYN, NY 11216
Site Code: 503333
Control Name: O&M Plan
HW Code: C224206
Control Code: 33
Control Type: INST
Dt record added: 12/06/2017
Dt rec updated: 11/30/2020
Updated By: LSZINOMA
Site Code: 503333
Site Description: "Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump: False
Structure: False
Lagoon: False

1525 BEDFORD AVENUE (Continued) **S117535351**

Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-01-09 14:32:00
Record Upd: 2018-01-03 12:28:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Alicia Pritchard
Owner Company: Brooklyn Public Library - Bedford Library
Owner Address: 496 Franklin Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Michelle George
Owner Company: Brooklyn Community Board 8
Owner Address: 1291 St. Marks Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11213
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Avenue, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Omri Sachs
Owner Company: Bedford Joint Venture LLC
Owner Address: 850 Third Ave, Suite 13D
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10022
Owner Country: United States of America
HW Code: C224206
Waste Type: TOLUENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224206
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

1525 BEDFORD AVENUE (Continued) **S117535351**

Crossref ID: C224206-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-26 08:50:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-12-20 10:17:00
Updated By: RPMUSTIC
Crossref ID: 2-337579
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-10-16 09:29:00
Record Updated: 2017-10-16 09:29:00
Updated By: JAAVERSA
Crossref ID: C224206-12-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-12-07 14:37:00
Record Updated: 2017-12-07 14:39:00
Updated By: RPMUSTIC
Crossref ID: 2017050101237001
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-11-10 14:38:00
Record Updated: 2017-11-10 14:38:00
Updated By: RPMUSTIC

BROWNFIELDS:

Name:	1525 BEDFORD AVENUE
Address:	1519-1535 BEDFORD AVENUE
City,State,Zip:	BROOKLYN, NY 11216
Program:	BCP
Site Code:	503333
Acres:	0.668
HW Code:	C224206
SWIS:	2401
Town:	New York City
Record Added Date:	12/29/2014
Record Updated Date:	02/09/2022
Update By:	WBBENNET
Site Description:	"Location: The 1525 Bedford Avenue site is located in an urban area in the Crown Heights neighborhood of Brooklyn, NY. The site is bound by Bedford Avenue to the west, Lincoln Place to the north, multiple-story residential buildings to the east, and Eastern Parkway and the Metropolitan Transit Authority tunnels to the south. Site Features: The site occupies an area of approximately 29,076-square-feet, and has been developed into a multi-story residential and commercial structure. Prior to development, the site was occupied by a gasoline filling station, a service garage with a cellar level, a two-story retail store/office space and a car wash. Current Zoning/Use: The site is currently zoned as R7D residential with a C2-4 commercial overlay. Historic Use: The site has been occupied by auto-related facilities (auto garages/repair, filling

1525 BEDFORD AVENUE (Continued) **S117535351**

	stations, car washes) since at least 1924. Site Geology and Hydrogeology: The site and surrounding area slope to the north and is at an elevation of 135 feet above mean sea level. Regional groundwater flow is relatively flat with a slight gradient towards the north east. Perched groundwater was encountered at depths ranging from 20 to 50 feet below grade surface. The Upper Glacial Aquifer was encountered at 126 to 136 below grade surface. Soil beneath the site consists of fill material underlain by glacial till. The site is underlain by bedrock which consists of fine-grained quartz-feldspar granulite."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern included the petroleum volatile organic compounds (VOCs) benzene, toluene, ethylbenzene, and xylene (BTEX) in soil, groundwater and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Remaining contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-01-09 14:32:00
Record Upd:	2018-01-03 12:28:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Alicia Pritchard
Owner Company:	Brooklyn Public Library - Bedford Library
Owner Address:	496 Franklin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Michelle George
Owner Company:	Brooklyn Community Board 8
Owner Address:	1291 St. Marks Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11213
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Avenue, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
Own Op:	6

1525 BEDFORD AVENUE (Continued) **S117535351**

Sub Type:	P03
Owner Name:	Omri Sachs
Owner Company:	Bedford Joint Venture LLC
Owner Address:	850 Third Ave, Suite 13D
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10022
Owner Country:	United States of America
HW Code:	C224206
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224206
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224206-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-26 08:50:00
Updated By:	RPMUSTIC
Crossref ID:	2017050101237001
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-12-20 10:17:00
Updated By:	RPMUSTIC
Crossref ID:	2-337579
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-10-16 09:29:00
Record Updated:	2017-10-16 09:29:00
Updated By:	JAAVERSA
Crossref ID:	C224206-12-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-12-07 14:37:00
Record Updated:	2017-12-07 14:39:00
Updated By:	RPMUSTIC
Crossref ID:	2017050101237001
Cross Ref Type Code:	31
Cross Ref Type:	Environmental Easement No.
Record Added Date:	2017-11-10 14:38:00
Record Updated:	2017-11-10 14:38:00
Updated By:	RPMUSTIC

262
ENE
1/4-1/2
0.470 mi.
2479 ft.

1150 CARROLL STREET
1150 CARROLL STREET
BROOKLYN, NY 11225

NY LTANKS **S108765830**
N/A

Relative:
Higher

Actual:
116 ft.

LTANKS:

Name:	MEDGAR EVERS COLLEGE
Address:	1150 CARROLL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0706996 / 2010-02-05
Facility ID:	0706996
Site ID:	387613
Spill Date:	2007-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-09-24
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-24
Spill Record Last Update:	2010-02-05
Spiller Name:	WILLIAM KLEIN
Spiller Company:	MEDGAR EVERS COLLEGE
Spiller Address:	1150 CARROLL ST
Spiller County:	001
Spiller Contact:	WILLIAM KLEIN
Spiller Phone:	(718) 762-5200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	69279
DEC Memo:	"10/1/07 bf: Called Frank Tumminello of Medgar Evers College (718)270-6099. He said CUNY isa brinigng in contractors soon to make repairs and retest. He was unsure of when. I confirmed address and told himn registration expired. I told him I would send him a letter and explained that it would tell him what he needs to do. i told him the registration expired and he said he would forward application to person who handles it. ttf letter sent to: Frank Tumminello Medgar Evers College 1150 Carroll St. Brooklyn, NY 11225 10/3/07 Received call from esther Hundley of CUNY. See Spill comments for 10/3/07 of spill 0706994 for details. bf 11/1/07 Received letter from Woodward & Curran. Failed likely because of corrosion around the manway. Tank to be abandoned in place and replaced with 2 AST. UST is in front of entrance to building. Will excavate to tank top. Clean and purge tank. Drill 4 spoil boings around tank to determine if there is a release. if release, will implement remedial actions. Will install 6,ooo gallon AST. 12/20/07 Received phone message from Ester Hundley, Safety Officer, CUNY. She received a letter from a DEC attorney (no name given) stating that she is fined $1,000. She believes there is

1150 CARROLL STREET (Continued) **S108765830**

no violation. Her ph. no. 212-541-0430. bf 1/15/08 received call on Friday 1/11/08 from M. Vanderhajen. Returned his call today, but he is not in the office today. Left message on voicemail. bf 1/16/08 Faxed Spill Reports 0313371 and 9703262 to M. Vanderhajden at (914)448-0147. Tank to be temp closed. bf 5/9/08 Received message from Ester Hundley Safety officer for CUNY (212)541-0430. Requested call back. 5/12/08 Called back E. Hundley. She wanted to know if I knew of any consent order requiring the removal of the tank(s). She wants to close them in place rather than remove them. I said I did not see any order, however, she should call Ben Conlon of DEC DLA to confirm. She wanted to know if tanks are legally allowed to be closed in place I told her yes, but if DEC directs removal, they would need to be removed. bf 5/15/08 Yesterday, received message from Mark Randazzo of O'Brien & Gere (781)883-6432. (781 is correct, not 718). He is project manager and wanted to make sure they are heading in the right direction for the spill closure. I called back and left message to call me. bf 5/19/08 Received 2 messages from M. Randazzo (5/15 and 5/19). I called him back. CUNY plans to take samples and clean out the tank tomorrow. i explained to him that i spoke with E. Hundley and recommended that she call Mr. Conlon of DEC DLA regarding the closure of the tanks. bf 6/19/08 Called M. Randazzo re: removal of tank. Left message on voicemail. He called back. I told him that the tank at Carroll Street is illegal because database states it was installed in 1997. He states it was installed in 1943. bf 6/25/08 Received closure report for tank. Report states tank to be closed in place, however, CUNY was told that tasnk must be removed. Report does not have sample results for all STARS contaminants. Tank has a liner, but no info was provided on registration application. bf 11/20/08 Received letter dated 11/18/08 from Mark Randazzo of O'Brien & Gere. Tank 001 was removed and petroleum contaminated soil found. Tank 002 was closed in place approximately 35 years ago. Tank 002 was removed. Also found third UST that was not on registration. Approximately 350 cy of material excavated.from the proximity of transfer lines between the lines for 001 and 002. Will provide a comprehensive report detailing site assessment activities to me shortly. bf 01/13/10 Called Esther Hundley (212)541-0430. Left message on voice mail to call me back with status. bf 1/20/10 Received closure report by e-mail from M. Randazzo. bf 2/5/10 Most petroleum impacted soil was found between the two tanks. Contaminated soil was removed. Visual inspection of tanks on removal showed no perforations. Sample results are below DEC Soil Cleanup Objectives to protect GW Quality. The valuers in the report were compared to Part 375.6 soil cleanup criteria. However the EPA sampling methods used were 8260 and 8270. Third tank that was assumed to exist was not found based on probes in possible location of piping. NFA. bf"

Remarks: "ESTER BROOK THREE TEST USED; TANK TOP FAILURE;"

All TTF:

Facility ID:	0706996
Spill Number:	0706996
Spill Tank Test:	1764136
Site ID:	387613
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

1150 CARROLL STREET (Continued) **S108765830**

Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	387613
Operable Unit ID:	1144813
Operable Unit:	01
Material ID:	2135124
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	1150 CARROLL STREET
Address:	1150 CARROLL STREET
City,State,Zip:	BROOKLYN, NY 11225
Spill Number/Closed Date:	0313371 / 2008-07-11
Facility ID:	0313371
Site ID:	73622
Spill Date:	2004-03-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2004-03-05
CID:	403
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-05
Spill Record Last Update:	2008-07-11
Spiller Name:	IGOR UMGELSOM
Spiller Company:	1150 CARROLL ST
Spiller Address:	1150 CARROLL ST
Spiller County:	001
Spiller Contact:	IGOR UMGELSOM
Spiller Phone:	(718) 270-6009
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	20130

1150 CARROLL STREET (Continued) **S108765830**

DEC Memo: "12/27/05, Dyber: OBG has not made any progress on this spill. Refer to region. Next Step: Perform state-funded investigation. 11/2/05, Dyber: Hartman is no longer with OBG. Left message for Stuart Spiegel. 10/24/05, Dyber: No return call from Hartman - left message. 9/21/05, Dyber: No return call from Hartman - left message. 9/6/05, Dyber: Spoke with Kevin Hartman. He does not have a closure report but the dormitory authority believes that they have one. He will call me when he gets report. 8/11/05, Dyber: Kevin Hartman called. He has not found closure report yet. He will call back before Labor Day. 7/27/05, Dyber: Spoke with Mike Woodward. He referred me to Frank Tuminello (718-270-6099). He said that I should talk to O'Brien & Gere (OBG), who is preparing for an EPA audit. He said to call Jim Paye (518-452-9392 x-13), Christina Hine (x-16) or Stuart Spiegel. I called Jim Paye, who said that none of the three contacts is working on the UST issues. He will find out who is addressing the tanks and have them call me. Kevin Hartman from OBG called me (315-437-6100 x-2861). He will try to find closure report for 9703262 and call me. The active tank is nearly empty and will be repaired, which will address 0313371. 7/26/05, Dyber: Called Igor Umgelsom. He said to call Michael Woodward tomorrow at 718-270-6010 from 7-3. 7/26/05, Ng: It was agreed between Ng and Dyber that Dyber will be handling this spill (0313371)under one of Dyber's Spill # 9703262. Any further remarks regarding this spill should be directed towards Dyber. 7/20/05, Dyber: Spill #9703262 will be handled as part of this spill. Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO SENT TTF LETTER 9/21/06 - called NYS Dormitory Authority, Ed Nikolsky. He's not working on the spill. Project mgr. is Eugene Leung - office:(212)273-5109; field:(718)774-2897. E. Leung is not in office today. I called E. Leung and left message. bf. 9/27/06 called R. Leung. He told me NYS Dormitory Authority not reponsible for tanks. CUNY made agreement to take over college from NYS. he gave me 2 contacts: Frank Tumminello, Campus Facilities Officer 1150 Carroll St. Brooklyn, NY (718)270-6099 and Kay Xanthakos, CUNY, 57th St., NYC (212)501-0182. 7/11/08 Administratively closed. Same site as Spill 0706996. Refer to that spill. bf"

Remarks: "tank test failed"

All TTF:

Facility ID:	0313371
Spill Number:	0313371
Spill Tank Test:	1529024
Site ID:	73622
Tank Number:	002
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

1150 CARROLL STREET (Continued) **S108765830**

Site ID:	73622
Operable Unit ID:	878597
Operable Unit:	01
Material ID:	498523
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	NYS DORMITORY AUTHORITY -
Address:	1150 CARROLL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9703262 / 2005-07-20
Facility ID:	9703262
Site ID:	73623
Spill Date:	1997-06-16
Spill Cause:	Tank Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JLDYBER
Referred To:	Not reported
Reported to Dept:	1997-06-16
CID:	370
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-06-16
Spill Record Last Update:	2005-07-20
Spiller Name:	ED NIKOLSKY
Spiller Company:	NYS DORMITORY AUTHORITY
Spiller Address:	ONE PENN PLAZA, 52ND FL
Spiller County:	001
Spiller Contact:	ED NIKOLSKY
Spiller Phone:	(212) 273-5042
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	69279
DEC Memo:	"7/20/05, Dyber: This spill will be handled using a later spill number 0313371 7/18/05, Dyber: Spill #0313371 is also open at this property. Will talk with Chek Ng, who is assigned to the spill, about closing out this spill and doing the work under the other spill number."
Remarks:	"TEST SAMPLES TAKEN IN MAY 1996 RESULTS BACK TODAY SHOWED PETROLEUM CONSTITUENTS SLIGHTLY OVER STARS CRITERIA FURTHER INVESTIGATION TO CONTAMINATION. SAMPLES WERE FOR A CLOSURE OF TANK"

1150 CARROLL STREET (Continued) **S108765830**

All Materials:

Site ID:	73623
Operable Unit ID:	1046050
Operable Unit:	01
Material ID:	336161
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

263 **SAUTIN RESIDENCE** **NY LTANKS** **S117269602**
SSE **181 FENIMORE ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.473 mi.
2497 ft.

Relative: **Lower**

Actual: **62 ft.**

LTANKS:

Name:	SAUTIN RESIDENCE
Address:	181 FENIMORE ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1402553 / 2014-07-11
Facility ID:	1402553
Site ID:	495881
Spill Date:	2014-06-09
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2014-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-06-09
Spill Record Last Update:	2014-07-11
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	NICK SAUTIN
Spiller Phone:	(917) 304-2775
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	450759
DEC Memo:	"06/10/14-Hiralkumar Patel. alternate address: none no other spills

SAUTIN RESIDENCE (Continued) **S117269602**

or PBS found. Lindsey Berns / Nicholas Sautin **property owners** 181 Fenimore Street Brooklyn, NY 11225 PH. (917) 304-2775 email: nicksautin@gmail.com 3:32 PM:- spoke with Pat with Protest. they tested a 550 gal UST and it failed in dry portion. there was about 360 gal product in the tank during test. Protest has submitted cost estimate for isolation test. Pat mentioned that the tank test was done as part of property transfer. 3:36 PM:- left message for Mr. Sautin. 3:44 PM:- received call from Mr. Sautin. informed him that the department requires isolation test. 3:54 PM:- sent TTF letter to Mr. Sautin, requiring report submission by 07/14/14. letter emailed to Mr. Sautin. 06/17/14-Hiralkumar Patel. 9:10 AM:- received email from Mike from AARCO. he proposes to conduct subsurface investigation around UST via installation of soil borings. he did not mentioned anything about reason for initial tank test failure. Michael McArdle AARCO Environmental Ph. (631) 586-5900 email: mmcardle@aarcoenvironmental.com 12:19 PM:- spoke with Mike at AARCO. informed him that the department requires an isolation test to locate the leak and then further investigation accordingly. he will talk to property owner. **report due on 07/14/14.** 7/11/14 TJD Received request from ProTest to review submitted closure report as DEC project manager (Patel) is on extended leave. As per ProTest report, spill cause was an out of service suction line still connected to the tank. Contractor uncovered tank (550 UST) and disconnected/removed and plugged old out of service suction line and then proceeded to temporarily cap remote fill and vent piping. On 6/26/14, the UST was then retested and passed the required isolation test (suction/return lines still connected). Protest then proceeded to return the tank system to service by reconnecting fill/vent lines and retested complete tank system on 6/27/14, obtaining a passing system test. As per ProTest report, no visible contamination was identified in the excavation. Based upon the above information, no further action is required. Spill has been reassigned from Patel to DeMeo. All required closure documentation has been uploaded to DECDOCS. Spill closed."

Remarks: "repair/retest pending"

All Materials:

Site ID:	495881
Operable Unit ID:	1245376
Operable Unit:	01
Material ID:	2246384
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AL264 **18 ST. CHARLES PL/BKLYN** **NY LTANKS** **S106703547**
NNE **18 ST. CHARLES PLACE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.483 mi.
2550 ft. **Site 1 of 2 in cluster AL**

Relative:
Higher

Actual:
130 ft.

LTANKS:

Name:	18 ST. CHARLES PL/BKLYN
Address:	18 ST. CHARLES PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9102191 / 1995-06-20
Facility ID:	9102191
Site ID:	310623
Spill Date:	1991-05-23
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1995-06-20
SWIS:	2401
Investigator:	FINGER
Referred To:	Not reported
Reported to Dept:	1991-05-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-06-03
Spill Record Last Update:	2003-01-27
Spiller Name:	Not reported
Spiller Company:	MR. SUTTON
Spiller Address:	18 ST. CHARLES PLACE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	250728
DEC Memo:	""
Remarks:	"TANK LEAK ON BASEMENT TILE FLOOR,OWNER CLEANED UP SOME OF SPILL, BAERENKLAU PUT DOWN MORE SPEEDY DRY,TO CLEAN UP REST OF SPILL."

All Materials:

Site ID:	310623
Operable Unit ID:	953246
Operable Unit:	01
Material ID:	424714
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AL265 **BENT RESIDENCE** **NY LTANKS** **S102663773**
NNE **16 ST CHARLES PL** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.487 mi.
2569 ft. **Site 2 of 2 in cluster AL**

Relative:
Higher

Actual:
129 ft.

LTANKS:

Name:	BENT RESIDENCE
Address:	16 ST CHARLES PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9708264 / 1997-11-13
Facility ID:	9708264
Site ID:	279943
Spill Date:	1997-10-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	LUCE
Referred To:	Not reported
Reported to Dept:	1997-10-14
CID:	297
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-14
Spill Record Last Update:	1997-11-13
Spiller Name:	ANTHONY EREMITAGGIO
Spiller Company:	PETRO FUEL
Spiller Address:	55-60 58TH ST
Spiller County:	001
Spiller Contact:	MR BENT
Spiller Phone:	(718) 467-9723
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	227283
DEC Memo:	""
Remarks:	"DRIVER OVERFILLED THE TANK IN THE BASEMENT AND FUEL OIL SPILLED FROM THE GUAGE ON THE TANK"

All Materials:

Site ID:	279943
Operable Unit ID:	1054891
Operable Unit:	01
Material ID:	330247
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

266
South
1/4-1/2
0.491 mi.
2594 ft.

LAKE VIEW HOUSES - TTF
217 OCEAN AVE
BROOKLYN, NY

NY LTANKS **S109583780**
N/A

Relative:
Lower

Actual:
66 ft.

LTANKS:

Name:	LAKE VIEW HOUSES - TTF
Address:	217 OCEAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0900014 / 2009-07-14
Facility ID:	0900014
Site ID:	411923
Spill Date:	2009-04-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2009-04-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-01
Spill Record Last Update:	2009-07-14
Spiller Name:	MARTIN
Spiller Company:	LAKE VIEW HOUSES
Spiller Address:	217 OCEAN AVE
Spiller County:	999
Spiller Contact:	RICKEY ROUFF
Spiller Phone:	(718) 714-6898
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	361124
DEC Memo:	"***5,000 gal UST with NO PBS******** Sangesland spoke to Empire Environmental. No TTF letter was sent because Empire was doing all the correct work - almost done. Tank was pumped out - Soil samples were taken through the bottom of the tank and came back clean. Tank was foamed and closed in place. Empire is finishing off the report as of 5/20/09 and will mail it into Krimgold. 07/14/09. J.Krimgold reviewed the Site Assessment Report submitted by Empire Environmental and dated April 13, 2009. Based on the data provided four soil samples were taken through the tank walls. No VOCs or SVOCs were found in excess of DEC soil guidance. NFA. No PBS registration, No notification for the tank closure, No previous t/tests."
Remarks:	"TANK TEST FAILURE ON A 5000 GALLON TANK UNK IF ANY PRODUCT WAS SPILLED."

All Materials:

Site ID:	411923
Operable Unit ID:	1168417
Operable Unit:	01
Material ID:	2160023

LAKE VIEW HOUSES - TTF (Continued) **S109583780**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

267
SE
1/2-1
0.819 mi.
4326 ft.

FLATBUSH STATION A AND B **EDR MGP** **1008407886**
NOSTRAND AVE. WINTHROP ST., NEW YORK AND PARKSIDE AV **N/A**
BROOKLYN, NY 11225

Relative:
Lower

Actual:
56 ft.

Manufactured Gas Plants:
No additional information available

268
SE
1/2-1
0.850 mi.
4486 ft.

FLATBUSH STATION B **EDR MGP** **1008407887**
NOSTRAND. CLARKSON. NEW YORK AND PARKSIDE AVES **N/A**
BROOKLYN, NY 11225

Relative:
Lower

Actual:
58 ft.

Manufactured Gas Plants:
No additional information available

Count: 8 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S113916585	DAVIDSON PIPE SUPPLY COMPANY	3RD AVE & 37TH STREET		NY SHWS
BROOKLYN	S105265266	VICTORY CONTRACTING CO; I	780 EAST 95ST	0	NY SWF/LF
BROOKLYN	S126023326	MARINE PARK	BOUNDED BY FLATBUSH AVENUE, RO		NY SWF/LF
BROOKLYN	S126022645	BROOKLYN MODEL CITY - DEKALB AVE/W	BOUNDED BY DEKALB AVENUE, NOST		NY SWF/LF
BROOKLYN	S113916802	CATON PLACE GW	CATON PLACE BETWEEN OCEAN PARK	11218	NY SHWS
BROOKLYN	S128781725	GOLDEN TOUCH CLEANERS	326 FLATBUSH AVE		NY DRYCLEANERS
BROOKLYN	S113916531	FLATBUSH STATION B	NOSTRAND,CLARKSON, NEW YORK &	11203	NY VCP, NY BROWNFIELDS
BROOKLYN	S117535331	BASEMENT	925 UNION ST		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 08/25/2022
Date Data Arrived at EDR: 09/06/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 11/02/2022
Date Data Arrived at EDR: 11/08/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 63

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 08/15/2022
Date Data Arrived at EDR: 08/17/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/16/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 08/15/2022
Date Data Arrived at EDR: 08/17/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/16/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/12/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 12/19/2022
Number of Days to Update: 5

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/21/2022
Date Data Arrived at EDR: 12/22/2022
Date Made Active in Reports: 12/30/2022
Number of Days to Update: 8

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/20/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/08/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/11/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/28/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 06/02/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 79
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/14/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/26/2022
Number of Days to Update: 79
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 88

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/20/2022
Date Made Active in Reports: 12/01/2022
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/20/2022
Date Made Active in Reports: 12/01/2022
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/20/2022
Date Made Active in Reports: 12/01/2022
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/20/2022
Date Made Active in Reports: 12/01/2022
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/08/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/14/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/07/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/11/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/28/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 06/02/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 79

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/20/2022
Date Made Active in Reports: 12/01/2022
Number of Days to Update: 72
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 06/22/2022
Date Data Arrived at EDR: 09/12/2022
Date Made Active in Reports: 12/01/2022
Number of Days to Update: 80
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 12/12/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 06/22/2022
Date Data Arrived at EDR: 09/21/2022
Date Made Active in Reports: 12/01/2022
Number of Days to Update: 71
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 12/12/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 09/05/2022
Date Data Arrived at EDR: 09/06/2022
Date Made Active in Reports: 11/21/2022
Number of Days to Update: 76

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 12/05/2022
Next Scheduled EDR Contact: 03/20/2023
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 0

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/07/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 12/01/2022
Next Scheduled EDR Contact: 03/20/2023
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/21/2022
Date Data Arrived at EDR: 12/22/2022
Date Made Active in Reports: 12/30/2022
Number of Days to Update: 8

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/20/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 07/29/2022
Date Data Arrived at EDR: 08/18/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 67

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 07/29/2022
Date Data Arrived at EDR: 08/18/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 67

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 10/27/2022
Date Made Active in Reports: 01/13/2023
Number of Days to Update: 78

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 10/27/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/19/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 11

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/26/2022
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 08/11/2022
Date Data Arrived at EDR: 08/11/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 50

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/10/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/03/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/20/2022
Date Made Active in Reports: 12/22/2022
Number of Days to Update: 93

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/12/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/17/2022
Date Data Arrived at EDR: 10/18/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 84

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/18/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 01/20/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 64

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/04/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/26/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 13
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 11/29/2022
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 11/23/2022
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/03/2022
Next Scheduled EDR Contact: 02/13/2023
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 12/20/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/24/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2022
Date Data Arrived at EDR: 10/21/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 81

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 23

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 10/27/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/09/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 11/29/2022
Date Data Arrived at EDR: 11/30/2022
Date Made Active in Reports: 12/22/2022
Number of Days to Update: 22

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/03/2022
Date Data Arrived at EDR: 08/17/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 14

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 11/17/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/21/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/21/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines
An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/13/2022
Date Data Arrived at EDR: 09/14/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 82

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 03/20/2023
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 08/03/2022
Date Data Arrived at EDR: 08/25/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 60

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 11/29/2022
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/15/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/25/2022
Date Data Arrived at EDR: 09/30/2022
Date Made Active in Reports: 12/22/2022
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 01/04/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 11/09/2021
Date Data Arrived at EDR: 10/20/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 82

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/09/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/11/2022
Date Data Arrived at EDR: 08/11/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 50

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/10/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 07/08/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 123

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 01/10/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 10/26/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Fluoropolymer coatings are blends of resins and lubricants used in products such as water-repellent clothing, furniture, adhesives, paint and varnish, food packaging, heat-resistant non-stick cooking surfaces and insulation of electrical wires. Chemicals in this group include perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS).

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 99

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 10/29/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 04/26/2022
Number of Days to Update: 158

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 01/10/2023
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 11/03/2022
Next Scheduled EDR Contact: 02/13/2023
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 07/27/2022
Date Data Arrived at EDR: 07/27/2022
Date Made Active in Reports: 08/04/2022
Number of Days to Update: 8

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 10/03/2022
Date Data Arrived at EDR: 10/04/2022
Date Made Active in Reports: 12/20/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/20/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 08/30/2022
Date Data Arrived at EDR: 08/31/2022
Date Made Active in Reports: 09/07/2022
Number of Days to Update: 7

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 12/01/2022
Next Scheduled EDR Contact: 03/20/2023
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 09/21/2022
Date Data Arrived at EDR: 10/14/2022
Date Made Active in Reports: 10/19/2022
Number of Days to Update: 5

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 12/12/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 09/29/2022
Date Data Arrived at EDR: 09/30/2022
Date Made Active in Reports: 10/06/2022
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/20/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 12/01/2022
Next Scheduled EDR Contact: 03/20/2023
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 08/26/2022
Date Data Arrived at EDR: 10/31/2022
Date Made Active in Reports: 01/19/2023
Number of Days to Update: 80

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 10/31/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 10/31/2022
Date Data Arrived at EDR: 10/31/2022
Date Made Active in Reports: 01/19/2023
Number of Days to Update: 80

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 10/31/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 03/25/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/18/2022
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 11/10/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

UIC: Underground Injection Control Wells
A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 08/24/2022
Date Data Arrived at EDR: 08/25/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 11/30/2022
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers
This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 10/04/2022
Date Data Arrived at EDR: 10/10/2022
Date Made Active in Reports: 01/04/2023
Number of Days to Update: 86

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/11/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits
An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 11/22/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Varies

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 11/02/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 11/02/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 11/02/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/22/2022
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/22/2022
Next Scheduled EDR Contact: 03/13/2023
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 07/20/2022
Date Data Arrived at EDR: 08/23/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 83

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/24/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 07/20/2022
Date Data Arrived at EDR: 08/23/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 83

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/24/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/21/2022
Number of Days to Update: 74

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/16/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 12/20/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 12/01/2022
Next Scheduled EDR Contact: 03/20/2023
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

962 & 972
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

TARGET PROPERTY COORDINATES

Latitude (North):	40.665112 - 40ˆ 39’ 54.40’’
Longitude (West):	73.960462 - 73ˆ 57’ 37.66’’
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	587870.8
UTM Y (Meters):	4501890.5
Elevation:	90 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970073B	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
3604970211F	FEMA FIRM Flood data
3604970063B	FEMA Q3 Flood data
3604970064B	FEMA Q3 Flood data
3604970074B	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS40000827691	0 - 1/8 Mile South
A2	USGS40000827672	0 - 1/8 Mile SSE
A3	USGS40000827673	0 - 1/8 Mile SSE
4	USGS40000827642	1/8 - 1/4 Mile SSW
C7	USGS40000827602	1/4 - 1/2 Mile SSW
C8	USGS40000827603	1/4 - 1/2 Mile SSW
9	USGS40000827690	1/4 - 1/2 Mile East
11	USGS40000827148	1/4 - 1/2 Mile South
D12	USGS40000827627	1/2 - 1 Mile ESE
D13	USGS40000827628	1/2 - 1 Mile ESE
14	USGS40000828264	1/2 - 1 Mile North
15	USGS40000827062	1/2 - 1 Mile SE
17	USGS40000828310	1/2 - 1 Mile North
G21	USGS40000827060	1/2 - 1 Mile SE
G22	USGS40000827061	1/2 - 1 Mile SE
23	USGS40000827626	1/2 - 1 Mile ESE
24	USGS40000827216	1/2 - 1 Mile ESE
E25	USGS40000826983	1/2 - 1 Mile SSW
E26	USGS40000826984	1/2 - 1 Mile SSW
27	USGS40000826958	1/2 - 1 Mile South

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
B5	NYREG1000000074	1/8 - 1/4 Mile NE
B6	NYREG1000000075	1/8 - 1/4 Mile NE
10	NYREG1000000126	1/4 - 1/2 Mile NE
16	NYREG1000000176	1/2 - 1 Mile ESE
E18	NYREG1000000249	1/2 - 1 Mile SSW
F19	NYREG1000000072	1/2 - 1 Mile SE
F20	NYREG1000000073	1/2 - 1 Mile SE

PHYSICAL SETTING SOURCE MAP - 7231046.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	962 & 972	CLIENT:	The ALC Group, LLC T/A ALC
ADDRESS:	972 Franklin Avenue Brooklyn NY 11225	CONTACT:	Tania Castro
		INQUIRY #:	7231046.2s
LAT/LONG:	40.665112 / 73.960462	DATE:	January 23, 2023 10:43 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
South
0 - 1/8 Mile
Lower | **FED USGS** | **USGS40000827691**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 531. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	360	Well Depth Units:	ft
Well Hole Depth:	378	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	17	Level reading date:	1947-12-17
Feet below surface:	Not Reported	Feet to sea level:	-15.99
Note:	Not Reported		

Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-15.99	Note:	Not Reported
Level reading date:	1947-11-18	Feet below surface:	Not Reported
Feet to sea level:	-15.99	Note:	Not Reported
Level reading date:	1947-10-30	Feet below surface:	Not Reported
Feet to sea level:	-16.99	Note:	Not Reported
Level reading date:	1947-10-21	Feet below surface:	Not Reported
Feet to sea level:	-16.99	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-16.99	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-16.99	Note:	Not Reported
Level reading date:	1947-10-04	Feet below surface:	Not Reported
Feet to sea level:	-16.99	Note:	Not Reported
Level reading date:	1947-09-20	Feet below surface:	Not Reported
Feet to sea level:	-16.99	Note:	Not Reported
Level reading date:	1947-08-29	Feet below surface:	Not Reported
Feet to sea level:	-17.99	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-17.99	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-17.99	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-20.34	Note:	Not Reported
Level reading date:	1947-07-03	Feet below surface:	Not Reported
Feet to sea level:	-21.03	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported

Feet to sea level:	-21.03	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-21.03	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-20.34	Note:	Not Reported

A2
SSE **FED USGS** **USGS40000827672**
0 - 1/8 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1338. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	129
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	97	Level reading date:	1951-11-29
Feet below surface:	Not Reported	Feet to sea level:	-0.45
Note:	Not Reported		
Level reading date:	1951-11-02	Feet below surface:	Not Reported
Feet to sea level:	-0.61	Note:	Not Reported
Level reading date:	1951-09-25	Feet below surface:	Not Reported
Feet to sea level:	-0.81	Note:	Not Reported
Level reading date:	1951-08-27	Feet below surface:	Not Reported
Feet to sea level:	-0.93	Note:	Not Reported
Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	-1.04	Note:	Not Reported
Level reading date:	1951-06-27	Feet below surface:	Not Reported
Feet to sea level:	-0.23	Note:	Not Reported
Level reading date:	1951-05-28	Feet below surface:	Not Reported
Feet to sea level:	-0.58	Note:	Not Reported
Level reading date:	1951-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.56	Note:	Not Reported
Level reading date:	1951-03-26	Feet below surface:	Not Reported
Feet to sea level:	-0.14	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	4.75	Note:	Not Reported
Level reading date:	1951-01-29	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	0.74	Note:	Not Reported

Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-1.49	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-2.08	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-2.25	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-2.33	Note:	Not Reported
Level reading date:	1950-08-16	Feet below surface:	Not Reported
Feet to sea level:	-2.25	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-2.18	Note:	Not Reported
Level reading date:	1950-07-13	Feet below surface:	Not Reported
Feet to sea level:	-2.28	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-2.19	Note:	Not Reported
Level reading date:	1950-06-13	Feet below surface:	Not Reported
Feet to sea level:	-2.19	Note:	Not Reported
Level reading date:	1950-06-01	Feet below surface:	Not Reported
Feet to sea level:	-2.20	Note:	Not Reported
Level reading date:	1950-05-18	Feet below surface:	Not Reported
Feet to sea level:	-2.26	Note:	Not Reported
Level reading date:	1950-05-10	Feet below surface:	Not Reported
Feet to sea level:	-2.28	Note:	Not Reported
Level reading date:	1950-05-04	Feet below surface:	Not Reported
Feet to sea level:	-2.26	Note:	Not Reported
Level reading date:	1950-04-17	Feet below surface:	Not Reported
Feet to sea level:	-2.23	Note:	Not Reported
Level reading date:	1950-03-30	Feet below surface:	Not Reported
Feet to sea level:	-0.32	Note:	Not Reported
Level reading date:	1950-03-16	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-2.49	Note:	Not Reported
Level reading date:	1950-01-12	Feet below surface:	Not Reported
Feet to sea level:	-2.56	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported
Level reading date:	1949-12-15	Feet below surface:	Not Reported
Feet to sea level:	-2.60	Note:	Not Reported

Level reading date:	1949-11-30	Feet below surface:	Not Reported
Feet to sea level:	-2.61	Note:	Not Reported
Level reading date:	1949-11-17	Feet below surface:	Not Reported
Feet to sea level:	-2.65	Note:	Not Reported
Level reading date:	1949-11-01	Feet below surface:	Not Reported
Feet to sea level:	-2.76	Note:	Not Reported
Level reading date:	1949-10-17	Feet below surface:	Not Reported
Feet to sea level:	-2.87	Note:	Not Reported
Level reading date:	1949-09-29	Feet below surface:	Not Reported
Feet to sea level:	-2.97	Note:	Not Reported
Level reading date:	1949-09-20	Feet below surface:	Not Reported
Feet to sea level:	-3.02	Note:	Not Reported
Level reading date:	1949-09-01	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1949-08-19	Feet below surface:	Not Reported
Feet to sea level:	-3.26	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-3.45	Note:	Not Reported
Level reading date:	1949-07-14	Feet below surface:	Not Reported
Feet to sea level:	-3.57	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.74	Note:	Not Reported
Level reading date:	1949-06-16	Feet below surface:	Not Reported
Feet to sea level:	-3.86	Note:	Not Reported
Level reading date:	1949-06-02	Feet below surface:	Not Reported
Feet to sea level:	-4.01	Note:	Not Reported
Level reading date:	1949-05-12	Feet below surface:	Not Reported
Feet to sea level:	-4.31	Note:	Not Reported
Level reading date:	1949-04-29	Feet below surface:	Not Reported
Feet to sea level:	-4.52	Note:	Not Reported
Level reading date:	1949-04-18	Feet below surface:	Not Reported
Feet to sea level:	-4.64	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-4.81	Note:	Not Reported
Level reading date:	1949-03-21	Feet below surface:	Not Reported
Feet to sea level:	-5.09	Note:	Not Reported
Level reading date:	1949-03-02	Feet below surface:	Not Reported
Feet to sea level:	-5.25	Note:	Not Reported
Level reading date:	1949-02-15	Feet below surface:	Not Reported
Feet to sea level:	-5.42	Note:	Not Reported
Level reading date:	1949-01-28	Feet below surface:	Not Reported
Feet to sea level:	-5.63	Note:	Not Reported

Level reading date:	1949-01-14	Feet below surface:	Not Reported
Feet to sea level:	-5.78	Note:	Not Reported
Level reading date:	1948-12-29	Feet below surface:	Not Reported
Feet to sea level:	-6.01	Note:	Not Reported
Level reading date:	1948-12-13	Feet below surface:	Not Reported
Feet to sea level:	-6.19	Note:	Not Reported
Level reading date:	1948-11-24	Feet below surface:	Not Reported
Feet to sea level:	-6.43	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-6.80	Note:	Not Reported
Level reading date:	1948-10-21	Feet below surface:	Not Reported
Feet to sea level:	-7.03	Note:	Not Reported
Level reading date:	1948-10-05	Feet below surface:	Not Reported
Feet to sea level:	-7.20	Note:	Not Reported
Level reading date:	1948-08-10	Feet below surface:	Not Reported
Feet to sea level:	-8.42	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	-8.69	Note:	Not Reported
Level reading date:	1948-07-14	Feet below surface:	Not Reported
Feet to sea level:	-8.48	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-9.30	Note:	Not Reported
Level reading date:	1948-06-10	Feet below surface:	Not Reported
Feet to sea level:	-9.77	Note:	Not Reported
Level reading date:	1948-05-22	Feet below surface:	Not Reported
Feet to sea level:	-10.28	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-11.21	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-11.54	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-11.92	Note:	Not Reported
Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-12.29	Note:	Not Reported
Level reading date:	1948-02-14	Feet below surface:	Not Reported
Feet to sea level:	-12.71	Note:	Not Reported
Level reading date:	1948-01-30	Feet below surface:	Not Reported
Feet to sea level:	-13.07	Note:	Not Reported
Level reading date:	1948-01-06	Feet below surface:	Not Reported
Feet to sea level:	-13.58	Note:	Not Reported

Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-14.73	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-14.89	Note:	Not Reported
Level reading date:	1947-11-18	Feet below surface:	Not Reported
Feet to sea level:	-15.01	Note:	Not Reported
Level reading date:	1947-10-30	Feet below surface:	Not Reported
Feet to sea level:	-15.69	Note:	Not Reported
Level reading date:	1947-10-21	Feet below surface:	Not Reported
Feet to sea level:	-15.96	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-16.12	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-16.34	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-16.54	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-17.28	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-17.65	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-18.16	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-18.60	Note:	Not Reported
Level reading date:	1947-07-22	Feet below surface:	Not Reported
Feet to sea level:	-18.95	Note:	Not Reported
Level reading date:	1947-07-14	Feet below surface:	Not Reported
Feet to sea level:	-19.23	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-19.52	Note:	Not Reported
Level reading date:	1947-07-03	Feet below surface:	Not Reported
Feet to sea level:	-19.82	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-19.93	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-20.10	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-20.41	Note:	Not Reported
Level reading date:	1947-06-27	Feet below surface:	Not Reported
Feet to sea level:	-36.36	Note:	The site was being pumped.
Level reading date:	1946-06-07	Feet below surface:	Not Reported
Feet to sea level:	-35.29	Note:	The site was being pumped.

Level reading date:	1944-08-21	Feet below surface:	Not Reported
Feet to sea level:	-35.12	Note:	Not Reported

A3
SSE **FED USGS** **USGS40000827673**
0 - 1/8 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 526. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	358
Well Depth Units:	ft	Well Hole Depth:	400
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	99	Level reading date:	1952-02-19
Feet below surface:	Not Reported	Feet to sea level:	-1.63
Note:	Not Reported		

Level reading date:	1952-01-28	Feet below surface:	Not Reported
Feet to sea level:	-2.95	Note:	Not Reported
Level reading date:	1951-12-19	Feet below surface:	Not Reported
Feet to sea level:	-3.63	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-3.73	Note:	Not Reported
Level reading date:	1951-11-02	Feet below surface:	Not Reported
Feet to sea level:	-4.00	Note:	Not Reported
Level reading date:	1951-09-25	Feet below surface:	Not Reported
Feet to sea level:	-4.21	Note:	Not Reported
Level reading date:	1951-09-11	Feet below surface:	Not Reported
Feet to sea level:	-4.34	Note:	Not Reported
Level reading date:	1951-08-27	Feet below surface:	Not Reported
Feet to sea level:	-4.28	Note:	Not Reported
Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	-4.53	Note:	Not Reported
Level reading date:	1951-06-27	Feet below surface:	Not Reported
Feet to sea level:	-4.45	Note:	Not Reported
Level reading date:	1951-05-28	Feet below surface:	Not Reported
Feet to sea level:	-4.49	Note:	Not Reported
Level reading date:	1951-04-27	Feet below surface:	Not Reported
Feet to sea level:	-4.89	Note:	Not Reported
Level reading date:	1951-03-26	Feet below surface:	Not Reported
Feet to sea level:	-5.07	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported

Feet to sea level:	-5.36	Note:	Not Reported
Level reading date:	1951-01-29	Feet below surface:	Not Reported
Feet to sea level:	-5.43	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-5.65	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-5.79	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-5.92	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-6.19	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-6.03	Note:	Not Reported
Level reading date:	1950-08-16	Feet below surface:	Not Reported
Feet to sea level:	-6.07	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-5.88	Note:	Not Reported
Level reading date:	1950-07-13	Feet below surface:	Not Reported
Feet to sea level:	-5.84	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-5.95	Note:	Not Reported
Level reading date:	1950-06-13	Feet below surface:	Not Reported
Feet to sea level:	-5.91	Note:	Not Reported
Level reading date:	1950-06-01	Feet below surface:	Not Reported
Feet to sea level:	-5.74	Note:	Not Reported
Level reading date:	1950-05-18	Feet below surface:	Not Reported
Feet to sea level:	-5.85	Note:	Not Reported
Level reading date:	1950-05-10	Feet below surface:	Not Reported
Feet to sea level:	-5.74	Note:	Not Reported
Level reading date:	1950-03-30	Feet below surface:	Not Reported
Feet to sea level:	-6.12	Note:	Not Reported
Level reading date:	1950-03-16	Feet below surface:	Not Reported
Feet to sea level:	-6.03	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-6.13	Note:	Not Reported
Level reading date:	1950-02-13	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1950-02-09	Feet below surface:	Not Reported
Feet to sea level:	-6.15	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-6.28	Note:	Not Reported

Level reading date:	1950-01-12	Feet below surface:	Not Reported
Feet to sea level:	-6.44	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-6.17	Note:	Not Reported
Level reading date:	1949-12-15	Feet below surface:	Not Reported
Feet to sea level:	-6.49	Note:	Not Reported
Level reading date:	1949-11-30	Feet below surface:	Not Reported
Feet to sea level:	-6.52	Note:	Not Reported
Level reading date:	1949-11-17	Feet below surface:	Not Reported
Feet to sea level:	-6.60	Note:	Not Reported
Level reading date:	1949-11-01	Feet below surface:	Not Reported
Feet to sea level:	-6.78	Note:	Not Reported
Level reading date:	1949-10-17	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1949-09-29	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported
Level reading date:	1949-09-20	Feet below surface:	Not Reported
Feet to sea level:	-6.89	Note:	Not Reported
Level reading date:	1949-09-01	Feet below surface:	Not Reported
Feet to sea level:	-7.02	Note:	Not Reported
Level reading date:	1949-08-19	Feet below surface:	Not Reported
Feet to sea level:	-6.97	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-7.10	Note:	Not Reported
Level reading date:	1949-07-14	Feet below surface:	Not Reported
Feet to sea level:	-7.09	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-7.26	Note:	Not Reported
Level reading date:	1949-06-16	Feet below surface:	Not Reported
Feet to sea level:	-7.30	Note:	Not Reported
Level reading date:	1949-06-02	Feet below surface:	Not Reported
Feet to sea level:	-7.34	Note:	Not Reported
Level reading date:	1949-05-12	Feet below surface:	Not Reported
Feet to sea level:	-7.52	Note:	Not Reported
Level reading date:	1949-04-29	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1949-04-18	Feet below surface:	Not Reported
Feet to sea level:	-7.70	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-7.81	Note:	Not Reported
Level reading date:	1949-03-21	Feet below surface:	Not Reported
Feet to sea level:	-8.02	Note:	Not Reported

Level reading date:	1949-03-02	Feet below surface:	Not Reported
Feet to sea level:	-8.31	Note:	Not Reported
Level reading date:	1949-02-15	Feet below surface:	Not Reported
Feet to sea level:	-8.52	Note:	Not Reported
Level reading date:	1949-01-28	Feet below surface:	Not Reported
Feet to sea level:	-8.52	Note:	Not Reported
Level reading date:	1949-01-14	Feet below surface:	Not Reported
Feet to sea level:	-8.97	Note:	Not Reported
Level reading date:	1948-12-29	Feet below surface:	Not Reported
Feet to sea level:	-9.15	Note:	Not Reported
Level reading date:	1948-12-13	Feet below surface:	Not Reported
Feet to sea level:	-9.28	Note:	Not Reported
Level reading date:	1948-11-24	Feet below surface:	Not Reported
Feet to sea level:	-9.57	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-9.84	Note:	Not Reported
Level reading date:	1948-10-21	Feet below surface:	Not Reported
Feet to sea level:	-10.06	Note:	Not Reported
Level reading date:	1948-10-05	Feet below surface:	Not Reported
Feet to sea level:	-9.14	Note:	Not Reported
Level reading date:	1948-08-10	Feet below surface:	Not Reported
Feet to sea level:	-10.97	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	-11.28	Note:	Not Reported
Level reading date:	1948-07-14	Feet below surface:	Not Reported
Feet to sea level:	-11.56	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-11.77	Note:	Not Reported
Level reading date:	1948-06-10	Feet below surface:	Not Reported
Feet to sea level:	-12.06	Note:	Not Reported
Level reading date:	1948-05-22	Feet below surface:	Not Reported
Feet to sea level:	-12.32	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-12.60	Note:	Not Reported
Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-13.02	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-13.33	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-13.50	Note:	Not Reported
Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-13.75	Note:	Not Reported

Level reading date:	1948-02-14	Feet below surface:	Not Reported
Feet to sea level:	-14.17	Note:	Not Reported
Level reading date:	1948-01-30	Feet below surface:	Not Reported
Feet to sea level:	-14.59	Note:	Not Reported
Level reading date:	1948-01-06	Feet below surface:	Not Reported
Feet to sea level:	-15.04	Note:	Not Reported
Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-15.64	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-15.76	Note:	Not Reported
Level reading date:	1947-11-18	Feet below surface:	Not Reported
Feet to sea level:	-16.11	Note:	Not Reported
Level reading date:	1947-10-30	Feet below surface:	Not Reported
Feet to sea level:	-16.60	Note:	Not Reported
Level reading date:	1947-10-21	Feet below surface:	Not Reported
Feet to sea level:	-16.84	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-16.91	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-17.09	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-17.26	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-17.85	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-18.01	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-18.23	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-18.71	Note:	Not Reported
Level reading date:	1947-07-22	Feet below surface:	Not Reported
Feet to sea level:	-18.98	Note:	Not Reported
Level reading date:	1947-07-14	Feet below surface:	Not Reported
Feet to sea level:	-19.23	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-19.49	Note:	Not Reported
Level reading date:	1947-07-03	Feet below surface:	Not Reported
Feet to sea level:	-19.98	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-20.02	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-20.09	Note:	Not Reported

Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-18.68	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-98.37	Note:	The site was being pumped.

4
SSW **FED USGS** **USGS40000827642**
1/8 - 1/4 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2482. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

B5
NE **NY WELLS** **NYREG1000000074**
1/8 - 1/4 Mile
Higher

Well Number:	K003435	Owner:	Nyc Sanitation Dept.
Well Depth:	190	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

B6
NE **NY WELLS** **NYREG1000000075**
1/8 - 1/4 Mile
Higher

Well Number:	K003435	Owner:	Nyc Sanitation Dept.
Well Depth:	190	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

C7
SSW **FED USGS** **USGS40000827602**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3430. 1	Type:	Well
Description:	4301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	120

Well Depth Units:	ft	Well Hole Depth:	120
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	34	Level reading date:	2003-07-01
Feet below surface:	Not Reported	Feet to sea level:	10.89
Note:	Not Reported		

Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.25	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	9.21	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	9.05	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	9.07	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	9.24	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	9.27	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	9.28	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	9.35	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	9.30	Note:	Not Reported
Level reading date:	1999-07-20	Feet below surface:	Not Reported
Feet to sea level:	9.32	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	9.40	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	9.46	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	9.54	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	9.58	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	9.62	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	9.71	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	9.97	Note:	Not Reported

Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	10.06	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	10.26	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	10.42	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	10.57	Note:	Not Reported
Level reading date:	1998-05-28	Feet below surface:	Not Reported
Feet to sea level:	10.34	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	10.06	Note:	Not Reported
Level reading date:	1998-03-24	Feet below surface:	Not Reported
Feet to sea level:	9.86	Note:	Not Reported
Level reading date:	1998-02-26	Feet below surface:	Not Reported
Feet to sea level:	9.85	Note:	Not Reported
Level reading date:	1998-01-26	Feet below surface:	Not Reported
Feet to sea level:	9.63	Note:	Not Reported
Level reading date:	1997-12-29	Feet below surface:	Not Reported
Feet to sea level:	9.75	Note:	Not Reported
Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	9.95	Note:	Not Reported
Level reading date:	1997-10-29	Feet below surface:	Not Reported
Feet to sea level:	9.89	Note:	Not Reported
Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	10.13	Note:	Not Reported
Level reading date:	1997-03-24	Feet below surface:	Not Reported
Feet to sea level:	10.03	Note:	Not Reported
Level reading date:	1996-07-12	Feet below surface:	Not Reported
Feet to sea level:	9.92	Note:	Not Reported

C8
SSW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827603**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3431. 1	Type:	Well
Description:	4302	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Magothy Aquifer	Aquifer Type:	Not Reported
Construction Date:	19951003	Well Depth:	385
Well Depth Units:	ft	Well Hole Depth:	385
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	86	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	11.94
Note:	Not Reported		

Level reading date:	2005-01-21	Feet below surface:	Not Reported
Feet to sea level:	11.93	Note:	Not Reported
Level reading date:	2004-12-15	Feet below surface:	Not Reported
Feet to sea level:	11.87	Note:	Not Reported
Level reading date:	2004-11-30	Feet below surface:	Not Reported
Feet to sea level:	11.84	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	11.98	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	11.83	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	11.71	Note:	Not Reported
Level reading date:	2004-07-20	Feet below surface:	Not Reported
Feet to sea level:	11.63	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	11.56	Note:	Not Reported
Level reading date:	2004-05-21	Feet below surface:	Not Reported
Feet to sea level:	11.40	Note:	Not Reported
Level reading date:	2004-04-30	Feet below surface:	Not Reported
Feet to sea level:	11.29	Note:	Not Reported
Level reading date:	2004-03-24	Feet below surface:	Not Reported
Feet to sea level:	11.18	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	11.21	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	11.13	Note:	Not Reported
Level reading date:	2003-11-19	Feet below surface:	Not Reported
Feet to sea level:	11.15	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	11.20	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	11.19	Note:	Not Reported
Level reading date:	2003-08-26	Feet below surface:	Not Reported
Feet to sea level:	11.11	Note:	Not Reported
Level reading date:	2003-07-22	Feet below surface:	Not Reported
Feet to sea level:	10.87	Note:	Not Reported
Level reading date:	2003-06-27	Feet below surface:	Not Reported
Feet to sea level:	10.62	Note:	Not Reported
Level reading date:	2003-05-20	Feet below surface:	Not Reported

Feet to sea level:	10.29	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	10.25	Note:	Not Reported
Level reading date:	2003-03-17	Feet below surface:	Not Reported
Feet to sea level:	9.95	Note:	Not Reported
Level reading date:	2003-02-27	Feet below surface:	Not Reported
Feet to sea level:	9.72	Note:	Not Reported
Level reading date:	2003-01-28	Feet below surface:	Not Reported
Feet to sea level:	9.52	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	9.14	Note:	Not Reported
Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	9.14	Note:	Not Reported
Level reading date:	2002-08-30	Feet below surface:	Not Reported
Feet to sea level:	9.06	Note:	Not Reported
Level reading date:	2002-07-22	Feet below surface:	Not Reported
Feet to sea level:	9.31	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	9.34	Note:	Not Reported
Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	9.38	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	9.53	Note:	Not Reported
Level reading date:	2002-03-21	Feet below surface:	Not Reported
Feet to sea level:	9.77	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	9.89	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	10.07	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	10.46	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	10.60	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	10.64	Note:	Not Reported
Level reading date:	2001-09-04	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	10.79	Note:	Not Reported

Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	10.80	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	10.77	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	10.61	Note:	Not Reported
Level reading date:	2001-03-21	Feet below surface:	Not Reported
Feet to sea level:	10.14	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	10.14	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	10.25	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	10.37	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	10.46	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	10.58	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	10.66	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.79	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	10.69	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	10.63	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	10.47	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	10.37	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	10.34	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	10.58	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	10.65	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	10.75	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	10.80	Note:	Not Reported

Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	10.70	Note:	Not Reported
Level reading date:	1999-07-20	Feet below surface:	Not Reported
Feet to sea level:	10.78	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	10.89	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	10.97	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	11.05	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	11.18	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	11.30	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	11.48	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	11.81	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	11.98	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	12.16	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	12.30	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	12.47	Note:	Not Reported
Level reading date:	1998-05-28	Feet below surface:	Not Reported
Feet to sea level:	12.13	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	11.74	Note:	Not Reported
Level reading date:	1998-03-24	Feet below surface:	Not Reported
Feet to sea level:	11.47	Note:	Not Reported
Level reading date:	1998-02-26	Feet below surface:	Not Reported
Feet to sea level:	11.41	Note:	Not Reported
Level reading date:	1998-01-26	Feet below surface:	Not Reported
Feet to sea level:	11.44	Note:	Not Reported
Level reading date:	1997-12-29	Feet below surface:	Not Reported
Feet to sea level:	11.63	Note:	Not Reported
Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	11.85	Note:	Not Reported
Level reading date:	1997-10-29	Feet below surface:	Not Reported
Feet to sea level:	11.86	Note:	Not Reported

Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	12.16	Note:	Not Reported
Level reading date:	1997-03-24	Feet below surface:	Not Reported
Feet to sea level:	11.74	Note:	Not Reported
Level reading date:	1996-07-12	Feet below surface:	Not Reported
Feet to sea level:	11.39	Note:	Not Reported

9
East **FED USGS** **USGS40000827690**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 517. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	303
Well Hole Depth Units:	ft		

10
NE **NY WELLS** **NYREG1000000126**
1/4 - 1/2 Mile
Higher

Well Number:	K003481	Owner:	Rym Station Bedford Incorporated
Well Depth:	150	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

11
South **FED USGS** **USGS40000827148**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1504. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	180
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	22	Level reading date:	1948-02-14
Feet below surface:	Not Reported	Feet to sea level:	-9.65
Note:	Not Reported		
Level reading date:	1948-01-30	Feet below surface:	Not Reported

Feet to sea level:	-9.93	Note:	Not Reported
Level reading date:	1948-01-06	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1947-12-18	Feet below surface:	Not Reported
Feet to sea level:	-11.18	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-11.73	Note:	Not Reported
Level reading date:	1947-11-18	Feet below surface:	Not Reported
Feet to sea level:	-12.13	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-13.36	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-13.59	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-11.86	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-14.38	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-15.23	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-15.88	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-16.83	Note:	Not Reported
Level reading date:	1947-07-22	Feet below surface:	Not Reported
Feet to sea level:	-17.07	Note:	Not Reported
Level reading date:	1947-07-14	Feet below surface:	Not Reported
Feet to sea level:	-17.51	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-17.81	Note:	Not Reported
Level reading date:	1947-07-03	Feet below surface:	Not Reported
Feet to sea level:	-18.00	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-18.03	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-18.09	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-18.11	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-18.12	Note:	Not Reported
Level reading date:	1946-10-25	Feet below surface:	Not Reported
Feet to sea level:	-17.36	Note:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D12
ESE
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000827627**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1329. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	162
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	12	Level reading date:	1947-10-30
Feet below surface:	Not Reported	Feet to sea level:	-15.49
Note:	Not Reported		

Level reading date:	1947-10-21	Feet below surface:	Not Reported
Feet to sea level:	-15.88	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-16.05	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-16.31	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-16.48	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-17.10	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-17.83	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-18.40	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-19.45	Note:	Not Reported
Level reading date:	1947-07-21	Feet below surface:	Not Reported
Feet to sea level:	-19.58	Note:	Not Reported
Level reading date:	1947-07-15	Feet below surface:	Not Reported
Feet to sea level:	-20.06	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-20.70	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D13
ESE
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000827628**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1516. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	225
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	120	Level reading date:	1956-12-27
Feet below surface:	Not Reported	Feet to sea level:	5.64
Note:	Not Reported		

Level reading date:	1956-01-03	Feet below surface:	Not Reported
Feet to sea level:	4.17	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	4.03	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1954-02-27	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	3.99	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	3.89	Note:	Not Reported
Level reading date:	1953-10-30	Feet below surface:	Not Reported
Feet to sea level:	3.84	Note:	Not Reported
Level reading date:	1953-09-24	Feet below surface:	Not Reported
Feet to sea level:	3.73	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	3.80	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	3.45	Note:	Not Reported

Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported
Level reading date:	1953-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1953-04-28	Feet below surface:	Not Reported
Feet to sea level:	2.67	Note:	Not Reported
Level reading date:	1953-03-23	Feet below surface:	Not Reported
Feet to sea level:	2.37	Note:	Not Reported
Level reading date:	1953-02-25	Feet below surface:	Not Reported
Feet to sea level:	2.24	Note:	Not Reported
Level reading date:	1953-02-02	Feet below surface:	Not Reported
Feet to sea level:	2.16	Note:	Not Reported
Level reading date:	1952-12-22	Feet below surface:	Not Reported
Feet to sea level:	1.99	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1952-08-26	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	0.75	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	0.53	Note:	Not Reported
Level reading date:	1952-04-28	Feet below surface:	Not Reported
Feet to sea level:	0.31	Note:	Not Reported
Level reading date:	1952-03-19	Feet below surface:	Not Reported
Feet to sea level:	0.01	Note:	Not Reported
Level reading date:	1952-02-19	Feet below surface:	Not Reported
Feet to sea level:	-0.14	Note:	Not Reported
Level reading date:	1952-01-28	Feet below surface:	Not Reported
Feet to sea level:	-0.18	Note:	Not Reported
Level reading date:	1951-12-19	Feet below surface:	Not Reported
Feet to sea level:	-0.68	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-0.82	Note:	Not Reported
Level reading date:	1951-11-02	Feet below surface:	Not Reported
Feet to sea level:	-0.99	Note:	Not Reported
Level reading date:	1951-09-25	Feet below surface:	Not Reported
Feet to sea level:	-1.24	Note:	Not Reported
Level reading date:	1951-08-27	Feet below surface:	Not Reported
Feet to sea level:	-1.38	Note:	Not Reported

Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	-1.54	Note:	Not Reported
Level reading date:	1951-06-27	Feet below surface:	Not Reported
Feet to sea level:	-1.65	Note:	Not Reported
Level reading date:	1951-05-28	Feet below surface:	Not Reported
Feet to sea level:	-1.81	Note:	Not Reported
Level reading date:	1951-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.04	Note:	Not Reported
Level reading date:	1951-03-26	Feet below surface:	Not Reported
Feet to sea level:	-2.21	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-2.34	Note:	Not Reported
Level reading date:	1951-01-29	Feet below surface:	Not Reported
Feet to sea level:	-2.41	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-2.50	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-2.54	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-2.60	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-2.64	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-2.60	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-2.56	Note:	Not Reported
Level reading date:	1950-07-13	Feet below surface:	Not Reported
Feet to sea level:	-2.54	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-2.52	Note:	Not Reported
Level reading date:	1950-06-13	Feet below surface:	Not Reported
Feet to sea level:	-2.52	Note:	Not Reported
Level reading date:	1950-06-01	Feet below surface:	Not Reported
Feet to sea level:	-2.54	Note:	Not Reported
Level reading date:	1950-05-18	Feet below surface:	Not Reported
Feet to sea level:	-2.53	Note:	Not Reported
Level reading date:	1950-05-04	Feet below surface:	Not Reported
Feet to sea level:	-2.51	Note:	Not Reported
Level reading date:	1950-04-17	Feet below surface:	Not Reported
Feet to sea level:	-2.46	Note:	Not Reported
Level reading date:	1950-03-30	Feet below surface:	Not Reported
Feet to sea level:	-2.28	Note:	Not Reported

Level reading date:	1950-03-16	Feet below surface:	Not Reported
Feet to sea level:	-2.81	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1950-02-09	Feet below surface:	Not Reported
Feet to sea level:	-2.91	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-2.95	Note:	Not Reported
Level reading date:	1950-01-12	Feet below surface:	Not Reported
Feet to sea level:	-3.00	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1949-12-15	Feet below surface:	Not Reported
Feet to sea level:	-3.09	Note:	Not Reported
Level reading date:	1949-11-30	Feet below surface:	Not Reported
Feet to sea level:	-3.13	Note:	Not Reported
Level reading date:	1949-11-17	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1949-11-01	Feet below surface:	Not Reported
Feet to sea level:	-3.30	Note:	Not Reported
Level reading date:	1949-10-17	Feet below surface:	Not Reported
Feet to sea level:	-3.40	Note:	Not Reported
Level reading date:	1949-09-29	Feet below surface:	Not Reported
Feet to sea level:	-3.50	Note:	Not Reported
Level reading date:	1949-09-20	Feet below surface:	Not Reported
Feet to sea level:	-3.55	Note:	Not Reported
Level reading date:	1949-09-01	Feet below surface:	Not Reported
Feet to sea level:	-3.68	Note:	Not Reported
Level reading date:	1949-08-19	Feet below surface:	Not Reported
Feet to sea level:	-3.76	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-3.90	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-4.15	Note:	Not Reported
Level reading date:	1949-06-02	Feet below surface:	Not Reported
Feet to sea level:	-4.45	Note:	Not Reported
Level reading date:	1949-05-12	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1949-04-29	Feet below surface:	Not Reported
Feet to sea level:	-4.89	Note:	Not Reported
Level reading date:	1949-04-18	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported

Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-5.25	Note:	Not Reported
Level reading date:	1949-03-21	Feet below surface:	Not Reported
Feet to sea level:	-5.47	Note:	Not Reported
Level reading date:	1949-03-02	Feet below surface:	Not Reported
Feet to sea level:	-5.72	Note:	Not Reported
Level reading date:	1949-02-15	Feet below surface:	Not Reported
Feet to sea level:	-5.90	Note:	Not Reported
Level reading date:	1949-01-28	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1949-01-14	Feet below surface:	Not Reported
Feet to sea level:	-6.32	Note:	Not Reported
Level reading date:	1948-12-29	Feet below surface:	Not Reported
Feet to sea level:	-6.54	Note:	Not Reported
Level reading date:	1948-12-13	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1948-11-24	Feet below surface:	Not Reported
Feet to sea level:	-8.22	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-7.45	Note:	Not Reported
Level reading date:	1948-10-21	Feet below surface:	Not Reported
Feet to sea level:	-7.64	Note:	Not Reported
Level reading date:	1948-09-23	Feet below surface:	Not Reported
Feet to sea level:	-8.02	Note:	Not Reported
Level reading date:	1948-09-02	Feet below surface:	Not Reported
Feet to sea level:	-8.12	Note:	Not Reported
Level reading date:	1948-08-23	Feet below surface:	Not Reported
Feet to sea level:	-8.02	Note:	Not Reported
Level reading date:	1948-08-10	Feet below surface:	Not Reported
Feet to sea level:	-7.80	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	-7.62	Note:	Not Reported
Level reading date:	1948-07-14	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-8.10	Note:	Not Reported
Level reading date:	1948-06-10	Feet below surface:	Not Reported
Feet to sea level:	-8.86	Note:	Not Reported
Level reading date:	1948-05-22	Feet below surface:	Not Reported
Feet to sea level:	-10.49	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-11.04	Note:	Not Reported

Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-11.75	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-11.92	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-12.45	Note:	Not Reported
Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-12.82	Note:	Not Reported
Level reading date:	1948-02-14	Feet below surface:	Not Reported
Feet to sea level:	-13.02	Note:	Not Reported
Level reading date:	1948-01-30	Feet below surface:	Not Reported
Feet to sea level:	-12.94	Note:	Not Reported
Level reading date:	1948-01-06	Feet below surface:	Not Reported
Feet to sea level:	-11.97	Note:	Not Reported
Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-4.25	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-4.32	Note:	Not Reported
Level reading date:	1947-11-18	Feet below surface:	Not Reported
Feet to sea level:	-15.08	Note:	Not Reported
Level reading date:	1947-10-30	Feet below surface:	Not Reported
Feet to sea level:	-15.66	Note:	Not Reported
Level reading date:	1947-10-21	Feet below surface:	Not Reported
Feet to sea level:	-15.96	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-16.21	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-16.46	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-16.66	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-17.47	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-17.89	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-18.41	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-18.99	Note:	Not Reported
Level reading date:	1947-07-21	Feet below surface:	Not Reported
Feet to sea level:	-19.47	Note:	Not Reported
Level reading date:	1947-07-14	Feet below surface:	Not Reported
Feet to sea level:	-19.79	Note:	Not Reported

Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-20.28	Note:	Not Reported

14
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000828264**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2450. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	101	Well Hole Depth Units:	ft

15
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000827062**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 528. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	307
Well Depth Units:	ft	Well Hole Depth:	371
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	29	Level reading date:	1948-07-14
Feet below surface:	Not Reported	Feet to sea level:	-7.88
Note:	Not Reported		
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1948-06-10	Feet below surface:	Not Reported
Feet to sea level:	-8.50	Note:	Not Reported
Level reading date:	1948-05-22	Feet below surface:	Not Reported
Feet to sea level:	-8.88	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-9.19	Note:	Not Reported
Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-9.75	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-10.10	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-10.39	Note:	Not Reported

Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-11.70	Note:	Not Reported
Level reading date:	1948-02-14	Feet below surface:	Not Reported
Feet to sea level:	-11.12	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-11.41	Note:	Not Reported
Level reading date:	1948-01-05	Feet below surface:	Not Reported
Feet to sea level:	-11.90	Note:	Not Reported
Level reading date:	1947-12-18	Feet below surface:	Not Reported
Feet to sea level:	-12.97	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-13.23	Note:	Not Reported
Level reading date:	1947-11-19	Feet below surface:	Not Reported
Feet to sea level:	-12.95	Note:	Not Reported
Level reading date:	1947-10-29	Feet below surface:	Not Reported
Feet to sea level:	-13.54	Note:	Not Reported
Level reading date:	1947-10-20	Feet below surface:	Not Reported
Feet to sea level:	-13.78	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-13.96	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-14.21	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-14.41	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-15.11	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-15.55	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-16.04	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-17.22	Note:	Not Reported
Level reading date:	1947-07-21	Feet below surface:	Not Reported
Feet to sea level:	-17.66	Note:	Not Reported
Level reading date:	1947-07-15	Feet below surface:	Not Reported
Feet to sea level:	-17.45	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-18.42	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-19.41	Note:	Not Reported
Level reading date:	1946-10-30	Feet below surface:	Not Reported
Feet to sea level:	-20.63	Note:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

16
ESE
1/2 - 1 Mile
Lower

NY WELLS **NYREG1000000176**

Well Number:	K003527	Owner:	Kings County Nurseries Incorporated
Well Depth:	75	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

17
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000828310**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 921. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	264	Well Depth Units:	ft
Well Hole Depth:	331	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	248	Level reading date:	1942-12-26
Feet below surface:	Not Reported	Feet to sea level:	-25.79
Note:	Not Reported		

Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-26.09	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-26.31	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-26.20	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-26.23	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-26.38	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-26.45	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-26.35	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported

Feet to sea level:	-26.36	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-26.43	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-26.42	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-26.30	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-26.28	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-26.27	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-26.15	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-25.93	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-26.00	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-26.10	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-25.95	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-26.08	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-26.28	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-26.22	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-26.18	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-26.05	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-25.12	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-26.04	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-26.06	Note:	Not Reported

Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-26.03	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-26.10	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-26.14	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-26.09	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-26.02	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-26.00	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-26.09	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-26.05	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-25.99	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-26.16	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-26.14	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-26.07	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-26.11	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-26.07	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-26.11	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-26.22	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-26.19	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-26.18	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-26.31	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-26.23	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-26.38	Note:	Not Reported

Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-26.30	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-26.50	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-26.39	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-26.43	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-26.54	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-26.55	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-26.41	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-26.59	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-26.51	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-26.54	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-26.47	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-26.38	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-26.38	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-26.34	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-25.50	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-25.48	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-23.89	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-23.86	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-24.23	Note:	Not Reported

Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-24.25	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-25.43	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-25.73	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-25.62	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-25.52	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-25.48	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-25.58	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-25.55	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-25.51	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-25.36	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-25.39	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-25.21	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-25.22	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-25.33	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-25.36	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-25.13	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-25.24	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-25.22	Note:	Not Reported

Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-25.32	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-25.35	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-25.38	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-25.41	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-25.46	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-25.23	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-25.27	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-25.45	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-25.44	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-25.46	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-25.63	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-25.64	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-25.64	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-25.76	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-25.70	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-25.74	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-25.67	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-25.67	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-25.60	Note:	Not Reported

Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-25.81	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-25.70	Note:	Not Reported
Level reading date:	1940-08-26	Feet below surface:	Not Reported
Feet to sea level:	-25.36	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-25.48	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-25.39	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1940-07-27	Feet below surface:	Not Reported
Feet to sea level:	-25.61	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-25.71	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-25.55	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-25.30	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-25.36	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-25.40	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-25.43	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-25.43	Note:	Not Reported
Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-25.13	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-25.06	Note:	Not Reported
Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-25.04	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-23.42	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-23.44	Note:	Not Reported

Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-23.38	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-23.45	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-23.18	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-24.58	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-24.81	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-24.82	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-24.82	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-24.87	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-24.77	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-24.79	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-25.02	Note:	Not Reported
Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-25.03	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-24.94	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-25.05	Note:	Not Reported
Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-25.01	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-24.92	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-24.95	Note:	Not Reported

Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-24.89	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-25.08	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-25.05	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-25.04	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-25.14	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-24.96	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-24.49	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-25.05	Note:	Not Reported
Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-25.19	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-25.02	Note:	Not Reported
Level reading date:	1939-09-16	Feet below surface:	Not Reported
Feet to sea level:	-25.04	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-25.16	Note:	Not Reported
Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-25.06	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-25.00	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-24.95	Note:	Not Reported
Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-24.67	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-24.86	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1939-07-21	Feet below surface:	Not Reported
Feet to sea level:	-24.87	Note:	Not Reported
Level reading date:	1939-07-14	Feet below surface:	Not Reported
Feet to sea level:	-24.72	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-24.70	Note:	Not Reported

Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-24.67	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-24.42	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-24.36	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-24.34	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-24.31	Note:	Not Reported
Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-24.08	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-23.77	Note:	Not Reported
Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-24.31	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-24.27	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-24.33	Note:	Not Reported
Level reading date:	1939-04-08	Feet below surface:	Not Reported
Feet to sea level:	-24.26	Note:	Not Reported
Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-24.47	Note:	Not Reported
Level reading date:	1939-03-24	Feet below surface:	Not Reported
Feet to sea level:	-24.57	Note:	Not Reported
Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-24.75	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-24.51	Note:	Not Reported
Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-24.47	Note:	Not Reported
Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-24.50	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-24.58	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported

Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-24.70	Note:	Not Reported
Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-24.72	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-24.39	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-24.64	Note:	Not Reported
Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-24.21	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-27.23	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported
Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-24.37	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-24.39	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-23.70	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-23.80	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-23.60	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-23.84	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-22.77	Note:	Not Reported
Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-24.77	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-24.72	Note:	Not Reported
Level reading date:	1938-09-23	Feet below surface:	Not Reported
Feet to sea level:	-24.93	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-25.24	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-23.97	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-25.13	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-25.12	Note:	Not Reported

Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-25.12	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-25.00	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-25.05	Note:	Not Reported
Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-24.98	Note:	Not Reported
Level reading date:	1938-07-22	Feet below surface:	Not Reported
Feet to sea level:	-24.88	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-24.79	Note:	Not Reported
Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-24.66	Note:	Not Reported
Level reading date:	1938-06-25	Feet below surface:	Not Reported
Feet to sea level:	-24.75	Note:	Not Reported
Level reading date:	1938-06-18	Feet below surface:	Not Reported
Feet to sea level:	-24.09	Note:	Not Reported
Level reading date:	1938-06-11	Feet below surface:	Not Reported
Feet to sea level:	-24.43	Note:	Not Reported
Level reading date:	1938-06-04	Feet below surface:	Not Reported
Feet to sea level:	-24.48	Note:	Not Reported
Level reading date:	1938-05-28	Feet below surface:	Not Reported
Feet to sea level:	-24.29	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-24.32	Note:	Not Reported
Level reading date:	1938-05-14	Feet below surface:	Not Reported
Feet to sea level:	-24.35	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-24.29	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-24.32	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-24.17	Note:	Not Reported
Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-24.36	Note:	Not Reported
Level reading date:	1938-04-09	Feet below surface:	Not Reported
Feet to sea level:	-24.05	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-24.24	Note:	Not Reported

Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-24.10	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-24.07	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-23.99	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-23.99	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-24.17	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-24.19	Note:	Not Reported
Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-24.00	Note:	Not Reported

E18
SSW **NY WELLS** **NYREG1000000249**
1/2 - 1 Mile
Lower

Well Number:	K003597	Owner:	123 On The Park Llc.
Well Depth:	122	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

F19
SE **NY WELLS** **NYREG1000000072**
1/2 - 1 Mile
Lower

Well Number:	K003434	Owner:	Nyc Sanitation Dept.
Well Depth:	80	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

F20
SE **NY WELLS** **NYREG1000000073**
1/2 - 1 Mile
Lower

Well Number:	K003434	Owner:	Nyc Sanitation Dept.
Well Depth:	80	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G21
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000827060**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1351. 1	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	146
Well Depth Units:	ft	Well Hole Depth:	180
Well Hole Depth Units:	ft		

G22
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000827061**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1352. 1	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	180
Well Hole Depth Units:	ft		

23
ESE
1/2 - 1 Mile
Lower

FED USGS **USGS40000827626**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1331. 1	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	137
Well Depth Units:	ft	Well Hole Depth:	145
Well Hole Depth Units:	ft		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

24
ESE
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000827216**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3272. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	45
Well Depth Units:	ft	Well Hole Depth:	45
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	16	Level reading date:	1988-05-05
Feet below surface:	Not Reported	Feet to sea level:	Not Reported
Note:	The well was destroyed (no water level is recorded).		

Level reading date:	1985-05-20	Feet below surface:	Not Reported
Feet to sea level:	10.84	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	12.15	Note:	Not Reported
Level reading date:	1984-10-03	Feet below surface:	Not Reported
Feet to sea level:	12.59	Note:	Not Reported
Level reading date:	1984-06-27	Feet below surface:	Not Reported
Feet to sea level:	12.43	Note:	Not Reported
Level reading date:	1984-03-19	Feet below surface:	Not Reported
Feet to sea level:	12.30	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	12.12	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	11.71	Note:	Not Reported
Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	11.76	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	10.09	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	10.69	Note:	Not Reported
Level reading date:	1982-06-01	Feet below surface:	Not Reported
Feet to sea level:	11.20	Note:	Not Reported
Level reading date:	1981-12-28	Feet below surface:	Not Reported
Feet to sea level:	11.83	Note:	Not Reported

Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	11.69	Note:	Not Reported
Level reading date:	1981-06-25	Feet below surface:	Not Reported
Feet to sea level:	11.41	Note:	Not Reported

E25
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000826983**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1232. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	129
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	76	Level reading date:	1950-05-04
Feet below surface:	Not Reported	Feet to sea level:	1.26
Note:	Not Reported		
Level reading date:	1950-04-17	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1950-03-30	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1950-03-16	Feet below surface:	Not Reported
Feet to sea level:	1.18	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1950-02-09	Feet below surface:	Not Reported
Feet to sea level:	1.28	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	1.19	Note:	Not Reported
Level reading date:	1950-01-12	Feet below surface:	Not Reported
Feet to sea level:	1.15	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.34	Note:	Not Reported
Level reading date:	1949-12-15	Feet below surface:	Not Reported
Feet to sea level:	1.27	Note:	Not Reported
Level reading date:	1949-11-30	Feet below surface:	Not Reported
Feet to sea level:	1.40	Note:	Not Reported
Level reading date:	1949-11-17	Feet below surface:	Not Reported
Feet to sea level:	1.42	Note:	Not Reported
Level reading date:	1949-11-01	Feet below surface:	Not Reported

Feet to sea level:	1.31	Note:	Not Reported
Level reading date:	1949-10-17	Feet below surface:	Not Reported
Feet to sea level:	1.30	Note:	Not Reported
Level reading date:	1949-09-29	Feet below surface:	Not Reported
Feet to sea level:	1.36	Note:	Not Reported
Level reading date:	1949-09-20	Feet below surface:	Not Reported
Feet to sea level:	1.32	Note:	Not Reported
Level reading date:	1949-09-01	Feet below surface:	Not Reported
Feet to sea level:	1.27	Note:	Not Reported
Level reading date:	1949-08-19	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1949-07-14	Feet below surface:	Not Reported
Feet to sea level:	1.07	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	0.91	Note:	Not Reported
Level reading date:	1949-06-16	Feet below surface:	Not Reported
Feet to sea level:	0.86	Note:	Not Reported
Level reading date:	1949-06-02	Feet below surface:	Not Reported
Feet to sea level:	0.76	Note:	Not Reported
Level reading date:	1949-05-12	Feet below surface:	Not Reported
Feet to sea level:	0.57	Note:	Not Reported
Level reading date:	1949-04-29	Feet below surface:	Not Reported
Feet to sea level:	0.35	Note:	Not Reported
Level reading date:	1949-04-18	Feet below surface:	Not Reported
Feet to sea level:	0.23	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	0.12	Note:	Not Reported
Level reading date:	1949-03-21	Feet below surface:	Not Reported
Feet to sea level:	-0.12	Note:	Not Reported
Level reading date:	1949-03-02	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1949-02-15	Feet below surface:	Not Reported
Feet to sea level:	-0.38	Note:	Not Reported
Level reading date:	1949-01-28	Feet below surface:	Not Reported
Feet to sea level:	-0.55	Note:	Not Reported
Level reading date:	1949-01-14	Feet below surface:	Not Reported
Feet to sea level:	-0.71	Note:	Not Reported
Level reading date:	1948-12-29	Feet below surface:	Not Reported
Feet to sea level:	-0.84	Note:	Not Reported

Level reading date:	1948-12-13	Feet below surface:	Not Reported
Feet to sea level:	-0.92	Note:	Not Reported
Level reading date:	1948-11-24	Feet below surface:	Not Reported
Feet to sea level:	-1.01	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-1.20	Note:	Not Reported
Level reading date:	1948-10-21	Feet below surface:	Not Reported
Feet to sea level:	-1.26	Note:	Not Reported
Level reading date:	1948-10-05	Feet below surface:	Not Reported
Feet to sea level:	-1.50	Note:	Not Reported
Level reading date:	1948-09-23	Feet below surface:	Not Reported
Feet to sea level:	-1.65	Note:	Not Reported
Level reading date:	1948-09-07	Feet below surface:	Not Reported
Feet to sea level:	-1.87	Note:	Not Reported
Level reading date:	1948-08-23	Feet below surface:	Not Reported
Feet to sea level:	-2.13	Note:	Not Reported
Level reading date:	1948-08-10	Feet below surface:	Not Reported
Feet to sea level:	-2.38	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	-2.68	Note:	Not Reported
Level reading date:	1948-07-14	Feet below surface:	Not Reported
Feet to sea level:	-3.02	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.24	Note:	Not Reported
Level reading date:	1948-06-10	Feet below surface:	Not Reported
Feet to sea level:	-3.76	Note:	Not Reported
Level reading date:	1948-05-22	Feet below surface:	Not Reported
Feet to sea level:	-4.18	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-4.57	Note:	Not Reported
Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-5.11	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-5.53	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-5.92	Note:	Not Reported
Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-6.33	Note:	Not Reported
Level reading date:	1948-02-28	Feet below surface:	Not Reported
Feet to sea level:	-4.21	Note:	Not Reported
Level reading date:	1948-01-30	Feet below surface:	Not Reported
Feet to sea level:	-7.18	Note:	Not Reported

Level reading date:	1948-01-09	Feet below surface:	Not Reported
Feet to sea level:	-7.64	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-8.34	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-8.79	Note:	Not Reported
Level reading date:	1947-11-18	Feet below surface:	Not Reported
Feet to sea level:	-9.15	Note:	Not Reported
Level reading date:	1947-10-30	Feet below surface:	Not Reported
Feet to sea level:	-9.75	Note:	Not Reported
Level reading date:	1947-10-21	Feet below surface:	Not Reported
Feet to sea level:	-10.05	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-9.90	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-10.30	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-10.54	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-11.66	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-12.25	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-12.91	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-13.67	Note:	Not Reported
Level reading date:	1947-07-22	Feet below surface:	Not Reported
Feet to sea level:	-14.23	Note:	Not Reported
Level reading date:	1947-07-14	Feet below surface:	Not Reported
Feet to sea level:	-14.81	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-15.40	Note:	Not Reported
Level reading date:	1947-07-03	Feet below surface:	Not Reported
Feet to sea level:	-15.98	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-16.23	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-16.59	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-17.32	Note:	Not Reported
Level reading date:	1947-06-23	Feet below surface:	Not Reported
Feet to sea level:	-31.50	Note:	The site was being pumped.

Level reading date:	1946-07-27	Feet below surface:	Not Reported
Feet to sea level:	-19.12	Note:	Not Reported

E26
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000826984**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1233. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	160
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	75	Level reading date:	1950-05-04
Feet below surface:	Not Reported	Feet to sea level:	1.27
Note:	Not Reported		

Level reading date:	1950-04-17	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1950-03-30	Feet below surface:	Not Reported
Feet to sea level:	1.22	Note:	Not Reported
Level reading date:	1950-03-16	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	1.18	Note:	Not Reported
Level reading date:	1950-02-09	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1950-01-12	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.33	Note:	Not Reported
Level reading date:	1949-12-15	Feet below surface:	Not Reported
Feet to sea level:	1.30	Note:	Not Reported
Level reading date:	1949-11-30	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1949-11-17	Feet below surface:	Not Reported
Feet to sea level:	1.41	Note:	Not Reported
Level reading date:	1949-11-01	Feet below surface:	Not Reported
Feet to sea level:	1.35	Note:	Not Reported
Level reading date:	1949-10-17	Feet below surface:	Not Reported

Feet to sea level:	1.34	Note:	Not Reported
Level reading date:	1949-09-29	Feet below surface:	Not Reported
Feet to sea level:	1.39	Note:	Not Reported
Level reading date:	1949-09-20	Feet below surface:	Not Reported
Feet to sea level:	1.37	Note:	Not Reported
Level reading date:	1949-09-01	Feet below surface:	Not Reported
Feet to sea level:	1.31	Note:	Not Reported
Level reading date:	1949-08-19	Feet below surface:	Not Reported
Feet to sea level:	1.27	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1949-07-14	Feet below surface:	Not Reported
Feet to sea level:	1.09	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	0.94	Note:	Not Reported
Level reading date:	1949-06-16	Feet below surface:	Not Reported
Feet to sea level:	0.89	Note:	Not Reported
Level reading date:	1949-06-02	Feet below surface:	Not Reported
Feet to sea level:	0.79	Note:	Not Reported
Level reading date:	1949-05-12	Feet below surface:	Not Reported
Feet to sea level:	0.60	Note:	Not Reported
Level reading date:	1949-04-29	Feet below surface:	Not Reported
Feet to sea level:	0.38	Note:	Not Reported
Level reading date:	1949-04-18	Feet below surface:	Not Reported
Feet to sea level:	0.28	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1949-03-21	Feet below surface:	Not Reported
Feet to sea level:	-0.09	Note:	Not Reported
Level reading date:	1949-03-02	Feet below surface:	Not Reported
Feet to sea level:	-0.04	Note:	Not Reported
Level reading date:	1949-02-15	Feet below surface:	Not Reported
Feet to sea level:	-0.37	Note:	Not Reported
Level reading date:	1949-01-28	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1949-01-14	Feet below surface:	Not Reported
Feet to sea level:	-0.65	Note:	Not Reported
Level reading date:	1948-12-29	Feet below surface:	Not Reported
Feet to sea level:	-0.74	Note:	Not Reported
Level reading date:	1948-12-13	Feet below surface:	Not Reported
Feet to sea level:	-0.89	Note:	Not Reported

Level reading date:	1948-11-24	Feet below surface:	Not Reported
Feet to sea level:	-0.98	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-1.19	Note:	Not Reported
Level reading date:	1948-10-21	Feet below surface:	Not Reported
Feet to sea level:	-1.33	Note:	Not Reported
Level reading date:	1948-10-05	Feet below surface:	Not Reported
Feet to sea level:	-1.49	Note:	Not Reported
Level reading date:	1948-09-23	Feet below surface:	Not Reported
Feet to sea level:	-1.62	Note:	Not Reported
Level reading date:	1948-09-07	Feet below surface:	Not Reported
Feet to sea level:	-1.88	Note:	Not Reported
Level reading date:	1948-08-23	Feet below surface:	Not Reported
Feet to sea level:	-2.14	Note:	Not Reported
Level reading date:	1948-08-10	Feet below surface:	Not Reported
Feet to sea level:	-3.27	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	-2.70	Note:	Not Reported
Level reading date:	1948-07-14	Feet below surface:	Not Reported
Feet to sea level:	-3.01	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1948-06-10	Feet below surface:	Not Reported
Feet to sea level:	-3.74	Note:	Not Reported
Level reading date:	1948-05-22	Feet below surface:	Not Reported
Feet to sea level:	-4.16	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-4.57	Note:	Not Reported
Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-5.09	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-5.51	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-5.93	Note:	Not Reported
Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-6.36	Note:	Not Reported
Level reading date:	1948-02-28	Feet below surface:	Not Reported
Feet to sea level:	-6.42	Note:	Not Reported
Level reading date:	1948-01-30	Feet below surface:	Not Reported
Feet to sea level:	-7.18	Note:	Not Reported
Level reading date:	1948-01-09	Feet below surface:	Not Reported
Feet to sea level:	-7.67	Note:	Not Reported

Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-8.37	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1947-11-18	Feet below surface:	Not Reported
Feet to sea level:	-9.17	Note:	Not Reported
Level reading date:	1947-10-30	Feet below surface:	Not Reported
Feet to sea level:	-9.76	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-10.25	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-10.53	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-10.76	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-11.57	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-12.17	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-12.83	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-13.60	Note:	Not Reported
Level reading date:	1947-07-22	Feet below surface:	Not Reported
Feet to sea level:	-14.16	Note:	Not Reported
Level reading date:	1947-07-14	Feet below surface:	Not Reported
Feet to sea level:	-14.71	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-15.34	Note:	Not Reported
Level reading date:	1947-07-03	Feet below surface:	Not Reported
Feet to sea level:	-15.91	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-16.16	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-16.55	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-17.25	Note:	Not Reported
Level reading date:	1947-06-27	Feet below surface:	Not Reported
Feet to sea level:	-41.20	Note:	The site was being pumped.
Level reading date:	1946-04-28	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
FED USGS	**USGS40000826958**

27
South
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1287. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	161	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX 15.5

SUPPORTING DOCUMENTATION

SITE MANAGER – PRE-SURVEY QUESTIONNAIRE

Name of person completing questionnaire:	**David Linehan**
Association with property:	**Development Manager**
Length of association with property:	**1.5 Years**
Date:	**1/25/23**
Phone Number:	**646-522-2848**
Project Site:	970 Franklin Avenue, Brooklyn, NY 11225

Directions: Please answer all questions to the best of your knowledge and in good faith. Mark the column corresponding to the appropriate response. Additional details necessary to explain any yes or unknown responses should be provided in the "Comments" column.
Note: *U/NR* indicates *"Unknown"* or *"No Response"*.

QUESTION		RESPONSE			COMMENTS
		Y	N	U/NR	
1A.	Is the property used for industrial purposes?		N		It was possibly used that way in the past.
1B.	Are any adjoining properties used for industrial purposes?		N		The adjoining property was used that way in the past
2A.	To the best of your knowledge, has the property been used for industrial purposes in the past?	Y			
2B.	To the best of your knowledge, has any of the adjoining properties been used for industrial purposes in the past?	Y			
3A.	Is the property used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		N		
3B.	Is any a**djoining property** used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		N		
4A.	To the best of your knowledge, has the property been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		N		
4B.	To the best of your knowledge, has any **adjoining property** been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		N		

U/NR: *"Unknown"* or *"No Response*

QUESTION		RESPONSE			COMMENTS
		Y	N	U/NR	
5A.	Are there currently any automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers greater than 5 gallons in volume or 50 gallons in the aggregate, stored on or used at the Property?		N		
5B.	To the best of your knowledge, have there been previously any automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers greater than 5-gallons in volume or 50-gallons in the aggregate, stored on or used at the Property?		N		
6A.	Are there currently any industrial drums (typically 55 gallon) or sacks of chemicals located on the Property?		N		
6B.	To the best of your knowledge, have there been previously any industrial drums (typically 55 gallon) or sacks of chemicals located on the Property?		N		
7A.	Has fill dirt been brought onto the Property which originated from a **contaminated site**?		N		
7B.	Has fill dirt been brought onto the Property which is of an **unknown origin**?		N		
8A.	Are there currently any pits, ponds or lagoons located on the Property in connection with waste treatment or waste disposal?		N		
8B.	To the best of your knowledge, have there been previously any pits, ponds or lagoons located on the Property in connection with waste treatment or waste disposal?		N		
9.	Is there currently, any stained soil on the Property?		N		
10A.	Are there currently any registered or unregistered storage tanks (above or underground) located on the Property?		N		
10B.	To the best of your knowledge, have there been previously any registered or unregistered storage tanks (above or underground) located on the Property?		N		
11A.	Are there currently any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the Property or adjacent to any structure located on the Property?		N		
11B.	To the best of your knowledge, have there been previously any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the Property or adjacent to any structure located on the Property?		N		
12A.	Is there currently evidence of leaks, spills or staining by substances other than water, or foul odors associated with any flooring, drains, walls, ceilings, or exposed grounds on the Property?		N		

U/NR: *"Unknown"* or *"No Response*

QUESTION		RESPONSE			COMMENTS
		Y	N	U/NR	
12B.	To the best of your knowledge, have there been previously any evidence of leaks, spills or staining by substances other than water, or foul odors associated with any flooring, drains, walls, ceilings, or exposed grounds on the Property		N		
13A.	If the Property is served by a private well or non-public water system, have contaminants been identified in the well or system that exceed guidelines applicable to the water system?		N		
13B.	If the Property is served by a private well or non-public water system has the well been designated as contaminated by any government environmental/health agency?		N		
14A.	Have you been informed of the past existence of hazardous substances or petroleum products with respect to the Property or any facility located on the Property?		N		
14B.	Have you been informed of the current existence of hazardous substances or petroleum products with respect to the Property or any facility located on the Property?		N		
15.	Are there any environmental liens or governmental notification relating to past or current violations of environmental laws with respect to the Property or any facility located on the Property?		N		
16.	Have there been any environmental site assessments of the Property that indicated the presence of hazardous substances or petroleum products on, or contamination of, the Property or recommended further assessment of the Property?		N		
17.	Does the Property discharge waste water on or adjacent to the property, other than storm water, into a storm water sewer system?		N		
18.	Have any hazardous substances or petroleum products, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials been dumped above grade, buried and/or burned on the Property?		N		
19.	Is there a transformer, capacitor or any hydraulic equipment for which there are any records indicating the presence of PCBs?		N		
Summarize historical Property use (when was the Property developed with the current improvements, what modifications have taken place, what was the Property used for prior to it's current use):		The existing warehouse on the property was part of a spice manufacturing and storage facility on the adjoining property, and was possibly built in the early 1900's.			

U/NR: *"Unknown"* or *"No Response*

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

962 FRANKLIN AVENUE **BROOKLYN 11225** **BIN# 3839651**

FRANKLIN AVENUE 962 - 966

Health Area	: 2720	**Tax Block**	: 1102
Census Tract	: 213	**Tax Lot**	: 63
Community Board	: 309		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	MONTGOMERY STREET, SULLIVAN PLACE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO

Additional BINs for Building: 3029728 3815331
HPD Multiple Dwelling: No

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: F9-FACTORY/INDSTRIAL

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Actions	6	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Buildings

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 964 FRANKLIN AVENUE BROOKLYN **BIN: 3029728 Block: 1192 Lot: 63**

NUMBER		TYPE	FILE DATE
ALT 4394-55WITHDRAWN 3-14-56		ALTERATION	12/01/1955
ALT 414-56 (962-66)		ALTERATION	02/07/1956
CERT ISSUED 154457 ALT 414-56	(PDF)	CERTIFICATE OF OCCUPANCY	01/31/1957
DEMO 516-39 (980)			05/22/1939
DOC 3254-56		DOCKET	03/16/1956
NB 19416-38 (966-94)		NEW BUILDING	12/22/1938
P&D 1379-21 DENIED		PLUMBING & DRAINAGE	08/13/1921
PRS 569-56		PLUMBING REPAIR SLIP	02/21/1956
SR 938-48		SPECIAL REPORT	05/04/1948

Select Violation Type: Show All Violations Refresh

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

972 FRANKLIN AVENUE **BROOKLYN 11225** **BIN# 3029729**

FRANKLIN AVENUE 972 - 972

Health Area	: 2720	**Tax Block**	: 1192
Census Tract	: 213	**Tax Lot**	: 66
Community Board	: 309	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	MONTGOMERY STREET, SULLIVAN PLACE		
DOB Special Place Name:	DM#321747197 S/O RQD(03/2022)		
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: E9-WAREHOUSE

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	3	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	1	
ARA / LAA Jobs	0	
Total Jobs	1	
Total Actions	0	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Document Overview

Premises: 972 FRANKLIN AVENUE BROOKLYN **Job No: 321747197**

BIN: 3029729 Block: 1192 Lot: 66 **Num. of Documents: 1** **Job Type: DM - FULL DEMOLITION**

DOC NO	WORK TYPE(S) / STATUS / JOB DESCRIPTION
01	DEMOLITION OF STRUCTURE

Status: E - APPLICATION PROCESSED - NO PLAN EXAM **Status Date:** 04/25/2018

Plans Page Count: Not Provided

Directive 14: N **Applicant Name:** SHAPIRO LAWRENCE **Pre-Filing Date:** 04/25/2018

TYPE	STATUS DATE	STATUS
DM - DEMOLITION	04/25/2018	A: PRE-FILING

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

METRO ANALYTICAL LABORATORIES
255 West 36th St., Suite #101
New York, NY 10018
p: (212) 695-0165 f: (212) 695-0183

ASBESTOS ANALYSIS of BULK SAMPLE by POLARIZED LIGHT MICROSCOPY and TRANSMISSION ELECTRON MICROSCOPY

Client:	**ALC Environmental**	Contract:	**122A,Mongomery LLC c/o Continuum Co. LLC**	**Metro Lab ID #:**	**B17070686**
Address:	121 West 27th Street	Client Job #:			
	New York NY 10001	Location:	**972 Franklin Avenue**		
	P: (212) 675-5544 F: (212) 675-4698		**Full Demo Survey - Club House**	Sample Received:	07/28/2017
			Brooklyn New York	PLM Analysis Date:	07/28/2017
Contact:	**Pat Mullo**	Sampled By:	O.W./S.S./H.A.	TEM Analysis Date:	N/A
	M: (646) 529-6529	Sampled Date:	07/18/2017, 07/20/2017	Reported By:	Trenaise Lance
	E: Pat.Mullo@alcenvironmental.com	Turnaround Time:	72 hrs	Report Date:	07/31/2017

Summary of Analysis

LAB ID #	Client Sample #	Sample Description	Test	Fibrous Material	Non-Fibrous Material	Asbestos	Total Asbestos
1	1	Black Homogenous NOB R - ROOF - MEMBRANE - EAST - ASPHALT ROLL BLACK	NY ELAP 198.1				3.2%
			NY ELAP 198.6			3.2% Chrysotile	
			NY ELAP 198.4			Not Analyzed	
2	2	Black Homogenous NOB R - ROOF - MEMBRANE - WEST - ASPHALT ROLL BLACK	NY ELAP 198.1				
			NY ELAP 198.6			Positive Stop Not Analyzed	
			NY ELAP 198.4			Not Analyzed	
3	3	Black Homogenous NOB R - ROOF - PARAPET - EAST - FLASHING TAR BLACK	NY ELAP 198.1				2.4%
			NY ELAP 198.6			2.4% Chrysotile	
			NY ELAP 198.4			Not Analyzed	
4	4	Black Homogenous NOB R - ROOF - PARAPET - NORTH - FLASHING TAR BLACK	NY ELAP 198.1				
			NY ELAP 198.6			Positive Stop Not Analyzed	
			NY ELAP 198.4			Not Analyzed	
5	5	Grey Homogenous Cementitious 1 - PERIMETER WALL - EAST - BRICK MORTAR GREY	NY ELAP 198.1		100% Non-Fibrous	None Detected	
			NY ELAP 198.6				
			NY ELAP 198.4				
6	6	Grey Homogenous Cementitious 1 - PERIMETER WALL - NORTH - BRICK MORTAR GREY	NY ELAP 198.1		100% Non-Fibrous	None Detected	
			NY ELAP 198.6				
			NY ELAP 198.4				
7	7	Grey Homogenous Cementitious 1 - PERIMETER WALL - EAST - CMU MORTAR GREY	NY ELAP 198.1		100% Non-Fibrous	None Detected	
			NY ELAP 198.6				
			NY ELAP 198.4				
8	8	Grey Homogenous Cementitious 1 - PERIMETER WALL - NW - CMU MORTAR GREY	NY ELAP 198.1		100% Non-Fibrous	None Detected	
			NY ELAP 198.6				
			NY ELAP 198.4				
9	9	Grey Homogenous Cementitious 1 - PERIMETER WALL - EAST STUCCO GREY	NY ELAP 198.1		100% Non-Fibrous	None Detected	
			NY ELAP 198.6				
			NY ELAP 198.4				
10	10	Grey Homogenous Cementitious 1 - PERIMETER WALL - NORTH - STUCCO GREY	NY ELAP 198.1		100% Non-Fibrous	None Detected	
			NY ELAP 198.6				
			NY ELAP 198.4				

Comments

Zlatan Dimitrijevic
Laboratory Director

Youssef Ibrahim
PLM Analyst

N/A
TEM Analyst

NYS ELAP ID # 12003

NVLAP Lab Code: 500081-0

METRO ANALYTICAL LABORATORIES
255 West 36th St., Suite #101
New York, NY 10018
p: (212) 695-0165 f: (212) 695-0183

Report Notes

General Notes and Disclaimers

• The samples analyzed in this report were not collected by this laboratory - they were received from the client, or an agent of the client, in good condition, unless otherwise noted.

• All results are calculated based on client-provided measurements.

• The report shall not be reproduced, except in full, without the written approval of the laboratory.

• This report relates only to the samples tested. It may not be used by the client to claim project endorsement by NVLAP, NYS ELAP, or any other government agency.

• All samples will be properly disposed of after 60 days.

• Quality Control data (including 95% confidence limits, laboratory / analysis accuracy and precision) is available upon request.

Notes Regarding Asbestos Testing

• Air Sample Analysis by Phase Contrast Microscopy (PCM) adheres to Method NIOSH-7400. Results < 7 fibers / mm^2 are statistically insignificant.

• Percentages are calculated using the EPA equivalent Stratified Point-Count Method.

• Bulk Sample Analysis by Polarized Light Microscopy (PLM) Friable adheres to EPA/600/M4-082-20 or NYS ELAP 198.1.

• Bulk Sample Analysis by Polarized Light Microscopy (PLM) NOB adheres to NYS ELAP 198.6. This method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing greater than 10% vermiculite.

• All inhomogeneous layers of the bulk samples were analyzed separately.

• Analytical results are sometimes based on the residue percentage(s) provided by the client along with the filters. Trace denotes asbestos detected at < 1%. Smiliarly, samples below quantitation limit (RL) are reported with a less than sign (<).

• Polarized Light Microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

• Bulk Sample Analysis by Transmission Electron Microscopy (TEM) NOB adheres to NYS ELAP Method 198.4.

• Air Sample Analysis by Transmission Electron Microscopy (TEM) adheres to Method EPA CFR Part 763 Final Rule (AHERA).

• Air Sample Analysis by Transmission Electron Microscopy (TEM) Worksheets are available upon request.

ALC Environmental, Inc.
121 West 27th Street, 4th Floor
New York, NY 10001
Phone: (212) 675-5544 Fax: (212) 675-6718

BULK SAMPLE DATA FORM
CHAIN OF CUSTODY DOCUMENT

B1707686

LABORATORY NAME:	ELAP # 12003
Metro Analitical Lab, 255 W 36	Laboratory Job #

CLIENT NAME	*BROOKLYN 122A MONTGOMERY LLC c/o The Continuum Company LLC*					
PROJECT NAME/LOCATION:	972 FRANKLIN AVE, BROOKLYN, NY	6 Hr.	12 Hr.	48 Hr.	72 Hr.	(Circle)
SCOPE OF WORK:	FULL DEMO SURVEY Club House					
DATE OF INSPECTION:	07-18-17 --07-20-17	PLM	PLM-NOB	TEM-NOB		(Circle)
INSPECTORS NAME(S)	Investigator Octavius Whitehead/Sergey Shulyak/H. Ali	1st Positive Stop - Per. Each HA Group				

SAMPLE ID NUMBER	FLOOR AREA	SAMPLE MATERIAL DESCRIPTION & SAMPLE LOCATION DESCRIPTION	HA GROUP	Quantity SF/LF	CONDITION	LAB RESULTS
1	R	ROOF - MEMBRANE - EAST - ASPHALT ROLL BLACK	1	1,000 SF		
2	↓	WEST - ↓ ↓	↓	↓		
3	↓	PARAPET - EAST FLASHING TAR BLACK	2	380 SF		
4	↓	NORTH ↓ ↓	↓	↓		
5	1	PERIMETER WALL EAST BRICK MORTAR GREY	3	3,500 SF		
6	↓	NORTH ↓ ↓	↓	↓		
7	↓	EAST CMU MORTAR GREY	4	350 SF		
8	↓	NW ↓ ↓	↓	↓		
9	↓	EAST STUCCO GREY	5	2,800 SF		
10	↓	NORTH ↓	↓	↓		

ADDITIONAL COMMENTS:

RELINQUISHED BY:	Sergey Shulyak			RELINQUISHED BY:			
NAME: Sshulyak	SIGNATURE:	Time:	Date: 7-28-17	NAME:	SIGNATURE:	Time:	Date:
RECEIVED BY:	Gabriele Soriano	1:05pm	7/28/17	RECEIVED BY:			
NAME:	SIGNATURE:	Time:	Date:	NAME:	SIGNATURE:	Time:	Date:

Email Results to:

Condition Assessment: G-Good F-Fair P-Poor

NYC DEPARTMENT OF FINANCE
OFFICE OF THE CITY REGISTER

This page is part of the instrument. The City Register will rely on the information provided by you on this page for purposes of indexing this instrument.The information on this page will control for indexing purposes in the event of any conflict with the rest of the document.

2017112100765001001E78FE

RECORDING AND ENDORSEMENT COVER PAGE **PAGE 1 OF 5**

Document ID: 2017112100765001 Document Date: 11-17-2017 Preparation Date: 11-21-2017
Document Type: DEED
Document Page Count: 4

PRESENTER:

FIRST NATIONWIDE TITLE AGENCY LLC
HOLD FOR DENNISE A. TO PICK UP - FN-13256-NY
50 CHARLES LINDBERGH BLVD - SUITE 600
UNIONDALE, NY 11553
212-499-0100
RECORDING@FIRSTNATIONWIDETITLE.COM

RETURN TO:

FIRST NATIONWIDE TITLE AGENCY LLC
HOLD FOR DENNISE A. TO PICK UP - FN-13256-NY
50 CHARLES LINDBERGH BLVD - SUITE 600
UNIONDALE, NY 11553
212-499-0100
RECORDING@FIRSTNATIONWIDETITLE.COM

PROPERTY DATA

Borough	Block	Lot	Unit	Address
BROOKLYN	1192	63	Entire Lot	962 FRANKLIN AVENUE

Property Type: COMMERCIAL REAL ESTATE

Borough	Block	Lot	Unit	Address
BROOKLYN	1192	66	Entire Lot	972 FRANKLIN AVENUE

Property Type: COMMERCIAL REAL ESTATE

CROSS REFERENCE DATA

CRFN_____ *or* DocumentID_____ *or* _____ Year_____ Reel____ Page_____ *or* File Number_____

PARTIES

GRANTOR/SELLER:

HPG ASSOCIATES, INC.
C/O ZEV GOLOMBECK, 1 LORD AVENUE
LAWRENCE, NY 11559

GRANTEE/BUYER:

FRANKLIN AVE PROPERTY OWNER LLC
C/O THE CONTINUUM COMPANY, 30 WEST 21ST STREET 11TH FLOOR
NEW YORK, NY 10010

FEES AND TAXES

Mortgage :		
Mortgage Amount:	$	0.00
Taxable Mortgage Amount:	$	0.00
Exemption:		
TAXES: County (Basic):	$	0.00
City (Additional):	$	0.00
Spec (Additional):	$	0.00
TASF:	$	0.00
MTA:	$	0.00
NYCTA:	$	0.00
Additional MRT:	$	0.00
TOTAL:	$	0.00
Recording Fee:	$	60.00
Affidavit Fee:	$	0.00

Filing Fee:	$	250.00
NYC Real Property Transfer Tax:	$	866,250.00
NYS Real Estate Transfer Tax:	$	132,000.00

RECORDED OR FILED IN THE OFFICE OF THE CITY REGISTER OF THE CITY OF NEW YORK
Recorded/Filed 11-27-2017 15:13
City Register File No.(CRFN): **2017000433997**

City Register Official Signature

/4

FN-13256-NY
Kings
BIK: 1192
Lots: 63, 66

WARRANTY DEED

This instrument drafted by
and after recording return to:

Duval & Stachenfeld LLP
555 Madison Avenue, 6th Floor
New York, New York 10022
Attention: Michael Estreicher, Esq.

THIS INDENTURE, made as of this 17 day of November, 2017, by HPG ASSOCIATES, INC., a New York corporation, having an office at c/o Zev Golombeck, 1 Lord Avenue, Lawrence, New York 11559 ("***Grantor***"), in favor of FRANKLIN AVE PROPERTY OWNER LLC, a Delaware limited liability company, having its office at c/o The Continuum Company, LLC, 30 West 21st Street, 11th Floor, New York, NY, 10010 ("***Grantee***").

WITNESSETH:

That Grantor, in consideration of Ten Dollars ($10.00) and other good and valuable consideration paid by Grantee, the receipt and sufficiency of which are hereby acknowledged, does hereby convey, grant and release unto Grantee, its heirs and successors and assigns, forever, all right, title and interest of Grantor in and to the following:

All that certain plots, pieces, or parcels of land, with the buildings and improvements thereon erected, situate, lying and being in the County of Kings, City of New York, State of New York, located at 962 and 972 Franklin Avenue and designated as Block 1192, Lot 63 and Lot 66; and as more particularly described in **Exhibit A** attached hereto and incorporated herein for all purposes (the "***Property***").

TOGETHER with all right, title and interest, if any, of Grantor in and to any streets and roads abutting the above described premises to the center lines thereof;

TOGETHER with the appurtenances and all the estate and rights of Grantor in and to said premises;

TO HAVE AND TO HOLD the premises herein granted unto Grantee, its heirs and successors and assigns, forever. The above described Property being and intended to be the same premises described in the deeds to Grantor recorded in Reel 1402, Page 1573.

Grantor covenants as follows: that Grantor is seized of the said premises in fee simple, and has good right to convey the same; that the Grantee shall quietly enjoy the said premises; that the said premises are free from encumbrances, except as aforesaid; that the Grantor will execute or procure any further necessary assurance of the title to said premises; and that Grantor will forever warrant the title to said premises.

Grantor, in compliance with Section 13 of the Lien Law of the State of New York, covenants that Grantor will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvement of the Property, and will apply the same first to the payment of the cost of the improvement of the Property, before using any part of the total of the same for any other purpose.

(signatures appear on next page)

IN WITNESS WHEREOF, Grantor has duly executed this Deed the day and year first above written.

HPG ASSOCIATES, INC.

By: _____
Name: Abraham "Zev" Golombeck
Title: President

STATE OF NEW YORK)
) ss.:
COUNTY OF NEW YORK)

On the 7 day of November in the year 2017, before me, the undersigned, a notary public in and for said state, personally appeared Abraham Golombeck personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that she executed the same in her capacity and that by her signature on the instrument, the individual or the person upon behalf of which the individual acted, executed the instrument.

CAROL SILVERSTEIN
Notary Public, State of New York
No. 24-5010587
Qualified in Kings County
Commission Expires April 5, 2019

_____
Notary Public

My commission expires: 4/5/19

SEAL

962 & 972
972 Franklin Avenue
Brooklyn, NY 11225

Inquiry Number: 7231046.2s
February 2, 2023

EDR Vapor Encroachment Screen

Prepared using EDR's Vapor Encroachment Worksheet

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	**ES1**
Primary Map	**2**
Secondary Map	**3**
Map Findings	**4**
Record Sources and Currency	**GR-1**

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

The EDR Vapor Encroachment Worksheet enables EDR's customers to make certain online modifications that effects maps, text and calculations contained in this Report. As a result, maps, text and calculations contained in this Report may have been so modified. EDR has not taken any action to verify any such modifications, and this report and the findings set forth herein must be read in light of this fact. Environmental Data Resources shall not be responsible for any customer's decision to include or not include in any final report any records determined to be within the relevant minimum search distances.

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by EDR. The report was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property Involved in Real Estate Transactions (E 2600).

STANDARD ENVIRONMENTAL RECORDS	Default Area of Concern (Miles)*	property	1/10	> 1/10
Lists of Federal NPL (Superfund) sites	1.0	0	0	0
Lists of Federal Delisted NPL sites	1.0	0	0	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders	0.5	0	0	0
Lists of Federal CERCLA sites with NFRAP	0.5	0	0	0
Lists of Federal RCRA facilities undergoing Corrective Action	1.0	0	0	0
Lists of Federal RCRA TSD facilities	0.5	0	0	0
Lists of Federal RCRA generators	0.25	0	1	0
Federal institutional controls / engineering controls registries	0.5	0	0	0
Federal ERNS list	property	0	-	-
Lists of state- and tribal (Superfund) equivalent sites	not searched	-	-	-
Lists of state- and tribal hazardous waste facilities	1.0	0	0	0
Lists of state and tribal landfills and solid waste disposal facilities	0.5	0	0	0
Lists of state and tribal leaking storage tanks	0.5	0	0	9
Lists of state and tribal registered storage tanks	0.5	0	0	1
State and tribal institutional control / engineering control registries	0.5	0	0	0
Lists of state and tribal voluntary cleanup sites	0.5	0	0	2
Lists of state and tribal brownfield sites	0.5	0	0	0

ADDITIONAL ENVIRONMENTAL RECORDS				
Local Brownfield lists	0.5	0	0	0
Local Lists of Landfill / Solid Waste Disposal Sites	0.5	0	0	0
Local Lists of Hazardous waste / Contaminated Sites	1.0	0	0	0
Local Lists of Registered Storage Tanks	0.25	0	0	0
Local Land Records	property	0	-	-
Records of Emergency Release Reports	0.125	0	1	3
Other Ascertainable Records	1.0	0	2	5

EDR HIGH RISK HISTORICAL RECORDS				
EDR Exclusive Records	1.0	0	1	0
Exclusive Recovered Govt. Archives	property	0	-	-

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

EDR Exclusive Records	1.0	0	1	0
Exclusive Recovered Govt. Archives	property	0	-	-

*The Default Area of Concern may be adjusted by the environmental professional using experience and professional judgement. Each category may include several databases, and each database may have a different distance. A list of individual databases is provided at the back of this report.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

962 & 972
972 FRANKLIN AVENUE
BROOKLYN, NY 11225

COORDINATES

Latitude (North):	40.665112 - 40° 39′ 54.40155″
Longitude (West):	73.960462 - 73° 57′ 37.67212″
Elevation:	90 ft. above sea level

EXECUTIVE SUMMARY

SEARCH RESULTS

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
NYC BD OF ED - IS 320K RCRA-VSQG: RCRA-VSQG NY Spills: SPILLS LEAD: NYC LEAD MANIFEST: NY MANIFEST	46 MCKEEVER PL	<1/10 E	◆ 1	10
54 CROWN STREET VCP: VCP	46 CROWN STREET	1/10 - 1/3 NNE	▲ G5	30
CENTRAL LAUNDRY CORP.-SEACREST DIV. NY Spills: SPILLS CBS: CBS LTANKS: LTANKS AST: AST	46 CROWN STREET	1/10 - 1/3 NNE	▲ G6	31
TANK TEST LTANKS: LTANKS	49 CROWN ST	1/10 - 1/3 N	▲ 7	36
BROOKLYN EAST 09 DOS -DDC NY Spills: SPILLS LTANKS: LTANKS	115 CROWN STREET	1/10 - 1/3 NE	▲ 8	38
NYCTA - CHEMICAL LABORATORY FINDS: FINDS ECHO: ECHO RCRA NonGen / NLR: RCRA NonGen / NLR LTANKS: LTANKS	960 CARROLL ST	1/10 - 1/3 NNE	▲ O9	52
931 CARROLL STREET VCP: VCP	931 CARROLL STREET	1/10 - 1/3 NNE	▲ Q10	61
SEACREST LINEN E DESIGNATION: E DESIGNATION LTANKS: LTANKS	931 CARROLL ST	1/10 - 1/3 NNE	▲ Q11	62
CLARA BARTON HIGH SCHOOL LTANKS: LTANKS	925 CARROLL ST	1/10 - 1/3 N	▲ 12	65
CLARA BARTON HIGH SCHOOL LTANKS: LTANKS	CLASSON AVE AT PRESIDENT	1/10 - 1/3 N	▲ 14	75
BOARD OF EDUCATION NY Spills: SPILLS LTANKS: LTANKS	901 CLASSON AVE	1/10 - 1/3 NNW	▲ 15	76
POLLOCK FILM INC	1579 BEDFORD AVE-LOADING AREA	1/10 - 1/3 NE	▲ 16	78

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
RCRA NonGen / NLR: RCRA NonGen / NLR LTANKS: LTANKS MANIFEST: NY MANIFEST				

ADDITIONAL ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
NYC BD OF ED - IS 320K RCRA-VSQG: RCRA-VSQG NY Spills: SPILLS LEAD: NYC LEAD MANIFEST: NY MANIFEST	46 MCKEEVER PL	<1/10 E	◆ 1	10
GARDEN CLEANERS DRYCLEANERS: DRYCLEANERS	96 MONTGOMERY STREET	<1/10 NNW	▲ D2	28
SEA CREST LINEN/CENTRAL LAUNDRY SERVICE DRYCLEANERS: DRYCLEANERS	46 CROWN STREET	1/10 - 1/3 NNE	▲ G4	29
CENTRAL LAUNDRY CORP.-SEACREST DIV. NY Spills: SPILLS CBS: CBS LTANKS: LTANKS AST: AST	46 CROWN STREET	1/10 - 1/3 NNE	▲ G6	31
BROOKLYN EAST 09 DOS -DDC NY Spills: SPILLS LTANKS: LTANKS	115 CROWN STREET	1/10 - 1/3 NE	▲ 8	38
NYCTA - CHEMICAL LABORATORY FINDS: FINDS ECHO: ECHO RCRA NonGen / NLR: RCRA NonGen / NLR LTANKS: LTANKS	960 CARROLL ST	1/10 - 1/3 NNE	▲ O9	52
SEACREST LINEN E DESIGNATION: E DESIGNATION LTANKS: LTANKS	931 CARROLL ST	1/10 - 1/3 NNE	▲ Q11	62
NEW GARDEN CLEANER DRYCLEANERS: DRYCLEANERS	879 FRANKLIN AVE	1/10 - 1/3 NNE	▲ O13	66
BOARD OF EDUCATION NY Spills: SPILLS LTANKS: LTANKS	901 CLASSON AVE	1/10 - 1/3 NNW	▲ 15	76
POLLOCK FILM INC RCRA NonGen / NLR: RCRA NonGen / NLR LTANKS: LTANKS MANIFEST: NY MANIFEST	1579 BEDFORD AVE-LOADING AREA	1/10 - 1/3 NE	▲ 16	78

EDR HIGH RISK HISTORICAL RECORDS

Name	Address	Dist/Dir	Map ID	Page

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
GARDEN CLEANING	96 MONTGOMERY ST	<1/10 NNW	▲ D3	29
EDR Hist Cleaner: EDR Hist Cleaner				

EDR RECOVERED GOVERNMENT ARCHIVES

Name	Address	Dist/Dir	Map ID	Page
Not Reported				

PRIMARY MAP - 7231046.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

National Wetland Inventory

State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 962 & 972	CLIENT: The ALC Group, LLC T/A ALC
ADDRESS: 972 Franklin Avenue Brooklyn NY 11225	CONTACT: Tania Castro INQUIRY #: 7231046.2s
LAT/LONG: 40.665112 / 73.960462	DATE: January 23, 2023 10:42 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

SECONDARY MAP - 7231046.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

Power transmission lines

Pipelines

National Wetland Inventory

State Wetlands

Upgradient Area

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	962 & 972	CLIENT:	The ALC Group, LLC T/A ALC
ADDRESS:	972 Franklin Avenue Brooklyn NY 11225	CONTACT:	Tania Castro
		INQUIRY #:	7231046.2s
LAT/LONG:	40.665112 / 73.960462	DATE:	January 23, 2023 10:41 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS

LEGEND

FACILITY NAME **FACILITY ADDRESS, CITY, ST, ZIP**		EDR SITE ID NUMBER
◆ **MAP ID#**	Direction Distance Range (Distance feet / miles) Relative Elevation Feet Above Sea Level	ASTM 2600 Record Sources found in this report. Each database searched has been assigned to one or more categories. For detailed information about categorization, see the section of the report Records Searched and Currency.

Worksheet:

Comments:
Comments may be added on the online Vapor Encroachment Worksheet.

DATABASE ACRONYM: Applicable categories (A hoverbox with database description).

NYC BD OF ED - IS 320K 46 MCKEEVER PL, BROOKLYN, NY, 11225			1005444316
◆ 1	E <1/10	(280 ft. / 0.053 mi.)	Lists of Federal RCRA generators Records of Emergency Release Reports Other Ascertainable Records
	4 ft. Lower Elevation	86 ft. Above Sea Level	

Worksheet:

RCRA Listings: Lists of Federal RCRA generators

Date Form Received by Agency:	20070101
Handler Name:	NYC BD OF ED - IS 320K
Handler Address:	46 MCKEEVER PL
Handler City,State,Zip:	BROOKLYN, NY 11225
EPA ID:	NYR000106377
Contact Name:	BERNARD ORLAN
Contact Address:	QUEENS PLZ N
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-391-6475
Contact Fax:	Not Reported
Contact Email:	Not Reported
Contact Title:	Not Reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not Reported
Biennial Report Cycle:	Not Reported
Accessibility:	Not Reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	QUEENS PLZ N
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	NYC BOARD OF EDUCATION

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Owner Type:	Municipal
Operator Name:	NYC BOARD OF EDUCATION
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not Reported
Active Site Converter Treatment storage and Disposal Facility:	Not Reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not Reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not Reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not Reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not Reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not Reported
Permit Workload Universe:	Not Reported
Permit Progress Universe:	Not Reported
Post-Closure Workload Universe:	Not Reported
Closure Workload Universe:	Not Reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Operating TSDF Universe:	Not Reported
Full Enforcement Universe:	Not Reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not Reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not Reported
Manifest Broker:	Not Reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC BOARD OF EDUCATION
Legal Status:	Municipal
Date Became Current:	Not Reported
Date Ended Current:	Not Reported
Owner/Operator Address:	2811 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-391-6475
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC BOARD OF EDUCATION
Legal Status:	Municipal
Date Became Current:	20010101
Date Ended Current:	Not Reported
Owner/Operator Address:	2811 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-391-6475
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC BOARD OF EDUCATION
Legal Status:	Municipal
Date Became Current:	20010101
Date Ended Current:	Not Reported
Owner/Operator Address:	2811 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-391-6475
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported

Historic Generators:

Receive Date:	20060101
Handler Name:	NYC BD OF ED - IS 320K
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

Receive Date:	20070101
Handler Name:	NYC BD OF ED - IS 320K
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

Receive Date:	20020517
Handler Name:	NYC BD OF ED - IS 320K
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Listing - General
Date Violation was Determined:	20150316
Actual Return to Compliance Date:	20150916
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not Reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150416
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not Reported
Enforcement Attorney:	Not Reported
Corrective Action Component:	No
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported
Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYCMK
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported
SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported

Found Violation:	Yes

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Agency Which Determined Violation:	State
Violation Short Description:	Listing - General
Date Violation was Determined:	20150316
Actual Return to Compliance Date:	20150916
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not Reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150416
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not Reported
Enforcement Attorney:	Not Reported
Corrective Action Component:	No
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported
Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYCMK
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported
SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20150316
Actual Return to Compliance Date:	20150506
Return to Compliance Qualifier:	Not Resolved
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not Reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150416
Enforcement Responsible Agency:	State

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Enforcement Docket Number:	Not Reported
Enforcement Attorney:	Not Reported
Corrective Action Component:	No
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported
Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYCMK
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported
SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20150316
Actual Return to Compliance Date:	20150916
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not Reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150416
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not Reported
Enforcement Attorney:	Not Reported
Corrective Action Component:	No
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYCMK
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported
SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20150316
Actual Return to Compliance Date:	20150916
Return to Compliance Qualifier:	Not Resolved
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not Reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150416
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not Reported
Enforcement Attorney:	Not Reported
Corrective Action Component:	No
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported
Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYCMK
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20150316
Actual Return to Compliance Date:	20150909
Return to Compliance Qualifier:	Not Resolved
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not Reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150416
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not Reported
Enforcement Attorney:	Not Reported
Corrective Action Component:	No
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported
Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYCMK
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported
SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported

Evaluation Action Summary:

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916
Scheduled Compliance Date:	Not Reported
Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916
Scheduled Compliance Date:	Not Reported
Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150506
Scheduled Compliance Date:	Not Reported
Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported

Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Scheduled Compliance Date:	Not Reported
Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported
Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150916
Scheduled Compliance Date:	Not Reported
Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported
Evaluation Date:	20150316
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYCMK
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20150909
Scheduled Compliance Date:	Not Reported
Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported

SPILLS: Records of Emergency Release Reports

Name:	SCHOOL
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2101518 / 2021-09-13
Facility ID:	2101518
Facility Type:	ER
DER Facility ID:	566842
Site ID:	619234
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not Reported
SWIS:	2401
Spill Date:	2021-05-18
Investigator:	AAOBLIGA

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Referred To:	Not Reported
Reported to Dept:	2021-05-19
CID:	Not Reported
Water Affected:	Not Reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not Reported
Cleanup Meets Std:	False
Last Inspection:	Not Reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-05-19
Spill Record Last Update:	2021-09-13
Spiller Name:	Not Reported
Spiller Company:	NYC SCHOOL CONSTRUCTION AUTHORITY
Spiller Address:	Not Reported
Spiller Company:	999
Contact Name:	JENNA RAUP
DEC Memo:	"5/19/21 - Obligado - Desk Duty - There was a temporary boiler with a 10,000 gallon AST in the street. Once of the valves was leaking. It was a slow leak that they noticed yesterday morning. Easco went yesterday to clean and they will do more today. The repair of the valve has been completed. Jenn of NYCSCA will send me email with pictures documenting the work. According to Jenn no drains were impacted."
Remarks:	"Clean-up pending."

All Materials:

Site ID:	619234
Operable Unit ID:	1366410
Operable Unit:	01
Material ID:	2379041
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	3.00
Units:	Not Reported
Recovered:	Not Reported
Oxygenate:	Not Reported

Name:	46 MCKEEVER PLACE
Address:	46 MCKEEVER PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9302528 / 1993-05-25
Facility ID:	9302528
Facility Type:	ER

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

DER Facility ID:	114686
Site ID:	133241
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1993-05-25
Investigator:	KSTANG
Referred To:	Not Reported
Reported to Dept:	1993-05-25
CID:	Not Reported
Water Affected:	Not Reported
Spill Source:	Vessel
Spill Notifier:	Other
Cleanup Ceased:	1993-05-25
Cleanup Meets Std:	True
Last Inspection:	Not Reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-05-25
Spill Record Last Update:	1993-07-19
Spiller Name:	Not Reported
Spiller Company:	PUB. SCHOOL 320.
Spiller Address:	Not Reported
Spiller Company:	001
Contact Name:	Not Reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG. "
Remarks:	"FUEL LEAKED DUE TO FAULTY PLUMBING- DRIVER WASN'T NOTIFIED OF PROBLEM UNTIL OFTER SPILL OCCURRED. DRIVER CUSTODIAN CLEANED SPILL-NYC DEP TO BE NOTIFIED."

All Materials:

Site ID:	133241
Operable Unit ID:	980857
Operable Unit:	01
Material ID:	399650
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

NYC LEAD 2: Other Ascertainable Records

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	103
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	106
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	108
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	114
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	116
Deteriorated Paint:	NO
Presence of LBP:	NA

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	118
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	120
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	126
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	128
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Room:	135
Deteriorated Paint:	YES
Presence of LBP:	NO
Stabilization Required:	NO
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	214B
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	224/226
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	229
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	231
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	AUD
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	C-15
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	C-17
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 375 - BROOKLYN
Address:	46 MCKEEVER PLACE
City,State,Zip:	BROOKLYN, NY
Geographical District:	17
Building Code:	K320
Room:	cafe
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

NY MANIFEST: Other Ascertainable Records

Name:	NYC BOARD OF EDUCATION
Address:	46 MCKEEVER PL
City,State,Zip:	BROOKLYN, NY 11225
Country:	USA
EPA ID:	NYR000106377
Facility Status:	Not Reported
Location Address 1:	46 MCKEEVER PLACE
Code:	BP

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

Location Address 2:	Not Reported
Total Tanks:	Not Reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11226
Location Zip 4:	Not Reported

NY MANIFEST:

EPAID:	NYR000106377
Mailing Name:	NYC BOARD OF EDUCATION
Mailing Contact:	N/S
Mailing Address 1:	46 MCKEEVER PL
Mailing Address 2:	Not Reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11225
Mailing Zip 4:	Not Reported
Mailing Country:	USA
Mailing Phone:	7189414514

NY MANIFEST:

Document ID:	Not Reported
Manifest Status:	Not Reported
seq:	Not Reported
Year:	2018
Trans1 State ID:	NYD986938645
Trans2 State ID:	Not Reported
Generator Ship Date:	12/05/2014
Trans1 Recv Date:	12/05/2014
Trans2 Recv Date:	Not Reported
TSD Site Recv Date:	12/10/2014
Part A Recv Date:	Not Reported
Part B Recv Date:	Not Reported
Generator EPA ID:	NYR000106377
Trans1 EPA ID:	Not Reported
Trans2 EPA ID:	Not Reported
TSDF ID 1:	MAC300017498
TSDF ID 2:	Not Reported
Manifest Tracking Number:	002581461GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not Reported
Alt Facility RCRA ID:	Not Reported
Alt Facility Sign Date:	Not Reported

NYC BD OF ED - IS 320K, 46 MCKEEVER PL, BROOKLYN, NY 11225 (Continued)

MGMT Method Type Code:	H141
Waste Code:	Not Reported
Waste Code:	Not Reported
Waste Code:	Not Reported
Waste Code:	Not Reported
Waste Code:	Not Reported
Waste Code:	Not Reported
Quantity:	31
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not Reported
Waste Code 1_3:	Not Reported
Waste Code 1_4:	Not Reported
Waste Code 1_5:	Not Reported
Waste Code 1_6:	Not Reported

GARDEN CLEANERS
96 MONTGOMERY STREET, BROOKLYN, NY, 11225 S110246668

▲ D2	NNW <1/10	(344 ft. / 0.065 mi.)	Other Ascertainable Records
	12 ft. Higher Elevation	102 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Comments: This site is approximately 334 feet to the northwest and up-gradient from the Subject Property. Per the records, this facility began operating in 1994 and the last inspection was completed on November 19, 2003. The records indicate that the facility has closed. There are no reported releases or violations.

Conditions:

Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

DRYCLEANERS: Other Ascertainable Records

Name:	GARDEN CLEANERS
Address:	96 MONTGOMERY STREET
City,State,Zip:	BROOKLYN, NY 11225
Facility ID:	2-6104-00816
Phone Number:	NOT LISTED
Region:	Not Reported
Registration Effective Date:	N/A
Inspection Date:	2003-11-19 00:00:00
Install Date:	94/03
Expiration Date:	Not Reported
Removal Date:	Not Reported

GARDEN CLEANERS, 96 MONTGOMERY STREET, BROOKLYN, NY 11225 (Continued)

Drop Shop:	Not Reported
Shutdown:	Y
Alternate Solvent:	Not Reported
Current Business:	Not Reported

GARDEN CLEANING 96 MONTGOMERY ST, NEW YORK - BROOKLYN, NY, 11225		1018429970
▲ D3	NNW <1/10 (344 ft. / 0.065 mi.)	EDR Exclusive Records
	12 ft. Higher Elevation 102 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Comments: The records indicate that Garden Cleaning operated at this site between at least 1986 and 1996. This site was cross-listed in the NY DRYCLEANERS database. The records indicate that this facility was last inspected on November 19, 2003, and that the facility has been closed. There are no reported releases or violations. Based on the distance, and the presence of buildings and a road in between this site and the Subject Property, no significant impacts to the Subject Property are anticipated from this site.

Conditions:

Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

EDR Hist Cleaner: EDR Exclusive Records

Year:	Name: / Type:
1986:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1987:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1988:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1989:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1990:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1991:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1992:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1993:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1994:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1995:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents
1996:	GARDEN CLEANING / Garment Pressing And Cleaners' Agents

SEA CREST LINEN/CENTRAL LAUNDRY SERVICE 46 CROWN STREET, BROOKLYN, NY, 11225		S110247883
▲ G4	NNE 1/10 - 1/3 (668 ft. / 0.127 mi.)	Other Ascertainable Records
	15 ft. Higher Elevation 105 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.

Conditions:

Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

DRYCLEANERS: Other Ascertainable Records

Name:	SEA CREST LINEN/CENTRAL LAUNDRY SERVICE
Address:	46 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Facility ID:	2-6104-00778
Phone Number:	718-287-4800
Region:	Not Reported
Registration Effective Date:	N/A
Inspection Date:	2003-11-19 00:00:00
Install Date:	Not Reported
Expiration Date:	Not Reported
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Y
Alternate Solvent:	Not Reported
Current Business:	Not Reported

54 CROWN STREET 46 CROWN STREET, NEW YORK CITY, NY,			S125317144
▲ G5	NNE 1/10 - 1/3	(668 ft. / 0.127 mi.)	Lists of state and tribal voluntary cleanup sites
	15 ft. Higher Elevation	105 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist
Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Both COC & PHC: YES
Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

VCP NYC: Lists of state and tribal voluntary cleanup sites

Project ID:	19TMP1132K,19EH-A295K,20CVCP031K
Name:	54 CROWN STREET
Address:	46 CROWN STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0119000293011901E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.667294
Longitude:	-73.960028
Postcode:	9
Community Board:	35
Council District:	213
Census Tract:	3330786
BIN:	3011900029

54 CROWN STREET, 46 CROWN STREET, NEW YORK CITY, NY (Continued)

NTA: Crown Heights South

CENTRAL LAUNDRY CORP.-SEACREST DIV. 46 CROWN STREET, BROOKLYN, NY, 11225		S103941438	
▲ G6	NNE 1/10 - 1/3	(668 ft. / 0.127 mi.)	Lists of state and tribal leaking storage tanks Lists of state and tribal registered storage tanks Records of Emergency Release Reports
	15 ft. Higher Elevation	105 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist
Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Both COC & PHC: YES
Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	TANK TEST FAILURE AT COMMERCIAL BUILDING
Address:	46 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1406415 / 2015-01-29
Facility ID:	1406415
Site ID:	499883
Spill Date:	2014-09-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	RMPIPER
Referred To:	Not Reported
Reported to Dept:	2014-09-16
CID:	Not Reported
Water Affected:	Not Reported
Spill Notifier:	Other
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-09-16
Spill Record Last Update:	2015-02-06
Spiller Name:	Not Reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not Reported
Spiller County:	999
Spiller Contact:	RAY KAHN
Spiller Phone:	(212) 330-7501

CENTRAL LAUNDRY CORP.-SEACREST DIV., 46 CROWN STREET, BROOKLYN, NY 11225 (Continued)

Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	95767
DEC Memo:	"11-09-2014-DEC Piper spoke with Ray Kahn, tank is rbeing removed today. Cont soil is present and will be overexcavated. Once done, endpoints will be taken. Report to follow. 1/29/15- DECPiper received tank removal/ closure report. Based on excavation removal and endpoints, this spill is closed. See Dec Docs for Report."
Remarks:	"reccommend removal"

All Materials:

Site ID:	499883
Operable Unit ID:	1249290
Operable Unit:	01
Material ID:	2250854
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	Not Reported
Units:	Not Reported
Recovered:	Not Reported
Oxygenate:	Not Reported

Name:	SEA CREST LINEN
Address:	46 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9903240 / 1999-08-10
Facility ID:	9903240
Site ID:	108983
Spill Date:	1999-06-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not Reported
Reported to Dept:	1999-06-21
CID:	365
Water Affected:	Not Reported
Spill Notifier:	Tank Tester
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-21
Spill Record Last Update:	2003-11-20

CENTRAL LAUNDRY CORP.-SEACREST DIV., 46 CROWN STREET, BROOKLYN, NY 11225 (Continued)

Spiller Name:	T WILLIAMS
Spiller Company:	SEA CREST LINEN
Spiller Address:	46 CROWN ST
Spiller County:	001
Spiller Contact:	T WILLIAMS
Spiller Phone:	(718) 287-4800
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	95767
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND JUNE 24, 1999 PROTEST WAS AT SITE AND RE-TESTED THE TANK ALONE AND THE LINES ALONE.... BOTH PAST THE TEST.... HOWEVER, PROTEST DISCOVERED SOIL CONTAMINATION NEAR THE OIL FILL PORT. THEY DUG AROUND THAT AREA AND REMOVED 2 CUBIC YARDS OF CONTAMINATION. THE CONTAMINATION SEEMS TO BE BETWEEN THE SIDE OF THE BURIED TANK AND THE BUILDING FOUNDATION WALL. SANGESLAND TOLD PROTEST TO EXCAVATE AS MUCH CONTAMINATION AS POSSIBLE (MAINTAINING BUILDING STRUCTUAL INTEGRITY) AND TAKE END POINT SAMPLES. IF THE CONTAMINATION GETS WORSE OR DOESN'T END PROTEST WILL CALL BACK. 8/10/99 RECEIVED A REPORT FROM PROTEST SHOWING SYSTEM NOW PASSES HORNER EZY 3 TIGHTNESS TEST. 49.84 TONS OF CONTAMINATED SOIL WERE REMOVED (MANIFESTED TO CLEAN WATERS OF AMERICA 603-798-4700) 2 END POINT SAMPLES WERE TAKEN FROM THE EXCAVATION. SOME SLIGHT HITS, VERY MINOR. SPILL CLOSED 8/10/99 "
Remarks:	"horner ez 3 - underground tank"

All TTF:

Facility ID:	9903240
Spill Number:	9903240
Spill Tank Test:	1547284
Site ID:	108983
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not Reported
UST:	Not Reported
Cause:	Not Reported
Source:	Not Reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not Reported

All Materials:

CENTRAL LAUNDRY CORP.-SEACREST DIV., 46 CROWN STREET, BROOKLYN, NY 11225 (Continued)

Site ID:	108983
Operable Unit ID:	1082164
Operable Unit:	01
Material ID:	303168
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

CBS: Lists of state and tribal registered storage tanks

Name:	CENTRAL LAUNDRY CORP.-SEACREST DIV.
Address:	46 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
CBS Number:	2-000158
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not Reported
Dec Region:	2
UTMX:	587897.10291
UTMY:	4502342.23434

AST: Lists of state and tribal registered storage tanks

Name:	CENTRAL LAUNDRY CORP.-SEACREST DIV.
Address:	46 CROWN STREET
City,State,Zip:	BROOKLYN, NY 11225
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000158
Program Type:	CBS
UTM X:	587897.10291
UTM Y:	4502342.23434
Expiration Date:	N/A
Site Type:	Other

Tank Info:

Tank Number:	00001
Tank Id:	188041
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not Reported
Install Date:	01/01/1985
Capacity Gallons:	288

CENTRAL LAUNDRY CORP.-SEACREST DIV., 46 CROWN STREET, BROOKLYN, NY 11225 (Continued)

Tightness Test Method:	NN
Date Test:	Not Reported
Next Test Date:	Not Reported
Date Tank Closed:	Not Reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not Reported

Tank Number:	00002
Tank Id:	188042
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not Reported
Install Date:	06/01/1980
Capacity Gallons:	352
Tightness Test Method:	NN
Date Test:	Not Reported
Next Test Date:	Not Reported
Date Tank Closed:	Not Reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not Reported

SPILLS: Records of Emergency Release Reports

Name:	CP VI CROWN HEIGHTS LLC
Address:	46 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1903555 / Not Reported
Facility ID:	1903555
Facility Type:	ER
DER Facility ID:	95767
Site ID:	591519
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not Reported
SWIS:	2401
Spill Date:	2019-07-08
Investigator:	RHLIN
Referred To:	Not Reported
Reported to Dept:	2019-07-08
CID:	Not Reported
Water Affected:	Not Reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not Reported
Cleanup Meets Std:	False

CENTRAL LAUNDRY CORP.-SEACREST DIV., 46 CROWN STREET, BROOKLYN, NY 11225 (Continued)

Last Inspection:	Not Reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2019-07-08
Spill Record Last Update:	2019-07-10
Spiller Name:	MATTHEW FELDMAN
Spiller Company:	CP VI CROWN HEIGHTS LLC
Spiller Address:	46 CROWN ST
Spiller Company:	999
Contact Name:	AMANDA FORSBURG
DEC Memo:	"7/8/19 - Sekhon Historic impacts confirmed in lab results for E - designated site. Case transferred to DEC Rick Lin for follow up. Company: CP VI Crown Heights LLC Contact Person: Matt Feldman Email: mfeldman@carmelpartners.com Phone: 212.202.5783 "
Remarks:	"historic impacts confirmed in lab results"

All Materials:

Site ID:	591519
Operable Unit ID:	1339136
Operable Unit:	01
Material ID:	2348671
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	Not Reported
Units:	Not Reported
Recovered:	Not Reported
Oxygenate:	Not Reported

TANK TEST 49 CROWN ST, BROOKLYN, NY,			S118263465
▲ 7	N 1/10 - 1/3	(727 ft. / 0.138 mi.)	Lists of state and tribal leaking storage tanks
	10 ft. Higher Elevation	100 ft. Above Sea Level	

Worksheet:

LTANKS: Lists of state and tribal leaking storage tanks

Name:	TANK TEST
Address:	49 CROWN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1505659 / 2015-10-09
Facility ID:	1505659
Site ID:	513042
Spill Date:	2015-08-25

TANK TEST, 49 CROWN ST, BROOKLYN, NY (Continued)

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not Reported
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not Reported
Reported to Dept:	2015-08-26
CID:	Not Reported
Water Affected:	Not Reported
Spill Notifier:	Other
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-08-26
Spill Record Last Update:	2015-10-09
Spiller Name:	ERIK DEITZ
Spiller Company:	WCC
Spiller Address:	49 CROWN ST
Spiller County:	999
Spiller Contact:	ERIK DEITZ
Spiller Phone:	8455649555
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	467580
DEC Memo:	"09/01/15-Hiralkumar Patel. alternate address: 43-65 Crown Street, 900 Franklin Ave no other spills found. PBS #: 2-032956. as per PBS record, the site has one (1) 20,000 gal #2 oil UST, in-service, installed in Nov. 1973. 3:08 PM:- spoke with Erik. he mentioned that a dry leak was found due to a loose connection of fill line on top of the tank. 3:15 PM:- spoke with Ms. Vazquez. she mentioned that there is no product level drop in the tank. they have hired a contractor who will fix and retest the tank system by 09/04/15. asked her to submit report by the end of 09/04/15. Tivoli Towers Housing Co. Inc. **property owner** c/o Stellar Management 156 William Street, 10th Floor New York, NY 10038 Attn.: Katina Vazquez Ph. (212) 843-3783 email: kvazquez@stellarmanagement.com 3:22 PM:- sent email to Ms. Vazquez and asked her to submit result of system retest by the end of 09/04/15. 09/16/15-Hiralkumar Patel. 10:22 AM:- spoke with Ms. Vazquez. she mentioned that the loose fill line connection was fixed earlier and they are conducting system retest today. she will submit result once available. 10:23 AM:- sent email to Ms. Vazquez. 1:58

TANK TEST, 49 CROWN ST, BROOKLYN, NY (Continued)

PM:- received call from Eric from tank testing company. he mentioned that the tank system passed the retest. 10/09/15-Hiralkumar Patel. 3:27 PM:- sent email to Ms. Vazquez and asked her to submit report immediately. 3:39 PM:- received email from Ms. Vazquez including closure report. as per the report, tank system failed the test due to damaged coupling in the fill line. there was no petroleum impacted soil noted during tank repair activities. tank system was tested tight on 06/16/15. case closed. 3:54 PM:- sent email to Ms. Vazquez informing about case closure."

Remarks: "Loose fill stick line"

All Materials:

Site ID:	513042
Operable Unit ID:	1262274
Operable Unit:	01
Material ID:	2265794
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	Not Reported
Units:	Not Reported
Recovered:	Not Reported
Oxygenate:	Not Reported

BROOKLYN EAST 09 DOS -DDC 115 CROWN STREET, BROOKLYN, NY,		S104621550	
▲ 8	NE 1/10 - 1/3	(928 ft. / 0.176 mi.)	Lists of state and tribal leaking storage tanks Records of Emergency Release Reports
	18 ft. Higher Elevation	108 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist
Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES
Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9614782 / 2005-02-23
Facility ID:	9614782

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Site ID:	117169
Spill Date:	1997-03-24
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not Reported
Reported to Dept:	1997-03-24
CID:	205
Water Affected:	Not Reported
Spill Notifier:	Other
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-03-24
Spill Record Last Update:	2005-02-23
Spiller Name:	WILLIAM FENNELL
Spiller Company:	DEPT OF SANITATION
Spiller Address:	301 WEST 215TH ST
Spiller County:	001
Spiller Contact:	TONY MARINO
Spiller Phone:	Not Reported
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	101929
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY The spill is closed in consultation with Alex to consolidate with spill # 9702991. -II (02/23/05). "
Remarks:	"SOIL SAMPLES SHOWED CONTAMINATION OF BOTH GASOLINE & DIESEL"

All Materials:

Site ID:	117169
Operable Unit ID:	1042444
Operable Unit:	01
Material ID:	339883
Material Code:	0008
Material Name:	diesel
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported
Site ID:	117169
Operable Unit ID:	1042444

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Operable Unit:	01
Material ID:	339884
Material Code:	0009
Material Name:	gasoline
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported
Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001495 / 2005-05-09
Facility ID:	0001495
Site ID:	314854
Spill Date:	2000-05-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not Reported
Reported to Dept:	2000-05-05
CID:	390
Water Affected:	Not Reported
Spill Notifier:	Tank Tester
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-05
Spill Record Last Update:	2005-05-09
Spiller Name:	JOHN LEDDY
Spiller Company:	NYC DEPT OF SANITATION.
Spiller Address:	115 CROWN ST
Spiller County:	001
Spiller Contact:	JOHN LEDDY
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	101929
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY This spill is also referred to spill #s 0001496 and 0001497. - II (01/23/05). 5/9/05- The site is under active remediation by LiRo Engineers through installation of SVE system in

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

	place for soil contamination. Most recent monitoring results of
	influent air show that soil VOC contamination has been removed.
	Close-out soil borings are underway. The site has another open spill
	(# 9702991) from motor oil. As such this spill is closed to
	consolidate with that spill. -II. "
Remarks:	"TANK FAILED TEST, NO PRODUCT SPILLAGE C/R - NEXT 2 SPILLS FROM SAME LOCATION"

All TTF:

Facility ID:	0001495
Spill Number:	0001495
Spill Tank Test:	1525560
Site ID:	314854
Tank Number:	1
Tank Size:	550
Material:	0015A
EPA UST:	Not Reported
UST:	Not Reported
Cause:	Not Reported
Source:	Not Reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not Reported
Modified By:	Spills
Last Modified Date:	Not Reported

All Materials:

Site ID:	314854
Operable Unit ID:	823090
Operable Unit:	01
Material ID:	289715
Material Code:	0015
Material Name:	motor oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001496 / 2005-02-23
Facility ID:	0001496
Site ID:	314855

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Spill Date:	2000-05-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not Reported
Reported to Dept:	2000-05-05
CID:	390
Water Affected:	Not Reported
Spill Notifier:	Tank Tester
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-05
Spill Record Last Update:	2005-02-23
Spiller Name:	JOHN LEDDY
Spiller Company:	NYC DEPT OF SANITATION.
Spiller Address:	115 CROWN ST
Spiller County:	001
Spiller Contact:	JOHN LEDDY
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	101929
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY The spill is closed in consultation with Alex to consolidate with spill # 0001495. This spill is also referred to spill #s 0001497 and 0001495. -II (02/23/05). "
Remarks:	"TANK FAILED TEST - NO PRODUCT SPILLAGE C/R - PREVIOUS AND NEXT SPILL FROM SAME LOCATION"

All TTF:

Facility ID:	0001496
Spill Number:	0001496
Spill Tank Test:	1525561
Site ID:	314855
Tank Number:	2
Tank Size:	550
Material:	1096A
EPA UST:	Not Reported
UST:	Not Reported
Cause:	Not Reported
Source:	Not Reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Leak Rate:	.00
Gross Fail:	Not Reported
Modified By:	Spills
Last Modified Date:	Not Reported

All Materials:

Site ID:	314855
Operable Unit ID:	823091
Operable Unit:	01
Material ID:	289716
Material Code:	1096A
Material Name:	hoist oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001497 / 2005-02-23
Facility ID:	0001497
Site ID:	314856
Spill Date:	2000-05-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	AIIslam
Referred To:	Not Reported
Reported to Dept:	2000-05-05
CID:	390
Water Affected:	Not Reported
Spill Notifier:	Tank Tester
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-05
Spill Record Last Update:	2005-02-23
Spiller Name:	JOHN LEDDY
Spiller Company:	NYC DEPT OF SANITATION.
Spiller Address:	115 CROWN ST
Spiller County:	001
Spiller Contact:	JOHN LEDDY

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Spiller Phone:	(631) 321-4670
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	101929
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY I spoke with Afsar and told her that tanks must be taken out of service or repaired immeadiately. Afsar Taherzadeh told me that tanks will be taken out of service May 15, 2000. The spill is closed in consultation with Alex to consolidate with spill # 0001495. - II (02/23/05) "
Remarks:	"TANK FAILED TEST - NO PRODUCT SPILLAGE C/R - PREVIOUS 2 SPILLS AT SAME LOCATION"

All TTF:

Facility ID:	0001497
Spill Number:	0001497
Spill Tank Test:	1525562
Site ID:	314856
Tank Number:	3
Tank Size:	550
Material:	1096A
EPA UST:	Not Reported
UST:	Not Reported
Cause:	Not Reported
Source:	Not Reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not Reported
Modified By:	Spills
Last Modified Date:	Not Reported

All Materials:

Site ID:	314856
Operable Unit ID:	823092
Operable Unit:	01
Material ID:	289717
Material Code:	1096A
Material Name:	hoist oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

SPILLS: Records of Emergency Release Reports

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702991 / 2009-06-08
Facility ID:	9702991
Facility Type:	ER
DER Facility ID:	101929
Site ID:	314857
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1997-06-10
Investigator:	jamaison
Referred To:	NFA
Reported to Dept:	1997-06-10
CID:	370
Water Affected:	Not Reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not Reported
Cleanup Meets Std:	False
Last Inspection:	Not Reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-06-10
Spill Record Last Update:	2009-06-08
Spiller Name:	Not Reported
Spiller Company:	NYC SANITATION GARAGE
Spiller Address:	50 KENT AV
Spiller Company:	001
Contact Name:	ABOVE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY TRANSFERRED TO I. ISLAM This spill is also referred to spill # 9614782. -II (02/23/05). 6/6/05- The soil only contamination at the site is being treated by operating SVE system at the site by LiRo Engineers. GW is at 80'bgs. Reviewed the quarterly monitoring report Jan/05-Mar/05. The SVE system is remediating soil effectively. Confirmation soil borings and soil samplings are required to be done during the next quarter to consider closing out of the spill. - II 6/15/05- LiRo's email request for five close-out soil boring locations is approved via email with a modification to relocate SBR-24 further north.- II 5/23/05- Finally, close-out soil sampling plan (for 6 locations-SBR-20 to SBR-25)is approved.Soil boring to be

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

started in the 1st week of July/05. STV Inc on behalf of Dormitory Authority of State of NY (DASNY)submitted a plan to develop the site for the construction of Dormitory building and parking lot of the Edgar Evers College. A decision on this is dependent upon the close-out soil sampling results.- II 9/13/05- Reviewed the Apr.-July/05 quarterly monitoring report.And, had a meeting with Peter Burger of STV. In principle, it's agreed that existing SVE sytem on eastern area can be dismantled to allow foundation excavation for the proposed Dormitory Bldg., and shallow depth contaminated soil will be removed. The western side SVE system will continue until such time that parking area dev. works on the area starts. It's anticipated that it will require about 6 months to 1 year to start working in parking area. Sudden spike of TVOC (20,900 ug/m^3)in SVE influent air in the month of June is a concern. LiRo has been asked to provide with the latest data on this.- II 10/24/05- Reviewed the August-Sept/05 monitoring report. The Sept./05 system influent air VOC concentration (4,740ug/m^3) suggests that the system may be collecting slightly more VOCs than it had been collecting prior to June 2005 and the amount of increase is said to be attributable to natural causes such as changes in soil moisture conditions. The reason for SVE system influent air spike in June 2005 is not clear. Based on PID readings, no unusual event occurred to cause the sudden increase, and it is said that the spike might be as a result of cross-contamination or lab. error. Spoke to Peter Burger of STV Inc. who is the consultant for DASNY to construct the dormitory bldg at the site. He indicated that the dismantling of the existing bldg. in eastern area would take place in this winter to start foundation excavation in next year April/May. It has been agreed that the SVE system in the eastern area may be shut down and the proposed excavation for the dormitory bldg construction should address any shallow residual contamination in the eastern portion of the site. On the other hand, SVE system at the western portion may continue until such time that the proposed parking area dev starts in next year summer. The dev. of parking area is considered to be protective of human health and environment, and any remaining residual contamination at deeper depth (at 25'-35') will be addressed through natural attenuation. A letter was issued to this

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

effect addessed to NYCDDC and cc'd to DASNY, STV and LiRo. Filed the report in the eDoc.- II 03/29/06: This spill transferred from I.Islam to S.Kraszewski - SK 03/31/06: Sent Email to Steve Frank at LiRo asking for new contact information. Ed Looney , PM GREYHAWK North America, L.L.C. 260 Crossways Park Drive Woodbury, NY 11797 * phone: 516.921.1900 * fax: 516.921.5649 * email: elooney@greyhawk.com DOS is no longer at the site. Greyhawk started site visits in January, but was locked out for the first 9 days. Turns out that DASNY has started the process of taking down the building; it is slated for demolition. Ed has professed his disagreement and proposes that Turner Contructions go no further until the system can be analyzed by his guys. He will keep me breast of any future activities. - SK 04/21/06: Spoke with Peter Burger, from STV about the Brooklyn East 9 site for NYCDDC. DASNY wants to build a dormitory on the site. Peter is requesting to shut-down the SVE in order to begin construction and excavation activities on-site. Based on the most recent SVE system monitoring data, he believes that little residual soil contamination remains. GW is said to be a 90 fbg, too deep to be impacted. Peter will be stopping by on Monday at 1:00PM to discuss what plan of action should be taken. - SK 04/24/06: Met with Pete Burger from STV, accompanied by J.Kolleeny. Pete explained the situation with the site and what plans are in place to address the existing SVE system and residual soil contamination. Since Imdad's October 2005 letter giving the go-ahead to shutdown the system, STV has been hired by DASNY to work with Greyhawk and DDC to reclaim the site and build an academic building. The buildings footprint will cover most of the environmental conditions limit area expected to be impacted by the contamination. Two areas of concern are identified: residual contamination in subsurface soil ranging from 20' - 40' below ground as determined by soil borings. STV plans to keep the system running until mid-May, then proposes to shutdown and dismatle it. One area of concern will be addressed by excavation activities for the structure, since it is relatively shallow. Pete has told us that they will excavate until screening and soil tests confirm that no contamination remains. The second area will be left alone and natural attenuation will take its course. Continuous monitoring activities will be conducted during excavation for the entire site. All on-site USTs and

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

ASTs will be removed and disposed of properly. The building will have a passive ventalation system installed throughout the structure and based on a month long post-construction air monitoring event it will be determined whether an active system will be necessary. As mentioned, Imdad has already given the word to allow these activites to begin. John mentioned that since DDC is the RP and Greyhawk is the contractor responsible we would require a requested letter from Greyhawk to shutdown the system rather than STV requesting it. SK will be sending out an Email to Ed Looney asking for them to submit a letter to request terminattion of SVE system activities. - SK 05/01/06: Fatemeh Ashkan called asking for the documents STV submitted and to inquire about the Wednesday meeting. I told her that I would PDF the documents and send her an Email. Jon and I will discuss about attending the meeting. - SK 06/12/06: Received SVE Shutdown Request dated April 9, 2006 (typo: date should be June 9, 2006)prepared and submitted by Greyhawk on behalf of NYCDDC. The letter formaly requests the termination and removal of the SVE system on-site.The Department approves this request, letter sent out. - SK 10/27/06 Spill case transferred from S. Kraszewski to J. Maisonave. - JAM 01/09/07 Met with P. Burger at SVT to discuss the remediation plan/site redevelopment. The site is behind schedule. Excavation/tank removal is slated for the week of Jan. 15 and the site-wide excavation is slated for Jan. 22. - JAM 01/18/07 Sent email to P. Burger and NYCDDC letting him know that a PBS application form for information correction must be submitted to change the status of the tanks from Closed in Place to Closed-Removed. - JAM 2/27/06 Met with Peter Burger of STV to go over the tank closure report. STV wrote two reports, one for this site address at 115 Crown St and one for address 123 Crown St. All active ASTs and USTs were removed from the site and closure soil sampling showed very little petroleum impacts. The entire site will be excavated as soon as a DASNY finishes negotiating with the disposal facilities. - JAM 3/15/07. Recieved a call from P. Burger of SVT. Four 550-gallon USTs were discovered while excavating the site for construction of the new academic building. The tanks were abandoned-in-place by an unknown party. All the tanks will be removed and end-point samples will be taken. - JAM 3/19/07 The four tanks were removed. No visible soil impacts were

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

observed and soil sampling will be done across the entire site. 4/23/07 Received a call from P. Burger. Three additional tanks were discovered under the basement floor of the previous facility. The tanks were abondoned-in-place and filled with sand. The tanks were encased in concrete and the surrounding soil was visibly contaminated. All the tanks will be removed along with any contaminated soil. Soils will be screen with PID while being excavated. When PID readings are zero, end-point samples will be taken. - JAM 6/1/07 Visited the site at 1:30pm. Closure sampling has begun throughout the entire site. A total of 29 samples will be taken to characterize soil at grade. 16 samples were taken and analyzed so far and all are below TAGM numbers. P. Burger of STV asked me to come look at the area where 4 USTs were removed (1 4,000-gal and 3 550-gal). Surrounding soil was screened with a PID and determined to be contaminated. This is the area above Residual Area 2. Since the construction trailors are adhacent to the contaminated soil, they believe excavation has reached its limit without undermining the construction trailors. Mr. Burger said they plan to excavate as much soil as possible and take endpoint samples (2 from both the north and south walls, 3 from both the east and west walls, and 4 bottom, total 14). If there is still contamination based on laboratory endpoint samples then they will come back to remediate after the trailors are removed. - JAM 10/29/07 Spoke to P. Burger today. He will prepare a Remedial Summary Report. - JAM 6/19/08 PBS numbers 115 Crown Street - 2-456020 123 Crown Street - 2-610277 Met with P. Burger from STV yesterday to go over the closure report. All tanks on-site and contaminated soils to a depth of 20' were removed. Residual soil contamination remains at the interval from 20' to 40', which is beneath a new asphalt parking lot next to the academic building. DASNY is reviewing the closure report and when they complete their review, STV will submit the report to Greyhawk/Roux and the NYSDEC. Spill number 9011356, which was open at this site for a fuel oil spill, was closed today and consolidated with spill number 9702991. Since all tanks, associated piping and shallow contaminated soil have been removed, the tank associated with spill number 9011356 no longer exists on the site. - JAM 6/5/09 Reviewed the Closure Assessment Report for 115 Crown St. and 123 Crown St submitted by STV, on behalf

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

of DASNY, to Roux and forwarded to the DEC by Roux. The report summarizes all remedial activities performed on-site prior to constructing a new academic building for Medgar Evers College. Soil contamination from petroleum releases (gasoline and diesel) occurred at this former DOS garage and was being remediated with a SVE system, which was initiated in July 2001. The new academic building encompasses two addresses: 115 Crown St. (former DOS garage) and 123 Crown St. (former auto service shop). The groundwater table, located at 90 ft below ground surface, was not impacted. The SVE system operated until August 2006 when it was shut down (with DEC approval) prior to excavation activities. All USTs and ASTs were removed from both sites and contaminated soils were excavated down to 20-25 ft below grade prior to construction of the new building. End-point soil samples were collected after the tank removals. Some contaminated soil was encountered after excavating the USTs, however, further soil excavation occurred later for the building foundation. End-point soil samples were collected in a grid pattern from the excavation of the building footprint. No VOCs were detected above regulatory criteria in any samples from the building excavation. However, there were some minor SVOC and metals exceeding criteria. The concentrations for metals were shown to be less than background levels. Deeper known soil contamination (greater than 20 feet) was left in place, which the DEC agreed to in correspondence on October 25, 2005 because this soil contamination is not affecting the deep water table and poses no threat to human health. The building was constructed with a vapor barrier and a passive sub-slab venting system. STV recommends that this site be considered for closure. On January 19, 2009, Roux submitted a letter with STV s Closure Assessment Report attached, requesting that spill number 9702991 be closed. Based on the available information, this site poses no threat to human health or the environment. On June 8, 2009, DEC issued a No Further Action letter. All 3 STV Reports and Roux's Request for Spill Closure Report as well as the NFA letter are uploaded to eDocs. - JAM"

Remarks: "CALLER IS IN PROCESS OF DOING TANK ABANDONMENT FOUND CONTAMINATED SOIL ON TOP OF TANK SOIL WAS EXCAVATED AND REMOVED"

All Materials:

Site ID: 314857
Operable Unit ID: 1045721

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Operable Unit:	01
Material ID:	335904
Material Code:	0009
Material Name:	gasoline
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported
Name:	BROOKLYN EAST 09 DOS -DDC
Address:	115 CROWN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9011356 / 2008-06-19
Facility ID:	9011356
Facility Type:	ER
DER Facility ID:	101929
Site ID:	117168
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1991-01-28
Investigator:	jamaison
Referred To:	Not Reported
Reported to Dept:	1991-01-28
CID:	Not Reported
Water Affected:	Not Reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not Reported
Cleanup Meets Std:	False
Last Inspection:	Not Reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-02-08
Spill Record Last Update:	2008-06-19
Spiller Name:	C/O MIDWOOD MGNT CO
Spiller Company:	NATHAINEL USDAIN
Spiller Address:	60 EAST 42ND STREET
Spiller Company:	001
Contact Name:	Not Reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY 01/28/91: DEC INSPECTED SITE,FOUND THICK #4 F.O. ACCUMULATING AROUND THE FILL PIPE, NYCDOS TO EMPTY OUT TANK,SET UP TEMPORARY TANK FOR HEATING, EXCAVATE AREA ALONG FILLPIPE TO LOCATE LEAK & VAC OUT OIL. 10/27/06 Spill case transferred from S.

BROOKLYN EAST 09 DOS -DDC, 115 CROWN STREET, BROOKLYN, NY (Continued)

Kraszewski to J. Maisonave. - JAM 6/19/08 This spill case has been tracked under spill number 9702991. The environmental consultant, STV, was hired on behalf of DASNY to oversee the construction of a new academic building for Medgar Evers College. All USTs and ASTs on-site have already been removed and contaminated soils were excavated for the foundation of the new building. This spill case is closed. Refer to spill 9702991. - JAM"

Remarks: "NYCDOS LEASED PROPERTY,WHILE DOING EXCAVATION ON SITE TO REPLACE EXISTING TANK,TO BE CLOSED ON SITE, OIL WAS DISCOVERED IN EXCAVATION, NYCDOS CLAIMS SPILL COULD BE FROM PIPE LEAK."

All Materials:

Site ID:	117168
Operable Unit ID:	951436
Operable Unit:	01
Material ID:	427904
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

NYCTA - CHEMICAL LABORATORY 960 CARROLL ST, BROOKLYN, NY, 11225-1802		1000299187
▲ O9	NNE 1/10 - 1/3 (992 ft. / 0.188 mi.) 23 ft. Higher Elevation 113 ft. Above Sea Level	Lists of state and tribal leaking storage tanks Other Ascertainable Records

Worksheet:

Impact on Target Property: VEC does not exist
Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	CHEMICAL LAB- NYCT
Address:	960 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9100192 / 2001-11-30
Facility ID:	9100192

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Site ID:	181513
Spill Date:	1991-04-03
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not Reported
Reported to Dept:	1991-04-03
CID:	Not Reported
Water Affected:	Not Reported
Spill Notifier:	Tank Tester
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-17
Spill Record Last Update:	2005-03-21
Spiller Name:	Not Reported
Spiller Company:	NYCTA
Spiller Address:	Not Reported
Spiller County:	001
Spiller Contact:	Not Reported
Spiller Phone:	Not Reported
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	152215
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 11/16/94: REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 11/16/94. transfered from Hale to Tibbe on 12/27/00. tank replaced. closure investigation pending. 11/30/01 NO CONTAMINATION FOUND DURING INVESTIGATION. SEE FILE."
Remarks:	"5K TANK FAILED PETRO TITE WITH A LEAK RATE OF -.939GPH."

All TTF:

Facility ID:	9100192
Spill Number:	9100192
Spill Tank Test:	1538416
Site ID:	181513
Tank Number:	Not Reported
Tank Size:	0
Material:	0001
EPA UST:	Not Reported
UST:	Not Reported
Cause:	Not Reported
Source:	Not Reported
Test Method:	00

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not Reported
Modified By:	Spills
Last Modified Date:	Not Reported

All Materials:

Site ID:	181513
Operable Unit ID:	953734
Operable Unit:	01
Material ID:	426403
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not Reported

RCRA Listings: Other Ascertainable Records

Date Form Received by Agency:	20070101
Handler Name:	NYCTA - CHEMICAL LABORATORY
Handler Address:	960 CARROLL ST
Handler City,State,Zip:	BROOKLYN, NY 11225-1802
EPA ID:	NYD980653885
Contact Name:	Not Reported
Contact Address:	CARROLL ST
Contact City,State,Zip:	BROOKLYN, NY 11225
Contact Telephone:	Not Reported
Contact Fax:	Not Reported
Contact Email:	Not Reported
Contact Title:	Not Reported
EPA Region:	02
Land Type:	Not Reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not Reported
Biennial Report Cycle:	Not Reported
Accessibility:	Not Reported
Active Site Indicator:	Not Reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	CARROLL ST
Mailing City,State,Zip:	BROOKLYN, NY 11225
Owner Name:	NEW YORK CITY TRANSIT AUTHORITY
Owner Type:	Private
Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Operator Type:	Private

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not Reported
Active Site Converter Treatment storage and Disposal Facility:	Not Reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not Reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not Reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not Reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not Reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not Reported
Permit Workload Universe:	Not Reported
Permit Progress Universe:	Not Reported
Post-Closure Workload Universe:	Not Reported
Closure Workload Universe:	Not Reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not Reported
Full Enforcement Universe:	Not Reported
Significant Non-Complier Universe:	No

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not Reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F004
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	Private
Date Became Current:	Not Reported
Date Ended Current:	Not Reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	Private
Date Became Current:	Not Reported
Date Ended Current:	Not Reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	Private
Date Became Current:	Not Reported
Date Ended Current:	Not Reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported

Historic Generators:

Receive Date:	19990708
Handler Name:	NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Receive Date:	20060101
Handler Name:	NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

Receive Date:	20070101
Handler Name:	NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

Receive Date:	19821215
Handler Name:	NYCTA - CHEMICAL LABORATORY
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

Receive Date:	19920316
Handler Name:	NYCTA
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported
Receive Date:	19940330
Handler Name:	NYCTA
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported
Receive Date:	19960320
Handler Name:	NYCT/CHEMICAL LABORATORY
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

List of NAICS Codes and Descriptions:

NAICS Code:	485999
NAICS Description:	ALL OTHER TRANSIT AND GROUND PASSENGER TRANSPORTATION
NAICS Code:	561599
NAICS Description:	ALL OTHER TRAVEL ARRANGEMENT AND RESERVATION SERVICES

Facility Has Received Notices of Violation:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19891212
Actual Return to Compliance Date:	19900405
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19900409
Enforcement Identifier:	001
Date of Enforcement Action:	19900108
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not Reported

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

Enforcement Attorney:	Not Reported
Corrective Action Component:	No
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported
Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not Reported
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported
SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported

Evaluation Action Summary:

Evaluation Date:	19891212
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not Reported
Actual Return to Compliance Date:	19900405
Scheduled Compliance Date:	19900409
Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported

FINDS: Other Ascertainable Records

Registry ID:	110000808886
Click Here for FRS Facility Detail Report:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110000808886

Environmental Interest/Information System:

NYCTA - CHEMICAL LABORATORY, 960 CARROLL ST, BROOKLYN, NY 11225-1802 (Continued)

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

The Click here to access additional FINDS: detail in the EDR Site Report. database contains
http://www.edrnet.com/srf2/FinalSiteReport.aspx?ID=6s3W6y9ssQAm3s3NWkji3qZIyKeA9Y9UsR1yAnGGQSWkANDZm3J56tVus71U3AYANYsV3iaRk4c.jNYziada69p.qED.ZGslIZT9AN5tK4Pre7vEAmdS8EXpYtk59artUz0l6.JERVfg1.QFyujg61MbnHcWG6qqGw4Q6pmasL8c35V3We4M3f4SycRa9FTIs05A9gM8QvcHAva4mzQA3ugTsTUT3TS7N1Ur4DbUki5njsclicq65WbpqBioZHj1li4A6q.WK.3seJeoAFkr56EvYbBy9EPiUUnw6V9gR0aF1q1Dyo8u6lUksy..3m0mWOlS4krByZcb9z1gsj.l3pNwQNaEAcDnmJGAAVIcszjQ3ZUlNUOU5M8bk5TWj.LliE3w63s6qetHZNZ0IDCD4MT6KvSvewhqALX33YqHYnd19UQ4Uib773xmRNGj1JqlyliO95ymnTeVGFt9GmIK2xWiSPAQWUhUkLik5u6aNfK1DwwQZIACvdSK3SuiJNLv5SkQ6qbUs7i736D7WKYA4a8LyZgH9JTtsbQz3.rDQtyiAjuWmVgp4ssPsHXG3YytNu8e3ZBDkWFKjME3i9Li3KdwqjfIZ0NvIMEr3nXoKRoEe81kAViI5Cf1YlEQ9AiuU9jACDNoR1WJ1IHXy6vWC76GnzR3GbsZGbS845jRSxplWbQ6kThlB6YtNHqdDounZTX8AHyP31tEJlLF5QID3 additional records for this site. Please contact your EDR Account Executive for more information.

ECHO: Other Ascertainable Records

Envid:	1000299187
Registry ID:	110000808886
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000808886
Name:	NYCTA - CHEMICAL LABORATORY
Address:	960 CARROLL ST
City,State,Zip:	BROOKLYN, NY 11225

931 CARROLL STREET
931 CARROLL STREET, NEW YORK CITY, NY, S125317246

▲ Q10	NNE 1/10 - 1/3	(1137 ft. / 0.215 mi.)	Lists of state and tribal voluntary cleanup sites
	27 ft. Higher Elevation	117 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.

Conditions:

Both COC & PHC: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

VCP NYC: Lists of state and tribal voluntary cleanup sites

Project ID:	19TMP1475K,19EH-A320K,19CVCP064K
Name:	931 CARROLL STREET
Address:	931 CARROLL STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3011880058
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Approved Remedial Plan
Latitude:	40.668183
Longitude:	-73.959685
Postcode:	9
Community Board:	35
Council District:	213
Census Tract:	3029709

931 CARROLL STREET, 931 CARROLL STREET, NEW YORK CITY, NY (Continued)

BIN: 3011880058
NTA: Crown Heights South

SEACREST LINEN 931 CARROLL ST, BROOKLYN, NY,			S104621873
▲ Q11	NNE 1/10 - 1/3	(1137 ft. / 0.215 mi.)	Lists of state and tribal leaking storage tanks Other Ascertainable Records
	27 ft. Higher Elevation	117 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist
Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	SEACREST LINEN
Address:	931 CARROLL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0003909 / 2005-07-14
Facility ID:	0003909
Site ID:	147612
Spill Date:	2000-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	JXGRECO
Referred To:	Not Reported
Reported to Dept:	2000-06-29
CID:	390
Water Affected:	Not Reported
Spill Notifier:	Tank Tester
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-06-29
Spill Record Last Update:	2005-07-14
Spiller Name:	DANIEL GREENBERG
Spiller Company:	SEACREST LINEN
Spiller Address:	931 CARROLL ST
Spiller County:	001
Spiller Contact:	DANIEL GREENBERG

SEACREST LINEN, 931 CARROLL ST, BROOKLYN, NY (Continued)

Spiller Phone:	(718) 287-4800
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	125661
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/9/03 TJD Transferred Demeo >>> Rommel. June, 2005: Spill transferred to Greco as part of Spill Closure Initiative. The facility contact, Mr. Daniel Greenberg, was called on 6/16/05. Mr. Greenberg claims that all remedial work is complete and that the DEC was involved in the project. Unfortunately, the project file contains only the Spill Report and the second tank test report (i.e., the one that Mr. Greenberg claims was done following tank repair and soils remediation). Mr. Greenberg is attempting to find the engineer's report on the remediation. 06/20/05 JDG July 14: Pro Test (the firm that did the tank testing)contacted me on 7/13/05 and explained that Mr. Greenberg had confused this site with another site he had been involved in (i.e., 9903240, located at a different Sea Crest Linen site at 46 Crown St.). The 46 Crown St. site did require remediation and was ultimately closed by the DEC. Pro Test went on to say that the 931 Carroll St. site had two tanks that failed tightness testing, however, they were determined to not have leaked (i.e., it was a vent line breach, only). This was determined during an excavation and tank upgrade performed following the first tightness failure. The tanks have been upgraded and have passed tightness testing. Sice there was no reported release to the environment and the tanks now have been upgraded and pass testing, the spill was closed. JDG 7/14/05"
Remarks:	"both tanks failed test - no product spilage"

All TTF:

Facility ID:	0003909
Spill Number:	0003909
Spill Tank Test:	1525736
Site ID:	147612
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	Not Reported
UST:	Not Reported
Cause:	Not Reported
Source:	Not Reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00

SEACREST LINEN, 931 CARROLL ST, BROOKLYN, NY (Continued)

Gross Fail:	Not Reported
Modified By:	Spills
Last Modified Date:	Not Reported

All Materials:

Site ID:	147612
Operable Unit ID:	825133
Operable Unit:	01
Material ID:	548661
Material Code:	0008
Material Name:	diesel
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

Site ID:	147612
Operable Unit ID:	825133
Operable Unit:	01
Material ID:	548662
Material Code:	0009
Material Name:	gasoline
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

E DESIGNATION: Other Ascertainable Records

Name:	LOT 58,TAXBLOCK 1188
Address:	931 CARROLL STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	58
Tax Block:	1188
Borough Code:	Not Reported
E-No:	E-405
Effective Date:	12/20/2018
Satisfaction Date:	Not Reported
Ceqr Number:	17DCP067K
Ulurp Number:	180347ZMK, 180348ZRK180347ZMK, 180348ZRK
Zoning Map No:	16d
Description:	Air Quality - HVAC fuel limited to natural gas
Lot Remediation Date:	Not Reported
Description:	Exhaust stack location limitations
Lot Remediation Date:	Not Reported

SEACREST LINEN, 931 CARROLL ST, BROOKLYN, NY (Continued)

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not Reported

CLARA BARTON HIGH SCHOOL 925 CARROLL ST, BROOKLYN, NY,		S118953450	
▲ 12	N 1/10 - 1/3	(1176 ft. / 0.223 mi.)	Lists of state and tribal leaking storage tanks
	39 ft. Higher Elevation	129 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist
Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES
Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	CLARA BARTON HIGH SCHOOL
Address:	925 CARROLL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012946 / 2004-06-09
Facility ID:	0012946
Site ID:	115013
Spill Date:	2001-03-09
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not Reported
Reported to Dept:	2001-03-09
CID:	281
Water Affected:	Not Reported
Spill Notifier:	Other
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-09
Spill Record Last Update:	2004-10-14
Spiller Name:	JEFF BRADY
Spiller Company:	NYC SCHOOL DISTRICT
Spiller Address:	901 CLASSON AVE
Spiller County:	001
Spiller Contact:	JEFF BRADY

CLARA BARTON HIGH SCHOOL, 925 CARROLL ST, BROOKLYN, NY (Continued)

Spiller Phone:	(718) 243-1843
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	267502
DEC Memo:	"10/14/2004 Case was closed out in June 2004 under the address of 901 Classon Ave, Brooklyn. School Construction Authority requested the address be changed to 925 Carroll St. This change was made. "
Remarks:	"DURING ROUTINE CLEANING OF TANK AT ABOVE LOCATION A HOLE HAS BEEN DISCOVERED. TANK TO BE DRAINED AND FURTHER EVALUATION TO BE DONE. TANK IS A 20,000 GALLON UNDERGROUND UNIT."

All Materials:

Site ID:	115013
Operable Unit ID:	834878
Operable Unit:	01
Material ID:	539665
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

NEW GARDEN CLEANER
879 FRANKLIN AVE, BROOKLYN, NY, 11225 1304 S110247427

▲ O13	NNE 1/10 - 1/3	(1220 ft. / 0.231 mi.)	Other Ascertainable Records
	28 ft. Higher Elevation	118 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist
Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Chemicals of Concern: YES
Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

DRYCLEANERS: Other Ascertainable Records

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2003-12-17 07:10:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2003-12-17 07:10:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2015-12-17 12:00:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2015-12-17 12:00:00
Install Date:	Not Reported

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2014-12-11 08:15:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2014-12-11 08:15:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2013-12-12 09:30:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2013-12-12 09:30:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2012-12-12 09:40:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2012-12-12 09:40:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2011-12-15 10:00:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2011-12-15 10:00:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2010-12-14 11:00:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2004-12-20 14:00:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2004-12-20 14:00:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2005-12-12 09:00:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2005-12-12 09:00:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2006-12-06 13:00:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2006-12-06 13:00:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2007-12-05 10:10:00
Install Date:	Not Reported

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2007-12-05 10:10:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2008-12-08 09:15:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2008-12-08 09:15:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported

NEW GARDEN CLEANER, 879 FRANKLIN AVE, BROOKLYN, NY 11225 1304 (Continued)

Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2009-12-09 08:15:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2006-02-28 11:07:39
Inspection Date:	2009-12-09 08:15:00
Install Date:	Not Reported
Expiration Date:	09/08/2017
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

Name:	NEW GARDEN CLEANER
Address:	879 FRANKLIN AVE
City,State,Zip:	BROOKLYN, NY 11225 1304
Facility ID:	2-6104-01321
Phone Number:	7187740827
Region:	Not Reported
Registration Effective Date:	2003-12-08 14:15:29
Inspection Date:	2010-12-14 11:00:00
Install Date:	Not Reported
Expiration Date:	02/01/2006
Removal Date:	Not Reported
Drop Shop:	Not Reported
Shutdown:	Not Reported
Alternate Solvent:	Not Reported
Current Business:	Not Reported

MAP FINDINGS

CLARA BARTON HIGH SCHOOL CLASSON AVE AT PRESIDENT, BROOKLYN, NY,			S102960526
▲ 14	N 1/10 - 1/3	(1469 ft. / 0.278 mi.)	Lists of state and tribal leaking storage tanks
	49 ft. Higher Elevation	139 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.

Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	CLARA BARTON HIGH SCHOOL
Address:	CLASSON AVE AT PRESIDENT
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712737 / 2003-03-03
Facility ID:	9712737
Site ID:	74434
Spill Date:	1998-02-13
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not Reported
Reported to Dept:	1998-02-13
CID:	322
Water Affected:	Not Reported
Spill Notifier:	Local Agency
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-13
Spill Record Last Update:	2003-03-03
Spiller Name:	Not Reported
Spiller Company:	UNK
Spiller Address:	Not Reported
Spiller County:	999
Spiller Contact:	HOWARD LEVY
Spiller Phone:	(718) 595-6700
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	69836
DEC Memo:	""

CLARA BARTON HIGH SCHOOL, CLASSON AVE AT PRESIDENT, BROOKLYN, NY (Continued)

Remarks: "tank at school overfilled - spill ran into street unk if any sewers are effected "

All Materials:

Site ID:	74434
Operable Unit ID:	1055600
Operable Unit:	01
Material ID:	569448
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

BOARD OF EDUCATION
901 CLASSON AVE, BROOKLYN, NY, S104621283

▲ 15	NNW 1/10 - 1/3	(1509 ft. / 0.286 mi.)	Lists of state and tribal leaking storage tanks Records of Emergency Release Reports
	51 ft. Higher Elevation	141 ft. Above Sea Level	

Worksheet:

Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.

Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	NYC PUBLIC SCHOOL
Address:	901 CLASSON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712739 / 1999-07-21
Facility ID:	9712739
Site ID:	175550
Spill Date:	1998-02-13
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not Reported
Reported to Dept:	1998-02-14
CID:	297

BOARD OF EDUCATION, 901 CLASSON AVE, BROOKLYN, NY (Continued)

Water Affected:	Not Reported
Spill Notifier:	Other
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-14
Spill Record Last Update:	2000-05-03
Spiller Name:	Not Reported
Spiller Company:	UNKNOWN
Spiller Address:	Not Reported
Spiller County:	999
Spiller Contact:	MIKE BURKE
Spiller Phone:	(718) 855-3376
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	100236
DEC Memo:	""
Remarks:	"CALLERS COMPANY HIRED TO CLEAN UP THE ABOVE SPILL - CALLER THOUGHT THE SCHOOL DISTRICT CALLED THE SPILL IN"

All Materials:

Site ID:	175550
Operable Unit ID:	1058955
Operable Unit:	01
Material ID:	327330
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	200.00
Oxygenate:	Not Reported

SPILLS: Records of Emergency Release Reports

Name:	BOARD OF EDUCATION
Address:	901 CLASSON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012493 / 2003-06-02
Facility ID:	0012493
Facility Type:	ER
DER Facility ID:	100236
Site ID:	115012
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	2401

BOARD OF EDUCATION, 901 CLASSON AVE, BROOKLYN, NY (Continued)

Spill Date:	2001-02-21
Investigator:	TJDEMEO
Referred To:	Not Reported
Reported to Dept:	2001-02-22
CID:	398
Water Affected:	Not Reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not Reported
Cleanup Meets Std:	False
Last Inspection:	Not Reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-22
Spill Record Last Update:	2003-06-02
Spiller Name:	Not Reported
Spiller Company:	BOARD OF EDUCATION
Spiller Address:	Not Reported
Spiller Company:	001
Contact Name:	ANTHONY LARA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO SAME AS 0012491. "
Remarks:	"TRANSFERRING FUL FROM TANK 1 TO TANK 2. ENROUTE TO CLEAN UP PRODUCT. 917-335-0369 CELL FROM CALLER. WISHES A CALL BACK."

All Materials:

Site ID:	115012
Operable Unit ID:	834391
Operable Unit:	01
Material ID:	542757
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	500.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

POLLOCK FILM INC
1579 BEDFORD AVE-LOADING AREA, BROOKLYN, NY, 11225-1306 1001489074

▲ 16	NE 1/10 - 1/3	(1573 ft. / 0.298 mi.)	Lists of state and tribal leaking storage tanks Other Ascertainable Records
	36 ft. Higher Elevation	126 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Comments: The source is not within the area of concern, based on its distance, gradient and suspected chemical of concern.
Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

LTANKS: Lists of state and tribal leaking storage tanks

Name:	1579 BEDFORD AV/NYS/NAVAL
Address:	1579 BEDFORD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9109496 / 2003-03-07
Facility ID:	9109496
Site ID:	158643
Spill Date:	1991-12-05
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not Reported
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not Reported
Reported to Dept:	1991-12-06
CID:	Not Reported
Water Affected:	Not Reported
Spill Notifier:	Other
Last Inspection:	Not Reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-12-11
Spill Record Last Update:	2003-03-07
Spiller Name:	Not Reported
Spiller Company:	Not Reported
Spiller Address:	Not Reported
Spiller County:	001
Spiller Contact:	Not Reported
Spiller Phone:	Not Reported
Spiller Extention:	Not Reported
DEC Region:	2
DER Facility ID:	134045
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 6/24/98 TRANSCRIBING NOTES FROM K.S.TANG FROM 12/6/91, 11:30 AM: CALL RICH, LEFT MESSAGE TO CALL BACK BET 3-4. TOLD HIM TO DISPOSE OF SOIL PROPERLY, SUBMIT POST-EXCAVATION SOIL SAMPLING RESULTS AND BILL OF LADING FOR THE SOIL. ALSO, SUBMIT THE PBS FORM. 03/07/2003-AUSTIN/ckc As per directive to close out spills with no recent history, close out."

POLLOCK FILM INC, 1579 BEDFORD AVE-LOADING AREA, BROOKLYN, NY 11225-1306 (Continued)

Remarks:	"2K TANKPULL; STOCKPILE, TEST, PICKUP & DISPOSE."

All Materials:

Site ID:	158643
Operable Unit ID:	963347
Operable Unit:	01
Material ID:	418110
Material Code:	0008
Material Name:	diesel
Case No.:	Not Reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not Reported

RCRA Listings: Other Ascertainable Records

Date Form Received by Agency:	20070101
Handler Name:	POLLOCK FILM INC
Handler Address:	1579 BEDFORD AVE-LOADING AREA
Handler City,State,Zip:	BROOKLYN, NY 11225-1306
EPA ID:	NYR000070946
Contact Name:	THOMAS NOUSIAS
Contact Address:	GREENWICH ST #7C
Contact City,State,Zip:	NEW YORK, NY 10014
Contact Telephone:	212-604-0360
Contact Fax:	Not Reported
Contact Email:	Not Reported
Contact Title:	Not Reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not Reported
Biennial Report Cycle:	Not Reported
Accessibility:	Not Reported
Active Site Indicator:	Not Reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	GREENWICH ST #7C
Mailing City,State,Zip:	NEW YORK, NY 10014
Owner Name:	DIVISION OF MILITARY & NAVAL AFFAIRS
Owner Type:	State
Operator Name:	DIVISION OF MILITARY & NAVAL AFFAIRS
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

POLLOCK FILM INC, 1579 BEDFORD AVE-LOADING AREA, BROOKLYN, NY 11225-1306 (Continued)

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not Reported
Active Site Converter Treatment storage and Disposal Facility:	Not Reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not Reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not Reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not Reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not Reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not Reported
Permit Workload Universe:	Not Reported
Permit Progress Universe:	Not Reported
Post-Closure Workload Universe:	Not Reported
Closure Workload Universe:	Not Reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not Reported
Full Enforcement Universe:	Not Reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

POLLOCK FILM INC, 1579 BEDFORD AVE-LOADING AREA, BROOKLYN, NY 11225-1306 (Continued)

Financial Assurance Required:	Not Reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DIVISION OF MILITARY & NAVAL AFFAIRS
Legal Status:	State
Date Became Current:	Not Reported
Date Ended Current:	Not Reported
Owner/Operator Address:	330 OLD NISKAYUNA RD
Owner/Operator City,State,Zip:	LATHAM, NY 12110
Owner/Operator Telephone:	518-786-4495
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DIVISION OF MILITARY & NAVAL AFFAIRS
Legal Status:	State
Date Became Current:	Not Reported
Date Ended Current:	Not Reported
Owner/Operator Address:	330 OLD NISKAYUNA RD
Owner/Operator City,State,Zip:	LATHAM, NY 12110
Owner/Operator Telephone:	518-786-4495
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported
Owner/Operator Email:	Not Reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DIVISION OF MILITARY & NAVAL AFFAIRS
Legal Status:	State
Date Became Current:	Not Reported
Date Ended Current:	Not Reported
Owner/Operator Address:	330 OLD NISKAYUNA RD
Owner/Operator City,State,Zip:	LATHAM, NY 12110
Owner/Operator Telephone:	518-786-4495
Owner/Operator Telephone Ext:	Not Reported
Owner/Operator Fax:	Not Reported

POLLOCK FILM INC, 1579 BEDFORD AVE-LOADING AREA, BROOKLYN, NY 11225-1306 (Continued)

Owner/Operator Email:	Not Reported

Historic Generators:

Receive Date:	20060101
Handler Name:	POLLOCK FILM INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

Receive Date:	20070101
Handler Name:	POLLOCK FILM INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

Receive Date:	19990422
Handler Name:	POLLOCK FILM INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not Reported
Electronic Manifest Broker:	Not Reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	No

POLLOCK FILM INC, 1579 BEDFORD AVE-LOADING AREA, BROOKLYN, NY 11225-1306 (Continued)

Agency Which Determined Violation:	Not Reported
Violation Short Description:	Not Reported
Date Violation was Determined:	Not Reported
Actual Return to Compliance Date:	Not Reported
Return to Compliance Qualifier:	Not Reported
Violation Responsible Agency:	Not Reported
Scheduled Compliance Date:	Not Reported
Enforcement Identifier:	Not Reported
Date of Enforcement Action:	Not Reported
Enforcement Responsible Agency:	Not Reported
Enforcement Docket Number:	Not Reported
Enforcement Attorney:	Not Reported
Corrective Action Component:	Not Reported
Appeal Initiated Date:	Not Reported
Appeal Resolution Date:	Not Reported
Disposition Status Date:	Not Reported
Disposition Status:	Not Reported
Disposition Status Description:	Not Reported
Consent/Final Order Sequence Number:	Not Reported
Consent/Final Order Respondent Name:	Not Reported
Consent/Final Order Lead Agency:	Not Reported
Enforcement Type:	Not Reported
Enforcement Responsible Person:	Not Reported
Enforcement Responsible Sub-Organization:	Not Reported
SEP Sequence Number:	Not Reported
SEP Expenditure Amount:	Not Reported
SEP Scheduled Completion Date:	Not Reported
SEP Actual Date:	Not Reported
SEP Defaulted Date:	Not Reported
SEP Type:	Not Reported
SEP Type Description:	Not Reported
Proposed Amount:	Not Reported
Final Monetary Amount:	Not Reported
Paid Amount:	Not Reported
Final Count:	Not Reported
Final Amount:	Not Reported

Evaluation Action Summary:

Evaluation Date:	20110311
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not Reported
Scheduled Compliance Date:	Not Reported

POLLOCK FILM INC, 1579 BEDFORD AVE-LOADING AREA, BROOKLYN, NY 11225-1306 (Continued)

Date of Request:	Not Reported
Date Response Received:	Not Reported
Request Agency:	Not Reported
Former Citation:	Not Reported

NY MANIFEST: Other Ascertainable Records

Name:	POLLOCK FILMS INC
Address:	1579 BEDFORD AVE-LOADING AREA
City,State,Zip:	BROOKLYN, NY 11225-1306
Country:	USA
EPA ID:	NYR000070946
Facility Status:	Not Reported
Location Address 1:	1579 BEDFORD AVE
Code:	BP
Location Address 2:	Not Reported
Total Tanks:	Not Reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not Reported
Location Zip 4:	Not Reported

NY MANIFEST:

EPAID:	NYR000070946
Mailing Name:	POLLOCK FILMS INC
Mailing Contact:	N/S
Mailing Address 1:	609 GREENWICH ST
Mailing Address 2:	Not Reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10014
Mailing Zip 4:	Not Reported
Mailing Country:	USA
Mailing Phone:	7189537441

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
ENVIRONMENTAL RECORDS						
Federal NPL site list						
US	NPL	National Priority List	EPA	10/27/2022	11/01/2022	11/15/2022
US	Proposed NPL	Proposed National Priority List Sites	EPA	10/27/2022	11/01/2022	11/15/2022
US	NPL LIENS	Federal Superfund Liens	EPA	10/15/1991	02/02/1994	03/30/1994
Federal CERCLIS list						
US	SEMS	Superfund Enterprise Management System	EPA	10/27/2022	11/01/2022	11/15/2022
Federal RCRA CORRACTS facilities list						
US	CORRACTS	Corrective Action Report	EPA	11/21/2022	11/21/2022	12/05/2022
Federal RCRA TSD facilities list						
US	RCRA-TSDF	RCRA - Treatment, Storage and Disposal	Environmental Protection Agency	11/21/2022	11/21/2022	12/05/2022
Federal RCRA generators list						
US	RCRA-LQG	RCRA - Large Quantity Generators	Environmental Protection Agency	11/21/2022	11/21/2022	12/05/2022
US	RCRA-SQG	RCRA - Small Quantity Generators	Environmental Protection Agency	11/21/2022	11/21/2022	12/05/2022
US	RCRA-VSQG	RCRA - Very Small Quantity Generators (Formerly Conditionall	Environmental Protection Agency	11/21/2022	11/21/2022	12/05/2022
Federal institutional controls / engineering controls registries						
US	LUCIS	Land Use Control Information System	Department of the Navy	11/02/2022	11/08/2022	01/10/2023
US	US ENG CONTROLS	Engineering Controls Sites List	Environmental Protection Agency	08/15/2022	08/17/2022	10/24/2022
US	US INST CONTROLS	Institutional Controls Sites List	Environmental Protection Agency	08/15/2022	08/17/2022	10/24/2022
Federal ERNS list						
US	ERNS	Emergency Response Notification System	National Response Center, United States Coast	12/12/2022	12/14/2022	12/19/2022
State and tribal - equivalent CERCLIS						
NY	SHWS	Inactive Hazardous Waste Disposal Sites in New York State	Department of Environmental Conservation	08/08/2022	08/08/2022	10/24/2022
State and tribal landfill / solid waste disposal						
NY	SWF/LF	Facility Register	Department of Environmental Conservation	12/21/2022	12/22/2022	12/30/2022
State and tribal leaking storage tank lists						
US	INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land	EPA Region 10	04/20/2022	06/13/2022	08/16/2022
US	INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land	EPA Region 4	06/02/2022	06/13/2022	08/31/2022
US	INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land	EPA Region 7	04/14/2022	06/13/2022	08/16/2022
US	INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land	EPA Region 6	04/28/2022	06/13/2022	08/16/2022
US	INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land	EPA, Region 5	04/11/2022	06/13/2022	08/16/2022
US	INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land	EPA Region 1	04/28/2021	06/11/2021	09/07/2021
US	INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land	Environmental Protection Agency	04/08/2022	06/13/2022	08/16/2022
US	INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land	EPA Region 8	04/20/2022	06/13/2022	08/16/2022
NY	LTANKS	Spills Information Database	Department of Environmental Conservation	08/08/2022	08/08/2022	10/26/2022
NY	HIST LTANKS	Listing of Leaking Storage Tanks	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
State and tribal registered storage tank lists						
NY	TANKS	Storage Tank Faciliy Listing	Department of Environmental Conservation	09/19/2022	09/20/2022	12/01/2022
NY	UST	Petroleum Bulk Storage (PBS) Database	Department of Environmental Conservation	09/19/2022	09/20/2022	12/01/2022
NY	CBS UST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	MOSF UST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	AST	Petroleum Bulk Storage	Department of Environmental Conservation	09/19/2022	09/20/2022	12/01/2022
NY	CBS AST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	MOSF AST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	CBS	Chemical Bulk Storage Site Listing	Department of Environmental Conservation	09/19/2022	09/20/2022	12/01/2022
NY	MOSF	Major Oil Storage Facility Site Listing	Department of Environmental Conservation	09/19/2022	09/20/2022	12/01/2022
US	INDIAN UST R5	Underground Storage Tanks on Indian Land	EPA Region 5	04/11/2022	06/13/2022	08/16/2022
US	INDIAN UST R1	Underground Storage Tanks on Indian Land	EPA, Region 1	04/07/2022	06/13/2022	08/16/2022
US	INDIAN UST R10	Underground Storage Tanks on Indian Land	EPA Region 10	04/20/2022	06/13/2022	08/16/2022
US	INDIAN UST R7	Underground Storage Tanks on Indian Land	EPA Region 7	04/14/2022	06/13/2022	08/16/2022
US	INDIAN UST R8	Underground Storage Tanks on Indian Land	EPA Region 8	04/20/2022	06/13/2022	08/16/2022
US	INDIAN UST R9	Underground Storage Tanks on Indian Land	EPA Region 9	04/08/2022	06/13/2022	08/16/2022
US	INDIAN UST R6	Underground Storage Tanks on Indian Land	EPA Region 6	04/28/2022	06/13/2022	08/16/2022
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 4	06/02/2022	06/13/2022	08/31/2022
US	FEMA UST	Underground Storage Tank Listing	FEMA	10/14/2021	11/05/2021	02/01/2022
State and tribal institutional control / engineering control registries						
NY	RES DECL	Restrictive Declarations Listing	NYC Department of City Planning	06/22/2022	09/12/2022	12/01/2022
NY	ENV RES DECL	Environmental Restrictive Declarations	New York City Department of City Planning	06/22/2022	09/21/2022	12/01/2022
NY	ENG CONTROLS	Registry of Engineering Controls	Department of Environmental Conservation	08/08/2022	08/08/2022	10/24/2022
NY	INST CONTROL	Registry of Institutional Controls	Department of Environmental Conservation	08/08/2022	08/08/2022	10/24/2022
State and tribal voluntary cleanup sites						
US	INDIAN VCP R7	Voluntary Cleanup Priority Lisitng	EPA, Region 7	03/20/2008	04/22/2008	05/19/2008
US	INDIAN VCP R1	Voluntary Cleanup Priority Listing	EPA, Region 1	07/27/2015	09/29/2015	02/18/2016
NY	VCP NYC	Voluntary Cleanup Program Listing NYC	New York City Office of Environmental Protect	09/05/2022	09/06/2022	11/21/2022
NY	VCP	Voluntary Cleanup Agreements	Department of Environmental Conservation	08/08/2022	08/08/2022	10/24/2022
State and tribal Brownfields sites						
NY	BROWNFIELDS	Brownfields Site List	Department of Environmental Conservation	08/08/2022	08/08/2022	10/24/2022
NY	ERP	Environmental Restoration Program Listing	Department of Environmental Conservation	08/08/2022	08/08/2022	10/24/2022
Other Records						
US	CONSENT	Superfund (CERCLA) Consent Decrees	Department of Justice, Consent Decree Library	09/30/2022	10/21/2022	01/10/2023
US	ROD	Records Of Decision	EPA	10/27/2022	11/01/2022	11/15/2022
US	LIENS 2	CERCLA Lien Information	Environmental Protection Agency	10/27/2022	11/01/2022	11/15/2022
NY	DEL SHWS	Delisted Registry Sites	Department of Environmental Conservation	08/08/2022	08/08/2022	10/24/2022
US	DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations	EPA, Region 9	01/12/2009	05/07/2009	09/21/2009
NY	SWTIRE	Registered Waste Tire Storage & Facility List	Department of Environmental Conservation	02/27/2018	04/06/2018	06/08/2018
NY	SWRCY	Registered Recycling Facility List	Department of Environmental Conservation	12/21/2022	12/22/2022	12/30/2022
NY	HIST UST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006
NY	HIST AST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	LEAD SMELTER 1	Lead Smelter Sites	Environmental Protection Agency	10/27/2022	11/01/2022	11/15/2022
US	FUSRAP	Formerly Utilized Sites Remedial Action Program	Department of Energy	07/26/2021	07/27/2021	10/22/2021
US	COAL ASH DOE	Steam-Electric Plant Operation Data	Department of Energy	12/31/2020	11/30/2021	02/22/2022
US	US HIST CDL	National Clandestine Laboratory Register	Drug Enforcement Administration	07/29/2022	08/18/2022	10/24/2022
US	SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing	Environmental Protection Agency	01/01/2017	02/03/2017	04/07/2017
US	PCB TRANSFORMER	PCB Transformer Registration Database	Environmental Protection Agency	09/13/2019	11/06/2019	02/10/2020
US	US AIRS MINOR	Air Facility System Data	EPA	10/12/2016	10/26/2016	02/03/2017
US	US AIRS (AFS)	Aerometric Information Retrieval System Facility Subsystem (	EPA	10/12/2016	10/26/2016	02/03/2017
US	EPA WATCH LIST	EPA WATCH LIST	Environmental Protection Agency	08/30/2013	03/21/2014	06/17/2014
US	LEAD SMELTER 2	Lead Smelter Sites	American Journal of Public Health	04/05/2001	10/27/2010	12/02/2010
US	COAL ASH EPA	Coal Combustion Residues Surface Impoundments List	Environmental Protection Agency	01/12/2017	03/05/2019	11/11/2019
US	US FIN ASSUR	Financial Assurance Information	Environmental Protection Agency	09/19/2022	09/20/2022	12/22/2022
US	2020 COR ACTION	2020 Corrective Action Program List	Environmental Protection Agency	09/30/2017	05/08/2018	07/20/2018
US	Delisted NPL	National Priority List Deletions	EPA	10/27/2022	11/01/2022	11/15/2022
US	SEMS-ARCHIVE	Superfund Enterprise Management System Archive	EPA	10/27/2022	11/01/2022	11/15/2022
US	RCRA NonGen / NLR	RCRA - Non Generators / No Longer Regulated	Environmental Protection Agency	11/21/2022	11/21/2022	12/05/2022
US	HMIRS	Hazardous Materials Information Reporting System	U.S. Department of Transportation	09/19/2022	09/19/2022	09/30/2022
US	DOT OPS	Incident and Accident Data	Department of Transporation, Office of Pipeli	01/02/2020	01/28/2020	04/17/2020
US	US CDL	Clandestine Drug Labs	Drug Enforcement Administration	07/29/2022	08/18/2022	10/24/2022
US	US BROWNFIELDS	A Listing of Brownfields Sites	Environmental Protection Agency	02/23/2022	03/10/2022	03/10/2022
US	DOD	Department of Defense Sites	USGS	06/07/2021	07/13/2021	03/09/2022
US	FEDLAND	Federal and Indian Lands	U.S. Geological Survey	04/02/2018	04/11/2018	11/06/2019
US	FUDS	Formerly Used Defense Sites	U.S. Army Corps of Engineers	08/11/2022	08/11/2022	09/30/2022
US	UMTRA	Uranium Mill Tailings Sites	Department of Energy	08/30/2019	11/15/2019	01/28/2020
US	ODI	Open Dump Inventory	Environmental Protection Agency	06/30/1985	08/09/2004	09/17/2004
US	US MINES	Mines Master Index File	Department of Labor, Mine Safety and Health A	08/03/2022	08/17/2022	08/31/2022
US	MINES VIOLATIONS	MSHA Violation Assessment Data	DOL, Mine Safety & Health Admi	11/29/2022	11/30/2022	12/22/2022
US	US MINES 2	Ferrous and Nonferrous Metal Mines Database Listing	USGS	05/06/2020	05/27/2020	08/13/2020
US	US MINES 3	Active Mines & Mineral Plants Database Listing	USGS	04/14/2011	06/08/2011	09/13/2011
US	PRP	Potentially Responsible Parties	EPA	10/27/2022	11/01/2022	11/15/2022
US	TRIS	Toxic Chemical Release Inventory System	EPA	12/31/2018	08/14/2020	11/04/2020
US	TSCA	Toxic Substances Control Act	EPA	12/31/2016	06/17/2020	09/10/2020
US	FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA/Office of Prevention, Pesticides and Toxi	04/09/2009	04/16/2009	05/11/2009
US	FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA	04/09/2009	04/16/2009	05/11/2009
US	HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HIST FTTS INSP	FIFRA/TSCA Tracking System Inspection & Enforcement Case Lis	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	SSTS	Section 7 Tracking Systems	EPA	10/17/2022	10/18/2022	01/10/2023
US	ICIS	Integrated Compliance Information System	Environmental Protection Agency	11/18/2016	11/23/2016	02/10/2017
US	PADS	PCB Activity Database System	EPA	01/20/2022	01/20/2022	03/25/2022
US	MLTS	Material Licensing Tracking System	Nuclear Regulatory Commission	10/26/2022	11/22/2022	12/05/2022
US	RADINFO	Radiation Information Database	Environmental Protection Agency	07/01/2019	07/01/2019	09/23/2019
US	FINDS	Facility Index System/Facility Registry System	EPA	08/03/2022	08/25/2022	10/24/2022
US	RAATS	RCRA Administrative Action Tracking System	EPA	04/17/1995	07/03/1995	08/07/1995
US	RMP	Risk Management Plans	Environmental Protection Agency	04/27/2022	05/04/2022	05/10/2022
US	BRS	Biennial Reporting System	EPA/NTIS	12/31/2019	03/02/2022	03/25/2022
US	PWS	Public Water System Data	EPA	12/17/2013	01/09/2014	10/15/2014
US	INDIAN RESERV	Indian Reservations	USGS	12/31/2014	07/14/2015	01/10/2017

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	INDIAN ODI	Report on the Status of Open Dumps on Indian Lands	Environmental Protection Agency	12/31/1998	12/03/2007	01/24/2008
US	IHS OPEN DUMPS	Open Dumps on Indian Land	Department of Health & Human Serivces, Indian	04/01/2014	08/06/2014	01/29/2015
US	ABANDONED MINES	Abandoned Mines	Department of Interior	09/13/2022	09/14/2022	12/05/2022
NY	AIRS	Air Emissions Data	Department of Environmental Conservation	07/27/2022	07/27/2022	08/04/2022
NY	COAL ASH	Coal Ash Disposal Site Listing	Department of Environmental Conservation	10/03/2022	10/04/2022	12/20/2022
NY	PFAS 3	PFAS Environmental Site Remediation List	Department of Environmental Conservation	08/08/2022	08/08/2022	11/15/2022
NY	PFAS 2	New York State Inactive Landfill Initiative	Department of Environmental Conservation	10/29/2021	11/19/2021	04/26/2022
NY	DRYCLEANERS	Registered Drycleaners	Department of Environmental Conservation	08/30/2022	08/31/2022	09/07/2022
NY	E DESIGNATION	E DESIGNATION SITE LISTING	New York City Department of City Planning	09/21/2022	10/14/2022	10/19/2022
NY	Financial Assurance 1	Financial Assurance Information Listing	Department of Environmental Conservation	09/29/2022	09/30/2022	10/06/2022
NY	Financial Assurance 2	Financial Assurance Information Listing	Department of Environmental Conservation	06/11/2020	06/16/2020	09/02/2020
NY	HIST SPILLS	SPILLS Database	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005
NY	HSWDS	Hazardous Substance Waste Disposal Site Inventory	Department of Environmental Conservation	01/01/2003	10/20/2006	11/30/2006
NY	LIENS	Spill Liens Information	Office of the State Comptroller	10/27/2022	10/27/2022	01/13/2023
NY	NY MANIFEST	Facility and Manifest Data	Department of Environmental Conservation	01/01/2019	10/29/2021	01/19/2022
NY	SPDES	State Pollutant Discharge Elimination System	Department of Environmental Conservation	03/25/2022	05/05/2022	05/18/2022
NY	SPILLS	Spills Information Database	Department of Environmental Conservation	08/08/2022	08/08/2022	10/26/2022
NY	SPILLS 80	SPILLS80 data from FirstSearch	FirstSearch	11/02/2010	01/03/2013	03/07/2013
NY	SPILLS 90	SPILLS90 data from FirstSearch	FirstSearch	12/14/2012	01/03/2013	02/12/2013
NY	UIC	Underground Injection Control Wells	Department of Environmental Conservation	08/24/2022	08/25/2022	11/14/2022
NY	VAPOR REOPENED	Vapor Intrusion Legacy Site List	Department of Environmenal Conservation	01/01/2022	02/08/2022	05/06/2022
US	MINES MRDS	Mineral Resources Data System	USGS	04/06/2018	10/21/2019	10/24/2019
US	FEDERAL FACILITY	Federal Facility Site Information listing	Environmental Protection Agency	08/25/2022	09/06/2022	12/05/2022
US	PFAS FEDERAL SITES	Federal Sites PFAS Information	Environmental Protection Agency	02/23/2022	03/31/2022	11/08/2022
US	PFAS PART 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing	Environmental Protection Agency	08/22/2018	10/26/2022	11/08/2022
US	PFAS ECHO FIRE TRAINING	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	08/22/2018	03/31/2022	11/08/2022
US	PFAS WQP	Ambient Environmental Sampling for PFAS	Environmental Protection Agency	01/03/2022	03/31/2022	11/08/2022
US	UXO	Unexploded Ordnance Sites	Department of Defense	11/09/2021	10/20/2022	01/10/2023
US	FUELS PROGRAM	EPA Fuels Program Registered Listing	EPA	08/11/2022	08/11/2022	09/30/2022
US	PFAS NPDES	Clean Water Act Discharge Monitoring Information	Environmental Protection Agency	01/03/2022	03/31/2022	11/08/2022
US	PFAS ATSDR	PFAS Contamination Site Location Listing	Department of Health & Human Services	06/24/2020	03/17/2021	11/08/2022
US	ECHO	Enforcement & Compliance History Information	Environmental Protection Agency	09/25/2022	09/30/2022	12/22/2022
US	DOCKET HWC	Hazardous Waste Compliance Docket Listing	Environmental Protection Agency	05/06/2021	05/21/2021	08/11/2021
NY	PFAS	PFAS Contamination Site Location Listing	Department of Environmental Conservation	01/16/2019	05/08/2019	06/24/2019
US	PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing	Environmental Protection Agency	01/03/2022	03/31/2022	11/08/2022
NY	NYC LEAD 2	Recent Lead Paint Violations	New York City Department of Housing Preservat	10/31/2022	10/31/2022	01/19/2023
NY	NYC LEAD	Lead-based Paint Testing Results	New York City Department of Education	08/26/2022	10/31/2022	01/19/2023
NY	COOLING TOWERS	Registered Cooling Towers	Department of Health	10/04/2022	10/10/2022	01/04/2023
US	PFAS NPL	Superfund Sites with PFAS Detections Information	Environmental Protection Agency	02/23/2022	07/08/2022	11/08/2022
US	AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing	Environmental Protection Agency	02/23/2022	03/31/2022	11/08/2022
US	PFAS TSCA	PFAS Manufacture and Imports Information	Environmental Protection Agency	01/03/2022	03/31/2022	11/08/2022
US	PFAS ECHO	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	01/03/2022	03/31/2022	11/08/2022

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
HISTORICAL USE RECORDS						
US	EDR MGP	EDR Proprietary Manufactured Gas Plants	EDR, Inc.			
US	EDR Hist Auto	EDR Exclusive Historical Auto Stations	EDR, Inc.			
US	EDR Hist Cleaner	EDR Exclusive Historical Cleaners	EDR, Inc.			
NY	RGA HWS	Recovered Government Archive State Hazardous Waste Facilitie	Department of Environmental Conservation		07/01/2013	12/30/2013
NY	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Environmental Conservation		07/01/2013	01/10/2014
COUNTY RECORDS						
NY	AST - CORTLAND	Cortland County Storage Tank Listing	Cortland County Health Department	08/20/2019	08/20/2019	10/16/2019
NY	UST - CORTLAND	Cortland County Storage Tank Listing	Cortland County Health Department	08/20/2019	08/20/2019	10/16/2019
NY	AST - NASSAU	Registered Tank Database	Nassau County Health Department	01/09/2017	01/11/2017	02/15/2017
NY	AST NCFM	Storage Tank Database	Nassau County Office of the Fire Marshal	02/15/2011	02/23/2011	03/29/2011
NY	TANKS NASSAU	Registered Tank Database in Nassau County	Nassau County Department of Health	01/09/2017	01/11/2017	02/15/2017
NY	UST - NASSAU	Registered Tank Database	Nassau County Health Department	01/09/2017	01/11/2017	02/15/2017
NY	UST NCFM	Storage Tank Database	Nassau County Office of the Fire Marshal	02/15/2011	02/23/2011	03/29/2011
NY	AST - ROCKLAND	Petroleum Bulk Storage Database	Rockland County Health Department	02/02/2017	03/17/2017	09/22/2017
NY	UST - ROCKLAND	Petroleum Bulk Storage Database	Rockland County Health Department	02/02/2017	03/17/2017	09/22/2017
NY	AST - SUFFOLK	Storage Tank Database	Suffolk County Department of Health Services	06/28/2018	12/06/2018	02/07/2019
NY	TANKS SUFFOLK	Storage Tank Database	Department of Health Services	06/28/2018	02/05/2019	03/08/2019
NY	UST - SUFFOLK	Storage Tank Database	Suffolk County Department of Health Services	06/28/2018	12/06/2018	02/07/2019
NY	AST - WESTCHESTER	Listing of Storage Tanks	Westchester County Department of Health	07/20/2022	08/23/2022	11/14/2022
NY	UST - WESTCHESTER	Listing of Storage Tanks	Westchester County Department of Health	07/20/2022	08/23/2022	11/14/2022

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX 15.6

CONTRACTUAL CONDITIONS BETWEEN USER AND ENVIRONMENTAL PROFESSIONAL

TERMS AND CONDITIONS

1. Clients Obligation

To assist ALC in performance of the Services hereunder, Client shall (a) permit reasonable access to Client location. Client agrees to have a representative from property assisting the technician throughout the process.

2. Standard of Performance

ALC shall use its best level of effort consistent with professional standards in performing services by applying its judgment and experience to information received, obtained, or otherwise used by ALC in connection with the facility or study area in question

3. Confidentiality

Each party shall retain as confidential all information and data furnished to it by the other party and shall not disclose such information to any other party. However, nothing herein is meant to prevent ALC from adding Client's name to its client and/or referral list.

4. Indemnification

It is understood and agreed that, in seeking the professional services of ALC under this Agreement, the Client is requesting ALC to undertake potentially uninsurable obligations for the Client's benefit, involving the presence or potential presence of hazardous or toxic substances. Therefore, the Client agrees to hold harmless, indemnify and defend ALC from and against any and all claims, losses, damages, liability and costs, including but not limited to cost of defense, arising out of or in any way connected with the presence, discharge, release or escape of contaminants of any kind, excepting only such liability as may arise out of the sole negligence of ALC in the performance of services under this Agreement.

5. Insurance

ALC maintains the following limits of Insurance:

Comprehensive General Liability

Bodily Injury $1,000,000/occurrence
Property Damage $1,000,000/occurrence
Property Damage $2,000,000/aggregate
General Liability Coverage Up to $2,000,000/aggregate
Professional Liability $1,000,000

Automobile Employers
Non-Ownership/Hired Car $1,000,000
Bodily Injury $1,000,000/person
Property Damage $1,000,000/occurrence

Worker's Compensation Statutory
Each occurrence $100,000/person
Disease policy limit $500,000/aggregate
Disease policy limit $100,000/occurrence

6. Compliance with Applicable Law

ALC shall use its best efforts to observe and abide by applicable laws, regulations, ordinances and other rules of the United States, any state, territory or political subdivision thereof, wherein the Services are to be performed.

APPENDIX 15.7

QUALIFICATIONS OF THE ENVIRONMENTAL PROFESSIONAL

Tania Castro: Director of Real Estate Division

EDUCATION

Masters Environmental and Occupational Health Sciences, Hunter College-2002

PROFESSIONAL SUMMARY

Ms. Castro has over 15 years of managerial experience in the environmental field with expertise in environmental site assessments, lead-based paint, and asbestos and indoor air quality. Ms. Castro has a strong working knowledge of applicable federal, state, and local regulations and has proven ability to customize services to fully satisfy the client's needs. Her experience includes training, asbestos inspections, indoor air quality inspections, lead inspection, environmental site assessments, abatement, abatement design, indoor and outdoor air monitoring, and management in a variety of public and commercial settings.

PROFESSIONAL EXPERIENCE

ALC Environmental:

- Managing the daily operations of the Real Estate Due Diligence Division.
- Perform Phase I Environmental Site Assessments throughout the tri-state area.
- Monitor and manage Phase II projects.
- Analyze and QAC all field inspection results prior to report finalization. .
- Prepare proposals, invoices, billings, and project documentations for clients.
- Provide inspection and abatement recommendations, rate costs, and regulatory information to clients.

KEY PROJECTS

The Community Preservation Corporation- Environmental Site Assessments; The New York School Construction Authority- Lead and Asbestos projects; Metropolitan Transit Authority- Lead and Asbestos Management Services, and ACE Environmental Risk- Health and Safety Training Program.

CERTIFICATIONS

- EPA Lead Inspector/Risk Assessor
- NYSDOL Asbestos Inspector and Designer
- 29 CFR.120 (Hazwopper).